PHASE I ENVIRONMENTAL SITE ASSESSMENT

HALSTEAD STATION (VACANT LAND)
255 Huguenot Street
New Rochelle, Westchester County, New York 10801

Prepared for:
Khosla Capital LLC
and
Signature Bank

June 6, 2022
Project Number: KHOSNJ001.02

BLACKSTONE
CONSULTING LLC | A Rimkus Company
Our Insight. Your Success.
BLACKSTONECONSULTING.COM

TABLE OF CONTENTS

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS ..... **i**
EXECUTIVE SUMMARY ..... **ii**
1 INTRODUCTION **1**
1.1 Purpose 1
1.2 Special Terms and Conditions 2
1.3 Scope of Services 2
1.4 Significant Assumptions and Data Gaps 3
1.5 Report Viability 4
2 USER PROVIDED INFORMATION **6**
2.1 Reason For Performing the Phase I ESA 6
2.2 ASTM E1527-21 User Questionnaire 6
2.3 Owner, Key Site Manager, and Occupant Information 7
2.4 Past Owners, Operators, and Occupant Interviews 7
2.5 Representation and Reliance 8
3 SUBJECT PROPERTY DESCRIPTION **9**
3.1 Subject Property Characteristics and Features 9
3.2 Utilities 9
4 VICINITY RECONNAISSANCE **11**
5 PHYSICAL SETTING **12**
6 HISTORICAL INFORMATION REVIEW **13**
6.1 Historical Fire Insurance Maps 13
6.2 Aerial Photographs 14
6.3 Historical Topographic Maps 15
6.4 City Directories 15
6.5 Agency Records, Interviews, and Other Historical Sources 16
6.6 Environmental Lien/AUL Search 17
6.7 Previous Environmental Reports 17
6.8 Historical Information Conclusions 19
7 ENVIRONMENTAL DATABASE SEARCH AND REVIEW **20**
7.1 Federal, State, Local, Tribal, and Proprietary Databases 21
7.2 Unmappable Facilities 22
7.3 Vapor Encroachment Screening 23
7.4 Affirmation 23
7.5 Environmental Database Search and Review Conclusions 23
8 SUBJECT PROPERTY INSPECTION **24**
8.1 Underground Storage Tanks (USTs) 24
8.2 Aboveground Storage Tanks (ASTs) 24
8.3 Hazardous Substances and Petroleum Products 24
8.4 Hazardous Substances and Petroleum Products Wastes 25
8.5 Non-Hazardous Wastes 25
8.6 Polychlorinated Biphenyls (PCBs) 25
8.7 Wastewater Discharges 25

8.8 Stormwater Discharges 26
8.9 Pits, Ponds, and Lagoons (On-Site Process Water Discharge) 26
8.10 Wells 26
8.11 Underground Product Pipelines 26
8.12 Strong, Pungent, or Noxious Odors 27
8.13 Pools of Liquid 27
8.14 Stressed Vegetation or Stained Surfaces 27
8.15 Stains or Corrosion on Floors, Walls, or Ceilings 27
8.16 Subject Property Inspection Conclusions 27
9 ASTM NON-SCOPE CONSIDERATIONS 28
9.1 Asbestos-Containing Materials (ACM) 28
9.2 Lead-Based Paint (LBP) 28
9.3 Radon Gas 28
9.4 Apparent Mold Growth (AMG) 28
9.5 Drinking Water Quality 28
9.6 Air Emissions 29
9.7 Wetlands 29
10 CONCLUSIONS AND RECOMMENDATIONS 30

APPENDICES

Appendix A: Subject Property Maps, Plans, and Photographs
- Subject Property Location Map
- Subject Property Plan
- Subject Property Photographs

Appendix B: Historical Sources
- Historical Fire Insurance Maps
- Historical Aerial Photographs
- Historical Topographic Maps
- Historical City Directories

Appendix C: Previous Environmental Reports/Supporting Documents
Appendix D: Environmental Database Search Report
Appendix E: AAI User Questionnaire
Appendix F: Qualifications of Professionals

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

This Phase I Environmental Site Assessment (ESA) Report documents the research methodology used by qualified environmental professionals of Rimkus Consulting Group, Inc., DBA Blackstone Consulting LLC (Blackstone) to identify recognized environmental conditions using the scope and limitations of ASTM Standard Practice E1527-21 and the May 13, 2022 proposal (Agreement) between Khosla Capital LLC and Blackstone.

We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR 312, and we have the specific education, training, and experience qualifications necessary to assess a subject property of the nature, history, and setting of the subject property. We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.


Prepared By:



Lauren Beyrent
Senior Project Manager

06/06/2022
Date

Technical Review and Concurrence By:



Allan S. Coffee
Director, Environmental Due Diligence Services

06/06/2022
Date

Oversight By:



Becky Renick
Director, Assessment Services

06/06/2022
Date

sn

EXECUTIVE SUMMARY

Rimkus Consulting Group, Inc., DBA Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of Halstead Station (Vacant Lot) located at 255 Huguenot Street in New Rochelle, Westchester County, New York (subject property). The purpose of the Phase I ESA is to identify recognized environmental conditions (RECs) in accordance with ASTM Standard E1527-21 and other agreed-upon ASTM *Non-Scope Considerations (Business Environmental Risk Issues)*. Blackstone understands that this assessment is being performed for a potential acquisition.

SUBJECT PROPERTY INSPECTION DETAILS

Name of Inspector:	Lauren Beyrent
Date of Inspection:	May 24, 2022
Subject Property Representative(s):	Blackstone was unaccompanied during the subject property inspection

SUBJECT PROPERTY DESCRIPTION

Street Address:	255 Huguenot Street
City and State:	New Rochelle, New York
County:	Westchester
Legal Description:	City of New Rochelle Parcel Number: 1-234-0002
Owner(s):	New Rochelle Ind Dev Agency
Size:	Approximately 0.46 acre
Building(s) (Type and Size):	None
Use/Operations:	Vacant land
Year(s) Built:	Not Applicable
Other Features:	A storage trailer and constructions materials were observed to be stored on the northern portion of the subject property

HISTORICAL SUMMARY

Reasonably ascertainable historical information indicates the subject property was initially developed with a residential structure prior to 1887. By the late 1800s/early 1900s, the subject property was developed with multiple commercial buildings along the northern portion, and, by 1930, the subject property was developed with commercial and office buildings. Historical uses of the subject property included a laundry business (1896 only), a post office, hotel, restaurants, a theatre, retail storefronts, and offices. Between the 1950s and 1990s, the northwestern portion of the subject property was utilized for surface parking. These structures were demolished in the early 1990s, and the subject property was redeveloped in 2001 with a single-story extension of the present-day south adjoining apartment building and exterior amenities (pool, playground, etc.). The former subject property improvements were razed by 2019 and the subject property has been vacant since that time.

The north, east, and south adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, and a lighting company between approximately 1931 and 1951, prior to the construction of the present-day Chase Bank office building in the early 1970s. The east adjoining properties beyond Huguenot Street consisted of multiple commercial structures, including a "Chinese laundry" in 1896, and a hotel between approximately 1911 and 1951. The present-day surface parking lot to the adjoining east was constructed in the 1970s and the present-day Ruby Dee Park on Library Green was developed in the 2000s. The south adjoining properties consisted of multiple commercial structures, including a "Chinese laundry" in 1911, and surface parking in the 1950s through 1990s, prior to the construction of the present-day apartment building and parking garage in 2001. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

SUMMARY OF FINDINGS AND OPINIONS

The subject property and adjoining properties were identified with retail laundry or dry cleaning operations in the late 1890s and early 1900s. The use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. These facilities are not identified on any databases indicative of releases or cleanup actions. Based on the era of operation, absence of reported releases, and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities is not considered a REC.

Blackstone performed a Phase I ESA of the subject property in conformance with the scope and limitations of ASTM Standard Practice E1527-21, the regulations at 40 CFR Part 312, and the May 13, 2022, proposal (Agreement) between Khosla Capital LLC and Blackstone. Any exceptions to, or deletions from, this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no *recognized environmental conditions* (*RECs*), *controlled recognized environmental conditions (CRECs),* or *significant data gaps* in connection with the subject property. No further investigation is recommended.

The Executive Summary is only intended to represent a brief summary of our findings and is not a detailed account of all the information provided in this report. The report should be reviewed in its entirety prior

to drawing any final conclusions as to potential environmental conditions associated with the subject property.

1 INTRODUCTION

1.1 PURPOSE

Rimkus Consulting Group, Inc., DBA Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of Halstead Station (Vacant Lot) located at 255 Huguenot Street in New Rochelle, Westchester County, New York (subject property).

The purpose of this Phase I ESA is to investigate and identify *recognized environmental conditions* (*RECs*) associated with the subject property and/or surrounding properties. ASTM Standard Practice E1527-21 defines RECs as:

> *(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment*.
>
> *A de minimis condition is not a recognized environmental condition. A de minimis condition is a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies*.

Additionally, this Phase I ESA was conducted to identify *controlled recognized environmental conditions (CRECs)* associated with the subject property and/or surrounding properties. ASTM Standard Practice E1527-21 defines CRECs as:

> *A recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).*

This Phase I ESA also was conducted to identify *historical recognized environmental conditions* (*HRECs*) associated with the subject property and/or surrounding properties. ASTM Standard Practice E1527-21 defines HRECs as:

> *A previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.*

This practice is generally intended for the User to satisfy one of the requirements to qualify for the *innocent landowner, contiguous property owner,* or *bona fide prospective purchaser* limitations on CERCLA liability; that is, this practice constitutes all appropriate inquiries (AAI) into the previous ownership and uses of the subject property consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312.

ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues)* are detailed in Section 1.3 and outlined in the May 13, 2022 proposal and scope of work (Agreement) between Khosla Capital LLC and Blackstone.

1.2 SPECIAL TERMS AND CONDITIONS

This Phase I ESA has been conducted in accordance with ASTM Standard Practice E1527-21, the regulations at 40 CFR Part 312, and the Agreement between Khosla Capital LLC and Blackstone. Qualifications of the professionals who conducted this assessment are provided in the appendices.

Blackstone performed the professional services, obtained findings, rendered conclusions, and prepared recommendations in accordance with generally accepted practices of other environmental consultants undertaking similar assessments at the same time in the same geographical area.

Historical and environmental information pertaining to the subject property is included in this report to the extent that such information is *practically reviewable*, as defined in the above-referenced standard practice.

1.3 SCOPE OF SERVICES

As detailed in the Agreement, this Phase I ESA was conducted in accordance with the industry standard ASTM Standard Practice E1527-21 and in accordance with all appropriate inquiries (AAI) into the previous ownership and uses of the subject property consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312. An update by the EPA of the regulations at 40 CFR 312 to reference the current ASTM E1527-21 standard is forthcoming. This Phase I ESA included the following services:

1. A subject property inspection to identify and evaluate potential sources of RECs such as underground storage tanks (USTs), aboveground storage tanks (ASTs), equipment containing polychlorinated biphenyls (PCBs), waste and chemical storage areas, air emissions, and wastewater and stormwater discharges; the inspection included observations for evidence of chemical spills, releases, or on-site waste disposal;

2. A review of subject property records and interviews with subject property representatives with regard to current and former subject property operations to identify known or potential environmental concerns;

3. A visual survey of the properties in the vicinity of the subject property to evaluate the potential for RECs at the subject property from these properties;

4. A review of historical information to identify RECs at the subject property from historic on-site and off-site uses; to the extent feasible under the conditions of the assessment, the historical information obtained included verbal information from the subject property and/or local agency representatives; in addition, some or all of the following records, where *publicly available* and *practically reviewable*, were reviewed: construction plans, zoning maps, building permits, property record cards, topographic maps, fire insurance maps, historical city directories, and aerial photographs; and

5. A review of State and Federal environmental database information.

In addition, to identify ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) in addition to the ASTM requirements and as required per the Agreement, Blackstone also performed document research, visual and/or sampling surveys, and interviews for the presence of:

- Asbestos-containing materials (ACM),
- Lead-based paint (LBP),
- Radon Gas,
- Apparent mold growth (AMG) and moisture intrusion conditions conducive to mold growth,
- Drinking water quality,
- Air emissions, and
- Wetlands.

The scope of this Phase I ESA did not include surface water, soil, soil vapor, or groundwater sampling. Consequently, conclusions provided with regard to surface water, soil, soil vapor, and groundwater impacts are limited to those that can be formed based on a non-intrusive investigation. The absence of environmental hazards in the subsurface cannot be guaranteed based on conditions observed on the surface.

Where performed, the limited ACM, LBP, AMG, and radon surveys are intended to provide an indication of the potential for significant environmental issues associated with these ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*). Hidden materials or locations such as those inside walls, inaccessible attics, and inside ductwork and piping were not evaluated. As such, these surveys should not be regarded as comprehensive surveys for demolition or renovation purposes or indoor air quality health risk assessments, vapor intrusion into buildings, or explosion hazards.

1.4 SIGNIFICANT ASSUMPTIONS AND DATA GAPS

The subject property inspection consisted of a walkover of the subject property perimeter and exterior subject property areas. Furthermore, during the subject property inspection, Blackstone did not inspect inaccessible areas of the subject property including under manholes or within the storage trailer. The adjoining properties were visually observed from curbside without being entered. Blackstone has no

reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

The historical information reviewed did not confirm the first developed use of the subject property. *Data failure*, as defined by ASTM, has occurred in attempting to identify obvious uses of the subject property back to the first developed use, or back to 1940, whichever is earlier. Information regarding the use of the subject property prior to 1887 was not available from the *standard historical sources* (including available aerial photographs, fire insurance maps, property tax files, recorded land title records, USGS topographic maps, local street directories, building department records, or zoning/land use records). There were no other reasonably ascertainable historical sources available for review that were considered sufficiently useful. It is the opinion of Blackstone that the data failure does not represent a significant data gap that impacts our ability to identify RECs.

Conclusions stated herein are based upon publicly available information and other documented sources. Blackstone has assumed, where reasonable, that the information reviewed is true and accurate. Blackstone assumes no responsibility for inaccurate information that is not otherwise obvious in light of information of which Blackstone has actual knowledge. Blackstone's subject property observations are of the conditions observed at the time of the assessment.

Blackstone reviewed an environmental database search report. Blackstone's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, Blackstone's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the subject property.

This report provides an estimation of groundwater flow direction at the subject property based on visual observations and topographical data. This assessment did not include groundwater sampling and water table elevation measurement. True groundwater flow direction can only be determined through direct measurement of groundwater elevations from properly installed on-site groundwater monitoring wells. The groundwater flow direction estimation should not be considered a true measurement of groundwater flow direction.

1.5 REPORT VIABILITY

Per ASTM Standard Practice E1527-21, a Phase I ESA is presumed to be viable when it is conducted within 180 days prior to the date of acquisition of the *subject property* (or, for transactions not involving an acquisition, the date of the intended transaction).

The dates of the components presented for *interviews*, review of government records, visual inspections, and declaration by *environmental professional*, are provided below. Completion of searches for recorded environmental cleanup liens is a *User* responsibility; however, if the *User* has engaged Blackstone to conduct these searches, the date will be identified below.

TABLE OF CRITICAL DATES

Visual Inspection	May 24, 2022
Interviews with owners, operator, and occupants	May 24, 2022
Declaration of Environmental Professionals	June 6, 2022
Review of federal, tribal, state, and/or local government records	May 19, 2022
Environmental Lien Search	N/A

*N/A = Not included within the scope of work

2 USER PROVIDED INFORMATION

As defined under ASTM Standard Practice E1527-21, Khosla Capital LLC is considered the "User" of this Phase I ESA report. To qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002 (the *"Brownfields Amendments"),* the User should provide certain information based on their relationship to the purpose of the due diligence and as required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31.

The information requested from the User and associated responses are outlined below in Section 2.2.

2.1 REASON FOR PERFORMING THE PHASE I ESA

Blackstone understands that this assessment was performed for Khosla Capital LLC as the potential purchaser of the subject property. As such, this Phase I ESA was conducted in an effort to qualify for the *innocent landowner, contiguous property owner,* and *bona fide prospective purchaser* defense to CERCLA liability and performed as an appropriate risk management and due diligence standard for real estate transactions in accordance with general industry standards which include ASTM Standard E1527-21 and the regulations at 40 CFR Part 312.

2.2 ASTM E1527-21 USER QUESTIONNAIRE

The User Questionnaire was completed and returned to Blackstone and is included in the appendices. The information requested and associated User responses are outlined below:

INFORMATION REQUESTED	***USER RESPONSE (YES, NO, OR UNKNOWN)***
Environmental liens (40 CFR 312.25) and activity and land use limitations (AULs) (40 CFR 312.26(a)(1)(v) and (vi)) Did a search of land title records (or judicial records where appropriate) identify environmental liens and/or AULs (such as engineering controls, land use restrictions, or institutional controls) that are in place at the subject property and/or have been filed or recorded against the subject property under federal, tribal, state or local law?	No*
Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28) As the User, do you have any specialized knowledge or experience related to the *property* or nearby properties?	Yes

INFORMATION REQUESTED	***USER RESPONSE (YES, NO, OR UNKNOWN)***
Relationship of the purchase price to the fair market value of the subject property if it were not contaminated (40 CFR 312.29) Does the purchase price being paid for this property reasonably reflect the fair market value of the property and has not been reduced due to contamination known or believed to be present at the property?	Yes
Commonly known or reasonably ascertainable information about the subject property (40 CFR 312.30) Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases (such as past uses of the subject property, specific chemicals that are present or once were present at the subject property, spills or other chemical releases that have taken place at the subject property, and environmental cleanups that have taken place at the subject property)?	No The User provided Blackstone with prior environmental reports for the subject property, which are further discussed in Section 6.7.
The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31). As the User, based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the subject property?	No

*The User did not request Blackstone to perform a Lien and AUL search as part of the scope of work. Nor was this documentation provided to Blackstone. In accordance with ASTM E1527-21, Blackstone reviewed an environmental database search report that included a search of institutional control and engineering control databases as further discussed in Section 7.

2.3 OWNER, KEY SITE MANAGER, AND OCCUPANT INFORMATION

The subject property owner was not available to provide information regarding the environmental conditions at the subject property. In addition, as the subject property currently consists of vacant land, no Key Site Manager or occupants/operators were interviewed.

2.4 PAST OWNERS, OPERATORS, AND OCCUPANT INTERVIEWS

In accordance with ASTM Standard Practice E1527-21, interviews with past owners, operators, and occupants shall be conducted to the extent that they have been identified and that the information likely to be obtained is not duplicative of information already obtained. Blackstone has no reason to believe that such interviews were necessary for this subject property or would alter the findings or recommendations set forth in this report.

2.5 REPRESENTATION AND RELIANCE

The work performed for this assessment is consistent with the standards of care and skill ordinarily exercised by members of the profession currently practicing in the same locality under similar conditions. No other representation, expressed or implied, and no warranty or guarantee is included or intended in the report.

Khosla Capital LLC and Signature Bank may rely on this report subject to the terms and conditions of the Agreement between Khosla Capital LLC and Blackstone. No other person may rely on this report without written authorization from Blackstone and Khosla Capital LLC. If any of the above limitations conflict with the Agreement, the Agreement governs.

3 SUBJECT PROPERTY DESCRIPTION

3.1 SUBJECT PROPERTY CHARACTERISTICS AND FEATURES

Street Address:	255 Huguenot Street
City and State:	New Rochelle, New York
County:	Westchester
Legal Description:	City of New Rochelle Parcel Number: 1-234-0002
Owner(s):	New Rochelle Ind Dev Agency
Size:	Approximately 0.46 acre
Zoning:	DMUR (Downtown Mixed Use Urban Renewal)
Building(s) (Type and Size):	None
Use/Operations:	Vacant land
Year(s) Built:	Not Applicable
Construction Materials:	Not Applicable
Heating/Cooling Systems:	Not Applicable
Other Features:	A storage trailer and constructions materials were observed to be stored on the northern portion of the subject property.

A Subject Property Location Map depicted on the local U.S. Geological Survey (USGS) topographic quadrangle, a Subject Property Plan, and Subject Property Photographs are included in the appendices.

3.2 UTILITIES

Electricity Provider:	Not provided, but available through Con Edison
Natural Gas Provider:	Not provided, but available through Con Edison
Potable Water:	Not provided, but available through United Water New York
Sewer Services:	City of New Rochelle

According to previous environmental reports, the previous on-site structures were connected to the municipal systems for sanitary sewer disposal and potable water supply. The subject property was historically developed with multiple commercial and residential structures since at least the 1880s. The City of New Rochelle water and sewer systems date back to at least the late 1800s; therefore, it is likely that the former subject property buildings were connected to the municipal potable water and sanitary sewer systems.

No RECs were identified as a result of the review of the subject property as described in this section of the report.

4 VICINITY RECONNAISSANCE

The subject property is located in New Rochelle, Westchester County, New York, within an area characterized by urban commercial development. Adjoining property use is summarized as follows:

	ADJOINING PROPERTY USE
North:	Bridge Street, followed by Chase Bank office building (270 North Avenue)
East:	Huguenot Street followed by a surface parking lot and the Ruby Dee Park on Library Green
South:	Halstead Station apartment building (255 Huguenot Street/1 Shearwood Place), followed by a parking garage (275 Huguenot Street)
West:	Station Plaza South followed by the New Rochelle train station, parking areas, and associated railroad tracks

SOURCE	***FINDINGS***
Field observations	Blackstone observed no current industrial, manufacturing, or military operations such as outdoor chemical or hazardous waste storage or handling activities that may impact the subject property and no evidence of chemical spills, releases, or waste disposal was observed. From accessible vantage points, Blackstone identified no outdoor chemical or waste storage, wastewater treatment facilities, or other operations that may impact the subject property, and no pits, ponds, or lagoons for apparent discharge and/or treatment of actively generated industrial process water were observed.
Environmental databases search	Adjoining and/or nearby properties identified in the environmental databases searched are further discussed in Section 7.
	No RECs were identified during the vicinity reconnaissance.

5 PHYSICAL SETTING

The following summarizes the physical setting of the subject property based on information provided in available resources:

SUMMARY OF PHYSICAL SETTING

Item	*Findings*	*Reference*
Surficial Soils Beneath Subject property	Urban land	USDA NRCS Web Soil Survey and EDR Report
Depth to Bedrock	Between approximately 5 and 50 feet bgs	USDA NRCS Web Soil Survey and EDR Report
Topography	The subject property is generally flat, and the surrounding area exhibits a slight slope to the east	USGS *Mount Vernon, New York* topographic map and subject property observations
Elevation	Approximately 80 feet NAVD	USGS *Mount Vernon, New York* topographic map
Depth to Shallow Groundwater	Approximately 10 to 30 feet bgs	EDR Report
Estimated Groundwater Flow Direction	East	USGS *Mount Vernon, New York* topographic map

bgs: below ground surface
EDR Report: Environmental Data Resources Database Report
NAVD: North American Vertical Datum, 1988-1990
USGS: United States Geological Survey
USDA: United States Department of Agriculture
NRCS: Natural Resources Conservation Service

No RECs were identified as a result of the physical setting records review.

6 HISTORICAL INFORMATION REVIEW

As part of this Phase I ESA, Blackstone reviewed historical information to identify RECs associated with the historical use of the subject property and surrounding properties. Blackstone obtained historical information from interviews with subject property representatives and other individuals familiar with the subject property as well as aerial photographs, historical maps, and other *practically reviewable* standard historical sources that are considered *reasonably ascertainable*.

6.1 HISTORICAL FIRE INSURANCE MAPS

Environmental Data Resources, Inc. (EDR) searched available historical fire insurance maps for the subject property and subject property vicinity. Historical fire insurance maps are scaled drawings that indicate the location and use of building structures present in a given area from as early as the late 1800s. The maps provide information regarding the development and historical use of subject property structures and can indicate the historical presence of tanks at the subject property and other potential environmental concerns.

The following table includes descriptions of the subject property and surrounding properties on the earliest maps available and only includes significant changes in subsequent years. The Sanborn maps are reproduced in the appendices.

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	*Subject Property*	*Adjoining Properties*
1887	Residential dwelling	Residential and commercial development to north and east; dwellings to the south; railroad tracks and railroad passenger depot to the west; and Bridge Street and Huguenot Street to the north and east (respectively).
1892	Multiple commercial structures (including a post office building) along northern perimeter	Commercial structures to the north, east, and south
1896	Additional commercial development depicted, including a hotel, restaurant, offices, and laundry business	Additional commercial development to the south; “Chinese laundry” to the east
1903	Laundry business no longer depicted	No significant changes
1911	Multiple commercial and residential structures, including various offices and a theatre	Urban commercial development to the north, east, and south; hotel to the east; and “Chinese laundry” depicted on the north and south adjoining properties.
1931 1942	Multiple commercial and office structures	Lighting company to the north, hotel to the east, various stores to the south
1951	Surface parking lot at northwestern portion	No significant changes
1990 1991	Parking area at western portion, and several on-site structures labelled as vacant	Present-day north adjoining office building and present-day east adjoining parking area depicted

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	*Subject Property*	*Adjoining Properties*
		Surface parking to the south and the present-day railroad station to the west
1992 1993 1994 1995 1996	Primarily vacant land with surface parking at west-northwest portion	South adjoining property generally is vacant with parking area; however, small retail building and gas tank are depicted.
2003	Two commercial buildings, which are attached to the south adjoining apartment building.	Present-day apartment building and parking garage depicted to south. Present-day park depicted to east.

Findings: As further discussed in Section 6.8, the former on-site laundry business and the former north, east, and south adjoining "Chinese laundry" tenants are not considered RECs. As further discussed in Section 7.1, the gas tank depicted at the south adjoining property is not considered a REC. No RECs were identified from the review of historical Sanborn Fire Insurance Maps.

6.2 AERIAL PHOTOGRAPHS

EDR provided aerial photographs of the subject property area, which are included in the appendices and summarized below. The following table includes descriptions of the subject property and surrounding properties on the earliest aerial photographs available and only includes significant changes in subsequent years.

SUMMARY OF HISTORICAL AERIAL PHOTOGRAPH REVIEW

Year	*Subject Property*	*Adjoining Properties*
1946	Multiple commercial structures	Urban commercial development visible to north, east, and south. Railroad tracks and a presumed rail station visible to west.
1951 1954 1961 1966	West-northwest portion appears to be a surface parking lot.	Surface parking areas appear to the north and south.
1974 1980 1985	No significant changes	Present-day north adjoining office building visible. Present-day parking area appears to the east.
1994	Primarily vacant land, with a portion of a surface parking lot visible in the western area.	South adjoining property appears primarily as vacant land with surface parking and small commercial structure.
2006 2009 2013 2017	Developed with commercial structure and pool.	Appear in present-day configuration.

Findings: No RECs were identified from the review of historical aerial photographs.

6.3 HISTORICAL TOPOGRAPHIC MAPS

EDR provided historical topographic maps of the subject property area, which are included in the appendices and summarized below. The following table includes descriptions of the subject property and surrounding properties on the earliest historical topographic maps available and only includes significant changes in subsequent years.

SUMMARY OF HISTORICAL TOPOGRAPHIC MAP REVIEW

Year	*Subject Property*	*Adjoining Properties*
1897 1898 1900 1947	Depicted with structures located within a densely developed area	Depicted with structures located within a densely developed area; railroad tracks depicted to west.
1956 1966 1979 1995	Shaded denoting location within a densely developed area	Shaded denoting location within a densely developed area; railroad tracks and station depicted to west.
2013 2016 2019	This topographic map does not include structures or shading (similar to a street map, except with contour lines). The present-day adjoining and nearby roads are depicted.	

Findings: No RECs were identified as a result of the review of historical topographic maps.

6.4 CITY DIRECTORIES

EDR provided City Directories for the subject property and adjoining properties at approximately five-year intervals for the years spanning 1964 to 2017. The City Directory listings are included in the appendices and summarized below.

SUMMARY OF CITY DIRECTORY REVIEW

Subject Property Listings		
Addresses Reviewed	***Years***	***Review Summary***
255 Huguenot Street (current subject property and south adjoining property address)	1972-2017	New Rochelle Maennerchor; Portuguese American Club; apartments with multi-family residential listings
245-255 Huguenot Street (odd numbers) (former subject property addresses)	1964-2017	Primarily commercial listings, including restaurants, offices, and retail outlets

SUMMARY OF CITY DIRECTORY REVIEW

Subject Property Listings		
Adjoining Property Listings		
Direction From Subject Property	***Addresses Reviewed***	***Review Summary***
East	264 Huguenot Street	Commercial between 1964 and 1972
South	255-275 Huguenot Street	New Rochelle Maennerchor; Portuguese American Club; apartments with multi-family residential listings; 255 Huguenot St Corp/275 Huguenot Garage between 1972 and 2017

Findings: No RECs were identified as a result of the review of historical city directories.

6.5 AGENCY RECORDS, INTERVIEWS, AND OTHER HISTORICAL SOURCES

In accordance with ASTM E1527-21, Blackstone requested subject property history and/or regulatory information regarding the subject property from federal, state, and/or local government officials. Information regarding the subject property is obtained from regulatory agency officials either by:

1) Conducting interviews by telephone or in-person at various federal, state, and/or local agencies; or
2) Requesting file information via submission of an open records request to the appropriate agency contact based upon applicable agency requirements, and in accordance with the Freedom of Information Act (FOIA).

Findings from the interviews/records review are summarized below:

SUMMARY OF AGENCY RECORDS, INTERVIEWS, AND OTHER HISTORICAL SOURCES

Source	***Information Requested***	***Findings***
City of New Rochelle Assessor's Office Online Query https://www.newrochelleny.com/199/Assessments	Typical ownership data, parcel information, and valuation data	No conditions of environmental concern were identified for the subject property. Typical subject property ownership, parcel size, dates of construction, and tax assessment data were obtained for the subject property and/or adjoining properties.
City of New Rochelle, City Clerk, FOIL Request Form, via email cityclerkinfo@newrochelleny.com	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any emergency environmental responses or incidents	A FOIA request was submitted to this agency. A response has not been received to date and is not considered reasonably ascertainable for inclusion in this report.

SUMMARY OF AGENCY RECORDS, INTERVIEWS, AND OTHER HISTORICAL SOURCES

Source	*Information Requested*	*Findings*
United Water New York https://mywater.veolia.us/sites/default/files/WC1waterquality2021.pdf	Water supply	Drinking water quality information is provided in Section 9.5
New York State Department of Environmental Conservation (NYSDEC) https://www.dec.ny.gov/chemical/8437.html	On-line review of spills incidents, Petroleum Bulk Storage (PBS), and remediation databases	Information obtained from the NYSDEC database is discussed in pertinent sections of the report.

Findings: No RECs were identified from the review of the local agency records, interviews, or other readily available historical sources.

6.6 ENVIRONMENTAL LIEN/AUL SEARCH

As previously discussed in Section 2.2, an environmental lien and activity & use limitation (AUL) search was not included in the scope of this assessment and was not provided to Blackstone for review by the User.

6.7 PREVIOUS ENVIRONMENTAL REPORTS

Blackstone was provided with the following previous environmental reports regarding the subject property for review:

- *Fannie Mae Phase I Environmental Site Assessment, La Rochelle, 255 and 275 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC (Blackstone) for Walker & Dunlop, and dated June 3, 2016 (2016 Blackstone ESA)

At the time of the 2016 Blackstone ESA, the subject property was developed with a single-story building containing apartment amenities, which was an extension of the south-adjoining apartment building. The 2016 Blackstone ESA also included the south-adjoining properties, which consisted of the present-day 24-story apartment building and five-story parking structure. At the time of the 2016 Blackstone ESA, the south-adjoining apartment building also included several street-level commercial spaces.

According to the 2016 Blackstone ESA, the subject property and south adjoining properties were initially developed with residential structures prior to 1887. By 1900, the northern majority of the subject property was developed with commercial buildings, and by 1930, the entire subject property was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. The former subject property structures were reportedly demolished between the early and mid-1990s.

The 2016 Blackstone ESA reported that Sound Dry-cleaning was located at the south adjoining property by at least the mid-2000s. Blackstone indicated that this tenant operated as a drop-off/pick-up only location and was not involved in active dry-cleaning activities. In addition, this tenant was not identified on any databases indicative of the generation or disposal of hazardous wastes typically associated with an active dry-cleaning facility. As such, Blackstone concluded that this drycleaner tenant was not considered a REC.

- *Fannie Mae Environmental Database and Document Review, La Rochelle, 255 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC (Blackstone) for Walker & Dunlop, and dated April 18, 2018 (2018 Blackstone Report)

The purpose of the 2018 Blackstone Report was to determine if the subject property or nearby properties were listed within various local, state, and federal agency database files and if these listings represented a potential Environmental Risk Management Issue. The environmental database review does not constitute a Phase I Environmental Site Assessment in accordance with ASTM E1527-13 and does not meet the requirements of the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI). A subject property visit was not conducted as part of the 2018 Blackstone Report and identifying Recognized Environmental Conditions (RECs) was beyond the scope of work.

The 2018 Blackstone Report was performed for the present-day subject property, along with the present-day south adjoining properties. Based on the data obtained, the environmental database report, and historical documents review, Blackstone concluded that no facilities identified within the specified search distances appeared to represent an Environmental Risk Management Issue requiring further investigation.

The 2016 Blackstone ESA revealed no evidence of RECs, as defined in ASTM E 1527-13, in connection with the subject property. No further assessment was recommended.

- *Freddie Mac Phase I Environmental Site Assessment, Halstead Station (Vacant Land), 255 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC (Blackstone) for Walker & Dunlop, and dated September 28, 2020 (2020 Blackstone ESA)

The 2020 Blackstone ESA was conducted on the current subject property, which at the time consisted of vacant land. The 2020 Blackstone ESA concluded the subject property was initially developed with a residential structure prior to 1887. By the late 1800s/early 1900s, the subject property was developed with multiple commercial buildings along the northern portion and by 1930, the subject property was developed with commercial and office buildings. Historical uses of the subject property included a laundry business (1896 only), a post office, hotel, restaurants, a theatre, retail storefronts, and offices. Between the 1950s and 1990s, the northwestern portion of the subject property was utilized for surface parking. These structures were demolished in the early 1990s, and the subject property was redeveloped in 2001 with a single-story extension of the present-day south adjoining apartment building and exterior amenities (pool, playground, etc.). The single-story extension contained amenities associated with the south-adjoining apartment building. The former subject property improvements were razed by 2019 and the subject property had been vacant since that time.

The assessment revealed no evidence of RECs, CRECs, or HRECs, as defined by ASTM E1527-13, in connection with the subject property. No further investigation was recommended.

Copies of the previous environmental reports are included in the appendices.

6.8 HISTORICAL INFORMATION CONCLUSIONS

Reasonably ascertainable historical information indicates the subject property was initially developed with a residential structure prior to 1887. By the late 1800s/early 1900s, the subject property was developed with multiple commercial buildings along the northern portion and by 1930, the subject property was developed with commercial and office buildings. Historical uses of the subject property included a laundry business (1896 only), a post office, hotel, restaurants, a theatre, retail storefronts, and offices. Between the 1950s and 1990s, the northwestern portion of the subject property was utilized for surface parking. These structures were demolished in the early-1990s, and the subject property was redeveloped in 2001 with a single-story extension of the present-day south adjoining apartment building and exterior amenities (pool, playground, etc.). The single-story extension contained amenities associated with the south-adjoining apartment building. The former subject property improvements were razed by 2019 and the subject property has been vacant since that time.

The north, east, and south-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a “Chinese laundry” in 1911, and a lighting company between approximately 1931 and 1951 prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures, including a “Chinese laundry” in 1896, and a hotel between approximately 1911 and 1951. The present-day surface parking lot to the adjoining east was constructed in the 1970s and the present-day Ruby Dee Park on Library Green was developed in the 2000s. The south adjoining properties consisted of multiple commercial structures, including a “Chinese laundry” in 1911, and surface parking in the 1950s through 1990s prior to the construction of the present-day apartment building and parking garage in 2001. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

The subject property and adjoining properties were identified with retail laundry or dry cleaning operations in the late 1890s and early 1900s. The use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. These facilities are not identified on any databases indicative of releases or cleanup actions. Based on the era of operation, absence of reported releases, and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities is not considered a REC.

No significant use, treatment, storage, disposal, or generation of hazardous or petroleum products associated with the historical subject property and adjoining use was identified as a result of the review of the historical information.

No RECs were identified as a result of the review of the historical information.

7 ENVIRONMENTAL DATABASE SEARCH AND REVIEW

EDR provided Blackstone a search report of federal, state, local, tribal, and proprietary environmental databases to determine the environmental regulatory status of the subject property, adjoining facilities, and facilities identified within the specified approximate minimum search distance (AMSD) of the subject property. ASTM Standard E1527-21, Section 8.2.1 establishes the distance from the subject property that each database is searched. S*tandard federal, state, and tribal databases* searched, and the search distances specified for each database are summarized as follows:

STANDARD ENVIRONMENTAL RECORD SOURCES

Federal Databases	***Search Distance***
NPL: National Priority List (Superfund) Sites	1.0 mile
Proposed NPL: Proposed National Priority List Sites	1.0 mile
Delisted NPL: National Priority List Deletions	0.5 mile
CERCLA No Further Remedial Action Planned (NFRAP) Sites	0.5 mile
NPL Liens: Federal Superfund Liens	Subject Property only
FEDERAL FACILITY: Federal Facility Site Information Listing	1.0 mile
SEMS: Superfund Enterprise Management System	0.5 mile
SEMS-ARCHIVE: Superfund Enterprise Management System Archive	0.5 mile
RCRA CORRACTS: Resource Conservation and Recovery Act - Corrective Action Sites	1.0 mile
RCRA TSDF: RCRA – Treatment, Storage and Disposal Facilities	0.5 mile
RCRA LQGs: RCRA - Large-Quantity Generators	Subject Property and adjoining
RCRA SQGs: RCRA - Small-Quantity Generators	Subject Property and adjoining
RCRA CESQG: RCRA – Conditionally Exempt Small-Quantity Generators	Subject Property and adjoining
US ENG CONTROLS: Engineering Controls Sites List	Subject Property only
US INST CONTROL: Sites with Institutional Controls	Subject Property only
ERNS: Emergency Response Notification System	Subject Property only
State and Tribal Databases	
SHWS: State Hazardous Waste Site/State ”Superfund” Equivalent Sites	1.0 mile
SWF/LF: Solid Waste Facilities & Landfill Sites	0.5 mile
LUST: Leaking Underground Storage Tanks	0.5 mile
LAST: Leaking Aboveground Storage Tanks	0.5 mile
INDIAN LUST: Leaking Underground Storage Tanks on Indian Lands	0.5 mile
UST: Registered Underground Storage Tanks	Subject Property and adjoining
AST: Registered Aboveground Storage Tanks	Subject Property and adjoining

STANDARD ENVIRONMENTAL RECORD SOURCES

INDIAN UST: Registered Underground Storage Tanks on Indian Lands	Subject Property and adjoining
INST CONTROL: Sites with Institutional Controls	Subject Property only
ENG CONTROLS: Sites with Engineering Controls	Subject Property only
VCP: Voluntary Cleanup Program Sites	0.5 mile
INDIAN VCP: Voluntary Cleanup Priority sites on Indian Lands	0.5 mile
BROWNFIELDS: Brownfields Listings	0.5 mile

All federal, state, local, tribal, and proprietary databases searched, the search distances specified for each database, and the results of the environmental database search are provided in the complete database report (*EDR Radius Map*), which is included in the appendices. The database search report also includes the date and a detailed description of each database searched, which include, but are not limited to, the *standard environmental records sources,* as defined in ASTM Standard E1527-21.

7.1 FEDERAL, STATE, LOCAL, TRIBAL, AND PROPRIETARY DATABASES

A review of the databases included in the *EDR Radius Map* has been performed. Please refer to the *EDR Radius Map*, included in the appendices, for a complete list of the properties included on the databases within the required AMSD. The summary below includes database listings, if present, associated with the subject property and adjoining properties, as well as any additional property/listing within the AMSD that is deemed by the *environmental professional* to be at a distance or status that presents a higher potential risk for environmental concerns to the subject property and requires discussion:

SUBJECT PROPERTY

Not listed

ADJOINING OR FACILITIES IN CLOSE PROXIMITY

The south adjoining property, identified as Office Building (8-10 Railroad Place) and "UST" (Memorial Highway and Huguenot Street), is located in crossgradient direction based on inferred groundwater flow and is identified on the Spills database. Review of the available Spills information indicates that a spill was reported on November 28, 1990, pertaining to a release of gasoline from an underground storage tank (UST) that appeared to be leaking. The cleanup work was identified as having met standard, and the case was issued regulatory closure on May 8, 1991. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spill Incidents Database confirmed that the case has been issued regulatory closure. In addition, another spill was reported on February 4, 2000, pertaining to the discovery of impacted soils during the removal of a UST. The cleanup work was identified as having met standard, and the case was issued regulatory closure on April 4, 2000. Review of information on the NYSDEC Spill Incidents Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the cases were closed, and that the property has since been redeveloped with a high-rise apartment/parking garage that required significant excavation activities, these listings are not considered a REC.

In addition, the south adjoining property is listed as Sound Cleaners (63 Memorial Highway) and identified on the EDR Historical Cleaners and Drycleaners databases. The property address is identified as Sound Cleaners between 2007 and 2014. The EDR Historical Cleaners database is a proprietary database compiled exclusively from EDRs internal review of historical business directories and names potentially associated with dry cleaning related businesses, and is not indicative of a confirmed business location or operation. This former tenant at the south adjoining property is not identified on any additional databases indicative of the generation or disposal of hazardous wastes typically associated with an active dry cleaning facility. It was reported that this former facility only operated as a drop off/pick up location, and no dry cleaning was performed on-site. As such, these listings are not considered a REC.

Metro North Tracks/Metro North Train Station is located to the adjoining west of the subject property in an upgradient direction based on inferred groundwater flow. This property is identified on the Spills databases for two release incidents. In July 1989, a small amount of PCB oil was spilled from a punctured transformer. Additionally, In October 2003, a spill was reported between two tracks. Cleanups were completed and the two spills were issued regulatory closure. Based on the nature of the incidents and the current regulatory status, the database listings at the west adjoining property are not considered a REC.

North Brook Realty Associates (270 North Avenue, Suite 200) is located to the adjoining north of the subject property in a crossgradient direction based on inferred groundwater flow. This property is listed on the UST database for having a 15,000-gallon fuel oil UST currently in service at the property. No violations or release incidents have been reported. Based on the regulatory status, this listing is not considered a REC.

Numerous Con Edison utility vaults and manholes are located beneath the streets or sidewalks in the public right of way adjoining the subject property, which are listed in the RCRA NonGen/NLR, RCRA-LQG, Manifest, FINDS, ECHO, and Spills database. The spill incidents have been granted closure by NYSDEC. Based on the nature of these listings, closed regulatory status, and Con Edison ownership, these listings are not considered a REC.

NON-ADJOINING FACILITIES WITHIN APPROXIMATE MINIMUM SEARCH DISTANCE

As detailed in the EDR Report, several other facilities on various databases are within the ASTM E1527-21 Approximate Minimum Search Distance (AMSD). Based on factors such as distance to the subject property, topography, media affected (surface water, soil, soil vapor, groundwater, or air), depth to groundwater, anticipated and reported groundwater flow direction away from the subject property, hydrological separation, and/or a “Closed Out” and/or “No Further Action (NFA)” regulatory status, these non-adjoining facilities within the AMSD are unlikely to have current or former releases of hazardous substances and/or petroleum products that could migrate to the subject property and are not considered RECs.

7.2 UNMAPPABLE FACILITIES

Due to inadequate address information or other erroneous facility information, EDR may not be able to plot certain facilities listed in the environmental databases on the radius map but includes the facilities in the EDR Report’s unmappable facility summary. Blackstone reviewed this summary to determine if any of the listed facilities include or adjoin the subject property. The unmappable facility listings are summarized as follows:

SUBJECT PROPERTY:
Not listed

ADJOINING FACILITIES:
None listed

7.3 VAPOR ENCROACHMENT SCREENING

Blackstone performed a Tier 1 Vapor Encroachment Screening in accordance with ASTM E 2600-15, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*. The objective of Tier 1 screening is to determine if a Vapor Encroachment Condition (VEC) exists in connection with the subject property. Tier 1 screening is a non-numeric evaluation that considers available information for the subject property and nearby properties from historical sources, government records, and other resources that are practically reviewable and typically reviewed as part of a Phase I ESA. Based on the findings of the Phase I ESA and application of the Tier 1 screening criteria, a VEC does not exist at the subject property and no further investigation of vapor encroachment is recommended.

7.4 AFFIRMATION

The conclusions Blackstone draws from the EDR report are limited to the accuracy of that report. To the extent possible, Blackstone used field observations to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the subject property. The database reviewed is sufficiently complete and current to be used as a source to satisfy the regulatory database requirements outlined in ASTM Standard E1527-21.

7.5 ENVIRONMENTAL DATABASE SEARCH AND REVIEW CONCLUSIONS

Based on Blackstone's review of the EDR database report, no regulatory file reviews are warranted. No RECs were identified as a result of the environmental database search and review.

8 SUBJECT PROPERTY INSPECTION

Name of Inspector: Lauren Beyrent
Date of Subject Property Inspection: May 24, 2022

SUBJECT PROPERTY REPRESENTATIVE(S)

Name	*Title or Association with Subject Property*	*Years Associated with Subject Property*
N/A		

The subject property inspection consisted of a walkover of the subject property perimeter and exterior subject property areas. Furthermore, during the subject property inspection, Blackstone did not inspect inaccessible areas of the subject property including under manholes or within the storage trailer. The adjoining properties were visually observed from curbside without being entered. Blackstone has no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

8.1 UNDERGROUND STORAGE TANKS (USTS)

Number of USTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
None					No

Blackstone identified no physical evidence of current or former USTs during the subject property inspection.

8.2 ABOVEGROUND STORAGE TANKS (ASTS)

Number of ASTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
None					No

Blackstone identified no physical evidence of current or former ASTs during the subject property inspection.

8.3 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS

The following section describes chemical and petroleum storage at the subject property (i.e., drums, totes, and intermediate bulk containers). This section includes the chemical and petroleum storage containers

observed (both in connection with the subject property use and not in connection with the subject property use (if observed)). Where applicable, all bulk fixed chemical and petroleum product storage (such as USTs and/or ASTs) is discussed in Sections 8.1 and 8.2.

Chemical or Material	*Use*	*Container Type*	*Location*	*REC*
None				No

Blackstone identified significant use, treatment, storage, or generation of hazardous or petroleum products.

8.4 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS WASTES

Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

Blackstone identified no physical evidence of on-site hazardous waste generation, storage, or disposal during the subject property inspection.

8.5 NON-HAZARDOUS WASTES

Non-Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

Blackstone identified no physical evidence of on-site non-hazardous waste disposal during the subject property inspection.

8.6 POLYCHLORINATED BIPHENYLS (PCBS)

PCBs can be present in coolants or lubricating oils used in older electrical transformers, hydraulic systems, and other similar equipment. The 1976 Toxic Substances Control Act (TSCA) extended regulatory control over the use of PCBs to the United States Environmental Protection Agency (USEPA). In November 1979, the USEPA generally prohibited the domestic manufacture of PCBs in electromagnets, transformers, and heat-transfer and hydraulic equipment. Blackstone did not identify possible PCB-containing equipment at the subject property.

8.7 WASTEWATER DISCHARGES

Type	*Generated By*	*Discharged To*	*Status/Notes*	*REC*
None				No

Blackstone identified no physical evidence of septic systems, cesspools, clarifiers, or oil/water separators during the subject property inspection.

8.8 STORMWATER DISCHARGES

Discharged From	*Discharged To*	*Status/Notes*	*REC*
Exterior subject property surfaces	Surface gradient to adjoining public right of ways	None	No

Blackstone identified no on-site stormwater retention ponds during the subject property inspection.

8.9 PITS, PONDS, AND LAGOONS (ON-SITE PROCESS WATER DISCHARGE)

Type	*Contents*	*Location*	*Status/Notes*	*REC*
None				No

Blackstone identified no pits, ponds, or lagoons used for process water discharge during the subject property inspection.

8.10 WELLS

Type	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no physical evidence of groundwater monitoring wells, dry wells, injection wells, extraction wells, vapor wells, groundwater production wells, abandoned wells, or other wells during the subject property inspection.

8.11 UNDERGROUND PRODUCT PIPELINES

Type	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no physical evidence of underground product pipelines carrying petroleum or other hazardous substances during the subject property inspection.

8.12 STRONG, PUNGENT, OR NOXIOUS ODORS

Odors	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no strong, pungent, or noxious odors indicative of environmental concerns during the subject property inspection.

8.13 POOLS OF LIQUID

Pools of Liquid	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no pools or sumps containing liquids indicative of environmental concerns during the subject property inspection.

8.14 STRESSED VEGETATION OR STAINED SURFACES

Stressed Vegetation or Stained Surfaces	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no stained soils or stressed vegetation during the subject property inspection.

8.15 STAINS OR CORROSION ON FLOORS, WALLS, OR CEILINGS

Stains or corrosion on floors, walls, or ceilings	*Location*	*Status/Notes*	*REC*
None			No

Blackstone identified no stains or corrosion on floors, walls, or ceilings during the subject property inspection.

8.16 SUBJECT PROPERTY INSPECTION CONCLUSIONS

No evidence of RECs was identified in connection with the subject property as a result of the subject property inspection.

9 ASTM NON-SCOPE CONSIDERATIONS

Blackstone performed the following client-specific activities to identify ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) in addition to the ASTM requirements and as required per the Agreement.

9.1 ASBESTOS-CONTAINING MATERIALS (ACM)

No structures are currently on the subject property and no suspect ACM was observed. As such, sampling was not required, and no further evaluation is recommended.

9.2 LEAD-BASED PAINT (LBP)

No structures are currently on the subject property and no suspect LBP was observed. As such, sampling was not required, and no further evaluation is recommended.

9.3 RADON GAS

A review of records regarding radon concentrations in Westchester County, New York, was conducted to determine if concentrations of radon in the general area of the subject property are within the USEPA guidelines. The USEPA uses a continuous exposure level of 4.0 pCi/L (picoCuries per liter of air) or greater as a guidance level at which further evaluation and potential remedial actions are recommended.

According to USEPA Office of Radiation and Indoor Air information/mapping, the subject property is located within a Radon Zone Level 3. This zone has a predicted average indoor radon gas screening level less than 2.0 pCi/L, which is within USEPA guidance levels.

Considering there are no permanent structures currently located on the subject property and the subject property's location within Radon Zone Level 3, no further evaluation is recommended at this time.

9.4 APPARENT MOLD GROWTH (AMG)

No structures are currently on the subject property and no AMG was observed. As such, no further evaluation is recommended.

9.5 DRINKING WATER QUALITY

Although not currently provided, United Water New York provides drinking water to the surrounding area. The United Water New York/Suez *Annual Water Quality Report for 2021* (the most recent report available

for review) indicates the municipal water system meets the requirements as established by the USEPA, state, and local authorities for drinking water quality, including lead content. As such, no further investigation of drinking water quality is recommended.

9.6 AIR EMISSIONS

Regulated Emissions Source	*Discharged To*	*Potential Impacts*	*Status/Notes*	*REC*
None				No

At the time of the subject property inspection, no permitted discharges to air were identified for the subject property.

9.7 WETLANDS


As defined by the USEPA and U.S. Army Corps of Engineers (USACE), wetlands are "those areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions."

Wetlands possess three essential characteristics: (1) hydrophytic vegetation; (2) hydric soils; and (3) hydrology. All three characteristics must be prevalent to document an area as a jurisdictional wetland. The following summarizes information Blackstone obtained regarding the potential presence of wetlands at the subject property:

Information Source	*Findings*
National Wetlands Inventory (NWI) on-line Wetland Mapper at https://www.fws.gov/wetlands/data/Mapper.html	No mapped federal wetlands are located at the subject property.
Field observations	No vegetation or ponded areas that are characteristic of wetlands were observed at the subject property.

10 CONCLUSIONS AND RECOMMENDATIONS

Blackstone performed a Phase I ESA of the subject property in conformance with the scope and limitations of ASTM Standard Practice E1527-21, the regulations at 40 CFR Part 312, and the May 13, 2022, proposal (Agreement) between Khosla Capital LLC and Blackstone. Any exceptions to, or deletions from, this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no *recognized environmental conditions* (*RECs*), *controlled recognized environmental conditions (CRECs),* or *significant data gaps* in connection with the subject property. No further investigation is recommended.



Project No. KHOSNJ001.02

Halstead Station (Vacant Lannd)
New Rochelle, Westchester County, New York

Subject Property Location Map

(USGS Mount Vernon, New York Topographic Map, 2019)

N
W E
S

BLACKSTONE CONSULTING LLC | A Rimkus Company



Project No. KHOSNJ001.02

Halstead Station (Vacant Land)
New Rochelle, Westchester County, New York

Subject Property Plan

(Approximate Scale Shown)

N
W E
S

BLACKSTONE CONSULTING LLC | A Rimkus Company



PHOTOGRAPH 1
Aerial view of the subject property



PHOTOGRAPH 2
View of the subject property from the southern elevation



PHOTOGRAPH 3
View of the trailer and construction supplies stored on the subject property



PHOTOGRAPH 4
View of the subject property from the northeastern elevation



PHOTOGRAPH 5
View of the north adjoining property



PHOTOGRAPH 6
View of east adjoining property



PHOTOGRAPH 7
View of the south adjoining property



PHOTOGRAPH 8
View of the west adjoining property

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6986656.3

May 19, 2022

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

05/19/22

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6986656.3

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Julie Brunner

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Blackstone Consulting, LLC were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 8FCF-4DCC-A90F

PO # NA

Project Halstead Station

Maps Provided:

2003	1951
1996	1942
1995	1931
1994	1911
1993	1903
1992	1896
1991	1892
1990	1887

Sanborn® Library search results

Certification #: 8FCF-4DCC-A90F

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Blackstone Consulting, LLC (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets


Volume 1, Sheet 2
2003


Volume 1, Sheet 3
2003


Volume 1, Sheet 7
2003



Volume 1, Sheet 8
2003

1996 Source Sheets


Volume 1, Sheet 2
1996


Volume 1, Sheet 3
1996


Volume 1, Sheet 7
1996


Volume 1, Sheet 8
1996

1995 Source Sheets


Volume 1, Sheet 2
1995


Volume 1, Sheet 3
1995



Volume 1, Sheet 7
1995



Volume 1, Sheet 8
1995

1994 Source Sheets


Volume 1, Sheet 2
1994


Volume 1, Sheet 3
1994


Volume 1, Sheet 7
1994


Volume 1, Sheet 8
1994

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1993 Source Sheets


Volume 1, Sheet 7
1993


Volume 1, Sheet 8
1993



Volume 1, Sheet 2
1993


Volume 1, Sheet 3
1993

1992 Source Sheets


Volume 1, Sheet 2
1992


Volume 1, Sheet 3
1992


Volume 1, Sheet 7
1992



Volume 1, Sheet 8
1992

1991 Source Sheets


Volume 1, Sheet 2
1991


Volume 1, Sheet 3
1991



Volume 1, Sheet 7
1991


Volume 1, Sheet 8
1991

1990 Source Sheets


Volume 1, Sheet 3
1990


Volume 1, Sheet 7
1990


Volume 1, Sheet 8
1990



Volume 1, Sheet 2
1990

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1951 Source Sheets


Volume 1, Sheet 2
1951


Volume 1, Sheet 3
1951


Volume 1, Sheet 7
1951



Volume 1, Sheet 8
1951

1942 Source Sheets



Volume 1, Sheet 6
1942


Volume 1, Sheet 7
1942

1931 Source Sheets


Volume 1, Sheet 2
1931



Volume 1, Sheet 3
1931


Volume 1, Sheet 7
1931


Volume 1, Sheet 8
1931

1911 Source Sheets


Volume 1, Sheet 49
1911


Volume 1, Sheet 54
1911


Volume 1, Sheet 55
1911



Volume 1, Sheet 65
1911


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1903 Source Sheets



Volume 1, Sheet 5
1903


Volume 1, Sheet 6
1903


Volume 1, Sheet 9
1903


Volume 1, Sheet 10
1903

1896 Source Sheets


Volume 1, Sheet 3
1896



Volume 1, Sheet 4
1896


Volume 1, Sheet 7
1896


Volume 1, Sheet 8
1896

1892 Source Sheets


Volume 1, Sheet 10
1892


Volume 1, Sheet 11
1892



Volume 1, Sheet 9
1892


Volume 1, Sheet 12
1892

1887 Source Sheets



Volume 1, Sheet 2
1887


Volume 1, Sheet 4
1887


Volume 1, Sheet 5
1887

Certified Sanborn® Map

2003





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 2
Volume 1, Sheet 8
Volume 1, Sheet 7

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




Certification #8FCF-4DCC-A90F

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 2
Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1942

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 7
Volume 1, Sheet 6

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1931

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1911

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 65
Volume 1, Sheet 55
Volume 1, Sheet 54
Volume 1, Sheet 49

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8FCF-4DCC-A90F

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1903

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 10
Volume 1, Sheet 9
Volume 1, Sheet 6
Volume 1, Sheet 5

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1896

THE SANBORN LIBRARY LLC
Sanborn
SEAL OF AUTHENTICITY

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 4
Volume 1, Sheet 3

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #	8FCF-4DCC-A90F
Copyright	1892

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 12
Volume 1, Sheet 9
Volume 1, Sheet 11
Volume 1, Sheet 10

0 Feet 150 300 600


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6986656.3
Order Date:	05/19/2022
Certification #:	8FCF-4DCC-A90F
Copyright	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 5
Volume 1, Sheet 4
Volume 1, Sheet 2

0 Feet 150 300 600

N

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6986656.8

May 19, 2022

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

05/19/22

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6986656.8

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Julie Brunner

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Flight Date: April 08, 1994	USDA
1985	1"=500'	Flight Date: March 16, 1985	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1974	1"=500'	Flight Date: October 24, 1974	USDA
1966	1"=500'	Flight Date: January 12, 1966	USGS
1961	1"=500'	Flight Date: November 22, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 23, 1954	USGS
1951	1"=500'	Flight Date: April 20, 1951	EDR Proprietary Aerial Viewpoint
1946	1"=500'	Flight Date: January 01, 1946	FirstSearch


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 6986656.8
YEAR: 2017
= 500'
N
EDR




INQUIRY #: 6986656.8

YEAR: 2013

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 2009

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 2006

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1994

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1985

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1980

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1974

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1966

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1961

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1954

= 500'

N

EDR




INQUIRY #: 6986656.8

YEAR: 1951

= 500'

N

EDR



INQUIRY #: 6986656.8

YEAR: 1946

= 500'

N

EDR

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6986656.4

May 19, 2022

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

05/19/22

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6986656.4

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Julie Brunner

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Blackstone Consulting, LLC were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA

Project: Halstead Station

Coordinates:

Latitude:	40.91054 40° 54' 38" North
Longitude:	-73.783836 -73° 47' 2" West
UTM Zone:	Zone 18 North
UTM X Meters:	602420.53
UTM Y Meters:	4529538.14
Elevation:	90.07' above sea level

Maps Provided:

2019	1900
2016	1898
2013	1897
1995	
1979	
1966	
1956	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Mount Vernon
2019
7.5-minute, 24000

2016 Source Sheets




Mount Vernon
2016
7.5-minute, 24000

2013 Source Sheets



Mount Vernon
2013
7.5-minute, 24000

1995 Source Sheets




Mount Vernon
1995
7.5-minute, 24000
Aerial Photo Revised 1977

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets



Mount Vernon
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1966 Source Sheets



Mount Vernon
1966
7.5-minute, 24000
Aerial Photo Revised 1966

1956 Source Sheets



Mount Vernon
1956
7.5-minute, 24000
Aerial Photo Revised 1954

1947 Source Sheets



Mt Vernon
1947
7.5-minute, 24000
Aerial Photo Revised 1941

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets



Harlem
1900
15-minute, 62500

1898 Source Sheets



Harlem
1898
15-minute, 62500

1897 Source Sheets



Harlem
1897
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Mount Vernon, 2019, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

NW N NE
W E
SW S SE

TP, Mount Vernon, 2016, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

Historical Topo Map

1979



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1979, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1966, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1956, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mt Vernon, 1947, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 6986656.5
May 24, 2022

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☑	☑	EDR Digital Archive
2014	☑	☑	EDR Digital Archive
2010	☑	☑	EDR Digital Archive
2005	☑	☑	EDR Digital Archive
2000	☑	☑	EDR Digital Archive
1995	☑	☑	EDR Digital Archive
1992	☑	☑	EDR Digital Archive
1987	☑	☑	Cole Criss-Cross Directory
1982	☑	☑	Cole Criss-Cross Directory
1977	☑	☑	Cole Criss-Cross Directory
1972	☑	☑	Cole Criss-Cross Directory
1964	☑	☑	Cole Criss-Cross Directory
	☑	☑	Polk's City Directory

FINDINGS

TARGET PROPERTY STREET

255 Huguenot Street
New Rochelle, NY 10801

Year	*CD Image*	*Source*
HUGUENOT ST		
2017	pg A2	EDR Digital Archive
2014	pg A15	EDR Digital Archive
2010	pg A28	EDR Digital Archive
2005	pg A38	EDR Digital Archive
2000	pg A49	EDR Digital Archive
1995	pg A53	EDR Digital Archive
1992	pg A57	EDR Digital Archive
1987	pg A62	Cole Criss-Cross Directory
1982	pg A66	Cole Criss-Cross Directory
1977	pg A69	Cole Criss-Cross Directory
1972	pg A72	Cole Criss-Cross Directory
1964	pg A76	Polk's City Directory

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
DIVISION ST			
2017	pg. A1	EDR Digital Archive	
2014	pg. A13	EDR Digital Archive	
2010	pg. A26	EDR Digital Archive	
2005	pg. A37	EDR Digital Archive	
2000	pg. A48	EDR Digital Archive	
1995	pg. A52	EDR Digital Archive	
1992	pg. A55	EDR Digital Archive	
1987	pg. A60	Cole Criss-Cross Directory	
1987	pg. A61	Cole Criss-Cross Directory	
1982	pg. A64	Cole Criss-Cross Directory	
1982	pg. A65	Cole Criss-Cross Directory	
1977	pg. A68	Cole Criss-Cross Directory	
1972	pg. A71	Cole Criss-Cross Directory	
1964	pg. A74	Polk's City Directory	
1964	pg. A75	Polk's City Directory	
SHEARWOOD PL			
2017	-	EDR Digital Archive	Target and Adjoining not listed in Source
2014	-	EDR Digital Archive	Target and Adjoining not listed in Source
2010	-	EDR Digital Archive	Target and Adjoining not listed in Source
2005	-	EDR Digital Archive	Target and Adjoining not listed in Source
2000	-	EDR Digital Archive	Target and Adjoining not listed in Source
1995	-	EDR Digital Archive	Target and Adjoining not listed in Source
1992	-	EDR Digital Archive	Target and Adjoining not listed in Source
1987	-	Cole Criss-Cross Directory	Street not listed in Source
1982	-	Cole Criss-Cross Directory	Street not listed in Source
1977	-	Cole Criss-Cross Directory	Street not listed in Source
1972	-	Cole Criss-Cross Directory	Street not listed in Source
1964	-	Cole Criss-Cross Directory	Street not listed in Source

FINDINGS

Year	*CD Image*	*Source*	
STATION PLZ			
2017	pg. A12	EDR Digital Archive	
2014	pg. A25	EDR Digital Archive	
2010	pg. A36	EDR Digital Archive	
2005	pg. A47	EDR Digital Archive	
2000	pg. A51	EDR Digital Archive	
1995	pg. A54	EDR Digital Archive	
1992	pg. A59	EDR Digital Archive	
1987	pg. A63	Cole Criss-Cross Directory	
1982	pg. A67	Cole Criss-Cross Directory	
1977	pg. A70	Cole Criss-Cross Directory	
1972	pg. A73	Cole Criss-Cross Directory	
1964	-	Polk's City Directory	Street not listed in Source

City Directory Images

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 2017

2	BORAM INC
	OQUENDO ZASTARILLA
	SUSAN NAGIB SUSA S DESIGNS
5	ADVANCED AESTHETIC SOLUTIONS
	PELORUS NAIL SPA
	SYNERGY LASER SOLUTION LLC
6	BEST BAY LOCKSMITH
	BSD LOCKSMITH OF WOLFS
	DIVISION PLUMBING & HEATING
	FRESH TACO
	NEW ROCHELLES LOCKSMITH
7	FREDS BEAUTY SALON
8	RENU BEAUTY SALON
9	AWA AFRICAN HAIR BRAIDING
	CEPEDA, FAUSTO A
	GALLEGO, AMANDA
	MAJOR BARGAIN
10	BASE ONE TECHNOLOGY
	DAILY DEALS CORP
	TIMELESS TIMELESS
	USELL GLOBAL
	VIRTUAL MONTESSOURI
11	INTIMA FASHION
	TRIPLE A MINIMART
12	FIFTH AVE TANNING SPA
15	FEGO, KELLY F
	YEUNG, PAUL K
16	BRICKYARD BISTRO
	LEFT OF CENTER
	LEFT OF CENTRE
18	BARCELONA CAFE INC
	KAFFEINE EXPRESSO BAR
	TEAM LOCKSMITH CO
20	NEW ROCHELLE JEWELERS
	NEW ROCHELLE JEWELERS LLC
22	POSTO 22
23	ALFREDOS PIZZERIA LLC
	SAFELITE LOCK & SAFE SERVICE
	SHIRLEYS CONSTRUCTION COMP
24	AMBER HAIR DESIGN
	DINO & DAN BARBER SHOP
27	ENGLISH, LORRAINE
30	COROMANDEL
37	JUST FUNKI
38	NEW ROCHELLE IRISH BENEVOLENT SOC
40	ATTILIOS BARBER SHOP
41	DACUTT HAIR STYLE
	EVERYDAY LOCKSMITH
112	RELIG
120	ST GABRIELS CHURCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2017

175 ADAMS, JOSHUA
ADOLPH, GERALD S
ALBERGA, ROBERT F
ARMIENTO, BRITTANY
ASFD, TERSSEA
AUFFARTH, NICOLE J
BABATUNDE, OSOTIMEHIN
BATRA, RAKESH
BERG, WOLFGANG
BRENES, JULISSA
BROWN, TRENTON
CABRERA, T
CAMA, REGINA
CASTRO-PEREZ, EDITH A
CESPEDES, DIANA M
CHAT, HANS
CHESTNUT, TAMISHA M
CHOI, KENNETH S
COCKBURN, ADORA A
COLE, DONALD
CROZIER, JOHN B
CULLEN, KIRSTEN A
CYPRESS HILLS MANAGEMENT INC
DABBRACCIO, THERESA
DEBBAGH, AZIZ
DEMATTEIS, NICK A
DOE, YASHRRIA
DORIA, MIKE J
DORITY, KATHY D
FELIX, ELIZABETH
FERRARO, THERESA
FERREIRA, ANGELA
FIERSTEIN, NAT P
FISHER, MICHAEL L
FLEURANTIN, RALPH
FONTENOT, FRANCESCA E
FRANKENBERGER, BURKHARD H
FREYBERGER, AMI J
FUENTES, FERNANDO
GALINDO, EDIXON A
GAMBLE, KENNETH E
GBK HOLDINGS LLC
GENTILE, JAMES
GERMAN, ELVIN
GOODFRIEND SELF STORAGE
GRAHAM, LEWIS
GRANADY, LYNDA R
GREENBERG, DAVID J
HADAVI, SHAWA
HAMER, SYLVIA I

HUGUENOT ST 2017 (Cont'd)

175 HARMITT, NICOLA A
HEADLEY, DARRYL G
HECKARD, LASHONTAE V
HERZ, ERIK I
HOCH, ETHAN
HSUEH, ERIC C
IACHETTA, ANTONIO
JENNINGS, BRANDON
JLAYER, ZAHRA
JOHNSON, CHRISTOPHER
KAPP, DANA
KENNEY, KAREN L
KIM, SEOUNG D
KLEIN, LEONARD S
KOOTTALA, SASEEDARAN K
KROOP, MARK A
LAGANA, ELIZABETH
LAVALLE-VALDES, ROBERTO
LEE, DANIEL
LEE, DAVID D
LEPORE, ALPHONSE E
LERMAN, HANNAH
LEVINE, JOSHUAH
LOMBARDI, LINDA C
LUIS, VICTOR
MAIER, DONNA
MARANZANO, GIANCARLO
MARCOPOULOS, STEFANOS Y
MARTIN, JOHN A
MCDOWELL, FENELLA S
MCLEAN, AMANDA
MCTIGUE, MICHAEL G
MILLER, ALEX
MORGAN, DANIEL
MULHERN, RICHARD
NEW YORK CITY SPORTS CLUB AT NEW ROC
NEW YORK SPORTS CLUBS
NICCHIA, BIAGIO M
NOSCHESE, JOHN P
NYSC NEW ROCHELLE
OCONNOR, CHRISTOPHER J
OROURKE, SEAN
ORTIZ, JOSE
PARK, AUSTIN
PATEL, MINAL
PATTON, LYNNE
PHUPAKDI, WIPANEE
PRADA, SUKPOKKIJ
RANDONE, JOHN
REAVES, LISA R

HUGUENOT ST 2017 (Cont'd)

175	REGUS
	RIAD, MIRIAM
	RIVA, SUZANNE
	RONAN, DAN N
	RONG, WNAG
	ROOT, GJ
	RUSSO, JENNA
	SANET, ALIA
	SANTOS, ALEXIS L
	SCHMID, KAROLINE M
	SHABAZZ, MALCOLM
	SHINER, ANDY F
	SMITH, ALFRED
	SMITH, KENNETH M
	SOUTHWELL, RUDOLPH U
	STORCK, BRIAN R
	TAN, CHEE L
	TANZOLA, PATRICK
	TECE, BASAK R
	THE LANE CONSTRUCTION
	THOMAS, JOHNNY T
	TORGALKAR, SHAILA
	TRUMP PLAZA AT NEW ROCHELLE
	TUPILI, LAKSHMI
	UPPUANDURI, KRISHNA
	VELEZ, MELISSA
	VONBRAUN, ALEX
	WAITT, LORNA
	WALSH, COLLIN J
	WATT, LOUISE
	WILLIAMS, GERALDINE D
	WILSON, PETER A
	WISE, BENJAMIN J
	WYNTER, OVRAL J
	ZHANG, FAN
	ZHENG, JIE
	ZIADAT, KAMAL J
181	TEXAS ROADHOUSE
245	KINEXUS GROUP
255	ABREU, LISMELL
	AGUILA, MELISSA
	AHN, MICHAEL
	ALAM, SHARFUL
	ALBERT, ANTON
	ALLEYNE, FELICIA
	AREVALO, CHRISTINA
	ATIENO, SARAH D
	ATOLAGBE, OLUWATOSIN A
	BABKA, SAMADI
	BALKCOM, NATASHA

HUGUENOT ST 2017 (Cont'd)

255 BARNES, ARNOLD L
BAUMERT, EMILY
BHARGAVA, TANUJ
BISHOP, ASHLEY
BLAZQUEZ, HECTOR G
BRAMBILLA, VANESSA
BRIGHT, MICHAEL
BROWN, AMBRAI
BROWN, JAMES D
BRUDERLE, MATT A
BRYAN, SIMONE O
BYA, MI
CARDONE, VICKY
CARMOEGA, NICOLE E
CARPENTER, GEOFFREY C
CEDAR CONSTRUCTION
CELIK, SELDA
CEPEDA, IVETTE
CHAUHAN, KARAN
CHIUSANO, MARK J
CINTRON, MELISSA L
CLARK, SILVERLANE G
CLAVIJO, JULIETH
COLLINS, JASON J
COWART, TIMMY L
COYNE, JENNIFER L
CREMAULT, CHRISTOPHER J
CRUTE, DARIEN
DADOYAN, TALINE A
DAMICO, ANTHONY J
DANIELS, CYNARA E
DAS, SUMANTA
DAVIDSON, PATRICK
DAVIS, VALERIE A
DECORNEZ, STEPHANE
DELAFIELD, WALTER B
DENLEY, SCOTT L
DEVINE, CAITLIN
DEWITT, ANDREA L
DIAMOND, JESSICA S
DIAZ, DEBBIE
DIGERONIMO, KATIE
DITKOFF, MICHALE B
DONCH, MARY A
DONOHUE, JOHN J
DPC TECH
DUBE, RAQUEL
DUNEVITZ, BENJAMIN J
DUNN, SARAH L
EDWARDS, BRYAN S

HUGUENOT ST 2017 (Cont'd)

255	EDWARDS, MARISA K
	FAIRCLOUGH, DUNJA M
	FAN, REBECCA
	FEENEY, JESSE J
	FENSTER, TILLIE
	FEUERSTEIN, JOHN D
	FICHTALI, ADI
	FISCHER, ENID
	FITZPATRICK, CHRISTOPHER R
	FONDERSON, ELEANOR
	FOSTER, JASMINE
	FOUNTAIN, KIANI S
	FREYNE, SEAMUS
	FULGENCIO, FRANCES
	FULTON, MARSHALL R
	GABAY, VICTOR H
	GABRI, AMITOZ
	GABRIEL, CALVIN
	GALATI, SUZANNE
	GARCIA, RAFAEL A
	GARRETT, GINGER E
	GENESIS
	GILBERT, SARA
	GONZALEZ, RAUL
	GORDON, KARA V
	GRAHAM, TERESA L
	GRANT, JULIANNA M
	GRULLON, YADIRA
	GUINEY, DANIEL
	HABER, MARK N
	HAHN, ELISA D
	HALPIN, JOHN T
	HAMMETT, STEVE C
	HENLEY, STEVEN
	HUGH, ALLISON Y
	HUNT, KEVIN L
	HUNTER, KEITH L
	IVANOV, VALENTIN L
	IVORY, RICKY R
	JACKSON, ROBERTA J
	JACOBS, ELIZABETH A
	JACOBS, GEORGE L
	JOHNSON, TREVOR
	JONES, SHAVONNE E
	JOSEPH, ANTONIO J
	JUDICE, KRISTINA D
	KAMARA, FACHIA
	KANE, JESSICA
	KAPLAN, GARY U
	KESSLER, BENJAMIN J

HUGUENOT ST 2017 (Cont'd)

255	KINGBROWN, KRISTIE
	KLONSKY, DAVID H
	KNOX, DAWN J
	KOBLICK, SARAH
	KONADU, NANA S
	KONTOPIDIS, IOANNIS
	KONYANGO, JACKSON
	KRASELNIK, BERNARDO M
	KUBECKA, FALLON J
	KYEMBE, JULIA M
	LA ROCHELLE APARTMENTS
	LAKSHMAN, NARAYAN
	LANE, LAWRENCE G
	LARANGEIRO, MIGUEL
	LEBOWITZ, JANE
	LEE, WILLIAM R
	LEJA, JAN L
	LEWIS, MILES M
	LIFLEUR, INGRID
	LING, JIN
	LOVALLO, SUSAN L
	LYDE, MATTHEW S
	LYNCH, CAROLYN R
	MACEDO, COLLEEN
	MADUHU, ELLEN
	MAGISTRADO, JERNEL
	MAK, IRLEN
	MAKITA, KAZUAKI
	MALCOLM, FELICIA
	MARINHO, FRANCISCA
	MARRON, NIKKI
	MARTINO, MARCK P
	MATIAS, GENISE
	MAYNARD, KAREN
	MAZUCCI, THOMAS R
	MCCORMICK, RICHARD H
	METRO MARKET
	MGAWE, SALMA
	MILLER, BRYAN A
	MILLER, NATHAN J
	MINGO, PAULA T
	MOAVENI, HOUTAN
	MORAN, MEGAN E
	MORENO, GLENDA E
	MORRIS, JASON Z
	MOSK, GARY S
	MOUKHTAR, LAILA A
	MRAZ, SCOTT E
	MUNDY, MARINE A
	MUSSER, DOUG

HUGUENOT ST 2017 (Cont'd)

255	MUZZIO, CARLOS O
	NASSON, NATALIA J
	NAZIM, KAMRAN
	NIKWIGIZE, ANDRE
	NIVEN, POLLY F
	NKWAIN, STANISLAUS
	NOONAN, CHARLES
	NUDELMAN, GARY M
	OFFERMAN, SUZANNE I
	OHARA, MICHAEL P
	OSHAUGHNESSY, MATTHEW J
	OSINLOYE, SHANE
	OTTLEY, ANNETTE
	PARDES, GISSELT
	PARMAR, RAGHAVKUMAR
	PATEL, VIPULKUMAR
	PAVEGLIO, ANTHONY P
	PERRY, JAMES
	PHILLIPS, NADIA
	PHILLIPS, VIRGINIA
	PICKETT, ANGELA
	PICONE, KEVIN W
	PISANO, BARBARA
	PITT, CECELIA F
	POLYCARPE, MYREILLE P
	POWELL, DIONE
	PUCHALSKY, JEFF
	QIN, JIDONG
	QUILIO, GLORIA
	RAFF, JOSHUA A
	RAMSEWAK, KENNETH B
	REDMOND, EILEEN
	REHG, PHILLIP A
	REILLY, COLLEEN C
	REINOSO, YOKASTA
	REIS, ADEILSON
	RESMI, SULEKHA
	RFN LLC
	RHETT, GEOFFREY V
	RIGANO, DAVID
	ROBERTS, BRUCE J
	ROBERTS, TOYA F
	RODRIGUEZ, MAYRA
	RODRIGUEZ, RAFAEL
	RODRIGUEZ, ROBERTO
	RODRIGUEZ, VINCENT
	ROGERS, SURAYYA
	ROTHENBERG, RUSSELL K
	RUIZ, JEREMIAH G
	RUSSELL, MICHELLE

HUGUENOT ST 2017 (Cont'd)

255 SABIN, MICHAEL
SALE, GREGORY
SARGENT, ALBERT B
SASAKI, MORIFUMI
SATTI, SOLAFA
SCHONAUER, DAVID G
SELBY, MAISHA I
SEPULVEDA, RICHARD L
SHAGA, ABRAHAM B
SIGUNOV, VLADIMIR
SILVERBERG, JOHANNA
SIMO, ELSA
SINATRA, PATRICIA M
SMERKOL, MARCO
SMITH, AMBER N
SMITH, JULIET
SOH, HOOI L
STEELE, TAMMY B
SUNA, JONATHAN B
SUTHERLAND, ALEXANDER B
SUZUKI, MASAKO
TAKAGI, AKIRA
TALL, PAPE
TANOU, KONE
TANTAWY, AHMED K
TESFA, LYDIA
THOMAS, DANA M
THOMPSON, ANYA S
THORNTON, LISA A
TRUBKIN, LEON G
TSUKANOVA, MYROSLAVA
TUPILI, RAJA S
USANDIVARAS, PABLO A
UTZ, THEODORE N
UZUNOVA, GENOVEVA P
VANBRAKLE, JOE
VANCLEAVE, THOMAS
VANHUYSEN, JOSEPH
VARDIN, ERIC
VENKAT, SRIVATHSAN
VEREAU, JORGE S
VERMA, AMIT
VINCENT, BRITTANY
VONAHRENS, DAGNY E
WALDEN-NEWMAN, ANNE
WALKER, MICHAEL D
WALLACE, LAMONT J
WALLOS, ROBERT
WATKINS, LATOYA
WEINER, GEORGE

HUGUENOT ST 2017 (Cont'd)

255	WIDJAJA, WILDIA
	WILLIAMS, PAUL T
	WILLIAMS, TARA K
	WILLIAMS, TIFFANY V
	WILLIAMS, VERONICA A
	WILSON, CLAY S
	YADIRA, G
	YANCEY, MIYUKI K
	YANSANEH, IBRAHIM S
	YAU, CHARLES J
	YEPEZ, RAYMOND
	YOUNG, GERRY
	YUN, SUNG Y
	ZAIN, SAAMI
	ZANFORDINO, CHARLES
	ZELSON, JOSEPH G
	ZHANG, JINGNAN
265	JAVA DREAMS CAFE
	OMNIBUS ENTERPRISES
268	AOC FINE WINES
275	255 HUGUENOT STREET CORP
	275 HUGEUNOT GR
282	SORELL SORELL
296	ANDERSON, DALE C
	HUGUENOT ST FLORIST
	JOSEPH, DORCELUS
	MCLEOD, DEBORAH A
	MORALES, JIMMY
	MORRIS PARK FLORIST
	MUNOZ, SARA
300	IRENES BEAUTY PLUS
	QNIQUES HAIR SOLUTIONS
302	HOUSE OF INK
304	RUBENS TAILOR
306	CASHER, ALBERTO F
	COLBERT, GLEN
	CORONA, JOSE C
	DIXON, FAREED N
	EDWARDS, DAVID B
	ESQUIVEL, GILBERT F
	GARCIA, RAUL
	GOULD, CHRISTINA
	GRAVES, ELIZABETH
	JIMENEZ, ASPIN
	MIRANDA, SHARON D
	NIXON, EDWARD L
	PALMER, HARVEY A
	PEREZ, SHAINA L
	RHETT, LISHA R
	ROYSTER, PHYLLIS A

HUGUENOT ST 2017 (Cont'd)

306	SCHOENBRUN, STUART M
	SUSSMAN, BRIAN H
	TAYLOR, JAMES C
310	MIDWAY GARAGE DOOR & LOCSMITH
	MODERN RESTAURANT
	MODERN RESTAURANT & LOUNGE
	MODERN RESTAURANT & PIZZERIA
311	NEW ROCHELLE 24 7 LOCKSMITH
	TRINITY & PAULS CHURC
	TRINITY COOPERATIVE NURSRY SCHL
	TRINITYST PAULS EPISCOPAL CHURCH
316	MODERN PAINT & HARDWARE
326	EL SABOR DE MI TIERRA RESTAURANT
328	THE LITTLE RANCH
330	EXPRESS DELI
342	A & A ALCOHOL ABUSE & DRUG ADDICTION
	CONSTRUCTION TECHNOLOGY
	HEALTH PLUS
	INNOVENTIVE POWER LLC
	SACCENTES HOUSE OF PRINTING
	SACCENTES HOUSE OF PRINTING DBA SHOP
	ST NERSESS ARMENIAN SEMINARY
	TRICITY OVERHEAD DOOR SVCES
	TRISTATE CARPET & UPHOLSTERY
	VERIZON
347	ALLEN, TREVOR
	BOYD, JEAN
	DAVID FRENCH CATERING
	DESANTO, CHRISTINE
	GOODMAN, EMANUEL G
	HARDING, BERYL A
	HOLTON, HENRY L
	HOLTON, LEWIS
	LAGUERRE, HILDA
	MAULDIN, AUDREY D
	NEWTON, LEWIS M
	SCOTT, MURDELL
	SHEPPY, KIRK D
	VALDOVINOS, MARIA D
	WILLIAMS, TAISHA

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 2017

1 HERTZ
HERTZ CAR RENTAL
LARCHMONT STATION TAXI
LIBERTY LINES TRANSIT
STATION CAFE
24 GREEN TEAM CAB CORP
STATION CAFE

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 2014

2	BORAM INCORPORATED
	OQUENDO ZASTARILLA
	ROLLER, DAUNELL L
	SUSAN NAGIB SUSA S DESIGNS
	TURNER, CHRISTOPHER M
5	ADVANCED AESTHETIC SOLUTIONS
	PELORUS NAIL SPA
	SYNERGY LASER SOLUTION LLC
6	BEST BAY LOCKSMITH
	DIVISION LOCKSMITH
	DIVISON PLUMBING & HEATING
	FRESH TACO
	NEW ROCHELLE SPEEDY LOCKSM
7	FREDS BEAUTY SALON
8	RENU BEAUTY SALON
	SPICE RESTAURANT & LOUNGE
9	AWA AFRICAN HAIR BRAIDING
	CEPEDA, FAUSTO
	GALLEGO, AMANDA
	MAJOR BARGAIN
	RHETT, LISHA R
	SANABRIA, BENJAMIN H
10	BASE ONE TECHNOLOGY
	DAILY DEALS CORPORATION
	GREEN MELONS INCORPORATED
	NEW ROC ALL IN ONE
	THE TRAVELING ADDICT
	TIMELESS TIMELESS
	USELL GLOBAL
11	TRIPLE A MINIMART
12	MODERN SUN TANNING
15	ABEL, JAMES C
	BENJUMEA, CARLO E
	DANS CARPETS COMPANY
	DOMINGUEZ, ROLANDO
	PEREZ, HORACIO
	TAVARES, ROSEMEIRE
	YEUNG, PAUL K
16	LEFT OF CENTER
	LEFT OF CENTRE
18	BARCELONA CAFE INCORPORATED
	KAFFEINE EXPRESSO BAR
	TEAM LOCKSMITH COMPANY
20	NEW ROCHELLE JEWELERS LLC
22	POSTO TWENTY TWO
23	SAFELITE LOCK & SAFE SERVICE
	SHIRLEYS CONSTRUCTION COMP
	TOWN LOCKSMITH
24	DINO & DAN BARBER SHOP
27	BHARUCHA, DELNA

DIVISION ST 2014 (Cont'd)

27	CHO, JEAN F
	FERRARO, FRANK
	FORTIER, MARY P
	GERHARD, AMY E
	KANHAI, MIKE
	KESSEL, CYBIL R
	MATOS, NARCISO
	MERRIWEATHER, ANTHONY
	MONOD, ANNA C
	SALUJA, PRIYA
	SCHAPIRA, DANIEL
	SHIMAO, MATT
	WATANABE, M
30	COROMANDEL
38	NEW ROCHELLE IRISH BENEVOLENT SOCIET
39	CORTEZ, ANTONIO
40	ATTILIOS BARBER SHOP
41	DACUTT HAIR STYLE
	EVERYDAY LOCKSMITH
48	MUNGULA, MARIA
112	RELIG
120	ST GABRIELS CHURCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2014

175	ABOLAHRARI, SABA
	ADOLPH, GERALD S
	AGU, ADAEZE
	ALMODOVAR, CARLOS
	BA, ALEX
	BARBER, EILEEN
	BOOT, MAX
	BOSCO, FRANCIS J
	BOYD, THOMAS C
	BRENES, JULISSA
	BRIMBERG, MARILYN
	BRITO, MERCEDES A
	BROWN, TRENTON
	CABRERA, MARIA T
	CARMOSKY, JANET M
	CHOPAK, IRWIN
	CLANCY, BRENDAN D
	COCKBURN, MARK I
	COHEN, TOMER
	COTTERALL, TERESA C
	CYPRESS HILLS MANAGEMENT
	DABBRACCIO, THERESA
	DEBBAGH, AZIZ
	DOONAN, JON F
	DORITY, KATHY L
	FELKER, BARBARA A
	FERREIRA, ANGELA
	FONTENOT, LESLIE C
	FOULADVANO, MOHAMMAD
	FRANCIS, GARY
	FRANKENBERGER, BURKHARD H
	GAINEY, KRYSTA A
	GAMBLE, KENNETH G
	GONZALEZ, ROBERTO
	GRAHAM, LEWIS
	GRANNIS, KEITH W
	GREENBERG, DAVID J
	GRZANKA, HEATHER E
	HAMER, SYLVIA
	HARMITT, NICOLA A
	HARRIS, SHARON
	HEADLEY, DARRYL G
	HERZ, ERIK I
	HOLLOMAN, ALFONSO L
	HOPPER, PATRICK E
	IACHETTA, ANTONIO
	ILIESCU, NICOLETA
	IVANOVA, JANINE P
	JASON, MARC
	KEARNEY, JOHN A

HUGUENOT ST 2014 (Cont'd)

175 KEITH, GEORGE H
KIM, SEOUNG D
KISSELBACH, DONALD W
KOMINSKL, CHRISTINA M
LAVALLE, TOMOKO K
LEE, JONG G
LEE, PAUL S
LIMJAP, JOSE E
LINDBLOM, PAUL R
LOMBARDI, LINDA C
LUIS, VICTOR
LYNE, GRANADY
MA, TERRENCE P
MAJIMA, SHINGO Y
MAKAROV, ALEXEY A
MARCOPOULOS, STEFANOS Y
MCDOWELL, FENELLA S
MCTIGUE, MICHAEL G
MULHERN, RICHARD
MUNRO, ROBERT
MUSCARELLA, ALEX
NARAYAN, PRITVI
NARLIEV, VASKO N
NICCHIA, BIAGIO
NOSCHESE, JOHN P
NYSC NEW ROCHELLE
OCONNOR, CHRISTOPHER J
ORTIZ, JOSE
OSOTIMEHIN, BABATUNDE
PARK, AUSTIN
PATEL, ATIT R
PATTON, LYNNE
PERDUE, PATRICK F
PEREZ-JOHNSON, ADELIZA P
PHUPAKDI, WIPANEE
PIGNATELLI, CARMELA
PORTANOVA, JOSEPH
PRADA, SUKPOKKIJ
PRUSOCK, DONALD S
QUEEN, MOLLY
RANA, THAKOR C
RANDONE, JOHN
RIAD, MIRIAM
RISHER, PETER J
RIVAS, DAVID
ROJAS, MIREYA
SANET, ALLA
SANTORELLI, ANTHONY
SAUNDERS, CHARLES D
SCHMID, KAROLINE M

HUGUENOT ST 2014 (Cont'd)

175	SHABAZZ, MALCOLM
	SHEEHY, G
	SHUKLA, SALIL
	SMITH, ALFRED
	SONTAG, STEVEN P
	STORCK, BRIAN R
	SUH, MINJI
	SULLIVAN, FRANK
	TALLAJ, RAMON
	TANNER, LESTER J
	TECE, SUNGUR S
	THOMAS, JOHN
	TORGALKAR, SHAILA
	TRUMP SALES OFFICE
	TUPILI, LAKSHMI
	VALENTINI, JOHN
	VECCHIANO, ANTHONY P
	VELEZ, MELISSA
	VICTOR & BROTHERS ROOFING
	VONBRAUN, ALEX
	WAGER, RICHARD E
	WAITT, LORNA
	WATT, LOUISE
	WILLIAMS, GERALDINE
	WYNTER, OVRAL J
	ZHANG, YIMING
	ZHENG, JIE
	ZHENG, SHUAI
	ZIADAT, KAMAL J
181	TEXAS ROADHOUSE HOLDING LLC
244	MARGARITES, MICHAEL
255	255 HUGUENOT STREET CORPORATION
	ABA, MARK A
	ABUBAKER, SYEDA
	ADIMORA, PATRICIA
	AGUILA, MELISSA
	AIRNEST GROUP INCORPORATED
	AKMAN, BERFU A
	ALDRIDGE, JAMES
	ARABITG, CELIA A
	ARIS, JEANINE
	ARNOLD, GREGORY C
	ASKEW, KIMBERLY L
	ATEYAH, GHASSAN
	AYDELOTTE, CAROLINE
	AZHAR, MOHAMMAD
	BABKA, SAMADI
	BARIL, ETHEL J
	BORRERO, SAM
	BROWN, JAMES D

HUGUENOT ST 2014 (Cont'd)

255 BRUCKMANN, CHRISTOPHER M
BRUDERLE, MATT A
BULLINER, MARY
BUNCH, KELLY T
BUSIEK, CHRISTINE M
CAHN, JOSHUA D
CALDERONE, SALVATORE
CARPENTER, GEOFFREY C
CELIK, SELDA
CHAKAVARIKA, EMILY
CHANG, SAMMY C
CHAUDHURI, REMY R
CHEE, JOHN R
CHRISTIAN, SHARON
CHU, CHIH P
CLARK, JAMESETTA L
COLEMAN, KIARA
COLLINS, JASON J
COULIBALY, OUMAR
COYNE, JENNIFER L
CRAWFORD, IVORY
CREMAULT, CHRISTOPHER J
CRUTE, DARIEN
CRUZ, JUAN J
CYNKIN, SIMME
DADOYAN, TALINE A
DAMICO, ANTHONY J
DAMICO, LOUIS D
DARDEN, ROBERT D
DAVIDSON, PATRICK
DAVIS, KARIS M
DAVIS, VALERIE Y
DAWSON, DAVID K
DEBISINGH, GEETA
DEBRUIN, MORNING
DELAFIELD, WALTER B
DENLEY, SCOTT L
DEWITT, ANDREA L
DIAMOND, JESSICA S
DILLON, DWANNA
DILLON, HOBY B
DILLON, MARK E
DIOUF, ABDOU
DONOHUE, JOHN J
DPC TECH
DUNBAR, LESLIE A
DUNEVITZ, BENJAMIN J
EDWARDS, BRYAN
EDWARDS, SHEEBA R
EPPS, DARRYL A

HUGUENOT ST 2014 (Cont'd)

255	EWANG, KENNETH
	EZEDIARO, ANGEL U
	FINK, CANDIDA A
	FITZGERALD, CYNTHIA A
	FLAKE, WILLIAM A
	FOERSTER, LISA
	FONDERSON, ELEANOR
	FORRESTER, RYAN
	FOSTER, SAMMARA
	FRANCE, JAMES M
	FREYNE, SEAMUS
	FULTON, MARSHALL
	GABAY, VICTOR H
	GABRIEL, CALVIN
	GALAN, TATIANA
	GAO, KUN
	GARLAND, AMY C
	GARROW, JON W
	GEFFRARD, GASNER
	GENESIS
	GERMAN, ROBERT R
	GIBSON-DAWSON, JULIANNA M
	GO, ELIZABETH
	GOLAS, ABHISHEK
	GONZALEZ, RAUL
	GORDON, SIMONE N
	GOTO, TAKUYA
	GOTTIPATI, SAMEER K
	GRABLEVSKY, TATYANA B
	GRAHAM, KENNETH R
	GRAHAM, TERESA L
	GRAJEDA, AMILCAR H
	GREEN, EUGENE
	GREENBERG, GARY
	GROSS, IRVING L
	GRULLORY, YADIRA
	GUPTA, NITIN
	HALPIN, ANTHONY
	HAMMARLUND, KARIN A
	HAMMETT, STEVE C
	HASEGAWA, HIROSHI
	HENLEY, STEVEN
	HOCHBERG, J S
	JACOBS, GEORGE
	JACOBSON, MARIA J
	JAIN, SACHIN
	JOHNSON, DEBORAH J
	JOSEPH, ANTONIO
	JOVINE, MASSIEL
	KARUMBA, WANJIKU N

HUGUENOT ST 2014 (Cont'd)

255 KESSLER, BEN
KHANNA, SAURABH
KINGBROWN, KRISTIE
KLEIN, LEONARD S
KLONSKY, IRENE
KOBLICK, SARAH
KOCK, ELVIRA C
KRAN, RANDY L
KREGER, RICHARD
KUBECKA, FALLON J
LATISHA, PATRICIA
LEACH, ISAIAH M
LEE, CHARISSE E
LEGROS, JACQUES
LEJA, JAN L
LELE, KAREN
LEWIS, MILES M
LEWIS, PAMELA
LIMMER, ROBIN P
LIU, CHRISTINA
LIVINGSTON, REGINOLD M
LURIE, JEROME
MACATANGAY, ELLEN V
MANONGI, TUVAKO
MARINO, PETE
MARULANDA, MARIA E
MATIAS, GENISE
MATSUNAGA, KAZUMI
MAYES, CHAD S
MCCOOTY, HUGH H
MCCORMICK, RICHARD H
MCDONNELL, OLIVIA
MCSTOCKER, JOHN C
MEDER, CARLOS
MEYERSON, MARIANNA N
MGAWE, SALMA
MISHRA, DEBASIS
MORAD, AHMAD
MORALES, ITZEL
MORGAN, WILLIAM E
MOSK, GARY S
MOU, JEROME
MURPHY, PHILIP M
NELSON, KENNETH S
NKWAIN, STANISLAUS
NOEL, ALEX
NOMANI, MOHAMMAD
NORTON, JENNIFER
ODERMAN, BRUCE N
OGAGA, CHRISTIAN O

HUGUENOT ST 2014 (Cont'd)

255	OLIVERAS, JOAQUIN C
	OSHAUGHNES, PATRICK
	OSULLIVAN, VIRGINIA M
	PARKER, TRACY D
	PAZOS, JORGE
	PEELE, DENISE J
	PENYAK, KATIE E
	PEREIRA, ROBERT J
	PERRY, JAMES
	PETGRAVE, PHIL
	PFINGSTLER, SUSAN
	PIRSON, MICHAEL
	POITEVIE, ERIC
	POLYCARPE, MYREILLE P
	POWELL, DIONE
	PRYOR, SUSAN M
	QUARLESS, RICHARD A
	RAJPOLT, MATTHEW
	RAZVAN, DARVOOSH E
	REBHUHN, ERIC F
	REGIMBAL, DENIS
	REID, KIMBERLY
	REILLY, MATTHEW C
	REITZ, KATIE
	RESHWAN, MOAYAD
	RFN LLC
	RIGANO, RITA A
	RIGOS, A
	RIVEILI, ERIN
	ROBERTS, ANTHONY
	ROBERTS, PAUL S
	ROBINSON, ZAKIYYAH A
	RODRIGUEZ, RAFAEL
	ROSADO, NANCY
	ROY, BRADFORD
	RUCCI, CHRISTOPHER M
	RYAN, MATTHEW J
	SAAVEDRA, DAISY G
	SALLUSTIO, ANTHONY T
	SANCHEZ, JERALD
	SANDERS, KYLE T
	SARGENT, ALBERT E
	SASAKI, NORIFUMI
	SCARCELLI, BRENDA
	SELBY, MAISHA I
	SHIMIZU, GRACE M
	SIERRA, JOSE A
	SINATRA, TRISTAN M
	SLOVUT, DAVID P
	SMITH, DION

HUGUENOT ST 2014 (Cont'd)

255 SMITHWRICK, STEVEN J
SONG, THOMAS
STANSELL, KACI L
STEELE, LEONARD D
STEELE, TAMMY B
STEWART, GARY
STRACQUODAINE, STEPHEN E
SUAREZ, SELINA
SUKENIK, MOSHE M
SULLIVAN, CARRINGTON C
SUTTON, MILICENT C
TERZANO, ALEKSANDRA
TESFA, LYDIA
THORNTON, LISA A
TODMAN, JANELLE M
TOIN, JON
TOUNKARA, AGNES
TRACEY, ROGER
TSE, LILIA
TULLIO, NINA
TUPILI, RAJA S
TURTON, V
UTZ, JENNIFER
UZUNOVA, GENOVEVA P
VANBRAKLE, JOE
VASQUEZ, ERIKA E
VENKAT, VENKYY
VERMA, AMIT
VILLEDA, MIRIAM T
VOGEL, WAYNE A
WALKER, GLORIA M
WALKER, KEITH E
WALKER, MICHAEL D
WEISENFELD, LEINA G
WHITE, MORJORIEE
WHYTE, OMAR
WIDJAJA, WILDIA
WILLIAMS, ORSON E
WILLIAMS, TIFFANY V
WILLIAMS, VERONICA A
WILSON, CLAY S
WILSON, GERARD
WILSON, MICHELLE S
WITHERS, PAULA B
WOODLEY, DARIUS
WOODRUFF, AARON T
WOOLMER, JASON
WYNNE, SHEILA
YADAVALLI, BHARADWAJ
YUN, SUNG Y

HUGUENOT ST 2014 (Cont'd)

255	ZITO, LOUIS A
	ZOOK, TRACY L
265	JAVA DREAMS CAFE
	OMNIBUS ENTERPRISES
268	AOC FINE WINES
275	255 HUGUENOT STREET CORPORATION
282	SORELL SORELL
296	ANDERSON, DALE C
	ESPINO, VIOLETA
	FLOWERS BY SUTTON
	HUGUENOT STREET FLORIST
	JEROME, GUIRLAINE
	MERGONY, GUILLERMO
	MORALES, JIMMY
	MORRIS PARK FLORIST
	MUIIOZ, SARA
	MUNOZ, JESUS
	RAMIREZ, ALVARO A
	SUTTON FLORIST
300	IRENES BEAUTY PLUS
302	HOUSE OF INK
304	RUBENS TAILOR
306	BROWN, PATRICIA D
	CASHER, ALBERTO F
	CERRON, ROSA C
	COLBERT, GLEN
	COOPER, MAMIE
	CORONA, JOSE C
	ESQUIVEL, GILBERT F
	FOUNTAIN, EDWARD W
	GALLARDO, CAROLINA
	GARCIA, RAUL
	GOULD, CHRISTINA
	GRAVES, ELIZABETH
	MIRANDA, SHARON D
	MONICA GARAFOLO
	MORALES, RIGOBERTO
	NIXON, EDWARD L
	PALMER, HARVEY A
	PEREZ, MARVIN
	ROYSTER, PHYLLIS A
	SCHOENBRUN, STUART M
	SPADY, SAMUEL
	SUSSMAN, BRIAN H
	VIDAL, SHANISE
	WARD, CHRISTOPHER
	WILLIAMS, RIPTON M
	WILSON, DAVID
310	MIDWAY GARAGE DOOR & LOCSMITH
	MODERN RESTAURANT

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2014 (Cont'd)

311	TRINITY & PAULS CHURC
	TRINITY COOPERATIVE NURSERY SCHOOL
	TRINITYST PAULS EPISCOPAL CHURCH
316	MODERN PAINT & HARDWARE
326	EL SABOR DE MI TIERRA RESTAURANT
328	THE LITTLE RANCH
330	EXPRESS DELI
331	VIGGIANI, JULIO C
342	I A G INCORPORATED
	INNOVENTIVE POWER LLC
	TRI CITY OVERHEAD DOOR SERVICES
347	ALEXANDER, RACHEL
	ALLEN, TREVOR
	CAREY, TAMMI M
	DAVID FRENCH CATERING
	GOODMAN, EMANUEL G
	HARDING, BERYL A
	HOLTON, HENRY L
	MAULDIN, AUDREY D
	MORRIS, LOUELLA
	NEWTON, LEWIS M
	ROYSTER, VERONICA
	SCOTT, MURDELL
	SHEPPY, KIRK D
	TRINIDAD, JORGE
	VALDOVINOS, MARIA D
348	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 2014

1	BLUE BIRD TAXI SERVICING CORP
	HERTZ
	LARCHMONT STATION TAXI
	LIBERTY LINES TRANSIT
24	GREEN TEAM CAB CORPORATION
	M & E DRY CLEANERS
	STATION CAFE

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 2010

2	GILCHRIST, SHAWN
	ROLLER, DAUNELL L
	TURNER, CHRISTOPHER M
5	OQUENDO INC
6	FRESH TACO
7	FREDS BEAUTY SALON
8	NICK RUSSO REAL ESTATE LLC
9	AWA AFRICAN HAIR BRAIDING
	GALLEGO, AMANDA
	GOMEZ, J G
	RHETT, LISHA R
	SANABRIA, BENJAMIN H
10	HEADS TOGETHER
11	LUSO AMERICA FISH MARKET
12	FIFTH AVENUE TANNING SPA
14	WEST ROCHELLE TRAVEL AGENCY
15	ABEL, TODD D
	BENJUMEA, PAULA A
	DANS CARPETS CO
	LOPEZ, ISRAEL
	WELLINGTON, MARK
	YEUNG, KEE
16	BRICKYARD BISTRO
18	KAFFENE ESPRESSO BAR
20	NEW ROCHELLE COIN & JEWELRY
22	POSTO 22
23	ALFREDOS PIZZA CAFE
	SHIRLEYS CONSTRUCTION CO
24	AMBER HAIR DESIGNS
	DINO & DAN BARBER SHOP
27	ALAMPI, ANDREA R
	BAIR, C
	BALDWEN, GAYENELLE
	BIGGS, DARRELL E
	BLAUSTEIN, DAVID
	DIPILATO, ANGELA
	DOWNES, GRANT
	FAZIO, THOMAS J
	FIELDS, LARRY
	HERSHENHORN, MARTIN A
	ITOH, WATARU
	JEFFERSON, FRANKLIN
	JOHNSON, CAMERON
	KANHAI, MIKE
	KESSEL, CYBIL R
	MATOS, NARCISO
	RICHARDS, ARTHUR B
	SATTERLEE, ROBERT T
	SILVERSTEIN, JEFFREY
	TURNER CONSTRUCTION

DIVISION ST 2010 (Cont'd)

27	VENZI, ANITA A
	WATSON, ANN M
	XIAO, JACK Q
30	COROMANDEL CUISINE OF INDIA
38	NEW ROCHELLE IRISH SOCIETY
39	VILLA, CIRILA
40	ATTILIOS BARBER SHOP
	CATALOGNE, EDGAR M
	CINNAMON, RACHEL
	KOERNER, JAMES L
	LARA, ANA
	LONGHITANO, JEANNE
	MARCIDO, ADRIAN
	PADILLA, YOLANDA N
	SCHMID, EDWARD F
	SHEPHERD, JOAN B
	SYNAN, KATHLEEN
48	MUNGULA, MARIA
64	BULMARO, MOTOLINIA
112	RELIG
120	ST GABRIELS CHURCH
127	TUOLLE, MARIA

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2010

175	ABREU, CESAR
	ADOLPH, GERALD S
	AGU, ADAEZE
	AHMED, SHER
	ALBERGA, ROBERT F
	ALMODOVAR, CARLOS
	AUFFARTH, HENRY
	BABEL, STEVEN
	BENENSON, JOSH M
	BHAT, SHEETAL
	BOIANO, ANTONIO
	BOSCO, JOHN
	BRICKWEDDE, JENNIFER
	BROWN, TRENTON
	BURKE, MICHAEL W
	CABRERA, T
	CHOPAK, IRWIN
	COLE, KAREN A
	DELACRUZ, MARJORIE A
	DENIGRIS, DANIEL C
	DIOP, MALICK M
	DOONAN, JON F
	DORITY, KATHY L
	DUGGAL, SACHIN D
	DUMAIS, DENNIS R
	FERREIRA, ANGELA
	FRANCHINI, JOHN
	FRANCIS, GARY
	FRASER, LESMAH J
	GAMBLE, KENNETH G
	GARFIELD, HOWARD
	GRAHAM, LEWIS
	GRANADY, LYNELLE C
	HARMITT, NICOLA A
	HARRIS-BRIAN, SHARON
	HEADLEY, DARRYL G
	HOLLOMAN, ALFONSO L
	IACHETTA, ANTONIO
	JASON, MARC
	JOHNSON, DAWN
	JOHNSON, S
	KARIMI, PEGHA
	KEANE, JOHN
	KIZNER, ILONA
	KMETZ, DAVID J
	KRESO, KEVIN R
	KUMPIBAL, ANNIE
	KWON, ANDREW O
	LAGANA, VINCENT J
	LEE, JONG G

HUGUENOT ST 2010 (Cont'd)

175 LIMJAP, JOSE E
LOMBARDI, LINDA C
MAKAROV, ALEXEY A
MCDOWELL, FENELLA S
MCMULLAN, HOLLY
MECHAUX, YOANN
MOMMSEN, BRIAN
MULHERN PROPERTIES INC
MULHERN, RICHARD
MUNRO, ROBERT
NARAYAN, PRITHVI
NEW YORK CITY SPORTS CLUB
NICCHIA, BIAGIO
NIETO, JAIME H
NOSCHESE, JOHN P
NYSC NEW ROCHELLE
OCANSEY, ANA
OCONNOR, CHRISTOPHER J
OELSCHIG, TREVOR H
ORTIZ, JOSE
PARK, AUSTIN
PATEL, MINAL
PERDUE, PATRICK F
PHUPAKDI, WIPANEE
PRUSOCK, DONALD S
QURESHI, A
RABIN, PHILIP
RANA, THAKOR C
RIVAS, DAVID
ROCK, MEGHAN E
RODRIGUEZ, JON
SHABAZZ, MALCOLM
SHUKLA, SALIL
SPANN, RONALD
STARR, S
SUH, MINJI
SUKPOKKIJ, PRADA
SULLIVAN, FRANK
SUMMO, JOSEPH M
SUZUKI, SHIGEYUKI
TABACHNICK, PHILLIPS
TAKRITI, SAMER
TAYLOR, MONIQUE
TIRPAN, ANI
TRUMP SALES OFFICE
TUNG, ANDY H
TUPILI, RAJA
TURCAN, MARK
TYNER, RICHARD A
WAGNER, ELIZABETH

HUGUENOT ST 2010 (Cont'd)

175 WAITT, KEITH
WANG, HUALU
WANG, S W
WHITE, JILLIAN E
WILLIAMS, ANDRE S
WYNTER, OVRAL
ZIADAT, KAMAL J
225 LIEWEHR, SCOTT
MASKA, KIMBERLY R
255 ACHOKI, ALLOYCE J
ANKER, MICHAEL S
ARIS, ANTHONY
ARROYO, MILDRED
ASHINOFF, REID L
ASKEW, KIMBERLY L
ATLER, ARIANA L
AVALON ON THE SOUND
AWOKE, AKLILU S
BABKA, SAMADI
BAKER, KIMBERLY R
BANDLER, BRIAN C
BISHOP, A
BONNEY, NIKISHA M
BRAGGS, JOHNNY A
BRUCKMANN, CHRISTOPHER
BRUDERLE, MATTHEW A
BUNCH, KELLY
CANCEL, ALICIA
CARPANZANO, NATALIE
CARPENTER, GEOFFREY C
CASADEVALL, ARTURO M
CHARLES, LINCOLN
CHAVIS, LEONARD M
CHEE, JOHN R
CHEN, WEI
CHO, HYUN J
CHTCHERBA, ARTHUR D
CLENDENON, JACOB N
CLEVENGER, JEFFERY
COCCO, KATIE
COGHLAN, MAUREEN
COHN, KENNETH
COLLINS, JASON J
COMPUTER MD INC
CREMAULT, CHRISTOPHER E
CUMBERBATCH, ALANA
DADOYAN, DANIEL A
DAMICO, ANTHONY J
DAMSTRA, ROBERT E
DEBRUIN, MORNING

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2010 (Cont'd)

255	DENGO, MANUEL B
	DEVADAS, PRAMILA
	DEVINE, GERARD P
	DEWITT, ANDREA L
	DONOU, ETIENNE L
	EGAN, BRANDON M
	ELLIS, LIORA
	FARRELL, JACQULINE
	FELIPE, JEROME
	FLAKE, WILLIAM A
	FONTENELLE, OLAF
	FRANKLIN, LAFREDA
	FRIEDMAN, ROBERT
	FUNES, STELLA
	GABAY, VICTOR H
	GARDNER, NIGEL
	GENESIS
	GERMAN, ROBERT R
	GIAMPIETRO, RICARDO
	GOLDSCHMIDT, BEATRIZ
	GRAHAM, KENNETH
	GRAJEDA, AMILCAR H
	GRAY, CHRISTOPHER J
	GRIFFITHS, NATALIE A
	GROBMAN, SHARYN L
	GROTEKE, SUSAN E
	GUADALUPE, JOSE E
	HADDON, KARLENE M
	HARDING, RONNY
	HAROLD, YOUNG
	HAWI, MAHA E
	HAWKINS, JARYD
	HENGO, ALICIA
	HERNANDEZ, DAVID
	HIMEI, YUKIHIRO
	HOCHBERG, J S
	HODGES, JASON E
	HOWARD, LAUREN
	HUNTER, ALEXANDER W
	IGBINOVIA, PATRICIA
	IRVING, KRISTIN
	JACKSON, DAHLIA A
	JACKSON, ROBERTA J
	JACKSON, TRACI S
	JOHNSON, DEBORAH J
	JOHNSON, JAMES G
	JOHNSON, ROGELIO B
	KIM, JENNIFER
	KIRLEW, ANNETTE M
	KIVI, LINDSAY

HUGUENOT ST 2010 (Cont'd)

255 KORWIN, RICHARD
KREGER, ALEXANDER
LAYNE, DAVID
LEE, JACQUELINE L
LEGRAMANDI, SANTO H
LELE, AJAY B
LIMMER, ROBIN P
LITTLE, TINEA S
LLOPIS, RAFAEL E
LOPEZ, MARCO A
LU, YONG
LUCAS, ANDREW J
LURIE, ELYSE C
MACATANGAY, ELLEN V
MAGNAYE, IVAN M
MANKOFF, GERI L
MANONGI, T
MARCUS, STEVEN M
MARTINEZ, IRIS O
MCCORMICK, RICHARD H
MCDOWELL, FENELLA
MCSTOCKER, JOHN C
MERJANIAN, CAROLINE
MEX, CARL H
MEYERSON, DAVID S
MORGAN, JENNIFER
MORGAN, WILLIAM
NICOLAS, ROLAND S
NIVEN, POLLY F
NOCITO, DAVID V
OCONNOR, CAROLYN J
ODOHERTY, G D
OLIVERAS, JOAQUIN C
OSTROWSKY, MORTON A
OWINOW, GEORGE
PANTIN, GARY B
PAREKH, RUJUL B
PATEL, MANISH
PEROLINI, CLAUDIA M
PICONE, KEVIN W
PIRSON, MARINA
POITIER, SANDRA
POLYCARPE, MYREILLE P
PROIA, MARIA
QUARLESS, DIANE
RAFF, JACK A
RAFIDAIN PARTNERS
RAINBOW, ANDREW J
RAJPOLT, MATTHEW
RENITA, T

HUGUENOT ST 2010 (Cont'd)

255 RFNLLC
RIGOS, A
RITSCHL, DORIE R
RIVERA, MIGUEL A
ROBARGE, RONALD
ROBERTS, PAUL
RODGERS, MELANIE
RODRIGUEZ, EVITA E
ROOHIPOUR, MIR
ROSENZWAIG, JAVIER M
RUCCI, CHRISTOPHER M
SALOGUB, CHRISTOPHER M
SANDERS, KYLE T
SILEO, JASON P
SINATRA, JEAN J
SINATRA, ROBERT J
SINKFIELD, TONY
SMITH, FREDDIE D
SMITH, MICHELLE N
SPAMPINATO, MARIA C
STEELE, LEONARD D
STERN, JAMES A
STEWART STAFFING SUPPORT SVC
STOVBOUN, ALEX Y
SULLIVAN, PATRIC J
SUNA, JONATHAN B
SUTTON, MILLICENT C
TAN, MARY L
TAYLOR, SHANTE M
TAYLOR, T
TEJEDA, ERIC R
THOMASMA, CAROLYN J
THORNTON, SONDRA M
VANTUIN, JON A
WALKER, LATOYA D
WALKER, MICHAEL D
WALL, MARY A
WALLA, LATISHA B
WILLIAMS, CHERYL L
WILLIAMS, ORSON E
WILLIAMS, SHARON K
WILLIS, KYLIE M
YANG, YIJIA
YANSANEH, IBRAHIM S
YOUNG, MELANIE M
YU, ARTEMIS
ZELATIS, B
ZENGOTITA, ALEXANDER
ZHOU, JUN
265 JAVA DREAMS CAFE

HUGUENOT ST 2010 (Cont'd)

268	AOC FINE WINES
284	MR CLEAN WINDOWS CLEANING SVC
296	MERGONI, GUILLERMO A
	MUNOZ, SARA
	NEW ROCHELLE FLORIST INC
	SAAVEDRA, BARBARA M
	SUTTON FLORIST
300	IRENES BEAUTY PLUS
	QNIQUES HAIR SOLUTIONS
304	RESUME CENTER
	RUBENS TAILOR
306	AYALA, SALVADOR
	BROWN, PATRICIA D
	CALDERON, DIGNA
	COLBERT, GLEN
	COOPER, MAMIE
	ESQUIVEL, GILBERT
	FLOWERS, G
	FOUNTAIN, G
	GALLARDO, CAROLINA
	GARCIA, RAUL
	GORHAM, STORMY
	GRAVES, ELIZABETH
	MIRANDA, SHARON
	REYES, RAMIRO
	ROBERTS, OMMA
	SANCHEZ, KARINA
	SUSSMAN, BRIAN H
	WARD, MICHELLE
	WILSON, DAVID
311	SENIOR PERSONNEL PLACEMENT BUR
	TRINITY COOP NURSERY SCHOOL
	TRINITYST PAULS EPISCOPAL
316	MODERN HARDWARE & PAINT
	PARK SPORTING ARMS
326	EL SABORDEMITITRRA
328	LITTLE RANCH
330	MADABA DELI
331	VIGGIANI, JULIO C
342	INNOVENTIVE POWER LLC
	VERIZON WIRELESS
347	ALEXANDER, KEITH A
	ALLEN, TREVOR
	FELTON, DARLENE
	GRIFFITHS, ROAN T
	HARDING, BERYL A
	HICKS, DANIELLE C
	HOLTON, LINDA
	KYDD, CLARISSA S
	LINEBERGER, HENRY L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2010 (Cont'd)

347	MAULDIN, AUDREY A
	NEWTON, LEWIS M
	RUFF, CLAUDIA
	SCOTT, MURDELL
	SHEPPY, KIRK D
	STEINBERG, MARIAN
348	MARINAS NIGHT CLUB
	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 2010

1 BLUE BIRD TAXI SERVICING CORP
LIBERTY LINES TRANSIT
SMALL SHEILA E
STANDARD PARKING
STATION CAFE

2 HERTZ LOCAL EDITION

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 2005

2	ANDREASSI, JANE
	MACASSAR, AUNTIE
	PETROVA, NATALIYA
	ROLLER, D
	TURNER, CHRISTOPHER M
5	ROSSI CUSTOM TAILORING
9	EVANS, LESLIE A
	GOMEZ, J G
	LLERENA, AMANDA
	SABOGAL, MARIA R
	SANABRIA, BENJAMIN H
10	HEADS TOGETHER
11	DIVISION ELEVEN BILLIARDS CORP
	LUSO AMERICA FISH MARKET
12	FIFTH AVE TANNING SPA
	V M C CONSULTING SERVICES
13	ARTISTIC HAIR SALON
15	BENJUMEA, CARLO E
	DDFJ CORP
	DESANTE, VINCENT E
	HUNTER, S
	HUZCANGA, IRMA
	LEE, FAY
	SUAREZ, VICTOR
	YEUNG, KEE
17	CENTRAL PARKING 129
	FERNANDEZ, MONICA
20	NEW ROCHELLE COIN & JEWELRY EXCHANGE
	NEW ROCHELLE COIN AND JEWELRY EXCHAN
22	22 DIV
	VINENZOS PIZZERIA INC
24	DINO & DAN
27	SMART, GEORGIA
36	NEW RCHLLE IRISH BENEVOLENT
38	NEW ROCHELLE IRISH BENEVOLENT SOC
39	CHEN, JIU K
41	DACUTT HAIR STYLE
42	VACCACHAN, ABRAHAM
46	BORDAS ART & FRAME SHOP INC
61	BENNETT, STANFORD
64	BULMARO, MOTOLINIA
68	AMERICO, JOSE
120	ST GABRIELS CHURCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2005

225	MASKA, KIMBERLY R
255	ANDRY, RITA M
	ANEJA, ANKUR
	ANGERSBACH, CHARLES
	AOYAMA, TAKUMA
	AQUILINO, PHILIP A
	ARCHBALD, CHERYL D
	ARORA, SABENA
	ARTAUD, SEBASTIEN
	ATLAS INC
	AVALON ON THE SOUND
	AVALONBAY COMMUNITIES INC
	AWAD, AHMED
	BABKA, SAMADI
	BADURI, AHMED T
	BAKER, LINDA J
	BALAN, GUY R
	BALDESSARRE, PHILIP
	BANCEL, PATRICK
	BANDLER, BRIAN C
	BARRETT, ANTHONY R
	BAYLOR, KIRK
	BEDI, R
	BEEBEE, SANDHYA
	BELBRUNE, REGINALD R
	BELCHICK, C A
	BELLINI, ANNA P
	BENEDUCE, ANDREW
	BENNER, MATTHEW
	BETHUNE LAMBERT HOLDINGS LLC
	BILBAO, MARGARITA H
	BISHOP, A
	BLECKER, DAVID S
	BOCKEMIHO, LOIS
	BONALLE, DAVID
	BORK, IRVING
	BOVICH, SHANNAN
	BROWAR, LISA M
	BROWN, ANDREA M
	BROWN, RUSSELL
	BRUCKMANN, CHRISTOPHER
	BRUTTINI, LINNETT
	CAULWAY, CARI J
	CDI INC
	CERULLO, DARREN
	CHAN, RANDY S
	CHU, CHIH P
	CHUN, JANG H
	CLARKE, ROBERT
	CLAYTON, HYACINTH I

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2005 (Cont'd)

255	CLENDENON, JACOB N
	COHEN, NEIL I
	COLOMBO, KIM A
	COMENOS, JOHN
	CONNELL, SCOTT D
	COPPOLA, LINDA
	CORRIGAN, PETER M
	CRAIG, SCOTT
	CREMAULT, CHRISTOPHER E
	CRONIN, JAMES
	CROWLEY, COLIN
	CURL, NANCY A
	CYR, JAY J
	DALAL, RUJU I
	DAVID, HALLIDAY
	DAWSON, VERONICA M
	DEBUYS, LAURA
	DECKER, CHRITOPHER T
	DENGO, MANUEL B
	DIAZ, ELAINE
	DILLON, HOBY B
	DRAWER A LLC
	DUHANEY, KEITH
	DULANTO, GONZALO
	DULBERG, BETTY M
	DUNBAR, LESLIE A
	DUNHAM, MICHAEL R
	EARWOOD, M
	ESPOSITO, MICHAEL R
	ESTREMERA, FRANCES
	EVANS, DERRICK
	FAIRCHILD, JOE
	FASANO, ANGELA R
	FATEHI, BEHROOZ
	FENSTERSTOCK, ERIC
	FERGUSON, GILLIAN C
	FINATERI, SILVIO S
	FISCHER, BRIAN
	FISH, DANIEL G
	FLOOD, THOMAS L
	FLORES, LUIS
	FOLTA, HOWARD S
	FONTENLA, ERNESTO
	FORDE, KEVIN
	FORT, S
	FORTI, MATTHEW
	FRANCIS, RENEE
	FRANZEK, CHRIS
	FRIEDMAN, ROBERT
	FUJII, SHINSUKE

HUGUENOT ST 2005 (Cont'd)

255	FUNES, STELLA
	GABAY, VICTOR H
	GABCO PROPERTY MANAGEMENT LLC
	GALLAWAY, CHRIS
	GALLOWAY, COREY L
	GARCIA-VALINO, MARIANO
	GARRETT, CHARLENE K
	GEORGE, GREGORY C
	GIDDON, K
	GLENN, DEBORAH A
	GOCHBERG, WORRAKORN
	GOTO, TAKUYA
	GOYAL, ADARSH
	GRAHAM, KENNETH
	GRANT, MERREDITH
	GRANTCHAROV, ALEXANDRE E
	GREEN, KATHERINE B
	GREENLEAF, SUSAN E
	GREGG, EDDIE
	GROSS, JEFFREY A
	GRUNWALD, JUDITH
	GUADALUPE, JOSE E
	GUGLIELMELLO, MICHAEL
	HARA, KEI
	HARAN, ADIYAN
	HARRIS, JAMES
	HASEGAWA, HIROSHI
	HASHIMI, SAUD A
	HASTINGS, LAURA D
	HEAVEY, AMY L
	HERAUD, ANTHONY
	HERTZOG, MATTHEW
	HINES, JASON A
	HIRAO, YUHIKO
	HOECK, PAUL A
	HOKI, MASAMI
	HONEGAN, DENISE A
	HUGHES, ROBERT
	HUMBERT, PASCAL
	HUNT, SCOTT
	IACARINO, JUDITH E
	ILARIO, M
	ISHII, NAOKI
	ITA, SHINFUKE
	IYER, SIVASUBRAMANIAN P
	JACKSON, DAHLIA A
	JACKSON, MAKESHA L
	JACKSON, TRACI S
	JAMES, ROSCOE W
	JEFFERSON, FRANKLIN

HUGUENOT ST 2005 (Cont'd)

255 JENNIFER PICHARDO DDS PC
JIM, KAMWAH F
JOHNSON, JAMES G
JONZIN INC
JOSEPH PORTANOVA LANDSCAPING & MASON
KANEFSKY, DAVID H
KANEKO, HARUYO
KANEYAMA, TAKUJI
KAWAMORI, CHIAKI
KEMPSON, KENDRA M
KERAI, ASAD S
KESHAVJEE, ARIF
KHAN, SAIRA
KIATTICHUANCHAI, WILAIRUT
KIELEY, DANIEL
KING, TARA
KLAUSMAN, NOAH
KLAUSMAN, SARA
KOCK, ELVIRA C
KREGER, ALEXANDER
KUMAMOTO, NORITAKA
KURAMATA, S
KURIYAMA, KEN
LALOR, SUZANNE
LEDWITH, REBECCA
LEE, DOEUN
LEE, JACQUELINE
LEE, NICOLE J
LEFF, JONATHAN
LELE, AJAY B
LEMERE, MICHAEL
LEMPA, A
LENNON, LUIS A
LERNER, DANIEL
LEWIS, RUSS
LIEWEHR, SCOTT C
LIMMER, ROBIN
LINCOLN, DAVID F
LLOYD, AUDREY D
LONGO, TARYN
LU, PING
MACATANGAY, ELLEN V
MAHON, THERESA R
MALOMBE, JOYCE M
MARCONTELL, P W
MARCY, ELIZABETH V
MARGARITES, MICHAEL D
MASATOSHI, SUZUKI
MASCARI, L
MAZUCCI, THOMAS R

HUGUENOT ST 2005 (Cont'd)

255 MCCLAIN, MELISSA
MCGUIGAN, JAMES
MCIVER, LAURIEANNE
MEKOLO, ALPHONSE
MELLER, JENNIFER A
MESSINA, NEIL C
METALIOS, STEVE
MICHALEAS, GERRY N
MIKAIL, EBRAHIM
MIKEL, BRENDA R
MILLAN, C
MILLS, CHRIS
MILONE, ANGELO
MOELLER, MARTINE J
MONAGHAN, LARRY
MONTELL, SYLVIA R
MOROCK, JOSEPH J
MORRIS, JASON Z
MORROCK, JOSEPH J
MOSHMAN, JEANNE
MOSKOVICH, RONALD S
NAKA, HIDEFUMI
NAQVI, ALI M
NASEER, AAMER
NELSON, JOHN
NEW ENGLAND IMPORTS LLC
NOVOSEL, SETH
NUNEZ, R
OAK, MARY
OAKS, MARY
OBRIEN-BRIGGS, HELEN I
OCONNOR, K
OE, MAYUMI
OFFREDO, S
OLAVARRIA, FRANCISCO
OLCESE, LUIGI N
OMUKAI, YUMI
ORLANDO, ANDREW
OVERTON, JOHN
PAK, MARY
PAPP, ENDRE K
PARADESES, JOHN M
PARK, CHANG K
PAULL, ROGER I
PECORARO, PETE
PEMBURY, ARTHUR M
PENSKY, BARRY
PEREIRA, CARLOS
PERRY, PATRICIA K
PFEIFFER, J

HUGUENOT ST 2005 (Cont'd)

255 PHILLIPS, VALERIE A
PICONE, KEVIN W
POPE, KENDRA
PORTANOVA, JOSEPH P
PRYOR, SUSAN M
PRYWES, HARRY C
QAROONI, HAMZA
QUARLESS, RICHARD
RAJEE, I
RAJPOLT, MATTHEW
RAMPAL, ADITYA
RAPPAPORT, JON
RC GOLD LLC
REID, KENDALL
REYCRAFT, TOM
REYES, ARIEL
RIFKIN, T
ROBERTS, NORMA T
RODDY, PETER
RODRIGUEZ, CARLOS J
ROSENZWAIG, MAXIMA
ROY, RAYMOND
RYAN, PAULA
SANCHEZ-BOYCE, MICHELLE
SANDERS, VAL R
SANTIAGO, RUBEN
SAPORITO, MICHAEL
SARR, AMADOU
SATO, PRISCILLA L
SATRIALE, KIMBERLY A
SCAVELLA-ABRIGO, CHRISTINE
SCIARROTTA, ANTHONY
SCLAFANI, MARIA
SEDLARCIK, RAEGAN
SEGER, RANDOLPH
SEIDMAN, BENEDICT S
SEIP, JOHN
SHAPIRO, ZEV J
SHAW, WILLIAM P
SMART EDGE SOLUTIONS LLC
SMITH, ERIC J
SNYDER, ROBERT
SOLER, JAUME
SOLIMINE, JENNIFER
SONODA, KOJI
STANLEY, MAURICE
STANTON, BELINDA M
STEELE, LEONARD D
STERN, JAMES A
STJACQUES, HENOCK

HUGUENOT ST 2005 (Cont'd)

255 STOJKOVIC, GORAN
STOVBOUN, ALEX
SUEHIRO, YUKO
SULLIVAN, CHRISTOPHER
TAMURA, YUICHI
TAWNEY, M R
TAYLOR, T
TEDESCHI, MARCO Q
TEDESCO, DONALD D
TEIXEIRE, JULIO A
TEMPLE, K R
TETALI, SRINIVAS V
TETSUMASU, KEIJI
THE SEASONS GROUP
THORNTON, SONDRA M
TOURE, AMINATA
TRETTER, A
TRIPATHY, AMARESH S
TSARNAS, MICHAEL Z
TSOMAYA, VICTORIA
TSUCHIYA, HITOSHI
TSUKAGOSHI, YUJI
TSYGANOV, YURIY A
TURMEL, COLETTE
TURTON, V
UCCELLI, JENNIFER L
UCHIDA, YOSUKE
VAIDYA, KAUSHAL
VALERINO, LUCIA M
VALIATHAN, SREEKUMAR
VARMA, VINOD
VOGEL, WAYNE D
VOLLERTSEN, JOSHUA
WACHTER, BRIAN
WAGNON, BRIGITTE
WAINER, RON M
WALLINGTON, JOHN
WATADA, MARCUS
WESTCHESTER, A R
WESTCOTT, RICHARD W
WONG, CHARMANE A
WRIGHT, EBONI
XI, HAO
YAMAGUCHI, TAKAHIRO
YARRIS, STEVEN
YU, CHRIS
ZAKI, STEVEN
ZDRILIC, JANKO
ZELSON, GERRY
ZENENGA, RAISEDON

HUGUENOT ST 2005 (Cont'd)

285	DIAZ, RUDOLFO M
296	FLOWERS BY SUTTON INC
	JEAN, SHILDER
	MERGONI, GUILLERMO A
	MUNOZ, SARA
	RAMIREZ, LETICIA
	ROJAS, LORENA
	SAAVEDRA, BARBARA
	SUTTON FLORIST
	VELEZ, ESTELLA
300	HENRY MORGAN CUSTOM UPHOLSTERERS
	JENNIFERS PREMIER PRINTING
304	BEE TAXI CORP
306	BROWN, P
	CALDERON, DIGNA
	COOPER, MAMIE
	EBONY EXPRESS LLC
	ESQUIVEL, GILBERT
	FLORES, EMILIO
	FLOWERS, WILLIE
	FOUNTAIN, BETTY G
	HAWKINS, BARBARA A
	JEFFERSON, MARY
	JOHNSON, NATASHA
	JONES, EVON
	MCGHEE, HERMAN
	MIRANDA, SHARON
	MULLINGS, DEBORAH A
	ORTIZ, EDGAR A
	REYES, RAMIRO
	SPADY, SAMUEL
	SUSSMAN SOFTWARE
	SUSSMAN, BRIAN H
	WHITE, DOROTHY
	WILSON, DAVID
308	BASS UPHOLSTERY SUPPLY CO INC
310	NEW ROCHELLE RESTAURANT SUPPLY
311	CATHEDRAL CHURCH SAINT JOHN DIVIN
	TRINITY COOPERATIVE NURSERY SCHOOL
	TRINITY ST PAULS EPISCOPAL CHURCH
316	MODERN HARDWARE & PAINT
328	LITTLE RANCH
331	VIGGIANI, JULIO C
342	205 E 3RD CORP
	VERIZON COMMUNICATIONS INC
347	ALEXANDER, KEITH A
	BRYANT, WILLIE
	CAREY, TAMMI M
	DEITZ, DONALD
	EVANS, JOI A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2005 (Cont'd)

347	FREDERICKS, DOLORES
	GAINEY, LEAH
	HARDING, BERYL A
	HICKS, MARILYN
	HOLDINGS, L
	HOLTON, LINDA
	HUGUENOT, HOLDINGS
	LINEBERGER, HENRY
	MILLER, MARY L
	MORRIS, LOUELLA
	NEWTON, LEWIS M
	RUFF, CLAUDIA
	SCOTT, MURDELL
	STEINBERG, MARIAN
	YOUNG, ANNIE
348	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 2005

1	ROCHELLE DELUXE TAXI
15	BLUEBIRD TAXI SERVICING CORP
33	GLOBAL LICENSING AUDIT SERVICES INC

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 2000

2	CHOICE INCORPORATED
	HENNINGS, DERRELL
	KEATING, JOSEPH
	MACASSAR, AUNTIE
	MERLE PERLMUTTER ETCHINGS
	TURNER, C
5	ROSSI CUSTOM TAILORING
6	BORDAS ART & FRAME SHOP INCORPORATED
	GREENE GALLERY INCORPORATED
7	FREDS BEAUTY SALON
8	CHILDRENS SVCE LEAGUE THRIFT BOUTIQUE
9	LOPEZ, AMANDA
	SABOGAL, MARIA
	SANABRIA, B
10	HEADS TOGETHER
11	LUSO AMERICA FISH MARKET
12	FIFTH AVE TANNING SPA
14	GOLF HOLIDAYS
	WEST ROCHELLE TRAVL AGENCY I
15	BENJUMEA, CARLO
	DANS CARPET COMPANY
	DAWSON, BARBARA
	DESANTE, VINCENT
	GOODRICH, GLADYS
	HOUSEWORTH, WARREN
	LEE, FAY
	SCHAEFER, ROBERT
	VIDALIC, ANTON
	YEUNG, KEE
16	DIVISION STREET DELI
18	LOWRIDER STYLE
20	CLARIDGE BROKERAGE
	NEW ROCHELLE COIN STAMP & JEWELRY EXCHANGE
	NUMISMATIC ASSET STRATEGIES
22	DANTES INFERNO INCORPORATED
	VINCENTS PIZZA & ITALIAN RESTAURANT
24	BENITO HAIR DESIGN
	DINO & DAN BARBER SHOP
30	ALAM, MOHD S
	TANDOORI TASTE OF INDIA
38	NEW ROCHELLE IRISH BENEVOLENT SOC
40	ATTILIOS BARBER SHOP
48	BENTO, F
	NASCIMENTO, JOSE
61	A M ADVANCED PEST CONTROL I
64	OCCUPANT UNKNOWN,
68	JOSE, LUIS
75	OCCUPANT UNKNOWN,
112	NEW ROCHELLE HIGH SCHOOL OF RELIGION
120	ST GABRIELS CHURCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2000

280	CALLENDER J HOLLIGAN ATTORNEY
296	ANDERSON, DALE C
	BAQUERO, JOSE Y
	BEQUERO, CLAUDIA P
	FLORES, LUZ
	MERGONI, G
	MUNOZ, SARA
	ROJAS, LORENA
	SUTTON FLOWERS
297	RODRIGUEZ, EMILIO
300	HENRY MORGAN CUSTOM UPHOLSTERERS
302	FAITH HOPE & CHARITY BALLOO
306	ADAMSON, LARON
	CAPPARELLE, M
	COOPER, M
	EVANS, LESLIE
	FLEMING, LEVIE
	HAWKINS, BARBARA
	HENRY, LATASHA
	JOHNSON, N
	MCGHEE, HERMAN
	MIRANDA, S
	TORRES, SANDRA
	WILLIAMS, HAROLD
	WILSON, DAVID
	WILSON, XAVIER
308	BASS UPHOLSTERERS SUPPLIES
	FOAM RUBBR HEADQUARTERS
310	NEW ROCHELLE RESTRNT SUPPLY INCORPORATED
311	SENIOR PERSONNEL PLACEMENT BUR INCORPORATED
	TRINITY COOPERATIVE NURSRY SCHOOL
	WESTCHESTER COMMUNITY OPPORTUNITY PROGRAM
316	ESSIES
	MODERN HARDWARE & PAINT
	PARK SPORTING ARMS
326	LAVOZ LATINA
330	MADABA DELI 9
347	BROOKS, GRACIE M
	CAREY, TAMMI
	DEITZ, DONALD
	EARLYBIRD HAIR SALON
	HARDING, BERYL
	KERSHAW, TRACY
	LOPEZ, NATHAN
	MARTINEZ, ZORAIDA M
	NEWTON, LEWIS M
	SEARS, R
	SELINSKI, JOHN
	STEINBERG, MARIAN
	TERRANOVA, BERT

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 2000 (Cont'd)

347	TORIAN, C
	TORRES, ANTONIO H
	WILLIAMS, DIEDRA
	YOUNG, ANNIE
348	AMC PRINTING
	MARINAS NIGHT CLUB

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 2000

1 DELUXE RADIO TAXI INCORPORATED
NEW STATION CLEANERS
POST STATIONERY & GIFTS

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 1995

2	HAIR FACTORY INC
	MERLE PERLMUTTER ETCHINGS
5	ROSSI CUSTOM TAILORING
6	BORDAS ART & FRAME SHOP INC
	GREENE GALLERY INC
7	FRED'S BEAUTY SALON
8	CHILDRENS SVCE LEAGUE THRIFT BOUTIQUE
9	HAIRSTYLES ONLY
10	ENECON METRO CORP
	ENVIRONMENTAL ASBESTOS CONTROL LTD
	HEADS TOGETHER
	MRM ENVIRONMENTAL SERVICES INC
11	LUSO AMERICA FISH MKT
12	FIFTH AVE TANNING SPA
14	WEST ROCHELLE TRAVL AGNCY INC
15	DAN'S CARPET CO
16	DIVISION STREET DELI
18	PAO BOUTIQUE
20	CLARIDGE BROKERAGE
	IMPERIAL STAMP & COIN INC
	NEW ROCHELLE COIN STAMP & JEWELRY EXCHANGE
22	VINCENT'S ITALIAN RESTRNT & PIZZERIA
24	BENITO HAIR DESIGN
	DINO & DAN BARBER SHOP
30	ABHILASH INDIA CUISINE
33	CHIAVERINI, P, PET GROOMING
	PATTI'S GROOMING BOUTIQUE & SUPPLIES
	TROPICAL GROCERY STORE
36	DADSONS HOME IMPROVEMENTS
37	RESUME CENTER THE
38	NEW ROCHELLE IRISH BENEVOLENT SOC
40	AIDING CAREGIVERS OF THE ELDERLY INC
41	AMC PRINTING
43	ALEX SHOE REPAIR
	ATTILIOS BARBER SHOP
61	A M ADVANCED PEST CONTROL INC
	NORTHEASTERN FUEL OIL CO
112	NEW ROCHELLE HIGH SCHOOL OF RELIGION
	RELIG
120	ST GABRIEL'S CHURCH
415	GENERAL WATERWORKS-N Y DIST

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 1995

280	CALLENDER, J HOLLIGAN, ATTY
	DAKWAM NEW YORK IMPORT & EXPORT INC
286	HUMANE SOCIETY THRIFT SHOP
288	LAVOZ LATINA
290	BIBLE WAY CHURCH
292	FAITH HOPE & CHARITY
294	AUTO INSURANCE SPECIALISTS
	AUTO INSURANCE SPECIALISTS, INSURANCE
296	FLOWERS BY SUTTON
	SUTTON FLOWERS
300	HENRY MORGAN CUSTOM UPHOLSTERS
304	VICTORIA SEWING
308	BASS UPHOLSTERERS SUPLS
	FOAM RUBBR HDQTRS
310	NEW ROCHELLE RESTRNT SUPL INC
311	SENIOR PERSONNEL PLACEMENT BUR INC
	TRINITY COOPERATIVE NURSRY SCHL
	TRINITY-ST PAULS EPISCOPAL CHURCH
	WESTCHESTER COMMUNITY OPPORTUNITY PROGRAM
316	ESSIE'S
	MODERN HARDWARE & PAINT
	PARK SPORTING ARMS
328	SOLID STATE AUDIO & TV
330	NICK'S DELI & GROCERY
348	JONES EXTERMINATING INC

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 1995

1 NEW STATION CLEANERS

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DIVISION ST 1992

2	ADATO, L
	CONTE, DEREK
	HAIR FACTORY INC
	MACASSAR, AUNTIE
	PERLMUTTER, MERLE
6	BORDAS ART & FRAME SHOP INC
	GREENE GALLERY INC
7	FRED'S BEAUTY SALON
8	CHILDRENS SVCE LEAGUE THRIFT BOUTIQUE
9	HAIRSTYLES ONLY
	MARTINEZ, SIXTO
	PULIDO, RAQUEL
	TANG, LILA
10	HEADS TOGETHER
	HEADS TOGETHER CORP
11	LUSO AMERICA FISH MKT
12	HEALTHY GLOW TANNING SPA
14	WEST ROCHELLE TRAVL AGNCY INC
15	DAN'S CARPET CO
	LEE, FAY
	VELA, JOSEPH VINCENT
	WATKINS, EDWARD
	YEUNG, KEE
16	SIDE STREET DELI LTD
18	BEST BUY DISCOUNT
20	CLARIDGE BROKERAGE
	MARSHALL HUGH S INC, OPTCN
	NEW ROCHELLE COIN STAMP & JEWELRY EXCHANGE
	SCHNEIDER, LAWRENCE, OPTCN
22	VINCENTS'S ITALIAN RESTRNT & PIZZERIA
24	BENITO HAIR DESIGN
	DINO & DAN BARBER SHOP
27	ALVAREZ, JUAN
	BEDOYA, CLIUDIA
	CANTERO, NORA
	CANTERO, SARMETO
	CASTELLANOS, MEDARDO V
	CEJA, JESSE RIVEL
	GOTTI, J
	LOPEZ, AMANDA
	MERGONI, GUILLERMO
	MESA, LUIS E
	PINEDA, SALVADOR
	PINZON, N
	VAIL, ROBERT K
	YOMAZZO, HENRY
30	ABHILASH INDIA CUISINE
33	ARREOLA, RICARDO U
	CHERUVATHOOR, JOSEPH
	CHIAVERINI, P, PET GROOMING

DIVISION ST 1992 (Cont'd)

33	MASCARENHAS, WILFRED T
	O'SULLIVAN, MARY
	PATTI'S GROOMING BOUTIQUE & SUPPLIES
	TROPICAL GROCERY STORE
	VARGHESE, JOJO
35	A J B CATERING
	CABRERA, VICENTE
	NEW ROCH PORK STORE
	PORK STORE NEW ROCHELLE
	SIQUEIRA, ALAOR
	WESTCHESTER IRISH CNTR
36	DADSONS HOME IMPROVEMENTS
37	RESUME CENTER THE
38	NEW ROCHELLE IRISH BENEVOLENT SOC
40	AIDING CAREGIVERS OF THE ELDERLY INC
41	AMC PRINTING
	LET'S DANCE, GIFTS
43	ANDERSON, D
	ATTILIOS BARBER SHOP
	CEBALLOS-BENJUMEA, ALDEMAR
	JEFFRIES, RAYMOND
	SIERRA, JANETH
48	NASCIMENTO, JOSE
112	NEW ROCHELLE HIGH SCHOOL OF RELIGION
	RELIG
120	ST GABRIEL'S CHURCH
415	GENERAL WATERWORKS-N Y DIST
2729	PEREZ, JESUS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

HUGUENOT ST 1992

245	GLICK HENRY B, OFC SUPLS
	LIBBY CORINI, RL EST
	PERSHING SQ PLANNING & INVESTING CORP
	TOMORROW, NEWSPAPER
	TOMORROW, NEWSPR
	WANDERMAN PHILIP L, ADVTG
278	D & F GROCERY
280	AMERICAN RIBBON CO
	B & S ASSOCIATES
	CALLENDER, J HOLLIGAN, ATTY
	DAKWAM NEW YORK IMPORT & EXPORT INC
	KOCH EMPLOYMENT AGENCY
288	ADJOYI, YAO
	CHIN, MICHAEL
	LAVOZ LATINA
	OCHOA, RAPHAEL
290	BIBLE WAY CHURCH
294	NORMA'S HAIR DESIGN
296	DILLON, JOHN
	FLOWERS BY SUTTON
	HOHL, H
	LEDDY, MARY
	OCONNOR, MAURICE
	SCARANGELLA, D P
	SUTTON FLOWERS
300	HENRY MORGAN CUSTOM UPHOLSTERS
306	CAPPARELLE, M
	COOPER, M
	EVANS, J
	EVANS, L
	FISHER, PEARLIE S
	GAINES, LOUIS T
	GRAY, ESTHER
	HAWKINS, BARBARA
	HYLEN, R M
	MASKIE, JOHN
	MINER, JAS
	MIRANDA, S
	SUSSMAN, B
	TAYLOR, HALLIE
308	BASS UPHOLSTERERS SUPLS
	FOAM RUBBR HDQTRS
310	NEW ROCHELLE RESTRNT SUPL INC
311	CASHER, RAYMOND
	TRINITY COOPERATIVE NURSRY SCHL
	TRINITY-ST PAULS EPISCOPAL CHURCH
	WESTCHESTER COMMUNITY OPPORTUNITY PROGRAM
316	ESSIE'S
	MODERN HARDWARE & PAINT
326	JONES EXTRMNGTG INC

HUGUENOT ST 1992 (Cont'd)

328 SOLID STATE AUDIO & TV
330 EDWARDS EVANSTON
FIRST IMPRESSION
JAD INC CENTRE D'AFFAIRES
347 A & D CLNG SVCE
ALLEN, TOMMIE
BROOKS, G M
FINNEY, JAMES
HARDING, BERYL
MCCLEAN, JAMES
MILLER, MARY
NELSON, K
NEWTON, LEWIS M
REYNOLDS, S
RIFFE, ANN M
ROSS, ESTELLA
SCOTT, MURDELL
TAYLOR, HALLIE
VAUGHN, RENEE
WILLIAMSON, V
YOUNG, ANNIE
YOUNG, J
348 BACK STAGE LTD

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

STATION PLZ 1992

1 NEW STATION CLEANERS

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1987

17	★	P&P Fruit&Veg Mkt	.78	235-2024
19		Dorothy Tucker	.83	632-1336
39		Janet Mejia	⌑	636-5178
41		David Rabius	–	632-3155
42			NP	
43		Lajos Bagi	.79	633-7525
44		Joseph Poirier	.72	636-8286
		Joseph Poirier III	.83	576-6938
48		Jose Martins	.79	636-4897
		Joao Prazeres	.74	576-2660
		Luis Quintero	⌑	633-1458
		Manuel Simoes	.83	633-9216
60			NP	
61	★	AAA Answering Svce	.85	636-4300
	★	ABC Bldg Supls	.85	636-2737
	★	Accurate Prof Answ	.85	937-5560
	★	Advanced Pest Con	.82	636-5811
	★	All Pro Alumimum	⌑	633-2744
	★	Alps Air Cond Inc	–	633-8430
	★	Archer Exchange		636-8424
	★	City Window Clng	.85	632-1683
	★	Complex Sys Softwr	⌑	576-3480
	★	County Answrng Svc	–	664-7700
	★	Diamond Decorators	.74	636-8426
	★	Edax Intrntl	–	576-3117
	★	Graham Abstract Co	.85	946-2638
	★	Dr E S Greenwald	–	632-2124
	★	Kleen Sweep	.85	633-2786
	★	Messgs By Radio	.85	636-4300
	★	Northeastern Fuel	.75	636-8740
	★	Pintard Tel Exch	.85	636-4300
	★	Proud Painters	.85	636-4300
	★	Public Coin Laundr	.85	939-8591
	★	Philip Sena Rprs	.79	237-7238

MAY NOT BE KEY PUNCHED ENTERED INTO A COMPUT

g To The Street ★ — Business Listing CT — Census Trac

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1987

61	★ **Tuckahoe Windw Cln**	**.85**	**633-2785**
	★ **Peter Wekerle**	**.83**	**235-3740**
64	Jose Alves	.82	636-7365
	A M Roth	.80	235-9614
67	Muzaffer Fidan	.82	633-7396
68	Luis Jose	.81	235-6952
	Seth Ruzi	.85	576-2126
71	James Miranda	.72	235-8347
72	Anthony Gelsomino	.76	632-2522
75	J Cifra	.85	576-7427
76	Karen Arent	¤	576-7869
	Terry C Sawchuk	.85	235-2486
79	Jens Burre	.59	636-2262
	Steven Coccodrilli	¤	576-7458
	Catherine Ziegler	¤	636-4309
80	George Goetz	.83	632-9725
	Jack Quigley	.84	632-3374
83	Bryan Eccleston	-	235-9619
84	Francis J Arland	.85	235-7792
	C L Buchberger	¤	235-0967
	Mark Salta	.84	235-6358
88	Frank Grillo	.82	235-5784
	Frank Rembach	-	632-9281

50 RESIDENCE 37 BUSINESS


Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

HUGUENOT ST 1987

249	★	**F H Connelly Aty**		**632-9300**
	★	**F H Connelly Jr**		**632-9300**
	★	**E A Davidson Aty**	83	**632-9300**
	★	**K G Davidson Aty**		**632-9300**
	★	**A F Fanelli Aty**		**632-9300**
	★	**Douglas R Hoyt Aty**	74	**632-9300**
	★	**Charles K McGoey**	83	**632-9300**
	★	**R J McGoey Aty**	74	**632-9300**
	★	**McGovern&Asc Aty**		**632-9300**
	★	**Soll Connelly&Asc**		**632-9300**
	★	**John A Vasile Aty**	77	**632-9300**
251			NP	
253		John Dillon	¤	235-9634
	★	**McKiernans Bar**		**636-9789**
		D L Scott	83	632-8758
		Fred E White	85	235-2632
55		**LAWTON**		
255	★	**Portugese Amer Clb**	85	**636-4100**
257	★	**Schindels**		**632-9666**
261	★	**Franks Musicl Exch**		**632-5072**
263		Humberto Arias	¤	632-6134
		Sichan Kim	¤	235-5918
	★	**Modern Hardwre&Pnt**	79	**632-8060**
		Oscar Motolinia	¤	235-8506
		M Torres	¤	576-3252
265		Carl F Bollinger	74	632-6160
	★	**J McGovern&Co Plbg**		**632-1839**
		Fredk L Richter Jr	84	576-2964
266			NP	
267	★	**El Tequila**	81	**632-9340**
271	★	**Renaissance Projct**	80	**235-8048**
273	★	**Jac-Q Enterprises**	¤	**633-5763**
60		**MECHANIC**		
277	★	**V&G Auto Parts**	85	**636-6068**
278	★	**Daisys Chickn Plr**	83	**632-9198**
280	★	**J H Callender Aty**		**636-2617**
	★	**Neufville Rl Est**	85	**633-1013**
281	★	**Wchstr Platg&Plshg**		**636-7137**
282			NP	
283		Leon Drew	¤	632-3391
284	★	**Rainbow Records**	¤	**636-0711**
285		Loris Crawford	83	235-8316
		Pauline Crawford	¤	576-7556
	★	**King Fish Aquatic**	81	**235-9005**
		Jesus Naba	¤	633-3801

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

STATION PLZ 1987



● STATION PLZ N 10801

New Rochelle PO

1- 99 CT 60 $D..H15

1★NW Sta Cleaners . . . ¤ 636-4677
★Paper Train Ltd 82 636-8420
NO #★Blue Bird Taxi Sv . . .79 834-4244
NO #★Blue Bird Taxi Svc . .75 632-0909
NO #★Fotomat Corp 78 636-7877
NO #★Jartran Trk Rental . .80 235-7358
NO #★Littel Caboose 84 633-7242
NO #★Station Parking 78 235-7358
NO #★U-Sweep of America .78 235-7358
NO #★Joseph Wasley 80 632-8600
NO #★Waslikoff&Sons Inc . .80 632-8600

11 BUSINESS

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1982

28★West Roch Trvl Agy . . . 633-7275
33 Ricardo U Arreola 79 235-8415
Marta Fajardo . . . . . .¤ 576-1527
Marion Gallagher 65 235-0340
★A Levine Bookbndr 235-1420
Mary OSullivan 67 235-6590
Juan Reano 79 633-7007
★Tropical Grocery 636-3697
Ronald Wallace 75 235-9772
35★New Roch Pork Stre . . . 632-3442
C L Pinkowski . . . . . .¤ 632-7707
★Wchstr Irish Centr 636-9776
36★Hayes-Kathryn-Frey 636-8200
★Kathryn Hayes-Frey 632-7809
★K Hayes-Freys 636-8200
38★Place of Yestr Yrs 235-6150
39★Lillies Beauty Lng 636-9151
298 HUGUENOT
40★Marcel Eisen 636-0593
★Marcel&Susan Tlrs 636-0593
43★Attilios Barbr Shp 576-0090
Miguel Calvache 79 636-8464
Clark Cowie 78 636-3564
Luisa Murillo . . . . . .¤ 632-0446
Michael Vick . . . . . .¤ 636-5249
55★Bartlett T V&Air 636-7254

© COPYRIGHT INFORMATION ON THIS PAGE MAY
¤ — New Listing to the Directory - — New Listin

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1982

57 ★Diamond Glass Corp . . . 576-2121
61 ★Benro Contr Corp 235-4262
★Ger Industries . . . . . - 633-7799
Joseph Greenstein 69 235-4676
★Visual Home Inspcn 337-7788
★Wschstr Time Clock 636-1111
67 68 . . . . . NP
71 Gilberto Vargas . . . . . ¤ 235-0236
Antonio Vazquez . . . . . ¤ 632-0170
76 83 84 . . . . . NP

20 UNION AV

112 ★New Rcli Hi Sc REL . . . 632-8336
120 ★St Gabriels Chr 632-0211
★St Gabriels Church 632-1802
Rev Joseph Traube 75 235-2930
★Westchstr Hspnc Cl 632-3068

14 WASHINGTON AV

175 . . . . . NP
415 ★General Waterwork 632-0901

44 Residence 52 Business

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

HUGUENOT ST 1982

245 ★A&M Assocs Ltd 235-4672
Thomas V Burke 78 636-8205
★Chempro Prods Inc . . . .¤ 235-1211
★Corini&Grassi Ins 235-0777
★O A Corini Agency . . . .¤ 235-0777
★R O Corini Atty 235-0784
★Custom Specialty C 636-4646
★H B Glick Ofc Sups . . . 632-2300
★C Libby Rl Est 235-0777
★Manhatn Life Ins 235-0777
★O Mueller Inc 632-2300
★New Rochll Est Lst 636-5131
★NW Roch Typewrtg 632-6580
★P Palumbo Pub Sten . . . 632-6580
★Pershing Sq Invstg 235-0777
★Regar Land Fill 235-5015
★Sakal Gallers Ltd 632-5667
★P L Wanderman Advg . . 636-4646
249 ★F H Connelly Atty 632-9300
★F H Connelly Jr 632-9300
★H G Davidson Atty 632-9300
★A F Fanelli Atty 632-9300
★Douglas R Hoyt Aty . . . 632-9300
★R J McGoey Atty 632-9300
★McGovern&Asc Attys . . . 632-9300
★Soll& Assoc Attys 632-9300
★John A Vasile Atty 632-9300
251 . . . . . .NP
253 ★McKiernans Bar 636-9789
★Shore Trnsprtn Inc 632-3444

55 LAWTON

255 ★NW Roch Maennerchr . . 636-9086
257 ★Schindels Army&Nvy . . . 636-9844
261 ★Franks Musicl Exch 632-5072
263 ★Modern Hardwre&Pnt . . . 632-8060
Santa Montesinos 79 235-7652
265 Carl F Bollinger 74 632-6160
★J McGovern&Co Plbg . . . 632-1839
Frances H Reilly 71 633-7723
Matthew J Reilly 633-7723
266 . . . . . .NP
271 ★Renaissance Projct . . . . .- 235-8048
273 ★Gales Army&Nvy Str . . . 636-9612
★Gales Ct Rate Army . . . 636-9612

60 MECHANIC

277 ★Discount Clothing 235-2224
★Fromberrys Clthng 235-2224
278 ★Chicken Castle Inc 636-1230
279 ★Pasquale Patti 235-4382
★279 Delcatesn Crp 636-9400
280 ★J H Callender Atty 636-2617
★The Photo Loft Inc 632-9731
★Spalo Signs 636-8624
281 ★Wchstr Platg&Plshg 636-7137
282 . . . . . .NP
283 John Epps . . . . . .¤ 636-2719
284 ★Bobs Fish Market 636-8971
285 ★New Rochll Rst Spl 636-6661
Ronald Potter 79 636-4988
286 ★Hoffsteds Unsx SLN 632-5685
287 ★Koch Employ Agncy 235-1650
288 La Tina Lavoz 79 633-9506

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

STATION PLZ 1982

STATION PLAZA N 10801
New Rochelle PO
1- 99 TZ 60 SE..R 4
113680

1	★Between The Lines	235-3937
	★Jartran Truck Rntl .....¤	963-9062
No #	★Blue Bird Taxi Sv	834-4244
No #	★Blue Bird Taxi Svc	576-3800
No #	★Blue Bird Taxi Svc	632-0909
No #	★Discount Rent-A-Cr	235-7358
No #	★Fotomat Corp	636-7877
No #	★Jartran Truck Rntl .....¤	636-6707
No #	★National Car Rentl	235-7358
No #	★Corey J Platzner	235-7770
No #	★H K Platzner	235-7770
No #	★Platzner Orgnztn	235-7770
No #	★Station Parking	235-7358
No #	★TJS Sta Lounge Inc ....¤	636-2733
No #	★U-Sweep of America ...	235-7358
No #	★Joseph Wasley .....¤	632-8600
No #	★Waslikoff&Sons Inc ....¤	632-8600

17 Business

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1977

28	★ West Roch Trvl Agy		633-7275
30	★ Halberts Linoleum		NE6-7235
33	★ Demelo Groceries		636-3697
	Mrs Elizabeth Dews	8	235-6920
	Marion Gallagher		235-0340
	★ A Levine Bookbndr		BE5-1420
	Mary OSullivan	7	235-6590
	John L Sullivan	1	636-0516
	Ronald Wallace	5	235-9772
35	★ New Roch Pork Stre		NE2-3442
	William Scott		636-4228
	★ Wchstr Irish Centr		636-9776
36	★ Hayes-Kathryn-Frey		NE6-8200
	★ Kathryn Hayes Frey		NE2-7809
	★ K Hayes-Freys		NE6-8200
37	★ Blue Jay Commnctns	¤	576-1818
39	★ Lillies Beauty Lng		636-9151
	298 HUGUENOT		
40	★ Marcel Eisen		NE6-0593
	★ Marcel&Susan Tlrs		NE6-0593
41	M Hunter	–	235-6150
43	★ Attilios Barbr Shp		576-0090
	Agnes M Cowie		NE6-3564
	A Ortiz	¤	576-0148
	L D Rodriguez	¤	235-5503
57	★ Diamond Glass Corp		576-2121
61	Joseph Greenstein	9	235-4676
	★ Westinghouse Elec		738-5199
65	★ S Alex&Son Plmbg		632-3183
	★ Alex Scott&Son		632-3183
67		NP	
71		NP	
76		NP	
83		NP	
84		NP	
	20 UNION AV		
112	David Downs	5	632-3696
120	★ Catholic Charities	¤	576-0504
	Rev Dennis Keane	1	576-1828
	★ St Gabriels Chr		NE2-0211
	Rev F P Sexton	¤	576-2579
	Rev Joseph Traube	5	235-2930
	14 WASHINGTON AV		
175		NP	
185	★ Community Chest		632-4212
	★ Community Chest		632-4212
	★ United Way NW Rchl		632-4212
415	★ General Waterwork		632-0901
	44 Residence		56 Business

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

HUGUENOT ST 1977

245	★	A&M Assocs Ltd	235-4672
	★	Corini&Grassi Ins	235-0777
	★	Custom Specialty C	636-4646
	★	H B Glick Ofc Sups	632-2300
	★	C F Heaphy Paper ¤	576-0640
	★	C F Heaphy Co Ppr ¤	576-0640
	★	Larochelle Wdw Clg	632-9128
	★	Libby Corini	235-0777
	★	Manhatn Life Ins	235-0777
	★	O Mueller Inc	632-2300
	★	New Roch Realty Bd	636-5131
	★	NW Roch Typewrtg	632-6580
	★	P Palumbo Pub Sten	632-6580
	★	Pershing Sq Invstg	235-0777
	★	P L Wanderman Adv	636-4646
249	★	F H Connelly Atty	NE2-9300
	★	F H Connelly Jr	NE2-9300
	★	H G Davidson Atty	NE2-9300
	★	A F Fanelli Atty	NE2-9300
	★	Douglas R Hoyt Aty	NE2-9300
	★	R J McGoey Atty	NE2-9300
	★	McGovern&Asc Attys	NE2-9300
	★	J R McGovern	NE2-9300
	★	R McGovern Atty	NE2-9300
	★	McGovern&Asc Attys	NE2-9300
	★	Soll&Assoc	NE2-9300
251		Michl E Tesmacher	NE3-8650
253		D L Scott 5	632-8825
		55 LAWTON	
255	★	NW Roch Maennerchr	NE6-9086
257	★	Schindels Army&Nvy	636-9844
260	★	McKiernans Bar	636-9789
261	★	Franks Musicl Exch	632-5072
263	★	Modern Paint&Glass	NE2-8060
		Harvey Westendorf	BE5-4265
	★	H Westendorf Pnts	NE2-8060
265		Carl F Bollinger 4	632-6160
	★	J McGovern&Co Plbg	NE2-1839
		Frances H Reilly 1	NE3-7723
		Matthew J Reilly	NE3-7723
		B Terranova –	235-5748
266		Alfonse Christian 2	235-1085
	★	Federation Thrift	632-5751
267	★	Lawton Restrnt	636-9043
	★	Lawton Restaurant	636-9127
268	★	Glatzer Indust	576-2700
271	★	New England Bath ¤	636-8095
273	★	Gales Army&Nvy Str	NE6-9612
	★	Gales Ct Rate Army	NE6-9612
		60 MECHANIC	
277	★	Discount Clothing	BE5-2224
	★	Fromberrys Clthng	BE5-2224
	★	Raymond Lerner	BE5-2224
278	★	Chicken Castle Inc ¤	NE6-1230
279	★	279 Delcatesn Crp	636-9400
280	★	J H Callender Atty	NE6-2617
	★	The Photo Loft Inc	632-9731
	★	Royal Crwn Drv Sch	636-7878
	★	Spalo Signs	NE6-8624
	★	Wstcstr Yng Judea	636-3668

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

STATION PLZ 1977



STATION PLAZA N 10801
New Rochelle

	1	★	Between The Lines	¤	235-3937
No	#		Corey J Platzner		235-7770
No	#	★	Platzner Orgnztn		235-7770
No	#	★	Railroad Sta Ounge		632-7117
No	#	★	Whistlestp Spirits		633-9308
No	#	★	Blue Bird Taxi Svc		576-3800
No	#	★	Blue Bird Taxi Svc		632-0909
No	#		Herbert B Platzner	5	235-7770
No	#	★	Station Parking	¤	235-7358
No	#	★	U-Haul Co	–	235-7358

2 Residence 8 Business

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

DIVISION ST 1972

28*AIRLINE CHARTER 6323366
*L L FIRRANTELLO 6323366
*WEST ROCH TRVL AGY 6337275
29*TROPICANA LNDROMAT NE69005
30*HALBERTS LINOLEUM NE67235
33 MRS ELIZABETH DEWS
8 2356920
MARION GALLAGHER 5 2350340
R M KENDIG 7 6337735
MRS ALICE N KINZEL NE22144
KURT W KINZEL 4 NE22144
MARY OSULLIVAN 7 2356590
JOHN L SULLIVAN ¤6360516
*THE HSE OF ATREUS NE27392
RONALD WALLACE 4 8E52780
35*NEW ROCH PORK STRE NE23442
A F RAINONE 0 2351074
RICHARD SCOTT ¤6321577
WILLIAM SCOTT 6364228
*WCHSTR IRISH CENTR 6369776
36*K HAYES-FREYS CLNR NE27809
*K HAYES-FREYS NE68200
37*YOUR PHOTO -6362922
•• 298 HUGUENOT ••
40*MARCEL EISEN NE60593
*MARCEL&SUSAN TLRS NE60593
41*KEEFERS FISH MKT NE21570
43*ATTILIOS BARBR SHP 5760090
PAULINE CLAPS NE37392
TIMOTHY CONNELL NE62355
AGNES M COWIE NE63564
JOHN J GENOY NE38287
HUGH MCMAHON 8E56860
55*BARTLETT TV 6367254
57*DIAMOND GLSS FRNTS 6364900
*DIAMOND PLATE GLSS NE64900
61 JOSEPH GREENSTEIN9 2354676
65*S ALEX&SON PLMBG 6323183
*ALEX SCOTT&SON 6323183
83 LAUREL ECCLESTON 9 2356136
•• 20 UNION AV ••
112 M K JENSEN 0 6323696
120 REV DENNIS KEANE ¤5761828
JOHN LYNCH 0 6337607
*ST GABRIELS CHR NE20211
REV PATK J TEMPLE 2359102
•• 14 WASHINGTON ••
•• AV ••
175 R B DOYLE ¤6321119
*YOUNG MENS CHRISTN NE21818
185*COMMUNITY CHEST 6324212
*UNITED FUND NW ROC 6324212
47 RESIDENCE 56 BUSINESS

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory


HUGUENOT ST 1972

```
••  BRIDGE                    ••
245*A&M ASSOCS LTD          2354672
   *CROWN SHIRT CO          NE20592
   *CUSTOM SPECIALTY C      6364646
   *G&B CONTRCTRS           NE26232
   *H B GLICK OFC SUPS      6322300
   *G JOHNSEN SUPL CRP      2354513
   *C K JOHNSON RL EST      NE26232
   *LAROCHELLE WDW CLG      6329128
   *O MUELLER INC           6322300
   *NEW ROCH REALTY BD      6365131
   *NW ROCH TYPEWRTG        6326580
   *P PALUMBO PUB STEN      6326580
   *VICTORY MTL LF INS      NE26232
   *P L WANDERMAN ADVG      6364646
249*F H CONNELLY ATTY       NE29300
   *F H CONNELLY JR         NE29300
   *H G DAVIDSON ATTY       NE29300
   *A F FANELLI ATTY        NE29300
   *J A GEOGHEGAN ATTY      NE29300
   *MCGOVERN&ASSOCS         NE29300
   *J R MCGOVERN            NE29300
   *R MCGOVERN ATTY         NE29300
   *MCGOVERN&ASSOCS         NE29300
   *SOLL&ASSOCS             NE29300
251 JOHN T P SIU         0  NE64816
    MICHL E TESMACHER       NE38650
253*JAY ESS REALTY CO       6367384
   *S J KALMANSON ATTY      6367384
••  55 LAWTON                ••
255*NW ROCH MAENNERCHR      NE69086
257*SCHINDEL MRCNTL CO      NE69844
260*MCKIERNANS BAR          6369789
261*FRANKS MUSICL EXCH      6325072
263*MODERN PAINT&GLASS      NE28060
    HARVEY WESTENDORF       BE54265
   *H WESTENDORF PNTS       NE28060
264*METHADONE MAINT TR□6328300
   *GUIDANCE CENTER    □6328300
265*T D BURKE PLMBR         NE21839
   *J MCGOVERN&CO PLBG      NE21839
    FRANK POLIMENI          5760167
    FRANCES H REILLY    □NE37723
    MATTHEW J REILLY        NE37723
    BERT TERRANOVA JR   -2355748
266*FEDERATION THRIFT       6325751
    GLADYS GLADNEY     -6327262
    JANIE MURRAY            6361794
267*TONYS RESTRNT           6369646
268*NANCYS FASHION INC      6369881
   *NANCYS FASHION INC      6325364
273*GALES ARMY&NVY STR      NE69612
   *GALES CT RATE ARMY      NE69612
••  60 MECHANIC              ••
277*DISCOUNT CLOTHING       BE52224
   *FROMBERRYS CLTHNG       BE52224
   *RAYMOND LERNER          BE52224
278*CHICKEN DELIGHT         NE61230
```

AS AUTHORIZED IN WRITING BY THE PUBLISHER.

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

STATION PLZ 1972


STATION PLAZA N 10801

NEW ROCHELLE

*BENZ TRAVEL AGENCY-6338016

*GREYHOUND BUS LNS ¤6338016

2 BUSINESS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

DIVISION ST 1964

30-34 Halbert's Linoleum Arts Inc
NE6-7235
33 Phillips Marie Hair Stylist
NE2-7392
Berry Sarah A Mrs drsmkr
NE6-5542

Apartments:

1 Pettersen Alf NE6-3038
2 Vacant
3 Vacant
4 DiBella Marie Mrs NE2-9671
5 Young Fred BE5-1389
6 Smith Julia Mrs BE5-0553
7 Schoonover Buford C NE2-3246

Street continued

35 Little Picture Shop NE2-7564
Westchester Irish Center tavern
NE6-9896

Apartments:

1 Lund Christian NE2-7564
2 Scott Wm NE6-4228
3 Bartels Henry E NE3-7149
4 Mason Geo A NE3-8416

Westchester pl ends

36-38 Kathryn-Hayes-Frey's Inc cln
NE2-7809
39 Vacant store
40 Vacant
41 Keefer's Fish Mkt NE2-1570
42 Marcel & Susan's Fashion Center
NE6-0593
43 Evanson Helen J Mrs NE3-6775

Target Street	Cross Street	Source
-	✓	Polk's City Directory

DIVISION ST 1964

Claps Pauline A NE3-7392
Thompson Gertrude Mrs
Ciardullo Rosina Mrs NE6-8225
Dory Dora
Cowie Agnes Mrs NE6-3564
Genoy John J NE3-8287

Huguenot crosses

55 Gotsch & Steinmetz Agency real est and ins NE6-7390
57 Diamond A & Sons Inc glass NE6-4900
65 Zari Fred Motors Inc NE2-0430

Railroad pl crosses

28

Union av crosses

112 Downs David D NE2-3696
120 StGabriel's Rectory © NE2-0211

Washington av crosses

New England crosses

Van Guilder av begins

Burling la crosses

175 Young Men's Christian Assn NE2-1818
185 Visiting Nurse Assn of New Rochelle Inc NE2-3722

Target Street	Cross Street	Source
✓	-	Polk's City Directory

HUGUENOT ST 1964

Street continued

245-247 Mueller O Inc ofc supplies
NE2-2300
246 New Rochelle Check Cashing Serv
BE5-6786
248 Saxton's Barber Shop NE6-9540

Lawton ends

249-51 **McGovern Building**
McGovern Vincent and Connelly
252 Vacant
253 All American Typewriter Co
NE2-2763
All American Furn
Hock Loretta Mrs
255 Vacant
256 Vacant
257 Schindel's Men's & Boy's Weat
NE6-9844

Sherwood la crosses

258 Vacant
260 Hyfra Grill Inc NE6-9789
261 Frank's Musical Exchange
NE2-5072
263 Modern Paint & Glass Co
NE2-8060
Westendorf Harvey © BE5-4265
264 Schombert J D Inc furn NE6-6885
265 McGovern John and Co Inc plmbs
NE2-1839
O'Reilly Agnes Mrs NE2-5018
Reilly Margt Mrs NE3-7723
266 Raben J H paints NE2-3888
Hamilton Rose Mrs NE3-7696
267 Tony's New Rochelle Restr &
Sandwich Shop NE6-9646
268 Little Red Rose Tavern NE6-9471
Carolyn Dress Shop NE3-9365
269 Vacant
271 Frank's Barber Shop NE3-9931
273 Gale's Army & Navy Store
NE6-9612
275 Vacant

PHASE I ENVIRONMENTAL SITE ASSESSMENT

DRAFT FOR DISCUSSION PURPOSES ONLY

HALSTEAD STATION
(VACANT LAND)
255 Huguenot Street
New Rochelle, Westchester County, New York 10801

Prepared for:
Walker & Dunlop
and
Freddie Mac

September 28, 2020
Project Number: WALKGA136.09

BLACKSTONE
CONSULTING LLC

Our Insight. Your Success.

BLACKSTONECONSULTING.COM

TABLE OF CONTENTS

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS i
EXECUTIVE SUMMARY ii
1.0 INTRODUCTION 1
1.1 Purpose 1
1.2 Special Terms and Conditions 2
1.3 Scope of Services 2
1.4 Significant Assumptions and Data Gaps 3
2.0 USER PROVIDED INFORMATION 5
2.1 Reason For Performing the Phase I ESA 5
2.2 Environmental Liens and Activity And Use Limitations (AULs) 5
2.3 Specialized Knowledge, Commonly Known & Degree of Obviousness 6
2.4 Value Reduction for Environmental Issues 6
2.5 Owner, Key Site Manager, and Occupant Information 6
2.6 Past Owners, Operators and Occupant Interviews 7
2.7 Reliance 7
3.0 SITE DESCRIPTION 8
3.1 Site Characteristics and Features 8
3.2 Utilities 8
4.0 VICINITY RECONNAISSANCE 10
5.0 PHYSICAL SETTING 11
6.0 HISTORICAL INFORMATION REVIEW 12
6.1 Historical Fire Insurance Maps 12
6.2 Aerial Photographs 13
6.3 Historical Topographic Maps 14
6.4 Agency Records, Interviews and Other Historical Sources 14
6.5 City Directories 15
6.6 Environmental Lien/AUL Search 16
6.7 Previous Environmental Reports 16
6.8 Historical Information Conclusions 17
7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW 19
7.1 Federal, State, Local, Tribal and Proprietary Databases 20
7.2 Unmappable Facilities 21
7.3 Affirmation 21
7.4 Environmental Database Search and Review Conclusions 22
8.0 SITE INSPECTION 23
8.1 Underground Storage Tanks (USTs) 23
8.2 Aboveground Storage Tanks (ASTs) 23
8.3 Chemicals and Materials Usage 23
8.4 Hazardous Wastes 24
8.5 Non-Hazardous Wastes 24
8.6 Polychlorinated Biphenyls (PCBs) 24
8.7 Wastewater Discharges 25

DRAFT

8.8 Stormwater Discharges 25
8.9 Pits, Ponds, and Lagoons (On-Site Process Water Discharge) 25
8.10 Wells 25
8.11 Underground Product Pipelines 25
8.12 Odors 26
8.13 Pools of Liquid 26
8.14 Stressed Vegetation or Stained Surfaces 26
8.15 Site Inspection Conclusions 26
9.0 ASTM NON-SCOPE CONSIDERATIONS 27
9.1 Asbestos-Containing Materials (ACM) 27
9.2 Lead-Based Paint (LBP) 27
9.3 Radon Gas 27
9.4 Apparent Mold Growth (AMG) 27
9.5 Lead In Drinking Water 27
9.6 Environmental Superlien 28
10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS 29

Appendices

Appendix A: Freddie Mac Multi-Family Seller/Servicer Guide Form 1103
Appendix B: Site Maps, Plans, and Photographs
- Site Location Map
- Site Plan
- Site Photographs

Appendix C: Historical Sources
- Historical Fire Insurance Maps
- Historical Aerial Photographs
- Historical Topographic Maps

Appendix D: Previous Environmental Reports
Appendix E: Environmental Database Search Report
Appendix F: Qualifications of Professionals

DRAFT

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

This Phase I Environmental Site Assessment (ESA) Report documents the research methodology used by qualified environmental professionals of Blackstone Consulting LLC (Blackstone) to identify *recognized environmental conditions* using the scope and limitations of ASTM Standard Practice E 1527-13, the Freddie Mac Phase I ESA Guidelines, and the September 14, 2020 proposal (Agreement) between Walker & Dunlop and Blackstone.

We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR 312, and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Inspected By:

_____ _____
John O'Connor Date
Senior Project Manager

Prepared By:

_____ _____
Lauren Beyrent Date
Project Manager

Technical Review and Concurrence By:

_____ _____
Akisha Staggers Date
Senior Project Manager

Oversight By:

_____ _____
Becky Renick Date
Principal

jh

DRAFT

EXECUTIVE SUMMARY

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the Halstead Station (Vacant Land) located at 255 Huguenot Street in New Rochelle, Westchester County, New York (site). The purpose of the Phase I ESA is to identify recognized environmental conditions (RECs) in general accordance with ASTM Standard E 1527-13, the Freddie Mac Multi-Family Seller/Servicer Phase I ESA Guidelines (Freddie Mac Phase I ESA Guidelines), and other agreed-upon ASTM Non-Scope Considerations (Business Environmental Risk Issues). It is understood that the site is being evaluated for loan considerations.

SITE INSPECTION

Name of Inspector: John O'Connor

Date of Inspection: February 3, 2020

Site Representative: Ms. Jessica Albasi, Property Manager and Mr. Lamont Harris, Maintenance Supervisor

SITE DESCRIPTION

Street Address: 255 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Parcel Number: 1-234-0001

Owner: New Rochelle Ind Dev Agency

Site Size: Approximately 0.46 acres

Site Use: The site consists of vacant land.

Year Built: Not Applicable (N/A)

Other Site Features: N/A

HISTORICAL INFORMATION

Reasonably ascertainable historical information indicates the site was initially developed with a residential structure prior to 1887. By the late 1800s/early 1900s, the site was developed with multiple commercial buildings along the northern portion and by 1930, the site was developed with commercial and office

DRAFT

buildings. Historical uses of the site included a laundry business (1896 only), a post office, hotel, restaurants, a theatre, retail storefronts, and offices. Between the 1950s and 1990s, the northwestern portion of the site was utilized for surface parking. These structures were demolished in the early-1990s, and the site was redeveloped in 2001 with a single-story extension of the present-day south adjoining apartment building and exterior amenities (pool, playground, etc.). The single-story extension contained amenities associated with the south-adjoining apartment building. The former site improvements were razed by 2019 and the site has been vacant since that time.

The north, east, and south-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, and a lighting company between approximately 1931 and 1951 prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures, including a "Chinese laundry" in 1896, and a hotel between approximately 1911 and 1951. The present-day surface parking lot to the adjoining east was constructed in the 1970s and the present-day Ruby Dee Park on Library Green was developed in the 2000s. The south adjoining properties consisted of multiple commercial structures, including a "Chinese laundry" in 1911, and was also utilized for surface parking in the 1950s through 1990s prior to the construction of the present-day apartment building and parking garage in 2001. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

SUMMARY OF FINDINGS

The site and adjoining properties were identified with retail laundry or dry cleaning operations in the late 1890s and early 1900s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. In addition, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. Based on the era of operation, absence of reported releases, and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities is not considered a REC.

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Freddie Mac Phase I ESA Guidelines, and the September 14, 2020 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*), *controlled recognized environmental conditions* (*CRECs*), or *historical recognized environmental conditions (HRECs*) in connection with the site. No further investigation is recommended.

This section is only intended to represent a brief summary of our findings and is not a detailed account of all the information provided in this report. The report should be reviewed in its entirety prior to drawing any final conclusions as to potential environmental conditions associated with the site.

DRAFT

1.0 INTRODUCTION

1.1 PURPOSE

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the Halstead Station (Vacant Land) located at 255 Huguenot Street in New Rochelle, Westchester County, New York (site).

The purpose of this Phase I ESA is to investigate and identify *recognized environmental conditions (RECs)* associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines RECs as:

The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property due to any release to the environment, under conditions indicative of a release to the environment, or under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions.

A *de minimis* condition is a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Additionally, this Phase I ESA was conducted to identify *controlled recognized environmental conditions (CRECs)* associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines CRECs as:

A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by a regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This Phase I ESA also was conducted to identify *historical recognized environmental conditions (HRECs)* associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines HRECs as:

A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This practice is generally intended for the User to satisfy one of the requirements to qualify for the *innocent landowner, contiguous property owner, or bona fide prospective purchaser* limitations on CERCLA

DRAFT

liability; that is, this practice constitutes all appropriate inquiries (AAI) into the previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312.

ASTM *Non-Scope Considerations (Business Environmental Risk Issues)* are detailed in Section 1.3 and outlined in the September 14, 2020 proposal and scope of work (Agreement) between Walker & Dunlop and Blackstone.

1.2 SPECIAL TERMS AND CONDITIONS

This Phase I ESA has been conducted in accordance with ASTM Standard Practice E 1527-13, the regulations at 40 CFR Part 312, and the Agreement between Walker & Dunlop and Blackstone. In addition, this Phase I ESA was conducted in accordance with the Freddie Mac Multi-Family Seller/Servicer Phase I ESA Guidelines (Freddie Mac Phase I ESA Guidelines). Qualifications of the professionals conducting this assessment have been provided in Appendix F.

Blackstone performed the professional services, obtained findings, rendered conclusions, and prepared recommendations in accordance with generally accepted practices of other environmental consultants undertaking similar assessments at the same time in the same geographical area.

Historical and environmental information pertaining to the site has been included in this report to the extent that such information is *practically reviewable*, as defined in the above-referenced standard practice.

1.3 SCOPE OF SERVICES

As detailed in the Agreement, this Phase I ESA was conducted in accordance with the industry standard ASTM Standard Practice E 1527-13 and as such in accordance with all appropriate inquiries (AAI) into the previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312. In addition, this Phase I ESA was conducted in accordance with the Freddie Mac Phase I ESA Guidelines. The Phase I ESA presented herein may vary from “guidelines” or “standards” required by organizations other than ASTM and Freddie Mac. This Phase I ESA included the following services:

1. A site inspection to identify and evaluate potential sources of RECs such as underground storage tanks (USTs), aboveground storage tanks (ASTs), equipment containing polychlorinated biphenyls (PCBs), waste and chemical storage areas, and wastewater and stormwater discharges. The inspection included observations for evidence of chemical spills, releases, or on-site waste disposal.
2. A review of site records and interviews with site representatives with regard to current and former site operations to identify known or potential environmental concerns.

DRAFT

3. A visual survey of the properties in the vicinity of the site to evaluate the potential for RECs at the site from these properties.
4. A review of historical information to identify RECs at the site from historic on-site and off-site uses. To the extent feasible under the conditions of the assessment, the historical information obtained included verbal information from the site and/or local agency representatives. In addition, some or all of the following records, where *publicly available* and *practically reviewable*, were reviewed: construction plans, zoning maps, building permits, property record cards, topographic maps, fire insurance maps, historical city directories, and aerial photographs.
5. A review of State and Federal environmental database information.

Blackstone also performed the following activities to identify ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) in addition to the ASTM requirements and as required by the Freddie Mac Phase I ESA Guidelines, and as required per the Agreement:

Document research, visual and/or sampling surveys, and interviews for the presence of:

- Asbestos-containing materials (ACM),
- Lead-based paint (LBP),
- Radon,
- Apparent mold growth (AMG),
- Lead in Drinking Water, and
- Environmental Superlien.

The scope of this Phase I ESA did not include surface water, soil, soil vapor, or groundwater sampling. Consequently, conclusions provided with regard to surface water, soil, soil vapor, and groundwater impacts are limited to those that can be formed based on a non-intrusive investigation. The absence of environmental hazards in the subsurface cannot be guaranteed based on conditions observed on the surface.

Where performed, the limited ACM, LBP, AMG, and radon surveys are intended to provide an indication of the potential for significant environmental issues associated with these ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*). Hidden materials or locations such as those inside walls, inaccessible attics, crawl spaces, and inside ductwork and piping were not evaluated. As such, these surveys should not be regarded as comprehensive surveys for demolition or renovation purposes or indoor air quality health risk assessments, vapor intrusion into buildings, or explosion hazards.

1.4 SIGNIFICANT ASSUMPTIONS AND DATA GAPS

The site inspection consisted of a walkover of the site perimeter and exterior site areas. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within locked utility vaults. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

DRAFT

The historical information reviewed did not confirm the first developed use of the site. *Data failure*, as defined by ASTM, has occurred in attempting to identify obvious uses of the site back to the first developed use, or back to 1940, whichever is earlier. Information regarding the use of the site prior to 1887 was not available from the *standard historical sources* (including available aerial photographs, fire insurance maps, property tax files, recorded land title records, USGS topographic maps, local street directories, building department records, or zoning/land use records). There were no other reasonably ascertainable historical sources available for review that were considered sufficiently useful. It is the opinion of Blackstone that the data failure does not represent a significant data gap that impacts our ability to identify RECs.

Conclusions stated herein are based upon publicly available information and other documented sources. Blackstone has assumed, where reasonable, that the information reviewed is true and accurate. Blackstone assumes no responsibility for inaccurate information that is not otherwise obvious in light of information of which Blackstone has actual knowledge. Blackstone's site observations are of the conditions observed at the time of the assessment.

Blackstone reviewed an environmental database search report. Blackstone's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, Blackstone's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site.

This report provides an estimation of groundwater flow direction at the site based on visual observations and topographical data. This assessment did not include groundwater sampling and water table elevation measurement. True groundwater flow direction can only be determined through direct measurement of groundwater elevations from properly installed on-site groundwater monitoring wells. The groundwater flow direction estimation should not be considered a true measurement of groundwater flow direction.

DRAFT

2.0 USER PROVIDED INFORMATION

As defined under ASTM Standard Practice E 1527-13, Walker & Dunlop and Freddie Mac are considered the "User" of this Phase I ESA report. To qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002 (the *"Brownfields Amendments"*), the User must provide certain information based on their relationship to the purpose of the due diligence and as required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31.

As part of this Phase I ESA, Blackstone requested certain information from the User. The User did not provide the requested information to Blackstone pursuant to the User's Responsibilities described in ASTM Standard Practice E 1527-13 (Section 6.0) and as outlined below in Sections 2.2 through 2.4. However, there is no reason to believe that the absence of the User provided information would significantly alter the findings or recommendations set forth in this report or be considered a significant data gap.

The owner's representative, Ms. Jessica Albasi, Property Manager and Mr. Lamont Harris, Maintenance Supervisor (collectively, the "Site Representative"), provided information about the site. The information requested, and associated responses are outlined below in Section 2.5.

2.1 REASON FOR PERFORMING THE PHASE I ESA

Blackstone understands that this assessment was performed for Walker & Dunlop for financing purposes. In addition, this assessment was performed for Freddie Mac in consideration of making a potential loan secured by the site. As such, this Phase I ESA was performed as an appropriate risk management and environmental due diligence review associated with a potential real-estate collateralized lending transaction.

2.2 ENVIRONMENTAL LIENS AND ACTIVITY AND USE LIMITATIONS (AULS)

With reference to environmental liens that are filed or recorded against the site (40 CFR 312.25) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an environmental lien search as part of the scope of work.

With reference to activity and use limitations (AULs) that are in place on the site or that have been filed or recorded against the site (40 CFR 312.26(a)(1)(v) and (vi)) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an AUL search as part of the scope of work. In accordance with ASTM E 1527-13, Blackstone reviewed an environmental database search report that included a search of institutional control and engineering control databases as further discussed in Section 7.0.

DRAFT

2.3 SPECIALIZED KNOWLEDGE, COMMONLY KNOWN & DEGREE OF OBVIOUSNESS

With reference to specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28), the User did not provide any information to Blackstone regarding specialized knowledge or experience related to the site or nearby properties.

With reference to commonly known or *reasonably ascertainable* information about the site (40 CFR 312.30), the User did not provide any information to Blackstone regarding commonly known or *reasonably ascertainable* information about the site that would help the *environmental professional* to identify conditions indicative of releases or threatened releases, such as:

1. Past uses of the site;
2. Specific chemicals that are present or once were present at the site;
3. Spills or other chemical releases that have taken place at the site; and
4. Environmental cleanups that have taken place at the site.

The User provided Blackstone with a previous environmental report regarding the site, which is further discussed in Section 6.7.

With reference to the degree of obviousness of the presence or likely presence of releases or threatened releases at the site, and the ability to detect releases or threatened releases by appropriate investigation (40 CFR 312.31), the User did not provide any information to Blackstone regarding *obvious* indicators that point to the presence or likely presence of releases at the site.

2.4 VALUE REDUCTION FOR ENVIRONMENTAL ISSUES

The User did not provide information with reference to the relationship of the purchase price to the fair market value of the site if contamination is known or believed to be present at the site (40 CFR 312.29).

2.5 OWNER, KEY SITE MANAGER, AND OCCUPANT INFORMATION

Blackstone interviewed the Site Representative (including the Key Site Manager) regarding environmental conditions at the site. The Site Representative was not aware of: (1) pending, threatened, or past litigation relevant to environmental conditions on the site; (2) any pending, threatened, or past administrative proceedings relevant to environmental conditions in, on, or from the site; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to environmental conditions on the site.

The site owner was not available to provide information regarding the environmental conditions at the site. In addition, as the site is used for multi-family residential purposes, the occupants were not interviewed.

DRAFT

2.6 PAST OWNERS, OPERATORS AND OCCUPANT INTERVIEWS

In accordance with ASTM Standard Practice E 1527-13, interviews with past owners, operators, and occupants shall be conducted to the extent that they have been identified and that the information likely to be obtained is not duplicative of information already obtained. There is no reason to believe that such interviews were necessary for this site or would alter the findings or recommendations set forth in this report.

2.7 RELIANCE

This report is for the use and benefit of, and may be relied upon by (a) Walker & Dunlop, Freddie Mac, and any successors and assigns ("Lender"); (b) independent auditors, accountants, attorneys and other professionals acting on behalf of Lender; (c) governmental agencies having regulatory authority over Lender; (d) designated persons pursuant to an order or legal process of any court or governmental agency; (e) prospective purchasers of the Mortgage; and (f) with respect to any debt (or portion thereof) and/or securities secured, directly or indirectly, by the Property which is the subject of this report, the following parties and their respective successors and assigns:

- any placement agent or broker/dealer and any of their respective affiliates, agents and advisors;
- any initial purchaser or subsequent holder of such debt and/or securities;
- any Servicer or other agent acting on behalf of the holders of such debt and/or securities;
- any indenture trustee;
- any rating agency; and
- any institutional provider from time to time of any liquidity facility or credit support for such financings.

In addition, this report, or a reference to this report, may be included or quoted in any offering circular, information circular, offering memorandum, registration statement, private placement memorandum, prospectus or sales brochure (in either electronic or hard copy format) in connection with a securitization or transaction involving such debt (or portion thereof) and/or securities.

DRAFT

3.0 SITE DESCRIPTION

The site is located at 255 Huguenot Street in New Rochelle, Westchester County, New York. A Site Location Map, depicted on the U.S. Geological Survey (USGS) *Mount Vernon, New York* topographic quadrangle, is included in Appendix B.

3.1 SITE CHARACTERISTICS AND FEATURES

Street Address: 255 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Parcel Number: 1-234-0001

Owner: New Rochelle Ind Dev Agency

Site Size: Approximately 0.46 acres

Zoning: *DMUR (Downtown Mixed Use Urban Renewal)*

Site Use: The site consists of vacant land.

Year Built: N/A

Construction Materials:	N/A
Heating/Cooling Systems:	N/A
Other Site Features:	N/A

A Site Plan and Site Photographs are provided in Appendix B.

3.2 UTILITIES

Electricity Provider: Con Edison

Natural Gas Provider: Con Edison

Potable Water: United Water New York

Sewer Services: City of New Rochelle

DRAFT

According to the Site Representative, the recently demolished improvements were connected to the municipal systems for sanitary sewer disposal and potable water supply. The site was historically developed with multiple commercial and residential structures since at least the 1880s. The City of New Rochelle water and sewer systems date back to at least the late 1800s; therefore, it is likely that the former site buildings were connected to the municipal potable water and sanitary sewer systems.

No RECs were identified as a result of the review of the site as described in this section of the report.

DRAFT

4.0 VICINITY RECONNAISSANCE

The site is located in New Rochelle, Westchester County, New York, within an area characterized by urban commercial development. Adjoining property use is summarized as follows:

North: Bridge Street, followed by Chase Bank office building (270 North Avenue)

East: Huguenot Street followed by a surface parking lot and the Ruby Dee Park on Library Green

South: Halstead Station apartment building (255 Huguenot Street), followed by a parking garage (275 Huguenot Street)

West: Station Plaza South followed by the New Rochelle train station, parking garage and associated railroad tracks

Source	Findings
Field observations	Blackstone observed no industrial, manufacturing or military operations such as outdoor chemical or hazardous waste storage or handling activities that may impact the site and no evidence of chemical spills, releases, or waste disposal was observed. From accessible vantage points, Blackstone identified no outdoor chemical or waste storage, wastewater treatment facilities, or other operations that may impact the site and no pits, ponds or lagoons for apparent discharge and/or treatment of process water were observed.
Environmental databases search	Adjoining and/or nearby properties identified on the environmental databases searched are discussed further in Section 7.0.

No RECs were identified as a result of the vicinity reconnaissance.

DRAFT

5.0 PHYSICAL SETTING

	Findings	*Sources of Findings*
Surficial Soils Beneath Site	Urban land	EDR Report
Depth to Bedrock	Between 5 and 50 feet bgs	EDR Report
Topography	The site is relatively flat with an overall area declination to the east	Site observations, USGS *Mount Vernon, New York* topographic map, and EDR Report
Elevation	Approximately 84 feet NAVD	USGS *Mount Vernon, New York* topographic map and EDR Report
Depth to Shallow Groundwater	Approximately 10 to 30 feet bgs	EDR Report
Estimated Groundwater Flow Direction	Generally, to the east	USGS *Mount Vernon, New York* topographic map and EDR Report

bgs: below ground surface
EDR Report: Environmental Data Resources Database Report with GeoCheck®
NAVD: North American Vertical Datum, 1988
USGS: United States Geological Survey

No RECs were identified as a result of the physical setting records review.

DRAFT

6.0 HISTORICAL INFORMATION REVIEW

As part of this Phase I ESA, Blackstone reviewed historical information to identify RECs associated with the historical use of the site and surrounding properties. Blackstone obtained historical information from interviews with site representatives and other individuals familiar with the site as well as aerial photographs, historical maps, and other practically reviewable standard historical sources that are considered reasonably ascertainable.

6.1 HISTORICAL FIRE INSURANCE MAPS

Environmental Data Resources, Inc. (EDR) conducted a search of Sanborn historical fire insurance maps for the site and site vicinity. Sanborn historical fire insurance maps are scaled drawings that indicate the location and use of building structures present in a given area from as early as the late 1800s. The maps provide information regarding the development and historic use of site structures and can indicate the historic presence of tanks at the site. Sanborn Fire Insurance Company maps were available for the site and adjoining properties from EDR. The Sanborn maps are reproduced in Appendix C and are summarized as follows:

Sanborn Fire Insurance Maps: Development/Land Uses/Occupants		
Year	***Site***	***Adjoining Properties***
1887	The site is depicted with a residential dwelling.	The north and east adjoining properties are depicted with residential and commercial development. Dwellings are depicted to the south. The west-adjoining property is depicted with railroad tracks and a railroad passenger depot. Bridge Street and Huguenot Street are depicted to the north and east (respectively).
1892	Multiple commercial structures, including a post office building, are depicted along the northern site perimeter. No other significant changes depicted.	Commercial structures are depicted to the north, east, and south. No other significant changes depicted.
1896	Additional commercial development is depicted at the site, including a hotel, restaurant, offices, and a laundry business.	Additional commercial development is depicted to the south. A “Chinese laundry” is depicted to the east. No other significant changes depicted.
1903	The laundry business is no longer depicted onsite.	No significant changes depicted.
1911	The site is depicted with multiple residential and commercial structures, including various offices and a theatre.	The north, east, and south adjoining properties are depicted with urban commercial development. In addition, a hotel is depicted to the east. A “Chinese laundry” is depicted on the north and south adjoining properties. No other significant changes depicted.

DRAFT

Sanborn Fire Insurance Maps: Development/Land Uses/Occupants		
Year	***Site***	***Adjoining Properties***
1931 1942	The site is depicted with multiple commercial and office structures.	The north, east, and south adjoining properties are depicted with urban commercial development, including a lighting company to the north, hotel to the east, and various stores to the south. No other significant changes depicted.
1951	A surface parking lot is depicted at the northwestern portion of the site. No other significant changes depicted.	No other significant changes depicted.
1990 1991	A parking area is depicted at the western portion of the site. Several of the onsite structures are depicted as vacant. No other significant changes depicted.	The present-day office building is depicted to the north and the present-day surface parking area is depicted to the east. A surface parking area is depicted to the south.. The present-day railroad station is depicted to the adjoining west. No other significant changes depicted.
1992 1993 1994 1995 1996	The site is primarily vacant land with surface parking at the western-northwestern portion.	The south adjoining property is generally depicted as vacant land with parking areas; however, a small retail building and a gas tank are depicted on this property. No other significant changes depicted.
2003	The site is depicted with two adjoining commercial buildings, which are attached to the south adjoining apartment building.	The present-day apartment building and parking garage are depicted to the south. The present-day park is depicted to the adjoining east. No other significant changes depicted.

Findings: As further discussed in Section 6.8, the former onsite laundry business and the former north, east, and south adjoining "Chinese laundry" tenants are not considered a REC. In addition, the gas tank depicted at the southern adjoining property is not considered a REC and is discussed further in Section 7.1. No RECs were identified as a result of the review of historical Sanborn Fire Insurance Maps.

6.2 AERIAL PHOTOGRAPHS

Aerial photographs of the site area were obtained from EDR. The aerial photographs are reproduced in Appendix C and are summarized as follows:

Aerial Photographs: Development/Land Uses		
Year	***Site***	***Adjoining Properties***
1946	The site appears to be developed with multiple commercial structures.	Urban commercial development is visible to the adjoining north, east, and south. Railroad tracks and a presumed rail station are visible to the adjoining west.
1951 1954 1961 1966	The western-northwestern portion of the site appears to be surface parking. No other significant changes are visible.	Surface parking areas appear to the north and south. No other significant changes are visible.

Aerial Photographs: Development/Land Uses		
Year	***Site***	***Adjoining Properties***
1974 1980 1985	No significant changes are visible.	The present-day office building appears to the north. The present-day parking area appears to the east. No other significant changes are visible.
1994	The site is primarily vacant land, with a portion of a surface parking lot visible at the western portion.	The south adjoining property appears primarily as vacant land with surface parking and a small commercial structure. No other significant changes are visible.
2006 2009 2017	The site appears to be developed with a commercial structure and pool.	The adjoining properties appear in the present-day configuration.

Findings: No RECs were identified as a result of the review of historical aerial photographs.

6.3 HISTORICAL TOPOGRAPHIC MAPS

Historical topographic maps of the site area were obtained from EDR. The historical topographic maps are included in Appendix C and are summarized as follows:

Historical Topographic Maps: Development/Land Uses		
Year	***Site***	***Adjoining Properties***
1897 1898 1900 1947	The site is depicted with areas of black shading (indicative of areas covered with buildings).	The adjoining properties are depicted with areas of black shading. Railroad tracks are depicted to the adjoining west.
1956 1966 1979 1995	The site is depicted with pink shading (indicative of dense urban development).	The adjoining properties are depicted with pink shading. Railroad tracks and a station are depicted to the adjoining west.
2013	The 2013 topographic map does not include shading or structures (similar to a street map, except with contour lines). The present-day adjoining and nearby roads are depicted.	

Findings: No RECs were identified as a result of the review of historical topographic maps.

6.4 AGENCY RECORDS, INTERVIEWS AND OTHER HISTORICAL SOURCES

In accordance with ASTM E1527-13, Blackstone requested site history and/or regulatory information regarding the site from federal, state and/or local government officials. Information regarding the site is obtained from regulatory agency officials either by:

1) Conducting interviews by telephone or in-person at various federal, state and/or local agencies; or
2) Requesting file information via submission of an open records request to the appropriate agency contact based upon applicable agency requirements, and in accordance with the Freedom of Information Act (FOIA).

Findings from the interviews/records review are summarized below:

Agency Records, Interviews and Other Historical Sources		
Source	***Information Requested***	***Findings***
Westchester County Assessor's Office at https://www.sccassessor.org/index.php/online-services/property-search/real-property	Typical ownership data, parcel information, and valuation data	No conditions of environmental concern were identified for the site. Typical site tax assessment data obtained.
City of New Rochelle Assessor's Office Online Query https://www.newrochelleny.com/199/Assessments	Typical ownership data, parcel information, and valuation data	No conditions of environmental concern were identified for the site. Typical site tax assessment data obtained.
City of New Rochelle, City Clerk, FOIL Request Form, via email cityclerkinfo@newrochelleny.com	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any emergency environmental responses or incidents	A FOIA request was submitted to this agency. A response has not been received to date and is not considered reasonably ascertainable for inclusion in this report.
New York State Department of Environmental Conservation (NYSDEC), online database	On-line spills incident, Petroleum Bulk Storage (PBS), and remediation database	Information obtained from the NYSDEC database is discussed in pertinent sections of the report.
NYSDEC FOIL Coordinator, via email (no name provided) access.records@dec.ny.gov	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any records of emergency environmental responses or incidents	A FOIA request was submitted to this agency. To date a response has not been received and available records are not considered reasonably ascertainable for inclusion in this report.

Findings: No RECs were identified from the review of the local agency records, interviews, or other readily available historical sources.

6.5 CITY DIRECTORIES

Blackstone requested a city directory review for the site address from EDR. City directories were reviewed at approximately five-year intervals for the years spanning 1972 through 2013. The present-day site address and south adjoining property address of 255 Huguenot Street was identified as the Portuguese American Club in the 1987 city directory and as the Avalon on the Sound Apartments with multiple residential listings in the city directories dated between 2003 and 2013. The historical site addresses of 245-255 Huguenot Street (odd) were primarily identified with multiple commercial listings, including restaurants, offices, and retail outlets, in the city directories dated between 1972 and 1992. No listings of environmental concern were identified for the site.

DRAFT

The north-adjoining property at 270 North Avenue was identified as the National Bank of Westchester and professional office listings in the city directories dated between 1972 and 1982 and as Chase Bank and professional office listings in the city directories dated between 1987 and 2013. The east-adjoining properties are primarily identified with commercial listings in the city directories dated between 1972 and 2013. The south adjoining property historical site addresses of 253-295 Huguenot Street (odd) were primarily identified with multiple commercial listings, including restaurants, offices, and retail outlets, in the city directories dated between 1972 and 1992. No listings of environmental concern were identified for the site.

No RECs were identified during the review of city directories.

6.6 ENVIRONMENTAL LIEN/AUL SEARCH

As previously discussed in Section 2.2, an environmental lien and activity & use limitation (AUL) search was not included in the scope of this assessment and was not provided to Blackstone for review by the User.

6.7 PREVIOUS ENVIRONMENTAL REPORTS

Blackstone was provided with the following previous environmental reports for review regarding the site:

- *Fannie Mae Environmental Database and Document Review, La Rochelle, 255 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC (Blackstone) for Walker & Dunlop, and dated April 18, 2018 (2018 Blackstone Report)

The purpose of the 2018 Blackstone Report was to determine if the site or nearby properties were listed within various local, state, and federal agency database files and if these listings represented a potential Environmental Risk Management Issue. The environmental database review does not constitute a Phase I Environmental Site Assessment in accordance with ASTM E1527-13 and does not meet the requirements of the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI). A site visit was not conducted as part of the 2018 Blackstone Report and identifying Recognized Environmental Conditions (RECs) was beyond the scope of work.

The 2018 Blackstone Report was performed for the present-day site, along with the present-day south adjoining properties. Based on the data obtained, the environmental database report, and historical documents review, Blackstone concluded that no facilities identified within the specified search distances appeared to represent an Environmental Risk Management Issue requiring further investigation.

- *Fannie Mae Phase I Environmental Site Assessment, La Rochelle, 255 and 275 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC (Blackstone) for Walker & Dunlop, and dated June 3, 2016 (2016 Blackstone ESA)

DRAFT

At the time of the 2016 Blackstone ESA, the site was developed with a single-story building containing apartment amenities, which was an extension of the south-adjoining apartment building. The 2016 Blackstone ESA also included the south-adjoining properties, which consisted of the present-day 24-story apartment building and five-story parking structure. At the time of the 2016 Blackstone ESA, the south-adjoining apartment building also included several street-level commercial spaces.

According to the 2016 Blackstone ESA, the site and south adjoining properties were initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. The former site structures were reportedly demolished between the early and mid-1990s.

The 2016 Blackstone ESA reported that Sound Drycleaning was located at the south adjoining property by at least the mid-2000s. Blackstone indicated that this tenant operated as a drop-off/pick-up only location, and was not involved in active dry-cleaning activities. In addition, this site tenant was not identified on any databases indicative of the generation or disposal of hazardous wastes typically associated with an active dry-cleaning facility. As such, Blackstone concluded that this drycleaner tenant was not considered a REC.

The 2016 Blackstone ESA revealed no evidence of RECs, as defined in ASTM E 1527-13, in connection with the site. No further assessment was recommended.

Copies of the above-referenced reports are included in Appendix D.

6.8 HISTORICAL INFORMATION CONCLUSIONS

Reasonably ascertainable historical information indicates the site was initially developed with a residential structure prior to 1887. By the late 1800s/early 1900s, the site was developed with multiple commercial buildings along the northern portion and by 1930, the site was developed with commercial and office buildings. Historical uses of the site included a laundry business (1896 only), a post office, hotel, restaurants, a theatre, retail storefronts, and offices. Between the 1950s and 1990s, the northwestern portion of the site was utilized for surface parking. These structures were demolished in the early-1990s, and the site was redeveloped in 2001 with a single-story extension of the present-day south adjoining apartment building and exterior amenities (pool, playground, etc.). The single-story extension contained amenities associated with the south-adjoining apartment building. The former site improvements were razed by 2019 and the site has been vacant since that time.

The north, east, and south-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a “Chinese laundry” in 1911, and a lighting company between approximately 1931 and 1951 prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures, including a “Chinese laundry” in 1896, and a hotel between approximately 1911 and 1951. The

present-day surface parking lot to the adjoining east was constructed in the 1970s and the present-day Ruby Dee Park on Library Green was developed in the 2000s. The south adjoining properties consisted of multiple commercial structures, including a “Chinese laundry” in 1911, and was also utilized for surface parking in the 1950s through 1990s prior to the construction of the present-day apartment building and parking garage in 2001. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

The site and adjoining properties were identified with retail laundry or dry cleaning operations in the late 1890s and early 1900s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. In addition, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. Based on the era of operation, absence of reported releases, and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities is not considered a REC.

No RECs were identified as a result of the review of the historical records.

DRAFT

7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW

EDR provided Blackstone a search report of federal, state, local, tribal and proprietary environmental databases to determine the environmental regulatory status of the site, adjoining facilities, and facilities identified within the specified approximate minimum search distance (AMSD) of the site. ASTM Standard E 1527-13, Section 8.2.1 establishes the distance from the site that each database is searched. Standard federal, state, and tribal databases searched, and the search distances specified for each database are summarized as follows:

Standard Environmental Record Sources	Search Distance
Federal Databases	
NPL: National Priority List Sites	1.0 mile
Proposed NPL: Proposed National Priority List Sites	1.0 mile
Delisted NPL: National Priority List Deletions	0.5 mile
NPL Liens: Federal Superfund Liens	Site only
FEDERAL FACILITY: Federal Facility Site Information Listing	1.0 mile
SEMS: Superfund Enterprise Management System	0.5 mile
SEMS-ARCHIVE: Superfund Enterprise Management System Archive	0.5 mile
RCRA CORRACTS: Resource Conservation and Recovery Act - Corrective Action Sites	1.0 mile
RCRA TSDF: RCRA – Treatment, Storage and Disposal Facilities	0.5 mile
RCRA LQGs: RCRA - Large-Quantity Generators	Site and adjoining
RCRA SQGs: RCRA - Small-Quantity Generators	Site and adjoining
RCRA CESQG: RCRA – Conditionally Exempt Small-Quantity Generators	Site and adjoining
US ENG CONTROLS: Engineering Controls Sites List	Site only
US INST CONTROL: Sites with Institutional Controls	Site only
ERNS: Emergency Response Notification System	Site only
State and Tribal Databases	
SHWS: State Hazardous Waste Site	1.0 mile
SWF/LF: Solid Waste Facilities & Landfill Sites	0.5 mile
LUST: Leaking Underground Storage Tanks	0.5 mile
LAST: Leaking Aboveground Storage Tanks	0.5 mile
INDIAN LUST: Leaking Underground Storage Tanks on Indian Lands	0.5 mile
UST: Registered Underground Storage Tanks	Site and adjoining
AST: Registered Aboveground Storage Tanks	Site and adjoining
INDIAN UST: Registered Underground Storage Tanks on Indian Lands	Site and adjoining
INST CONTROL: Sites with Institutional Controls	Site only
ENG CONTROLS: Sites with Engineering Controls	Site only
VCP: Voluntary Cleanup Program Sites	0.5 mile
INDIAN VCP: Voluntary Cleanup Priority sites on Indian Lands	0.5 mile
BROWNFIELDS: Brownfields Listings	0.5 mile

All federal, state, local, tribal and proprietary databases searched, the search distances specified for each database, and the results of the environmental database search are provided in the complete database report (EDR Radius Map) in Appendix E. The database search report also includes the date and a detailed

DRAFT

description of each database searched. These databases include, but are not limited to, the standard environmental records sources, as defined in ASTM Standard E 1527-13.

7.1 FEDERAL, STATE, LOCAL, TRIBAL AND PROPRIETARY DATABASES

A review of the databases included in the EDR Radius Map has been performed. Please refer to Appendix E for a complete list of the properties included in the databases within the required AMSD. The summary below includes database listings, if present, associated with the site and adjoining properties, as well as any additional property/listing within the AMSD that is deemed by the environmental professional to be at a distance or status that presents a higher potential risk for environmental concerns to the site and requires discussion.

The results of the database search are summarized as follows:

SITE:
Not listed

ADJOINING OR FACILITIES IN CLOSE PROXIMITY:
The south adjoining property, identified as Office Building at 8-10 Railroad Place, is identified on the Spills database. Review of the available Spills information indicates that a spill was reported on November 28, 1990, pertaining to a release of gasoline from an underground storage tank (UST) that appeared to be leaking. The cleanup work was identified as having met standard, and the case was issued regulatory closure on May 8, 1991. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 25 years), and that the adjoining property was ultimately redeveloped with a portion of a high-rise apartment building that required significant site excavation, the database listing is not considered a REC.

The south adjoining property, under the name Sound Cleaners at 63 Memorial Highway, is identified on the EDR Historical Cleaners and Drycleaners databases. The address is identified as Sound Cleaners between 2007 and 2014. The EDR Historical Cleaners database is a proprietary database compiled exclusively from EDRs internal review of historical city directories and names potentially associated with dry cleaning related businesses, and is not indicative of a confirmed business location or operation. This former tenant is not identified on any additional databases indicative of the generation or disposal of hazardous wastes typically associated with an active drycleaning facility. Based on previous site inspection and interviews from the 2016 Blackstone ESA, this former facility only operated as a drop off/pick up location, and no dry cleaning was performed at this location. As such, the database listings at the south adjoining property are not considered a REC.

The south adjoining property, under the name UST/Avalon on the Sound at Memorial Highway and Huguenot Street, is identified on the UST and Spills databases. According to the UST database, a 2,000-gallon UST was removed from the property on February 1, 2000. Review of the available Spills information indicates that the spill was reported on February 4, 2000, pertaining to the discovery of impacted soils during the removal of a UST. The cleanup work was identified as having met standard, and the case was issued regulatory closure on April 4, 2000. Review of information on the NYSDEC Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was closed (approximately 20 years), and that the property has since been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, these listings are not considered a REC.

DRAFT

The west adjoining property identified as Metro North Tracks/Metro North Train Station is identified on the Spills databases for two release incidents. In July 1989, a small amount of PCB oil was spilled from a punctured transformer. Additionally, In October 2003, a spill was reported between two tracks. Cleanups were completed and the two spills were issued regulatory closure. Based on the nature of the incidents and the current regulatory status, the database listings at the west adjoining property are not considered a REC.

The north adjoining property at 270 North Avenue, Suite 200 is identified as North Brook Realty Associates on the UST database. According to database information, a 15,000-gallon fuel oil UST is currently in service at the property. No violations or release incidents have been reported. Based on the regulatory status, this listing is not considered a REC.

Numerous Con Ed utility vaults and manholes are located adjoining the site, which are listed in the RCRA-Non-Gen/NLR database, FINDS, ECHO, Manifest, and Spills databases. No RCRA regulatory violations have been reported. A Spills incident was reported at Huguenot and Lawton Avenue to the adjoining east in 2000; however, a cleanup was completed and the spill was issued regulatory closure. Based on the regulatory status and downgradient location, these listing are not considered RECs.

NON-ADJOINING FACILITIES WITHIN APPROXIMATE MINIMUM SEARCH DISTANCE:
As detailed in the EDR Report, several other facilities on various databases are within the ASTM E 1527-13 Approximate Minimum Search Distance (AMSD). Based on factors such as distance to the site, topography, media affected (surface water, soil, soil vapor, or air), depth to groundwater, anticipated groundwater flow direction away from the site, and/or a "Case Closed" and/or "No Further Action (NFA)" regulatory status, these non-adjoining facilities within the AMSD are unlikely to have current or former releases of hazardous substances and/or petroleum products that could migrate to the site and are not considered RECs.

7.2 UNMAPPABLE FACILITIES

Due to inadequate address information or other erroneous facility information, facilities listed in the environmental databases searched may not be plotted by EDR on a radius map. However, these facilities are still identified in the EDR report by grouping them into an unmappable facility summary. Blackstone Consulting LLC reviewed this summary to determine if any of the listed facilities include or adjoin the site. The unmappable facility listings are summarized as follows:

SITE:
Not listed

ADJOINING FACILITIES:
None listed

7.3 AFFIRMATION

Blackstone's conclusions based on the EDR report are limited to the accuracy of that report. To the extent possible, field observations are used by Blackstone to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site. The database reviewed is sufficiently complete and current to be used as a source to satisfy the regulatory database requirements outlined in ASTM Standard E1527-13.

DRAFT

7.4 ENVIRONMENTAL DATABASE SEARCH AND REVIEW CONCLUSIONS

Based upon Blackstone's review of the EDR database report, no regulatory file reviews are warranted. No RECs were identified as a result of the environmental database search and review.

DRAFT

8.0 SITE INSPECTION

Name of Inspector: John O'Connor
Date of Site Inspection: September 17, 2020

SITE REPRESENTATIVE		
Name	***Title or Association with Site***	***Time Associated with Site***
Ms. Jessica Albasi	Property Manager	2.5 years
Mr. Lamont Harris	Maintenance Supervisor	3 years

The site inspection consisted of a walkover of the site perimeter and exterior site areas. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within locked utility vaults. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

8.1 UNDERGROUND STORAGE TANKS (USTs)

Number of USTs	***Capacity (gallons)***	***Contents***	***Location***	***Status/Notes***	***REC***
None					No

No physical evidence of current or former USTs was identified during the site inspection. The Site Representative was unaware of current or former USTs.

8.2 ABOVEGROUND STORAGE TANKS (ASTs)

Number of ASTs	***Capacity (gallons)***	***Contents***	***Location***	***Status/Notes***	***REC***
None					No

No physical evidence of current or former ASTs was identified during the site inspection. The Site Representative was unaware of current or former ASTs.

8.3 CHEMICALS AND MATERIALS USAGE

The following section describes non-bulk (55-gallons or less) chemical and petroleum storage at the site. Where applicable, all bulk fixed chemical and petroleum product storage (i.e. USTs and/or ASTs) is discussed in Sections 8.1 and 8.2.

DRAFT

Chemical or Material	*Use*	*Container Type*	*Location*	*REC*
None				

No physical evidence of chemicals and/or petroleum product storage was identified during the site inspection. The Site Representative was unaware of any on-site chemicals and/or petroleum product storage.

8.4 HAZARDOUS WASTES

Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

No physical evidence of on-site hazardous waste generation, storage, or disposal was identified during the site inspection. The Site Representative was unaware of any on-site hazardous waste generation, storage, or disposal.

8.5 NON-HAZARDOUS WASTES

Non-Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

No physical evidence of on-site non-hazardous waste disposal was identified during the site inspection. The Site Representative was unaware of any on-site non-hazardous waste disposal.

8.6 POLYCHLORINATED BIPHENYLS (PCBs)

PCBs can be present in coolants or lubricating oils used in older electrical transformers, hydraulic systems, and other similar equipment. The 1976 Toxic Substances Control Act (TSCA) extended regulatory control over the use of PCBs to the United States Environmental Protection Agency (USEPA). In November 1979, the USEPA generally prohibited the domestic manufacture of PCBs in electromagnets, transformers, and heat-transfer and hydraulic equipment.

Equipment	*Location*	*Owner*	*Status/Notes*	*REC*
Vaulted transformers	Presumed to be under the sidewalk site perimeters	Con Edison	See discussion below	No

Blackstone did not observe any pad or pole-mounted transformers on the site, and it is assumed that the transformers serving the site are vaulted (presumed to be located under the sidewalk along the site perimeters). In addition, should fluid spills or releases from an electrical transformer occur, associated

DRAFT

remediation efforts are typically the responsibility of the transformer owner (Con Edison) per Federal regulation (40 CFR 761.125). As such, the transformers are not considered a REC.

8.7 WASTEWATER DISCHARGES

Type	*Generated By*	*Discharged To*	*Status/Notes*	*REC*
None				No

No physical evidence of septic systems, cesspools, clarifiers, or oil/water separators was observed. The Site Representative was unaware of such features on the site.

8.8 STORMWATER DISCHARGES

Discharged From	*Discharged To*	*Status/Notes*	*REC*
Exterior site surfaces	Adjacent roadways	No concerns noted	No

No on-site stormwater retention ponds were observed. The Site Representative was unaware of such features on the site.

8.9 PITS, PONDS, AND LAGOONS (ON-SITE PROCESS WATER DISCHARGE)

Type	*Contents*	*Location*	*Status/Notes*	*REC*
None				No

No pits, ponds or lagoons used for process water discharge were observed at the site. The Site Representative was unaware of such features on the site.

8.10 WELLS

Type	*Location*	*Status/Notes*	*REC*
None			No

No physical evidence of any groundwater monitoring wells, injection wells, extraction wells, or vapor wells was identified during the site inspection. The Site Representative was unaware of on-site wells.

8.11 UNDERGROUND PRODUCT PIPELINES

Type	*Location*	*Status/Notes*	*REC*

DRAFT

None			No

No physical evidence of underground product pipelines carrying petroleum or other hazardous substances was identified during the site inspection. The Site Representative was unaware of on-site product pipelines.

8.12 ODORS

Odors	*Location*	*Status/Notes*	*REC*
None			No

No unusual odors indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of such odors at the site.

8.13 POOLS OF LIQUID

Pools of Liquid	*Location*	*Status/Notes*	*REC*
None			No

No pools or sumps containing liquids indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of pools or sumps containing liquids at the site.

8.14 STRESSED VEGETATION OR STAINED SURFACES

Stressed Vegetation or Stained Surfaces	*Location*	*Status/Notes*	*REC*
None			No

No stained surfaces or stressed vegetation were observed by Blackstone. The Site Representative was unaware of stressed vegetation or stained surfaces.

8.15 SITE INSPECTION CONCLUSIONS

No evidence of RECs was identified in connection with the site as a result of the site inspection.

DRAFT

9.0 ASTM NON-SCOPE CONSIDERATIONS

Blackstone performed the following client-specific activities to identify ASTM Non-Scope Considerations (Business Environmental Risk Issues) in addition to the ASTM and as required per the Agreement and Freddie Mac.

9.1 ASBESTOS-CONTAINING MATERIALS (ACM)

No permanent structures are currently located on the site and no suspect ACM was observed. As such, sampling was not required, and no further evaluation is recommended.

9.2 LEAD-BASED PAINT (LBP)

No permanent structures are currently located on the site and no suspect LBP was observed. As such, sampling was not required, and no further evaluation is recommended.

9.3 RADON GAS

A review of records regarding radon concentrations in Westchester County, New York, was conducted to determine if concentrations of radon in the general area of the site are within the USEPA guidelines. The USEPA uses a continuous exposure level of 4.0 pCi/L (picoCuries per liter of air) or greater as a guidance level at which further evaluation and potential remedial actions are recommended.

According to USEPA Office of Radiation and Indoor Air information/mapping, the site is located within a Radon Zone Level 3. This zone has a predicted average indoor radon gas screening level less than 2.0 pCi/L, which is within USEPA guidance levels.

No permanent structures are currently located on site. As such, no further evaluation is recommended at this time.

9.4 APPARENT MOLD GROWTH (AMG)

No permanent structures are currently located on site and no AMG was observed. As such, no further evaluation is recommended.

9.5 LEAD IN DRINKING WATER

United Water New York provides drinking water to the site. The United Water New York/Suez Annual Drinking Water Quality Report for 2019 (most recent report available for review) indicates the municipal water system meets the requirements as established by the USEPA, state, and local authorities for lead content in drinking water.

DRAFT

9.6 ENVIRONMENTAL SUPERLIEN

Based on information reviewed by Blackstone, the State of New York has a first priority Super Lien Statute for cleanup of hazardous waste under New York Environmental Conservation Law §56-0508 (Enacted in 2003) and New York City (NYC) Administrative Code §16-131.3 (Enacted in 1990, amended in 2005). New York Environmental Conservation Law §56-0508 stipulates that upon commencement of tax foreclosure proceedings, the local governmental authority may seek a court order allowing authority to conduct an environmental restoration investigation pursuant to state Brownfield law. Costs of investigation are added to the taxes owed to, and tax lien of, the local governmental authority. The NYC Administrative Code §16-131.3 allows the Department of Sanitation to file a first priority lien, subject only to tax liens, where the Department has abated a property and conditions, including solid waste, have been found hazardous to the public health and safety. As such, the User may wish to consult with legal counsel regarding potential environmental superlien statutes for the site. No liens were listed for the site in the EDR databases searched.

DRAFT

10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Freddie Mac Phase I ESA Guidelines, and the September 14, 2020 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*), *controlled recognized environmental conditions* (*CRECs*), or *historical recognized environmental conditions (HRECs*) in connection with the site. No further investigation is recommended.

DRAFT

PENDING

DRAFT



Project No. WALKGA136.09

Halstead Station (Vacant Land)
New Rochelle, Westchester County, New York

Site Location Map

(USGS Mount Vernon, New York Topographic Map, 2013)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.09

Halstead Station (Vacant Land)
New Rochelle, Westchester County, New York

Site Plan

(Approximate Scale Shown)

N
W E
S

BLACKSTONE CONSULTING LLC



PHOTOGRAPH 1
Site facing west



PHOTOGRAPH 2
Site facing west



PHOTOGRAPH 3
Site facing east



PHOTOGRAPH 4
Site facing north



PHOTOGRAPH 5
North adjoining property



PHOTOGRAPH 6
East adjoining property



PHOTOGRAPH 7
South adjoining property



PHOTOGRAPH 8
West adjoining property

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6193173.3

September 16, 2020

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

09/16/20

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6193173.3

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Michelle Thomas

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Blackstone Consulting, LLC were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # ED5F-475E-B9EA

PO # NA

Project WALKGA136.07

Maps Provided:

2003	1951
1996	1942
1995	1931
1994	1911
1993	1903
1992	1896
1991	1892
1990	1887

Sanborn® Library search results

Certification #: ED5F-475E-B9EA

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Blackstone Consulting, LLC (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets


Volume 1, Sheet 2
2003


Volume 1, Sheet 3
2003


Volume 1, Sheet 7
2003



Volume 1, Sheet 8
2003

1996 Source Sheets


Volume 1, Sheet 2
1996


Volume 1, Sheet 3
1996


Volume 1, Sheet 7
1996


Volume 1, Sheet 8
1996

1995 Source Sheets


Volume 1, Sheet 2
1995


Volume 1, Sheet 3
1995



Volume 1, Sheet 7
1995



Volume 1, Sheet 8
1995

1994 Source Sheets


Volume 1, Sheet 2
1994


Volume 1, Sheet 3
1994


Volume 1, Sheet 7
1994


Volume 1, Sheet 8
1994

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1993 Source Sheets


Volume 1, Sheet 7
1993


Volume 1, Sheet 8
1993



Volume 1, Sheet 2
1993


Volume 1, Sheet 3
1993

1992 Source Sheets


Volume 1, Sheet 2
1992


Volume 1, Sheet 3
1992


Volume 1, Sheet 7
1992



Volume 1, Sheet 8
1992

1991 Source Sheets


Volume 1, Sheet 2
1991


Volume 1, Sheet 3
1991



Volume 1, Sheet 7
1991


Volume 1, Sheet 8
1991

1990 Source Sheets


Volume 1, Sheet 3
1990


Volume 1, Sheet 7
1990


Volume 1, Sheet 8
1990



Volume 1, Sheet 2
1990

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1951 Source Sheets


Volume 1, Sheet 2
1951


Volume 1, Sheet 3
1951


Volume 1, Sheet 7
1951



Volume 1, Sheet 8
1951

1942 Source Sheets



Volume 1, Sheet 6
1942


Volume 1, Sheet 7
1942

1931 Source Sheets


Volume 1, Sheet 2
1931



Volume 1, Sheet 3
1931


Volume 1, Sheet 7
1931


Volume 1, Sheet 8
1931

1911 Source Sheets


Volume 1, Sheet 49
1911


Volume 1, Sheet 54
1911


Volume 1, Sheet 55
1911



Volume 1, Sheet 65
1911


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1903 Source Sheets



Volume 1, Sheet 5
1903


Volume 1, Sheet 6
1903


Volume 1, Sheet 9
1903


Volume 1, Sheet 10
1903

1896 Source Sheets


Volume 1, Sheet 3
1896



Volume 1, Sheet 4
1896


Volume 1, Sheet 7
1896


Volume 1, Sheet 8
1896

1892 Source Sheets


Volume 1, Sheet 10
1892


Volume 1, Sheet 11
1892



Volume 1, Sheet 9
1892



Volume 1, Sheet 12
1892

1887 Source Sheets


Volume 1, Sheet 2
1887


Volume 1, Sheet 4
1887


Volume 1, Sheet 5
1887




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #	ED5F-475E-B9EA
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #	ED5F-475E-B9EA
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #	ED5F-475E-B9EA
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 2
Volume 1, Sheet 8
Volume 1, Sheet 7

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #	ED5F-475E-B9EA
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 2
Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1942

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 6

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1931

THE SANBORN LIBRARY LLC — Sanborn — SEAL OF AUTHENTICITY

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1911

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 65
Volume 1, Sheet 55
Volume 1, Sheet 54
Volume 1, Sheet 49

0 Feet 150 300 600


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #	ED5F-475E-B9EA
Copyright	1903

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 10
Volume 1, Sheet 9
Volume 1, Sheet 6
Volume 1, Sheet 5

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED5F-475E-B9EA

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1896

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 7
Volume 1, Sheet 4
Volume 1, Sheet 3

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1892

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 12
Volume 1, Sheet 9
Volume 1, Sheet 11
Volume 1, Sheet 10

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Halstead Station
Address:	255 Huguenot Street
City, ST, ZIP:	New Rochelle, NY 10801
Client:	Blackstone Consulting, LLC
EDR Inquiry:	6193173.3
Order Date:	09/16/2020
Certification #:	ED5F-475E-B9EA
Copyright	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 5
Volume 1, Sheet 4
Volume 1, Sheet 2

0 Feet 150 300 600

N

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6193173.8

September 16, 2020

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

09/16/20

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6193173.8

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Michelle Thomas

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 08, 1994	USGS/DOQQ
1985	1"=500'	Flight Date: March 16, 1985	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1974	1"=500'	Flight Date: October 24, 1974	USDA
1966	1"=500'	Flight Date: January 12, 1966	USGS
1961	1"=500'	Flight Date: November 22, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 23, 1954	USGS
1951	1"=500'	Flight Date: April 20, 1951	EDR Proprietary Aerial Viewpoint
1946	1"=500'	Flight Date: January 01, 1946	FirstSearch

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.




INQUIRY #: 6193173.8

YEAR: 2017

= 500'

N

EDR




INQUIRY #: 6193173.8

YEAR: 2009

= 500'

N

EDR




INQUIRY #: 6193173.8

YEAR: 2006

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1994

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.



INQUIRY #: 6193173.8

YEAR: 1985

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1980

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1974

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1966

= 500'

N

EDR




INQUIRY #: 6193173.8

YEAR: 1961

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1954

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1951

= 500'

N

EDR



INQUIRY #: 6193173.8

YEAR: 1946

= 500'

N

EDR

Halstead Station

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 6193173.4

September 16, 2020

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

09/16/20

Site Name:

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801
EDR Inquiry # 6193173.4

Client Name:

Blackstone Consulting, LLC
5500 Rolling Meadows Court
Saint Louis, MO 63129
Contact: Michelle Thomas

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Blackstone Consulting, LLC were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: WALKGA136.07

Coordinates:

Latitude:	40.910597 40° 54' 38" North
Longitude:	-73.783767 -73° 47' 2" West
UTM Zone:	Zone 18 North
UTM X Meters:	602426.26
UTM Y Meters:	4529544.55
Elevation:	88.66' above sea level

Maps Provided:

2013	1897
1995	
1979	
1966	
1956	
1947	
1900	
1898	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2013 Source Sheets




Mount Vernon
2013
7.5-minute, 24000

1995 Source Sheets



Mount Vernon
1995
7.5-minute, 24000
Aerial Photo Revised 1977

1979 Source Sheets



Mount Vernon
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1966 Source Sheets



Mount Vernon
1966
7.5-minute, 24000
Aerial Photo Revised 1966

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1956 Source Sheets



Mount Vernon
1956
7.5-minute, 24000
Aerial Photo Revised 1954

1947 Source Sheets



Mt Vernon
1947
7.5-minute, 24000
Aerial Photo Revised 1941

1900 Source Sheets



Harlem
1900
15-minute, 62500

1898 Source Sheets



Harlem
1898
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.


1897 Source Sheets



Harlem
1897
15-minute, 62500

Historical Topo Map

2013



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1979, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1966, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1956, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mt Vernon, 1947, 7.5-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute

SITE NAME: Halstead Station
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

BLACKSTONE
CONSULTING LLC

FANNIE MAE
ENVIRONMENTAL DATABASE AND DOCUMENT REVIEW

La Rochelle
255 Huguenot Street
New Rochelle, Westchester County, New York 10801

Prepared For:

Wayne Elibero
Deputy Chief Underwriter
Walker & Dunlop
63 Kendrick Street
Needham, MA 02494

Submitted By:

Blackstone Consulting LLC
Project No. WALKGA136.06

April 18, 2018

TABLE OF CONTENTS

PAGE

1.0 INTRODUCTION 1
1.1 Purpose 1

2.0 ENVIRONMENTAL DOCUMENT REVIEW 2
2.1 Environmental Document Review 2

3.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW 4
3.1 Federal, State, Local, Tribal and Proprietary Databases 5
3.2 Unmappable Facilities 6
3.3 Affirmation 7

4.0 FINDINGS AND CONCLUSIONS 8

5.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 9

LIST OF APPENDICES

Appendix A: Previous Environmental Report
Appendix B: Environmental Database Search Report

1.0 INTRODUCTION

1.1 Purpose

Blackstone Consulting LLC (Blackstone) was retained by Walker & Dunlop to perform an environmental database and document review of La Rochelle located at 255 Huguenot Street in New Rochelle, Westchester County, New York (site). The site is developed with a 24-story apartment building, containing 408 dwelling units, and a five-story parking structure situated on approximately 2.46 acres of land. The apartment building includes basement and penthouse mechanical levels and a single-story building extension containing the community amenities. Former street-level commercial space has been removed and is currently being renovated into a community amenity area. The current single-story building extension containing the community amenities is slated for demolition within the next six months. The site is bisected by Memorial Highway, which separates the parking garage from the apartment building. The apartment building and parking garage are connected via a covered, elevated walkway over Memorial Highway. The site buildings were reportedly constructed in 2001.

The purpose of the environmental database review is to determine if the site or nearby properties are listed within various local, state, and federal agency database files and if these listings represent a potential *Environmental Risk Management Issue*. In addition, a review of supplemental environmental documents, if provided by Walker & Dunlop, is performed to assist in the evaluation of the findings of the environmental database review.

Blackstone performed this environmental database review on behalf of and exclusively for Walker & Dunlop and Fannie Mae and each of their affiliates, attorneys, lenders, investors, successors and each of their assigns subject to the terms and conditions of the Agreement between Walker & Dunlop and Blackstone. This report is addressed to Walker & Dunlop and its affiliates. Walker & Dunlop and its affiliates, their respective successors and assigns (including, without limitation, investors who purchase the mortgage loan or a participation interest in the mortgage loan and the trustee in a securitization that includes the mortgage loan), each servicer of the mortgage loan, and all rating agencies involved in any sale, securitization or syndication involving the mortgage loan may use and rely upon this Report, including, without limitation, utilizing selected information from the Report in the offering materials (either in electronic or hard copy format) relating to any sale, securitization or syndication involving the mortgage loan. The Assessor agrees to cooperate in answering questions by any of the above parties in connection with the sale, securitization or syndication, as communicated by Walker & Dunlop personnel.

This environmental database and document review is being completed for Walker & Dunlop as part of its internal environmental review associated with a potential real-estate collateralized lending transaction.

2.0 ENVIRONMENTAL DOCUMENT REVIEW

2.1 Environmental Document Review

Blackstone was provided with the following previous environmental report regarding the site:

- *Fannie Mae Phase I Environmental Site Assessment, La Rochelle, 255 and 274 Huguenot Street, New Rochelle, Westchester County, New York 10801,* prepared by Blackstone Consulting LLC for Walker & Dunlop, and dated June 3, 2016 (2016 Blackstone ESA)

At the time of the 2016 Blackstone ESA, the site was developed with the present-day apartment community, which included the present-day 24-story apartment building and five-story parking structure.

According to the 2016 Blackstone ESA, the site was initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. Historical commercial uses of the site included hotels, office space, retail stores, restaurants, a post office, a bowling alley, a theater, a "Chinese laundry" (1911 only), an auto sales and service facility (southwest corner from the 1930s until the 1980s), and surface parking lots. The former site structures were reportedly demolished between the early and mid-1990s.

The 2016 Blackstone ESA identified a small "Chinese laundry" facility at the site in 1911. Blackstone opined that this type of facility in this era was typically a hand washing operation. Blackstone indicated that the use of chlorinated solvents was not introduced into the dry-cleaning industry until the late 1930s, and its use became widespread in the late 1940s following World War II. The 2016 Blackstone ESA identified no additional historic cleaners or dry-cleaning operations on the site. Based on the era of operation and the duration of time since the facility was identified on the site (over 100 years), Blackstone concluded this laundry facility was not considered a REC.

The 2016 Blackstone ESA reported that Sound Drycleaning had been located at the site since at least the mid-2000s. Blackstone indicated that this tenant operated as a drop-off/pick-up only location, and was not involved in active dry-cleaning activities. In addition, this site tenant was not identified on any databases indicative of the generation or disposal of hazardous wastes typically associated with an active dry-cleaning facility. As such, Blackstone concluded that this drycleaner tenant was not considered a REC.

The 2016 Blackstone ESA reported that an auto sales and service facility occupied the southwest corner of the site between at least the 1930s and the 1980s. This former facility was not identified on any databases indicative of the generation, disposal or release of hazardous materials and/or waste, nor the operation of underground storage tanks (USTs). The site area where this facility

was historically located is directly beneath the present-day site parking garage. Blackstone indicated there was no report of impacted soil or other remnants of the auto service operation encountered during the development of the site parking structure in 2001. Considering the regulatory status (no reported releases), the amount of time that had passed since this facility was active (approximately 30 years), and that this site area had been redeveloped with a multi-story parking garage that would have necessitated significant excavation during construction, Blackstone concluded that the historical presence of the auto sales and service facility in the southwest corner of the site was not considered a REC.

Historical information reviewed by Blackstone as part of the 2016 Blackstone ESA identified a 2000-gallon gasoline UST on the central-western area of the site, near the intersection of Memorial Highway and Railroad Place. According to Blackstone's review of the regulatory database, the UST was removed from the site on February 1, 2000, with some impacted soil discovered during removal. Based on the minor soil impacts discovered during removal, the site was listed with a Spills case. However, following the over-excavation of the UST area, all of the impacted soil was removed, the cleanup work was identified as having met applicable standards, and the case was issued regulatory closure on April 4, 2000. Blackstone's review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case had been issued regulatory closure. Considering the status (UST and impacted soil removed, regulatory closure issued, and that the area of the UST had since been redeveloped with a high-rise apartment building with a basement level that required significant site excavation to develop), Blackstone concluded that the historical presence of the UST at the site was not considered a REC.

The 2016 Blackstone ESA reported that a "Chinese laundry" facility was historically located to the adjoining north in at least 1911 and a dry-cleaning facility was located in the southern portion of the east-adjoining property in at least the 1930s. These facilities were not identified on any databases indicative of the generation or disposal of hazardous waste. Blackstone identified no additional cleaners or dry-cleaning operations on adjoining properties. Based on the era of operation and the duration of time since these facilities were identified (over 80 years), Blackstone concluded that the historical presence of these facilities on the adjoining properties was not considered a REC.

The 2016 Blackstone ESA revealed no evidence of *RECs*, as defined in ASTM E 1527-13, in connection with the site. No further assessment was recommended.

The previous report is provided in Appendix A.

3.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW

EDR provided Blackstone a search report of federal, state, local, tribal and proprietary environmental databases to determine the environmental regulatory status of the site, adjoining facilities, and facilities identified within the specified approximate minimum search distance (AMSD) of the site. ASTM Standard E 1527-13, Section 8.2.1 establishes the distance from the site that each database is searched. S*tandard federal, state, and tribal databases* searched and the search distances specified for each database are summarized as follows:

Standard Environmental Record Sources	*Search Distance*
Federal Databases	
NPL: National Priority List Sites	1.0 mile
Proposed NPL: Proposed National Priority List Sites	1.0 mile
Delisted NPL: National Priority List Deletions	0.5 mile
NPL Liens: Federal Superfund Liens	Site only
FEDERAL FACILITY: Federal Facility Site Information Listing	1.0 mile
SEMS: Superfund Enterprise Management System	0.5 mile
SEMS-ARCHIVE: Superfund Enterprise Management System Archive	0.5 mile
RCRA CORRACTS: Resource Conservation and Recovery Act - Corrective Action Sites	1.0 mile
RCRA TSDF: RCRA – Treatment, Storage and Disposal Facilities	0.5 mile
RCRA LQGs: RCRA - Large-Quantity Generators	Site and adjoining
RCRA SQGs: RCRA - Small-Quantity Generators	Site and adjoining
RCRA CESQG: RCRA – Conditionally Exempt Small-Quantity Generators	Site and adjoining
US ENG CONTROLS: Engineering Controls Sites List	Site only
US INST CONTROL: Sites with Institutional Controls	Site only
ERNS: Emergency Response Notification System	Site only
State and Tribal Databases	
SHWS: State Hazardous Waste Site	1.0 mile
SWF/LF: Solid Waste Facilities & Landfill Sites	0.5 mile
LUST: Leaking Underground Storage Tanks	0.5 mile
LAST: Leaking Aboveground Storage Tanks	0.5 mile
INDIAN LUST: Leaking Underground Storage Tanks on Indian Lands	0.5 mile
UST: Registered Underground Storage Tanks	Site and adjoining
AST: Registered Aboveground Storage Tanks	Site and adjoining
INDIAN UST: Registered Underground Storage Tanks on Indian Lands	Site and adjoining
INST CONTROL: Sites with Institutional Controls	Site only
ENG CONTROLS: Sites with Engineering Controls	Site only
VCP: Voluntary Cleanup Program Sites	0.5 mile
INDIAN VCP: Voluntary Cleanup Priority sites on Indian Lands	0.5 mile
BROWNFIELDS: Brownfields Listings	0.5 mile

All federal, state, local, tribal and proprietary databases searched, the search distances specified for each database, and the results of the environmental database search are provided in the complete database report (*EDR Radius Map*) in Appendix B. The database search report also includes the date and a detailed description of each database searched. These databases include,

but are not limited to, the *standard environmental records sources,* as defined in ASTM Standard E 1527-13.

3.1 Federal, State, Local, Tribal and Proprietary Databases

A review of the databases included in the *EDR Radius Map* has been performed. Please refer to Appendix B for a complete list of the properties included on the databases within the required AMSD. The summary below includes database listings, if present, associated with the site and adjoining properties, as well as any additional property/listing within the AMSD that is deemed by the *environmental professional* to be at a distance or status that presents a higher potential risk for environmental concerns to the site and requires discussion.

The results of the database search are summarized as follows:

SITE:
The site, under the name Office Building at 8-10 Railroad Place, is identified on the Spills database. Review of the available Spills information indicates that the site dates to November 28, 1990, pertained to a release of gasoline from an underground storage tank (UST) that appeared to be leaking, the cleanup work was identified as having met clean-up standards, and the case was issued regulatory closure on May 8, 1991. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 25 years), and that the site has since been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listing on the Spills database is not considered an *Environmental Risk Management Issue*.

The site, under the name Sound Cleaners at 63 Memorial Highway, is identified on the EDR Historical Cleaners and Drycleaners databases. The site address is identified as Sound Cleaners between 2009 and 2012. The EDR Historical Cleaners database is a proprietary database compiled exclusively from EDRs internal review of historical information potentially associated with dry cleaning related businesses, and is not indicative of a confirmed business location or operation. This site tenant is not identified on any additional databases indicative of the generation or disposal of hazardous wastes typically associated with an active dry-cleaning facility. Based on the previous site inspection and interviews for the 2016 Blackstone ESA, this facility has only been occupied as a drop off/pick up location, and no dry cleaning has been performed on the site. As such, the site drycleaner listing is not considered an *Environmental Risk Management Issue*.

The site, listed as UST/Avalon on the Sound at Memorial Highway and Huguenot Street, is identified on the UST and Spills databases. According to the UST database, a 2,000-gallon UST was removed from the site on February 1, 2000. Review of the available Spills information indicates that the spill dates to February 4, 2000, and pertained to the discovery of impacted soils during the removal of a UST, the cleanup work was identified as having met the clean-up standards, and the case was issued regulatory closure on April 4, 2000. Review of information on the NYSDEC Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 15 years), and that the site has since been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listings on the UST and Spills databases are not considered an *Environmental Risk Management Issue*.

ADJOINING OR FACILITIES IN CLOSE PROXIMITY:
Vacant Lot (Huguenot Street/Division Street) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 2005, pertained to the discovery of a release during a UST removal, cleanup work was performed, and the case was issued regulatory on March 15, 2006. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered an *Environmental Risk Management Issue*.

Shoreline Oil (296 Huguenot Street Rear) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 1988, pertained to a tank overfill, cleanup work was performed, and the case was issued regulatory on April 6, 1988. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered an *Environmental Risk Management Issue*.

Jones Residence/Trinity St. Paul's Episcopal Church (311 Huguenot Street) is located approximately 100 feet to the adjoining south of the site and crossgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the UST and LTANKS databases. Review of the available UST information indicates that this facility previously contained a UST that was closed in place in 2005. According to the LTANKS database, the case dates to 2004, pertained to the closure of a UST, no contamination was discovered in the soil samples obtained, and the case was issued regulatory on September 11, 2005. Considering the current regulatory status and the crossgradient position in relationship to the site, this facility is not considered an *Environmental Risk Management Issue*.

Con Edison (Memorial Highway and Huguenot Street/Division Street and Huguenot Street) is located to the adjoining east and downgradient of the site based on inferred direction of groundwater flow. This facility is listed on the RCRA-LQG, RCRA Non-Gen/NLR, and Manifest databases. Con Edison has at least eight listings for the east-adjoining roadways on the Manifest database, presumably for the replacement of electrical transformers, that date between 2007 and 2014. Con Edison is identified as a large quantity generator of hazardous waste in the form of lead and was previously a non-generator of hazardous waste. No RCRA violations have been identified. Based on the current regulatory status, this west adjoining facility is not considered an *Environmental Risk Management Issue*.

NON-ADJOINING FACILITIES WITHIN APPROXIMATE MINIMUM SEARCH DISTANCE:
As detailed in the EDR Report, other facilities on various databases are within the ASTM E 1527-13 Approximate Minimum Search Distance (AMSD). Based on factors such as distance to the site, topography, media affected (surface water, soil, soil vapor, groundwater, or air), depth to groundwater, anticipated groundwater flow direction away from the site, and/or a "Case Closed" and/or "No Further Action (NFA)" regulatory status, these non-adjoining facilities within the AMSD are unlikely to have current or former releases of hazardous substances and/or petroleum products that could migrate to the site and are not considered *Environmental Risk Management Issues*.

3.2 Unmappable Facilities

Due to inadequate address information or other erroneous facility information, several facilities listed in the environmental databases searched could not be plotted by EDR on a radius map. However, these facilities are still identified in the EDR report by grouping them into an

unmappable facility summary. Blackstone reviewed this summary to determine if any of the listed facilities include or adjoin the site. The unmappable facility listings are summarized as follows:

SITE:
Not listed

ADJOINING FACILITIES:
None listed

3.3 Affirmation

Blackstone's conclusions based on the EDR report are limited to the accuracy of that report. To the extent possible, Blackstone attempts to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site.

4.0 FINDINGS AND CONCLUSIONS

No facilities identified within the specified search distances appear to represent an *Environmental Risk Management Issue* requiring further investigation.

5.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

Blackstone performed this Environmental Database and Document Review to constitute an inquiry consistent with good commercial and customary practice.


Prepared By:



Craig R. Snavely
Senior Project Manager

04/18/2018
Date


Technical Review and Concurrence By:



Akisha Staggers
Senior Project Manager

04/18/2018
Date

Principal Review By:



Becky Renick
Principal

04/18/2018
Date

jh

BLACKSTONE
CONSULTING LLC

FANNIE MAE
PHASE I ENVIRONMENTAL SITE ASSESSMENT

La Rochelle
255 and 275 Huguenot Street
New Rochelle, Westchester County, New York 10801

Prepared For:

Walker & Dunlop
Atlanta, Georgia

Prepared By:

Blackstone Consulting LLC
Project No. WALKGA136.01

June 3, 2016

TABLE OF CONTENTS

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS i
EXECUTIVE SUMMARY ii
1.0 INTRODUCTION 1
1.1 Purpose 1
1.2 Special Terms and Conditions 2
1.3 Scope of Services 2
1.4 Significant Assumptions and Data Gaps 3
2.0 USER PROVIDED INFORMATION 5
2.1 Reason For Performing the Phase I ESA 5
2.2 Environmental Liens and Activity Use And Limitations (AULs) 5
2.3 Specialized Knowledge, Commonly Known & Degree of Obviousness 6
2.4 Value Reduction for Environmental Issues 6
2.5 Owner, Key Site Manager, and Occupant Information 6
2.6 Past Owners, Operators and Occupant Interviews 7
2.7 Reliance 7
3.0 SITE DESCRIPTION 8
3.1 Site Characteristics and Features 8
3.2 Utilities 9
4.0 VICINITY RECONNAISSANCE 11
5.0 PHYSICAL SETTING 12
6.0 HISTORICAL INFORMATION REVIEW 13
6.1 Historical Fire Insurance Maps 13
6.2 Aerial Photographs 15
6.3 Historical Topographic Maps 16
6.4 Agency Records, Interviews and Other Historical Sources 16
6.5 City Directories 17
6.6 Environmental Lien/AUL Search 18
6.7 Previous Environmental Reports 18
6.8 Historical Information Conclusions 18
7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW 20
7.1 Federal, State, Local, Tribal and Proprietary Databases 20
7.2 Unmappable Facilities 25
7.3 Affirmation 25
7.4 Environmental Database Search and Review Conclusions 25
8.0 SITE INSPECTION 26
8.1 Underground Storage Tanks (USTs) 26
8.2 Aboveground Storage Tanks (ASTs) 26
8.3 Chemicals and Materials Usage 27
8.4 Hazardous Wastes 27
8.5 Non-Hazardous Wastes 27
8.6 Polychlorinated Biphenyls (PCBs) 28
8.7 Wastewater Discharges 29
8.8 Stormwater Discharges 29
8.9 Pits, Ponds, and Lagoons (On-site Process Water Discharge) 29

8.10 Wells 29
8.11 Underground Product Pipelines 30
8.12 Odors 30
8.13 Pools of Liquid 30
8.14 Stressed Vegetation or Stained Surfaces 30
8.15 Site Inspection Conclusions 31
9.0 ASTM NON-SCOPE CONSIDERATIONS 32
9.1 Asbestos-Containing Materials (ACM) 32
9.2 Lead-Based Paint (LBP) 32
9.3 Radon Gas 32
9.4 Apparent Mold Growth (AMG) 33
9.5 Lead In Drinking Water 33
9.6 Wetlands 33
10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS 35

APPENDICES

Appendix A: Site Maps, Plans and Photographs
- Site Location Map
- Site Plan
- Site Photographs

Appendix B: Historical Sources
- Historical Fire Insurance Maps
- Historical Aerial Photographs
- Historical Topographic Maps


Appendix C: Environmental Database Search Report
Appendix D: Qualifications of Professionals

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

This Phase I Environmental Site Assessment (ESA) Report documents the research methodology used by qualified environmental professionals of Blackstone to identify recognized environmental conditions using the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone.


We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR 312, and we have the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Prepared By:




John O'Connor — 06/03/16
Senior Project Manager — Date

Technical Review and Concurrence By:



Allan S. Coffee — 06/03/16
Senior Associate — Date

Principal Review By:



Stephen E. Manelis — 06/03/16
Principal — Date

dd

EXECUTIVE SUMMARY

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the La Rochelle located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York (site). The purpose of the Phase I ESA is to identify recognized environmental conditions (RECs) in general accordance with ASTM Standard E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide, dated April 29, 2011 (Fannie Mae DUS Guidelines), and other agreed-upon ASTM *Non-Scope Considerations (Business Environmental Risk Issues)*. It is understood that the site is being evaluated for loan considerations.

SITE INSPECTION

Name of Inspector: John O'Connor

Date of Inspection: May 25, 2016

Site Representative: Ms. Kimberly Periard, Community Manager, and Mr. Lennie Dawson, Maintenance Technician

SITE DESCRIPTION

Street Address: 255 and 275 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Tax Map Identification Numbers: 1-234-0001 (Apartment Building) and 2-418-0001 (Parking Garage)

Owner: New Rochelle Ind. Development Agency (Apartment Building)
Avalon Bay Communities Inc. (Parking Garage)

Site Size: Approximately 2.3 acres

Site Use: The site is developed with a 24-story apartment building, containing 412 total dwelling units, and a five-story parking structure. The site apartment building includes basement and penthouse mechanical levels, four street level commercial tenant spaces, and a single-story building extension containing the apartment amenities. Two of the commercial spaces are currently vacant and the remaining two are currently occupied by Sound Drycleaners (drop-off/pick-up only) and Metro Market (convenience store). The site property is bisected by Memorial Highway, which separates the parking garage from the apartment tower building; however, the apartment building and parking

garage are connected via a covered, elevated walkway over Memorial Highway.

Year Built: 2001

Structures	***Location On Site***	***Number of Stories***	***Size (approx. square feet)***
Apartment Building	Northern	24 with basement and penthouse mechanical levels	431,125 SF
Parking Garage	Southern	5	180,000

Other Site Features: Amenities and additional features at the site include a leasing/management office, a club room, a conference room, a common tenant laundry room, a fitness center, a yoga room, a tot room, an outdoor in-ground swimming pool, a picnic area, and a playground. Vertical transportation for the apartment building is provided by four cable-driven elevators. The remainder of the site consists concrete pedestrian walkways and moderate landscape features.

HISTORICAL INFORMATION

Reasonably ascertainable historical information indicates the site was initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. Historical commercial uses of the site included hotels, office space, retail stores, restaurants, a post office, a bowling alley, a theater, a "Chinese laundry" (1911 only), an auto sales and service facility (southwest corner from the 1930s until the 1980s), and surface parking lots. The former site structures were demolished between the early and mid-1990s, and the site was redeveloped with the present-day high rise apartment building and the present-day parking garage in 2001.

The site was identified with a small "Chinese laundry" facility in 1911. This type of facility in this era was typically a hand washing operation. The use of chlorinated solvents was not introduced into the dry cleaning industry until the late 1930s, and its use became widespread in the late 1940s following World War II. No addition historic cleaners or dry cleaning operations are identified on the site. Based on the era of operation and the duration of time since the facility was identified on the site (over 100 years), this laundry facility is not considered a REC.

Sound Drycleaning has been located at the site since at least the mid-2000s. However, this tenant only operated as a drop-off/pick-up only location, and is not involved in active drycleaning activities. This site tenant is not identified on any databases indicative of the generation or

disposal of hazardous wastes typically associated with an active drycleaning facility. As such, the site drycleaner tenant is not considered a REC.

The site historically contained an auto sales and service facility in the southwest corner of the site between at least the 1930s and the 1980s. This facility is not identified on any databases indicative of the generation, disposal or release of hazardous materials and/or waste, nor the operation of underground storage tanks (USTs). The site area where this facility was located is directly beneath the present-day site parking garage. There was no report of impacted soil or other remnants of the auto service operation encountered during the development of the site parking structure in 2001. Considering the current regulatory status (no reports releases), the amount of time that has passed since this facility was active (approximately 30 years), and that this site area has been redeveloped with a multi-story parking garage that would have necessitated significant excavation during construction, the historical presence of the auto sales and service facility in the southwest corner of the site is not considered a REC.

Historical information reviewed identified a 2000-gallon gasoline UST on the central-western area of the site, near the intersection of Memorial Highway and Railroad Place. According to the regulatory database, the UST was removed from the site on February 1, 2000, with some impacted soil discovered during removal. Based on the minor soil impacts discovered during removal, the site was listed with a Spills case. However, following the over-excavation of the UST area, all of the impacted soil was removed, the cleanup work was identified as having met applicable standards, and the case was issued regulatory closure on April 4, 2000. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current status (UST and impacted soil removed, regulatory closure issued and that the area of the UST has since been redeveloped with a high-rise apartment building with a basement level that required significant site excavation to develop, the historical presence of the UST at the site is not considered a REC.

The north and east-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures between the late 1800s and the late 1900s, including a drycleaning facility in the 1930s in the southern portion of the east-adjoining property, prior to the construction of the present-day improvements. The present-day surface parking lot to the adjoining east was constructed in the 1970s. The present-day Ruby Dee Park on Library Green was developed in the 2000s, the present-day Halstead New Rochelle apartment building to the adjoining east was constructed in the late 2000s, and the commercial development located in the southern portion of the east-adjoining property was constructed in the mid-1900s. The present-day Trinity St. Paul Anglican Episcopal Church to the adjoining south beyond Division Street was reportedly constructed in the 1860s. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

A "Chinese laundry" facility was historically located to the adjoining north in at least 1911 and a drycleaning facility was located in the southern portion of the east-adjoining property in at least the 1930s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. As stated previously, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. No addition cleaners or dry cleaning operations are identified on adjacent properties. Based on the era of operation and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities on the adjoining properties is not considered a REC.

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*) in connection with the site. No further investigation is recommended.

This section is only intended to represent a brief summary of our findings, and is not a detailed account of all the information provided in this report. The report should be reviewed in its entirety prior to drawing any final conclusions as to potential environmental conditions associated with the site.

1.0 INTRODUCTION

1.1 PURPOSE

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the La Rochelle located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York (site).

The purpose of this Phase I ESA is to investigate and identify *recognized environmental conditions* (*RECs*) associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines RECs as:

The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property due to any release to the environment, under conditions indicative of a release to the environment, or under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions.

A *de minimis condition* is a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Additionally, this Phase I ESA was conducted to identify *controlled recognized environmental conditions (CRECs)* associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines CRECs as:

A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by a regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This Phase I ESA also was conducted to identify *historical recognized environmental conditions* (*HRECs*) associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines HRECs as:

A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This practice is generally intended for the User to satisfy one of the requirements to qualify for the *innocent landowner, contiguous property owner,* or *bona fide prospective purchaser* limitations on CERCLA liability; that is, this practice constitutes all appropriate inquiries (AAI) into the

previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312.

ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) are detailed in Section 1.3 and outlined in the accepted scope detailed in the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone.

1.2 SPECIAL TERMS AND CONDITIONS

This Phase I ESA has been conducted in accordance with ASTM Standard Practice E 1527-13, the regulations at 40 CFR Part 312, and the Agreement between Walker & Dunlop and Blackstone. In addition, this Phase I ESA was conducted in accordance with the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide, dated April 29, 2011 (Fannie Mae DUS Guidelines). Qualifications of the professionals conducting this assessment have been provided in Appendix D.

Blackstone performed the professional services, obtained findings, rendered conclusions, and prepared recommendations in accordance with generally accepted practices of other environmental consultants undertaking similar assessments at the same time in the same geographical area.

Historical and environmental information pertaining to the site has been included in this report to the extent that such information is *practically reviewable*, as defined in the above-referenced standard practice.

1.3 SCOPE OF SERVICES

As detailed in the Agreement, this Phase I ESA was conducted in accordance with the industry standard ASTM Standard Practice E 1527-13 and as such in accordance with all appropriate inquiries (AAI) into the previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312. In addition, this Phase I ESA was conducted in accordance with the Fannie Mae DUS Guidelines. The Phase I ESA presented herein may vary from "guidelines" or "standards" required by organizations other than ASTM and Fannie Mae. This Phase I ESA included the following services:

1. A site inspection to identify and evaluate potential sources of RECs such as underground storage tanks (USTs), aboveground storage tanks (ASTs), equipment containing polychlorinated biphenyls (PCBs), waste and chemical storage areas, and wastewater and storm water discharges. The inspection included observations for evidence of chemical spills, releases, or on site waste disposal.

2. A review of site records and interviews with site representatives with regard to current and former site operations to identify known or potential environmental concerns.

3. A visual survey of the properties in the vicinity of the site to evaluate the potential for RECs at the site from these properties.

4. A review of historical information to identify RECs at the site from historic on-site and off-site uses. To the extent feasible under the conditions of the assessment, the historical information obtained included verbal information from site and/or local agency representatives. In addition, some or all of the following records, where *publicly available* and *practically reviewable*, were reviewed: construction plans, zoning maps, building permits, property record cards, topographic maps, fire insurance maps, historical city directories, and aerial photographs.

5. A review of State and Federal environmental database information.

Blackstone also performed the following activities to identify *Business Environmental Risk Issues* in addition to the ASTM requirements and as required by the Fannie Mae DUS Guidelines, and as required per the Agreement:

Document research, visual and/or sampling surveys, and interviews for the presence of:

- Asbestos-containing materials (ACM),
- Lead-based paint (LBP),
- Radon,
- Apparent mold growth (AMG),
- Lead in Drinking Water, and
- Wetlands.

The scope of this Phase I ESA did not include surface water, soil, soil vapor, or groundwater sampling. Consequently, conclusions provided with regard to surface water, soil, soil vapor, and groundwater impacts are limited to those that can be formed based on a non-intrusive investigation. The absence of environmental hazards in the subsurface cannot be guaranteed based on conditions observed on the surface.

Where performed, the limited ACM, LBP, AMG, and radon surveys are intended to provide an indication of the potential for significant environmental issues associated with these ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*). Hidden materials or locations such as those inside walls, inaccessible attics, crawl spaces, and inside ductwork and piping were not evaluated. As such, these surveys should not be regarded as comprehensive surveys for demolition or renovation purposes or indoor air quality health risk assessments, vapor intrusion into buildings, or explosion hazards.

1.4 SIGNIFICANT ASSUMPTIONS AND DATA GAPS

The site inspection consisted of a walkover of the site perimeter and exterior site areas, and a walk-through of the leasing office, common areas, maintenance/storage areas, mechanical rooms, parking garage, the commercial tenant spaces, and 42 representative dwelling units selected by Blackstone (Units 107, 117, 201, 202, 204, 310, 316, 402, 405, 410, 415, 1601, 1604, 1608, 1616, 1703,

1718, 1803, 1806, 1816, 1902, 1903, 1909, 1915, 2005, 2006, 2013, 2017, 2105, 2109, 2114, 2203, 2217, 2315, 2316, 2409, 2411, 2418, 2507, 2508, 2511, and 2516). The building interior was walked through at the direction of the Site Representative. Not all dwelling units were entered nor were all common and/or storage areas observed. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within the elevator pits. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

The historical information reviewed did not confirm the first developed use of the site. *Data failure*, as defined by ASTM, has occurred in attempting to identify obvious uses of the site back to the first developed use, or back to 1940, whichever is earlier. Information regarding the use of the site prior to 1887 was not available from the *standard historical sources* (including available aerial photographs, fire insurance maps, property tax files, recorded land title records, USGS topographic maps, local street directories, building department records, or zoning/land use records). There were no other reasonably ascertainable historical sources available for review that were considered sufficiently useful. It is the opinion of Blackstone that the data failure does not represent a significant data gap that impacts our ability to identify RECs.

Conclusions stated herein are based upon publicly available information and other documented sources. Blackstone has assumed, where reasonable, that the information reviewed is true and accurate. Blackstone assumes no responsibility for inaccurate information that is not otherwise obvious in light of information of which Blackstone has actual knowledge. Blackstone's site observations are of the conditions observed at the time of the assessment.

Blackstone reviewed an environmental database search report. Blackstone's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, Blackstone's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site.

This report provides an estimation of groundwater flow direction at the site based on visual observations and topographical data. This assessment did not include groundwater sampling and water table elevation measurement. True groundwater flow direction can only be determined through direct measurement of groundwater elevations from properly installed on-site groundwater monitoring wells. The groundwater flow direction estimation should not be considered a true measurement of groundwater flow direction.

2.0 USER PROVIDED INFORMATION

As defined under ASTM Standard Practice E 1527-13, Walker & Dunlop and Fannie Mae are considered the "User" of this Phase I ESA report. To qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002 (the "*Brownfields Amendments")*, the User must provide certain information based on their relationship to the purpose of the due diligence and as required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31.

As part of this Phase I ESA, Blackstone requested certain information from the User. The User did not provide the requested information to Blackstone pursuant to the User's Responsibilities described in ASTM Standard Practice E 1527-13 (Section 6.0) and as outlined below in Sections 2.2 through 2.4. However, there is no reason to believe that the absence of the User provided information would significantly alter the findings or recommendations set forth in this report or be considered a significant data gap.

The owner's representatives, Ms. Kimberly Periard, Community Manager, and Mr. Lennie Dawson, Maintenance Technician (collectively "Site Representative"), provided information about the site. The information requested and associated responses are outlined below in Section 2.5.

2.1 REASON FOR PERFORMING THE PHASE I ESA

Blackstone understands that this assessment was performed for Walker & Dunlop for financing purposes. In addition, this assessment was performed for Fannie Mae in consideration of making a potential loan secured by the site. As such, this Phase I ESA was performed as an appropriate risk management and environmental due diligence review associated with a potential real-estate collateralized lending transaction.

2.2 ENVIRONMENTAL LIENS AND ACTIVITY USE AND LIMITATIONS (AULS)

With reference to environmental liens that are filed or recorded against the site (40 CFR 312.25) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an environmental lien search as part of the scope of work.

With reference to activity and use limitations (AULs) that are in place on the site or that have been filed or recorded against the site (40 CFR 312.26(a)(1)(v) and (vi)) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an AUL search as part of the scope of work. In accordance with ASTM E 1527-13, Blackstone reviewed an environmental database search report that included a search of institutional control and engineering control databases as further discussed in Section 7.0.

2.3 SPECIALIZED KNOWLEDGE, COMMONLY KNOWN & DEGREE OF OBVIOUSNESS

With reference to specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28), the User did not provide any information to Blackstone regarding specialized knowledge or experience related to the site or nearby properties.

With reference to commonly known or *reasonably ascertainable* information about the site (40 CFR 312.30), the User did not provide any information to Blackstone regarding commonly known or *reasonably ascertainable* information about the site that would help the *environmental professional* to identify conditions indicative of releases or threatened releases, such as:

1. Past uses of the site;
2. Specific chemicals that are present or once were present at the site;
3. Spills or other chemical releases that have taken place at the site; and
4. Environmental cleanups that have taken place at the site.

The User provided Blackstone with a prior environmental report for the site, which is further discussed in Section 6.7.

With reference to the degree of obviousness of the presence or likely presence of releases or threatened releases at the site, and the ability to detect releases or threatened releases by appropriate investigation (40 CFR 312.31), the User did not provide any information to Blackstone regarding *obvious* indicators that point to the presence or likely presence of releases at the site.

2.4 VALUE REDUCTION FOR ENVIRONMENTAL ISSUES

The User did not provide information with reference to the relationship of the purchase price to the fair market value of the site if contamination is known or believed to be present at the site (40 CFR 312.29).

2.5 OWNER, KEY SITE MANAGER, AND OCCUPANT INFORMATION

Blackstone interviewed the Site Representative (including the Key Site Manager) regarding environmental conditions at the site. The Site Representative was not aware of: (1) pending, threatened, or past litigation relevant to environmental conditions on the site; (2) any pending, threatened, or past administrative proceedings relevant to environmental conditions in, on, or from the site; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to environmental conditions on the site.

The site owner was not available to provide information regarding the environmental conditions at the site. In addition, as the site is used for multi-family residential purposes, the occupants were not interviewed.

2.6 PAST OWNERS, OPERATORS AND OCCUPANT INTERVIEWS

In accordance with ASTM Standard Practice E 1527-13, interviews with past owners, operators, and occupants shall be conducted to the extent that they have been identified and that the information likely to be obtained is not duplicative of information already obtained. There is no reason to believe that such interviews were necessary for this site or would alter the findings or recommendations set forth in this report.

2.7 RELIANCE

Blackstone performed this Phase I ESA on behalf of and exclusively for Walker & Dunlop and Fannie Mae and each of their affiliates, attorneys, lenders, investors, successors and each of their assigns subject to the terms and conditions of the Agreement between Walker & Dunlop and Blackstone. This report is addressed to Walker & Dunlop and its affiliates. Walker & Dunlop and its affiliates, their respective successors and assigns (including, without limitation, investors who purchase the mortgage loan or a participation interest in the mortgage loan and the trustee in a securitization that includes the mortgage loan), each servicer of the mortgage loan, and all rating agencies involved in any sale, securitization or syndication involving the mortgage loan may use and rely upon this Report, including, without limitation, utilizing selected information from the Report in the offering materials (either in electronic or hard copy format) relating to any sale, securitization or syndication involving the mortgage loan. The Assessor agrees to cooperate in answering questions by any of the above parties in connection with the sale, securitization or syndication, as communicated by Walker & Dunlop personnel.

In addition, this assessment is subject to the stated limitations of the above-referenced Fannie Mae DUS Guidelines and other qualifications as described within the report. Any reliance upon this report by third parties beyond its intended purpose shall be at the parties' sole risk.

3.0 SITE DESCRIPTION

The site is located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York. A Site Location Map, depicted on the U.S. Geological Survey (USGS) *Mount Vernon, New York* topographic quadrangle, is included in Appendix A.

3.1 SITE CHARACTERISTICS AND FEATURES

Street Address: 255 and 275 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Tax Map Identification Numbers: 1-234-0001 (Apartment Building) and 2-418-0001 (Parking Garage)

Owner: New Rochelle Ind. Development Agency (Apartment Building)
Avalon Bay Communities Inc. (Parking Garage)

Site Size: Approximately 2.3 acres

Zoning: DMUR (Downtown Mixed Use Urban Renewal District) and is located with the Central Parking Area Overlay District

Site Use: The site is developed with a 24-story apartment building, containing 412 total dwelling units, and a five-story parking structure. The site apartment building includes basement and penthouse mechanical levels, four street level commercial tenant spaces, and a single-story building extension containing the apartment amenities. Two of the commercial spaces are currently vacant and the remaining two are currently occupied by Sound Drycleaners (drop-off/pick-up only) and Metro Market (convenience store). The site property is bisected by Memorial Highway, which separates the parking garage from the apartment tower building; however, the apartment building and parking garage are connected via a covered, elevated walkway over Memorial Highway.

Year Built: 2001

Structure	***Location On Site***	***Number of Stories***	***Size (approx. square feet)***
Apartment Building	Northern	24 with basement and penthouse mechanical levels	431,125 SF
Parking Garage	Southern	5	180,000

Construction Materials	
Apartment Building	The apartment building is structural steel and concrete framed with reinforced concrete beams, columns and floor decks. The foundation systems are presumed to be constructed of a concrete slab below grade with piers at column locations and perimeter grade beams with reinforced concrete foundation walls. The building exterior finishes consist of brick veneer with decorative aluminum elements at the window openings. The low-slope roofs are concrete framed and are primarily covered with IRMA (inverted roof membrane assembly) membranes; the mechanical penthouse low-slope roof is covered with modified bitumen cap sheets.
Parking Garage	The parking garage is reinforced concrete framed with reinforced concrete floor decks.
Heating/Cooling Systems:	Heating is provided by five central, natural gas-fired low-pressure boilers which distribute heated water to individual thru-wall mounted PTAC units within the dwelling units. The PTAC units also contain integral compressors/condensers for cooling. Domestic hot water is provided by four total central, natural gas-fired low-pressure boilers with external storage tanks.
Other Site Features:	Amenities and additional features at the site include a leasing/management office, a club room, a conference room, a common tenant laundry room, a fitness center, a yoga room, a tot room, an outdoor in-ground swimming pool, a picnic area, and a playground. Vertical transportation for the apartment building is provided by four cable-driven elevators. The remainder of the site consists concrete pedestrian walkways and moderate landscape features.

A Site Plan and Site Photographs are provided in Appendix A.

3.2 UTILITIES

Electricity Provider: Con Edison

Natural Gas Provider: Con Edison

Potable Water: United Water New York

Sewer Services: City of New Rochelle

According to the Site Representative, the site has been connected to the municipal systems for sanitary sewage disposal and potable water supply since construction was completed in 2001. The site was previously developed with multiple commercial and residential structures since at least the 1880s. The City of New Rochelle water and sewer systems date back to at least the late 1800s; therefore, it is likely that the former site buildings were connected to the municipal potable water and sanitary sewer systems.

No RECs were identified as a result of the review of the site as described in this section of the report.

4.0 VICINITY RECONNAISSANCE

The site is located in the City of New Rochelle, New York, within an area characterized by urban commercial development. Adjoining property use is summarized as follows:

North: Bridge Street followed by Chase Bank office building (270 North Avenue)

East: Huguenot Street followed by a surface parking lot, the Ruby Dee Park on Library Green, the Halstead New Rochelle apartments (40 Memorial Highway), and commercial development (multiple addresses along Huguenot Street, uses include a florist, a restaurant, and a market)

South: Division Street followed by the Trinity St. Paul Anglican Episcopal Church (311 Huguenot Street)

West: Station Plaza South followed by the New Rochelle train station, parking garage and associated railroad tracks

Source	Findings
Field observations	Blackstone observed no industrial, manufacturing or military operations such as outdoor chemical or hazardous waste storage or handling activities that may impact the site and no evidence of chemical spills, releases, or waste disposal was observed. From accessible vantage points, Blackstone identified no outdoor chemical or waste storage, wastewater treatment facilities, or other operations that may impact the site and no pits, ponds or lagoons for apparent discharge and/or treatment of process water.
Environmental databases search	Adjoining and/or nearby properties identified in the environmental databases searched are further discussed in Section 7.0.

No RECs were identified as a result of the vicinity reconnaissance.

5.0 PHYSICAL SETTING

	Findings	*Sources of Findings*
Surficial Soils Beneath Site	Urban land	EDR Report
Depth to Bedrock	Between 5 and 50 feet bgs	EDR Report
Topography	The site is relatively flat with an overall area declination to the east.	Site observations, USGS *Mount Vernon, New York,* topographic map and EDR Report
Elevation	Approximately 84 feet NAVD	USGS *Mount Vernon, New York,* topographic map and EDR Report
Depth to Shallow Groundwater	Approximately 10-30 feet bgs	EDR Report
Estimated Groundwater Flow Direction	East	USGS *Mount Vernon, New York,* topographic map and EDR Report

bgs: below ground surface
EDR Report: Environmental Data Resources Database Report with GeoCheck®
NAVD: North American Vertical Datum, 1988-1990
USGS: United States Geological Survey

No RECs were identified as a result of the physical setting records review.

6.0 HISTORICAL INFORMATION REVIEW

As part of this Phase I ESA, Blackstone reviewed historical information to identify RECs associated with the historical use of the site and surrounding properties. Blackstone obtained historical information from interviews with site representatives and other individuals familiar with the site as well as aerial photographs, historical maps, and other *practically reviewable* standard historical sources that are considered *reasonably ascertainable*.

6.1 HISTORICAL FIRE INSURANCE MAPS

Environmental Data Resources, Inc. (EDR) conducted a search of available historical fire insurance maps for the site and site vicinity. Historical fire insurance maps are scaled drawings that indicate the location and use of building structures present in a given area from as early as the late 1800s. The maps provide information regarding the development and historical use of site structures and can indicate the historical presence of tanks at the site and other potential environmental concerns.

Sanborn Fire Insurance Company maps were available for the site from EDR. Select Sanborn maps are reproduced in Appendix B and are summarized as follows:

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	Site	Adjoining Properties
1887	The site is depicted with three residential dwellings.	The north and east adjoining properties are depicted with residential and commercial development. The west-adjoining property is depicted with railroad tracks and a railroad passenger depot. The present-day church is depicted to the adjoining south.
1892	Multiple commercial structures are depicted along the northern perimeter of the site.	A portion of the east-adjoining property is depicted with a hospital.
1896	Additional commercial development is depicted at the site, including a hotel, several restaurants, a post office, and multiple offices.	The hospital is no longer depicted to the adjoining east.
1903	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1911	The site is depicted with multiple commercial structures, including a theater and a "Chinese laundry".	The north and east adjoining properties are depicted with urban commercial development. A "Chinese laundry" is depicted to the adjoining north.
1931	The site is depicted with multiple commercial structures, including a bowling alley. A used car sales and storage structure is depicted in the southwest corner of the site.	The north and east adjoining properties are depicted with urban commercial development. A drycleaning facility is depicted to the adjoining east.

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	Site	Adjoining Properties
1942	The former used car storage structure is identified as Hill Motors Corporation Chevrolet.	The adjoining properties are depicted as similar to the previous Sanborn map. The former drycleaning facility is no longer depicted to the adjoining east.
1951	Several surface parking lots are depicted in the northwest corner of the site.	The adjoining properties are depicted as similar to the previous Sanborn map.
1990	The site is depicted with multiple commercial structures and surface parking lots. A gas tank is depicted along the western perimeter of the site, near the intersection of Memorial Highway and Railroad Place (location of the present-day apartment building) adjoining a small retail building (identified with three retail stores).	The present-day office building is depicted to the adjoining north. Commercial development and surface parking lots are depicted to the adjoining east. The present-day church is depicted to the adjoining south. The present-day railroad station is depicted to the adjoining west.
1991	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1992	The site is primarily vacant land and surface parking lots, with one three-tenant retail structure and the adjoining gas tank remaining depicted along the western perimeter.	The adjoining properties are depicted as similar to the previous Sanborn map.
1993	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1994	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1995	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1996	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
2003	The site is depicted with the present-day apartment building and parking garage. None of the former improvement remain.	The present-day park is depicted to the adjoining east. The location of the present-day apartment building to the adjoining east is depicted as vacant land.

Findings: As further discussed in Section 6.8, the former auto sales and service facility, "Chinese laundry", and gas tank depicted on the site are not considered RECs, and the historical north adjoining "Chinese laundry" and east-adjoining drycleaning facility are not considered a REC. No RECs were identified as a result of the review of historical fire insurance maps.

6.2 AERIAL PHOTOGRAPHS

Aerial photographs of the site area were obtained from EDR. The aerial photographs are reproduced in Appendix B and are summarized as follows:

Year	Aerial Photographs: Development/Land Uses	
	Site	*Adjoining Properties*
1951	The site appears to be developed with multiple commercial structures. The northwest corner of the site appears to be a surface parking lot.	Urban commercial development is visible to the adjoining north and east. The present-day church structure is visible to the adjoining south. Railroad tracks and a presumed rail station are visible to the adjoining west.
1954	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1961	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1966	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1974	The site appears similar to the previous aerial photograph.	The present-day bank structure is visible to the adjoining north. The present-day surface parking lot is visible to the adjoining east.
1980	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1985	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1994	The site is primarily vacant land, with a surface parking lot visible in the northeast corner of the site and a small commercial-type structure along the western perimeter.	The adjoining properties appear similar to the previous aerial photograph.
2006	The site is developed with the present-day apartment building and parking garage.	The present-day park area is visible to the adjoining east. The present-day east-adjoining apartment building appears to be undergoing development.
2009	The site appears similar to the previous aerial photograph.	The present-day apartment building to the adjoining east is visible.
2011	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.

Findings: No RECs were identified as a result of the review of historical aerial photographs.

6.3 HISTORICAL TOPOGRAPHIC MAPS

Historical topographic maps of the site area were obtained from EDR. The historical topographic maps are included in Appendix B and are summarized as follows:

Year	Historical Topographic Maps: Development/Land Uses	
	Site	*Adjoining Properties*
1897	The site is depicted with areas of black shading (indicative of areas covered with buildings).	The adjoining properties are depicted with areas of black shading. Railroad tracks are depicted to the adjoining west.
1898	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1900	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1947	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1956	The site is depicted with pink shading (indicative of dense urban development).	The adjoining properties are depicted with pink shading. Railroad tracks are depicted to the adjoining west.
1966	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1979	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1995	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
2013	The 2013 topographic map does not include structures or shading (similar to a street map, except with contour lines).	

Findings: No RECs were identified as a result of the review of historical topographic maps.

6.4 AGENCY RECORDS, INTERVIEWS AND OTHER HISTORICAL SOURCES

In accordance with ASTM E1527-13, Blackstone requested site history and/or regulatory information regarding the site from federal, state and/or local government officials. Information regarding the site is obtained from regulatory agency officials either by:

1) Conducting interviews by telephone or in-person at various federal, state and/or local agencies; or

2) Requesting file information via submission of an open records request to the appropriate agency contact based upon applicable agency requirements, and in accordance with the Freedom of Information Act (FOIA).

Findings from the interviews/records review are summarized below:

Agency Records, Interviews and Other Historical Sources		
Source	*Information Requested*	*Findings*
City of New Rochelle Tax Assessor website	On-line query for development, ownership information, and tax assessment data.	No environmental concerns were identified. Typical site ownership and tax assessment data were obtained.
City of New Rochelle, City Clerk, FOIL Request Form, via email cityclerkinfo@newrochelleny.com	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any emergency environmental responses or incidents	A FOIA request was submitted to this agency. A response has not been received to date and is not considered reasonably ascertainable for inclusion in this report.
Zoning Map of the City of New Rochelle, New York, revised December 14, 2010	Zoning information	The site is zoned DMUR (Downtown Mixed Use Urban Renewal District) and is located with the Central Parking Area Overlay District.
New York State Department of Environmental Conservation (NYSDEC), online database	On-line spills incident, Petroleum Bulk Storage (PBS), and remediation database	Information obtained from the NYSDEC database is discussed in pertinent sections of the report.
NYSDEC FOIL Coordinator, via email (no name provided) access.records@dec.ny.gov	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any records of emergency environmental responses or incidents	A FOIA request was submitted to this agency. To date a response has not been received and available records are not considered reasonably ascertainable for inclusion in this report.

Findings: No RECs were identified from the review of the local agency records, interviews, or other readily available historical sources.

6.5 CITY DIRECTORIES

Blackstone requested a city directory review for the site address from EDR. City directories were reviewed at approximately five-year intervals for the years spanning 1972 through 2013. The present-day site address of 255 Huguenot Street was identified as the Portuguese American Club in the 1987 city directory and as the Avalon on the Sound Apartments with multiple residential listings in the city directories dated between 2003 and 2013. The present-day site address of 275 Huguenot Street was not identified in the city directories provided for review. The historical site addresses of 245-295 Huguenot Street (odd), 58-73 Memorial Highway (odd and even) and 55-65 Division Street (odd) was primarily identified with multiple commercial listings, including restaurants, offices, and retail outlets, in the city directories dated between 1972 and 1992. No listings of environmental concern were identified for the site.

The north-adjoining property at 270 North Avenue was identified as the National Bank of Westchester and professional office listings in the city directories dated between 1972 and 1982 and as Chase Bank and professional office listings in the city directories dated between 1987 and

2013. The east-adjoining properties are primarily identified with commercial listings in the city directories dated between 1972 and 2013. The east-adjoining property at 40 Memorial Highway is identified with multiple residential listings in the 2013 city directory. The south-adjoining property at 311 Huguenot Street is identified as the Trinity Episcopal Church in the city directories dated between 1972 and 2013. No listings of environmental concern were identified for the site.

No RECs were identified during the review of city directories.

6.6 ENVIRONMENTAL LIEN/AUL SEARCH

As previously discussed in Section 2.2, an environmental lien and activity & use limitation (AUL) search was not included in the scope of this assessment and was not provided to Blackstone for review by the User.

6.7 PREVIOUS ENVIRONMENTAL REPORTS

Blackstone was not provided with any previous environmental reports for review regarding the site.

6.8 HISTORICAL INFORMATION CONCLUSIONS

Reasonably ascertainable historical information indicates the site was initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. Historical commercial uses of the site included hotels, office space, retail stores, restaurants, a post office, a bowling alley, a theater, a "Chinese laundry" (1911 only), an auto sales and service facility (southwest corner from the 1930s until the 1980s), and surface parking lots. The former site structures were demolished between the early and mid-1990s, and the site was redeveloped with the present-day high rise apartment building and the present-day parking garage in 2001.

The site was identified with a small "Chinese laundry" facility in 1911. This type of facility in this era was typically a hand washing operation. The use of chlorinated solvents was not introduced into the dry cleaning industry until the late 1930s, and its use became widespread in the late 1940s following World War II. No addition historic cleaners or dry cleaning operations are identified on the site. Based on the era of operation and the duration of time since the facility was identified on the site (over 100 years), this laundry facility is not considered a REC.

Sound Drycleaning has been located at the site since at least the mid-2000s. However, this tenant only operated as a drop-off/pick-up only location, and is not involved in active drycleaning activities. This site tenant is not identified on any databases indicative of the generation or disposal of hazardous wastes typically associated with an active drycleaning facility. As such, the site drycleaner tenant is not considered a REC.

The site historically contained an auto sales and service facility in the southwest corner of the site between at least the 1930s and the 1980s. This facility is not identified on any databases indicative of the generation, disposal or release of hazardous materials and/or waste, nor the operation of underground storage tanks (USTs). The site area where this facility was located is directly beneath the present-day site parking garage. There was no report of impacted soil or other remnants of the auto service operation encountered during the development of the site parking structure in 2001. Considering the current regulatory status (no reports releases), the amount of time that has passed since this facility was active (approximately 30 years), and that this site area has been redeveloped with a multi-story parking garage that would have necessitated significant excavation during construction, the historical presence of the auto sales and service facility in the southwest corner of the site is not considered a REC.

The Sanborn maps from the 1990s included the depiction of a gasoline tank on the western portion of the site. As further discussed in Section 7.1, a 2000-gallon UST was removed from this area of the site in February 2000, during redevelopment activities. Some minor soil impacts were identified and excavated during the UST removal process, and the UST closure was approved by the lead regulatory agency; therefore, the historical presence of the UST at the site is not considered a REC.

The north and east-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures between the late 1800s and the late 1900s, including a drycleaning facility in the 1930s in the southern portion of the east-adjoining property, prior to the construction of the present-day improvements. The present-day surface parking lot to the adjoining east was constructed in the 1970s. The present-day Ruby Dee Park on Library Green was developed in the 2000s, the present-day Halstead New Rochelle apartment building to the adjoining east was constructed in the late 2000s, and the commercial development located in the southern portion of the east-adjoining property was constructed in the mid-1900s. The present-day Trinity St. Paul Anglican Episcopal Church to the adjoining south beyond Division Street was reportedly constructed in the 1860s. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

A "Chinese laundry" facility was historically located to the adjoining north in at least 1911 and a drycleaning facility was located in the southern portion of the east-adjoining property in at least the 1930s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. As stated previously, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. No addition cleaners or dry cleaning operations are identified on adjacent properties. Based on the era of operation and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities on the adjoining properties is not considered a REC.

No RECs were identified as a result of the historical records review.

7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW

EDR provided Blackstone a search report of federal, state, local, tribal and proprietary environmental databases to determine the environmental regulatory status of the site, adjoining facilities, and facilities identified within the specified approximate minimum search distance (AMSD) of the site. ASTM Standard E 1527-13 establishes the distance from the site that each database is searched. The database search report, including the date and a detailed description of each database searched, is provided in Appendix C.

The federal, state, local, tribal and proprietary databases searched, the search distances specified for each database, and the results of the environmental database search are summarized as follows:

7.1 FEDERAL, STATE, LOCAL, TRIBAL AND PROPRIETARY DATABASES

Blackstone reviewed the following databases:

Standard Environmental Record Sources	*Search Distance*
Federal Databases	
NPL: National Priority List Sites	1.0 mile
Proposed NPL: Proposed National Priority List Sites	1.0 mile
Delisted NPL: National Priority List Deletions	0.5 mile
NPL Liens: Federal Superfund Liens	Site only
FEDERAL FACILITY: Federal Facility Site Information Listing	1.0 mile
SEMS: Superfund Enterprise Management System	0.5 mile
SEMS-ARCHIVE: Superfund Enterprise Management System Archive	0.5 mile
RCRA CORRACTS: Resource Conservation and Recovery Act - Corrective Action Sites	1.0 mile
RCRA TSDF: RCRA – Treatment, Storage and Disposal Facilities	0.5 mile
RCRA LQGs: RCRA - Large-Quantity Generators	Site and adjoining
RCRA SQGs: RCRA - Small-Quantity Generators	Site and adjoining
RCRA CESQG: RCRA – Conditionally Exempt Small-Quantity Generators	Site and adjoining
US ENG CONTROLS: Engineering Controls Sites List	Site only
US INST CONTROL: Sites with Institutional Controls	Site only
LUCIS: Land Use Control Information System	0.5 mile
ERNS: Emergency Response Notification System	Site only
FEMA UST: FEMA Owned UST Listing	Site and adjoining
State and Tribal Databases	
NY SHWS: Inactive Hazardous Waste Disposal Sites in New York State	1.0 mile
NY VAPOR REPOPENED: Vapor Intrusion Legacy Site List	1.0 mile

Standard Environmental Record Sources	*Search Distance*
NY SWF/LF: Solid Waste Facilities & Landfill Sites	0.5 mile
NY LTANKS: Leaking Storage Tank Incident Reports	0.5 mile
NY HIST LTANKS: Historical Leaking Storage Tanks	0.5 mile
INDIAN LUST: Leaking Underground Storage Tanks on Indian Lands	0.5 mile
NY UST: Registered Underground Storage Tanks	Site and adjoining
NY CBS UST: Chemical Bulk Underground Storage Tank Database	Site and adjoining
NY MOSF UST: Major Oil Underground Storage Tank Facilities	Site and adjoining
NY AST: Registered Petroleum Bulk Aboveground Storage Tank	Site and adjoining
NY CBS AST: Chemical Bulk Aboveground Storage Tank Database	Site and adjoining
NY MOSF AST: Major Oil Aboveground Storage Tank Facilities	Site and adjoining
NY MOSF: Major Oil Storage Facilities Database	Site and adjoining
NY CBS: Chemical Bulk Storage Site Listings	Site and adjoining
INDIAN UST: Underground Storage Tanks on Indian Lands	Site and adjoining
NY ENG CONTROLS: Registry of Engineering Controls	Site only
NY INST CONTROL: Registry of Institutional Controls	Site only
NY RES DECL: Restrictive Declarations Listing	Site only
NY VCP: Voluntary Cleanup Agreements	0.5 mile
INDIAN VCP: Voluntary Cleanup Priority sites on Indian Lands	0.5 mile
NY ERP: Environmental Restoration Program Listing	0.5 mile
NY BROWNFIELDS: Brownfields Assessment Sites	0.5 mile

Additional Environmental Record Sources	*Search Distance*
Federal Databases	
US BROWNFIELDS: Listing of Brownfields Sites	0.5 mile
ODI: Open Dump Inventory	0.5 mile
DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations	0.5 mile
US CDL: United States Clandestine Drug Labs	Site only
US HIST CDL: National Clandestine Laboratory Register	Site only
LIENS 2: CERCLA Lien Information	Site only
HMIRS: Hazardous Materials Information Reporting System	Site only
RCRA Non-Gen: RCRA – Non Generators	Site and adjoining
DOT OPS: Department of Transportation Incident and Accident Data	Site only
DOD: Department of Defense Sites	1.0 mile
FUDS: Formerly Used Defense Sites	1.0 mile
CONSENT: Superfund (CERCLA) Consent Decrees	1.0 mile
ROD: Records of Decision	1.0 mile

Additional Environmental Record Sources	*Search Distance*
UMTRA: Uranium Mill Tailings Sites	0.5 mile
MINES: Mines Master Index File	0.25 mile
TRIS: Toxic Chemical Release Inventory System	Site only
TSCA: Toxic Substances Control Act	Site only
FTTS: Federal Insecticide, Fungicide & Rodenticide Act (FIFRA)/TSCA Tracking System	Site only
HIST FTTS: Historic FIFRA/TSCA Tracking System Listings	Site only
SSTS: Section 7 Tracking System	Site only
ICIS: Integrated Compliance Information System	Site only
PADS: PCB (Polychlorinated Biphenyl) Activity Database System	Site only
MLTS: Material Licensing Tracking System	Site only
RADINFO: Radiation Information Database	Site only
FINDS: Facility Index System/Facility Identification Initiative Program Summary	Site only
RAATS: RCRA Administrative Action Tracking System	Site only
RMP: Risk Management Plans	Site only
SCRD DRYCLEANERS: State Coalition For Remediation of Drycleaners Listing	0.5 mile
PCB TRANSFORMER: PCB Transformer Registration Database	Site only
COAL ASH EPA: Coal Combustion Residues Surface Impoundments List	0.5 mile
COAL ASH DOE: Steam-Electric Plant Operation Data – Power Plants	Site only
EPA WATCH LIST: EPA Watch List	Site only
2020 CORRECTIVE ACTION: 2020 Corrective Action Program List - RCRA	0.25 mile
US FIN ASSUR: Financial Assurance Information	Site only
PRP: Potentially Responsible Parties	Site only
US AIRS: Aerometric Information Retrieval System Facility Subsystem	Site only
LEAD SMELTERS: Lead Smelter Sites	Site only
UXO: Unexploded Ordnance Sites	1.0 mile
DOCKET HWC: Hazardous Waste Compliance Docket Listing	Site only
FUSRAP: Formerly Utilized Sites Remedial Action Program	1.0 mile
FUELS PROGRAM: EPA Fuels Program Registered Listing	0.25 mile
ECHO: Enforcement & Compliance History Information	Site only
State, Local and Tribal Databases	
NY SWTIRE: Registered Waste Tire Storage & Facility List	0.5 mile
NY SWRCY: Registered Recycling Facility List	0.5 mile
NY DEL SHWS: Delisted Registry Sites	1.0 mile
NY HIST UST: Historical Petroleum Bulk Underground Storage Tank Database	Site and adjoining
NY HIST AST: Historical Petroleum Bulk Aboveground Storage Tank Database	Site and adjoining
NY SPILLS: Spills Information Database	Site only
NY SPILLS 80: SPILLS 80 data from FirstSearch	Site only
NY SPILLS 90: SPILLS 90 data from FirstSearch	Site only
NY HIST SPILLS: Historical Spills Database	Site only
NY HSWDS: Hazardous Substance Waste Disposal Site Inventory	0.5 mile
NY UIC: Underground Injection Control Wells	Site only
NY MANIFEST: Facility & Manifest Data	0.25 mile
NY DRYCLEANERS: Registered Drycleaners	0.25 mile
NY NPDES: New York Pollutant Discharge Elimination System	Site only

Additional Environmental Record Sources	*Search Distance*
NY AIRS: Air Emissions Data	Site only
NY E DESIGNATION: E Designation Site Listing	Site only
NY FINANCIAL ASSURANCE: Financial Assurance Information Listing	Site only
NY COAL ASH: Coal Ash Disposal Site Listing	0.5 mile
INDIAN RESERV: Indian Reservations	1.0 mile
INDIAN ODI: Status of Open Dumps on Indian Lands	0.5 mile

EDR Proprietary Databases	*Search Distance*
MGP: Manufactured Gas Plants Database	1.0 mile
Historical Auto Stations	0.25 mile
Historical Cleaners	0.25 mile

EDR Recovered Government Archives	*Search Distance*
RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List	Site only
RGA LF: Recovered Government Archive Solid Waste Facilities List	Site only

The results of the database search are summarized as follows:

SITE:
The site, under the name Office Building at 8-10 Railroad Place, is identified on the Spills database. Review of the available Spills information indicates that the site dates to November 28, 1990, pertained to a release of gasoline from an underground storage tank (UST) that appeared to be leaking, the cleanup work was identified as having met standard, and the case was issued regulatory closure on May 8, 1991. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 25 years), and that the site has since been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listing on the Spills database is not considered a REC.

The site, under the name Sound Cleaners at 255 Huguenot Street/63 Memorial Highway, is identified on the EDR Historical Cleaners and Drycleaners databases. The site address is identified Sound Cleaners between 2009 and 2012. The EDR Historical Cleaners database is a proprietary database compiled exclusively from EDRs internal review of historical city directories and names potentially associated with dry cleaning related businesses, and is not indicative of a confirmed business location or operation. This site tenant is not identified on any additional databases indicative of the generation or disposal of hazardous wastes typically associated with an active drycleaning facility. Based on the site inspection and interviews, this facility has only been occupied as a drop off/pick up location, and dry cleaning performed on the site. As such, the site drycleaner listing is not considered a REC.

The site, under the name AvalonBay Communities/Avalon on the Sound at Memorial Highway and Huguenot Street, is identified on the UST and Spills databases. According to the UST database, a 2,000-gallon UST was removed from the site on February 1, 2000. Review of the available Spills information indicates that the spill dates to February 4, 2000, and pertained to the discovery of impacted soils during the removal of a UST, the cleanup work was identified as having met standard, and the case was issued regulatory closure on April 4, 2000. Review of information on the NYSDEC Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 15 years), and that the site has since

been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listings on the UST and Spills databases are not considered a REC.

ADJOINING OR FACILITIES IN CLOSE PROXIMITY:

Vacant Lot (Huguenot Street/Division Street) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 2005, pertained to the discovery of a release during a UST removal, cleanup work was performed, and the case was issued regulatory on March 15, 2006. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered a REC.

Shoreline Oil (296 Huguenot Street Rear) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 1988, pertained to a tank overfill, cleanup work was performed, and the case was issued regulatory on April 6, 1988. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered a REC.

Jones Residence/Trinity St. Paul's Episcopal Church (311 Huguenot Street) is located approximately 100 feet to the adjoining south of the site and crossgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the UST and LTANKS databases. Review of the available UST information indicates that this facility previously contained a UST that was closed in place in 2005. According to the LTANKS database, the case dates to 2004, pertained to the closure of a UST, no contamination was discovered in the soil samples obtained, and the case was issued regulatory on September 11, 2005. Considering the current regulatory status and the crossgradient position in relationship to the site, this facility is not considered a REC.

Con Edison (Memorial Highway and Huguenot Street/Division Street and Huguenot Street) is located to the adjoining east and downgradient of the site based on inferred direction of groundwater flow. This facility is listed on the RCRA-LQG, RCRA Non Gen/NLR, and Manifest databases. Con Edison has at least eight listings for the east-adjoining roadways on the Manifest database, presumably for the replacement of electrical transformers, that date to between 2007 and 2014. Con Edison is identified as a large quantity generator of hazardous waste in the form of lead and was previously a non-generator of hazardous waste. No RCRA violations have been identified. Based on the current regulatory status, this west adjoining facility is not considered a REC.

NON-ADJOINING FACILITIES WITHIN APPROXIMATE MINIMUM SEARCH DISTANCE:

As detailed in the EDR Report, several other facilities on various databases are within the Fannie Mae designated search parameters and the ASTM E 1527-13 Approximate Minimum Search Distance (AMSD). Based on factors such as distance to the site, topography, media affected (surface water, soil, soil vapor, groundwater, or air), depth to groundwater, anticipated and reported groundwater flow direction away from the site, hydrological separation, and/or a "Closed Out" and/or "No Further Action (NFA)" regulatory status, these non-adjoining facilities within the Fannie Mae designated search parameters and the AMSD are unlikely to have current or former releases of hazardous substances and/or petroleum products that could migrate to the site and are not considered RECs.

7.2 UNMAPPABLE FACILITIES

Due to inadequate address information or other erroneous facility information, several facilities listed in the environmental databases searched could not be plotted by EDR on a radius map. However, these facilities are still identified in the EDR report by grouping them into an unmappable facility summary. Blackstone reviewed this summary to determine if any of the listed facilities include or adjoin the site. The unmappable facility listings are summarized as follows:

SITE:
Not listed

ADJOINING FACILITIES:
None listed

7.3 AFFIRMATION

Blackstone's conclusions based on the EDR report are limited to the accuracy of that report. To the extent possible, field observations are used by Blackstone to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site. The database reviewed is sufficiently complete and current to be used as a source to satisfy the regulatory database requirements outlined in ASTM Standard E1527-13.

7.4 ENVIRONMENTAL DATABASE SEARCH AND REVIEW CONCLUSIONS

Based upon Blackstone's review of the EDR database report, no regulatory file reviews are warranted. No RECs were identified as a result of the environmental database search and review.

8.0 SITE INSPECTION

Name of Inspector: John O'Connor
Date of Site Inspection: May 25, 2016

SITE REPRESENTATIVE		
Name	*Title or Association with Site*	*Years Associated with Site*
Ms. Kimberly Periard	Community Manager	2.5 years
Mr. Lennie Dawson	Maintenance Technician	1 year

The site inspection consisted of a walkover of the site perimeter and exterior site areas, and a walk-through of the leasing office, common areas, maintenance/storage areas, mechanical rooms, parking garage, the commercial tenant spaces, and 42 representative dwelling units selected by Blackstone (Units 107, 117, 201, 202, 204, 310, 316, 402, 405, 410, 415, 1601, 1604, 1608, 1616, 1703, 1718, 1803, 1806, 1816, 1902, 1903, 1909, 1915, 2005, 2006, 2013, 2017, 2105, 2109, 2114, 2203, 2217, 2315, 2316, 2409, 2411, 2418, 2507, 2508, 2511, and 2516). The building interior was walked through at the direction of the Site Representative. Not all dwelling units were entered nor were all common and/or storage areas observed. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within the elevator pits. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

8.1 UNDERGROUND STORAGE TANKS (USTS)

Number of USTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
None					No

No physical evidence of current or former USTs was identified during the site inspection. The Site Representative was unaware of current or former USTs.

8.2 ABOVEGROUND STORAGE TANKS (ASTS)

Number of ASTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
1	175	Diesel	Exterior northern side of apartment building	Fuels emergency generator; registration not required. Equipment is owned by the site. No visible evidence of leaks or spills was observed. No concerns were identified.	No

No physical evidence of other current or former ASTs was identified during the site inspection. The Site Representative was unaware of any other current or former ASTs.

8.3 CHEMICALS AND MATERIALS USAGE

The following section describes non-bulk (55-gallons or less) chemical and petroleum storage at the site. Where applicable, all bulk fixed chemical and petroleum product storage (i.e. USTs and/or ASTs) is discussed in Sections 8.1 and 8.2.

Chemical or Material	*Use*	*Container Type*	*Location*	*REC*
Cleaning supplies	General maintenance	5-gallons or smaller	Maintenance storage areas and dwelling units	No
Pool chemicals	Pool maintenance	5-gallons or smaller	Pool equipment enclosure	No
General maintenance supplies (paints, cleaners, degreasers, adhesives, etc.)	General maintenance	5-gallons or smaller	Maintenance storage areas	No

No evidence of surface staining, spills, or releases was apparent in the chemical storage areas. All chemicals were observed to be properly stored. According to the Site Representative, no releases of chemicals or materials requiring emergency response and/or agency notification have occurred at the site.

8.4 HAZARDOUS WASTES

Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

No physical evidence of on-site hazardous waste generation, storage, or disposal was identified during the site inspection. The Site Representative was unaware of any on-site hazardous waste generation, storage, or disposal.

8.5 NON-HAZARDOUS WASTES

Non-Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
General refuse and recyclables	Residents and employees	Trash compactor	Trash room in the apartment building	Emptied regularly by contracted waste hauler	No

No physical evidence of on-site non-hazardous waste disposal was identified during the site inspection. The refuse area was observed in good condition. The Site Representative was unaware of any on-site non-hazardous waste disposal.

8.6 POLYCHLORINATED BIPHENYLS (PCBS)

PCBs can be present in coolants or lubricating oils used in older electrical transformers, hydraulic systems, and other similar equipment. The 1976 Toxic Substances Control Act (TSCA) extended regulatory control over the use of PCBs to the United States Environmental Protection Agency (USEPA). In November 1979, the USEPA generally prohibited the domestic manufacture of PCBs in electromagnets, transformers, and heat-transfer and hydraulic equipment.

Equipment	*Location*	*Owner*	*Status/Notes*	*REC*
Vaulted transformers	Presumed to be under the sidewalk site perimeters	Con Edison	See discussion below	No
Trash compactor	Eastern portion of the site	Site	See discussion below	No
Hydraulic elevator	Parking garage	Site	See discussion below	No

Blackstone did not observe any pad or pole-mounted transformers on the site, and it is assumed that the transformers serving the site are vaulted (presumed to be located under the sidewalk along the site perimeters). Based on the date the site buildings were constructed (2001), the presence of PCB-containing fluid is unlikely. In addition, should fluid spills or releases from an electrical transformer occur, associated remediation efforts are typically the responsibility of the transformer owner (Con Edison) per Federal regulation (40 CFR 761.125). As such, the transformers are not considered a REC.

The site contains a hydraulic trash compactor within a trash room in the apartment building. The compactor is owned by the site and is maintained and regularly emptied by a contracted waste disposal firm. The compactor hydraulic reservoir was observed in generally good condition, with no signs of staining or leakage beneath the reservoirs. Considering the presumed installation date of the compactor (2001), the presence of PCB-containing fluid is unlikely. As such, the hydraulic compactor is not considered a REC.

The site contains a hydraulic elevator that is located within the site parking garage. According to the Site Representative, the site elevator is are regularly maintained by a contracted service firm. No visible evidence of leakage was observed in connection with the hydraulic equipment. The elevator pit was not available for inspection. Based on the reported date of installation and the absence of observed leaks, the hydraulic elevator is not considered a REC.

8.7 WASTEWATER DISCHARGES

Type	*Generated By*	*Discharged To*	*Status/Notes*	*REC*
Sanitary	Residents and staff	Municipal sewer	No concerns noted	No

No physical evidence of septic systems, cesspools, clarifiers, or oil/water separators was observed during the site inspection. The Site Representative was unaware of other such features on the site.

8.8 STORMWATER DISCHARGES

Discharged From	*Discharged To*	*Status/Notes*	*REC*
Roof through internal inlets	Direct discharge to the municipal stormwater system	No concerns noted	No
Parking garage	Trench drains, with eventual discharge to the municipal stormwater system	No concerns noted	No
Exterior site surfaces	Directed to the adjoining streets and municipal stormwater system	No concerns noted	No

No stormwater retention ponds were observed on the site. No environmental issues were observed associated with the on-site stormwater flow. The Site Representative was unaware of any stormwater issues on the site.

8.9 PITS, PONDS, AND LAGOONS (ON-SITE PROCESS WATER DISCHARGE)

Type	*Contents*	*Location*	*Status/Notes*	*REC*
Grease trap (aboveground)	Cooking grease	Metro Market commercial tenant space	The grease trap is emptied on a monthly basis. No concerns were identified.	No

No other pits, ponds or lagoons used for process water discharge were observed at the site. The Site Representative was unaware of other such features on the site.

8.10 WELLS

Type	*Location*	*Status/Notes*	*REC*
None			No

No physical evidence of groundwater monitoring wells, injection wells, extraction wells, vapor wells, drywells, or groundwater production wells was identified during the site inspection. The Site Representative was unaware of any on-site wells.

8.11 UNDERGROUND PRODUCT PIPELINES

Type	*Location*	*Status/Notes*	*REC*
None			No

No physical evidence of underground product pipelines carrying petroleum or other hazardous substances was identified during the site inspection. The Site Representative was unaware of on-site product pipelines.

8.12 ODORS

Odors	*Location*	*Status/Notes*	*REC*
None			No

No unusual odors indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of such odors at the site.

8.13 POOLS OF LIQUID

Pools of Liquid	*Location*	*Status/Notes*	*REC*
None			No

No pools or sumps containing liquids indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of pools or sumps containing liquids at the site.

8.14 STRESSED VEGETATION OR STAINED SURFACES

Stressed Vegetation or Stained Surfaces	*Location*	*Status/Notes*	*REC*
None			No

No stained soils or stressed vegetation were observed by Blackstone. The Site Representative was unaware of stressed vegetation or stained surfaces.

8.15 SITE INSPECTION CONCLUSIONS

No evidence of RECs was identified in connection with the site as a result of the site inspection.

9.0 ASTM NON-SCOPE CONSIDERATIONS

Blackstone performed the following client-specific activities to identify ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) in addition to the ASTM and as required per the Agreement and Fannie Mae.

9.1 ASBESTOS-CONTAINING MATERIALS (ACM)

Frequently encountered types of ACM used in building construction include floor tile and mastic, spray-applied fireproofing, acoustical/decorative ceiling plaster, wallboard and joint compound, insulation, and many other building materials in common use prior to 1981. Materials that contain greater than one percent asbestos fibers are considered regulated ACM and must be handled according to USEPA and Occupational Safety and Health Administration (OSHA) regulations.

Based on the construction date of the site buildings (2001) and in accordance with the Fannie Mae DUS Guidelines, no bulk samples were collected and the presence of regulated ACM is unlikely. No further evaluation of ACM is recommended.

This limited survey should not be construed as a comprehensive asbestos survey for pre-demolition or pre-renovation purposes. As such, prior to demolition or renovation activities at the site, additional sampling of the specific materials to be disturbed will be necessary to satisfy National Emissions Standards for Hazardous Air Pollutants (NESHAPs) and state regulations. Furthermore, all regulated ACM must be handled in accordance with applicable regulations. These regulations may include removal of certain ACMs prior to renovation activities.

9.2 LEAD-BASED PAINT (LBP)

Considering the site buildings were developed after the recognized 1978 LBP determination date, the presence of LBP is unlikely and sampling of painted surfaces was not conducted as part of the scope of this assessment. No further evaluation of LBP is recommended.

9.3 RADON GAS

A review of records regarding radon concentrations in Westchester County, New York, was conducted to determine if concentrations of radon in the general area of the site are within the USEPA guidelines. The USEPA uses a continuous exposure level of 4.0 pCi/L (picoCuries per liter of air) or greater as a guidance level at which further evaluation and potential remedial actions are recommended.

According to USEPA Office of Radiation and Indoor Air information/mapping, the site is located within a Radon Zone Level 3. This zone has a predicted average indoor radon gas screening level less than 2.0 pCi/L, which is within USEPA guidance levels.

Based on the absence of ground-floor (on-slab) residential units, radon screening was not conducted at the site. No further evaluation of radon is recommended.

9.4 APPARENT MOLD GROWTH (AMG)

As part of this site assessment, Blackstone performed the following tasks: looked for evidence of AMG in the areas surveyed during the site assessment; made inquiries of property management regarding past and current leaks or known mold issues; made inquiries of property management whether there have been tenant complaints regarding health problems, musty odors or water leaks; observed areas where significant leaks were reported; and conducted a representative visual/olfactory survey for evidence of current or past water leakage and/or mold.

No AMG was observed within the dwelling units or common areas accessed. The Site Representative was not aware of AMG issues at the site and no tenant complaints were reported. As such, no further evaluation is recommended.

The limited AMG visual survey is intended to provide an indication of the potential for significant environmental issues associated with AMG. Due to the size of the site, all apartment units could not be examined for AMG. In addition, inaccessible areas such as behind walls, in crawl spaces, and inside ductwork were not inspected. As such, the limited AMG visual survey should not be regarded as a comprehensive survey.

9.5 LEAD IN DRINKING WATER

United Water New York provides drinking water to the site. The United Water New York 2015 Annual Water Quality Report indicates the municipal water system meets the requirements as established by the USEPA, state, and local authorities for lead content in drinking water. As such, no further investigation is recommended.

9.6 WETLANDS

As defined by the USEPA and U.S. Army Corps of Engineers (USACE), wetlands are "those areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions."


Wetlands possess three essential characteristics: (1) hydrophytic vegetation; (2) hydric soils; and (3) hydrology. All three characteristics must be prevalent to document an area as a jurisdictional wetland.

Wetlands	
Information Source	***Findings***
National Wetlands Inventory (NWI) on-line Wetland Mapper:	No mapped federal wetlands are located at the site.

Wetlands	
Information Source	***Findings***
(http://www.fws.gov/wetlands/Data/Mapper.html)	
Field observations	No vegetation or ponded areas that are characteristic of wetlands were observed at the site.

10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*) in connection with the site. No further investigation is recommended.



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York


Site Location Map

(USGS Mount Vernon, NY, Topographic Map, 1995)

N
W E
S

miles 0 0.5 1.0

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

Site Plan

(Not to Scale)

N
W E
S

BLACKSTONE CONSULTING LLC



PHOTOGRAPH 1
Site Signage



PHOTOGRAPH 2
Site Apartment Building Exterior



PHOTOGRAPH 3
Site Apartment Building Exterior



PHOTOGRAPH 4
Typical Dwelling Unit Interior



PHOTOGRAPH 5
Typical Dwelling Unit Interior



PHOTOGRAPH 6
Typical Site Water Boilers



PHOTOGRAPH 7
Typical Dwelling Unit HVAC Unit



PHOTOGRAPH 8
Hazardous Material Storage



PHOTOGRAPH 9
Site Swimming Pool



PHOTOGRAPH 10
Site Drycleaner Tenant Space (Pick-Up/Drop-Off Only)



PHOTOGRAPH 11
Emergency Generator with Integrated Aboveground Storage Tank for Diesel Fuel Storage



PHOTOGRAPH 12
Grease Trap in Commercial Tenant Space



PHOTOGRAPH 13
Parking Garage Exterior



PHOTOGRAPH 14
Parking Garage Interior



PHOTOGRAPH 15
Hydraulic Elevator Equipment Located within Parking Garage



PHOTOGRAPH 16
Elevated Walkway Between Parking Garage and Apartment Building



PHOTOGRAPH 17
North-Adjoining Property



PHOTOGRAPH 18
East-Adjoining Property



PHOTOGRAPH 19
West-Adjoining Property



PHOTOGRAPH 20
South-Adjoining Property




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2003 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1996 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1995 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1994 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1993 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1992 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1991 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1990 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1951 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1942 Sanborn Map

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1931 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1911 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1903 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1896 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1892 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1887 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2011 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2009 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

2006 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1994 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1985 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1980 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1974 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1966 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1961 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1954 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1951 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC

La Rochelle

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 4628045.4

May 24, 2016


EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Historical Topo Map

2013



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1979, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1966, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Mount Vernon, 1956, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

Historical Topo Map

1947



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mt Vernon, 1947, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

La Rochelle
255 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 4628045.2s
May 24, 2016

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	776
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

COORDINATES

Latitude (North):	40.9108080 - 40° 54' 38.90''
Longitude (West):	73.7835360 - 73° 47' 0.72''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602448.1
UTM Y (Meters):	4529356.5
Elevation:	84 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20110710
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1		255 HUGUENOT ST	EDR Hist Cleaner		TP
A2	OFFICE BUILDING	8-10 RAILROAD PLACE	NY Spills	Lower	1 ft.
A3		63 MEMORIAL HWY	EDR Hist Cleaner	Lower	6, 0.001, WSW
A4	SOUND CLEANER	63 MEMORIAL HWY	NY DRYCLEANERS	Lower	6, 0.001, WSW
B5	RESIDENCE	129 DIVISON ST	NY Spills	Higher	34, 0.006, SSW
A6	CONSOLIDATED EDISON	MEMORIAL HIGHWAY & H	NY MANIFEST	Higher	39, 0.007, South
B7	CON EDISON	HUGENOT & DIVISION S	NY MANIFEST	Higher	48, 0.009, SSW
B8	CON EDISON MANHOLE:	HUGENOT AVE & DIVISI	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	48, 0.009, SSW
B9	CON ED	DIVISION ST & HUGENO	NY MANIFEST	Higher	48, 0.009, SSW
B10	CON EDISON - TRANSFO	DIVISION ST AND HUGE	RCRA-LQG	Higher	48, 0.009, SSW
B11	CON EDISON	DIVISION & HUGUENOT	NY MANIFEST	Higher	48, 0.009, SSW
B12	CON EDISON	HUGENOT ST & DIVISIO	NY MANIFEST	Higher	48, 0.009, SSW
B13	CON EDISON TRANSFORM	DIVISION ST & HUGUEN	RCRA NonGen / NLR	Higher	48, 0.009, SSW
B14	NYSDOT BIN 1049890	DIVISION ST OVER MET	RCRA NonGen / NLR	Higher	52, 0.010, SSW
C15	METRO NORTH TRACKS	EAST OF NEW ROCHELLE	NY Spills	Lower	53, 0.010, WSW
C16	METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	NY Spills	Lower	53, 0.010, WSW
A17	MH1204	HUGUENOT AVE/LAWTON	NY Spills	Higher	100, 0.019, ESE
B18	MEMORIAL HIGHWAY AND	HUGUNOT ST	NY Spills	Higher	114, 0.022, South
B19	AVALON ON THE SOUND	HUGUENOT STREET AND	NY UST	Higher	116, 0.022, South
B20	VACANT LOT	HUGUENOT ST/DIVISION	NY LTANKS	Higher	165, 0.031, South
B21	ROAD	HUGUENOT ST/DIVISION	NY Spills	Higher	165, 0.031, South
B22	SHORELINE OIL	296 HUGENOT ST,REAR	NY LTANKS	Higher	174, 0.033, SSW
B23	LILLIAN VERNON CO.	WESTCHESTER PLACE	NY LTANKS	Higher	181, 0.034, South
C24	NYSDOT BIN 1091390	DIVISION ST OVER I 9	RCRA NonGen / NLR	Lower	190, 0.036, WSW
B25	NEW ROCHELLE IRISH B	38 DIVISION STREET	NY UST	Higher	208, 0.039, South
B26	JONES RESIDENCE	311 HUGUENOT STREET	NY LTANKS	Higher	239, 0.045, SSW
B27	TRINITY-ST. PAUL'S E	311 HUGUENOT STREET	NY UST	Higher	239, 0.045, SSW
D28	HUGUENOT AND NORTH A	HUGUENOT AND NORTH A	NY Spills	Higher	243, 0.046, NE
D29	CON EDISON MANHOLE:	HUGUENOT AVE & NORTH	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	243, 0.046, NE
D30	CON EDISON TRANSFORM	NORTH AVE & HUGUENOT	RCRA NonGen / NLR, NY MANIFEST	Higher	243, 0.046, NE
D31	CON EDISON MANHOLE:	HUGENUOT ST & NORTH	RCRA NonGen / NLR	Higher	243, 0.046, NE
E32	MAIN LIBRARY	LAWTON ST	NY LTANKS	Higher	243, 0.046, ESE
E33	ACCESSOCRAFT PRODUCT	48 LAWTON ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	245, 0.046, SE
F34	SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	NY Spills	Lower	261, 0.049, WSW
D35	UNITED STATES POST O	255 NORTH AVENUE	NY UST	Higher	261, 0.049, ENE
D36	US POSTAL SERVICE	255 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	261, 0.049, ENE
B37	CERUSSI AND VERE	306 HUGUENOT ST	NY UST	Higher	270, 0.051, SSW
B38	306 HUGUENOT STREET	306 HUGUENOT STREET	NY AST	Higher	270, 0.051, SSW
D39	KAUFMAN HUGUENOT COM	271 NORTH AVENUE	NY UST, NY AST	Higher	290, 0.055, NE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	PAVEMENT	41 LAWTON STREET	NY Spills	Higher	294, 0.056, ESE
E41	LAWTON STREET REALTY	41-43 LAWTON STREET	NY UST	Higher	294, 0.056, ESE
D42	FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	RCRA NonGen / NLR	Higher	295, 0.056, East
G43		24 STATION PLZ N	EDR Hist Cleaner	Lower	302, 0.057, NW
G44		24 STATION PLZ	EDR Hist Cleaner	Lower	302, 0.057, NW
H45	CABLE	29 DIVISION STREET	NY Spills	Higher	303, 0.057, South
I46	NORTH BROOK REALTY A	270 NORTH AVENUE - U	NY UST	Lower	329, 0.062, NNE
I47	277 NORTH LLC	277 NORTH AVENUE	NY LTANKS	Lower	382, 0.072, NNE
I48	CON EDISON MANHOLE:	277 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	382, 0.072, NNE
I49	BUSINESS	277 NORTH AVENUE	NY LTANKS	Lower	382, 0.072, NNE
I50	277 NORTH LLC	277 NORTH AVENUE	NY UST	Lower	382, 0.072, NNE
I51	EAST RIVER SAVINGS B	277 NORTH AVE.	NY LTANKS	Lower	382, 0.072, NNE
F52		107 DIVISION ST	EDR Hist Auto	Higher	392, 0.074, West
H53	ARIEL CABLE	19 DIVISION STREET/W	NY Spills	Higher	422, 0.080, South
J54	5 ANDERSON ST	5 ANDERSON ST	NY LTANKS	Higher	427, 0.081, East
J55	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY AST	Higher	427, 0.081, East
J56	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY UST	Higher	427, 0.081, East
E57	CON EDISON TRANSFORM	NORTH AVE & ANDERSON	RCRA NonGen / NLR, NY MANIFEST	Higher	428, 0.081, East
E58	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	428, 0.081, East
E59	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	428, 0.081, East
E60	CON EDISON	ANDERSON ST & NORTH	NY MANIFEST	Higher	428, 0.081, East
E61	MKM EQUITY, LLC	230 NORTH AVENUE	NY AST	Higher	447, 0.085, East
E62	CONCRETE FLOORING WI	230 NORTH AVENUE	NY Spills	Higher	447, 0.085, East
H63	COMM/RESIDENT. PROPE	15 DIVISION STREET	NY LTANKS	Higher	468, 0.089, South
E64	NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	NY LTANKS	Higher	486, 0.092, ESE
K65	APARTMENT BLDG	54 CENTRE AVE	NY LTANKS	Higher	487, 0.092, SSW
K66	CEMENT COURT YARD	54 CENTER AVE	NY Spills	Higher	487, 0.092, SSW
K67	SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	NY UST	Higher	487, 0.092, SSW
68		35 UNION AVE	EDR Hist Auto	Higher	519, 0.098, West
K69	CON EDISON	HUGUENOT ST & CENTRE	RCRA NonGen / NLR	Higher	521, 0.099, SSW
K70	CON EDISON	CENTER & HUGUENOT	NY MANIFEST	Higher	521, 0.099, SSW
K71	CON EDISON	CENTRE AVE & HUGUENO	NY MANIFEST	Higher	521, 0.099, SSW
K72	CON EDISON	HUGENOT & CENTRE ST	NY MANIFEST	Higher	521, 0.099, SSW
J73	CVS PHARMACY #8447	222 NORTH AVE	RCRA-LQG, NY MANIFEST	Higher	523, 0.099, ESE
L74	DELUXE TAXI	10 STATION PLAZA	NY UST	Lower	529, 0.100, North
I75	DEVELOPMENT SITE	175 HUGUENOT STREET	NY LTANKS, NY Spills	Higher	536, 0.102, NE
K76	M.J. HACKER & SONS I	64 CENTRE AVE	NY UST	Higher	538, 0.102, South
H77	RPM REALTY INC	9-15 DIVISION STREET	NY AST	Higher	543, 0.103, SSE
H78	RPM REALTY INC	9-15 DIVISION STREET	NY UST	Higher	543, 0.103, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K79	ERIC S TURNER & CO I	33-35 CENTRE AVE	RCRA-CESQG, NJ MANIFEST, NY MANIFEST	Higher	545, 0.103, SSW
M80	P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	NY Spills	Lower	560, 0.106, SW
M81	I-95	I-95EB MP54	NY Spills	Lower	560, 0.106, SW
N82	DEPOT PLACE LLC	1 DEPOT PLACE	NY UST	Lower	560, 0.106, NW
N83	STATION CLEANERS	1 DEPOT PLAZA #1	NY DRYCLEANERS	Lower	560, 0.106, NW
K84	GREEN HEAVEN/CENTRE	62 CENTRE AVE.	NY DRYCLEANERS	Higher	574, 0.109, SSW
K85		62 CENTRE AVE	EDR Hist Cleaner	Higher	574, 0.109, SSW
K86	SIMONETTI CLEANERS	62 CENTRE ST	RCRA-CESQG, US AIRS, FINDS, NY MANIFEST, ECHO	Higher	574, 0.109, SSW
K87	COMMERCIAL PROPERTY	64 CENTRE AVE	NY LTANKS	Higher	585, 0.111, SSW
O88	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	594, 0.112, SW
O89	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	594, 0.112, SW
P90	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	594, 0.112, NE
P91	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	594, 0.112, NE
P92	CON EDISON	HUGENOT ST & LECOUNT	NY MANIFEST	Higher	594, 0.112, NE
K93	NYNEX LOCATION	342 HUEGNOT ST	NY LTANKS	Higher	598, 0.113, SSW
J94	SPEEDY CLEANERS	217 NORTH AVENUE	US AIRS, FINDS, NY DRYCLEANERS, ECHO	Higher	598, 0.113, ESE
L95	SPOKEN ARTS BUILDING	310 NORTH AVENUE	NY UST	Lower	603, 0.114, North
J96	MACYS NEW ROCHELLE	THE MALL	NY UST	Higher	616, 0.117, East
L97	NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	NY UST	Lower	618, 0.117, North
O98	APPAREL PLUS	27 CENTRE AVE	NY Spills	Higher	624, 0.118, SW
Q99	SIDNEY FURNITURE	535 MAIN ST	NY Spills	Higher	632, 0.120, SSE
Q100	SPILL NUMBER 9900400	535 MAIN ST	NY Spills	Higher	632, 0.120, SSE
N101		35 GRAND ST	EDR Hist Auto	Lower	639, 0.121, NW
Q102	LILLIAN VERNON CORP.	543 MAIN STREET	NY LTANKS, NY Spills	Higher	649, 0.123, South
Q103	LILLIAN VERNON CORPO	543-549 MAIN STREET	NY UST	Higher	649, 0.123, South
Q104	543 MAIN STREET	543 MAIN STREET	NY UST	Higher	649, 0.123, South
K105	NEW YORK TELEPHONE C	342 HUGUENOT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	650, 0.123, SSW
K106	VERIZON	342 HUGUENOT ST	NY Spills	Higher	650, 0.123, SSW
K107	VERIZON NEW YORK INC	342 HUGUENOT STREET	NY UST, NY AST	Higher	650, 0.123, SSW
Q108	CON EDISON	S DIVSION ST & MAIN	NY MANIFEST	Higher	653, 0.124, SSE
Q109	CONSOLIDATED EDISON	DIVISION & MAIN	NY MANIFEST	Higher	653, 0.124, SSE
L110	CON EDISON MANHOLE:	313 NORTH AVE FRONT	RCRA NonGen / NLR	Lower	658, 0.125, North
R111	CON EDISON	208 NORTH AVE	NY MANIFEST	Higher	659, 0.125, ESE
K112	75 CENTRE AVENUE LLC	75 CENTRE AVENUE	NY UST, NY AST	Higher	662, 0.125, SSW
J113	MACYS	33 LE COUNT PLACE	NY MANIFEST	Higher	672, 0.127, East
L114	4 STORY APARTMENT BU	320 NORTH AVENUE	NY UST	Lower	674, 0.128, North
Q115	COMMERCIAL PROPERTY	522 MAIN STREET	NY LTANKS	Higher	681, 0.129, SSE
K116	COCO RESIDENCE	81 CENTRE AVE	NY LTANKS	Higher	684, 0.130, South
S117	COMMERCIAL BUILDING	507 MAIN STREET	NY LTANKS	Higher	690, 0.131, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q118	CON EDISON TRANSFORM	CHURCH ST & MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q119	CON EDISON TRANSFORM	MAIN ST & CHRUCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q120	CON EDISON MANHOLE:	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q121	CON EDISON	MAIN ST & CHURCH ST	NY MANIFEST	Higher	691, 0.131, SSE
K122	HUGUENOT HOLDINGS, L	347 HUGUENOT STREET	NY AST	Higher	702, 0.133, SSW
R123	CATHOLIC NEWS PUBLIS	210 NORTH AVE	NY LTANKS	Higher	723, 0.137, ESE
Q124	OFFICE BLDG	542 MAIN STREET	NY LTANKS	Higher	728, 0.138, South
Q125	542 MAIN STREET LLC	542 MAIN STREET	NY UST	Higher	728, 0.138, South
S126	NEW ROCHELLE PUBLIC	ONE LIBRARY PLAZA	NY UST	Higher	730, 0.138, SE
L127	CON EDISON MANHOLE:	NORTH ST & GARDEN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L128	CON EDISON MANHOLE 4	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L129	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L130	CON EDISON SERVICE B	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L131	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, FINDS, ECHO	Lower	732, 0.139, North
L132	CON EDISON - MANHOLE	GARDEN ST AND NORTH	RCRA-LQG, NY MANIFEST	Lower	732, 0.139, North
T133	BLOOMINGDALE PARKING	554 MAIN ST	NY UST	Higher	734, 0.139, South
R134	BARON MANAGEMENT	200 NORTH AVENUE	NY UST	Higher	736, 0.139, ESE
S135	BARCLAYS BANK OF NY/	491 MAIN ST.	NY LTANKS	Higher	749, 0.142, SE
S136	J P MORGAN CHASE BAN	491 MAIN STREET	NY UST, NY AST	Higher	749, 0.142, SE
S137	NEW ROCHELLE PUBLIC	1 LAWTON	NY LTANKS	Higher	751, 0.142, SE
N138	CIOTTI RESIDENCE	60 GRAND STREET	NY LTANKS, NY Spills	Lower	752, 0.142, NW
O139	MR CHIMNEY CLEAN	32 RELYEA PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	758, 0.144, SSW
Q140	NEW ROCHELLE SUPERMA	538 MAIN STREET	NY AST	Higher	770, 0.146, SSE
T141	HANGERS CLEANERS	562-564 MAIN STREET	NY DRYCLEANERS	Higher	777, 0.147, South
S142	ADREAN PRINTING CO	490 MAIN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	778, 0.147, SE
O143	PRO AUTO PARTS	41 REYLEA PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	780, 0.148, SW
U144	NYS THRUWAY AUTH	THRUWAY BRIDGE MP 60	RCRA NonGen / NLR, NY MANIFEST	Lower	784, 0.148, North
V145	FIRST METRO SERVICES	357 HUGONOT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	787, 0.149, SSW
N146	GUIDANCE CENTER INC	70 GRAND ST	NY LTANKS	Lower	789, 0.149, NW
T147	CENTRE MAIN EQUITIES	573-579 MAIN STREET	NY UST, NY AST	Higher	793, 0.150, South
T148	CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	NY LTANKS	Higher	802, 0.152, South
O149	INDUST OVERALL SERVI	10 BARTELS PLACE	NY LTANKS	Higher	806, 0.153, SW
O150	INDUSTRIAL OVERALL S	10 BARTELLS PLACE	NY UST	Higher	806, 0.153, SW
O151	INDUSTRIAL OVERALL S	10 BARTELS PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	806, 0.153, SW
O152	INDUSTRIAL OVERALL S	10 BARTELS PLACE	NY SHWS, NY CBS	Higher	806, 0.153, SW
O153	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY CBS AST	Higher	806, 0.153, SW
R154	RETTNER MANAGEMENT C	481 MAIN ST	NY UST	Higher	816, 0.155, SE
T155	CON EDISON TRANSFORM	CENTRE AVE & MAIN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	821, 0.155, South
T156	CON EDISON	MAIN ST & CENTRE ST	NY MANIFEST	Higher	821, 0.155, South

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
T157	CON ED	CENTRE AVE & MAIN ST	NY MANIFEST	Higher	821, 0.155, South
158	RITZCOVAN - TTF	22 BURLING LANE	NY LTANKS	Lower	827, 0.157, NNW
U159	CON EDISON MANHOLE:	NORTH AVE & BURLING	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	830, 0.157, North
W160	CASARRA RESIDENCE	9 BADEAU PL	NY LTANKS	Higher	869, 0.165, West
V161	STORAGE USA	363 HUGUENOT STREET	NY UST	Higher	869, 0.165, SSW
X162	DRIVE IT YOURSELF	20 GARDEN STREET	NY UST	Lower	922, 0.175, North
Y163	NYNEX	40 WASHINGTON AVE	NY LTANKS	Higher	924, 0.175, WNW
Z164	ROTH CLEANERS	1 LEROY PL	RCRA NonGen / NLR, FINDS, NY DRYCLEANERS, NY...	Higher	938, 0.178, SSE
Z165	CONSOLIDATED EDISON	DIVISION ST & LEROY	NY MANIFEST	Higher	957, 0.181, SSE
AA166	CON ED-V37	LECOUNT PL & MAIN ST	NY MANIFEST	Higher	959, 0.182, ESE
AA167	CON ED-V14	LECOUNT PL & MAIN ST	NY MANIFEST	Higher	959, 0.182, ESE
W168	RESIDENCE	18 BADEAU PLACE	NY LTANKS	Higher	964, 0.183, West
AB169	J B & FRANKS	27 BARTELS PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	977, 0.185, SW
Y170	ST GABRIEL SCHOOL	50 WASHINGTON AVE	NY LTANKS	Higher	985, 0.187, WNW
Y171	SAINT GABRIEL HIGH S	50 WASHINGTON AVENUE	NY UST	Higher	985, 0.187, WNW
Y172	50 WASHINTON AVE	50 WASHINTON AVE	NY LTANKS	Higher	985, 0.187, WNW
V173	CON EDISON	HUGENOT AVE & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
V174	CON EDISON	HUGUENOT ST & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
V175	CON EDISON	HUGENOT ST & COLUMBU	NY MANIFEST	Higher	990, 0.188, SSW
X176	FURNITURE RESTORNATI	26 GARDEN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	993, 0.188, NNE
W177	DIIORGI HOME	47 WARREN STREET	NY LTANKS	Higher	999, 0.189, WSW
U178	CON EDISON MANHOLE:	350 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1018, 0.193, North
AB179	CON EDISON	35 BARTELS PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1020, 0.193, SW
AB180	CON EDISON	35 BARTELS PL	NY MANIFEST	Lower	1020, 0.193, SW
AC181	BARRAGAN RESIDENCE	40 WARREN ST	NY LTANKS, NY Spills	Higher	1022, 0.194, WSW
AD182	CON EDISON TRANSFORM	595 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1035, 0.196, SSW
AB183	RUSH MFG CORP	18 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1054, 0.200, SSW
W184	NYNEX	UNION AVENUE AND WAR	NY MANIFEST	Higher	1063, 0.201, West
AD185	CON EDISON TRANSFORM	592 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1066, 0.202, South
186	CITIZEN	33 GROVE ST	NY LTANKS	Higher	1067, 0.202, WSW
AE187	THE MALL	MAIN STREET	NY LTANKS	Lower	1079, 0.204, East
AF188	175 MEMORIAL HWY. RE	175 MEMORIAL HWY.	NY UST	Higher	1079, 0.204, NW
AG189	CON EDISON SERVICE B	CENTRE AVE & LEROY	RCRA NonGen / NLR, FINDS	Higher	1085, 0.205, South
AG190	CON EDISON SERVICE B	LEROY PL & CENTER AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1085, 0.205, South
AG191	CON EDISON	CENTRE AVE & LEROY	NY MANIFEST	Higher	1085, 0.205, South
AH192	CON EDISON SERVICE B	174 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1093, 0.207, SE
AI193	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1098, 0.208, NNW
AI194	MAYCO, LLC	18-20 MAY ST	NY AST	Lower	1115, 0.211, NNW
AJ195	NEW ROCHELLE HOSPITA	COVION PLACE	NY LTANKS	Higher	1116, 0.211, NW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AI196	SCHMUCKLERS CLEANERS	360 NORTH AVE	RCRA-CESQG, NY MANIFEST	Lower	1117, 0.212, NNW
AI197	SCHMUKLER'S CLEANERS	360 NORTH AVE.	NY DRYCLEANERS	Lower	1117, 0.212, NNW
AE198	NEW ROCHELLE MALL	425 MAIN STREET	NY UST	Lower	1118, 0.212, East
AJ199	MONTEFIORE - NEW ROC	16 GUION PLACE	NY UST, NY AST	Higher	1143, 0.216, NW
AJ200	SOUND SHORE MEDICAL	16 GUION PL	PA MANIFEST	Higher	1143, 0.216, NW
AJ201	SOUTH SHORE MED CENT	16 GUION PLACE	NY LTANKS	Higher	1143, 0.216, NW
AJ202	SOUND SHORE MEDICAL	16 GUION PL	RCRA-SQG, FINDS, NY MANIFEST, ECHO	Higher	1143, 0.216, NW
203	RESIDENCE	79 WARREN ST	NY LTANKS	Higher	1145, 0.217, West
AF204	66 MEMORIAL BLVD	66 MEMORIAL BLVD	NY LTANKS	Higher	1146, 0.217, NW
AK205	LEXINGTON CENTER FOR	3 COTTAGE PL	NJ MANIFEST	Lower	1147, 0.217, NNE
AK206	LEXINGTON CENTER FOR	3 COTTAGE PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1147, 0.217, NNE
207	CON EDISON	46 CLINTON PL	RCRA-CESQG, NY MANIFEST	Higher	1156, 0.219, SE
AE208	MONROE COLLEGE	420 MAIN STREET	NY AST	Lower	1179, 0.223, East
AD209	CON EDISON	MAIN ST & MAPLE AVE	NY MANIFEST	Higher	1191, 0.226, SSW
AD210	CON EDISON	MAPLE AVE & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST	Higher	1191, 0.226, SSW
AD211	CON EDISON MANHOLE:	MAIN ST & MAPLE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1191, 0.226, SSW
AL212	CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NY MANIFEST	Lower	1192, 0.226, NE
AL213	CON EDISON MANHOLE 1	HUGEONOT ST & HARRIS	RCRA NonGen / NLR, NJ MANIFEST	Lower	1192, 0.226, NE
AC214	PREFERRED CLEANERS	95 UNION AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	1193, 0.226, West
AH215	SINNOTT MANAGEMENT C	35 CLINTON PLACE	NY AST	Higher	1198, 0.227, SE
AB216	ALL AMERICAN SPORTS	44 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1205, 0.228, SW
AH217	30 CLINTON PLACE OWN	30 CLINTON PLACE	NY UST, NY AST	Higher	1208, 0.229, SE
AH218	CO-OP	30 CLINTON PLACE	NY LTANKS	Higher	1208, 0.229, SE
AH219	CON EDISON	150 NORTH AV	NY MANIFEST	Higher	1211, 0.229, SE
AM220	NEW ROCHELLE FIRE ST	45 HARRISON STREET	NY UST, NY AST	Lower	1223, 0.232, ENE
AM221	CITY OF NEW ROCHELLE	45 HARRISON STREET	NY LTANKS	Lower	1223, 0.232, ENE
AM222	CON EDISON	45 HARRISON ST	NY MANIFEST	Lower	1223, 0.232, ENE
AH223	CON EDISON MANHOLE:	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1224, 0.232, SE
AH224	CON EDISON SERVICE B	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1224, 0.232, SE
AC225	100-102 UNION AVENUE	100-102 UNION AVENUE	NY LTANKS	Higher	1229, 0.233, West
AC226	LJNJ ASSOCIATES	100-102 UNION AVE	NY UST	Higher	1229, 0.233, West
AI227	CON EDISON TRANSFORM	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR, NY MANIFEST	Lower	1230, 0.233, NNW
AI228	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1230, 0.233, NNW
AI229	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1230, 0.233, NNW
AI230	CON EDISON	LOCKWOOD AVE & NORTH	NY MANIFEST	Lower	1230, 0.233, NNW
AM231	CON ED	HARRISON ST & CEDAR	NY MANIFEST	Lower	1231, 0.233, ENE
AC232	KAGEL HOME	99 UNION AVE	NY LTANKS	Higher	1232, 0.233, West
AG233	125	CENTRE AVE	NY LTANKS	Higher	1233, 0.234, South
AI234	368 NORTH AVE MGMT C	368 NORTH AVENUE	NY UST	Lower	1234, 0.234, NNW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL235	GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NY AST	Lower	1247, 0.236, NE
AL236	LONGINES WITTNAUER W	145 HUGUENOT ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1247, 0.236, NE
AL237	GALESI ENTERPRICES	145 HUGUENOT ST	NY LTANKS, NY Spills	Lower	1247, 0.236, NE
AM238	CON ED	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1250, 0.237, ENE
AM239	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1250, 0.237, ENE
AM240	CON EDISON	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1250, 0.237, ENE
AM241	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1250, 0.237, ENE
AE242	MONROE COLLEGE	5 FRANKLIN AVE	NY LTANKS	Lower	1252, 0.237, East
AI243	CASANOVA BROS. REALT	370 NORTH AVENUE	NY UST	Lower	1257, 0.238, NNW
AC244	TANK TEST FAILURE	50 WALNUT ST	NY LTANKS	Higher	1265, 0.240, WSW
AN245	DOMENICO PROCOPIO PR	618 MAIN ST	NY LTANKS, NY Spills	Higher	1279, 0.242, SSW
AN246	DOMENICO PROCOPIO	618 MAIN STREET	NY UST, NY AST	Higher	1279, 0.242, SSW
AC247	ROBERTS HOME	58 WALNUT STREET	NY LTANKS	Higher	1283, 0.243, WSW
AO248	@	60 WALNUT STREET	NY LTANKS	Higher	1289, 0.244, WSW
AN249	VACANT	399 HUGUENOT STREET	NY UST, NY AST	Lower	1295, 0.245, SSW
AH250	COLONIAL CLEANERS CO	149 NORTH AVE	RCRA NonGen / NLR	Higher	1299, 0.246, SE
AH251	FLAMINGO/TYK CLEANER	149 NORTH AV.	NY DRYCLEANERS	Higher	1299, 0.246, SE
AH252	FLAMINGO CLEANERS	149 NORTH AVE	RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Higher	1299, 0.246, SE
AH253	OFF-SITE FLAMINGO CL	149 NORTH AVENUE	NY BROWNFIELDS	Higher	1299, 0.246, SE
AP254	MAY PARTNERS, LLC	35-45 MAY STREET	NY AST	Lower	1306, 0.247, NNW
AM255	FIREHOUSE	HARRISON ST	NY LTANKS	Lower	1332, 0.252, ENE
AL256	BERGMAN REALTY SERVI	140 HUGUENOT STREET	NY LTANKS	Lower	1334, 0.253, ENE
AQ257	BLESSED SACREMENT CH	15 SHEA PL	NY LTANKS	Higher	1393, 0.264, South
AO258	APARTMENT BLDG.	114 UNION AVE.	NY LTANKS, NY Spills	Higher	1395, 0.264, West
AP259	DIMATTOE TTF	55 MAY STREET	NY LTANKS	Lower	1409, 0.267, NNW
260	CITY OF NEW ROCHELLE	1 HARRISON STREET	NY LTANKS	Lower	1414, 0.268, East
AN261	CUMBERLAND FARM	635 MAIN STREET	NY LTANKS, NY Spills	Higher	1419, 0.269, SSW
262	NEW ROCHELLE CATH MI	24 MAPLE AV	NY LTANKS, NY Spills	Higher	1425, 0.270, South
AR263	COMMERCIAL PROPERTY	38 LOCUST AVE	NY LTANKS	Higher	1442, 0.273, ESE
AR264	COMMERCIAL SITE	38 LOCUST AVE	NY LTANKS	Higher	1442, 0.273, ESE
AS265	SPILL NUMBER 0208792	386 NORTH AV	NY LTANKS	Lower	1452, 0.275, NNW
AT266	DEMELIA - TTF	95 WASHINGTON AVE	NY LTANKS	Higher	1453, 0.275, West
AQ267	BLESSED SACRAMENT HI	24 SHEA PLACE	NY LTANKS	Higher	1466, 0.278, South
AQ268	BLESSED SACRAMENT HS	24 SHEA PLACE	NY LTANKS	Higher	1466, 0.278, South
269	RESIDENCE	64 CHURCH ST	NY LTANKS	Higher	1486, 0.281, SSE
AU270	CANDREA/GALLETTA RES	35 CHARLES ST	NY LTANKS	Higher	1517, 0.287, WSW
AO271	SPILL NUMBER 0007965	45 CHARLES ST	NY LTANKS	Higher	1530, 0.290, WSW
AV272	RUSH MFG. CORP.	10-12 PINE CT	CORRACTS, RCRA-CESQG, NY Spills, FINDS, NJ...	Lower	1535, 0.291, SW
AV273	GKIDS REALTY	10/12 PINE COURT	NY LTANKS	Lower	1535, 0.291, SW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AT274	BRAM REALTY	105 WASHINGTON AVE	NY LTANKS	Higher	1553, 0.294, West
AU275	MERLUCCI RESIDENCE	30 CHARLES STREET	NY LTANKS	Higher	1553, 0.294, WSW
AS276	KGM PROPERTY ASSOC.	394 N. AVE.	NY LTANKS	Lower	1557, 0.295, NNW
AS277	KGM REALTY CO.	396 NORTH AVE.	NY LTANKS	Lower	1566, 0.297, NNW
AS278	GETTY# 677	381 NORTH AVE	NY LTANKS, NY Spills	Lower	1577, 0.299, NNW
AR279	APT. BUILDING	55-59 LOCUST AVE.	NY LTANKS	Higher	1587, 0.301, ESE
AW280	BLESSED SACRAMENT CH	SHEA PLACE	NY LTANKS	Higher	1629, 0.309, SSE
AX281	PROFESSIONAL BUILDIN	421 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	1642, 0.311, SSW
282	FRANKA INC.	132-143 UNION AVE.	NY LTANKS	Higher	1644, 0.311, West
AW283	APARTMENT HOUSE	156-168 CENTRE AVE	NY LTANKS	Higher	1652, 0.313, SSE
AW284	FAILED TANK TEST	156 CENTRE AVE	NY LTANKS	Higher	1652, 0.313, SSE
AS285	DIPASQUALE PROPERTY	400 NORTH AVE	NY LTANKS	Lower	1677, 0.318, NNW
AV286	INDUSTRIAL OVERALL S	30 PINE ST	RCRA-LQG, NY SHWS, NY Spills, FINDS, NJ MANIFEST,...	Lower	1691, 0.320, SW
287	POGLIA RES	119 WASHINGTON AVE	NY LTANKS	Lower	1698, 0.322, West
288	APT. BUILDING	47 MAPLE AV	NY LTANKS, NY Spills	Higher	1705, 0.323, South
289	SPILL 0106072 / PBS	370 MAIN ST	NY LTANKS	Lower	1706, 0.323, East
AY290	BUSINESS	88 GROVE AVE.	NY LTANKS	Higher	1715, 0.325, WSW
AY291	COMMERCIAL BUILDING	88-90 GROVE AVE.	NY LTANKS	Higher	1715, 0.325, WSW
292	ANON	108 VAN GUILDER AVE	NY LTANKS, NY Spills	Lower	1769, 0.335, WNW
AV293	BELIVE HOME	20 PINE STREET	NY LTANKS	Lower	1780, 0.337, SW
294	CON EDISON-CEDAR ST	ONE RAMADA PLAZA	EDR MGP	Lower	1794, 0.340, NE
295	CHURCH OF LATTER DAY	111 NORTH AVE	NY LTANKS	Lower	1799, 0.341, SE
296	APARTMENT BUILDING	67-70 LOCUST AVE	NY LTANKS	Lower	1824, 0.345, SE
AX297	SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	NY LTANKS	Lower	1836, 0.348, SSW
298	BUSINESS COMPLEX	55 WEBSTER AVE	NY LTANKS	Lower	1885, 0.357, SW
AZ299	APARTMENT BLDG	1 THE BOULEVARD	NY LTANKS	Lower	1898, 0.359, North
BA300	GETTY S/S	ECHO & BOSTON POST R	NY LTANKS	Lower	1913, 0.362, ENE
AZ301	PRIVATE DWELLING	19 ROCHELLE PLACE	NY LTANKS	Lower	1917, 0.363, NNW
BB302	RESIDENCE	14 REVERE RD	NY LTANKS	Lower	1923, 0.364, ENE
303	NEW ROCHELLE RADIOLO	150 LOCKWOOD AV	NY LTANKS, NY Spills	Higher	1933, 0.366, WNW
304	NICK MAZZA RESIDENCE	20 DAVIS AVE	NY LTANKS	Lower	1943, 0.368, SSE
BC305	SHERIDEN PLAZA	1 SHERIDEN PLAZA	NY LTANKS	Lower	1955, 0.370, NE
BD306	JASON PARTNERS LTD	675 MAIN ST	NY LTANKS	Lower	1968, 0.373, SSW
BE307	ABANDONED GAS STATIO	197 WEBSTER AV	NY LTANKS	Lower	1989, 0.377, West
BC308	MUTUAL BISCUIT COMPA	65 RIVER ST.	NY LTANKS, NY Spills	Lower	2002, 0.379, NE
BA309	GETTY 58114	340 MAIN STREET	NY LTANKS, NY Spills	Lower	2007, 0.380, ENE
BB310	SUNOCO / A-PLUS	71 HUGUENOT	NY LTANKS, NY Spills	Lower	2017, 0.382, ENE
BD311	6 WEBSTER	6 WEBSTER AVE	NY LTANKS	Lower	2025, 0.384, SSW
BF312	SPILL NUMBER 0314082	136 VANGUILDER AVE	NY LTANKS	Lower	2040, 0.386, West

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BG313	STEWART RESIDENCE	100 SICKLES AVE	NY LTANKS, NY Spills	Lower	2047, 0.388, NW
BE314	CITGO STATION	210 WEBSTER AVE	NY LTANKS, NY Spills	Lower	2090, 0.396, West
315	SPILL NUMBER 0302495	85 NORTH AVE	NY LTANKS, NY Spills	Lower	2097, 0.397, SE
BA316	JEROME RESIDENCE	33 ECHO AVE	NY LTANKS	Lower	2097, 0.397, ENE
BG317	BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NY LTANKS	Lower	2098, 0.397, NW
BH318	MICELI HOME	194 CENTRE AVE	NY LTANKS	Lower	2098, 0.397, SSE
BA319	POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	NY LTANKS	Lower	2111, 0.400, ENE
BG320	POINVIL RESIDENCE	107 SICKLES AVE	NY LTANKS	Lower	2113, 0.400, NW
BD321	AMOCO SERVICE STATIO	690 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	2128, 0.403, SSW
BI322	RESIDENCE	10 LAFAYETTE ST	NY LTANKS	Lower	2132, 0.404, East
BF323	YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	NY LTANKS	Lower	2133, 0.404, West
BJ324	COMMERCIAL-TTF	172 UNION AVE	NY LTANKS	Lower	2133, 0.404, West
BG325	TAHIR RESIDENCE	112 SICKLES AVE	NY LTANKS, NY Spills	Lower	2147, 0.407, NW
BK326	GAS STATION	44 ECHO AVE	NY LTANKS	Lower	2150, 0.407, ENE
BK327	DAVENPORT AUTO / WES	44 ECHO AVE	NY LTANKS, NY Spills	Lower	2150, 0.407, ENE
328	SPILL NUMBER 0012427	22 LAUREL PL	NY LTANKS	Lower	2158, 0.409, SSW
BH329	200 CENTRA CORP	200 CENTER AVE	NY LTANKS	Lower	2175, 0.412, SSE
BK330	CONSOLIDATED EDISON	ECHO AVENUE	NY SHWS	Lower	2178, 0.412, ENE
BJ331	FIRST ASSEMBLY OF GO	177 UNION AVE	NY LTANKS	Lower	2186, 0.414, West
332	48 1ST STREET	48 1ST STREET	NY LTANKS	Lower	2193, 0.415, WSW
BI333	GONCALVES RESIDENCE	1 LAFAYETTE STREET	NY LTANKS	Lower	2196, 0.416, East
BI334	GONCALVES RESIDENCE	1 LAFFAYETTE STREET	NY LTANKS	Lower	2196, 0.416, East
BG335	RESIDENCE	7 PRINCE ST	NY LTANKS	Lower	2198, 0.416, NW
BJ336	SPILL NUMBER 0210119	68 FIRST STREET	NY LTANKS	Lower	2212, 0.419, WSW
BG337	RENTAL HOUSE	119 SICKLES AVE.	NY LTANKS	Lower	2221, 0.421, NW
BL338	SPILL NUMBER 0104402	30 LINCOLN ST	NY LTANKS	Lower	2247, 0.426, NE
BJ339	SPILL NUMBER 0210366	182 UNION AV	NY LTANKS	Lower	2253, 0.427, West
BM340	PLASTIC WORKS	115 CEDAR ST	NY LTANKS	Lower	2268, 0.430, NNE
BH341	SPILL NUMBER 0202241	208 CENTER AVE	NY LTANKS, NY Spills	Lower	2277, 0.431, SSE
BL342	SPILL NUMBER 0300463	52 LINCOLN ST	NY LTANKS, NY Spills	Lower	2279, 0.432, NE
BM343	I-95 EXIT 16	OPP. 111 CEDAR ST.	NY LTANKS	Lower	2300, 0.436, NNE
BN344	SPILL NUMBER 0009195	17 POPLAR PL	NY LTANKS	Lower	2316, 0.439, SSE
BH345	RESIDENCE	6 POPLAR ROAD	NY LTANKS	Lower	2321, 0.440, SSE
346	LIPMAN RESIDENCE	54 LIBERTY AVE	NY LTANKS	Lower	2334, 0.442, South
BO347	TELEDYNE HYDRA-POWER	310 MAIN ST	NY SWF/LF, NY Spills, RCRA NonGen / NLR, FINDS, NY...	Lower	2335, 0.442, ENE
348	WALTON RESIDENCE	129 SICKLES AVE	NY LTANKS	Lower	2336, 0.442, NW
349	FIUMFREDO RESIDENCE	12 BAYVIEW AVE	NY LTANKS	Lower	2344, 0.444, East
350	CONTAMINATRED SOIL	23 FIRST ST	NY LTANKS	Lower	2360, 0.447, WSW
351	RESIDENCE	38 BEECHWOOD AVE	NY LTANKS	Lower	2367, 0.448, SW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BO352	DEFENDER MARINE SUPP	309 MAIN ST	NY LTANKS	Lower	2367, 0.448, ENE
BN353	FUNICELOLO HOME	24 POPLAR PLACE	NY LTANKS	Lower	2375, 0.450, SSE
BN354	LABELLA RESIDENCE	219 CENTRE AVE	NY LTANKS	Lower	2397, 0.454, SSE
355	SPILL NUMBER 0210080	196 UNION AV	NY LTANKS	Lower	2423, 0.459, West
BP356	RESIDENCE	98 LIBERTY AVE	NY LTANKS	Lower	2426, 0.459, South
357	MANONE PLACE	15 COLONIAL PLACE	NY LTANKS	Higher	2443, 0.463, WNW
358	TRINITY ARMS APARTME	25 TRINITY PLACE	NY LTANKS	Lower	2463, 0.466, SSE
BQ359	SPILL NUMBER 9814027	48 REMINGTON PL	NY LTANKS	Lower	2488, 0.471, NW
360	RITACCO HOME	24 JACKSON STREET	NY LTANKS	Lower	2490, 0.472, ENE
361	COMMERICAL BUILIDING	719 MAIN ST	NY LTANKS	Lower	2502, 0.474, SSW
362	CONSOLIDATED EDISON-	ECHO AVE	SEMS-ARCHIVE, RCRA-CESQG, NY Spills, NY MANIFEST	Lower	2505, 0.474, East
BP363	SPILL NUMBER 9803423	106 LIBERTY AV	NY LTANKS	Lower	2547, 0.482, South
364	TTF AT RESIDENCE	68 JACKSON ST	NY LTANKS	Lower	2558, 0.484, NE
BP365	COLLEGE OF NEW ROCHE	103 LIBERTY AVE	NY LTANKS	Lower	2565, 0.486, South
366	CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	NY LTANKS	Lower	2567, 0.486, SE
367	NELSTAD MATERIAL COR	40 HUNTINGTON PL	NY LTANKS, NY Spills, NY SPDES	Lower	2573, 0.487, ENE
BP368	BLANCO RESIDENCE	30 LINDEN PLACE	NY LTANKS	Lower	2575, 0.488, South
369	NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	NY SWF/LF	Lower	2583, 0.489, SW
370	7-UP BOTTLING CO	PALMER AVE & CEDAR S	NY LTANKS	Lower	2587, 0.490, NNE
371	NORTH EVARTS	44 NORTH EVARTS AVE	NY LTANKS	Lower	2588, 0.490, SE
BQ372	HERNANDEZ - TTF	70 REMINGTON PLACE	NY LTANKS	Higher	2588, 0.490, NW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
255 HUGUENOT ST 255 HUGUENOT ST NEW ROCHELLE, NY 10801	EDR Hist Cleaner	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent CERCLIS

NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

State and tribal leaking storage tank lists

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---- Underground Storage Tank Listing
NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF UST ---- Major Oil Storage Facilities Database
NY MOSF ---- Major Oil Storage Facility Site Listing
NY MOSF AST ---- Major Oil Storage Facilities Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing
NY ENG CONTROLS ---- Registry of Engineering Controls
NY INST CONTROL ---- Registry of Institutional Controls

State and tribal voluntary cleanup sites

NY VCP ---- Voluntary Cleanup Agreements
INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---- Registered Recycling Facility List
NY SWTIRE ---- Registered Waste Tire Storage & Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---- Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database

NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY UIC ---- Underground Injection Control Wells
FUELS PROGRAM ---- EPA Fuels Program Registered Listing

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 03/07/2016 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON-	***ECHO AVE***	***E 1/4 - 1/2 (0.474 mi.)***	***362***	***749***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/09/2015 has revealed that there is 1

CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSH MFG. CORP.	***10-12 PINE CT***	***SW 1/4 - 1/2 (0.291 mi.)***	***AV272***	***531***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 4 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO	DIVISION ST AND HUGE	SSW 0 - 1/8 (0.009 mi.)	B10	16
CVS PHARMACY #8447	***222 NORTH AVE***	***ESE 0 - 1/8 (0.099 mi.)***	***J73***	***93***
FLAMINGO CLEANERS	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***L132***	***210***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/09/2015 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ202***	***375***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 4 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ERIC S TURNER & CO I	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
SIMONETTI CLEANERS	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***K86***	***133***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***207***	***399***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***NNW 1/8 - 1/4 (0.212 mi.)***	***AI196***	***348***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.153 mi.)***	***O152***	***257***
Site Code: 413917				
Class Code: Significant threat to the public health or environment - action required.				

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***30 PINE ST***	***SW 1/4 - 1/2 (0.320 mi.)***	***AV286***	***580***
Site Code: 355304				
CONSOLIDATED EDISON	ECHO AVENUE	ENE 1/4 - 1/2 (0.412 mi.)	BK330	693
Site Code: 56077				

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 01/05/2016 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELEDYNE HYDRA-POWER	***310 MAIN ST***	***ENE 1/4 - 1/2 (0.442 mi.)***	***BO347***	***716***
NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	SW 1/4 - 1/2 (0.489 mi.)	369	771

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 163 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VACANT LOT Spill Number/Closed Date: 0510542 / 2006-03-15 Site ID: 356539 Program Number: 0510542	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B20	27
SHORELINE OIL Spill Number/Closed Date: 8709425 / 1988-04-06 Site ID: 83347 Program Number: 8709425	296 HUGENOT ST,REAR	SSW 0 - 1/8 (0.033 mi.)	B22	29
LILLIAN VERNON CO. Spill Number/Closed Date: 9213055 / 1995-03-16 Site ID: 201286 Program Number: 9213055	WESTCHESTER PLACE	S 0 - 1/8 (0.034 mi.)	B23	31
JONES RESIDENCE Spill Number/Closed Date: 0410335 / 2005-09-11 Site ID: 335236 Program Number: 0410335	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	B26	34
MAIN LIBRARY Spill Number/Closed Date: 9713843 / 1998-03-27 Site ID: 273025 Program Number: 9713843	LAWTON ST	ESE 0 - 1/8 (0.046 mi.)	E32	41
5 ANDERSON ST Spill Number/Closed Date: 9812585 / 1999-07-12 Spill Number/Closed Date: 8803214 / 1989-11-30 Spill Number/Closed Date: 9812584 / 1999-07-12 Site ID: 68771 Site ID: 68769 Site ID: 68770 Program Number: 9812585 Program Number: 8803214 Program Number: 9812584	5 ANDERSON ST	E 0 - 1/8 (0.081 mi.)	J54	68
COMM/RESIDENT. PROPE Spill Number/Closed Date: 9405558 / 2005-02-10 Site ID: 119901 Program Number: 9405558	15 DIVISION STREET	S 0 - 1/8 (0.089 mi.)	H63	81
NEW ROCHELLE PUBLIC Spill Number/Closed Date: 9111450 / 1992-02-06 Site ID: 306853 Program Number: 9111450	MEMORIAL HIGHWAY	ESE 0 - 1/8 (0.092 mi.)	E64	82
APARTMENT BLDG Spill Number/Closed Date: 0206558 / 2005-02-27	54 CENTRE AVE	SSW 0 - 1/8 (0.092 mi.)	K65	83

Spill Number/Closed Date: 0403405 / 2004-12-10
Site ID: 254563
Site ID: 84302
Program Number: 0206558
Program Number: 0403405

DEVELOPMENT SITE ***175 HUGUENOT STREET*** ***NE 0 - 1/8 (0.102 mi.)*** ***I75*** ***111***
Spill Number/Closed Date: 0512575 / 2006-03-08
Site ID: 358910
Program Number: 0512575

COMMERCIAL PROPERTY 64 CENTRE AVE SSW 0 - 1/8 (0.111 mi.) K87 145
Spill Number/Closed Date: 1308480 / 2015-04-28
Site ID: 489220
Program Number: 1308480

NYNEX LOCATION 342 HUEGNOT ST SSW 0 - 1/8 (0.113 mi.) K93 157
Spill Number/Closed Date: 9708146 / 1997-10-10
Site ID: 270876
Program Number: 9708146

LILLIAN VERNON CORP. ***543 MAIN STREET*** ***S 0 - 1/8 (0.123 mi.)*** ***Q102*** ***167***
Spill Number/Closed Date: 0308082 / 2004-05-12
Site ID: 94435
Program Number: 0308082

COMMERCIAL PROPERTY 522 MAIN STREET SSE 1/8 - 1/4 (0.129 mi.) Q115 187
Spill Number/Closed Date: 1100723 / 2011-06-06
Site ID: 448142
Program Number: 1100723

COCO RESIDENCE 81 CENTRE AVE S 1/8 - 1/4 (0.130 mi.) K116 188
Spill Number/Closed Date: 0311339 / 2005-01-10
Site ID: 313391
Program Number: 0311339

COMMERCIAL BUILDING 507 MAIN STREET SSE 1/8 - 1/4 (0.131 mi.) S117 189
Spill Number/Closed Date: 9110835 / 1992-03-10
Site ID: 286303
Program Number: 9110835

CATHOLIC NEWS PUBLIS 210 NORTH AVE ESE 1/8 - 1/4 (0.137 mi.) R123 197
Spill Number/Closed Date: 0503023 / 2005-08-28
Site ID: 347516
Program Number: 0503023

OFFICE BLDG 542 MAIN STREET S 1/8 - 1/4 (0.138 mi.) Q124 199
Spill Number/Closed Date: 0509995 / 2006-03-22
Site ID: 355877
Program Number: 0509995

BARCLAYS BANK OF NY/ 491 MAIN ST. SE 1/8 - 1/4 (0.142 mi.) S135 214
Spill Number/Closed Date: 8905129 / 1991-03-25
Site ID: 299548
Program Number: 8905129

NEW ROCHELLE PUBLIC 1 LAWTON SE 1/8 - 1/4 (0.142 mi.) S137 216
Spill Number/Closed Date: 1311408 / Not Reported
Spill Number/Closed Date: 0201697 / 2002-09-18
Site ID: 492304
Site ID: 306611
Program Number: 1311408

Program Number: 0201697

CENTRE-MAIN ASSOCIAT Spill Number/Closed Date: 0311823 / 2004-12-30 Site ID: 149369 Program Number: 0311823	75 - 77 CENTER AVE	S 1/8 - 1/4 (0.152 mi.)	T148	240
INDUST OVERALL SERVI Spill Number/Closed Date: 1400928 / Not Reported Site ID: 494186 Program Number: 1400928	10 BARTELS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O149	242
CASARRA RESIDENCE Spill Number/Closed Date: 0209171 / 2003-02-05 Site ID: 157707 Program Number: 0209171	9 BADEAU PL	W 1/8 - 1/4 (0.165 mi.)	W160	271
NYNEX Spill Number/Closed Date: 8803234 / 1988-07-22 Site ID: 60528 Program Number: 8803234	40 WASHINGTON AVE	WNW 1/8 - 1/4 (0.175 mi.)	Y163	273
RESIDENCE Spill Number/Closed Date: 9609269 / 1996-10-24 Site ID: 177416 Program Number: 9609269	18 BADEAU PLACE	W 1/8 - 1/4 (0.183 mi.)	W168	288
ST GABRIEL SCHOOL Spill Number/Closed Date: 0302359 / 2003-12-12 Site ID: 314440 Program Number: 0302359	50 WASHINGTON AVE	WNW 1/8 - 1/4 (0.187 mi.)	Y170	291
50 WASHINTON AVE Spill Number/Closed Date: 0305820 / 2003-12-23 Site ID: 280324 Program Number: 0305820	50 WASHINTON AVE	WNW 1/8 - 1/4 (0.187 mi.)	Y172	294
DIIORGI HOME Spill Number/Closed Date: 0500295 / 2005-08-28 Site ID: 343230 Program Number: 0500295	47 WARREN STREET	WSW 1/8 - 1/4 (0.189 mi.)	W177	303
BARRAGAN RESIDENCE Spill Number/Closed Date: 0109254 / 2001-12-19 Spill Number/Closed Date: 0812107 / 2009-03-03 Site ID: 150939 Site ID: 409713 Program Number: 0109254 Program Number: 0812107	***40 WARREN ST***	***WSW 1/8 - 1/4 (0.194 mi.)***	***AC181***	***317***
CITIZEN Spill Number/Closed Date: 8708588 / 1989-11-28 Site ID: 135309 Program Number: 8708588	33 GROVE ST	WSW 1/8 - 1/4 (0.202 mi.)	186	335
NEW ROCHELLE HOSPITA Spill Number/Closed Date: 9003911 / 1991-03-15 Site ID: 136814 Program Number: 9003911	COVION PLACE	NW 1/8 - 1/4 (0.211 mi.)	AJ195	347
SOUTH SHORE MED CENT Spill Number/Closed Date: 0512440 / 2006-12-19 Site ID: 358758	16 GUION PLACE	NW 1/8 - 1/4 (0.216 mi.)	AJ201	373

Program Number: 0512440				
RESIDENCE Spill Number/Closed Date: 0510555 / 2006-03-28 Site ID: 356553 Program Number: 0510555	79 WARREN ST	W 1/8 - 1/4 (0.217 mi.)	203	392
66 MEMORIAL BLVD Spill Number/Closed Date: 0002907 / 2000-10-24 Site ID: 59397 Program Number: 0002907	66 MEMORIAL BLVD	NW 1/8 - 1/4 (0.217 mi.)	AF204	393
CO-OP Spill Number/Closed Date: 9504589 / 1997-04-15 Site ID: 189169 Program Number: 9504589	30 CLINTON PLACE	SE 1/8 - 1/4 (0.229 mi.)	AH218	426
100-102 UNION AVENUE Spill Number/Closed Date: 9608199 / 1996-11-08 Site ID: 166425 Program Number: 9608199	100-102 UNION AVENUE	W 1/8 - 1/4 (0.233 mi.)	AC225	438
KAGEL HOME Spill Number/Closed Date: 0513684 / 2006-03-09 Site ID: 360201 Program Number: 0513684	99 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AC232	452
125 Spill Number/Closed Date: 0001835 / 2000-05-15 Site ID: 205498 Program Number: 0001835	CENTRE AVE	S 1/8 - 1/4 (0.234 mi.)	AG233	453
TANK TEST FAILURE Spill Number/Closed Date: 1107925 / 2013-02-05 Site ID: 455637 Program Number: 1107925	50 WALNUT ST	WSW 1/8 - 1/4 (0.240 mi.)	AC244	475
DOMENICO PROCOPIO PR Spill Number/Closed Date: 9809866 / 2004-03-30 Site ID: 278454 Program Number: 9809866	***618 MAIN ST***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN245***	***476***
ROBERTS HOME Spill Number/Closed Date: 0608623 / 2012-08-17 Site ID: 372634 Program Number: 0608623	58 WALNUT STREET	WSW 1/8 - 1/4 (0.243 mi.)	AC247	480
@ Spill Number/Closed Date: 0502010 / 2005-07-17 Site ID: 346287 Program Number: 0502010	60 WALNUT STREET	WSW 1/8 - 1/4 (0.244 mi.)	AO248	481
BLESSED SACREMENT CH Spill Number/Closed Date: 0204856 / 2003-10-03 Site ID: 167332 Program Number: 0204856	15 SHEA PL	S 1/4 - 1/2 (0.264 mi.)	AQ257	506
APARTMENT BLDG. Spill Number/Closed Date: 9414493 / 1995-02-14 Spill Number/Closed Date: 0011198 / 2001-04-06 Site ID: 238808 Site ID: 151446 Program Number: 9414493	***114 UNION AVE.***	***W 1/4 - 1/2 (0.264 mi.)***	***AO258***	***507***

Program Number: 0011198

CUMBERLAND FARM	***635 MAIN STREET***	***SSW 1/4 - 1/2 (0.269 mi.)***	***AN261***	***513***
Spill Number/Closed Date: 9206930 / 2005-03-11				
Site ID: 140421				
Program Number: 9206930				
NEW ROCHELLE CATH MI	***24 MAPLE AV***	***S 1/4 - 1/2 (0.270 mi.)***	***262***	***516***
Spill Number/Closed Date: 0204857 / 2003-10-03				
Site ID: 80066				
Program Number: 0204857				
COMMERCIAL PROPERTY	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AR263	519
Spill Number/Closed Date: 1213228 / 2013-02-04				
Site ID: 476407				
Program Number: 1213228				
COMMERCIAL SITE	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AR264	520
Spill Number/Closed Date: 0206043 / 2002-09-26				
Spill Number/Closed Date: 0408593 / 2005-02-13				
Site ID: 239569				
Site ID: 333366				
Program Number: 0206043				
Program Number: 0408593				
DEMELIA - TTF	95 WASHINGTON AVE	W 1/4 - 1/2 (0.275 mi.)	AT266	523
Spill Number/Closed Date: 1406916 / 2015-04-14				
Site ID: 500408				
Program Number: 1406916				
BLESSED SACRAMENT HI	24 SHEA PLACE	S 1/4 - 1/2 (0.278 mi.)	AQ267	525
Spill Number/Closed Date: 0400709 / 2004-07-06				
Site ID: 249284				
Program Number: 0400709				
BLESSED SACRAMENT HS	24 SHEA PLACE	S 1/4 - 1/2 (0.278 mi.)	AQ268	526
Spill Number/Closed Date: 1300960 / Not Reported				
Site ID: 481320				
Program Number: 1300960				
RESIDENCE	64 CHURCH ST	SSE 1/4 - 1/2 (0.281 mi.)	269	528
Spill Number/Closed Date: 0408510 / 2008-05-01				
Site ID: 333255				
Program Number: 0408510				
CANDREA/GALLETTA RES	35 CHARLES ST	WSW 1/4 - 1/2 (0.287 mi.)	AU270	529
Spill Number/Closed Date: 1202322 / 2012-09-13				
Site ID: 465083				
Program Number: 1202322				
SPILL NUMBER 0007965	45 CHARLES ST	WSW 1/4 - 1/2 (0.290 mi.)	AO271	530
Spill Number/Closed Date: 0007965 / 2000-10-26				
Site ID: 61314				
Program Number: 0007965				
BRAM REALTY	105 WASHINGTON AVE	W 1/4 - 1/2 (0.294 mi.)	AT274	560
Spill Number/Closed Date: 0902464 / 2010-02-01				
Site ID: 414506				
Program Number: 0902464				
MERLUCCI RESIDENCE	30 CHARLES STREET	WSW 1/4 - 1/2 (0.294 mi.)	AU275	561
Spill Number/Closed Date: 1103221 / 2011-11-14				
Site ID: 450778				

Program Number: 1103221

APT. BUILDING	55-59 LOCUST AVE.	ESE 1/4 - 1/2 (0.301 mi.)	AR279	571
Spill Number/Closed Date: 9200639 / 1992-06-26				
Site ID: 168647				
Program Number: 9200639				
BLESSED SACRAMENT CH	SHEA PLACE	SSE 1/4 - 1/2 (0.309 mi.)	AW280	572
Spill Number/Closed Date: 8704259 / 1987-11-20				
Site ID: 324974				
Program Number: 8704259				
FRANKA INC.	132-143 UNION AVE.	W 1/4 - 1/2 (0.311 mi.)	282	575
Spill Number/Closed Date: 9312205 / 1995-11-09				
Site ID: 176106				
Program Number: 9312205				
APARTMENT HOUSE	156-168 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AW283	577
Spill Number/Closed Date: 0312650 / 2004-04-22				
Site ID: 267104				
Program Number: 0312650				
FAILED TANK TEST	156 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AW284	578
Spill Number/Closed Date: 1308221 / Not Reported				
Site ID: 488939				
Program Number: 1308221				
APT. BUILDING	***47 MAPLE AV***	***S 1/4 - 1/2 (0.323 mi.)***	***288***	***602***
Spill Number/Closed Date: 9603128 / 1996-06-14				
Site ID: 178537				
Program Number: 9603128				
BUSINESS	88 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AY290	605
Spill Number/Closed Date: 9411669 / 2010-04-28				
Site ID: 172950				
Program Number: 9411669				
COMMERCIAL BUILDING	88-90 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AY291	607
Spill Number/Closed Date: 9411598 / 2010-04-28				
Site ID: 113133				
Program Number: 9411598				
NEW ROCHELLE RADIOLO	***150 LOCKWOOD AV***	***WNW 1/4 - 1/2 (0.366 mi.)***	***303***	***623***
Spill Number/Closed Date: 0209497 / 2005-03-18				
Site ID: 221207				
Program Number: 0209497				
MANONE PLACE	15 COLONIAL PLACE	WNW 1/4 - 1/2 (0.463 mi.)	357	743
Spill Number/Closed Date: 0513004 / 2006-05-08				
Site ID: 359413				
Program Number: 0513004				
HERNANDEZ - TTF	70 REMINGTON PLACE	NW 1/4 - 1/2 (0.490 mi.)	BQ372	774
Spill Number/Closed Date: 1411959 / 2015-06-16				
Site ID: 505764				
Program Number: 1411959				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
277 NORTH LLC	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I47	60
Spill Number/Closed Date: 0611648 / 2008-12-04				
Site ID: 376329				

Program Number: 0611648				
BUSINESS Spill Number/Closed Date: 0611580 / 2008-12-04 Site ID: 376243 Program Number: 0611580	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I49	63
EAST RIVER SAVINGS B Spill Number/Closed Date: 8912285 / 1991-01-16 Site ID: 271129 Program Number: 8912285	277 NORTH AVE.	NNE 0 - 1/8 (0.072 mi.)	I51	65
CIOTTI RESIDENCE Spill Number/Closed Date: 0407555 / 2004-10-07 Site ID: 332054 Program Number: 0407555	***60 GRAND STREET***	***NW 1/8 - 1/4 (0.142 mi.)***	***N138***	***219***
GUIDANCE CENTER INC Spill Number/Closed Date: 9613894 / 1997-10-03 Site ID: 77017 Program Number: 9613894	70 GRAND ST	NW 1/8 - 1/4 (0.149 mi.)	N146	238
RITZCOVAN - TTF Spill Number/Closed Date: 1506693 / Not Reported Site ID: 514123 Program Number: 1506693	22 BURLING LANE	NNW 1/8 - 1/4 (0.157 mi.)	158	267
THE MALL Spill Number/Closed Date: 9010648 / 1991-01-04 Site ID: 326514 Program Number: 9010648	MAIN STREET	E 1/8 - 1/4 (0.204 mi.)	AE187	336
CITY OF NEW ROCHELLE Spill Number/Closed Date: 0513733 / 2006-06-21 Site ID: 360263 Program Number: 0513733	45 HARRISON STREET	ENE 1/8 - 1/4 (0.232 mi.)	AM221	431
GALESI ENTERPRICES Spill Number/Closed Date: 8901038 / 1989-06-01 Site ID: 259815 Program Number: 8901038	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL237***	***461***
MONROE COLLEGE Spill Number/Closed Date: 0307536 / 2005-03-27 Site ID: 165556 Program Number: 0307536	5 FRANKLIN AVE	E 1/8 - 1/4 (0.237 mi.)	AE242	473
FIREHOUSE Spill Number/Closed Date: 9713840 / 1998-03-27 Site ID: 252028 Program Number: 9713840	HARRISON ST	ENE 1/4 - 1/2 (0.252 mi.)	AM255	503
BERGMAN REALTY SERVI Spill Number/Closed Date: 0505137 / 2007-11-07 Site ID: 350100 Program Number: 0505137	140 HUGUENOT STREET	ENE 1/4 - 1/2 (0.253 mi.)	AL256	505
DIMATTOE TTF Spill Number/Closed Date: 1301890 / 2013-08-08 Site ID: 482303 Program Number: 1301890	55 MAY STREET	NNW 1/4 - 1/2 (0.267 mi.)	AP259	510
CITY OF NEW ROCHELLE	1 HARRISON STREET	E 1/4 - 1/2 (0.268 mi.)	260	512

Spill Number/Closed Date: 0201696 / 2002-09-18
Site ID: 75380
Program Number: 0201696

SPILL NUMBER 0208792 — 386 NORTH AV — NNW 1/4 - 1/2 (0.275 mi.) — AS265 — 522
Spill Number/Closed Date: 0208792 / 2002-11-26
Site ID: 71430
Program Number: 0208792

GKIDS REALTY — 10/12 PINE COURT — SW 1/4 - 1/2 (0.291 mi.) — AV273 — 558
Spill Number/Closed Date: 0200337 / 2003-12-09
Site ID: 235436
Program Number: 0200337

KGM PROPERTY ASSOC. — 394 N. AVE. — NNW 1/4 - 1/2 (0.295 mi.) — AS276 — 562
Spill Number/Closed Date: 9202033 / 1993-01-27
Site ID: 69270
Program Number: 9202033

KGM REALTY CO. — 396 NORTH AVE. — NNW 1/4 - 1/2 (0.297 mi.) — AS277 — 563
Spill Number/Closed Date: 9201744 / 1993-01-27
Site ID: 89642
Program Number: 9201744

GETTY# 677 — ***381 NORTH AVE*** — ***NNW 1/4 - 1/2 (0.299 mi.)*** — ***AS278*** — ***565***
Spill Number/Closed Date: 0400912 / 2005-01-18
Site ID: 242546
Program Number: 0400912

PROFESSIONAL BUILDIN — ***421 HUGUENOT STREET*** — ***SSW 1/4 - 1/2 (0.311 mi.)*** — ***AX281*** — ***573***
Spill Number/Closed Date: 0606014 / 2007-01-29
Site ID: 369299
Program Number: 0606014

DIPASQUALE PROPERTY — 400 NORTH AVE — NNW 1/4 - 1/2 (0.318 mi.) — AS285 — 579
Spill Number/Closed Date: 1103122 / 2012-04-26
Site ID: 450672
Program Number: 1103122

POGLIA RES — 119 WASHINGTON AVE — W 1/4 - 1/2 (0.322 mi.) — 287 — 601
Spill Number/Closed Date: 0109023 / 2002-03-06
Site ID: 317087
Program Number: 0109023

SPILL 0106072 / PBS — 370 MAIN ST — E 1/4 - 1/2 (0.323 mi.) — 289 — 604
Spill Number/Closed Date: 0106072 / 2001-11-13
Site ID: 133647
Program Number: 0106072

ANON — ***108 VAN GUILDER AVE*** — ***WNW 1/4 - 1/2 (0.335 mi.)*** — ***292*** — ***608***
Spill Number/Closed Date: 0308565 / 2005-02-12
Site ID: 214235
Program Number: 0308565

BELIVE HOME — 20 PINE STREET — SW 1/4 - 1/2 (0.337 mi.) — AV293 — 611
Spill Number/Closed Date: 0500819 / 2005-05-22
Spill Number/Closed Date: 0413182 / 2005-05-22
Site ID: 343902
Site ID: 339043
Program Number: 0500819
Program Number: 0413182

CHURCH OF LATTER DAY — 111 NORTH AVE — SE 1/4 - 1/2 (0.341 mi.) — 295 — 614

Spill Number/Closed Date: 0403126 / 2004-09-21
Site ID: 266466
Program Number: 0403126

APARTMENT BUILDING	67-70 LOCUST AVE	SE 1/4 - 1/2 (0.345 mi.)	296	615
Spill Number/Closed Date: 1008207 / 2011-03-10				
Site ID: 441682				
Program Number: 1008207				
SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	SSW 1/4 - 1/2 (0.348 mi.)	AX297	616
Spill Number/Closed Date: 9908602 / 2000-09-14				
Site ID: 283271				
Program Number: 9908602				
BUSINESS COMPLEX	55 WEBSTER AVE	SW 1/4 - 1/2 (0.357 mi.)	298	617
Spill Number/Closed Date: 9912136 / 2000-05-11				
Site ID: 86196				
Program Number: 9912136				
APARTMENT BLDG	1 THE BOULEVARD	N 1/4 - 1/2 (0.359 mi.)	AZ299	618
Spill Number/Closed Date: 9809315 / 1999-10-14				
Site ID: 303319				
Program Number: 9809315				
GETTY S/S	ECHO & BOSTON POST R	ENE 1/4 - 1/2 (0.362 mi.)	BA300	620
Spill Number/Closed Date: 8602124 / 1989-11-28				
Site ID: 124816				
Program Number: 8602124				
PRIVATE DWELLING	19 ROCHELLE PLACE	NNW 1/4 - 1/2 (0.363 mi.)	AZ301	621
Spill Number/Closed Date: 0706958 / 2008-02-01				
Site ID: 387568				
Program Number: 0706958				
RESIDENCE	14 REVERE RD	ENE 1/4 - 1/2 (0.364 mi.)	BB302	622
Spill Number/Closed Date: 9611129 / 1996-12-11				
Site ID: 69656				
Program Number: 9611129				
NICK MAZZA RESIDENCE	20 DAVIS AVE	SSE 1/4 - 1/2 (0.368 mi.)	304	626
Spill Number/Closed Date: 0000532 / 2000-04-20				
Site ID: 211468				
Program Number: 0000532				
SHERIDEN PLAZA	1 SHERIDEN PLAZA	NE 1/4 - 1/2 (0.370 mi.)	BC305	627
Spill Number/Closed Date: 8909204 / 1990-03-07				
Site ID: 80178				
Program Number: 8909204				
JASON PARTNERS LTD	675 MAIN ST	SSW 1/4 - 1/2 (0.373 mi.)	BD306	628
Spill Number/Closed Date: 0211105 / 2003-03-26				
Site ID: 86967				
Program Number: 0211105				
ABANDONED GAS STATIO	197 WEBSTER AV	W 1/4 - 1/2 (0.377 mi.)	BE307	629
Spill Number/Closed Date: 9707099 / 2001-07-19				
Site ID: 231589				
Program Number: 9707099				
MUTUAL BISCUIT COMPA	***65 RIVER ST.***	***NE 1/4 - 1/2 (0.379 mi.)***	***BC308***	***630***
Spill Number/Closed Date: 8707334 / 1988-02-18				
Spill Number/Closed Date: 8708530 / 1988-02-18				
Site ID: 286036				

Site ID: 286037
Program Number: 8707334
Program Number: 8708530

GETTY 58114	***340 MAIN STREET***	***ENE 1/4 - 1/2 (0.380 mi.)***	***BA309***	***635***
Spill Number/Closed Date: 0913713 / 2010-04-29 Site ID: 426673 Program Number: 0913713				
SUNOCO / A-PLUS	***71 HUGUENOT***	***ENE 1/4 - 1/2 (0.382 mi.)***	***BB310***	***642***
Spill Number/Closed Date: 9514850 / 1996-07-26 Site ID: 255332 Program Number: 9514850				
6 WEBSTER	6 WEBSTER AVE	SSW 1/4 - 1/2 (0.384 mi.)	BD311	645
Spill Number/Closed Date: 0403816 / 2004-10-08 Site ID: 81655 Program Number: 0403816				
SPILL NUMBER 0314082	136 VANGUILDER AVE	W 1/4 - 1/2 (0.386 mi.)	BF312	646
Spill Number/Closed Date: 0314082 / 2004-06-08 Site ID: 80232 Program Number: 0314082				
STEWART RESIDENCE	***100 SICKLES AVE***	***NW 1/4 - 1/2 (0.388 mi.)***	***BG313***	***647***
Spill Number/Closed Date: 1200264 / 2012-08-13 Site ID: 462885 Program Number: 1200264				
CITGO STATION	***210 WEBSTER AVE***	***W 1/4 - 1/2 (0.396 mi.)***	***BE314***	***650***
Spill Number/Closed Date: 1311416 / Not Reported Site ID: 492314 Program Number: 1311416				
SPILL NUMBER 0302495	***85 NORTH AVE***	***SE 1/4 - 1/2 (0.397 mi.)***	***315***	***657***
Spill Number/Closed Date: 0507677 / 2009-10-09 Spill Number/Closed Date: 0302495 / 2003-08-12 Site ID: 353132 Site ID: 114935 Program Number: 0507677 Program Number: 0302495				
JEROME RESIDENCE	33 ECHO AVE	ENE 1/4 - 1/2 (0.397 mi.)	BA316	660
Spill Number/Closed Date: 0405389 / 2005-02-13 Site ID: 235222 Program Number: 0405389				
BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NW 1/4 - 1/2 (0.397 mi.)	BG317	662
Spill Number/Closed Date: 0304963 / 2004-02-02 Site ID: 219644 Program Number: 0304963				
MICELI HOME	194 CENTRE AVE	SSE 1/4 - 1/2 (0.397 mi.)	BH318	663
Spill Number/Closed Date: 0604103 / 2006-10-22 Site ID: 366997 Program Number: 0604103				
POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	ENE 1/4 - 1/2 (0.400 mi.)	BA319	664
Spill Number/Closed Date: 8709260 / 1988-02-11 Site ID: 283199 Program Number: 8709260				
POINVIL RESIDENCE	107 SICKLES AVE	NW 1/4 - 1/2 (0.400 mi.)	BG320	665

Spill Number/Closed Date: 1104844 / 2014-11-05
Site ID: 452458
Program Number: 1104844

AMOCO SERVICE STATIO	***690 MAIN ST***	***SSW 1/4 - 1/2 (0.403 mi.)***	***BD321***	***667***
Spill Number/Closed Date: 0209490 / 2002-12-16 Spill Number/Closed Date: 0212950 / 2003-04-01 Spill Number/Closed Date: 8604411 / 1987-01-14 Site ID: 274754 Site ID: 274755 Site ID: 274757 Program Number: 0209490 Program Number: 0212950 Program Number: 8604411				
RESIDENCE	10 LAFAYETTE ST	E 1/4 - 1/2 (0.404 mi.)	BI322	678
Spill Number/Closed Date: 0512638 / 2006-03-15 Site ID: 358990 Program Number: 0512638				
YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	W 1/4 - 1/2 (0.404 mi.)	BF323	679
Spill Number/Closed Date: 0507808 / 2005-12-18 Site ID: 353295 Program Number: 0507808				
COMMERCIAL-TTF	172 UNION AVE	W 1/4 - 1/2 (0.404 mi.)	BJ324	680
Spill Number/Closed Date: 1502358 / Not Reported Site ID: 508618 Program Number: 1502358				
TAHIR RESIDENCE	***112 SICKLES AVE***	***NW 1/4 - 1/2 (0.407 mi.)***	***BG325***	***681***
Spill Number/Closed Date: 0610140 / 2007-10-24 Site ID: 374522 Program Number: 0610140				
GAS STATION	44 ECHO AVE	ENE 1/4 - 1/2 (0.407 mi.)	BK326	684
Spill Number/Closed Date: 1309599 / 2014-02-13 Site ID: 490405 Program Number: 1309599				
DAVENPORT AUTO / WES	***44 ECHO AVE***	***ENE 1/4 - 1/2 (0.407 mi.)***	***BK327***	***685***
Spill Number/Closed Date: 9201557 / 2006-02-17 Spill Number/Closed Date: 9210810 / 1995-02-09 Spill Number/Closed Date: 1001469 / 2010-11-01 Site ID: 130487 Site ID: 130489 Site ID: 434525 Program Number: 9201557 Program Number: 9210810 Program Number: 1001469				
SPILL NUMBER 0012427	22 LAUREL PL	SSW 1/4 - 1/2 (0.409 mi.)	328	691
Spill Number/Closed Date: 0012427 / 2001-05-10 Site ID: 104510 Program Number: 0012427				
200 CENTRA CORP	200 CENTER AVE	SSE 1/4 - 1/2 (0.412 mi.)	BH329	692
Spill Number/Closed Date: 0604650 / 2007-12-12 Site ID: 367663 Program Number: 0604650				
FIRST ASSEMBLY OF GO	177 UNION AVE	W 1/4 - 1/2 (0.414 mi.)	BJ331	695

Spill Number/Closed Date: 1002183 / 2010-08-30
Site ID: 435290
Program Number: 1002183

48 1ST STREET	48 1ST STREET	WSW 1/4 - 1/2 (0.415 mi.)	332	696
Spill Number/Closed Date: 9911183 / 1999-12-22 Site ID: 116893 Program Number: 9911183				
GONCALVES RESIDENCE	1 LAFAYETTE STREET	E 1/4 - 1/2 (0.416 mi.)	BI333	697
Spill Number/Closed Date: 0609401 / 2007-01-10 Site ID: 373629 Program Number: 0609401				
GONCALVES RESIDENCE	1 LAFFAYETTE STREET	E 1/4 - 1/2 (0.416 mi.)	BI334	698
Spill Number/Closed Date: 9410991 / 1994-11-29 Site ID: 156301 Program Number: 9410991				
RESIDENCE	7 PRINCE ST	NW 1/4 - 1/2 (0.416 mi.)	BG335	699
Spill Number/Closed Date: 0506424 / 2005-10-29 Site ID: 351640 Program Number: 0506424				
SPILL NUMBER 0210119	68 FIRST STREET	WSW 1/4 - 1/2 (0.419 mi.)	BJ336	701
Spill Number/Closed Date: 0210119 / 2003-03-03 Site ID: 267616 Program Number: 0210119				
RENTAL HOUSE	119 SICKLES AVE.	NW 1/4 - 1/2 (0.421 mi.)	BG337	702
Spill Number/Closed Date: 9107320 / 1991-11-25 Site ID: 119461 Program Number: 9107320				
SPILL NUMBER 0104402	30 LINCOLN ST	NE 1/4 - 1/2 (0.426 mi.)	BL338	703
Spill Number/Closed Date: 0104402 / 2001-11-14 Site ID: 328750 Program Number: 0104402				
SPILL NUMBER 0210366	182 UNION AV	W 1/4 - 1/2 (0.427 mi.)	BJ339	704
Spill Number/Closed Date: 0210366 / 2003-03-03 Site ID: 282696 Program Number: 0210366				
PLASTIC WORKS	115 CEDAR ST	NNE 1/4 - 1/2 (0.430 mi.)	BM340	705
Spill Number/Closed Date: 9812998 / 1999-02-22 Site ID: 163894 Program Number: 9812998				
SPILL NUMBER 0202241	***208 CENTER AVE***	***SSE 1/4 - 1/2 (0.431 mi.)***	***BH341***	***706***
Spill Number/Closed Date: 9314003 / 1994-03-11 Spill Number/Closed Date: 9315255 / 1994-04-11 Site ID: 215702 Site ID: 215703 Program Number: 9314003 Program Number: 9315255				
SPILL NUMBER 0300463	***52 LINCOLN ST***	***NE 1/4 - 1/2 (0.432 mi.)***	***BL342***	***709***
Spill Number/Closed Date: 0300463 / 2003-04-14 Site ID: 202585 Program Number: 0300463				
I-95 EXIT 16	OPP. 111 CEDAR ST.	NNE 1/4 - 1/2 (0.436 mi.)	BM343	712

Spill Number/Closed Date: 9001240 / 1990-08-01 Site ID: 244221 Program Number: 9001240				
SPILL NUMBER 0009195 Spill Number/Closed Date: 0009195 / 2001-01-08 Site ID: 63217 Program Number: 0009195	17 POPLAR PL	SSE 1/4 - 1/2 (0.439 mi.)	BN344	713
RESIDENCE Spill Number/Closed Date: 0310014 / 2012-08-13 Site ID: 82997 Program Number: 0310014	6 POPLAR ROAD	SSE 1/4 - 1/2 (0.440 mi.)	BH345	714
LIPMAN RESIDENCE Spill Number/Closed Date: 0409061 / 2005-04-02 Site ID: 333699 Program Number: 0409061	54 LIBERTY AVE	S 1/4 - 1/2 (0.442 mi.)	346	715
WALTON RESIDENCE Spill Number/Closed Date: 0703375 / 2007-08-28 Site ID: 383296 Program Number: 0703375	129 SICKLES AVE	NW 1/4 - 1/2 (0.442 mi.)	348	731
FIUMFREDO RESIDENCE Spill Number/Closed Date: 1100096 / 2011-09-22 Site ID: 447470 Program Number: 1100096	12 BAYVIEW AVE	E 1/4 - 1/2 (0.444 mi.)	349	732
CONTAMINATRED SOIL Spill Number/Closed Date: 9702187 / 1999-06-10 Site ID: 102476 Program Number: 9702187	23 FIRST ST	WSW 1/4 - 1/2 (0.447 mi.)	350	734
RESIDENCE Spill Number/Closed Date: 9705244 / 1997-11-10 Site ID: 105369 Program Number: 9705244	38 BEECHWOOD AVE	SW 1/4 - 1/2 (0.448 mi.)	351	735
DEFENDER MARINE SUPP Spill Number/Closed Date: 9806235 / 2002-09-19 Site ID: 93459 Program Number: 9806235	309 MAIN ST	ENE 1/4 - 1/2 (0.448 mi.)	BO352	736
FUNICELOLO HOME Spill Number/Closed Date: 0509719 / 2006-11-19 Site ID: 355533 Program Number: 0509719	24 POPLAR PLACE	SSE 1/4 - 1/2 (0.450 mi.)	BN353	738
LABELLA RESIDENCE Spill Number/Closed Date: 0601959 / 2009-09-01 Site ID: 364328 Program Number: 0601959	219 CENTRE AVE	SSE 1/4 - 1/2 (0.454 mi.)	BN354	739
SPILL NUMBER 0210080 Spill Number/Closed Date: 0210080 / 2003-03-03 Site ID: 155360 Program Number: 0210080	196 UNION AV	W 1/4 - 1/2 (0.459 mi.)	355	740
RESIDENCE Spill Number/Closed Date: 0107187 / 2002-01-11 Site ID: 204562 Program Number: 0107187	98 LIBERTY AVE	S 1/4 - 1/2 (0.459 mi.)	BP356	741
TRINITY ARMS APARTME	25 TRINITY PLACE	SSE 1/4 - 1/2 (0.466 mi.)	358	744

Spill Number/Closed Date: 0811859 / 2009-04-22
Spill Number/Closed Date: 8905211 / 1992-07-30
Site ID: 409448
Site ID: 283512
Program Number: 0811859
Program Number: 8905211

SPILL NUMBER 9814027	48 REMINGTON PL	NW 1/4 - 1/2 (0.471 mi.)	BQ359	746
Spill Number/Closed Date: 9814027 / 1999-02-19				
Site ID: 80830				
Program Number: 9814027				
RITACCO HOME	24 JACKSON STREET	ENE 1/4 - 1/2 (0.472 mi.)	360	747
Spill Number/Closed Date: 0600187 / 2006-07-28				
Site ID: 362141				
Program Number: 0600187				
COMMERICAL BUILIDING	719 MAIN ST	SSW 1/4 - 1/2 (0.474 mi.)	361	748
Spill Number/Closed Date: 0404182 / 2004-10-28				
Site ID: 301693				
Program Number: 0404182				
SPILL NUMBER 9803423	106 LIBERTY AV	S 1/4 - 1/2 (0.482 mi.)	BP363	762
Spill Number/Closed Date: 9803423 / 1998-08-18				
Site ID: 140786				
Program Number: 9803423				
TTF AT RESIDENCE	68 JACKSON ST	NE 1/4 - 1/2 (0.484 mi.)	364	763
Spill Number/Closed Date: 0707955 / 2008-03-26				
Site ID: 388761				
Program Number: 0707955				
COLLEGE OF NEW ROCHE	103 LIBERTY AVE	S 1/4 - 1/2 (0.486 mi.)	BP365	764
Spill Number/Closed Date: 9809357 / 2005-04-17				
Site ID: 118985				
Program Number: 9809357				
CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	SE 1/4 - 1/2 (0.486 mi.)	366	765
Spill Number/Closed Date: 0204230 / 2010-07-13				
Site ID: 161898				
Program Number: 0204230				
NELSTAD MATERIAL COR	***40 HUNTINGTON PL***	***ENE 1/4 - 1/2 (0.487 mi.)***	***367***	***766***
Spill Number/Closed Date: 0208898 / 2004-05-03				
Site ID: 200280				
Program Number: 0208898				
BLANCO RESIDENCE	30 LINDEN PLACE	S 1/4 - 1/2 (0.488 mi.)	BP368	770
Spill Number/Closed Date: 9802704 / 1998-07-30				
Site ID: 227988				
Program Number: 9802704				
7-UP BOTTLING CO	PALMER AVE & CEDAR S	NNE 1/4 - 1/2 (0.490 mi.)	370	772
Spill Number/Closed Date: 9302874 / 1999-08-02				
Site ID: 60684				
Program Number: 9302874				
NORTH EVARTS	44 NORTH EVARTS AVE	SE 1/4 - 1/2 (0.490 mi.)	371	773
Spill Number/Closed Date: 9913333 / 2005-02-26				
Site ID: 74554				
Program Number: 9913333				

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 03/29/2016 has revealed that there are 44 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AVALON ON THE SOUND Status: 5. Closed - removed Id/Status:: 3-800626 Site Status: Unregulated: <1101 gal. PBS	HUGUENOT STREET AND	S 0 - 1/8 (0.022 mi.)	B19	27
NEW ROCHELLE IRISH B Status: 5. Closed - removed Id/Status:: 3-600097 Site Status: Unregulated	38 DIVISION STREET	S 0 - 1/8 (0.039 mi.)	B25	33
TRINITY-ST. PAUL'S E Status: 4. Closed - in place Id/Status:: 3-801006 Site Status: Unregulated: <1101 gal. PBS	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	B27	35
UNITED STATES POST O Status: 0. Administratively closed Status: 1. In-Service Id/Status:: 3-448699 Site Status: Unregulated: <1101 gal. PBS	255 NORTH AVENUE	ENE 0 - 1/8 (0.049 mi.)	D35	49
CERUSSI AND VERE Status: 0. Administratively closed Id/Status:: 3-078360 Site Status: Administratively Closed	306 HUGUENOT ST	SSW 0 - 1/8 (0.051 mi.)	B37	52
KAUFMAN HUGUENOT COM Status: 4. Closed - in place Id/Status:: 3-183776 Site Status: Active	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D39***	***54***
LAWTON STREET REALTY Status: 1. In-Service Id/Status:: 3-801435 Site Status: Active	41-43 LAWTON STREET	ESE 0 - 1/8 (0.056 mi.)	E41	56
ANDERSON DEVELOPMENT Status: 5. Closed - removed Id/Status:: 3-185515 Site Status: Unregulated	5 ANDERSON STREET	E 0 - 1/8 (0.081 mi.)	J56	72
SEASONWEIN MANAGEMEN Status: 1. In-Service Id/Status:: 3-169773 Site Status: Active	54 CENTRE AVENUE	SSW 0 - 1/8 (0.092 mi.)	K67	88
M.J. HACKER & SONS I Status: 8. Unregistered Status: 5. Closed - removed Status: 3. Closed - Prior to 04/1991	64 CENTRE AVE	S 0 - 1/8 (0.102 mi.)	K76	114

Id/Status:: 3-137979 Site Status: Unregulated				
RPM REALTY INC Status: 5. Closed - removed Id/Status:: 3-166189 Site Status: Active	9-15 DIVISION STREET	SSE 0 - 1/8 (0.103 mi.)	H78	118
MACYS NEW ROCHELLE Status: 4. Closed - in place Id/Status:: 3-167037 Site Status: Unregulated: <1101 gal. PBS	THE MALL	E 0 - 1/8 (0.117 mi.)	J96	160
LILLIAN VERNON CORPO Status: 5. Closed - removed Id/Status:: 3-600279 Site Status: Unregulated: <1101 gal. PBS	543-549 MAIN STREET	S 0 - 1/8 (0.123 mi.)	Q103	169
543 MAIN STREET Status: 5. Closed - removed Id/Status:: 3-801106 Site Status: Unregulated: <1101 gal. PBS	543 MAIN STREET	S 0 - 1/8 (0.123 mi.)	Q104	170
VERIZON NEW YORK INC Status: 5. Closed - removed Status: 1. In-Service Id/Status:: 3-184586 Site Status: Active	***342 HUGUENOT STREET***	***SSW 0 - 1/8 (0.123 mi.)***	***K107***	***175***
75 CENTRE AVENUE LLC Status: 5. Closed - removed Id/Status:: 3-800240 Site Status: Active	***75 CENTRE AVENUE***	***SSW 1/8 - 1/4 (0.125 mi.)***	***K112***	***183***
542 MAIN STREET LLC Status: 1. In-Service Id/Status:: 3-800617 Site Status: Active	542 MAIN STREET	S 1/8 - 1/4 (0.138 mi.)	Q125	200
NEW ROCHELLE PUBLIC Status: 1. In-Service Id/Status:: 3-601216 Site Status: Active	ONE LIBRARY PLAZA	SE 1/8 - 1/4 (0.138 mi.)	S126	201
BLOOMINGDALE PARKING Status: 4. Closed - in place Id/Status:: 3-600330 Site Status: Unregulated: <1101 gal. PBS	554 MAIN ST	S 1/8 - 1/4 (0.139 mi.)	T133	212
BARON MANAGEMENT Status: 0. Administratively closed Id/Status:: 3-167843 Site Status: Administratively Closed	200 NORTH AVENUE	ESE 1/8 - 1/4 (0.139 mi.)	R134	213
J P MORGAN CHASE BAN Status: 4. Closed - in place Id/Status:: 3-164372 Site Status: Active	***491 MAIN STREET***	***SE 1/8 - 1/4 (0.142 mi.)***	***S136***	***215***
CENTRE MAIN EQUITIES Status: 5. Closed - removed Id/Status:: 3-800238 Site Status: Active	***573-579 MAIN STREET***	***S 1/8 - 1/4 (0.150 mi.)***	***T147***	***239***
INDUSTRIAL OVERALL S	10 BARTELLS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O150	243

Status: 0. Administratively closed Status: 5. Closed - removed Id/Status:: 3-025453 Site Status: Unregulated				
RETTNER MANAGEMENT C Status: 0. Administratively closed Status: 1. In-Service Id/Status:: 3-255033 Site Status: Active	481 MAIN ST	SE 1/8 - 1/4 (0.155 mi.)	R154	261
STORAGE USA Status: 5. Closed - removed Id/Status:: 3-801137 Site Status: Administratively Closed	363 HUGUENOT STREET	SSW 1/8 - 1/4 (0.165 mi.)	V161	272
SAINT GABRIEL HIGH S Status: 5. Closed - removed Status: 1. In-Service Id/Status:: 3-058122 Site Status: Active	50 WASHINGTON AVENUE	WNW 1/8 - 1/4 (0.187 mi.)	Y171	292
175 MEMORIAL HWY. RE Status: 4. Closed - in place Id/Status:: 3-800711 Site Status: Unregulated: <1101 gal. PBS	175 MEMORIAL HWY.	NW 1/8 - 1/4 (0.204 mi.)	AF188	338
MONTEFIORE - NEW ROC Status: 1. In-Service Status: 5. Closed - removed Status: 4. Closed - in place Id/Status:: 3-123269 Site Status: Active	***16 GUION PLACE***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ199***	***365***
30 CLINTON PLACE OWN Status: 5. Closed - removed Id/Status:: 3-078727 Site Status: Active	***30 CLINTON PLACE***	***SE 1/8 - 1/4 (0.229 mi.)***	***AH217***	***425***
LJNJ ASSOCIATES Status: 0. Administratively closed Status: 5. Closed - removed Id/Status:: 3-601056 Site Status: Unregulated: <1101 gal. PBS	100-102 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AC226	439
DOMENICO PROCOPIO Status: 5. Closed - removed Id/Status:: 3-800233 Site Status: Unregulated: <1101 gal. PBS	***618 MAIN STREET***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN246***	***478***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NORTH BROOK REALTY A Status: 1. In-Service Id/Status:: 3-600117 Site Status: Active	270 NORTH AVENUE - U	NNE 0 - 1/8 (0.062 mi.)	I46	59
277 NORTH LLC Status: 1. In-Service Status: 5. Closed - removed Id/Status:: 3-502049	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I50	64

Site Status: Active				
DELUXE TAXI Status: 5. Closed - removed Id/Status:: 3-600004 Site Status: Unregulated: <1101 gal. PBS	10 STATION PLAZA	N 0 - 1/8 (0.100 mi.)	L74	109
DEPOT PLACE LLC Status: 4. Closed - in place Id/Status:: 3-801085 Site Status: Unregulated: <1101 gal. PBS	1 DEPOT PLACE	NW 0 - 1/8 (0.106 mi.)	N82	131
SPOKEN ARTS BUILDING Status: 5. Closed - removed Id/Status:: 3-600705 Site Status: Unregulated: <1101 gal. PBS	310 NORTH AVENUE	N 0 - 1/8 (0.114 mi.)	L95	159
NORTH GARDEN ASSOCIA Status: 1. In-Service Id/Status:: 3-496928 Site Status: Active	309-311 NORTH AVENUE	N 0 - 1/8 (0.117 mi.)	L97	161
4 STORY APARTMENT BU Status: 5. Closed - removed Id/Status:: 3-600732 Site Status: Unregulated: <1101 gal. PBS	320 NORTH AVENUE	N 1/8 - 1/4 (0.128 mi.)	L114	185
DRIVE IT YOURSELF Status: 5. Closed - removed Id/Status:: 3-494380 Site Status: Unregulated	20 GARDEN STREET	N 1/8 - 1/4 (0.175 mi.)	X162	272
NEW ROCHELLE MALL Status: 4. Closed - in place Id/Status:: 3-600042 Site Status: Unregulated: <1101 gal. PBS	425 MAIN STREET	E 1/8 - 1/4 (0.212 mi.)	AE198	364
NEW ROCHELLE FIRE ST Status: 1. In-Service Status: 5. Closed - removed Id/Status:: 3-600407 Site Status: Active	***45 HARRISON STREET***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AM220***	***429***
368 NORTH AVE MGMT C Status: 5. Closed - removed Id/Status:: 3-600272 Site Status: Unregulated: <1101 gal. PBS	368 NORTH AVENUE	NNW 1/8 - 1/4 (0.234 mi.)	AI234	454
CASANOVA BROS. REALT Status: 4. Closed - in place Id/Status:: 3-800088 Site Status: Unregulated: <1101 gal. PBS	370 NORTH AVENUE	NNW 1/8 - 1/4 (0.238 mi.)	AI243	474
VACANT Status: 5. Closed - removed Status: 4. Closed - in place Id/Status:: 3-801616 Site Status: Unregulated	***399 HUGUENOT STREET***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AN249***	***482***

EXECUTIVE SUMMARY

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 03/29/2016 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.153 mi.)***	***O152***	***257***
Facility Status: Unregulated/Closed CBS Number: 3-000235				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 03/29/2016 has revealed that there are 21 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
306 HUGUENOT STREET Status: 1. In-Service PBS Number: 3-800236	306 HUGUENOT STREET	SSW 0 - 1/8 (0.051 mi.)	B38	53
KAUFMAN HUGUENOT COM Status: 1. In-Service PBS Number: 3-183776	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D39***	***54***
ANDERSON DEVELOPMENT Status: 6. Closed - Work Permit Open PBS Number: 3-185515	5 ANDERSON STREET	E 0 - 1/8 (0.081 mi.)	J55	71
MKM EQUITY, LLC Status: 5. Closed - removed PBS Number: 3-600105	230 NORTH AVENUE	E 0 - 1/8 (0.085 mi.)	E61	79
RPM REALTY INC Status: 1. In-Service PBS Number: 3-166189	9-15 DIVISION STREET	SSE 0 - 1/8 (0.103 mi.)	H77	117
VERIZON NEW YORK INC Status: 1. In-Service PBS Number: 3-184586	***342 HUGUENOT STREET***	***SSW 0 - 1/8 (0.123 mi.)***	***K107***	***175***
75 CENTRE AVENUE LLC Status: 1. In-Service PBS Number: 3-800240	***75 CENTRE AVENUE***	***SSW 1/8 - 1/4 (0.125 mi.)***	***K112***	***183***
HUGUENOT HOLDINGS, L Status: 1. In-Service PBS Number: 3-502626	347 HUGUENOT STREET	SSW 1/8 - 1/4 (0.133 mi.)	K122	197
J P MORGAN CHASE BAN Status: 1. In-Service PBS Number: 3-164372	***491 MAIN STREET***	***SE 1/8 - 1/4 (0.142 mi.)***	***S136***	***215***
NEW ROCHELLE SUPERMA Status: 5. Closed - removed PBS Number: 3-166995	538 MAIN STREET	SSE 1/8 - 1/4 (0.146 mi.)	Q140	225
CENTRE MAIN EQUITIES	***573-579 MAIN STREET***	***S 1/8 - 1/4 (0.150 mi.)***	***T147***	***239***

Status: 1. In-Service PBS Number: 3-800238				
MONTEFIORE - NEW ROC Status: 1. In-Service Status: 5. Closed - removed PBS Number: 3-123269	***16 GUION PLACE***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ199***	***365***
SINNOTT MANAGEMENT C Status: 1. In-Service PBS Number: 3-078646	35 CLINTON PLACE	SE 1/8 - 1/4 (0.227 mi.)	AH215	421
30 CLINTON PLACE OWN Status: 4. Closed - in place Status: 1. In-Service PBS Number: 3-078727	***30 CLINTON PLACE***	***SE 1/8 - 1/4 (0.229 mi.)***	***AH217***	***425***
DOMENICO PROCOPIO Status: 0. Administratively closed PBS Number: 3-800233	***618 MAIN STREET***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN246***	***478***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAYCO, LLC Status: 1. In-Service PBS Number: 3-175447	18-20 MAY ST	NNW 1/8 - 1/4 (0.211 mi.)	AI194	346
MONROE COLLEGE Status: 0. Administratively closed Status: 5. Closed - removed Status: 1. In-Service PBS Number: 3-800251	420 MAIN STREET	E 1/8 - 1/4 (0.223 mi.)	AE208	401
NEW ROCHELLE FIRE ST Status: 1. In-Service PBS Number: 3-600407	***45 HARRISON STREET***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AM220***	***429***
GHP 145 HUGUENOT DEL Status: 1. In-Service PBS Number: 3-497436	145 HUGUENOT STREET	NE 1/8 - 1/4 (0.236 mi.)	AL235	455
VACANT Status: 5. Closed - removed PBS Number: 3-801616	***399 HUGUENOT STREET***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AN249***	***482***
MAY PARTNERS, LLC Status: 5. Closed - removed Status: 1. In-Service PBS Number: 3-600544	35-45 MAY STREET	NNW 1/8 - 1/4 (0.247 mi.)	AP254	502

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	10 BARTELS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O153	261

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 3 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FLAMINGO CLEANERS Site Code: 335220	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***
OFF-SITE FLAMINGO CL Site Code: 414661	149 NORTH AVENUE	SE 1/8 - 1/4 (0.246 mi.)	AH253	501

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLER'S DRY CLE Site Code: 357446	358-364 NORTH AVENUE	NNW 1/8 - 1/4 (0.208 mi.)	AI193	344

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/17/2016 has revealed that there are 22 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Spill Number/Closed Date: 0810056 / 2010-05-04 spillno: 0810056 Site ID: 407567	129 DIVISON ST	SSW 0 - 1/8 (0.006 mi.)	B5	10
MH1204 Spill Number/Closed Date: 9912755 / 2000-02-14 spillno: 9912755 Site ID: 262084	HUGUENOT AVE/LAWTON	ESE 0 - 1/8 (0.019 mi.)	A17	24
MEMORIAL HIGHWAY AND Spill Number/Closed Date: 9912617 / 2000-04-04 spillno: 9912617 Site ID: 254637	HUGUNOT ST	S 0 - 1/8 (0.022 mi.)	B18	25
ROAD	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B21	28

Spill Number/Closed Date: 0606187 / 2006-09-03 spillno: 0606187 Site ID: 369495				
HUGUENOT AND NORTH A Spill Number/Closed Date: 0310260 / 2005-03-05 spillno: 0310260 Site ID: 313618	HUGUENOT AND NORTH A	NE 0 - 1/8 (0.046 mi.)	D28	36
PAVEMENT Spill Number/Closed Date: 1203965 / 2012-07-23 spillno: 1203965 Site ID: 466814	41 LAWTON STREET	ESE 0 - 1/8 (0.056 mi.)	E40	55
CABLE Spill Number/Closed Date: 0804961 / 2008-07-30 spillno: 0804961 Site ID: 401965	29 DIVISION STREET	S 0 - 1/8 (0.057 mi.)	H45	58
ARIEL CABLE Spill Number/Closed Date: 0804960 / 2008-08-16 spillno: 0804960 Site ID: 401964	19 DIVISION STREET/W	S 0 - 1/8 (0.080 mi.)	H53	67
CONCRETE FLOORING WI Spill Number/Closed Date: 1400277 / Not Reported spillno: 1400277 Site ID: 493512	230 NORTH AVENUE	E 0 - 1/8 (0.085 mi.)	E62	79
CEMENT COURT YARD Spill Number/Closed Date: 9908117 / 1999-10-04 Spill Number/Closed Date: 9804849 / 2002-07-15 spillno: 9804849 spillno: 9908117 Site ID: 114515 Site ID: 114516	54 CENTER AVE	SSW 0 - 1/8 (0.092 mi.)	K66	86
DEVELOPMENT SITE Spill Number/Closed Date: 0510932 / 2005-12-19 Spill Number/Closed Date: 0504821 / 2006-03-08 spillno: 0504821 spillno: 0510932 Site ID: 349739 Site ID: 356986	***175 HUGUENOT STREET***	***NE 0 - 1/8 (0.102 mi.)***	***I75***	***111***
APPAREL PLUS Spill Number/Closed Date: 1309988 / 2014-01-14 spillno: 1309988 Site ID: 490810	27 CENTRE AVE	SW 0 - 1/8 (0.118 mi.)	O98	161
SIDNEY FURNITURE Spill Number/Closed Date: 1509029 / 2015-12-04 spillno: 1509029 Site ID: 517634	535 MAIN ST	SSE 0 - 1/8 (0.120 mi.)	Q99	163
SPILL NUMBER 9900400 Spill Number/Closed Date: 9900400 / 1999-07-09 Spill Number/Closed Date: 9415294 / 1995-03-03 spillno: 9415294 spillno: 9900400 Site ID: 251083	535 MAIN ST	SSE 0 - 1/8 (0.120 mi.)	Q100	164

Site ID: 81102

LILLIAN VERNON CORP.	***543 MAIN STREET***	***S 0 - 1/8 (0.123 mi.)***	***Q102***	***167***
Spill Number/Closed Date: 9212475 / 2004-05-12 spillno: 9212475 Site ID: 125220				
VERIZON	342 HUGUENOT ST	SSW 0 - 1/8 (0.123 mi.)	K106	174
Spill Number/Closed Date: 0413326 / 2005-09-11 spillno: 0413326 Site ID: 342403				

Lower Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING	8-10 RAILROAD PLACE	0 - 1/8 (0.000 mi.)	A2	8
Spill Number/Closed Date: 9009493 / 1991-05-07 spillno: 9009493 Site ID: 220275				
METRO NORTH TRACKS	EAST OF NEW ROCHELLE	WSW 0 - 1/8 (0.010 mi.)	C15	22
Spill Number/Closed Date: 0308130 / 2004-07-16 spillno: 0308130 Site ID: 279322				
METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	WSW 0 - 1/8 (0.010 mi.)	C16	23
Spill Number/Closed Date: 8903573 / 1989-07-19 spillno: 8903573 Site ID: 104107				
SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	WSW 0 - 1/8 (0.049 mi.)	F34	48
Spill Number/Closed Date: 9803949 / 1998-06-29 spillno: 9803949 Site ID: 166821				
P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	SW 0 - 1/8 (0.106 mi.)	M80	128
Spill Number/Closed Date: 0308809 / 2003-11-26 spillno: 0308809 Site ID: 329742				
I-95	I-95EB MP54	SW 0 - 1/8 (0.106 mi.)	M81	130
Spill Number/Closed Date: 8700158 / 1987-04-07 spillno: 8700158 Site ID: 121121				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/09/2015 has revealed that there are 59 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE:	***HUGENOT AVE & DIVISI***	***SSW 0 - 1/8 (0.009 mi.)***	***B8***	***13***
CON EDISON TRANSFORM	DIVISION ST & HUGUEN	SSW 0 - 1/8 (0.009 mi.)	B13	20

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1049890	DIVISION ST OVER MET	SSW 0 - 1/8 (0.010 mi.)	B14	21
CON EDISON MANHOLE:	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D29***	***37***
CON EDISON TRANSFORM	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D30***	***39***
CON EDISON MANHOLE:	HUGENUOT ST & NORTH	NE 0 - 1/8 (0.046 mi.)	D31	41
ACCESSOCRAFT PRODUCT	***48 LAWTON ST***	***SE 0 - 1/8 (0.046 mi.)***	***E33***	***43***
US POSTAL SERVICE	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D36***	***50***
FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	E 0 - 1/8 (0.056 mi.)	D42	57
CON EDISON TRANSFORM	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.081 mi.)***	***E57***	***73***
CON EDISON	HUGUENOT ST & CENTRE	SSW 0 - 1/8 (0.099 mi.)	K69	89
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O88***	***146***
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O89***	***148***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
NEW YORK TELEPHONE C	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.123 mi.)***	***K105***	***170***
CON EDISON TRANSFORM	***CHURCH ST & MAIN ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q118***	***190***
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q119***	***192***
CON EDISON MANHOLE:	***MAIN ST & CHURCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q120***	***194***
MR CHIMNEY CLEAN	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.144 mi.)***	***O139***	***222***
ADREAN PRINTING CO	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S142***	***226***
PRO AUTO PARTS	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***O143***	***230***
FIRST METRO SERVICES	***357 HUGONOT ST***	***SSW 1/8 - 1/4 (0.149 mi.)***	***V145***	***236***
INDUSTRIAL OVERALL S	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.153 mi.)***	***O151***	***244***
CON EDISON TRANSFORM	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***T155***	***262***
ROTH CLEANERS	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
CON EDISON TRANSFORM	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD182***	***320***
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AD185***	***333***
CON EDISON SERVICE B	***CENTRE AVE & LEROY***	***S 1/8 - 1/4 (0.205 mi.)***	***AG189***	***338***
CON EDISON SERVICE B	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG190***	***339***
CON EDISON SERVICE B	***174 NORTH AVE***	***SE 1/8 - 1/4 (0.207 mi.)***	***AH192***	***342***
CON EDISON	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD210***	***403***
CON EDISON MANHOLE:	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD211***	***406***
PREFERRED CLEANERS	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AC214***	***411***
CON EDISON MANHOLE:	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH223***	***434***
CON EDISON SERVICE B	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH224***	***436***
COLONIAL CLEANERS CO	149 NORTH AVE	SE 1/8 - 1/4 (0.246 mi.)	AH250	485

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1091390	DIVISION ST OVER I 9	WSW 0 - 1/8 (0.036 mi.)	C24	32
CON EDISON MANHOLE:	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***I48***	***61***
CON EDISON MANHOLE:	313 NORTH AVE FRONT	N 0 - 1/8 (0.125 mi.)	L110	181
CON EDISON MANHOLE:	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***L127***	***201***
CON EDISON MANHOLE 4	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L128***	***203***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L129***	***205***
CON EDISON SERVICE B	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L130***	***207***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L131***	***208***
NYS THRUWAY AUTH	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.148 mi.)***	***U144***	***232***
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.157 mi.)***	***U159***	***268***
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***AB169***	***289***
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***X176***	***298***
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.193 mi.)***	***U178***	***304***
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB179***	***306***
RUSH MFG CORP	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AB183***	***322***
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK206***	***396***
CON EDISON MANHOLE 1	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AL213***	***409***
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AB216***	***422***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TRANSFORM	***LOCKWOOD AVE & NORTH***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI227***	***441***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***
LONGINES WITTNAUER W	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL236***	***455***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 10/16/2015 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREEN HEAVEN/CENTRE Facility Id: 3-5510-00298	62 CENTRE AVE.	SSW 0 - 1/8 (0.109 mi.)	K84	132
SPEEDY CLEANERS Facility Id: 3-5510-00344	***217 NORTH AVENUE***	***ESE 0 - 1/8 (0.113 mi.)***	***J94***	***158***
HANGERS CLEANERS Facility Id: 3-5510-00358	562-564 MAIN STREET	S 1/8 - 1/4 (0.147 mi.)	T141	225
ROTH CLEANERS Facility Id: 3-5510-00292	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
FLAMINGO/TYK CLEANER Facility Id: 3-5510-00335	149 NORTH AV.	SE 1/8 - 1/4 (0.246 mi.)	AH251	487

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANER	63 MEMORIAL HWY	WSW 0 - 1/8 (0.001 mi.)	A4	9
STATION CLEANERS Facility Id: ---	1 DEPOT PLAZA #1	NW 0 - 1/8 (0.106 mi.)	N83	131
SCHMUKLER'S CLEANERS Facility Id: 3-5510-00327	360 NORTH AVE.	NNW 1/8 - 1/4 (0.212 mi.)	AI197	364

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there are 92 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004151221	MEMORIAL HIGHWAY & H	S 0 - 1/8 (0.007 mi.)	A6	11
CON EDISON EPA ID: NYP004677548	HUGENOT & DIVISION S	SSW 0 - 1/8 (0.009 mi.)	B7	12
CON EDISON MANHOLE: EPA ID: NYP004317285	***HUGENOT AVE & DIVISI***	***SSW 0 - 1/8 (0.009 mi.)***	***B8***	***13***
CON ED EPA ID: NYP004353199	DIVISION ST & HUGENO	SSW 0 - 1/8 (0.009 mi.)	B9	15
CON EDISON	DIVISION & HUGUENOT	SSW 0 - 1/8 (0.009 mi.)	B11	18

EPA ID: NYP004676847				
CON EDISON EPA ID: NYP004677894	HUGENOT ST & DIVISIO	SSW 0 - 1/8 (0.009 mi.)	B12	19
CON EDISON MANHOLE: EPA ID: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D29***	***37***
CON EDISON TRANSFORM EPA ID: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D30***	***39***
ACCESSOCRAFT PRODUCT EPA ID: NYR000014753	***48 LAWTON ST***	***SE 0 - 1/8 (0.046 mi.)***	***E33***	***43***
US POSTAL SERVICE EPA ID: NYR000106369	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D36***	***50***
CON EDISON TRANSFORM EPA ID: NYP004367611	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.081 mi.)***	***E57***	***73***
CON EDISON EPA ID: NYP004683272	NORTH AVE & ANDERSON	E 0 - 1/8 (0.081 mi.)	E58	75
CON EDISON EPA ID: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.081 mi.)	E59	76
CON EDISON EPA ID: NYP004709622	ANDERSON ST & NORTH	E 0 - 1/8 (0.081 mi.)	E60	78
CON EDISON EPA ID: NYP004676839	CENTER & HUGUENOT	SSW 0 - 1/8 (0.099 mi.)	K70	89
CON EDISON EPA ID: NYP004332961	CENTRE AVE & HUGUENO	SSW 0 - 1/8 (0.099 mi.)	K71	90
CON EDISON EPA ID: NYP004677530	HUGENOT & CENTRE ST	SSW 0 - 1/8 (0.099 mi.)	K72	91
CVS PHARMACY #8447 EPA ID: NYR000194654	***222 NORTH AVE***	***ESE 0 - 1/8 (0.099 mi.)***	***J73***	***93***
ERIC S TURNER & CO I EPA ID: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
SIMONETTI CLEANERS EPA ID: NYD982531634	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***K86***	***133***
CON EDISON TRANSFORM EPA ID: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O88***	***146***
CON EDISON TRANSFORM EPA ID: NYP004365318	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O89***	***148***
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
CON EDISON EPA ID: NYP004837407	HUGENOT ST & LECOUNT	NE 0 - 1/8 (0.112 mi.)	P92	156
NEW YORK TELEPHONE C EPA ID: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.123 mi.)***	***K105***	***170***
CON EDISON EPA ID: NYP004872319	S DIVSION ST & MAIN	SSE 0 - 1/8 (0.124 mi.)	Q108	178
CONSOLIDATED EDISON	DIVISION & MAIN	SSE 0 - 1/8 (0.124 mi.)	Q109	179

EPA ID: NYP004123873				
CON EDISON EPA ID: NYP004772265	208 NORTH AVE	ESE 0 - 1/8 (0.125 mi.)	R111	182
MACYS EPA ID: NYP000890137	33 LE COUNT PLACE	E 1/8 - 1/4 (0.127 mi.)	J113	185
CON EDISON TRANSFORM EPA ID: NYP004478517	***CHURCH ST & MAIN ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q118***	***190***
CON EDISON TRANSFORM EPA ID: NYP004364576	***MAIN ST & CHRUCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q119***	***192***
CON EDISON MANHOLE: EPA ID: NYP004478624	***MAIN ST & CHURCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q120***	***194***
CON EDISON EPA ID: NYP004680070	MAIN ST & CHURCH ST	SSE 1/8 - 1/4 (0.131 mi.)	Q121	196
MR CHIMNEY CLEAN EPA ID: NYD987011855	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.144 mi.)***	***O139***	***222***
ADREAN PRINTING CO EPA ID: NY0000233981	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S142***	***226***
PRO AUTO PARTS EPA ID: NYR000016535	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***O143***	***230***
INDUSTRIAL OVERALL S EPA ID: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.153 mi.)***	***O151***	***244***
CON EDISON TRANSFORM EPA ID: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***T155***	***262***
CON EDISON EPA ID: NYP004658019	MAIN ST & CENTRE ST	S 1/8 - 1/4 (0.155 mi.)	T156	264
CON ED EPA ID: NYP004760815	CENTRE AVE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	T157	265
ROTH CLEANERS EPA ID: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
CONSOLIDATED EDISON EPA ID: NYP004124210	DIVISION ST & LEROY	SSE 1/8 - 1/4 (0.181 mi.)	Z165	286
CON ED-V37 EPA ID: NYP004027967	LECOUNT PL & MAIN ST	ESE 1/8 - 1/4 (0.182 mi.)	AA166	287
CON ED-V14 EPA ID: NYP004028122	LECOUNT PL & MAIN ST	ESE 1/8 - 1/4 (0.182 mi.)	AA167	287
CON EDISON EPA ID: NYP004677621	HUGENOT AVE & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	V173	295
CON EDISON EPA ID: NYP004687802	HUGUENOT ST & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	V174	296
CON EDISON EPA ID: NYP004677837	HUGENOT ST & COLUMBU	SSW 1/8 - 1/4 (0.188 mi.)	V175	297
CON EDISON TRANSFORM EPA ID: NYP004464459	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD182***	***320***
NYNEX EPA ID: NYP000932509	UNION AVENUE AND WAR	W 1/8 - 1/4 (0.201 mi.)	W184	333
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AD185***	***333***

EPA ID: NYP004357059				
CON EDISON SERVICE B EPA ID: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG190***	***339***
CON EDISON EPA ID: NYP004517694	CENTRE AVE & LEROY	S 1/8 - 1/4 (0.205 mi.)	AG191	341
CON EDISON SERVICE B EPA ID: NYP004442943	***174 NORTH AVE***	***SE 1/8 - 1/4 (0.207 mi.)***	***AH192***	***342***
SOUND SHORE MEDICAL EPA ID: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ202***	***375***
CON EDISON EPA ID: NYP004157665	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***207***	***399***
CON EDISON EPA ID: NYP004674354	MAIN ST & MAPLE AVE	SSW 1/8 - 1/4 (0.226 mi.)	AD209	402
CON EDISON MANHOLE: EPA ID: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD211***	***406***
PREFERRED CLEANERS EPA ID: NYD050275254	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AC214***	***411***
CON EDISON EPA ID: NYP004710497	150 NORTH AV	SE 1/8 - 1/4 (0.229 mi.)	AH219	428
CON EDISON MANHOLE: EPA ID: NYP004443198	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH223***	***434***
CON EDISON SERVICE B EPA ID: NYP004452439	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH224***	***436***
FLAMINGO CLEANERS EPA ID: NYD012946885	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***I48***	***61***
CON EDISON MANHOLE: EPA ID: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***L127***	***201***
CON EDISON MANHOLE 4 EPA ID: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L128***	***203***
CON EDISON MANHOLE: EPA ID: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L129***	***205***
CON EDISON SERVICE B EPA ID: NYP004463667	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L130***	***207***
CON EDISON - MANHOLE EPA ID: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***L132***	***210***
NYS THRUWAY AUTH EPA ID: NYD986963445	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.148 mi.)***	***U144***	***232***
CON EDISON MANHOLE: EPA ID: NYP004307492	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.157 mi.)***	***U159***	***268***
J B & FRANKS EPA ID: NYD986884732	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***AB169***	***289***
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***X176***	***298***

EPA ID: NYD987034998				
CON EDISON MANHOLE: EPA ID: NYP004432886	***350 NORTH AVE***	***N 1/8 - 1/4 (0.193 mi.)***	***U178***	***304***
CON EDISON EPA ID: NYP004205654	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB179***	***306***
CON EDISON EPA ID: NYP004744074	35 BARTELS PL	SW 1/8 - 1/4 (0.193 mi.)	AB180	308
RUSH MFG CORP EPA ID: NYD981185051	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AB183***	***322***
SCHMUCKLERS CLEANERS EPA ID: NYD012950770	***360 NORTH AVE***	***NNW 1/8 - 1/4 (0.212 mi.)***	***AI196***	***348***
LEXINGTON CENTER FOR EPA ID: NYR000193854	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK206***	***396***
CONSOLIDATED EDISON EPA ID: NYP004219572	HUGUENOT ST & HARRIS	NE 1/8 - 1/4 (0.226 mi.)	AL212	408
ALL AMERICAN SPORTS EPA ID: NYD002182897 EPA ID: NYR000040113	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AB216***	***422***
CON EDISON EPA ID: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.232 mi.)	AM222	432
CON EDISON TRANSFORM EPA ID: NYP004372751	***LOCKWOOD AVE & NORTH***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI227***	***441***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***
CON EDISON EPA ID: NYP004838332	LOCKWOOD AVE & NORTH	NNW 1/8 - 1/4 (0.233 mi.)	AI230	449
CON ED EPA ID: NYP004759924	HARRISON ST & CEDAR	ENE 1/8 - 1/4 (0.233 mi.)	AM231	450
LONGINES WITTNAUER W EPA ID: NYD001317221	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL236***	***455***
CON ED EPA ID: NYP004759510	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AM238	466
CON EDISON EPA ID: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AM239	468
CON EDISON EPA ID: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AM240	469
CON EDISON EPA ID: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AM241	471

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL Generator EPA Id: NYD075431502	16 GUION PL	NW 1/8 - 1/4 (0.216 mi.)	AJ200	371

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there are 8 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ERIC S TURNER & CO I EPA ID: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
CON EDISON EPA Id: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD210***	***403***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LEXINGTON CENTER FOR EPA Id: NYR000193854	3 COTTAGE PL	NNE 1/8 - 1/4 (0.217 mi.)	AK205	394
CON EDISON MANHOLE 1 EPA Id: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AL213***	***409***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within

approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON-CEDAR ST	ONE RAMADA PLAZA	NE 1/4 - 1/2 (0.340 mi.)	294	613

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	107 DIVISION ST	W 0 - 1/8 (0.074 mi.)	F52	67
Not reported	35 UNION AVE	W 0 - 1/8 (0.098 mi.)	68	88
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
Not reported	35 GRAND ST	NW 0 - 1/8 (0.121 mi.)	N101	166

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	62 CENTRE AVE	SSW 0 - 1/8 (0.109 mi.)	K85	132
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
Not reported	63 MEMORIAL HWY	WSW 0 - 1/8 (0.001 mi.)	A3	9
Not reported	24 STATION PLZ N	NW 0 - 1/8 (0.057 mi.)	G43	58
Not reported	24 STATION PLZ	NW 0 - 1/8 (0.057 mi.)	G44	58

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 7 records.

Site Name	Database(s)
MEARL CORP.	NY SHWS
VALU CLEAN CLEANERS	NY DRYCLEANERS
SIDEWALK / IN FRONT OF NE	NY LTANKS
N.SHORE LONG ISLAND SOUND	NY LTANKS
MM 5.4 LEFT LANE	NY LTANKS
NEW ROCHELLE CREEK CABLES	FINDS, ECHO
CE-CEDAR ST MGP NEW ROCHELLE	NY VCP

OVERVIEW MAP - 4628045.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: La Rochelle	CLIENT: Blackstone Consulting, LLC
ADDRESS: 255 Huguenot Street New Rochelle NY 10801	CONTACT: Amy Stanton
LAT/LONG: 40.910808 / 73.783536	INQUIRY #: 4628045.2s DATE: May 24, 2016 1:06 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 4628045.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- 100-year flood zone
- 500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
		INQUIRY #:	4628045.2s
LAT/LONG:	40.910808 / 73.783536	DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	1	0	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	2	NR	NR	NR	4
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		2	2	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	1	2	0	NR	3
NY VAPOR REOPENED	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		16	36	111	NR	NR	163
NY HIST LTANKS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		21	23	NR	NR	NR	44
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	15	NR	NR	NR	21
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	3	0	NR	NR	3
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		22	NR	NR	NR	NR	22
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		19	40	NR	NR	NR	59
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		4	4	NR	NR	NR	8
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		30	62	NR	NR	NR	92
RI MANIFEST	0.250		0	0	NR	NR	NR	0
PA MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250		3	5	NR	NR	NR	8
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		3	NR	NR	NR	NR	3
EDR Hist Cleaner	0.125	1	4	NR	NR	NR	NR	5
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		1	132	197	118	0	0	448

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target Property **255 HUGUENOT ST**
NEW ROCHELLE, NY 10801

EDR Hist Cleaner **1015029078**
N/A

Site 1 of 6 in cluster A

Actual:
84 ft.

EDR Historical Cleaners:
Name: SOUND CLEANERS
Year: 2009
Address: 255 HUGUENOT ST

A2
OFFICE BUILDING
8-10 RAILROAD PLACE
< 1/8
NEW ROCHELLE, NY
1 ft.

NY Spills **S102154161**
N/A

Site 2 of 6 in cluster A

Relative:
Lower

Actual:
81 ft.

SPILLS:
Facility ID: 9009493
Facility Type: ER
DER Facility ID: 182194
Site ID: 220275
DEC Region: 3
Spill Date: 1990-11-28
Spill Number/Closed Date: 9009493 / 1991-05-07
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: TAYLOR
Referred To: Not reported
Reported to Dept: 1990-11-30
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 1991-03-18
Cleanup Meets Std: True
Last Inspection: 1991-03-18
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1990-12-06
Spill Record Last Update: 1991-05-08
Spiller Name: Not reported
Spiller Company: 8 RAILROAD PLACE CORP.
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: ""
Remarks: "UNDERGROUND TANK SYSTEM APPEARS TO BE LEAKING ACCORDING TO READINGS MAPLE MAINTENANCE LAGRANGEVILLE NO ODORS NO PRODUCT IN VIEW CALLED JOHN TENORE MAPLE MAINT. WILL BE DOING A TANK TEST MAYBE ONLY 100"

Material:
Site ID: 220275
Operable Unit ID: 946581
Operable Unit: 01

OFFICE BUILDING (Continued) **S102154161**

Material ID:	429706
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	800.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

A3 **EDR Hist Cleaner** **1015082888**
WSW **63 MEMORIAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.001 mi.
6 ft. **Site 3 of 6 in cluster A**

Relative:
Lower

Actual:
83 ft.

EDR Historical Cleaners:

Name:	SOUND CLEANERS
Year:	2010
Address:	63 MEMORIAL HWY
Name:	SOUND CLEANERS
Year:	2011
Address:	63 MEMORIAL HWY
Name:	SOUND CLEANERS
Year:	2012
Address:	63 MEMORIAL HWY

A4 **SOUND CLEANER** **NY DRYCLEANERS** **S110247943**
WSW **63 MEMORIAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.001 mi.
6 ft. **Site 4 of 6 in cluster A**

Relative:
Lower

Actual:
83 ft.

DRYCLEANERS:

Facility ID:	Not reported
Phone Number:	Not reported
Region:	3
Registration Effective Date:	Not reported
Inspection Date:	Not reported
Install Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

B5 **RESIDENCE** **NY Spills** **S109413260**
SSW **129 DIVISON ST** **N/A**
< 1/8 **TARRYTOWN, NY**
0.006 mi.
34 ft. **Site 1 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Facility ID:	0810056
Facility Type:	ER
DER Facility ID:	356816
Site ID:	407567
DEC Region:	3
Spill Date:	2008-12-09
Spill Number/Closed Date:	0810056 / 2010-05-04
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6026
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-09
Spill Record Last Update:	2010-08-27
Spiller Name:	Not reported
Spiller Company:	3RD PARTY SPILL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT
Contact Phone:	(212) 580-8383
DEC Memo:	"12/09/2008: Con Ed reports that this location is the former GM site that was/is a Brownsfield site. Con Ed was laying a gas line when stained soils was found in the trench...ra 08/27/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	"CALLER STATES THAT THEY RECIEVED A 3RD PARTY CALLL STATING THAT THEY FOUND AN UNK PETROLEUM PRODUCT DURING AN EXCAVATION. CLEAN UP IS PENDING."

Material:

Site ID:	407567
Operable Unit ID:	1164107
Operable Unit:	01
Material ID:	2155468
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	Not reported

RESIDENCE (Continued) **S109413260**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

A6 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650791**
South **MEMORIAL HIGHWAY & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.007 mi.
39 ft. **Site 5 of 6 in cluster A**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:
EPA ID: NYP004151221
Country: USA
Location Address 1: MEMORIAL HIGHWAY & HUGUENOT ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 06/21/2007
Trans1 Recv Date: 06/21/2007
Trans2 Recv Date: 06/22/2007
TSD Site Recv Date: 06/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004151221
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 1820
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000174983GBF
Import Ind: N
Export Ind: N

CONSOLIDATED EDISON (Continued) **S108650791**

Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H129

B7 **CON EDISON** **NY MANIFEST** **S117535593**
SSW **HUGENOT & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 2 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004677548
Country:	USA
Location Address 1:	HUGENOT & DIVISION ST
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677548
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014

CON EDISON (Continued) **S117535593**

Manifest Tracking Num:	012774875JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

B8 **CON EDISON MANHOLE: 1215** **RCRA NonGen / NLR** **1016678044**
SSW **HUGENOT AVE & DIVISION ST NE** **FINDS** **NYP004317285**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.009 mi. **ECHO**
48 ft.

Site 3 of 20 in cluster B

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/30/2013
Facility name:	CON EDISON MANHOLE: 1215
Facility address:	HUGENOT AVE & DIVISION ST NE COR NEW ROCHELLE, NY 10801
EPA ID:	NYP004317285
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/30/2013

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Site name: CON EDISON MANHOLE: 1215
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058874865

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004317285
Country: USA
Location Address 1: DIVISION ST & HUGUENOT ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/30/2013
Trans1 Recv Date: 05/30/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/30/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004317285
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010842831JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

Envid:	1016678044
Registry ID:	110058874865
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058874865

B9 **CON ED** **NY MANIFEST** **1016962307**
SSW **DIVISION ST & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 4 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004353199
Country:	USA
Location Address 1:	DIVISION ST AND HUGENOT ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2013
Trans1 Recv Date:	08/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON ED (Continued) **1016962307**

Generator EPA ID:	NYP004353199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011694814JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

B10 **CON EDISON - TRANSFORMER MANHOLE 1154** **RCRA-LQG** **1016962308**
SSW **DIVISION ST AND HUGENOT ST** **NYP004353199**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 5 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - TRANSFORMER MANHOLE 1154
Facility address:	DIVISION ST AND HUGENOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004353199
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/29/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/29/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D008
. Waste name:	LEAD

Historical Generators:

Date form received by agency:	09/29/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 1154
Classification:	Not a generator, verified

Date form received by agency:	08/29/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 1154
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B11
SSW
< 1/8
0.009 mi.
48 ft.

Relative:
Higher

Actual:
101 ft.

CON EDISON
DIVISION & HUGUENOT
NEW ROCHELLE, NY

Site 6 of 20 in cluster B

NY MANIFEST **S117319604**
N/A

NY MANIFEST:

EPA ID:	NYP004676847
Country:	USA
Location Address 1:	DIVISION & HUGUENOT
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770952JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117319604**

Mgmt Method Type Code: H110

B12
SSW
< 1/8
0.009 mi.
48 ft.

Relative: Higher

Actual: 101 ft.

CON EDISON **NY MANIFEST** **S117535602**
HUGENOT ST & DIVISION ST **N/A**
NEW ROCHELLE, NY 10802

Site 7 of 20 in cluster B

NY MANIFEST:

EPA ID:	NYP004677894
Country:	USA
Location Address 1:	HUGENOT ST & DIVISION ST
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677894
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774861JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

CON EDISON (Continued) **S117535602**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

B13 **CON EDISON TRANSFORMER MANHOLE: 1154** **RCRA NonGen / NLR** **1016961985**
SSW **DIVISION ST & HUGUENOT ST** **NYP004349395**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 8 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/21/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 1154
Facility address: DIVISION ST & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004349395
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B14
SSW
< 1/8
0.010 mi.
52 ft.

NYSDOT BIN 1049890
DIVISION ST OVER METRO NORTH
NEW ROCHELLE, NY 10803

Site 9 of 20 in cluster B

RCRA NonGen / NLR | **1000789726** | **NYD987011897**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1049890
Facility address:	DIVISION ST OVER METRO NORTH NEW ROCHELLE, NY 10803
EPA ID:	NYD987011897
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	(914) 431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

NYSDOT BIN 1049890 (Continued) **1000789726**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

Date form received by agency: 08/12/1992
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

C15 **METRO NORTH TRACKS** **NY Spills** **S106126232**
WSW **EAST OF NEW ROCHELLE STAT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.010 mi.
53 ft. **Site 1 of 3 in cluster C**

Relative:
Lower

Actual:
81 ft.

SPILLS:
Facility ID: 0308130
Facility Type: ER
DER Facility ID: 226808
Site ID: 279322
DEC Region: 3
Spill Date: 2003-10-31
Spill Number/Closed Date: 0308130 / 2004-07-16
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2003-10-31
CID: 418
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-10-31
Spill Record Last Update: 2004-07-16
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -

METRO NORTH TRACKS (Continued) **S106126232**

Spiller Company:	001
Contact Name:	JOANNE REILLEY
Contact Phone:	(212) 340-3342
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/5/03 Joanne Reilly stated that the area is inaccessible to work in because of hi speed train taffic. Requested permission to cleanup during a planned closure for a capital project scheduled in 2004. Will submit request in writing to TG. TG 07-15-04 Letter rec'd from Metro North claiming cleanup has been completed. NFA. TG."
Remarks:	"caller states that spill is between 2 tracks and currently have a company rep enroute to the scene"

Material:

Site ID:	279322
Operable Unit ID:	874415
Operable Unit:	01
Material ID:	501652
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

C16 **METRO NORTH TRAIN STATION** **NY Spills** **S102153509**
WSW **NEW HAVEN LINE &R/R PLAZA** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.010 mi.
53 ft. **Site 2 of 3 in cluster C**

Relative:
Lower

Actual:
81 ft.

SPILLS:

Facility ID:	8903573
Facility Type:	ER
DER Facility ID:	92033
Site ID:	104107
DEC Region:	3
Spill Date:	1989-07-10
Spill Number/Closed Date:	8903573 / 1989-07-19
Spill Cause:	Vandalism
Spill Class:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-07-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-07-10
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False

METRO NORTH TRAIN STATION (Continued) **S102153509**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-19
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	METRO NORTH TRAIN STATION
Spiller Address:	NEW HAVEN LINE &R/R PLAZA
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"SOMEONE PUT STEEL BAR ON TRACK. TRAIN HIT BAR, PUNCTURED SMALL HOLE IN TRANFORMER. CAR #8669, EMPLOYEE WALKED TRACK. CLEAN UP IN PROGRESS. WCHD WILL INVESTIGATE, AMER. ENV. TECH, RCIHFIELD CT, NFA"

Material:

Site ID:	104107
Operable Unit ID:	928993
Operable Unit:	01
Material ID:	447657
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

A17 **MH1204** **NY Spills** **S104509750**
ESE **HUGUENOT AVE/LAWTON AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.019 mi.
100 ft. **Site 6 of 6 in cluster A**

Relative:
Higher

Actual:
91 ft.

SPILLS:

Facility ID:	9912755
Facility Type:	ER
DER Facility ID:	214030
Site ID:	262084
DEC Region:	3
Spill Date:	2000-02-09
Spill Number/Closed Date:	9912755 / 2000-02-14
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-02-09
CID:	270
Water Affected:	Not reported

MH1204 (Continued) **S104509750**

Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2000-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/09/2000 SOURCE UNKNOWN-NO OIL FILLED CONED EQUIPMENT NEARBY. VAC TRUCK BEING SENT TO SITE. WILL CALL WITH RESULTS OF PRODUCT I.D. SPILL VOLUME DOWNGRADED TO 3 GALLONS. 02/14/2000 CLEANUP REPORT SENT TO TARRYTOWN OFFICE. AMOUNT SPILLED WAS ACTUALLY 3 GALLONS. NFA"
Remarks:	"OIL STAGNANT SAMPLES WILL BE TAKEN CLEAN UP PENDING"

Material:

Site ID:	262084
Operable Unit ID:	1091472
Operable Unit:	01
Material ID:	294626
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B18 **MEMORIAL HIGHWAY AND** **NY Spills** **S104509646**
South **HUGUNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.022 mi.
114 ft. **Site 10 of 20 in cluster B**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9912617
Facility Type:	ER
DER Facility ID:	208558
Site ID:	254637
DEC Region:	3
Spill Date:	2000-02-04
Spill Number/Closed Date:	9912617 / 2000-04-04
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

MEMORIAL HIGHWAY AND (Continued) **S104509646**

	Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-02-04
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-04
Spill Record Last Update:	2000-04-14
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	AVALONBAY COMMUNITIES
Contact Phone:	(914) 576-3005
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/04/2000 STEVE AT AKRF. NEW ROCHELLE F.D. HAS BEEN ON SITE AS WELL AS T. GHIOSAY 04/04/2000 LETTER SENT TO AKRF BY T. GHIOSAY; CLEANUP SATISFACTORY - SPILL FILE CLOSED."
Remarks:	"CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL"

Material:

Site ID:	254637
Operable Unit ID:	1091315
Operable Unit:	01
Material ID:	294499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B19 **AVALON ON THE SOUND** **NY UST** **U003994344**
South **HUGUENOT STREET AND MEMORAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.022 mi.
116 ft. **Site 11 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800626 / Unregulated: <1101 gal. PBS
Operator Name:	Avalonbay
Owner Name:	Avalonbay Redevelopment LLC
Owner Street:	535 Fifth Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10017
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/01/2000
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

B20 **VACANT LOT** **NY LTANKS** **S107489335**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 12 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	356539
Spill Number/Closed Date:	0510542 / 2006-03-15
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported

VACANT LOT (Continued) **S107489335**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-15
Spiller Name:	STEVE GRENS
Spiller Company:	VACANT LOT
Spiller Address:	HUGUENOT ST/DIVISION ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVE GRENS
Spiller Phone:	(914) 806-5650
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306600
DEC Memo:	"March 15, 2006: BROOKSIDE ENVIRONMENTAL DISPOSED OF LUST AND 5.62 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM AKRF. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallons."

Material:

Site ID:	356539
Operable Unit ID:	1113840
Operable Unit:	01
Material ID:	2103900
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B21 **ROAD** **NY Spills** **S108130430**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 13 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Facility ID:	0606187
Facility Type:	ER
DER Facility ID:	306600
Site ID:	369495
DEC Region:	3
Spill Date:	2006-08-29
Spill Number/Closed Date:	0606187 / 2006-09-03
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

ROAD (Continued) **S108130430**

	Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-29
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-29
Spill Record Last Update:	2006-09-03
Spiller Name:	JEFF CULLEN
Spiller Company:	GC RELIABLE SERVICE COMPA
Spiller Address:	80 GROVE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	WESTCHESTER FIRE CONTROL
Contact Phone:	(914) 231-1905
DEC Memo:	"DPW sanded road. No product to recover. jod"
Remarks:	"SPILL SPANS FOR FIVE BLOCKS BETWEEN THE TWO STREETS GIVEN IN LOCATION: CLEANUP IN PROGRESS: DPW ON SCENE:"

Material:

Site ID:	369495
Operable Unit ID:	1127329
Operable Unit:	01
Material ID:	2116923
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B22 **SHORELINE OIL** **NY LTANKS** **S102674768**
SSW **296 HUGENOT ST,REAR OF** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.033 mi.
174 ft. **Site 14 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	83347
Spill Number/Closed Date:	8709425 / 1988-04-06
Spill Date:	1988-02-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial

SHORELINE OIL (Continued) **S102674768**

Spill Class:	Not reported
Cleanup Ceased:	1988-04-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1988-05-02
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	1988-05-05
Spiller Name:	Not reported
Spiller Company:	SHORELINE OIL
Spiller Address:	34 EVANS ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10805
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76706
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : SITE INSPECT:NO EVIDENCE OF CONTAMINATION FROM OUTSIDE LOCKED GATE. N.F.A. T.D. 05/03/88: NO EVIDENCE OF CONTAMINATION OBSERVED DURING INSPECTION. NFA. "
Remarks:	"OIL INTO PRIVATE DRAIN, TO SUMP,TO SEWER,FROM CAPT.O'CONNOR NRFD(914-654-2215). COMPANY CLEANING UP. DEC TO INVESIGATE & VERIFY CLEAN UP. N.F.A. SEE UPDATE."

Material:

Site ID:	83347
Operable Unit ID:	914524
Operable Unit:	01
Material ID:	464747
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B23
South
< 1/8
0.034 mi.
181 ft.

LILLIAN VERNON CO.
WESTCHESTER PLACE
NEW ROCHELLE, NY

Site 15 of 20 in cluster B

NY LTANKS **S100494788**
N/A

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	201286
Spill Number/Closed Date:	9213055 / 1995-03-16
Spill Date:	1993-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-03-16
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-23
Spill Record Last Update:	1995-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	167465
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO HAVE MEETING TO DISCUSS FURTHER ACTION TANK IS BEING PUMPED DOWN TEMP TANK BEING SET UP AES SYSTEM II"

Material:

Site ID:	201286
Operable Unit ID:	977443
Operable Unit:	01
Material ID:	570289
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

LILLIAN VERNON CO. (Continued) **S100494788**

Tank Test:

Site ID:	201286
Spill Tank Test:	1541204
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

C24 **NYSDOT BIN 1091390** **RCRA NonGen / NLR** **1000790435**
WSW **DIVISION ST OVER I 95** **NYD987019197**
< 1/8 **NEW ROCHELLE, NY 10803**
0.036 mi.
190 ft. **Site 3 of 3 in cluster C**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1091390
Facility address:	DIVISION ST OVER I 95 NEW ROCHELLE, NY 10803
EPA ID:	NYD987019197
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	(914) 431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	4 BURNETT BLVD POUGHKEEPSIE, NY 12603
Owner/operator country:	US
Owner/operator telephone:	(914) 431-5743
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	4 BURNETT BLVD POUGHKEEPSIE, NY 12603
Owner/operator country:	US
Owner/operator telephone:	(914) 431-5743
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

NYSDOT BIN 1091390 (Continued) **1000790435**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

Date form received by agency: 09/25/1992
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

B25 **NEW ROCHELLE IRISH BENEVOLENT SOCIETY** **NY UST** **U003884840**
South **38 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.039 mi.
208 ft. **Site 16 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-600097 / Unregulated
Operator Name: New Rochelle Irish Benevolent Society
Owner Name: New Rochelle Irish Benevolent Society
Owner Street: 38 Division Street
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 26051652
Status: 5. Closed - removed
Capacity: 2000
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1940

NEW ROCHELLE IRISH BENEVOLENT SOCIETY (Continued) **U003884840**

Date Perm Closure:	01/09/2015
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	8. Wrapped (Piping)
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	9. Copper
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

B26 **JONES RESIDENCE** **NY LTANKS** **S106737602**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
239 ft. **Site 17 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	335236
Spill Number/Closed Date:	0410335 / 2005-09-11
Spill Date:	2004-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-12-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-17
Spill Record Last Update:	2005-09-11
Spiller Name:	DARRYL JONES
Spiller Company:	JONES RESIDENCE
Spiller Address:	311 HUGENOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DARRYL JONES
Spiller Phone:	(914) 632-5368
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	270458
DEC Memo:	"12/21/04 PBS FACILITY: 3-801006. jbo September 11, 2005: TANK CLOSED IN PLACE. FIVE SAMPLES TAKEN, NO CONTAMINATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-801006 "

JONES RESIDENCE (Continued) **S106737602**

Material:

Site ID:	335236
Operable Unit ID:	1097307
Operable Unit:	01
Material ID:	577292
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	335236
Spill Tank Test:	1548406
Tank Number:	1
Tank Size:	1500
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

B27 **TRINITY-ST. PAUL'S EPISCOPAL CHURCH** **NY UST** **U003995010**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
239 ft. **Site 18 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801006 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Trinity Episcopal Church
Owner Street:	311 Huguenot Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	03/23/2005
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

TRINITY-ST. PAUL'S EPISCOPAL CHURCH (Continued) **U003995010**

Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

D28 **HUGUENOT AND NORTH AVE** **NY Spills** **S106126832**
NE **HUGUENOT AND NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
243 ft. **Site 1 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

SPILLS:

Facility ID:	0310260
Facility Type:	ER
DER Facility ID:	252866
Site ID:	313618
DEC Region:	3
Spill Date:	2003-12-03
Spill Number/Closed Date:	0310260 / 2005-03-05
Spill Cause:	Traffic Accident
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-03
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-09
Spill Record Last Update:	2005-03-05
Spiller Name:	CARLOS TORRES
Spiller Company:	HUGUENOT AND NORTH AVE
Spiller Address:	HUGUENOT AND NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller Company:	001
Contact Name:	CARLOS TORRES
Contact Phone:	(914) 813-5166
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 3/5/05 5gallon surface spill--close "
Remarks:	"a tow truck carrying a dump truck . the dump truck ruptured and spilled about 5 to 6 gallons of fuel"

Material:

Tank Test:

D29
NE
< 1/8
0.046 mi.
243 ft.

CON EDISON MANHOLE: 5071
HUGUENOT AVE & NORTH AVE
NEW ROCHELLE, NY 10805

Site 2 of 8 in cluster D

RCRA NonGen / NLR
FINDS
NY MANIFEST
ECHO

1016677599
NYP004312476

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/14/2013
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGUENOT AVE & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004312476
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/14/2013
Site name:	CON EDISON MANHOLE: 5071
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110058876550

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

NY MANIFEST:

EPA ID:	NYP004312476
Country:	USA
Location Address 1:	HUGUENOT & NORTH AVE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007658348JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Envid: 1016677599
Registry ID: 110058876550
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110058876550

D30 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963620**
NE **NORTH AVE & HUGUENOT ST** **NY MANIFEST** **NYP004366100**
< 1/8 **NEW ROCHELLE, NY 10801**
0.046 mi.
243 ft. **Site 3 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:
Date form received by agency: 10/25/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 5042
Facility address: NORTH AVE & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004366100
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/25/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004366100
Country: USA
Location Address 1: NOAR/HUGUNOT ST
Location Address 2: MH5042

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/25/2013
Trans1 Recv Date: 09/25/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004366100
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 150
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694648JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

D31 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016968295**
NE **HUGENUOT ST & NORTH AVE** **NYP004419065**
< 1/8 **NEW ROCHELLE, NY 10805**
0.046 mi.
243 ft. **Site 4 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/15/2014
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGENUOT ST & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004419065
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2014
Site name:	CON EDISON MANHOLE: 5071
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

E32 **MAIN LIBRARY** **NY LTANKS** **S103037429**
ESE **LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
243 ft. **Site 1 of 11 in cluster E**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	273025
Spill Number/Closed Date:	9713843 / 1998-03-27
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

MAIN LIBRARY (Continued) **S103037429**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	FRANK GALLELLO
Spiller Phone:	(914) 654-2315
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222185
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED - SYSTEM PASSED. NFA."
Remarks:	""

Material:

Site ID:	273025
Operable Unit ID:	1056692
Operable Unit:	01
Material ID:	324833
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	273025
Spill Tank Test:	1545675
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

MAIN LIBRARY (Continued) **S103037429**

Last Modified: Not reported
Test Method: Horner EZ Check I or II

E33 **ACCESSOCRAFT PRODUCTS INC** **RCRA NonGen / NLR** **1001079768**
SE **48 LAWTON ST** **FINDS** **NYR000014753**
< 1/8 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.046 mi. **ECHO**
245 ft. **Site 2 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ACCESSOCRAFT PRODUCTS INC
Facility address: 48 LAWTON ST
NEW ROCHELLE, NY 10802
EPA ID: NYR000014753
Mailing address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact: Not reported
Contact address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 654-2163
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 654-2163
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

Date form received by agency: 05/10/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 03/06/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 10/11/1995
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Violation Status: No violations found

FINDS:

Registry ID: 110000849672

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000014753
Country: USA
Location Address 1: 48 LAWTON STREET
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: ACCESSOCRAFT INC
Contact: PAUL STEINMAN
Address: 48 LAWTON STREET
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-632-2411

Manifest:

Document ID: RIC0034295
Manifest Status: Completed copy

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Trans1 State ID:	RI49238
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1996
Trans1 Recv Date:	01/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/23/1996
Part A Recv Date:	02/01/1996
Part B Recv Date:	02/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	RID059735761
Trans2 EPA ID:	Not reported
TSDF ID:	RID059735761
Waste Code:	F009 - UNKNOWN
Quantity:	00148
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	00160
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity:	00152
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYB6969834
Manifest Status:	Completed copy
Trans1 State ID:	NYPP5193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/1995
Trans1 Recv Date:	10/23/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/23/1995
Part A Recv Date:	02/22/1996
Part B Recv Date:	11/07/1995
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00195
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: NYB6969807
Manifest Status: Completed copy
Trans1 State ID: PD1011
Trans2 State ID: Not reported
Generator Ship Date: 10/19/1995
Trans1 Recv Date: 10/19/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 10/19/1995
Part A Recv Date: 02/22/1996
Part B Recv Date: 11/07/1995
Generator EPA ID: NYR000014753
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1995

Document ID: NYB7484175
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: LB49775QC
Generator Ship Date: 12/19/1995
Trans1 Recv Date: 12/19/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 12/20/1995
Part A Recv Date: 01/04/1996

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Part B Recv Date:	01/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	NYD986909752
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Quantity:	07496
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1995

ECHO:

Envid:	1001079768
Registry ID:	110000849672
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110000849672

F34 **SPILL NUMBER 9803949** **NY Spills** **S104647160**
WSW **MILEPOST 5.5 SB I95** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.049 mi.
261 ft. **Site 1 of 2 in cluster F**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	9803949
Facility Type:	ER
DER Facility ID:	140562
Site ID:	166821
DEC Region:	3
Spill Date:	1998-06-29
Spill Number/Closed Date:	9803949 / 1998-06-29
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-29
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-29
Spill Record Last Update:	1998-07-02
Spiller Name:	MR STEPHEN WELDON
Spiller Company:	STEPHENS TRANSP INC
Spiller Address:	60 JOFFRE
Spiller City,St,Zip:	AUBURN, ME 04210-
Spiller Company:	001

SPILL NUMBER 9803949 (Continued) **S104647160**

Contact Name: SGT POWELL
Contact Phone: (800) 635-8856
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "drive shaft broke on trk rupturing the saddle tank - cleanup in progress"

Material:
Site ID: 166821
Operable Unit ID: 1064663
Operable Unit: 01
Material ID: 322269
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

D35 **UNITED STATES POST OFFICE** **NY UST** **U004177544**
ENE **255 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.049 mi.
261 ft. **Site 5 of 8 in cluster D**

Relative: Higher

Actual: 87 ft.

WESTCHESTER CO. UST:
Id/Status: 3-448699 / Unregulated: <1101 gal. PBS
Operator Name: U.S. Postal Service
Owner Name: U.s. Postal Service
Owner Street: 255 North Ave.
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10802
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 05/01/2003
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: Not reported
Piping Type: 2. Galvanized steel
Piping External Protection: 0. None

UNITED STATES POST OFFICE (Continued) **U004177544**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

D36 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1005444315**
ENE **255 NORTH AVE** **NY MANIFEST** **NYR000106369**
< 1/8 **NEW ROCHELLE, NY 10801**
0.049 mi.
261 ft. **Site 6 of 8 in cluster D**

Relative:
Higher

Actual:
87 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	US POSTAL SERVICE
Facility address:	255 NORTH AVE NEW ROCHELLE, NY 108019998
EPA ID:	NYR000106369
Mailing address:	WESTCHESTER AVE WHITE PLAINS, NY 106109111
Contact:	JOANNE KUNNY
Contact address:	WESTCHESTER AVE WHITE PLAINS, NY 106109111
Contact country:	US
Contact telephone:	(914) 697-7074
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	255 NORTH AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 632-5906

US POSTAL SERVICE (Continued) **1005444315**

Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: US POSTAL SERVICE
Owner/operator address: 255 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-5906
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: US POSTAL SERVICE
Classification: Not a generator, verified

Date form received by agency: 05/17/2002
Site name: US POSTAL SERVICE
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000106369
Country: USA
Location Address 1: 255 NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:

US POSTAL SERVICE (Continued) **1005444315**

Name: US POSTAL SERVICE
Contact: RICHARD FERRARI
Address: 255 NORTH AVENUE
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-697-7074

Manifest:

Document ID: NYG2937357
Manifest Status: Not reported
Trans1 State ID: 27571PANY
Trans2 State ID: PW8913
Generator Ship Date: 05/29/2002
Trans1 Recv Date: 05/29/2002
Trans2 Recv Date: 05/30/2002
TSD Site Recv Date: 05/31/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000106369
Trans1 EPA ID: NYD986908085
Trans2 EPA ID: NYD082785429
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00060
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

B37 **CERUSSI AND VERE** **NY UST** **U004187246**
SSW **306 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 19 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-078360 / Administratively Closed
Operator Name: Not reported
Owner Name: Michael A Cerussi & F G Vere
Owner Street: 88 Woodlands Rd
Owner Address2: Not reported
Owner City: Harrison
Owner State: NY
Owner Zipcode: 10528
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 1500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1986
Date Perm Closure: 12/01/2001

CERUSSI AND VERE (Continued) **U004187246**

Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

B38 **306 HUGUENOT STREET CORP.** **NY AST** **U004187406**
SSW **306 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 20 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. AST:

PBS Number:	3-800236
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	306 Huguenot Street Corp.
Owner Street:	P.O. Box 196
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	001
Status:	1. In-Service
Date Installation:	12/01/1986
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	Not reported
Dispenser:	3. Gravity

D39 **KAUFMAN HUGUENOT COMPANY** **NY UST** **U003994672**
NE **271 NORTH AVENUE** **NY AST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
290 ft. **Site 7 of 8 in cluster D**

Relative:
Higher

Actual:
84 ft.

WESTCHESTER CO. UST:

Id/Status:	3-183776 / Active
Operator Name:	David Rabius
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10123
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1900
Date Perm Closure:	01/01/2011
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-183776
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Rabius
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10123
Tank Number:	002
Status:	1. In-Service
Date Installation:	08/01/2007
Capacity:	5000
Product Stored:	4. No. 6 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

KAUFMAN HUGUENOT COMPANY (Continued) **U003994672**

Tank Leak Detection:	4. Groundwater Well
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	2. Transfer Station Containment
Dispenser:	2. Suction

E40 **PAVEMENT** **NY Spills** **S112147960**
ESE **41 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.056 mi.
294 ft. **Site 3 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Facility ID:	1203965
Facility Type:	ER
DER Facility ID:	421153
Site ID:	466814
DEC Region:	3
Spill Date:	2012-07-23
Spill Number/Closed Date:	1203965 / 2012-07-23
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2012-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-23
Spill Record Last Update:	2012-07-23
Spiller Name:	BADGE 620
Spiller Company:	UNKNOWN
Spiller Address:	41 LAWTON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	BADGE 620
Contact Phone:	(914) 231-1905
DEC Memo:	"7-23-12 FD cleaned up. jc"
Remarks:	"Possibly from garbage truck. Fire Dept. Clean up."

Material:

Site ID:	466814
Operable Unit ID:	1216796

PAVEMENT (Continued) **S112147960**

Operable Unit:	01
Material ID:	2215011
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

E41 **LAWTON STREET REALTY CORP.** **NY UST** **U004176798**
ESE **41-43 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
294 ft. **Site 4 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801435 / Active
Operator Name:	Lawton Street Realty Corp.
Owner Name:	Lawton Street Realty Corp.
Owner Street:	4391 Boston Post Road
Owner Address2:	Not reported
Owner City:	Pelham Manor
Owner State:	NY
Owner Zipcode:	10803
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	06/01/1927
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

D42 **FEDERAL PROPERTY MAINTENANCE CORP** **RCRA NonGen / NLR** **1012186472**
East **244 NORTH AVE SUITE 153** **NYR000163337**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
295 ft. **Site 8 of 8 in cluster D**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/23/2009
Facility name:	FEDERAL PROPERTY MAINTENANCE CORP
Facility address:	244 NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
EPA ID:	NYR000163337
Mailing address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact:	KRISTIE EFFEREN
Contact address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 355-2226
Contact email:	FEDERALPMC@AOL
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KRISTIE EFFEREN
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/24/2005
Owner/Op end date:	Not reported

Owner/operator name:	ANTHONY VALENTINO
Owner/operator address:	GRANT AVE HARRISON, NY 10528
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/20/1978
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

G43 **EDR Hist Cleaner** **1015025386**
NW **24 STATION PLZ N** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
302 ft. **Site 1 of 2 in cluster G**

Relative:
Lower

Actual:
71 ft.

EDR Historical Cleaners:
Name: GREEN TRAIN CLEANERS
Year: 2011
Address: 24 STATION PLZ N

G44 **EDR Hist Cleaner** **1015025387**
NW **24 STATION PLZ** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
302 ft. **Site 2 of 2 in cluster G**

Relative:
Lower

Actual:
71 ft.

EDR Historical Cleaners:
Name: STATION CLEANERS
Year: 2006
Address: 24 STATION PLZ

Name: M & E DRY CLEANERS
Year: 2012
Address: 24 STATION PLZ

H45 **CABLE** **NY Spills** **S109206706**
South **29 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.057 mi.
303 ft. **Site 1 of 5 in cluster H**

Relative:
Higher

Actual:
101 ft.

SPILLS:
Facility ID: 0804961
Facility Type: ER
DER Facility ID: 351170
Site ID: 401965
DEC Region: 3
Spill Date: 2008-07-30
Spill Number/Closed Date: 0804961 / 2008-07-30
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: jpcummin
Referred To: Not reported
Reported to Dept: 2008-07-30
CID: 444
Water Affected: Not reported

CABLE (Continued) **S109206706**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-07-31
Spiller Name:	ERTSDESK
Spiller Company:	CABLE
Spiller Address:	29 DIVISION STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERTSDESK
Contact Phone:	(212) 580-8383
DEC Memo:	"SEE SP: 0804960. -- NFA"
Remarks:	"8 OUNCES AND ON GOING AND WONT MAKE 2 HOUR CLEAN UP"

Material:

Site ID:	401965
Operable Unit ID:	1158737
Operable Unit:	01
Material ID:	2149827
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

I46 **NORTH BROOK REALTY ASSOCIATES** **NY UST** **U003994769**
NNE **270 NORTH AVENUE - UNDERGROUND** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.062 mi.
329 ft. **Site 1 of 7 in cluster I**

Relative:
Lower

Actual:
80 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600117 / Active
Operator Name:	North Brook Realty Associates
Owner Name:	270 North Avenue Realty Corp.
Owner Street:	270 North Avenue, Suite 200
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	15000

NORTH BROOK REALTY ASSOCIATES (Continued) **U003994769**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

I47 **277 NORTH LLC** **NY LTANKS** **S108467546**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 2 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	376329
Spill Number/Closed Date:	0611648 / 2008-12-04
Spill Date:	2007-01-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-19
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE MOSES
Spiller Company:	277 NORTH LLC
Spiller Address:	277 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	BRUCE MOSES
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11580 12/4/08: Northeast

277 NORTH LLC (Continued) **S108467546**

Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"

Remarks: "EZ 3 LP WAS TEST USED: TANK IS BEING VACCED OUT AND TEMP TANK PUT IN PLACE: ARRANGEMENTS FOR FURTHER TESTING ARE BEING MADE:"

Material:

Site ID:	376329
Operable Unit ID:	1133914
Operable Unit:	01
Material ID:	2123743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	376329
Spill Tank Test:	1550579
Tank Number:	1
Tank Size:	10000
Test Method:	99
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v

I48 **CON EDISON MANHOLE: 11295** **RCRA NonGen / NLR** **1016960384**
NNE **277 NORTH AVE** **NY MANIFEST** **NYP004323457**
< 1/8 **NEW ROCHELLE, NY 10802**
0.072 mi.
382 ft. **Site 3 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2013
Facility name:	CON EDISON MANHOLE: 11295
Facility address:	277 NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004323457
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/28/2013
Site name:	CON EDISON MANHOLE: 11295
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004323457
Country:	USA
Location Address 1:	FO 277 NORTH AVE
Location Address 2:	MH #11295
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2013
Trans1 Recv Date:	06/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004323457

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011693229JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

I49 **BUSINESS** **NY LTANKS** **S108467526**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 4 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	376243
Spill Number/Closed Date:	0611580 / 2008-12-04
Spill Date:	2007-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-18
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE
Spiller Company:	BUSINESS
Spiller Address:	277 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

BUSINESS (Continued) **S108467526**

Spiller Contact:	BRUCE
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11648 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"PIN HOLE IN TANK"

Material:

Site ID:	376243
Operable Unit ID:	1133835
Operable Unit:	01
Material ID:	2123664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	376243
Spill Tank Test:	1550567
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

I50 **277 NORTH LLC** **NY UST** **U003994270**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.072 mi.
382 ft. **Site 5 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

WESTCHESTER CO. UST:

Id/Status:	3-502049 / Active
Operator Name:	Bruce J. Moses
Owner Name:	Robert J. Leaf
Owner Street:	3720 South Ocean Blvd
Owner Address2:	#1606
Owner City:	Highland Beach
Owner State:	FL
Owner Zipcode:	33487
GDS Number:	Not reported

277 NORTH LLC (Continued) **U003994270**

Tank Number:	1
Status:	5. Closed - removed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	01/01/1900
Date Perm Closure:	10/10/2007
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	10/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	7. Jacketed (tank),9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	10. Flexible Piping
Piping External Protection:	8. Wrapped (Piping),9. Urethane
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

I51 **EAST RIVER SAVINGS BANK** **NY LTANKS** **U003647446**
NNE **277 NORTH AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 6 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	271129
Spill Number/Closed Date:	8912285 / 1991-01-16
Spill Date:	1990-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True

EAST RIVER SAVINGS BANK (Continued) **U003647446**

SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-03-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-29
Spill Record Last Update:	1991-03-19
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220684
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/19/91: TANK WAS REKINED AND PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK WAS ISOLATED AND THEY WILL RETEST PETRO-TITE -.3385 GPH"

Material:

Site ID:	271129
Operable Unit ID:	937979
Operable Unit:	01
Material ID:	441756
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	271129
Spill Tank Test:	1536885
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

F52
West
< 1/8
0.074 mi.
392 ft.

107 DIVISION ST — **EDR Hist Auto** — **1015143779** / **N/A**
NEW ROCHELLE, NY 10801

Site 2 of 2 in cluster F

Relative: Higher

Actual: 89 ft.

EDR Historical Auto Stations:

Name:	VARIEDADES CENTER REPAIR
Year:	2012
Address:	107 DIVISION ST

H53
South
< 1/8
0.080 mi.
422 ft.

ARIEL CABLE — **NY Spills** — **S109206705** / **N/A**
19 DIVISION STREET/WASHIN
NEW ROCHELLE, NY

Site 2 of 5 in cluster H

Relative: Higher

Actual: 100 ft.

SPILLS:

Facility ID:	0804960
Facility Type:	ER
DER Facility ID:	351169
Site ID:	401964
DEC Region:	3
Spill Date:	2008-07-30
Spill Number/Closed Date:	0804960 / 2008-08-16
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-08-16
Spiller Name:	ERTSDESK
Spiller Company:	ARIEL CABLE
Spiller Address:	19 DIVISION STREET/WASHIN
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERTSDESK
Contact Phone:	(212) 580-8383
DEC Memo:	"CONTRACTOR ENROUTE"
Remarks:	"6 OUNCES AND ONGOING AND CRW WILL BE ENROUTE"

Material:

Site ID:	401964
Operable Unit ID:	1158736
Operable Unit:	01
Material ID:	2149826
Material Code:	0541A

ARIEL CABLE (Continued) **S109206705**

Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

J54 **5 ANDERSON ST** **NY LTANKS** **S103559119**
East **5 ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.081 mi.
427 ft. **Site 1 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	68771
Spill Number/Closed Date:	9812585 / 1999-07-12
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	1999-09-07
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

Material:

Site ID:	68771
Operable Unit ID:	1069838

5 ANDERSON ST (Continued) **S103559119**

Operable Unit:	01
Material ID:	312860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	68771
Spill Tank Test:	1546739
Tank Number:	2
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Site ID:	68769
Spill Number/Closed Date:	8803214 / 1989-11-30
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-28
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	YOSHIAKI KOWANISHA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	281826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

5 ANDERSON ST (Continued) **S103559119**

OKESSON "
Remarks: "2K FAILED 4-GAL. PER HOUR"

Material:
Site ID: 68769
Operable Unit ID: 918394
Operable Unit: 01
Material ID: 458777
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 68769
Spill Tank Test: 1534286
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

Site ID: 68770
Spill Number/Closed Date: 9812584 / 1999-07-12
Spill Date: 1999-01-12
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1999-01-12
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-01-12
Spill Record Last Update: 2003-07-01
Spiller Name: YOSHIAKI KAWANISHA
Spiller Company: 5 ANDERSON ST

5 ANDERSON ST (Continued) **S103559119**

Spiller Address:	5 ANDERSON ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

Material:

Site ID:	68770
Operable Unit ID:	1069836
Operable Unit:	01
Material ID:	557973
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	68770
Spill Tank Test:	1546738
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

J55 **ANDERSON DEVELOPMENT GROUP** **NY AST** **A100276594**
East **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 2 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:

PBS Number:	3-185515
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Yonkers, NY 10701
Tank Number:	01
Status:	6. Closed - Work Permit Open

ANDERSON DEVELOPMENT GROUP (Continued) **A100276594**

Date Installation:	04/01/1999
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	02/10/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access),5. Synthetic Liner
Piping Location:	1. Aboveground
Piping Type:	2. Galvanized Steel
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	7. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

J56 **ANDERSON DEVELOPMENT GROUP** **NY UST** **U003994331**
East **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 3 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. UST:

Id/Status:	3-185515 / Unregulated
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	7. Excavation/trench Liner system
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

ANDERSON DEVELOPMENT GROUP (Continued) **U003994331**

Tank Number:	2
Status:	5. Closed - removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

E57 **CON EDISON TRANSFORMER MANHOLE: 3585** **RCRA NonGen / NLR** **1016963788**
East **NORTH AVE & ANDERSON ST** **NY MANIFEST** **NYP004367611**
< 1/8 **NEW ROCHELLE, NY 10802**
0.081 mi.
428 ft. **Site 5 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/29/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3585
Facility address:	NORTH AVE & ANDERSON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004367611
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 3585
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004367611
Country: USA
Location Address 1: NORTH AVE & ANDERSON ST
Location Address 2: TM3585
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2013
Trans1 Recv Date: 09/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004367611
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694650JJK
Import Ind: N
Export Ind: N

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E58 **CON EDISON** **NY MANIFEST** **S113920666**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 6 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004683272
Country:	USA
Location Address 1:	NORTH AVE & ANDERSON ST
Location Address 2:	TM3585
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2014
Trans1 Recv Date:	10/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S113920666**

Year:	2014
Manifest Tracking Num:	012773173JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E59 **CON EDISON** **NY MANIFEST** **S118088384**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.081 mi.
428 ft. **Site 7 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004759452
Country:	USA
Location Address 1:	NORTH AVE & ANDERSON ST
Location Address 2:	TM 3585
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S118088384**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091137JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091137JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E60 **CON EDISON** **NY MANIFEST** **S117538298**
East **ANDERSON ST & NORTH AV** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 8 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004709622
Country:	USA
Location Address 1:	ANDERSON ST & NORTH AV
Location Address 2:	SB2063
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709622
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012773453JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117538298**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

E61 **MKM EQUITY, LLC** **NY AST** **A100365275**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.085 mi.
447 ft. **Site 9 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:

PBS Number:	3-600105
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MKM Equity, LLC c/o Cornell Pace Inc.
Owner Street:	542 Main Street, Ste. 2
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	5. Closed - removed
Date Installation:	08/01/1931
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2014
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	0. None

E62 **CONCRETE FLOORING WITH CRACKS** **NY Spills** **S116554293**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.085 mi.
447 ft. **Site 10 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

SPILLS:

Facility ID:	1400277
Facility Type:	ER
DER Facility ID:	448397
Site ID:	493512
DEC Region:	3
Spill Date:	2014-04-08
Spill Number/Closed Date:	1400277 / Not Reported
Spill Cause:	Equipment Failure

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	WCDOH PBS
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2014-04-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2014-04-10
Spiller Name:	Not reported
Spiller Company:	STERLING SOLUTIONS
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	FRANK LANZELLI
Contact Phone:	(914) 666-4328
DEC Memo:	"4-9-14 Last night I traded voicemails with Jerry. He said that he didn't know anymore than provided to the Hotline and I should talk to Frank in the morning. This morning I spoke to Frank. Location has a 1500 gallon vaulted tank with a remote fill at curb. There is currently some oil in the basement sump. Sump is unplugged and it doesn't appear any was pumped out. Frank doesn't know where oil came from, but vault sounds inaccessible. Frank is trying to contact management company to let them know tank needs to be tested. Management Company: Sterling Solutions, 914/437-6245, Aurora is Almeada contact Owner: Milka Iwanow, 914/409-6513 jc 4/09/14: Email received this morning from Chris Lalak: Sebastian went to this one and will follow up. It is a block away from my office. The tank in a vaulted AST (1500 gallon from 1931). There is a spill across the floor and in cracks in the floor getting to a sump pump. The sump goes to the sanitary. The spill may have been going on for so time, the super was very vague. The AST is visible except for a small area that sticks into the floor of the vault. The tank is not visibly leaking. Almeida replaced the underground lines with above ground lines recently. The between the tank, the former underground lines, and the sump is some distance and they will need to excavate the floor. The building has hired Dutchess. Pumping out the tank is not simple. The building has natural gas and oil. jod 04-09-14 followup email, After a second look at this one with a plumber,It looks like the old lines might be leaking. The plumber will uncover the old lines. The tank is not being pumped out at this time. The bottom of the tank is visible for the most part. (the plumber went in the vault, before we were there).Possibly, the remote fill is also an issue. They will replace the tank with an unregulated tank. Sebastian will continue to handle the spill. The floor will be opened up tomorrow to investigate. RDB "
Remarks:	"Caller advised unknown amount of oil spilled onto concrete floor with cracks. Clean up is pending."

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Material:

Site ID:	493512
Operable Unit ID:	1243015
Operable Unit:	01
Material ID:	2243651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

H63 **COMM/RESIDENT. PROPERTY** **NY LTANKS** **S101341321**
South **15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.089 mi.
468 ft. **Site 3 of 5 in cluster H**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	119901
Spill Number/Closed Date:	9405558 / 2005-02-10
Spill Date:	1994-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104134

COMM/RESIDENT. PROPERTY (Continued) **S101341321**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. Tank taken out of service by Royal Environmental. "
Remarks: "TANK TEST ON 7/21/94"

Material:
Site ID: 119901
Operable Unit ID: 1002771
Operable Unit: 01
Material ID: 382138
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 119901
Spill Tank Test: 1542973
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

E64 **NEW ROCHELLE PUBLIC LIBR.** **NY LTANKS** **S100177858**
ESE **MEMORIAL HIGHWAY** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
486 ft. **Site 11 of 11 in cluster E**

Relative:
Higher

Actual:
93 ft.

LTANKS:
Site ID: 306853
Spill Number/Closed Date: 9111450 / 1992-02-06
Spill Date: 1992-02-06
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-02-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported

NEW ROCHELLE PUBLIC LIBR. (Continued) **S100177858**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247822
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SOME ON PAVEMENT,SOME IN STORM DRAIN F.D.HAZMAT USED SORBENT TO CONTAIN AND VENTED BUILING SPOKE WITH DEP. CHIEF STONE"

Material:

Site ID:	306853
Operable Unit ID:	965176
Operable Unit:	01
Material ID:	416486
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

K65 **APARTMENT BLDG** **NY LTANKS** **S105996855**
SSW **54 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
487 ft. **Site 1 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	254563
Spill Number/Closed Date:	0206558 / 2005-02-27
Spill Date:	2002-09-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D

APARTMENT BLDG (Continued) **S105996855**

Reported to Dept:	2002-09-24
CID:	390
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2005-02-27
Spiller Name:	ENERITO GONZALEZ
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AV
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	ENERITO GONZALEZ
Spiller Phone:	(914) 309-2775
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208499
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 2/27/05 #4 overfill to surface--close "
Remarks:	"spill was noticed on 9/6 - unk when it occurred"

Material:

Site ID:	254563
Operable Unit ID:	858169
Operable Unit:	01
Material ID:	517160
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	84302
Spill Number/Closed Date:	0403405 / 2004-12-10
Spill Date:	2004-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-06-29
CID:	406

APARTMENT BLDG (Continued) **S105996855**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-29
Spill Record Last Update:	2004-12-10
Spiller Name:	BASSAM MABER
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BASSAM MABER
Spiller Phone:	(914) 645-6420
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77542
DEC Memo:	"12/10/04 PBS facility. Tank passed a retest after piping was repaired. Spill file closed by Danielle Jackson of the Westchester County Health Dept. No further action is required at this time. jbo"
Remarks:	"Tank Test Failure. Reccommend Retest."

Material:

Site ID:	84302
Operable Unit ID:	886824
Operable Unit:	01
Material ID:	490990
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	84302
Spill Tank Test:	1529391
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

K66 **CEMENT COURT YARD** **NY Spills** **S104282704**
SSW **54 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
487 ft. **Site 2 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Facility ID:	9908117
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114516
DEC Region:	3
Spill Date:	1999-10-04
Spill Number/Closed Date:	9908117 / 1999-10-04
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1999-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-04
Spill Record Last Update:	1999-10-06
Spiller Name:	Not reported
Spiller Company:	CEMENT COURT YARD
Spiller Address:	54 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 10/4/99 SPILLER CLEANED UP. NFA"
Remarks:	"BLDG SUPER OVERORDERED - CLEANED UP"

Material:

Site ID:	114516
Operable Unit ID:	1082403
Operable Unit:	01
Material ID:	555958
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	Gallons
Recovered:	6.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CEMENT COURT YARD (Continued) **S104282704**

Tank Test:

Facility ID:	9804849
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114515
DEC Region:	3
Spill Date:	1998-07-18
Spill Number/Closed Date:	9804849 / 2002-07-15
Spill Cause:	Deliberate
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-18
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-18
Spill Record Last Update:	2002-07-15
Spiller Name:	Not reported
Spiller Company:	NABER REALTY INC
Spiller Address:	BOX 156H
Spiller City,St,Zip:	SCARSDALE, NY 10583-
Spiller Company:	001
Contact Name:	CAPT DIMEGLIA
Contact Phone:	(914) 654-2215
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"fd called to an odor of fuel oil in a residence- upon arrival in basement it appeared were working on the oil boiler and were pumping product into sewer thru sump pumps"

Material:

Site ID:	114515
Operable Unit ID:	1065894
Operable Unit:	01
Material ID:	319611
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CEMENT COURT YARD (Continued) **S104282704**

Tank Test:

K67 **SEASONWEIN MANAGEMENT LLC** **NY UST** **U003994353**
SSW **54 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.092 mi.
487 ft. **Site 3 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

WESTCHESTER CO. UST:

Id/Status:	3-169773 / Active
Operator Name:	Matt Seasonwein
Owner Name:	Seasonwein Management LLC
Owner Street:	300 Gramatan Avenue
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10552
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1928
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

---

68 **EDR Hist Auto** **1015441959**
West **35 UNION AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
519 ft.

Relative:
Higher

Actual:
101 ft.

EDR Historical Auto Stations:

Name:	RANILLAS AUTO BODY SHOP
Year:	2007
Address:	35 UNION AVE

K69 **CON EDISON** **RCRA NonGen / NLR** **1014398803**
SSW **HUGUENOT ST & CENTRE ST** **NYP004211728**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 4 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/19/2010
Facility name:	CON EDISON
Facility address:	HUGUENOT ST & CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004211728
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

K70 **CON EDISON** **NY MANIFEST** **S117319603**
SSW **CENTER & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.099 mi.
521 ft. **Site 5 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

EPA ID:	NYP004676839
Country:	USA
Location Address 1:	CENTER & HUGUENOT
Location Address 2:	MH 1230
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON

CON EDISON (Continued) **S117319603**

Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770954JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K71 **CON EDISON** **NY MANIFEST** **S113917500**
SSW **CENTRE AVE & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 6 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

EPA ID:	NYP004332961
Country:	USA
Location Address 1:	CENTRE AVE & HUGUENOT ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801

CON EDISON (Continued) **S113917500**

Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2013
Trans1 Recv Date: 07/22/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004332961
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011695949JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

K72 **CON EDISON** **NY MANIFEST** **S117535592**
SSW **HUGENOT & CENTRE ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 7 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:
EPA ID: NYP004677530
Country: USA
Location Address 1: HUGENOT & CENTRE ST
Location Address 2: MH 1230

CON EDISON (Continued) **S117535592**

Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/14/2014
Trans1 Recv Date: 10/14/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677530
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012774876JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

J73 **CVS PHARMACY #8447** **RCRA-LQG** **1014958220**
ESE **222 NORTH AVE** **NY MANIFEST** **NYR000194654**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
523 ft. **Site 4 of 7 in cluster J**

Relative:
Higher

Actual:
91 ft.

RCRA-LQG:

Date form received by agency:	03/17/2014
Facility name:	CVS PHARMACY #8447
Facility address:	222 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYR000194654
Mailing address:	CVS DR 23062A WOONSOCKET, RI 02895
Contact:	WENDY BRANT
Contact address:	CVS DR WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	(401) 765-1500
Contact email:	WENDY.BRANT@CVSCAREMARK.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	45 SOUTH MAIN STREET CORP
Owner/operator address:	GLEN OAKS DR RYE, NY 10580
Owner/operator country:	US
Owner/operator telephone:	(917) 757-4922
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/20/2011
Owner/Op end date:	Not reported

Owner/operator name:	45 SOUTH MAIN STREET CORP
Owner/operator address:	GLEN OAKS DRIVE RYE, NY 10580
Owner/operator country:	US
Owner/operator telephone:	(917) 757-4922
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/20/2011
Owner/Op end date:	Not reported

Owner/operator name:	CVS ALBANY, L.L.C.
Owner/operator address:	GLEN OAKS DRIVE RYE, NY 10580

CVS PHARMACY #8447 (Continued) **1014958220**

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D010
. Waste name: SELENIUM

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL--YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

CVS PHARMACY #8447 (Continued) **1014958220**

Historical Generators:
Date form received by agency: 07/01/2013
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Date form received by agency: 03/05/2012
Site name: CVS PHARMACY #8447
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081

CVS PHARMACY #8447 (Continued) **1014958220**

. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000194654
Country: USA
Location Address 1: 222 NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CVS PHARMACY #8447
Contact: CVS PHARMACY #8447
Address: 222 NORTH AVE
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-637-7591

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJR000063677
Generator Ship Date: 05/13/2015
Trans1 Recv Date: 05/13/2015
Trans2 Recv Date: 05/19/2015
TSD Site Recv Date: 05/21/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID040098352
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 007425277FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

CVS PHARMACY #8447 (Continued) **1014958220**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/13/2015
Trans1 Recv Date:	05/13/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	05/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	17
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007425277FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/17/2015
Trans1 Recv Date:	10/17/2015
Trans2 Recv Date:	10/23/2015
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	6
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

CVS PHARMACY #8447 (Continued) **1014958220**

Year:	2015
Manifest Tracking Num:	008652237FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/13/2015
Trans1 Recv Date:	05/13/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	06/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007425276FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/17/2015
Trans1 Recv Date:	10/17/2015

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 Recv Date:	10/23/2015
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008652238FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	03/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007385576FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	03/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007385576FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	07/30/2015
TSD Site Recv Date:	08/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006428508FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	07/30/2015
TSD Site Recv Date:	08/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	7
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006428508FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJR000063677
Generator Ship Date: 02/24/2015
Trans1 Recv Date: 02/24/2015
Trans2 Recv Date: 02/26/2015
TSD Site Recv Date: 03/25/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 0.04
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 007385576FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 09/09/2014
Trans1 Recv Date: 09/09/2014
Trans2 Recv Date: 09/23/2014
TSD Site Recv Date: 10/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 5
Units: P - Pounds
Number of Containers: 1

CVS PHARMACY #8447 (Continued) **1014958220**

Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	Not reported
Quantity:	6
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274057FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	Not reported
Quantity:	3
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274057FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	PAD982661381
Generator Ship Date:	12/08/2014
Trans1 Recv Date:	12/08/2014
Trans2 Recv Date:	12/15/2014
TSD Site Recv Date:	01/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007292048FLE
Import Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	PAD982661381
Generator Ship Date:	12/08/2014
Trans1 Recv Date:	12/08/2014
Trans2 Recv Date:	12/15/2014
TSD Site Recv Date:	01/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	4
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007292048FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/09/2014
Part A Recv Date:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	06/16/2014
Trans1 Recv Date:	06/16/2014
Trans2 Recv Date:	06/19/2014
TSD Site Recv Date:	06/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.01
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007211387FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	03/28/2014
Trans1 Recv Date:	03/28/2014
Trans2 Recv Date:	04/03/2014
TSD Site Recv Date:	04/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Quantity:	27
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	006441835FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	03/28/2014
Trans1 Recv Date:	03/28/2014
Trans2 Recv Date:	04/03/2014
TSD Site Recv Date:	04/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	006441835FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

L74 **DELUXE TAXI** **NY UST** **U001736524**
North **10 STATION PLAZA** **N/A**
< 1/8 **NEW ROCHELLE - WESCHESTER, NY 10801**
0.100 mi.
529 ft. **Site 1 of 11 in cluster L**

Relative:
Lower

Actual:
77 ft.

UST:

Id/Status:	2-601600 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	566353.87500
UTM Y:	4486105.00000
Site Type:	Unknown

Affiliation Records:

Site Id:	23562
Affiliation Type:	Facility Owner
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Mail Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	On-Site Operator
Company Name:	DELUXE TAXI
Contact Type:	Not reported
Contact Name:	ROCHELLE DELUXE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

DELUXE TAXI (Continued) **U001736524**

Zip Code:	Not reported
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Emergency Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	JOHN TENORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 632-2108
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47103
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	05/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron

DELUXE TAXI (Continued) **U001736524**

WESTCHESTER CO. UST:

Id/Status:	3-600004 / Unregulated: <1101 gal. PBS
Operator Name:	Rochell Deluxe Taxi, Inc.
Owner Name:	8 Railroad Place Corporation
Owner Street:	8 Station Plaza South
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	11/03/1993
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

I75 **DEVELOPMENT SITE** **NY LTANKS S107522540**
NE **175 HUGUENOT STREET** **NY Spills N/A**
< 1/8 **NEW ROCHELLE, NY**
0.102 mi.
536 ft. **Site 7 of 7 in cluster I**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	358910
Spill Number/Closed Date:	0512575 / 2006-03-08
Spill Date:	2006-01-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-01-30
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

DEVELOPMENT SITE (Continued) **S107522540**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-30
Spill Record Last Update:	2006-03-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JOHN MANFREDI
Spiller Phone:	(914) 241-3795
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	307023
DEC Memo:	"3/08/06 See JM associates spill closure report for 05-04821. TG"
Remarks:	""

Material:

Site ID:	358910
Operable Unit ID:	1116137
Operable Unit:	01
Material ID:	2106280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0510932
Facility Type:	ER
DER Facility ID:	307023
Site ID:	356986
DEC Region:	3
Spill Date:	2005-12-19
Spill Number/Closed Date:	0510932 / 2005-12-19
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

DEVELOPMENT SITE (Continued) **S107522540**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2006-03-08
Spiller Name:	SEAN MCKAY
Spiller Company:	TRUMP PLAZA
Spiller Address:	175 HUEGOTNOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEAN MCKAY
Contact Phone:	(646) 772-6987
DEC Memo:	"CONFIRMED CLEANUP WITH WCDOH 3/8/06 See spill JM Associates closure report for 05-04821"
Remarks:	"SPILL AROUND GENERATOR AND IN PROCESS OF BEING CLEANED UP;"

Material:

Site ID:	356986
Operable Unit ID:	1114275
Operable Unit:	01
Material ID:	2104355
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0504821
Facility Type:	ER
DER Facility ID:	307023
Site ID:	349739
DEC Region:	3
Spill Date:	2005-07-20
Spill Number/Closed Date:	0504821 / 2006-03-08
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

DEVELOPMENT SITE (Continued) **S107522540**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2006-03-08
Spiller Name:	JOHN MANFREDIE
Spiller Company:	NEW ROCHELLE #1A
Spiller Address:	HUGIGNOT /LAACONTA
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	JOHN MANFREDIE
Contact Phone:	(914) 241-3795
DEC Memo:	"3/02/06 UST removal report submitted by JM Associates including information about two other spill reports listed for the same parcel, 05-10932 and 05-12575. A total of 5 UST's were removed along with 3,351.05 tons of petroleum impacted soil. Based on the information contained in the report, no further action is required. TG"
Remarks:	"DURING EXCAVATION FOUND AN ABANDON TANK: AND FOUND CONTAMINATED SOIL"
	Not reported

Material:

Site ID:	349739
Operable Unit ID:	1107327
Operable Unit:	01
Material ID:	2097217
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

K76 **M.J. HACKER & SONS INC.** **NY UST** **U004176847**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
538 ft. **Site 8 of 20 in cluster K**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-137979 / Unregulated
Operator Name:	Steve Mangels
Owner Name:	Steve Mangels
Owner Street:	64 Centre Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Prior to 04/1991
Capacity:	4000
Product Stored:	7. Gasoline

M.J. HACKER & SONS INC. (Continued) **U004176847**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1973
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	002
Status:	3. Closed - Prior to 04/1991
Capacity:	2000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1980
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	003
Status:	8. Unregistered
Capacity:	500
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported

M.J. HACKER & SONS INC. (Continued) **U004176847**

Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 004
Status: 5. Closed - removed
Capacity: 750
Product Stored: 13. Waste/Used Oil
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: 01/01/1900
Date Perm Closure: 05/12/2014
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: Not reported
Tank External Protection: Not reported
Tank Secondary Containment: Not reported
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: Not reported
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 005
Status: 5. Closed - removed
Capacity: Not reported
Product Stored: 7. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 05/14/2014
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: Not reported

Tank Number: 4
Status: 5. Closed - removed
Capacity: 550
Product Stored: 13. Waste/Used Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 06/01/1979
Date Perm Closure: 03/06/2014

M.J. HACKER & SONS INC. (Continued) **U004176847**

Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

H77 **RPM REALTY INC** **NY AST** **A100412045**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 4 of 5 in cluster H**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. AST:

PBS Number:	3-166189
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536

Tank Number:	2
Status:	1. In-Service
Date Installation:	06/01/1997
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

H78 **RPM REALTY INC** **NY UST** **U004240676**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 5 of 5 in cluster H**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-166189 / Active
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City:	Katonah
Owner State:	NY
Owner Zipcode:	10536
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	Not reported
Date Perm Closure:	06/17/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

K79 **ERIC S TURNER & CO INC.** **RCRA-CESQG** **1007204937**
SSW **33-35 CENTRE AVE** **NJ MANIFEST** **NYD002015402**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.103 mi.
545 ft. **Site 9 of 20 in cluster K**

Relative:
Higher

Actual:
94 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	ERIC S TURNER & CO INC.
Facility address:	33-35 CENTRE AVE NEW ROCHELLE, NY 108010000
EPA ID:	NYD002015402
Mailing address:	PO BOX #816 NEW ROCHELLE, NY 108010000
Contact:	WILLIAM TURNER
Contact address:	PO BOX #816 NEW ROCHELLE, NY 108010000
Contact country:	US
Contact telephone:	(914) 235-7114
Telephone ext.:	9999
Contact email:	Not reported
EPA Region:	02

ERIC S TURNER & CO INC. (Continued) **1007204937**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ERIC S TURNER & CO INC.
Classification: Small Quantity Generator

Date form received by agency: 03/18/2005
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Date form received by agency: 03/21/1994
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYD002015402
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: 9142357114
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5224399
EPA ID:	NYD002015402
Date Shipped:	12/06/2004
TSDF EPA ID:	NJR000022442
Transporter EPA ID:	NJR000023325
Transporter 2 EPA ID:	OHD009865825
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/06/2004
Date Trans2 Transported Waste:	12/07/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01250521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NY MANIFEST:

EPA ID:	NYD002015402
Country:	USA
Location Address 1:	33-35 CENTRE AVE

ERIC S TURNER & CO INC. (Continued) **1007204937**

Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: ERIC S TURNER & CO INC.
Contact: W V TURNER PRESIDENT
Address: P. O. BOX 816
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-235-7114

Manifest:

Document ID: NJA5224399
Manifest Status: Not reported
Trans1 State ID: NJAF906B
Trans2 State ID: 58746
Generator Ship Date: 12/06/2004
Trans1 Recv Date: 12/06/2004
Trans2 Recv Date: 12/07/2004
TSD Site Recv Date: 12/08/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002015402
Trans1 EPA ID: NJR000023325
Trans2 EPA ID: Not reported
TSDF ID: NJR000022
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2004

Document ID: MAQ0630594
Manifest Status: Not reported
Trans1 State ID: NJAF906B
Trans2 State ID: Not reported
Generator Ship Date: 12/06/2004
Trans1 Recv Date: 12/06/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/06/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

Generator EPA ID: NYD002015402
Trans1 EPA ID: NJR000023325
Trans2 EPA ID: Not reported
TSDF ID: MAD047075
Waste Code: D007 - CHROMIUM 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2004

Document ID: NYB7375383
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GE9561
Trans2 State ID: Not reported
Generator Ship Date: 11/13/1995
Trans1 Recv Date: 11/13/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/13/1995
Part A Recv Date: 11/27/1995
Part B Recv Date: 12/11/1995
Generator EPA ID: NYD002015402
Trans1 EPA ID: NYD981182769
Trans2 EPA ID: Not reported
TSDF ID: NYD981182769
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1995

Document ID: PAE1357226
Manifest Status: Completed copy
Trans1 State ID: PAAH0317
Trans2 State ID: Not reported
Generator Ship Date: 12/12/1994
Trans1 Recv Date: 12/12/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 12/14/1994
Part A Recv Date: / /
Part B Recv Date: 01/03/1995
Generator EPA ID: NYD002015402
Trans1 EPA ID: PAD982661381
Trans2 EPA ID: Not reported
TSDF ID: PAD085690592
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)

ERIC S TURNER & CO INC. (Continued) **1007204937**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1994

Document ID:	PAE0182103
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PAAH0317
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/1993
Trans1 Recv Date:	09/02/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/10/1993
Part A Recv Date:	10/15/1993
Part B Recv Date:	10/04/1993
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00225
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00155
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1993

Document ID:	NYA1234098
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS632
Trans2 State ID:	Not reported
Generator Ship Date:	10/11/1984
Trans1 Recv Date:	10/11/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/11/1984
Part A Recv Date:	10/16/1984
Part B Recv Date:	10/19/1984
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279

ERIC S TURNER & CO INC. (Continued) **1007204937**

Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1984

Document ID:	NYB2551311
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GX6293
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/1991
Trans1 Recv Date:	10/10/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/11/1991
Part A Recv Date:	10/18/1991
Part B Recv Date:	11/06/1991
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1991

Document ID:	NYB2109852
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GX6293
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/1990
Trans1 Recv Date:	04/30/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/07/1990
Part A Recv Date:	11/01/1990
Part B Recv Date:	06/22/1990
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	01500

ERIC S TURNER & CO INC. (Continued) **1007204937**

Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1990

Document ID: NYB2111013
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GX6293
Trans2 State ID: Not reported
Generator Ship Date: 04/30/1990
Trans1 Recv Date: 04/30/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 05/07/1990
Part A Recv Date: 11/01/1990
Part B Recv Date: 06/22/1990
Generator EPA ID: NYD002015402
Trans1 EPA ID: NYD000691949
Trans2 EPA ID: Not reported
TSDF ID: NYD000691949
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1990

Document ID: NYA7204554
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000

ERIC S TURNER & CO INC. (Continued) **1007204937**

Generator Ship Date:	03/29/1989
Trans1 Recv Date:	03/29/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/29/1989
Part A Recv Date:	04/04/1989
Part B Recv Date:	04/12/1989
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1989

Document ID:	NJA0009467
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS632
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	06/03/1985
Part B Recv Date:	03/07/1985
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1985

Document ID:	NYO1552698
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	08/09/1984
Trans1 Recv Date:	08/09/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/09/1984
Part A Recv Date:	08/30/1984
Part B Recv Date:	09/05/1984
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

TSDF ID:	NJD048810279
Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1984

Document ID:	NJA2870118
Manifest Status:	Not reported
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/1998
Trans1 Recv Date:	09/16/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID:	NJR000022442
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5591092
Manifest Status:	Not reported
Trans1 State ID:	ILP39038
Trans2 State ID:	564TUH
Generator Ship Date:	06/16/1999
Trans1 Recv Date:	06/16/1999
Trans2 Recv Date:	06/18/1999
TSD Site Recv Date:	06/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	NYD000708198
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP

ERIC S TURNER & CO INC. (Continued) **1007204937**

Quantity:	00004
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	PAC0336453
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0278
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1992
Trans1 Recv Date:	07/22/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/23/1992
Part A Recv Date:	08/05/1992
Part B Recv Date:	07/30/1992
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD000813477
Trans2 EPA ID:	Not reported
TSDF ID:	PAD087561015
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	02900
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1992

M80 **P&D TRANSPORT - HOT TAR** **NY Spills** **S106126552**
SW **I-95 NB @ MM 5.4** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 1 of 2 in cluster M**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	0308809
Facility Type:	ER
DER Facility ID:	265298
Site ID:	329742
DEC Region:	3
Spill Date:	2003-11-18
Spill Number/Closed Date:	0308809 / 2003-11-26
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS:	6010
Investigator:	tdghiosa

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

Referred To:	Not reported
Reported to Dept:	2003-11-18
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-18
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	P&D TRANSPORT
Spiller Address:	171 BROWNSTONE AVE
Spiller City,St,Zip:	PORTLAND, CT 06480-
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11-18-03 P&D Transport trailer carrying 5000 gallons of a hot tar product developed several leaks from seams and holes beneath the trailer. The driver, John Culbreath, pulled the vehicle to the shoulder of I-95 NB at mm 5.4 in New Rochelle. The trailer drained hot tar to the road shoulder where it flowed downhill until it cooled and solidified. Approximatley 200 feet of shoulder where affected before the trailer could be offloaded. DEC called out Castlton Environmental contractors when a company Rep stated that he/she would not sent a second truck to offload the damaged trailer. Castlton contacted Mystic Bulk Carriers and requested their assistance. Mystic provided a heated truck, suitable to offload the cargo and return it to Ownes Corning in Kearny where the load was originally picked up. The P&D damaged trailer was towed off the road to a spot near the I-95 toll plaza. Castlton performed the removal of the solidified tar several days later as they were delayed by heavy rain which created hazardous working conditions on busily traveled I-95. As of 11-18-03, Portland Asphalt indicated that they would pay Caslton directly for the cost of the cleanup. "
Remarks:	"material goes into a manhole which leads to a water way. poss hutchinson river. spill not controlled yet. caller req call back from rep"

Material:

Site ID:	329742
Operable Unit ID:	877435
Operable Unit:	01
Material ID:	498725
Material Code:	0018A
Material Name:	tar
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

Tank Test:

M81 **I-95** **NY Spills** **S102152708**
SW **I-95EB MP54** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 2 of 2 in cluster M**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	8700158
Facility Type:	ER
DER Facility ID:	105126
Site ID:	121121
DEC Region:	3
Spill Date:	1987-04-07
Spill Number/Closed Date:	8700158 / 1987-04-07
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	6010
Investigator:	WEED
Referred To:	Not reported
Reported to Dept:	1987-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	1987-04-07
Cleanup Meets Std:	True
Last Inspection:	1987-04-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-04-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	""

Material:

Site ID:	121121
Operable Unit ID:	904779
Operable Unit:	01
Material ID:	473726
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

I-95 (Continued) **S102152708**

Oxygenate: Not reported

Tank Test:

N82 **DEPOT PLACE LLC** **NY UST** **U003994482**
NW **1 DEPOT PLACE** **N/A**
< 1/8 **MAMARONECK (T), NY**
0.106 mi.
560 ft. **Site 1 of 5 in cluster N**

Relative:
Lower

Actual:
72 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801085 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Depot LLC
Owner Street:	1 Depot Place
Owner Address2:	Not reported
Owner City:	Mamaroneck
Owner State:	NY
Owner Zipcode:	Not reported
GDS Number:	Not reported
Tank Number:	001
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/21/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

N83 **STATION CLEANERS** **NY DRYCLEANERS** **S110247994**
NW **1 DEPOT PLAZA #1** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.106 mi.
560 ft. **Site 2 of 5 in cluster N**

Relative:
Lower

Actual:
72 ft.

DRYCLEANERS:

Facility ID:	---
Phone Number:	Not reported
Region:	3
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported

STATION CLEANERS (Continued) **S110247994**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: ???

K84 **GREEN HEAVEN/CENTRE CLEANERS** **NY DRYCLEANERS** **S106437149**
SSW **62 CENTRE AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
574 ft. **Site 10 of 20 in cluster K**

Relative: Higher

Actual: 98 ft.

DRYCLEANERS:
Facility ID: 3-5510-00298
Phone Number: 914-636-5350
Region: Not reported
Registration Effective Date: 9/24/2003 13:22:51:203
Inspection Date: 11SEP8
Install Date: 88/98
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF2000
Current Business: Not reported

K85 **EDR Hist Cleaner** **1015081768**
SSW **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
574 ft. **Site 11 of 20 in cluster K**

Relative: Higher

Actual: 98 ft.

EDR Historical Cleaners:
Name: CENTRE CLEANERS TAILORS INCORPORATED
Year: 2000
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2001
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2002
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2003
Address: 62 CENTRE AVE

Name: CENTER CLEANERS
Year: 2007
Address: 62 CENTRE AVE

Name: CENTER CLEANERS
Year: 2008
Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORS INC
Year: 2010

(Continued) **1015081768**

Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORING INC
Year: 2011
Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORS
Year: 2012
Address: 62 CENTRE AVE

K86 **SIMONETTI CLEANERS** **RCRA-CESQG** **1000338662**
SSW **62 CENTRE ST** **US AIRS** **NYD982531634**
< 1/8 **NEW ROCHELLE, NY 10801** **FINDS**
0.109 mi. **NY MANIFEST**
574 ft. **Site 12 of 20 in cluster K** **ECHO**

Relative:
Higher

Actual:
98 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: SIMONETTI CLEANERS
Facility address: 62 CENTRE ST
NEW ROCHELLE, NY 10801
EPA ID: NYD982531634
Mailing address: CENTRE ST
NEW ROCHELLE, NY 10801
Contact: KWANG YUN
Contact address: CENTRE ST
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 636-5350
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: KWANG YUN
Owner/operator address: 24 SUMMIT AVE
MOUNT VERNON, NY 10550
Owner/operator country: US
Owner/operator telephone: (914) 665-0274
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Owner/operator name: KWANG YUN
Owner/operator address: 24 SUMMIT AVE
MOUNT VERNON, NY 10550
Owner/operator country: US
Owner/operator telephone: (914) 665-0274
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SIMONETTI CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/21/1996
Site name: SIMONETTI CLEANERS
Classification: Small Quantity Generator

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

SIMONETTI CLEANERS (Continued) **1000338662**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

US AIRS MINOR:

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR 020000003606156000
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR NY0000NY3551000298
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012174805

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

SIMONETTI CLEANERS (Continued) **1000338662**

AIR MINOR

NY MANIFEST:

EPA ID:	NYD982531634
Country:	USA
Location Address 1:	62 CENTRE AVENUE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SIMONETTI CLEANERS
Contact:	SIMONETTI CLEANERS
Address:	62 CENTRE AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-636-5350

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000664906
Trans2 State ID:	CDX761010010
Generator Ship Date:	01/10/2009
Trans1 Recv Date:	01/10/2009
Trans2 Recv Date:	01/16/2009
TSD Site Recv Date:	01/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	390.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004562249JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

SIMONETTI CLEANERS (Continued) **1000338662**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/12/2007
Trans1 Recv Date:	05/12/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000497613SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	NYC7340343
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	T19L8DNJ
Generator Ship Date:	05/03/2004
Trans1 Recv Date:	05/03/2004
Trans2 Recv Date:	05/05/2004
TSD Site Recv Date:	05/06/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

SIMONETTI CLEANERS (Continued) **1000338662**

Year: 2004

Document ID: NYC7459705
Manifest Status: Not reported
Trans1 State ID: NY49455JF
Trans2 State ID: T470GL
Generator Ship Date: 11/29/2004
Trans1 Recv Date: 11/29/2004
Trans2 Recv Date: 12/01/2004
TSD Site Recv Date: 12/03/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: OHD980587
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYC7252356
Manifest Status: Not reported
Trans1 State ID: NYCF7875
Trans2 State ID: NJ044
Generator Ship Date: 12/29/2003
Trans1 Recv Date: 12/29/2003
Trans2 Recv Date: 12/30/2003
TSD Site Recv Date: 01/05/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00300
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7086767
Manifest Status: Not reported
Trans1 State ID: NYCR3164
Trans2 State ID: AH0697
Generator Ship Date: 05/16/2003
Trans1 Recv Date: 05/16/2003

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 Recv Date:	05/21/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7019346
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	T25L8DNJ
Generator Ship Date:	01/24/2003
Trans1 Recv Date:	01/24/2003
Trans2 Recv Date:	01/29/2003
TSD Site Recv Date:	01/30/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC6663240
Manifest Status:	Not reported
Trans1 State ID:	DW9495
Trans2 State ID:	NJT51G9T
Generator Ship Date:	02/26/2002
Trans1 Recv Date:	02/26/2002
Trans2 Recv Date:	03/04/2002
TSD Site Recv Date:	03/05/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

SIMONETTI CLEANERS (Continued) **1000338662**

Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6873568
Manifest Status: Not reported
Trans1 State ID: NY49455JF
Trans2 State ID: T53G9TNJ
Generator Ship Date: 09/30/2002
Trans1 Recv Date: 09/30/2002
Trans2 Recv Date: 10/02/2002
TSD Site Recv Date: 10/03/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6494207
Manifest Status: Not reported
Trans1 State ID: 19952JF
Trans2 State ID: NJ044
Generator Ship Date: 11/06/2001
Trans1 Recv Date: 11/06/2001
Trans2 Recv Date: 11/12/2001
TSD Site Recv Date: 11/13/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

SIMONETTI CLEANERS (Continued) **1000338662**

Document ID:	NYC5750392
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2001
Trans1 Recv Date:	04/24/2001
Trans2 Recv Date:	04/27/2001
TSD Site Recv Date:	04/28/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYC6083190
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	03/08/2000
Trans1 Recv Date:	03/08/2000
Trans2 Recv Date:	03/09/2000
TSD Site Recv Date:	03/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6190817
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/28/2000
Trans1 Recv Date:	06/28/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC6304983
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: TNT218034
Generator Ship Date: 12/06/2000
Trans1 Recv Date: 12/06/2000
Trans2 Recv Date: 12/06/2000
TSD Site Recv Date: 12/11/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC5974018
Manifest Status: Not reported
Trans1 State ID: NYR2436
Trans2 State ID: T422NXNJ
Generator Ship Date: 11/10/1999
Trans1 Recv Date: 11/10/1999
Trans2 Recv Date: 11/15/1999
TSD Site Recv Date: 11/19/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001

SIMONETTI CLEANERS (Continued) **1000338662**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5644552
Manifest Status: Not reported
Trans1 State ID: NYCR243
Trans2 State ID: T422NXNY
Generator Ship Date: 05/28/1999
Trans1 Recv Date: 05/28/1999
Trans2 Recv Date: 06/01/1999
TSD Site Recv Date: 06/03/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5849605
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: T104414IL
Generator Ship Date: 07/20/1999
Trans1 Recv Date: 07/20/1999
Trans2 Recv Date: 07/22/1999
TSD Site Recv Date: 07/26/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5520666
Manifest Status: Not reported
Trans1 State ID: NYCR2436

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	CTF0671288
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1998
Trans1 Recv Date:	01/08/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0688517
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/1998
Trans1 Recv Date:	03/06/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00140
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

ECHO:

Envid:	1000338662
Registry ID:	110012174805
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110012174805

K87 **COMMERCIAL PROPERTY** **NY LTANKS** **S116156733**
SSW **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.111 mi.
585 ft. **Site 13 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	489220
Spill Number/Closed Date:	1308480 / 2015-04-28
Spill Date:	2013-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-20
Spill Record Last Update:	2015-05-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	64 CENTRE AVE
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	STEVE MANGELS
Spiller Phone:	(914) 632-2610
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444316
DEC Memo:	"11-20-13: Chris/WCHD call to V.Mc./Dispt.: Closed Unreg. PBS faciliy. Wayne/WCHD to handle. 11/20/2013 1:48:33 PM:: From Chris

COMMERCIAL PROPERTY (Continued) **S116156733**

Lalak to Wayne Schneider via email:: Wayne, Former PBS site 3-137979 Expired in 1992 (removed gasoline tanks) TTF for Underground waste oil tank estimated as a 550 (Ullage leak and they plan to remove the tank.) The Facility is: M. Hacker and Sons. Please get them to register and deal with the TTF jod 04/23/15 HydroEnvironmental Solutions submitted a report documenting the installation of a temporary monitoring well in the location were the LUST was removed. (See report in DecDocs) Trace levels of VOCs & SVOCs in the sample. TG 4-28-15 closed NFA -RDB"

Remarks: ""

Material:

Site ID:	489220
Operable Unit ID:	1238809
Operable Unit:	01
Material ID:	2238759
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

O88 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016965006**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004379020**
< 1/8 **NEW ROCHELLE, NY 10802**
0.112 mi.
594 ft. **Site 1 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10802
EPA ID:	NYP004379020
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/23/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 4319
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004379020
Country:	USA
Location Address 1:	CENTRE AVE & RELYEA PL
Location Address 2:	SB4314
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011693664JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

O89 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016963532**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004365318**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
594 ft. **Site 2 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/24/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004365318
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/24/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 4319
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004365318
Country: USA
Location Address 1: CENTRE AVE & RELYEA PL
Location Address 2: TM 4319
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/24/2013
Trans1 Recv Date: 09/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004365318
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694707JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

P90 **CON EDISON MANHOLE 1181** **RCRA NonGen / NLR** **1014918324**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219380**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
594 ft. **Site 1 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/02/2010
Facility name:	CON EDISON MANHOLE 1181
Facility address:	HUGUENOT ST & LECOUNT PL MH 1181 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219380
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/02/2010
Site name:	CON EDISON MANHOLE 1181
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON MANHOLE 1181 (Continued) **1014918324**

NJ MANIFEST:

EPA Id:	NYP004219380
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874911JJK
EPA ID:	NYP004219380
Date Shipped:	11/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

NY MANIFEST:
EPA ID: NYP004219380
Country: USA
Location Address 1: HUGENOT ST & LE COURT
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON - MH 1181
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/02/2010
Trans1 Recv Date: 11/02/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004219380
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874911JJK
Import Ind: N
Export Ind: N

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

P91 **CON EDISON MANHOLE 1178** **RCRA NonGen / NLR** **1014918331**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219455**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
594 ft. **Site 2 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/03/2010
Facility name:	CON EDISON MANHOLE 1178
Facility address:	HUGUENOT ST & LECOUNT PL MH 1178 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219455
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/03/2010
Site name:	CON EDISON MANHOLE 1178
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004219455
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874912JJK
EPA ID:	NYP004219455
Date Shipped:	11/03/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

NY MANIFEST:
EPA ID: NYP004219455
Country: USA
Location Address 1: HUGUENOT ST & LE COURT
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON - MH 1178
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/03/2010
Trans1 Recv Date: 11/03/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004219455
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874912JJK
Import Ind: N

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

P92 **CON EDISON** **NY MANIFEST** **S118259788**
NE **HUGENOT ST & LECOUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.112 mi.
594 ft. **Site 3 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:

EPA ID:	NYP004837407
Country:	USA
Location Address 1:	HUGENOT ST & LECOUNT PL
Location Address 2:	V 7723
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/2015
Trans1 Recv Date:	09/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837407
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S118259788**

Year:	2015
Manifest Tracking Num:	014472144JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K93 **NYNEX LOCATION** **NY LTANKS** **S102660218**
SSW **342 HUEGNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.113 mi.
598 ft. **Site 14 of 20 in cluster K**

Relative:
Higher

Actual:
99 ft.

LTANKS:

Site ID:	270876
Spill Number/Closed Date:	9708146 / 1997-10-10
Spill Date:	1997-10-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1997-11-12
Spiller Name:	RICH KALISTA
Spiller Company:	BELL ATLANTIC
Spiller Address:	2203 MCCONNELL ST
Spiller City,St,Zip:	BELLMORE, NY
Spiller County:	001
Spiller Contact:	TOM MUFF
Spiller Phone:	(914) 449-5321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220510
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DOING AN UPGRADE FOR A NYNEX LOCATION AND REMOVING 2 UNDERGROUND TANKS FROM A BASEMENT - TANKS WERE ENCASED BY SAND & WHEN REMOVED THE SAND WAS CONTAMINATED - THEY HAVE REMOVED SAND."

NYNEX LOCATION (Continued) **S102660218**

Material:

Site ID:	270876
Operable Unit ID:	1051372
Operable Unit:	01
Material ID:	330133
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

J94 **SPEEDY CLEANERS** **US AIRS** **1006295756**
ESE **217 NORTH AVENUE** **FINDS** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801** **NY DRYCLEANERS**
0.113 mi. **ECHO**
598 ft. **Site 5 of 7 in cluster J**

Relative:
Higher

Actual:
91 ft.

US AIRS MINOR:

Envid:	1006295756
Region Code:	02
Programmatic ID:	AIR NY0000NY3551000344
Facility Registry ID:	110012166921
D and B Number:	Not reported
Primary SIC Code:	7212
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012166921

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking

SPEEDY CLEANERS (Continued) **1006295756**

environmental facility information found across the State.

AIR MINOR

DRYCLEANERS:

Facility ID:	3-5510-00344
Phone Number:	914-654-9082
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	03DEC31
Install Date:	00/03
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

ECHO:

Envid:	1006295756
Registry ID:	110012166921
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110012166921

L95 **SPOKEN ARTS BUILDING (FORMER)** **NY UST** **U003885171**
North **310 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.114 mi.
603 ft. **Site 2 of 11 in cluster L**

Relative:
Lower

Actual:
75 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600705 / Unregulated: <1101 gal. PBS
Operator Name:	Mr. Anthony Blaise
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1994
Date Perm Closure:	09/01/1994
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported

SPOKEN ARTS BUILDING (FORMER) (Continued) **U003885171**

Spill Prevention: 0. None
Dispenser: 0. None

J96 **MACYS NEW ROCHELLE** **NY UST** **U003856957**
East **THE MALL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.117 mi.
616 ft. **Site 6 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. UST:
Id/Status: 3-167037 / Unregulated: <1101 gal. PBS
Operator Name: Macys New York
Owner Name: Macys New York
Owner Street: The Mall
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 4. Closed - in place
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1967
Date Perm Closure: 09/26/1997
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 2
Status: 4. Closed - in place
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1967
Date Perm Closure: 09/26/1997
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None

MACYS NEW ROCHELLE (Continued) **U003856957**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

L97 **NORTH GARDEN ASSOCIATES LLC** **NY UST** **U004177039**
North **309-311 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.117 mi.
618 ft. **Site 3 of 11 in cluster L**

Relative:
Lower

Actual:
74 ft.

WESTCHESTER CO. UST:

Id/Status:	3-496928 / Active
Operator Name:	Harrin Platzner
Owner Name:	North Garden Associates LLC
Owner Street:	P.O Box 111
Owner Address2:	309-311 North Avenue
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/15/1947
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	9. Copper
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	2. Suction

O98 **APPAREL PLUS** **NY Spills** **S116156116**
SW **27 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.118 mi.
624 ft. **Site 3 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

SPILLS:

Facility ID:	1309988
Facility Type:	ER
DER Facility ID:	445839
Site ID:	490810
DEC Region:	3
Spill Date:	2014-01-14

APPAREL PLUS (Continued) **S116156116**

Spill Number/Closed Date:	1309988 / 2014-01-14
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	DXWEITZ
Referred To:	Not reported
Reported to Dept:	2014-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-14
Spill Record Last Update:	2014-01-14
Spiller Name:	CHRIS LALAK
Spiller Company:	APPAREL PLUS LAUNDRY
Spiller Address:	27 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CHRIS LALAK
Contact Phone:	(914) 224-7649
DEC Memo:	"1/14/14 Chris Lalak from WCHD called and said that this was motor oil from a truck in the parking lot. People at the laundry did the cleanup. According to Chris Lalak, the spill can be closed. They were there for other reasons. NFA dw"
Remarks:	"loss to sewer. c/u in progress"

Material:

Site ID:	490810
Operable Unit ID:	1240364
Operable Unit:	01
Material ID:	2240510
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q99 **SIDNEY FURNITURE** **NY Spills** **S118460140**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 1 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	1509029
Facility Type:	ER
DER Facility ID:	75076
Site ID:	517634
DEC Region:	3
Spill Date:	2015-12-03
Spill Number/Closed Date:	1509029 / 2015-12-04
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-04
Spill Record Last Update:	2015-12-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MICHELLE GUERRERO
Contact Phone:	(347) 982-5522
DEC Memo:	"12/04/15: Caller states she is at work, states she is pregnant, and states that they were working on the furnace and there was a small oil spill. She wanted to know if oil spills are hazardous. I was in the process of answering her questions and she hung up. Westchester County Dept of Health notified. No further DEC action. jod"
Remarks:	"Caller advised aprx 1/2 gal of oil spilled onto carpet. Clean up is pending. Caller is requesting a call back"

Material:

Site ID:	517634
Operable Unit ID:	1266703
Operable Unit:	01
Material ID:	2270652
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons

SIDNEY FURNITURE (Continued) **S118460140**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Q100 **SPILL NUMBER 9900400** **NY Spills** **S104648843**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 2 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9900400
Facility Type:	ER
DER Facility ID:	75076
Site ID:	81102
DEC Region:	3
Spill Date:	1999-04-08
Spill Number/Closed Date:	9900400 / 1999-07-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-04-12
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-12
Spill Record Last Update:	2004-02-24
Spiller Name:	MR GOLDBERG
Spiller Company:	MR GOLDBERG
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	001
Contact Name:	MR GOLDBERG
Contact Phone:	(212) 370-1333
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/9/99 SPILL CLEANED BY TOWN & COUNTRYF OIL. NFA"
Remarks:	"FAULTY VENT ALARM - SPILLED LESS THAN 1 GAL - CLEANED UP - TENANTS STILL COMPLAINING OF ODORS"

Material:

Site ID:	81102
Operable Unit ID:	1075164
Operable Unit:	01
Material ID:	307538
Material Code:	0001A

SPILL NUMBER 9900400 (Continued) **S104648843**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9415294
Facility Type:	ER
DER Facility ID:	205781
Site ID:	251083
DEC Region:	3
Spill Date:	1995-02-17
Spill Number/Closed Date:	9415294 / 1995-03-03
Spill Cause:	Human Error
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER DID NOT HEAR VENT ALARM AND OVERFILLED TANK REGENT OIL CLEANED UP"

Material:

Site ID:	251083
Operable Unit ID:	1012611
Operable Unit:	01
Material ID:	370473
Material Code:	0001A

SPILL NUMBER 9900400 (Continued) **S104648843**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

N101 **EDR Hist Auto** **1015441746**
NW **35 GRAND ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.121 mi.
639 ft. **Site 3 of 5 in cluster N**

Relative:
Lower

Actual:
76 ft.

EDR Historical Auto Stations:

Name:	EAST COAST AUTO TRIM
Year:	1999
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2000
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2001
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2002
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2003
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2004
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2005
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2006
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2007
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2009

(Continued) **1015441746**

Address: 35 GRAND ST

Q102 **LILLIAN VERNON CORP.** **NY LTANKS** **S102152290**
South **543 MAIN STREET** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
649 ft. **Site 3 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	94435
Spill Number/Closed Date:	0308082 / 2004-05-12
Spill Date:	2003-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-10-30
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-05-19
Spiller Name:	JEFF WEIR
Spiller Company:	BLUE GILL REALTY
Spiller Address:	543 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	JEFF WEIR
Spiller Phone:	(646) 435-8110
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	84546
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MAGNUSON 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #9212475. Letter has PBS #3-801106."
Remarks:	"TANK HAS BEEN REMOVED."

Material:

Site ID:	94435
Operable Unit ID:	876585
Operable Unit:	01
Material ID:	501599
Material Code:	0001A
Material Name:	#2 fuel oil

LILLIAN VERNON CORP. (Continued) **S102152290**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	94435
Spill Tank Test:	1528780
Tank Number:	1
Tank Size:	2500
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	9212475
Facility Type:	ER
DER Facility ID:	108333
Site ID:	125220
DEC Region:	3
Spill Date:	1993-02-03
Spill Number/Closed Date:	9212475 / 2004-05-12
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2004-05-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

LILLIAN VERNON CORP. (Continued) **S102152290**

GHIOSAY 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #0308082."

Remarks: "FUEL OIL LINE HAS PIN HOLE LEAK DISCOVERED IN EXCAVATION BY EMER.ENVIRO. SERVICE TODAY REMOTE FILL LINE 2 VERY BADLY PITTED AND CORRODED WILL DRILL WELL 2/4/93"

Material:

Site ID:	125220
Operable Unit ID:	976940
Operable Unit:	01
Material ID:	402326
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q103 **LILLIAN VERNON CORPORATION** **NY UST** **U003994695**
South **543-549 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 4 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600279 / Unregulated: <1101 gal. PBS
Operator Name:	Joseph F. Dimicco
Owner Name:	Lillian Vernon Corp.
Owner Street:	510 South Fulton Ave
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10550
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground

LILLIAN VERNON CORPORATION (Continued) **U003994695**

Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Q104 **543 MAIN STREET** **NY UST** **U003994286**
South **543 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 5 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801106 / Unregulated: <1101 gal. PBS
Operator Name:	Paul Risse
Owner Name:	Bluegill Realty, LLC
Owner Street:	250 West 30th Street
Owner Address2:	Not reported
Owner City:	NY
Owner State:	NY
Owner Zipcode:	10001
GDS Number:	Not reported
Tank Number:	001
Status:	5. Closed - removed
Capacity:	2500
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/07/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

K105 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000553730**
SSW **342 HUGUENOT ST** **NY MANIFEST** **NYD986961605**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
650 ft. **Site 15 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NEW YORK TELEPHONE CO
Facility address:	342 HUGUENOT ST
	NEW ROCHELLE, NY 10801

NEW YORK TELEPHONE CO (Continued) **1000553730**

EPA ID: NYD986961605
Mailing address: NINTH AVE
NEW YORK, NY 10001
Contact: CATHERINE ROM
Contact address: NINTH AVE
NEW YORK, NY 10001
Contact country: US
Contact telephone: (212) 502-7694
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-9964
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-9964
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

NEW YORK TELEPHONE CO (Continued) **1000553730**

Date form received by agency: 07/02/1991
Site name: NEW YORK TELEPHONE CO
Classification: Small Quantity Generator

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986961605
Country: USA
Location Address 1: 342 HUGANAUGHT STREET
Location Address 2: Not reported
Location City: WESTCHESTER
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: TELESECTOR RESOURCES GROUP
Contact: WAYNE SEBRO
Address: 441 9TH AVENUE 5TH FLOOR
City/State/Zip: NEW YORK, NY 10001
Country: USA
Phone: 212-502-7694

Manifest:

Document ID: ILA7651009
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 1478
Trans2 State ID: 2075
Generator Ship Date: 10/23/1997
Trans1 Recv Date: 10/23/1997
Trans2 Recv Date: 10/23/1997
TSD Site Recv Date: 10/29/1997
Part A Recv Date: 11/26/1997
Part B Recv Date: 11/20/1997
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: NJD000813477
TSDF ID: ILD000608471
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

NEW YORK TELEPHONE CO (Continued) **1000553730**

Year: 1997

Document ID: MAF3478760
Manifest Status: Completed copy
Trans1 State ID: 50C143OH
Trans2 State ID: 50C143OH
Generator Ship Date: 07/11/1991
Trans1 Recv Date: 07/11/1991
Trans2 Recv Date: 07/12/1991
TSD Site Recv Date: 07/15/1991
Part A Recv Date: 07/26/1991
Part B Recv Date: 07/26/1991
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: MAD039322250
TSDF ID: MAD053452637
Waste Code: B005 - PCB ARTICLES WITH 500 PPM OR > PCB
Quantity: 00364
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1991

Document ID: MAH2671330
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: MA970642
Trans2 State ID: Not reported
Generator Ship Date: 11/23/1993
Trans1 Recv Date: 11/23/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 11/24/1993
Part A Recv Date: / /
Part B Recv Date: 12/20/1993
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID: MAD980523203
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00004
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

K106 **VERIZON** **NY Spills** **S106867403**
SSW **342 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
650 ft. **Site 16 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

SPILLS:

Facility ID:	0413326
Facility Type:	ER
DER Facility ID:	288752
Site ID:	342403
DEC Region:	3
Spill Date:	2005-03-22
Spill Number/Closed Date:	0413326 / 2005-09-11
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-22
Spill Record Last Update:	2005-09-11
Spiller Name:	CLAUDIA
Spiller Company:	VERIZON
Spiller Address:	342 HUGUENOT ST.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CLAUDIA
Contact Phone:	Not reported
DEC Memo:	"September 11, 2005: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank is tight has a bad vent line. Will be replacing the vent line."

Material:

Site ID:	342403
Operable Unit ID:	1101130
Operable Unit:	01
Material ID:	581261
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

VERIZON (Continued) **S106867403**

Tank Test:

Site ID:	342403
Spill Tank Test:	1548716
Tank Number:	6
Tank Size:	6000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

K107 **VERIZON NEW YORK INC. (NY96332)** **NY UST U003949914**
SSW **342 HUGUENOT STREET** **NY AST N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
650 ft. **Site 17 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

WESTCHESTER CO. UST:

Id/Status:	3-184586 / Active
Operator Name:	Verizon New York Inc.
Owner Name:	Verizon New York Inc.
Owner Street:	140 West Street
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10007
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	01/01/1990
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported

VERIZON NEW YORK INC. (NY96332) (Continued) **U003949914**

Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	11/01/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	11/01/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	4
Status:	5. Closed - removed
Capacity:	550
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	09/01/1997
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported

VERIZON NEW YORK INC. (NY96332) (Continued) **U003949914**

Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	6
Status:	1. In-Service
Capacity:	6000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	11/01/1997
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	6. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	99. Other
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-184586
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Verizon New York Inc.
Owner Name:	Verizon New York Inc.
Owner Street:	140 West Street
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10007

Tank Number:	5
Status:	1. In-Service
Date Installation:	09/01/1997
Capacity:	300
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	0. None
Dispenser:	2. Suction

Q108 **CON EDISON** **NY MANIFEST** **S118464238**
SSE **S DIVSION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 6 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

EPA ID:	NYP004872319
Country:	USA
Location Address 1:	S DIVSION ST & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/23/2015
Trans1 Recv Date:	11/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004872319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	9020
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	013245368JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118464238**

Mgmt Method Type Code: H110

Q109 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243060**
SSE **DIVISION & MAIN** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.124 mi.
653 ft. **Site 7 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

EPA ID:	NYP004123873
Country:	USA
Location Address 1:	DIVISION & MAIN
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON
Contact:	FRANKLIN MURRAY
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-2808

Manifest:

Document ID:	NYE1274139
Manifest Status:	Not reported
Trans1 State ID:	46207JMNY
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2004
Trans1 Recv Date:	08/22/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/23/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	01400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2004

CONSOLIDATED EDISON (Continued) **1009243060**

Document ID:	NYE1309977
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2004
Trans1 Recv Date:	08/28/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00001
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYE1308411
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/23/2004
Trans1 Recv Date:	08/23/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYE1308357
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/25/2004
Trans1 Recv Date:	08/25/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/25/2004
Part A Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **1009243060**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00008
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

L110 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016963395**
North **313 NORTH AVE FRONT OF** **NYP004364030**
< 1/8 **NEW ROCHELLE, NY 10801**
0.125 mi.
658 ft. **Site 4 of 11 in cluster L**

Relative:
Lower

Actual:
74 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/20/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	313 NORTH AVE FRONT OF NEW ROCHELLE, NY 10801
EPA ID:	NYP004364030
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/20/2013

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

Site name: CON EDISON MANHOLE: 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

R111 **CON EDISON** **NY MANIFEST** **S118089619**
ESE **208 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.125 mi.
659 ft. **Site 1 of 4 in cluster R**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:
EPA ID: NYP004772265
Country: USA
Location Address 1: 208 NORTH AVE
Location Address 2: SB 2029
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/22/2015
Trans1 Recv Date: 04/22/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004772265
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014454078JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N

CON EDISON (Continued) **S118089619**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014454078JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K112 **75 CENTRE AVENUE LLC** **NY UST U004175967**
SSW **75 CENTRE AVENUE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.125 mi.
662 ft. **Site 18 of 20 in cluster K**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800240 / Active
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	52 North Central Ave.
Owner Address2:	Not reported
Owner City:	Elmsford
Owner State:	NY
Owner Zipcode:	10523

75 CENTRE AVENUE LLC (Continued) **U004175967**

GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

WESTCHESTER CO. AST:
PBS Number: 3-800240
Site Status: Active
GDS Number: Not reported
Operator Name: Dino Rentoulis
Owner Name: John & Dino Rentoulis
Owner Street: 52 North Central Ave.
Owner Address2: Not reported
Owner City/State/Zip: Elmsford, NY 10523

Tank Number: 002
Status: 1. In-Service
Date Installation: 09/01/2004
Capacity: 1500
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 1. Aboveground (contact w/ soil)
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 1. Diking (aboveground only)
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

J113 **MACYS** **NY MANIFEST** **1009232715**
East **33 LE COUNT PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.127 mi.
672 ft. **Site 7 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP000890137
Country:	USA
Location Address 1:	33 LE COUNT PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	MACYS
Contact:	MACYS
Address:	33 LE COUNT PLACE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-633-7700

Manifest:

Document ID:	NYA7026894
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	06/22/1989
Trans1 Recv Date:	06/22/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/22/1989
Part A Recv Date:	08/03/1989
Part B Recv Date:	06/29/1989
Generator EPA ID:	NYP000890137
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1989

L114 **4 STORY APARTMENT BUILDING** **NY UST** **U003883840**
North **320 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.128 mi.
674 ft. **Site 5 of 11 in cluster L**

Relative:
Lower

Actual:
72 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600732 / Unregulated: <1101 gal. PBS
Operator Name:	City Of New Rochelle
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue

4 STORY APARTMENT BUILDING (Continued) **U003883840**

Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1961
Date Perm Closure:	02/28/1995
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	12. Cut-off Walls
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	2
Status:	5. Closed - removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	02/28/1995
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Q115
SSE
1/8-1/4
0.129 mi.
681 ft.

COMMERCIAL PROPERTY
522 MAIN STREET
NEW ROCHELLE, NY

Site 8 of 15 in cluster Q

NY LTANKS **S111012266**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	448142
Spill Number/Closed Date:	1100723 / 2011-06-06
Spill Date:	2011-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-20
Spill Record Last Update:	2011-06-06
Spiller Name:	PETER OH
Spiller Company:	ADELPHI
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JEFF
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402739
DEC Memo:	"Spoke to Georgia at Advanced. Soil boring had field evidence of petroleum impact. DT 4/20/11 6/6/11: Report from Preferred Environmental entered into eDocs. NFA jod"
Remarks:	"1721 THE CALLER ADVISED DISPATCH THEY ARE AWAITING TANK TEST RESULTS."

Material:

Site ID:	448142
Operable Unit ID:	1198388
Operable Unit:	01
Material ID:	2194662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported

COMMERCIAL PROPERTY (Continued) **S111012266**

Oxygenate: Not reported

Tank Test:

K116 **COCO RESIDENCE** **NY LTANKS** **S106123934**
South **81 CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
684 ft. **Site 19 of 20 in cluster K**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	313391
Spill Number/Closed Date:	0311339 / 2005-01-10
Spill Date:	2004-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-07
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-07
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	ED COCO
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 01/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson dated 9Feb2004(?). WCDOH requires NFA at this time."
Remarks:	"Failed test. Unknown if the tank is leaking"

Material:

Site ID:	313391
Operable Unit ID:	878986
Operable Unit:	01
Material ID:	500153
Material Code:	0001A
Material Name:	#2 fuel oil

COCO RESIDENCE (Continued) **S106123934**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	313391
Spill Tank Test:	1528899
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

S117 **COMMERCIAL BUILDING** **NY LTANKS** **S100177795**
SSE **507 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.131 mi.
690 ft. **Site 1 of 6 in cluster S**

Relative:
Higher

Actual:
96 ft.

LTANKS:

Site ID:	286303
Spill Number/Closed Date:	9110835 / 1992-03-10
Spill Date:	1992-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-02-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	1992-02-06
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-23
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	EPHRAIM ASSOC.
Spiller Address:	300 EAST 74TH STREET
Spiller City,St,Zip:	NEW YORK, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

COMMERCIAL BUILDING (Continued) **S100177795**

DEC Region: 3
DER Facility ID: 232045
DEC Memo: ""
Remarks: "BANK AGREEMENT ASSESMENT REVEALED 1K #2 FUEL TANK 12 IN CONCRETE REMAINDER A/G IN BRICK VAULT TANK PULLED TODAY WITH ONE HOLE IN BOTTOM CONCRETE SLAB NOT CRACKED WILL PULL AND INSPECT ON MONDAY"

Material:
Site ID: 286303
Operable Unit ID: 960971
Operable Unit: 01
Material ID: 415913
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Q118 **CON EDISON TRANSFORMER MANHOLE: 3586** **RCRA NonGen / NLR** **1016974043**
SSE **CHURCH ST & MAIN ST** **NY MANIFEST** **NYP004478517**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.131 mi.
691 ft. **Site 9 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/25/2014
Facility name: CON EDISON TRANSFORMER MANHOLE: 3586
Facility address: CHURCH ST & MAIN ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004478517
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/25/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 3586
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004478517
Country: USA
Location Address 1: CHURCH MAIN ST
Location Address 2: SB3586
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/25/2014
Trans1 Recv Date: 03/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004478517
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770521JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Q119 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963458**
SSE **MAIN ST & CHRUCH ST** **NY MANIFEST** **NYP004364576**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
691 ft. **Site 10 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5042
Facility address:	MAIN ST & CHRUCH ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004364576
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Historical Generators:
Date form received by agency: 09/23/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004364576
Country: USA
Location Address 1: MAINS T & CHURCH ST
Location Address 2: TM 5042
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/23/2013
Trans1 Recv Date: 09/23/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004364576
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 120
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694706JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Q120 **CON EDISON MANHOLE: 12758** **RCRA NonGen / NLR** **1016974052**
SSE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004478624**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
691 ft. **Site 11 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/25/2014
Facility name: CON EDISON MANHOLE: 12758
Facility address: MAIN ST & CHURCH ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004478624
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/25/2014
Site name: CON EDISON MANHOLE: 12758
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004478624
Country: USA
Location Address 1: MAIN & CHURCH ST

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Location Address 2: SB12758
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/25/2014
Trans1 Recv Date: 03/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004478624
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012770524JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Q121
SSE
1/8-1/4
0.131 mi.
691 ft.

CON EDISON
MAIN ST & CHURCH ST
OSSINING, NY 10801

Site 12 of 15 in cluster Q

NY MANIFEST **S117535683**
N/A

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP004680070
Country:	USA
Location Address 1:	MAIN ST & CHURCH ST
Location Address 2:	MH2419
Location City:	OSSINING
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2014
Trans1 Recv Date:	10/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680070
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774891JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117535683**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

K122 **HUGUENOT HOLDINGS, LLC** **NY AST** **A100359858**
SSW **347 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.133 mi.
702 ft. **Site 20 of 20 in cluster K**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. AST:

PBS Number:	3-502626
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Owen Henry (Super)
Owner Name:	Huguenot Holdings, LLC
Owner Street:	1333 A North Avenue
Owner Address2:	#419
Owner City/State/Zip:	New Rochelle, NY 10583
Tank Number:	1
Status:	1. In-Service
Date Installation:	06/01/1995
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

R123 **CATHOLIC NEWS PUBLISHING** **NY LTANKS** **S106972587**
ESE **210 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.137 mi.
723 ft. **Site 2 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	347516
Spill Number/Closed Date:	0503023 / 2005-08-28
Spill Date:	2005-06-13
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported

CATHOLIC NEWS PUBLISHING (Continued) **S106972587**

Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-13
CID:	44
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-13
Spill Record Last Update:	2005-08-28
Spiller Name:	MYLES RIDDER
Spiller Company:	CATHOLIC NEWS PUBLISHING
Spiller Address:	210 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MYLES RIDDER
Spiller Phone:	(914) 632-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293840
DEC Memo:	"August 28, 2005: NORTHEAT DISPOSED OF LUST AND 48.90 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK AND HOLES IN TANK"

Material:

Site ID:	347516
Operable Unit ID:	1105241
Operable Unit:	01
Material ID:	1502620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q124 **OFFICE BLDG** **NY LTANKS** **S107489194**
South **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.138 mi.
728 ft. **Site 13 of 15 in cluster Q**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	355877
Spill Number/Closed Date:	0509995 / 2006-03-22
Spill Date:	2005-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2005-11-21
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-03-22
Spiller Name:	UNKNOWN
Spiller Company:	OFFICE BLDG
Spiller Address:	542 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305921
DEC Memo:	"March 22, 2006 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	""

Material:

Site ID:	355877
Operable Unit ID:	1113209
Operable Unit:	01
Material ID:	2103275
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

OFFICE BLDG (Continued) **S107489194**

Tank Test:

Site ID:	355877
Spill Tank Test:	1549528
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Q125 **542 MAIN STREET LLC** **NY UST** **U003917838**
South **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
728 ft. **Site 14 of 15 in cluster Q**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800617 / Active
Operator Name:	Cornell Pace Inc.
Owner Name:	542 Main Street LLC
Owner Street:	542 Main Street, 2nd Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1904
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	2. Rubber liner
Tank External Protection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

S126 **NEW ROCHELLE PUBLIC LIBRARY** **NY UST** **U004177022**
SE **ONE LIBRARY PLAZA** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
730 ft. **Site 2 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-601216 / Active
Operator Name:	Thomas Geoffino
Owner Name:	New Rochelle Public Library
Owner Street:	One Library Plaza
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	LIB 1
Status:	1. In-Service
Capacity:	10000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

L127 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016677331**
North **NORTH ST & GARDEN ST** **NY MANIFEST** **NYP004309076**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
732 ft. **Site 6 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/08/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	NORTH ST & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004309076
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/08/2013
Site name:	CON EDISON MANHOLE: 4175
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004309076
Country:	USA
Location Address 1:	NORTH AVE & GARDEN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2013
Trans1 Recv Date:	05/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004309076

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007655511JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

L128 **CON EDISON MANHOLE 4175** **RCRA NonGen / NLR** **1014918789**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004224085**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
732 ft. **Site 7 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/14/2011
Facility name:	CON EDISON MANHOLE 4175
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004224085
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2011
Site name:	CON EDISON MANHOLE 4175
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004224085
Country:	USA
Location Address 1:	NORTH AV & GARDEN ST
Location Address 2:	MH 4175
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-2757

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/15/2011
Trans1 Recv Date:	01/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224085
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Manifest Tracking Num:	007655781JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

L129 **CON EDISON MANHOLE: 4177** **RCRA NonGen / NLR** **1016451046**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004300836**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
732 ft. **Site 8 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/11/2013
Facility name:	CON EDISON MANHOLE: 4177
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004300836
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/11/2013
Site name:	CON EDISON MANHOLE: 4177
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004300836
Country: USA
Location Address 1: NORTH AVE C/O GARDEN ST
Location Address 2: MH 4177
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2013
Trans1 Recv Date: 04/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004300836
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 010707795JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

L130 **CON EDISON SERVICE BOX: 1539** **RCRA NonGen / NLR** **1016972589**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004463667**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.139 mi.
732 ft. **Site 9 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/11/2014
Facility name:	CON EDISON SERVICE BOX: 1539
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004463667
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/11/2014
Site name:	CON EDISON SERVICE BOX: 1539
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004463667
Country:	USA
Location Address 1:	NO AVE 48 AND 48 GARDEN ST
Location Address 2:	SB 1539
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/11/2014
Trans1 Recv Date: 03/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004463667
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 20
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012772800JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

L131 **CON EDISON MANHOLE: 20274** **RCRA NonGen / NLR** **1016677685**
North **NORTH AVE & GARDEN ST** **FINDS** **NYP004313615**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.139 mi.
732 ft. **Site 10 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/15/2013
Facility name: CON EDISON MANHOLE: 20274
Facility address: NORTH AVE & GARDEN ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004313615
Mailing address: VING PL, RM 828

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/15/2013
Site name: CON EDISON MANHOLE: 20274
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877390

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1016677685
Registry ID: 110058877390
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110058877390

L132 **CON EDISON - MANHOLE 1535** **RCRA-LQG** **1016451189**
North **GARDEN ST AND NORTH AVE** **NY MANIFEST** **NYP004302303**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
732 ft. **Site 11 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 1535
Facility address:	GARDEN ST AND NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004302303
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/17/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/17/2013
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 05/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Not a generator, verified

Date form received by agency: 04/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004302303
Country: USA
Location Address 1: GARDEN ST AND NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/17/2013
Trans1 Recv Date: 04/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2013

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004302303
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010456840JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

T133 **BLOOMINGDALE PARKING LOT** **NY UST** **U003884000**
South **554 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
734 ft. **Site 1 of 7 in cluster T**

Relative:
Higher

Actual:
102 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600330 / Unregulated: <1101 gal. PBS
Operator Name:	Mel Watson
Owner Name:	Fraydun Enterprises
Owner Street:	3 New York Plaza
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10004
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing

BLOOMINGDALE PARKING LOT (Continued) **U003884000**

Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	4. Closed - in place
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

R134 **BARON MANAGEMENT** **NY UST** **U004187277**
ESE **200 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
736 ft. **Site 3 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Id/Status:	3-167843 / Administratively Closed
Operator Name:	Segundo Tirado
Owner Name:	Ronald Rettner
Owner Street:	481 Main Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	03/05/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

BARON MANAGEMENT (Continued) **U004187277**

Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

S135 **BARCLAYS BANK OF NY/NA** **NY LTANKS** **S100140601**
SE **491 MAIN ST.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
749 ft. **Site 3 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	299548
Spill Number/Closed Date:	8905129 / 1991-03-25
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	1997-02-12
Spiller Name:	Not reported
Spiller Company:	BARCLAYS BANK OF NY/NA
Spiller Address:	604 BROAD HOLLOW RD.
Spiller City,St,Zip:	MELVILLE, NY 11747
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	242324
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 10/06/89: GND INC. (516) 933-1085 NAT MOSER: 1500 GAL #2 FAILED RETEST -.132GPH. TANK TO BE RELINED OR REPLACED. 03/25/91: TANK REMOVED. "
Remarks:	"NAT MOSER (TELECOM 8-23, 1615) WILL CALL BACK AFTER CONTACTING BARCLAYS AND REVIEWING OPTIONS. PETRO TITE 2K 4 GPH"

Material:

Site ID:	299548

BARCLAYS BANK OF NY/NA (Continued) **S100140601**

Operable Unit ID:	930451
Operable Unit:	01
Material ID:	445568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	299548
Spill Tank Test:	1535898
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

S136 **J P MORGAN CHASE BANK N.A.** **NY UST U003885235**
SE **491 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.142 mi.
749 ft. **Site 4 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-164372 / Active
Operator Name:	Domenick Margotta
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard
Owner Address2:	14th Floor
Owner City:	Jersey City
Owner State:	NJ
Owner Zipcode:	07310
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/05/1990
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing

J P MORGAN CHASE BANK N.A. (Continued) **U003885235**

Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-164372
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Domenick Margotta
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard
Owner Address2:	14th Floor
Owner City/State/Zip:	Jersey City, NJ 07310
Tank Number:	02
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	Not reported
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

S137 **NEW ROCHELLE PUBLIC LIBRARY** **NY LTANKS** **S105995872**
SE **1 LAWTON** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
751 ft. **Site 5 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	492304
Spill Number/Closed Date:	1311408 / Not Reported
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2015-10-16
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE PUBLIC LIBRARY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	ROB
Spiller Phone:	(914) 473-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	447251
DEC Memo:	"Tank failed with a dry leak. Will most likely be uncovering, repairing and retesting. WCDOH has been notified...mm 10-15-15 email update request sent to WCHD RDB 10-16-15 Wayne is handling and will forward an update"
Remarks:	""

Material:

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242328
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242331
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Tank Test:

Site ID:	492304
Spill Tank Test:	2495159
Tank Number:	1
Tank Size:	10000
Test Method:	21
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MBMASTRO
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

Site ID:	306611
Spill Number/Closed Date:	0201697 / 2002-09-18
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE LIBRARY
Spiller Address:	1 LAWTON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	FRANK GALLELO
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	274126
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST "

Material:

Site ID:	306611
Operable Unit ID:	852656
Operable Unit:	01
Material ID:	523107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	306611
Spill Tank Test:	1527134
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

N138 **CIOTTI RESIDENCE** **NY LTANKS S107788125**
NW **60 GRAND STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
752 ft. **Site 4 of 5 in cluster N**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Site ID:	332054
Spill Number/Closed Date:	0407555 / 2004-10-07
Spill Date:	2004-10-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2004-10-07
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-07
Spill Record Last Update:	2004-11-01
Spiller Name:	ROB HILL
Spiller Company:	RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 579-3414
Spiller Extention:	Not reported

CIOTTI RESIDENCE (Continued) **S107788125**

DEC Region: 3
DER Facility ID: 267201
DEC Memo: ""
Remarks: "TRUCK DIRVER OVERFILLED AND BLEW A LINE. CREWS ARE IN ROUTE."

Material:
Site ID: 332054
Operable Unit ID: 1094311
Operable Unit: 01
Material ID: 574419
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

SPILLS:
Facility ID: 0602271
Facility Type: ER
DER Facility ID: 267201
Site ID: 364705
DEC Region: 3
Spill Date: 2006-05-31
Spill Number/Closed Date: 0602271 / 2007-02-16
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-05-31
CID: 444
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-31
Spill Record Last Update: 2007-02-16
Spiller Name: ROBERT CIOTTI
Spiller Company: CIOTTI RESIDENCE
Spiller Address: 60 GRAND STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: ROBERT CIOTTI

CIOTTI RESIDENCE (Continued) **S107788125**

Contact Phone: (914) 479-8680
DEC Memo: ""
Remarks: "TESTED THE REMOTE FILL PIPE AND FOUND IT NOT WORKING: 02/15/07 Northeast Envoronmental reported that they excavated 12.31 tons of petroleum impacted soil. NFA TG"

Material:
Site ID: 364705
Operable Unit ID: 1122726
Operable Unit: 01
Material ID: 2112202
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0601618
Facility Type: ER
DER Facility ID: 267201
Site ID: 363896
DEC Region: 3
Spill Date: 2006-05-12
Spill Number/Closed Date: 0601618 / 2006-11-07
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-05-12
CID: 408
Water Affected: STORM DRAINS ON GRAN
Spill Source: Private Dwelling
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-12
Spill Record Last Update: 2006-11-07
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: WAYNE SCHNEIDER
Contact Phone: (914) 813-5972

CIOTTI RESIDENCE (Continued) **S107788125**

DEC Memo: "05/12/06 Friday Stefan Goreau reported from the field that the spilled oil resembled motor oil rather than fuel oil, so he doesn't believe that the spill came from the residence. Northeast Environmental was called by the homeowner to do the cleanup but now the homeowner is not considered the RP. Since rain is imminent and Northeast has a vac truck on site, NE was advised to pump the oil out of the drains. DEC to pick up the expense. TG 11/07/06 IRS completed. TG"
Remarks: "CAUSE IS EITHER TANK OVERFILL OR CHECK VALVE FAILURE."

Material:
Site ID: 363896
Operable Unit ID: 1121950
Operable Unit: 01
Material ID: 2111430
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

O139 **MR CHIMNEY CLEAN** **RCRA NonGen / NLR** **1004758604**
SSW **32 RELYEA PL** **FINDS** **NYD987011855**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.144 mi. **ECHO**
758 ft. **Site 4 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MR CHIMNEY CLEAN
Facility address: 32 RELYEA PL
NEW ROCHELLE, NY 10801
EPA ID: NYD987011855
Mailing address: RELYEA PL
NEW ROCHELLE, NY 10801
Contact: MAURICE MCKENNA
Contact address: RELYEA PL
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 632-6660
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NAUAL MOTION PICTURES
Owner/operator address: 270 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US

MR CHIMNEY CLEAN (Continued) **1004758604**

Owner/operator telephone: (914) 632-2406
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NAUAL MOTION PICTURES
Owner/operator address: 270 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-2406
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MR CHIMNEY CLEAN
Classification: Not a generator, verified

Date form received by agency: 06/01/1994
Site name: MR CHIMNEY CLEAN
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004493922

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

MR CHIMNEY CLEAN (Continued) **1004758604**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD987011855
Country:	USA
Location Address 1:	270 MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NAVAL MOTION PICTURE SERVICE
Contact:	PAUL RAMOS
Address:	270 MAIN ST
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	000-000-0000

Manifest:

Document ID:	CTF0276746
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/1994
Trans1 Recv Date:	06/23/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/27/1994
Part A Recv Date:	/ /
Part B Recv Date:	07/11/1994
Generator EPA ID:	NYD987011855
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported
TSDF ID:	CTD000604488
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

ECHO:

Envid:	1004758604
Registry ID:	110004493922
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004493922

Q140 **NEW ROCHELLE SUPERMARKET CORP.** **NY AST** **A100204374**
SSE **538 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.146 mi.
770 ft. **Site 15 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. AST:

PBS Number:	3-166995
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Andrew Taveras
Owner Name:	New Rochelle Supermarket Corp.
Owner Street:	538 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/09/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

T141 **HANGERS CLEANERS** **NY DRYCLEANERS** **S110246761**
South **562-564 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.147 mi.
777 ft. **Site 2 of 7 in cluster T**

Relative:
Higher

Actual:
102 ft.

DRYCLEANERS:

Facility ID:	3-5510-00358
Phone Number:	914-235-0300
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	04MAR23
Install Date:	02
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	CO2
Current Business:	Not reported

S142 **ADREAN PRINTING CO** **RCRA NonGen / NLR** **1004755683**
SE **490 MAIN ST** **FINDS** **NY0000233981**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.147 mi. **ECHO**
778 ft. **Site 6 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ADREAN PRINTING CO
Facility address:	490 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NY0000233981
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	MICHAEL GOLDBERGER
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 636-0200
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 636-0200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 636-0200
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

ADREAN PRINTING CO (Continued) **1004755683**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ADREAN PRINTING CO
Classification: Not a generator, verified

Date form received by agency: 04/21/1994
Site name: ADREAN PRINTING CO
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004314297

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NY0000233981
Country: USA
Location Address 1: 490 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: ADREAN PRINTING
Contact: WILLIAM C WHITE
Address: 490 MAIN ST
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-636-0200

Manifest:

Document ID: NYB8521299
Manifest Status: Completed copy
Trans1 State ID: PW2414

ADREAN PRINTING CO (Continued) **1004755683**

Trans2 State ID:	Not reported
Generator Ship Date:	01/16/1997
Trans1 Recv Date:	01/16/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/16/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/31/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYG0919566
Manifest Status:	Completed copy
Trans1 State ID:	PW2414
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/28/1997
Part A Recv Date:	/ /
Part B Recv Date:	09/19/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYB6575904
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/1994
Trans1 Recv Date:	11/11/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/11/1994
Part A Recv Date:	11/21/1994
Part B Recv Date:	12/05/1994
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769

ADREAN PRINTING CO (Continued) **1004755683**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1994

Document ID:	NYB7902711
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	05/25/1995
Trans1 Recv Date:	05/25/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/25/1995
Part A Recv Date:	06/16/1995
Part B Recv Date:	06/07/1995
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	NYB7750935
Manifest Status:	Completed copy
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/1996
Trans1 Recv Date:	04/16/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/16/1996
Part A Recv Date:	05/01/1996
Part B Recv Date:	05/03/1996
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

ADREAN PRINTING CO (Continued) **1004755683**

Year: 1996

ECHO:
Envid: 1004755683
Registry ID: 110004314297
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004314297

O143 **PRO AUTO PARTS** **RCRA NonGen / NLR** **1001079946**
SW **41 REYLEA PL** **FINDS** **NYR000016535**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.148 mi. **ECHO**
780 ft. **Site 5 of 10 in cluster O**

Relative:
Higher

Actual:
87 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: PRO AUTO PARTS
Facility address: 41 REYLEA PL
NEW ROCHELLE, NY 108016918
EPA ID: NYR000016535
Mailing address: SUMMERFIELD ST
SCARSDALE, NY 10853
Contact: Not reported
Contact address: SUMMERFIELD ST
SCARSDALE, NY 10853
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PRO AUTO PARTS CORP
Owner/operator address: 135 SUMMER FIELD ST
SCARSDALE, NY 10853
Owner/operator country: US
Owner/operator telephone: (914) 772-4871
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PRO AUTO PARTS CORP
Owner/operator address: 135 SUMMER FIELD ST
SCARSDALE, NY 10853
Owner/operator country: US
Owner/operator telephone: (914) 772-4871
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

PRO AUTO PARTS (Continued) **1001079946**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 11/16/1995
Site name: PRO AUTO PARTS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

FINDS:

Registry ID: 110004520377

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000016535
Country: USA
Location Address 1: 41 REYLEA PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY

PRO AUTO PARTS (Continued) **1001079946**

Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: PRO AUTO PARTS
Contact: PHILIP A MORRIS JR
Address: 135 SUMMERFIELD ROAD
City/State/Zip: SCARSDALE, NY 10583
Country: USA
Phone: 914-793-3336

Manifest:

Document ID: NYB7350417
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 12/21/1995
Trans1 Recv Date: 12/21/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 12/21/1995
Part A Recv Date: 01/05/1996
Part B Recv Date: 01/03/1996
Generator EPA ID: NYR000016535
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00130
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 089
Year: 1995

ECHO:
Envid: 1001079946
Registry ID: 110004520377
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004520377

U144 **NYS THRUWAY AUTH** **RCRA NonGen / NLR** **1000553909**
North **THRUWAY BRIDGE MP 605.75** **NY MANIFEST** **NYD986963445**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.148 mi.
784 ft. **Site 1 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYS THRUWAY AUTH
Facility address: THRUWAY BRIDGE MP 605.75
NEW ROCHELLE, NY 10801
EPA ID: NYD986963445
Mailing address: S BROADWAY
TARRYTOWN, NY 105915697
Contact: Not reported
Contact address: S BROADWAY

NYS THRUWAY AUTH (Continued) **1000553909**

TARRYTOWN, NY 105915697
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYS THRUWAY AUTH
Owner/operator address: PO BOX 189
ALBANY, NY 12201
Owner/operator country: US
Owner/operator telephone: (518) 436-2811
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYS THRUWAY AUTH
Owner/operator address: PO BOX 189
ALBANY, NY 12201
Owner/operator country: US
Owner/operator telephone: (518) 436-2811
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 02/19/1992

NYS THRUWAY AUTH (Continued) **1000553909**

Site name: NYS THRUWAY
Classification: Large Quantity Generator

Date form received by agency: 07/12/1991
Site name: NYS THRUWAY AUTH
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986963445
Country: USA
Location Address 1: I-95 NORTH & NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: NEW YORK STATE THRUWAY AUTHORITY
Contact: NEW YORK STATE THRUWAY AUTHORITY
Address: 333 SOUTH BROADWAY
City/State/Zip: TARRYTOWN, NY 10591
Country: USA
Phone: 000-000-0000

Manifest:

Document ID: MIA2285792
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: MI5808
Trans2 State ID: Not reported
Generator Ship Date: 04/23/1992
Trans1 Recv Date: 04/23/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 04/24/1992
Part A Recv Date: / /
Part B Recv Date: 06/02/1992
Generator EPA ID: NYD986963445
Trans1 EPA ID: PAD064375470
Trans2 EPA ID: Not reported
TSDF ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1992

NYS THRUWAY AUTH (Continued) **1000553909**

Document ID:	MIA2540754
Manifest Status:	Completed copy
Trans1 State ID:	5825
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/1992
Trans1 Recv Date:	05/26/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/27/1992
Part A Recv Date:	/ /
Part B Recv Date:	06/16/1992
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	PAD064375470
Trans2 EPA ID:	Not reported
TSDF ID:	MID000724831
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1992

Document ID:	NJA1042129
Manifest Status:	Completed copy
Trans1 State ID:	46403ANY
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/1991
Trans1 Recv Date:	08/06/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1991
Part A Recv Date:	/ /
Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	22400
Units:	P - Pounds
Number of Containers:	028
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1042128
Manifest Status:	Completed copy
Trans1 State ID:	S7246
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/1991
Trans1 Recv Date:	08/06/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1991
Part A Recv Date:	/ /

NYS THRUWAY AUTH (Continued) **1000553909**

Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	32800
Units:	P - Pounds
Number of Containers:	041
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1042127
Manifest Status:	Completed copy
Trans1 State ID:	39413BNY
Trans2 State ID:	Not reported
Generator Ship Date:	08/02/1991
Trans1 Recv Date:	08/02/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/02/1991
Part A Recv Date:	/ /
Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	040
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

V145 **FIRST METRO SERVICES** **RCRA NonGen / NLR** **1004759815**
SSW **357 HUGONOT ST** **FINDS** **NYR000022053**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.149 mi.
787 ft. **Site 1 of 5 in cluster V**

Relative:
Higher

Actual:
92 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FIRST METRO SERVICES
Facility address:	357 HUGONOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYR000022053
Mailing address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact:	BILL LIVANOS
Contact address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact country:	US
Contact telephone:	(914) 576-7210
Contact email:	Not reported

FIRST METRO SERVICES (Continued) **1004759815**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: (914) 632-9692
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: (914) 632-9692
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FIRST METRO SERVICES
Classification: Not a generator, verified

Date form received by agency: 04/09/1996
Site name: FIRST METRO SERVICES
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D006
. Waste name: CADMIUM

FIRST METRO SERVICES (Continued) **1004759815**

Violation Status: No violations found

FINDS:

Registry ID: 110004523882

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1004759815
Registry ID: 110004523882
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004523882

N146 **GUIDANCE CENTER INC** **NY LTANKS** **S102556009**
NW **70 GRAND ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.149 mi.
789 ft. **Site 5 of 5 in cluster N**

Relative:
Lower

Actual:
80 ft.

LTANKS:
Site ID: 77017
Spill Number/Closed Date: 9613894 / 1997-10-03
Spill Date: 1997-02-26
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-02-26
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1997-02-26
Spill Record Last Update: 1997-10-22
Spiller Name: STEVEN SMITH
Spiller Company: GUIDANCE CENTER INC
Spiller Address: 70 GRAND ST
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: STEVEN SMITH
Spiller Phone: (914) 636-4440
Spiller Extention: 250
DEC Region: 3

GUIDANCE CENTER INC (Continued) **S102556009**

DER Facility ID: 71920
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/03/97 LETTER SENT; BASED ON TANK REMOVAL REPORT, NFA; "
Remarks: "OLD GASOLINE TANK FOUND UNDER THE GROUND - FOUND CONTAMINATED SOIL PHASE 2 COMPLETED - NO REMEDATION STARTED OWNER OF PROPERTY WILL AWAIT DIRECTION FROM DEC ABOUT TANK REMOVAL"

Material:
Site ID: 77017
Operable Unit ID: 1041477
Operable Unit: 01
Material ID: 339001
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

T147 **CENTRE MAIN EQUITIES LLC** **NY UST U004176186**
South **573-579 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.150 mi.
793 ft. **Site 3 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800238 / Active
Operator Name: Pedro Benoit
Owner Name: Centre Main Equities LLC
Owner Street: 542 Main Street, 2nd Floor
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron

CENTRE MAIN EQUITIES LLC (Continued) **U004176186**

Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

WESTCHESTER CO. AST:
PBS Number: 3-800238
Site Status: Active
GDS Number: Not reported
Operator Name: Pedro Benoit
Owner Name: Centre Main Equities LLC
Owner Street: 542 Main Street, 2nd Floor
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 001
Status: 1. In-Service
Date Installation: 09/01/2004
Capacity: 2000
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 6. Aboveground in subterranean vault with access for inspections
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating,99. Other
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 0. None
Dispenser: 2. Suction

T148 **CENTRE-MAIN ASSOCIATES** **NY LTANKS** **S106123770**
South **75 - 77 CENTER AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.152 mi.
802 ft. **Site 4 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

LTANKS:
Site ID: 149369
Spill Number/Closed Date: 0311823 / 2004-12-30
Spill Date: 2004-01-21
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: WESTCHESTER CNTY HEALTH D

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

Reported to Dept:	2004-01-21
CID:	44
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2005-01-10
Spiller Name:	ED
Spiller Company:	Not reported
Spiller Address:	75 - 77 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ED
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127066
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 1/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson, WCDOH dated 30Dec2004. WCDOH requires NFA at this time."
Remarks:	"recommend, uncover repair and retest. Tank is bolted in basement."

Material:

Site ID:	149369
Operable Unit ID:	877137
Operable Unit:	01
Material ID:	497066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	149369
Spill Tank Test:	1528926
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

O149 **INDUST OVERALL SERVICE CORP** **NY LTANKS** **S116555778**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.153 mi.
806 ft. **Site 6 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

LTANKS:

Site ID:	494186
Spill Number/Closed Date:	1400928 / Not Reported
Spill Date:	2014-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	ELMOORE
Referred To:	Not reported
Reported to Dept:	2014-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-04-28
Spill Record Last Update:	2014-06-19
Spiller Name:	BOB OBRIEN
Spiller Company:	INDUSTRIAL OVERALL SERV CORP
Spiller Address:	10 BARTELL PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	BOB OBRIEN
Spiller Phone:	(914) 235-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449117
DEC Memo:	"4-28-14: Chris/WCHD call to Dispt./V.Mc.: Heating oil tank, out of service, failed test."
Remarks:	"tank 2 5000 gallon"

Material:

Site ID:	494186
Operable Unit ID:	1243715
Operable Unit:	01
Material ID:	2244419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Tank Test:

Site ID:	494186
Spill Tank Test:	2495577
Tank Number:	1
Tank Size:	4000
Test Method:	99
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v
Site ID:	494186
Spill Tank Test:	2495578
Tank Number:	2
Tank Size:	5000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

O150 **INDUSTRIAL OVERALL SERVICE CORP.** **NY UST** **U004176640**
SW **10 BARTELLS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 7 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

WESTCHESTER CO. UST:

Id/Status:	3-025453 / Unregulated
Operator Name:	Robert O'Brien
Owner Name:	Industrial Overall Service Corp.
Owner Street:	10 Bartels Place
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	4000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	03/11/2003
Tank Location:	5. Underground
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **U004176640**

Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1980
Date Perm Closure:	08/26/2014
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	0. None

O151 **INDUSTRIAL OVERALL SERVICE CORP** **RCRA NonGen / NLR** **1016678149**
SW **10 BARTELS PL** **FINDS** **NYR000208967**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.153 mi. **ECHO**
806 ft. **Site 8 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/09/2014
Facility name:	INDUSTRIAL OVERALL SERVICE CORP
Facility address:	10 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000208967
Mailing address:	BARTELS PL NEW ROCHELLE, NY 10801
Contact:	ROBERT R OBRIEN
Contact address:	BUSHNELL ST ESSEX, CT 06426
Contact country:	US
Contact telephone:	(914) 235-1220
Contact email:	BOB@LINENGUY.COM
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/01/1950
Owner/Op end date: Not reported

Owner/operator name: INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address: BARTELS PL
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 235-1220
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/23/2010
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Historical Generators:
Date form received by agency: 03/31/2014
Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Small Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/14/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 12000

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Paid penalty amount: 12000

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 04/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 10000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/31/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/08/2014
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/01/2014
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Listing - General
Date achieved compliance: 07/08/2014
Evaluation lead agency: State

Evaluation date: 03/18/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 07/08/2014
Evaluation lead agency: State

FINDS:

Registry ID: 110058881152

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000208967
Country:	USA
Location Address 1:	10 BARTELS PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Contact:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address:	10 BARTELS PL
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	7500
Units:	P - Pounds
Number of Containers:	15
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/09/2015
Trans1 Recv Date: 04/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/09/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200
Units: P - Pounds
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 000959895GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/26/2015
Trans1 Recv Date: 01/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/26/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 700
Units: P - Pounds

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 010914098JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/29/2015
Trans1 Recv Date: 10/29/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/29/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 800
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014168256JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014168256JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2014
Trans1 Recv Date:	06/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	32440
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133085JJK

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	05/14/2014
Trans1 Recv Date:	05/14/2014
Trans2 Recv Date:	05/19/2014
TSD Site Recv Date:	05/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	6000
Units:	P - Pounds
Number of Containers:	3
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007176740FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2014
Trans1 Recv Date:	06/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	39860
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133084JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2014
Trans1 Recv Date:	06/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	40340
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133058JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	38940
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133056JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Waste Code:	Not reported
Quantity:	30
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133055JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2014
Trans1 Recv Date:	06/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	39060
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013132604JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	38380
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133054JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	7500
Units:	P - Pounds
Number of Containers:	15
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2015
Trans1 Recv Date:	01/26/2015

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	010914098JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1016678149
Registry ID:	110058881152
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058881152

O152 **INDUSTRIAL OVERALL SERVICE CORP.** **NY SHWS** **S110043643**
SW **10 BARTELS PLACE** **NY CBS** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 9 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

SHWS:

Program:	HW
Site Code:	413917
Classification:	Significant threat to the public health or environment - action required.
Region:	3
Acres:	0.42
HW Code:	360109
Record Add:	05/15/2009
Record Upd:	09/18/2015
Updated By:	DACROSBY

Site Description: Location: The Industrial Overall Service Corporation site is located at 10 Bartels Place in the City of New Rochelle, Westchester County, NY. The site is located east of I-95 and west of US-1 (Huguenot Street) and it is bounded by Reylea Place, Bartels Place, Centre Avenue and the Metro North railroad property and tracks. Site Features: The site is 0.42 acres in size and resides on a slightly

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

sloping irregularly shaped parcel. The main site feature includes a six-sided building which occupies the majority of the property and a small parking area located to the south and southwest of the building. The surrounding area is urban with a mix of commercial and residential establishments mixed in between the commercial businesses. Current Zoning/ Uses: This property is zoned for commercial use. The building is the location of two active businesses, Workingmans Closet and Apparel +Plus. The Workingmans Closet business uses the business address of 27 Centre Street. Historic Uses: Industrial Overall Services has been operating at the current location as a uniform and industrial clothing laundering facility, historically cleaning heavily soiled clothing from auto body and gasoline dispensing businesses since 1939. Based on a Sanborn Fire Insurance Map form 1931, the site previously operated as an automobile garage. In 1980, Workingmans Closet which sells new and reclaimed work clothes, was opened, and a dry cleaning facility operated there for a short time in the same decade. Today, Workingmans Closet launders linens and uniforms for restaurants and other businesses, and Apparel +Plus is a retail uniform business. Laundry operations on the site have used various cleaning products in the past. A remedial investigation conducted at the site has measured high concentrations of the dry cleaning chemical tetrachloroethylene (PCE) and its degradation products which is migrating from two sources: the subsurface lint trap located within the site building, and a debris and waste disposal area on the ground surface on site and on the adjacent Metro North Railroad property. Contamination migrating from these sources has impacted groundwater in the bedrock and overburden aquifers and has developed a plume extending downgradient (southwest) from the site over 1900 feet, as well as the bedrock itself.Site Geology and Hydrology: Groundwater is found in the overburden and in the bedrock. Groundwater is generally found 10 to 15 feet below ground surface and flows in a southwesterly direction. Overburden in the vicinity ranges in thickness from 2.2 feet to 32 feet, and consists of fill material (1-5 feet in thickness) and varied amounts of fine to coarse sand with varying amounts of silt. Deeper overburden is described as having till-like characteristics (higher density, well consolidated, and lower moisture content). Bedrock in the vicinity is a highly weathered gneissic/schistosic rock which is undulating in nature and is generally more transmissive than the till-like overburden material directly above.

Env Problem: Nature and Extent of Contamination: The primary contaminants of concern at the site include tetrachloroethylene (PCE) and its associated breakdown products. PCE was detected in groundwater at the site and downgradient off-site. On-site PCE in groundwater was noted at greater than 5,300 parts per billion (ppb) in site. The levels of PCE appear to diminish from the 1,000's of ppb of PCE to non detectable approximately 1000 feet to the southwest of the site. However, a high (PCE) concentration of 200 ppm was documented by within the adjoining Metro North railway property. Trichloroethylene (TCE) and TCA, were also detected in the groundwater both downgradient and on the site. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. No significant environmental resources have been identified near the site. Significant Threat: The site presents a significant threat to the environment and a potential threat to human health due to the ongoing release of contamination from the site and from adjoining

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Metro North property into groundwater and soil vapor.

Health Problem: Direct contact with contaminants in groundwater is unlikely because the area is served by an uncontaminated public water supply. While the majority of the site is covered with buildings and pavement, trespassers or employees may come in direct contact with some contaminated surficial soils on site and on the adjacent Metro North Railroad property. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion (SVI). Inhalation of site contaminants in indoor air due to soil vapor intrusion is unknown because the on-site building is an active laundry facility. However, an evaluation to determine the potential for soil vapor intrusion to occur, will be needed should the current site use of the building or chemical use change in the future. Sub-slab depressurization systems have been installed in two off-site buildings to prevent the inhalation of site-related contamination. In addition, air monitoring is on-going at four additional off-site buildings to verify further actions are not needed. Sampling indicates soil vapor intrusion may be a concern for additional off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: UNKNOWN
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 6/11/2009 3:11:00 PM
Record Upd: 8/10/2015 11:09:00 AM
Updated By: KATHOMPS
Own Op: On-Site Operator
Sub Type: 08
Owner Name: Robert R. O'Brien
Owner Company: Apparel + Plus Textile Rental, LLC
Owner Address: 27 Centre Avenue/10 Bartells Place
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: ROBERT O'BRIEN
Owner Company: WORKING MAN'S CLOSET, INC
Owner Address: 3 KOLBERT DRIVE
Owner Addr2: Not reported
Owner City,St,Zip: SCARSDALE, NY 10583

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Region 3 Headquarters
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	21 South Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Mr Burton Dorfman, Esq.
Owner Company:	Industrial Overall Services, Inc.(IOS)
Owner Address:	10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	360109
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	360087
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	5/21/2009 3:07:00 PM
Record Updated:	5/21/2009 3:07:00 PM
Updated By:	RXKEATIN
Crossref ID:	1309988
Cross Ref Type Code:	01

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Cross Ref Type: Spill No.
Record Added Date: 4/14/2014 11:03:00 AM
Record Updated: 4/14/2014 11:03:00 AM
Updated By: RDBENDEL
Crossref ID: 1310684
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/14/2014 8:19:00 AM
Record Updated: 2/14/2014 8:19:00 AM
Updated By: ELMOORE

CBS:
CBS Number: 3-000235
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 3
UTMX: 602235.14737
UTMY: 4529262.58924

O153 **INDUSTRIAL OVERALL** **NY CBS AST** **S105455801**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 10 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

R154 **RETTNER MANAGEMENT CORP** **NY UST** **U004177201**
SE **481 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
816 ft. **Site 4 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:
Id/Status: 3-255033 / Active
Operator Name: Arnoldo Diaz
Owner Name: Rettner Main Street, LLC
Owner Street: 374 McLean Avenue
Owner Address2: Not reported
Owner City: Yonkers
Owner State: NY
Owner Zipcode: 10705
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 3000
Product Stored: 7. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 09/01/2002
Tank Location: Not reported
Tank Type: 1. Steel/Carbon steel/Iron

RETTNER MANAGEMENT CORP (Continued) **U004177201**

Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/01/1970
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

T155 **CON EDISON TRANSFORMER MANHOLE: 2750** **RCRA NonGen / NLR** **1016677840**
South **CENTRE AVE & MAIN ST** **FINDS** **NYP004315198**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.155 mi. **ECHO**
821 ft. **Site 5 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/21/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2750
Facility address:	CENTRE AVE & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004315198
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2750
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058871369

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004315198
Country: USA
Location Address 1: CENTRE ST & MAIN
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/2013
Trans1 Recv Date:	05/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004315198
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007019053JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

Envid:	1016677840
Registry ID:	110058871369
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058871369

T156 **CON EDISON** **NY MANIFEST** **S117318285**
South **MAIN ST & CENTRE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
821 ft. **Site 6 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

EPA ID:	NYP004658019
Country:	USA
Location Address 1:	MAIN ST & CENTRE ST
Location Address 2:	MH734
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON

CON EDISON (Continued) **S117318285**

Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/16/2014
Trans1 Recv Date: 09/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/19/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004658019
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012771786JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

T157 **CON ED** **NY MANIFEST** **S118088511**
South **CENTRE AVE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
821 ft. **Site 7 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:
EPA ID: NYP004760815
Country: USA
Location Address 1: CENTRE AVE & MAIN ST
Location Address 2: TM 2750
Location City: NEW ROCHELLE
Location State: NY

CON ED (Continued) **S118088511**

Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/31/2015
Trans1 Recv Date: 03/31/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004760815
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091694JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/31/2015
Trans1 Recv Date: 03/31/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2015

CON ED (Continued) **S118088511**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760815
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091694JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

158
NNW
1/8-1/4
0.157 mi.
827 ft.

RITZCOVAN - TTF **NY LTANKS** **S118263505**
22 BURLING LANE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	514123
Spill Number/Closed Date:	1506693 / Not Reported
Spill Date:	2015-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2015-10-09
Spiller Name:	Not given

RITZCOVAN - TTF (Continued) **S118263505**

Spiller Company:	Ritzcovan (Owner)
Spiller Address:	22 BURLING LANE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	BRUCE
Spiller Phone:	9147120600
Spiller Extention:	1
DEC Region:	3
DER Facility ID:	468599
DEC Memo:	"9/24/15 Spoke to Bruce, the contact, who is trying to arrange tank removal, as he is tentatively purchasing the property from Ritzcovan. I gave him a list of contractors in Westchester. dw"
Remarks:	"unknown whether contaminated. option recover & repair, or remove; unknown at this time"

Material:

Site ID:	514123
Operable Unit ID:	1263331
Operable Unit:	01
Material ID:	2267021
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	514123
Spill Tank Test:	2498471
Tank Number:	Not reported
Tank Size:	275
Test Method:	NN
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	DXWEITZ
Last Modified:	Not reported
Test Method:	Testing Not Required

U159 **CON EDISON MANHOLE: 12245** **RCRA NonGen / NLR** **1016677186**
North **NORTH AVE & BURLING LANE** **FINDS** **NYP004307492**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.157 mi. **ECHO**
830 ft. **Site 2 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/06/2013
Facility name:	CON EDISON MANHOLE: 12245
Facility address:	NORTH AVE & BURLING LANE NEW ROCHELLE, NY 10801
EPA ID:	NYP004307492
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Contact: GINO FRABASILE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/06/2013
Site name: CON EDISON MANHOLE: 12245
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877531

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004307492
Country: USA
Location Address 1: NORTH AVE & BURLING LANE
Location Address 2: MH 12245
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10580
Location Zip Code 4: Not reported

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	05/07/2013
TSD Site Recv Date:	05/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307492
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	004816866FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1016677186
Registry ID:	110058877531
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058877531

W160 **CASARRA RESIDENCE** **NY LTANKS** **S105997517**
West **9 BADEAU PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.165 mi.
869 ft. **Site 1 of 4 in cluster W**

Relative:
Higher

Actual:
104 ft.

LTANKS:

Site ID:	157707
Spill Number/Closed Date:	0209171 / 2003-02-05
Spill Date:	2002-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-12-06
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-06
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	9 BADEAU PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SAL CASARRA
Spiller Phone:	(914) 235-0620
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/05/2003 Northeast Environmental removed the tank and reported that no contamination was present. NFA TG"
Remarks:	"uncover repair and retest"

Material:

Site ID:	157707
Operable Unit ID:	860605
Operable Unit:	01
Material ID:	516149
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CASARRA RESIDENCE (Continued) **S105997517**

Tank Test:

V161 **STORAGE USA** **NY UST** **U003949850**
SSW **363 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.165 mi.
869 ft. **Site 2 of 5 in cluster V**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801137 / Administratively Closed
Operator Name:	Narine Nathu
Owner Name:	SUSA Partnership, L.P.
Owner Street:	175 Toyota Plaza
Owner Address2:	Not reported
Owner City:	Memphis
Owner State:	TN
Owner Zipcode:	38103
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1934
Date Perm Closure:	03/15/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

X162 **DRIVE IT YOURSELF** **NY UST** **U004176354**
North **20 GARDEN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.175 mi.
922 ft. **Site 1 of 2 in cluster X**

Relative:
Lower

Actual:
71 ft.

WESTCHESTER CO. UST:

Id/Status:	3-494380 / Unregulated
Operator Name:	Drive It Yourself
Owner Name:	Ed;edward Jr;tim Tostanowski
Owner Street:	128 Saw Mill River Rd.
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701

DRIVE IT YOURSELF (Continued) **U004176354**

GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1974
Date Perm Closure:	02/01/1998
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Y163 **NYNEX** **NY LTANKS** **S100164268**
WNW **40 WASHINGTON AVE** **N/A**
1/8-1/4 **GREENBUSH, NY**
0.175 mi.
924 ft. **Site 1 of 4 in cluster Y**

Relative:
Higher

Actual:
112 ft.

LTANKS:

Site ID:	60528
Spill Number/Closed Date:	8803234 / 1988-07-22
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-07-22
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-07-22
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-28
Spill Record Last Update:	1988-09-07
Spiller Name:	Not reported
Spiller Company:	JOHN ALBARANO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

NYNEX (Continued) **S100164268**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 59075
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK PUMED OUT.TO BE REMOVED. "
Remarks: "#2FUEL 5K 1.842 / 4K .170 DIESEL"

Material:
Site ID: 60528
Operable Unit ID: 918404
Operable Unit: 01
Material ID: 458797
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 60528
Spill Tank Test: 1534290
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

Z164 **ROTH CLEANERS** **RCRA NonGen / NLR** **1000237840**
SSE **1 LEROY PL** **FINDS** **NYD078706686**
1/8-1/4 **NEW ROCHELLE, NY 10805** **NY DRYCLEANERS**
0.178 mi. **NY MANIFEST**
938 ft. **Site 1 of 2 in cluster Z** **ECHO**

Relative: Higher

Actual: 100 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ROTH CLEANERS
Facility address: 1 LEROY PL
NEW ROCHELLE, NY 10805
EPA ID: NYD078706686
Mailing address: LEROY PL
NEW ROCHELLE, NY 10805
Contact: BEN ROTH
Contact address: LEROY PL
NEW ROCHELLE, NY 10805
Contact country: US
Contact telephone: (914) 633-7114
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.

ROTH CLEANERS (Continued) **1000237840**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROTH CLEANERS
Classification: Not a generator, verified

Date form received by agency: 08/27/1986
Site name: ROTH CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE

ROTH CLEANERS (Continued) **1000237840**

USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - Manifest
- Date violation determined: 04/24/1987
- Date achieved compliance: 04/26/1987
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 04/24/1987
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 04/24/1987
- Evaluation: NON-FINANCIAL RECORD REVIEW
- Area of violation: Generators - Manifest
- Date achieved compliance: 04/26/1987
- Evaluation lead agency: State

FINDS:

Registry ID: 110004370369

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

DRYCLEANERS:
- Facility ID: 3-5510-00292
- Phone Number: 914-633-7114
- Region: Not reported
- Registration Effective Date: N/A
- Inspection Date: 09JUL16
- Install Date: 98
- Drop Shop: Not reported
- Shutdown: Y
- Alternate Solvent: Not reported
- Current Business: Not reported

ROTH CLEANERS (Continued) **1000237840**

NY MANIFEST:

EPA ID:	NYD078706686
Country:	USA
Location Address 1:	1 LEROY PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	ROTH CLEANERS
Contact:	ROTH CLEANERS
Address:	1 LEROY PLACE
City/State/Zip:	NEW ROCHELLE, NY 10805
Country:	USA
Phone:	914-633-7114

Manifest:

Document ID:	NYC6083291
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	03/08/2000
Trans1 Recv Date:	03/08/2000
Trans2 Recv Date:	03/09/2000
TSD Site Recv Date:	03/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6190896
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/23/2000
Trans1 Recv Date:	06/23/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

ROTH CLEANERS (Continued) **1000237840**

TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6133320
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	05/03/2000
Trans1 Recv Date:	05/03/2000
Trans2 Recv Date:	05/04/2000
TSD Site Recv Date:	05/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6038177
Manifest Status:	Not reported
Trans1 State ID:	NYCR2346
Trans2 State ID:	ILT104414
Generator Ship Date:	01/04/2000
Trans1 Recv Date:	01/04/2000
Trans2 Recv Date:	01/06/2000
TSD Site Recv Date:	01/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

ROTH CLEANERS (Continued) **1000237840**

Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC5558095
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	NJT913LY
Generator Ship Date:	03/02/1999
Trans1 Recv Date:	03/02/1999
Trans2 Recv Date:	03/04/1999
TSD Site Recv Date:	03/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5658401
Manifest Status:	Not reported
Trans1 State ID:	CR2436
Trans2 State ID:	T162VWNJ
Generator Ship Date:	06/22/1999
Trans1 Recv Date:	06/22/1999
Trans2 Recv Date:	06/25/1999
TSD Site Recv Date:	07/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

ROTH CLEANERS (Continued) **1000237840**

Document ID:	NYC5580404
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	NJT913LY
Generator Ship Date:	04/05/1999
Trans1 Recv Date:	04/05/1999
Trans2 Recv Date:	04/08/1999
TSD Site Recv Date:	04/14/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5849730
Manifest Status:	Not reported
Trans1 State ID:	NYC2436
Trans2 State ID:	T604414IL
Generator Ship Date:	07/20/1999
Trans1 Recv Date:	07/20/1999
Trans2 Recv Date:	07/22/1999
TSD Site Recv Date:	07/26/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5520780
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported

ROTH CLEANERS (Continued) **1000237840**

Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: CTF0671298
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 01/08/1998
Trans1 Recv Date: 01/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0680858
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 02/09/1998
Trans1 Recv Date: 02/09/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001

ROTH CLEANERS (Continued) **1000237840**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0688530
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: Not reported
Generator Ship Date: 03/06/1998
Trans1 Recv Date: 03/06/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0691573
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 03/30/1998
Trans1 Recv Date: 03/30/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/02/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0712380
Manifest Status: Not reported
Trans1 State ID: NYCR2436

ROTH CLEANERS (Continued) **1000237840**

Trans2 State ID:	Not reported
Generator Ship Date:	05/27/1998
Trans1 Recv Date:	05/27/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0722807
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	06/29/1998
Trans1 Recv Date:	06/29/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/01/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0723823
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1998
Trans1 Recv Date:	08/19/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/31/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202

ROTH CLEANERS (Continued) **1000237840**

Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5443334
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NYNJ
Generator Ship Date:	11/09/1998
Trans1 Recv Date:	11/09/1998
Trans2 Recv Date:	11/12/1998
TSD Site Recv Date:	11/20/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5478750
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NXNJ
Generator Ship Date:	12/10/1998
Trans1 Recv Date:	12/10/1998
Trans2 Recv Date:	12/14/1998
TSD Site Recv Date:	12/18/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

ROTH CLEANERS (Continued) **1000237840**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0622944
Manifest Status:	Completed copy
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/1997
Trans1 Recv Date:	05/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/05/1997
Part A Recv Date:	06/10/1997
Part B Recv Date:	06/19/1997
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	CTF0624862
Manifest Status:	Completed copy
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	04/29/1997
Trans1 Recv Date:	04/29/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/01/1997
Part A Recv Date:	05/13/1997
Part B Recv Date:	05/14/1997
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

ROTH CLEANERS (Continued) **1000237840**

ECHO:
Envid: 1000237840
Registry ID: 110004370369
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004370369

Z165 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243086**
SSE **DIVISION ST & LEROY PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.181 mi.
957 ft. **Site 2 of 2 in cluster Z**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:
EPA ID: NYP004124210
Country: USA
Location Address 1: DIVISION ST & LEROY PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: NYE1309986
Manifest Status: Not reported
Trans1 State ID: 46614JM
Trans2 State ID: Not reported
Generator Ship Date: 08/30/2004
Trans1 Recv Date: 08/30/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/30/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004124210
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00014
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

AA166
ESE
1/8-1/4
0.182 mi.
959 ft.

CON ED-V37
LECOUNT PL & MAIN ST
NEW ROCHELLE, NY 10801

Site 1 of 2 in cluster AA

NY MANIFEST **S109064681**
N/A

Relative:
Higher

Actual:
87 ft.

NY MANIFEST:

EPA ID:	NYP004027967
Country:	USA
Location Address 1:	LECOUNT PL & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	0000

Mailing Info:

Name:	CON ED-V37
Contact:	Not reported
Address:	Not reported
City/State/Zip:	Not reported
Country:	Not reported
Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

AA167
ESE
1/8-1/4
0.182 mi.
959 ft.

CON ED-V14
LECOUNT PL & MAIN ST
NEW ROCHELLE, NY 10801

Site 2 of 2 in cluster AA

NY MANIFEST **S109064677**
N/A

Relative:
Higher

Actual:
87 ft.

NY MANIFEST:

EPA ID:	NYP004028122
Country:	USA
Location Address 1:	LECOUNT PL & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	0000

Mailing Info:

Name:	CON ED-V14
Contact:	Not reported
Address:	Not reported
City/State/Zip:	Not reported
Country:	Not reported
Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

W168
West
1/8-1/4
0.183 mi.
964 ft.

RESIDENCE
18 BADEAU PLACE
NEW ROCHELLE, NY

Site 2 of 4 in cluster W

NY LTANKS **S102663947**
N/A

Relative:
Higher

Actual:
104 ft.

LTANKS:

Site ID:	177416
Spill Number/Closed Date:	9609269 / 1996-10-24
Spill Date:	1996-10-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-24
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-24
Spill Record Last Update:	1996-12-05
Spiller Name:	Not reported
Spiller Company:	JULIO VALER
Spiller Address:	18 BADEAU PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JULIO VALER
Spiller Phone:	(914) 636-8917
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149078
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED TOO MUCH OIL. SPILLED ONTO BLACKTOP DRIVEWAY. CLEANED UP."

Material:

Site ID:	177416
Operable Unit ID:	1037374
Operable Unit:	01
Material ID:	345000
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	5.00
Resource Affected:	Not reported
Oxygenate:	Not reported

RESIDENCE (Continued) **S102663947**

Tank Test:

AB169 **J B & FRANKS** **RCRA NonGen / NLR** **1000100357**
SW **27 BARTELS PL** **FINDS** **NYD986884732**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.185 mi. **ECHO**
977 ft. **Site 1 of 5 in cluster AB**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: J B & FRANKS
Facility address: 27 BARTELS PL
NEW ROCHELLE, NY 108016901
EPA ID: NYD986884732
Mailing address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact: Not reported
Contact address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

J B & FRANKS (Continued) **1000100357**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 12/01/1989
Site name: J B & FRANKS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004439705

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986884732
Country: USA
Location Address 1: 27 BARTELS PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10804
Location Zip Code 4: Not reported

Mailing Info:
Name: J B FRANKS
Contact: J B FRANKS
Address: 27 BARTELS PLACE
City/State/Zip: NEW ROCHELLE, NY 10804
Country: USA
Phone: 914-636-0570

J B & FRANKS (Continued) **1000100357**

Manifest:

Document ID:	NYA7038792
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	N23008
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/1989
Trans1 Recv Date:	12/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/07/1989
Part A Recv Date:	01/24/1990
Part B Recv Date:	12/18/1989
Generator EPA ID:	NYD986884732
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1989

ECHO:

Envid:	1000100357
Registry ID:	110004439705
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004439705

Y170 **ST GABRIEL SCHOOL** **NY LTANKS** **S105999147**
WNW **50 WASHINGTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.187 mi.
985 ft. **Site 2 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Site ID:	314440
Spill Number/Closed Date:	0302359 / 2003-12-12
Spill Date:	2003-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0

ST GABRIEL SCHOOL (Continued) **S105999147**

Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2003-12-12
Spiller Name:	LARRY
Spiller Company:	ST GABRIEL SCHOOL
Spiller Address:	50 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 12/12/03 ALSO REPORTED AS 03-05820. SEE THAT FILE FOR UPDATES. NFA THIS NUMBER."
Remarks:	""

Material:

Site ID:	314440
Operable Unit ID:	869188
Operable Unit:	01
Material ID:	506840
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	314440
Spill Tank Test:	1528429
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Y171 **SAINT GABRIEL HIGH SCHOOL** **NY UST** **U003994885**
WNW **50 WASHINGTON AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.187 mi.
985 ft. **Site 3 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

WESTCHESTER CO. UST:

Id/Status:	3-058122 / Active
Operator Name:	Lawrence Baker
Owner Name:	Church of St. Gabriel
Owner Street:	120 Division Street
Owner Address2:	Not reported

SAINT GABRIEL HIGH SCHOOL (Continued) **U003994885**

Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	09/02/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	09/01/2003
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	7. Jacketed (tank)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	10. Flexible Piping
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Y172 **50 WASHINTON AVE** **NY LTANKS** **S105999773**
WNW **50 WASHINTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.187 mi.
985 ft. **Site 4 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Site ID:	280324
Spill Number/Closed Date:	0305820 / 2003-12-23
Spill Date:	2003-09-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-09-02
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-02
Spill Record Last Update:	2004-01-08
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller County:	999
Spiller Contact:	MIGEL ROSARIO
Spiller Phone:	(914) 632-0211
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	227605
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 12/12/03 PREVIOUSLY REPORTED AS SPILL 03-02359. 12/26/03: Letter sent to Fr. Patrick V. McNamara, St Gabriel Church-Archdiocese NY from Wayne Schneider, WCDOH dated 23Dec2003. Closure report has been reviewed. WCDOH recommends NFAA at this time."
	Not reported
Remarks:	"ST GABRIELS CHURCH - FR PATRICK MCNAMARA WOULD LIKE A CALL HE CAN BE REACHED AT 914-632-0211 THE CHURCH IS RESPONSIBLE FOR THE SPILL "

Material:

Site ID:	280324
Operable Unit ID:	874264
Operable Unit:	01
Material ID:	503057
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

50 WASHINTON AVE (Continued) **S105999773**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

V173 **CON EDISON** **NY MANIFEST** **S117535594**
SSW **HUGENOT AVE & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 3 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:
EPA ID: NYP004677621
Country: USA
Location Address 1: HUGENOT AVE & COLUMBUS AVE
Location Address 2: MH 3424
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/15/2014
Trans1 Recv Date: 10/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677621
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012774907JJK
Import Ind: N

CON EDISON (Continued) **S117535594**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

V174 **CON EDISON** **NY MANIFEST** **S117536317**
SSW **HUGUENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.188 mi.
990 ft. **Site 4 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

EPA ID:	NYP004687802
Country:	USA
Location Address 1:	HUGUENOT ST & COLUMBUS AVE
Location Address 2:	MH 3424
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2014
Trans1 Recv Date:	10/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004687802
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117536317**

Year:	2014
Manifest Tracking Num:	012773160JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

V175 **CON EDISON** **NY MANIFEST** **S117535600**
SSW **HUGENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 5 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

EPA ID:	NYP004677837
Country:	USA
Location Address 1:	HUGENOT ST & COLUMBUS AVE
Location Address 2:	MH 3424
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677837
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S117535600**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774864JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

X176 **FURNITURE RESTORNATION CENTER** **RCRA NonGen / NLR** **1000872286**
NNE **26 GARDEN ST** **FINDS** **NYD987034998**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.188 mi. **ECHO**
993 ft. **Site 2 of 2 in cluster X**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FURNITURE RESTORNATION CENTER
Facility address:	26 GARDEN ST NEW ROCHELLE, NY 108014204
EPA ID:	NYD987034998
Mailing address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 633-9292
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Owner/operator telephone: (914) 633-9292
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 06/02/1993
Site name: FURNITURE RESTORNATION CENTER
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/02/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004505287

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD987034998
Country: USA
Location Address 1: 26 GARDEN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: FURNITURE RESTORATION OF NEW ROCHELLE
Contact: HENRY FLAVIC
Address: 166 WEBSTER AVE
City/State/Zip: NEW ROCHELLE, NY 10801 6111
Country: USA
Phone: 914-592-3132

Manifest:

Document ID: NYG1592532
Manifest Status: Not reported
Trans1 State ID: AE53110PA
Trans2 State ID: Not reported
Generator Ship Date: 07/06/2000
Trans1 Recv Date: 07/06/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: PAD987358587
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Quantity:	00935
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	017
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYG1592451
Manifest Status:	Not reported
Trans1 State ID:	AB92108PA
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/1999
Trans1 Recv Date:	12/29/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported
TSDF ID:	OHD066060609
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	MAK4973810
Manifest Status:	Not reported
Trans1 State ID:	MA14654
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/1998
Trans1 Recv Date:	06/10/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/10/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	SCD987574647
Trans2 EPA ID:	Not reported
TSDF ID:	MAD000604447
Waste Code:	F001 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F001 - UNKNOWN
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 016
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F001 - UNKNOWN
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: NYB7459911
Manifest Status: Not reported
Trans1 State ID: 50059
Trans2 State ID: Not reported
Generator Ship Date: 08/17/1999
Trans1 Recv Date: 08/17/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/27/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: NJD986607380
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00475
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 1999

Document ID: NYB7459101
Manifest Status: Not reported
Trans1 State ID: 50059
Trans2 State ID: Not reported
Generator Ship Date: 04/08/1999
Trans1 Recv Date: 04/08/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/14/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: NJD986607380

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Trans2 EPA ID:	Not reported
TSDF ID:	OHD980681571
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

ECHO:

Envid:	1000872286
Registry ID:	110004505287
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004505287

W177 **DIIORGI HOME** **NY LTANKS** **S106869098**
WSW **47 WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.189 mi.
999 ft. **Site 3 of 4 in cluster W**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	343230
Spill Number/Closed Date:	0500295 / 2005-08-28
Spill Date:	2005-04-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2005-08-28
Spiller Name:	ANTHONY DIIORGI
Spiller Company:	DIIORGI HOME
Spiller Address:	47 WARREN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

DIIORGI HOME (Continued) **S106869098**

Spiller Contact: ANTHONY DIIORGI
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 289715
DEC Memo: "August 28, 2005: GC RELIABLE REMOVED LUST AND CONTAMINATED SOIL. NORTHEST ENVIRONMENTAL DISPOSED OF 18 DRUMS OF SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "SHE WILL CALLL BACK WITH MORE INFO:"

Material:
Site ID: 343230
Operable Unit ID: 1101915
Operable Unit: 01
Material ID: 582154
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

U178 **CON EDISON MANHOLE: 4179** **RCRA NonGen / NLR 1016969613**
North **350 NORTH AVE** **NY MANIFEST NYP004432886**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1018 ft. **Site 3 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/04/2014
Facility name: CON EDISON MANHOLE: 4179
Facility address: 350 NORTH AVE
NEW ROCHELLE, NY 10805
EPA ID: NYP004432886
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/04/2014
Site name:	CON EDISON MANHOLE: 4179
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004432886
Country:	USA
Location Address 1:	OPP 350 NORTH AVE
Location Address 2:	MH4179
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004432886
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	011692716JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AB179 **CON EDISON** **RCRA NonGen / NLR** **1014398214**
SW **35 BARTELS PL** **NY MANIFEST** **NYP004205654**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.193 mi.
1020 ft. **Site 2 of 5 in cluster AB**

Relative:
Lower

Actual:
67 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2010
Facility name:	CON EDISON
Facility address:	35 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004205654
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	PATRICK HANLEY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(347) 203-1475
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON (Continued) **1014398214**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004205654
Country: USA
Location Address 1: 35 BARTELS PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/19/2010
Trans1 Recv Date: 04/19/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/19/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004205654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 15.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 002012659FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

CON EDISON (Continued) **1014398214**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

AB180 **CON EDISON** **NY MANIFEST** **S117741191**
SW **35 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 3 of 5 in cluster AB**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:
EPA ID: NYP004744074
Country: USA
Location Address 1: 35 BARTELS PL
Location Address 2: DRIP WATER
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/16/2015
Trans1 Recv Date: 03/16/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/18/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 3
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683647FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

CON EDISON (Continued) **S117741191**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683633FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2015
Trans1 Recv Date:	03/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939

CON EDISON (Continued) **S117741191**

Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683630FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2015
Trans1 Recv Date:	03/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	20
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683625FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

CON EDISON (Continued) **S117741191**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2015
Trans1 Recv Date:	03/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	2
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683620FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2015
Trans1 Recv Date:	03/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	4
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117741191**

Year:	2015
Manifest Tracking Num:	008683616FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683680FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/16/2015
Trans1 Recv Date:	03/16/2015

CON EDISON (Continued) **S117741191**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	3
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683647FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683633FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

CON EDISON (Continued) **S117741191**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/06/2015
Trans1 Recv Date: 03/06/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 1
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683630FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/05/2015
Trans1 Recv Date: 03/05/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S117741191**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	20
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683625FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2015
Trans1 Recv Date:	03/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	2
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683620FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117741191**

Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2015
Trans1 Recv Date: 03/10/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 4
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683616FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/28/2015
Trans1 Recv Date: 03/28/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/30/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 1
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1

CON EDISON (Continued) **S117741191**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683680FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

AC181 **BARRAGAN RESIDENCE** **NY LTANKS** **S105230135**
WSW **40 WARREN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.194 mi.
1022 ft. **Site 1 of 7 in cluster AC**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	150939
Spill Number/Closed Date:	0109254 / 2001-12-19
Spill Date:	2001-12-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2001-12-19
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-19
Spill Record Last Update:	2002-01-03
Spiller Name:	Not reported
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	MALLARDI RES
Spiller Phone:	(914) 636-7448
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128278
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "

BARRAGAN RESIDENCE (Continued) **S105230135**

Remarks: "DRIVER OVERFILLED TANK - SPILL CONTAINED WITH PADS - CLEAN UP CREW ENROUTE"

Material:

Site ID:	150939
Operable Unit ID:	846633
Operable Unit:	01
Material ID:	530463
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	409713
Spill Number/Closed Date:	0812107 / 2009-03-03
Spill Date:	2009-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-06
Spill Record Last Update:	2009-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	359905
DEC Memo:	"Piping failure, need to repair and retest - mm 02/20/2009 Passed retest results that came into PBS to J. O'Dee---BHY 3/3/09: Review of

BARRAGAN RESIDENCE (Continued) **S105230135**

report submitted by WCC Tank Technology. Tank was tested by WCC on 1-9-09 for the property owner. The tank passed the test and documentation was submitted to the owner and the New Rochelle FD. Elite Environmental tested the tank for a prospective buyer on 2-6-09 and failed the tank, resulting in this spill report to the DEC. On 2-12-09 WCC again tested the tank with reps from New Rochelle FD and Royal Environmental. The tank passed this test. All three tests were preformed with the Horner Locator Plus system. Based upon the information received as of this date, DEC is requiring No Further Action at this time. jod"

Remarks: "550 gal tank failed test/ failure due to bad fitting"

Material:

Site ID:	409713
Operable Unit ID:	1166213
Operable Unit:	01
Material ID:	2157665
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0908848
Facility Type:	ER
DER Facility ID:	128278
Site ID:	421508
DEC Region:	3
Spill Date:	2009-11-06
Spill Number/Closed Date:	0908848 / 2010-04-08
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-06

BARRAGAN RESIDENCE (Continued) **S105230135**

Spill Record Last Update:	2010-04-08
Spiller Name:	GABREILLE BARRAGAN
Spiller Company:	GABREILLE BARRAGAN
Spiller Address:	40 WARREN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	NIKKI RICKETTS
Contact Phone:	(914) 777-1930
DEC Memo:	"11/06/09: Property was purchased by a new owner within the past year. New owner passed away, his wife was having the tank replaced for sale of the property. Northeast installed a new AST in the basement and pulled this 1K tank. Contamination evident. New Rochelle FD inspected. Northeast will be completing clean up. jod 02/09/10 Northeast Environmental reported that they excavated and removed one tank along with 35.64 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG"
Remarks:	"REMOVAL OF A 1000 GALLON UST SOIL CONTAMINATION FOUND CLEAN UP PENDING."

Material:

Site ID:	421508
Operable Unit ID:	1177396
Operable Unit:	01
Material ID:	2170184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AD182 **CON EDISON TRANSFORMER MANHOLE: 5365** **RCRA NonGen / NLR** **1016972665**
SSW **595 MAIN ST** **NY MANIFEST** **NYP004464459**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.196 mi.
1035 ft. **Site 1 of 5 in cluster AD**

Relative:
Higher

Actual:
93 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/12/2014
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5365
Facility address:	595 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004464459
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/12/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 5365
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004464459
Country: USA
Location Address 1: 595 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10804
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/12/2014
Trans1 Recv Date: 03/12/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/12/2014

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004464459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012771156JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AB183 **RUSH MFG CORP** **RCRA NonGen / NLR** **1000238316**
SSW **18 COLUMBUS AVE** **FINDS** **NYD981185051**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.200 mi. **ECHO**
1054 ft. **Site 4 of 5 in cluster AB**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RUSH MFG CORP
Facility address:	18 COLUMBUS AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD981185051
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact:	DENNIS MCNAMARA
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 636-2700
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212

RUSH MFG CORP (Continued) **1000238316**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MATTHEW RUSH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MFG CORP
Classification: Not a generator, verified

Date form received by agency: 03/03/1986
Site name: RUSH MFG CORP
Classification: Small Quantity Generator

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Violation Status: No violations found

FINDS:

Registry ID: 110002092967

Environmental Interest/Information System
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource

RUSH MFG CORP (Continued) **1000238316**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD981185051
Country:	USA
Location Address 1:	381 HUGUENOT STREET
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	RUSH MANUFACTURING CORPORATION
Contact:	RUSH MANUFACTURING CORPORATION
Address:	381 HUGUENOT STREET
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-236-2700

Manifest:

Document ID:	NJA2751945
Manifest Status:	Completed copy
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1997
Trans1 Recv Date:	12/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1997
Part A Recv Date:	01/15/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYA3088056
Manifest Status:	Completed copy
Trans1 State ID:	18946GL
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1986
Trans1 Recv Date:	05/13/1986

RUSH MFG CORP (Continued) **1000238316**

Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/13/1986
Part A Recv Date:	05/30/1986
Part B Recv Date:	05/29/1986
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1986

Document ID:	NYB7226073
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PR8562NY
Trans2 State ID:	24269SNY
Generator Ship Date:	10/08/1996
Trans1 Recv Date:	10/08/1996
Trans2 Recv Date:	10/14/1996
TSD Site Recv Date:	10/21/1996
Part A Recv Date:	10/22/1996
Part B Recv Date:	11/14/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NYD013277454
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2295832
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	050060
Trans2 State ID:	50060
Generator Ship Date:	12/30/1996
Trans1 Recv Date:	12/30/1996
Trans2 Recv Date:	12/30/1996
TSD Site Recv Date:	01/16/1997
Part A Recv Date:	/ /
Part B Recv Date:	02/03/1997
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN

RUSH MFG CORP (Continued) **1000238316**

Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2539813
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/1996
Trans1 Recv Date:	04/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/30/1996
Part A Recv Date:	04/29/1996
Part B Recv Date:	05/15/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00508
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2505461
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/1996
Trans1 Recv Date:	07/17/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/22/1996
Part A Recv Date:	07/31/1996
Part B Recv Date:	08/06/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00421
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

RUSH MFG CORP (Continued) **1000238316**

Document ID:	NYC3879944
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/1996
Trans1 Recv Date:	02/12/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/21/1996
Part A Recv Date:	/ /
Part B Recv Date:	03/04/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	CTF0340411
Manifest Status:	Completed copy
Trans1 State ID:	ILP39038
Trans2 State ID:	Not reported
Generator Ship Date:	02/03/1995
Trans1 Recv Date:	02/03/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/06/1995
Part A Recv Date:	02/13/1995
Part B Recv Date:	02/15/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01018
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC2078559
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	P39038
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/1995
Trans1 Recv Date:	11/22/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/30/1995
Part A Recv Date:	12/08/1995

RUSH MFG CORP (Continued) **1000238316**

Part B Recv Date:	12/21/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	F001 - UNKNOWN
Quantity:	00844
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	CTF0477109
Manifest Status:	Completed copy
Trans1 State ID:	P188420
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/1995
Trans1 Recv Date:	07/27/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/03/1995
Part A Recv Date:	08/07/1995
Part B Recv Date:	08/18/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01018
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	CTF0477189
Manifest Status:	Completed copy
Trans1 State ID:	ILP39038
Trans2 State ID:	Not reported
Generator Ship Date:	05/05/1995
Trans1 Recv Date:	05/05/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1995
Part A Recv Date:	05/15/1995
Part B Recv Date:	05/19/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001

RUSH MFG CORP (Continued) **1000238316**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0476006
Manifest Status: Completed copy
Trans1 State ID: P39038IL
Trans2 State ID: Not reported
Generator Ship Date: 11/22/1995
Trans1 Recv Date: 11/22/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/27/1995
Part A Recv Date: 12/08/1995
Part B Recv Date: 12/12/1995
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01018
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0300971
Manifest Status: Completed copy
Trans1 State ID: P39038IL
Trans2 State ID: Not reported
Generator Ship Date: 06/03/1994
Trans1 Recv Date: 06/03/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 06/06/1994
Part A Recv Date: / /
Part B Recv Date: 06/17/1994
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01017
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1994

Document ID: CTF0341256
Manifest Status: Completed copy
Trans1 State ID: ILP39038

RUSH MFG CORP (Continued) **1000238316**

Trans2 State ID:	Not reported
Generator Ship Date:	11/04/1994
Trans1 Recv Date:	11/04/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/07/1994
Part A Recv Date:	11/14/1994
Part B Recv Date:	11/21/1994
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01017
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	CTF0232232
Manifest Status:	Completed copy
Trans1 State ID:	P39038ILL
Trans2 State ID:	T748NYNJ
Generator Ship Date:	12/16/1993
Trans1 Recv Date:	12/16/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/17/1993
Part A Recv Date:	12/27/1993
Part B Recv Date:	12/30/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD984908202
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01017
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1993

Document ID:	NJA1501495
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPES28
Trans2 State ID:	Not reported
Generator Ship Date:	09/07/1993
Trans1 Recv Date:	09/07/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/07/1993
Part A Recv Date:	10/22/1993
Part B Recv Date:	10/04/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544

RUSH MFG CORP (Continued) **1000238316**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1993

Document ID:	CTF0147909
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/1993
Trans1 Recv Date:	04/07/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/13/1993
Part A Recv Date:	04/26/1993
Part B Recv Date:	04/23/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1993

Document ID:	CTF0317142
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	08/04/1993
Trans1 Recv Date:	08/04/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1993
Part A Recv Date:	08/13/1993
Part B Recv Date:	08/20/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

RUSH MFG CORP (Continued) **1000238316**

Year: 1993

Document ID: CTF0140731
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 01/06/1993
Trans1 Recv Date: 01/06/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 01/07/1993
Part A Recv Date: 01/15/1993
Part B Recv Date: 01/20/1993
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01018
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

Document ID: NJA1212610
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 02/26/1992
Trans1 Recv Date: 02/26/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 03/03/1992
Part A Recv Date: 03/09/1992
Part B Recv Date: 03/18/1992
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F001 - UNKNOWN
Quantity: 00508
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1992

ECHO:
Envid: 1000238316
Registry ID: 110002092967
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002092967

W184 **NYNEX** **NY MANIFEST** **1009234555**
West **UNION AVENUE AND WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.201 mi.
1063 ft. **Site 4 of 4 in cluster W**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP000932509
Country:	USA
Location Address 1:	UNION AVENUE AND WARREN STREET
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NYNEX
Contact:	V ORCHIER
Address:	221 EAST 37TH STREET
City/State/Zip:	NEW YORK, NY 10016
Country:	USA
Phone:	212-338-7126

Manifest:

Document ID:	MIA4512835
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1996
Trans1 Recv Date:	12/17/1996
Trans2 Recv Date:	12/20/1996
TSD Site Recv Date:	01/03/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/23/1997
Generator EPA ID:	NYP000932509
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574
TSDF ID:	MID096963194
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1996

AD185 **CON EDISON TRANSFORMER MANHOLE: 2806** **RCRA NonGen / NLR** **1016962648**
South **592 MAIN ST** **NY MANIFEST** **NYP004357059**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.202 mi.
1066 ft. **Site 2 of 5 in cluster AD**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/09/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2806
Facility address:	592 MAIN ST NEW ROCHELLE, NY 10804

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

EPA ID: NYP004357059
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/09/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2806
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004357059
Country: USA
Location Address 1: 592 MAIN ST.
Location Address 2: MH # 2806
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2013
Trans1 Recv Date:	09/09/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004357059
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010707806JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

---

186 **CITIZEN** **NY LTANKS** **S100165790**
WSW **33 GROVE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.202 mi.
1067 ft.

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	135309
Spill Number/Closed Date:	8708588 / 1989-11-28
Spill Date:	1988-01-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-11-28
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported

CITIZEN (Continued) **S100165790**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-27
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	CAPT. FERGESON
Spiller City,St,Zip:	NEW ROCHELLE F.D., ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK RUPTURE IN CITIZEN'S BASEMENT. TANK TO BE EMPTIED."

Material:

Site ID:	135309
Operable Unit ID:	913258
Operable Unit:	01
Material ID:	463968
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	550.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AE187 **THE MALL** **NY LTANKS** **S100141913**
East **MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.204 mi.
1079 ft. **Site 1 of 4 in cluster AE**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Site ID:	326514
Spill Number/Closed Date:	9010648 / 1991-01-04
Spill Date:	1991-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-01-04
CID:	Not reported

THE MALL (Continued) **S100141913**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-10
Spill Record Last Update:	1992-07-31
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	263025
DEC Memo:	"Administratively closed due to file review and/or information received. If new information arises to contradict this determination DEC reserves the right to reopen this spill without prejudice. Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WATER FOUND IN TANK TO BE PUMPED OUT HONER EASY -.087"

Material:

Site ID:	326514
Operable Unit ID:	947782
Operable Unit:	01
Material ID:	430787
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	326514
Spill Tank Test:	1538129
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AF188 **175 MEMORIAL HWY. REALTY, INC.** **NY UST** **U003994239**
NW **175 MEMORIAL HWY.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.204 mi.
1079 ft. **Site 1 of 2 in cluster AF**

Relative:
Higher

Actual:
85 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800711 / Unregulated: <1101 gal. PBS
Operator Name:	A. Langhitano
Owner Name:	175 Memorial Hwy. Realty, Inc.
Owner Street:	175 Memorial Hwy.
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10802
GDS Number:	Not reported
Tank Number:	175-1
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AG189 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1017773973**
South **CENTRE AVE & LEROY** **FINDS** **NYP004517694**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1085 ft. **Site 1 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/30/2014
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	CENTRE AVE & LEROY NEW ROCHELLE, NY 10801
EPA ID:	NYP004517694
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063800506

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AG190 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1016973761**
South **LEROY PL & CENTER AVE** **NY MANIFEST** **NYP004475687**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.205 mi.
1085 ft. **Site 2 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/22/2014
Facility name: CON EDISON SERVICE BOX: 3313
Facility address: LEROY PL & CENTER AVE
NEW ROCHELLE, NY 10802
EPA ID: NYP004475687
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Contact:	THOMAS TEELING
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/22/2014
Site name:	CON EDISON SERVICE BOX: 3313
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004475687
Country:	USA
Location Address 1:	SEC LEROY & CENTRE AVE
Location Address 2:	SB3313
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING ST
Address 2:	15TH ST
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2014
Trans1 Recv Date:	03/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004475687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012772784JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AG191 **CON EDISON** **NY MANIFEST** **S117059593**
South **CENTRE AVE & LEROY** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1085 ft. **Site 3 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004517694
Country:	USA
Location Address 1:	C/O CENTRE AVE & LEROY PL
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

CON EDISON (Continued) **S117059593**

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004517694
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012772797JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH192 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016970578**
SE **174 NORTH AVE** **NY MANIFEST** **NYP004442943**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1093 ft. **Site 1 of 11 in cluster AH**

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	174 NORTH AVE NEW ROCHELLE, NY 10804
EPA ID:	NYP004442943
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2014
Site name: CON EDISON SERVICE BOX: 2040
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004442943
Country: USA
Location Address 1: FO 174 NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2014

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004442943
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	011692698JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AI193 **SCHMUCKLER'S DRY CLEANERS** **NY BROWNFIELDS** **S107787044**
NNW **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.208 mi.
1098 ft. **Site 1 of 10 in cluster AI**

Relative:
Lower

Actual:
74 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	357446
Acres:	0.21
HW Code:	C360088
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/29/2005
Record Updated Date:	12/31/2015
Update By:	DACROSBY
Site Description:	Location: The Schmucklers Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. The site is 0.21 acres, most of which is covered by a two-story row building with a full basement. Site Features: In addition to the former dry cleaners, historically located on the first floor, the site also includes an enclosed backyard area to the immediate west of the building. The backyard is mostly covered by lawn, but also includes elevated vegetable beds, and a paved walkway. Current Zoning/Use(s): The site is commercially zoned, and currently has five commercial tenants occupying both the first and second floors. Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commerical uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

is provided from a municipal source.Past Uses of the Site: The building on-site was built in 1891, and operated by Schmucklers Cleaners from 1914 to 2006 on the first floor and basement of the building. Additions were added to the building in 1937, and two in 1987. The site was acquired by the Volunteer, HNJ Realty, LLC, in August 2005, and entered into a BCA in June 2006. An interim remedial measure (IRM) was conducted starting in late 2008 to install a combined soil vapor extraction system/sub-slab depressurization system (SVE/SSDS) in the former dry cleaner to mitigate PCE in indoor air. The IRM was deemed complete in December 2013, but the SVE/SSDS continues to operate. A second IRM work plan was approved in May 2015 to conduct a pilot study of an enhanced biological in situ treatment to remediate contaminants under the on-site building slab. Site Geology and Hydrogeology: The site is underlain by historic fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater at the site flows in a southeasterly direction. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater.

Env Problem:

Based on the investigations conducted to date, the primary contaminants of concern at the site are chlorinated volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE) and its breakdown compounds, in soils, groundwater, sub-slab vapor, and soil gas; petroleum-related VOCs in soils, groundwater, sub-slab vapor, and soil gas; and semi-volatile organic compounds (SVOCs) in groundwater. Soils: Tetrachloroethylene (PCE), trichloroethene (TCE), and multiple petroleum related VOCs were detected in onsite soils underneath the building slab. The highest concentration of PCE at 210 parts per million (ppm), exceeding restricted commercial soil cleanup objectives (SCOs), was located underneath the former dry cleaning equipment room. Other contaminants detected in soils only exceeded the Protection of Groundwater SCOs. These exceedences were largely in soils located downgradient of the dry cleaning equipment room and consisted of: TCE at 1.3 ppm, cis-1,2 dichloroethene (cis-1,2-DCE) at 3 ppm, n-propylbenzene at 16 ppm, m+p xylenes at 15 ppm, ethylbenzene at 6.6 ppm, 1,3,5-trimethylbenzene at 63 ppm, and 1,2,4-trimethylbenzene at 99 ppm. Groundwater: Petroleum-based floating product (LNAPL, or light non-aqueous phase liquid) was observed in groundwater under much of the on-site building slab, a maximum of 6 inches thick under the former dry cleaning equipment room. Also observed were very high concentrations of select VOCs also under the former drycleaning equipment room. The maximum detected PCE was 830,000 parts per billion (ppb), and TCE at 58,000 ppb, indicating the presence of these compounds as free product DNAPLs (dense non-aqueous phase liquid) in groundwater. 25 individual VOCs were also detected in site groundwater samples exceeding NYS Class GA groundwater standards. These include the above-mentioned PCE, TCE, as well as other maximum detected concentrations of PCE breakdown products: cis-1,2-DCE at 8,700 ppb, and vinyl chloride at 28 ppb. BTEX was detected, with benzene at 62 ppb, toluene at 130 ppb, ethylbenzene at 150 ppb, m+p xylene at 520 ppb, and o-xylene at 290 ppb. Other significant concentrations of VOCs detected in groundwater include 1,3,5-trimethylbenzene at 890 ppb, and 1,2,4-trimethylbenzene at 840 ppb. Eight SVOCs were detected over groundwater standards in

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

groundwater under the building slab, including napthalene at a concentration of 1300 ppb, phenanthrene at 2400 ppb, acenapthene at 710 ppb, and antracene at 280 ppb. Bedrock wells were installed off-site in the downgradient, sidegradient, and upgradient directions. Petroleum-based VOCs and SVOCs were detected in the bedrock aquifer at concentrations above groundwater standards. For VOCs, total maximum BTEX concentration of 722 ppb was detected in a downgradient bedrock well. 11 individual SVOC contaminants were detected over groundwater standards in the same downgradient off-site bedrock well, including naphthalene at 4100 ppb, phenanthrene at 2800 ppb, acenapthene at 710 ppb, and antracene at 300 ppb.The extent of groundwater contamination is concentrated underneath the on-site building slab, with petroleum-based VOC and SVOC contaminants and LNAPL extending off-site in the bedrock downgradient or southeast direction. Soil Gas/Soil Vapor: The high concentrations of PCE (787,000 ug/m3), TCE (15,200 ug/m3), cis-1,2-DCE (46,000 ug/m3), and Vinyl Chloride (34 ug/m3) in soil vapor under the slab of the on-site building required the installation and continuing operation of a combined soil vapor extraction and sub-slab mitigation system during a 2008-2013 Interim Remedial Measure (IRM) action. PCE (at 91 ug/m3) and TCE (13.4 ug/m3) were also detected in soil gas outside of the building near the location of a former drywell. Benzene (37 ug/m3), toluene (126 ug/m3), ethylbenzene (85 ug/m3), xylene (555 ug/m3), 1,3,5-trimethylbenzene (3 ug/m3), and 1,2,4-trimethylbenzene (14 ug/m3) were also detected in subslab vapor and soil gas. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.

Health Problem: While direct contact with contaminants in the soil is unlikely because most contaminated soils are found beneath the on-site building, persons who dig below the ground surface adjacent to the building may come into contact with contaminants in subsurface soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. A sub-slab depressurization system was installed in the on-site building to prevent vapors beneath the slab from entering the building. Sampling indicates soil vapor intrusion is not a concern in one adjacent off-site building. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for other nearby off-site buildings.

AI194 **MAYCO, LLC** **NY AST** **A100252337**
NNW **18-20 MAY ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.211 mi.
1115 ft. **Site 2 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

WESTCHESTER CO. AST:

PBS Number:	3-175447
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Alex Hay
Owner Name:	Mayco, LLC
Owner Street:	P.O. Box 1755
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10156
Tank Number:	1

MAYCO, LLC (Continued) **A100252337**

Status:	1. In-Service
Date Installation:	01/01/1980
Capacity:	4000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

AJ195 **NEW ROCHELLE HOSPITAL** **NY LTANKS** **S100141273**
NW **COVION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.211 mi.
1116 ft. **Site 1 of 5 in cluster AJ**

Relative:
Higher

Actual:
102 ft.

LTANKS:

Site ID:	136814
Spill Number/Closed Date:	9003911 / 1991-03-15
Spill Date:	1990-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	1991-04-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

DER Facility ID: 117069
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/15/91: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks: "WILL EIR PBS TO FOLLOW AINLEY +.094"

Material:
Site ID: 136814
Operable Unit ID: 941734
Operable Unit: 01
Material ID: 435036
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 136814
Spill Tank Test: 1537277
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

AI196 **SCHMUCKLERS CLEANERS** **RCRA-CESQG** **1000303485**
NNW **360 NORTH AVE** **NY MANIFEST** **NYD012950770**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1117 ft. **Site 3 of 10 in cluster AI**

Relative:
Lower

Actual:
75 ft.

RCRA-CESQG:
Date form received by agency: 03/31/2008
Facility name: SCHMUCKLERS CLEANERS
Facility address: 360 NORTH AVE
NEW ROCHELLE, NY 10801
EPA ID: NYD012950770
Mailing address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact: HAL I SHAPIRO
Contact address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact country: US
Contact telephone: (917) 693-9019
Contact email: HALSHAP@GMAIL.COM
EPA Region: 02
Land type: Private

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: HNJ REALTY LLC
Owner/operator address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2005
Owner/Op end date: Not reported

Owner/operator name: HNJ REALTY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D007
. Waste name: CHROMIUM

SCHMUCKLERS CLEANERS (Continued) **1000303485**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 03/30/2008
Site name: SCHMUCKLERS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: SCHMUKLERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/09/1998
Site name: SCHMUKLERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 10/29/1993

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Site name: SCHMUKLERS
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(3)
Area of violation: Generators - General
Date violation determined: 09/08/2003
Date achieved compliance: 09/18/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/18/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/08/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYD012950770
Country: USA
Location Address 1: 360 NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: SHMUCKLERS DRY CLEANERS
Contact: SHMUCKLERS DRY CLEANERS
Address: 360 NORTH AVENUE
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-632-2705

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 06/11/2015
Trans1 Recv Date: 06/12/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/29/2015
Part A Recv Date: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987270725
Waste Code:	Not reported
Quantity:	691
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006197558FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H039

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	2100.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Quantity:	1600.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	60.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2015
Trans1 Recv Date:	06/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987270725
Waste Code:	Not reported
Quantity:	691
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006197558FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H039

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	02/09/2007
Trans1 Recv Date:	02/09/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	12
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Year:	2007
Manifest Tracking Num:	000461860SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/15/2007
Trans1 Recv Date:	05/15/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000472131SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	NYC7242423
Manifest Status:	Not reported
Trans1 State ID:	NY49555JE
Trans2 State ID:	T465GLNJ
Generator Ship Date:	08/05/2004
Trans1 Recv Date:	08/05/2004

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans2 Recv Date:	08/11/2004
TSD Site Recv Date:	08/16/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7301520
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	T364DANJ
Generator Ship Date:	01/20/2004
Trans1 Recv Date:	01/20/2004
Trans2 Recv Date:	01/28/2004
TSD Site Recv Date:	01/29/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7145853

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	044AE381M
Generator Ship Date:	01/07/2004
Trans1 Recv Date:	01/07/2004
Trans2 Recv Date:	01/14/2004
TSD Site Recv Date:	01/15/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7146044
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	NJ044T468
Generator Ship Date:	05/21/2004
Trans1 Recv Date:	05/21/2004
Trans2 Recv Date:	05/26/2004
TSD Site Recv Date:	05/27/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00330
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7228765
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans2 State ID:	T39K7HNJ
Generator Ship Date:	07/14/2004
Trans1 Recv Date:	07/14/2004
Trans2 Recv Date:	07/21/2004
TSD Site Recv Date:	07/22/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7198380
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	T853MVNJ
Generator Ship Date:	04/02/2004
Trans1 Recv Date:	04/02/2004
Trans2 Recv Date:	04/07/2004
TSD Site Recv Date:	04/08/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Document ID:	NYC7576920
Manifest Status:	Not reported
Trans1 State ID:	NY49455JC
Trans2 State ID:	NJT27L8D
Generator Ship Date:	12/22/2004
Trans1 Recv Date:	12/22/2004
Trans2 Recv Date:	12/29/2004
TSD Site Recv Date:	12/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00440
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC6976811
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	FT97358CA
Generator Ship Date:	04/17/2003
Trans1 Recv Date:	04/17/2003
Trans2 Recv Date:	04/23/2003
TSD Site Recv Date:	04/24/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7043872
Manifest Status:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans1 State ID:	NYCR3164
Trans2 State ID:	T854MWNJ
Generator Ship Date:	06/10/2003
Trans1 Recv Date:	06/10/2003
Trans2 Recv Date:	06/18/2003
TSD Site Recv Date:	06/19/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC6983008
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	T2L230NJ
Generator Ship Date:	02/21/2003
Trans1 Recv Date:	02/21/2003
Trans2 Recv Date:	02/26/2003
TSD Site Recv Date:	02/27/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Year: 2003

Document ID: NYC7019357
Manifest Status: Not reported
Trans1 State ID: NYCR3164
Trans2 State ID: T25L8DNJ
Generator Ship Date: 01/22/2003
Trans1 Recv Date: 01/22/2003
Trans2 Recv Date: 01/29/2003
TSD Site Recv Date: 01/30/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012950770
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00220
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7150318
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: T83G9TNJ
Generator Ship Date: 11/04/2003
Trans1 Recv Date: 11/04/2003
Trans2 Recv Date: 11/12/2003
TSD Site Recv Date: 11/13/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012950770
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00090
Units: P - Pounds
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

AI197 **SCHMUKLER'S CLEANERS** **NY DRYCLEANERS** **S110247878**
NNW **360 NORTH AVE.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1117 ft. **Site 4 of 10 in cluster AI**

Relative:
Lower

Actual:
75 ft.

DRYCLEANERS:

Facility ID:	3-5510-00327
Phone Number:	914-632-2705
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	07NOV13
Install Date:	98/06
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AE198 **NEW ROCHELLE MALL** **NY UST** **U003857279**
East **425 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1118 ft. **Site 2 of 4 in cluster AE**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600042 / Unregulated: <1101 gal. PBS
Operator Name:	Unknown
Owner Name:	New Roc Associates
Owner Street:	30 Glenn St.
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10603
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	15000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	05/26/1998
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AJ199 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **NY UST** **U003857945**
NW **16 GUION PLACE** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1143 ft. **Site 2 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-123269 / Active
Operator Name:	Thomas Irving
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10467
GDS Number:	Not reported
Tank Number:	2 day
Status:	4. Closed - in place
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1978
Date Perm Closure:	Not reported
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	4
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	07/01/1996
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Number:	5
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1981
Date Perm Closure:	07/19/2006
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5B
Status:	1. In-Service
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	07/01/2006
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	8
Status:	1. In-Service
Capacity:	3000
Product Stored:	6. Diesel
Product Stored Percent:	0
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	10/22/2010
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	10. Urethane clad steel
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	plastic sleeve
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-123269
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Thomas Irving
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10467
Tank Number:	# 8 Day
Status:	1. In-Service
Date Installation:	10/22/2010
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	04
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1996
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	other
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	99. Other

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	5. Closed - removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 day
Status:	1. In-Service
Date Installation:	06/01/1976
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	5. Closed - removed
Date Installation:	12/01/1967
Capacity:	16000

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1971
Capacity:	30000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3 day
Status:	1. In-Service
Date Installation:	07/01/1980
Capacity:	50
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	5. Closed - removed
Date Installation:	12/01/1981
Capacity:	500
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	12/01/2005
Capacity:	700
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/2016

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Capacity:	10000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	7. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AJ200 **SOUND SHORE MEDICAL CENTER** **PA MANIFEST** **S111771577**
NW **16 GUION PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1143 ft. **Site 3 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

Manifest Details:

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U188
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AJ201 **SOUTH SHORE MED CENTER** **NY LTANKS** **S107523501**
NW **16 GUION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1143 ft. **Site 4 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	358758
Spill Number/Closed Date:	0512440 / 2006-12-19
Spill Date:	2006-01-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

SOUTH SHORE MED CENTER (Continued) **S107523501**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-01-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2006-12-22
Spiller Name:	VERONICA
Spiller Company:	SOUND SHORE MED CENTER
Spiller Address:	16 GUION PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	VERONICA
Spiller Phone:	(201) 489-8700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308757
DEC Memo:	"Tank removed, no contamination found. NFA jod 12/22/06 - Letter from Wayne Schneider of WCDOD dated 8/29/06 addressed to Dir. of Engr., Sound Shore Medical Center, has requested NYSDEC to colose this spill #."
Remarks:	"Tank test failure. Ullage leak was detected."

Material:

Site ID:	358758
Operable Unit ID:	1115985
Operable Unit:	01
Material ID:	2106096
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	358758
Spill Tank Test:	1549678
Tank Number:	5
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported

SOUTH SHORE MED CENTER (Continued) **S107523501**

Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AJ202 **SOUND SHORE MEDICAL CENTER** **RCRA-SQG** **1000130172**
NW **16 GUION PL** **FINDS** **NYD075431502**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.216 mi. **ECHO**
1143 ft. **Site 5 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

RCRA-SQG:
Date form received by agency: 10/31/2013
Facility name: SOUND SHORE MEDICAL CENTER
Facility address: 16 GUION PL
NEW ROCHELLE, NY 10802
EPA ID: NYD075431502
Mailing address: GUION PL
NEW ROCHELLE, NY 10802
Contact: GARRETT T DOERING
Contact address: E 210TH ST
BRONX, NY 10467
Contact country: US
Contact telephone: (717) 920-7600
Contact email: GDOREING@MONTEFIORE.ORG
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 632-5000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 632-5000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: (914) 378-6300
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/01/2013
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175
YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: (914) 378-6300
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-MET OXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U170
. Waste name: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Historical Generators:
Date form received by agency: 01/01/2007
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/08/1997
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/11/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004368620

Environmental Interest/Information System

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

COMPLIANCE AND EMISSIONS REPORTING

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD075431502
Country:	USA
Location Address 1:	16 GUION PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SOUND SHORE MEDICAL CENTER
Contact:	NEW ROCHELLE HOSPITAL
Address:	16 QUINN PLACE
City/State/Zip:	NEW ROCHELLE, NY 10802
Country:	USA
Phone:	914-632-5000

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	05/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	31
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213253FLE

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	07/14/2015
TSD Site Recv Date:	07/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	96
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008212114FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	07/21/2015
Trans1 Recv Date:	07/21/2015
Trans2 Recv Date:	07/28/2015
TSD Site Recv Date:	07/30/2015

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	111
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008229168FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	09/08/2015
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	66
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915668FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	09/08/2015
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	19
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915668FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	08/18/2015
Trans1 Recv Date:	08/18/2015
Trans2 Recv Date:	08/25/2015
TSD Site Recv Date:	08/27/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Waste Code:	Not reported
Quantity:	67
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915884FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/15/2015
Trans1 Recv Date:	09/15/2015
Trans2 Recv Date:	09/22/2015
TSD Site Recv Date:	09/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	96
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008938471FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2015
Trans1 Recv Date:	02/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	31
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007885181FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	03/03/2015
Trans1 Recv Date:	03/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	35
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Year:	2015
Manifest Tracking Num:	008210510FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	14
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008210971FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	16
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211044FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2015
Trans1 Recv Date:	04/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	27
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211112FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2015
Trans1 Recv Date:	04/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	68
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211204FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2015
Trans1 Recv Date:	04/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	42
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211204FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	13
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008212115FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAC300016672
Trans2 State ID: Not reported
Generator Ship Date: 07/07/2015
Trans1 Recv Date: 07/07/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075431502
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 22
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008212115FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAC300016672
Trans2 State ID: Not reported
Generator Ship Date: 06/09/2015
Trans1 Recv Date: 06/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075431502
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 35
Units: P - Pounds
Number of Containers: 1

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213009FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2015
Trans1 Recv Date:	05/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213269FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	33
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213288FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213288FLE
Import Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1000130172
Registry ID:	110004368620
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004368620

203
West
1/8-1/4
0.217 mi.
1145 ft.

RESIDENCE **NY LTANKS** **S107489339**
79 WARREN ST **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	356553
Spill Number/Closed Date:	0510555 / 2006-03-28
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-28
Spiller Name:	ISHMAL GALVIN
Spiller Company:	RESIDENCE
Spiller Address:	79 WARREN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	ISHMAL GALVIN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306611
DEC Memo:	"March 28, 2006: GRAZI-1 CORP DISPOSED OF LUST AND 67.95 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER

RESIDENCE (Continued) **S107489339**

ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Tank removal, tank size 550 gallons"

Material:
Site ID: 356553
Operable Unit ID: 1113853
Operable Unit: 01
Material ID: 2103913
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AF204 **66 MEMORIAL BLVD** **NY LTANKS** **S104621761**
NW **66 MEMORIAL BLVD** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.217 mi.
1146 ft. **Site 2 of 2 in cluster AF**

Relative:
Higher

Actual:
90 ft.

LTANKS:
Site ID: 59397
Spill Number/Closed Date: 0002907 / 2000-10-24
Spill Date: 2000-06-08
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2000-06-08
CID: 389
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-06-08
Spill Record Last Update: 2000-11-21
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller City,St,Zip: UNKNOWN, NY
Spiller County: 999
Spiller Contact: CALLER
Spiller Phone: Not reported

66 MEMORIAL BLVD (Continued) **S104621761**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 58153
DEC Memo: ""
Remarks: "caller reporting a spill of material from a tank being hit while escavating land for a basement. no callback is necessary caller is anaymous. clena up is being done at this time."

Material:
Site ID: 59397
Operable Unit ID: 824416
Operable Unit: 01
Material ID: 551247
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: Gallons
Recovered: 10.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AK205 **LEXINGTON CENTER FOR RECOVERY INC** **NJ MANIFEST** **S117987423**
NNE **3 COTTAGE PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1147 ft. **Site 1 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:
EPA Id: NYR000193854
Mail Address: COTTAGE PL
Mail City/State/Zip: NEW ROCHELLE, NY 10801
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: LISA OBRIEN
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 008900746JJK
EPA ID: NYR000193854
Date Shipped: 5/25/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NY0001031814
Transporter 2 EPA ID: Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	30.00 Pounds

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	300.00 Pounds

AK206 **LEXINGTON CENTER FOR RECOVERY INC** **RCRA NonGen / NLR** **1014958140**
NNE **3 COTTAGE PL** **NY MANIFEST** **NYR000193854**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1147 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/27/2012
Facility name:	LEXINGTON CENTER FOR RECOVERY INC
Facility address:	3 COTTAGE PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000193854
Mailing address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact:	LISA OBRIEN
Contact address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 235-6633
Telephone ext.:	1503
Contact email:	LOBRIEN@LEXINGTONCTR.ORG
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BARRY J JACOBSON
Owner/operator address:	E 40TH ST 8TH FL NEW YORK, NY 10016
Owner/operator country:	US
Owner/operator telephone:	(212) 889-7460
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/02/1983
Owner/Op end date:	Not reported
Owner/operator name:	LEXINGTON CENTER FOR RECOVERY INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/2008
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D009
. Waste name: MERCURY

Historical Generators:
Date form received by agency: 05/18/2012
Site name: LEXINGTON CENTER FOR RECOVERY INC
Classification: Large Quantity Generator

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/19/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYR000193854
Country: USA
Location Address 1: 3 COTTAGE PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: LEXINGTON CENTER FOR RECOVERY INC
Contact: LEXINGTON CENTER FOR RECOVERY INC
Address: 3 COTTAGE PL
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-235-6633

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NY0001031814
Trans2 State ID: NJ0000027193
Generator Ship Date: 05/25/2012
Trans1 Recv Date: 05/25/2012
Trans2 Recv Date: 06/01/2012
TSD Site Recv Date: 06/06/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193854

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008900746JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NY0001031814
Trans2 State ID:	NJ0000027193
Generator Ship Date:	05/25/2012
Trans1 Recv Date:	05/25/2012
Trans2 Recv Date:	06/01/2012
TSD Site Recv Date:	06/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000193854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008900746JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

207
SE
1/8-1/4
0.219 mi.
1156 ft.

CON EDISON
46 CLINTON PL
NEW ROCHELLE, NY 10801

RCRA-CESQG **1012184999**
NY MANIFEST **NYP004157665**

Relative:
Higher

Actual:
91 ft.

RCRA-CESQG:

Date form received by agency:	04/01/2008
Facility name:	CON EDISON
Facility address:	46 CLINTON PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004157665
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1012184999**

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004157665
Country: USA
Location Address 1: 46 CLINTON PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRAMKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/01/2008
Trans1 Recv Date: 04/01/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004157665
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 180.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 6.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 002013408FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

AE208 **MONROE COLLEGE** **NY AST** **A100252339**
East **420 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.223 mi.
1179 ft. **Site 3 of 4 in cluster AE**

Relative:
Lower

Actual:
77 ft.

WESTCHESTER CO. AST:

PBS Number:	3-800251
Site Status:	Active
GDS Number:	Not reported
Operator Name:	James Moore
Owner Name:	Monroe College
Owner Street:	434 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	07/01/2004
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	0
Date Perm Closure:	04/13/2004
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity
Tank Number:	001old
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	04/13/2004
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	99. Other
Tank External Protection:	99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	99. Other
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	99. Other
Spill Prevention:	Not reported

MONROE COLLEGE (Continued) **A100252339**

Dispenser: 2. Suction

Tank Number: 1
Status: 0. Administratively closed
Date Installation: 01/01/1900
Capacity: 275
Product Stored: Not reported
Product Stored Percent: Not reported
Date Perm Closure: 11/06/2003
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

AD209 **CON EDISON** **NY MANIFEST** **S117535572**
SSW **MAIN ST & MAPLE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.226 mi.
1191 ft. **Site 3 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:
EPA ID: NYP004674354
Country: USA
Location Address 1: MAIN ST & MAPLE AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 10/07/2014
Trans1 Recv Date: 10/07/2014
Trans2 Recv Date: Not reported

CON EDISON (Continued) **S117535572**

TSD Site Recv Date:	10/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004674354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MAD053452637
Waste Code:	Not reported
Quantity:	559
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007747843FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AD210 **CON EDISON** **RCRA NonGen / NLR** **1014399091**
SSW **MAPLE AVE & MAIN ST** **NJ MANIFEST** **NYP004214680**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.226 mi.
1191 ft. **Site 4 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/01/2010
Facility name:	CON EDISON
Facility address:	MAPLE AVE & MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004214680
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

CON EDISON (Continued) **1014399091**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004214680
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DENNIS ROHRER
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 004086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/01/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 09/02/2010

CON EDISON (Continued) **1014399091**

TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 120 P

Manifest Number: 001086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/01/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 09/02/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported

CON EDISON (Continued) **1014399091**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 120 P

AD211 **CON EDISON MANHOLE: 734** **RCRA NonGen / NLR** **1016969502**
SSW **MAIN ST & MAPLE ST** **NY MANIFEST** **NYP004431706**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.226 mi.
1191 ft. **Site 5 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/01/2014
Facility name: CON EDISON MANHOLE: 734
Facility address: MAIN ST & MAPLE ST
NEW ROCHELLE, NY 10805
EPA ID: NYP004431706
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Date form received by agency: 02/01/2014
Site name: CON EDISON MANHOLE: 734
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004431706
Country: USA
Location Address 1: 591 MAIN ST
Location Address 2: MH 734
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/01/2014
Trans1 Recv Date: 02/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004431706
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 011696225JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AL212 **CONSOLIDATED EDISON - MH 1174** **NY MANIFEST** **S110709396**
NE **HUGUENOT ST & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1192 ft. **Site 1 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

NY MANIFEST:

EPA ID:	NYP004219572
Country:	USA
Location Address 1:	HUGUENOT ST & HARRISON ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON - MH 1174
Contact:	TOM TEELING
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2010
Trans1 Recv Date:	11/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	006874917JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

CONSOLIDATED EDISON - MH 1174 (Continued) **S110709396**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AL213 **CON EDISON MANHOLE 1174** **RCRA NonGen / NLR** **1014918343**
NE **HUGEONOT ST & HARRISON ST** **NJ MANIFEST** **NYP004219570**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1192 ft. **Site 2 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:
Date form received by agency: 12/04/2010
Facility name: CON EDISON MANHOLE 1174
Facility address: HUGEONOT ST & HARRISON ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004219570
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/04/2010
Site name: CON EDISON MANHOLE 1174
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004219570
Mail Address: IRVING PL RM 828

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874917JJK
EPA ID:	NYP004219570
Date Shipped:	11/04/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/04/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

AC214 **PREFERRED CLEANERS** **RCRA NonGen / NLR** **1000353766**
West **95 UNION AVE** **FINDS** **NYD050275254**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.226 mi. **ECHO**
1193 ft. **Site 2 of 7 in cluster AC**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PREFERRED CLEANERS
Facility address:	95 UNION AVE NEW ROCHELLE, NY 108016238
EPA ID:	NYD050275254
Mailing address:	UNION AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	UNION AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	(914) 472-6038
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	(914) 472-6038
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

PREFERRED CLEANERS (Continued) **1000353766**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 06/19/1995
Site name: PREFERRED CLEANERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004357918

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

PREFERRED CLEANERS (Continued) **1000353766**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD050275254
Country:	USA
Location Address 1:	95 UNION AVENUE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NEBRASKA CLEANERS
Contact:	NEBRASKA CLEANERS
Address:	95 UNION AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-636-4937

Manifest:

Document ID:	NYC3571378
Manifest Status:	Completed copy
Trans1 State ID:	GT9066
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1995
Trans1 Recv Date:	07/14/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/14/1995
Part A Recv Date:	/ /
Part B Recv Date:	07/25/1995
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00320
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

PREFERRED CLEANERS (Continued) **1000353766**

Document ID: NYA3828047
Manifest Status: Completed copy
Trans1 State ID: IL009
Trans2 State ID: Not reported
Generator Ship Date: 12/05/1986
Trans1 Recv Date: 12/05/1986
Trans2 Recv Date: / /
TSD Site Recv Date: 12/05/1986
Part A Recv Date: 12/16/1986
Part B Recv Date: 12/16/1986
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1986

Document ID: NYC3571604
Manifest Status: Completed copy
Trans1 State ID: NYGT9060
Trans2 State ID: Not reported
Generator Ship Date: 08/24/1995
Trans1 Recv Date: 08/24/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 08/24/1995
Part A Recv Date: / /
Part B Recv Date: 09/06/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0452797
Manifest Status: Completed copy
Trans1 State ID: NYLH7543
Trans2 State ID: Not reported
Generator Ship Date: 11/20/1995
Trans1 Recv Date: 11/20/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/27/1995
Part A Recv Date: / /

PREFERRED CLEANERS (Continued) **1000353766**

Part B Recv Date: 12/13/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: NYC3341856
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 11/15/1994
Trans1 Recv Date: 11/15/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 11/15/1994
Part A Recv Date: 11/23/1994
Part B Recv Date: 11/28/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3289757
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 10/18/1994
Trans1 Recv Date: 10/18/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 10/18/1994
Part A Recv Date: 10/28/1994
Part B Recv Date: 10/27/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002

PREFERRED CLEANERS (Continued) **1000353766**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3062384
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1994
Trans1 Recv Date: 07/01/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 07/01/1994
Part A Recv Date: 07/14/1994
Part B Recv Date: 07/13/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC2928633
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 06/03/1994
Trans1 Recv Date: 06/03/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 06/03/1994
Part A Recv Date: 06/15/1994
Part B Recv Date: 06/13/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

PREFERRED CLEANERS (Continued) **1000353766**

Specific Gravity: 100
Year: 1994

Document ID: NYC3378047
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 12/12/1994
Trans1 Recv Date: 12/12/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 12/12/1994
Part A Recv Date: 01/09/1995
Part B Recv Date: 12/20/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3241991
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 09/22/1994
Trans1 Recv Date: 09/22/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 09/22/1994
Part A Recv Date: 10/05/1994
Part B Recv Date: 10/03/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

PREFERRED CLEANERS (Continued) **1000353766**

Document ID:	NYC1263071
Manifest Status:	Completed copy
Trans1 State ID:	DW9495-NY
Trans2 State ID:	Not reported
Generator Ship Date:	11/27/1991
Trans1 Recv Date:	11/27/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/27/1991
Part A Recv Date:	/ /
Part B Recv Date:	12/05/1991
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1991

Document ID:	NYC0617049
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	DW9495NY
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/1991
Trans1 Recv Date:	04/30/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/30/1991
Part A Recv Date:	06/10/1991
Part B Recv Date:	05/14/1991
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1991

Document ID:	NYA9519412
Manifest Status:	Completed copy

PREFERRED CLEANERS (Continued) **1000353766**

Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	11/21/1989
Trans1 Recv Date:	11/21/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/21/1989
Part A Recv Date:	12/11/1989
Part B Recv Date:	11/29/1989
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00080
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYC0546221
Manifest Status:	Completed copy
Trans1 State ID:	NJDEP8690
Trans2 State ID:	Not reported
Generator Ship Date:	11/15/1990
Trans1 Recv Date:	11/15/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/15/1990
Part A Recv Date:	12/06/1990
Part B Recv Date:	12/10/1990
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00180
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

PREFERRED CLEANERS (Continued) **1000353766**

Year: 1990

Document ID: NYA5711589
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AV4489
Trans2 State ID: Not reported
Generator Ship Date: 11/23/1987
Trans1 Recv Date: 11/23/1987
Trans2 Recv Date: / /
TSD Site Recv Date: 11/23/1987
Part A Recv Date: 01/04/1988
Part B Recv Date: 11/27/1987
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1987

Document ID: NYA8779825
Manifest Status: Completed copy
Trans1 State ID: DW9495
Trans2 State ID: Not reported
Generator Ship Date: 12/15/1988
Trans1 Recv Date: 12/15/1988
Trans2 Recv Date: / /
TSD Site Recv Date: 12/15/1988
Part A Recv Date: 12/21/1988
Part B Recv Date: 12/22/1988
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080

PREFERRED CLEANERS (Continued) **1000353766**

Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1988

Document ID: NYC3462107
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 02/03/1995
Trans1 Recv Date: 02/03/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 02/03/1995
Part A Recv Date: 02/17/1995
Part B Recv Date: 02/14/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

ECHO:
Envid: 1000353766
Registry ID: 110004357918
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004357918

AH215 **SINNOTT MANAGEMENT COMPANY LLC** **NY AST** **A100359845**
SE **35 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.227 mi.
1198 ft. **Site 2 of 11 in cluster AH**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:
PBS Number: 3-078646
Site Status: Active
GDS Number: Not reported
Operator Name: Norman Avelenda
Owner Name: 35 Clinton Place LLC
Owner Street: 35 Clinton Place, #1B
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 1
Status: 1. In-Service
Date Installation: 12/01/1939
Capacity: 5000
Product Stored: 2. No. 4 fuel oil

SINNOTT MANAGEMENT COMPANY LLC (Continued) **A100359845**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Fiberglass
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	3. Gravity

AB216 **ALL AMERICAN SPORTS CORP** **RCRA NonGen / NLR** **1004760316**
SW **44 COLUMBUS AVE** **FINDS** **NYR000040113**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.228 mi. **ECHO**
1205 ft. **Site 5 of 5 in cluster AB**

Relative:
Lower

Actual:
66 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ALL AMERICAN SPORTS CORP
Facility address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
EPA ID:	NYR000040113
Mailing address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact:	LAMELLE WILLIAMS
Contact address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	(914) 636-7070
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	(914) 636-7070
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	(914) 636-7070

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ALL AMERICAN SPORTS CORP
Classification: Not a generator, verified

Date form received by agency: 05/30/1997
Site name: ALL AMERICAN SPORTS CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004534709

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000040113
Country: USA
Location Address 1: 44 COLUMBUS AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: ALL AMERICAN SPORTS CORP
Contact: LAMELLE WILLIAMS
Address: 44 COLUMBUS AVE
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-636-7070

Manifest:

Document ID: NJA2706453
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 10/13/1997
Trans1 Recv Date: 10/13/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 10/20/1997
Part A Recv Date: 10/29/1997
Part B Recv Date: 11/12/1997
Generator EPA ID: NYR000040113
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F005 - UNKNOWN
Quantity: 00426
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

EPA ID: NYD002182897
Country: USA
Location Address 1: 44 COLUMBUS AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: RIDDELL ALL AMERICAN
Contact: PERSING MEJIA
Address: 44 COLUMBUS AVE
City/State/Zip: NEW ROCHELLE, NY 10805
Country: USA
Phone: 914-636-7070

NY MANIFEST:
No Manifest Records Available

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

ECHO:
Envid: 1004760316
Registry ID: 110004534709
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004534709

AH217 **30 CLINTON PLACE OWNERS INC.** **NY UST U003855209**
SE **30 CLINTON PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1208 ft. **Site 3 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

WESTCHESTER CO. UST:
Id/Status: 3-078727 / Active
Operator Name: Dave Kuilan
Owner Name: 30 Clinton Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1old
Status: 5. Closed - removed
Capacity: 5000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 07/01/1995
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on Ground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 3. Gravity

WESTCHESTER CO. AST:
PBS Number: 3-078727
Site Status: Active
GDS Number: Not reported
Operator Name: Dave Kuilan
Owner Name: 30 Clinton Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 001
Status: 1. In-Service
Date Installation: 10/01/1996
Capacity: 3500

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	4. Closed - in place
Date Installation:	01/01/1996
Capacity:	4200
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AH218 **CO-OP** **NY LTANKS** **S101658613**
SE **30 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.229 mi.
1208 ft. **Site 4 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	189169
Spill Number/Closed Date:	9504589 / 1997-04-15
Spill Date:	1995-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010

CO-OP (Continued) **S101658613**

Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-20
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	MERILITH MNGT.
Spiller Address:	1101 MIDLAND AVE.
Spiller City,St,Zip:	BRONXVILLE, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157941
DEC Memo:	""
Remarks:	"OIL SEEPING INTO BASEMENT POSSIBLE TANK FAILURE SOME OIL GOT INTO SUMP PIT AND DISCHARGED OUT SUMP PUMP TAKEN OFF LINE"

Material:

Site ID:	189169
Operable Unit ID:	1019355
Operable Unit:	01
Material ID:	366101
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	189169
Spill Tank Test:	1544004
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AH219 **CON EDISON** **NY MANIFEST** **S117538379**
SE **150 NORTH AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1211 ft. **Site 5 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

NY MANIFEST:

EPA ID:	NYP004710497
Country:	USA
Location Address 1:	150 NORTH AV
Location Address 2:	SB2044
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004710497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774700JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117538379**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AM220 **NEW ROCHELLE FIRE STATION # 1** **NY UST** **U003994763**
ENE **45 HARRISON STREET** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1223 ft. **Site 1 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600407 / Active
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	FS101
Status:	1. In-Service
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1966
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	FS102
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	FS103
Status:	5. Closed - removed
Capacity:	250
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

PBS Number:	3-600407
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801

Tank Number:	FS104
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	4000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,2. Sacrificial Anode (no retrofit)
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

Dispenser:	2. Suction
Tank Number:	FS105
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	280
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	0. None

AM221 **CITY OF NEW ROCHELLE** **NY LTANKS** **S107658678**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1223 ft. **Site 2 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

LTANKS:

Site ID:	360263
Spill Number/Closed Date:	0513733 / 2006-06-21
Spill Date:	2006-02-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-02-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-28
Spill Record Last Update:	2006-06-21
Spiller Name:	DEE LESTER
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	45 HARRISON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY

CITY OF NEW ROCHELLE (Continued) **S107658678**

Spiller County:	001
Spiller Contact:	DEE LESTER
Spiller Phone:	(914) 654-2072
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310380
DEC Memo:	"Tank passed retest after piping was replaced. NFA"
Remarks:	"TANK SIZE IS 5000 GALLON, TEST METHOD WAS EZ3 LOCATOR PLUS,"

Material:

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107948
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AM222 **CON EDISON** **NY MANIFEST** **S118088270**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.232 mi.
1223 ft. **Site 3 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

EPA ID:	NYP004758215
Country:	USA
Location Address 1:	45 HARRISON ST
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

CON EDISON (Continued) **S118088270**

Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758215
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091127JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758215
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S118088270**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091127JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH223 **CON EDISON MANHOLE: 2042** **RCRA NonGen / NLR** **1016970603**
SE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004443198**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.232 mi.
1224 ft. **Site 6 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON MANHOLE: 2042
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10804
EPA ID:	NYP004443198
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2014
Site name: CON EDISON MANHOLE: 2042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004443198
Country: USA
Location Address 1: NORTH AVE & CLINTON PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004443198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Manifest Tracking Num:	012772860JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH224 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016971500**
SE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004452439**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.232 mi.
1224 ft. **Site 7 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/26/2014
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10805
EPA ID:	NYP004452439
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/26/2014
Site name:	CON EDISON SERVICE BOX: 2040

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004452439
Country: USA
Location Address 1: NORTH AVE & CLINTON PLS
Location Address 2: SB2040
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2014
Trans1 Recv Date: 02/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004452439
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012772758JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Mgmt Method Type Code: H110

AC225 **100-102 UNION AVENUE** **NY LTANKS** **S104514442**
West **100-102 UNION AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1229 ft. **Site 3 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	166425
Spill Number/Closed Date:	9608199 / 1996-11-08
Spill Date:	1996-10-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-01
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-01
Spill Record Last Update:	1996-12-10
Spiller Name:	LJ NJ ASSOC
Spiller Company:	100-102 UNION AVENUE
Spiller Address:	100-102 UNION AVENUE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LJ NJ ASSOC
Spiller Phone:	(914) 636-7297
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140217
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/96 LETTER SENT BASED ON CLOSURE REPORT NFA"
Remarks:	"caller pulled tank and found contaminated soil."

Material:

Site ID:	166425
Operable Unit ID:	1036474
Operable Unit:	01
Material ID:	343940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

100-102 UNION AVENUE (Continued) **S104514442**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AC226
West
1/8-1/4
0.233 mi.
1229 ft.

LJNJ ASSOCIATES **NY UST** **U003884659**
100-102 UNION AVE **N/A**
NEW ROCHELLE, NY 10801

Site 4 of 7 in cluster AC

Relative:
Higher

Actual:
95 ft.

WESTCHESTER CO. UST:

Id/Status:	3-601056 / Unregulated: <1101 gal. PBS
Operator Name:	Bob Rossi
Owner Name:	Ljnj Associates
Owner Street:	133 Meadow Lane
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	1080
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1959
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None
Tank Number:	2
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

LJNJ ASSOCIATES (Continued) **U003884659**

Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	3
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	4
Status:	5. Closed - removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/01/1996
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	5
Status:	0. Administratively closed
Capacity:	275

LJNJ ASSOCIATES (Continued) **U003884659**

Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AI227 **CON EDISON TRANSFORMER MANHOLE: 1552** **RCRA NonGen / NLR** **1016964344**
NNW **LOCKWOOD AVE & NORTH ST** **NY MANIFEST** **NYP004372751**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.233 mi.
1230 ft. **Site 5 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/10/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 1552
Facility address:	LOCKWOOD AVE & NORTH ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004372751
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Used oil transporter: No

Historical Generators:
Date form received by agency: 10/10/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1552
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004372751
Country: USA
Location Address 1: LOCKWOOD AVE & NORTH ST
Location Address 2: TM 1552
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/10/2013
Trans1 Recv Date: 10/10/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004372751
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011693714JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AI228 **CON EDISON MANHOLE 1545** **RCRA NonGen / NLR** **1014918224**
NNW **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004218356**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.233 mi.
1230 ft. **Site 6 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 11/18/2010
Facility name: CON EDISON MANHOLE 1545
Facility address: NORTH AVE & LOCKWOOD AVE
NEW ROCHELLE, NY 10801
EPA ID: NYP004218356
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2010
Site name: CON EDISON MANHOLE 1545
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004218356

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CHRISTOPHER BLAICH
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874846JJK
EPA ID:	NYP004218356
Date Shipped:	10/19/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/19/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/20/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 2000 P

NY MANIFEST:
EPA ID: NYP004218356
Country: USA
Location Address 1: NORTH AV OPP LOCKWOOD
Location Address 2: MH 1545
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2010
Trans1 Recv Date: 10/19/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004218356
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874846JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: Y

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AI229 **CON EDISON MANHOLE 1562** **RCRA NonGen / NLR** **1014918646**
NNW **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004222626**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.233 mi.
1230 ft. **Site 7 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/30/2011
Facility name: CON EDISON MANHOLE 1562
Facility address: NORTH AVE & LOCKWOOD AVE
NEW ROCHELLE, NY 10801
EPA ID: NYP004222626
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: DONALD SENNO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2010
Site name: CON EDISON MANHOLE 1562
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

CON EDISON MANHOLE 1562 (Continued) **1014918646**

EPA Id:	NYP004222626
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655578JJK
EPA ID:	NYP004222626
Date Shipped:	12/31/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/31/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/04/2011
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Waste:
- Manifest Year: Not reported
- Waste Code: D008
- Hand Code: H111
- Quantity: 150 P

NY MANIFEST:
- EPA ID: NYP004222626
- Country: USA
- Location Address 1: NORTH AVE & LOCKHEED
- Location Address 2: MH 1962
- Location City: NEW ROCHELLE
- Location State: NY
- Location Zip Code: Not reported
- Location Zip Code 4: Not reported

Mailing Info:
- Name: CONSOLIDATED EDISON
- Contact: DENNIS HUACON
- Address: 4 IRVING PLACE RM 828
- City/State/Zip: NEW YORK, NY 10003
- Country: USA
- Phone: 212-460-2757

Manifest:

- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD006982359
- Trans2 State ID: Not reported
- Generator Ship Date: 12/31/2010
- Trans1 Recv Date: 12/31/2010
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 01/04/2011
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004222626
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID: NJD002200046
- Waste Code: Not reported
- Quantity: 150.0
- Units: P - Pounds
- Number of Containers: 1.0
- Container Type: TT - Cargo tank, tank trucks
- Handling Method: T Chemical, physical, or biological treatment.
- Specific Gravity: 1.0
- Year: 2010
- Manifest Tracking Num: 007655578JJK
- Import Ind: N
- Export Ind: N
- Discr Quantity Ind: N
- Discr Type Ind: Y

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AI230 **CON EDISON** **NY MANIFEST** **S118259837**
NNW **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1230 ft. **Site 8 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

NY MANIFEST:
EPA ID: NYP004838332
Country: USA
Location Address 1: LOCKWOOD AVE & NORTH AVE
Location Address 2: TM 1552
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2015
Trans1 Recv Date: 09/14/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/21/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004838332
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014472178JJK
Import Ind: N

CON EDISON (Continued) **S118259837**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM231 **CON ED** **NY MANIFEST** **S118088428**
ENE **HARRISON ST & CEDAR ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1231 ft. **Site 4 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004759924
Country:	USA
Location Address 1:	HARRISON ST & CEDAR ST
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON ED (Continued) **S118088428**

Year:	2015
Manifest Tracking Num:	014091107JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091107JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AC232 **KAGEL HOME** **NY LTANKS** **S107658662**
West **99 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1232 ft. **Site 5 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	360201
Spill Number/Closed Date:	0513684 / 2006-03-09
Spill Date:	2006-02-27
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	2006-03-06
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-27
Spill Record Last Update:	2006-03-09
Spiller Name:	ANDREW KAGEL
Spiller Company:	KAGEL HOME
Spiller Address:	99 UNION AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ANDREW KAGEL
Spiller Phone:	(914) 403-2881
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310321
DEC Memo:	"Homeowner waiting on proposal from N.E. to finish job. 3/6/06 Northeast Environmental reported that the tank was removed along with eight drums of petroleum impacted soil. NFA. TG"
Remarks:	"55o gallon tank had holes and found contaminated soil;"

Material:

Site ID:	360201
Operable Unit ID:	1117385
Operable Unit:	01
Material ID:	2107892
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

KAGEL HOME (Continued) **S107658662**

Tank Test:

AG233 **125** **NY LTANKS** **S104621592**
South **CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.234 mi.
1233 ft. **Site 4 of 4 in cluster AG**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	205498
Spill Number/Closed Date:	0001835 / 2000-05-15
Spill Date:	2000-05-12
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-12
CID:	196
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-12
Spill Record Last Update:	2000-06-21
Spiller Name:	UNKNOWN
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY 10454-
Spiller County:	001
Spiller Contact:	OPERATOR 631
Spiller Phone:	(914) 595-5901
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170636
DEC Memo:	""
Remarks:	"TANK OVER FILL AT THIS LOCATION. 10 GALLONS SPILLED AND THE SPILL WAS CLEANED UP BY THE FIRE DEPT. THE SPILL IS AT THE CHURCH BLESSED SACRMENT CHURCH. BABR MCDONALD FROM COUNTY HEATH DEPT. 637-4890 WAS CALLED TO THE SCENE ALSO."

Material:

Site ID:	205498
Operable Unit ID:	823753
Operable Unit:	01
Material ID:	290047
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

125 (Continued) **S104621592**

Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AI234 **368 NORTH AVE MGMT CO. INC.** **NY UST** **U003994274**
NNW **368 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1234 ft. **Site 9 of 10 in cluster AI**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600272 / Unregulated: <1101 gal. PBS
Operator Name:	Barry Shapiro
Owner Name:	368 North Ave Mgmt Co. Inc.
Owner Street:	27 Country Ridge Road
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/24/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AL235 **GHP 145 HUGUENOT DELAWARE, LLC** **NY AST** **U003994574**
NE **145 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 3 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

WESTCHESTER CO. AST:

PBS Number:	3-497436
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Clemente
Owner Name:	GHP 145 Huguenot Delaware, LLC
Owner Street:	4 West Red Oak Lane, Suite 200
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10604
Tank Number:	3-497436
Status:	1. In-Service
Date Installation:	07/01/1989
Capacity:	6000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

AL236 **LONGINES WITTNAUER WATCH CO** **RCRA NonGen / NLR** **1000235411**
NE **145 HUGUENOT ST** **FINDS** **NYD001317221**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.236 mi. **ECHO**
1247 ft. **Site 4 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	LONGINES WITTNAUER WATCH CO
Facility address:	145 HUGUENOT ST NEW ROCHELLE, NY 10802
EPA ID:	NYD001317221
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact:	Not reported
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 03/11/1985
Site name: LONGINES WITTNAUER WATCH CO
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P013
. Waste name: BARIUM CYANIDE

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P097
. Waste name: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/17/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/19/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:

Registry ID: 110004333720

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD001317221
Country: USA
Location Address 1: 145 HUGUENOT STREET
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: LONGINES WITTHAVER WATCH COMPANY
Contact: LONGINES WITTHAVER WATCH COMPANY

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Address: 145 HUGUENOT STREET
City/State/Zip: NEW RTOCHELLE, NY 10802
Country: USA
Phone: 914-576-1000

Manifest:

Document ID: NJA0309928
Manifest Status: Completed copy
Trans1 State ID: NJDEP#S10
Trans2 State ID: Not reported
Generator Ship Date: 08/19/1987
Trans1 Recv Date: 08/19/1987
Trans2 Recv Date: / /
TSD Site Recv Date: 08/20/1987
Part A Recv Date: 08/28/1987
Part B Recv Date: 08/27/1987
Generator EPA ID: NYD001317221
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NJD089216790
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00224
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 021
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00450
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: P106 - SODIUM CYANIDE
Quantity: 00064
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00036
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1987

Document ID: NJA0062673
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 04/23/1985

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Trans1 Recv Date:	04/23/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/23/1985
Part A Recv Date:	05/24/1985
Part B Recv Date:	05/15/1985
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00030
Units:	P - Pounds
Number of Containers:	002
Container Type:	CW - Wooden boxes
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1985

Document ID:	NJA0056902
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/1985
Trans1 Recv Date:	04/23/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/23/1985
Part A Recv Date:	05/24/1985
Part B Recv Date:	05/15/1985
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	X850 - NJ ONLY
Quantity:	00650
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00400
Units:	P - Pounds

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	CW - Wooden boxes
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1985

Document ID:	NJA0309927
Manifest Status:	Completed copy
Trans1 State ID:	NJDEP#S10
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1987
Trans1 Recv Date:	08/19/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/20/1987
Part A Recv Date:	08/28/1987
Part B Recv Date:	08/27/1987
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID:	NJD089216790
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00036
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00004
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00062
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1987

ECHO:

Envid:	1000235411
Registry ID:	110004333720
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004333720

AL237 **GALESI ENTERPRICES** **NY LTANKS** **S105236833**
NE **145 HUGUENOT ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.236 mi.
1247 ft. **Site 5 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

LTANKS:

Site ID:	259815
Spill Number/Closed Date:	8901038 / 1989-06-01
Spill Date:	1989-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1989-06-01
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212473
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. "
Remarks:	"8K, -.116"

Material:

Site ID:	259815
Operable Unit ID:	927170
Operable Unit:	01
Material ID:	452349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

GALESI ENTERPRICES (Continued) **S105236833**

Tank Test:

Site ID:	259815
Spill Tank Test:	1535410
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0909155
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421828
DEC Region:	3
Spill Date:	2009-11-16
Spill Number/Closed Date:	0909155 / 2009-11-16
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
Contact Phone:	(718) 579-3414
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

Material:

Site ID:	421828
Operable Unit ID:	1177706
Operable Unit:	01
Material ID:	2170525

GALESI ENTERPRICES (Continued) **S105236833**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0909156
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421829
DEC Region:	3
Spill Date:	2009-11-16
Spill Number/Closed Date:	0909156 / 2009-11-16
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
Contact Phone:	(718) 579-3414
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

Material:

Site ID:	421829
Operable Unit ID:	1177707
Operable Unit:	01
Material ID:	2170526
Material Code:	0001A

GALESI ENTERPRICES (Continued) **S105236833**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0308837
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259814
DEC Region:	3
Spill Date:	2003-11-19
Spill Number/Closed Date:	0308837 / 2003-11-19
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-11-19
CID:	322
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-19
Spill Record Last Update:	2003-12-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	CHRIS LALAK
Contact Phone:	(914) 424-4679
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 11/19/03: Spill is unrecoverable per C. Lalak, WCDOH. Recommends NFA at this time."
Remarks:	"approx 10 gal unk oil on roadway - highway dept placing sand "

Material:

Site ID:	259814
Operable Unit ID:	875003
Operable Unit:	01
Material ID:	571327
Material Code:	0066A
Material Name:	unknown petroleum

GALESI ENTERPRICES (Continued) **S105236833**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0109500
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259813
DEC Region:	3
Spill Date:	2001-12-28
Spill Number/Closed Date:	0109500 / 2001-12-28
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-12-28
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-28
Spill Record Last Update:	2002-01-03
Spiller Name:	CHRIS LALAK
Spiller Company:	HEALTH DEPT OFFICE
Spiller Address:	145 HUGUENOT ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CHRIS LALAK
Contact Phone:	(917) 578-9269
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 12/28/2001 C. LALAK @ WCDOH HANDLED. SPILL CLEANED UP. NO FURTHER ACTION."
Remarks:	"all cleaned up less than 1 oz"

Material:

Site ID:	259813
Operable Unit ID:	846776
Operable Unit:	01
Material ID:	527159
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976

GALESI ENTERPRICES (Continued) **S105236833**

Material FA:	Hazardous Material
Quantity:	1.00
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AM238 **CON ED** **NY MANIFEST** **S118088390**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1250 ft. **Site 5 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004759510
Country:	USA
Location Address 1:	HARRISON ST & FOUNTAIN PL
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON ED (Continued) **S118088390**

Year:	2015
Manifest Tracking Num:	014091122JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091122JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM239 **CON EDISON** **NY MANIFEST** **S118089335**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1250 ft. **Site 6 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004769345
Country:	USA
Location Address 1:	FOUNTAIN PL & HARRISON ST
Location Address 2:	MH 8008
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769345
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660843GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118089335**

Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 04/16/2015
Trans1 Recv Date: 04/16/2015
Trans2 Recv Date: 04/20/2015
TSD Site Recv Date: 04/20/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004769345
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 002660843GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AM240 **CON EDISON** **NY MANIFEST** **S118088276**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.237 mi.
1250 ft. **Site 7 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:
EPA ID: NYP004758272
Country: USA
Location Address 1: HARRISON ST & FOUNTAIN PL
Location Address 2: SB 8044
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL

CON EDISON (Continued) **S118088276**

City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091128JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported

CON EDISON (Continued) **S118088276**

Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091128JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM241 **CON EDISON** **NY MANIFEST** **S118089345**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1250 ft. **Site 8 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004769477
Country:	USA
Location Address 1:	FOUNTAIN PL & HARRISON ST
Location Address 2:	SB 8007
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118089345**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660844GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660844GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118089345**

Mgmt Method Type Code: H110

AE242 **MONROE COLLEGE** **NY LTANKS** **S106124169**
East **5 FRANKLIN AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1252 ft. **Site 4 of 4 in cluster AE**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	165556
Spill Number/Closed Date:	0307536 / 2005-03-27
Spill Date:	2003-10-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-10-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-16
Spill Record Last Update:	2005-03-27
Spiller Name:	JIM MOORE
Spiller Company:	MONROE COLLEGE
Spiller Address:	5 FRANKLIN AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JIM MOORE
Spiller Phone:	(914) 403-3458
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	278527
DEC Memo:	"03/27/05 CLEAN UP COMPLETED. SPILL FILE CLOSED BY OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod As per email from WCHD: 03-07536 5 Franklin Ave, NEw Rochelle, NY (also known as 420 Main St, New Rochelle) Tank removed from basement, soil disposed of. NFA"
Remarks:	"recomend repair retest"

Material:

Site ID:	165556
Operable Unit ID:	873930
Operable Unit:	01
Material ID:	501063
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

MONROE COLLEGE (Continued) **S106124169**

Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	165556
Spill Tank Test:	1528740
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AI243 **CASANOVA BROS. REALTY** **NY UST** **U003884076**
NNW **370 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.238 mi.
1257 ft. **Site 10 of 10 in cluster AI**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800088 / Unregulated: <1101 gal. PBS
Operator Name:	Israel Estrada
Owner Name:	Casanova Bros. Realty
Owner Street:	370 North Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/14/2002
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AC244 **TANK TEST FAILURE** **NY LTANKS** **S111239332**
WSW **50 WALNUT ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.240 mi.
1265 ft. **Site 6 of 7 in cluster AC**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	455637
Spill Number/Closed Date:	1107925 / 2013-02-05
Spill Date:	2011-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-21
Spill Record Last Update:	2013-02-06
Spiller Name:	Not reported
Spiller Company:	SAL VIGNA
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	KEN RONK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	410212
DEC Memo:	"9-21-11 Owner is Pietro Vigna and doesn't speak english. Sal is his son. Sal cell: (914)424-2239. Sal has Eastern Env coming out Wed to investigate further. jc 2/6/13: Northeast Environmental disposed of LUST and a total of 21.05 tons of petroleum contaminated soil. Exit sample results showed residual contamination over CP-51 Guidance values. Additional excavation of contaminted soil is not possible with causing possible structural damage to the building foundations. Based upon the information provided, this Department requires no further action at this time. Closed - doesn not meet standarsds. jod"
Remarks:	"tank test failure"

Material:

Site ID:	455637
Operable Unit ID:	1205789
Operable Unit:	01
Material ID:	2202749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

TANK TEST FAILURE (Continued) **S111239332**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AN245 **DOMENICO PROCOPIO PROPERTY** **NY LTANKS** **S103558292**
SSW **618 MAIN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.242 mi.
1279 ft. **Site 1 of 4 in cluster AN**

Relative:
Higher

Actual:
87 ft.

LTANKS:

Site ID:	278454
Spill Number/Closed Date:	9809866 / 2004-03-30
Spill Date:	1998-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-05
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-05
Spill Record Last Update:	2004-03-30
Spiller Name:	DOMINIC PROCOPIO
Spiller Company:	DOMINIC PROCOPIO
Spiller Address:	10 MAPLE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	DOMINIC PROCOPIO
Spiller Phone:	(914) 576-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	226099
DEC Memo:	""
Remarks:	"CHECK PIPING AND RETEST"

Material:

Site ID:	278454
Operable Unit ID:	1067125
Operable Unit:	01
Material ID:	313759
Material Code:	0001A

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 278454
Spill Tank Test: 1546499
Tank Number: 1
Tank Size: 1500
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 0408557
Facility Type: ER
DER Facility ID: 226099
Site ID: 333327
DEC Region: 3
Spill Date: 2004-11-03
Spill Number/Closed Date: 0408557 / 2005-03-17
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2004-11-03
CID: 407
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-11-03
Spill Record Last Update: 2005-04-05
Spiller Name: DOMINICKO PROCOPIO
Spiller Company: Not reported
Spiller Address: 618 MAIN ST
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: DOMINICKO PROCOPIO
Contact Phone: (914) 636-9570

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

DEC Memo: "PBS #3-800233 11/16/2004 Stephan Goreau of WCDOH spill update -- several inches in basement of sewer/oil mix---BHY 4/4/05: Letter to Vincent Rippa, Domenico Procopio Property from Stefan Goreau, WCDOH dated 17Mar2005. WCDOH requires NFA at this time."
Remarks: "Imporperly Abondoned tank."

Material:
Site ID: 333327
Operable Unit ID: 1095482
Operable Unit: 01
Material ID: 575615
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AN246 **DOMENICO PROCOPIO** **NY UST U003988536**
SSW **618 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.242 mi.
1279 ft. **Site 2 of 4 in cluster AN**

Relative: Higher

Actual: 87 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800233 / Unregulated: <1101 gal. PBS
Operator Name: Domenico Procopio
Owner Name: Domenico Procopio
Owner Street: 126 Liberty Avenue
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10805
GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 1500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 11/24/2004
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 9. Copper
Piping External Protection: 0. None
Overfill Prevention: 0. None

DOMENICO PROCOPIO (Continued) **U003988536**

Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 3. Gravity

WESTCHESTER CO. AST:
PBS Number: 3-800233
Site Status: Unregulated: <1101 gal. PBS
GDS Number: Not reported
Operator Name: Domenico Procopio
Owner Name: Domenico Procopio
Owner Street: 126 Liberty Avenue
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10805

Tank Number: 2
Status: 0. Administratively closed
Date Installation: 06/01/1998
Capacity: 330
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported
Piping Location: 1. Aboveground
Piping Type: 9. Copper
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 4. Product Level Gauge (Aboveground Only)
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 3
Status: 0. Administratively closed
Date Installation: 06/01/1998
Capacity: 330
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported
Piping Location: 1. Aboveground
Piping Type: 9. Copper
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 4. Product Level Gauge (Aboveground Only)
Spill Prevention: Not reported

DOMENICO PROCOPIO (Continued) **U003988536**

Dispenser: 2. Suction

AC247 **ROBERTS HOME** **NY LTANKS** **S108298719**
WSW **58 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.243 mi.
1283 ft. **Site 7 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	372634
Spill Number/Closed Date:	0608623 / 2012-08-17
Spill Date:	2006-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2012-08-17
Spiller Name:	TOM ROBERTS
Spiller Company:	ROBERTS HOME
Spiller Address:	58 WALNUT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	TOM ROBERTS
Spiller Phone:	(914) 755-9816
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	322369
DEC Memo:	"8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M"
Remarks:	""

Material:

Site ID:	372634
Operable Unit ID:	1130371
Operable Unit:	01
Material ID:	2120048
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

ROBERTS HOME (Continued) **S108298719**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 372634
Spill Tank Test: 1550391
Tank Number: 1
Tank Size: 550
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AO248 @ **NY LTANKS** **S106971852**
WSW **60 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.244 mi.
1289 ft. **Site 1 of 3 in cluster AO**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Site ID: 346287
Spill Number/Closed Date: 0502010 / 2005-07-17
Spill Date: 2005-05-19
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-05-19
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-05-19
Spill Record Last Update: 2005-07-17
Spiller Name: MR. GALLERO
Spiller Company: Not reported
Spiller Address: 60 WALNUT STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: MR. GALLERO
Spiller Phone: (914) 469-7160
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 292543
DEC Memo: "July 17, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 33.65

@ (Continued) **S106971852**

TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "1000 GALLON TANK HAD HOLES IN IT:"

Material:
Site ID: 346287
Operable Unit ID: 1104017
Operable Unit: 01
Material ID: 584224
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AN249 **VACANT** **NY UST U004177556**
SSW **399 HUGUENOT STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1295 ft. **Site 3 of 4 in cluster AN**

Relative:
Lower

Actual:
83 ft.

WESTCHESTER CO. UST:
Id/Status: 3-801616 / Unregulated
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City: New York
Owner State: NY
Owner Zipcode: 10017
GDS Number: Not reported

Tank Number: 5
Status: 5. Closed - removed
Capacity: 1500
Product Stored: 2. No. 4 fuel oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None

VACANT (Continued) **U004177556**

Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 6
Status: 4. Closed - in place
Capacity: 1000
Product Stored: 2. No. 4 fuel oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 7
Status: 5. Closed - removed
Capacity: 1000
Product Stored: 7. Gasoline
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-801616
Site Status: Unregulated
GDS Number: Not reported
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City/State/Zip: New York, NY 10017

VACANT (Continued) **U004177556**

Tank Number:	1
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	2
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	750
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	3
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported

VACANT (Continued) **U004177556**

Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	4
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

AH250 **COLONIAL CLEANERS CORP** **RCRA NonGen / NLR** **1000338874**
SE **149 NORTH AVE** **NYD982718058**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 8 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	COLONIAL CLEANERS CORP
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 108017405
EPA ID:	NYD982718058
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

COLONIAL CLEANERS CORP (Continued) **1000338874**

Owner/Operator Summary:
- Owner/operator name: COLONIAL CLEANERS CORP
- Owner/operator address: NOT REQUIRED
  NOT REQUIRED, WY 99999
- Owner/operator country: US
- Owner/operator telephone: (212) 555-1212
- Legal status: Private
- Owner/Operator Type: Owner
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

- Owner/operator name: COLONIAL CLEANERS CORP
- Owner/operator address: NOT REQUIRED
  NOT REQUIRED, WY 99999
- Owner/operator country: US
- Owner/operator telephone: (212) 555-1212
- Legal status: Private
- Owner/Operator Type: Operator
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 01/01/2006
- Site name: COLONIAL CLEANERS CORP
- Classification: Not a generator, verified

- Date form received by agency: 07/08/1999
- Site name: COLONIAL CLEANERS CORP
- Classification: Not a generator, verified

- Date form received by agency: 11/30/1988
- Site name: COLONIAL CLEANERS CORP
- Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

COLONIAL CLEANERS CORP (Continued) **1000338874**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

AH251 **FLAMINGO/TYK CLEANERS** **NY DRYCLEANERS** **S110246604**
SE **149 NORTH AV.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 9 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

DRYCLEANERS:

Facility ID:	3-5510-00335
Phone Number:	914-235-1591
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	08SEP19
Install Date:	94/08
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AH252 **FLAMINGO CLEANERS** **RCRA-LQG** **1000299848**
SE **149 NORTH AVE** **NY BROWNFIELDS** **NYD012946885**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.246 mi.
1299 ft. **Site 10 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA-LQG:

Date form received by agency:	07/10/2012
Facility name:	FLAMINGO CLEANERS
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD012946885
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	RICHARD H DORAN
Contact address:	DORSON ENVIRONMENTAL MGMT INC 45 KNOLLWOOD RD SUITE 300 ELMSFORD, NY 10523
Contact country:	US
Contact telephone:	(914) 592-3117
Contact email:	RDORAN@DORSON.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less

FLAMINGO CLEANERS (Continued) **1000299848**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	TAEYOON KIM
Owner/operator address:	149 NORTH AVE
	NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 235-1591
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	V & V CAPITAL LLC
Owner/operator address:	PHILLIPS HILL RD
	NEW CITY, NY 10956
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/14/2011
Owner/Op end date:	Not reported

Owner/operator name:	LUIGI LLESHAJ
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/14/2011
Owner/Op end date:	Not reported

Owner/operator name:	TAEYOON KIM
Owner/operator address:	149 NORTH AVE
	NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 235-1591
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

FLAMINGO CLEANERS (Continued) **1000299848**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

FLAMINGO CLEANERS (Continued) **1000299848**

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/01/2007
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/21/1991
Site name: FLAMINGO CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/10/2006
Date achieved compliance: 08/18/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/03/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/10/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 08/18/2006
Evaluation lead agency: State

BROWNFIELDS:
Program: BCP
Site Code: 335220

FLAMINGO CLEANERS (Continued) **1000299848**

Acres:	0.12
HW Code:	C360078
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/16/2004
Record Updated Date:	05/28/2015
Update By:	DACROSBY
Site Description:	Location: The Flamingo Cleaners site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site is a one-story commercial building with a full basement. The building is divided into four tenant spaces which include a bar/lounge, beauty salon, and two vacant spaces that previously housed a travel agency and a dry-cleaner.Current Zoning/use(s): The site consists of four retail spaces, two of which are currently occupied. The site is zoned for commercial use. The surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a medical center, and a church. The dry cleaning operation is no longer active and the space is currently vacant.Historical Uses: The existing building was constructed in 1941 and used for retail. Flamingo Cleaners began dry cleaning operations in 1958, and ran until 2005 when all dry-cleaning equipment was removed. Site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE).Prior completed investigations include a Phase I Investigation in October of 2003 and a Phase II Investigation completed in March of 2004. The Volunteer entered into a Brownfield Cleanup Agreement in April 2005. A Decision Document was issued in March 2012 for a remedy involving source soil removal and in situ chemical oxidation treatment of groundwater. Based on the extent of the site contamination, a referral to State Superfund for an off-site investigation was completed in December 2007. The groundwater plume was found to be isolated to immediately behind the building and little to no off-site impacts were noted in groundwater, soils, nor in soil vapor.Site Geology/hydrogeology: The site is underlain by glacial till which sits atop highly weathered bedrock. Bedrock ranges from 5 - 22 feet below ground surface. The water table is between 5 - 11 feet below ground surface. Groundwater flow direction dominantly to the south-southeast toward Long Island Sound, however, site specific groundwater flow direction is radial, and seasonally affected.
Env Problem:	Nature and Extent of Contamination: Based on the investigations conducted to date, the primary contaminant of concern at the site is tetrachloroethylene (PCE or perc), a dry cleaning solvent. PCE has been detected in exceedance of SCGs in on-site soils, soil vapor, on-site indoor air, and on-site groundwater. The off-site investigation to date indicates that there are no off-site impacts.Source area soils contained as much as 1,300 parts per million (ppm) of PCE, which exceeds the 1.3 ppm protection of groundwater soil cleanup objective. Immediately outside of the source area, soil concentrations of PCE ranged from 0.06 ppm - 0.91 ppm and did not exceed the soil cleanup objective for commercial use. PCE in groundwater was found at concentrations ranging from 1,000 parts per billion (ppb) - 19,000 ppb, which greatly exceeds the 5 ppb groundwater standard. PCE concentrations in sub-slab soil gas ranged from 15,700 ug/m3 - 570,000 ug/m3, and PCE in indoor air ranged from 115 ug/m3 - 1,040 ug/m3, exceeding NYDOH ambient air guidance value

FLAMINGO CLEANERS (Continued) **1000299848**

of 100 ug/m3 PCE. Concentrations of other volatile organic compounds (VOCs) including trichloroethene (TCE), 1,2-dichloroethene (1,2-DCE) and 1,1,1 trichloroethane (1,1,1 TCA) also exceeded groundwater standards but to a lesser extent. A state-funded RI/FS of the off-site extent of soil vapor and groundwater contamination was conducted from 2009-2011. The results indicate that the groundwater and soil vapor plumes appear to be limited to immediately below the site.Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater and/or soil may move into the soil vapor (air space within the soil), which in turn may move into overlying building and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilate/remove the air beneath the building) has been installed in the on-site building to prevent the indoor air quality from being affected by the contamination in the soil vapor beneath the building. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

NY MANIFEST:

EPA ID:	NYD012946885
Country:	USA
Location Address 1:	149 NORTH AVE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	V & V CAPITAL LLC
Contact:	V&V CAPITAL LLC - FORMER FLAMINGO CLEANERS
Address:	149 NORTH AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	361-586-5900

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2013
Trans1 Recv Date:	01/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	12000
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835158JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	NJD054126164
Generator Ship Date:	01/30/2013
Trans1 Recv Date:	01/30/2013
Trans2 Recv Date:	01/30/2013
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	12080
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835159JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2013
Trans1 Recv Date:	01/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	6160
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835161JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NYC7146663
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	NJ044T468
Generator Ship Date:	05/18/2004
Trans1 Recv Date:	05/18/2004
Trans2 Recv Date:	05/26/2004
TSD Site Recv Date:	05/27/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150

FLAMINGO CLEANERS (Continued) **1000299848**

Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYC3062226
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 09/07/1994
Trans1 Recv Date: 09/07/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 09/07/1994
Part A Recv Date: 10/03/1994
Part B Recv Date: 09/15/1994
Generator EPA ID: NYD012946885
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00560
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC7252402
Manifest Status: Not reported
Trans1 State ID: NYCF7875
Trans2 State ID: NJ044
Generator Ship Date: 12/29/2003
Trans1 Recv Date: 12/29/2003
Trans2 Recv Date: 12/30/2003
TSD Site Recv Date: 01/05/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00156
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7019403

FLAMINGO CLEANERS (Continued) **1000299848**

Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	619TVANJ
Generator Ship Date:	01/17/2003
Trans1 Recv Date:	01/17/2003
Trans2 Recv Date:	01/23/2003
TSD Site Recv Date:	01/23/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7072514
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	NJ044
Generator Ship Date:	07/29/2003
Trans1 Recv Date:	07/29/2003
Trans2 Recv Date:	08/06/2003
TSD Site Recv Date:	08/07/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC5692331
Manifest Status:	Not reported
Trans1 State ID:	NY43803AV
Trans2 State ID:	NJ044
Generator Ship Date:	06/11/2002
Trans1 Recv Date:	06/11/2002
Trans2 Recv Date:	06/12/2002
TSD Site Recv Date:	06/13/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6809681
Manifest Status: Not reported
Trans1 State ID: NY49455JE
Trans2 State ID: T474GL
Generator Ship Date: 08/06/2002
Trans1 Recv Date: 08/06/2002
Trans2 Recv Date: 08/07/2002
TSD Site Recv Date: 08/08/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6422760
Manifest Status: Not reported
Trans1 State ID: NYC2456
Trans2 State ID: Not reported
Generator Ship Date: 04/23/2001
Trans1 Recv Date: 04/23/2001
Trans2 Recv Date: 04/27/2001
TSD Site Recv Date: 04/28/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: MOD095038998
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

FLAMINGO CLEANERS (Continued) **1000299848**

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC6508574
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: NJ044
Generator Ship Date: 09/26/2001
Trans1 Recv Date: 09/26/2001
Trans2 Recv Date: 10/01/2001
TSD Site Recv Date: 10/02/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC5724303
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: T422NYNJ
Generator Ship Date: 01/19/2000
Trans1 Recv Date: 01/19/2000
Trans2 Recv Date: 01/24/2000
TSD Site Recv Date: 01/27/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC6305040
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: T748NYNJ

FLAMINGO CLEANERS (Continued) **1000299848**

Generator Ship Date:	12/06/2000
Trans1 Recv Date:	12/06/2000
Trans2 Recv Date:	12/11/2000
TSD Site Recv Date:	12/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6133296
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	05/02/2000
Trans1 Recv Date:	05/02/2000
Trans2 Recv Date:	05/04/2000
TSD Site Recv Date:	05/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6240633
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	08/15/2000
Trans1 Recv Date:	08/15/2000
Trans2 Recv Date:	08/16/2000
TSD Site Recv Date:	08/18/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

FLAMINGO CLEANERS (Continued) **1000299848**

TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC5644653
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NXNJ
Generator Ship Date:	05/20/1999
Trans1 Recv Date:	05/20/1999
Trans2 Recv Date:	05/24/1999
TSD Site Recv Date:	05/26/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5193562
Manifest Status:	Not reported
Trans1 State ID:	NYRC2745
Trans2 State ID:	FY22NXNJ
Generator Ship Date:	10/13/1999
Trans1 Recv Date:	10/13/1999
Trans2 Recv Date:	10/18/1999
TSD Site Recv Date:	10/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

FLAMINGO CLEANERS (Continued) **1000299848**

Document ID:	NYC5520745
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	CTF0671282
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1998
Trans1 Recv Date:	01/08/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

AH253 **OFF-SITE FLAMINGO CLEANERS** **NY BROWNFIELDS** **S110043637**
SE **149 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 11 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	414661
Acres:	Not reported
HW Code:	C360078A

OFF-SITE FLAMINGO CLEANERS (Continued) **S110043637**

SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/03/2009
Record Updated Date:	03/02/2015
Update By:	DACROSBY
Site Description:	Location: This site is the off-site component of the former Flamingo Dry Cleaners site (C360078). The site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site itself is a one-story commercial building which includes four stores including the vacant dry cleaners. This off-site component is comprised of immediately-surrounding areas. Current Zoning/Uses: Surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a college, a medical facility, and a church. Historical Uses: The on-site building was constructed in 1941 and used for retail. Flamingo Cleaners began operations in 1958 and ran until 2005 when all dry-cleaning equipment was removed. On-site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). A referral for off-site work was completed in December 2007 and a SSF RI/FS Work assignment was approved in March 2009. The RI field work was conducted in the summer of 2009 and fall of 2009. Additional round of gw analyses occurred in spring 2010. The on-going off-site investigation thus far indicates that PCE is not present in environmental media above standards in the area surrounding the site.Site Geology/Hydrogeology: The area surrounding the site is underlain by glacial till which sit atop highly weathered bedrock. Area bedrock ranges from 5-25 feet below ground surface. The water table ranges from 5-11 feet below ground surface. Groundwater flow direction is dominantly to the south-southwest toward Long Island Sound, but site specific groundwater flow direction is radial and seasonally affected.(1/13)
Env Problem:	Nature and Extent of Contamination: Based on investigations to date, the primary contaminant of concern at the site is tetracholoroethylene (PCE), a dry cleaning solvent. On-site, PCE has been detected in soils, soil vapor, indoor air, and groundwater. The off-site investigation to date indicates that there are no off-site impacts. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.
Health Problem:	Not reported

AP254 **MAY PARTNERS, LLC** **NY AST** **A100355569**
NNW **35-45 MAY STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.247 mi.
1306 ft. **Site 1 of 2 in cluster AP**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. AST:

PBS Number:	3-600544
Site Status:	Active
GDS Number:	Not reported
Operator Name:	May Partners, LLC
Owner Name:	May Partners, LLC c/o Andover Properties
Owner Street:	25 East Spring Valley Avenue, Suite 280
Owner Address2:	Not reported
Owner City/State/Zip:	Maywood, NJ 07607

MAY PARTNERS, LLC (Continued) **A100355569**

Tank Number:	001
Status:	5. Closed - removed
Date Installation:	Not reported
Capacity:	4800
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	Not reported
Tank Location:	4. Aboveground: w/ 10% or more below ground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	5000
Product Stored:	2. No. 4 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	0. None

AM255 **FIREHOUSE** **NY LTANKS** **S103037428**
ENE **HARRISON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.252 mi.
1332 ft. **Site 9 of 9 in cluster AM**

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	252028
Spill Number/Closed Date:	9713840 / 1998-03-27
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

FIREHOUSE (Continued) **S103037428**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	FRANK GALELLO
Spiller Phone:	(914) 654-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED. SYSTEM PASSED. NFA"
Remarks:	""

Material:

Site ID:	252028
Operable Unit ID:	1059801
Operable Unit:	01
Material ID:	324831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	252028
Spill Tank Test:	1545673
Tank Number:	2
Tank Size:	5000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported

FIREHOUSE (Continued) **S103037428**

Test Method: Horner EZ Check I or II

AL256 **BERGMAN REALTY SERVICES** **NY LTANKS** **S106972591**
ENE **140 HUGUENOT STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.253 mi.
1334 ft. **Site 6 of 6 in cluster AL**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Site ID:	350100
Spill Number/Closed Date:	0505137 / 2007-11-07
Spill Date:	2005-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	WCDOH
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2007-11-07
Spiller Name:	STEVE RING
Spiller Company:	RING HOME
Spiller Address:	140 HUGINOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVE RING
Spiller Phone:	(732) 855-8600
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	296544
DEC Memo:	"10/13/05 Closure letter sent to the RP from Danielle Jackson of the WCHD based on information submitted in a tank closure report. NFA TG"
Remarks:	""

Material:

Site ID:	350100
Operable Unit ID:	1107682
Operable Unit:	01
Material ID:	2097572
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

BERGMAN REALTY SERVICES (Continued) **S106972591**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 350100
Spill Tank Test: 1549133
Tank Number: 1
Tank Size: 10000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AQ257 **BLESSED SACREMENT CHURCH** **NY LTANKS** **S105996474**
South **15 SHEA PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1393 ft. **Site 1 of 3 in cluster AQ**

Relative:
Higher

Actual:
97 ft.

LTANKS:
Site ID: 167332
Spill Number/Closed Date: 0204856 / 2003-10-03
Spill Date: 2002-08-07
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-08-07
CID: 211
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-08-07
Spill Record Last Update: 2003-12-09
Spiller Name: Not reported
Spiller Company: BLESSED SACREMENT CHURCH
Spiller Address: 15 SHEA PL
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 140984
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

BLESSED SACREMENT CHURCH (Continued) **S105996474**

WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."

Remarks: "DRY LEAK"

Material:

Site ID:	167332
Operable Unit ID:	856138
Operable Unit:	01
Material ID:	519078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	167332
Spill Tank Test:	1527358
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AO258 **APARTMENT BLDG.** **NY LTANKS** **S104950549**
West **114 UNION AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1395 ft. **Site 2 of 3 in cluster AO**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	238808
Spill Number/Closed Date:	9414493 / 1995-02-14
Spill Date:	1995-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-02-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-03-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"ESTIMATED WRONG TANK SIZE SPILL CONTAINED NATL.ENVIR.CO. SPILL CREW ON WAY ENV PROD. AND SERVICES HIRED TO CLEAN UP. WILL EXCAVATE DRYWELL."

Material:

Site ID:	238808
Operable Unit ID:	1012066
Operable Unit:	01
Material ID:	373228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	175.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	151446
Spill Number/Closed Date:	0011198 / 2001-04-06
Spill Date:	2001-01-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-14
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-14
Spill Record Last Update:	2001-04-24
Spiller Name:	Not reported
Spiller Company:	ALBINO FUELS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128711
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE SEE ONE PAGE UDATE BY V. MCCABE 04/06/2001 NORTHEAST COMPLETED CLEANUP. DISPOSED OF 4 DRUMS OF CONTAMINATION. SPILL INFORMATION FORWARDED TO LAW ENFORCEMENT FOR FURTHER ACTION. SPILLS - NO FURTHER ACTION."
Remarks:	"tank overfilled caused spill - spill is contained in a parking lot spiller is - albano fuel - 667-0900 (914)-clean up crew on site at this time"

Material:

Site ID:	151446
Operable Unit ID:	832582
Operable Unit:	01
Material ID:	541520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9414511
Facility Type:	ER
DER Facility ID:	196552
Site ID:	238809
DEC Region:	3
Spill Date:	1995-02-02
Spill Number/Closed Date:	9414511 / 1995-02-13
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-02-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-02-13
Spiller Name:	Not reported
Spiller Company:	REGENT OIL
Spiller Address:	53 CHARLES STREET
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SPILLER MAKING DELIVERY FILLED WRONG HOLE FD & CLEAN UP CREW ON SCENE TANK OVERFILL EP & S HIRED BY SPILLER AND ON SCENE CONTACTED WCHD WILL RESPOND SEE SPILL #94-14493"

Material:

Site ID:	238809
Operable Unit ID:	1008085
Operable Unit:	01
Material ID:	373246
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AP259 **DIMATTOE TTF** **NY LTANKS** **S113820294**
NNW **55 MAY STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.267 mi.
1409 ft. **Site 2 of 2 in cluster AP**

Relative:
Lower

Actual:
79 ft.

LTANKS:

Site ID:	482303
Spill Number/Closed Date:	1301890 / 2013-08-08
Spill Date:	2013-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party.

DIMATTOE TTF (Continued) **S113820294**

	Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2013-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-23
Spill Record Last Update:	2013-08-08
Spiller Name:	Not reported
Spiller Company:	DIMATTOE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	AMELIO DIMATTOE
Spiller Phone:	(914) 403-1942
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	437556
DEC Memo:	"5/23/13 left message on homeowner's phone. Spoke to Kathy, at US Tank Tech Tank is 1000 gal. Real estate transaction, and plans are to retest. dw 07/31/13 Northeast Environmental reported that they cut & cleaned the tank and obtained a soil sample from beneath the tank. The soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"repair/retest pending"

Material:

Site ID:	482303
Operable Unit ID:	1232041
Operable Unit:	01
Material ID:	2230831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	482303
Spill Tank Test:	2493480
Tank Number:	1
Tank Size:	1000
Test Method:	21
Leak Rate:	.70
Gross Fail:	Not reported

DIMATTOE TTF (Continued) **S113820294**

Modified By: jbodee
Last Modified: Not reported
Test Method: Horner EZY3/EZY3 Locator Plus

260
East
1/4-1/2
0.268 mi.
1414 ft.

CITY OF NEW ROCHELLE FIRE **NY LTANKS** **S105995871**
1 HARRISON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
72 ft.

LTANKS:

Site ID:	75380
Spill Number/Closed Date:	0201696 / 2002-09-18
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE FIRE DEPT
Spiller Address:	1 HARRISON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	FRANK GALLELLO-FIRE DEPT
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70557
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST.PBS 3-600407 "

Material:

Site ID:	75380
Operable Unit ID:	854864
Operable Unit:	01
Material ID:	523106
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

CITY OF NEW ROCHELLE FIRE (Continued) **S105995871**

Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 75380
Spill Tank Test: 1527133
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AN261 **CUMBERLAND FARM** **NY LTANKS** **1000553075**
SSW **635 MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.269 mi.
1419 ft. **Site 4 of 4 in cluster AN**

Relative:
Higher

Actual:
85 ft.

LTANKS:
Site ID: 140421
Spill Number/Closed Date: 9206930 / 2005-03-11
Spill Date: 1992-09-16
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 6010
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1992-09-16
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2005-03-12
Spiller Name: Not reported
Spiller Company: EXXON
Spiller Address: Not reported
Spiller City,St,Zip: WESTBURG, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 119925

CUMBERLAND FARM (Continued) **1000553075**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/11/05 per contractors report 7 tanks removes all in good condition (no evidence of holes or cracks; no detect in post excavation samples--close "
Remarks: "DURING TANK REMOVAL CONTAMINATED SOIL DISCOVERED WILL TEST"

Material:
Site ID: 140421
Operable Unit ID: 970699
Operable Unit: 01
Material ID: 407611
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

SPILLS:
Facility ID: 1405322
Facility Type: ER
DER Facility ID: 119925
Site ID: 498745
DEC Region: 3
Spill Date: 2014-08-15
Spill Number/Closed Date: 1405322 / Not Reported
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2014-08-15
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 2014-08-15
Spill Record Last Update: 2016-02-09
Spiller Name: Not reported
Spiller Company: CUMBERLAND FARMS 70288
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999

CUMBERLAND FARM (Continued) **1000553075**

Contact Name:	JOHN
Contact Phone:	Not reported
DEC Memo:	"8-15-14 Spoke with Angela Pimento at CF. She will have John return call to dispatch desk. jm Recv'd callback from Chris Lalak - WCDOH. He has spoken with John. Double wall fiberglass piping from dispensers to tanks. Leak is contained in tanktop sump. System has has been shut down at this time until they figure out what they are going to do. They believe they will probably replace lines. Chris says no leak to environment and he will be taking lead. jm 5-15 new spill 15-01325; Phase 2report 10-15-15 email status request sent to WCHD & Cumby RDB 10-22-15, from Cumby In response to the line failure, CFI engaged Island Pump & Tank (IPT) to perform the repairs. In lieu of replacing the product piping, IPT installed a siphon bar on the regular tanks and removed the submersible pump from the regular tank that had the failed product piping. IPT then removed and capped the regular product piping that had failed. The secondary line was tested and the dispenser pans and STP sumps were hydrostatically tested and passed. RDB 2-16 new SPills 15-10746"
Remarks:	"spill to containment/clean up complete"

Material:

Site ID:	498745
Operable Unit ID:	1248186
Operable Unit:	01
Material ID:	2249583
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0514511
Facility Type:	ER
DER Facility ID:	119925
Site ID:	361248
DEC Region:	3
Spill Date:	2006-03-20
Spill Number/Closed Date:	0514511 / 2006-03-20
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RXAMATO
Referred To:	WCDOH
Reported to Dept:	2006-03-20
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

CUMBERLAND FARM (Continued) **1000553075**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-31
Spiller Name:	MELISSA GLIDEN
Spiller Company:	CUMBERLAND FARM
Spiller Address:	635 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
Contact Phone:	(800) 225-9702 3412
DEC Memo:	"03/21/06: Closed - NFA R. Amato"
Remarks:	"water in the dispenser pan and tyree enroute to clean up"

Material:

Tank Test:

---

262 **NEW ROCHELLE CATH MIDDLE** **NY LTANKS** **S102154123**
South **24 MAPLE AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.270 mi.
1425 ft.

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	80066
Spill Number/Closed Date:	0204857 / 2003-10-03
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE CATH MIDDLE
Spiller Address:	24 MAPLE AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARV
Spiller Phone:	(914) 637-7505

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 74246
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks: ""

Material:
Site ID: 80066
Operable Unit ID: 856140
Operable Unit: 01
Material ID: 519079
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 80066
Spill Tank Test: 1527359
Tank Number: 1
Tank Size: 2000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 9111148
Facility Type: ER
DER Facility ID: 107755
Site ID: 124421
DEC Region: 3
Spill Date: 1992-01-29
Spill Number/Closed Date: 9111148 / 1992-03-17
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1992-01-29
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: 1992-02-05

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Cleanup Meets Std:	True
Last Inspection:	1992-02-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-30
Spill Record Last Update:	1992-03-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"OIL DISCOVERED SEEPING OUT OF GROUND/BLACKTOP WALKWAY (BETWEEN SCHOOL AND BEAUTY SALON) SUSPECT BROKEN RETURN LINE APPROX 30' FROM TANK TO BURNER - 2K TANK AL EASTMAN TO EIR CASTLE OIL CREW ENROUTE"

Material:

Site ID:	124421
Operable Unit ID:	964875
Operable Unit:	01
Material ID:	416206
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9008354
Facility Type:	ER
DER Facility ID:	107755
Site ID:	124420
DEC Region:	3
Spill Date:	1990-10-30
Spill Number/Closed Date:	9008354 / 1990-11-26
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-10-31
Cleanup Meets Std:	True
Last Inspection:	1990-10-31

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-06
Spill Record Last Update:	1990-11-26
Spiller Name:	Not reported
Spiller Company:	CASTLE FUEL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE BURST DURING DELIVERY WC FIRE CONTROL ON SCENE ABSORBANT PADS HAVE BEEN PUT DOWN CHIEF MCCAFFREY CONTACTED BUT HE WASN'T ON SCENE HAS NO INFO."

Material:

Site ID:	124420
Operable Unit ID:	945552
Operable Unit:	01
Material ID:	432188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AR263 **COMMERCIAL PROPERTY** **NY LTANKS** **S112810152**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1442 ft. **Site 1 of 3 in cluster AR**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	476407
Spill Number/Closed Date:	1213228 / 2013-02-04
Spill Date:	2012-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-12-10
CID:	Not reported
Water Affected:	Not reported

COMMERCIAL PROPERTY (Continued) **S112810152**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-10
Spill Record Last Update:	2013-02-04
Spiller Name:	Not reported
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	HAL SHAPIRO
Spiller Phone:	(914) 355-5350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"12-10-12 PBS site. Tank failed with popping. US Tank Tech has been testing since '98. Super was at site during test and Shapiro notified by phone. jc 12/19/12: Update from WCDoH PBS: >>> Lalak, Chris >>cjl1@westchestergov.com> 12/11/2012 4:23 PM >>> 1213228 38 Locust, new Rochelle PBS 3-800080 TTF 3K tank from 84 Tyra/Carlos Lead jod 2/4/2013: Tank passed a retest after piping was repaired. Report entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"1211 THE CALLER IS REPORTING A FAILED TANK TEST."

Material:

Site ID:	476407
Operable Unit ID:	1226235
Operable Unit:	01
Material ID:	2223616
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AR264 **COMMERCIAL SITE** **NY LTANKS** **U003857828**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1442 ft. **Site 2 of 3 in cluster AR**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	239569
Spill Number/Closed Date:	0206043 / 2002-09-26
Spill Date:	2002-09-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

COMMERCIAL SITE (Continued) **U003857828**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-10-29
Spiller Name:	BARRY SHAPIRO
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	38 LOCUST AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	""
Remarks:	"RECOMMENDATION IS TO UNCOVER - REPAIR - AND RE-TEST."

Material:

Site ID:	239569
Operable Unit ID:	857630
Operable Unit:	01
Material ID:	571516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	239569
Spill Tank Test:	1527440
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

COMMERCIAL SITE (Continued) **U003857828**

Site ID:	333366
Spill Number/Closed Date:	0408593 / 2005-02-13
Spill Date:	2004-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-11-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-05
Spill Record Last Update:	2005-02-13
Spiller Name:	BARRY SHAPIRO
Spiller Company:	COMMERCIAL SITE
Spiller Address:	38 LOCUS AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"02/13/05 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-800080 "

Material:

Tank Test:

AS265 **SPILL NUMBER 0208792** **NY LTANKS** **S105997404**
NNW **386 NORTH AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.275 mi.
1452 ft. **Site 1 of 5 in cluster AS**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	71430
Spill Number/Closed Date:	0208792 / 2002-11-26
Spill Date:	2002-11-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported

SPILL NUMBER 0208792 (Continued) **S105997404**

Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-11-26
Spiller Name:	ROBERT CRIILLO
Spiller Company:	WILCO
Spiller Address:	95 PLAIN AV
Spiller City,St,Zip:	NEWROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	CARTER RESIDENCE
Spiller Phone:	(914) 632-6577
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67588
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 SPILL CLEANUP TO BE COMPLETED TOMORROW."
Remarks:	"take pride environmental enroute to clean up the soil"

Material:

Site ID:	71430
Operable Unit ID:	861979
Operable Unit:	01
Material ID:	515786
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AT266 **DEMELIA - TTF** **NY LTANKS** **S117364514**
West **95 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.275 mi.
1453 ft. **Site 1 of 2 in cluster AT**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	500408
Spill Number/Closed Date:	1406916 / 2015-04-14
Spill Date:	2014-10-01
Spill Cause:	Tank Test Failure

DEMELIA - TTF (Continued) **S117364514**

Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-01
Spill Record Last Update:	2015-04-14
Spiller Name:	ROSEMARIE DEMELIA
Spiller Company:	Estate of DeMelia
Spiller Address:	95 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455413
DEC Memo:	"This house is the estate of R Demellia's late mother. Tank failed with only hissing, maybe a line leak but cant be sure. House is being prep'ed for sale....mm 12/08/14: From Envirostar: We pulled a 550 UST at 95 Washington Ave New Rochelle that had previously failed a tank test (spill # 1406916). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Chuck LiVecchi 95 Washington Ave New Rochelle NY jod 3/20/15: Update from Envirostar via email: We removed 6 containers of contaminated soil Between march 12th and yesterday we took samples and back filled the hole. We will Submit for closure. jod 4/13/15: Report with request for closure entered into DecDocs. Post-Ex soil samples show contamination in excess of CP-51 Guidance. Additional information being requested from Envirostar. jod 4/14/2015: Envirostar removed and disposed of the leaking UST and a total of 108.96 tons of petroleum contaminated soil. Some residual contamination over CP-51 Guidance could not be excavated from along the foundation and due to safety concerns with buried utility lines. No evidence of ground water impact noted. Based upon information provided, no further action required at this time. jod"
Remarks:	"550 test failure"

Material:

Site ID:	500408
Operable Unit ID:	1249816
Operable Unit:	01
Material ID:	2251444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

DEMELIA - TTF (Continued) **S117364514**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	500408
Spill Tank Test:	2496432
Tank Number:	1
Tank Size:	550
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AQ267 **BLESSED SACRAMENT HIGH SC** **NY LTANKS** **S106385926**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.278 mi.
1466 ft. **Site 2 of 3 in cluster AQ**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	249284
Spill Number/Closed Date:	0400709 / 2004-07-06
Spill Date:	2004-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-04-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-21
Spill Record Last Update:	2004-07-06
Spiller Name:	LARRY HANSEN
Spiller Company:	BLESSED SACRAMENT HIGH SC
Spiller Address:	24 SHEA PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LARRY HANSEN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

DEC Region: 3
DER Facility ID: 204413
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 07/06/04 TANK PASSED RETEST."
Remarks: "FAILED SUBLINGS RECOMMEND UNCOVER REPAIR & RETEST OR REMOVE: "

Material:
Site ID: 249284
Operable Unit ID: 884909
Operable Unit: 01
Material ID: 491955
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 249284
Spill Tank Test: 1529181
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AQ268 **BLESSED SACRAMENT HS** **NY LTANKS** **S113494296**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.278 mi.
1466 ft. **Site 3 of 3 in cluster AQ**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Site ID: 481320
Spill Number/Closed Date: 1300960 / Not Reported
Spill Date: 2013-04-29
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 6010
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2013-04-29
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester

BLESSED SACRAMENT HS (Continued) **S113494296**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-04-29
Spill Record Last Update:	2013-08-05
Spiller Name:	ED SULLIVAN
Spiller Company:	HIGH SCHOOL
Spiller Address:	24 SHEA PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ED SULLIVAN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"This is a 1K ust. Testing done every year. Appears to be a piping problem, will uncover, repair and retest. WCDOH has been notified....mm 8/5/13 Failed retest. Spoke to Kathy Morgan at US Tank Test. dw "
Remarks:	"tank test failure"

Material:

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2230143
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2229789
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	481320
Spill Tank Test:	2493383
Tank Number:	0
Tank Size:	1000
Test Method:	21

BLESSED SACRAMENT HS (Continued) **S113494296**

Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

---

269 **RESIDENCE** **NY LTANKS** **S106971497**
SSE **64 CHURCH ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.281 mi.
1486 ft.

Relative:
Higher

Actual:
86 ft.

LTANKS:

Site ID:	333255
Spill Number/Closed Date:	0408510 / 2008-05-01
Spill Date:	2004-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-02
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-02-16
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2008-05-01
Spiller Name:	RAMONE OCEGUERA
Spiller Company:	Not reported
Spiller Address:	64 CHURCH ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RAMONE OCEGUERA
Spiller Phone:	(914) 396-7293
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268502
DEC Memo:	"11/22/04 AST ON GROUND UNDER DECK. TANK LOST APPROX 150 GALLONS AFTER TEST. FREE PRODUCT IN SUMP PIT IN BASEMENT. FURTHER INVESTIGATION TO BE DONE BY ADVANCED ENVIRONMENTAL. jod 5/1/2008: Advanced Environmental disposed of LUST and 26.15 tons of contaminated soil. Ground water was impacted and sampled. Spill closure report from ECC submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"tank test failed."

Material:

RESIDENCE (Continued) **S106971497**

Site ID:	333255
Operable Unit ID:	1095424
Operable Unit:	01
Material ID:	575563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	333255
Spill Tank Test:	1548304
Tank Number:	1
Tank Size:	275
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AU270 **CANDREA/GALLETTA RESIDENCE** **NY LTANKS** **S112148789**
WSW **35 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.287 mi.
1517 ft. **Site 1 of 2 in cluster AU**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	465083
Spill Number/Closed Date:	1202322 / 2012-09-13
Spill Date:	2012-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-07
Spill Record Last Update:	2012-09-13

CANDREA/GALLETTA RESIDENCE (Continued) **S112148789**

Spiller Name:	Not reported
Spiller Company:	GALETTA
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	GALETTA
Spiller Phone:	914-497-9141
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	419452
DEC Memo:	"6-7-12 Kathy already notified owner. Spoke with Anthony, owners son-in-law. Told him to forward passing retest to office for spill to be closed. He asked for email to that affect. I sent. jc 6/18/12- US Tank reports that retest failed. Unknown further action. DT 09/13/12 Castlton Environmental reported that they excavated and removed the tank along with 21.04 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"550 gal ust"

Material:

Site ID:	465083
Operable Unit ID:	1215116
Operable Unit:	01
Material ID:	2213205
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AO271 **SPILL NUMBER 0007965** **NY LTANKS** **S104782459**
WSW **45 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.290 mi.
1530 ft. **Site 3 of 3 in cluster AO**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	61314
Spill Number/Closed Date:	0007965 / 2000-10-26
Spill Date:	2000-10-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-06

SPILL NUMBER 0007965 (Continued) **S104782459**

CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-06
Spill Record Last Update:	2000-11-07
Spiller Name:	Not reported
Spiller Company:	ALBANO FUEL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	ALBANO FUEL
Spiller Phone:	(914) 667-0900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/26/2000 TRI-STATE COMPLETED CLEANUP AFTER DEC INSPECTION. INITIAL SPILL BY ALBANO FUEL WAS NEVER REPORTED. NFA"
Remarks:	"SPILL OCCURRED DURING FILL. TRI STATE WAS CONTRACTED FOR CLEAN UP."

Material:

Site ID:	61314
Operable Unit ID:	830442
Operable Unit:	01
Material ID:	545482
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV272 **RUSH MFG. CORP.** **CORRACTS** **1000201737**
SW **10-12 PINE CT** **RCRA-CESQG** **NYD075436394**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY Spills**
0.291 mi. **FINDS**
1535 ft. **Site 1 of 4 in cluster AV** **NJ MANIFEST**
RI MANIFEST
Relative: **NY MANIFEST**
Lower **ECHO**

Actual: CORRACTS:
56 ft.

EPA ID:	NYD075436394
EPA Region:	02
Area Name:	SITEWIDE

RUSH MFG. CORP. (Continued) **1000201737**

Actual Date: 19940503
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD075436394
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19920922
Action: CA050 - RFA Completed
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: RUSH MANUFACTURING CORP
Facility address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
EPA ID: NYD075436394
Mailing address: PINE CT
NEW ROCHELLE, NY 10801
Contact: DENNIS MCNAMARA
Contact address: PINE CT
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 636-2700
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: TELEDYNE HYDRA-POWER

RUSH MFG. CORP. (Continued) **1000201737**

Owner/operator address: 10-12 PINE COURT
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (914) 632-2200
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RUSH MANUFACTURING CORP
Owner/operator address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 636-2700
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/09/1997
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE

RUSH MFG. CORP. (Continued) **1000201737**

SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 02/25/1992
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980
Site name: RUSH MANUFACTURING CORP
Classification: Not a generator, verified

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

RUSH MFG. CORP. (Continued) **1000201737**

SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 12/31/1979
Site name: RUSH MANUFACTURING CORP
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 09/22/1992
Event: RFA Completed

Event date: 05/03/1994
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/26/1990
Date achieved compliance: 05/02/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/12/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/23/1989
Date achieved compliance: 05/12/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/16/1988
Date achieved compliance: 11/17/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/09/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/27/1987
Date achieved compliance: 11/17/1988
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/19/1986
Date achieved compliance: 05/27/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/15/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Area of violation: Generators - General
Date violation determined: 02/23/1984
Date achieved compliance: 10/07/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/26/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/02/1990
Evaluation lead agency: State

Evaluation date: 02/23/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/12/1989
Evaluation lead agency: State

Evaluation date: 03/16/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: State

Evaluation date: 03/11/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: EPA

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/27/1986
Evaluation lead agency: State

Evaluation date: 02/23/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/07/1985
Evaluation lead agency: State

SPILLS:

RUSH MFG. CORP. (Continued) **1000201737**

Facility ID:	0901536
Facility Type:	ER
DER Facility ID:	350696
Site ID:	413531
DEC Region:	3
Spill Date:	2009-05-07
Spill Number/Closed Date:	0901536 / 2009-06-22
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-06-22
Spiller Name:	Not reported
Spiller Company:	ALPHA MEDICAL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	NIKI
Contact Phone:	(914) 777-1930
DEC Memo:	"5/7/09 At a construction site, contaminated soils were encountered, which was confirmed by soil tests done by Northeast. They will be doing the site remediation and will submit a cleanup report. dw 06/12/09 Northeast Environmental provided oversight activity when petroleum impacted soil was discovered and need to be removed. Remediation consisted of the removal of 425.66 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were all below DEC guidance values. NFA required. TG"
Remarks:	"1231 The caller advised dispatch North East Environmental will conduct the clean up. The caller requested a call back. No water ways affected."

Material:

Site ID:	413531
Operable Unit ID:	1169955
Operable Unit:	01
Material ID:	2161660
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Oxygenate: Not reported

Tank Test:

Facility ID:	0804532
Facility Type:	ER
DER Facility ID:	350696
Site ID:	401456
DEC Region:	3
Spill Date:	2008-07-21
Spill Number/Closed Date:	0804532 / 2008-09-26
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-21
Spill Record Last Update:	2008-09-26
Spiller Name:	MICHEAL
Spiller Company:	COMMERCIAL MACHINE SHOP
Spiller Address:	10-12 PINE COURT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MICHEAL
Contact Phone:	(845) 561-1512
DEC Memo:	"08/01/08 Conklin Services & Construction submitted a Limited Subsurface Investigation Report. Four geoprobe borings were placed around an abandoned tank. Slight soil contamination exists in borings 1 and 2, however the levels are below DEC TAGM guidance values. NFA TG"
Remarks:	"SOIL BORINGS SHOWED CONTAMINATED SHOP"

Material:

Site ID:	401456
Operable Unit ID:	1158245
Operable Unit:	01
Material ID:	2149301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

RUSH MFG. CORP. (Continued) **1000201737**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

FINDS:

Registry ID: 110009468343

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

EPA Id:	NYD075436394
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001619722SKS
EPA ID:	NYD075436394
Date Shipped:	02/23/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/26/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	002115978SKS
EPA ID:	NYD075436394
Date Shipped:	10/01/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	5 G

Manifest Number:	001803673SKS
EPA ID:	NYD075436394
Date Shipped:	05/08/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001811141SKS
EPA ID:	NYD075436394
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 8 G

Manifest Number: 002486638SKS
EPA ID: NYD075436394
Date Shipped: 01/29/2010
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/01/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H020
Quantity: 7 G

RUSH MFG. CORP. (Continued) **1000201737**

Manifest Number:	000266181CEX
EPA ID:	NYD075436394
Date Shipped:	10/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	9 G

Manifest Number:	001632477SKS
EPA ID:	NYD075436394
Date Shipped:	01/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001819324SKS
EPA ID:	NYD075436394
Date Shipped:	07/16/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

RI MANIFEST:

EPA Id:	NYD075436394
Manifest Document Number:	CTC0168898
GEN Cert Date:	10/7/1991
TSDF Id:	CTD021816889
TSDF Name:	UNITED
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Transporter 2 Name:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported

Details:

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991

RUSH MFG. CORP. (Continued) **1000201737**

Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991
Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

NY MANIFEST:

EPA ID:	NYD075436394
Country:	USA
Location Address 1:	10-12 PINE COURT
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	6908

Mailing Info:

Name:	TELEDYNE HYDRA-POWER INC
Contact:	MARCY LATELLA
Address:	10-12 PINE COURT
City/State/Zip:	NEW ROCHELLE, NY 10801 6908
Country:	USA
Phone:	914-636-2700

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/2009
Trans1 Recv Date:	10/01/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	5.0
Units:	G - Gallons (liquids only)* (8.3 pounds)

RUSH MFG. CORP. (Continued) **1000201737**

Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002115978SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	02/23/2009
Trans1 Recv Date:	02/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	7.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001619722SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2009
Trans1 Recv Date:	07/16/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	8.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001819324SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2009
Trans1 Recv Date:	05/08/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	7.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001803673SKS

RUSH MFG. CORP. (Continued) **1000201737**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	08/31/2009
Trans1 Recv Date:	08/31/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	8.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001811141SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2009
Trans1 Recv Date:	10/30/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2009

RUSH MFG. CORP. (Continued) **1000201737**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	9.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000266181CEX
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2008
Trans1 Recv Date:	08/22/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/22/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	77.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001491827SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

RUSH MFG. CORP. (Continued) **1000201737**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: CTD1170550
Manifest Status: Not reported
Trans1 State ID: CTJ71372
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2004
Trans1 Recv Date: 09/14/2004
Trans2 Recv Date: 09/16/2004
TSD Site Recv Date: 09/21/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: CTD002593
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: CTF1045117
Manifest Status: Not reported
Trans1 State ID: CTJ11372
Trans2 State ID: V59864CT
Generator Ship Date: 05/25/2004
Trans1 Recv Date: 05/25/2004
Trans2 Recv Date: 05/26/2004
TSD Site Recv Date: 06/01/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: CTD002593
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: CTF1140188
Manifest Status: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 State ID:	CT30006A
Trans2 State ID:	VS9864
Generator Ship Date:	06/23/2003
Trans1 Recv Date:	06/23/2003
Trans2 Recv Date:	06/28/2003
TSD Site Recv Date:	07/07/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	CTD021816889
TSDF ID:	CTD002593887
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC5692522
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	CAFT97593
Generator Ship Date:	05/21/2002
Trans1 Recv Date:	05/21/2002
Trans2 Recv Date:	05/29/2002
TSD Site Recv Date:	06/01/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	MOD095038998
TSDF ID:	KYD053348108
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NJA4016263
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2001
Trans1 Recv Date:	12/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/12/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA3218557
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	07/26/2001
Trans1 Recv Date:	07/26/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00453
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA3218563
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2001
Trans1 Recv Date:	10/10/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.

RUSH MFG. CORP. (Continued) **1000201737**

Specific Gravity: 01.00
Year: 2001

Document ID: NJA3163834
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 06/14/2001
Trans1 Recv Date: 06/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00430
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NJA3051384
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: H10364
Generator Ship Date: 11/08/2000
Trans1 Recv Date: 11/08/2000
Trans2 Recv Date: 11/09/2000
TSD Site Recv Date: 11/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00127
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NJA3084154
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: H10364
Generator Ship Date: 08/03/2000

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 Recv Date:	08/03/2000
Trans2 Recv Date:	08/07/2000
TSD Site Recv Date:	08/09/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00435
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA2819479
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	02/10/2000
Trans1 Recv Date:	02/10/2000
Trans2 Recv Date:	02/14/2000
TSD Site Recv Date:	02/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA3009958
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	05/12/1999
Trans1 Recv Date:	05/12/1999
Trans2 Recv Date:	05/13/1999
TSD Site Recv Date:	05/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	NJD002182897

RUSH MFG. CORP. (Continued) **1000201737**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00435
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	NJA2839958
Manifest Status:	Not reported
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/1998
Trans1 Recv Date:	04/21/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

ECHO:

Envid:	1000201737
Registry ID:	110009468343
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110009468343

AV273 **GKIDS REALTY** **NY LTANKS** **S105995601**
SW **10/12 PINE COURT** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.291 mi.
1535 ft. **Site 2 of 4 in cluster AV**

Relative:
Lower

Actual:
56 ft.

LTANKS:

Site ID:	235436
Spill Number/Closed Date:	0200337 / 2003-12-09
Spill Date:	2002-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

GKIDS REALTY (Continued) **S105995601**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-04-10
CID:	204
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-10
Spill Record Last Update:	2003-12-10
Spiller Name:	GKIDS REALTY
Spiller Company:	GKIDS REALTY
Spiller Address:	10/12 PINE COURT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MICHAEL GOLD
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193919
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER #2 PBS 3-504998 handled by WCHD 12/09/03 TANK CLOSED IN PLACE, SAMPLE RESULTS BELOW TAGM. SPILL CLOSED BY WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE - RECOMMEND TO ISOLATE PIPING AND RETEST "

Material:

Site ID:	235436
Operable Unit ID:	851333
Operable Unit:	01
Material ID:	525339
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	235436
Spill Tank Test:	1527023
Tank Number:	1
Tank Size:	5000
Test Method:	99
Leak Rate:	.00
Gross Fail:	Not reported

GKIDS REALTY (Continued) **S105995601**

Modified By:	Spills
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v

AT274 **BRAM REALTY** **NY LTANKS** **S109583709**
West **105 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
85 ft.

LTANKS:

Site ID:	414506
Spill Number/Closed Date:	0902464 / 2010-02-01
Spill Date:	2009-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-01
Spill Record Last Update:	2010-02-01
Spiller Name:	HAL SHAPIRO
Spiller Company:	BRAM REALTY
Spiller Address:	105 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	363644
DEC Memo:	"6-1-09: V.Mc.^ Hal/BRAM REALTY: Left Mess: Req.Callbk. to dispt &/or J.O'Dee. 6-3-09: HAL SHAPIRO CALLED AND STATED IS WAS AWARE OF PROPER PROCEDURES TO FOLLOW. HE WILL CONTACT HIS OIL CO. FOR DIRECTION AND NOTIFY DEC OF OUTCOME. 01/25/10 Enviroshield reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was obseved in the tank excavation. NFA TG "
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST UNK IF ANY PRODUCT WAS SPILLED."

Material:

Site ID:	414506
Operable Unit ID:	1170891
Operable Unit:	01

BRAM REALTY (Continued) **S109583709**

Material ID:	2162674
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AU275 **MERLUCCI RESIDENCE** **NY LTANKS** **S111063886**
WSW **30 CHARLES STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AU**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	450778
Spill Number/Closed Date:	1103221 / 2011-11-14
Spill Date:	2011-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-22
Spill Record Last Update:	2011-11-14
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	MR MERLUCCI
Spiller Phone:	(914) 632-2099
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	405335
DEC Memo:	"6/22/11 UST is 62 years old, according to Ms. Merlucci. House is for sale. US Tank Tech has notified Town & Country Oil not evacuate tank prior to further action (repair, retest, tank pull) of owner. dw 11/14/11: UST removed by JM Associates. Report states tank was

MERLUCCI RESIDENCE (Continued) **S111063886**

inspected and no corrosion holes were found. Soil samples taken from tank grave showed minor amounts of contamination, most below CP-51 with a few slight exceedences of SVOCs. Excavation was backfilled. Report will be entered into eDocs. jod"

Remarks: "repair retest pending or removal"

Material:

Site ID:	450778
Operable Unit ID:	1200979
Operable Unit:	01
Material ID:	2197455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AS276 **KGM PROPERTY ASSOC.** **NY LTANKS** **U003647638**
NNW **394 N. AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.295 mi.
1557 ft. **Site 2 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	69270
Spill Number/Closed Date:	9202033 / 1993-01-27
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1993-01-27
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-20
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ

KGM PROPERTY ASSOC. (Continued) **U003647638**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65872
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK IS 38 YEARS OLD THIS TANK WAS ORIGINAL REPORTED UNDER #9201744 BUT IS LOCATED AT DIFFERENT ADDRESS PETRO-TITE -.422 GPH"

Material:

Site ID:	69270
Operable Unit ID:	966124
Operable Unit:	01
Material ID:	557154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	69270
Spill Tank Test:	1540014
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AS277 **KGM REALTY CO.** **NY LTANKS** **S100493525**
NNW **396 NORTH AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.297 mi.
1566 ft. **Site 3 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	89642
Spill Number/Closed Date:	9201744 / 1993-01-27
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1993-01-27
Cleanup Meets Standard:	False
SWIS:	6010

KGM REALTY CO. (Continued) **S100493525**

Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-13
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK #1 IS 64 YEARS OLD AND TANK #2 IS 38 YEARS OLD WILL EIR TANK #2 NEXT WEEK"

Material:

Site ID:	89642
Operable Unit ID:	969160
Operable Unit:	01
Material ID:	413039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	89642
Spill Tank Test:	1539987
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AS278 **GETTY# 677** **NY LTANKS** **S103482965**
NNW **381 NORTH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.299 mi.
1577 ft. **Site 4 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	242546
Spill Number/Closed Date:	0400912 / 2005-01-18
Spill Date:	2004-04-27
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-04-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-27
Spill Record Last Update:	2005-01-18
Spiller Name:	STEVEN PHELTS
Spiller Company:	GETTY# 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVEN PHELTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 1/18/2005 close and handle under existing spill 9003146 "
Remarks:	"FOUND CONTAMINATED SOIL WHILE REMOVING TANK: "

Material:

Site ID:	242546
Operable Unit ID:	882894
Operable Unit:	01
Material ID:	555170
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

SPILLS:

Facility ID:	1012947
Facility Type:	ER
DER Facility ID:	401849
Site ID:	447247
DEC Region:	3
Spill Date:	2011-03-29
Spill Number/Closed Date:	1012947 / 2011-03-31
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6038
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2011-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-29
Spill Record Last Update:	2011-03-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 786-4945
DEC Memo:	"3-29-11 Called and left message for Mike to return call to dispatch desk. jm 3-31-11 Spoke with Mike. Spill was as stated and cleanup completed. jm"
Remarks:	"contained to bay floor, clean up"

Material:

Site ID:	447247
Operable Unit ID:	1197384
Operable Unit:	01
Material ID:	2193703
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	1005811
Facility Type:	ER
DER Facility ID:	199318
Site ID:	439142
DEC Region:	3
Spill Date:	2010-08-25
Spill Number/Closed Date:	1005811 / 2010-08-25
Spill Cause:	Housekeeping
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-08-25
Spill Record Last Update:	2010-08-25
Spiller Name:	MIKE CARR
Spiller Company:	GETTY
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"8/25/10 Confirmed clean up with caller, nfa...mm"
Remarks:	"Caller stated they had spilt waste oil on concrete, Are has been cleaned up."

Material:

Site ID:	439142
Operable Unit ID:	1189791
Operable Unit:	01
Material ID:	2184749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	1001015
Facility Type:	ER
DER Facility ID:	199318
Site ID:	433723
DEC Region:	3
Spill Date:	2010-04-27
Spill Number/Closed Date:	1001015 / 2010-04-27
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2010-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-04-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-05-10
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CARRIE WILSEY
Contact Phone:	(518) 786-3200
DEC Memo:	"4/27/10 - Spill cleaned up. NFA. KAB 5/10/10: Update from Denise Heinzinger of WCDOH who inspected: #1001015 small spill onto concrete at 381 North Ave, New Rochelle, clean up performed jod"
Remarks:	"1 pint onto concrete. Clean up complete"

Material:

Site ID:	433723
Operable Unit ID:	1184583
Operable Unit:	01
Material ID:	2178854
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	0912229
Facility Type:	ER
DER Facility ID:	199318
Site ID:	425106
DEC Region:	3
Spill Date:	2010-02-23
Spill Number/Closed Date:	0912229 / 2010-02-23
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-02-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-23
Spill Record Last Update:	2010-03-30
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"2/23/10 confirmed clean up, nfa...mm"
Remarks:	"HALF GALLON OF WASTE OIL TO CONCRETE CLEAN UP WAS DONE."

Material:

Site ID:	425106
Operable Unit ID:	1180837
Operable Unit:	01
Material ID:	2174836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

GETTY# 677 (Continued) **S103482965**

Facility ID:	0900607
Facility Type:	ER
DER Facility ID:	199318
Site ID:	412555
DEC Region:	3
Spill Date:	2009-04-16
Spill Number/Closed Date:	0900607 / 2009-04-16
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RXAMATO
Referred To:	Not reported
Reported to Dept:	2009-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-16
Spill Record Last Update:	2009-04-16
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CARRIE WILSEY
Contact Phone:	(518) 369-7822
DEC Memo:	"4/17/09: Vac truck pumped out dispenser sump...close/nfa..ra"
Remarks:	"DUE TO POOR HOUSEKEEPING A HALF GALLON OF PRODUCT WAS SPILLED TO CONRETE BAY FLOORS. CLEAN UP WAS DONE."

Material:

Site ID:	412555
Operable Unit ID:	1169019
Operable Unit:	01
Material ID:	2160665
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons
Recovered:	.50
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

AR279 **APT. BUILDING** **NY LTANKS** **S102660713**
ESE **55-59 LOCUST AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.301 mi.
1587 ft. **Site 3 of 3 in cluster AR**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	168647
Spill Number/Closed Date:	9200639 / 1992-06-26
Spill Date:	1992-04-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-05-12
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1992-05-12
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	1998-01-14
Spiller Name:	Not reported
Spiller Company:	N.Y. PROPERTIES CO.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142042
DEC Memo:	""
Remarks:	"TWO UC TANKS WERE BURIED RAIN FORCES OIL UP THROUGH BLACKTOP MGNT. CO.APPLIES SPEEDI-DRY BUT DOES NOT REPORT OR REPAIR"

Material:

Site ID:	168647
Operable Unit ID:	964508
Operable Unit:	01
Material ID:	415419
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

APT. BUILDING (Continued) **S102660713**

Tank Test:

AW280 **BLESSED SACRAMENT CHURCH** **NY LTANKS** **S100165619**
SSE **SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.309 mi.
1629 ft. **Site 1 of 3 in cluster AW**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	324974
Spill Number/Closed Date:	8704259 / 1987-11-20
Spill Date:	1987-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-11-20
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-08-02
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-30
Spill Record Last Update:	1987-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261780
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST. / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST RETEST PASSED.NFA. "
Remarks:	"TTTF-TWO TANKS FAILED"

Material:

Site ID:	324974
Operable Unit ID:	908133
Operable Unit:	01
Material ID:	466902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 324974
Spill Tank Test: 1531452
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

AX281 **PROFESSIONAL BUILDING COP** **NY LTANKS** **S108982494**
SSW **421 HUGUENOT STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.311 mi.
1642 ft. **Site 1 of 2 in cluster AX**

Relative:
Lower

Actual:
77 ft.

LTANKS:
Site ID: 369299
Spill Number/Closed Date: 0606014 / 2007-01-29
Spill Date: 2006-08-23
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: WCDOH
Reported to Dept: 2006-08-24
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-08-24
Spill Record Last Update: 2007-01-29
Spiller Name: GERRI SEENY
Spiller Company: PROFESSIONAL OFFICE CORP
Spiller Address: 421 HUGUENOT STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: GERRI SEENY
Spiller Phone: (914) 632-3400
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 319185
DEC Memo: "RECOMMENDING ISOLATION. 0606014 - 421 Huguenot St, New Rochelle -

PROFESSIONAL BUILDING COP (Continued) **S108982494**

removed petrometer and remote fill from system and retested, passed. NFA. 10/23/06 test date"
Remarks: ""

Material:
Site ID: 369299
Operable Unit ID: 1127138
Operable Unit: 01
Material ID: 2116724
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 369299
Spill Tank Test: 1550220
Tank Number: 1
Tank Size: 3000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 0711337
Facility Type: ER
DER Facility ID: 319185
Site ID: 392804
DEC Region: 3
Spill Date: 2008-01-28
Spill Number/Closed Date: 0711337 / 2008-06-24
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: WCHD
Referred To: SCHNEIDER
Reported to Dept: 2008-01-28
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Remediation Phase:	0
Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2008-06-24
Spiller Name:	GERRY
Spiller Company:	PROFESSIONAL BUILDING COP
Spiller Address:	421 HUGUENOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	GERRY
Contact Phone:	(914) 632-3400
DEC Memo:	"Spoke to Gerry. Danielle Jackson of WCHD may be handling. WCHD to inspect today. 06/24/08 Wayne Schneider WCHD reported 421 Huguenot St, New Rochelle - leaking tank. Contaminated soil remediated. See attached NFA TG "
Remarks:	"HOLES AND CONTAMINATED SOIL"

Material:

Site ID:	392804
Operable Unit ID:	1149789
Operable Unit:	01
Material ID:	2140347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	392804
Spill Tank Test:	2384563
Tank Number:	Not reported
Tank Size:	3000
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Unknown

---

282 West 1/4-1/2 0.311 mi. 1644 ft.

Relative: Higher

Actual: 90 ft.

FRANKA INC. **NY LTANKS** **S104276153**
132-143 UNION AVE. **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	176106
Spill Number/Closed Date:	9312205 / 1995-11-09
Spill Date:	1994-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

FRANKA INC. (Continued) **S104276153**

Cleanup Ceased:	1995-11-09
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1995-11-08
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-24
Spill Record Last Update:	1995-11-27
Spiller Name:	Not reported
Spiller Company:	REGENT OIL CO.
Spiller Address:	53 CHARLES STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148008
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/95 FINAL INSPECTION PERFORMED TRENCH IS OIL FREE SUMP PIT IS OIL FREE BASEMENT IS FREE OF PETROLEUM NO OIL STAIN ON SIDEWALK"
Remarks:	"1K TANK UNDERGROUND POSSIBLE LEAK CLEAN UP CREW ENROUTE"

Material:

Site ID:	176106
Operable Unit ID:	994225
Operable Unit:	01
Material ID:	391197
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AW283 **APARTMENT HOUSE** **NY LTANKS** **S106385339**
SSE **156-168 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1652 ft. **Site 2 of 3 in cluster AW**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	267104
Spill Number/Closed Date:	0312650 / 2004-04-22
Spill Date:	2004-02-13
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-02-13
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-13
Spill Record Last Update:	2004-04-22
Spiller Name:	JIM DONELAN
Spiller Company:	PROTEST
Spiller Address:	PO BOX 1937
Spiller City,St,Zip:	WEST BABYLON, NY 11704
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 698-4100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217585
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 04/22/04 TANK PASSED A RETEST ON 3-22-04. NFA jbo"
Remarks:	"Failed tank test"

Material:

Tank Test:

Site ID:	267104
Spill Tank Test:	1528979
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AW284 **FAILED TANK TEST** **NY LTANKS** **S114561821**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1652 ft. **Site 3 of 3 in cluster AW**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	488939
Spill Number/Closed Date:	1308221 / Not Reported
Spill Date:	2013-11-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-11-12
Spill Record Last Update:	2013-11-22
Spiller Name:	WILLIE
Spiller Company:	FAILED TANK TEST
Spiller Address:	156 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	WILLIE
Spiller Phone:	(914) 774-2508
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	"11/12/13: Residential tank test failure. No indication of a release at this time. Message sent to Elite requesting additional information on the owner, or their realtor. jod 11/12/13: Update received from Chris Lalak. This is not a residential tank. This is a 10K #4 Oil tank, PBS 3-600412. Wayne Schneider will follow up on retest. jod"
Remarks:	"Tank test failure"

Material:

Site ID:	488939
Operable Unit ID:	1238546
Operable Unit:	01
Material ID:	2238468
Material Code:	9999
Material Name:	other - failed tank test
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

FAILED TANK TEST (Continued) **S114561821**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 488939
Spill Tank Test: 2494704
Tank Number: 1
Tank Size: 10000
Test Method: 21
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: JBODEE
Last Modified: Not reported
Test Method: Horner EZY3/EZY3 Locator Plus

AS285 **DIPASQUALE PROPERTY** **NY LTANKS** **S111063882**
NNW **400 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1677 ft. **Site 5 of 5 in cluster AS**

Relative:
Lower

Actual:
70 ft.

LTANKS:
Site ID: 450672
Spill Number/Closed Date: 1103122 / 2012-04-26
Spill Date: 2011-06-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2011-06-20
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2011-06-20
Spill Record Last Update: 2012-04-26
Spiller Name: MR CHARLIE DIPASQUALE
Spiller Company: NDR GROUP
Spiller Address: 400 NORTH AVE
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 999
Spiller Contact: MR DIPASQUALE
Spiller Phone: (914) 633-7092
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 404310
DEC Memo: "6/20/11: This spill initially reported as a residential TTF. Property is actually a commercial office building with apartments on

DIPASQUALE PROPERTY (Continued) **S111063882**

the second floor. Previous Spill number for this site is 1102214 which was reported on May 27th. Owner informed US Tank Tech of the prior Phase I site investigation, but apparently did not inform them of the Phase II which found high levels of contamination. US Tank Tech reports they were hired to test the in-service 550 gallon heating oil tank, and perform a site investigation to locate a second, out-of-service tank. The 550 failed the vaccuum test, petroleum odors evident in the well point. US Tank Tech also reports they believe the second out-of-service tank may be located under the office building. Owner states the second tank is a 275 gallon heating oil, but that can not be confirmed at this time. US Tank Tech also reports there are at least two additional sets of fill and vent pipes, for other out-of-service or abandoned USTs. Tester also noted petroleum odors from the basement sump pit. jod 6/21/11: US Tank Tech reported that the owner says he hired Northeast Environmental to address these two spills issues. Message sent to Northeast asking for confirmation. jod 9/29/11: Northeast reports the owner has hired them to begin investigation and remediation. jod 10/21/11: The UST has been removed by Northeast and contaminated soil is evident. Remediation work is being scheduled. jod 4/26/2012: Closure report from Northeast Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"

Remarks: "repair/retest pending"

Material:

Site ID:	450672
Operable Unit ID:	1200876
Operable Unit:	01
Material ID:	2197327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV286 **INDUSTRIAL OVERALL SERVICES FORMER** **RCRA-LQG** **1004571492**
SW **30 PINE ST** **NY SHWS** **NYD986925808**
1/4-1/2 **NEW ROCHELLE, NY 10805** **NY Spills**
0.320 mi. **FINDS**
1691 ft. **Site 3 of 4 in cluster AV** **NJ MANIFEST**
NY MANIFEST
Relative: **ECHO**
Lower

Actual: **49 ft.**

RCRA-LQG:

Date form received by agency:	06/27/2012
Facility name:	INDUSTRIAL OVERALL SERVICES FORMER
Facility address:	30 PINE ST NEW ROCHELLE, NY 10805
EPA ID:	NYD986925808
Mailing address:	PINE ST

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

NEW ROCHELLE, NY 10805
Contact: BURT DORFMAN
Contact address: BARTELS AVE
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (845) 353-3500
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address: BARTELS AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (845) 353-3500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2010
Owner/Op end date: Not reported

Owner/operator name: NYS DEPT ENVIRONMENTAL CONSERVATION
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 12/13/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 12/16/2008
Site name: BAKERS PRIDE OVEN
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: BAKERS PRIDE OVEN CO INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/12/1994
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/14/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SHWS:
Program: HW
Site Code: 355304
Classification: N
Region: 3
Acres: 3.75
HW Code: 360087
Record Add: 11/08/2005
Record Upd: 07/21/2009
Updated By: RXKEATIN
Site Description: The Baker?s Pride site is located at 30 Pine Street in the City of New Rochelle, Westchester County, NY. The surrounding area is urban with commercial and residential establishments mixed in between the commercial businesses. The Baker?s Pride site is an approximately 3.75 acre flat to severely sloping irregularly shaped parcel. The Baker?s Pride building occupies approximately 111,450 sf of building space and occupies the majority of the property. Baker?s Pride owns the Bakers Pride Oven Company Inc and is engaged in the production of restaurant/commercial grade ovens and broilers.The site is bordered by Metro North railroad tracks to the west and northwest, a mix of commercial and residential properties to the northeast, east, and south. Interstate (I-95) is located to the west of the Metro North railroad tracks. In 2005, a Phase II Environmental Assessment report was completed by Enercon as part of closure proceedings for a 3,000 gallon fuel oil UST that was closed in place and a 10,000 gallon fuel oil UST that was removed. Monitoring wells installed as part of this assessment revealed the presence of PCE in groundwater at levels up to 1,430 ppb. (The State groundwater standard for PCE is 5 ppb.) Also, this report noted chemical storage for cutting oils, lubricants, solvents and paints. No products were indicated that contained PCE. In 2007 a follow up report was conducted which revealed PCE in groundwater at levels up to 1,700 ppb. The site was added as a potential inactive hazardous waste disposal site ("P site") in 2007. A State funded site characterization was initiated in 2008 to determine the source of the PCE groundwater plume. A total of 9 monitoring wells were installed in the fall of 2008. Groundwater contaminated with PCE showed higher levels of PCE in wells upgradient from the Baker?s Pride facility. The PCE

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

concentrations were as high as 3,700 ppb in MW-13 which is located about 300 feet upgradient from the Baker?s Pride facility. This prompted the State to do a second round of groundwater sampling further upgradient of MW-13. Two additional wells (MW-24 and MW-25) were installed about 150 feet upgradient of MW-13 in the winter of 2009. MW-24 revealed PCE at 5,300 ppb. The second round of sampling further defined a groundwater plume with a source area upgradient from the Bakers Pride site.Since the site information for Baker?s Pride indicates that the plume of PCE is coming from an off-site source, the Baker?s Pride site (360087) will not be listed in the Registry of Inactive Hazardous Waste Disposal sites. A separate site was added to the Registry to address the source of the PCE plume (See site #360109.)

Env Problem:	Based upon investigations to date, the primary contaminants of concern at the site include tetrachloroetylene (PCE) and its associated breakdown products. PCE was detected in upgradient groundwater as well as on-site and also in indoor air in residences upgradient of the site. PCE was detected on-site in groundwater from non-detect up to 3,200 parts per billion (ppb) at MW-1) above the respective groundwater standard of 5 ppb. Upgradient off-site levels of PCE were as high as 5,300 ppb. Indoor air was impacted in two residences with the highest level being 530 micrograms per cubic meter (ug/m3) at a property on Bartels Place. Since the highest levels of PCE were identified in the groundwater upgradient of the site this suggests an off-site source that is impacting the Baker?s Pride site. The source of this contamination is the Industrial Overall Service Corp. Class 2 site (#360109)
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Updated By: Not reported

SPILLS:

Facility ID:	9404759
Facility Type:	ER
DER Facility ID:	122872
Site ID:	144128
DEC Region:	3
Spill Date:	1994-07-07
Spill Number/Closed Date:	9404759 / 2003-10-08
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1994-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-11
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 10/17/03: Letter to Mark Fogarty, Baker's Pride from Danielle Jackson, dated 10/8/2003. Closure report by Env. Products & Services and sample results have been reviewed. While there is some contamination remaining, WCDOH does not see the contamination as a risk to human health. WCDOH recommends NFA at this time."
Remarks:	"SOIL STOCKPILED BOB SPERONI WAS ON SITE FAXED TO TARRYTOWN & WCHD"

Material:

Site ID:	144128
Operable Unit ID:	1001834
Operable Unit:	01
Material ID:	381361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

FINDS:

Registry ID: 110002092949

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NJ MANIFEST:
EPA Id: NYD986925808
Mail Address: 30 PINE ST
Mail City/State/Zip: NEW ROCHELLE 10801
Facility Phone: 9145760200
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 008921150JJK
EPA ID: NYD986925808
Date Shipped: 7/2/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,815.00 gallons

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	008923493JJK
EPA ID:	NYD986925808
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,800.00 Pounds

Manifest Number:	008923039JJK
EPA ID:	NYD986925808
Date Shipped:	7/31/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	150.00 Pounds

Manifest Number:	NJA4033255
EPA ID:	NYD986925808
Date Shipped:	04/02/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/02/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030425
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

NY MANIFEST:

EPA ID:	NYD986925808
Country:	USA
Location Address 1:	30 PINE ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	INDUSTIRAL OVERALL UNIFORM
Contact:	IRA NEVIN
Address:	30 PINE ST
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	518-402-9564

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2014
Trans1 Recv Date:	05/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012352197JJK
Import Ind:	N
Export Ind:	N

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2014
Trans1 Recv Date:	05/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012352197JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049543SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049543SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 10/15/2009
Trans1 Recv Date: 10/15/2009
Trans2 Recv Date: 10/19/2009
TSD Site Recv Date: 10/25/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986925808
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: Not reported
Quantity: 10.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 002049551SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629926
Generator Ship Date: 10/15/2009
Trans1 Recv Date: 10/15/2009
Trans2 Recv Date: 10/19/2009
TSD Site Recv Date: 10/21/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986925808
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 200.0

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049550SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629926
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	20.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049550SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/28/2012
Trans1 Recv Date:	12/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1800.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923493JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2012
Trans1 Recv Date:	07/31/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Manifest Tracking Num:	008923039JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/2012
Trans1 Recv Date:	07/02/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	31.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008921150JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/2012
Trans1 Recv Date:	07/02/2012
Trans2 Recv Date:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

TSD Site Recv Date:	07/02/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1815.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	33.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008921150JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NJA4033255
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2004
Trans1 Recv Date:	04/02/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00242
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NJA2889530
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Generator Ship Date:	02/09/2001
Trans1 Recv Date:	02/09/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/13/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA2968556
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	S50060
Generator Ship Date:	08/23/1999
Trans1 Recv Date:	08/23/1999
Trans2 Recv Date:	08/24/1999
TSD Site Recv Date:	08/27/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NJA2295827
Manifest Status:	Not reported
Trans1 State ID:	S50060
Trans2 State ID:	88672
Generator Ship Date:	08/14/1998
Trans1 Recv Date:	08/14/1998
Trans2 Recv Date:	08/26/1998
TSD Site Recv Date:	08/27/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NJA2729357
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	50060
Trans2 State ID:	Not reported
Generator Ship Date:	05/20/1997
Trans1 Recv Date:	05/20/1997
Trans2 Recv Date:	05/23/1997
TSD Site Recv Date:	05/29/1997
Part A Recv Date:	06/10/1997
Part B Recv Date:	07/15/1997
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NJA2590786
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S50060
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1997
Trans1 Recv Date:	12/17/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/18/1997
Part A Recv Date:	01/07/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Document ID:	NJA2630871
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S50060
Trans2 State ID:	S50060
Generator Ship Date:	11/08/1996
Trans1 Recv Date:	11/08/1996
Trans2 Recv Date:	11/17/1996
TSD Site Recv Date:	11/20/1996
Part A Recv Date:	12/02/1996
Part B Recv Date:	01/31/1997
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2133346
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/1996
Trans1 Recv Date:	06/27/1996
Trans2 Recv Date:	07/05/1996
TSD Site Recv Date:	07/15/1996
Part A Recv Date:	07/16/1996
Part B Recv Date:	08/02/1996
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2630864
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	75818
Trans2 State ID:	S50060
Generator Ship Date:	10/25/1996
Trans1 Recv Date:	10/25/1996
Trans2 Recv Date:	11/05/1996
TSD Site Recv Date:	11/06/1996
Part A Recv Date:	11/12/1996

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Part B Recv Date:	12/16/1996
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

ECHO:

Envid:	1004571492
Registry ID:	110002092949
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002092949

287
West
1/4-1/2
0.322 mi.
1698 ft.

Relative:
Lower

Actual:
80 ft.

POGLIA RES **NY LTANKS** **S105230529**
119 WASHINGTON AVE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	317087
Spill Number/Closed Date:	0109023 / 2002-03-06
Spill Date:	2001-12-11
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-12-11
CID:	397
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-11
Spill Record Last Update:	2002-03-22
Spiller Name:	CALLER
Spiller Company:	POGLIA RES
Spiller Address:	119 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

POGLIA RES (Continued) **S105230529**

DER Facility ID: 255607
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/06/2002 NES DISPOSED OF TANK AND 40 TONS OF CONTAMINATED SOIL. DORSON SUBMITTED CLOSURE REPORT. NO FURTHER ACTION."
Remarks: "callers co was removing tank and discovered the tank failure. in process of being cleaned"

Material:
Site ID: 317087
Operable Unit ID: 847335
Operable Unit: 01
Material ID: 530237
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

---

288 **APT. BUILDING** **NY LTANKS S102241692**
South **47 MAPLE AV** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.323 mi.
1705 ft.

Relative:
Higher

Actual:
87 ft.

LTANKS:
Site ID: 178537
Spill Number/Closed Date: 9603128 / 1996-06-14
Spill Date: 1996-06-05
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1996-06-05
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1996-06-05
Spill Record Last Update: 1996-09-04
Spiller Name: A D VANDROFF
Spiller Company: A D VANDROFF
Spiller Address: 47 MAPLE AVENUE

APT. BUILDING (Continued) **S102241692**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	A D VANDROFF
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/14/96 SEE SPILL # 9603064"
Remarks:	"gross failure of tank."

Material:

Tank Test:

SPILLS:

Facility ID:	9603064
Facility Type:	ER
DER Facility ID:	248269
Site ID:	307417
DEC Region:	3
Spill Date:	1996-06-04
Spill Number/Closed Date:	9603064 / 1996-08-12
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-04
CID:	349
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-06-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-04
Spill Record Last Update:	1996-10-21
Spiller Name:	OWNER - ARTHUR DANDROFF
Spiller Company:	Not reported
Spiller Address:	47 MAPLE AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	OWNER - ARTHUR DANDROFF
Contact Phone:	(941) 954-4445
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/04/96 WCHD TO INSPECT 06/14/96 SEE SPILL # 9603128 08/12/96 CONTENTS GONE IN FOUR DAYS AFTER FILL UP TANK REMOVED LINES TESTED NO LEAKS FOUND FROM TESTS SMALL HOLES FOUND IN TANKS VERY MINIMAL CONTAMINATION "
Remarks:	"APARTMENT BLDG - SUPERINTENDENT MRS CHURCHILL 914-636-4142 -

APT. BUILDING (Continued) **S102241692**

RECIEVED 900 GALLONS ON THURSDAY - NOW ITS IS EMPTY - CHECK OF AREA INCLUDING SEWERS NO ODOR - FD ON SCENE - WILL BE TESTING W/WATER - TEMP. TANK TO BE PUT IN"

Material:

Site ID:	307417
Operable Unit ID:	1030609
Operable Unit:	01
Material ID:	349302
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

289
East
1/4-1/2
0.323 mi.
1706 ft.

SPILL 0106072 / PBS 3-800919 **NY LTANKS** **S105135128**
370 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
60 ft.

LTANKS:

Site ID:	133647
Spill Number/Closed Date:	0106072 / 2001-11-13
Spill Date:	2001-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2014-08-15
Spiller Name:	STEVEN WOODS
Spiller Company:	Monroe College
Spiller Address:	370 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	Not reported

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114844
DEC Memo:	"09/07/2001 PROPERTY FOR SALE. TANK TESTED BY POTENTIAL BUYER. SELLER TO REMOVE OR RETEST. 11/13/2001 TANK PASSED A RETEST AFTER REFIT. NO FURTHER ACTION. 8/15/14: Hard copy file pulled for FOIL. File scanned to PDF, will wiil entered into DecDocs. Paper file discarded. NOTE: WCDoH PBS records indicate this UST was Closed - in place and the site listed as Unregulated 7/30/2002. jod"
Remarks:	"will fill tank with sand and abandoned it"

Material:

Site ID:	133647
Operable Unit ID:	844476
Operable Unit:	01
Material ID:	530955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	133647
Spill Tank Test:	2495803
Tank Number:	1
Tank Size:	2000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AY290 **BUSINESS** **NY LTANKS** **S101341432**
WSW **88 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 1 of 2 in cluster AY**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	172950
Spill Number/Closed Date:	9411669 / 2010-04-28
Spill Date:	1994-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010

BUSINESS (Continued) **S101341432**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	MR. OGMAN
Spiller Address:	88 GROVE AVE.
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	145542
DEC Memo:	"4/28/10 16 year old TTF No further info NFA JO'M "
Remarks:	"WILL EXPLORE IT NEXT"

Material:

Site ID:	172950
Operable Unit ID:	1005375
Operable Unit:	01
Material ID:	374006
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	172950
Spill Tank Test:	1543408
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AY291 **COMMERCIAL BUILDING** **NY LTANKS** **S104276178**
WSW **88-90 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 2 of 2 in cluster AY**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	113133
Spill Number/Closed Date:	9411598 / 2010-04-28
Spill Date:	1994-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	98741
DEC Memo:	"4/28/10 16 year old TTF NFA JO'M"
Remarks:	"TANK TEST FAILURE PETRO-TITE II VISUAL"

Material:

Site ID:	113133
Operable Unit ID:	1005335
Operable Unit:	01
Material ID:	373942
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

COMMERCIAL BUILDING (Continued) **S104276178**

Site ID:	113133
Spill Tank Test:	1543402
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

---

292 WNW 1/4-1/2 0.335 mi. 1769 ft. **ANON** **NY LTANKS S106124350**
108 VAN GUILDER AVE **NY Spills N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 77 ft.

LTANKS:

Site ID:	214235
Spill Number/Closed Date:	0308565 / 2005-02-12
Spill Date:	2003-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-11-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-13
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	RICHARD KLING
Spiller Phone:	(914) 636-0076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177496
DEC Memo:	"03/24/04 TANK IS IN A CRAWL SPACE UNDER THE FOUNDATION AND CANNOT BE REMOVED. ROYAL ENVIRONMENTAL INSPECTED TANK AND FOUND NO EVIDENCE OF CONTAMINATION. ROYAL INSTALLED A NEW 275 AST BUT HAS NOT YET PUT THAT TANK IN SERVICE, AWAITING INSPECTION FROM NEW ROCHELLE FIRE DEPT. ONCE AST IS IN SERVICE, ROYAL IS TO CUT AND CLEAN 550 UST AND OBTAIN A SOIL SAMPLE FROM BENEATH TANK. SAMPLE RESULTS TO BE FORWARDED TO DEC. ADDITIONAL SPILL NUMBERS CALLED IN: 03-13745 AND 03-14031. jbo"

ANON (Continued) **S106124350**

Remarks: "uncover / repair / retest"

Material:

Site ID:	214235
Operable Unit ID:	874811
Operable Unit:	01
Material ID:	502049
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	214235
Spill Tank Test:	1528806
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	0314031
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214237
DEC Region:	3
Spill Date:	2004-03-24
Spill Number/Closed Date:	0314031 / 2004-03-24
Spill Cause:	Unknown
Spill Class:	No spill occured. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-24
CID:	407
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-24
Spill Record Last Update:	2005-02-12

ANON (Continued) **S106124350**

Spiller Name:	RICHARD KLING MD
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	RICHARD KLING MD
Contact Phone:	Not reported
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo 03/30/04 SITE INSPECTED BY STEFAN GOREAU OF WCHD. jbo"
Remarks:	"unknown if spill, caller refused to give name, detected odor of gas/oil from neighbors building, renovation ongoing at building, caller believed odor was related to work."

Material:

Site ID:	214237
Operable Unit ID:	880985
Operable Unit:	01
Material ID:	495617
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0313745
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214236
DEC Region:	3
Spill Date:	2004-03-16
Spill Number/Closed Date:	0313745 / 2004-03-24
Spill Cause:	Unknown
Spill Class:	No spill occured. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2005-02-12
Spiller Name:	DR RICHARD KLEIN

ANON (Continued) **S106124350**

Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	DR RICHARD KLEIN
Contact Phone:	Not reported
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo"
Remarks:	"CALLER STATES THAT THERE IS A VERY STRONG ODOR AT THE DOCTOR'S OFFICE AND SHE CAN SMELL IT AT HER HOME. SOMETIMES ODOR IS VERY OVERWELMING: A LARGE CONTAINER IS IN THE BACK YARD OF DOCTOR'S OFFICE: SHE JUST WANTED SOMEONE TO CHECK OUT: *****UPDATE***** SHE CALLED BACK AND SAID THAT SOMEONE TOLD HER THAT A COMPANY CAME IN A CHECKED IT OUT- ROYAL IN PELHAM NY*"

Material:

Site ID:	214236
Operable Unit ID:	879034
Operable Unit:	01
Material ID:	495337
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV293 **BELIVE HOME** **NY LTANKS** **S106869214**
SW **20 PINE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.337 mi.
1780 ft. **Site 4 of 4 in cluster AV**

Relative:
Lower

Actual:
47 ft.

LTANKS:

Site ID:	343902
Spill Number/Closed Date:	0500819 / 2005-05-22
Spill Date:	2005-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

BELIVE HOME (Continued) **S106869214**

Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2005-05-22
Spiller Name:	JOHN BELIVE
Spiller Company:	BELIVE HOME
Spiller Address:	20 PINE STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOHN BELIVE
Spiller Phone:	(914) 253-8449
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"05/22/05 PREVIOUSLY REPORTED TTF IS 04-13182. NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 34.56 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 gallon , found holes and contaminated soil:"

Material:

Site ID:	343902
Operable Unit ID:	1102568
Operable Unit:	01
Material ID:	582785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	339043
Spill Number/Closed Date:	0413182 / 2005-05-22
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

BELIVE HOME (Continued) **S106869214**

Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-22
Spiller Name:	JOE PONSERELLA
Spiller Company:	PONSERELLA HOME
Spiller Address:	20 PINE STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOE PONSERELLA
Spiller Phone:	(914) 760-6684
Spiller Extention:	CELL
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"5/22/05 See spill 05-00819. NFA this number. jod"
Remarks:	""

Material:

Site ID:	339043
Operable Unit ID:	1100961
Operable Unit:	01
Material ID:	581111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	339043
Spill Tank Test:	1548700
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

294 **CON EDISON-CEDAR ST WORKS-NEWROCH'LE MGP** **EDR MGP** **1008407973**
NE **ONE RAMADA PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.340 mi.
1794 ft.

Relative:
Lower

Actual:
50 ft.

Manufactured Gas Plants:
No additional information available

295 SE 1/4-1/2 0.341 mi. 1799 ft.

CHURCH OF LATTER DAY SAIN
111 NORTH AVE
NEW ROCHELLE, NY

NY LTANKS **S106471932** **N/A**

Relative: Lower

Actual: 83 ft.

LTANKS:

Site ID:	266466
Spill Number/Closed Date:	0403126 / 2004-09-21
Spill Date:	2004-06-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates a file or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-06-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22
Spill Record Last Update:	2004-09-21
Spiller Name:	MATT SCHIEFERSTEIN
Spiller Company:	CHURCH OF LATTER DAY SAIN
Spiller Address:	111 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MATT SCHIEFERSTEIN
Spiller Phone:	(631) 351-3555
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217081
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/23/04 APPROXIMATELY 200 TONS OF CONTAMINATED SOIL REMOVED. CLOSURE REPORT TO FOLLOW. jbo 09/21/04 ANSON ENVIRONMENTAL DISPOSED OF LUST AND 168.02 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"WHILE DIGGING A FOUNDATION FOUND A TANK: CONTAMINATED SOIL ALSO: "

Material:

Site ID:	266466
Operable Unit ID:	885085
Operable Unit:	01
Material ID:	490726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CHURCH OF LATTER DAY SAIN (Continued) **S106471932**

Tank Test:

296
SE
1/4-1/2
0.345 mi.
1824 ft.

APARTMENT BUILDING **NY LTANKS** **S110611357**
67-70 LOCUST AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Site ID:	441682
Spill Number/Closed Date:	1008207 / 2011-03-10
Spill Date:	2010-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-04
Spill Record Last Update:	2011-03-10
Spiller Name:	ABRAHAM WATHCELL
Spiller Company:	UNKNOWN
Spiller Address:	67- 70 LOCUST AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ABRAHAM WATHCELL
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396710
DEC Memo:	"Left message for callback. DT 11/4/10 11/5/10: Call back from Abraham Wathcell of NY Tank Testing to dispatch desk. This was a test failure of an 8K heating oil tank at a co-op. PBS #3-413925 will handled by WCDOH. Mr Wathcell stated he had discussed the results with the management compny and was recommending removal of the tank rather than retest. jod 3/10/11 As per WCDOH eplaced fill pipe, manway gasket and repaired gauge. Passed retest on 2/14/11. NFA JO'M "
	Not reported
Remarks:	""

Material:

Site ID:	441682
Operable Unit ID:	1192229
Operable Unit:	01
Material ID:	2187465

APARTMENT BUILDING (Continued) **S110611357**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	441682
Spill Tank Test:	2489743
Tank Number:	1
Tank Size:	8000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AX297 **SPILL NUMBER 9908602** **NY LTANKS** **S104620556**
SSW **HUGUENOT ST & SOUTH PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.348 mi.
1836 ft. **Site 2 of 2 in cluster AX**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	283271
Spill Number/Closed Date:	9908602 / 2000-09-14
Spill Date:	1999-10-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1999-10-15
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-10-15
Spill Record Last Update:	2000-09-26
Spiller Name:	CITY OF NEW ROCHELLE
Spiller Company:	Not reported
Spiller Address:	HUGUENOT ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

SPILL NUMBER 9908602 (Continued) **S104620556**

Spiller Contact:	CITY OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229755
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 10/15/99 DELUXE TAXICAB SITE; TANKS HAD BEEN REMOVED BUT CONTAMINATED SOIL; SOIL BEING REMOVED--WILL SUBMIT REPORT. 12/09/99 LETTER SENT TO N. RECCHIA; MUST BETTER DEFINE THE EXTENT OF CONTAMINATION IN THE OVERBURDEN SOIL & GROUNDWATER 05/18/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; ADDITIONAL INVESTIGATION IS REQUIRED AT THIS SITE 09/14/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; BASED ON RESULTS REPORTED BY THE ENERGY & ENVIRONMENTAL ANLAYSISTS, INC. IN AUGUST 2000, THIS SPILL IS CLOSED. "
Remarks:	"VACANT LOT AND DURING EXCAVATION - CONTAMINATED SOIL FOUND"

Material:

Site ID:	283271
Operable Unit ID:	1087287
Operable Unit:	01
Material ID:	297711
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

298
SW
1/4-1/2
0.357 mi.
1885 ft.

BUSINESS COMPLEX **NY LTANKS** **S104516367**
55 WEBSTER AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
54 ft.

LTANKS:

Site ID:	86196
Spill Number/Closed Date:	9912136 / 2000-05-11
Spill Date:	2000-01-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2000-01-20
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other

BUSINESS COMPLEX (Continued) **S104516367**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2004-11-23
Spiller Name:	MR LIBERETT
Spiller Company:	BUSINESS COMPLEX
Spiller Address:	55 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	MR LIBERETT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79113
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/09/2000 ACCORDING TO MR. BOB ALERES PHASE 11 REPORT COMPLETED. WILL SUBMIT COPY TO T. GHIOSAY. 05/11/00 - Spill closure letter sent by J. O'Mara to: DL Rothberg & Associates PC 1350 Broadway Suite 1711 NY NY 10018 Attention Debra Rothberg, Esq"
Remarks:	"THEY REMOVED A 3,000 GALLON TANK AND PUT IN A NEW 1,000 GALLON TANK THEY SUSPECT THE 3,000 GALLON HAD LEAKED UNKNOWN MATERIAL INTO THE GROUND.THEY GOT THE LAB RESULTS BACK YESTERDAY.THEY SUSPECT IT MAY BE HEATING OIL BUT ARE NOT SURE."

Material:

Site ID:	86196
Operable Unit ID:	1086666
Operable Unit:	01
Material ID:	294030
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AZ299 **APARTMENT BLDG** **NY LTANKS** **S104515070**
North **1 THE BOULEVARD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.359 mi.
1898 ft. **Site 1 of 2 in cluster AZ**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	303319
Spill Number/Closed Date:	9809315 / 1999-10-14
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known

APARTMENT BLDG (Continued) **S104515070**

	release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-10-26
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	1999-11-22
Spiller Name:	ELJAK REALTY
Spiller Company:	APT BLDG
Spiller Address:	1 THE BLVD
Spiller City,St,Zip:	NEW ROCHELELE, NY 10801-
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	245085
DEC Memo:	""
Remarks:	"EXCAVATE PIPING AND RETEST"

Material:

Site ID:	303319
Operable Unit ID:	1070412
Operable Unit:	01
Material ID:	316775
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	303319
Spill Tank Test:	1546451
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BA300 **GETTY S/S** **NY LTANKS** **S105054437**
ENE **ECHO & BOSTON POST RD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.362 mi.
1913 ft. **Site 1 of 4 in cluster BA**

Relative:
Lower

Actual:
42 ft.

LTANKS:

Site ID:	124816
Spill Number/Closed Date:	8602124 / 1989-11-28
Spill Date:	1986-06-28
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1989-11-28
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1986-06-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	1988-08-19
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-09-21
Spill Record Last Update:	1990-11-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	108052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : 6/29-NEPCCO DRILLED RECOVERY WELLS. / / : 6/29-NEPCCO DRILLED RECOVERY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL. / / : 6/29-NEPCCO DRILLED RECOVERY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL.7/1/86-TANKS MUST BE PETRO-TITE TESTED. / / : 7/1/86-PROBLEM REPAIRED-NFAY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL.7/1/86-TANKS MUST BE PETRO-TITE TESTED. / / : 7/23/86-NO EXPLOSIVE READINGS IN SEWER.MONITORING WELLS ON SITE HAVE NO FREE PRODUCT. 08/18/88: BAILED ALL WELLS,NO FREE PRODUCT. "
Remarks:	"FD FLUSHED SEWERS.NEPCO DRILLING RECOVERY WELLS. ALL WELLS CLEAN OF FREE PRODUCT."

Material:

Site ID:	124816
Operable Unit ID:	898693
Operable Unit:	01
Material ID:	478579
Material Code:	0009
Material Name:	gasoline

GETTY S/S (Continued) **S105054437**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AZ301 **PRIVATE DWELLING** **NY LTANKS** **S108765819**
NNW **19 ROCHELLE PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.363 mi.
1917 ft. **Site 2 of 2 in cluster AZ**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	387568
Spill Number/Closed Date:	0706958 / 2008-02-01
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2008-02-01
Spiller Name:	ROLAND ANDRALOISKI
Spiller Company:	Not reported
Spiller Address:	19 ROCHELLE PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ROLAND ANDRALOISKI
Spiller Phone:	(914) 774-7362
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	336995
DEC Memo:	"To uncover and retest. 12/05/08 Northeast Environmental reported that the tank was excavated and removed. Noe cotaminated soil was observed in the tank grave. TAGM soil sample results were below DEC guidance values. NFA. TG "
Remarks:	""

PRIVATE DWELLING (Continued) **S108765819**

Material:

Site ID:	387568
Operable Unit ID:	1144768
Operable Unit:	01
Material ID:	2135078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	387568
Spill Tank Test:	1764128
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BB302 **RESIDENCE** **NY LTANKS** **S102448122**
ENE **14 REVERE RD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.364 mi.
1923 ft. **Site 1 of 2 in cluster BB**

Relative:
Lower

Actual:
34 ft.

LTANKS:

Site ID:	69656
Spill Number/Closed Date:	9611129 / 1996-12-11
Spill Date:	1996-12-09
Spill Cause:	Tank Failure
Spill Source:	Tank Truck
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-09
CID:	233
Water Affected:	CARPENTERS POND
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-09
Spill Record Last Update:	1997-01-02

RESIDENCE (Continued) **S102448122**

Spiller Name:	Not reported
Spiller Company:	FRED M. SCHILDWACHLER &
Spiller Address:	SONS
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	66210
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/10/96 WCHD AT SITE."
Remarks:	"DRIVER OVERFILLED TANK OIL INTO BROOK BROOK RUNS TO A POND (CARPENTERS POND) FD ON SCENE CELL # FOR CHIEF 914-263-2302 WESTCHESTER FIRE CONTROL 914-593-5905"

Material:

Site ID:	69656
Operable Unit ID:	1042681
Operable Unit:	01
Material ID:	343331
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	50.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

303
WNW
1/4-1/2
0.366 mi.
1933 ft.

NEW ROCHELLE RADIOLOGY **NY LTANKS** **S105997625**
150 LOCKWOOD AV **NY Spills** **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
85 ft.

LTANKS:

Site ID:	221207
Spill Number/Closed Date:	0209497 / 2005-03-18
Spill Date:	2002-12-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-12-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2005-04-05
Spiller Name:	RICK TROY
Spiller Company:	RICK TROY
Spiller Address:	150 LOCKWOOD AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RICK TROY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	182943
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 12/16/02: WCDOH ON SITE. 140 TONS SOIL REMOVED. CLOSURE REPORT PENDING. 04/08/03: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 3/26/2003. Closure report from GFE has been reviewed. Groundwater samples must be collected. Result submitted to WCHD by May 12, 2003. PBS #3-601067 & 3-601068. 08/13/02: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 7/21/03. Further remediation and quarterly sampling is required. Results of sampling are to be submitted to WCDOH quarterly. First report due by 9/01/2003. 5/25/04: Letter to Lockwood Realty, LLC, from Christopher Lalak, WCDOH, dated 25May2004. Two rounds of sampling have been received, third is overdue. Third round must be received by 25Jun2004. 11/22/04: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 17Nov2004. Based on groundwater sampling results, closure report and inspections, sampling must continue for the next year on a quarterly basis. After sampling, site will be reviewed. Next results due 28Feb2005. 4/4/05: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 18Mar2005. Spill has been satisfactorily remediated. WCDOH requires NFA."
Remarks:	"CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL"

Material:

Site ID:	221207
Operable Unit ID:	860802
Operable Unit:	01
Material ID:	512920
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

SPILLS:

Facility ID:	0209877
Facility Type:	ER
DER Facility ID:	182943
Site ID:	221208
DEC Region:	3
Spill Date:	2002-12-27
Spill Number/Closed Date:	0209877 / 2003-03-28
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-30
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"CALLER WENT TO HAVE A MAMMOGRAM DONE & SHE STAATED THE ENTIRE BLDG SMELLED LIKE FUEL OIL - UNK IF IT HAD TO DO WITH THE CONSTRUCTION THAT WAS GOING ON IN THE PARKING LOT OR NOT"

Material:

Site ID:	221208
Operable Unit ID:	861114
Operable Unit:	01
Material ID:	513296
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

304
SSE
1/4-1/2
0.368 mi.
1943 ft.

NICK MAZZA RESIDENCE
20 DAVIS AVE
NEW ROCHELLE, NY

NY LTANKS **S104621408**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	211468
Spill Number/Closed Date:	0000532 / 2000-04-20
Spill Date:	2000-04-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-13
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-13
Spill Record Last Update:	2000-05-03
Spiller Name:	N/A
Spiller Company:	NICK MAZZA
Spiller Address:	20 DAVIS AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/14/2000 ENVIROSTAR REPAIRED; U.S. TANK TO RETEST ON 4/17/2000. 04/20/2000 U.S. TANK TECH RETESTED TANK AFTER ENVIROSTAR REPLACED PIPING. TANK PASSED RETEST. NFA"
Remarks:	"tank failed the test. he did not have the homeowners name or phone number "

Material:

Site ID:	211468
Operable Unit ID:	822249
Operable Unit:	01
Material ID:	288777
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

NICK MAZZA RESIDENCE (Continued) **S104621408**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 211468
Spill Tank Test: 1525485
Tank Number: 1
Tank Size: 1000
Test Method: 18
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)

BC305 **SHERIDEN PLAZA** **NY LTANKS** **S100138278**
NE **1 SHERIDEN PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.370 mi.
1955 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
36 ft.

LTANKS:
Site ID: 80178
Spill Number/Closed Date: 8909204 / 1990-03-07
Spill Date: 1989-12-19
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
Cleanup Meets Standard: True
SWIS: 6000
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1989-12-19
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1989-12-21
Spill Record Last Update: 1992-02-10
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 74339
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "CONTAMINATION FOUND DURING TANK REMOVAL SOIL TO BE STOCKPILED ON

SHERIDEN PLAZA (Continued) **S100138278**

PLASTIC DEC TO INSPECT TANK HOLE TYREE VACING OUT HOLE"

Material:

Site ID:	80178
Operable Unit ID:	934143
Operable Unit:	01
Material ID:	442378
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BD306 **JASON PARTNERS LTD** **NY LTANKS** **S105998096**
SSW **675 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.373 mi.
1968 ft. **Site 1 of 3 in cluster BD**

Relative:
Lower

Actual:
65 ft.

LTANKS:

Site ID:	86967
Spill Number/Closed Date:	0211105 / 2003-03-26
Spill Date:	2003-02-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-02-05
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-05
Spill Record Last Update:	2003-04-09
Spiller Name:	JAMIE MIZRAHI
Spiller Company:	JASON PARTNERS LTD
Spiller Address:	675 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JAMIE MIZRAHI
Spiller Phone:	(914) 682-6664
Spiller Extention:	Not reported

JASON PARTNERS LTD (Continued) **S105998096**

DEC Region: 3
DER Facility ID: 79721
DEC Memo: ""
Remarks: "CALLERS COMPANY HIRED TO REMOVE A 3000 GAL INGROUND TANK AT THE ABOVE LOCATION, AFTER TANK WAS REMOVED, HOLE WERE FOUND IN TANK AND CONTAMINATED SOIL WAS DISCOVERED - DIRT IS BEING REMOVED AND STORED ON PLASTIC"

Material:
Site ID: 86967
Operable Unit ID: 862143
Operable Unit: 01
Material ID: 514466
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BE307 **ABANDONED GAS STATION** **NY LTANKS** **S102660200**
West **197 WEBSTER AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.377 mi.
1989 ft. **Site 1 of 2 in cluster BE**

Relative:
Lower

Actual:
79 ft.

LTANKS:
Site ID: 231589
Spill Number/Closed Date: 9707099 / 2001-07-19
Spill Date: 1997-09-15
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-09-15
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1997-09-15
Spill Record Last Update: 2001-08-06
Spiller Name: Not reported
Spiller Company: UNKNOWN

ABANDONED GAS STATION (Continued) **S102660200**

Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	EDWARD SELLIAN
Spiller Phone:	(561) 221-1754
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	190875
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/19/2001 LETTER SENT TO IRA CONKLIN & SONS BY T. GHIOSAY; BASED ON SUBSURFACE INVESTIGATION REPORT, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL LISTED AS CLOSED."
Remarks:	"CALLER REMOVING TANKS AND FOUND SOIL CONTAMINATION"

Material:

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BC308 **MUTUAL BISCUIT COMPANY** **NY LTANKS** **S104193116**
NE **65 RIVER ST.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.379 mi.
2002 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	286036
Spill Number/Closed Date:	8707334 / 1988-02-18
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-25
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-01
Spill Record Last Update:	1988-03-11
Spiller Name:	HUGH GEORGE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : WILL RETEST. / / : TANKS REMOVED. LR 02-18-88 N F A. "
Remarks:	"TTTF-4K TANK;-0.7584 GPH,4K TANK;-0.3312 GPH"

Material:

Site ID:	286036
Operable Unit ID:	911503
Operable Unit:	01
Material ID:	466293
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	286036
Spill Tank Test:	1532438
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Last Modified:	Not reported
Test Method:	Unknown
Site ID:	286037
Spill Number/Closed Date:	8708530 / 1988-02-18
Spill Date:	1988-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	HUGH GEORGE
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANKS REMOVED 02-18-88 LR N F A. "
Remarks:	"5K (RETEST) 1.34GPH TO PUMP & PULL TANK"

Material:

Site ID:	286037
Operable Unit ID:	913194
Operable Unit:	01
Material ID:	570954
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Tank Test:

Site ID:	286037
Spill Tank Test:	1532919
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	9908179
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139057
DEC Region:	3
Spill Date:	1999-10-05
Spill Number/Closed Date:	9908179 / 1999-10-18
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-05
Spill Record Last Update:	1999-11-04
Spiller Name:	MICHAEL GRAVANESE
Spiller Company:	POST MARINE SUPLLY
Spiller Address:	65 RIVER SR
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/18/99 DEC INSPECTED SITE. ONE LEAKY BATTERY FOUND NEXT TO DIESEL TANKS. BATTERIES TO BE REMOVED LATER TODAY. NFA"
Remarks:	"CALLER IS AN EX EMPLOYEE REPORTING BATTERIES BEING STORED NEXT TO GASOLINE TANKS AND BELIEVES THEY MIGHT BE LEAKING BATTERY ACID."

Material:

Site ID:	139057
Operable Unit ID:	1082477

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Operable Unit:	01
Material ID:	300856
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9904805
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139056
DEC Region:	3
Spill Date:	1999-07-22
Spill Number/Closed Date:	9904805 / 1999-07-22
Spill Cause:	Deliberate
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1999-07-22
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-22
Spill Record Last Update:	1999-09-10
Spiller Name:	NASER JABER
Spiller Company:	POST MARINE SUPPLY
Spiller Address:	65 RIVER ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	NASER JABER
Contact Phone:	(914) 235-9800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA "
Remarks:	"CALLER STATES THAT HE WITTNESSED SUBJ DUMPING GAS INTO A STORM DRAIN. JOHN O'MARA (REGION 3 SPILLS) NOTIFIED AND ALSO ENCON POLICE"

Material:

Site ID:	139056
Operable Unit ID:	1079250
Operable Unit:	01

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Material ID:	301132
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA309 **GETTY 58114** **NY LTANKS S107657288**
ENE **340 MAIN STREET** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.380 mi.
2007 ft. **Site 2 of 4 in cluster BA**

Relative:
Lower

Actual:
38 ft.

LTANKS:

Site ID:	426673
Spill Number/Closed Date:	0913713 / 2010-04-29
Spill Date:	2010-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-26
Spill Record Last Update:	2010-04-29
Spiller Name:	ROBERT O'KEEFE
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	TOM ANDERSON
Spiller Phone:	(845) 216-8064
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310476
DEC Memo:	"3/26/10 Tyree to go there on Mon. 3/29 to do repairs. dw 4/29/10 Getty 340 Main St New Rochelle line test failed do to faulty check valve. Tyree replaced check valve. Passed retest on 4/12/10 NFA JO'M "
	Not reported

GETTY 58114 (Continued) **S107657288**

Remarks: "in line problem - Tyree notified - cleanup and repair pending"

Material:

Site ID:	426673
Operable Unit ID:	1182349
Operable Unit:	01
Material ID:	2176532
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0606306
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369636
DEC Region:	3
Spill Date:	2006-09-01
Spill Number/Closed Date:	0606306 / 2006-09-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-01
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"LESS THAN A GAL OF BOTH ABND THEY HAVE BEEN CLEANED UP."

GETTY 58114 (Continued) **S107657288**

Material:

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117069
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117068
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0606253
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369567
DEC Region:	3
Spill Date:	2006-08-30
Spill Number/Closed Date:	0606253 / 2006-09-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-30
CID:	77
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-31

GETTY 58114 (Continued) **S107657288**

Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"1 qt of waste oil spilled onto asphalt, speedy dry applied."

Material:

Site ID:	369567
Operable Unit ID:	1127402
Operable Unit:	01
Material ID:	2117000
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0603586
Facility Type:	ER
DER Facility ID:	310476
Site ID:	366335
DEC Region:	3
Spill Date:	2006-06-30
Spill Number/Closed Date:	0603586 / 2006-07-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2006-06-30
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-30
Spill Record Last Update:	2006-07-11
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114

GETTY 58114 (Continued) **S107657288**

Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"COMBINED TOTAL OF LESS THAN A GAL. HAS BEEN CLEANED UP."

Material:

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113775
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113776
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0602340
Facility Type:	ER
DER Facility ID:	310476
Site ID:	364789
DEC Region:	3
Spill Date:	2006-06-01
Spill Number/Closed Date:	0602340 / 2006-06-07
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-06-01
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other

GETTY 58114 (Continued) **S107657288**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-01
Spill Record Last Update:	2006-06-07
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"SPEEDI DRI DOWN STAINING ONLY"

Material:

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112286
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0601041
Facility Type:	ER
DER Facility ID:	310476
Site ID:	363188
DEC Region:	3
Spill Date:	2006-04-27
Spill Number/Closed Date:	0601041 / 2006-04-27
Spill Cause:	Housekeeping

GETTY 58114 (Continued) **S107657288**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2006-04-27
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-27
Spill Record Last Update:	2006-05-02
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"5/2/06: Staining - cleaned up NFA"
Remarks:	"speedi dri applied and cleaned up"

Material:

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110750
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01

GETTY 58114 (Continued) **S107657288**

Material ID:	2110748
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

BB310 **SUNOCO / A-PLUS** **NY LTANKS** **S102233475**
ENE **71 HUGUENOT** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.382 mi.
2017 ft. **Site 2 of 2 in cluster BB**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	255332
Spill Number/Closed Date:	9514850 / 1996-07-26
Spill Date:	1996-02-20
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-20
Spill Record Last Update:	1996-09-05
Spiller Name:	RUSSELL HAMMOND
Spiller Company:	SUNOCO / A-PLUS
Spiller Address:	71 HUGUENOT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209140
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SUNOCO / A-PLUS (Continued) **S102233475**

Remarks: GHIOSAY 07/26/96 EPS SUBMITTED G.W. INVESTIAGATION WHICH INDICATES THAT SUNOCO IS THE SOURCE OF G.W. CONTAM. ON 15 RIVER ST. " "soil boring for assessment for station upgrade - head space reading indicates potential of petroleum release"

Material:

Site ID:	255332
Operable Unit ID:	1025945
Operable Unit:	01
Material ID:	354972
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9610201
Facility Type:	ER
DER Facility ID:	201279
Site ID:	245037
DEC Region:	3
Spill Date:	1996-02-28
Spill Number/Closed Date:	9610201 / 2005-01-20
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-11-15
CID:	366
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-15
Spill Record Last Update:	2005-01-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	RUSSELL HAMMOND

SUNOCO / A-PLUS (Continued) **S102233475**

Contact Phone: (516) 239-2431
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 11/15/96 PETROLEUM FOUND DURING WELL SAMPLING; 09/22/97 LETTER SENT; REMEDIATION IS REQUIRED AT THIS SITE; 01/02/98 LETTER SENT; REMEDIATION PROPOSAL IS APPROVED; WORK MUST START WITHIN THIRTY DAYS; 12/30/99 LETTER SENT TO SUN COMPANY; PROPOSAL TO INSTALL HI-VAC SYSTEM AT THIS SITE IS APPROVED & REQUIRED 1/20/05 nfa letter has been sent do to low and declining groundwater contamination--close 05/18/00 LETTER SENT TO MATRIX ENV. BY J. HARDY; REMEDIAL ACTION PLAN OF 1/12/00 IS APPROVED AND REQUIRED 04/19/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; YOU ARE AUTHOR IZED TO OPERATE REMEDIAL SYSTEMS FOR 90 DAYS WHILE DISCHARGE PERMIT APPLICATIONS ARE BEING PROCESSED 06/22/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; AUTHORIZED BY WCDOH TO OPERATE SYSTEM FOR 90 DAYS WHILE PERMITTING IS IN PROGRESS 05/09/03: Letter sent to Matrix Env. Tech. by J. Hardy; Report submitted dated March 20, 2003. Next report due after completion of one year monitoring period. 2/12/04: Letter sent to Matrix Env. Tech. by J. Hardy. No further action is required at this time. Spill cannot be closed due to BTEX levels in monitoring wells 2 & 4."
Remarks: "while removing old tanks discovered contaminated soil. caller's company is cleaning. "

Material:
Site ID: 245037
Operable Unit ID: 1038129
Operable Unit: 01
Material ID: 342418
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported
Site ID: 245037
Operable Unit ID: 1038129
Operable Unit: 01
Material ID: 2096838
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BD311 **6 WEBSTER** **NY LTANKS** **S106472061**
SSW **6 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.384 mi.
2025 ft. **Site 2 of 3 in cluster BD**

Relative:
Lower

Actual:
60 ft.

LTANKS:

Site ID:	81655
Spill Number/Closed Date:	0403816 / 2004-10-08
Spill Date:	2004-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-07-09
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-09
Spill Record Last Update:	2004-10-08
Spiller Name:	SANDRA
Spiller Company:	Not reported
Spiller Address:	6 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SANDRA
Spiller Phone:	(914) 738-4106
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75517
DEC Memo:	"10/08/04 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. SPILL CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NFA REQUIRED AT THIS TIME. jbo "
Remarks:	"tank test failed.uncover the tank isolate,and retest"

Material:

Site ID:	81655
Operable Unit ID:	886220
Operable Unit:	01
Material ID:	491374
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

6 WEBSTER (Continued) **S106472061**

Tank Test:

Site ID:	81655
Spill Tank Test:	1529427
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BF312 **SPILL NUMBER 0314082** **NY LTANKS** **S106385679**
West **136 VANGUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.386 mi.
2040 ft. **Site 1 of 2 in cluster BF**

Relative:
Lower

Actual:
76 ft.

LTANKS:

Site ID:	80232
Spill Number/Closed Date:	0314082 / 2004-06-08
Spill Date:	2004-03-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-25
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-25
Spill Record Last Update:	2004-06-08
Spiller Name:	SILVANA CARRUSA
Spiller Company:	Not reported
Spiller Address:	136 VANGUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SILVANA CARRUSA
Spiller Phone:	(914) 654-1101
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74387
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/08/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 43.55 TONS OF CONTAMINATED SOIL. NFA REQUIRED. jbo"
Remarks:	"tank test failed. repair and retest and remove"

SPILL NUMBER 0314082 (Continued) **S106385679**

Material:

Site ID:	80232
Operable Unit ID:	881015
Operable Unit:	01
Material ID:	495664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	80232
Spill Tank Test:	1529072
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BG313 **STEWART RESIDENCE** **NY LTANKS** **S109414263**
NW **100 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.388 mi.
2047 ft. **Site 1 of 6 in cluster BG**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	462885
Spill Number/Closed Date:	1200264 / 2012-08-13
Spill Date:	2012-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-04-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-10

STEWART RESIDENCE (Continued) **S109414263**

Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	STEWART
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	STEWART
Spiller Phone:	914-235-6390
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	326980
DEC Memo:	"4-10-12 Spoke with Kathy. Failed with a popping sound. They have recommended a retest because this sound usually means piping or fitting leak. Homeowner is elderly so they are dealing with her daughter, Eunice at 914-715-1040. jm 8/13/2012: Envirostar removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"550gal ust"

Material:

Site ID:	462885
Operable Unit ID:	1212990
Operable Unit:	01
Material ID:	2210869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0811178
Facility Type:	ER
DER Facility ID:	326980
Site ID:	408736
DEC Region:	3
Spill Date:	2009-01-09
Spill Number/Closed Date:	0811178 / 2009-01-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	dxweitz
Referred To:	Not reported
Reported to Dept:	2009-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling

STEWART RESIDENCE (Continued) **S109414263**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-09
Spill Record Last Update:	2009-01-09
Spiller Name:	SUE LUGO
Spiller Company:	TOWN & COUNTRY OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	NN
Spiller Company:	999
Contact Name:	NECOLA STEWART
Contact Phone:	(914) 235-6390
DEC Memo:	"1/9/09 Problem with the vent whistle. Town and Country is there fixing the vent, and cleaning up the 1 gal spill. NFA dw"
Remarks:	"Caller states during a fill some oil sprayed out of the vent pipe onto soil. Spill was cleaned."

Material:

Site ID:	408736
Operable Unit ID:	1165255
Operable Unit:	01
Material ID:	2156662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0612561
Facility Type:	ER
DER Facility ID:	326980
Site ID:	377421
DEC Region:	3
Spill Date:	2007-02-19
Spill Number/Closed Date:	0612561 / 2007-03-12
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-02-19
CID:	410
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party

STEWART RESIDENCE (Continued) **S109414263**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-20
Spill Record Last Update:	2007-03-12
Spiller Name:	SUZANNE LUGO
Spiller Company:	TOWN AND COUNTRY OIL
Spiller Address:	275 EAST 7TH STREET
Spiller City,St,Zip:	MOUNT VERNON, NY 10550
Spiller Company:	001
Contact Name:	NECOLA STEWART
Contact Phone:	(914) 235-6390
DEC Memo:	""
Remarks:	"SPILL WAS LESS THAN ONE GALLON ON ICE OUTSIDE OF RESIDENCE: CLEANUP IN PROGRESS: MATERIAL CAME OUT OF VENT PIPE:"

Material:

Site ID:	377421
Operable Unit ID:	1134955
Operable Unit:	01
Material ID:	2124838
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BE314 **CITGO STATION** **NY LTANKS S103568792**
West **210 WEBSTER AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2090 ft. **Site 2 of 2 in cluster BE**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	492314
Spill Number/Closed Date:	1311416 / Not Reported
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06

CITGO STATION (Continued) **S103568792**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2014-03-06
Spiller Name:	Not reported
Spiller Company:	LINE TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	VISHAL KUMAR
Spiller Phone:	(914) 632-2364
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	216842
DEC Memo:	"Wanye Schneider, WCDOH, is handling...mm"
Remarks:	"regular and super product line test failure - repair/retest pending"

Material:

Site ID:	492314
Operable Unit ID:	1241846
Operable Unit:	01
Material ID:	2242337
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1200103
Facility Type:	ER
DER Facility ID:	216842
Site ID:	462718
DEC Region:	3
Spill Date:	2012-04-04
Spill Number/Closed Date:	1200103 / 2013-11-06
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2012-04-04
CID:	Not reported

CITGO STATION (Continued) **S103568792**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-04
Spill Record Last Update:	2013-11-06
Spiller Name:	MR KUMAR
Spiller Company:	SSN REALTY
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MR KUMAR
Contact Phone:	917 535-6017
DEC Memo:	"4-4-12: V.Mc. call to Mr.Kumar: Phone # no longer is service. 4-4-12: V.Mc. call to SEBASTIAN/WCHD: Left Mess.: Req. callbk. to Dispt. Update from WCDOH: greater than greater than greater than Bimonte, Sebastian greater than spb4@westchestergov.com greater than 4/5/2012 9:46 AM greater than greater than greater than John, SSN Realty 210 Webster Ave New Rochelle NY Super Tank product in interstitial space. Manual check during PBS inspection yesterday. Product clear no water or dirt. Diesel Tank product in interstitial space. Manual check during PBS Inspection yesterday. Product clear no water of dirt. Tanks One was hired to test inner and outer tanks. Super, inner wall passed, outer wall failed. Diesel inner wall failed, outer wall passed. Both tanks should be pumped out by today. Sebastian Bimonte jod 5/23/2012 -- After a meeting in NPO among owner, tank maintenance contractor, Mr. Nesci (attorney), WC DOH, and CK last Friday (5/18), Ispoke to Rachel at Hydro Environmental about a site assessment. Work plan to be submitted shortly. ELM 6/05/12: Update received from Sebastian Bimonte of WCDOH PBS: 1200103: SNN Realty in Mount Vernon. This was product in the interstitial during PBS inspection. No release to environment. Tank repaired NOH issued and can be closed. jod 6/5/2012 -- Site assessment being conducted at my request: field work on 210 Webster Ave in New Rochelle on Tuesday, June 12, 2012 per email from Hydro Enviro. ELM 7/31/2012 -- RI report clearly shows groundwater contamination (BETX/MTBE) around the tank field and dispensers. Need further delineation and RAP. Nothing in unsaturated soils. ELM 8/22/2012 -- Contractor working on a Phase II RI work plan. ELM 9/19/2012 -- Approved an RI work plan. Except that they did include the schedule and failed to mention RAP possibilities. ELM 1/22/2013 -- HydroTech informed me that they have the permit needed from the muny to perform the remediation. ELM 2/21/2013 -- Still no word on mobilizing for remediation. ELM 11-6-13 email from county, There is a whole history here.The 1200103 was for product in the interstitial. Sebastian and Carlos worked with Ed Moore on it.Basically double walled tanks leaked into the interstitial. It appear to be the striker plate were missing and from sticking the tanks they wore out. Eastmond lined the tanks and had trouble removing the product from the IS (completely). We requested spill closure and Ed Moore kept the spill open and continued to work on the PBS issues. They are replacing all tanks now. American Petroleum (Ed- Thank You for making this happen)Wayne Schneider is

CITGO STATION (Continued) **S103568792**

	inspected the site this afternoon and will handle the spill. I suggest we close out spill 1200103 and keep 1307998.(Wayne please provide a brief update to all after your inspection today.) 11-6-13 tanks yanked, new spill 13-07998, close this one RDB "
Remarks:	"12 oz per product found during investigation on inter.cont., on the super tank and diesel tank."

Material:

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210675
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0600746
Facility Type:	ER
DER Facility ID:	216842
Site ID:	362821
DEC Region:	3
Spill Date:	2006-04-19
Spill Number/Closed Date:	0600746 / 2006-08-15
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-04-19
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported

CITGO STATION (Continued) **S103568792**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-04-19
Spill Record Last Update:	2006-12-28
Spiller Name:	SEBASTIAN BELLAFONTE
Spiller Company:	CITGO STATION.
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN BELLAFONTE
Contact Phone:	Not reported
DEC Memo:	"04/25/06: refer to WC PBS. 12/21/06 - Letter from Barbara McDonald from WCDOH to Sebastian Bulfamonte, SSN Realty 94 1st Street, New Rochelle, NY 10801, states that documentation is acceptable to the Westchester County Department of Health and the work permits issued 5/11/06 and 6/6/06 are closed. NFA."
Remarks:	"FOUND THE MATERIAL BETWEEN THE INTERSTIAL SPACE OF THE TWO TANKS. 4000 GAL TANKS. PBS 3-180092"

Material:

Site ID:	362821
Operable Unit ID:	1120900
Operable Unit:	01
Material ID:	2110381
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0413599
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342744
DEC Region:	3
Spill Date:	2005-03-30
Spill Number/Closed Date:	0413599 / 2005-03-30
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6000
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

CITGO STATION (Continued) **S103568792**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN
Contact Phone:	(914) 447-6407
DEC Memo:	""
Remarks:	"IT WAS SOME RESIDEU IN A SPILL BUCKET ALL CLEANED UP:"

Material:

Site ID:	342744
Operable Unit ID:	1101460
Operable Unit:	01
Material ID:	581627
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0413600
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342745
DEC Region:	3
Spill Date:	2005-03-30
Spill Number/Closed Date:	0413600 / 2005-03-30
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6000
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

CITGO STATION (Continued) **S103568792**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN
Contact Phone:	(914) 447-6407
DEC Memo:	""
Remarks:	"WHILE CHANGING OIL THEY KICKED A BUCKET OVER AND IN PROCESS OF CLEANING UP AT THIS TIME;"

Material:

Site ID:	342745
Operable Unit ID:	1101461
Operable Unit:	01
Material ID:	581628
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	8906053
Facility Type:	ER
DER Facility ID:	216842
Site ID:	266088
DEC Region:	3
Spill Date:	1989-07-22
Spill Number/Closed Date:	8906053 / 1989-09-21
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-09-19
Cleanup Meets Std:	True
Last Inspection:	1989-09-19

CITGO STATION (Continued) **S103568792**

Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	MAR-LAP SVC CNTR
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL."
Remarks:	"HAVE EXCAVATED AND REMOVED GAS CONTAMINATED SOIL FROM AROUND 3 5ANKS. SOIL BEING REMOVED TODAY BY E.E.S. NFA"

Material:

Site ID:	266088
Operable Unit ID:	931218
Operable Unit:	01
Material ID:	446446
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

315
SE
1/4-1/2
0.397 mi.
2097 ft.

SPILL NUMBER 0302495 **NY LTANKS S105999167**
85 NORTH AVE **NY Spills N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	353132
Spill Number/Closed Date:	0507677 / 2009-10-09
Spill Date:	2005-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jkomara

SPILL NUMBER 0302495 (Continued) **S105999167**

Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2009-10-09
Spiller Name:	FRANK
Spiller Company:	GAS STATION
Spiller Address:	85 NORTH AVE.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FRANK
Spiller Phone:	(914) 632-2109
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	"9/28/05 Also see spills 03-04446, 05-11827 and 05-07653. jod Closure report received and site visit with WCHD performed. NFA if no money State money spent on Spill # 0304446 pin # 03236. 4/5/07 JO'M 10/9/09 Closed this spill refer to 0304446 JO'M"
Remarks:	"LINE FAILURE."

Material:

Site ID:	353132
Operable Unit ID:	1110599
Operable Unit:	01
Material ID:	2100636
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	114935
Spill Number/Closed Date:	0302495 / 2003-08-12
Spill Date:	2003-06-09
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD

SPILL NUMBER 0302495 (Continued) **S105999167**

Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-09
CID:	405
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-08-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	85 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DISPATCHER 629
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	""
Remarks:	"caller states that there is an overspill at the above address - some has gone into the sewer - cell # 914-760-1305 is for the fire chief on scene - unknown if the spill is stopped or not"

Material:

Site ID:	114935
Operable Unit ID:	869316
Operable Unit:	01
Material ID:	506969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0507653
Facility Type:	ER
DER Facility ID:	100200
Site ID:	353098
DEC Region:	3
Spill Date:	2005-09-26
Spill Number/Closed Date:	0507653 / 2005-10-07
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010

SPILL NUMBER 0302495 (Continued) **S105999167**

Investigator:	JKOMARA
Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2005-10-07
Spiller Name:	FRANK
Spiller Company:	FRANKIES AUTO
Spiller Address:	85 NORTH AVE.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	FRANK
Contact Phone:	(914) 632-2109
DEC Memo:	"9/28/05 Also see spills 03-04446, 03-11827 and 05-07677. jod 10/07/05 Refer to spill 05-07677 for all updates. This spill number closed. jod"
Remarks:	"GASOLINE IN SANITARY SEWER NEXT TO STATION AND ODORS: PLEASE CALL DOH ON THIS ISSUE"

Material:

Site ID:	353098
Operable Unit ID:	1110568
Operable Unit:	01
Material ID:	2100602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA316 **JEROME RESIDENCE** **NY LTANKS** **S106702572**
ENE **33 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2097 ft. **Site 3 of 4 in cluster BA**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	235222
Spill Number/Closed Date:	0405389 / 2005-02-13
Spill Date:	2004-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

JEROME RESIDENCE (Continued) **S106702572**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-08-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-17
Spill Record Last Update:	2005-02-13
Spiller Name:	MARK JEROME
Spiller Company:	JEROME RESIDENCE
Spiller Address:	33 ECHO AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARK JEROME
Spiller Phone:	(914) 632-5400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193747
DEC Memo:	"02/13/05 MILLER ENVIRONMENTAL REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- ISOLATION & RETEST"

Material:

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489552
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

JEROME RESIDENCE (Continued) **S106702572**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 235222
Spill Tank Test: 1529557
Tank Number: Not reported
Tank Size: 1000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

BG317 **BRIEN-AMIE RESIDENCE** **NY LTANKS** **S105999591**
NW **105 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2098 ft. **Site 2 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:
Site ID: 219644
Spill Number/Closed Date: 0304963 / 2004-02-02
Spill Date: 2003-08-08
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-08-11
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-08-11
Spill Record Last Update: 2004-02-02
Spiller Name: BRIEN-AMIE RESIDENCE
Spiller Company: Not reported
Spiller Address: 105 SICKLES AVE
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: BRIEN-AMIE RESIDENCE
Spiller Phone: (914) 576-6823
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 181652
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/11/03: 1000 gal. underground tank. 02/02/04 DUTCHESS

BRIEN-AMIE RESIDENCE (Continued) **S105999591**

DISPOSED OF LUST AND 75.35 TONS OF CONTAMINATED SOIL. SAMPLE RESULTS BELOW TAGM LIMITS. NFA jbo"

Remarks: "they were doing an inplace closure tank abandonment & encountered contaminated soil from the 550 gal underground tank - unk about soil removal at this point"

Material:

Site ID:	219644
Operable Unit ID:	873280
Operable Unit:	01
Material ID:	502238
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH318 **MICELI HOME** **NY LTANKS** **S108059468**
SSE **194 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2098 ft. **Site 1 of 4 in cluster BH**

Relative: **Lower**

Actual: **78 ft.**

LTANKS:

Site ID:	366997
Spill Number/Closed Date:	0604103 / 2006-10-22
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-10-22
Spiller Name:	MARIO MICELI
Spiller Company:	MICELI HOME
Spiller Address:	194 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY

MICELI HOME (Continued) **S108059468**

Spiller County:	001
Spiller Contact:	MARIO MICELI
Spiller Phone:	(914) 235-2198
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317018
DEC Memo:	"CLOSING REPORT TO JOHN O'DEE. October 22, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 23.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 gallon tank had holes"

Material:

Site ID:	366997
Operable Unit ID:	1124924
Operable Unit:	01
Material ID:	2114431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA319 **POWERTEST,ECHO & MAIN** **NY LTANKS** **S100139866**
ENE **36 ECHO AVE @ MAIN ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2111 ft. **Site 4 of 4 in cluster BA**

Relative:
Lower

Actual:
33 ft.

LTANKS:

Site ID:	283199
Spill Number/Closed Date:	8709260 / 1988-02-11
Spill Date:	1988-01-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-11
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True

POWERTEST,ECHO & MAIN (Continued) **S100139866**

Remediation Phase:	0
Date Entered In Computer:	1988-02-01
Spill Record Last Update:	1988-06-13
Spiller Name:	Not reported
Spiller Company:	HACKER,JOSHUA;POWERTEST
Spiller Address:	Not reported
Spiller City,St,Zip:	LISK, MA
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229700
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 02-01-88 TANK REPLACED 5 YRS.AGO. AS PER DEPUTY CHIEF WILLIAM COMVERY,BASEMENT ODORS GREATLY DISSAPATED, ONCE VENTED. 02/11/88: CHECKED STATION; SEEMS TO BE ODOR PROBLEM DURING DELIVERIES. 11/29/95: This is additional information about material spilled from the translation of the old spill file: FUMES."
Remarks:	"DELIVERY THIS MORNING, ONGOING PROBLEM, EXPLOSIVE READING IN BASEMENT. NEW ROCHELLE F.D. HAS VENTED BASEMENT AND WILL MONITOR."

Material:

Site ID:	283199
Operable Unit ID:	914517
Operable Unit:	01
Material ID:	464589
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG320 **POINVIL RESIDENCE** **NY LTANKS** **S111160012**
NW **107 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2113 ft. **Site 3 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	452458
Spill Number/Closed Date:	1104844 / 2014-11-05
Spill Date:	2011-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False

POINVIL RESIDENCE (Continued) **S111160012**

SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-28
Spill Record Last Update:	2014-11-05
Spiller Name:	HENRY POINVILE
Spiller Company:	POINVILE
Spiller Address:	107 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NN
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	407046
DEC Memo:	"7-28-11 Spoke with Kathy Morgan, This a is a real estate transaction. The plan at this time is to uncover, isolate and retest. The tank is 1080 gallon UST that is probably the original tank - age unknown. jm 2/17/12: Residential TTF, DEC Lead changed to unassigned. jod 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M"
Remarks:	"repair/retest pending -"

Material:

Site ID:	452458
Operable Unit ID:	1202639
Operable Unit:	01
Material ID:	2199228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BD321 **AMOCO SERVICE STATION #736** **NY LTANKS** **1001128018**
SSW **690 MAIN ST** **NY Spills** **NYR000036855**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.403 mi. **NY MANIFEST**
2128 ft. **Site 3 of 3 in cluster BD**

Relative:
Lower

Actual:
64 ft.

LTANKS:

Site ID:	274754
Spill Number/Closed Date:	0209490 / 2002-12-16
Spill Date:	2002-12-16
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-16
CID:	246
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2002-12-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller County:	999
Spiller Contact:	DAVE BERRY
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"Tanker overfilled tank and material spilled at location. Approx 10 gal went into storm drain and sewer. Fire dept on scene now speedy dry applied"

Material:

Site ID:	274754
Operable Unit ID:	862563
Operable Unit:	01
Material ID:	512914
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	Gallons
Recovered:	15.00
Resource Affected:	Not reported
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Tank Test:

Site ID:	274755
Spill Number/Closed Date:	0212950 / 2003-04-01
Spill Date:	2003-03-31
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-03-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-31
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	WESTCHESTER CO 911
Spiller Phone:	(914) 231-1904
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"PRODUCT DID ENTER CONTAINMENT AREA - NO CLEAN UP"

Material:

Site ID:	274755
Operable Unit ID:	863771
Operable Unit:	01
Material ID:	512669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Site ID:	274757
Spill Number/Closed Date:	8604411 / 1987-01-14
Spill Date:	1986-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1987-01-14
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-01-14
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-10-16
Spill Record Last Update:	1998-03-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	SAME
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"TTTF"

Material:

Site ID:	274757
Operable Unit ID:	901332
Operable Unit:	01
Material ID:	477220
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	274757
Spill Tank Test:	1530280
Tank Number:	Not reported
Tank Size:	0
Test Method:	00

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0305414
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274756
DEC Region:	3
Spill Date:	2003-08-21
Spill Number/Closed Date:	0305414 / 2003-10-29
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-08-21
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2003-10-29
Spiller Name:	Not reported
Spiller Company:	USA PETRO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CINDY BADOLATO
Contact Phone:	(914) 813-5165
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BADOLATO 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED AS OF 9/12/03"
Remarks:	"leaking valve on a pump - pbs #3-183660 - pump taken out of service"

Material:

Site ID:	274756
Operable Unit ID:	873709
Operable Unit:	01
Material ID:	502669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0002007
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274753
DEC Region:	3
Spill Date:	2000-05-17
Spill Number/Closed Date:	0002007 / 2000-05-17
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-17
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-05-17
Spill Record Last Update:	2000-07-17
Spiller Name:	ALFRED
Spiller Company:	AM0CO STATION 736
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ALFRED
Contact Phone:	(914) 632-8617
DEC Memo:	""
Remarks:	"maintance crew on the way for cleanup and repairs"

Material:

Site ID:	274753
Operable Unit ID:	823636
Operable Unit:	01
Material ID:	550387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Tank Test:

Facility ID:	9806161
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274759
DEC Region:	3
Spill Date:	1998-08-18
Spill Number/Closed Date:	9806161 / 2005-02-14
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-08-18
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-18
Spill Record Last Update:	2005-02-14
Spiller Name:	ERIC LISMANIS
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERIC LISMANIS
Contact Phone:	(914) 273-2626
DEC Memo:	"2/14/05 HANDLE AS PART OF 9613029--CLSOE"
Remarks:	"PUMP MALFUNCTION FOR UNDERGROUND STORAGE TANK / NO CLEAN UP"

Material:

Site ID:	274759
Operable Unit ID:	1067358
Operable Unit:	01
Material ID:	317336
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Facility ID:	9613029
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274758
DEC Region:	3
Spill Date:	1997-01-29
Spill Number/Closed Date:	9613029 / 2013-04-26
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1997-02-04
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-04
Spill Record Last Update:	2013-04-26
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY ALSO SEE SPILL 91-11342. 02/07/97 AS PART OF AN ONGOING REMEDIATION THEY FOUND NEWER PRODUCT INFLUENCING THEIR CLEAN UP. 04/24/97 LETTER & STIPULATION AGREEMENT SENT TO BE SIGNED. 12/10/97 COPY OF SIGNED STIPULATION SENT BACK 08/11/98 LETTER SENT; IMMEDIATE ACTION TOWARD AUTOMATED PRODUCT REMOVAL AND GROUNDWATER CONTROL AT SITE IS REQUIRED. 12/07/00 LETTER SENT TO DELTA ENVIRONMENTAL BY J. HARDY; PROPOSE A REMEDIAL ACTION PLAN WHICH IS SUBSTANTIALLY MORE AGRESSIVE THAN THE ONE EXISTING AT THIS TIME. 01/11/01 LETTER SENT TO DELTA ENV. BY J. HARDY; CONCEPTUAL REMEDIAL ACTION PLAN OF 12/13/00 IS APPROVED & REQUIRED. 4/23/04: Letter to Aaron Lapine, Delta Env. Consultants by J. Hardy. Submit one report per year. Include operating data and GW monitoring data in same report. 8/9/04: Letter to A. Lapine, Delta Env. from J Hardy. Reduce monitor well sampling to semi-annual. Report annually. 6/15/09 annual submitted 6/9/09 shows relatively stable groundwater levels but no info as to system operation--sent email to envirotrac to submit operation info jh 4/20/10 site in remediation as system has been operating for many years. Original impacts to adjoining restaurant have also been resolved for years so it seems spill is contained; spill cannot be closed however as there is still significant contamination jh 07/02/12 Contaminated soils on the station have been excavated down to bedrock. 4 gw wells remain, 1 on-site upgradient, 2 off-site downgradient , 1 in the tank field. After review of the documentation

AMOCO SERVICE STATION #736 (Continued) **1001128018**

and a phone conversation, consultant will submit a quarterly groundwater monitoring plan for the next year, after which time the monitoring frequency may be adjusted based on results. It appears the source has been removed. mt 4/26/13 Spill Closed, asymptptic conditions approaching gw standards in final well. no further action required. mt "

Remarks: "THEY HAVE A 1991 SPILL NUMBER, BUT THIS APPEARS TO BE A FRESH SPILL UNK IF SAME"

Material:

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	2096843
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	341679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9313209
Facility Type:	ER
DER Facility ID:	101511
Site ID:	116685
DEC Region:	3
Spill Date:	1994-02-07
Spill Number/Closed Date:	9313209 / 1994-02-28
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-07
CID:	Not reported
Water Affected:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	1994-06-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/03/94: NO DEC RESPONSE. "
Remarks:	"ICE IN FILL BOX SORBENTS USED TO CLEAN UP"

Material:

Site ID:	116685
Operable Unit ID:	995095
Operable Unit:	01
Material ID:	388600
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AMOCO SERVICE STATION #736
Facility address:	690 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYR000036855
Mailing address:	OLD POST RD BALTEZ ASSOCIATES INC BEDFORD, NY 10506
Contact:	Not reported
Contact address:	OLD POST RD BEDFORD, NY 10506
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: (201) 331-7000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: (201) 331-7000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AMOCO SERVICE STATION #736
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: AMOCO SERVICE STATION #736
Classification: Small Quantity Generator

Date form received by agency: 03/21/1997
Site name: AMOCO SERVICE STATION #736
Classification: Large Quantity Generator

. Waste code: D001

AMOCO SERVICE STATION #736 (Continued) **1001128018**

. Waste name: IGNITABLE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000036855
Country: USA
Location Address 1: 690 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: AMOCO SERVICE STATION #736
Contact: JONATHAN LANDAU
Address: 130 BUSINESS PARK DR
City/State/Zip: ARMONK, NY 10504
Country: USA
Phone: 914-234-9580

Manifest:

Document ID: CTF0396117
Manifest Status: Completed copy
Trans1 State ID: 7069A
Trans2 State ID: Not reported
Generator Ship Date: 04/24/1997
Trans1 Recv Date: 04/24/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 04/25/1997
Part A Recv Date: 05/21/1997
Part B Recv Date: 05/15/1997
Generator EPA ID: NYR000036855
Trans1 EPA ID: CTD983883745
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00619
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

Document ID: NYG0063774
Manifest Status: Not reported
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 04/27/1998
Trans1 Recv Date: 04/27/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Generator EPA ID:	NYR000036855
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID:	GAD093380814
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

BI322 **RESIDENCE** **NY LTANKS** **S107523528**
East **10 LAFAYETTE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2132 ft. **Site 1 of 3 in cluster BI**

Relative:
Lower

Actual:
47 ft.

LTANKS:

Site ID:	358990
Spill Number/Closed Date:	0512638 / 2006-03-15
Spill Date:	2006-02-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-01
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-01
Spill Record Last Update:	2006-03-15
Spiller Name:	MARIO KOTLAR
Spiller Company:	RESIDENCE
Spiller Address:	10 LAFFEYTE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	MARIO KOTLAR
Spiller Phone:	(914) 235-8882
Spiller Extention:	Not reported
DEC Region:	3

RESIDENCE (Continued) **S107523528**

DER Facility ID: 308993
DEC Memo: "Northeast to return 2/3/06 for soil excavation & sampling. March 15, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 42.57 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Tank removal, tank size 1000 gallon."

Material:
Site ID: 358990
Operable Unit ID: 1116216
Operable Unit: 01
Material ID: 2106363
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BF323 **YOUNG ADULT INSTITUTE** **NY LTANKS** **S107410752**
West **150 VAN GUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 2 of 2 in cluster BF**

Relative:
Lower

Actual:
77 ft.

LTANKS:
Site ID: 353295
Spill Number/Closed Date: 0507808 / 2005-12-18
Spill Date: 2005-09-29
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-09-29
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-09-29
Spill Record Last Update: 2005-12-18
Spiller Name: MARGARET FORC
Spiller Company: YOUNG ADULT INSTITUTE
Spiller Address: 150 VAN GUILDER AVE

YOUNG ADULT INSTITUTE (Continued) **S107410752**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARGARET FORC
Spiller Phone:	(212) 273-6172
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300615
DEC Memo:	"Left message with contact. Robison returning to clean up fuel in street. New England was removing UST and some product leaked out of tank on ground. Area roped off by Fire Marshal. December 18, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 13.63 TONS OF CONTAMINATED SOIL. CLEAN UP COMPLETED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. DISPOSAL RECEIPT FORWARDED TO BECI. jod"
Remarks:	"550 GALLON TANK AND FOUND HOLES: FIRE MARSHALL ON SCENE"

Material:

Site ID:	353295
Operable Unit ID:	1110757
Operable Unit:	01
Material ID:	2100797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BJ324 **COMMERCIAL-TTF** **NY LTANKS** **S117975659**
West **172 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 1 of 4 in cluster BJ**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	508618
Spill Number/Closed Date:	1502358 / Not Reported
Spill Date:	2015-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported
Water Affected:	Not reported

COMMERCIAL-TTF (Continued) **S117975659**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2015-08-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	463301
DEC Memo:	"6/3/15 Spoke to Mr. Scorzelli, who did not have contact info for owner at that time, and does not know what owner will be doing. dw "
Remarks:	"TEST FAILURE"

Material:

Site ID:	508618
Operable Unit ID:	1257927
Operable Unit:	01
Material ID:	2260991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG325 **TAHIR RESIDENCE** **NY LTANKS** **S108299038**
NW **112 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2147 ft. **Site 4 of 6 in cluster BG**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	374522
Spill Number/Closed Date:	0610140 / 2007-10-24
Spill Date:	2006-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA

TAHIR RESIDENCE (Continued) **S108299038**

Referred To:	Not reported
Reported to Dept:	2006-12-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-06
Spill Record Last Update:	2007-10-24
Spiller Name:	ISMAIL GALVAN
Spiller Company:	Not reported
Spiller Address:	112 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ISMAIL GALVAN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	324199
DEC Memo:	"09/18/07 Dutchess Environmental reported that the 550 gallon tank was removed and that no sign of oil contamination was observed in the tank grave. NFA TG"
Remarks:	"UNCOVER REPAIR AND TEST OR REMOVE"

Material:

Site ID:	374522
Operable Unit ID:	1132196
Operable Unit:	01
Material ID:	2121918
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	374522
Spill Tank Test:	1550484
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	0911724

TAHIR RESIDENCE (Continued) **S108299038**

Facility Type:	ER
DER Facility ID:	324199
Site ID:	424559
DEC Region:	3
Spill Date:	2010-02-02
Spill Number/Closed Date:	0911724 / 2010-03-22
Spill Cause:	Human Error
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2010-02-12
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2010-03-22
Spiller Name:	CHRIS
Spiller Company:	PARADISE OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ISHMAEL TAHIR
Contact Phone:	(914) 563-5682
DEC Memo:	"2/3/10 homeowner, Mr. Tahir, is satisfied with cleanup done by Paradise Oil Co., both inside and outside the house. NFA dw 2/12/10: Spill re-opened. WCDOH reported this spill, after complaints by home owner that the oil company had taken no action. Marc Grazioli re-inspected the site today and reports the spill has still not been remediated. jod 2/17/10: Update from Marc Grazioli: The outside portion of the spill was handled before the big snow that came last week. I was only able to look into the basement through an open window since no one was home when I was there. There was absorbent on the ground and I would guess it was the second round of cleanup because it appeared dry. jod 3/22/10: DEC requires no further action at this time. jod"
Remarks:	"5gals oil to basement area/10 gals to out side,driveway. Clean up complete"

Material:

Site ID:	424559
Operable Unit ID:	1180325
Operable Unit:	01
Material ID:	2174200
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons

TAHIR RESIDENCE (Continued) **S108299038**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BK326 **GAS STATION** **NY LTANKS** **S116156793**
ENE **44 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2150 ft. **Site 1 of 3 in cluster BK**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	490405
Spill Number/Closed Date:	1309599 / 2014-02-13
Spill Date:	2014-01-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-02
Spill Record Last Update:	2014-02-13
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	CARLOS TORREZ
Spiller Phone:	(914) 424-5927
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"1/2/14 - WCDOH is oversight the ongoing tank tests. KAB 1/2/2014 -- APECCO hired by new operator (lease signed within past 6 weeks). Piping and dispensers and electronic leak monitoring equipment to be replaced. Based on lack of leak detection records for past 10 to 12 years, DEC requested TT and IS tests and system check of electronics. Tanks are probably suitable for service, but testing required for confirmation. It appears to be loose fittings. Electronics recently rewired at the computer console within past couple of weeks, but wiring ended near the top of the tanks. No probes in the interstitial space, just loose wiring near top of tank. Owner’s representative took electronic system wire ends from the site despite WCDOH’s

GAS STATION (Continued) **S116156793**

request to take custody. ELM 2-13-14 closed and referred to spill 13-10365 which revealed contaminated soils when the failed lines were removed. RDB"

Remarks: "repair/retest pending - to Ed Moore (waiting for results)"

Material:

Site ID:	490405
Operable Unit ID:	1239966
Operable Unit:	01
Material ID:	2240056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BK327 **DAVENPORT AUTO / WEST PLAINS SERVICE** **NY LTANKS** **S110309404**
ENE **44 ECHO AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2150 ft. **Site 2 of 3 in cluster BK**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	130487
Spill Number/Closed Date:	9201557 / 2006-02-17
Spill Date:	1992-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	1992-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/17/06 SEE SPILLS 92-10118 AND 92-10810. jod"
Remarks:	"FOUND LINE LEAKING AT DISPENSER GASOLINE TANK IS OK MAIN & ELMSFORD TO POSS. REPAIR MONDAY WILLIAMS SUGGESTED TO MAIN & ELMSFORD CO. THAT THEUY SHUT THIS PUMP DOWN UNTIL REPAIRS ARE MADE SPOKE W/ WILL"

Material:

Site ID:	130487
Operable Unit ID:	968828
Operable Unit:	01
Material ID:	412859
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	130487
Spill Tank Test:	1539973
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	130489
Spill Number/Closed Date:	9210810 / 1995-02-09
Spill Date:	1992-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-02-09
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E.I.R. PETRO-TITE"

Material:

Site ID:	130489
Operable Unit ID:	975022
Operable Unit:	01
Material ID:	404252
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	130489
Spill Tank Test:	1540972
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	434525
Spill Number/Closed Date:	1001469 / 2010-11-01
Spill Date:	2010-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-07
Spill Record Last Update:	2010-11-01
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	INA -
Spiller Phone:	(914) 235-8073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"5/7/10 Metro Env. tested UST, and it failed a TT. Davenport Auto thinks it may be fuel lines, and got list of contractors to examine problem more closely, and to determine remedial actions. Site is a WCHD-PBS site# 3-137480 Tank was tank #6- 550 gal. dw 11/1/10 As per WCDOH Two tanks pulled, reviewed TCR, recommend NFA. NFA JOM "
Remarks:	"tank test - cleanup pending"

Material:

Site ID:	434525
Operable Unit ID:	1185347
Operable Unit:	01
Material ID:	2179667
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1310365
Facility Type:	ER
DER Facility ID:	389397
Site ID:	491212
DEC Region:	3
Spill Date:	2014-01-29

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Spill Number/Closed Date:	1310365 / Not Reported
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-01-29
Spill Record Last Update:	2014-07-22
Spiller Name:	Not reported
Spiller Company:	WEST PLAINS SERVICE INC
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MICHAEL BURNSTEIN
Contact Phone:	(914) 235-8073
DEC Memo:	"Chris Lalak called duty desk. American Petro is pulling tanks today. WCDOH is handling this and will do follow up...mm 1/29/2014 -- Called Pat Dunn @ APECCO to get some details. Dispensers had no sumps; discovered soil contamination under a dispenser. Trench along side dispenser is clean to 2 1/2 feet below grade; they expect limited dig and haul. ELM 2-11-14 Iyt was not a tank pull as originally noted by WCHD only line and dispenser replacement. RDB 2-13-14, spill #13-09599 was closed and referred to this one, the line test failure led to thic contamination RDB 03-14 contamination deep in excavation under former dispenser. crews worried about garage and building under neath, met on site with Gary and owner, advised them additional soil needed removal. 03-10-14 Using a Hydro Vac to get the remaining contaminated soils from excavation. 03-18-14 status report in edocs 05-13-14 email from Gary, Work done, report done,plan on forwarding report to you today once we get payment. RDB 07-22-14 gary looking for closure, I am looking for closure report.sent email requesting RDB"
Remarks:	"cleanup in progress"

Material:

Site ID:	491212
Operable Unit ID:	1240767
Operable Unit:	01
Material ID:	2240992
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 9210118
Facility Type: ER
DER Facility ID: 309856
Site ID: 130488
DEC Region: 3
Spill Date: 1992-12-01
Spill Number/Closed Date: 9210118 / 1997-11-07
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-12-01
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1992-12-15
Spill Record Last Update: 2006-02-17
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "GASOLINE ODOR IN BASEMENT OF APARTMENT BUILDING NEXT DOOR TO GAS STATION GAS STATION RECEIVED A DELIVERY AT 8:00 A.M. T. GHIOSAY RESPONDED"

Material:
Site ID: 130488
Operable Unit ID: 976578
Operable Unit: 01
Material ID: 407123
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Pounds
Recovered: .00

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

328
SSW
1/4-1/2
0.409 mi.
2158 ft.

SPILL NUMBER 0012427 **NY LTANKS** **S104950616**
22 LAUREL PL **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	104510
Spill Number/Closed Date:	0012427 / 2001-05-10
Spill Date:	2001-02-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-02-20
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-20
Spill Record Last Update:	2001-06-05
Spiller Name:	LOUIS MEAD
Spiller Company:	Not reported
Spiller Address:	22 LAUREL PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LOUIS MEAD
Spiller Phone:	(914) 662-3557
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92327
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/20/2001 TANK OUT OF USE FOR 20 YEARS. PIN HOLES & MINOR SOIL CONTAMINATION FOUND. 05/10/2001 ELITE ENVIRONMENTAL AND NES PULLED TANK AND COMPLETED CLEANUP; NO FURTHER ACTION."
Remarks:	"small amount of contamination found while pulling a 1000 gal tank. "

Material:

Site ID:	104510
Operable Unit ID:	833963
Operable Unit:	01
Material ID:	542696
Material Code:	0001A

SPILL NUMBER 0012427 (Continued) **S104950616**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH329 **200 CENTRA CORP** **NY LTANKS** **S108059537**
SSE **200 CENTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.412 mi.
2175 ft. **Site 2 of 4 in cluster BH**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	367663
Spill Number/Closed Date:	0604650 / 2007-12-12
Spill Date:	2006-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-07-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-25
Spill Record Last Update:	2007-12-12
Spiller Name:	SHARON ROURKE
Spiller Company:	200 CENTRA CORP
Spiller Address:	200 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SHARON ROURKE
Spiller Phone:	(203) 557-3600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317637
DEC Memo:	"12/04/06 Tank removed and samples ok according to D Jackson - WCHD. TG"
Remarks:	"PBS No: 3-800237 -PBS No. not found in UIS, may be invalid. UNCOVER REPAIR AND TEST"

200 CENTRA CORP (Continued) **S108059537**

Material:

Site ID:	367663
Operable Unit ID:	1125568
Operable Unit:	01
Material ID:	2115091
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	367663
Spill Tank Test:	1550151
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BK330 **CONSOLIDATED EDISON - ECHO AVE. SITE** **NY SHWS** **S101008407**
ENE **ECHO AVENUE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.412 mi.
2178 ft. **Site 3 of 3 in cluster BK**

Relative:
Lower

Actual:
30 ft.

SHWS:

Program:	HW
Site Code:	56077
Classification:	P
Region:	3
Acres:	3
HW Code:	360016
Record Add:	11/18/1999
Record Upd:	04/07/2015
Updated By:	GWHEITZM

Site Description: LocationThe Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. This 3 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal).Site FeaturesAll the former structures and underground utility services have been removed, and the whole site has been levelled, top-soiled and grassed.Current UseThe site is currently vacantPast Use of the SiteCon Edison used the site as an electrical distribution substation until 1981. PCBs transformers were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. The soil on site and the sediment in the Bay were

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

	contaminated with PCBs.
Env Problem:	Prior to remediation the contaminant of concern was PCBs.Remediation of the site is complete. The cleanup of PCBs and other incidentally detected contaminants has mitigated the threat to the environment, and in particular to the natural habitat in the bay.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BJ331 **FIRST ASSEMBLY OF GOD** **NY LTANKS** **S110490783**
West **177 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.414 mi.
2186 ft. **Site 2 of 4 in cluster BJ**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	435290
Spill Number/Closed Date:	1002183 / 2010-08-30
Spill Date:	2010-05-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-26
Spill Record Last Update:	2010-08-30
Spiller Name:	Not reported
Spiller Company:	BARNABY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	BARNABY
Spiller Phone:	(914) 632-0031
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	390193
DEC Memo:	"7/1/10: No call backs made by dispatch desk. No indication of contamination at the time of the report. Unknown action at this time. jod 08/19/10 Northeast Environmental reported that they excavated and removed the LUST along with 40.92 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA. TG"

FIRST ASSEMBLY OF GOD (Continued) **S110490783**

Remarks: "550gal ust"

Material:
Site ID: 435290
Operable Unit ID: 1186074
Operable Unit: 01
Material ID: 2180843
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

332
WSW
1/4-1/2
0.415 mi.
2193 ft.

48 1ST STREET **NY LTANKS** **S104279084**
48 1ST STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:
Site ID: 116893
Spill Number/Closed Date: 9911183 / 1999-12-22
Spill Date: 1999-12-22
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: PJDECICC
Referred To: Not reported
Reported to Dept: 1999-12-22
CID: 389
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-12-22
Spill Record Last Update: 1999-12-30
Spiller Name: CALLER
Spiller Company: CASTLE OIL CORPORTATION
Spiller Address: 290 LOCUST AVENUE
Spiller City,St,Zip: BRONX, NY
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported

48 1ST STREET (Continued) **S104279084**

DEC Region: 3
DER Facility ID: 101696
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO "
Remarks: "caller reporting a spill of material from a tank overfill clean up was done no callback is necessary"

Material:
Site ID: 116893
Operable Unit ID: 1089889
Operable Unit: 01
Material ID: 296651
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: Gallons
Recovered: 5.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BI333 **GONCALVES RESIDENCE** **NY LTANKS** **S108298870**
East **1 LAFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2196 ft. **Site 2 of 3 in cluster BI**

Relative:
Lower

Actual:
35 ft.

LTANKS:
Site ID: 373629
Spill Number/Closed Date: 0609401 / 2007-01-10
Spill Date: 2006-11-15
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-11-15
CID: 410
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-11-15
Spill Record Last Update: 2007-01-10
Spiller Name: ED ALLEN
Spiller Company: ROBINSON OIL
Spiller Address: 500 EXECUTIVE BLVD

GONCALVES RESIDENCE (Continued) **S108298870**

Spiller City,St,Zip:	ELMSFORD, NY
Spiller County:	001
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323367
DEC Memo:	""
Remarks:	"CLEANUP IN PROGRESS:"

Material:

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	2.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BI334 **GONCALVES RESIDENCE** **NY LTANKS** **S102674341**
East **1 LAFFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2196 ft. **Site 3 of 3 in cluster BI**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	156301
Spill Number/Closed Date:	9410991 / 1994-11-29
Spill Date:	1994-11-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-11-29
Cleanup Meets Standard:	False

GONCALVES RESIDENCE (Continued) **S102674341**

SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132292
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED 100 GAL. COULDN'T FIT BEING CLEANED NOW SPEEDI-DRI AND PADS COMPLETED"

Material:

Site ID:	156301
Operable Unit ID:	1008868
Operable Unit:	01
Material ID:	376855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG335 **RESIDENCE** **NY LTANKS** **S107410404**
NW **7 PRINCE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2198 ft. **Site 5 of 6 in cluster BG**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Site ID:	351640
Spill Number/Closed Date:	0506424 / 2005-10-29
Spill Date:	2005-08-24
Spill Cause:	Tank Failure

RESIDENCE (Continued) **S107410404**

Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-24
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-24
Spill Record Last Update:	2005-10-29
Spiller Name:	JOHN BROWN
Spiller Company:	RESIDENCE
Spiller Address:	7 PRINCE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10803
Spiller County:	001
Spiller Contact:	JOHN BROWN
Spiller Phone:	(914) 879-7900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	298912
DEC Memo:	"Report to John O'Dee -RA October 29, 2005: CASTLTON DISPOSED OF LUST AND 57.27 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

Material:

Site ID:	351640
Operable Unit ID:	1109140
Operable Unit:	01
Material ID:	2099127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BJ336 **SPILL NUMBER 0210119** **NY LTANKS** **S105997830**
WSW **68 FIRST STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.419 mi.
2212 ft. **Site 3 of 4 in cluster BJ**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	267616
Spill Number/Closed Date:	0210119 / 2003-03-03
Spill Date:	2002-12-03
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-07
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-07
Spill Record Last Update:	2003-03-03
Spiller Name:	OWNER
Spiller Company:	NEW ROCHELLE HOUSING
Spiller Address:	68 FIRST STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	218016
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/07/03: Also see spill #02-10080. Dec 2003 - 1000 gallon UST removed along with 150 tons of impacted soil. Tank removal report submitted by American Envionmental Assessment Corp. NFA. TG"
Remarks:	"CALLER PULLED TANK AND FOUND CONTAMINATION. "

Material:

Site ID:	267616
Operable Unit ID:	861369
Operable Unit:	01
Material ID:	513520
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILL NUMBER 0210119 (Continued) **S105997830**

Tank Test:

BG337 **RENTAL HOUSE** **NY LTANKS** **S100153568**
NW **119 SICKLES AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.421 mi.
2221 ft. **Site 6 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	119461
Spill Number/Closed Date:	9107320 / 1991-11-25
Spill Date:	1991-10-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	HOULIHAN & LAWRENCE RLTY.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103766
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DISCOVERED SEEPAGE FROM TANK ON BASEMENT CONCRETE FLOOR APPLIED SPEEDI-DRY SPILLER WILL CONTACT LUZON OIL FOR CLEAN UP"

Material:

Site ID:	119461
Operable Unit ID:	961556
Operable Unit:	01
Material ID:	419532
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

RENTAL HOUSE (Continued) **S100153568**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BL338 **SPILL NUMBER 0104402** **NY LTANKS** **S105135031**
NE **30 LINCOLN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.426 mi.
2247 ft. **Site 1 of 2 in cluster BL**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Site ID:	328750
Spill Number/Closed Date:	0104402 / 2001-11-14
Spill Date:	2001-07-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-07-25
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-25
Spill Record Last Update:	2002-02-07
Spiller Name:	OWNER
Spiller Company:	AVALLONE
Spiller Address:	30 LINCOLN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	264577
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/14/2001 G.C. RELIABLE PULLED TANK. NO LEAK OR DISCHARGE EVIDENT. NO FURTHER ACTION."
Remarks:	"failed test"

Material:

Site ID:	328750
Operable Unit ID:	841036
Operable Unit:	01
Material ID:	532897

SPILL NUMBER 0104402 (Continued) **S105135031**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	328750
Spill Tank Test:	1526481
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BJ339 **SPILL NUMBER 0210366** **NY LTANKS** **S105997907**
West **182 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.427 mi.
2253 ft. **Site 4 of 4 in cluster BJ**

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	282696
Spill Number/Closed Date:	0210366 / 2003-03-03
Spill Date:	2003-01-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-14
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001

SPILL NUMBER 0210366 (Continued) **S105997907**

Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229505
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Jan 2003 - 1000 gallon tank was removed from the property. 100 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environemtal Assessement. NFA. TG"
Remarks:	"SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL AT ABOVE LOCATION. PROPTERY IS OWNED BY THE CITY OF NEW ROCHELLE AND CALLER IS A CONTRACTOR FOR THE CITY. TANK APPEARS TO HAVE BEEN ABANDONED YEARDS AGO. "

Material:

Site ID:	282696
Operable Unit ID:	861605
Operable Unit:	01
Material ID:	513753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BM340 **PLASTIC WORKS** **NY LTANKS** **S103824027**
NNE **115 CEDAR ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.430 mi.
2268 ft. **Site 1 of 2 in cluster BM**

Relative:
Lower

Actual:
50 ft.

LTANKS:

Site ID:	163894
Spill Number/Closed Date:	9812998 / 1999-02-22
Spill Date:	1999-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

PLASTIC WORKS (Continued) **S103824027**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	1999-03-01
Spiller Name:	GARY STRUTTEN
Spiller Company:	PLASTIC WORKS
Spiller Address:	115 CEDAR ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	GARY STRUTTEN
Spiller Phone:	(914) 576-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	138224
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER'S COMPANY WAS PULLING A 550GAL UST - TANK WAS FULL OF HOLES"

Material:

Site ID:	163894
Operable Unit ID:	1073438
Operable Unit:	01
Material ID:	313271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH341 **SPILL NUMBER 0202241** **NY LTANKS S102674170**
SSE **208 CENTER AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2277 ft. **Site 3 of 4 in cluster BH**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	215702
Spill Number/Closed Date:	9314003 / 1994-03-11
Spill Date:	1994-02-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-03-11
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-28

SPILL NUMBER 0202241 (Continued) **S102674170**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-11
Spill Record Last Update:	1995-01-05
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK WAS OVERFILLED CASTLE CREW TO CLEAN UP"

Material:

Site ID:	215702
Operable Unit ID:	996014
Operable Unit:	01
Material ID:	389350
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	215703
Spill Number/Closed Date:	9315255 / 1994-04-11
Spill Date:	1994-03-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-04-11
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-26
CID:	Not reported
Water Affected:	Not reported

SPILL NUMBER 0202241 (Continued) **S102674170**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-11
Spill Record Last Update:	1995-01-04
Spiller Name:	Not reported
Spiller Company:	WRG
Spiller Address:	420 WESTCHESTER AVE.
Spiller City,St,Zip:	PORTCHESTER, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY GUAGE RESULTED IN OVERFILL WCHD NOTIFIED CASTLE OIL WILL CLEAN UP"

Material:

Site ID:	215703
Operable Unit ID:	997178
Operable Unit:	01
Material ID:	387016
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0202241
Facility Type:	ER
DER Facility ID:	177797
Site ID:	214599
DEC Region:	3
Spill Date:	2002-06-01
Spill Number/Closed Date:	0202241 / 2002-08-12
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-06-01
CID:	257

SPILL NUMBER 0202241 (Continued) **S102674170**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-01
Spill Record Last Update:	2002-09-26
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	208 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"bad gauge - contained - cleanup to be done by castleton enviromental"
	Not reported

Material:

Site ID:	214599
Operable Unit ID:	855230
Operable Unit:	01
Material ID:	520107
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BL342 **SPILL NUMBER 0300463** **NY LTANKS S105998684**
NE **52 LINCOLN ST** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.432 mi.
2279 ft. **Site 2 of 2 in cluster BL**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Site ID:	202585
Spill Number/Closed Date:	0300463 / 2003-04-14
Spill Date:	2003-04-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy

SPILL NUMBER 0300463 (Continued) **S105998684**

Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-22
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller City,St,Zip:	ELMSFORD, NY 10523-
Spiller County:	001
Spiller Contact:	ED ALLAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	168519
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"Above material reported spilled at above location due to tank overfill. Crew is on site and cleanup is in progress at time of call. All material is expected to be recovered."

Material:

Site ID:	202585
Operable Unit ID:	868761
Operable Unit:	01
Material ID:	508540
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0806544
Facility Type:	ER
DER Facility ID:	168519
Site ID:	403827
DEC Region:	3
Spill Date:	2008-09-10
Spill Number/Closed Date:	0806544 / 2008-12-26
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SPILL NUMBER 0300463 (Continued) **S105998684**

SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-09-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-11
Spill Record Last Update:	2008-12-26
Spiller Name:	LOUIS VACCARO
Spiller Company:	LOIS VACCARO
Spiller Address:	52 LINCOLN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	LOUIS VACCARO
Contact Phone:	(914) 235-8284
DEC Memo:	"11/16/08 New England Tank Services reported that they removed one 550 gallon tank along with 7.09 tons of petroleum contaminated soil. NFA TG"
Remarks:	"Callers company was removing a 550 gallon tank and found it had holes in it. Unknown how much fuel had been leaking or for how long. Clean up will start within the next few days."

Material:

Site ID:	403827
Operable Unit ID:	1160514
Operable Unit:	01
Material ID:	2151689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BM343 **I-95 EXIT 16** **NY LTANKS** **S102673537**
NNE **OPP. 111 CEDAR ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.436 mi.
2300 ft. **Site 2 of 2 in cluster BM**

Relative:
Lower

Actual:
62 ft.

LTANKS:

Site ID:	244221
Spill Number/Closed Date:	9001240 / 1990-08-01
Spill Date:	1990-05-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1990-08-01
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	MIGOYA CONST. CO. ?
Spiller Address:	3520 DELAVAL AVE.
Spiller City,St,Zip:	BRONX, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	200593
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : N.F.A. 09/27/95: This is additional information about material spilled from the translation of the old spill file: POSS. WASTE OIL."
Remarks:	"DIESEL SPILLED WHILE FILLING HEAVY CONSTRUCTION EQUIPMENT ALSO APPEARSTHAT THEY HAVE CHANGED THEIR CRANKCASE OIL BY DRAINING ONTO GROUND A USED OIL FILTER WAS FOUND THERE ALSO"

Material:

Site ID:	244221
Operable Unit ID:	941067
Operable Unit:	01
Material ID:	439592
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

I-95 EXIT 16 (Continued) **S102673537**

Oxygenate: Not reported

Tank Test:

BN344 **SPILL NUMBER 0009195** **NY LTANKS** **S104877181**
SSE **17 POPLAR PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.439 mi.
2316 ft. **Site 1 of 3 in cluster BN**

Relative:
Lower

Actual:
74 ft.

LTANKS:

Site ID:	63217
Spill Number/Closed Date:	0009195 / 2001-01-08
Spill Date:	2000-11-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-09
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-09
Spill Record Last Update:	2001-02-02
Spiller Name:	DESIGN BUILDERS GROUP
Spiller Company:	Not reported
Spiller Address:	17 POPLAR PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DESIGN BUILDERS GROUP
Spiller Phone:	(914) 948-9785
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	61128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/17/2000 TANK TEST FAILURE LETTER SENT. TANK SCHEDULED FOR RETEST ON 11/20/00. 01/08/2001 ENVIROSTAR PULLED TANK. TANK WAS SOUND, NO RELEASE. EVIROSTAR REPORTS TANK FAILED DUE TO FAULTY OIL LINES. NO CONTAMINATION FOUND. NO FURTHER ACTION REQUIRED."
Remarks:	"uncover repair retest"

Material:

Site ID:	63217
Operable Unit ID:	831505
Operable Unit:	01
Material ID:	543152

SPILL NUMBER 0009195 (Continued) **S104877181**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH345 **RESIDENCE** **NY LTANKS** **S106124419**
SSE **6 POPLAR ROAD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.440 mi.
2321 ft. **Site 4 of 4 in cluster BH**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	82997
Spill Number/Closed Date:	0310014 / 2012-08-13
Spill Date:	2003-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-11-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	RUDY TAYLOR
Spiller Phone:	(914) 833-0287
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76439
DEC Memo:	"7/29/10 Homeowner TTF JO'M 7/25/12: There is no such address as 6 Poplar Road in New Rochelle. This should either be 6 Poplar Road in Larchmont, or 6 Poplar Place in New Rochelle. jod 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"

RESIDENCE (Continued) **S106124419**

Remarks: ""

Material:
Site ID: 82997
Operable Unit ID: 875149
Operable Unit: 01
Material ID: 498967
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Pounds
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 82997
Spill Tank Test: 1528823
Tank Number: 1
Tank Size: 500
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

346
South
1/4-1/2
0.442 mi.
2334 ft.

LIPMAN RESIDENCE **NY LTANKS** **S106971579**
54 LIBERTY AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
48 ft.

LTANKS:
Site ID: 333699
Spill Number/Closed Date: 0409061 / 2005-04-02
Spill Date: 2004-11-16
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2004-11-16
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0

LIPMAN RESIDENCE (Continued) **S106971579**

Date Entered In Computer:	2004-11-16
Spill Record Last Update:	2005-04-02
Spiller Name:	JOSH LITSMAN
Spiller Company:	LISTMAN RESIDENCE
Spiller Address:	54 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELE, NY
Spiller County:	001
Spiller Contact:	JOSH LITSMAN
Spiller Phone:	(914) 813-5024
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268950
DEC Memo:	"02/18/04 ZURICH CLAIM BEING HANDLED BY LEWIS ENVIRONMENTAL. SMALL AMOUNT OF CONTAMINATION UNDER PUBLIC SIDEWALK/ROADWAY CANNOT BE REMOVED SAFELY. DEC SPOKE WITH LEWIS (BOB KRAUSE) ABOUT SAMPLING REQUIREMENTS. REPORT TO FOLLOW. jod 04/02/05 LEWIS ENVIRONMENTAL DISPOSED OF LUST AND 82.08 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SOILTEST CAME BACK OVER THE LIMIT:"

Material:

Tank Test:

BO347 **TELEDYNE HYDRA-POWER** **NY SWF/LF** **1000201735**
ENE **310 MAIN ST** **NY Spills** **NYD001650209**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.442 mi. **FINDS**
2335 ft. **Site 1 of 2 in cluster BO** **NY MANIFEST**
ECHO

Relative:
Lower

Actual:
21 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling
Activity Number:	[60J11]
Active:	No
East Coordinate:	603184
North Coordinate:	4529831
Accuracy Code:	Not reported
Regulatory Status:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

SPILLS:

Facility ID:	1408123
Facility Type:	ER
DER Facility ID:	456652
Site ID:	501675
DEC Region:	3
Spill Date:	2014-11-06
Spill Number/Closed Date:	1408123 / 2014-11-06
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2014-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2014-11-06
Spiller Name:	MIKE TASHENT
Spiller Company:	M TECH MOTORS
Spiller Address:	310 MAIN ST REAR
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE TASHENT
Contact Phone:	(914) 355-2500
DEC Memo:	"11/6/14- Spoke to caller. He was on site and noted where auto shop flushed some waste oil to roadside curb. Cleanup completed by spiller with speedidry. Caller states cleanup is complete. NFA DT"
Remarks:	"loss to sewer and roadway. C/u in progress"

Material:

Site ID:	501675
Operable Unit ID:	1251062
Operable Unit:	01
Material ID:	2252898
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0713299
Facility Type: ER
DER Facility ID: 344570
Site ID: 395027
DEC Region: 3
Spill Date: 2008-03-17
Spill Number/Closed Date: 0713299 / 2010-11-30
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: jkomara
Referred To: WCDOH - PBS
Reported to Dept: 2008-03-17
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-03-17
Spill Record Last Update: 2010-11-30
Spiller Name: MIMI
Spiller Company: CAR DEALER
Spiller Address: 310 MAIN STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: MIMI
Contact Phone: (212) 962-4301
DEC Memo: "11/30/10 No Info 3 years old spills will nbot be following up NFA JO'M "
Remarks: "DURING SOIL BORINGS FOUND CONTAMINTAED SOIL"

Material:
Site ID: 395027
Operable Unit ID: 1151973
Operable Unit: 01
Material ID: 2142744
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Tank Test:

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	TELEDYNE HYDRA-POWER
Facility address:	310 MAIN ST NEW ROCHELLE, NY 108015716
EPA ID:	NYD001650209
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 632-2200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST OPERCITY, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(914) 632-2200
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 08/18/1980
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004335808

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:
EPA ID: NYD001650209
Country: USA
Location Address 1: 310 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: 5716

Mailing Info:
Name: TELEDYNE HYDRA POWER INC
Contact: RICHARD C. SNYDER
Address: 10-12 PINE COURT
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Phone: 914-632-2200

Manifest:

Document ID: PAC6193121
Manifest Status: Completed copy
Trans1 State ID: PAAH0421
Trans2 State ID: Not reported
Generator Ship Date: 01/21/1993
Trans1 Recv Date: 01/21/1993
Trans2 Recv Date: 01/22/1993
TSD Site Recv Date: 01/22/1993
Part A Recv Date: 02/02/1993
Part B Recv Date: 02/04/1993
Generator EPA ID: NYD001650209
Trans1 EPA ID: CTD983883745
Trans2 EPA ID: Not reported
TSDF ID: PAD067098822
Waste Code: F001 - UNKNOWN
Quantity: 00300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

Document ID: NYA1235367
Manifest Status: Completed copy
Trans1 State ID: PLATE#
Trans2 State ID: Not reported
Generator Ship Date: 10/08/1984
Trans1 Recv Date: 10/08/1984
Trans2 Recv Date: / /
TSD Site Recv Date: 10/08/1984
Part A Recv Date: 10/16/1984
Part B Recv Date: 10/19/1984
Generator EPA ID: NYD001650209
Trans1 EPA ID: NYD000824334
Trans2 EPA ID: Not reported
TSDF ID: NYD000824334
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1984

Document ID: NJA1241335
Manifest Status: Completed copy
Trans1 State ID: NJDEPS581
Trans2 State ID: Not reported
Generator Ship Date: 10/24/1991

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Trans1 Recv Date:	10/24/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/24/1991
Part A Recv Date:	/ /
Part B Recv Date:	11/08/1991
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1053512
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	11/28/1990
Trans1 Recv Date:	11/28/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/28/1990
Part A Recv Date:	12/28/1990
Part B Recv Date:	01/07/1991
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0798146
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	05/01/1990
Trans1 Recv Date:	05/01/1990
Trans2 Recv Date:	/ /

TELEDYNE HYDRA-POWER (Continued) **1000201735**

TSD Site Recv Date:	05/02/1990
Part A Recv Date:	06/14/1990
Part B Recv Date:	06/20/1990
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0846650
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS581
Trans2 State ID:	Not reported
Generator Ship Date:	01/25/1990
Trans1 Recv Date:	01/25/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/26/1990
Part A Recv Date:	03/28/1990
Part B Recv Date:	03/30/1990
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0632991
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S58112066
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/1989
Trans1 Recv Date:	10/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/06/1989
Part A Recv Date:	10/12/1989

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Part B Recv Date: 11/14/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1989

Document ID: NJA0632447
Manifest Status: Completed copy
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 06/26/1989
Trans1 Recv Date: 06/26/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 06/27/1989
Part A Recv Date: 07/19/1989
Part B Recv Date: 07/07/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1989

Document ID: NJA0632704
Manifest Status: Completed copy
Trans1 State ID: S58112066
Trans2 State ID: Not reported
Generator Ship Date: 08/22/1989
Trans1 Recv Date: 08/22/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 08/23/1989
Part A Recv Date: 09/07/1989
Part B Recv Date: 09/05/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1989

Document ID: CTC0168881
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: CTE43069
Trans2 State ID: Not reported
Generator Ship Date: 12/26/1990
Trans1 Recv Date: 12/26/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 12/26/1990
Part A Recv Date: 04/03/1991
Part B Recv Date: 01/23/1991
Generator EPA ID: NYD001650209
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

Document ID: NJA0560838
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 02/01/1989
Trans1 Recv Date: 02/01/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 02/06/1989
Part A Recv Date: 03/15/1989
Part B Recv Date: 02/13/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Specific Gravity: 100
Year: 1989

Document ID: NJA0798464
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS581
Trans2 State ID: Not reported
Generator Ship Date: 06/22/1990
Trans1 Recv Date: 06/22/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 06/25/1990
Part A Recv Date: 08/07/1990
Part B Recv Date: 08/06/1990
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

Document ID: NJA0632201
Manifest Status: Completed copy
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 04/25/1989
Trans1 Recv Date: 04/25/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 05/01/1989
Part A Recv Date: 05/10/1989
Part B Recv Date: 05/09/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYA6456618
Manifest Status:	Completed copy
Trans1 State ID:	PLATE#
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/1988
Trans1 Recv Date:	03/30/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/30/1988
Part A Recv Date:	04/05/1988
Part B Recv Date:	04/12/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1988

Document ID:	NYA5744286
Manifest Status:	Completed copy
Trans1 State ID:	PLATE#
Trans2 State ID:	57745GB
Generator Ship Date:	04/14/1987
Trans1 Recv Date:	04/14/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/14/1987
Part A Recv Date:	04/22/1987
Part B Recv Date:	05/05/1987
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1987

Document ID:	NYA6402132
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	57745GB
Generator Ship Date:	12/30/1987
Trans1 Recv Date:	12/30/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1987
Part A Recv Date:	01/15/1988
Part B Recv Date:	01/12/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1987

Document ID:	CTA0042088
Manifest Status:	Completed copy
Trans1 State ID:	CT4163A
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/1987
Trans1 Recv Date:	03/31/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/31/1987
Part A Recv Date:	04/07/1987
Part B Recv Date:	04/14/1987
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	CR02 - AUTHORIZED WASTE OIL
Quantity:	00500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1987

Document ID:	NYA6458922
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Trans1 State ID:	PLATE#
Trans2 State ID:	IC1244
Generator Ship Date:	06/24/1988
Trans1 Recv Date:	06/24/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/24/1988
Part A Recv Date:	07/01/1988
Part B Recv Date:	07/19/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1988

Document ID:	NJA0533423
Manifest Status:	Completed copy
Trans1 State ID:	S58112603
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/1988
Trans1 Recv Date:	11/21/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/22/1988
Part A Recv Date:	11/25/1988
Part B Recv Date:	11/30/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Year: 1988

Document ID: NYA3825472
Manifest Status: Completed copy
Trans1 State ID: PLATE#
Trans2 State ID: 577-45GB
Generator Ship Date: 10/29/1986
Trans1 Recv Date: 10/29/1986
Trans2 Recv Date: / /
TSD Site Recv Date: 10/29/1986
Part A Recv Date: 11/07/1986
Part B Recv Date: 11/10/1986
Generator EPA ID: NYD001650209
Trans1 EPA ID: NYD000824334
Trans2 EPA ID: Not reported
TSDF ID: NYD000824334
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1986

ECHO:
Envid: 1000201735
Registry ID: 110004335808
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004335808

348
NW
1/4-1/2
0.442 mi.
2336 ft.

WALTON RESIDENCE **NY LTANKS** **S108639866**
129 SICKLES AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
67 ft.

LTANKS:
Site ID: 383296
Spill Number/Closed Date: 0703375 / 2007-08-28
Spill Date: 2007-06-22
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2007-06-22
CID: 408
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 2007-06-28
Recommended Penalty: False
UST Involvement: False

WALTON RESIDENCE (Continued) **S108639866**

Remediation Phase:	0
Date Entered In Computer:	2007-06-22
Spill Record Last Update:	2007-08-28
Spiller Name:	MARGRET WALTON
Spiller Company:	PRIVATE HOME
Spiller Address:	129 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	MARGRET WALTON
Spiller Phone:	(914) 235-5241
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	332760
DEC Memo:	"6/29/07: Envirotrac is consultant for insurance company. Report to follow. jod 08/08/07 Northeast Environmental reported that the tank was excavated and removed along with 19.85 tons of impacted soil. NFA TG"
Remarks:	"soil contamination found during tank removal; NOT YET CONTAINED OR CLEANED;"

Material:

Site ID:	383296
Operable Unit ID:	1140659
Operable Unit:	01
Material ID:	2130748
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

349
East
1/4-1/2
0.444 mi.
2344 ft.

Relative:
Lower

Actual:
47 ft.

FIUMFREDO RESIDENCE **NY LTANKS** **S111012239**
12 BAYVIEW AVE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	447470
Spill Number/Closed Date:	1100096 / 2011-09-22
Spill Date:	2011-04-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported

FIUMFREDO RESIDENCE (Continued) **S111012239**

Reported to Dept:	2011-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2011-08-08
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-04
Spill Record Last Update:	2011-09-22
Spiller Name:	ROSE FIUMFREDO
Spiller Company:	ROSE FIUMFREDO
Spiller Address:	12 DAYVIEW AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ROSE FIUMFREDO
Spiller Phone:	(914) 632-0496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402070
DEC Memo:	"4/4/11 - To retest tank. KAB 4/28/11 Morris called in for follow up. Tank failed again. He said tank top was exposed for most of length and one side and some samples taken. Morris said whoever did repairs, sounds like they only put a new vent riser on. Did not check piping, which is heavily crusted. jc 5-6-11 Failed 2nd retest today. Owner giving Kathy a hard time. Morris will retest again next week. Kathy said road name should be Bayview not Dayview, made change. jc 5/13/11 Tank failed for a 3rd time. Plan to pull, according to Tank Tech. dw 8-4-11 Homeowner called dispatch desk. He wants to remove the tank himself and do ALL of the work. He says he would cut open the tank and clean with speedi dri, dispose of tank at scrap yard, etc. I recommended that he hire an environmental consultant to AT LEAST oversee project because the DEC will need a TCR which would include soil samples, manifests, disposal receipts, etc. I told him that this spill will not be closed out until a proper and acceptable Tank Closure Report has been submitted to this office for review. I told him to contact J O'Dee in White Plains for further info. This guy seems bent on doing everything himself even though it was recommended that he hire a consultant to oversee the project. jm 8/4/11: Recieved call from Sandy Perratta 914-557-0142. He is the same individual who called the dispatch desk earlier today. He is not the property owner but a friend of the owner. States he is in the construction business and he can remove the tank himself. He states he has the OSHA 30-hour training and also states he knows that he doesn't need confined space entry training if the tank is less than 4 feet below ground . I again stated he should have a professional contractor do the work for safety reasons. jod 8/8/11: Received voice-mail message from Mr Perratta stating he had removed the tank and it was on the lawn awaiting a DEC drive-by inspection. I met New Rochelle Fire Captain Henry Senno on site. The tank was cut and cleaned and is on plastic. The excavation is open and is not fenced or secured. There is no evidence of any holes in the tank, and no evidence of any leak or contamination. Captain Senno states he will follow up with the owner, as no permits were filed for the removal as required in New Rochelle. DEC Spills requires no further action at this time. jod 9/8/11: I left this spill open after discussing the situation with Capt Senno on either August 9th or 10th. There was still a 55-gallon drum of

FIUMFREDO RESIDENCE (Continued) **S111012239**

heating oil and heating oil sludge that was removed from the tank remaining on the site. On either Aug 11th or 12th I spoke with Mr Perrotta and stated the spill would be left open until he submitted a disposal receipt to DEC for proper disposal of that waste drum. To date, Mr Perrotta has submitted a disposal recipt for the tank (entered in eDocs) but has not submitted a disposal receipt for the drum. jod 9/22/11: Letter from Linda Enes forwarded to DEC. She states she is in posesseion of the 55-gallon drum, and is using it to fuel a space heater. I called her this morning and she states her husband transported the drum in his pick-up truck from New Rochelle to their home in Dover Plains NY. Letter has been entered into eDocs. DEC requires no further action. jod"

Remarks: "repair/retest pending"

Material:

Site ID:	447470
Operable Unit ID:	1197626
Operable Unit:	01
Material ID:	2193927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

350 WSW 1/4-1/2 0.447 mi. 2360 ft. **CONTAMINATRED SOIL** **NY LTANKS** **S104276929**
23 FIRST ST **N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 57 ft.

LTANKS:

Site ID:	102476
Spill Number/Closed Date:	9702187 / 1999-06-10
Spill Date:	1997-05-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-20
CID:	369
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False

CONTAMINATRED SOIL (Continued) **S104276929**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-20
Spill Record Last Update:	1999-06-11
Spiller Name:	Not reported
Spiller Company:	MR WILLIAMS
Spiller Address:	23 FIRST ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BRIAN SCHUG
Spiller Phone:	(914) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90745
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING SITE EVALUATION-CALLER WILL REMOVE SOIL-CLEANUP IN PROGRESS"

Material:

Site ID:	102476
Operable Unit ID:	1048062
Operable Unit:	01
Material ID:	335128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

351 **RESIDENCE** **NY LTANKS** **S102660166**
SW **38 BEECHWOOD AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.448 mi.
2367 ft.

Relative:
Lower

Actual:
37 ft.

LTANKS:

Site ID:	105369
Spill Number/Closed Date:	9705244 / 1997-11-10
Spill Date:	1997-07-31
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-31

RESIDENCE (Continued) **S102660166**

CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-31
Spill Record Last Update:	1998-02-05
Spiller Name:	MARVIN KAPUS
Spiller Company:	Not reported
Spiller Address:	38 BEECHWOOD AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	MARVIN KAPUS
Spiller Phone:	(914) 738-1351
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92963
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/31/97 CONTAMINATED SOIL BEING REMOVED & STOCKPILED; 08/01/97 TANK FOUND DURING DEMOLITION OF HOUSE; TANK AND CONTAMINATION REMOVED; "
Remarks:	"demolition of building - ust 550 gal tank - tank had holes in it contaminated soil found "

Material:

Site ID:	105369
Operable Unit ID:	1048510
Operable Unit:	01
Material ID:	334464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BO352 **DEFENDER MARINE SUPPLY** **NY LTANKS** **S103479285**
ENE **309 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.448 mi.
2367 ft. **Site 2 of 2 in cluster BO**

Relative:
Lower

Actual:
25 ft.

LTANKS:

Site ID:	93459
Spill Number/Closed Date:	9806235 / 2002-09-19
Spill Date:	1998-08-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

DEFENDER MARINE SUPPLY (Continued) **S103479285**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-08-19
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-19
Spill Record Last Update:	2002-09-19
Spiller Name:	WILLIAM GOING
Spiller Company:	DEFENDER MARINE SUPPLY
Spiller Address:	309 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	WILLIAM GOING
Spiller Phone:	(914) 744-3705
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83786
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/19/98 WCHD NOTIFIED. 09/14/02 - 8 TO 10 YARDS OF SOIL STOCKPILED. CLOSURE REPORT TO FOLLOW ONCE SAMPLE RESULTS RECEIVED. 09/19/02 CLOSURE REPORT RECEIVED FROM WILLIAM GOING. DISPOSAL OF TANK AND 10.45 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"during a tank removal caller found contamined soil"

Material:

Site ID:	93459
Operable Unit ID:	1067422
Operable Unit:	01
Material ID:	317407
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BN353 **FUNICELOLO HOME** **NY LTANKS** **S107489124**
SSE **24 POPLAR PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.450 mi.
2375 ft. **Site 2 of 3 in cluster BN**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	355533
Spill Number/Closed Date:	0509719 / 2006-11-19
Spill Date:	2005-11-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-11-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-14
Spill Record Last Update:	2006-11-19
Spiller Name:	FUNICEOLO HOME
Spiller Company:	FUNICELOLO HOME
Spiller Address:	24 POPULAR PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FUNICEOLO HOME
Spiller Phone:	(914) 636-5043
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305561
DEC Memo:	"PLAN WAS TO ABANDON BUT FOUND HOLES SO NOWTHEY WILL REMOVE NO KNOWN EXPERTS AT THIS TIME November 19, 2006: ONE HOLE FOUND ON TOP OF TANK. TANK CANNOT BE REMOVED DUE TO SAFETY AND STRUCTURAL CONSIDERATIONS. MUNICIPAL WATER AND SEWER. ROYAL ENVIRONMENTAL TOOK A GROUND WATER SAMPLE BENATH TANK, ALL ANALYTES NON-DETECT. TANK ABANDONED IN PLACE WITH SLURRY. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES FOUND IN A 1000 GALLON TANK;"

Material:

Site ID:	355533
Operable Unit ID:	1112888
Operable Unit:	01
Material ID:	2102930
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

FUNICELOLO HOME (Continued) **S107489124**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BN354 **LABELLA RESIDENCE** **NY LTANKS** **S107789449**
SSE **219 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.454 mi.
2397 ft. **Site 3 of 3 in cluster BN**

Relative:
Lower

Actual:
72 ft.

LTANKS:

Site ID:	364328
Spill Number/Closed Date:	0601959 / 2009-09-01
Spill Date:	2006-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2009-09-01
Spiller Name:	LARRY LABELLA
Spiller Company:	LABELLA RESIDENCE
Spiller Address:	219 CENTRAL AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LARRY LABELLA
Spiller Phone:	(914) 654-0719
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	314554
DEC Memo:	"05/24/06: Soil samples clean. US Tank Tech will be repairing and retesting. 9/1/09: Tank passed a retest in isolation on 6-13-06. At that time, new fuel lines had been run from the tank to the boiler room but were not hooked up at the time of the test. A full system test was performed 7-24-09 with the lines connected. The tank system passed this retest. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"UNCOVER REPAIR AND RETEST."

LABELLA RESIDENCE (Continued) **S107789449**

Material:

Site ID:	364328
Operable Unit ID:	1122357
Operable Unit:	01
Material ID:	2111830
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	364328
Spill Tank Test:	1550008
Tank Number:	1
Tank Size:	1000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

355 **SPILL NUMBER 0210080** **NY LTANKS** **S105997807**
West **196 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2423 ft.

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	155360
Spill Number/Closed Date:	0210080 / 2003-03-03
Spill Date:	2003-01-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-06
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-06
Spill Record Last Update:	2003-03-04

SPILL NUMBER 0210080 (Continued) **S105997807**

Spiller Name:	Not reported
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131601
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Dec. 2002 - One 1200 gallon tank was removed from the property. 300 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environmetnal Assessment. NFA. TG"
Remarks:	"1200 GAL UNDERGROUND STORAGE TANK - 4 OTHER SPILL #'S ON THIS SAME SITE - DELORES FROM DEC SAYS THEY NEED ANOTHER NEW SPILL #"

Material:

Site ID:	155360
Operable Unit ID:	861323
Operable Unit:	01
Material ID:	513483
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BP356 **RESIDENCE** **NY LTANKS** **S105230245**
South **98 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2426 ft. **Site 1 of 4 in cluster BP**

Relative:
Lower

Actual:
46 ft.

LTANKS:

Site ID:	204562
Spill Number/Closed Date:	0107187 / 2002-01-11
Spill Date:	2001-10-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-10-11
CID:	252

RESIDENCE (Continued) **S105230245**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-11
Spill Record Last Update:	2002-03-22
Spiller Name:	REALTOR
Spiller Company:	MR GAMIANO
Spiller Address:	98 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CAROL MASCOLINO-REALTOR
Spiller Phone:	(914) 576-1112
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170048
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/11/2002 ADVANCED PULLED TANK AND 99.6 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"PETROLEUM ODOR AND STAINING IN THE SOIL-RECOMMEND TANK REMOVAL"

Material:

Site ID:	204562
Operable Unit ID:	844253
Operable Unit:	01
Material ID:	532018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	204562
Spill Tank Test:	1526660
Tank Number:	Not reported
Tank Size:	1000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

357
WNW
1/4-1/2
0.463 mi.
2443 ft.

MANONE PLACE
15 COLONIAL PLACE
NEW ROCHELLE, NY

NY LTANKS **S107523607**
N/A

Relative:
Higher

Actual:
84 ft.

LTANKS:

Site ID:	359413
Spill Number/Closed Date:	0513004 / 2006-05-08
Spill Date:	2006-02-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-09
Spill Record Last Update:	2006-05-08
Spiller Name:	FLORENCE MANONE
Spiller Company:	MANONE PLACE
Spiller Address:	15 COLONIAL PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FLORENCE MANONE
Spiller Phone:	(914) 633-7791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309466
DEC Memo:	"John O'Dee is lead and will/has contacted. May 8, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND FIVE DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 GALLON TANK, HOLES AND CONTAMINATION, WOULD LIKE A CALL BACK PERTAINING TO THIS PROPERTY"

Material:

Site ID:	359413
Operable Unit ID:	1116622
Operable Unit:	01
Material ID:	2107064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

MANONE PLACE (Continued) **S107523607**

Oxygenate: Not reported

Tank Test:

358
SSE
1/4-1/2
0.466 mi.
2463 ft.

TRINITY ARMS APARTMENTS **NY LTANKS** **S109416298**
25 TRINITY PLACE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
70 ft.

LTANKS:

Site ID:	409448
Spill Number/Closed Date:	0811859 / 2009-04-22
Spill Date:	2009-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-30
Spill Record Last Update:	2009-04-22
Spiller Name:	WILLY SILSDORF
Spiller Company:	TRINITY ARMS LTD
Spiller Address:	25 TRINITY PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	LARRY BOYD
Spiller Phone:	(914) 682-5676
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Spoke to W. Silsdorf. Think it may be leak in piping or fitting. Will probably Uncover, repair and retest. dvw 04/21/09 Wayne Schnieder reported ttf 1/3/09. passing retest after line replacement. No contamination. NFA TG "
Remarks:	"Caller states he performed a EZ-3 test and had a failure. Caller does not believe a spill or resources are affected."

Material:

Site ID:	409448
Operable Unit ID:	1165955
Operable Unit:	01
Material ID:	2157389
Material Code:	0001A

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	283512
Spill Number/Closed Date:	8905211 / 1992-07-30
Spill Date:	1989-08-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-07-30
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ANN JASLOCKI
Spiller Address:	REAL ESTATE
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"4K PETRO TITE, -.234 GPH"

Material:

Site ID:	283512
Operable Unit ID:	932936
Operable Unit:	01
Material ID:	445651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	283512
Spill Tank Test:	1535913
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

BQ359 **SPILL NUMBER 9814027** **NY LTANKS** **S104619985**
NW **48 REMINGTON PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.471 mi.
2488 ft. **Site 1 of 2 in cluster BQ**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	80830
Spill Number/Closed Date:	9814027 / 1999-02-19
Spill Date:	1999-02-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-19
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-19
Spill Record Last Update:	1999-03-01
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AV
Spiller City,St,Zip:	BRONX, NY 10454-
Spiller County:	001
Spiller Contact:	MAMMY JONES
Spiller Phone:	(914) 636-5128
Spiller Extention:	Not reported

SPILL NUMBER 9814027 (Continued) **S104619985**

DEC Region: 3
DER Facility ID: 74863
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks: "STORAGE TANK OVERFILL - TANK IS OUTSIDE UNDERGROUND - CONTAMINATED SOIL WAS REMOVED & REPLACED WITH FRESH SOIL"

Material:
Site ID: 80830
Operable Unit ID: 1071478
Operable Unit: 01
Material ID: 310733
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: Gallons
Recovered: 3.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

360
ENE
1/4-1/2
0.472 mi.
2490 ft.

RITACCO HOME **NY LTANKS** **S107789088**
24 JACKSON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
24 ft.

LTANKS:
Site ID: 362141
Spill Number/Closed Date: 0600187 / 2006-07-28
Spill Date: 2006-04-06
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-04-06
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-04-06
Spill Record Last Update: 2006-07-28
Spiller Name: RITACCO HOME
Spiller Company: RITACCO HOME
Spiller Address: 24 JACKSON STREET

RITACCO HOME (Continued) **S107789088**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RITACCO HOME
Spiller Phone:	(914) 576-1430
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	312378
DEC Memo:	"04/10/06: Northeast to continue remediation. No GW involved as of now. July 28, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.00 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES IN A 550 GALLON AND CONTAMINATED SOIL;"

Material:

Site ID:	362141
Operable Unit ID:	1120244
Operable Unit:	01
Material ID:	2109739
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

361
SSW
1/4-1/2
0.474 mi.
2502 ft.

COMMERICAL BUILIDING **NY LTANKS** **S106472134**
719 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
59 ft.

LTANKS:

Site ID:	301693
Spill Number/Closed Date:	0404182 / 2004-10-28
Spill Date:	2004-07-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-07-19
CID:	405
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

COMMERICAL BUILIDING (Continued) **S106472134**

Remediation Phase:	0
Date Entered In Computer:	2004-07-19
Spill Record Last Update:	2004-10-28
Spiller Name:	JOHN DEURANTE
Spiller Company:	COMMERICAL BUILIDING
Spiller Address:	719 MAIN ST.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOHN DEURANTE
Spiller Phone:	(914) 632-4222
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	243806
DEC Memo:	"10/28/04 TANK PASSED RETEST AFTER PIPING WAS REPLACED. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"RECOMMEND, UNCOVER, REPAIR, RETEST"

Material:

Tank Test:

Site ID:	301693
Spill Tank Test:	1529456
Tank Number:	1
Tank Size:	1080
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

362
East
1/4-1/2
0.474 mi.
2505 ft.

CONSOLIDATED EDISON-ECHO AVE. SITE
ECHO AVE
NEW ROCHELLE, NY 10801

SEMS-ARCHIVE **1000111631**
RCRA-CESQG **NYD981141252**
NY Spills
NY MANIFEST

Relative:
Lower

Actual:
17 ft.

SEMS-ARCHIVE:

Site ID:	202659
EPA ID:	NYD981141252
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0202659
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Alias Name(s):

Alias Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
Alias Address:	Not reported WESTCHESTER, NY

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

CERCLIS-NFRAP Assessment History:

Action:	DISCOVERY
Date Started:	/ /
Date Completed:	04/19/88
Priority Level:	Not reported

Action:	ARCHIVE SITE
Date Started:	/ /
Date Completed:	09/30/92
Priority Level:	Not reported

Action:	PRELIMINARY ASSESSMENT
Date Started:	/ /
Date Completed:	09/30/92
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	CON EDISON - ECHO AVENUE SUBSTATION
Facility address:	ECHO AVENUE NEW ROCHELLE, NY 10801
EPA ID:	NYD981141252
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1951

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1951
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 01/01/2001
Site name: ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Small Quantity Generator

Date form received by agency: 03/29/1996
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 11/19/1985
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Large Quantity Generator

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

SPILLS:
Facility ID: 9711031
Facility Type: ER
DER Facility ID: 101608
Site ID: 116789
DEC Region: 3
Spill Date: 1998-01-01
Spill Number/Closed Date: 9711031 / 1998-01-06
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-01-01
CID: 204
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-01
Spill Record Last Update: 1998-01-29
Spiller Name: STEVE ROMERO
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: STEVE ROMERO
Contact Phone: (212) 580-6763
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/01/98 OIL/WATER SEPARATOR OVERFLOWED; SUSPECTS OUTLET PIPE BECAME CLOGGED OR FROZEN CAUSING OVERFLOW; 01/02/98 3,300 GAL CONTAINED IN DIKED AREA; 100 GAL OVERFLOWED DIKE ONTO SOIL AND INTO DRAIN; 01/06/98 SPILL CLEANED UP BY CON ED; H2O HAS LESS THAN 1 PPM PCB "
Remarks: "OIL / WATER SEPARATOR MALFUNCTIONED 3300 IN CONTAINMENT AREA"

Material:
Site ID: 116789
Operable Unit ID: 1053908
Operable Unit: 01
Material ID: 329298
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 3400.00
Units: Gallons

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

NY MANIFEST:
EPA ID: NYD981141252
Country: USA
Location Address 1: ECHO AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: NYB9791883
Manifest Status: Not reported
Trans1 State ID: AE50394PA
Trans2 State ID: Not reported
Generator Ship Date: 01/20/2003
Trans1 Recv Date: 01/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B004 - PCB ARTICLES WITH 50 PPM BUT < 500 PPM
Quantity: 08210
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2003

Document ID: NYA5717304
Manifest Status: Completed copy
Trans1 State ID: JA-113
Trans2 State ID: 558-TSM
Generator Ship Date: 01/28/1988

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans1 Recv Date:	01/28/1988
Trans2 Recv Date:	02/04/1988
TSD Site Recv Date:	02/05/1988
Part A Recv Date:	02/08/1988
Part B Recv Date:	02/11/1988
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	NJD054126164
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	21460
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	125
Year:	1988

Document ID:	NYG1699497
Manifest Status:	Not reported
Trans1 State ID:	XF31635PA
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2000
Trans1 Recv Date:	01/18/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/20/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	10100
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB9245052
Manifest Status:	Not reported
Trans1 State ID:	AD06661PA
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2000
Trans1 Recv Date:	01/27/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00499
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851671
Manifest Status:	Not reported
Trans1 State ID:	XH47240PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2000
Trans1 Recv Date:	03/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	45320
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851689
Manifest Status:	Not reported
Trans1 State ID:	TZ47345PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2000
Trans1 Recv Date:	03/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	50440
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Document ID: NYB8851698
Manifest Status: Not reported
Trans1 State ID: XB51788PA
Trans2 State ID: Not reported
Generator Ship Date: 03/14/2000
Trans1 Recv Date: 03/14/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/15/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 44140
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851707
Manifest Status: Not reported
Trans1 State ID: XG32072PA
Trans2 State ID: Not reported
Generator Ship Date: 03/14/2000
Trans1 Recv Date: 03/14/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/15/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 44160
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851716
Manifest Status: Not reported
Trans1 State ID: TV30802PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46640
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851725
Manifest Status: Not reported
Trans1 State ID: TY15443PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 57300
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851734
Manifest Status: Not reported
Trans1 State ID: XE53087PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50640
Units: P - Pounds
Number of Containers: 001

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851752
Manifest Status: Not reported
Trans1 State ID: XB51788PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49720
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851761
Manifest Status: Not reported
Trans1 State ID: XH447244P
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851779
Manifest Status: Not reported
Trans1 State ID: XA49178PA

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	47240
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851788
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	48460
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851797
Manifest Status:	Not reported
Trans1 State ID:	XG70657PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 59640
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851806
Manifest Status: Not reported
Trans1 State ID: TS31639PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 52920
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851815
Manifest Status: Not reported
Trans1 State ID: XC58821PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD196714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 51220
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Year: 2000

Document ID: NYB8851824
Manifest Status: Not reported
Trans1 State ID: XD54730PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 62880
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851833
Manifest Status: Not reported
Trans1 State ID: XG70656PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49100
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

BP363
South
1/4-1/2
0.482 mi.
2547 ft.

SPILL NUMBER 9803423
106 LIBERTY AV
NEW ROCHELLE, NY

Site 2 of 4 in cluster BP

NY LTANKS **S104619561**
N/A

Relative:
Lower

Actual:
45 ft.

LTANKS:

Site ID:	140786
Spill Number/Closed Date:	9803423 / 1998-08-18
Spill Date:	1998-06-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-17
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-17
Spill Record Last Update:	1998-10-02
Spiller Name:	MARGURITE FINCH
Spiller Company:	Not reported
Spiller Address:	106 LIBERTY AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARGURITE FINCH
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	120231
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PULLED THE TANK TODAY & FOUND IT TO BE LEAKING - CONTAMINATED SOIL IS BEING DUG UP & STOCK PILED"

Material:

Site ID:	140786
Operable Unit ID:	1064251
Operable Unit:	01
Material ID:	566529
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILL NUMBER 9803423 (Continued) **S104619561**

Tank Test:

364
NE
1/4-1/2
0.484 mi.
2558 ft.

TTF AT RESIDENCE
68 JACKSON ST
NEW ROCHELLE, NY

NY LTANKS **S108957764**
N/A

Relative:
Lower

Actual:
25 ft.

LTANKS:

Site ID:	388761
Spill Number/Closed Date:	0707955 / 2008-03-26
Spill Date:	2007-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-10-20
CID:	79
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-22
Spill Record Last Update:	2008-03-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	MR JOHNSON
Spiller Phone:	(914) 235-1496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	338305
DEC Memo:	"March 26, 2008: ENVIROSTAR REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"TEST FAILED DUE TO BUBBLING. HORNER EASY 3 TEST,"

Material:

Site ID:	388761
Operable Unit ID:	1145917
Operable Unit:	01
Material ID:	2136260
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

TTF AT RESIDENCE (Continued) **S108957764**

Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BP365 **COLLEGE OF NEW ROCHELLE** **NY LTANKS** **S104619776**
South **103 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.486 mi.
2565 ft. **Site 3 of 4 in cluster BP**

Relative:
Lower

Actual:
44 ft.

LTANKS:

Site ID:	118985
Spill Number/Closed Date:	9809357 / 2005-04-17
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-10-26
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	2005-04-17
Spiller Name:	UNKNOWN
Spiller Company:	COLLEGE OF NEW ROCHELLE
Spiller Address:	103 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	COLLEGE OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103367
DEC Memo:	"02/23/99 Letter sent to tank owner requesting information 04/17/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF RESULTS. NO CALL BACK REQUESTED AT TIME OF CALL."

Material:

Site ID:	118985

COLLEGE OF NEW ROCHELLE (Continued) **S104619776**

Operable Unit ID:	1066630
Operable Unit:	01
Material ID:	316813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	118985
Spill Tank Test:	1546454
Tank Number:	1
Tank Size:	1080
Test Method:	03
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

366
SE
1/4-1/2
0.486 mi.
2567 ft.

Relative:
Lower

Actual:
40 ft.

CIUSSETELLI RESIDENCE **NY LTANKS** **S105996325**
4 FAIRVIEW PLACE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	161898
Spill Number/Closed Date:	0204230 / 2010-07-13
Spill Date:	2002-07-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-07-23
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2010-07-13
Spiller Name:	Not reported

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	RON CIUSSETELLI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136674
DEC Memo:	"7/13/10: Report of a residential tank test failure. No indication of contamination noted on initial report. Report indicates all exterior piping loose, multiple vents and fills. Probable air leak. No further information received. jod"
Remarks:	"all exterior piping loose...multiple vents and fille..and questions contact caller."

Material:

Site ID:	161898
Operable Unit ID:	857023
Operable Unit:	01
Material ID:	518487
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	161898
Spill Tank Test:	1527307
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

367 **NELSTAD MATERIAL CORP** **NY LTANKS** **S102154943**
ENE **40 HUNTINGTON PL** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY SPDES**
0.487 mi.
2573 ft.

Relative:
Lower

Actual:
13 ft.

LTANKS:

Site ID:	200280
Spill Number/Closed Date:	0208898 / 2004-05-03
Spill Date:	2002-11-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response.

NELSTAD MATERIAL CORP (Continued) **S102154943**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-27
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-11-27
Spill Record Last Update:	2004-05-19
Spiller Name:	JOHN CAPOSELLA
Spiller Company:	NELSTAD CONCRETE
Spiller Address:	40 HUNTINGTON PL
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	JOHN CAPOSELLA
Spiller Phone:	(914) 636-8090
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	166657
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MANCINI 5/11/04: Letter to Nelstadt Materials Corp from Joe Mancini, WCDOH dated 3May2004. Closure report by Ira D Conklin has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"1000 UST LEAKING - CALLER DOING ABANDONMENT ON TANK AND DISCOVERED WATER IN IT"

Material:

Site ID:	200280
Operable Unit ID:	862078
Operable Unit:	01
Material ID:	515890
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9400648
Facility Type:	ER
DER Facility ID:	126495
Site ID:	148664

NELSTAD MATERIAL CORP (Continued) **S102154943**

DEC Region:	3
Spill Date:	1994-04-14
Spill Number/Closed Date:	9400648 / 1994-04-20
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-14
CID:	Not reported
Water Affected:	L.I. SOUND
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-20
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE LEAKING OIL INTO SOUND COAST GUARD WILL RESPOND PO NOWACK STORM DRAIN OUTFALL SHEEN PRESENTED BUT NOT RECOVERABLE RECURRING PROBLEM"

Material:

Site ID:	148664
Operable Unit ID:	994366
Operable Unit:	01
Material ID:	558757
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPDES:

Permit Number:	NYR00D345
State-Region:	03

NELSTAD MATERIAL CORP (Continued) **S102154943**

Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	3273
State Water Body Name:	ECHO BAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.912861 / -73.772611
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP
Non-Gov Permit Street Address:	NELSTAD MATERIAL CORP
Non-Gov Permit Supplemental Location:	40 HUNTINGTON PL
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Permit Street Address:	40 HUNTINGTON PL
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported

BP368 **BLANCO RESIDENCE** **NY LTANKS** **S103238839**
South **30 LINDEN PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.488 mi.
2575 ft. **Site 4 of 4 in cluster BP**

Relative:
Lower

Actual:
50 ft.

LTANKS:

Site ID:	227988
Spill Number/Closed Date:	9802704 / 1998-07-30
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-01
Spill Record Last Update:	1998-08-04
Spiller Name:	FRANK BLANCO
Spiller Company:	BLANCO RESIDENCE
Spiller Address:	30 LINDEN PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FRANK BLANCO
Spiller Phone:	(914) 633-7605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 LETTER REC'D FROM NES,INC. INDICATING TANK AND APPROX. 21.86 TONS CONTAMINATED SOIL WAS REMOVED. NFA."
Remarks:	"CALLERS AGENCY CALLED FOR NO HOT WATER - SERVICE MAN FOUND TANK EMPTY - POSSIBLY A TANK LEAK OR LINE FAILURE"

BLANCO RESIDENCE (Continued) **S103238839**

Material:
Site ID: 227988
Operable Unit ID: 1063369
Operable Unit: 01
Material ID: 321024
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

---

369 SW 1/4-1/2 0.489 mi. 2583 ft. **NEW ROCHELLE LEAF TS** **NY SWF/LF** **S103592520**
85 BEECHWOOD AVE **N/A**
NEW ROCHELLE, NY 10801

Relative: Lower

Actual: 57 ft.

SWF/LF:
Flag: ACTIVE
Region Code: 3
Phone Number: 9146542129
Owner Name: Westchester County
Owner Type: Municipal
Owner Address: 270 North Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Email: Not reported
Owner Phone: 9146373031
Contact Name: Alexander Tergis
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: atergis@newrochelleny.com
Contact Phone: 9146542136
Activity Desc: Transfer station - registration
Activity Number: [60R19]
Active: Yes
East Coordinate: 603779
North Coordinate: 4529858
Accuracy Code: Not reported
Regulatory Status: Registration
Waste Type: Yard Waste;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #: 60R19
Authorization Date: Not reported
Expiration Date: Not reported

370
NNE
1/4-1/2
0.490 mi.
2587 ft.

7-UP BOTTLING CO
PALMER AVE & CEDAR ST
NEW ROCHELLE, NY

NY LTANKS **S100560336**
N/A

Relative:
Lower

Actual:
28 ft.

LTANKS:

Site ID:	60684
Spill Number/Closed Date:	9302874 / 1999-08-02
Spill Date:	1993-06-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-12-08
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1993-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-08
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59196
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/08/94: CONTRACTOR WAS FENLEY AND NICOL. TANK PULLED AND CONTA. SOIL REMOVEDFROM PIT. TANK REMOVAL REPORT WAS REQUESTED BUT NOT RECIEVED. 08/02/99: FINAL CLOSURE REPORT RECEIVED FROM GIBSON, DUNN & CRUTCHER ON 7/27/99; SENT TO TARRYTOWN OFFICE. "
Remarks:	"TANK PULL DEC (TODD) IS AWARE OF AND HANDLING SPILL"

Material:

Site ID:	60684
Operable Unit ID:	981198
Operable Unit:	01
Material ID:	399984
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

7-UP BOTTLING CO (Continued) **S100560336**

Oxygenate: Not reported

Tank Test:

371
SE
1/4-1/2
0.490 mi.
2588 ft.

NORTH EVARTS **NY LTANKS** **S104620864**
44 NORTH EVARTS AVE **N/A**
ELSMFORD, NY

Relative:
Lower

Actual:
40 ft.

LTANKS:

Site ID:	74554
Spill Number/Closed Date:	9913333 / 2005-02-26
Spill Date:	2000-02-24
Spill Cause:	Tank Failure
Spill Source:	Vessel
Spill Class:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6000
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2005-02-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	44 NORTH EVARTS AVE
Spiller City,St,Zip:	ELSMFORD, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	69944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 2/26/05 surface spill from bilge tank on boat--j omara handled-close "
Remarks:	"bilge tank on boat ruptured - spill to soil and some contained in a catch basin - ny boat reg ny4947ju - fire dept and haz mat on scene- " Not reported

Material:

Site ID:	74554
Operable Unit ID:	1087874
Operable Unit:	01
Material ID:	295189
Material Code:	0009
Material Name:	gasoline

NORTH EVARTS (Continued) **S104620864**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BQ372 **HERNANDEZ - TTF** **NY LTANKS** **S117853761**
NW **70 REMINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.490 mi.
2588 ft. **Site 2 of 2 in cluster BQ**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	505764
Spill Number/Closed Date:	1411959 / 2015-06-16
Spill Date:	2015-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-23
Spill Record Last Update:	2015-06-17
Spiller Name:	DAISE Hernandez
Spiller Company:	Hernandez
Spiller Address:	70 REMINGTON PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	DAISE FENANDEZ
Spiller Phone:	(914) 563-3381
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	460572
DEC Memo:	"3-23-15: V.Mc call to Ms.Fenandez: Parents house, will speak w/Mom and try to find out age of house/UST and callbk w/update. Noted: gen. life time of UST 20 to 25 years, re-test Vs. remove. 6/16/15: UST removed by Envirostar. No evidence of leak or contamination was found. Tank Closure report entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
	Not reported

HERNANDEZ - TTF (Continued) **S117853761**

Remarks: "caller reporting a failed tank test, tank is a 550 gallon tank. repair and retest tank"

Material:

Site ID:	505764
Operable Unit ID:	1255071
Operable Unit:	01
Material ID:	2257761
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Count: 7 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NEW ROCHELLE	1007740476	NEW ROCHELLE CREEK CABLES	ADJACENT TO GLEN ISLAND BRIDGE	10804	FINDS, ECHO
NEW ROCHELLE	S108467789	SIDEWALK / IN FRONT OF NE	HARRISON STREET		NY LTANKS
NEW ROCHELLE	S100153602	N.SHORE LONG ISLAND SOUND	NEW ROCHELLE TO DANBURY		NY LTANKS
NEW ROCHELLE	S110248231	VALU CLEAN CLEANERS	1335 A NORTH AVE.	10804	NY DRYCLEANERS
NEW ROCHELLE	S105684699	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY VCP
NEW ROCHELLE	S113916612	MEARL CORP.	PALMER AVE	10801	NY SHWS
NEW ROCHELLE	S117975694	MM 5.4 LEFT LANE	I-95 SOUTHBOUND		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/13/2015
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 135

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 13

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/16/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/29/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/29/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 03/30/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 51

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 08/01/2015
Date Data Arrived at EDR: 11/19/2015
Date Made Active in Reports: 12/10/2015
Number of Days to Update: 21

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/04/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 52

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/08/2015
Date Data Arrived at EDR: 01/08/2015
Date Made Active in Reports: 02/09/2015
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/13/2015
Date Data Arrived at EDR: 10/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 118

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/28/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 08/20/2015
Date Data Arrived at EDR: 10/30/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 111

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/24/2015
Date Data Arrived at EDR: 12/01/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 34

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/27/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/11/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/24/2015
Date Data Arrived at EDR: 12/01/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 34

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 12/14/2014
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 28

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/13/2015
Date Data Arrived at EDR: 10/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 118

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Date Data Arrived at EDR: 11/25/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 65

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 08/20/2015
Date Data Arrived at EDR: 10/30/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 111

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 52

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 02/04/2016
Date Data Arrived at EDR: 03/24/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 04/01/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/22/2015
Date Data Arrived at EDR: 12/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 57
Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36
Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15
Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 01/15/2016
Next Scheduled EDR Contact: 05/02/2016
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/21/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/17/2015
Date Data Arrived at EDR: 12/04/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/01/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Annually

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/17/2015
Date Data Arrived at EDR: 12/04/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/01/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 02/08/2016
Date Data Arrived at EDR: 02/10/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 41

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/26/2015
Date Made Active in Reports: 09/02/2015
Number of Days to Update: 68

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 03/11/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/01/2015
Date Data Arrived at EDR: 09/03/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/18/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 133

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/08/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2015
Date Data Arrived at EDR: 08/26/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 10/15/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 33

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/12/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/18/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 28

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/11/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/07/2015
Date Data Arrived at EDR: 07/09/2015
Date Made Active in Reports: 09/16/2015
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 46

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/24/2015
Date Made Active in Reports: 09/30/2015
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/26/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 11/23/2015
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 86

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Date Data Arrived at EDR: 11/26/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/07/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/09/2016
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 44

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 03/02/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/04/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/04/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 07/20/2015
Date Data Arrived at EDR: 09/09/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 55

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 03/08/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 10/25/2015
Date Data Arrived at EDR: 01/29/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 67

Source: Department of Defense
Telephone: 571-373-0407
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 03/01/2016
Date Data Arrived at EDR: 03/03/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/25/2016
Date Data Arrived at EDR: 02/16/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 10/16/2015
Date Data Arrived at EDR: 01/12/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/14/2016
Next Scheduled EDR Contact: 06/27/2016
Data Release Frequency: Varies

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/24/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 01/11/2016
Date Data Arrived at EDR: 01/12/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/01/2015
Date Data Arrived at EDR: 12/29/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/16/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 02/01/2016
Date Data Arrived at EDR: 02/03/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Annually

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 02/04/2016
Date Data Arrived at EDR: 02/05/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 46

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/09/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/20/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/22/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 86

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/20/2015
Date Data Arrived at EDR: 09/23/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 103

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/23/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2016
Date Data Arrived at EDR: 02/25/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 26

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2016
Date Data Arrived at EDR: 02/25/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 26

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

Registered Tank Database in Nassau County

A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 12/16/2015
Date Data Arrived at EDR: 12/21/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 52
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/07/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 12/16/2015
Date Data Arrived at EDR: 12/21/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 52
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/07/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/19/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/19/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/13/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/17/2015
Date Made Active in Reports: 08/12/2015
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/12/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/24/2015
Date Made Active in Reports: 08/18/2015
Number of Days to Update: 25

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 03/16/2016
Date Data Arrived at EDR: 03/29/2016
Date Made Active in Reports: 04/19/2016
Number of Days to Update: 21

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 03/19/2015
Date Made Active in Reports: 04/07/2015
Number of Days to Update: 19

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/14/2016
Next Scheduled EDR Contact: 06/27/2016
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

LA ROCHELLE
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

TARGET PROPERTY COORDINATES

Latitude (North):	40.910808 - 40° 54' 38.91''
Longitude (West):	73.783536 - 73° 47' 0.73''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602448.1
UTM Y (Meters):	4529356.5
Elevation:	84 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 84 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
WESTCHESTER, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 36119C - FEMA DFIRM Flood data

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MOUNT VERNON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Ordovician
Series:	Middle Ordovician (Mohawkian)
Code:	O2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 4628045.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
		INQUIRY #:	4628045.2s
LAT/LONG:	40.910808 / 73.783536	DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: gravelly loam

Hydrologic Group: Not reported

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 127 inches

Depth to Watertable Min: > 38 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 141 Min: 4	Max: 7.3 Min: 4.5
2	3 inches	72 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000835790	0 - 1/8 Mile ESE
2	USGS40000835842	1/8 - 1/4 Mile NNE
3	USGS40000835908	1/2 - 1 Mile NNE
4	USGS40000835896	1/2 - 1 Mile NE
5	USGS40000835943	1/2 - 1 Mile NNW
6	USGS40000835557	1/2 - 1 Mile SSW
7	USGS40000835919	1/2 - 1 Mile ENE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG80000040052	1/4 - 1/2 Mile WSW
A2	NYOG80000040051	1/4 - 1/2 Mile WSW
A3	NYOG80000040050	1/2 - 1 Mile WSW
A4	NYOG80000040049	1/2 - 1 Mile WSW
A5	NYOG80000040053	1/2 - 1 Mile WSW

PHYSICAL SETTING SOURCE MAP - 4628045.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
LAT/LONG:	40.910808 / 73.783536	INQUIRY #:	4628045.2s
		DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ESE **FED USGS** **USGS40000835790**
0 - 1/8 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405436073465501		
Monloc name:	WE 105		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9100993
Longitude:	-73.7815215	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	98.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	268
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	8.00	

2
NNE **FED USGS** **USGS40000835842**
1/8 - 1/4 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405445073470001		
Monloc name:	WE 100		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9125993
Longitude:	-73.7829104	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	85.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	300
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	8.00	

3
NNE **FED USGS** **USGS40000835908**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405502073464401		
Monloc name:	WE 283		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9173214
Longitude:	-73.7784658	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

4
NE **FED USGS** **USGS40000835896**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405459073463801		
Monloc name:	WE 104		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9164881
Longitude:	-73.7767991	Sourcemap scale:	Not Reported

Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	750
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	15.00	

5
NNW **FED USGS** **USGS40000835943**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405510073471501		
Monloc name:	WE 98		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9195436
Longitude:	-73.7870772	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	55.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	401
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	4.00	

6
SSW **FED USGS** **USGS40000835557**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405354073472801		
Monloc name:	WE 103		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.8984329
Longitude:	-73.7906885	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	220
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	12.00	

7
ENE **FED USGS** **USGS40000835919**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405504073460301		
Monloc name:	WE1055		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.917877
Longitude:	-73.7670766	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	1
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Till		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	17
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	3.00	

Map ID
Direction
Distance

Database EDR ID Number

A1
WSW **OIL_GAS** **NYOG80000040052**
1/4 - 1/2 Mile

Api wellno:	31119237750000	Cnty:	0
Hole:	23775	Sidetrck:	0
Completion:	0	Well name:	SCW 4
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-02 00:00:00	Date total:	2008-09-19 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792499		
Surface la:	40.909323		
Bottom hol:	BH		
Bottom h00:	-73.792499		
Bottom h01:	40.909323		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	75	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:15.897000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237750000		
Site id:	NYOG80000040052		

A2
WSW **OIL_GAS** **NYOG80000040051**
1/4 - 1/2 Mile

Api wellno:	31119237740000	Cnty:	0
Hole:	23774	Sidetrck:	0
Completion:	0	Well name:	SCW 3
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-08-21 00:00:00	Date total:	2008-09-16 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792772		
Surface la:	40.909283		
Bottom hol:	BH		
Bottom h00:	-73.792772		

Bottom h01:	40.909283		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	73	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:30.367000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237740000		
Site id:	NYOG80000040051		

A3
WSW **OIL_GAS** **NYOG80000040050**
1/2 - 1 Mile

Api wellno:	31119237730000	Cnty:	0
Hole:	23773	Sidetrck:	0
Completion:	0	Well name:	SCW 2
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	NL	Map symbol:	OP
Well statu:	PA	Date statu:	2008-11-06 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-07-10 00:00:00	Date total:	2008-07-19 00:00:00
Date well :	Not Reported	Date wel00:	2008-10-10 00:00:00
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792953		
Surface la:	40.909185		
Bottom hol:	BH		
Bottom h00:	-73.792953		
Bottom h01:	40.909185		
True verti:	1500	Measured d:	1500
Kickoff:	0	Drilleddep:	1500
Elevation:	71	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:56.020000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237730000		
Site id:	NYOG80000040050		

A4
WSW **OIL_GAS** **NYOG80000040049**
1/2 - 1 Mile

Api wellno:	31119237720000	Cnty:	0
Hole:	23772	Sidetrck:	0
Completion:	0	Well name:	SCW 1
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-08 00:00:00	Date total:	2008-09-23 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.793051		
Surface la:	40.909223		
Bottom hol:	BH		
Bottom h00:	-73.793051		
Bottom h01:	40.909223		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	72	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-10 07:49:59.300000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237720000		
Site id:	NYOG80000040049		

A5
WSW **OIL_GAS** **NYOG80000040053**
1/2 - 1 Mile

Api wellno:	31119237760000	Cnty:	0
Hole:	23776	Sidetrck:	0
Completion:	0	Well name:	SCW 5
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-08 00:00:00	Date total:	2008-09-23 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.793036		
Surface la:	40.909069		
Bottom hol:	BH		
Bottom h00:	-73.793036		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Bottom h01:	40.909069		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	69	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-10 07:50:13.420000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237760000		
Site id:	NYOG80000040053		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

BLACKSTONE CONSULTING LLC

JOHN O'CONNOR

Senior Project Manager

PROFESSIONAL SUMMARY:

Mr. O'Connor has extensive experience in environmental programs compliance and management. He has performed and managed environmental projects related to hazardous materials building inspections; hazardous materials abatement site monitoring and emergency response planning; indoor air quality investigations (IAQ); Phase I and II environmental site assessments (ESA); underground/aboveground storage tank (UST/AST) removal and replacement and systems management; and quality control audits. He has written a variety of environmental assessment reports and proposals. Mr. O'Connor has performed these services at a variety of private, commercial, industrial and governmental facilities.

PROJECT EXPERIENCE:

- Over eighteen years of experience in conducting environmental assessments in commercial facilities, industrial properties, single and multi-family housing developments, and schools.
- Extensive experience in conducting Phase I Environmental Site Assessments in accordance with ASTM, HUD MAP, Fannie Mae and Freddie Mac Guidelines, as well as numerous private lender guidelines.
- Extensive experience in project management of asbestos and lead abatement projects, soil remediation projects and UST removals.
- Experience in conducting Phase II Environmental Site Assessments including materials sampling and soil and ground-water borings.
- Experience in environmental personnel management, project cost estimating, and effective staff scheduling.
- Experience in conducting quality control audits of field personnel for a multi-million dollar federal lead hazard risk assessment project.
- Experience as a Project Manager for a $500,000.00 mold abatement project.
- Knowledgeable in regulatory requirements for, and identification of, environmental hazards associated with commercial and residential buildings. Advises clients in effective management and resolution of the identified concerns.
- Trained in the health effects of lead and asbestos, federal and state regulations, techniques of assessment and abatement, use of protective equipment, assessment record keeping and reporting.

- A highly trained lead inspector, qualified in the use of Niton XL Spectrum Analyzer. Performs lead-based paint surveys in support of public and private multifamily developments and private residences.
- Experienced in conducting Energy Audits for single family residences, multi-family and commercial properties.
- Extensive training in environmental regulations, hazard identification, risk assessment and abatement methods.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

B.S., Millersville University, Major: Occupational Safety and Hygiene Management

Manufacturer's Training Course for Niton XL Spectrum Analyzer

EPA/AHERA Annual Asbestos Refresher Course

EPA Model Lead Paint Risk Assessor

Radon Measurement Operators Training Course

Home Energy Rating System Training

CERTIFICATIONS/ACCREDITATIONS/CONTINUING EDUCATION:

HUD Sponsored Multifamily Accelerated Processing (MAP) Training, Baltimore, Maryland

Maryland Accredited Lead Paint Risk Assessor

Pennsylvania Accredited Lead Paint Risk Assessor

Virginia Accredited Lead Paint Risk Assessor

District of Columbia Accredited Lead Paint Risk Assessor

EPA/AHERA Certified Asbestos Building Inspector

EPA/AHERA Certified Asbestos Management Planner

EPA Radon Measurement Proficiency Program Listed Inspector

Florida Licensed Radon Measurement Technician

Certified to Collect Drinking Water: Maryland

BLACKSTONE CONSULTING LLC

ALLAN S. COFFEE

Associate

PROFESSIONAL SUMMARY:

Mr. Coffee has over 25 years of experience assisting clients in their relationship with the built environment. He has expertise in all aspects of environmental oversight, regulation, and liability associated with property acquisition, management, and disposition. He also specializes in team leadership and oversight of Due Diligence activities, Phase I ESAs, Building Surveys, Subsurface Soil and Groundwater Sampling, Soil and Groundwater Remediation and Monitoring, as well as Regulatory Closure.

SELECTED PROJECT EXPERIENCE:

- Managed and directed technical and financial aspects of all operations in the Western United States Division for a national full-service environmental consulting company, including environmental services (Phase I ESAs, soil and groundwater, etc.), construction services (asbestos, lead, and other regulated building materials), industrial hygiene services (occupational monitoring, negative exposure assessments), and indoor air quality (moisture, microbial growth).
- Directed all aspects of environmental geology services for an environmental consulting company, including the oversight and management of technical approach, project budgeting and accounting for Due Diligence, Phase I ESAs, and soil and groundwater remediation.
- Performed Phase I ESAs, Soil and Groundwater Assessments, and regulatory communication for a variety of property owners, environmental consulting companies, and government projects.

EDUCATION AND PROFESSIONAL AFFILIATIONS

University of California at Los Angeles, CA, Bachelor of Science

OSHA 40-Hour HAZWOPER (Hazardous Waste Operator and Emergency Response)

NIOSH 582 Analyst Equivalent Certification

Indoor Air Quality Specialist/Inspector

California Registered Environmental Assessor I (REA I)

BLACKSTONE CONSULTING LLC

STEPHEN E. MANELIS

Principal and Co-Founder

PROFESSIONAL SUMMARY:

Mr. Manelis is co-founder of Blackstone and has over 18 years of experience with Environmental Site Assessments (ESAs) and other Due Diligence consulting during Real Estate Transactions and Mergers/Acquisitions. Specific experience includes Phase I and II ESAs, Environmental Compliance/Audit, and Asbestos, Lead-based paint, Radon gas, and Mold/IAQ consulting, and Property Condition Assessments. Additional experience includes soil/groundwater contamination assessments and regulatory agency coordination, remedial-action planning and management, pre-construction soil and groundwater characterization for urban redevelopment site/Brownfields, NPDES permitting and storm water management; wetland delineation and permitting; and threatened and endangered species studies.

In addition to leading Blackstone's Real Estate and Due Diligence business unit, Mr. Manelis is responsible for developing and maintaining Blackstone's national client accounts program.

SELECTED PROJECT EXPERIENCE:

Managed over 3300 Phase I Environmental Site Assessments (ESAs) for corporate real estate departments, real estate investment trusts (REITs), Fannie Mae/Freddie Mac underwriters, large national and regional banks, private/public investment groups and equity sponsors, and industrial/commercial facilities throughout the United States. In addition to site visit experience on numerous types of real estate, experiences include organization of project staff for single projects and/or portfolios, management of field activities and accurate interpretation of data, and final report QA/QC.

Third party review coordinator and project manager during industrial facility mergers/acquisitions throughout the continental U.S. As consultant to equity partners, provided capital expenditure and annual operating budgets associated with environmental compliance, waste management and disposal, and permitting.

Provided technical support and project management for wetland delineation and habitat assessment studies in the Southeast. Work involved reviewed of wetland field survey activities, surveying and map preparation, and the research of Federal and State databases concerning known occurrences of threatened and endangered species followed by field verification.

Program Manager for due diligence team associated industrial park acquisition by a publicly-traded REIT. Environmental issues included past manufacturing operations,

underground storage tanks usage, various hazardous materials storage, and adjoining property with known groundwater contamination migrating onto the site. Past on-site use and contamination triggered New Jersey ISRA reporting and coordination with the NJDEP. Phase I ESA and Phase II subsurface investigation work completed within 21-days and evaluation of risk and potential remediation cost defined. Quick response and resolution allowed transaction to occur and assigned liability to the appropriate parties protecting the buyer.

Program Manager for redevelopment of industrial property formerly consisting of vehicle repair facility, furniture stripper, machine shop, and light manufacturer. Client was publicly-traded REIT and project included mid-rise 200-unit multi-family housing development with subterranean parking. Contamination identified during due diligence required notification to state regulatory agency with potential to stall acquisition and development approvals. Remediation risk and cost defined during due diligence allowing transaction to occur before regulatory closure achieved. Remediation activities of soil and groundwater performed in conjunction with construction providing savings and fast-tracking regulatory closure with state agency. Project was completed and remains in client portfolio.

Program Manager for environmental due diligence and redevelopment consulting services for privately-held nationwide student housing developer. Project included acquisition and redevelopment of a high profile student housing project in Philadelphia, PA. Work included initial environmental due diligence, identification and resolution of asbestos and underground storage tank risk via sampling, and proper permitting prior to demolition of over 200,000 square feet of building space. Project construction proceeded as planned.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

University of Rhode Island - Bachelor of Science, Natural Resource Development

ASTM E-50 Committee for Environmental Assessment

National Registry of Environmental Professionals (NREP)

AHERA/EPA Asbestos in Buildings Inspector

Liability Design for Environmental Professionals (DPIC Companies)

40-Hour OSHA Training

LA Rochelle
275 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 5252505.2s
April 09, 2018

The EDR Radius Map™ Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	724
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

GeoCheck - Not Requested

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

COORDINATES

Latitude (North):	40.9100330 - 40˚ 54' 36.11''
Longitude (West):	73.7841430 - 73˚ 47' 2.91''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602398.2
UTM Y (Meters):	4529270.0
Elevation:	96 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	OFFICE BUILDING	8-10 RAILROAD PLACE	NY Spills	Lower	1 ft.
B2	SOUND CLEANER	63 MEMORIAL HWY	NY DRYCLEANERS	Lower	1 ft.
B3	SOUND CLEANERS	63 MEMORIAL HWY	EDR Hist Cleaner	Lower	1 ft.
C4	RESIDENCE	129 DIVISON ST	NY Spills	Higher	34, 0.006, South
B5	UST	MEMORIAL HIGHWAY AND	NY Spills	Higher	38, 0.007, ENE
B6	CONSOLIDATED EDISON	MEMORIAL HIGHWAY & H	NY MANIFEST	Higher	38, 0.007, ENE
C7	CON ED	DIVISION ST AND HUGE	NY MANIFEST	Higher	48, 0.009, South
C8	CON EDISON	HUGENOT & DIVISION S	NY MANIFEST	Higher	48, 0.009, South
C9	CON EDISON MANHOLE:	HUGENOT AVE & DIVISI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	48, 0.009, South
C10	CON EDISON	HUGENOT ST & DIVISIO	NY MANIFEST	Higher	48, 0.009, South
C11	CON EDISON	DIVISION & HUGUENOT	NY MANIFEST	Higher	48, 0.009, South
C12	CON EDISON - TRANSFO	DIVISION ST AND HUGE	RCRA-LQG	Higher	48, 0.009, South
C13	CON EDISON TRANSFORM	DIVISION ST & HUGUEN	RCRA NonGen / NLR	Higher	48, 0.009, South
B14	METRO NORTH TRACKS	EAST OF NEW ROCHELLE	NY Spills	Lower	49, 0.009, NNW
B15	METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	NY Spills	Lower	49, 0.009, NNW
C16	NYSDOT BIN 1049890	DIVISION ST OVER MET	RCRA NonGen / NLR	Higher	53, 0.010, SSE
A17	MH1204	HUGUENOT AVE/LAWTON	NY Spills	Lower	99, 0.019, ENE
C18	AVALON ON THE SOUND	HUGUENOT STREET AND	NY UST	Higher	115, 0.022, SE
C19	VACANT LOT	HUGUENOT ST/DIVISION	NY LTANKS	Higher	165, 0.031, SSE
C20	ROAD	HUGUENOT ST/DIVISION	NY Spills	Higher	165, 0.031, SSE
C21	SHORELINE OIL	296 HUGENOT ST,REAR	NY LTANKS	Higher	174, 0.033, South
C22	LILLIAN VERNON CO.	WESTCHESTER PLACE	NY LTANKS	Higher	180, 0.034, SSE
B23	NYSDOT BIN 1091390	DIVISION ST OVER I 9	RCRA NonGen / NLR	Lower	188, 0.036, NW
C24	NEW ROCHELLE IRISH B	38 DIVISION STREET	NY UST	Higher	208, 0.039, SSE
D25	CON EDISON	260 NORTH AVE	NJ MANIFEST	Lower	222, 0.042, NE
D26	CON EDISON	260 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	222, 0.042, NE
C27	HAYES KATHRYN INC	36-38 DIVISION ST	EDR Hist Cleaner	Higher	231, 0.044, SSE
C28	TRINITY-ST. PAUL'S E	311 HUGUENOT STREET	NY UST	Higher	238, 0.045, SSW
C29	JONES RESIDENCE	311 HUGUENOT STREET	NY LTANKS	Higher	238, 0.045, SSW
E30	MAIN LIBRARY	LAWTON ST	NY LTANKS	Lower	242, 0.046, ENE
E31	ACCESSOCRAFT PRODUCT	48 LAWTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	244, 0.046, East
D32	CON EDISON MANHOLE:	HUGUENOT AVE & NORTH	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	245, 0.046, NE
D33	HUGUENOT AND NORTH A	HUGUENOT AND NORTH A	NY Spills	Lower	245, 0.046, NE
D34	CON EDISON MANHOLE:	HUGENUOT ST & NORTH	RCRA NonGen / NLR	Lower	245, 0.046, NE
D35	CON EDISON	NORTH AVE & HUGENOT	NY MANIFEST	Lower	245, 0.046, NE
D36	CON EDISON TRANSFORM	NORTH AVE & HUGUENOT	RCRA NonGen / NLR, NY MANIFEST	Lower	245, 0.046, NE
37	SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	NY Spills	Lower	260, 0.049, WNW
D38	US POSTAL SERVICE	255 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	263, 0.050, NE
C39	306 HUGUENOT STREET	306 HUGUENOT STREET	NY AST	Higher	264, 0.050, South

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C40	CERUSSI AND VERE	306 HUGUENOT ST	NY UST	Higher	264, 0.050, South
D41	A PLUS INC	271 NORTH AVE STE 11	EDR Hist Auto	Lower	292, 0.055, NE
D42	KAUFMAN HUGUENOT COM	271 NORTH AVENUE	NY UST, NY AST	Lower	292, 0.055, NE
E43	APT BUILDING/LAWTON	41-43 LAWTON ST	NY LTANKS	Lower	293, 0.055, East
E44	LAWTON STREET REALTY	41-43 LAWTON ST	NY LTANKS	Lower	293, 0.055, East
E45	PAVEMENT	41 LAWTON STREET	NY Spills	Lower	293, 0.055, East
E46	LAWTON STREET REALTY	41-43 LAWTON STREET	NY UST	Lower	293, 0.055, East
D47	FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	RCRA NonGen / NLR	Lower	295, 0.056, ENE
F48	CABLE	29 DIVISION STREET	NY Spills	Higher	303, 0.057, SSE
49	STATION CLEANERS	24 STATION PLZ	EDR Hist Cleaner	Lower	303, 0.057, North
G50	NORTH BROOK REALTY A	270 NORTH AVENUE, SU	NY UST	Lower	333, 0.063, NNE
G51	277 NORTH LLC	277 NORTH AVENUE	NY LTANKS	Lower	386, 0.073, NNE
G52	CON EDISON MANHOLE:	277 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	386, 0.073, NNE
G53	277 NORTH LLC	277 NORTH AVENUE	NY UST	Lower	386, 0.073, NNE
G54	BUSINESS	277 NORTH AVENUE	NY LTANKS	Lower	386, 0.073, NNE
G55	EAST RIVER SAVINGS B	277 NORTH AVE.	NY LTANKS	Lower	386, 0.073, NNE
F56	CON EDISON	19 DIVISION ST & WAS	NY Spills, NY MANIFEST	Higher	422, 0.080, SSE
H57	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY UST	Lower	427, 0.081, ENE
H58	NORTH AVE REALITY	5 ANDERSON ST	NY LTANKS	Lower	427, 0.081, ENE
H59	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY AST	Lower	427, 0.081, ENE
E60	CON EDISON	ANDERSON ST & NORTH	NY MANIFEST	Lower	428, 0.081, ENE
E61	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Lower	428, 0.081, ENE
E62	CON EDISON TRANSFORM	NORTH AVE & ANDERSON	RCRA NonGen / NLR, NY MANIFEST	Lower	428, 0.081, ENE
E63	CON EDISON	NORTH AVE & ANDERSON	RCRA NonGen / NLR, FINDS, ECHO	Lower	428, 0.081, ENE
E64	CON EDISON	NORTH AVE & ANDERSON	NJ MANIFEST	Lower	428, 0.081, ENE
E65	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Lower	428, 0.081, ENE
E66	CONCRETE FLOORING WI	230 NORTH AVENUE	NY Spills	Lower	446, 0.084, ENE
E67	MKM EQUITY, LLC	230 NORTH AVENUE	NY AST	Lower	446, 0.084, ENE
E68	CON EDISON	230 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	446, 0.084, ENE
E69	CON ED	230 NORTH AVE	NY MANIFEST	Lower	446, 0.084, ENE
E70	CON EDISON	230 NORTH AVE	NJ MANIFEST	Lower	446, 0.084, ENE
F71	COMM/RESIDENT. PROPE	15 DIVISION STREET	NY LTANKS	Higher	468, 0.089, SSE
E72	NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	NY LTANKS	Lower	485, 0.092, East
I73	SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	NY UST	Higher	486, 0.092, SSW
I74	APARTMENT BLDG	54 CENTRE AVE	NY LTANKS	Higher	486, 0.092, SSW
I75	CEMENT COURT YARD	54 CENTER AVE	NY Spills	Higher	486, 0.092, SSW
I76	CON EDISON	HUGENOT & CENTRE ST	NY MANIFEST	Higher	520, 0.098, SSW
I77	CON EDISON	CENTER & HUGUENOT	NY MANIFEST	Higher	520, 0.098, SSW
I78	CON EDISON	CENTRE AVE & HUGUENO	NY MANIFEST	Higher	520, 0.098, SSW

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I79	CON EDISON	HUGUENOT ST & CENTRE	RCRA NonGen / NLR	Higher	520, 0.098, SSW
H80	CVS PHARMACY #8447	222 NORTH AVE	RCRA-LQG, NY MANIFEST	Lower	522, 0.099, East
J81	DELUXE TAXI	10 STATION PLAZA	NY UST	Lower	533, 0.101, North
F82	RPM REALTY INC	9-15 DIVISION STREET	NY UST	Higher	543, 0.103, SSE
F83	RPM REALTY INC	9-15 DIVISION STREET	NY AST	Higher	543, 0.103, SSE
I84	COMMERCIAL PROPERTY	64 CENTRE AVE	NY LTANKS	Higher	556, 0.105, South
I85	HACKER MORRIS J & SO	64 CENTRE AVE	EDR Hist Auto	Higher	556, 0.105, South
I86	M.J. HACKER & SONS I	64 CENTRE AVE	NY UST	Higher	556, 0.105, South
I87	ERIC S TURNER & CO I	33-35 CENTRE AVE	RCRA-CESQG, NY MANIFEST, NJ MANIFEST	Lower	560, 0.106, SSW
K88	I-95	I-95EB MP54	NY Spills	Lower	560, 0.106, WSW
K89	P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	NY Spills	Lower	560, 0.106, WSW
L90	DEPOT PLACE LLC	1 DEPOT PLACE	NY UST	Lower	562, 0.106, NNW
L91	STATION CLEANERS	1 DEPOT PLAZA #1	NY DRYCLEANERS	Lower	562, 0.106, NNW
I92	SIMONETTI CLEANERS &	62 CENTRE AVE	EDR Hist Cleaner	Higher	573, 0.109, South
I93	SIMONETTI CLEANERS	62 CENTRE ST	RCRA-CESQG, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	573, 0.109, South
I94	GREEN HEAVEN/CENTRE	62 CENTRE AVE.	NY DRYCLEANERS	Higher	573, 0.109, South
M95	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Lower	593, 0.112, SW
M96	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Lower	593, 0.112, SW
N97	CON EDISON	HUGUENOT ST & LE COU	NY MANIFEST	Lower	596, 0.113, NE
N98	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	596, 0.113, NE
N99	CON EDISON	HUGUENOT ST & LE COU	NJ MANIFEST	Lower	596, 0.113, NE
N100	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	596, 0.113, NE
N101	CON EDISON	HUGUENOT ST & LE COU	RCRA NonGen / NLR	Lower	596, 0.113, NE
H102	SPEEDY CLEANERS	217 NORTH AVENUE	US AIRS, FINDS, ECHO, NY DRYCLEANERS	Lower	597, 0.113, East
I103	VERIZON	342 HUGUENOT ST	NY Spills	Lower	608, 0.115, SSW
I104	NYNEX LOCATION	342 HUEGNOT ST	NY LTANKS	Lower	608, 0.115, SSW
I105	NEW YORK TELEPHONE C	342 HUGUENOT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	608, 0.115, SSW
J106	SPOKEN ARTS BUILDING	310 NORTH AVENUE	NY UST	Lower	608, 0.115, North
J107	NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	NY UST	Lower	622, 0.118, North
M108	APPAREL PLUS	27 CENTRE AVE	NY Spills	Lower	623, 0.118, SW
O109	SIDNEY FURNITURE	535 MAIN ST	NY Spills	Higher	632, 0.120, SSE
O110	535 MAIN ST ASSOCIAT	535 MAIN STREET	NY Spills	Higher	632, 0.120, SSE
L111	COMMERCIAL - UST	35 GRAND STREET	NY Spills	Lower	641, 0.121, NNW
O112	LILLIAN VERNON CORPO	543-549 MAIN STREET	NY UST	Higher	648, 0.123, SSE
O113	BLUE GILL REALTY	543 MAIN ST	NY LTANKS, NY Spills	Higher	648, 0.123, SSE
O114	543 MAIN STREET	543 MAIN STREET	NY UST	Higher	648, 0.123, SSE
H115	CON EDISON	LECOUNT PL & ANDERSO	NJ MANIFEST	Lower	649, 0.123, ENE
H116	CON EDISON	LECOUNT PL & ANDERSO	NY MANIFEST	Lower	649, 0.123, ENE
H117	CON EDISON	LECOUNT PL & ANDERSO	RCRA NonGen / NLR, FINDS, ECHO	Lower	649, 0.123, ENE

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
O118	CON EDISON - TRANSFO	DIVISION ST & MAIN S	RCRA-LQG	Higher	653, 0.124, SSE
O119	CON EDISON	DIVISION ST & MAIN S	NY MANIFEST	Higher	653, 0.124, SSE
O120	CONSOLIDATED EDISON	DIVISION & MAIN	NY MANIFEST	Higher	653, 0.124, SSE
O121	CON EDISON - TRANSFO	DIVISION ST & MAIN S	NJ MANIFEST	Higher	653, 0.124, SSE
P122	J P MORGAN CHASE BAN	491 MAIN STREET	NY UST, NY AST	Lower	653, 0.124, ESE
P123	BARCLAYS BANK OF NY/	491 MAIN ST.	NY LTANKS	Lower	653, 0.124, ESE
I124	75 CENTRE AVENUE LLC	75 CENTRE AVENUE	NY UST, NY AST	Higher	661, 0.125, South
J125	CON EDISON MANHOLE:	313 NORTH AVE FRONT	RCRA NonGen / NLR	Lower	662, 0.125, North
H126	MACYS	33 LE COUNT PLACE	NY MANIFEST	Lower	673, 0.127, ENE
J127	4 STORY APARTMENT BU	320 NORTH AVENUE	NY UST	Lower	678, 0.128, North
O128	COMMERCIAL PROPERTY	522 MAIN STREET	NY LTANKS	Higher	681, 0.129, SE
I129	MAISON 347 LLC	347 HUGUENOT STREET	NY UST	Lower	683, 0.129, SSW
I130	COCO RESIDENCE	81 CENTRE AVE	NY LTANKS	Higher	683, 0.129, South
131	CON EDISON	19 DIVISION ST & WAS	RCRA NonGen / NLR, FINDS, ECHO	Lower	686, 0.130, NW
P132	COMMERCIAL BUILDING	507 MAIN STREET	NY LTANKS	Higher	689, 0.130, SE
O133	CON EDISON TRANSFORM	MAIN ST & CHRUCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	692, 0.131, SE
O134	CON EDISON MANHOLE:	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	692, 0.131, SE
O135	CON EDISON	MAIN ST & CHURCH ST	NY MANIFEST	Higher	692, 0.131, SE
O136	CON EDISON TRANSFORM	CHURCH ST & MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	692, 0.131, SE
P137	CATHOLIC NEWS PUBLIS	210 NORTH AVE	NY LTANKS	Lower	698, 0.132, East
Q138	CON EDISON	205 NORTH AVE	RCRA NonGen / NLR	Lower	713, 0.135, East
Q139	CON EDISON	205 NORTH AVE	NY MANIFEST	Lower	713, 0.135, East
Q140	CON EDISON	205 NORTH AVE	NJ MANIFEST	Lower	713, 0.135, East
N141	TRUMP PLAZA	175 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	720, 0.136, NE
I142	587 MAIN STREET	348 HUGUENOT STREET	NY AST	Lower	721, 0.137, SSW
O143	CON EDISON	552 MAIN ST	NJ MANIFEST	Higher	724, 0.137, SSE
O144	CON EDISON	552 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	724, 0.137, SSE
O145	542 MAIN STREET LLC	542 MAIN STREET	NY UST	Higher	727, 0.138, SSE
O146	OFFICE BLDG	542 MAIN STREET	NY LTANKS	Higher	727, 0.138, SSE
P147	NEW ROCHELLE PUBLIC	ONE LIBRARY PLAZA	NY UST	Lower	729, 0.138, ESE
M148	MR CHIMNEY CLEAN	32 RELYEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	731, 0.138, SSW
R149	BLOOMINGDALE PARKING	554 MAIN ST	NY UST	Higher	733, 0.139, SSE
P150	BARON MANAGEMENT	200 NORTH AVENUE	NY UST	Lower	735, 0.139, East
J151	CON EDISON SERVICE B	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	736, 0.139, North
J152	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	736, 0.139, North
J153	CON EDISON MANHOLE:	NORTH ST & GARDEN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	736, 0.139, North
J154	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, FINDS, ECHO	Lower	736, 0.139, North
J155	CON EDISON - MANHOLE	GARDEN ST AND NORTH	RCRA-LQG, NY MANIFEST	Lower	736, 0.139, North
J156	CON EDISON MANHOLE 4	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	736, 0.139, North

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P157	NEW ROCHELLE PUBLIC	1 LAWTON	NY LTANKS	Lower	750, 0.142, ESE
L158	CIOTTI RESIDENCE	60 GRAND STREET	NY LTANKS, NY Spills	Lower	754, 0.143, NNW
R159	CON EDISON	565 MAIN ST	NJ MANIFEST	Higher	755, 0.143, South
R160	CON EDISON	565 MAIN ST	RCRA NonGen / NLR	Higher	755, 0.143, South
O161	NEW ROCHELLE SUPERMA	538 MAIN STREET	NY AST	Higher	769, 0.146, SSE
R162	HANGERS CLEANERS	562-564 MAIN STREET	NY DRYCLEANERS	Higher	777, 0.147, South
P163	ADREAN PRINTING CO	490 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	777, 0.147, ESE
M164	PRO AUTO PARTS	41 REYLEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	779, 0.148, SW
S165	FIRST METRO SERVICES	357 HUGONOT ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	786, 0.149, SSW
T166	NYS THRUWAY AUTH	THRUWAY BRIDGE MP 60	RCRA NonGen / NLR, NY MANIFEST	Lower	788, 0.149, North
L167	GUIDANCE CENTER INC	70 GRAND ST	NY LTANKS	Lower	791, 0.150, NNW
R168	MISR REALTY, LLC	573-579 MAIN STREET	NY AST	Higher	792, 0.150, South
R169	CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	NY LTANKS	Higher	802, 0.152, South
R170	MISR REALTY, LLC	573-579 MAIN STREET	NY UST	Higher	809, 0.153, South
M171	INDUST OVERALL SERVI	10 BARTELS PLACE	NY LTANKS	Lower	815, 0.154, SW
P172	RETTNER MANAGEMENT C	481 MAIN ST	NY UST	Lower	815, 0.154, ESE
M173	NYSDEC-SITE 360109 I	10 BARTELS PL	NJ MANIFEST	Lower	819, 0.155, SW
M174	NYSDEC-SITE 360109 I	10 BARTELS PL	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Lower	819, 0.155, SW
M175	INDUSTRIAL OVERALL S	10 BARTELS PLACE	NY SHWS, NY CBS	Lower	819, 0.155, SW
M176	INDUSTRIAL OVERALL S	10 BARTELLS PLACE	NY UST	Lower	819, 0.155, SW
M177	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY CBS AST	Lower	819, 0.155, SW
R178	CON EDISON	MAIN ST & CENTRE ST	NY MANIFEST	Higher	820, 0.155, South
R179	CON EDISON	CENTRE & MAIN ST	NJ MANIFEST	Higher	820, 0.155, South
R180	CON EDISON	CENTRE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	820, 0.155, South
R181	CON EDISON TRANSFORM	CENTRE AVE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	820, 0.155, South
R182	CON ED	CENTRE & MAIN ST	NY MANIFEST	Higher	820, 0.155, South
183	RITZCOVAN - TTF	22 BURLING LANE	NY LTANKS	Lower	830, 0.157, North
T184	CON EDISON MANHOLE:	NORTH AVE & BURLING	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	834, 0.158, North
S185	STORAGE USA	363 HUGUENOT STREET	NY UST	Lower	868, 0.164, SSW
U186	CASARRA RESIDENCE	9 BADEAU PL	NY LTANKS	Higher	869, 0.165, West
V187	NYNEX	40 WASHINGTON AVE	NY LTANKS	Higher	922, 0.175, WNW
W188	DRIVE IT YOURSELF	20 GARDEN STREET	NY UST	Lower	927, 0.176, NNE
X189	ROTH CLEANERS	1 LEROY PL	RCRA NonGen / NLR, FINDS, ECHO, NY DRYCLEANERS, NY...	Higher	937, 0.177, SSE
X190	CONSOLIDATED EDISON	DIVISION ST & LEROY	NY MANIFEST	Higher	956, 0.181, SSE
Y191	CON ED-V37	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	959, 0.182, East
Y192	CON ED-V14	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	959, 0.182, East
U193	RESIDENCE	18 BADEAU PLACE	NY LTANKS	Higher	964, 0.183, WNW
Z194	J B & FRANKS	27 BARTELS PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	976, 0.185, SW
V195	SAINT GABRIEL HIGH S	50 WASHINGTON AVENUE	NY UST	Higher	984, 0.186, WNW

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
V196	ST GABRIEL SCHOOL	50 WASHINGTON AVE	NY LTANKS	Higher	984, 0.186, WNW
V197	50 WASHINTON AVE	50 WASHINTON AVE	NY LTANKS	Higher	984, 0.186, WNW
S198	CON EDISON	HUGENOT AVE & COLUMB	NY MANIFEST	Lower	990, 0.188, SSW
S199	CON EDISON	HUGUENOT ST & COLUMB	NY MANIFEST	Lower	990, 0.188, SSW
S200	CON EDISON	HUGENOT ST & COLUMBU	NY MANIFEST	Lower	990, 0.188, SSW
W201	FURNITURE RESTORNATI	26 GARDEN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	997, 0.189, NNE
U202	DIIORGI HOME	47 WARREN STREET	NY LTANKS	Higher	999, 0.189, West
Z203	CON EDISON	35 BARTELS PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1020, 0.193, SW
Z204	CON EDISON	35 BARTELS PL	NY MANIFEST	Lower	1020, 0.193, SW
T205	CON EDISON MANHOLE:	350 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1022, 0.194, North
AA206	APT BUILDING	40 WARREN STREET	NY LTANKS, NY Spills	Lower	1022, 0.194, West
AB207	CON EDISON TRANSFORM	595 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1035, 0.196, South
Z208	RUSH MFG CORP	18 COLUMBUS AVE.	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1053, 0.199, SSW
U209	NYNEX	UNION AVENUE AND WAR	NY MANIFEST	Higher	1063, 0.201, West
AB210	CON EDISON TRANSFORM	592 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1065, 0.202, South
211	CITIZEN	33 GROVE ST	NY LTANKS	Lower	1067, 0.202, WSW
AC212	THE MALL	MAIN STREET	NY LTANKS	Lower	1079, 0.204, East
AD213	175 MEMORIAL HWY. RE	175 MEMORIAL HWY.	NY UST	Lower	1081, 0.205, NNW
AE214	CON EDISON SERVICE B	LEROY PL & CENTER AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1084, 0.205, South
AE215	CON EDISON	CENTRE AVE & LEROY	NY MANIFEST	Higher	1084, 0.205, South
AE216	CON EDISON SERVICE B	CENTRE AVE & LEROY	RCRA NonGen / NLR, FINDS	Higher	1084, 0.205, South
AF217	THE HUGUENOT	381-393 HUGUENOT STR	NY BROWNFIELDS	Lower	1091, 0.207, SSW
AG218	CON EDISON SERVICE B	174 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1092, 0.207, ESE
AH219	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1102, 0.209, North
AI220	NEW ROCHELLE HOSPITA	COVION PLACE	NY LTANKS	Higher	1115, 0.211, NW
AH221	MAYCO, LLC	18-20 MAY ST	NY AST	Lower	1118, 0.212, NNW
AH222	SCHMUCKLERS CLEANERS	360 NORTH AVE	RCRA-CESQG, NY MANIFEST	Lower	1121, 0.212, North
AH223	SCHMUKLER'S CLEANERS	360 NORTH AVE.	NY DRYCLEANERS	Lower	1121, 0.212, North
AI224	SOUTH SHORE MED CENT	16 GUION PLACE	NY LTANKS	Higher	1144, 0.217, NW
AI225	SOUND SHORE MEDICAL	16 GUION PL	PA MANIFEST	Higher	1144, 0.217, NW
AI226	MONTEFIORE - NEW ROC	16 GUION PLACE	NY UST, NY AST	Higher	1144, 0.217, NW
AI227	MONTEFIORE - NEW ROC	16 GUION PL	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	1144, 0.217, NW
228	RESIDENCE	79 WARREN ST	NY LTANKS	Higher	1145, 0.217, WNW
AD229	66 MEMORIAL BLVD	66 MEMORIAL BLVD	NY LTANKS	Lower	1147, 0.217, NNW
AJ230	LEXINGTON CENTER FOR	3 COTTAGE PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1152, 0.218, NNE
AJ231	LEXINGTON CENTER FOR	3 COTTAGE PL	NJ MANIFEST	Lower	1152, 0.218, NNE
232	CON EDISON	46 CLINTON PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1156, 0.219, SE
AC233	MONROE COLLEGE	420 MAIN STREET	NY AST	Lower	1179, 0.223, East
AB234	CON EDISON MANHOLE:	MAIN ST & MAPLE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1190, 0.225, SSW

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AB235	CON EDISON	MAPLE AVE & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST	Lower	1190, 0.225, SSW
AB236	CON EDISON	MAIN ST & MAPLE AVE	NY MANIFEST	Lower	1190, 0.225, SSW
AA237	PREFERRED CLEANERS	95 UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1193, 0.226, West
AK238	CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NY MANIFEST	Lower	1194, 0.226, NE
AK239	CON EDISON MANHOLE 1	HUGEONOT ST & HARRIS	RCRA NonGen / NLR, NJ MANIFEST	Lower	1194, 0.226, NE
AG240	35 CLINTON PLACE LLC	35 CLINTON PLACE	NY AST	Lower	1197, 0.227, ESE
Z241	ALL AMERICAN SPORTS	44 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1204, 0.228, SW
AG242	30 CLINTON PLACE OWN	30 CLINTON PLACE	NY UST, NY AST	Lower	1208, 0.229, ESE
AG243	CO-OP	30 CLINTON PLACE	NY LTANKS	Lower	1208, 0.229, ESE
AG244	CON EDISON	150 NORTH AV	NY MANIFEST	Lower	1210, 0.229, ESE
AG245	CON EDISON SERVICE B	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Lower	1223, 0.232, ESE
AG246	CON EDISON MANHOLE:	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Lower	1223, 0.232, ESE
AL247	NEW ROCHELLE FIRE ST	45 HARRISON STREET	NY UST, NY AST	Lower	1225, 0.232, ENE
AL248	CON EDISON	45 HARRISON ST	NJ MANIFEST	Lower	1225, 0.232, ENE
AL249	CON EDISON	45 HARRISON ST	NY MANIFEST	Lower	1225, 0.232, ENE
AL250	CON EDISON	45 HARRISON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1225, 0.232, ENE
AL251	CITY OF NEW ROCHELLE	45 HARRISON STREET	NY LTANKS	Lower	1225, 0.232, ENE
AA252	100-102 UNION AVENUE	100-102 UNION AVENUE	NY LTANKS	Lower	1229, 0.233, West
AA253	LJNJ ASSOCIATES	100-102 UNION AVE	NY UST	Lower	1229, 0.233, West
AA254	KAGEL HOME	99 UNION AVE	NY LTANKS	Lower	1232, 0.233, West
AL255	CON EDISON	HARRISON ST & CEDER	RCRA NonGen / NLR, FINDS, ECHO	Lower	1232, 0.233, ENE
AL256	CON ED	HARRISON ST & CEDER	NY MANIFEST	Lower	1232, 0.233, ENE
AL257	CON EDISON	HARRISON ST & CEDER	NJ MANIFEST	Lower	1232, 0.233, ENE
AE258	125	CENTRE AVE	NY LTANKS	Higher	1233, 0.234, SSE
AH259	CON EDISON	LOCKWOOD AVE & NORTH	NJ MANIFEST	Lower	1234, 0.234, North
AH260	CON EDISON	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR	Lower	1234, 0.234, North
AH261	CON EDISON TRANSFORM	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR, NY MANIFEST	Lower	1234, 0.234, North
AH262	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1234, 0.234, North
AH263	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1234, 0.234, North
AH264	CON EDISON	LOCKWOOD AVE & NORTH	NY MANIFEST	Lower	1234, 0.234, North
AH265	368 NORTH AVE MGMT C	368 NORTH AVENUE	NY UST	Lower	1237, 0.234, North
AK266	GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NY AST	Lower	1250, 0.237, NE
AK267	LONGINES WITTNAUER W	145 HUGUENOT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1250, 0.237, NE
AK268	GALESI ENTERPRICES	145 HUGUENOT ST	NY LTANKS, NY Spills	Lower	1250, 0.237, NE
AL269	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1251, 0.237, ENE
AL270	CON EDISON	HARRISON ST & FOUNTA	NJ MANIFEST	Lower	1251, 0.237, ENE
AL271	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1251, 0.237, ENE
AL272	CON ED	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1251, 0.237, ENE
AL273	CON EDISON	HARRISON ST & FOUNTA	RCRA NonGen / NLR, FINDS, ECHO	Lower	1251, 0.237, ENE

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL274	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1251, 0.237, ENE
AL275	CON EDISON SERVICE B	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR, NY MANIFEST	Lower	1251, 0.237, ENE
AL276	CON EDISON	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1251, 0.237, ENE
AL277	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1251, 0.237, ENE
AL278	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1251, 0.237, ENE
AL279	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1251, 0.237, ENE
AC280	MONROE COLLEGE	5 FRANKLIN AVE	NY LTANKS	Lower	1252, 0.237, East
AA281	TANK TEST FAILURE	50 WALNUT ST	NY LTANKS	Lower	1265, 0.240, West
AF282	DOMENICO PROCOPIO	618 MAIN STREET	NY UST, NY AST	Lower	1278, 0.242, SSW
AF283	DOMINIC PROCOPIO	618 MAIN ST	NY LTANKS, NY Spills	Lower	1278, 0.242, SSW
AH284	CASANOVA BROS. REALT	370 NORTH AVENUE	NY UST	Lower	1281, 0.243, North
AA285	ROBERTS HOME	58 WALNUT STREET	NY LTANKS	Lower	1283, 0.243, West
AM286	@	60 WALNUT STREET	NY LTANKS	Lower	1289, 0.244, West
AF287	VACANT	399 HUGUENOT STREET	NY UST, NY AST	Lower	1294, 0.245, SSW
AG288	OFF-SITE FLAMINGO CL	149 NORTH AVENUE	NY BROWNFIELDS	Lower	1298, 0.246, ESE
AG289	COLONIAL CLEANERS CO	149 NORTH AVE	RCRA NonGen / NLR	Lower	1298, 0.246, ESE
AG290	FLAMINGO CLEANERS	149 NORTH AVE	RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Lower	1298, 0.246, ESE
AG291	FLAMINGO/TYK CLEANER	149 NORTH AV.	NY DRYCLEANERS	Lower	1298, 0.246, ESE
AE292	BLESSED SACREMENT CH	15 SHEA PL	NY LTANKS	Higher	1301, 0.246, South
AN293	MAY PARTNERS, LLC	35-45 MAY STREET	NY AST	Lower	1309, 0.248, NNW
AL294	FIREHOUSE	HARRISON ST	NY LTANKS	Lower	1333, 0.252, ENE
AK295	BERGMAN REALTY SERVI	140 HUGUENOT STREET	NY LTANKS	Lower	1336, 0.253, NE
AM296	APARTMENT BLDG.	114 UNION AVE.	NY LTANKS, NY Spills	Lower	1395, 0.264, West
AN297	DIMATTOE TTF	55 MAY STREET	NY LTANKS	Lower	1412, 0.267, NNW
298	CITY OF NEW ROCHELLE	1 HARRISON STREET	NY LTANKS	Lower	1415, 0.268, ENE
299	CUMBERLAND FARM	635 MAIN STREET	NY LTANKS, NY Spills	Lower	1418, 0.269, SSW
300	NEW ROCHELLE CATH MI	24 MAPLE AV	NY LTANKS, NY Spills	Lower	1424, 0.270, South
AO301	COMMERCIAL SITE	38 LOCUST AVE	NY LTANKS	Lower	1441, 0.273, ESE
AO302	COMMERCIAL PROPERTY	38 LOCUST AVE	NY LTANKS	Lower	1441, 0.273, ESE
AP303	DEMELIA - TTF	95 WASHINGTON AVE	NY LTANKS	Lower	1453, 0.275, WNW
AQ304	SPILL NUMBER 0208792	386 NORTH AV	NY LTANKS	Lower	1456, 0.276, North
305	RESIDENCE	64 CHURCH ST	NY LTANKS	Lower	1486, 0.281, SE
AR306	CANDREA/GALLETTA RES	35 CHARLES ST	NY LTANKS	Lower	1517, 0.287, WSW
AM307	SPILL NUMBER 0007965	45 CHARLES ST	NY LTANKS	Lower	1530, 0.290, West
AS308	RUSH MFG CORP	10-12 PINE CT	CORRACTS, RCRA-CESQG, NY Spills, FINDS, ECHO, RI...	Lower	1534, 0.291, SW
AS309	GKIDS REALTY	10/12 PINE COURT	NY LTANKS	Lower	1534, 0.291, SW
AP310	BRAM REALTY	105 WASHINGTON AVE	NY LTANKS	Lower	1553, 0.294, WNW
AR311	MERLUCCI RESIDENCE	30 CHARLES STREET	NY LTANKS	Lower	1553, 0.294, WSW
AQ312	KGM PROPERTY ASSOC.	394 N. AVE.	NY LTANKS	Lower	1561, 0.296, North

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AQ313	KGM REALTY CO.	396 NORTH AVE.	NY LTANKS	Lower	1569, 0.297, North
AQ314	GETTY# 677	381 NORTH AVE	NY LTANKS, NY Spills	Lower	1580, 0.299, North
AO315	APT. BUILDING	55-59 LOCUST AVE.	NY LTANKS	Lower	1586, 0.300, ESE
AT316	BLESSED SACRAMENT HS	24 SHEA PLACE	NY LTANKS	Lower	1613, 0.305, South
AT317	BLESSED SACRAMENT HI	24 SHEA PLACE	NY LTANKS	Lower	1614, 0.306, South
AU318	BLESSED SACRAMENT CH	SHEA PLACE	NY LTANKS	Lower	1629, 0.309, SSE
AV319	PROFESSIONAL BUILDIN	421 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	1642, 0.311, SSW
320	FRANKA INC.	132-143 UNION AVE.	NY LTANKS	Lower	1644, 0.311, West
AU321	APARTMENT HOUSE	156-168 CENTRE AVE	NY LTANKS	Lower	1651, 0.313, SSE
AU322	FAILED TANK TEST	156 CENTRE AVE	NY LTANKS	Lower	1651, 0.313, SSE
AQ323	DIPASQUALE PROPERTY	400 NORTH AVE	NY LTANKS	Lower	1681, 0.318, North
AS324	BAKERS PRIDE OVEN CO	30 PINE ST.	RCRA-LQG, NY SHWS, NY Spills, FINDS, ECHO, NJ...	Lower	1691, 0.320, SW
AT325	APT. BUILDING	47 MAPLE AV	NY LTANKS, NY Spills	Lower	1704, 0.323, South
326	SPILL 0106072 / PBS	370 MAIN ST	NY LTANKS	Lower	1707, 0.323, ENE
AW327	COMMERCIAL BUILDING	88-90 GROVE AVE.	NY LTANKS	Lower	1715, 0.325, WSW
AW328	BUSINESS	88 GROVE AVE.	NY LTANKS	Lower	1715, 0.325, WSW
329	ANON	108 VAN GUILDER AVE	NY LTANKS, NY Spills	Lower	1769, 0.335, WNW
AS330	BELIVE HOME	20 PINE STREET	NY LTANKS	Lower	1779, 0.337, SW
331	CON EDISON-CEDAR ST	ONE RAMADA PLAZA	EDR MGP	Lower	1796, 0.340, NE
332	CHURCH OF LATTER DAY	111 NORTH AVE	NY LTANKS	Lower	1799, 0.341, ESE
333	APARTMENT BUILDING	67-70 LOCUST AVE	NY LTANKS	Lower	1823, 0.345, ESE
AV334	SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	NY LTANKS	Lower	1835, 0.348, SSW
335	BUSINESS COMPLEX	55 WEBSTER AVE	NY LTANKS	Lower	1885, 0.357, SW
AX336	APARTMENT BLDG	1 THE BOULEVARD	NY LTANKS	Lower	1902, 0.360, North
AX337	PRIVATE DWELLING	19 ROCHELLE PLACE	NY LTANKS	Lower	1920, 0.364, North
AY338	RESIDENCE	14 REVERE RD	NY LTANKS	Lower	1925, 0.365, NE
339	NEW ROCHELLE RADIOLO	150 LOCKWOOD AV	NY LTANKS, NY Spills	Lower	1931, 0.366, NW
340	NICK MAZZA RESIDENCE	20 DAVIS AVE	NY LTANKS	Lower	1942, 0.368, SE
AZ341	SHERIDEN PLAZA	1 SHERIDEN PLAZA	NY LTANKS	Lower	1957, 0.371, NE
BA342	JASON PARTNERS LTD	675 MAIN ST	NY LTANKS	Lower	1967, 0.373, SSW
BB343	ABANDONED GAS STATIO	197 WEBSTER AV	NY LTANKS	Lower	1989, 0.377, West
AZ344	POST MARINE SUPPLY	65 RIVER ST	NY LTANKS, NY Spills	Lower	2004, 0.380, NE
BC345	GETTY 58114	340 MAIN STREET	NY LTANKS, NY Spills	Lower	2008, 0.380, ENE
AY346	SUNOCO	71 HUGUENOT ST	NY LTANKS, NY Spills	Lower	2019, 0.382, ENE
BA347	6 WEBSTER	6 WEBSTER AVE	NY LTANKS	Lower	2025, 0.384, SSW
BD348	SPILL NUMBER 0314082	136 VANGUILDER AVE	NY LTANKS	Lower	2040, 0.386, WNW
BE349	STEWART DWELLING	100 SICKLES AVE	NY LTANKS, NY Spills	Lower	2049, 0.388, NW
BB350	CITGO WEBSTER FOOD M	210 WEBSTER AVE	NY LTANKS, NY Spills	Lower	2090, 0.396, West
351	SPILL NUMBER 0302495	85 NORTH AVE	NY LTANKS, NY Spills	Lower	2097, 0.397, SE

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BF352	MICELI HOME	194 CENTRE AVE	NY LTANKS	Lower	2098, 0.397, SSE
BC353	JEROME RESIDENCE	33 ECHO AVE	NY LTANKS	Lower	2099, 0.398, ENE
BE354	BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NY LTANKS	Lower	2100, 0.398, NW
BC355	POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	NY LTANKS	Lower	2112, 0.400, ENE
BE356	POINVIL RESIDENCE	107 SICKLES AVE	NY LTANKS	Lower	2115, 0.401, NW
BA357	AMOCO SERVICE STATIO	690 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	2127, 0.403, SSW
BG358	RESIDENCE	10 LAFAYETTE ST	NY LTANKS	Lower	2132, 0.404, ENE
BD359	YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	NY LTANKS	Lower	2133, 0.404, WNW
BH360	COMMERCIAL-TTF	172 UNION AVE	NY LTANKS	Lower	2133, 0.404, West
BE361	TAHIR RESIDENCE	112 SICKLES AVE	NY LTANKS, NY Spills	Lower	2149, 0.407, NW
BC362	DAVENPORT AUTO / WES	44 ECHO AVE	NY LTANKS, NY Spills	Lower	2151, 0.407, ENE
BC363	GAS STATION	44 ECHO AVE	NY LTANKS	Lower	2151, 0.407, ENE
BF364	200 CENTRA CORP	200 CENTER AVE	NY LTANKS	Lower	2174, 0.412, SSE
BC365	CONSOLIDATED EDISON	ECHO AVENUE	NY SHWS	Lower	2179, 0.413, ENE
BH366	FIRST ASSEMBLY OF GO	177 UNION AVE	NY LTANKS	Lower	2186, 0.414, West
367	48 1ST STREET	48 1ST STREET	NY LTANKS	Lower	2193, 0.415, WSW
BG368	GONCALVES RESIDENCE	1 LAFFAYETTE STREET	NY LTANKS	Lower	2197, 0.416, ENE
BG369	GONCALVES RESIDENCE	1 LAFAYETTE STREET	NY LTANKS	Lower	2197, 0.416, ENE
BE370	RESIDENCE	7 PRINCE ST	NY LTANKS	Lower	2200, 0.417, NW
BE371	RENTAL HOUSE	119 SICKLES AVE.	NY LTANKS	Lower	2223, 0.421, NW
BI372	SPILL NUMBER 0104402	30 LINCOLN ST	NY LTANKS	Lower	2249, 0.426, NE
BH373	SPILL NUMBER 0210366	182 UNION AV	NY LTANKS	Lower	2253, 0.427, West
BJ374	PLASTIC WORKS	115 CEDAR ST	NY LTANKS	Lower	2272, 0.430, NNE
BF375	APT. BUILDING	208 CENTER AVE.	NY LTANKS, NY Spills	Lower	2277, 0.431, SSE
BI376	SPILL NUMBER 0300463	52 LINCOLN ST	NY LTANKS, NY Spills	Lower	2282, 0.432, NE
BJ377	I-95 EXIT 16	OPP. 111 CEDAR ST.	NY LTANKS	Lower	2305, 0.437, NNE
BK378	SPILL NUMBER 0009195	17 POPLAR PL	NY LTANKS	Lower	2316, 0.439, SSE
BF379	RESIDENCE	6 POPLAR ROAD	NY LTANKS	Lower	2320, 0.439, SSE
380	LIPMAN RESIDENCE	54 LIBERTY AVE	NY LTANKS	Lower	2333, 0.442, South
BL381	TELEDYNE HYDRA-POWER	310 MAIN ST	NY SWF/LF, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	2336, 0.442, ENE
382	WALTON RESIDENCE	129 SICKLES AVE	NY LTANKS	Lower	2337, 0.443, NW
383	FIUMFREDO RESIDENCE	12 BAYVIEW AVE	NY LTANKS	Lower	2344, 0.444, East
384	WILLIAMS TTF	23 1ST ST	NY LTANKS	Lower	2360, 0.447, WSW
385	RESIDENCE	38 BEECHWOOD AVE	NY LTANKS	Lower	2366, 0.448, SW
BL386	DEFENDER MARINE SUPP	309 MAIN ST	NY LTANKS	Lower	2369, 0.449, ENE
BK387	FUNICELOLO HOME	24 POPLAR PLACE	NY LTANKS	Lower	2375, 0.450, SSE
BK388	LABELLA RESIDENCE	219 CENTRE AVE	NY LTANKS	Lower	2397, 0.454, SSE
389	SPILL NUMBER 0210080	196 UNION AV	NY LTANKS	Lower	2423, 0.459, West
BM390	RESIDENCE	98 LIBERTY AVE	NY LTANKS	Lower	2426, 0.459, South

MAPPED SITES SUMMARY

Target Property Address:
275 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
391	MANONE PLACE	15 COLONIAL PLACE	NY LTANKS	Lower	2441, 0.462, WNW
392	APT BLDG	25 TRINITY PLACE	NY LTANKS	Lower	2463, 0.466, SSE
BN393	SPILL NUMBER 9814027	48 REMINGTON PL	NY LTANKS	Lower	2489, 0.471, NW
394	RITACCO HOME	24 JACKSON STREET	NY LTANKS	Lower	2492, 0.472, NE
395	COMMERICAL BUILIDING	719 MAIN ST	NY LTANKS	Lower	2501, 0.474, SSW
396	CONSOLIDATED EDISON-	ECHO AVE	SEMS-ARCHIVE, RCRA-CESQG, NY Spills, NY MANIFEST	Lower	2506, 0.475, East
BM397	SPILL NUMBER 9803423	106 LIBERTY AV	NY LTANKS	Lower	2546, 0.482, South
398	TTF AT RESIDENCE	68 JACKSON ST	NY LTANKS	Lower	2560, 0.485, NE
BM399	COLLEGE OF NEW ROCHE	103 LIBERTY AVE	NY LTANKS	Lower	2564, 0.486, South
400	CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	NY LTANKS	Lower	2566, 0.486, ESE
BO401	FORMER MANCUSO MARIN	HUNTINGTON PLACE	US BROWNFIELDS	Lower	2571, 0.487, ENE
BM402	BLANCO RESIDENCE	30 LINDEN PLACE	NY LTANKS	Lower	2574, 0.488, South
BO403	NELSTAD MATERIAL COR	40 HUNTINGTON PL	NY LTANKS, NY Spills, NY SPDES	Lower	2574, 0.488, ENE
404	NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	NY SWF/LF	Lower	2583, 0.489, SW
405	NORTH EVARTS	44 NORTH EVARTS AVE	NY LTANKS	Lower	2587, 0.490, SE
BN406	HERNANDEZ - TTF	70 REMINGTON PLACE	NY LTANKS	Lower	2590, 0.491, NW
407	7-UP BOTTLING CO	PALMER AVE & CEDAR S	NY LTANKS	Lower	2590, 0.491, NNE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF UST ---- Major Oil Storage Facilities Database
NY MOSF ---- Major Oil Storage Facility Site Listing
NY MOSF AST ---- Major Oil Storage Facilities Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing
NY ENG CONTROLS ---- Registry of Engineering Controls
NY INST CONTROL ---- Registry of Institutional Controls

State and tribal voluntary cleanup sites

NY VCP ---- Voluntary Cleanup Agreements
INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---- Registered Waste Tire Storage & Facility List
NY SWRCY ---- Registered Recycling Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch

NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON-	***ECHO AVE***	***E 1/4 - 1/2 (0.475 mi.)***	***396***	***702***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSH MFG CORP	***10-12 PINE CT***	***SW 1/4 - 1/2 (0.291 mi.)***	***AS308***	***514***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA)

of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 6 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO	DIVISION ST AND HUGE	S 0 - 1/8 (0.009 mi.)	C12	21
CON EDISON - TRANSFO	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.124 mi.)	O118	174
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CVS PHARMACY #8447	***222 NORTH AVE***	***E 0 - 1/8 (0.099 mi.)***	***H80***	***111***
CON EDISON - MANHOLE	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***J155***	***226***
NYSDEC-SITE 360109 I	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.155 mi.)***	***M174***	***260***
FLAMINGO CLEANERS	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.246 mi.)***	***AG290***	***478***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MONTEFIORE - NEW ROC	***16 GUION PL***	***NW 1/8 - 1/4 (0.217 mi.)***	***AI227***	***366***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 3 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SIMONETTI CLEANERS	***62 CENTRE ST***	***S 0 - 1/8 (0.109 mi.)***	***I93***	***133***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
ERIC S TURNER & CO I	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I87***	***125***
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***N 1/8 - 1/4 (0.212 mi.)***	***AH222***	***350***

EXECUTIVE SUMMARY

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/12/2018 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.155 mi.)***	***M175***	***266***
Site Code: 413917				
Class Code: Significant threat to the public health or environment - action required.				
BAKERS PRIDE OVEN CO	***30 PINE ST.***	***SW 1/4 - 1/2 (0.320 mi.)***	***AS324***	***557***
Site Code: 355304				
CONSOLIDATED EDISON	ECHO AVENUE	ENE 1/4 - 1/2 (0.413 mi.)	BC365	657
Site Code: 56077				

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/08/2017 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELEDYNE HYDRA-POWER	***310 MAIN ST***	***ENE 1/4 - 1/2 (0.442 mi.)***	***BL381***	***678***
NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	SW 1/4 - 1/2 (0.489 mi.)	404	719

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/12/2018 has revealed that there are 161 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VACANT LOT	HUGUENOT ST/DIVISION	SSE 0 - 1/8 (0.031 mi.)	C19	29
Date Closed: 2006-03-15				
Site ID: 356539				
Program Number: 0510542				
SHORELINE OIL	296 HUGENOT ST,REAR	S 0 - 1/8 (0.033 mi.)	C21	31

Date Closed: 1988-04-06 Site ID: 83347 Program Number: 8709425				
LILLIAN VERNON CO. Date Closed: 1995-03-16 Site ID: 201286 Program Number: 9213055	WESTCHESTER PLACE	SSE 0 - 1/8 (0.034 mi.)	C22	32
JONES RESIDENCE Date Closed: 2005-09-11 Site ID: 335236 Program Number: 0410335	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	C29	39
COMM/RESIDENT. PROPE Date Closed: 2005-02-10 Site ID: 119901 Program Number: 9405558	15 DIVISION STREET	SSE 0 - 1/8 (0.089 mi.)	F71	98
APARTMENT BLDG Date Closed: 2005-02-27 Date Closed: 2004-12-10 Site ID: 254563 Site ID: 84302 Program Number: 0206558 Program Number: 0403405	54 CENTRE AVE	SSW 0 - 1/8 (0.092 mi.)	I74	101
COMMERCIAL PROPERTY Date Closed: 2015-04-28 Site ID: 489220 Program Number: 1308480	64 CENTRE AVE	S 0 - 1/8 (0.105 mi.)	I84	121
BLUE GILL REALTY Date Closed: 2004-05-12 Site ID: 94435 Program Number: 0308082	***543 MAIN ST***	***SSE 0 - 1/8 (0.123 mi.)***	***O113***	***167***
COMMERCIAL PROPERTY Date Closed: 2011-06-06 Site ID: 448142 Program Number: 1100723	522 MAIN STREET	SE 1/8 - 1/4 (0.129 mi.)	O128	187
COCO RESIDENCE Date Closed: 2005-01-10 Site ID: 313391 Program Number: 0311339	81 CENTRE AVE	S 1/8 - 1/4 (0.129 mi.)	I130	189
COMMERCIAL BUILDING Date Closed: 1992-03-10 Site ID: 286303 Program Number: 9110835	507 MAIN STREET	SE 1/8 - 1/4 (0.130 mi.)	P132	191
OFFICE BLDG Date Closed: 2006-03-22 Site ID: 355877 Program Number: 0509995	542 MAIN STREET	SSE 1/8 - 1/4 (0.138 mi.)	O146	212
CENTRE-MAIN ASSOCIAT Date Closed: 2004-12-30 Site ID: 149369 Program Number: 0311823	75 - 77 CENTER AVE	S 1/8 - 1/4 (0.152 mi.)	R169	253
CASARRA RESIDENCE	9 BADEAU PL	W 1/8 - 1/4 (0.165 mi.)	U186	285

Date Closed: 2003-02-05 Site ID: 157707 Program Number: 0209171				
NYNEX Date Closed: 1988-07-22 Site ID: 60528 Program Number: 8803234	40 WASHINGTON AVE	WNW 1/8 - 1/4 (0.175 mi.)	V187	286
RESIDENCE Date Closed: 1996-10-24 Site ID: 177416 Program Number: 9609269	18 BADEAU PLACE	WNW 1/8 - 1/4 (0.183 mi.)	U193	295
ST GABRIEL SCHOOL Date Closed: 2003-12-12 Site ID: 314440 Program Number: 0302359	50 WASHINGTON AVE	WNW 1/8 - 1/4 (0.186 mi.)	V196	300
50 WASHINTON AVE Date Closed: 2003-12-23 Site ID: 280324 Program Number: 0305820	50 WASHINTON AVE	WNW 1/8 - 1/4 (0.186 mi.)	V197	301
DIIORGI HOME Date Closed: 2005-08-28 Site ID: 343230 Program Number: 0500295	47 WARREN STREET	W 1/8 - 1/4 (0.189 mi.)	U202	310
NEW ROCHELLE HOSPITA Date Closed: 1991-03-15 Site ID: 136814 Program Number: 9003911	COVION PLACE	NW 1/8 - 1/4 (0.211 mi.)	AI220	348
SOUTH SHORE MED CENT Date Closed: 2006-12-19 Site ID: 358758 Program Number: 0512440	16 GUION PLACE	NW 1/8 - 1/4 (0.217 mi.)	AI224	355
RESIDENCE Date Closed: 2006-03-28 Site ID: 356553 Program Number: 0510555	79 WARREN ST	WNW 1/8 - 1/4 (0.217 mi.)	228	372
125 Date Closed: 2000-05-15 Site ID: 205498 Program Number: 0001835	CENTRE AVE	SSE 1/8 - 1/4 (0.234 mi.)	AE258	424
BLESSED SACREMENT CH Date Closed: 2003-10-03 Site ID: 167332 Program Number: 0204856	15 SHEA PL	S 1/8 - 1/4 (0.246 mi.)	AE292	487

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAIN LIBRARY Date Closed: 1998-03-27 Site ID: 273025 Program Number: 9713843	LAWTON ST	ENE 0 - 1/8 (0.046 mi.)	E30	40
APT BUILDING/LAWTON	41-43 LAWTON ST	E 0 - 1/8 (0.055 mi.)	E43	61

Site ID: 560365 Program Number: 1706064				
LAWTON STREET REALTY Site ID: 532284 Program Number: 1605726	41-43 LAWTON ST	E 0 - 1/8 (0.055 mi.)	E44	62
277 NORTH LLC Date Closed: 2008-12-04 Site ID: 376329 Program Number: 0611648	277 NORTH AVENUE	NNE 0 - 1/8 (0.073 mi.)	G51	68
BUSINESS Date Closed: 2008-12-04 Site ID: 376243 Program Number: 0611580	277 NORTH AVENUE	NNE 0 - 1/8 (0.073 mi.)	G54	73
EAST RIVER SAVINGS B Date Closed: 1991-01-16 Site ID: 271129 Program Number: 8912285	277 NORTH AVE.	NNE 0 - 1/8 (0.073 mi.)	G55	74
NORTH AVE REALITY Date Closed: 1989-11-30 Date Closed: 1999-07-12 Site ID: 68769 Site ID: 68770 Site ID: 68771 Program Number: 8803214 Program Number: 9812584 Program Number: 9812585	5 ANDERSON ST	ENE 0 - 1/8 (0.081 mi.)	H58	79
NEW ROCHELLE PUBLIC Date Closed: 1992-02-06 Site ID: 306853 Program Number: 9111450	MEMORIAL HIGHWAY	E 0 - 1/8 (0.092 mi.)	E72	100
NYNEX LOCATION Date Closed: 1997-10-10 Site ID: 270876 Program Number: 9708146	342 HUEGNOT ST	SSW 0 - 1/8 (0.115 mi.)	I104	156
BARCLAYS BANK OF NY/ Date Closed: 1991-03-25 Site ID: 299548 Program Number: 8905129	491 MAIN ST.	ESE 0 - 1/8 (0.124 mi.)	P123	181
CATHOLIC NEWS PUBLIS Date Closed: 2005-08-28 Site ID: 347516 Program Number: 0503023	210 NORTH AVE	E 1/8 - 1/4 (0.132 mi.)	P137	201
TRUMP PLAZA Date Closed: 2006-03-08 Site ID: 358910 Program Number: 0512575	***175 HUGUENOT STREET***	***NE 1/8 - 1/4 (0.136 mi.)***	***N141***	***205***
NEW ROCHELLE PUBLIC Date Closed: 2002-09-18 Site ID: 492304 Site ID: 306611 Program Number: 1311408	1 LAWTON	ESE 1/8 - 1/4 (0.142 mi.)	P157	231

Program Number: 0201697				
CIOTTI RESIDENCE	***60 GRAND STREET***	***NNW 1/8 - 1/4 (0.143 mi.)***	***L158***	***234***
Date Closed: 2004-10-07 Site ID: 332054 Program Number: 0407555				
GUIDANCE CENTER INC	70 GRAND ST	NNW 1/8 - 1/4 (0.150 mi.)	L167	251
Date Closed: 1997-10-03 Site ID: 77017 Program Number: 9613894				
INDUST OVERALL SERVI	10 BARTELS PLACE	SW 1/8 - 1/4 (0.154 mi.)	M171	255
Date Closed: 2017-03-30 Site ID: 494186 Program Number: 1400928				
RITZCOVAN - TTF	22 BURLING LANE	N 1/8 - 1/4 (0.157 mi.)	183	280
Date Closed: 2016-03-22 Site ID: 514123 Program Number: 1506693				
APT BUILDING	***40 WARREN STREET***	***W 1/8 - 1/4 (0.194 mi.)***	***AA206***	***317***
Date Closed: 2001-12-19 Date Closed: 2009-03-03 Site ID: 150939 Site ID: 409713 Program Number: 0109254 Program Number: 0812107				
CITIZEN	33 GROVE ST	WSW 1/8 - 1/4 (0.202 mi.)	211	329
Date Closed: 1989-11-28 Site ID: 135309 Program Number: 8708588				
THE MALL	MAIN STREET	E 1/8 - 1/4 (0.204 mi.)	AC212	330
Date Closed: 1991-01-04 Site ID: 326514 Program Number: 9010648				
66 MEMORIAL BLVD	66 MEMORIAL BLVD	NNW 1/8 - 1/4 (0.217 mi.)	AD229	373
Date Closed: 2000-10-24 Site ID: 59397 Program Number: 0002907				
CO-OP	30 CLINTON PLACE	ESE 1/8 - 1/4 (0.229 mi.)	AG243	401
Date Closed: 1997-04-15 Site ID: 189169 Program Number: 9504589				
CITY OF NEW ROCHELLE	45 HARRISON STREET	ENE 1/8 - 1/4 (0.232 mi.)	AL251	414
Date Closed: 2006-06-21 Site ID: 360263 Program Number: 0513733				
100-102 UNION AVENUE	100-102 UNION AVENUE	W 1/8 - 1/4 (0.233 mi.)	AA252	416
Date Closed: 1996-11-08 Site ID: 166425 Program Number: 9608199				
KAGEL HOME	99 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AA254	419
Date Closed: 2006-03-09 Site ID: 360201				

Program Number: 0513684				
GALESI ENTERPRICES Date Closed: 1989-06-01 Site ID: 259815 Program Number: 8901038	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.237 mi.)***	***AK268***	***443***
MONROE COLLEGE Date Closed: 2005-03-27 Site ID: 165556 Program Number: 0307536	5 FRANKLIN AVE	E 1/8 - 1/4 (0.237 mi.)	AC280	462
TANK TEST FAILURE Date Closed: 2013-02-05 Site ID: 455637 Program Number: 1107925	50 WALNUT ST	W 1/8 - 1/4 (0.240 mi.)	AA281	464
DOMINIC PROCOPIO Date Closed: 2004-03-30 Site ID: 278454 Program Number: 9809866	***618 MAIN ST***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AF283***	***467***
ROBERTS HOME Date Closed: 2012-08-17 Site ID: 372634 Program Number: 0608623	58 WALNUT STREET	W 1/8 - 1/4 (0.243 mi.)	AA285	470
@ Date Closed: 2005-07-17 Site ID: 346287 Program Number: 0502010	60 WALNUT STREET	W 1/8 - 1/4 (0.244 mi.)	AM286	471
FIREHOUSE Date Closed: 1998-03-27 Site ID: 252028 Program Number: 9713840	HARRISON ST	ENE 1/4 - 1/2 (0.252 mi.)	AL294	490
BERGMAN REALTY SERVI Date Closed: 2007-11-07 Site ID: 350100 Program Number: 0505137	140 HUGUENOT STREET	NE 1/4 - 1/2 (0.253 mi.)	AK295	491
APARTMENT BLDG. Date Closed: 2001-04-06 Date Closed: 1995-02-14 Site ID: 151446 Site ID: 238808 Program Number: 0011198 Program Number: 9414493	***114 UNION AVE.***	***W 1/4 - 1/2 (0.264 mi.)***	***AM296***	***493***
DIMATTOE TTF Date Closed: 2013-08-08 Site ID: 482303 Program Number: 1301890	55 MAY STREET	NNW 1/4 - 1/2 (0.267 mi.)	AN297	496
CITY OF NEW ROCHELLE Date Closed: 2002-09-18 Site ID: 75380 Program Number: 0201696	1 HARRISON STREET	ENE 1/4 - 1/2 (0.268 mi.)	298	497
CUMBERLAND FARM Date Closed: 2005-03-11 Site ID: 140421	***635 MAIN STREET***	***SSW 1/4 - 1/2 (0.269 mi.)***	***299***	***498***

Program Number: 9206930				
NEW ROCHELLE CATH MI Date Closed: 2003-10-03 Site ID: 80066 Program Number: 0204857	***24 MAPLE AV***	***S 1/4 - 1/2 (0.270 mi.)***	***300***	***501***
COMMERCIAL SITE Date Closed: 2005-02-13 Date Closed: 2002-09-26 Site ID: 333366 Site ID: 239569 Program Number: 0408593 Program Number: 0206043	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AO301	504
COMMERCIAL PROPERTY Date Closed: 2013-02-04 Site ID: 476407 Program Number: 1213228	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AO302	506
DEMELIA - TTF Date Closed: 2015-04-14 Site ID: 500408 Program Number: 1406916	95 WASHINGTON AVE	WNW 1/4 - 1/2 (0.275 mi.)	AP303	507
SPILL NUMBER 0208792 Date Closed: 2002-11-26 Site ID: 71430 Program Number: 0208792	386 NORTH AV	N 1/4 - 1/2 (0.276 mi.)	AQ304	509
RESIDENCE Date Closed: 2008-05-01 Site ID: 333255 Program Number: 0408510	64 CHURCH ST	SE 1/4 - 1/2 (0.281 mi.)	305	510
CANDREA/GALLETTA RES Date Closed: 2012-09-13 Site ID: 465083 Program Number: 1202322	35 CHARLES ST	WSW 1/4 - 1/2 (0.287 mi.)	AR306	512
SPILL NUMBER 0007965 Date Closed: 2000-10-26 Site ID: 61314 Program Number: 0007965	45 CHARLES ST	W 1/4 - 1/2 (0.290 mi.)	AM307	513
GKIDS REALTY Date Closed: 2003-12-09 Site ID: 235436 Program Number: 0200337	10/12 PINE COURT	SW 1/4 - 1/2 (0.291 mi.)	AS309	530
BRAM REALTY Date Closed: 2010-02-01 Site ID: 414506 Program Number: 0902464	105 WASHINGTON AVE	WNW 1/4 - 1/2 (0.294 mi.)	AP310	532
MERLUCCI RESIDENCE Date Closed: 2011-11-14 Site ID: 450778 Program Number: 1103221	30 CHARLES STREET	WSW 1/4 - 1/2 (0.294 mi.)	AR311	533
KGM PROPERTY ASSOC. Date Closed: 1993-01-27 Site ID: 69270	394 N. AVE.	N 1/4 - 1/2 (0.296 mi.)	AQ312	534

Program Number: 9202033				
KGM REALTY CO. Date Closed: 1993-01-27 Site ID: 89642 Program Number: 9201744	396 NORTH AVE.	N 1/4 - 1/2 (0.297 mi.)	AQ313	535
GETTY# 677 Date Closed: 2005-01-18 Site ID: 242546 Program Number: 0400912	***381 NORTH AVE***	***N 1/4 - 1/2 (0.299 mi.)***	***AQ314***	***537***
APT. BUILDING Date Closed: 1992-06-26 Site ID: 168647 Program Number: 9200639	55-59 LOCUST AVE.	ESE 1/4 - 1/2 (0.300 mi.)	AO315	544
BLESSED SACRAMENT HS Site ID: 481320 Program Number: 1300960	24 SHEA PLACE	S 1/4 - 1/2 (0.305 mi.)	AT316	545
BLESSED SACRAMENT HI Date Closed: 2004-07-06 Site ID: 249284 Program Number: 0400709	24 SHEA PLACE	S 1/4 - 1/2 (0.306 mi.)	AT317	546
BLESSED SACRAMENT CH Date Closed: 1987-11-20 Site ID: 324974 Program Number: 8704259	SHEA PLACE	SSE 1/4 - 1/2 (0.309 mi.)	AU318	548
PROFESSIONAL BUILDIN Date Closed: 2007-01-29 Site ID: 369299 Program Number: 0606014	***421 HUGUENOT STREET***	***SSW 1/4 - 1/2 (0.311 mi.)***	***AV319***	***549***
FRANKA INC. Date Closed: 1995-11-09 Site ID: 176106 Program Number: 9312205	132-143 UNION AVE.	W 1/4 - 1/2 (0.311 mi.)	320	552
APARTMENT HOUSE Date Closed: 2004-04-22 Site ID: 267104 Program Number: 0312650	156-168 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AU321	553
FAILED TANK TEST Site ID: 488939 Program Number: 1308221	156 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AU322	554
DIPASQUALE PROPERTY Date Closed: 2012-04-26 Site ID: 450672 Program Number: 1103122	400 NORTH AVE	N 1/4 - 1/2 (0.318 mi.)	AQ323	555
APT. BUILDING Date Closed: 1996-06-14 Site ID: 178537 Program Number: 9603128	***47 MAPLE AV***	***S 1/4 - 1/2 (0.323 mi.)***	***AT325***	***568***
SPILL 0106072 / PBS Date Closed: 2001-11-13 Site ID: 133647	370 MAIN ST	ENE 1/4 - 1/2 (0.323 mi.)	326	569

Program Number: 0106072				
COMMERCIAL BUILDING Date Closed: 2010-04-28 Site ID: 113133 Program Number: 9411598	88-90 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AW327	571
BUSINESS Date Closed: 2010-04-28 Site ID: 172950 Program Number: 9411669	88 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AW328	572
ANON Date Closed: 2005-02-12 Site ID: 214235 Program Number: 0308565	***108 VAN GUILDER AVE***	***WNW 1/4 - 1/2 (0.335 mi.)***	***329***	***573***
BELIVE HOME Date Closed: 2005-05-22 Site ID: 343902 Site ID: 339043 Program Number: 0500819 Program Number: 0413182	20 PINE STREET	SW 1/4 - 1/2 (0.337 mi.)	AS330	577
CHURCH OF LATTER DAY Date Closed: 2004-09-21 Site ID: 266466 Program Number: 0403126	111 NORTH AVE	ESE 1/4 - 1/2 (0.341 mi.)	332	579
APARTMENT BUILDING Date Closed: 2011-03-10 Site ID: 441682 Program Number: 1008207	67-70 LOCUST AVE	ESE 1/4 - 1/2 (0.345 mi.)	333	580
SPILL NUMBER 9908602 Date Closed: 2000-09-14 Site ID: 283271 Program Number: 9908602	HUGUENOT ST & SOUTH	SSW 1/4 - 1/2 (0.348 mi.)	AV334	582
BUSINESS COMPLEX Date Closed: 2000-05-11 Site ID: 86196 Program Number: 9912136	55 WEBSTER AVE	SW 1/4 - 1/2 (0.357 mi.)	335	583
APARTMENT BLDG Date Closed: 1999-10-14 Site ID: 303319 Program Number: 9809315	1 THE BOULEVARD	N 1/4 - 1/2 (0.360 mi.)	AX336	584
PRIVATE DWELLING Date Closed: 2008-02-01 Site ID: 387568 Program Number: 0706958	19 ROCHELLE PLACE	N 1/4 - 1/2 (0.364 mi.)	AX337	585
RESIDENCE Date Closed: 1996-12-11 Site ID: 69656 Program Number: 9611129	14 REVERE RD	NE 1/4 - 1/2 (0.365 mi.)	AY338	587
NEW ROCHELLE RADIOLO Date Closed: 2005-03-18 Site ID: 221207 Program Number: 0209497	***150 LOCKWOOD AV***	***NW 1/4 - 1/2 (0.366 mi.)***	***339***	***588***
NICK MAZZA RESIDENCE	20 DAVIS AVE	SE 1/4 - 1/2 (0.368 mi.)	340	590

Date Closed: 2000-04-20 Site ID: 211468 Program Number: 0000532				
SHERIDEN PLAZA Date Closed: 1990-03-07 Site ID: 80178 Program Number: 8909204	1 SHERIDEN PLAZA	NE 1/4 - 1/2 (0.371 mi.)	AZ341	591
JASON PARTNERS LTD Date Closed: 2003-03-26 Site ID: 86967 Program Number: 0211105	675 MAIN ST	SSW 1/4 - 1/2 (0.373 mi.)	BA342	592
ABANDONED GAS STATIO Date Closed: 2001-07-19 Site ID: 231589 Program Number: 9707099	197 WEBSTER AV	W 1/4 - 1/2 (0.377 mi.)	BB343	593
POST MARINE SUPPLY Date Closed: 1988-02-18 Site ID: 286036 Site ID: 286037 Program Number: 8707334 Program Number: 8708530	***65 RIVER ST***	***NE 1/4 - 1/2 (0.380 mi.)***	***AZ344***	***595***
GETTY 58114 Date Closed: 2010-04-29 Site ID: 426673 Program Number: 0913713	***340 MAIN STREET***	***ENE 1/4 - 1/2 (0.380 mi.)***	***BC345***	***599***
SUNOCO Date Closed: 1996-07-26 Site ID: 255332 Program Number: 9514850	***71 HUGUENOT ST***	***ENE 1/4 - 1/2 (0.382 mi.)***	***AY346***	***608***
6 WEBSTER Date Closed: 2004-10-08 Site ID: 81655 Program Number: 0403816	6 WEBSTER AVE	SSW 1/4 - 1/2 (0.384 mi.)	BA347	610
SPILL NUMBER 0314082 Date Closed: 2004-06-08 Site ID: 80232 Program Number: 0314082	136 VANGUILDER AVE	WNW 1/4 - 1/2 (0.386 mi.)	BD348	612
STEWART DWELLING Date Closed: 2012-08-13 Site ID: 462885 Program Number: 1200264	***100 SICKLES AVE***	***NW 1/4 - 1/2 (0.388 mi.)***	***BE349***	***613***
CITGO WEBSTER FOOD M Date Closed: 2017-04-06 Site ID: 492314 Program Number: 1311416	***210 WEBSTER AVE***	***W 1/4 - 1/2 (0.396 mi.)***	***BB350***	***616***
SPILL NUMBER 0302495 Date Closed: 2003-08-12 Date Closed: 2009-10-09 Site ID: 114935 Site ID: 353132 Program Number: 0302495	***85 NORTH AVE***	***SE 1/4 - 1/2 (0.397 mi.)***	***351***	***622***

Program Number: 0507677				
MICELI HOME Date Closed: 2006-10-22 Site ID: 366997 Program Number: 0604103	194 CENTRE AVE	SSE 1/4 - 1/2 (0.397 mi.)	BF352	625
JEROME RESIDENCE Date Closed: 2005-02-13 Site ID: 235222 Program Number: 0405389	33 ECHO AVE	ENE 1/4 - 1/2 (0.398 mi.)	BC353	626
BRIEN-AMIE RESIDENCE Date Closed: 2004-02-02 Site ID: 219644 Program Number: 0304963	105 SICKLES AVE	NW 1/4 - 1/2 (0.398 mi.)	BE354	628
POWERTEST,ECHO & MAI Date Closed: 1988-02-11 Site ID: 283199 Program Number: 8709260	36 ECHO AVE @ MAIN S	ENE 1/4 - 1/2 (0.400 mi.)	BC355	629
POINVIL RESIDENCE Date Closed: 2014-11-05 Site ID: 452458 Program Number: 1104844	107 SICKLES AVE	NW 1/4 - 1/2 (0.401 mi.)	BE356	630
AMOCO SERVICE STATIO Date Closed: 2002-12-16 Date Closed: 2003-04-01 Date Closed: 1987-01-14 Site ID: 274754 Site ID: 274755 Site ID: 274757 Program Number: 0209490 Program Number: 0212950 Program Number: 8604411	***690 MAIN ST***	***SSW 1/4 - 1/2 (0.403 mi.)***	***BA357***	***631***
RESIDENCE Date Closed: 2006-03-15 Site ID: 358990 Program Number: 0512638	10 LAFAYETTE ST	ENE 1/4 - 1/2 (0.404 mi.)	BG358	643
YOUNG ADULT INSTITUT Date Closed: 2005-12-18 Site ID: 353295 Program Number: 0507808	150 VAN GUILDER AVE	WNW 1/4 - 1/2 (0.404 mi.)	BD359	644
COMMERCIAL-TTF Site ID: 508618 Program Number: 1502358	172 UNION AVE	W 1/4 - 1/2 (0.404 mi.)	BH360	645
TAHIR RESIDENCE Date Closed: 2007-10-24 Site ID: 374522 Program Number: 0610140	***112 SICKLES AVE***	***NW 1/4 - 1/2 (0.407 mi.)***	***BE361***	***646***
DAVENPORT AUTO / WES Date Closed: 2010-11-01 Date Closed: 1995-02-09 Date Closed: 2006-02-17 Site ID: 434525	***44 ECHO AVE***	***ENE 1/4 - 1/2 (0.407 mi.)***	***BC362***	***649***

Site ID: 130489 Site ID: 130487 Program Number: 1001469 Program Number: 9210810 Program Number: 9201557				
GAS STATION Date Closed: 2014-02-13 Site ID: 490405 Program Number: 1309599	44 ECHO AVE	ENE 1/4 - 1/2 (0.407 mi.)	BC363	654
200 CENTRA CORP Date Closed: 2007-12-12 Site ID: 367663 Program Number: 0604650	200 CENTER AVE	SSE 1/4 - 1/2 (0.412 mi.)	BF364	656
FIRST ASSEMBLY OF GO Date Closed: 2010-08-30 Site ID: 435290 Program Number: 1002183	177 UNION AVE	W 1/4 - 1/2 (0.414 mi.)	BH366	659
48 1ST STREET Date Closed: 1999-12-22 Site ID: 116893 Program Number: 9911183	48 1ST STREET	WSW 1/4 - 1/2 (0.415 mi.)	367	660
GONCALVES RESIDENCE Date Closed: 1994-11-29 Site ID: 156301 Program Number: 9410991	1 LAFFAYETTE STREET	ENE 1/4 - 1/2 (0.416 mi.)	BG368	661
GONCALVES RESIDENCE Date Closed: 2007-01-10 Site ID: 373629 Program Number: 0609401	1 LAFAYETTE STREET	ENE 1/4 - 1/2 (0.416 mi.)	BG369	662
RESIDENCE Date Closed: 2005-10-29 Site ID: 351640 Program Number: 0506424	7 PRINCE ST	NW 1/4 - 1/2 (0.417 mi.)	BE370	663
RENTAL HOUSE Date Closed: 1991-11-25 Site ID: 119461 Program Number: 9107320	119 SICKLES AVE.	NW 1/4 - 1/2 (0.421 mi.)	BE371	664
SPILL NUMBER 0104402 Date Closed: 2001-11-14 Site ID: 328750 Program Number: 0104402	30 LINCOLN ST	NE 1/4 - 1/2 (0.426 mi.)	BI372	665
SPILL NUMBER 0210366 Date Closed: 2003-03-03 Site ID: 282696 Program Number: 0210366	182 UNION AV	W 1/4 - 1/2 (0.427 mi.)	BH373	666
PLASTIC WORKS Date Closed: 1999-02-22 Site ID: 163894 Program Number: 9812998	115 CEDAR ST	NNE 1/4 - 1/2 (0.430 mi.)	BJ374	668
APT. BUILDING Date Closed: 1994-03-11	***208 CENTER AVE.***	***SSE 1/4 - 1/2 (0.431 mi.)***	***BF375***	***669***

Date Closed: 1994-04-11 Site ID: 215702 Site ID: 215703 Program Number: 9314003 Program Number: 9315255				
SPILL NUMBER 0300463 Date Closed: 2003-04-14 Site ID: 202585 Program Number: 0300463	***52 LINCOLN ST***	***NE 1/4 - 1/2 (0.432 mi.)***	***BI376***	***671***
I-95 EXIT 16 Date Closed: 1990-08-01 Site ID: 244221 Program Number: 9001240	OPP. 111 CEDAR ST.	NNE 1/4 - 1/2 (0.437 mi.)	BJ377	673
SPILL NUMBER 0009195 Date Closed: 2001-01-08 Site ID: 63217 Program Number: 0009195	17 POPLAR PL	SSE 1/4 - 1/2 (0.439 mi.)	BK378	674
RESIDENCE Date Closed: 2012-08-13 Site ID: 82997 Program Number: 0310014	6 POPLAR ROAD	SSE 1/4 - 1/2 (0.439 mi.)	BF379	676
LIPMAN RESIDENCE Date Closed: 2005-04-02 Site ID: 333699 Program Number: 0409061	54 LIBERTY AVE	S 1/4 - 1/2 (0.442 mi.)	380	677
WALTON RESIDENCE Date Closed: 2007-08-28 Site ID: 383296 Program Number: 0703375	129 SICKLES AVE	NW 1/4 - 1/2 (0.443 mi.)	382	684
FIUMFREDO RESIDENCE Date Closed: 2011-09-22 Site ID: 447470 Program Number: 1100096	12 BAYVIEW AVE	E 1/4 - 1/2 (0.444 mi.)	383	686
WILLIAMS TTF Date Closed: 1999-06-10 Site ID: 102476 Program Number: 9702187	23 1ST ST	WSW 1/4 - 1/2 (0.447 mi.)	384	687
RESIDENCE Date Closed: 1997-11-10 Site ID: 105369 Program Number: 9705244	38 BEECHWOOD AVE	SW 1/4 - 1/2 (0.448 mi.)	385	688
DEFENDER MARINE SUPP Date Closed: 2002-09-19 Site ID: 93459 Program Number: 9806235	309 MAIN ST	ENE 1/4 - 1/2 (0.449 mi.)	BL386	690
FUNICELOLO HOME Date Closed: 2006-11-19 Site ID: 355533 Program Number: 0509719	24 POPLAR PLACE	SSE 1/4 - 1/2 (0.450 mi.)	BK387	691
LABELLA RESIDENCE Date Closed: 2009-09-01	219 CENTRE AVE	SSE 1/4 - 1/2 (0.454 mi.)	BK388	692

Site ID: 364328 Program Number: 0601959				
SPILL NUMBER 0210080 Date Closed: 2003-03-03 Site ID: 155360 Program Number: 0210080	196 UNION AV	W 1/4 - 1/2 (0.459 mi.)	389	693
RESIDENCE Date Closed: 2002-01-11 Site ID: 204562 Program Number: 0107187	98 LIBERTY AVE	S 1/4 - 1/2 (0.459 mi.)	BM390	694
MANONE PLACE Date Closed: 2006-05-08 Site ID: 359413 Program Number: 0513004	15 COLONIAL PLACE	WNW 1/4 - 1/2 (0.462 mi.)	391	696
APT BLDG Date Closed: 1992-07-30 Date Closed: 2009-04-22 Site ID: 283512 Site ID: 409448 Program Number: 8905211 Program Number: 0811859	25 TRINITY PLACE	SSE 1/4 - 1/2 (0.466 mi.)	392	697
SPILL NUMBER 9814027 Date Closed: 1999-02-19 Site ID: 80830 Program Number: 9814027	48 REMINGTON PL	NW 1/4 - 1/2 (0.471 mi.)	BN393	699
RITACCO HOME Date Closed: 2006-07-28 Site ID: 362141 Program Number: 0600187	24 JACKSON STREET	NE 1/4 - 1/2 (0.472 mi.)	394	700
COMMERICAL BUILIDING Date Closed: 2004-10-28 Site ID: 301693 Program Number: 0404182	719 MAIN ST	SSW 1/4 - 1/2 (0.474 mi.)	395	701
SPILL NUMBER 9803423 Date Closed: 1998-08-18 Site ID: 140786 Program Number: 9803423	106 LIBERTY AV	S 1/4 - 1/2 (0.482 mi.)	BM397	707
TTF AT RESIDENCE Date Closed: 2008-03-26 Site ID: 388761 Program Number: 0707955	68 JACKSON ST	NE 1/4 - 1/2 (0.485 mi.)	398	708
COLLEGE OF NEW ROCHE Date Closed: 2005-04-17 Site ID: 118985 Program Number: 9809357	103 LIBERTY AVE	S 1/4 - 1/2 (0.486 mi.)	BM399	709
CIUSSETELLI RESIDENC Date Closed: 2010-07-13 Site ID: 161898 Program Number: 0204230	4 FAIRVIEW PLACE	ESE 1/4 - 1/2 (0.486 mi.)	400	711
BLANCO RESIDENCE Date Closed: 1998-07-30	30 LINDEN PLACE	S 1/4 - 1/2 (0.488 mi.)	BM402	715

Site ID: 227988 Program Number: 9802704				
NELSTAD MATERIAL COR Date Closed: 2004-05-03 Site ID: 200280 Program Number: 0208898	***40 HUNTINGTON PL***	***ENE 1/4 - 1/2 (0.488 mi.)***	***BO403***	***716***
NORTH EVARTS Date Closed: 2005-02-26 Site ID: 74554 Program Number: 9913333	44 NORTH EVARTS AVE	SE 1/4 - 1/2 (0.490 mi.)	405	720
HERNANDEZ - TTF Date Closed: 2015-06-16 Site ID: 505764 Program Number: 1411959	70 REMINGTON PLACE	NW 1/4 - 1/2 (0.491 mi.)	BN406	721
7-UP BOTTLING CO Date Closed: 1999-08-02 Site ID: 60684 Program Number: 9302874	PALMER AVE & CEDAR S	NNE 1/4 - 1/2 (0.491 mi.)	407	722

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 41 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AVALON ON THE SOUND Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated: <1101 gal. PBS Id/Status:: 3-800626 Status: 3. Closed - Removed	HUGUENOT STREET AND	SE 0 - 1/8 (0.022 mi.)	C18	28
NEW ROCHELLE IRISH B Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated Id/Status:: 3-600097 Status: 3. Closed - Removed	38 DIVISION STREET	SSE 0 - 1/8 (0.039 mi.)	C24	35
TRINITY-ST. PAUL'S E Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated: <1101 gal. PBS Id/Status:: 3-801006 Status: 4. Closed - in place	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	C28	38
CERUSSI AND VERE Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Administratively Closed Id/Status:: 3-078360 Status: 0. Administratively closed	306 HUGUENOT ST	S 0 - 1/8 (0.050 mi.)	C40	59
SEASONWEIN MANAGEMEN Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018	54 CENTRE AVENUE	SSW 0 - 1/8 (0.092 mi.)	I73	101

Site Status: Active
Id/Status:: 3-169773
Status: 1. In-Service

RPM REALTY INC 9-15 DIVISION STREET SSE 0 - 1/8 (0.103 mi.) F82 119
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-166189
Status: 3. Closed - Removed

M.J. HACKER & SONS I 64 CENTRE AVE S 0 - 1/8 (0.105 mi.) I86 123
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated
Id/Status:: 3-137979
Status: 3. Closed - Removed
Status: 8. Unregistered
Status: 3a. Closed - Prior to 04/1991

LILLIAN VERNON CORPO 543-549 MAIN STREET SSE 0 - 1/8 (0.123 mi.) O112 167
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-600279
Status: 3. Closed - Removed

543 MAIN STREET 543 MAIN STREET SSE 0 - 1/8 (0.123 mi.) O114 170
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-801106
Status: 3. Closed - Removed

75 CENTRE AVENUE LLC 75 CENTRE AVENUE S 1/8 - 1/4 (0.125 mi.) I124 183
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-800240
Status: 3. Closed - Removed

542 MAIN STREET LLC 542 MAIN STREET SSE 1/8 - 1/4 (0.138 mi.) O145 211
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-800617
Status: 1. In-Service

BLOOMINGDALE PARKING 554 MAIN ST SSE 1/8 - 1/4 (0.139 mi.) R149 217
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-600330
Status: 4. Closed - in place

MISR REALTY, LLC 573-579 MAIN STREET S 1/8 - 1/4 (0.153 mi.) R170 254
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-800238
Status: 3. Closed - Removed

SAINT GABRIEL HIGH S 50 WASHINGTON AVENUE WNW 1/8 - 1/4 (0.186 mi.) V195 299
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-058122
Status: 3. Closed - Removed
Status: 1. In-Service

MONTEFIORE - NEW ROC 16 GUION PLACE NW 1/8 - 1/4 (0.217 mi.) AI226 359
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018

Site Status: Active
Id/Status:: 3-123269
Status: 1. In-Service
Status: 3. Closed - Removed
Status: 4. Closed - in place

Lower Elevation	Address	Direction / Distance	Map ID	Page
KAUFMAN HUGUENOT COM	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D42***	***60***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Active Id/Status:: 3-183776 Status: 4. Closed - in place				
LAWTON STREET REALTY	41-43 LAWTON STREET	E 0 - 1/8 (0.055 mi.)	E46	64
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Active Id/Status:: 3-801435 Status: 1. In-Service				
NORTH BROOK REALTY A	270 NORTH AVENUE, SU	NNE 0 - 1/8 (0.063 mi.)	G50	67
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Active Id/Status:: 3-600117 Status: 1. In-Service				
277 NORTH LLC	277 NORTH AVENUE	NNE 0 - 1/8 (0.073 mi.)	G53	71
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Active Id/Status:: 3-502049 Status: 1. In-Service Status: 3. Closed - Removed				
ANDERSON DEVELOPMENT	5 ANDERSON STREET	ENE 0 - 1/8 (0.081 mi.)	H57	78
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated Id/Status:: 3-185515 Status: 3. Closed - Removed				
DELUXE TAXI	10 STATION PLAZA	N 0 - 1/8 (0.101 mi.)	J81	117
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Database: UST, Date of Government Version: 12/22/2017 Site Status: Unregulated: <1101 gal. PBS Id/Status:: 3-600004 Status: 3. Closed - Removed				
DEPOT PLACE LLC	1 DEPOT PLACE	NNW 0 - 1/8 (0.106 mi.)	L90	131
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated: <1101 gal. PBS Id/Status:: 3-801085 Status: 4. Closed - in place				
SPOKEN ARTS BUILDING	310 NORTH AVENUE	N 0 - 1/8 (0.115 mi.)	J106	160
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018 Site Status: Unregulated: <1101 gal. PBS Id/Status:: 3-600705 Status: 3. Closed - Removed				
NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	N 0 - 1/8 (0.118 mi.)	J107	161
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018				

Site Status: Active
Id/Status:: 3-496928
Status: 1. In-Service

J P MORGAN CHASE BAN ***491 MAIN STREET*** ***ESE 0 - 1/8 (0.124 mi.)*** ***P122*** ***180***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-164372
Status: 4. Closed - in place

4 STORY APARTMENT BU 320 NORTH AVENUE N 1/8 - 1/4 (0.128 mi.) J127 186
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-600732
Status: 3. Closed - Removed

MAISON 347 LLC 347 HUGUENOT STREET SSW 1/8 - 1/4 (0.129 mi.) I129 188
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-502626
Status: 1. In-Service

NEW ROCHELLE PUBLIC ONE LIBRARY PLAZA ESE 1/8 - 1/4 (0.138 mi.) P147 213
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-601216
Status: 1. In-Service

BARON MANAGEMENT 200 NORTH AVENUE E 1/8 - 1/4 (0.139 mi.) P150 217
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Administratively Closed
Id/Status:: 3-167843
Status: 0. Administratively closed

RETTNER MANAGEMENT C 481 MAIN ST ESE 1/8 - 1/4 (0.154 mi.) P172 257
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-255033
Status: 0. Administratively closed
Status: 1. In-Service

INDUSTRIAL OVERALL S 10 BARTELLS PLACE SW 1/8 - 1/4 (0.155 mi.) M176 271
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated
Id/Status:: 3-025453
Status: 0. Administratively closed
Status: 3. Closed - Removed

STORAGE USA 363 HUGUENOT STREET SSW 1/8 - 1/4 (0.164 mi.) S185 284
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Administratively Closed
Id/Status:: 3-801137
Status: 3. Closed - Removed

DRIVE IT YOURSELF 20 GARDEN STREET NNE 1/8 - 1/4 (0.176 mi.) W188 287
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated
Id/Status:: 3-494380
Status: 3. Closed - Removed

175 MEMORIAL HWY. RE 175 MEMORIAL HWY. NNW 1/8 - 1/4 (0.205 mi.) AD213 332
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018

Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-800711
Status: 4. Closed - in place

30 CLINTON PLACE OWN ***30 CLINTON PLACE*** ***ESE 1/8 - 1/4 (0.229 mi.)*** ***AG242*** ***399***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-078727
Status: 3. Closed - Removed

NEW ROCHELLE FIRE ST ***45 HARRISON STREET*** ***ENE 1/8 - 1/4 (0.232 mi.)*** ***AL247*** ***408***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Active
Id/Status:: 3-600407
Status: 1. In-Service
Status: 3. Closed - Removed

LJNJ ASSOCIATES 100-102 UNION AVE W 1/8 - 1/4 (0.233 mi.) AA253 417
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-601056
Status: 0. Administratively closed
Status: 3. Closed - Removed

368 NORTH AVE MGMT C 368 NORTH AVENUE N 1/8 - 1/4 (0.234 mi.) AH265 437
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-600272
Status: 3. Closed - Removed

DOMENICO PROCOPIO ***618 MAIN STREET*** ***SSW 1/8 - 1/4 (0.242 mi.)*** ***AF282*** ***465***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-800233
Status: 3. Closed - Removed

CASANOVA BROS. REALT 370 NORTH AVENUE N 1/8 - 1/4 (0.243 mi.) AH284 469
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated: <1101 gal. PBS
Id/Status:: 3-800088
Status: 4. Closed - in place

VACANT ***399 HUGUENOT STREET*** ***SSW 1/8 - 1/4 (0.245 mi.)*** ***AF287*** ***472***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/05/2018
Site Status: Unregulated
Id/Status:: 3-801616
Status: 3. Closed - Removed
Status: 4. Closed - in place

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 12/22/2017 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.155 mi.)***	***M175***	***266***

Facility Status: Unregulated/Closed
CBS Number: 3-000235

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 20 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
306 HUGUENOT STREET	306 HUGUENOT STREET	S 0 - 1/8 (0.050 mi.)	C39	58
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service PBS Number: 3-800236				
RPM REALTY INC	9-15 DIVISION STREET	SSE 0 - 1/8 (0.103 mi.)	F83	120
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service PBS Number: 3-166189				
75 CENTRE AVENUE LLC	***75 CENTRE AVENUE***	***S 1/8 - 1/4 (0.125 mi.)***	***I124***	***183***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service PBS Number: 3-800240				
NEW ROCHELLE SUPERMA	538 MAIN STREET	SSE 1/8 - 1/4 (0.146 mi.)	O161	239
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 3. Closed - Removed PBS Number: 3-166995				
MISR REALTY, LLC	573-579 MAIN STREET	S 1/8 - 1/4 (0.150 mi.)	R168	252
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service PBS Number: 3-800238				
MONTEFIORE - NEW ROC	***16 GUION PLACE***	***NW 1/8 - 1/4 (0.217 mi.)***	***AI226***	***359***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service Status: 3. Closed - Removed PBS Number: 3-123269				

Lower Elevation	Address	Direction / Distance	Map ID	Page
KAUFMAN HUGUENOT COM	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D42***	***60***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 1. In-Service PBS Number: 3-183776				
ANDERSON DEVELOPMENT	5 ANDERSON STREET	ENE 0 - 1/8 (0.081 mi.)	H59	83
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 6. Closed - Work Permit Open PBS Number: 3-185515				
MKM EQUITY, LLC	230 NORTH AVENUE	ENE 0 - 1/8 (0.084 mi.)	E67	94
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018 Status: 3. Closed - Removed PBS Number: 3-600105				
J P MORGAN CHASE BAN	***491 MAIN STREET***	***ESE 0 - 1/8 (0.124 mi.)***	***P122***	***180***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018				

Status: 1. In-Service
PBS Number: 3-164372

587 MAIN STREET | 348 HUGUENOT STREET | SSW 1/8 - 1/4 (0.137 mi.) | I142 | 208
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 3. Closed - Removed
PBS Number: 3-802131

MAYCO, LLC | 18-20 MAY ST | NNW 1/8 - 1/4 (0.212 mi.) | AH221 | 349
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 1. In-Service
PBS Number: 3-175447

MONROE COLLEGE | 420 MAIN STREET | E 1/8 - 1/4 (0.223 mi.) | AC233 | 380
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 0. Administratively closed
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-800251

35 CLINTON PLACE LLC | 35 CLINTON PLACE | ESE 1/8 - 1/4 (0.227 mi.) | AG240 | 395
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 1. In-Service
PBS Number: 3-078646

30 CLINTON PLACE OWN | 30 CLINTON PLACE | ESE 1/8 - 1/4 (0.229 mi.) | AG242 | 399
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 4. Closed - in place
Status: 1. In-Service
PBS Number: 3-078727

NEW ROCHELLE FIRE ST | 45 HARRISON STREET | ENE 1/8 - 1/4 (0.232 mi.) | AL247 | 408
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 1. In-Service
PBS Number: 3-600407

GHP 145 HUGUENOT DEL | 145 HUGUENOT STREET | NE 1/8 - 1/4 (0.237 mi.) | AK266 | 438
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 1. In-Service
PBS Number: 3-497436

DOMENICO PROCOPIO | 618 MAIN STREET | SSW 1/8 - 1/4 (0.242 mi.) | AF282 | 465
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 0. Administratively closed
PBS Number: 3-800233

VACANT | 399 HUGUENOT STREET | SSW 1/8 - 1/4 (0.245 mi.) | AF287 | 472
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 3. Closed - Removed
PBS Number: 3-801616

MAY PARTNERS, LLC | 35-45 MAY STREET | NNW 1/8 - 1/4 (0.248 mi.) | AN293 | 489
Database: WESTCHESTER CO. AST, Date of Government Version: 01/05/2018
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-600544

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	10 BARTELS PLACE	SW 1/8 - 1/4 (0.155 mi.)	M177	272

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/12/2018 has revealed that there are 4 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
THE HUGUENOT Site Code: 544502	381-393 HUGUENOT STR	SSW 1/8 - 1/4 (0.207 mi.)	AF217	338
SCHMUCKLER'S DRY CLE Site Code: 357446	358-364 NORTH AVENUE	N 1/8 - 1/4 (0.209 mi.)	AH219	342
OFF-SITE FLAMINGO CL Site Code: 414661	149 NORTH AVENUE	ESE 1/8 - 1/4 (0.246 mi.)	AG288	475
FLAMINGO CLEANERS Site Code: 335220	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.246 mi.)***	***AG290***	***478***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 01/19/2018 has revealed that there is 1 US BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER MANCUSO MARIN	HUNTINGTON PLACE	ENE 1/4 - 1/2 (0.487 mi.)	BO401	712

EXECUTIVE SUMMARY

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/12/2018 has revealed that there are 22 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Date Closed: 2010-05-04 Spill Number: 0810056 Site ID: 407567	129 DIVISON ST	S 0 - 1/8 (0.006 mi.)	C4	9
UST Date Closed: 2000-04-04 Spill Number: 9912617 Site ID: 254637	MEMORIAL HIGHWAY AND	ENE 0 - 1/8 (0.007 mi.)	B5	10
ROAD Date Closed: 2006-09-03 Spill Number: 0606187 Site ID: 369495	HUGUENOT ST/DIVISION	SSE 0 - 1/8 (0.031 mi.)	C20	30
CABLE Date Closed: 2008-07-30 Spill Number: 0804961 Site ID: 401965	29 DIVISION STREET	SSE 0 - 1/8 (0.057 mi.)	F48	66
CON EDISON Date Closed: 2008-08-16 Spill Number: 0804960 Site ID: 401964	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.080 mi.)***	***F56***	***75***
CEMENT COURT YARD Date Closed: 2002-07-15 Date Closed: 1999-10-04 Spill Number: 9804849 Spill Number: 9908117 Site ID: 114515 Site ID: 114516	54 CENTER AVE	SSW 0 - 1/8 (0.092 mi.)	I75	104
SIDNEY FURNITURE Date Closed: 2015-12-04 Spill Number: 1509029 Site ID: 517634	535 MAIN ST	SSE 0 - 1/8 (0.120 mi.)	O109	162
535 MAIN ST ASSOCIAT Date Closed: 1995-03-03 Date Closed: 1999-07-09 Spill Number: 9415294 Spill Number: 9900400 Site ID: 251083 Site ID: 81102	535 MAIN STREET	SSE 0 - 1/8 (0.120 mi.)	O110	163
BLUE GILL REALTY Date Closed: 2004-05-12 Spill Number: 9212475	***543 MAIN ST***	***SSE 0 - 1/8 (0.123 mi.)***	***O113***	***167***

EXECUTIVE SUMMARY

Site ID: 125220

Lower Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING Date Closed: 1991-05-07 Spill Number: 9009493 Site ID: 220275	8-10 RAILROAD PLACE	0 - 1/8 (0.000 mi.)	A1	8
METRO NORTH TRACKS Date Closed: 2004-07-16 Spill Number: 0308130 Site ID: 279322	EAST OF NEW ROCHELLE	NNW 0 - 1/8 (0.009 mi.)	B14	24
METRO NORTH TRAIN ST Date Closed: 1989-07-19 Spill Number: 8903573 Site ID: 104107	NEW HAVEN LINE &R/R	NNW 0 - 1/8 (0.009 mi.)	B15	25
MH1204 Date Closed: 2000-02-14 Spill Number: 9912755 Site ID: 262084	HUGUENOT AVE/LAWTON	ENE 0 - 1/8 (0.019 mi.)	A17	27
HUGUENOT AND NORTH A Date Closed: 2005-03-05 Spill Number: 0310260 Site ID: 313618	HUGUENOT AND NORTH A	NE 0 - 1/8 (0.046 mi.)	D33	49
SPILL NUMBER 9803949 Date Closed: 1998-06-29 Spill Number: 9803949 Site ID: 166821	MILEPOST 5.5 SB I95	WNW 0 - 1/8 (0.049 mi.)	37	54
PAVEMENT Date Closed: 2012-07-23 Spill Number: 1203965 Site ID: 466814	41 LAWTON STREET	E 0 - 1/8 (0.055 mi.)	E45	63
CONCRETE FLOORING WI Spill Number: 1400277 Site ID: 493512	230 NORTH AVENUE	ENE 0 - 1/8 (0.084 mi.)	E66	92
I-95 Date Closed: 1987-04-07 Spill Number: 8700158 Site ID: 121121	I-95EB MP54	WSW 0 - 1/8 (0.106 mi.)	K88	129
P&D TRANSPORT - HOT Date Closed: 2003-11-26 Spill Number: 0308809 Site ID: 329742	I-95 NB @ MM 5.4	WSW 0 - 1/8 (0.106 mi.)	K89	130
VERIZON Date Closed: 2005-09-11 Spill Number: 0413326 Site ID: 342403	342 HUGUENOT ST	SSW 0 - 1/8 (0.115 mi.)	I103	155
APPAREL PLUS Date Closed: 2014-01-14 Spill Number: 1309988 Site ID: 490810	27 CENTRE AVE	SW 0 - 1/8 (0.118 mi.)	M108	161
COMMERCIAL - UST	35 GRAND STREET	NNW 0 - 1/8 (0.121 mi.)	L111	165

EXECUTIVE SUMMARY

Spill Number: 1706607
Site ID: 560927

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/11/2017 has revealed that there are 76 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE:	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.009 mi.)***	***C9***	***16***
CON EDISON TRANSFORM	DIVISION ST & HUGUEN	S 0 - 1/8 (0.009 mi.)	C13	23
NYSDOT BIN 1049890	DIVISION ST OVER MET	SSE 0 - 1/8 (0.010 mi.)	C16	26
CON EDISON	HUGUENOT ST & CENTRE	SSW 0 - 1/8 (0.098 mi.)	I79	110
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O133***	***192***
CON EDISON MANHOLE:	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O134***	***195***
CON EDISON TRANSFORM	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O136***	***198***
CON EDISON	***552 MAIN ST***	***SSE 1/8 - 1/4 (0.137 mi.)***	***O144***	***210***
CON EDISON	565 MAIN ST	S 1/8 - 1/4 (0.143 mi.)	R160	238
CON EDISON	***CENTRE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R180***	***275***
CON EDISON TRANSFORM	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R181***	***276***
ROTH CLEANERS	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***X189***	***288***
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AB210***	***327***
CON EDISON SERVICE B	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AE214***	***333***
CON EDISON SERVICE B	***CENTRE AVE & LEROY***	***S 1/8 - 1/4 (0.205 mi.)***	***AE216***	***336***
PREFERRED CLEANERS	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AA237***	***388***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1091390	DIVISION ST OVER I 9	NW 0 - 1/8 (0.036 mi.)	B23	33
CON EDISON	***260 NORTH AVE***	***NE 0 - 1/8 (0.042 mi.)***	***D26***	***37***
ACCESSOCRAFT PRODUCT	***48 LAWTON ST***	***E 0 - 1/8 (0.046 mi.)***	***E31***	***42***
CON EDISON MANHOLE:	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D32***	***46***
CON EDISON MANHOLE:	HUGENUOT ST & NORTH	NE 0 - 1/8 (0.046 mi.)	D34	50
CON EDISON TRANSFORM	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D36***	***52***
US POSTAL SERVICE	***255 NORTH AVE***	***NE 0 - 1/8 (0.050 mi.)***	***D38***	***55***
FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	ENE 0 - 1/8 (0.056 mi.)	D47	65
CON EDISON MANHOLE:	***277 NORTH AVE***	***NNE 0 - 1/8 (0.073 mi.)***	***G52***	***69***
CON EDISON TRANSFORM	***NORTH AVE & ANDERSON***	***ENE 0 - 1/8 (0.081 mi.)***	***E62***	***86***
CON EDISON	***NORTH AVE & ANDERSON***	***ENE 0 - 1/8 (0.081 mi.)***	***E63***	***88***
CON EDISON	***230 NORTH AVE***	***ENE 0 - 1/8 (0.084 mi.)***	***E68***	***94***
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***M95***	***138***
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***M96***	***141***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N98***	***144***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N100***	***149***
CON EDISON	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.113 mi.)	N101	152
NEW YORK TELEPHONE C	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.115 mi.)***	***I105***	***157***
CON EDISON	***LECOUNT PL & ANDERSO***	***ENE 0 - 1/8 (0.123 mi.)***	***H117***	***173***
CON EDISON MANHOLE:	313 NORTH AVE FRONT	N 1/8 - 1/4 (0.125 mi.)	J125	184

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	***19 DIVISION ST & WAS***	***NW 1/8 - 1/4 (0.130 mi.)***	***131***	***190***
CON EDISON	205 NORTH AVE	E 1/8 - 1/4 (0.135 mi.)	Q138	202
MR CHIMNEY CLEAN	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.138 mi.)***	***M148***	***214***
CON EDISON SERVICE B	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J151***	***218***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J152***	***220***
CON EDISON MANHOLE:	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***J153***	***223***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J154***	***225***
CON EDISON MANHOLE 4	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J156***	***229***
ADREAN PRINTING CO	***490 MAIN ST***	***ESE 1/8 - 1/4 (0.147 mi.)***	***P163***	***240***
PRO AUTO PARTS	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***M164***	***243***
FIRST METRO SERVICES	***357 HUGONOT ST***	***SSW 1/8 - 1/4 (0.149 mi.)***	***S165***	***246***
NYS THRUWAY AUTH	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.149 mi.)***	***T166***	***248***
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.158 mi.)***	***T184***	***282***
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***Z194***	***296***
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.189 mi.)***	***W201***	***307***
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***Z203***	***311***
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.194 mi.)***	***T205***	***315***
CON EDISON TRANSFORM	***595 MAIN ST***	***S 1/8 - 1/4 (0.196 mi.)***	***AB207***	***320***
RUSH MFG CORP	***18 COLUMBUS AVE.***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z208***	***323***
CON EDISON SERVICE B	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AG218***	***340***
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.218 mi.)***	***AJ230***	***374***
CON EDISON	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***232***	***378***
CON EDISON MANHOLE:	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AB234***	***382***
CON EDISON	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AB235***	***384***
CON EDISON MANHOLE 1	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AK239***	***393***
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***Z241***	***396***
CON EDISON SERVICE B	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.232 mi.)***	***AG245***	***404***
CON EDISON MANHOLE:	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.232 mi.)***	***AG246***	***406***
CON EDISON	***45 HARRISON ST***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AL250***	***413***
CON EDISON	***HARRISON ST & CEDER***	***ENE 1/8 - 1/4 (0.233 mi.)***	***AL255***	***420***
CON EDISON	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.234 mi.)	AH260	426
CON EDISON TRANSFORM	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.234 mi.)***	***AH261***	***427***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH262***	***429***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH263***	***432***
LONGINES WITTNAUER W	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.237 mi.)***	***AK267***	***439***
CON EDISON	***HARRISON ST & FOUNTA***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AL273***	***453***
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL274	455
CON EDISON SERVICE B	***FOUNTAIN PL & HARRIS***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AL275***	***455***
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL278	460
COLONIAL CLEANERS CO	149 NORTH AVE	ESE 1/8 - 1/4 (0.246 mi.)	AG289	477

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 11/22/2017 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREEN HEAVEN/CENTRE Facility Id: 3-5510-00298	62 CENTRE AVE.	S 0 - 1/8 (0.109 mi.)	I94	138
HANGERS CLEANERS Facility Id: 3-5510-00358	562-564 MAIN STREET	S 1/8 - 1/4 (0.147 mi.)	R162	240
ROTH CLEANERS	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***X189***	***288***

Facility Id: 3-5510-00292

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANER	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	B2	9
STATION CLEANERS Facility Id: ---	1 DEPOT PLAZA #1	NNW 0 - 1/8 (0.106 mi.)	L91	132
SPEEDY CLEANERS Facility Id: 3-5510-00344	***217 NORTH AVENUE***	***E 0 - 1/8 (0.113 mi.)***	***H102***	***153***
SCHMUKLER'S CLEANERS Facility Id: 3-5510-00327	360 NORTH AVE.	N 1/8 - 1/4 (0.212 mi.)	AH223	355
FLAMINGO/TYK CLEANER Facility Id: 3-5510-00335	149 NORTH AV.	ESE 1/8 - 1/4 (0.246 mi.)	AG291	487

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 97 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004151221	MEMORIAL HIGHWAY & H	ENE 0 - 1/8 (0.007 mi.)	B6	11
CON ED EPA ID: NYP004353199	DIVISION ST AND HUGE	S 0 - 1/8 (0.009 mi.)	C7	13
CON EDISON EPA ID: NYP004677548	HUGENOT & DIVISION S	S 0 - 1/8 (0.009 mi.)	C8	14
CON EDISON MANHOLE: EPA ID: NYP004317285	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.009 mi.)***	***C9***	***16***
CON EDISON EPA ID: NYP004677894	HUGENOT ST & DIVISIO	S 0 - 1/8 (0.009 mi.)	C10	18
CON EDISON EPA ID: NYP004676847	DIVISION & HUGUENOT	S 0 - 1/8 (0.009 mi.)	C11	20
CON EDISON EPA ID: NYP004800058	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.080 mi.)***	***F56***	***75***
CON EDISON EPA ID: NYP004677530	HUGENOT & CENTRE ST	SSW 0 - 1/8 (0.098 mi.)	I76	106
CON EDISON EPA ID: NYP004676839	CENTER & HUGUENOT	SSW 0 - 1/8 (0.098 mi.)	I77	107
CON EDISON EPA ID: NYP004332961	CENTRE AVE & HUGUENO	SSW 0 - 1/8 (0.098 mi.)	I78	109
SIMONETTI CLEANERS EPA ID: NYD982531634	***62 CENTRE ST***	***S 0 - 1/8 (0.109 mi.)***	***I93***	***133***
CON EDISON EPA ID: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.124 mi.)	O119	176
CONSOLIDATED EDISON EPA ID: NYP004123873	DIVISION & MAIN	SSE 0 - 1/8 (0.124 mi.)	O120	177
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O133***	***192***

EPA ID: NYP004364576				
CON EDISON MANHOLE: EPA ID: NYP004478624	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O134***	***195***
CON EDISON EPA ID: NYP004680070	MAIN ST & CHURCH ST	SE 1/8 - 1/4 (0.131 mi.)	O135	197
CON EDISON TRANSFORM EPA ID: NYP004478517	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.131 mi.)***	***O136***	***198***
CON EDISON EPA ID: NYP004658019	MAIN ST & CENTRE ST	S 1/8 - 1/4 (0.155 mi.)	R178	272
CON EDISON TRANSFORM EPA ID: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R181***	***276***
CON ED EPA ID: NYP004760815	CENTRE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	R182	279
ROTH CLEANERS EPA ID: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***X189***	***288***
CONSOLIDATED EDISON EPA ID: NYP004124210	DIVISION ST & LEROY	SSE 1/8 - 1/4 (0.181 mi.)	X190	292
NYNEX EPA ID: NYP000932509	UNION AVENUE AND WAR	W 1/8 - 1/4 (0.201 mi.)	U209	326
CON EDISON TRANSFORM EPA ID: NYP004357059	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AB210***	***327***
CON EDISON SERVICE B EPA ID: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AE214***	***333***
CON EDISON EPA ID: NYP004517694	CENTRE AVE & LEROY	S 1/8 - 1/4 (0.205 mi.)	AE215	335
MONTEFIORE - NEW ROC EPA ID: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.217 mi.)***	***AI227***	***366***
PREFERRED CLEANERS EPA ID: NYD050275254	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AA237***	***388***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACCESSOCRAFT PRODUCT EPA ID: NYR000014753	***48 LAWTON ST***	***E 0 - 1/8 (0.046 mi.)***	***E31***	***42***
CON EDISON MANHOLE: EPA ID: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D32***	***46***
CON EDISON EPA ID: NYP004343786	NORTH AVE & HUGENOT	NE 0 - 1/8 (0.046 mi.)	D35	50
CON EDISON TRANSFORM EPA ID: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D36***	***52***
US POSTAL SERVICE EPA ID: NYR000106369	***255 NORTH AVE***	***NE 0 - 1/8 (0.050 mi.)***	***D38***	***55***
CON EDISON MANHOLE: EPA ID: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.073 mi.)***	***G52***	***69***
CON EDISON EPA ID: NYP004709622	ANDERSON ST & NORTH	ENE 0 - 1/8 (0.081 mi.)	E60	83
CON EDISON	NORTH AVE & ANDERSON	ENE 0 - 1/8 (0.081 mi.)	E61	85

EPA ID: NYP004759452				
CON EDISON TRANSFORM EPA ID: NYP004367611	***NORTH AVE & ANDERSON***	***ENE 0 - 1/8 (0.081 mi.)***	***E62***	***86***
CON EDISON EPA ID: NYP004683272	NORTH AVE & ANDERSON	ENE 0 - 1/8 (0.081 mi.)	E65	91
CON ED EPA ID: NYP004760179	230 NORTH AVE	ENE 0 - 1/8 (0.084 mi.)	E69	96
CVS PHARMACY #8447 EPA ID: NYR000194654	***222 NORTH AVE***	***E 0 - 1/8 (0.099 mi.)***	***H80***	***111***
ERIC S TURNER & CO I EPA Id: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I87***	***125***
CON EDISON TRANSFORM EPA ID: NYP004365318	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***M95***	***138***
CON EDISON TRANSFORM EPA ID: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***M96***	***141***
CON EDISON EPA ID: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.113 mi.)	N97	143
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N98***	***144***
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N100***	***149***
NEW YORK TELEPHONE C EPA ID: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.115 mi.)***	***I105***	***157***
CON EDISON EPA ID: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.123 mi.)	H116	172
MACYS EPA ID: NYP000890137	33 LE COUNT PLACE	ENE 1/8 - 1/4 (0.127 mi.)	H126	185
CON EDISON EPA ID: NYP004772265	205 NORTH AVE	E 1/8 - 1/4 (0.135 mi.)	Q139	202
MR CHIMNEY CLEAN EPA ID: NYD987011855	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.138 mi.)***	***M148***	***214***
CON EDISON SERVICE B EPA ID: NYP004463667	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J151***	***218***
CON EDISON MANHOLE: EPA ID: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J152***	***220***
CON EDISON MANHOLE: EPA ID: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***J153***	***223***
CON EDISON - MANHOLE EPA ID: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***J155***	***226***
CON EDISON MANHOLE 4 EPA ID: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***J156***	***229***
ADREAN PRINTING CO EPA ID: NY0000233981	***490 MAIN ST***	***ESE 1/8 - 1/4 (0.147 mi.)***	***P163***	***240***
PRO AUTO PARTS EPA ID: NYR000016535	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***M164***	***243***
NYS THRUWAY AUTH	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.149 mi.)***	***T166***	***248***

EPA ID: NYD986963445				
NYSDEC-SITE 360109 I	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.155 mi.)***	***M174***	***260***
EPA ID: NYR000208967				
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.158 mi.)***	***T184***	***282***
EPA ID: NYP004307492				
CON ED-V37	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.182 mi.)	Y191	293
EPA ID: NYP004027967				
CON ED-V14	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.182 mi.)	Y192	294
EPA ID: NYP004028122				
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***Z194***	***296***
EPA ID: NYD986884732				
CON EDISON	HUGENOT AVE & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	S198	302
EPA ID: NYP004677621				
CON EDISON	HUGUENOT ST & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	S199	304
EPA ID: NYP004687802				
CON EDISON	HUGENOT ST & COLUMBU	SSW 1/8 - 1/4 (0.188 mi.)	S200	305
EPA ID: NYP004677837				
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.189 mi.)***	***W201***	***307***
EPA ID: NYD987034998				
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***Z203***	***311***
EPA ID: NYP004205654				
CON EDISON	35 BARTELS PL	SW 1/8 - 1/4 (0.193 mi.)	Z204	314
EPA ID: NYP004744074				
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.194 mi.)***	***T205***	***315***
EPA ID: NYP004432886				
CON EDISON TRANSFORM	***595 MAIN ST***	***S 1/8 - 1/4 (0.196 mi.)***	***AB207***	***320***
EPA ID: NYP004464459				
RUSH MFG CORP	***18 COLUMBUS AVE.***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z208***	***323***
EPA ID: NYD981185051				
CON EDISON SERVICE B	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AG218***	***340***
EPA ID: NYP004442943				
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***N 1/8 - 1/4 (0.212 mi.)***	***AH222***	***350***
EPA ID: NYD012950770				
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.218 mi.)***	***AJ230***	***374***
EPA ID: NYR000193854				
CON EDISON	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***232***	***378***
EPA ID: NYP004157665				
CON EDISON MANHOLE:	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AB234***	***382***
EPA ID: NYP004431706				
CON EDISON	MAIN ST & MAPLE AVE	SSW 1/8 - 1/4 (0.225 mi.)	AB236	387
EPA ID: NYP004674354				
CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NE 1/8 - 1/4 (0.226 mi.)	AK238	392
EPA ID: NYP004219572				
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***Z241***	***396***
EPA ID: NYR000040113				
EPA ID: NYD002182897				
CON EDISON	150 NORTH AV	ESE 1/8 - 1/4 (0.229 mi.)	AG244	402

EPA ID: NYP004710497				
CON EDISON SERVICE B EPA ID: NYP004452439	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.232 mi.)***	***AG245***	***404***
CON EDISON MANHOLE: EPA ID: NYP004443198	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.232 mi.)***	***AG246***	***406***
CON EDISON EPA ID: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.232 mi.)	AL249	412
CON ED EPA ID: NYP004759924	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.233 mi.)	AL256	421
CON EDISON TRANSFORM EPA ID: NYP004372751	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.234 mi.)***	***AH261***	***427***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH262***	***429***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH263***	***432***
CON EDISON EPA ID: NYP004838332	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.234 mi.)	AH264	436
LONGINES WITTNAUER W EPA ID: NYD001317221	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.237 mi.)***	***AK267***	***439***
CON EDISON EPA ID: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL269	448
CON EDISON EPA ID: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL271	450
CON ED EPA ID: NYP004759510	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AL272	452
CON EDISON SERVICE B EPA ID: NYP004366886	***FOUNTAIN PL & HARRIS***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AL275***	***455***
CON EDISON EPA ID: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AL276	458
FLAMINGO CLEANERS EPA ID: NYD012946885	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.246 mi.)***	***AG290***	***478***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL Generator EPA Id: NYD075431502	16 GUION PL	NW 1/8 - 1/4 (0.217 mi.)	AI225	357

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there are 25 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO EPA Id: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.124 mi.)	O121	179
CON EDISON EPA Id: NYP004828044	552 MAIN ST	SSE 1/8 - 1/4 (0.137 mi.)	O143	209
CON EDISON EPA Id: NYP004880023	565 MAIN ST	S 1/8 - 1/4 (0.143 mi.)	R159	237
CON EDISON EPA Id: NYP004760815	CENTRE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	R179	274

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004880056	260 NORTH AVE	NE 0 - 1/8 (0.042 mi.)	D25	36
CON EDISON EPA Id: NYP004759452	NORTH AVE & ANDERSON	ENE 0 - 1/8 (0.081 mi.)	E64	90
CON EDISON EPA Id: NYP004760179	230 NORTH AVE	ENE 0 - 1/8 (0.084 mi.)	E70	97
ERIC S TURNER & CO I EPA Id: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I87***	***125***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N98***	***144***
CON EDISON EPA Id: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.113 mi.)	N99	148
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.113 mi.)***	***N100***	***149***
CON EDISON EPA Id: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.123 mi.)	H115	170
CON EDISON EPA Id: NYP004772265	205 NORTH AVE	E 1/8 - 1/4 (0.135 mi.)	Q140	204
NYSDEC-SITE 360109 I EPA Id: NYR000208967	10 BARTELS PL	SW 1/8 - 1/4 (0.155 mi.)	M173	258
LEXINGTON CENTER FOR EPA Id: NYR000193854	3 COTTAGE PL	NNE 1/8 - 1/4 (0.218 mi.)	AJ231	377
CON EDISON EPA Id: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AB235***	***384***
CON EDISON MANHOLE 1 EPA Id: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AK239***	***393***
CON EDISON EPA Id: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.232 mi.)	AL248	411
CON EDISON EPA Id: NYP004759924	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.233 mi.)	AL257	423
CON EDISON	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.234 mi.)	AH259	425

EPA Id: NYP004838332				
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH262***	***429***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.234 mi.)***	***AH263***	***432***
CON EDISON EPA Id: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AL270	449
CON EDISON EPA Id: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL277	459
CON EDISON EPA Id: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AL279	461

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON-CEDAR ST	ONE RAMADA PLAZA	NE 1/4 - 1/2 (0.340 mi.)	331	579

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HACKER MORRIS J & SO	64 CENTRE AVE	S 0 - 1/8 (0.105 mi.)	I85	122

Lower Elevation	Address	Direction / Distance	Map ID	Page
A PLUS INC	271 NORTH AVE STE 11	NE 0 - 1/8 (0.055 mi.)	D41	59

EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HAYES KATHRYN INC	36-38 DIVISION ST	SSE 0 - 1/8 (0.044 mi.)	C27	38
SIMONETTI CLEANERS &	62 CENTRE AVE	S 0 - 1/8 (0.109 mi.)	I92	132


Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANERS	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	B3	9
STATION CLEANERS	24 STATION PLZ	N 0 - 1/8 (0.057 mi.)	49	67

EXECUTIVE SUMMARY


Due to poor or inadequate address information, the following sites were not mapped. Count: 8 records.

Site Name	Database(s)
MEARL CORP.	NY SHWS
VALU CLEAN CLEANERS	NY DRYCLEANERS
SIDEWALK / IN FRONT OF NE	NY LTANKS
APARTMENT BUILDING	NY LTANKS
N.SHORE LONG ISLAND SOUND	NY LTANKS
MM 5.4 LEFT LANE	NY LTANKS
NEW ROCHELLE CREEK CABLES	FINDS
CE-CEDAR ST MGP NEW ROCHELLE	NY VCP

OVERVIEW MAP - 5252505.2S


Eastchester Rd
Webster Ave
Colignl Ave
County Hwy-81
Lincoln Ave
Lockwood Ave
Washington Ave
Palmer Ave
Pelham Rd
Kings Hwy
Ward Ave
Weyman Ave
Hurlbut St
Division St
Huguenot St
Memorial Hwy
Hwy
Ave
St
Rd
I-95
US-1
NY-22
NY-125
NY-9A
NY-9W
NY-119
NY-120
NY-287
NY-678
NY-684
NY-895
NY-907
NY-907A
NY-907B
NY-907C
NY-907D
NY-907E
NY-907F
NY-907G
NY-907H
NY-907I
NY-907J
NY-907K
NY-907L
NY-907M
NY-907N
NY-907O
NY-907P
NY-907Q
NY-907R
NY-907S
NY-907T
NY-907U
NY-907V
NY-907W
NY-907X
NY-907Y
NY-907Z
NY-907AA
NY-907AB
NY-907AC
NY-907AD
NY-907AE
NY-907AF
NY-907AG
NY-907AH
NY-907AI
NY-907AJ
NY-907AK
NY-907AL
NY-907AM
NY-907AN
NY-907AO
NY-907AP
NY-907AQ
NY-907AR
NY-907AS
NY-907AT
NY-907AU
NY-907AV
NY-907AW
NY-907AX
NY-907AY
NY-907AZ
NY-907BA
NY-907BB
NY-907BC
NY-907BD
NY-907BE
NY-907BF
NY-907BG
NY-907BH
NY-907BI
NY-907BJ
NY-907BK
NY-907BL
NY-907BM
NY-907BN
NY-907BO
NY-907BP
NY-907BQ
NY-907BR
NY-907BS
NY-907BT
NY-907BU
NY-907BV
NY-907BW
NY-907BX
NY-907BY
NY-907BZ
NY-907CA
NY-907CB
NY-907CC
NY-907CD
NY-907CE
NY-907CF
NY-907CG
NY-907CH
NY-907CI
NY-907CJ
NY-907CK
NY-907CL
NY-907CM
NY-907CN
NY-907CO
NY-907CP
NY-907CQ
NY-907CR
NY-907CS
NY-907CT
NY-907CU
NY-907CV
NY-907CW
NY-907CX
NY-907CY
NY-907CZ
NY-907DA
NY-907DB
NY-907DC
NY-907DD
NY-907DE
NY-907DF
NY-907DG
NY-907DH
NY-907DI
NY-907DJ
NY-907DK
NY-907DL
NY-907DM
NY-907DN
NY-907DO
NY-907DP
NY-907DQ
NY-907DR
NY-907DS
NY-907DT
NY-907DU
NY-907DV
NY-907DW
NY-907DX
NY-907DY
NY-907DZ
NY-907EA
NY-907EB
NY-907EC
NY-907ED
NY-907EE
NY-907EF
NY-907EG
NY-907EH
NY-907EI
NY-907EJ
NY-907EK
NY-907EL
NY-907EM
NY-907EN
NY-907EO
NY-907EP
NY-907EQ
NY-907ER
NY-907ES
NY-907ET
NY-907EU
NY-907EV
NY-907EW
NY-907EX
NY-907EY
NY-907EZ
NY-907FA
NY-907FB
NY-907FC
NY-907FD
NY-907FE
NY-907FF
NY-907FG
NY-907FH
NY-907FI
NY-907FJ
NY-907FK
NY-907FL
NY-907FM
NY-907FN
NY-907FO
NY-907FP
NY-907FQ
NY-907FR
NY-907FS
NY-907FT
NY-907FU
NY-907FV
NY-907FW
NY-907FX
NY-907FY
NY-907FZ
NY-907GA
NY-907GB
NY-907GC
NY-907GD
NY-907GE
NY-907GF
NY-907GG
NY-907GH
NY-907GI
NY-907GJ
NY-907GK
NY-907GL
NY-907GM
NY-907GN
NY-907GO
NY-907GP
NY-907GQ
NY-907GR
NY-907GS
NY-907GT
NY-907GU
NY-907GV
NY-907GW
NY-907GX
NY-907GY
NY-907GZ
NY-907HA
NY-907HB
NY-907HC
NY-907HD
NY-907HE
NY-907HF
NY-907HG
NY-907HH
NY-907HI
NY-907HJ
NY-907HK
NY-907HL
NY-907HM
NY-907HN
NY-907HO
NY-907HP
NY-907HQ
NY-907HR
NY-907HS
NY-907HT
NY-907HU
NY-907HV
NY-907HW
NY-907HX
NY-907HY
NY-907HZ
NY-907IA
NY-907IB
NY-907IC
NY-907ID
NY-907IE
NY-907IF
NY-907IG
NY-907IH
NY-907II
NY-907IJ
NY-907IK
NY-907IL
NY-907IM
NY-907IN
NY-907IO
NY-907IP
NY-907IQ
NY-907IR
NY-907IS
NY-907IT
NY-907IU
NY-907IV
NY-907IW
NY-907IX
NY-907IY
NY-907IZ
NY-907JA
NY-907JB
NY-907JC
NY-907JD
NY-907JE
NY-907JF
NY-907JG
NY-907JH
NY-907JI
NY-907JJ
NY-907JK
NY-907JL
NY-907JM
NY-907JN
NY-907JO
NY-907JP
NY-907JQ
NY-907JR
NY-907JS
NY-907JT
NY-907JU
NY-907JV
NY-907JW
NY-907JX
NY-907JY
NY-907JZ
NY-907KA
NY-907KB
NY-907KC
NY-907KD
NY-907KE
NY-907KF
NY-907KG
NY-907KH
NY-907KI
NY-907KJ
NY-907KK
NY-907KL
NY-907KM
NY-907KN
NY-907KO
NY-907KP
NY-907KQ
NY-907KR
NY-907KS
NY-907KT
NY-907KU
NY-907KV
NY-907KW
NY-907KX
NY-907KY
NY-907KZ
NY-907LA
NY-907LB
NY-907LC
NY-907LD
NY-907LE
NY-907LF
NY-907LG
NY-907LH
NY-907LI
NY-907LJ
NY-907LK
NY-907LL
NY-907LM
NY-907LN
NY-907LO
NY-907LP
NY-907LQ
NY-907LR
NY-907LS
NY-907LT
NY-907LU
NY-907LV
NY-907LW
NY-907LX
NY-907LY
NY-907LZ
NY-907MA
NY-907MB
NY-907MC
NY-907MD
NY-907ME
NY-907MF
NY-907MG
NY-907MH
NY-907MI
NY-907MJ
NY-907MK
NY-907ML
NY-907MM
NY-907MN
NY-907MO
NY-907MP
NY-907MQ
NY-907MR
NY-907MS
NY-907MT
NY-907MU
NY-907MV
NY-907MW
NY-907MX
NY-907MY
NY-907MZ
NY-907NA
NY-907NB
NY-907NC
NY-907ND
NY-907NE
NY-907NF
NY-907NG
NY-907NH
NY-907NI
NY-907NJ
NY-907NK
NY-907NL
NY-907NM
NY-907NN
NY-907NO
NY-907NP
NY-907NQ
NY-907NR
NY-907NS
NY-907NT
NY-907NU
NY-907NV
NY-907NW
NY-907NX
NY-907NY
NY-907NZ
NY-907OA
NY-907OB
NY-907OC
NY-907OD
NY-907OE
NY-907OF
NY-907OG
NY-907OH
NY-907OI
NY-907OJ
NY-907OK
NY-907OL
NY-907OM
NY-907ON
NY-907OO
NY-907OP
NY-907OQ
NY-907OR
NY-907OS
NY-907OT
NY-907OU
NY-907OV
NY-907OW
NY-907OX
NY-907OY
NY-907OZ
NY-907PA
NY-907PB
NY-907PC
NY-907PD
NY-907PE
NY-907PF
NY-907PG
NY-907PH
NY-907PI
NY-907PJ
NY-907PK
NY-907PL
NY-907PM
NY-907PN
NY-907PO
NY-907PP
NY-907PQ
NY-907PR
NY-907PS
NY-907PT
NY-907PU
NY-907PV
NY-907PW
NY-907PX
NY-907PY
NY-907PZ
NY-907QA
NY-907QB
NY-907QC
NY-907QD
NY-907QE
NY-907QF
NY-907QG
NY-907QH
NY-907QI
NY-907QJ
NY-907QK
NY-907QL
NY-907QM
NY-907QN
NY-907QO
NY-907QP
NY-907QQ
NY-907QR
NY-907QS
NY-907QT
NY-907QU
NY-907QV
NY-907QW
NY-907QX
NY-907QY
NY-907QZ
NY-907RA
NY-907RB
NY-907RC
NY-907RD
NY-907RE
NY-907RF
NY-907RG
NY-907RH
NY-907RI
NY-907RJ
NY-907RK
NY-907RL
NY-907RM
NY-907RN
NY-907RO
NY-907RP
NY-907RQ
NY-907RR
NY-907RS
NY-907RT
NY-907RU
NY-907RV
NY-907RW
NY-907RX
NY-907RY
NY-907RZ
NY-907SA
NY-907SB
NY-907SC
NY-907SD
NY-907SE
NY-907SF
NY-907SG
NY-907SH
NY-907SI
NY-907SJ
NY-907SK
NY-907SL
NY-907SM
NY-907SN
NY-907SO
NY-907SP
NY-907SQ
NY-907SR
NY-907SS
NY-907ST
NY-907SU
NY-907SV
NY-907SW
NY-907SX
NY-907SY
NY-907SZ
NY-907TA
NY-907TB
NY-907TC
NY-907TD
NY-907TE
NY-907TF
NY-907TG
NY-907TH
NY-907TI
NY-907TJ
NY-907TK
NY-907TL
NY-907TM
NY-907TN
NY-907TO
NY-907TP
NY-907TQ
NY-907TR
NY-907TS
NY-907TT
NY-907TU
NY-907TV
NY-907TW
NY-907TX
NY-907TY
NY-907TZ
NY-907UA
NY-907UB
NY-907UC
NY-907UD
NY-907UE
NY-907UF
NY-907UG
NY-907UH
NY-907UI
NY-907UJ
NY-907UK
NY-907UL
NY-907UM
NY-907UN
NY-907UO
NY-907UP
NY-907UQ
NY-907UR
NY-907US
NY-907UT
NY-907UU
NY-907UV
NY-907UW
NY-907UX
NY-907UY
NY-907UZ
NY-907VA
NY-907VB
NY-907VC
NY-907VD
NY-907VE
NY-907VF
NY-907VG
NY-907VH
NY-907VI
NY-907VJ
NY-907VK
NY-907VL
NY-907VM
NY-907VN
NY-907VO
NY-907VP
NY-907VQ
NY-907VR
NY-907VS
NY-907VT
NY-907VU
NY-907VV
NY-907VW
NY-907VX
NY-907VY
NY-907VZ
NY-907WA
NY-907WB
NY-907WC
NY-907WD
NY-907WE
NY-907WF
NY-907WG
NY-907WH
NY-907WI
NY-907WJ
NY-907WK
NY-907WL
NY-907WM
NY-907WN
NY-907WO
NY-907WP
NY-907WQ
NY-907WR
NY-907WS
NY-907WT
NY-907WU
NY-907WV
NY-907WW
NY-907WX
NY-907WY
NY-907WZ
NY-907XA
NY-907XB
NY-907XC
NY-907XD
NY-907XE
NY-907XF
NY-907XG
NY-907XH
NY-907XI
NY-907XJ
NY-907XK
NY-907XL
NY-907XM
NY-907XN
NY-907XO
NY-907XP
NY-907XQ
NY-907XR
NY-907XS
NY-907XT
NY-907XU
NY-907XV
NY-907XW
NY-907XX
NY-907XY
NY-907XZ
NY-907YA
NY-907YB
NY-907YC
NY-907YD
NY-907YE
NY-907YF
NY-907YG
NY-907YH
NY-907YI
NY-907YJ
NY-907YK
NY-907YL
NY-907YM
NY-907YN
NY-907YO
NY-907YP
NY-907YQ
NY-907YR
NY-907YS
NY-907YT
NY-907YU
NY-907YV
NY-907YW
NY-907YX
NY-907YY
NY-907YZ
NY-907ZA
NY-907ZB
NY-907ZC
NY-907ZD
NY-907ZE
NY-907ZF
NY-907ZG
NY-907ZH
NY-907ZI
NY-907ZJ
NY-907ZK
NY-907ZL
NY-907ZM
NY-907ZN
NY-907ZO
NY-907ZP
NY-907ZQ
NY-907ZR
NY-907ZS
NY-907ZT
NY-907ZU
NY-907ZV
NY-907ZW
NY-907ZX
NY-907ZY
NY-907ZZ

DETAIL MAP - 5252505.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	LA Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	275 Huguenot Street New Rochelle NY 10801	CONTACT:	Michelle Sabol
		INQUIRY #:	5252505.2s
LAT/LONG:	40.910033 / 73.784143	DATE:	April 09, 2018 5:45 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	1	0	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		3	3	NR	NR	NR	6
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		2	1	NR	NR	NR	3
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	1	2	0	NR	3
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		18	37	106	NR	NR	161
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		19	22	NR	NR	NR	41
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	14	NR	NR	NR	20
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	4	0	NR	NR	4
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	1	NR	NR	1
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		22	NR	NR	NR	NR	22
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		23	53	NR	NR	NR	76
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		4	4	NR	NR	NR	8
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		33	64	NR	NR	NR	97
RI MANIFEST	0.250		0	0	NR	NR	NR	0
PA MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250		9	16	NR	NR	NR	25
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		4	NR	NR	NR	NR	4
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		0	145	223	114	0	0	482

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **OFFICE BUILDING** **NY Spills** **S102154161**
8-10 RAILROAD PLACE **N/A**
< 1/8 **NEW ROCHELLE, NY**
1 ft.

Site 1 of 2 in cluster A

Relative: SPILLS:
Lower

Actual:
81 ft.

Facility ID:	9009493
Facility Type:	ER
Spill Number:	9009493
DER Facility ID:	182194
Site ID:	220275
DEC Region:	3
Closed Date:	1991-05-07
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1990-11-28
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1990-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-03-18
Cleanup Meets Std:	True
Last Inspection:	1991-03-18
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-12-06
Spill Record Last Update:	1991-05-08
Spiller Name:	Not reported
Spiller Company:	8 RAILROAD PLACE CORP.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"UNDERGROUND TANK SYSTEM APPEARS TO BE LEAKING ACCORDING TO READINGS MAPLE MAINTENANCE LAGRANGEVILLE NO ODORS NO PRODUCT IN VIEW CALLED JOHN TENORE MAPLE MAINT. WILL BE DOING A TANK TEST MAYBE ONLY 100"

All Materials:

Site ID:	220275
Operable Unit ID:	946581
Operable Unit:	01
Material ID:	429706
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	800.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B2 **SOUND CLEANER** **NY DRYCLEANERS** **S110247943**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
1 ft.

Site 1 of 7 in cluster B

Relative: DRYCLEANERS:
Lower

Facility ID:	Not reported
Phone Number:	Not reported
Region:	3
Registration Effective Date:	Not reported
Inspection Date:	Not reported
Install Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
83 ft.

B3 **SOUND CLEANERS** **EDR Hist Cleaner** **1020090702**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
1 ft.

Site 2 of 7 in cluster B

Relative: EDR Hist Cleaner
Lower

Actual:
83 ft.

Year:	Name:	Type:
2007	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2010	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2011	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2012	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2013	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2014	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC

C4 **RESIDENCE** **NY Spills** **S109413260**
South **129 DIVISON ST** **N/A**
< 1/8 **TARRYTOWN, NY**
0.006 mi.
34 ft.

Site 1 of 20 in cluster C

Relative: SPILLS:
Higher

Facility ID:	0810056
Facility Type:	ER
Spill Number:	0810056
DER Facility ID:	356816
Site ID:	407567
DEC Region:	3
Closed Date:	2010-05-04
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6026
Spill Date:	2008-12-09
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-12-09
CID:	Not reported

Actual:
101 ft.

RESIDENCE (Continued) **S109413260**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-09
Spill Record Last Update:	2010-08-27
Spiller Name:	Not reported
Spiller Company:	3RD PARTY SPILL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"12/09/2008: Con Ed reports that this location is the former GM site that was/is a Brownsfield site. Con Ed was laying a gas line when stained soils was found in the trench...ra 08/27/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	"CALLER STATES THAT THEY RECIEVED A 3RD PARTY CALLL STATING THAT THEY FOUND AN UNK PETROLEUM PRODUCT DURING AN EXCAVATION. CLEAN UP IS PENDING."

All Materials:

Site ID:	407567
Operable Unit ID:	1164107
Operable Unit:	01
Material ID:	2155468
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

B5 **UST** **NY Spills** **S104509646**
ENE **MEMORIAL HIGHWAY AND HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.007 mi.
38 ft. **Site 3 of 7 in cluster B**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9912617
Facility Type:	ER
Spill Number:	9912617
DER Facility ID:	208558
Site ID:	254637
DEC Region:	3
Closed Date:	2000-04-04
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2000-02-04
Investigator:	tdghiosa

UST (Continued) **S104509646**

Referred To:	Not reported
Reported to Dept:	2000-02-04
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-04
Spill Record Last Update:	2017-10-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	AVALONBAY COMMUNITIES
DEC Memo:	" 02/04/2000 STEVE AT AKRF. NEW ROCHELLE F.D. HAS BEEN ON SITE AS WELL AS T. GHIOSAY 04/04/2000 LETTER SENT TO AKRF BY T. GHIOSAY; CLEANUP SATISFACTORY - SPILL FILE CLOSED."
Remarks:	"CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL"

All Materials:

Site ID:	254637
Operable Unit ID:	1091315
Operable Unit:	01
Material ID:	294499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B6 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650791**
ENE **MEMORIAL HIGHWAY & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.007 mi.
38 ft. **Site 4 of 7 in cluster B**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004151221
Facility Status:	Not reported
Location Address 1:	MEMORIAL HIGHWAY & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

CONSOLIDATED EDISON (Continued) **S108650791**

NY MANIFEST:

EPAID:	NYP004151221
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	06/21/2007
Trans1 Recv Date:	06/21/2007
Trans2 Recv Date:	06/22/2007
TSD Site Recv Date:	06/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004151221
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000174983GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H129
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1820
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CONSOLIDATED EDISON (Continued) **S108650791**

Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C7 **CON ED** **NY MANIFEST** **S119073734**
South **DIVISION ST AND HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 2 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004353199
Facility Status:	Not reported
Location Address 1:	DIVISION ST AND HUGENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004353199
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2013
Trans1 Recv Date:	08/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004353199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON ED (Continued) **S119073734**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694814JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C8 **CON EDISON** **NY MANIFEST** **S117535593**
South **HUGENOT & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 3 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677548
Facility Status:	Not reported
Location Address 1:	HUGENOT & DIVISION ST
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677548

CON EDISON (Continued) **S117535593**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677548
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774875JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117535593**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C9 **CON EDISON MANHOLE: 1215** **RCRA NonGen / NLR** **1016678044**
South **HUGENOT AVE & DIVISION ST NE** **FINDS** **NYP004317285**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.009 mi. **NY MANIFEST**
48 ft. **Site 4 of 20 in cluster C**

Relative: Higher

Actual: 101 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/30/2013
Facility name: CON EDISON MANHOLE: 1215
Facility address: HUGENOT AVE & DIVISION ST NE
COR
NEW ROCHELLE, NY 10801
EPA ID: NYP004317285
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: GINO FRABASILE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/30/2013
Site name: CON EDISON MANHOLE: 1215
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Registry ID: 110058874865

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678044
Registry ID: 110058874865
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058874865

NY MANIFEST:
Country: USA
EPA ID: NYP004317285
Facility Status: Not reported
Location Address 1: DIVISION ST & HUGUENOT ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004317285
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/30/2013
Trans1 Recv Date: 05/30/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/30/2013

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004317285
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842831JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C10 **CON EDISON** **NY MANIFEST** **S117535602**
South **HUGENOT ST & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.009 mi.
48 ft. **Site 5 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677894
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & DIVISION ST
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY

CON EDISON (Continued) **S117535602**

Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004677894
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/15/2014
Trans1 Recv Date: 10/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677894
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012774861JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117535602**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C11 **CON EDISON** **NY MANIFEST** **S117319604**
South **DIVISION & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.009 mi.
48 ft. **Site 6 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004676847
Facility Status:	Not reported
Location Address 1:	DIVISION & HUGUENOT
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676847
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676847

CON EDISON (Continued) **S117319604**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770952JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C12 **CON EDISON - TRANSFORMER MANHOLE 1154** **RCRA-LQG** **1016962308**
South **DIVISION ST AND HUGENOT ST** **NYP004353199**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 7 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - TRANSFORMER MANHOLE 1154
Facility address:	DIVISION ST AND HUGENOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004353199
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Contact email: HUACOND@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/29/2013
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/29/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Not a generator, verified

Date form received by agency: 08/29/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

C13 **CON EDISON TRANSFORMER MANHOLE: 1154** **RCRA NonGen / NLR** **1016961985**
South **DIVISION ST & HUGUENOT ST** **NYP004349395**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 8 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/21/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 1154
Facility address: DIVISION ST & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004349395
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

CON EDISON TRANSFORMER MANHOLE: 1154 (Continued) **1016961985**

Historical Generators:
Date form received by agency: 08/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B14 **METRO NORTH TRACKS** **NY Spills** **S106126232**
NNW **EAST OF NEW ROCHELLE STAT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.009 mi.
49 ft. **Site 5 of 7 in cluster B**

Relative: **Lower**
Actual: **81 ft.**

SPILLS:

Facility ID:	0308130
Facility Type:	ER
Spill Number:	0308130
DER Facility ID:	226808
Site ID:	279322
DEC Region:	3
Closed Date:	2004-07-16
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2003-10-31
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-10-31
CID:	418
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-31
Spill Record Last Update:	2004-07-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOANNE REILLEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/5/03 Joanne Reilly stated that the area is inaccessible to work in because of hi speed train taffic. Requested permission to cleanup during a planned closure for a capital project scheduled in 2004. Will submit request in writing to TG. TG 07-15-04 Letter rec'd from Metro North claiming cleanup has been completed. NFA. TG."
Remarks:	"caller states that spill is between 2 tracks and currently have a company rep enroute to the scene"

All Materials:

Site ID:	279322
Operable Unit ID:	874415
Operable Unit:	01
Material ID:	501652

METRO NORTH TRACKS (Continued) **S106126232**

Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B15 **METRO NORTH TRAIN STATION** **NY Spills** **S102153509**
NNW **NEW HAVEN LINE &R/R PLAZA** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.009 mi.
49 ft. **Site 6 of 7 in cluster B**

Relative:
Lower

Actual:
81 ft.

SPILLS:

Facility ID:	8903573
Facility Type:	ER
Spill Number:	8903573
DER Facility ID:	92033
Site ID:	104107
DEC Region:	3
Closed Date:	1989-07-19
Spill Cause:	Vandalism
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1989-07-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-07-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-07-10
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-19
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	METRO NORTH TRAIN STATION
Spiller Address:	NEW HAVEN LINE &R/R PLAZA
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"SOMEONE PUT STEEL BAR ON TRACK. TRAIN HIT BAR, PUNCTURED SMALL HOLE IN TRANFORMER. CAR #8669, EMPLOYEE WALKED TRACK. CLEAN UP IN PROGRESS. WCHD WILL INVESTIGATE, AMER. ENV. TECH, RCIHFIELD CT, NFA"

All Materials:

Site ID:	104107
Operable Unit ID:	928993
Operable Unit:	01

METRO NORTH TRAIN STATION (Continued) **S102153509**

Material ID:	447657
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C16 **NYSDOT BIN 1049890** **RCRA NonGen / NLR** **1000789726**
SSE **DIVISION ST OVER METRO NORTH** **NYD987011897**
< 1/8 **NEW ROCHELLE, NY 10803**
0.010 mi.
53 ft. **Site 9 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1049890
Facility address:	DIVISION ST OVER METRO NORTH NEW ROCHELLE, NY 10803
EPA ID:	NYD987011897
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	914-431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

NYSDOT BIN 1049890 (Continued) **1000789726**

Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

Date form received by agency: 08/12/1992
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

A17 **MH1204** **NY Spills** **S104509750**
ENE **HUGUENOT AVE/LAWTON AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.019 mi.
99 ft. **Site 2 of 2 in cluster A**

Relative: SPILLS:
Lower
Actual: Facility ID: 9912755
91 ft. Facility Type: ER
Spill Number: 9912755
DER Facility ID: 214030
Site ID: 262084
DEC Region: 3
Closed Date: 2000-02-14
Spill Cause: Unknown
Spill Class: C4
SWIS: 6010
Spill Date: 2000-02-09
Investigator: jbodee

MH1204 (Continued) **S104509750**

Referred To:	Not reported
Reported to Dept:	2000-02-09
CID:	270
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2000-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/09/2000 SOURCE UNKNOWN-NO OIL FILLED CONED EQUIPMENT NEARBY. VAC TRUCK BEING SENT TO SITE. WILL CALL WITH RESULTS OF PRODUCT I.D. SPILL VOLUME DOWNGRADED TO 3 GALLONS. 02/14/2000 CLEANUP REPORT SENT TO TARRYTOWN OFFICE. AMOUNT SPILLED WAS ACTUALLY 3 GALLONS. NFA"
Remarks:	"OIL STAGNANT SAMPLES WILL BE TAKEN CLEAN UP PENDING"

All Materials:

Site ID:	262084
Operable Unit ID:	1091472
Operable Unit:	01
Material ID:	294626
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C18 **AVALON ON THE SOUND** **NY UST** **U003994344**
SE **HUGUENOT STREET AND MEMORAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.022 mi.
115 ft. **Site 10 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800626 / Unregulated: <1101 gal. PBS
Operator Name:	Avalonbay
Owner Name:	Avalonbay Redevelopment LLC
Owner Street:	535 Fifth Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10017
GDS Number:	Not reported

AVALON ON THE SOUND (Continued) **U003994344**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/01/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

C19 **VACANT LOT** **NY LTANKS** **S107489335**
SSE **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 11 of 20 in cluster C**

Relative: **Higher**
Actual: **101 ft.**

LTANKS:

Facility ID:	0510542
Site ID:	356539
Closed Date:	2006-03-15
Spill Number:	0510542
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-15
Spiller Name:	STEVE GRENS
Spiller Company:	VACANT LOT
Spiller Address:	HUGUENOT ST/DIVISION ST
Spiller County:	001
Spiller Contact:	STEVE GRENS
Spiller Phone:	(914) 806-5650
Spiller Extention:	Not reported

VACANT LOT (Continued) **S107489335**

DEC Region: 3
DER Facility ID: 306600
DEC Memo: "March 15, 2006: BROOKSIDE ENVIRONMENTAL DISPOSED OF LUST AND 5.62 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM AKRF. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Tank removal, tank size 1000 gallons."

All Materials:
Site ID: 356539
Operable Unit ID: 1113840
Operable Unit: 01
Material ID: 2103900
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

C20 **ROAD** **NY Spills** **S108130430**
SSE **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 12 of 20 in cluster C**

Relative: **Higher**

Actual: **101 ft.**

SPILLS:
Facility ID: 0606187
Facility Type: ER
Spill Number: 0606187
DER Facility ID: 306600
Site ID: 369495
DEC Region: 3
Closed Date: 2006-09-03
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6010
Spill Date: 2006-08-29
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-08-29
CID: 410
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-08-29
Spill Record Last Update: 2006-09-03
Spiller Name: JEFF CULLEN
Spiller Company: GC RELIABLE SERVICE COMPA

ROAD (Continued) **S108130430**

Spiller Address: 80 GROVE ST
Spiller Company: 001
Contact Name: WESTCHESTER FIRE CONTROL
DEC Memo: "DPW sanded road. No product to recover. jod"
Remarks: "SPILL SPANS FOR FIVE BLOCKS BETWEEN THE TWO STREETS GIVEN IN LOCATION: CLEANUP IN PROGRESS: DPW ON SCENE:"

All Materials:
Site ID: 369495
Operable Unit ID: 1127329
Operable Unit: 01
Material ID: 2116923
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 60.00
Units: G
Recovered: .00
Oxygenate: Not reported

C21 **SHORELINE OIL** **NY LTANKS** **S102674768**
South **296 HUGENOT ST,REAR OF** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.033 mi.
174 ft. **Site 13 of 20 in cluster C**

Relative: **Higher**
Actual: **101 ft.**

LTANKS:
Facility ID: 8709425
Site ID: 83347
Closed Date: 1988-04-06
Spill Number: 8709425
Spill Date: 1988-02-03
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-04-06
SWIS: 6010
Investigator: dxtraver
Referred To: Not reported
Reported to Dept: 1988-02-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: 1988-05-02
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-02-10
Spill Record Last Update: 1988-05-05
Spiller Name: Not reported
Spiller Company: SHORELINE OIL
Spiller Address: 34 EVANS ST
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported

SHORELINE OIL (Continued) **S102674768**

Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76706
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : SITE INSPECT:NO EVIDENCE OF CONTAMINATION FROM OUTSIDE LOCKED GATE. N.F.A. T.D. 05/03/88: NO EVIDENCE OF CONTAMINATION OBSERVED DURING INSPECTION. NFA. "
Remarks:	"OIL INTO PRIVATE DRAIN, TO SUMP,TO SEWER,FROM CAPT.O'CONNOR NRFD(914-654-2215). COMPANY CLEANING UP. DEC TO INVESIGATE & VERIFY CLEAN UP. N.F.A. SEE UPDATE."

All Materials:

Site ID:	83347
Operable Unit ID:	914524
Operable Unit:	01
Material ID:	464747
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C22 **LILLIAN VERNON CO.** **NY LTANKS** **S100494788**
SSE **WESTCHESTER PLACE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.034 mi.
180 ft. **Site 14 of 20 in cluster C**

Relative: **Higher**
Actual: **101 ft.**

LTANKS:

Facility ID:	9213055
Site ID:	201286
Closed Date:	1995-03-16
Spill Number:	9213055
Spill Date:	1993-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-16
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-23
Spill Record Last Update:	1995-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported

LILLIAN VERNON CO. (Continued) **S100494788**

Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	167465
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO HAVE MEETING TO DISCUSS FURTHER ACTION TANK IS BEING PUMPED DOWN TEMP TANK BEING SET UP AES SYSTEM II"

All TTF:

Facility ID:	9213055
Spill Number:	9213055
Spill Tank Test:	1541204
Site ID:	201286
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	201286
Operable Unit ID:	977443
Operable Unit:	01
Material ID:	570289
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

B23 **NYSDOT BIN 1091390** **RCRA NonGen / NLR** **1000790435**
NW **DIVISION ST OVER I 95** **NYD987019197**
< 1/8 **NEW ROCHELLE, NY 10803**
0.036 mi.
188 ft. **Site 7 of 7 in cluster B**

Relative: **Lower**
Actual: **79 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1091390
Facility address:	DIVISION ST OVER I 95 NEW ROCHELLE, NY 10803

NYSDOT BIN 1091390 (Continued) **1000790435**

EPA ID: NYD987019197
Mailing address: BURNETT BLVD
POUGHKEEPSIE, NY 12603
Contact: RICHARD MANNS
Contact address: BURNETT BLVD
POUGHKEEPSIE, NY 12603
Contact country: US
Contact telephone: 914-431-5743
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYSDOT
Owner/operator address: 4 BURNETT BLVD
POUGHKEEPSIE, NY 12603
Owner/operator country: US
Owner/operator telephone: 914-431-5743
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 4 BURNETT BLVD
POUGHKEEPSIE, NY 12603
Owner/operator country: US
Owner/operator telephone: 914-431-5743
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

NYSDOT BIN 1091390 (Continued) **1000790435**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

Date form received by agency: 09/25/1992
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

C24 **NEW ROCHELLE IRISH BENEVOLENT SOCIETY** **NY UST** **U003884840**
SSE **38 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.039 mi.
208 ft. **Site 15 of 20 in cluster C**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-600097 / Unregulated
Operator Name: New Rochelle Irish Benevolent Society
Owner Name: New Rochelle Irish Benevolent Society
Owner Street: 38 Division Street
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 26051652
Status: 3. Closed - Removed
Capacity: 2000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1940
Date Perm Closure: 01/09/2015
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 6. Wrapped (Piping)
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on Ground
Piping Type: 10. Copper
Piping External Protection: 6. Wrapped (Piping)
Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: 0. None
Spill Prevention: 1. Catch Basin
Dispenser: 3. Gravity

D25
NE
< 1/8
0.042 mi.
222 ft.

CON EDISON
260 NORTH AVE
NEW ROCHELLE, NY 10801

Site 1 of 11 in cluster D

NJ MANIFEST **S120678197**
N/A

Relative:
Lower

Actual:
86 ft.

NJ MANIFEST:

EPA Id:	NYP004880056
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319282JJK
EPA ID:	NYP004880056
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120678197**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D26 **CON EDISON** **RCRA NonGen / NLR** **1019909014**
NE **260 NORTH AVE** **FINDS** **NYP004880056**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.042 mi.
222 ft. **Site 2 of 11 in cluster D**

Relative:
Lower

Actual:
86 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/16/2015
Facility name:	CON EDISON
Facility address:	260 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004880056
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/16/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019909014**

Registry ID: 110069645085

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909014
Registry ID: 110069645085
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069645085

C27 **HAYES KATHRYN INC** **EDR Hist Cleaner** **1020002440**
SSE **36-38 DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.044 mi.
231 ft. **Site 16 of 20 in cluster C**

Relative: EDR Hist Cleaner
Higher

Actual: **101 ft.**

Year:	Name:	Type:
1969	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1970	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1971	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1972	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1973	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1974	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1975	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1976	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1977	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs

C28 **TRINITY-ST. PAUL'S EPISCOPAL CHURCH** **NY UST** **U003995010**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
238 ft. **Site 17 of 20 in cluster C**

Relative: WESTCHESTER CO. UST:
Higher

Actual: **101 ft.**

Id/Status:	3-801006 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Trinity Episcopal Church
Owner Street:	311 Huguenot Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1

TRINITY-ST. PAUL'S EPISCOPAL CHURCH (Continued) **U003995010**

Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	03/23/2005
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

C29 **JONES RESIDENCE** **NY LTANKS** **S106737602**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
238 ft. **Site 18 of 20 in cluster C**

Relative: **Higher**
Actual: **101 ft.**

LTANKS:

Facility ID:	0410335
Site ID:	335236
Closed Date:	2005-09-11
Spill Number:	0410335
Spill Date:	2004-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-12-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-17
Spill Record Last Update:	2005-09-11
Spiller Name:	DARRYL JONES
Spiller Company:	JONES RESIDENCE
Spiller Address:	311 HUGENOT STREET
Spiller County:	001
Spiller Contact:	DARRYL JONES
Spiller Phone:	(914) 632-5368
Spiller Extention:	Not reported
DEC Region:	3

JONES RESIDENCE (Continued) **S106737602**

DER Facility ID: 270458
DEC Memo: "12/21/04 PBS FACILITY: 3-801006. jbo September 11, 2005: TANK CLOSED IN PLACE. FIVE SAMPLES TAKEN, NO CONTAMINATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "PBS No: 3-801006 "

All TTF:
Facility ID: 0410335
Spill Number: 0410335
Spill Tank Test: 1548406
Site ID: 335236
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 335236
Operable Unit ID: 1097307
Operable Unit: 01
Material ID: 577292
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

E30 **MAIN LIBRARY** **NY LTANKS** **S103037429**
ENE **LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
242 ft. **Site 1 of 18 in cluster E**

Relative: **Lower**
Actual: **91 ft.**

LTANKS:
Facility ID: 9713843
Site ID: 273025
Closed Date: 1998-03-27
Spill Number: 9713843
Spill Date: 1998-03-13
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010

MAIN LIBRARY (Continued) **S103037429**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALLELLO
Spiller Phone:	(914) 654-2315
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222185
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED - SYSTEM PASSED. NFA."
Remarks:	""

All TTF:

Facility ID:	9713843
Spill Number:	9713843
Spill Tank Test:	1545675
Site ID:	273025
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	273025
Operable Unit ID:	1056692
Operable Unit:	01
Material ID:	324833
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

MAIN LIBRARY (Continued) **S103037429**

Recovered: .00
Oxygenate: Not reported

E31 **ACCESSOCRAFT PRODUCTS INC** **RCRA NonGen / NLR** **1001079768**
East **48 LAWTON ST** **FINDS** **NYR000014753**
< 1/8 **NEW ROCHELLE, NY 10802** **ECHO**
0.046 mi. **NY MANIFEST**
244 ft. **Site 2 of 18 in cluster E**

Relative:
Lower

Actual:
94 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ACCESSOCRAFT PRODUCTS INC
Facility address: 48 LAWTON ST
NEW ROCHELLE, NY 10802
EPA ID: NYR000014753
Mailing address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact: Not reported
Contact address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-654-2163
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-654-2163
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

Date form received by agency: 05/10/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 03/06/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 10/11/1995
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Violation Status: No violations found

FINDS:

Registry ID: 110000849672

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079768
Registry ID: 110000849672
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000849672

NY MANIFEST:
Country: USA
EPA ID: NYR000014753
Facility Status: Not reported
Location Address 1: 48 LAWTON STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000014753
Mailing Name:	ACCESSOCRAFT INC
Mailing Contact:	PAUL STEINMAN
Mailing Address 1:	48 LAWTON STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146322411

NY MANIFEST:

Document ID:	RIC0034295
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	RI49238
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1996
Trans1 Recv Date:	01/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/23/1996
Part A Recv Date:	02/01/1996
Part B Recv Date:	02/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	RID059735761
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID059735761
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F009 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00148
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00160
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00152
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

D32 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016677599**
NE **HUGUENOT AVE & NORTH AVE** **FINDS** **NYP004312476**
< 1/8 **NEW ROCHELLE, NY 10805** **ECHO**
0.046 mi. **NY MANIFEST**
245 ft. **Site 3 of 11 in cluster D**

Relative:
Lower

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/14/2013
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGUENOT AVE & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004312476
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:
Date form received by agency: 05/14/2013
Site name: CON EDISON MANHOLE: 5071
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058876550

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677599
Registry ID: 110058876550
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058876550

NY MANIFEST:
Country: USA
EPA ID: NYP004312476
Facility Status: Not reported
Location Address 1: HUGUENOT & NORTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004312476

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658348JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

D33 **HUGUENOT AND NORTH AVE** **NY Spills** **S106126832**
NE **HUGUENOT AND NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
245 ft. **Site 4 of 11 in cluster D**

Relative: **Lower**

Actual: **85 ft.**

SPILLS:

Facility ID:	0310260
Facility Type:	ER
Spill Number:	0310260
DER Facility ID:	252866
Site ID:	313618
DEC Region:	3
Closed Date:	2005-03-05
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	6010
Spill Date:	2003-12-03
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-03
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-09
Spill Record Last Update:	2005-03-05
Spiller Name:	CARLOS TORRES
Spiller Company:	HUGUENOT AND NORTH AVE
Spiller Address:	HUGUENOT AND NORTH AVE
Spiller Company:	001
Contact Name:	CARLOS TORRES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 3/5/05 5gallon surface spill--close "
Remarks:	"a tow truck carrying a dump truck . the dump truck ruptured and spilled about 5 to 6 gallons of fuel"

D34
NE
< 1/8
0.046 mi.
245 ft.

CON EDISON MANHOLE: 5071
HUGENUOT ST & NORTH AVE
NEW ROCHELLE, NY 10805

Site 5 of 11 in cluster D

RCRA NonGen / NLR **1016968295**
NYP004419065

Relative:
Lower

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/15/2014
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGENUOT ST & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004419065
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2014
Site name:	CON EDISON MANHOLE: 5071
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

D35
NE
< 1/8
0.046 mi.
245 ft.

CON EDISON
NORTH AVE & HUGENOT ST
NEW ROCHELLE, NY 10801

Site 6 of 11 in cluster D

NY MANIFEST **1016961580**
N/A

Relative:
Lower

Actual:
85 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004343786
Facility Status:	Not reported
Location Address 1:	NORTH AVENUE & HUGENOT STR
Code:	BP

CON EDISON (Continued) **1016961580**

Location Address 2:	EET
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004343786
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2013
Trans1 Recv Date:	08/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004343786
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000

CON EDISON (Continued) **1016961580**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

D36 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963620**
NE **NORTH AVE & HUGUENOT ST** **NY MANIFEST** **NYP004366100**
< 1/8 **NEW ROCHELLE, NY 10801**
0.046 mi.
245 ft. **Site 7 of 11 in cluster D**

Relative: **Lower**

Actual: **85 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/25/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5042
Facility address:	NORTH AVE & HUGUENOT ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004366100
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Historical Generators:
Date form received by agency: 09/25/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004366100
Facility Status: Not reported
Location Address 1: NOAR/HUGUNOT ST
Code: BP
Location Address 2: MH5042
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004366100
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/25/2013
Trans1 Recv Date: 09/25/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004366100
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694648JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

37
WNW
< 1/8
0.049 mi.
260 ft.

SPILL NUMBER 9803949
MILEPOST 5.5 SB I95
NEW ROCHELLE, NY

NY Spills **S104647160**
N/A

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	9803949
Facility Type:	ER
Spill Number:	9803949
DER Facility ID:	140562
Site ID:	166821
DEC Region:	3
Closed Date:	1998-06-29
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-06-29
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-29
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

SPILL NUMBER 9803949 (Continued) **S104647160**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-29
Spill Record Last Update:	1998-07-02
Spiller Name:	MR STEPHEN WELDON
Spiller Company:	STEPHENS TRANSP INC
Spiller Address:	60 JOFFRE
Spiller Company:	001
Contact Name:	SGT POWELL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"drive shaft broke on trk rupturing the saddle tank - cleanup in progress"

All Materials:

Site ID:	166821
Operable Unit ID:	1064663
Operable Unit:	01
Material ID:	322269
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D38 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1005444315**
NE **255 NORTH AVE** **NY MANIFEST** **NYR000106369**
< 1/8 **NEW ROCHELLE, NY 10801**
0.050 mi.
263 ft. **Site 8 of 11 in cluster D**

Relative:
Lower

Actual:
87 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	US POSTAL SERVICE
Facility address:	255 NORTH AVE NEW ROCHELLE, NY 10801-9998
EPA ID:	NYR000106369
Mailing address:	WESTCHESTER AVE WHITE PLAINS, NY 10610-9111
Contact:	JOANNE KUNNY
Contact address:	WESTCHESTER AVE WHITE PLAINS, NY 10610-9111
Contact country:	US
Contact telephone:	914-697-7074
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	255 NORTH AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US

US POSTAL SERVICE (Continued) **1005444315**

Owner/operator telephone: 914-632-5906
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: US POSTAL SERVICE
Owner/operator address: 255 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-632-5906
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: US POSTAL SERVICE
Classification: Not a generator, verified

Date form received by agency: 05/17/2002
Site name: US POSTAL SERVICE
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000106369
Facility Status: Not reported

US POSTAL SERVICE (Continued) **1005444315**

Location Address 1:	255 NORTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000106369
Mailing Name:	US POSTAL SERVICE
Mailing Contact:	RICHARD FERRARI
Mailing Address 1:	255 NORTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146977074

NY MANIFEST:

Document ID:	NYG2937357
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	27571PANY
Trans2 State ID:	PW8913
Generator Ship Date:	05/29/2002
Trans1 Recv Date:	05/29/2002
Trans2 Recv Date:	05/30/2002
TSD Site Recv Date:	05/31/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106369
Trans1 EPA ID:	NYD986908085
Trans2 EPA ID:	NYD082785429
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

US POSTAL SERVICE (Continued) **1005444315**

Waste Code:	Not reported
Quantity:	00060
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C39 **306 HUGUENOT STREET CORP.** **NY AST** **U004187406**
South **306 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.050 mi.
264 ft. **Site 19 of 20 in cluster C**

Relative: **Higher**

Actual: **102 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-800236
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	306 Huguenot Street Corp.
Owner Street:	P.O. Box 196
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	001
Status:	1. In-Service
Date Installation:	12/01/1986
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	Not reported
Dispenser:	3. Gravity

C40 **CERUSSI AND VERE** **NY UST** **U004187246**
South **306 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.050 mi.
264 ft. **Site 20 of 20 in cluster C**

Relative: **Higher**
Actual: **102 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-078360 / Administratively Closed
Operator Name:	Not reported
Owner Name:	Michael A Cerussi & F G Vere
Owner Street:	88 Woodlands Rd
Owner Address2:	Not reported
Owner City:	Harrison
Owner State:	NY
Owner Zipcode:	10528
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1986
Date Perm Closure:	12/01/2001
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

D41 **A PLUS INC** **EDR Hist Auto** **1020468102**
NE **271 NORTH AVE STE 117** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
292 ft. **Site 9 of 11 in cluster D**

Relative: **Lower**
Actual: **84 ft.**

EDR Hist Auto

Year:	Name:	Type:
2014	A PLUS INC	Gasoline Service Stations, NEC

D42 **KAUFMAN HUGUENOT COMPANY** **NY UST** **U003994672**
NE **271 NORTH AVENUE** **NY AST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
292 ft. **Site 10 of 11 in cluster D**

Relative:
Lower

Actual:
84 ft.

WESTCHESTER CO. UST:

Id/Status:	3-183776 / Active
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10123
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1900
Date Perm Closure:	01/01/2011
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-183776
Site Status:	Active
GDS Number:	Not reported
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10123
Tank Number:	002
Status:	1. In-Service
Date Installation:	08/01/2007
Capacity:	5000
Product Stored:	0003. #6 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

KAUFMAN HUGUENOT COMPANY (Continued) **U003994672**

Tank Leak Detection:	4. Groundwater Well
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	2. Transfer Station Containment
Dispenser:	2. Suction

E43 **APT BUILDING/LAWTON ST REALTY CORP** **NY LTANKS** **S121120189**
East **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
293 ft. **Site 3 of 18 in cluster E**

Relative: **Lower**
Actual: **94 ft.**

LTANKS:

Facility ID:	1706064
Site ID:	560365
Closed Date:	Not reported
Spill Number:	1706064
Spill Date:	2017-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2017-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2017-09-21
Spill Record Last Update:	2017-09-27
Spiller Name:	Not reported
Spiller Company:	MIKE LAGE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MIKE LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/21/17 3000 gallon UST failed TT with hissing. Same tank failed test last year. Owner is waiting on Con Ed to convert over to natural gas. Conversion should be finished in 3-4 months. Tank will be pulled in approx. 6 months. WC PBS# 3-801435. ga 9-27-17 From Wchd, TTF at a PBS site. 41-43 Lawton St, New Rochelle 3k UST heating oil Old open TTF on site 1605726 RDB "
Remarks:	"3000 gal ust"

APT BUILDING/LAWTON ST REALTY CORP (Continued) **S121120189**

All Materials:

Site ID:	560365
Operable Unit ID:	1308365
Operable Unit:	01
Material ID:	2315311
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

E44 **LAWTON STREET REALTY CORP** **NY LTANKS** **S118953553**
East **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
293 ft. **Site 4 of 18 in cluster E**

Relative: **Lower**
Actual: **94 ft.**

LTANKS:

Facility ID:	1605726
Site ID:	532284
Closed Date:	Not reported
Spill Number:	1605726
Spill Date:	2016-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2016-09-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2016-09-07
Spill Record Last Update:	2017-05-04
Spiller Name:	MICHAEL LAGE
Spiller Company:	LAWTON STREET REALTY CORP
Spiller Address:	41-43 LAWTON ST
Spiller County:	999
Spiller Contact:	MICHAEL LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/7/16 Called Tank Tech - 3000 gal tank failed with popping sound indicative of piping & fitting failure. Owner notified on site. Spoke to owner. Tank to be removed & replaced, contract pending. Property

LAWTON STREET REALTY CORP (Continued) **S118953553**

is 13 residential & 2 commercial. Building is on municipal water. Sent owner draft guidelines and contractor list. ga 5-4-17 Meeting with WCDOH. WC to follow up. GHP"

Remarks: "pbs tank failure"

All Materials:

Site ID:	532284
Operable Unit ID:	1281058
Operable Unit:	01
Material ID:	2286307
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

E45 **PAVEMENT** **NY Spills** **S112147960**
East **41 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
293 ft. **Site 5 of 18 in cluster E**

Relative: **Lower**

Actual: **94 ft.**

SPILLS:

Facility ID:	1203965
Facility Type:	ER
Spill Number:	1203965
DER Facility ID:	421153
Site ID:	466814
DEC Region:	3
Closed Date:	2012-07-23
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2012-07-23
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2012-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-23
Spill Record Last Update:	2012-07-23
Spiller Name:	BADGE 620
Spiller Company:	UNKNOWN
Spiller Address:	41 LAWTON STREET
Spiller Company:	999
Contact Name:	BADGE 620

PAVEMENT (Continued) **S112147960**

DEC Memo: "7-23-12 FD cleaned up. jc"
Remarks: "Possibly from garbage truck. Fire Dept. Clean up."

All Materials:
Site ID: 466814
Operable Unit ID: 1216796
Operable Unit: 01
Material ID: 2215011
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

E46 **LAWTON STREET REALTY CORP.** **NY UST** **U004176798**
East **41-43 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
293 ft. **Site 6 of 18 in cluster E**

Relative: **Lower**
Actual: **94 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-801435 / Active
Operator Name: Lawton Street Realty Corp.
Owner Name: Lawton Street Realty Corp.
Owner Street: 4391 Boston Post Road
Owner Address2: Not reported
Owner City: Pelham Manor
Owner State: NY
Owner Zipcode: 10803
GDS Number: Not reported

Tank Number: 001
Status: 1. In-Service
Capacity: 3000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 06/01/1927
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

D47 **FEDERAL PROPERTY MAINTENANCE CORP** **RCRA NonGen / NLR** **1012186472**
ENE **244 NORTH AVE SUITE 153** **NYR000163337**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
295 ft. **Site 11 of 11 in cluster D**

Relative: **Lower**

Actual: **89 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/25/2017
Facility name:	FEDERAL PROPERTY MAINTENANCE CORP
Facility address:	244 NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
EPA ID:	NYR000163337
Mailing address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact:	KRISTIE EFFEREN
Contact address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-355-2226
Contact email:	FEDERALPMC@AOL.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KRISTIE EFFEREN
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/24/2005
Owner/Op end date:	Not reported

Owner/operator name:	ANTHONY VALENTINO
Owner/operator address:	GRANT AVE HARRISON, NY 10528
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/20/1978
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/23/2009
Site name:	FEDERAL PROPERTY MAINTENANCE CORP
Classification:	Not a generator, verified
Violation Status:	No violations found

F48 **CABLE** **NY Spills** **S109206706**
SSE **29 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.057 mi.
303 ft. **Site 1 of 5 in cluster F**

Relative: **Higher**
Actual: **101 ft.**

SPILLS:

Facility ID:	0804961
Facility Type:	ER
Spill Number:	0804961
DER Facility ID:	351170
Site ID:	401965
DEC Region:	3
Closed Date:	2008-07-30
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jpcummin
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-07-31
Spiller Name:	ERTSDESK
Spiller Company:	CABLE
Spiller Address:	29 DIVISION STREET
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"SEE SP: 0804960. -- NFA"
Remarks:	"8 OUNCES AND ON GOING AND WONT MAKE 2 HOUR CLEAN UP"

CABLE (Continued) **S109206706**

All Materials:

Site ID:	401965
Operable Unit ID:	1158737
Operable Unit:	01
Material ID:	2149827
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

49 **STATION CLEANERS** **EDR Hist Cleaner** **1020094775**
North **24 STATION PLZ** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
303 ft.

Relative: EDR Hist Cleaner
Lower

Actual:
71 ft.

Year:	Name:	Type:
2005	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2006	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC

G50 **NORTH BROOK REALTY ASSOCIATES** **NY UST** **U004259521**
NNE **270 NORTH AVENUE, SUITE 200** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.063 mi.
333 ft. **Site 1 of 6 in cluster G**

Relative: WESTCHESTER CO. UST:
Lower

Actual:
80 ft.

Id/Status:	3-600117 / Active
Operator Name:	North Brook Realty Associates
Owner Name:	North Brook Realty Associates
Owner Street:	270 North Avenue, Suite 200
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	15000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection

NORTH BROOK REALTY ASSOCIATES (Continued) **U004259521**

Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

G51 **277 NORTH LLC** **NY LTANKS** **S108467546**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.073 mi.
386 ft. **Site 2 of 6 in cluster G**

Relative: LTANKS:
Lower

Actual:
81 ft.

Facility ID:	0611648
Site ID:	376329
Closed Date:	2008-12-04
Spill Number:	0611648
Spill Date:	2007-01-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-19
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE MOSES
Spiller Company:	277 NORTH LLC
Spiller Address:	277 NORTH AVE
Spiller County:	001
Spiller Contact:	BRUCE MOSES
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11580 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"EZ 3 LP WAS TEST USED: TANK IS BEING VACCED OUT AND TEMP TANK PUT IN PLACE: ARRANGEMENTS FOR FURTHER TESTING ARE BEING MADE:"

277 NORTH LLC (Continued) **S108467546**

All TTF:

Facility ID:	0611648
Spill Number:	0611648
Spill Tank Test:	1550579
Site ID:	376329
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	376329
Operable Unit ID:	1133914
Operable Unit:	01
Material ID:	2123743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G52 **CON EDISON MANHOLE: 11295** **RCRA NonGen / NLR** **1016960384**
NNE **277 NORTH AVE** **NY MANIFEST** **NYP004323457**
< 1/8 **NEW ROCHELLE, NY 10802**
0.073 mi.
386 ft. **Site 3 of 6 in cluster G**

Relative: **Lower**

Actual: **81 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2013
Facility name:	CON EDISON MANHOLE: 11295
Facility address:	277 NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004323457
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/28/2013
Site name: CON EDISON MANHOLE: 11295
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004323457
Facility Status: Not reported
Location Address 1: FO 277 NORTH AVE
Code: BP
Location Address 2: MH #11295
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10805
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004323457
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Generator Ship Date:	06/28/2013
Trans1 Recv Date:	06/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004323457
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693229JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

G53 **277 NORTH LLC** **NY UST** **U003994270**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.073 mi.
386 ft. **Site 4 of 6 in cluster G**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-502049 / Active
Operator Name:	Bruce J. Moses
Owner Name:	Robert J. Leaf
Owner Street:	3720 South Ocean Blvd
Owner Address2:	#1606

Actual:
81 ft.

277 NORTH LLC (Continued) **U003994270**

Owner City:	Highland Beach
Owner State:	FL
Owner Zipcode:	33487
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	01/01/1900
Date Perm Closure:	10/10/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	2
Status:	1. In-Service
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	10/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	5. Jacketed,9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	6. Wrapped (Piping),9. Urethane
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

G54 **BUSINESS** **NY LTANKS** **S108467526**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.073 mi.
386 ft. **Site 5 of 6 in cluster G**

Relative: **Lower**

Actual: **81 ft.**

LTANKS:

Facility ID:	0611580
Site ID:	376243
Closed Date:	2008-12-04
Spill Number:	0611580
Spill Date:	2007-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-18
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE
Spiller Company:	BUSINESS
Spiller Address:	277 NORTH AVE
Spiller County:	001
Spiller Contact:	BRUCE
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11648 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"PIN HOLE IN TANK"

All TTF:

Facility ID:	0611580
Spill Number:	0611580
Spill Tank Test:	1550567
Site ID:	376243
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

BUSINESS (Continued) **S108467526**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 376243
Operable Unit ID: 1133835
Operable Unit: 01
Material ID: 2123664
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

G55 **EAST RIVER SAVINGS BANK** **NY LTANKS** **U003647446**
NNE **277 NORTH AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.073 mi.
386 ft. **Site 6 of 6 in cluster G**

Relative:
Lower

Actual:
81 ft.

LTANKS:
Facility ID: 8912285
Site ID: 271129
Closed Date: 1991-01-16
Spill Number: 8912285
Spill Date: 1990-03-26
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
SWIS: 6010
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1990-03-27
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1990-03-29
Spill Record Last Update: 1991-03-19
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

EAST RIVER SAVINGS BANK (Continued) **U003647446**

DEC Region: 3
DER Facility ID: 220684
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/19/91: TANK WAS REKINED AND PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks: "TANK WAS ISOLATED AND THEY WILL RETEST PETRO-TITE -.3385 GPH"

All TTF:
Facility ID: 8912285
Spill Number: 8912285
Spill Tank Test: 1536885
Site ID: 271129
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 271129
Operable Unit ID: 937979
Operable Unit: 01
Material ID: 441756
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

F56 **CON EDISON** **NY Spills** **S109206705**
SSE **19 DIVISION ST & WASHINGTON AV** **NY MANIFEST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
422 ft. **Site 2 of 5 in cluster F**

Relative:
Higher

Actual:
100 ft.

SPILLS:
Facility ID: 0804960
Facility Type: ER
Spill Number: 0804960
DER Facility ID: 351169
Site ID: 401964
DEC Region: 3
Closed Date: 2008-08-16
Spill Cause: Equipment Failure
Spill Class: C4

CON EDISON (Continued) **S109206705**

SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-08-16
Spiller Name:	ERTSDESK
Spiller Company:	ARIEL CABLE
Spiller Address:	19 DIVISION STREET/WASHIN
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"CONTRACTOR ENROUTE"
Remarks:	"6 OUNCES AND ONGOING AND CRW WILL BE ENROUTE"

All Materials:

Site ID:	401964
Operable Unit ID:	1158736
Operable Unit:	01
Material ID:	2149826
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004800058
Facility Status:	Not reported
Location Address 1:	WASHINGTON ST & HUEGONOT AVE
Code:	BP
Location Address 2:	MH 7241
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004800058
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL

CON EDISON (Continued) **S109206705**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2015
Trans1 Recv Date:	06/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004800058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469241JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	819
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S109206705**

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

H57 **ANDERSON DEVELOPMENT GROUP** **NY UST** **U003994331**
ENE **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 1 of 9 in cluster H**

Relative: **Lower**

Actual: **90 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-185515 / Unregulated
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	7. Excavation/trench Liner system
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron

ANDERSON DEVELOPMENT GROUP (Continued) **U003994331**

Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

H58 **NORTH AVE REALITY** **NY LTANKS** **S103559119**
ENE **5 ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.081 mi.
427 ft. **Site 2 of 9 in cluster H**

Relative: **Lower**
Actual: **90 ft.**

LTANKS:

Facility ID:	8803214
Site ID:	68769
Closed Date:	1989-11-30
Spill Number:	8803214
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-28
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	YOSHIAKI KOWANISHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	281826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K FAILED 4-GAL. PER HOUR"

All TTF:

Facility ID:	8803214
Spill Number:	8803214
Spill Tank Test:	1534286
Site ID:	68769
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported

NORTH AVE REALITY (Continued) **S103559119**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68769
Operable Unit ID:	918394
Operable Unit:	01
Material ID:	458777
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9812584
Site ID:	68770
Closed Date:	1999-07-12
Spill Number:	9812584
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	2003-07-01
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455

NORTH AVE REALITY (Continued) **S103559119**

DEC Memo: ""
Remarks: "TESTED TANK, TANK FAILED."

All TTF:
Facility ID: 9812584
Spill Number: 9812584
Spill Tank Test: 1546738
Site ID: 68770
Tank Number: 1
Tank Size: 2000
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 68770
Operable Unit ID: 1069836
Operable Unit: 01
Material ID: 557973
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Facility ID: 9812585
Site ID: 68771
Closed Date: 1999-07-12
Spill Number: 9812585
Spill Date: 1999-01-12
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1999-01-12
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False

NORTH AVE REALITY (Continued) **S103559119**

Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	1999-09-07
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

All TTF:

Facility ID:	9812585
Spill Number:	9812585
Spill Tank Test:	1546739
Site ID:	68771
Tank Number:	2
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68771
Operable Unit ID:	1069838
Operable Unit:	01
Material ID:	312860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H59 **ANDERSON DEVELOPMENT GROUP** **NY AST** **A100276594**
ENE **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 3 of 9 in cluster H**

Relative: **Lower**
Actual: **90 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-185515
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Yonkers, NY 10701
Tank Number:	01
Status:	6. Closed - Work Permit Open
Date Installation:	04/01/1999
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	02/10/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access),5. Synthetic Liner
Piping Location:	1. Aboveground
Piping Type:	2. Galvanized Steel
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

E60 **CON EDISON** **NY MANIFEST** **S117538298**
ENE **ANDERSON ST & NORTH AV** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 7 of 18 in cluster E**

Relative: **Lower**
Actual: **90 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004709622
Facility Status:	Not reported
Location Address 1:	ANDERSON ST & NORTH AV
Code:	BP
Location Address 2:	SB2063
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004709622
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117538298**

Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709622
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773453JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117538298**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E61 **CON EDISON** **NY MANIFEST** **S118088384**
ENE **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 8 of 18 in cluster E**

Relative:
Lower

Actual:
90 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004759452
Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759452
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091137JJK
Import Indicator:	N

CON EDISON (Continued) **S118088384**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

E62 **CON EDISON TRANSFORMER MANHOLE: 3585** **RCRA NonGen / NLR** **1016963788**
ENE **NORTH AVE & ANDERSON ST** **NY MANIFEST** **NYP004367611**
< 1/8 **NEW ROCHELLE, NY 10802**
0.081 mi.
428 ft. **Site 9 of 18 in cluster E**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	10/29/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3585
Facility address:	NORTH AVE & ANDERSON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004367611
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
90 ft.

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 3585
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004367611
Facility Status: Not reported
Location Address 1: NORTH AVE & ANDERSON ST
Code: BP
Location Address 2: TM3585
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004367611
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Generator Ship Date:	09/29/2013
Trans1 Recv Date:	09/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/02/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004367611
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694650JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E63 **CON EDISON** **RCRA NonGen / NLR** **1018281020**
ENE **NORTH AVE & ANDERSON** **FINDS** **NYP004759452**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.081 mi.
428 ft. **Site 10 of 18 in cluster E**

Relative: **Lower**
Actual: **90 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/28/2015
Facility name:	CON EDISON
Facility address:	NORTH AVE & ANDERSON NEW ROCHELLE, NY 10801
EPA ID:	NYP004759452

CON EDISON (Continued) **1018281020**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/28/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067686427

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281020
Registry ID: 110067686427
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067686427

E64 **CON EDISON** **NJ MANIFEST** **S120669728**
ENE **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 11 of 18 in cluster E**

Relative:
Lower

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004759452
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091137JJK
EPA ID:	NYP004759452
Date Shipped:	3/28/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669728**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

E65 **CON EDISON** **NY MANIFEST** **S113920666**
ENE **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 12 of 18 in cluster E**

Relative:
Lower

Actual:
90 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004683272
Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004683272
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2014
Trans1 Recv Date:	10/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

CON EDISON (Continued) **S113920666**

Manifest Tracking Number:	012773173JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E66 **CONCRETE FLOORING WITH CRACKS** **NY Spills** **S116554293**
ENE **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.084 mi.
446 ft. **Site 13 of 18 in cluster E**

Relative: SPILLS:
Lower

Actual:
90 ft.

Facility ID:	1400277
Facility Type:	ER
Spill Number:	1400277
DER Facility ID:	448397
Site ID:	493512
DEC Region:	3
Closed Date:	Not reported
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2014-04-08
Investigator:	RDBENDEL
Referred To:	WCDOH PBS
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2014-04-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2014-04-10
Spiller Name:	Not reported
Spiller Company:	STERLING SOLUTIONS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK LANZELLI
DEC Memo:	"4-9-14 Last night I traded voicemails with Jerry. He said that he didn't know anymore than provided to the Hotline and I should talk to Frank in the morning. This morning I spoke to Frank. Location has a 1500 gallon vaulted tank with a remote fill at curb. There is currently some oil in the basement sump. Sump is unplugged and it doesn't appear any was pumped out. Frank doesn't know where oil came from, but vault sounds inaccessible. Frank is trying to contact management company to let them know tank needs to be tested. Management Company: Sterling Solutions, 914/437-6245, Aurora is Almeada contact Owner: Milka Iwanow, 914/409-6513 jc 4/09/14: Email received this morning from Chris Lalak: Sebastian went to this one and will follow up. It is a block away from my office. The tank in a vaulted AST (1500 gallon from 1931). There is a spill across the floor and in cracks in the floor getting to a sump pump. The sump goes to the sanitary. The spill may have been going on for so time, the super was very vague. The AST is visible except for a small area that sticks into the floor of the vault. The tank is not visibly leaking. Almeida replaced the underground lines with above ground lines recently. The between the tank, the former underground lines, and the sump is some distance and they will need to excavate the floor. The building has hired Dutchess. Pumping out the tank is not simple. The building has natural gas and oil. jod 04-09-14 followup email, After a second look at this one with a plumber,It looks like the old lines might be leaking. The plumber will uncover the old lines. The tank is not being pumped out at this time. The bottom of the tank is visible for the most part. (the plumber went in the vault, before we were there).Possibly, the remote fill is also an issue. They will replace the tank with an unregulated tank. Sebastian will continue to handle the spill. The floor will be opened up tomorrow to investigate. RDB "
Remarks:	"Caller advised unknown amount of oil spilled onto concrete floor with cracks. Clean up is pending."

All Materials:

Site ID:	493512
Operable Unit ID:	1243015
Operable Unit:	01
Material ID:	2243651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

E67 **MKM EQUITY, LLC** **NY AST** **A100365275**
ENE **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
446 ft. **Site 14 of 18 in cluster E**

Relative: **Lower**
Actual: **90 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-600105
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MKM Equity, LLC c/o Cornell Pace Inc.
Owner Street:	542 Main Street, Ste. 2
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	08/01/1931
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2014
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	0. None

E68 **CON EDISON** **RCRA NonGen / NLR** **1018281086**
ENE **230 NORTH AVE** **FINDS** **NYP004760179**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.084 mi.
446 ft. **Site 15 of 18 in cluster E**

Relative: **Lower**
Actual: **90 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/30/2015
Facility name:	CON EDISON
Facility address:	230 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004760179
Mailing address:	IRVING PL, 15TH FL NE

CON EDISON (Continued) **1018281086**

NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/30/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067687015

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281086
Registry ID: 110067687015
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067687015

E69 **CON ED** **NY MANIFEST** **S118088454**
ENE **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
446 ft. **Site 16 of 18 in cluster E**

Relative:
Lower

Actual:
90 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004760179
Facility Status:	Not reported
Location Address 1:	OPP 230 NORTH AVE
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760179
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2015
Trans1 Recv Date:	03/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760179
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091109JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON ED (Continued) **S118088454**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

E70 **CON EDISON** **NJ MANIFEST** **S120669791**
ENE **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
446 ft. **Site 17 of 18 in cluster E**

Relative: **Lower**
Actual: **90 ft.**

NJ MANIFEST:

EPA Id:	NYP004760179
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091109JJK
EPA ID:	NYP004760179
Date Shipped:	3/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120669791**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F71 **COMM/RESIDENT. PROPERTY** **NY LTANKS** **S101341321**
SSE **15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.089 mi.
468 ft. **Site 3 of 5 in cluster F**

Relative: **Higher**

Actual: **100 ft.**

LTANKS:

Facility ID:	9405558
Site ID:	119901
Closed Date:	2005-02-10
Spill Number:	9405558
Spill Date:	1994-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-07-25
CID:	Not reported
Water Affected:	Not reported

COMM/RESIDENT. PROPERTY (Continued) **S101341321**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104134
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. Tank taken out of service by Royal Environmental. "
Remarks:	"TANK TEST ON 7/21/94"

All TTF:

Facility ID:	9405558
Spill Number:	9405558
Spill Tank Test:	1542973
Site ID:	119901
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	119901
Operable Unit ID:	1002771
Operable Unit:	01
Material ID:	382138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

E72 **NEW ROCHELLE PUBLIC LIBR.** **NY LTANKS** **S100177858**
East **MEMORIAL HIGHWAY** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
485 ft. **Site 18 of 18 in cluster E**

Relative: **Lower**

Actual: **93 ft.**

LTANKS:

Facility ID:	9111450
Site ID:	306853
Closed Date:	1992-02-06
Spill Number:	9111450
Spill Date:	1992-02-06
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247822
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SOME ON PAVEMENT,SOME IN STORM DRAIN F.D.HAZMAT USED SORBENT TO CONTAIN AND VENTED BUILING SPOKE WITH DEP. CHIEF STONE"

All Materials:

Site ID:	306853
Operable Unit ID:	965176
Operable Unit:	01
Material ID:	416486
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I73 **SEASONWEIN MANAGEMENT LLC** **NY UST** **U003994353**
SSW **54 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.092 mi.
486 ft. **Site 1 of 21 in cluster I**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-169773 / Active
Operator Name:	Matt Seasonwein
Owner Name:	Seasonwein Management LLC
Owner Street:	300 Gramatan Avenue
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10552
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1928
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Actual:
98 ft.

I74 **APARTMENT BLDG** **NY LTANKS** **S105996855**
SSW **54 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
486 ft. **Site 2 of 21 in cluster I**

Relative: LTANKS:
Higher

Facility ID:	0206558
Site ID:	254563
Closed Date:	2005-02-27
Spill Number:	0206558
Spill Date:	2002-09-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-09-24
CID:	390
Water Affected:	Not reported

Actual:
98 ft.

APARTMENT BLDG (Continued) **S105996855**

Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2005-02-27
Spiller Name:	ENERITO GONZALEZ
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AV
Spiller County:	001
Spiller Contact:	ENERITO GONZALEZ
Spiller Phone:	(914) 309-2775
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208499
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 2/27/05 #4 overfill to surface--close "
Remarks:	"spill was noticed on 9/6 - unk when it occurred"

All Materials:

Site ID:	254563
Operable Unit ID:	858169
Operable Unit:	01
Material ID:	517160
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0403405
Site ID:	84302
Closed Date:	2004-12-10
Spill Number:	0403405
Spill Date:	2004-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-06-29
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-29

APARTMENT BLDG (Continued) **S105996855**

Spill Record Last Update:	2004-12-10
Spiller Name:	BASSAM MABER
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AVE
Spiller County:	001
Spiller Contact:	BASSAM MABER
Spiller Phone:	(914) 645-6420
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77542
DEC Memo:	"12/10/04 PBS facility. Tank passed a retest after piping was repaired. Spill file closed by Danielle Jackson of the Westchester County Health Dept. No further action is required at this time. jbo"
Remarks:	"Tank Test Failure. Reccommend Retest."

All TTF:

Facility ID:	0403405
Spill Number:	0403405
Spill Tank Test:	1529391
Site ID:	84302
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84302
Operable Unit ID:	886824
Operable Unit:	01
Material ID:	490990
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I75 **CEMENT COURT YARD** **NY Spills** **S104282704**
SSW **54 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
486 ft. **Site 3 of 21 in cluster I**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Facility ID:	9804849
Facility Type:	ER
Spill Number:	9804849
DER Facility ID:	99871
Site ID:	114515
DEC Region:	3
Closed Date:	2002-07-15
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-07-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-18
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-18
Spill Record Last Update:	2002-07-15
Spiller Name:	Not reported
Spiller Company:	NABER REALTY INC
Spiller Address:	BOX 156H
Spiller Company:	001
Contact Name:	CAPT DIMEGLIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"fd called to an odor of fuel oil in a residence- upon arrival in basement it appeared were working on the oil boiler and were pumping product into sewer thru sump pumps"

All Materials:

Site ID:	114515
Operable Unit ID:	1065894
Operable Unit:	01
Material ID:	319611
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9908117

CEMENT COURT YARD (Continued) **S104282704**

Facility Type:	ER
Spill Number:	9908117
DER Facility ID:	99871
Site ID:	114516
DEC Region:	3
Closed Date:	1999-10-04
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-10-04
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1999-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-04
Spill Record Last Update:	1999-10-06
Spiller Name:	Not reported
Spiller Company:	CEMENT COURT YARD
Spiller Address:	54 CENTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 10/4/99 SPILLER CLEANED UP. NFA"
Remarks:	"BLDG SUPER OVERORDERED - CLEANED UP"

All Materials:

Site ID:	114516
Operable Unit ID:	1082403
Operable Unit:	01
Material ID:	555958
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	6.00
Oxygenate:	Not reported

I76
SSW
< 1/8
0.098 mi.
520 ft.

CON EDISON
HUGENOT & CENTRE ST
NEW ROCHELLE, NY 10801

Site 4 of 21 in cluster I

NY MANIFEST **S117535592**
N/A

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677530
Facility Status:	Not reported
Location Address 1:	HUGENOT & CENTRE ST
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677530
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677530
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774876JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117535592**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

I77 **CON EDISON** **NY MANIFEST** **S117319603**
SSW **CENTER & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.098 mi.
520 ft. **Site 5 of 21 in cluster I**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004676839
Facility Status:	Not reported
Location Address 1:	CENTER & HUGUENOT
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676839
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S117319603**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770954JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

I78
SSW
< 1/8
0.098 mi.
520 ft.

CON EDISON
CENTRE AVE & HUGUENOT ST
NEW ROCHELLE, NY 10801

Site 6 of 21 in cluster I

NY MANIFEST **S113917500**
N/A

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004332961
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004332961
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2013
Trans1 Recv Date:	07/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004332961
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695949JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S113917500**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

I79 **CON EDISON** **RCRA NonGen / NLR** **1014398803**
SSW **HUGUENOT ST & CENTRE ST** **NYP004211728**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
520 ft. **Site 7 of 21 in cluster I**

Relative: **Higher**
Actual: **96 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/19/2010
Facility name:	CON EDISON
Facility address:	HUGUENOT ST & CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004211728
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON (Continued) **1014398803**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

H80 **CVS PHARMACY #8447** **RCRA-LQG 1014958220**
East **222 NORTH AVE** **NY MANIFEST NYR000194654**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
522 ft. **Site 4 of 9 in cluster H**

Relative: **Lower**
Actual: **91 ft.**

RCRA-LQG:

Date form received by agency:	03/17/2016
Facility name:	CVS PHARMACY #8447
Facility address:	222 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYR000194654
Mailing address:	CVS DR MAIL DROP 23062A WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	401-770-7132
Contact email:	NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CVS ALBANY LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

CVS PHARMACY #8447 (Continued) **1014958220**

Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Owner/operator name: 45 SOUTH MAIN STREET CORP
Owner/operator address: NOT APPLICABLE
RYE, NY 10580
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/20/2011
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: CVS DR
WOONSOCKET, RI 02895
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Owner/operator name: 45 SOUTH MAIN STREET CORP
Owner/operator address: GLEN OAKS DR
RYE, NY 10580
Owner/operator country: US
Owner/operator telephone: 917-757-4922
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/20/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

CVS PHARMACY #8447 (Continued) **1014958220**

Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D010
. Waste name: SELENIUM

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

Historical Generators:
Date form received by agency: 03/17/2014
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D010
. Waste name: SELENIUM

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Date form received by agency: 07/01/2013
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

. Waste code: D001

CVS PHARMACY #8447 (Continued) **1014958220**

. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Date form received by agency: 03/05/2012
Site name: CVS PHARMACY #8447
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Biennial Reports:

Last Biennial Reporting Year: 2017

CVS PHARMACY #8447 (Continued) **1014958220**

Annual Waste Handled:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs):	47
Waste code:	D007
Waste name:	CHROMIUM
Amount (Lbs):	33
Waste code:	D010
Waste name:	SELENIUM
Amount (Lbs):	33
Waste code:	P001
Waste name:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs):	9
Waste code:	P075
Waste name:	NICOTINE, & SALTS
Amount (Lbs):	8
Waste code:	U002
Waste name:	ACETONE (I)
Amount (Lbs):	30

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYR000194654
Facility Status:	Not reported
Location Address 1:	222 NORTH AVE.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000194654
Mailing Name:	CVS PHARMACY #8447
Mailing Contact:	CVS PHARMACY #8447
Mailing Address 1:	222 NORTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Mailing Country:	USA
Mailing Phone:	9146377591

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/18/2017
Trans1 Recv Date:	10/18/2017
Trans2 Recv Date:	10/23/2017
TSD Site Recv Date:	10/23/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010052784FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	P001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
69 additional NY_MANIFEST: record(s) in the EDR Site Report.

J81 **DELUXE TAXI** **NY UST** **U001736524**
North **10 STATION PLAZA** **N/A**
< 1/8 **NEW ROCHELLE - WESCHESTER, NY 10801**
0.101 mi.
533 ft. **Site 1 of 11 in cluster J**

Relative:
Lower

Actual:
77 ft.

UST:

Id/Status:	2-601600 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	566353.87500
UTM Y:	4486105.00000
Site Type:	Unknown

Affiliation Records:

Site Id:	23562
Affiliation Type:	Facility Owner
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Mail Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Facility Operator
Company Name:	DELUXE TAXI
Contact Type:	Not reported
Contact Name:	ROCHELLE DELUXE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

DELUXE TAXI (Continued) **U001736524**

Zip Code:	Not reported
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Emergency Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	JOHN TENORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 632-2108
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47103
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	05/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

DELUXE TAXI (Continued) **U001736524**

WESTCHESTER CO. UST:

Id/Status:	3-600004 / Unregulated: <1101 gal. PBS
Operator Name:	Rochell Deluxe Taxi, Inc.
Owner Name:	8 Railroad Place Corporation
Owner Street:	8 Station Plaza South
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	11/03/1993
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

F82 **RPM REALTY INC** **NY UST** **U004240676**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 4 of 5 in cluster F**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-166189 / Active
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City:	Katonah
Owner State:	NY
Owner Zipcode:	10536
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	Not reported
Date Perm Closure:	06/17/1997

RPM REALTY INC (Continued) **U004240676**

Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

F83 **RPM REALTY INC** **NY AST** **A100412045**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 5 of 5 in cluster F**

Relative: **Higher**

Actual: **99 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-166189
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536

Tank Number:	2
Status:	1. In-Service
Date Installation:	06/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

I84 **COMMERCIAL PROPERTY** **NY LTANKS** **S116156733**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.105 mi.
556 ft. **Site 8 of 21 in cluster I**

Relative:
Higher

Actual:
99 ft.

LTANKS:

Facility ID:	1308480
Site ID:	489220
Closed Date:	2015-04-28
Spill Number:	1308480
Spill Date:	2013-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-20
Spill Record Last Update:	2015-05-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	64 CENTRE AVE
Spiller County:	999
Spiller Contact:	STEVE MANGELS
Spiller Phone:	(914) 632-2610
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444316
DEC Memo:	"11-20-13: Chris/WCHD call to V.Mc./Dispt.: Closed Unreg. PBS faciliy. Wayne/WCHD to handle. 11/20/2013 1:48:33 PM:: From Chris Lalak to Wayne Schneider via email:: Wayne, Former PBS site 3-137979 Expired in 1992 (removed gasoline tanks) TTF for Underground waste oil tank estimated as a 550 (Ullage leak and they plan to remove the tank.) The Facility is: M. Hacker and Sons. Please get them to register and deal with the TTF jod 04/23/15 HydroEnvironmental Solutions submitted a report documenting the installation of a temporary monitoring well in the location were the LUST was removed. (See report in DecDocs) Trace levels of VOCs & SVOCs in the sample. TG 4-28-15 closed NFA -RDB"
Remarks:	""

All Materials:

Site ID:	489220
Operable Unit ID:	1238809
Operable Unit:	01
Material ID:	2238759
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported

COMMERCIAL PROPERTY (Continued) **S116156733**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

I85 **HACKER MORRIS J & SONS INC** **EDR Hist Auto** **1020903179**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
556 ft. **Site 9 of 21 in cluster I**

Relative: EDR Hist Auto
Higher

Actual:
99 ft.

Year:	Name:	Type:
1969	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1970	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1971	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1972	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1973	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1974	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1975	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1976	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1977	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1978	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1979	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1980	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1982	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1983	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1985	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1986	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1987	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1988	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1989	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1990	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1991	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1992	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1993	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1994	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1995	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1996	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1997	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1998	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1999	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2000	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2001	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2002	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2003	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2004	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2005	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2006	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2007	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2008	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2009	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2010	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2011	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2012	MORRIS J HACKER & SONS INC	General Automotive Repair Shops

HACKER MORRIS J & SONS INC (Continued) **1020903179**

2013	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2014	MORRIS J HACKER & SONS INC	General Automotive Repair Shops

---

I86 **M.J. HACKER & SONS INC.** **NY UST** **U004176847**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
556 ft. **Site 10 of 21 in cluster I**

Relative: **Higher**

Actual: **99 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-137979 / Unregulated
Operator Name:	Steve Mangels
Owner Name:	Steve Mangels
Owner Street:	64 Centre Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	3a. Closed - Prior to 04/1991
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1973
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	002
Status:	3a. Closed - Prior to 04/1991
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1980
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None

M.J. HACKER & SONS INC. (Continued) **U004176847**

Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	003
Status:	8. Unregistered
Capacity:	500
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	004
Status:	3. Closed - Removed
Capacity:	750
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	05/12/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	005
Status:	3. Closed - Removed
Capacity:	Not reported
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900

M.J. HACKER & SONS INC. (Continued) **U004176847**

Date Perm Closure:	05/14/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1979
Date Perm Closure:	03/06/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

I87 **ERIC S TURNER & CO INC.** **RCRA-CESQG** **1007204937**
SSW **33-35 CENTRE AVE** **NY MANIFEST** **NYD002015402**
< 1/8 **NEW ROCHELLE, NY 10801** **NJ MANIFEST**
0.106 mi.
560 ft. **Site 11 of 21 in cluster I**

Relative: **Lower**

Actual: **92 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	ERIC S TURNER & CO INC.
Facility address:	33-35 CENTRE AVE NEW ROCHELLE, NY 10801-0000
EPA ID:	NYD002015402
Mailing address:	PO BOX #816 NEW ROCHELLE, NY 10801-0000
Contact:	WILLIAM TURNER
Contact address:	PO BOX #816 NEW ROCHELLE, NY 10801-0000
Contact country:	US
Contact telephone:	914-235-7114
Telephone ext.:	9999
Contact email:	Not reported
EPA Region:	02

ERIC S TURNER & CO INC. (Continued) **1007204937**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ERIC S TURNER & CO INC.
Classification: Small Quantity Generator

Date form received by agency: 03/18/2005
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Date form received by agency: 03/21/1994
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD002015402
Facility Status: Not reported
Location Address 1: 33-35 CENTRE AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE

ERIC S TURNER & CO INC. (Continued) **1007204937**

Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD002015402
Mailing Name:	ERIC S TURNER & CO INC.
Mailing Contact:	W V TURNER PRESIDENT
Mailing Address 1:	P. O. BOX 816
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142357114

NY MANIFEST:

Document ID:	NJA5224399
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NJAF906B
Trans2 State ID:	58746
Generator Ship Date:	12/06/2004
Trans1 Recv Date:	12/06/2004
Trans2 Recv Date:	12/07/2004
TSD Site Recv Date:	12/08/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJR000022
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)

ERIC S TURNER & CO INC. (Continued) **1007204937**

Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
14 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYD002015402
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	9142357114
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5224399
EPA ID:	NYD002015402
Date Shipped:	12/06/2004
TSDF EPA ID:	NJR000022442
Transporter EPA ID:	NJR000023325
Transporter 2 EPA ID:	OHD009865825
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/06/2004
Date Trans2 Transported Waste:	12/07/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01250521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

K88 **I-95** **NY Spills** **S102152708**
WSW **I-95EB MP54** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 1 of 2 in cluster K**

Relative: **Lower**

Actual: **79 ft.**

SPILLS:

Facility ID:	8700158
Facility Type:	ER
Spill Number:	8700158
DER Facility ID:	105126
Site ID:	121121
DEC Region:	3
Closed Date:	1987-04-07
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1987-04-07
Investigator:	WEED
Referred To:	Not reported
Reported to Dept:	1987-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	1987-04-07
Cleanup Meets Std:	True
Last Inspection:	1987-04-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-04-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN

I-95 (Continued) **S102152708**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""
Remarks: ""

All Materials:
Site ID: 121121
Operable Unit ID: 904779
Operable Unit: 01
Material ID: 473726
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

K89 **P&D TRANSPORT - HOT TAR** **NY Spills** **S106126552**
WSW **I-95 NB @ MM 5.4** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 2 of 2 in cluster K**

Relative:
Lower

Actual:
79 ft.

SPILLS:
Facility ID: 0308809
Facility Type: ER
Spill Number: 0308809
DER Facility ID: 265298
Site ID: 329742
DEC Region: 3
Closed Date: 2003-11-26
Spill Cause: Equipment Failure
Spill Class: B2
SWIS: 6010
Spill Date: 2003-11-18
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2003-11-18
CID: 270
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Police Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-11-18
Spill Record Last Update: 2003-12-02
Spiller Name: Not reported
Spiller Company: P&D TRANSPORT
Spiller Address: 171 BROWNSTONE AVE
Spiller Company: 001

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11-18-03 P&D Transport trailer carrying 5000 gallons of a hot tar product developed several leaks from seams and holes beneath the trailer. The driver, John Culbreath, pulled the vehicle to the shoulder of I-95 NB at mm 5.4 in New Rochelle. The trailer drained hot tar to the road shoulder where it flowed downhill until it cooled and solidified. Approximatley 200 feet of shoulder where affected before the trailer could be offloaded. DEC called out Castlton Environmental contractors when a company Rep stated that he/she would not sent a second truck to offload the damaged trailer. Castlton contacted Mystic Bulk Carriers and requested their assistance. Mystic provided a heated truck, suitable to offload the cargo and return it to Ownes Corning in Kearny where the load was originally picked up. The P&D damaged trailer was towed off the road to a spot near the I-95 toll plaza. Castlton performed the removal of the solidified tar several days later as they were delayed by heavy rain which created hazardous working conditions on busily traveled I-95. As of 11-18-03, Portland Asphalt indicated that they would pay Caslton directly for the cost of the cleanup. "
Remarks: "material goes into a manhole which leads to a water way. poss hutchinson river. spill not controlled yet. caller req call back from rep"

All Materials:
Site ID: 329742
Operable Unit ID: 877435
Operable Unit: 01
Material ID: 498725
Material Code: 0018A
Material Name: tar
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

L90 **DEPOT PLACE LLC** **NY UST** **U003994482**
NNW **1 DEPOT PLACE** **N/A**
< 1/8 **MAMARONECK (T), NY**
0.106 mi.
562 ft. **Site 1 of 5 in cluster L**

Relative: WESTCHESTER CO. UST:
Lower
Id/Status: 3-801085 / Unregulated: <1101 gal. PBS
Actual: Operator Name: Not reported
72 ft. Owner Name: Depot LLC
Owner Street: 1 Depot Place
Owner Address2: Not reported
Owner City: Mamaroneck
Owner State: NY
Owner Zipcode: Not reported
GDS Number: Not reported

Tank Number: 001
Status: 4. Closed - in place

DEPOT PLACE LLC (Continued) **U003994482**

Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/21/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

L91 **STATION CLEANERS** **NY DRYCLEANERS** **S110247994**
NNW **1 DEPOT PLAZA #1** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.106 mi.
562 ft. **Site 2 of 5 in cluster L**

Relative: **Lower**

Actual: **72 ft.**

DRYCLEANERS:

Facility ID:	---
Phone Number:	Not reported
Region:	3
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	???

I92 **SIMONETTI CLEANERS & TAYLORING** **EDR Hist Cleaner** **1020088094**
South **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
573 ft. **Site 12 of 21 in cluster I**

Relative: **Higher**

EDR Hist Cleaner

Actual: **98 ft.**

Year:	Name:	Type:
1980	GEM CLEANERS	Drycleaning Plants, Except Rugs
1982	GEM CLEANERS	Drycleaning Plants, Except Rugs
1983	GEM CLEANERS	Drycleaning Plants, Except Rugs
1985	GEM CLEANERS	Drycleaning Plants, Except Rugs
1986	GEM CLEANERS	Drycleaning Plants, Except Rugs
1987	GEM CLEANERS	Drycleaning Plants, Except Rugs
1988	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1989	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1990	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1991	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC

SIMONETTI CLEANERS & TAYLORING (Continued) **1020088094**

1992	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1993	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1994	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1995	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1996	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1997	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1998	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1999	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2000	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2001	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2002	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2003	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2004	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2005	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2006	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2007	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2008	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2009	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2010	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2011	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2012	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2013	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2014	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC

I93 **SIMONETTI CLEANERS** **RCRA-CESQG** **1000338662**
South **62 CENTRE ST** **US AIRS** **NYD982531634**
< 1/8 **NEW ROCHELLE, NY 10801** **FINDS**
0.109 mi. **ECHO**
573 ft. **Site 13 of 21 in cluster I** **NY MANIFEST**

Relative: **Higher**

Actual: **98 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	SIMONETTI CLEANERS
Facility address:	62 CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYD982531634
Mailing address:	CENTRE ST NEW ROCHELLE, NY 10801
Contact:	KWANG YUN
Contact address:	CENTRE ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-5350
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

SIMONETTI CLEANERS (Continued) **1000338662**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KWANG YUN
Owner/operator address:	24 SUMMIT AVE MOUNT VERNON, NY 10550
Owner/operator country:	US
Owner/operator telephone:	914-665-0274
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KWANG YUN
Owner/operator address:	24 SUMMIT AVE MOUNT VERNON, NY 10550
Owner/operator country:	US
Owner/operator telephone:	914-665-0274
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	SIMONETTI CLEANERS
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	03/21/1996
Site name:	SIMONETTI CLEANERS
Classification:	Small Quantity Generator

SIMONETTI CLEANERS (Continued) **1000338662**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

US AIRS MINOR:
Envid: 1000338662
Region Code: 02
Programmatic ID: AIR 020000003606156000
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

Envid: 1000338662
Region Code: 02
Programmatic ID: AIR NY0000003551000298
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Envid: 1000338662
Region Code: 02
Programmatic ID: AIR 020000003606156000
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216

SIMONETTI CLEANERS (Continued) **1000338662**

NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

Envid: 1000338662
Region Code: 02
Programmatic ID: AIR NY0000003551000298
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:

Registry ID: 110012174805

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000338662
Registry ID: 110012174805
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012174805

SIMONETTI CLEANERS (Continued) **1000338662**

NY MANIFEST:

Country:	USA
EPA ID:	NYD982531634
Facility Status:	Not reported
Location Address 1:	62 CENTRE AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982531634
Mailing Name:	SIMONETTI CLEANERS
Mailing Contact:	SIMONETTI CLEANERS
Mailing Address 1:	62 CENTRE AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146365350

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD000664906
Trans2 State ID:	CDX761010010
Generator Ship Date:	01/10/2009
Trans1 Recv Date:	01/10/2009
Trans2 Recv Date:	01/16/2009
TSD Site Recv Date:	01/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	004562249JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	390.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
85 additional NY_MANIFEST: record(s) in the EDR Site Report.

I94 **GREEN HEAVEN/CENTRE CLEANERS** **NY DRYCLEANERS** **S106437149**
South **62 CENTRE AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
573 ft. **Site 14 of 21 in cluster I**

Relative: **Higher**
Actual: **98 ft.**

DRYCLEANERS:

Facility ID:	3-5510-00298
Phone Number:	914-636-5350
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	11SEP8
Install Date:	88/98
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF2000
Current Business:	Not reported

M95 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016963532**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004365318**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
593 ft. **Site 1 of 11 in cluster M**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/24/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004365318
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/24/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 4319
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004365318
Facility Status: Not reported
Location Address 1: CENTRE AVE & RELYEA PL
Code: BP
Location Address 2: TM 4319
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004365318
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/24/2013
Trans1 Recv Date:	09/24/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004365318
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694707JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M96 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016965006**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004379020**
< 1/8 **NEW ROCHELLE, NY 10802**
0.112 mi.
593 ft. **Site 2 of 11 in cluster M**

Relative:
Lower

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10802
EPA ID:	NYP004379020
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/23/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 4319
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004379020
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & RELYEA PL
Code:	BP
Location Address 2:	SB4314
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004379020
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693664JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

N97 **CON EDISON** **NY MANIFEST** **S119077729**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.113 mi.
596 ft. **Site 1 of 6 in cluster N**

Relative: **Lower**
Actual: **88 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004837407
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & LECOUNT PL
Code:	BP
Location Address 2:	V 7723
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004837407
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/2015
Trans1 Recv Date:	09/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837407
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S119077729**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472144JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

N98 **CON EDISON MANHOLE 1178** **RCRA NonGen / NLR** **1014918331**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219455**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.113 mi.
596 ft. **Site 2 of 6 in cluster N**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/03/2010
Facility name:	CON EDISON MANHOLE 1178
Facility address:	HUGUENOT ST & LECOUNT PL MH 1178 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219455
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/03/2010
Site name: CON EDISON MANHOLE 1178
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004219455
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DOMINIC BIZZARO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874912JJK
EPA ID: NYP004219455
Date Shipped: 11/03/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004219455
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & LE COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219455
Mailing Name:	CONSOLIDATED EDISON - MH 1178
Mailing Contact:	TOM TEELING

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2010
Trans1 Recv Date:	11/03/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219455
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874912JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

N99 **CON EDISON** **NJ MANIFEST** **S120676596**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.113 mi.
596 ft. **Site 3 of 6 in cluster N**

Relative:
Lower

Actual:
88 ft.

NJ MANIFEST:

EPA Id:	NYP004837407
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472144JJK
EPA ID:	NYP004837407
Date Shipped:	9/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120676596**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N100 **CON EDISON MANHOLE 1181** **RCRA NonGen / NLR** **1014918324**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219380**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.113 mi.
596 ft. **Site 4 of 6 in cluster N**

Relative: **Lower**

Actual: **88 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/02/2010
Facility name:	CON EDISON MANHOLE 1181
Facility address:	HUGUENOT ST & LECOUNT PL MH 1181 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219380
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Historical Generators:
Date form received by agency: 11/02/2010
Site name: CON EDISON MANHOLE 1181
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004219380
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874911JJK
EPA ID:	NYP004219380
Date Shipped:	11/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004219380
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & LE COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219380
Mailing Name:	CONSOLIDATED EDISON - MH 1181
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/02/2010
Trans1 Recv Date:	11/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Generator EPA ID:	NYP004219380
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874911JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

N101 **CON EDISON** **RCRA NonGen / NLR** **1019907724**
NE **HUGUENOT ST & LE COUNT PL** **NYP004837407**
< 1/8 **NEW ROCHELLE, NY 10801**
0.113 mi.
596 ft. **Site 5 of 6 in cluster N**

Relative: **Lower**

Actual: **88 ft.**

RCRA NonGen / NLR:

Date form received by agency:	09/11/2015
Facility name:	CON EDISON
Facility address:	HUGUENOT ST & LE COUNT PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004837407
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported

CON EDISON (Continued) **1019907724**

Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/11/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

H102 **SPEEDY CLEANERS** **US AIRS 1006295756**
East **217 NORTH AVENUE** **FINDS N/A**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.113 mi. **NY DRYCLEANERS**
597 ft. **Site 5 of 9 in cluster H**

Relative:
Lower

Actual:
91 ft.

US AIRS MINOR:
Envid: 1006295756
Region Code: 02
Programmatic ID: AIR NY0000003551000344
Facility Registry ID: 110012166921
D and B Number: Not reported
Primary SIC Code: 7212
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Envid: 1006295756
Region Code: 02
Programmatic ID: AIR NY0000003551000344
Facility Registry ID: 110012166921
D and B Number: Not reported
Primary SIC Code: 7212
NAICS Code: 812320

SPEEDY CLEANERS (Continued) **1006295756**

Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:

Registry ID: 110012166921

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1006295756
Registry ID: 110012166921
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012166921

DRYCLEANERS:
Facility ID: 3-5510-00344
Phone Number: 914-654-9082
Region: Not reported
Registration Effective Date: 9/24/2003 13:22:51:203
Inspection Date: 03DEC31
Install Date: 00/03
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

I103 **VERIZON** **NY Spills** **S106867403**
SSW **342 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.115 mi.
608 ft. **Site 15 of 21 in cluster I**

Relative: **Lower**

Actual: **95 ft.**

SPILLS:

Facility ID:	0413326
Facility Type:	ER
Spill Number:	0413326
DER Facility ID:	288752
Site ID:	342403
DEC Region:	3
Closed Date:	2005-09-11
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-03-22
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-22
Spill Record Last Update:	2005-09-11
Spiller Name:	CLAUDIA
Spiller Company:	VERIZON
Spiller Address:	342 HUGUENOT ST.
Spiller Company:	001
Contact Name:	CLAUDIA
DEC Memo:	"September 11, 2005: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank is tight has a bad vent line. Will be replacing the vent line."

All TTF:

Facility ID:	0413326
Spill Number:	0413326
Spill Tank Test:	1548716
Site ID:	342403
Tank Number:	6
Tank Size:	6000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog

VERIZON (Continued) **S106867403**

Last Modified Date: Not reported

All Materials:
Site ID: 342403
Operable Unit ID: 1101130
Operable Unit: 01
Material ID: 581261
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

I104 **NYNEX LOCATION** **NY LTANKS** **S102660218**
SSW **342 HUEGNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.115 mi.
608 ft. **Site 16 of 21 in cluster I**

Relative: LTANKS:
Lower
Actual: Facility ID: 9708146
95 ft. Site ID: 270876
Closed Date: 1997-10-10
Spill Number: 9708146
Spill Date: 1997-10-10
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-10-10
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-10-10
Spill Record Last Update: 1997-11-12
Spiller Name: RICH KALISTA
Spiller Company: BELL ATLANTIC
Spiller Address: 2203 MCCONNELL ST
Spiller County: 001
Spiller Contact: TOM MUFF
Spiller Phone: (914) 449-5321
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 220510
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

NYNEX LOCATION (Continued) **S102660218**

GHIOSAY "
Remarks: "DOING AN UPGRADE FOR A NYNEX LOCATION AND REMOVING 2 UNDERGROUND TANKS FROM A BASEMENT - TANKS WERE ENCASED BY SAND & WHEN REMOVED THE SAND WAS CONTAMINATED - THEY HAVE REMOVED SAND."

All Materials:
Site ID: 270876
Operable Unit ID: 1051372
Operable Unit: 01
Material ID: 330133
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

I105 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000553730**
SSW **342 HUGUENOT ST** **NY MANIFEST** **NYD986961605**
< 1/8 **NEW ROCHELLE, NY 10801**
0.115 mi.
608 ft. **Site 17 of 21 in cluster I**

Relative: **Lower**
Actual: **95 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NEW YORK TELEPHONE CO
Facility address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYD986961605
Mailing address: NINTH AVE
NEW YORK, NY 10001
Contact: CATHERINE ROM
Contact address: NINTH AVE
NEW YORK, NY 10001
Contact country: US
Contact telephone: 212-502-7694
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-632-9964
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

NEW YORK TELEPHONE CO (Continued) **1000553730**

Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-632-9964
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

Date form received by agency: 07/02/1991
Site name: NEW YORK TELEPHONE CO
Classification: Small Quantity Generator

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD986961605
Facility Status: Not reported
Location Address 1: 342 HUGANAUGHT STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WESTCHESTER
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NEW YORK TELEPHONE CO (Continued) **1000553730**

NY MANIFEST:

EPAID:	NYD986961605
Mailing Name:	TELESECTOR RESOURCES GROUP
Mailing Contact:	WAYNE SEBRO
Mailing Address 1:	441 9TH AVENUE 5TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125027694

NY MANIFEST:

Document ID:	ILA7651009
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	1478
Trans2 State ID:	2075
Generator Ship Date:	10/23/1997
Trans1 Recv Date:	10/23/1997
Trans2 Recv Date:	10/23/1997
TSD Site Recv Date:	10/29/1997
Part A Recv Date:	11/26/1997
Part B Recv Date:	11/20/1997
Generator EPA ID:	NYD986961605
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	NJD000813477
TSDF ID 1:	ILD000608471
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES

NEW YORK TELEPHONE CO (Continued) **1000553730**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

J106 **SPOKEN ARTS BUILDING (FORMER)** **NY UST** **U003885171**
North **310 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.115 mi.
608 ft. **Site 2 of 11 in cluster J**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-600705 / Unregulated: <1101 gal. PBS
Operator Name:	Mr. Anthony Blaise
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

Actual:
75 ft.

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1994
Date Perm Closure:	09/01/1994
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

J107 **NORTH GARDEN ASSOCIATES LLC** **NY UST** **U004177039**
North **309-311 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.118 mi.
622 ft. **Site 3 of 11 in cluster J**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-496928 / Active
Operator Name:	Harrin Platzner
Owner Name:	North Garden Associates LLC
Owner Street:	P.O Box 111
Owner Address2:	309-311 North Avenue
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/15/1947
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	2. Suction

Actual:
74 ft.

M108 **APPAREL PLUS** **NY Spills** **S116156116**
SW **27 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.118 mi.
623 ft. **Site 3 of 11 in cluster M**

Relative: SPILLS:
Lower

Facility ID:	1309988
Facility Type:	ER
Spill Number:	1309988
DER Facility ID:	445839
Site ID:	490810
DEC Region:	3
Closed Date:	2014-01-14
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2014-01-14
Investigator:	DXWEITZ
Referred To:	Not reported
Reported to Dept:	2014-01-14
CID:	Not reported

Actual:
88 ft.

APPAREL PLUS (Continued) **S116156116**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-14
Spill Record Last Update:	2014-01-14
Spiller Name:	CHRIS LALAK
Spiller Company:	APPAREL PLUS LAUNDRY
Spiller Address:	27 CENTRE AVE
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"1/14/14 Chris Lalak from WCHD called and said that this was motor oil from a truck in the parking lot. People at the laundry did the cleanup. According to Chris Lalak, the spill can be closed. They were there for other reasons. NFA dw"
Remarks:	"loss to sewer. c/u in progress"

All Materials:

Site ID:	490810
Operable Unit ID:	1240364
Operable Unit:	01
Material ID:	2240510
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

O109 **SIDNEY FURNITURE** **NY Spills** **S118460140**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 1 of 19 in cluster O**

Relative: **Higher**
Actual: **99 ft.**

SPILLS:

Facility ID:	1509029
Facility Type:	ER
Spill Number:	1509029
DER Facility ID:	75076
Site ID:	517634
DEC Region:	3
Closed Date:	2015-12-04
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010
Spill Date:	2015-12-03
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-12-04

SIDNEY FURNITURE (Continued) **S118460140**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-04
Spill Record Last Update:	2015-12-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHELLE GUERRERO
DEC Memo:	"12/04/15: Caller states she is at work, states she is pregnant, and states that they were working on the furnace and there was a small oil spill. She wanted to know if oil spills are hazardous. I was in the process of answering her questions and she hung up. Westchester County Dept of Health notified. No further DEC action. jod"
Remarks:	"Caller advised aprx 1/2 gal of oil spilled onto carpet. Clean up is pending. Caller is requesting a call back"

All Materials:

Site ID:	517634
Operable Unit ID:	1266703
Operable Unit:	01
Material ID:	2270652
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

O110 **535 MAIN ST ASSOCIATION** **NY Spills** **S104648843**
SSE **535 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 2 of 19 in cluster O**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9415294
Facility Type:	ER
Spill Number:	9415294
DER Facility ID:	205781
Site ID:	251083
DEC Region:	3
Closed Date:	1995-03-03
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	6010
Spill Date:	1995-02-17

535 MAIN ST ASSOCIATION (Continued) **S104648843**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER DID NOT HEAR VENT ALARM AND OVERFILLED TANK REGENT OIL CLEANED UP"

All Materials:

Site ID:	251083
Operable Unit ID:	1012611
Operable Unit:	01
Material ID:	370473
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9900400
Facility Type:	ER
Spill Number:	9900400
DER Facility ID:	75076
Site ID:	81102
DEC Region:	3
Closed Date:	1999-07-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-04-08
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-04-12
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other

535 MAIN ST ASSOCIATION (Continued) **S104648843**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-12
Spill Record Last Update:	2004-02-24
Spiller Name:	MR GOLDBERG
Spiller Company:	MR GOLDBERG
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MR GOLDBERG
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/9/99 SPILL CLEANED BY TOWN & COUNTRYF OIL. NFA"
Remarks:	"FAULTY VENT ALARM - SPILLED LESS THAN 1 GAL - CLEANED UP - TENANTS STILL COMPLAINING OF ODORS"

All Materials:

Site ID:	81102
Operable Unit ID:	1075164
Operable Unit:	01
Material ID:	307538
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L111 **COMMERCIAL - UST** **NY Spills** **S121119478**
NNW **35 GRAND STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.121 mi.
641 ft. **Site 3 of 5 in cluster L**

Relative: **Lower**
Actual: **76 ft.**

SPILLS:

Facility ID:	1706607
Facility Type:	ER
Spill Number:	1706607
DER Facility ID:	514557
Site ID:	560927
DEC Region:	3
Closed Date:	Not reported
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	2017-10-06
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2017-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other

COMMERCIAL - UST (Continued) **S121119478**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2017-10-06
Spill Record Last Update:	2017-10-16
Spiller Name:	Not reported
Spiller Company:	The Luxuria
Spiller Address:	35 GRAND STREET
Spiller Company:	999
Contact Name:	GARY GIGLIO
DEC Memo:	"10/6/17 - A 1k gal. UST was removed. Laboratory soil post excavation samples were collected. TCR will be submitted to the DEC. KAB"
Remarks:	"underground 1,000 gallon oil tank. clean up is on going."

All TTF:

Facility ID:	1706607
Spill Number:	1706607
Spill Tank Test:	2504339
Site ID:	560927
Tank Number:	UST
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	560927
Operable Unit ID:	1308916
Operable Unit:	01
Material ID:	2315940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

O112 **LILLIAN VERNON CORPORATION** **NY UST** **U003994695**
SSE **543-549 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
648 ft. **Site 3 of 19 in cluster O**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-600279 / Unregulated: <1101 gal. PBS
Operator Name:	Joseph F. Dimicco
Owner Name:	Lillian Vernon Corp.
Owner Street:	510 South Fulton Ave
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10550
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Actual:
100 ft.

O113 **BLUE GILL REALTY** **NY LTANKS** **S102152290**
SSE **543 MAIN ST** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
648 ft. **Site 4 of 19 in cluster O**

Relative: LTANKS:
Higher

Facility ID:	0308082
Site ID:	94435
Closed Date:	2004-05-12
Spill Number:	0308082
Spill Date:	2003-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-10-30
CID:	252
Water Affected:	Not reported

Actual:
100 ft.

BLUE GILL REALTY (Continued) **S102152290**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-05-19
Spiller Name:	JEFF WEIR
Spiller Company:	BLUE GILL REALTY
Spiller Address:	543 MAIN ST
Spiller County:	001
Spiller Contact:	JEFF WEIR
Spiller Phone:	(646) 435-8110
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	84546
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MAGNUSON 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #9212475. Letter has PBS #3-801106."
Remarks:	"TANK HAS BEEN REMOVED."

All TTF:

Facility ID:	0308082
Spill Number:	0308082
Spill Tank Test:	1528780
Site ID:	94435
Tank Number:	1
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	94435
Operable Unit ID:	876585
Operable Unit:	01
Material ID:	501599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

BLUE GILL REALTY (Continued) **S102152290**

Oxygenate: Not reported

SPILLS:

Facility ID:	9212475
Facility Type:	ER
Spill Number:	9212475
DER Facility ID:	108333
Site ID:	125220
DEC Region:	3
Closed Date:	2004-05-12
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	1993-02-03
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2004-05-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #0308082."
Remarks:	"FUEL OIL LINE HAS PIN HOLE LEAK DISCOVERED IN EXCAVATION BY EMER.ENVIRO. SERVICE TODAY REMOTE FILL LINE 2 VERY BADLY PITTED AND CORRODED WILL DRILL WELL 2/4/93"

All Materials:

Site ID:	125220
Operable Unit ID:	976940
Operable Unit:	01
Material ID:	402326
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00

BLUE GILL REALTY (Continued) **S102152290**

Oxygenate: Not reported

O114 **543 MAIN STREET** **NY UST** **U003994286**
SSE **543 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
648 ft. **Site 5 of 19 in cluster O**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-801106 / Unregulated: <1101 gal. PBS
Operator Name:	Paul Risse
Owner Name:	Bluegill Realty, LLC
Owner Street:	250 West 30th Street
Owner Address2:	Not reported
Owner City:	NY
Owner State:	NY
Owner Zipcode:	10001
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	2500
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/07/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

H115 **CON EDISON** **NJ MANIFEST** **S120672272**
ENE **LECOUNT PL & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 6 of 9 in cluster H**

Relative: **Lower**
Actual: **90 ft.**

NJ MANIFEST:

EPA Id:	NYP004788378
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported

CON EDISON (Continued) **S120672272**

County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014467901JJK
EPA ID:	NYP004788378
Date Shipped:	5/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

H116 **CON EDISON** **NY MANIFEST** **S119075589**
ENE **LECOUNT PL & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 7 of 9 in cluster H**

Relative:
Lower

Actual:
90 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004788378
Facility Status:	Not reported
Location Address 1:	LECOUTN PL & MAIN ST
Code:	BP
Location Address 2:	SB 1996
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004788378
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2015
Trans1 Recv Date:	05/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004788378
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467901JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S119075589**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

H117 **CON EDISON** **RCRA NonGen / NLR** **1019903661**
ENE **LECOUNT PL & ANDERSON ST** **FINDS** **NYP004788378**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.123 mi.
649 ft. **Site 8 of 9 in cluster H**

Relative: **Lower**

Actual: **90 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/30/2015
Facility name:	CON EDISON
Facility address:	LECOUNT PL & ANDERSON ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004788378
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON (Continued) **1019903661**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/30/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069670270

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903661
Registry ID:	110069670270
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069670270

O118 **CON EDISON - TRANSFORMER MANHOLE 3307** **RCRA-LQG** **1019325947**
SSE **DIVISION ST & MAIN ST** **NYP004872319**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 6 of 19 in cluster O**

Relative:
Higher

Actual:
99 ft.

RCRA-LQG:

Date form received by agency:	02/26/2016
Facility name:	CON EDISON - TRANSFORMER MANHOLE 3307
Facility address:	DIVISION ST & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004872319
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Contact email: BURKARDT@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/23/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/23/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 9020

Violation Status: No violations found

O119 **CON EDISON** **NY MANIFEST** **S118464238**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 7 of 19 in cluster O**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004872319
Facility Status: Not reported
Location Address 1: DIVISION ST & MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004872319
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/23/2015

CON EDISON (Continued) **S118464238**

Trans1 Recv Date:	11/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004872319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245368JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9020
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

O120 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243060**
SSE **DIVISION & MAIN** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.124 mi.
653 ft. **Site 8 of 19 in cluster O**

Relative: NY MANIFEST:
Higher

Actual: Country:	USA
99 ft. EPA ID:	NYP004123873
Facility Status:	Not reported
Location Address 1:	DIVISION & MAIN
Code:	BP
Location Address 2:	Not reported

CONSOLIDATED EDISON (Continued) **1009243060**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004123873
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1309977
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2004
Trans1 Recv Date:	08/28/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	G - Gallons (liquids only)* (8.3 pounds)

CONSOLIDATED EDISON (Continued) **1009243060**

Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

O121 **CON EDISON - TRANSFORMER MANHOLE 3307** **NJ MANIFEST** **S120677907**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 9 of 19 in cluster O**

Relative:
Higher

Actual:
99 ft.

NJ MANIFEST:

EPA Id:	NYP004872319
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	013245368JJK
EPA ID:	NYP004872319
Date Shipped:	11/23/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **S120677907**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P122 **J P MORGAN CHASE BANK N.A.** **NY UST U003885235**
ESE **491 MAIN STREET** **NY AST N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 1 of 9 in cluster P**

Relative: **Lower**
Actual: **94 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-164372 / Active
Operator Name:	Chase
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard, 14th Floor
Owner Address2:	NY1-D213
Owner City:	Jersey City
Owner State:	NJ
Owner Zipcode:	07310
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/05/1990
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

J P MORGAN CHASE BANK N.A. (Continued) **U003885235**

WESTCHESTER CO. AST:

PBS Number:	3-164372
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Chase
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard, 14th Floor
Owner Address2:	NY1-D213
Owner City/State/Zip:	Jersey City, NJ 07310
Tank Number:	02
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

P123 **BARCLAYS BANK OF NY/NA** **NY LTANKS** **S100140601**
ESE **491 MAIN ST.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.124 mi.
653 ft. **Site 2 of 9 in cluster P**

Relative: **Lower**
Actual: **94 ft.**

LTANKS:

Facility ID:	8905129
Site ID:	299548
Closed Date:	1991-03-25
Spill Number:	8905129
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

BARCLAYS BANK OF NY/NA (Continued) **S100140601**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	1997-02-12
Spiller Name:	Not reported
Spiller Company:	BARCLAYS BANK OF NY/NA
Spiller Address:	604 BROAD HOLLOW RD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	242324
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 10/06/89: GND INC. (516) 933-1085 NAT MOSER: 1500 GAL #2 FAILED RETEST -.132GPH. TANK TO BE RELINED OR REPLACED. 03/25/91: TANK REMOVED. "
Remarks:	"NAT MOSER (TELECOM 8-23, 1615) WILL CALL BACK AFTER CONTACTING BARCLAYS AND REVIEWING OPTIONS. PETRO TITE 2K 4 GPH"

All TTF:

Facility ID:	8905129
Spill Number:	8905129
Spill Tank Test:	1535898
Site ID:	299548
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	299548
Operable Unit ID:	930451
Operable Unit:	01
Material ID:	445568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I124 **75 CENTRE AVENUE LLC** **NY UST** **U004175967**
South **75 CENTRE AVENUE** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.125 mi.
661 ft. **Site 18 of 21 in cluster I**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800240 / Active
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	52 North Central Ave.
Owner Address2:	Not reported
Owner City:	Elmsford
Owner State:	NY
Owner Zipcode:	10523
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	Not reported
Date Perm Closure:	11/01/2004
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

PBS Number:	3-800240
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	52 North Central Ave.
Owner Address2:	Not reported
Owner City/State/Zip:	Elmsford, NY 10523
Tank Number:	002
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

75 CENTRE AVENUE LLC (Continued) **U004175967**

Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

J125 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016963395**
North **313 NORTH AVE FRONT OF** **NYP004364030**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.125 mi.
662 ft. **Site 4 of 11 in cluster J**

Relative: **Lower**
Actual: **74 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/20/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	313 NORTH AVE FRONT OF NEW ROCHELLE, NY 10801
EPA ID:	NYP004364030
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/20/2013
Site name:	CON EDISON MANHOLE: 4175
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

Violation Status: No violations found

H126 **MACYS** **NY MANIFEST** **1009232715**
ENE **33 LE COUNT PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.127 mi.
673 ft. **Site 9 of 9 in cluster H**

Relative:
Lower

Actual:
90 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP000890137
Facility Status:	Not reported
Location Address 1:	33 LE COUNT PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000890137
Mailing Name:	MACYS
Mailing Contact:	MACYS
Mailing Address 1:	33 LE COUNT PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337700

NY MANIFEST:

Document ID:	NYA7026894
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	06/22/1989
Trans1 Recv Date:	06/22/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/22/1989
Part A Recv Date:	08/03/1989
Part B Recv Date:	06/29/1989
Generator EPA ID:	NYP000890137
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

MACYS (Continued) **1009232715**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J127 **4 STORY APARTMENT BUILDING** **NY UST** **U003883840**
North **320 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.128 mi.
678 ft. **Site 5 of 11 in cluster J**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-600732 / Unregulated: <1101 gal. PBS
Operator Name:	City Of New Rochelle
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1961
Date Perm Closure:	02/28/1995
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	12. Double-Walled (AST only)
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported

Actual:
72 ft.

4 STORY APARTMENT BUILDING (Continued) **U003883840**

Dispenser:	0. None
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	02/28/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

O128 **COMMERCIAL PROPERTY** **NY LTANKS** **S111012266**
SE **522 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.129 mi.
681 ft. **Site 10 of 19 in cluster O**

Relative: **Higher**
Actual: **98 ft.**

LTANKS:

Facility ID:	1100723
Site ID:	448142
Closed Date:	2011-06-06
Spill Number:	1100723
Spill Date:	2011-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-20
Spill Record Last Update:	2011-06-06
Spiller Name:	PETER OH
Spiller Company:	ADELPHI
Spiller Address:	Not reported
Spiller County:	999

COMMERCIAL PROPERTY (Continued) **S111012266**

Spiller Contact:	JEFF
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402739
DEC Memo:	"Spoke to Georgia at Advanced. Soil boring had field evidence of petroleum impact. DT 4/20/11 6/6/11: Report from Preferred Environmental entered into eDocs. NFA jod"
Remarks:	"1721 THE CALLER ADVISED DISPATCH THEY ARE AWAITING TANK TEST RESULTS."

All Materials:

Site ID:	448142
Operable Unit ID:	1198388
Operable Unit:	01
Material ID:	2194662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

I129 **MAISON 347 LLC** **NY UST** **U004274867**
SSW **347 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.129 mi.
683 ft. **Site 19 of 21 in cluster I**

Relative: **Lower**

Actual: **94 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-502626 / Active
Operator Name:	Maison 347 LLC
Owner Name:	Maison 347 LLC
Owner Street:	347 Huguenot St
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1995
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron

MAISON 347 LLC (Continued) **U004274867**

Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

I130 **COCO RESIDENCE** **NY LTANKS** **S106123934**
South **81 CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.129 mi.
683 ft. **Site 20 of 21 in cluster I**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Facility ID:	0311339
Site ID:	313391
Closed Date:	2005-01-10
Spill Number:	0311339
Spill Date:	2004-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-07
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-07
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ED COCO
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 01/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson dated 9Feb2004(?). WCDOH requires NFA at this time."
Remarks:	"Failed test. Unknown if the tank is leaking"

All TTF:

Facility ID:	0311339
Spill Number:	0311339
Spill Tank Test:	1528899
Site ID:	313391
Tank Number:	1
Tank Size:	2000

COCO RESIDENCE (Continued) **S106123934**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313391
Operable Unit ID:	878986
Operable Unit:	01
Material ID:	500153
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

131
NW
1/8-1/4
0.130 mi.
686 ft.

CON EDISON **RCRA NonGen / NLR** **1019904602**
19 DIVISION ST & WASHINGTON AVE **FINDS** **NYP004800058**
NEW ROCHELLE, NY 10801 **ECHO**

Relative:
Lower

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/28/2015
Facility name:	CON EDISON
Facility address:	19 DIVISION ST & WASHINGTON AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004800058
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON (Continued) **1019904602**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/28/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069642630

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904602
Registry ID:	110069642630
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069642630

P132 **COMMERCIAL BUILDING** **NY LTANKS** **S100177795**
SE **507 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
689 ft. **Site 3 of 9 in cluster P**

Relative: **Higher**
Actual: **96 ft.**

LTANKS:

Facility ID:	9110835
Site ID:	286303
Closed Date:	1992-03-10
Spill Number:	9110835
Spill Date:	1992-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-02-06
SWIS:	6010
Investigator:	TAYLOR

COMMERCIAL BUILDING (Continued) **S100177795**

Referred To:	Not reported
Reported to Dept:	1992-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	1992-02-06
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-23
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	EPHRAIM ASSOC.
Spiller Address:	300 EAST 74TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	232045
DEC Memo:	""
Remarks:	"BANK AGREEMENT ASSESMENT REVEALED 1K #2 FUEL TANK 12 IN CONCRETE REMAINDER A/G IN BRICK VAULT TANK PULLED TODAY WITH ONE HOLE IN BOTTOM CONCRETE SLAB NOT CRACKED WILL PULL AND INSPECT ON MONDAY"

All Materials:

Site ID:	286303
Operable Unit ID:	960971
Operable Unit:	01
Material ID:	415913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

O133 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963458**
SE **MAIN ST & CHRUCH ST** **NY MANIFEST** **NYP004364576**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
692 ft. **Site 11 of 19 in cluster O**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5042
Facility address:	MAIN ST & CHRUCH ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004364576
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/23/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004364576
Facility Status: Not reported
Location Address 1: MAINS T & CHURCH ST
Code: BP
Location Address 2: TM 5042
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004364576
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2013
Trans1 Recv Date:	09/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004364576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694706JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O134 **CON EDISON MANHOLE: 12758** **RCRA NonGen / NLR** **1016974052**
SE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004478624**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
692 ft. **Site 12 of 19 in cluster O**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/25/2014
Facility name:	CON EDISON MANHOLE: 12758
Facility address:	MAIN ST & CHURCH ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004478624
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/25/2014
Site name:	CON EDISON MANHOLE: 12758
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004478624
Facility Status:	Not reported
Location Address 1:	MAIN & CHURCH ST
Code:	BP
Location Address 2:	SB12758
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004478624
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/25/2014
Trans1 Recv Date: 03/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004478624
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012770524JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O135 **CON EDISON** **NY MANIFEST** **S117535683**
SE **MAIN ST & CHURCH ST** **N/A**
1/8-1/4 **OSSINING, NY 10801**
0.131 mi.
692 ft. **Site 13 of 19 in cluster O**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004680070
Facility Status:	Not reported
Location Address 1:	MAIN ST & CHURCH ST
Code:	BP
Location Address 2:	MH2419
Total Tanks:	Not reported
Location City:	OSSINING
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004680070
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2014
Trans1 Recv Date:	10/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680070
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117535683**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774891JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O136 **CON EDISON TRANSFORMER MANHOLE: 3586** **RCRA NonGen / NLR** **1016974043**
SE **CHURCH ST & MAIN ST** **NY MANIFEST** **NYP004478517**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.131 mi.
692 ft. **Site 14 of 19 in cluster O**

Relative: **Higher**

Actual: **97 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/25/2014
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3586
Facility address:	CHURCH ST & MAIN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004478517
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/25/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 3586
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004478517
Facility Status: Not reported
Location Address 1: CHURCH MAIN ST
Code: BP
Location Address 2: SB3586
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004478517
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/2014
Trans1 Recv Date:	03/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478517
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770521JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

P137 **CATHOLIC NEWS PUBLISHING** **NY LTANKS** **S106972587**
East **210 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.132 mi.
698 ft. **Site 4 of 9 in cluster P**

Relative: LTANKS:
Lower

Actual:
92 ft.

Facility ID:	0503023
Site ID:	347516
Closed Date:	2005-08-28
Spill Number:	0503023
Spill Date:	2005-06-13
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-13
CID:	44
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-13
Spill Record Last Update:	2005-08-28
Spiller Name:	MYLES RIDDER
Spiller Company:	CATHOLIC NEWS PUBLISHING
Spiller Address:	210 NORTH AVE
Spiller County:	001
Spiller Contact:	MYLES RIDDER
Spiller Phone:	(914) 632-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293840
DEC Memo:	"August 28, 2005: NORTHEAT DISPOSED OF LUST AND 48.90 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK AND HOLES IN TANK"

All Materials:

Site ID:	347516
Operable Unit ID:	1105241
Operable Unit:	01
Material ID:	1502620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q138 **CON EDISON** **RCRA NonGen / NLR** **1019902313**
East **205 NORTH AVE** **NYP004772265**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
713 ft. **Site 1 of 3 in cluster Q**

Relative: **Lower**
Actual: **91 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/22/2015
Facility name:	CON EDISON
Facility address:	205 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004772265
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/22/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

Q139 **CON EDISON** **NY MANIFEST** **S119074690**
East **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
713 ft. **Site 2 of 3 in cluster Q**

Relative: **Lower**
Actual: **91 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004772265
Facility Status:	Not reported
Location Address 1:	208 NORTH AVE
Code:	BP

CON EDISON (Continued) **S119074690**

Location Address 2:	SB 2029
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772265
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454078JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30

CON EDISON (Continued) **S119074690**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

Q140 **CON EDISON** **NJ MANIFEST** **S120670860**
East **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
713 ft. **Site 3 of 3 in cluster Q**

Relative: **Lower**

Actual: **91 ft.**

NJ MANIFEST:

EPA Id:	NYP004772265
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454078JJK
EPA ID:	NYP004772265
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120670860**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N141 **TRUMP PLAZA** **NY LTANKS S107522540**
NE **175 HUGUENOT STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.136 mi.
720 ft. **Site 6 of 6 in cluster N**

Relative: **Lower**
Actual: **89 ft.**

LTANKS:

Facility ID:	0512575
Site ID:	358910
Closed Date:	2006-03-08
Spill Number:	0512575
Spill Date:	2006-01-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-01-30
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-30
Spill Record Last Update:	2006-03-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN

TRUMP PLAZA (Continued) **S107522540**

Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN MANFREDI
Spiller Phone:	(914) 241-3795
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	307023
DEC Memo:	"3/08/06 See JM associates spill closure report for 05-04821. TG"
Remarks:	""

All Materials:

Site ID:	358910
Operable Unit ID:	1116137
Operable Unit:	01
Material ID:	2106280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0510932
Facility Type:	ER
Spill Number:	0510932
DER Facility ID:	307023
Site ID:	356986
DEC Region:	3
Closed Date:	2005-12-19
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-12-19
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2006-03-08
Spiller Name:	SEAN MCKAY
Spiller Company:	TRUMP PLAZA
Spiller Address:	175 HUEGOTNOT STREET
Spiller Company:	001
Contact Name:	SEAN MCKAY

TRUMP PLAZA (Continued) **S107522540**

DEC Memo: "CONFIRMED CLEANUP WITH WCDOH 3/8/06 See spill JM Associates closure report for 05-04821"
Remarks: "SPILL AROUND GENERATOR AND IN PROCESS OF BEING CLEANED UP;"

All Materials:
Site ID: 356986
Operable Unit ID: 1114275
Operable Unit: 01
Material ID: 2104355
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

Facility ID: 0504821
Facility Type: ER
Spill Number: 0504821
DER Facility ID: 307023
Site ID: 349739
DEC Region: 3
Closed Date: 2006-03-08
Spill Cause: Other
Spill Class: B3
SWIS: 6010
Spill Date: 2005-07-20
Investigator: JBODee
Referred To: WCDOH
Reported to Dept: 2005-07-21
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-07-21
Spill Record Last Update: 2006-03-08
Spiller Name: JOHN MANFREDIE
Spiller Company: NEW ROCHELLE #1A
Spiller Address: HUGIGNOT /LAACONTA
Spiller Company: 001
Contact Name: JOHN MANFREDIE
DEC Memo: "3/02/06 UST removal report submitted by JM Associates including information about two other spill reports listed for the same parcel, 05-10932 and 05-12575. A total of 5 UST's were removed along with 3,351.05 tons of petroleum impacted soil. Based on the information contained in the report, no further action is required. TG"
Remarks: "DURING EXCAVATION FOUND AN ABANDON TANK: AND FOUND CONTAMINATED SOIL" Not reported

TRUMP PLAZA (Continued) **S107522540**

All Materials:

Site ID:	349739
Operable Unit ID:	1107327
Operable Unit:	01
Material ID:	2097217
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I142 **587 MAIN STREET** **NY AST** **A100433537**
SSW **348 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.137 mi.
721 ft. **Site 21 of 21 in cluster I**

Relative: **Lower**
Actual: **95 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-802131
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Not reported
Owner Name:	RXR 587 Main Owner LLC
Owner Street:	625 RXR Plaza
Owner Address2:	Not reported
Owner City/State/Zip:	Uniondale, NY 11556
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	8000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/23/2017
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

O143 **CON EDISON** **NJ MANIFEST** **S120675741**
SSE **552 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.137 mi.
724 ft. **Site 15 of 19 in cluster O**

Relative:
Higher

Actual:
101 ft.

NJ MANIFEST:

EPA Id:	NYP004828044
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473164JJK
EPA ID:	NYP004828044
Date Shipped:	8/21/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675741**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

O144 **CON EDISON** **RCRA NonGen / NLR** **1019906923**
SSE **552 MAIN ST** **FINDS** **NYP004828044**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.137 mi.
724 ft. **Site 16 of 19 in cluster O**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/21/2015
Facility name:	CON EDISON
Facility address:	552 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004828044
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/21/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019906923**

Registry ID: 110069679360

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906923
Registry ID: 110069679360
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069679360

O145 **542 MAIN STREET LLC** **NY UST** **U003917838**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
727 ft. **Site 17 of 19 in cluster O**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800617 / Active
Operator Name: Cornell Pace Inc.
Owner Name: 542 Main Street LLC
Owner Street: 542 Main Street, 2nd Floor
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 001
Status: 1. In-Service
Capacity: 3000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1904
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 2. Rubber liner
Tank External Protection: 0. None
Tank Secondary Containment: 1. Diking (aboveground only)
Piping Location: 2. Underground/on Ground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

O146 **OFFICE BLDG** **NY LTANKS** **S107489194**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.138 mi.
727 ft. **Site 18 of 19 in cluster O**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Facility ID:	0509995
Site ID:	355877
Closed Date:	2006-03-22
Spill Number:	0509995
Spill Date:	2005-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2005-11-21
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-03-22
Spiller Name:	UNKNOWN
Spiller Company:	OFFICE BLDG
Spiller Address:	542 MAIN STREET
Spiller County:	001
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305921
DEC Memo:	"March 22, 2006 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	""

All TTF:

Facility ID:	0509995
Spill Number:	0509995
Spill Tank Test:	1549528
Site ID:	355877
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

OFFICE BLDG (Continued) **S107489194**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 355877
Operable Unit ID: 1113209
Operable Unit: 01
Material ID: 2103275
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

P147 **NEW ROCHELLE PUBLIC LIBRARY** **NY UST** **U004177022**
ESE **ONE LIBRARY PLAZA** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
729 ft. **Site 5 of 9 in cluster P**

Relative: **Lower**
Actual: **94 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-601216 / Active
Operator Name: Thomas Geoffino
Owner Name: New Rochelle Public Library
Owner Street: One Library Plaza
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: LIB 1
Status: 1. In-Service
Capacity: 10000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 09/01/1979
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Secondary Containment: Not reported
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

M148 **MR CHIMNEY CLEAN** **RCRA NonGen / NLR** **1004758604**
SSW **32 RELYEA PL** **FINDS** **NYD987011855**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.138 mi. **NY MANIFEST**
731 ft. **Site 4 of 11 in cluster M**

Relative:
Lower

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MR CHIMNEY CLEAN
Facility address:	32 RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYD987011855
Mailing address:	RELYEA PL NEW ROCHELLE, NY 10801
Contact:	MAURICE MCKENNA
Contact address:	RELYEA PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-632-6660
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NAUAL MOTION PICTURES
Owner/operator address:	270 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-2406
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NAUAL MOTION PICTURES
Owner/operator address:	270 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-2406
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

MR CHIMNEY CLEAN (Continued) **1004758604**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MR CHIMNEY CLEAN
Classification: Not a generator, verified

Date form received by agency: 06/01/1994
Site name: MR CHIMNEY CLEAN
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004493922

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004758604
Registry ID: 110004493922
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004493922

NY MANIFEST:
Country: USA
EPA ID: NYD987011855
Facility Status: Not reported
Location Address 1: 270 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

MR CHIMNEY CLEAN (Continued) **1004758604**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987011855
Mailing Name:	NAVAL MOTION PICTURE SERVICE
Mailing Contact:	PAUL RAMOS
Mailing Address 1:	270 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	CTF0276746
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/1994
Trans1 Recv Date:	06/23/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/27/1994
Part A Recv Date:	/ /
Part B Recv Date:	07/11/1994
Generator EPA ID:	NYD987011855
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

MR CHIMNEY CLEAN (Continued) **1004758604**

Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

R149 **BLOOMINGDALE PARKING LOT** **NY UST** **U003884000**
SSE **554 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
733 ft. **Site 1 of 12 in cluster R**

Relative: **Higher**
Actual: **102 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-600330 / Unregulated: <1101 gal. PBS
Operator Name:	Mel Watson
Owner Name:	Fraydun Enterprises
Owner Street:	3 New York Plaza
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10004
GDS Number:	Not reported
Tank Number:	2
Status:	4. Closed - in place
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

P150 **BARON MANAGEMENT** **NY UST** **U004187277**
East **200 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
735 ft. **Site 6 of 9 in cluster P**

Relative: **Lower**
Actual: **92 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-167843 / Administratively Closed
Operator Name:	Segundo Tirado
Owner Name:	Ronald Rettner

BARON MANAGEMENT (Continued) **U004187277**

Owner Street:	481 Main Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	03/05/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

J151 **CON EDISON SERVICE BOX: 1539** **RCRA NonGen / NLR** **1016972589**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004463667**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.139 mi.
736 ft. **Site 6 of 11 in cluster J**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/11/2014
Facility name:	CON EDISON SERVICE BOX: 1539
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004463667
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/11/2014
Site name: CON EDISON SERVICE BOX: 1539
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004463667
Facility Status: Not reported
Location Address 1: NO AVE 48 AND 48 GARDEN ST
Code: BP
Location Address 2: SB 1539
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004463667
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/11/2014
Trans1 Recv Date: 03/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2014
Part A Recv Date: Not reported

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004463667
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772800JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J152 **CON EDISON MANHOLE: 4177** **RCRA NonGen / NLR** **1016451046**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004300836**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
736 ft. **Site 7 of 11 in cluster J**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	05/11/2013
Facility name:	CON EDISON MANHOLE: 4177
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004300836
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219

Actual:
71 ft.

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/11/2013
Site name: CON EDISON MANHOLE: 4177
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004300836
Facility Status: Not reported
Location Address 1: NORTH AVE C/O GARDEN ST
Code: BP
Location Address 2: MH 4177
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004300836
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/11/2013
Trans1 Recv Date:	04/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004300836
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707795JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J153 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016677331**
North **NORTH ST & GARDEN ST** **NY MANIFEST** **NYP004309076**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
736 ft. **Site 8 of 11 in cluster J**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/08/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	NORTH ST & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004309076
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/08/2013
Site name:	CON EDISON MANHOLE: 4175
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004309076
Facility Status:	Not reported
Location Address 1:	NORTH AVE & GARDEN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004309076
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/08/2013
Trans1 Recv Date: 05/08/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/14/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004309076
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007655511JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J154 **CON EDISON MANHOLE: 20274** **RCRA NonGen / NLR** **1016677685**
North **NORTH AVE & GARDEN ST** **FINDS** **NYP004313615**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.139 mi.
736 ft. **Site 9 of 11 in cluster J**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/15/2013
Facility name:	CON EDISON MANHOLE: 20274
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004313615
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/15/2013
Site name:	CON EDISON MANHOLE: 20274
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

Violation Status: No violations found

FINDS:

Registry ID: 110058877390

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677685
Registry ID: 110058877390
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058877390

J155 **CON EDISON - MANHOLE 1535** **RCRA-LQG** **1016451189**
North **GARDEN ST AND NORTH AVE** **NY MANIFEST** **NYP004302303**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
736 ft. **Site 10 of 11 in cluster J**

Relative: **Lower**
Actual: **71 ft.**

RCRA-LQG:
Date form received by agency: 03/27/2014
Facility name: CON EDISON - MANHOLE 1535
Facility address: GARDEN ST AND NORTH AVE
NEW ROCHELLE, NY 10802
EPA ID: NYP004302303
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: DENNIS HUACON
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2757
Contact email: HUACOND@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/17/2013
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/17/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 05/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Not a generator, verified

Date form received by agency: 04/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004302303
Facility Status: Not reported
Location Address 1: GARDEN ST AND NORTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004302303
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/17/2013
Trans1 Recv Date: 04/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004302303
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010456840JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J156 **CON EDISON MANHOLE 4175** **RCRA NonGen / NLR** **1014918789**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004224085**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
736 ft. **Site 11 of 11 in cluster J**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/14/2011
Facility name:	CON EDISON MANHOLE 4175
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004224085
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/15/2011
Site name: CON EDISON MANHOLE 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004224085
Facility Status: Not reported
Location Address 1: NORTH AV & GARDEN ST
Code: BP
Location Address 2: MH 4175
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004224085
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/15/2011
Trans1 Recv Date: 01/15/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/17/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004224085
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON MANHOLE 4175 (Continued) **1014918789**

TSDF ID 2:	Not reported
Manifest Tracking Number:	007655781JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

P157 **NEW ROCHELLE PUBLIC LIBRARY** **NY LTANKS** **S105995872**
ESE **1 LAWTON** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
750 ft. **Site 7 of 9 in cluster P**

Relative: LTANKS:
Lower

Actual: Facility ID:	1311408
94 ft. Site ID:	492304
Closed Date:	Not reported
Spill Number:	1311408
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2015-10-16
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE PUBLIC LIBRARY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROB
Spiller Phone:	(914) 473-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	447251
DEC Memo:	"Tank failed with a dry leak. Will most likely be uncovering, repairing and retesting. WCDOH has been notified...mm 10-15-15 email update request sent to WCHD RDB 10-16-15 Wayne is handling and will forward an update"
Remarks:	""

All TTF:

Facility ID:	1311408
Spill Number:	1311408
Spill Tank Test:	2495159
Site ID:	492304
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MBMASTRO
Last Modified Date:	Not reported

All Materials:

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242331
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	492304

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242328
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	0201697
Site ID:	306611
Closed Date:	2002-09-18
Spill Number:	0201697
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE LIBRARY
Spiller Address:	1 LAWTON STREET
Spiller County:	001
Spiller Contact:	FRANK GALLELO
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	274126
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST "

All TTF:

Facility ID:	0201697
Spill Number:	0201697
Spill Tank Test:	1527134
Site ID:	306611
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306611
Operable Unit ID:	852656
Operable Unit:	01
Material ID:	523107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L158 **CIOTTI RESIDENCE** **NY LTANKS S107788125**
NNW **60 GRAND STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.143 mi.
754 ft. **Site 4 of 5 in cluster L**

Relative: **Lower**

Actual: **80 ft.**

LTANKS:

Facility ID:	0407555
Site ID:	332054
Closed Date:	2004-10-07
Spill Number:	0407555
Spill Date:	2004-10-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2004-10-07
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-07
Spill Record Last Update:	2004-11-01
Spiller Name:	ROB HILL
Spiller Company:	RESIDENCE
Spiller Address:	60 GRAND STREET

CIOTTI RESIDENCE (Continued) **S107788125**

Spiller County: 001
Spiller Contact: ROB HILL
Spiller Phone: (718) 579-3414
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 267201
DEC Memo: ""
Remarks: "TRUCK DIRVER OVERFILLED AND BLEW A LINE. CREWS ARE IN ROUTE."

All Materials:
Site ID: 332054
Operable Unit ID: 1094311
Operable Unit: 01
Material ID: 574419
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 0602271
Facility Type: ER
Spill Number: 0602271
DER Facility ID: 267201
Site ID: 364705
DEC Region: 3
Closed Date: 2007-02-16
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 2006-05-31
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-05-31
CID: 444
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-31
Spill Record Last Update: 2007-02-16
Spiller Name: ROBERT CIOTTI
Spiller Company: CIOTTI RESIDENCE
Spiller Address: 60 GRAND STREET
Spiller Company: 001
Contact Name: ROBERT CIOTTI
DEC Memo: ""

CIOTTI RESIDENCE (Continued) **S107788125**

Remarks: "TESTED THE REMOTE FILL PIPE AND FOUND IT NOT WORKING: 02/15/07 Northeast Envoronmental reported that they excavated 12.31 tons of petroleum impacted soil. NFA TG"

All Materials:

Site ID:	364705
Operable Unit ID:	1122726
Operable Unit:	01
Material ID:	2112202
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0601618
Facility Type:	ER
Spill Number:	0601618
DER Facility ID:	267201
Site ID:	363896
DEC Region:	3
Closed Date:	2006-11-07
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	6010
Spill Date:	2006-05-12
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-05-12
CID:	408
Water Affected:	STORM DRAINS ON GRAN
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-12
Spill Record Last Update:	2006-11-07
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WAYNE SCHNEIDER
DEC Memo:	"05/12/06 Friday Stefan Goreau reported from the field that the spilled oil resembled motor oil rather than fuel oil, so he doesn't believe that the spill came from the residence. Northeast Environmental was called by the homeowner to do the cleanup but now the homeowner is not considered the RP. Since rain is imminent and Northeast has a vac truck on site, NE was advised to pump the oil out of the drains. DEC to pick up the expense. TG 11/07/06 IRS completed. TG"

CIOTTI RESIDENCE (Continued) **S107788125**

Remarks: "CAUSE IS EITHER TANK OVERFILL OR CHECK VALVE FAILURE."

All Materials:

Site ID:	363896
Operable Unit ID:	1121950
Operable Unit:	01
Material ID:	2111430
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R159 **CON EDISON** **NJ MANIFEST** **S120678194**
South **565 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
755 ft. **Site 2 of 12 in cluster R**

Relative:
Higher

Actual:
101 ft.

NJ MANIFEST:

EPA Id:	NYP004880023
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319281JJK
EPA ID:	NYP004880023
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120678194**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R160 **CON EDISON** **RCRA NonGen / NLR** **1019909012**
South **565 MAIN ST** **NYP004880023**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
755 ft. **Site 3 of 12 in cluster R**

Relative: **Higher**

Actual: **101 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/16/2015
Facility name:	CON EDISON
Facility address:	565 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004880023
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON (Continued) **1019909012**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/16/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

O161 **NEW ROCHELLE SUPERMARKET CORP.** **NY AST** **A100204374**
SSE **538 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.146 mi.
769 ft. **Site 19 of 19 in cluster O**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. AST:

PBS Number:	3-166995
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Andrew Taveras
Owner Name:	New Rochelle Supermarket Corp.
Owner Street:	538 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/09/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

R162 **HANGERS CLEANERS** **NY DRYCLEANERS** **S110246761**
South **562-564 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.147 mi.
777 ft. **Site 4 of 12 in cluster R**

Relative: **Higher**
Actual: **102 ft.**

DRYCLEANERS:

Facility ID:	3-5510-00358
Phone Number:	914-235-0300
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	04MAR23
Install Date:	02
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	CO2
Current Business:	Not reported

P163 **ADREAN PRINTING CO** **RCRA NonGen / NLR** **1004755683**
ESE **490 MAIN ST** **FINDS** **NY0000233981**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.147 mi. **NY MANIFEST**
777 ft. **Site 8 of 9 in cluster P**

Relative: **Lower**
Actual: **94 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ADREAN PRINTING CO
Facility address:	490 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NY0000233981
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	MICHAEL GOLDBERGER
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-0200
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-636-0200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801

ADREAN PRINTING CO (Continued) **1004755683**

Owner/operator country: US
Owner/operator telephone: 914-636-0200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ADREAN PRINTING CO
Classification: Not a generator, verified

Date form received by agency: 04/21/1994
Site name: ADREAN PRINTING CO
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004314297

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ADREAN PRINTING CO (Continued) **1004755683**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755683
Registry ID:	110004314297
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004314297

NY MANIFEST:

Country:	USA
EPA ID:	NY0000233981
Facility Status:	Not reported
Location Address 1:	490 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000233981
Mailing Name:	ADREAN PRINTING
Mailing Contact:	WILLIAM C WHITE
Mailing Address 1:	490 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146360200

NY MANIFEST:

Document ID:	NYG0919566
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PW2414
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/28/1997
Part A Recv Date:	/ /
Part B Recv Date:	09/19/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

ADREAN PRINTING CO (Continued) **1004755683**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
4 additional NY_MANIFEST: record(s) in the EDR Site Report.

M164 **PRO AUTO PARTS** **RCRA NonGen / NLR** **1001079946**
SW **41 REYLEA PL** **FINDS** **NYR000016535**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.148 mi. **NY MANIFEST**
779 ft. **Site 5 of 11 in cluster M**

Relative: **Lower**
Actual: **87 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PRO AUTO PARTS
Facility address:	41 REYLEA PL NEW ROCHELLE, NY 10801-6918
EPA ID:	NYR000016535
Mailing address:	SUMMERFIELD ST SCARSDALE, NY 10853
Contact:	Not reported
Contact address:	SUMMERFIELD ST SCARSDALE, NY 10853
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PRO AUTO PARTS CORP
Owner/operator address:	135 SUMMER FIELD ST SCARSDALE, NY 10853
Owner/operator country:	US
Owner/operator telephone:	914-772-4871
Owner/operator email:	Not reported

PRO AUTO PARTS (Continued) **1001079946**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PRO AUTO PARTS CORP
Owner/operator address: 135 SUMMER FIELD ST
SCARSDALE, NY 10853
Owner/operator country: US
Owner/operator telephone: 914-772-4871
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 11/16/1995
Site name: PRO AUTO PARTS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

PRO AUTO PARTS (Continued) **1001079946**

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

FINDS:

Registry ID: 110004520377

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079946
Registry ID: 110004520377
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004520377

NY MANIFEST:
Country: USA
EPA ID: NYR000016535
Facility Status: Not reported
Location Address 1: 41 REYLEA PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000016535
Mailing Name: PRO AUTO PARTS
Mailing Contact: PHILIP A MORRIS JR
Mailing Address 1: 135 SUMMERFIELD ROAD
Mailing Address 2: Not reported
Mailing City: SCARSDALE
Mailing State: NY
Mailing Zip: 10583
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9147933336

NY MANIFEST:
Document ID: NYB7350417
Manifest Status: C
seq: Not reported
Year: 1995

PRO AUTO PARTS (Continued) **1001079946**

Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1995
Trans1 Recv Date:	12/21/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/21/1995
Part A Recv Date:	01/05/1996
Part B Recv Date:	01/03/1996
Generator EPA ID:	NYR000016535
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00130
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	089

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S165 **FIRST METRO SERVICES** **RCRA NonGen / NLR** **1004759815**
SSW **357 HUGONOT ST** **FINDS** **NYR000022053**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.149 mi.
786 ft. **Site 1 of 5 in cluster S**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	01/01/2007
Facility name:	FIRST METRO SERVICES
Facility address:	357 HUGONOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYR000022053
Mailing address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact:	BILL LIVANOS
Contact address:	S DIVISION ST

Actual:
92 ft.

FIRST METRO SERVICES (Continued) **1004759815**

NEW ROCHELLE, NY 10805
Contact country: US
Contact telephone: 914-576-7210
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: 914-632-9692
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: 914-632-9692
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FIRST METRO SERVICES
Classification: Not a generator, verified

FIRST METRO SERVICES (Continued) **1004759815**

Date form received by agency: 04/09/1996
Site name: FIRST METRO SERVICES
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D006
. Waste name: CADMIUM

Violation Status: No violations found

FINDS:

Registry ID: 110004523882

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759815
Registry ID: 110004523882
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004523882

T166 **NYS THRUWAY AUTH** **RCRA NonGen / NLR** **1000553909**
North **THRUWAY BRIDGE MP 605.75** **NY MANIFEST** **NYD986963445**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.149 mi.
788 ft. **Site 1 of 3 in cluster T**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYS THRUWAY AUTH
Facility address: THRUWAY BRIDGE MP 605.75
NEW ROCHELLE, NY 10801
EPA ID: NYD986963445
Mailing address: S BROADWAY
TARRYTOWN, NY 10591-5697
Contact: Not reported
Contact address: S BROADWAY
TARRYTOWN, NY 10591-5697
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

NYS THRUWAY AUTH (Continued) **1000553909**

Owner/Operator Summary:

Owner/operator name:	NYS THRUWAY AUTH
Owner/operator address:	PO BOX 189
	ALBANY, NY 12201
Owner/operator country:	US
Owner/operator telephone:	518-436-2811
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYS THRUWAY AUTH
Owner/operator address:	PO BOX 189
	ALBANY, NY 12201
Owner/operator country:	US
Owner/operator telephone:	518-436-2811
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	NYS THRUWAY AUTH
Classification:	Not a generator, verified

Date form received by agency:	07/08/1999
Site name:	NYS THRUWAY AUTH
Classification:	Not a generator, verified

Date form received by agency:	02/19/1992
Site name:	NYS THRUWAY
Classification:	Large Quantity Generator

NYS THRUWAY AUTH (Continued) **1000553909**

Date form received by agency: 07/12/1991
Site name: NYS THRUWAY AUTH
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD986963445
Facility Status: Not reported
Location Address 1: I-95 NORTH & NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986963445
Mailing Name: NEW YORK STATE THRUWAY AUTHORITY
Mailing Contact: NEW YORK STATE THRUWAY AUTHORITY
Mailing Address 1: 333 SOUTH BROADWAY
Mailing Address 2: Not reported
Mailing City: TARRYTOWN
Mailing State: NY
Mailing Zip: 10591
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

NY MANIFEST:
Document ID: MIA2540754
Manifest Status: C
seq: Not reported
Year: 1992
Trans1 State ID: 5825
Trans2 State ID: Not reported
Generator Ship Date: 05/26/1992
Trans1 Recv Date: 05/26/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 05/27/1992
Part A Recv Date: / /
Part B Recv Date: 06/16/1992
Generator EPA ID: NYD986963445
Trans1 EPA ID: PAD064375470
Trans2 EPA ID: Not reported
TSDF ID 1: MID000724831
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported

NYS THRUWAY AUTH (Continued) **1000553909**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
4 additional NY_MANIFEST: record(s) in the EDR Site Report.

L167 **GUIDANCE CENTER INC** **NY LTANKS** **S102556009**
NNW **70 GRAND ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.150 mi.
791 ft. **Site 5 of 5 in cluster L**

Relative: LTANKS:
Lower

Facility ID:	9613894
Site ID:	77017
Closed Date:	1997-10-03
Spill Number:	9613894
Spill Date:	1997-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-26
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-02-26
Spill Record Last Update:	1997-10-22
Spiller Name:	STEVEN SMITH

Actual:
80 ft.

GUIDANCE CENTER INC (Continued) **S102556009**

Spiller Company:	GUIDANCE CENTER INC
Spiller Address:	70 GRAND ST
Spiller County:	001
Spiller Contact:	STEVEN SMITH
Spiller Phone:	(914) 636-4440
Spiller Extention:	250
DEC Region:	3
DER Facility ID:	71920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/03/97 LETTER SENT; BASED ON TANK REMOVAL REPORT, NFA; "
Remarks:	"OLD GASOLINE TANK FOUND UNDER THE GROUND - FOUND CONTAMINATED SOIL PHASE 2 COMPLETED - NO REMEDATION STARTED OWNER OF PROPERTY WILL AWAIT DIRECTION FROM DEC ABOUT TANK REMOVAL"

All Materials:

Site ID:	77017
Operable Unit ID:	1041477
Operable Unit:	01
Material ID:	339001
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R168 **MISR REALTY, LLC** **NY AST** **U004176186**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.150 mi.
792 ft. **Site 5 of 12 in cluster R**

Relative: **Higher**

Actual: **100 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-800238
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MISR Realty LLC
Owner Street:	542 Main Street, 4th Floor
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None

MISR REALTY, LLC (Continued) **U004176186**

Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

R169 **CENTRE-MAIN ASSOCIATES** **NY LTANKS** **S106123770**
South **75 - 77 CENTER AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.152 mi.
802 ft. **Site 6 of 12 in cluster R**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Facility ID:	0311823
Site ID:	149369
Closed Date:	2004-12-30
Spill Number:	0311823
Spill Date:	2004-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-21
CID:	44
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2005-01-10
Spiller Name:	ED
Spiller Company:	Not reported
Spiller Address:	75 - 77 CENTER AVE
Spiller County:	001
Spiller Contact:	ED
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127066
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 1/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson, WCDOH dated 30Dec2004. WCDOH requires NFA at this time."
Remarks:	"recommend, uncover repair and retest. Tank is bolted in basement."

All TTF:

Facility ID:	0311823
Spill Number:	0311823
Spill Tank Test:	1528926

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

Site ID:	149369
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	149369
Operable Unit ID:	877137
Operable Unit:	01
Material ID:	497066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R170 **MISR REALTY, LLC** **NY UST** **U004259541**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
809 ft. **Site 7 of 12 in cluster R**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800238 / Active
Operator Name:	Pedro Benoit
Owner Name:	MISR Realty LLC
Owner Street:	542 Main Street, 4th Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	Not reported
Date Perm Closure:	11/01/2004
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron

MISR REALTY, LLC (Continued) **U004259541**

Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

M171 **INDUST OVERALL SERVICE CORP** **NY LTANKS** **S116555778**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.154 mi.
815 ft. **Site 6 of 11 in cluster M**

Relative: **Lower**
Actual: **81 ft.**

LTANKS:

Facility ID:	1400928
Site ID:	494186
Closed Date:	2017-03-30
Spill Number:	1400928
Spill Date:	2014-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	ELMOORE
Referred To:	Not reported
Reported to Dept:	2014-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-28
Spill Record Last Update:	2017-03-30
Spiller Name:	BOB OBRIEN
Spiller Company:	INDUSTRIAL OVERALL SERV CORP
Spiller Address:	10 BARTELL PL
Spiller County:	999
Spiller Contact:	BOB OBRIEN
Spiller Phone:	(914) 235-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449117
DEC Memo:	"4-28-14: Chris/WCHD call to Dispt./V.Mc.: Heating oil tank, out of service, failed test. 3/30/2017 -- Carlos drove by this week and the soil pile has been removed. This spill can be closed, with the entire site clean-up being accomplished under Haz Waste. 360109 ELM"
Remarks:	"tank 2 5000 gallon"

All TTF:

Facility ID:	1400928

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Spill Number:	1400928
Spill Tank Test:	2495577
Site ID:	494186
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	True
UST:	True
Cause:	03
Source:	00
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

Facility ID:	1400928
Spill Number:	1400928
Spill Tank Test:	2495578
Site ID:	494186
Tank Number:	2
Tank Size:	5000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	494186
Operable Unit ID:	1243715
Operable Unit:	01
Material ID:	2244419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

P172 **RETTNER MANAGEMENT CORP** **NY UST** **U004177201**
ESE **481 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
815 ft. **Site 9 of 9 in cluster P**

Relative: **Lower**

Actual: **92 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-255033 / Active
Operator Name:	Arnoldo Diaz
Owner Name:	Rettner Main Street, LLC
Owner Street:	374 McLean Avenue
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10705
GDS Number:	Not reported

Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	09/01/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/01/1970
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

M173
SW
1/8-1/4
0.155 mi.
819 ft.

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
10 BARTELS PL
NEW ROCHELLE, NY 10801

Site 7 of 11 in cluster M

NJ MANIFEST | **S120679001** | **N/A**

Relative:
Lower

Actual:
81 ft.

NJ MANIFEST:

EPA Id:	NYR000208967
Mail Address:	CENTRE AVE
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID CROSBY
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010914098JJK
EPA ID:	NYR000208967
Date Shipped:	1/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported
Manifest Number:	000959895GBF
EPA ID:	NYR000208967
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported
Manifest Number:	014168256JJK
EPA ID:	NYR000208967
Date Shipped:	10/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

M174 **NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP** **RCRA-LQG** **1016678149**
SW **10 BARTELS PL** **FINDS** **NYR000208967**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.155 mi. **NY MANIFEST**
819 ft. **Site 8 of 11 in cluster M**

Relative: **Lower**

Actual: **81 ft.**

RCRA-LQG:

Date form received by agency:	04/19/2016
Facility name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Facility address:	10 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000208967
Mailing address:	CENTRE AVE NEW ROCHELLE, NY 10801
Contact:	DAVID CROSBY
Contact address:	BROADWAY ALBANY, NY 12233
Contact country:	US
Contact telephone:	518-402-9662
Contact email:	DAVID.CROSBY@DEC.NY.GOV
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	BARTELS PL NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-235-1220
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/23/2010
Owner/Op end date:	Not reported

Owner/operator name:	ROBERT OBRIEN
Owner/operator address:	CENTRE AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Owner/operator name:	ROBERT OBRIEN
Owner/operator address:	CENTRE AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 12/09/2014

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Not a generator, verified

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 03/31/2014
Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Small Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 10230

Waste code: D008
Waste name: LEAD
Amount (Lbs): 10230

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 10230

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 10230

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 10230

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/14/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 12000
Paid penalty amount: 12000

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 04/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 10000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/31/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/08/2014
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/01/2014
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Listing - General
Date achieved compliance: 07/08/2014
Evaluation lead agency: State

Evaluation date: 03/18/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 07/08/2014

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Evaluation lead agency: State

FINDS:

Registry ID: 110058881152

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016678149
Registry ID:	110058881152
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058881152

NY MANIFEST:

Country:	USA
EPA ID:	NYR000208967
Facility Status:	Not reported
Location Address 1:	10 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000208967
Mailing Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Contact:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Address 1:	10 BARTELS PL
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014168256JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
20 additional NY_MANIFEST: record(s) in the EDR Site Report.

M175 **INDUSTRIAL OVERALL SERVICE CORP.** **NY SHWS S110043643**
SW **10 BARTELS PLACE** **NY CBS N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
819 ft. **Site 9 of 11 in cluster M**

Relative:
Lower

Actual:
81 ft.

SHWS:

Program:	HW
Site Code:	413917
Classification:	Significant threat to the public health or environment - action required.
Region:	3
Acres:	0.42

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

HW Code: 360109
Record Add: 05/15/2009
Record Upd: 09/28/2017
Updated By: DACROSBY
Site Description: Location: The Industrial Overall Service Corporation site is located at 10 Bartels Place in the City of New Rochelle, Westchester County. The site is located east of I-95 and west of US-1 (Huguenot Street) and it is bounded by Reylea Place, Bartels Place, Centre Avenue and the Metro North railroad property and tracks. Site Features: The site is 0.42 acres in size and resides on a slightly sloping irregularly shaped parcel consisting of two tax parcels. The main site feature includes a six-sided building which occupies the majority of the property and a small parking area located to the south and southwest of the building. Current Zoning/ Uses: This property is zoned for commercial use. The building is currently vacant and for sale. The surrounding area is a mix of commercial and residential establishments situated in an urban setting. Past Uses of the Site: Industrial Overall Service Corporation operated at the current location as a uniform and industrial clothing dry cleaning/laundering facility, historically cleaning heavily soiled clothing from industrial, auto body and gasoline dispensing businesses from 1956 until 2010. Dry cleaning equipment was reportedly decommissioned in 1978, but water washing continued. From 1980-1998 Workingman s Closet, an embroidery and uniform retail outfit, operated on the second floor of the building. From 2010 until 2016, Apparel Plus Textile Rental LLC ran a rental linen service company on both floors of the building, which involved water laundering. Historically, a precision scale company also operated out of the second floor of the building from sometime between 1932 and 1956 until sometime before 1973 when Industrial Overall purchased the building to occupy it entirely. Based on a Sanborn Fire Insurance Map from 1931, the site previously operated an automobile sales and service business. This site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site and adjacent Metro-north property. OU1 consists of the entire site property with the addition of an off-site source area which lies to the northeast of the site on the adjacent Metro-north property. Operable unit 2 (OU2) is the off-site groundwater plume. Site Geology and Hydrology: Groundwater is found in the overburden and in the bedrock. Groundwater is generally found 10 to 15 feet below ground surface and flows in a southwesterly direction. Overburden in the vicinity ranges in thickness from 2.2 feet to 32 feet, and consists of fill material (1-5 feet in thickness) and varied amounts of fine to coarse sand with varying amounts of silt. Below the sandy silt is a till like material. Depth to bedrock is variable across the site from a depth of a few feet to over 35 feet below grade. Bedrock in the vicinity is a highly weathered rock which is undulating in nature and is generally more transmissive than the till-like overburden material directly above.
Env Problem: This section summarizes the assessment of existing and potential future environmental impacts presented by the site. Environmental impacts may include existing and potential future exposure pathways to fish and wildlife receptors, wetlands, groundwater resources, and surface water. Based upon the resources and pathways identified and

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

the toxicity of the contaminants of ecological concern at this site, a Fish and Wildlife Resources Impact Analysis (FWRIA) was deemed not necessary for OU 01. Nature and Extent of Contamination: The primary contaminants of concern at the site include the dry cleaning chemicals tetrachloroethene (PCE), trichloroethene (TCE) and their associated breakdown products. PCE and TCE are found in on-site and off-site soil and groundwater. Two primary source areas remain at and adjacent to the site. These include a lint trap within on-site building and an off-site debris and waste disposal area located to the northwest outside the building on the adjacent Metro North Railroad property. Soil: Maximum concentrations of PCE and TCE in on-site soils/wastes located in the remaining lint trap source area exceed 21,000 parts per million (ppm) and 1,200 ppm, respectively. In addition to volatile organic compounds (VOCs), soils on- and off-site were also sampled for semi-volatile organic compounds (SVOCs) and metals. No SVOCs exceeded SCOs, but several metals (barium, cadmium, chromium, lead, and silver) exceeded their respective unrestricted use SCOs directly underneath the lint trap. Also under the lint trap, barium, cadmium, and lead exceeded commercial SCOs, while only barium out of these metals did not exceed protection of groundwater SCOs. Also chromium exceeds the protection of groundwater SCO in one off-site location. On-site and off-site soil contains VOCs mainly in the two source areas, but some soil located under the site parking lot also contained VOCs above protection of groundwater SCOs of 0.47 ppm for TCE and 1.3 ppm for PCE. Generally, however, concentrations of PCE and TCE in on-site soils decrease to below the soil cleanup objectives (SCOs) for the protection of groundwater not far from the actual lint trap. The debris and waste disposal source area on the off-site Metro North property contains a maximum PCE concentration of 500 ppm and a maximum TCE concentration of 11 ppm. Groundwater: Contamination migrating from the two source areas has impacted groundwater in the bedrock and overburden, and created a plume extending downgradient (southwest) more than 1,900 feet from the site. The highest level of PCE in on-site groundwater was 140,000 parts per billion (ppb) near the lint trap, compared to the groundwater standard of 5 ppb. In the off-site debris pile area, PCE concentrations in groundwater reached 38,000 ppb. The maximum level of TCE in on-site groundwater was 5,300 ppb near the lint trap, and 2,100 ppb beneath the off-site debris pile area, compared to the groundwater standard of 5 ppb. Several breakdown products of PCE and TCE were also noted in the groundwater. The maximum on-site cis-1,2 dichloroethene (cis-1,2 DCE) concentration was 5,300 ppb near the lint trap, and 890 ppb beneath the off-site debris pile area. The maximum on-site vinyl chloride (VC) concentration was 250 ppb near the lint trap, and 1-1-1 trichloroethane (1,1,1-TCA) was detected on-site at a maximum concentration of 630 ppb beneath the on-site building. However, 1,1,1-TCA was also detected upgradient of the site at 910 ppb indicating an off-site, upgradient source. Soil vapor: Soil vapor samples were collected from the sub-slab and indoor air of eleven off-site residential structures and five off-site commercial/industrial structures to assess the potential for soil vapor intrusion. The results indicated that PCE and TCE were present in sub-slab soil vapor and indoor air in six structures, two of which have subsequently received active vapor control measures and four of which are undergoing continued monitoring. One of the four actively-monitored structures was recently found to require mitigation, and that process is underway as of the date of this

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

document. Soil vapor samples were collected from three additional off-site locations in the downgradient groundwater plume direction. PCE was detected in all three samples but at low concentrations which did not require actions to address soil vapor intrusion. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. No significant environmental resources have been identified near the site.

Health Problem: Direct contact with contaminants in groundwater is unlikely because the area is served by an uncontaminated public water supply. While the majority of the site is covered with buildings and pavement, trespassers or employees may come in direct contact with some contaminated surficial soils on site and on the adjacent Metro North Railroad property. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion (SVI). Inhalation of site contaminants in indoor air due to soil vapor intrusion is unknown because the on-site building is an active laundry facility. However, an evaluation to determine the potential for soil vapor intrusion to occur, will be needed should the current site use of the building or chemical use change in the future. Sub-slab depressurization systems have been installed in two off-site buildings to prevent the inhalation of site-related contamination. In addition, air monitoring is on-going at four additional off-site buildings to verify further actions are not needed. Sampling indicates soil vapor intrusion may be a concern for additional off-site buildings where sampling has been offered but not accepted by building owners.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: UNKNOWN
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 6/11/2009 3:11:00 PM
Record Upd: 3/16/2017 1:50:00 PM
Updated By: KATHOMPS
Own Op: On-Site Operator
Sub Type: 08
Owner Name: Robert R. O'Brien
Owner Company: Apparel + Plus Textile Rental, LLC
Owner Address: 27 Centre Avenue/10 Bartells Place
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Own Op:	Owner
Sub Type:	NNN
Owner Name:	ROBERT O'BRIEN
Owner Company:	WORKING MAN'S CLOSET, INC
Owner Address:	3 KOLBERT DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	SCARSDALE, NY 10583
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Mr Burton Dorfman, Esq.
Owner Company:	Industrial Overall Service Corporation
Owner Address:	10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Region 3 Headquarters
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	21 South Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
HW Code:	360109
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	360087

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 5/21/2009 3:07:00 PM
Record Updated: 5/21/2009 3:07:00 PM
Updated By: RXKEATIN
Crossref ID: 1309988
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 4/14/2014 11:03:00 AM
Record Updated: 4/14/2014 11:03:00 AM
Updated By: RDBENDEL
Crossref ID: 1310684
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/14/2014 8:19:00 AM
Record Updated: 2/14/2014 8:19:00 AM
Updated By: ELMOORE

CBS:
CBS Number: 3-000235
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 3
UTMX: 602235.14737
UTMY: 4529262.58924

M176 **INDUSTRIAL OVERALL SERVICE CORP.** **NY UST** **U004176640**
SW **10 BARTELLS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
819 ft. **Site 10 of 11 in cluster M**

Relative: WESTCHESTER CO. UST:
Lower
Actual: Id/Status: 3-025453 / Unregulated
81 ft. Operator Name: Robert O'Brien
Owner Name: Industrial Overall Service Corp.
Owner Street: 10 Bartels Place
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 4000
Product Stored: 0009. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1979
Date Perm Closure: 03/11/2003
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **U004176640**

Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1980
Date Perm Closure:	08/26/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	0. None

M177 **INDUSTRIAL OVERALL** **NY CBS AST** **S105455801**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
819 ft. **Site 11 of 11 in cluster M**

Relative:
Lower

Actual:
81 ft.

R178 **CON EDISON** **NY MANIFEST** **S117318285**
South **MAIN ST & CENTRE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 8 of 12 in cluster R**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004658019
Facility Status:	Not reported
Location Address 1:	MAIN ST & CENTRE ST
Code:	BP
Location Address 2:	MH734
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

CON EDISON (Continued) **S117318285**

NY MANIFEST:

EPAID:	NYP004658019
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2014
Trans1 Recv Date:	09/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004658019
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771786JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117318285**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

R179 **CON EDISON** **NJ MANIFEST** **S120669849**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 9 of 12 in cluster R**

Relative:
Higher

Actual:
100 ft.

NJ MANIFEST:

EPA Id:	NYP004760815
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091694JJK
EPA ID:	NYP004760815
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120669849**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R180 **CON EDISON** **RCRA NonGen / NLR** **1019901339**
South **CENTRE & MAIN ST** **FINDS** **NYP004760815**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.155 mi.
820 ft. **Site 10 of 12 in cluster R**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/31/2015
Facility name:	CON EDISON
Facility address:	CENTRE & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004760815
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON (Continued) **1019901339**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/31/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069701530

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901339
Registry ID: 110069701530
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069701530

R181 **CON EDISON TRANSFORMER MANHOLE: 2750** **RCRA NonGen / NLR** **1016677840**
South **CENTRE AVE & MAIN ST** **FINDS** **NYP004315198**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.155 mi. **NY MANIFEST**
820 ft. **Site 11 of 12 in cluster R**

Relative: Higher
Actual: 100 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/21/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 2750
Facility address: CENTRE AVE & MAIN ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004315198
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2750
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058871369

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677840
Registry ID: 110058871369
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058871369

NY MANIFEST:
Country: USA
EPA ID: NYP004315198
Facility Status: Not reported
Location Address 1: CENTRE ST & MAIN
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004315198
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/21/2013
Trans1 Recv Date: 05/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/28/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004315198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007019053JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

R182 **CON ED** **NY MANIFEST** **S119074042**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 12 of 12 in cluster R**

Relative: **Higher**

Actual: **100 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004760815
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & MAIN ST
Code:	BP
Location Address 2:	TM 2750
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760815
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760815
Trans1 EPA ID:	Not reported

CON ED (Continued) **S119074042**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091694JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

183
North
1/8-1/4
0.157 mi.
830 ft.

RITZCOVAN - TTF
22 BURLING LANE
NEW ROCHELLE, NY

NY LTANKS **S118263505**
N/A

Relative:
Lower

Actual:
73 ft.

LTANKS:

Facility ID:	1506693
Site ID:	514123
Closed Date:	2016-03-22
Spill Number:	1506693
Spill Date:	2015-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-09-24

RITZCOVAN - TTF (Continued) **S118263505**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2016-03-22
Spiller Name:	Not given
Spiller Company:	Ritzcovan (Owner)
Spiller Address:	22 BURLING LANE
Spiller County:	999
Spiller Contact:	BRUCE
Spiller Phone:	9147120600
Spiller Extention:	1
DEC Region:	3
DER Facility ID:	468599
DEC Memo:	"9/24/15 Spoke to Bruce, the contact, who is trying to arrange tank removal, as he is tentatively purchasing the property from Ritzcovan. I gave him a list of contractors in Westchester. dw 3/22/16: Grazi-1 Environmental disposed of the leaking UST and approximately 10.15 tons of petroleum contaminated soil. Soil sample results submitted for review. Tank Closure Report entered into DecDocs system. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"unknown whether contaminated. option recover & repair, or remove; unknown at this time"

All TTF:

Facility ID:	1506693
Spill Number:	1506693
Spill Tank Test:	2498471
Site ID:	514123
Tank Number:	Not reported
Tank Size:	275
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	DXWEITZ
Last Modified Date:	Not reported

All Materials:

Site ID:	514123
Operable Unit ID:	1263331
Operable Unit:	01
Material ID:	2267021
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RITZCOVAN - TTF (Continued) **S118263505**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

T184 **CON EDISON MANHOLE: 12245** **RCRA NonGen / NLR** **1016677186**
North **NORTH AVE & BURLING LANE** **FINDS** **NYP004307492**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.158 mi. **NY MANIFEST**
834 ft. **Site 2 of 3 in cluster T**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/06/2013
Facility name:	CON EDISON MANHOLE: 12245
Facility address:	NORTH AVE & BURLING LANE NEW ROCHELLE, NY 10801
EPA ID:	NYP004307492
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/06/2013
Site name:	CON EDISON MANHOLE: 12245
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Registry ID: 110058877531

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677186
Registry ID: 110058877531
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058877531

NY MANIFEST:
Country: USA
EPA ID: NYP004307492
Facility Status: Not reported
Location Address 1: NORTH AVE & BURLING LANE
Code: BP
Location Address 2: MH 12245
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10580
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004307492
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: MAD039322250
Trans2 State ID: MAD039322250
Generator Ship Date: 05/06/2013
Trans1 Recv Date: 05/06/2013
Trans2 Recv Date: 05/07/2013
TSD Site Recv Date: 05/07/2013

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307492
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	004816866FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S185 **STORAGE USA** **NY UST** **U003949850**
SSW **363 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.164 mi.
868 ft. **Site 2 of 5 in cluster S**

Relative: **Lower**
Actual: **92 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-801137 / Administratively Closed
Operator Name:	Narine Nathu
Owner Name:	SUSA Partnership, L.P.
Owner Street:	175 Toyota Plaza
Owner Address2:	Not reported
Owner City:	Memphis
Owner State:	TN
Owner Zipcode:	38103
GDS Number:	Not reported

STORAGE USA (Continued) **U003949850**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1934
Date Perm Closure:	03/15/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

U186 **CASARRA RESIDENCE** **NY LTANKS** **S105997517**
West **9 BADEAU PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.165 mi.
869 ft. **Site 1 of 4 in cluster U**

Relative: LTANKS:
Higher

Actual:
104 ft.

Facility ID:	0209171
Site ID:	157707
Closed Date:	2003-02-05
Spill Number:	0209171
Spill Date:	2002-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-12-06
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-06
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	9 BADEAU PL
Spiller County:	001
Spiller Contact:	SAL CASARRA
Spiller Phone:	(914) 235-0620
Spiller Extention:	Not reported

CASARRA RESIDENCE (Continued) **S105997517**

DEC Region: 3
DER Facility ID: 133349
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/05/2003 Northeast Environmental removed the tank and reported that no contamination was present. NFA TG"
Remarks: "uncover repair and retest"

All Materials:
Site ID: 157707
Operable Unit ID: 860605
Operable Unit: 01
Material ID: 516149
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

V187 **NYNEX** **NY LTANKS** **S100164268**
WNW **40 WASHINGTON AVE** **N/A**
1/8-1/4 **GREENBUSH, NY**
0.175 mi.
922 ft. **Site 1 of 4 in cluster V**

Relative: **Higher**
Actual: **112 ft.**

LTANKS:
Facility ID: 8803234
Site ID: 60528
Closed Date: 1988-07-22
Spill Number: 8803234
Spill Date: 1988-07-14
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-07-22
SWIS: 6000
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-07-14
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 1988-07-22
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-03-28
Spill Record Last Update: 1988-09-07
Spiller Name: Not reported
Spiller Company: JOHN ALBARANO
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported

NYNEX (Continued) **S100164268**

Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59075
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK PUMED OUT.TO BE REMOVED. "
Remarks:	"#2FUEL 5K 1.842 / 4K .170 DIESEL"

All TTF:

Facility ID:	8803234
Spill Number:	8803234
Spill Tank Test:	1534290
Site ID:	60528
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	60528
Operable Unit ID:	918404
Operable Unit:	01
Material ID:	458797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

W188 **DRIVE IT YOURSELF** **NY UST** **U004176354**
NNE **20 GARDEN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.176 mi.
927 ft. **Site 1 of 2 in cluster W**

Relative: **Lower**
Actual: **71 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-494380 / Unregulated
Operator Name:	Drive It Yourself
Owner Name:	Ed;edward Jr;tim Tostanowski
Owner Street:	128 Saw Mill River Rd.
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported

DRIVE IT YOURSELF (Continued) **U004176354**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1974
Date Perm Closure:	02/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

X189 **ROTH CLEANERS** **RCRA NonGen / NLR** **1000237840**
SSE **1 LEROY PL** **FINDS** **NYD078706686**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.177 mi. **NY DRYCLEANERS**
937 ft. **Site 1 of 2 in cluster X** **NY MANIFEST**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROTH CLEANERS
Facility address:	1 LEROY PL NEW ROCHELLE, NY 10805
EPA ID:	NYD078706686
Mailing address:	LEROY PL NEW ROCHELLE, NY 10805
Contact:	BEN ROTH
Contact address:	LEROY PL NEW ROCHELLE, NY 10805
Contact country:	US
Contact telephone:	914-633-7114
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BEN ROTH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

ROTH CLEANERS (Continued) **1000237840**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROTH CLEANERS
Classification: Not a generator, verified

Date form received by agency: 08/27/1986
Site name: ROTH CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest

ROTH CLEANERS (Continued) **1000237840**

Date violation determined: 04/24/1987
Date achieved compliance: 04/26/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/24/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 04/26/1987
Evaluation lead agency: State

FINDS:

Registry ID: 110004370369

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000237840
Registry ID: 110004370369
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004370369

DRYCLEANERS:
Facility ID: 3-5510-00292
Phone Number: 914-633-7114
Region: Not reported
Registration Effective Date: N/A
Inspection Date: 09JUL16
Install Date: 98
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

ROTH CLEANERS (Continued) **1000237840**

NY MANIFEST:

Country:	USA
EPA ID:	NYD078706686
Facility Status:	Not reported
Location Address 1:	1 LEROY PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD078706686
Mailing Name:	ROTH CLEANERS
Mailing Contact:	ROTH CLEANERS
Mailing Address 1:	1 LEROY PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337114

NY MANIFEST:

Document ID:	NYC6190896
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/23/2000
Trans1 Recv Date:	06/23/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

ROTH CLEANERS (Continued) **1000237840**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
140 additional NY_MANIFEST: record(s) in the EDR Site Report.

X190 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243086**
SSE **DIVISION ST & LEROY PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.181 mi.
956 ft. **Site 2 of 2 in cluster X**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004124210
Facility Status:	Not reported
Location Address 1:	DIVISION ST & LEROY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004124210
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

CONSOLIDATED EDISON (Continued) **1009243086**

NY MANIFEST:

Document ID:	NYE1309986
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	46614JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/30/2004
Trans1 Recv Date:	08/30/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004124210
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00014
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y191 **CON ED-V37** **NY MANIFEST** **S109064681**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.182 mi.
959 ft. **Site 1 of 2 in cluster Y**

Relative: **Lower**

Actual: **87 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004027967
Facility Status:	Not reported

CON ED-V37 (Continued) **S109064681**

Location Address 1: LECOUNT PL & MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: 0000

NY MANIFEST:
EPAID: NYP004027967
Mailing Name: CON ED-V37
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

Y192 **CON ED-V14** **NY MANIFEST** **S109064677**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.182 mi.
959 ft. **Site 2 of 2 in cluster Y**

Relative:
Lower

Actual:
87 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004028122
Facility Status: Not reported
Location Address 1: LECOUNT PL & MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: 0000

NY MANIFEST:
EPAID: NYP004028122
Mailing Name: CON ED-V14
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

U193 **RESIDENCE** **NY LTANKS** **S102663947**
WNW **18 BADEAU PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.183 mi.
964 ft. **Site 2 of 4 in cluster U**

Relative:
Higher

Actual:
104 ft.

LTANKS:

Facility ID:	9609269
Site ID:	177416
Closed Date:	1996-10-24
Spill Number:	9609269
Spill Date:	1996-10-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-24
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-24
Spill Record Last Update:	1996-12-05
Spiller Name:	Not reported
Spiller Company:	JULIO VALER
Spiller Address:	18 BADEAU PLACE
Spiller County:	001
Spiller Contact:	JULIO VALER
Spiller Phone:	(914) 636-8917
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149078
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED TOO MUCH OIL. SPILLED ONTO BLACKTOP DRIVEWAY. CLEANED UP."

All Materials:

Site ID:	177416
Operable Unit ID:	1037374
Operable Unit:	01
Material ID:	345000
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

Z194 **J B & FRANKS** **RCRA NonGen / NLR** **1000100357**
SW **27 BARTELS PL** **FINDS** **NYD986884732**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.185 mi. **NY MANIFEST**
976 ft. **Site 1 of 5 in cluster Z**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	J B & FRANKS
Facility address:	27 BARTELS PL NEW ROCHELLE, NY 10801-6901
EPA ID:	NYD986884732
Mailing address:	BARTELS PL NEW ROCHELLE, NY 10804
Contact:	Not reported
Contact address:	BARTELS PL NEW ROCHELLE, NY 10804
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ANTHONY LANTZ
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ANTHONY LANTZ
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

J B & FRANKS (Continued) **1000100357**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 12/01/1989
Site name: J B & FRANKS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004439705

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000100357
Registry ID: 110004439705
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004439705

NY MANIFEST:
Country: USA
EPA ID: NYD986884732
Facility Status: Not reported
Location Address 1: 27 BARTELS PLACE
Code: BP
Location Address 2: Not reported

J B & FRANKS (Continued) **1000100357**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10804
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986884732
Mailing Name:	J B FRANKS
Mailing Contact:	J B FRANKS
Mailing Address 1:	27 BARTELS PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10804
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146360570

NY MANIFEST:

Document ID:	NYA7038792
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	N23008
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/1989
Trans1 Recv Date:	12/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/07/1989
Part A Recv Date:	01/24/1990
Part B Recv Date:	12/18/1989
Generator EPA ID:	NYD986884732
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)

J B & FRANKS (Continued) **1000100357**

Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

V195 **SAINT GABRIEL HIGH SCHOOL** **NY UST** **U003994885**
WNW **50 WASHINGTON AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.186 mi.
984 ft. **Site 2 of 4 in cluster V**

Relative:
Higher

Actual:
110 ft.

WESTCHESTER CO. UST:
Id/Status: 3-058122 / Active
Operator Name: Church of Saint Gabriel
Owner Name: Church of St. Gabriel
Owner Street: 120 Division Street
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 3000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 09/02/2003
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 2
Status: 1. In-Service
Capacity: 3000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 09/01/2003
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron

SAINT GABRIEL HIGH SCHOOL (Continued) **U003994885**

Tank Internal Protection:	0. None
Tank External Protection:	5. Jacketed
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	11. Flexible Piping
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

V196 **ST GABRIEL SCHOOL** **NY LTANKS** **S105999147**
WNW **50 WASHINGTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.186 mi.
984 ft. **Site 3 of 4 in cluster V**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Facility ID:	0302359
Site ID:	314440
Closed Date:	2003-12-12
Spill Number:	0302359
Spill Date:	2003-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2003-12-12
Spiller Name:	LARRY
Spiller Company:	ST GABRIEL SCHOOL
Spiller Address:	50 WASHINGTON AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 12/12/03 ALSO REPORTED AS 03-05820. SEE THAT FILE FOR UPDATES. NFA THIS NUMBER."
Remarks:	""

All TTF:

Facility ID:	0302359
Spill Number:	0302359

ST GABRIEL SCHOOL (Continued) **S105999147**

Spill Tank Test:	1528429
Site ID:	314440
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314440
Operable Unit ID:	869188
Operable Unit:	01
Material ID:	506840
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

V197 **50 WASHINTON AVE** **NY LTANKS** **S105999773**
WNW **50 WASHINTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.186 mi.
984 ft. **Site 4 of 4 in cluster V**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Facility ID:	0305820
Site ID:	280324
Closed Date:	2003-12-23
Spill Number:	0305820
Spill Date:	2003-09-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-09-02
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

50 WASHINTON AVE (Continued) **S105999773**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-02
Spill Record Last Update:	2004-01-08
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	MIGEL ROSARIO
Spiller Phone:	(914) 632-0211
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	227605
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 12/12/03 PREVIOUSLY REPORTED AS SPILL 03-02359. 12/26/03: Letter sent to Fr. Patrick V. McNamara, St Gabriel Church-Archdiocese NY from Wayne Schneider, WCDOH dated 23Dec2003. Closure report has been reviewed. WCDOH recommends NFAA at this time."
	Not reported
Remarks:	"ST GABRIELS CHURCH - FR PATRICK MCNAMARA WOULD LIKE A CALL HE CAN BE REACHED AT 914-632-0211 THE CHURCH IS RESPONSIBLE FOR THE SPILL "

All Materials:

Site ID:	280324
Operable Unit ID:	874264
Operable Unit:	01
Material ID:	503057
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S198 **CON EDISON** **NY MANIFEST** **S117535594**
SSW **HUGENOT AVE & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 3 of 5 in cluster S**

Relative: **Lower**

Actual: **91 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677621
Facility Status:	Not reported
Location Address 1:	HUGENOT AVE & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677621
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117535594**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774907JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117535594**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S199 **CON EDISON** **NY MANIFEST** **S117536317**
SSW **HUGUENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.188 mi.
990 ft. **Site 4 of 5 in cluster S**

Relative:
Lower

Actual:
91 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004687802
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004687802
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2014
Trans1 Recv Date:	10/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004687802
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773160JJK
Import Indicator:	N

CON EDISON (Continued) **S117536317**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S200 **CON EDISON** **NY MANIFEST** **S117535600**
SSW **HUGENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 5 of 5 in cluster S**

Relative:
Lower

Actual:
91 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677837
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677837
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported

CON EDISON (Continued) **S117535600**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677837
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774864JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117535600**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

W201 **FURNITURE RESTORNATION CENTER** **RCRA NonGen / NLR** **1000872286**
NNE **26 GARDEN ST** **FINDS** **NYD987034998**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.189 mi. **NY MANIFEST**
997 ft. **Site 2 of 2 in cluster W**

Relative: **Lower**
Actual: **72 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FURNITURE RESTORNATION CENTER
Facility address:	26 GARDEN ST NEW ROCHELLE, NY 10801-4204
EPA ID:	NYD987034998
Mailing address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-633-9292
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-633-9292
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 06/02/1993
Site name: FURNITURE RESTORNATION CENTER
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/02/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004505287

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000872286
Registry ID: 110004505287
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004505287

NY MANIFEST:
Country: USA
EPA ID: NYD987034998
Facility Status: Not reported
Location Address 1: 26 GARDEN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD987034998
Mailing Name: FURNITURE RESTORATION OF NEW ROCHELLE
Mailing Contact: HENRY FLAVIC
Mailing Address 1: 166 WEBSTER AVE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: 6111
Mailing Country: USA
Mailing Phone: 9145923132

NY MANIFEST:
Document ID: NYG1592532
Manifest Status: Not reported
seq: 01
Year: 2000
Trans1 State ID: AE53110PA

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Trans2 State ID:	Not reported
Generator Ship Date:	07/06/2000
Trans1 Recv Date:	07/06/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00935
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	017
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
4 additional NY_MANIFEST: record(s) in the EDR Site Report.

U202 **DIIORGI HOME** **NY LTANKS** **S106869098**
West **47 WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.189 mi.
999 ft. **Site 3 of 4 in cluster U**

Relative: LTANKS:
Higher

Facility ID:	0500295
Site ID:	343230
Closed Date:	2005-08-28
Spill Number:	0500295
Spill Date:	2005-04-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010

Actual:
98 ft.

DIIORGI HOME (Continued) **S106869098**

Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2005-08-28
Spiller Name:	ANTHONY DIIORGI
Spiller Company:	DIIORGI HOME
Spiller Address:	47 WARREN STREET
Spiller County:	001
Spiller Contact:	ANTHONY DIIORGI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	289715
DEC Memo:	"August 28, 2005: GC RELIABLE REMOVED LUST AND CONTAMINATED SOIL. NORTHEST ENVIRONMENTAL DISPOSED OF 18 DRUMS OF SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SHE WILL CALLL BACK WITH MORE INFO:"

All Materials:

Site ID:	343230
Operable Unit ID:	1101915
Operable Unit:	01
Material ID:	582154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z203 **CON EDISON** **RCRA NonGen / NLR** **1014398214**
SW **35 BARTELS PL** **NY MANIFEST** **NYP004205654**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 2 of 5 in cluster Z**

Relative: **Lower**
Actual: **67 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/05/2015
Facility name:	CON EDISON
Facility address:	35 BARTELS PL NEW ROCHELLE, NY 10805
EPA ID:	NYP004205654
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

CON EDISON (Continued) **1014398214**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/05/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004205654
Facility Status: Not reported
Location Address 1: 35 BARTELS PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004205654
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON (Continued) **1014398214**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2010
Trans1 Recv Date:	04/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004205654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	002012659FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z204 **CON EDISON** **NY MANIFEST** **S117741191**
SW **35 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 3 of 5 in cluster Z**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004744074
Facility Status:	Not reported
Location Address 1:	35 BARTELS PL
Code:	BP
Location Address 2:	DRIP WATER
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004744074
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	008683680FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117741191**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
20 additional NY_MANIFEST: record(s) in the EDR Site Report.

T205 **CON EDISON MANHOLE: 4179** **RCRA NonGen / NLR** **1016969613**
North **350 NORTH AVE** **NY MANIFEST** **NYP004432886**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.194 mi.
1022 ft. **Site 3 of 3 in cluster T**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/04/2014
Facility name:	CON EDISON MANHOLE: 4179
Facility address:	350 NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004432886
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/04/2014
Site name: CON EDISON MANHOLE: 4179
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004432886
Facility Status: Not reported
Location Address 1: OPP 350 NORTH AVE
Code: BP
Location Address 2: MH4179
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004432886
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/04/2014
Trans1 Recv Date: 02/04/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/04/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004432886

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692716JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AA206 **APT BUILDING** **NY LTANKS S105230135**
West **40 WARREN STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.194 mi.
1022 ft. **Site 1 of 7 in cluster AA**

Relative: LTANKS:
Lower

Actual: Facility ID:	0109254
92 ft. Site ID:	150939
Closed Date:	2001-12-19
Spill Number:	0109254
Spill Date:	2001-12-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported

APT BUILDING (Continued) **S105230135**

Reported to Dept:	2001-12-19
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-19
Spill Record Last Update:	2002-01-03
Spiller Name:	Not reported
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MALLARDI RES
Spiller Phone:	(914) 636-7448
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128278
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"DRIVER OVERFILLED TANK - SPILL CONTAINED WITH PADS - CLEAN UP CREW ENROUTE"

All Materials:

Site ID:	150939
Operable Unit ID:	846633
Operable Unit:	01
Material ID:	530463
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0812107
Site ID:	409713
Closed Date:	2009-03-03
Spill Number:	0812107
Spill Date:	2009-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

APT BUILDING (Continued) **S105230135**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-06
Spill Record Last Update:	2009-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	359905
DEC Memo:	"Piping failure, need to repair and retest - mm 02/20/2009 Passed retest results that came into PBS to J. O'Dee---BHY 3/3/09: Review of report submitted by WCC Tank Technology. Tank was tested by WCC on 1-9-09 for the property owner. The tank passed the test and documentation was submitted to the owner and the New Rochelle FD. Elite Environmental tested the tank for a prospective buyer on 2-6-09 and failed the tank, resulting in this spill report to the DEC. On 2-12-09 WCC again tested the tank with reps from New Rochelle FD and Royal Environmental. The tank passed this test. All three tests were preformed with the Horner Locator Plus system. Based upon the information received as of this date, DEC is requiring No Further Action at this time. jod"
Remarks:	"550 gal tank failed test/ failure due to bad fitting"

All Materials:

Site ID:	409713
Operable Unit ID:	1166213
Operable Unit:	01
Material ID:	2157665
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	0908848
Facility Type:	ER
Spill Number:	0908848
DER Facility ID:	128278
Site ID:	421508
DEC Region:	3
Closed Date:	2010-04-08
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-06
Investigator:	TDGHIOSA
Referred To:	Not reported

APT BUILDING (Continued) **S105230135**

Reported to Dept:	2009-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-06
Spill Record Last Update:	2010-04-08
Spiller Name:	GABREILLE BARRAGAN
Spiller Company:	GABREILLE BARRAGAN
Spiller Address:	40 WARREN ST
Spiller Company:	999
Contact Name:	NIKKI RICKETTS
DEC Memo:	"11/06/09: Property was purchased by a new owner within the past year. New owner passed away, his wife was having the tank replaced for sale of the property. Northeast installed a new AST in the basement and pulled this 1K tank. Contamination evident. New Rochelle FD inspected. Northeast will be completing clean up. jod 02/09/10 Northeast Environmental reported that they excavated and removed one tank along with 35.64 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG"
Remarks:	"REMOVAL OF A 1000 GALLON UST SOIL CONTAMINATION FOUND CLEAN UP PENDING."

All Materials:

Site ID:	421508
Operable Unit ID:	1177396
Operable Unit:	01
Material ID:	2170184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AB207 **CON EDISON TRANSFORMER MANHOLE: 5365** **RCRA NonGen / NLR** **1016972665**
South **595 MAIN ST** **NY MANIFEST** **NYP004464459**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.196 mi.
1035 ft. **Site 1 of 5 in cluster AB**

Relative:
Lower

Actual:
93 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/12/2014
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5365
Facility address:	595 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004464459
Mailing address:	IRVING PL, 15TH FL NE

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/12/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 5365
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004464459
Facility Status: Not reported
Location Address 1: 595 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10804
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004464459
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/12/2014
Trans1 Recv Date:	03/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004464459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771156JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z208 **RUSH MFG CORP** **RCRA NonGen / NLR** **1000238316**
SSW **18 COLUMBUS AVE.** **FINDS** **NYD981185051**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.199 mi. **NY MANIFEST**
1053 ft. **Site 4 of 5 in cluster Z**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RUSH MFG CORP
Facility address:	18 COLUMBUS AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD981185051
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact:	DENNIS MCNAMARA
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-2700
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

RUSH MFG CORP (Continued) **1000238316**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MFG CORP
Classification: Not a generator, verified

Date form received by agency: 03/03/1986
Site name: RUSH MFG CORP
Classification: Small Quantity Generator

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Violation Status: No violations found

FINDS:

Registry ID: 110002092967

Environmental Interest/Information System
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000238316
Registry ID: 110002092967
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002092967

NY MANIFEST:
Country: USA
EPA ID: NYD981185051
Facility Status: Not reported
Location Address 1: 381 HUGUENOT STREET
Code: BP

RUSH MFG CORP (Continued) **1000238316**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981185051
Mailing Name:	RUSH MANUFACTURING CORPORATION
Mailing Contact:	RUSH MANUFACTURING CORPORATION
Mailing Address 1:	381 HUGUENOT STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142362700

NY MANIFEST:

Document ID:	NJA2751945
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1997
Trans1 Recv Date:	12/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1997
Part A Recv Date:	01/15/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050

RUSH MFG CORP (Continued) **1000238316**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
36 additional NY_MANIFEST: record(s) in the EDR Site Report.

U209 **NYNEX** **NY MANIFEST** **1009234555**
West **UNION AVENUE AND WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.201 mi.
1063 ft. **Site 4 of 4 in cluster U**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP000932509
Facility Status:	Not reported
Location Address 1:	UNION AVENUE AND WARREN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000932509
Mailing Name:	NYNEX
Mailing Contact:	V ORCHIER
Mailing Address 1:	221 EAST 37TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123387126

NY MANIFEST:

Document ID:	MIA4512835
Manifest Status:	K
seq:	Not reported
Year:	1996
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1996
Trans1 Recv Date:	12/17/1996
Trans2 Recv Date:	12/20/1996
TSD Site Recv Date:	01/03/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/23/1997
Generator EPA ID:	NYP000932509
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574

NYNEX (Continued) **1009234555**

TSDF ID 1:	MID096963194
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AB210 **CON EDISON TRANSFORMER MANHOLE: 2806** **RCRA NonGen / NLR** **1016962648**
South **592 MAIN ST** **NY MANIFEST** **NYP004357059**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.202 mi.
1065 ft. **Site 2 of 5 in cluster AB**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/09/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2806
Facility address:	592 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004357059
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/09/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2806
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004357059
Facility Status: Not reported
Location Address 1: 592 MAIN ST.
Code: BP
Location Address 2: MH # 2806
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004357059
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/09/2013
Trans1 Recv Date: 09/09/2013

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004357059
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707806JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

---

211 **CITIZEN** **NY LTANKS** **S100165790**
WSW **33 GROVE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.202 mi.
1067 ft.

Relative: **Lower**
Actual: **89 ft.**

LTANKS:

Facility ID:	8708588
Site ID:	135309
Closed Date:	1989-11-28
Spill Number:	8708588
Spill Date:	1988-01-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling

CITIZEN (Continued) **S100165790**

Spill Class:	Not reported
Cleanup Ceased:	1989-11-28
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-27
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	CAPT. FERGESON
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK RUPTURE IN CITIZEN'S BASEMENT. TANK TO BE EMPTIED."

All Materials:

Site ID:	135309
Operable Unit ID:	913258
Operable Unit:	01
Material ID:	463968
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	550.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC212 **THE MALL** **NY LTANKS** **S100141913**
East **MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.204 mi.
1079 ft. **Site 1 of 3 in cluster AC**

Relative: LTANKS:
Lower

Facility ID:	9010648
Site ID:	326514
Closed Date:	1991-01-04
Spill Number:	9010648
Spill Date:	1991-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

Actual:
80 ft.

THE MALL (Continued) **S100141913**

Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-10
Spill Record Last Update:	1992-07-31
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	263025
DEC Memo:	"Administratively closed due to file review and/or information received. If new information arises to contradict this determination DEC reserves the right to reopen this spill without prejudice. Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WATER FOUND IN TANK TO BE PUMPED OUT HONER EASY -.087"

All TTF:

Facility ID:	9010648
Spill Number:	9010648
Spill Tank Test:	1538129
Site ID:	326514
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	326514
Operable Unit ID:	947782
Operable Unit:	01
Material ID:	430787

THE MALL (Continued) **S100141913**

Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AD213 **175 MEMORIAL HWY. REALTY, INC.** **NY UST** **U003994239**
NNW **175 MEMORIAL HWY.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.205 mi.
1081 ft. **Site 1 of 2 in cluster AD**

Relative:
Lower

Actual:
85 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800711 / Unregulated: <1101 gal. PBS
Operator Name:	A. Langhitano
Owner Name:	175 Memorial Hwy. Realty, Inc.
Owner Street:	175 Memorial Hwy.
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10802
GDS Number:	Not reported
Tank Number:	175-1
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AE214 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1016973761**
South **LEROY PL & CENTER AVE** **NY MANIFEST** **NYP004475687**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.205 mi.
1084 ft. **Site 1 of 5 in cluster AE**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/22/2014
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	LEROY PL & CENTER AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004475687
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/22/2014
Site name:	CON EDISON SERVICE BOX: 3313
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004475687
Facility Status:	Not reported
Location Address 1:	SEC LEROY & CENTRE AVE
Code:	BP
Location Address 2:	SB3313
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004475687
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/22/2014
Trans1 Recv Date: 03/22/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/25/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004475687
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772784JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 10
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE215 **CON EDISON** **NY MANIFEST** **S117059593**
South **CENTRE AVE & LEROY** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1084 ft. **Site 2 of 5 in cluster AE**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004517694
Facility Status:	Not reported
Location Address 1:	C/O CENTRE AVE & LEROY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004517694
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004517694
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117059593**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772797JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE216 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1017773973**
South **CENTRE AVE & LEROY** **FINDS** **NYP004517694**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1084 ft. **Site 3 of 5 in cluster AE**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	05/30/2014
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	CENTRE AVE & LEROY NEW ROCHELLE, NY 10801
EPA ID:	NYP004517694
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

Actual:
101 ft.

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063800506

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AF217 **THE HUGUENOT** **NY BROWNFIELDS** **S120706214**
SSW **381-393 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1091 ft. **Site 1 of 4 in cluster AF**

Relative: **Lower**
Actual: **90 ft.**

BROWNFIELDS:

Program:	BCP
Site Code:	544502
Acres:	Not reported
HW Code:	C360157
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	03/29/2017
Record Updated Date:	06/19/2017
Update By:	LSZINOMA
Site Description:	LOCATION: The Site is located at 381-393 Huguenot Street, in an urban area in New Rochelle, New York. The Site is bound to the north by a vacant store (first floor) with residential above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a Gulf labeled gasoline filling station; and to the west by an office building/warehouse. SITE FEATURES: The Subject Property consists of these (3) irregular shaped parcels totaling approximately 0.39 acres. The property currently maintains two structures. Lot 7 currently maintains an irregular shaped one-story building (with partial basement), with an approximate footprint of 3,400-square feet. This building is currently utilized for office and storage space associated with a U-Haul business, a real-estate firm, and a janitorial supply business. The first floor of the buildings maintained on Lots 3A and 4 house a church ministry, with the second floors occupied by one residential unit in each. The basement on Lot 4 is occupied by a hydraulic repair business. CURRENT ZONING AND LAND USE: The Site is currently utilized for mixed commercial and residential uses. The surrounding parcels are currently utilized for mixed commercial and residential uses. The Site is located within the City of New Rochelle s recently designated Downtown Overlay Zone (DOZ). The DOZ is part of a new zoning plan adopted in 2015 to re-establish the downtown as a center of vibrancy within a mixed-use, transit oriented setting. The characteristics of the Site allow a building of up to six stories, with the provision by the developer of a community benefit. Past Use of the Site: The northern portion of the Site (Lots 3A and 4 at 381 and 383 Huguenot Street) has been utilized for dry cleaning services circa 1931, and for manufacturing since the 1970s to 2010s. The potential source of contamination in this area includes former dry cleaning operations and the former fuel oil USTs. The central portion of the Site (385 & 387 Huguenot)has maintained a residential dwelling circa 1931, and as truck and trailer parking since 1990s. The potential source of contamination in this area includes a former fuel oil UST, which was removed prior to 1997. The southern portion of the Site (Lots 5 and 7 at 391 and 393 Huguenot)has maintained a gasoline filling station from 1930s to 1950s, and then as car wash and warehouse from 1970s to 2010s. The potential source of contamination in this area includes former gasoline USTs and car wash operation. In addition, urban fill material was detected throughout the site. Site Geology and Hydrogeology: Per the United State Department of Agriculture (USDA) Natural Resources Conservation Service, the soil at the Subject Property is classified as Uh-Urban. Actual soil conditions observed

THE HUGUENOT (Continued) **S120706214**

	during the Phase II ESA and the SSI field activities revealed that the subsurface soil consists of dark to brown medium to coarse sand from grade to 10 feet below. Groundwater was encountered at approximately 6 to 8 feet below grade. Site-specific groundwater flow direction is towards northwest.
Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Larry Sheldon
Owner Company:	New Rochelle Public Library
Owner Address:	One Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P02
Owner Name:	Frank Chechile
Owner Company:	381-383 Huguenot LLC
Owner Address:	11604 Luvie Ct.
Owner Addr2:	Not reported
Owner City,St,Zip:	Potamac, MD 20854
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AG218 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016970578**
ESE **174 NORTH AVE** **NY MANIFEST** **NYP004442943**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1092 ft. **Site 1 of 11 in cluster AG**

Relative:
Lower

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	174 NORTH AVE NEW ROCHELLE, NY 10804
EPA ID:	NYP004442943
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/16/2014
Site name:	CON EDISON SERVICE BOX: 2040
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004442943
Facility Status:	Not reported
Location Address 1:	FO 174 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004442943
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004442943
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692698JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 40
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH219 **SCHMUCKLER'S DRY CLEANERS** **NY BROWNFIELDS** **S107787044**
North **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.209 mi.
1102 ft. **Site 1 of 12 in cluster AH**

Relative: **Lower**
Actual: **74 ft.**

BROWNFIELDS:

Program:	BCP
Site Code:	357446
Acres:	0.21
HW Code:	C360088
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/29/2005
Record Updated Date:	12/30/2016
Update By:	DACROSBY
Site Description:	Location: The Schmuckler s Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. The site is 0.21 acres, most of which is covered by a two-story row building with a full basement. Site Features: In addition to the former dry cleaners, historically located on the first floor, the site also includes an enclosed backyard area to the immediate west of the building. The backyard is mostly covered by lawn, but also includes elevated planting beds, and a paved walkway. Current Zoning/Use(s): The site is commercially zoned, and currently has five commercial tenants occupying both the first and second floors. Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commerical uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site is provided from a municipal source. Past Uses of the Site: The building on-site was built in 1891, and operated by Schmuckler s Cleaners from 1914 to 2006 on the first floor and basement of the building. Additions were added to the building in 1937, and two in 1987. The site was acquired by the Volunteer, HNJ Realty, LLC, in August 2005, and entered into a BCA in June 2006. An interim remedial measure (IRM) was conducted starting in late 2008 to install a combined soil vapor extraction system/sub-slab depressurization system (SVE/SSDS) in the former dry cleaner to mitigate PCE in indoor air. The IRM was deemed complete in December 2013, but the SVE/SSDS continues to operate. A second IRM work plan was approved in May 2015 to conduct a pilot study of an enhanced biological in situ treatment to remediate contaminants under the on-site building slab. Site Geology and Hydrogeology: The site is underlain by fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater flows to the southeast. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater.

Env Problem: Based on the investigations conducted to date, the primary contaminants of concern at the site are chlorinated volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE) and its breakdown compounds, in soils, groundwater, sub-slab vapor, and soil gas; petroleum-related VOCs in soils, groundwater, sub-slab vapor, and soil gas; and semi-volatile organic compounds (SVOCs) in groundwater. Soils: Tetrachloroethylene (PCE), trichloroethene (TCE), and multiple petroleum related VOCs were detected in onsite soils underneath the building slab. The highest concentration of PCE at 210 parts per million (ppm), exceeding restricted commercial soil cleanup objectives (SCOs), was located underneath the former dry cleaning equipment room. Other contaminants detected in soils only exceeded the Protection of Groundwater SCOs. These exceedences were largely in soils located downgradient of the dry cleaning equipment room and consisted of: TCE at 1.3 ppm, cis-1,2 dichloroethene (cis-1,2-DCE) at 3 ppm, n-propylbenzene at 16 ppm, m+p xylenes at 15 ppm, ethylbenzene at 6.6 ppm, 1,3,5-trimethylbenzene at 63 ppm, and 1,2,4-trimethylbenzene at 99 ppm. Groundwater: Petroleum-based floating product (LNAPL, or light non-aqueous phase liquid) was observed in groundwater under much of the on-site building slab, a maximum of 6 inches thick under the former dry cleaning equipment room. Also observed were very high concentrations of select VOCs also under the former drycleaning equipment room. The maximum detected PCE was 830,000 parts per billion (ppb), and TCE at 58,000 ppb, indicating the presence of these compounds as free product DNAPLs (dense non-aqueous phase liquid) in groundwater. 25 individual VOCs were also detected in site groundwater samples exceeding NYS Class GA groundwater standards. These include the above-mentioned PCE, TCE, as well as other maximum detected concentrations of PCE breakdown products: cis-1,2-DCE at 8,700 ppb, and vinyl chloride at 28 ppb. BTEX was detected, with benzene at 62 ppb, toluene at 130 ppb, ethylbenzene at 150 ppb, m+p xylene at 520 ppb, and o-xylene at 290 ppb. Other significant concentrations of VOCs detected in groundwater include 1,3,5-trimethylbenzene at 890 ppb, and 1,2,4-trimethylbenzene at 840 ppb. Eight SVOCs were detected over groundwater standards in groundwater under the building slab, including napthalene at a concentration of 1300 ppb, phenanthrene at 2400 ppb, acenapthene at 710 ppb, and antracene at 280 ppb. Bedrock wells were installed off-site in the downgradient, sidegradient, and upgradient directions. Petroleum-based VOCs and SVOCs were detected in the bedrock aquifer at concentrations above groundwater standards. For VOCs, total maximum BTEX concentration of 722 ppb was detected in a downgradient bedrock well. 11 individual SVOC contaminants were detected over groundwater standards in the same downgradient off-site bedrock well, including naphthalene at 4100 ppb, phenanthrene at 2800 ppb, acenapthene at 710 ppb, and antracene at 300 ppb. The extent of groundwater contamination is concentrated underneath the on-site building slab, with petroleum-based VOC and SVOC contaminants and LNAPL extending off-site in the bedrock downgradient or southeast direction. Soil Gas/Soil Vapor: The high concentrations of PCE (787,000 ug/m3), TCE (15,200 ug/m3), cis-1,2-DCE (46,000 ug/m3), and

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

	Vinyl Chloride (34 ug/m3) in soil vapor under the slab of the on-site building required the installation and continuing operation of a combined soil vapor extraction and sub-slab mitigation system during a 2008-2013 Interim Remedial Measure (IRM) action. PCE (at 91 ug/m3) and TCE (13.4 ug/m3) were also detected in soil gas outside of the building near the location of a former drywell. Benzene (37 ug/m3), toluene (126 ug/m3), ethylbenzene (85 ug/m3), xylene (555 ug/m3), 1,3,5-trimethylbenzene (3 ug/m3), and 1,2,4-trimethylbenzene (14 ug/m3) were also detected in subslab vapor and soil gas. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.
Health Problem:	While direct contact with contaminants in the soil is unlikely because most contaminated soils are found beneath the on-site building, persons who dig below the ground surface adjacent to the building may come into contact with contaminants in subsurface soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. A sub-slab depressurization system was installed in the on-site building to prevent vapors beneath the slab from entering the building. Sampling indicates soil vapor intrusion is not a concern in one adjacent off-site building. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for other nearby off-site buildings.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:54'51 / 73:47'03
Dell:	False
Record Add:	12/29/2005 2:46:00 PM
Record Upd:	11/10/2015 3:54:00 PM
Updated By:	KATHOMPS
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Comfort Homes & Property Management LLC
Owner Address:	358 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	Hal Shapiro
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave #107
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Liberty Plaza

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	HAL SHAPIRO
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave
Owner Addr2:	#107
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	United Community Center of Westchester, Inc.
Owner Address:	360 - 362 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Sarah Shepard
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Neighborhood Taxi
Owner Address:	364 North Ave; Suite 108
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Swan Beauty Spa, Inc
Owner Address:	364 North Ave., Room 101
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	C360088
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	cymene

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,4-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	acenaphthene
Waste Quantity:	UNKNOWN

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Waste Code:	Not reported
HW Code:	C360088
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	diethyl phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1,2,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	fluorine
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Record Updated: Not reported
Updated By: Not reported

AI220 **NEW ROCHELLE HOSPITAL** **NY LTANKS** **S100141273**
NW **COVION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.211 mi.
1115 ft. **Site 1 of 5 in cluster AI**

Relative:
Higher

Actual:
102 ft.

LTANKS:

Facility ID:	9003911
Site ID:	136814
Closed Date:	1991-03-15
Spill Number:	9003911
Spill Date:	1990-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	1991-04-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	117069
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/15/91: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WILL EIR PBS TO FOLLOW AINLEY +.094"

All TTF:

Facility ID:	9003911
Spill Number:	9003911
Spill Tank Test:	1537277
Site ID:	136814
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	136814
Operable Unit ID:	941734
Operable Unit:	01
Material ID:	435036
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AH221 **MAYCO, LLC** **NY AST** **A100252337**
NNW **18-20 MAY ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1118 ft. **Site 2 of 12 in cluster AH**

Relative: **Lower**
Actual: **78 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-175447
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Alex Hay
Owner Name:	Mayco, LLC
Owner Street:	P.O. Box 1755
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10156
Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1980
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None

MAYCO, LLC (Continued) **A100252337**

Piping Secondary Containment: 0. None
Overfill Prevention: 5. Vent Whistle
Spill Prevention: 0. None
Dispenser: 2. Suction

AH222 **SCHMUCKLERS CLEANERS** **RCRA-CESQG** **1000303485**
North **360 NORTH AVE** **NY MANIFEST** **NYD012950770**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1121 ft. **Site 3 of 12 in cluster AH**

Relative: **Lower**
Actual: **75 ft.**

RCRA-CESQG:
Date form received by agency: 03/31/2008
Facility name: SCHMUCKLERS CLEANERS
Facility address: 360 NORTH AVE
NEW ROCHELLE, NY 10801
EPA ID: NYD012950770
Mailing address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact: HAL I SHAPIRO
Contact address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact country: US
Contact telephone: 917-693-9019
Contact email: HALSHAP@GMAIL.COM
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: HNJ REALTY LLC
Owner/operator address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2005
Owner/Op end date: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Owner/operator name: HNJ REALTY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 03/30/2008
Site name: SCHMUCKLERS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Site name: SCHMUKLERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/09/1998
Site name: SCHMUKLERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 10/29/1993
Site name: SCHMUKLERS
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(3)
Area of violation: Generators - General
Date violation determined: 09/08/2003
Date achieved compliance: 09/18/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/18/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/08/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

NY MANIFEST:
Country: USA
EPA ID: NYD012950770
Facility Status: Not reported
Location Address 1: 360 NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD012950770
Mailing Name: SHMUCKLERS DRY CLEANERS
Mailing Contact: SHMUCKLERS DRY CLEANERS
Mailing Address 1: 360 NORTH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146322705

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2017
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 01/31/2017
Trans1 Recv Date: 01/31/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/01/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012950770
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: PAD987270725
TSDF ID 2: Not reported
Manifest Tracking Number: 006197432FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H039
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	D040
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
198 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH223 **SCHMUKLER'S CLEANERS** **NY DRYCLEANERS** **S110247878**
North **360 NORTH AVE.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1121 ft. **Site 4 of 12 in cluster AH**

Relative: **Lower**
Actual: **75 ft.**

DRYCLEANERS:

Facility ID:	3-5510-00327
Phone Number:	914-632-2705
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	07NOV13
Install Date:	98/06
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AI224 **SOUTH SHORE MED CENTER** **NY LTANKS** **S107523501**
NW **16 GUION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.217 mi.
1144 ft. **Site 2 of 5 in cluster AI**

Relative: **Higher**
Actual: **100 ft.**

LTANKS:

Facility ID:	0512440
Site ID:	358758
Closed Date:	2006-12-19
Spill Number:	0512440
Spill Date:	2006-01-26

SOUTH SHORE MED CENTER (Continued) **S107523501**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-01-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2006-12-22
Spiller Name:	VERONICA
Spiller Company:	SOUND SHORE MED CENTER
Spiller Address:	16 GUION PLACE
Spiller County:	001
Spiller Contact:	VERONICA
Spiller Phone:	(201) 489-8700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308757
DEC Memo:	"Tank removed, no contamination found. NFA jod 12/22/06 - Letter from Wayne Schneider of WCDOD dated 8/29/06 addressed to Dir. of Engr., Sound Shore Medical Center, has requested NYSDEC to colose this spill #."
Remarks:	"Tank test failure. Ullage leak was detected."

All TTF:

Facility ID:	0512440
Spill Number:	0512440
Spill Tank Test:	1549678
Site ID:	358758
Tank Number:	5
Tank Size:	2000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	358758
Operable Unit ID:	1115985
Operable Unit:	01
Material ID:	2106096

SOUTH SHORE MED CENTER (Continued) **S107523501**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI225 **SOUND SHORE MEDICAL CENTER** **PA MANIFEST** **S111771577**
NW **16 GUION PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.217 mi.
1144 ft. **Site 3 of 5 in cluster AI**

Relative:
Higher

Actual:
100 ft.

Manifest Details:

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U188
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AI226 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **NY UST U003857945**
NW **16 GUION PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.217 mi.
1144 ft. **Site 4 of 5 in cluster AI**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-123269 / Active
Operator Name:	Thomas Irving
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10467
GDS Number:	Not reported
Tank Number:	2 day
Status:	4. Closed - in place
Capacity:	25
Product Stored:	0008. Diesel

Actual:
100 ft.

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1978
Date Perm Closure:	Not reported
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	07/01/1996
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1981
Date Perm Closure:	07/19/2006
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 5B
Status: 1. In-Service
Capacity: 2000
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 07/01/2006
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 9. Urethane
Tank Secondary Containment: 4. Double-Walled (underground only)
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 6. Wrapped (Piping)
Overfill Prevention: 2. High Level Alarm
Piping Secondary Containment: 4. Double-Walled (underground only)
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

Tank Number: 8
Status: 1. In-Service
Capacity: 3000
Product Stored: 0008. Diesel
Product Stored Percent: 0
Tank Leak Detection: 1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation: 10/22/2010
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 10. Urethane clad steel
Tank Internal Protection: 0. None
Tank External Protection: 9. Urethane
Tank Secondary Containment: 4. Double-Walled (underground only)
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: plastic sleeve
Overfill Prevention: 2. High Level Alarm
Piping Secondary Containment: 4. Double-Walled (underground only)
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-123269
Site Status: Active
GDS Number: Not reported
Operator Name: Thomas Irving
Owner Name: Montefiore Medical Center
Owner Street: 111 East 210th Street
Owner Address2: Not reported
Owner City/State/Zip: Bronx, NY 10467

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Number:	# 8 Day
Status:	1. In-Service
Date Installation:	10/22/2010
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	04
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1996
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	other
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	99. Other
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 day
Status:	1. In-Service
Date Installation:	06/01/1976
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1971
Capacity:	30000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3 day
Status:	1. In-Service
Date Installation:	07/01/1980
Capacity:	50
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	12/01/1981
Capacity:	500
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	12/01/2005
Capacity:	700
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/2016
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AI227 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **RCRA-SQG** **1000130172**
NW **16 GUION PL** **FINDS** **NYD075431502**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.217 mi. **NY MANIFEST**
1144 ft. **Site 5 of 5 in cluster AI**

Relative: Higher

Actual: 100 ft.

RCRA-SQG:

Date form received by agency:	10/31/2013
Facility name:	SOUND SHORE MEDICAL CENTER
Facility address:	16 GUION PL NEW ROCHELLE, NY 10802
EPA ID:	NYD075431502
Mailing address:	GUION PL NEW ROCHELLE, NY 10802
Contact:	GARRETT T DOERING
Contact address:	E 210TH ST BRONX, NY 10467
Contact country:	US
Contact telephone:	717-920-7600
Contact email:	GDOREING@MONTEFIORE.ORG
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	SOUND SHORE MEDICAL CENTER
Owner/operator address:	16 GUION PL NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	914-632-5000
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address:	CORPORATE BLVD SOUTH SUITE 175 YONKERS, NY 10701
Owner/operator country:	US
Owner/operator telephone:	914-378-6300
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/01/2013
Owner/Op end date:	Not reported

Owner/operator name:	SOUND SHORE MEDICAL CENTER
Owner/operator address:	16 GUION PL NEW ROCHELLE, NY 10802

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Owner/operator country: US
Owner/operator telephone: 914-632-5000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175
YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: 914-378-6300
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-MET HOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U170
. Waste name: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Historical Generators:
Date form received by agency: 01/01/2007
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/08/1997
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/11/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Registry ID: 110004368620

Environmental Interest/Information System
COMPLIANCE AND EMISSIONS REPORTING

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000130172
Registry ID:	110004368620
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004368620

NY MANIFEST:

Country:	USA
EPA ID:	NYD075431502
Facility Status:	Not reported
Location Address 1:	16 GUION PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD075431502
Mailing Name:	SOUND SHORE MEDICAL CENTER
Mailing Contact:	NEW ROCHELLE HOSPITAL
Mailing Address 1:	16 QUINN PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146325000

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	12/04/2017
Trans1 Recv Date:	12/04/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/06/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	011104541FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	22
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	U010
Waste Code 1_2:	U035
Waste Code 1_3:	U058
Waste Code 1_4:	U059
Waste Code 1_5:	U150
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
269 additional NY_MANIFEST: record(s) in the EDR Site Report.

228
WNW
1/8-1/4
0.217 mi.
1145 ft.

RESIDENCE
79 WARREN ST
NEW ROCHELLE, NY

NY LTANKS **S107489339**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Facility ID:	0510555
Site ID:	356553
Closed Date:	2006-03-28
Spill Number:	0510555
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-28
Spiller Name:	ISHMAL GALVIN
Spiller Company:	RESIDENCE
Spiller Address:	79 WARREN ST
Spiller County:	001
Spiller Contact:	ISHMAL GALVIN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306611
DEC Memo:	"March 28, 2006: GRAZI-1 CORP DISPOSED OF LUST AND 67.95 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons"

All Materials:

Site ID:	356553
Operable Unit ID:	1113853
Operable Unit:	01
Material ID:	2103913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AD229 **66 MEMORIAL BLVD** **NY LTANKS** **S104621761**
NNW **66 MEMORIAL BLVD** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.217 mi.
1147 ft. **Site 2 of 2 in cluster AD**

Relative:
Lower

Actual:
90 ft.

LTANKS:

Facility ID:	0002907
Site ID:	59397
Closed Date:	2000-10-24
Spill Number:	0002907
Spill Date:	2000-06-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-06-08
CID:	389
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-08
Spill Record Last Update:	2000-11-21
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	58153
DEC Memo:	""
Remarks:	"caller reporting a spill of material from a tank being hit while escavating land for a basement. no callback is necessary caller is anaymous. clena up is being done at this time."

All Materials:

Site ID:	59397
Operable Unit ID:	824416
Operable Unit:	01
Material ID:	551247
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AJ230 **LEXINGTON CENTER FOR RECOVERY INC** **RCRA NonGen / NLR** **1014958140**
NNE **3 COTTAGE PL** **NY MANIFEST** **NYR000193854**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1152 ft. **Site 1 of 2 in cluster AJ**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/27/2012
Facility name:	LEXINGTON CENTER FOR RECOVERY INC
Facility address:	3 COTTAGE PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000193854
Mailing address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact:	LISA OBRIEN
Contact address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-235-6633
Telephone ext.:	1503
Contact email:	LOBRIEN@LEXINGTONCTR.ORG
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BARRY J JACOBSON
Owner/operator address:	E 40TH ST 8TH FL NEW YORK, NY 10016
Owner/operator country:	US
Owner/operator telephone:	212-889-7460
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/02/1983
Owner/Op end date:	Not reported

Owner/operator name:	LEXINGTON CENTER FOR RECOVERY INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/2008
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D009
. Waste name: MERCURY

Historical Generators:
Date form received by agency: 05/18/2012
Site name: LEXINGTON CENTER FOR RECOVERY INC
Classification: Large Quantity Generator

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/19/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
Country: USA
EPA ID: NYR000193854
Facility Status: Not reported
Location Address 1: 3 COTTAGE PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000193854
Mailing Name: LEXINGTON CENTER FOR RECOVERY INC
Mailing Contact: LEXINGTON CENTER FOR RECOVERY INC
Mailing Address 1: 3 COTTAGE PL
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142356633

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NY0001031814
Trans2 State ID:	NJ0000027193
Generator Ship Date:	05/25/2012
Trans1 Recv Date:	05/25/2012
Trans2 Recv Date:	06/01/2012
TSD Site Recv Date:	06/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000193854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008900746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D009
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AJ231 **LEXINGTON CENTER FOR RECOVERY INC** **NJ MANIFEST** **S117987423**
NNE **3 COTTAGE PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1152 ft. **Site 2 of 2 in cluster AJ**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYR000193854
Mail Address:	COTTAGE PL
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LISA OBRIEN
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008900746JJK
EPA ID:	NYR000193854
Date Shipped:	5/25/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NY0001031814
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW ROCHELLE, NY 10801
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D009
Hand Code: Not reported
Quantity: 30.00 Pounds

Manifest Year: Not reported
Waste Code: D009
Hand Code: Not reported
Quantity: 300.00 Pounds

232
SE
1/8-1/4
0.219 mi.
1156 ft.

CON EDISON
46 CLINTON PL
NEW ROCHELLE, NY 10801

RCRA NonGen / NLR **1012184999**
NY MANIFEST **NYP004157665**

Relative:
Lower

Actual:
91 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/01/2016
Facility name: CON EDISON
Facility address: 46 CLINTON PL
NEW ROCHELLE, NY 10801
EPA ID: NYP004157665
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DAVID DUKE
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 212-580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

CON EDISON (Continued) **1012184999**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/01/2008
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004157665
Facility Status: Not reported
Location Address 1: 46 CLINTON PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10805
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004157665
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRAMKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2008
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/01/2008
Trans1 Recv Date: 04/01/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004157665
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD000705939
TSDF ID 2: Not reported
Manifest Tracking Number: 002013408FLE
Import Indicator: N
Export Indicator: N

CON EDISON (Continued) **1012184999**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	180.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	6.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC233 **MONROE COLLEGE** **NY AST** **A100252339**
East **420 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.223 mi.
1179 ft. **Site 2 of 3 in cluster AC**

Relative: **Lower**
Actual: **77 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-800251
Site Status:	Active
GDS Number:	Not reported
Operator Name:	James Moore
Owner Name:	Monroe College
Owner Street:	434 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	07/01/2004
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Date Perm Closure:	04/13/2004
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None

MONROE COLLEGE (Continued) **A100252339**

Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

Tank Number:	001old
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	04/13/2004
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	99. Other
Tank External Protection:	99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	99. Other
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	99. Other
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	1
Status:	0. Administratively closed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	11/06/2003
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AB234 **CON EDISON MANHOLE: 734** **RCRA NonGen / NLR** **1016969502**
SSW **MAIN ST & MAPLE ST** **NY MANIFEST** **NYP004431706**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.225 mi.
1190 ft. **Site 3 of 5 in cluster AB**

Relative:
Lower

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/01/2014
Facility name:	CON EDISON MANHOLE: 734
Facility address:	MAIN ST & MAPLE ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004431706
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/01/2014
Site name:	CON EDISON MANHOLE: 734
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004431706
Facility Status:	Not reported
Location Address 1:	591 MAIN ST
Code:	BP
Location Address 2:	MH 734
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004431706
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/01/2014
Trans1 Recv Date: 02/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004431706
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011696225JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AB235 **CON EDISON** **RCRA NonGen / NLR** **1014399091**
SSW **MAPLE AVE & MAIN ST** **NJ MANIFEST** **NYP004214680**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.225 mi.
1190 ft. **Site 4 of 5 in cluster AB**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date form received by agency:	09/01/2010
Facility name:	CON EDISON
Facility address:	MAPLE AVE & MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004214680
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004214680
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **1014399091**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	004086092GBF
EPA ID:	NYP004214680
Date Shipped:	09/01/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported

CON EDISON (Continued) **1014399091**

Waste Code:	D008
Hand Code:	H111
Quantity:	120 P

Manifest Number:	001086092GBF
EPA ID:	NYP004214680
Date Shipped:	09/01/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	120 P

AB236 **CON EDISON** **NY MANIFEST** **S117535572**
SSW **MAIN ST & MAPLE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.225 mi.
1190 ft. **Site 5 of 5 in cluster AB**

Relative:
Lower

Actual:
88 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004674354
Facility Status:	Not reported
Location Address 1:	MAIN ST & MAPLE AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004674354
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2014
Trans1 Recv Date:	10/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004674354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	007747843FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117535572**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	559
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	D005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AA237 **PREFERRED CLEANERS** **RCRA NonGen / NLR** **1000353766**
West **95 UNION AVE** **FINDS** **NYD050275254**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.226 mi. **NY MANIFEST**
1193 ft. **Site 2 of 7 in cluster AA**

Relative: **Higher**

Actual: **96 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PREFERRED CLEANERS
Facility address:	95 UNION AVE NEW ROCHELLE, NY 10801-6238
EPA ID:	NYD050275254
Mailing address:	UNION AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	UNION AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	914-472-6038
Owner/operator email:	Not reported

PREFERRED CLEANERS (Continued) **1000353766**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RICHARD MEYERING
Owner/operator address: 141 WILMOT RD
SCARSDALE, NY 10583
Owner/operator country: US
Owner/operator telephone: 914-472-6038
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 06/19/1995
Site name: PREFERRED CLEANERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

PREFERRED CLEANERS (Continued) **1000353766**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004357918

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000353766
Registry ID: 110004357918
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004357918

NY MANIFEST:
Country: USA
EPA ID: NYD050275254
Facility Status: Not reported
Location Address 1: 95 UNION AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD050275254
Mailing Name: NEBRASKA CLEANERS
Mailing Contact: NEBRASKA CLEANERS

PREFERRED CLEANERS (Continued) **1000353766**

Mailing Address 1:	95 UNION AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146364937

NY MANIFEST:

Document ID:	CTF0452797
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	NYLH7543
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/1995
Trans1 Recv Date:	11/20/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/27/1995
Part A Recv Date:	/ /
Part B Recv Date:	12/13/1995
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD001156009
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
16 additional NY_MANIFEST: record(s) in the EDR Site Report.

AK238 **CONSOLIDATED EDISON - MH 1174** **NY MANIFEST** **S110709396**
NE **HUGUENOT ST & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1194 ft. **Site 1 of 6 in cluster AK**

Relative:
Lower

Actual:
72 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004219572
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & HARRISON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219572
Mailing Name:	CONSOLIDATED EDISON - MH 1174
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2010
Trans1 Recv Date:	11/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874917JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CONSOLIDATED EDISON - MH 1174 (Continued) **S110709396**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AK239 **CON EDISON MANHOLE 1174** **RCRA NonGen / NLR** **1014918343**
NE **HUGEONOT ST & HARRISON ST** **NJ MANIFEST** **NYP004219570**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1194 ft. **Site 2 of 6 in cluster AK**

Relative: **Lower**

Actual: **72 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/04/2010
Facility name:	CON EDISON MANHOLE 1174
Facility address:	HUGEONOT ST & HARRISON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004219570
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON MANHOLE 1174 (Continued) **1014918343**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/04/2010
Site name: CON EDISON MANHOLE 1174
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004219570
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DENNIS ROHRER
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874917JJK
EPA ID: NYP004219570
Date Shipped: 11/04/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/04/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

AG240 **35 CLINTON PLACE LLC** **NY AST** **A100359845**
ESE **35 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.227 mi.
1197 ft. **Site 2 of 11 in cluster AG**

Relative: **Lower**
Actual: **90 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-078646
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Norman Avelenda
Owner Name:	35 Clinton Place LLC
Owner Street:	35 Clinton Place, #1B
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1939
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground

35 CLINTON PLACE LLC (Continued) **A100359845**

Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

Z241 **ALL AMERICAN SPORTS CORP** **RCRA NonGen / NLR** **1004760316**
SW **44 COLUMBUS AVE** **FINDS** **NYR000040113**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.228 mi. **NY MANIFEST**
1204 ft. **Site 5 of 5 in cluster Z**

Relative:
Lower

Actual:
66 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ALL AMERICAN SPORTS CORP
Facility address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
EPA ID:	NYR000040113
Mailing address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact:	LAMELLE WILLIAMS
Contact address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	914-636-7070
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	914-636-7070
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	914-636-7070
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ALL AMERICAN SPORTS CORP
Classification: Not a generator, verified

Date form received by agency: 05/30/1997
Site name: ALL AMERICAN SPORTS CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004534709

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004760316
Registry ID: 110004534709
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004534709

NY MANIFEST:
Country: USA

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

EPA ID: NYR000040113
Facility Status: Not reported
Location Address 1: 44 COLUMBUS AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000040113
Mailing Name: ALL AMERICAN SPORTS CORP
Mailing Contact: LAMELLE WILLIAMS
Mailing Address 1: 44 COLUMBUS AVE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10802
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146367070

NY MANIFEST:
Document ID: NJA2706453
Manifest Status: K
seq: Not reported
Year: 1997
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 10/13/1997
Trans1 Recv Date: 10/13/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 10/20/1997
Part A Recv Date: 10/29/1997
Part B Recv Date: 11/12/1997
Generator EPA ID: NYR000040113
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F005 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00426
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYD002182897
Facility Status:	Not reported
Location Address 1:	44 COLUMBUS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD002182897
Mailing Name:	RIDDELL ALL AMERICAN
Mailing Contact:	PERSING MEJIA
Mailing Address 1:	44 COLUMBUS AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146367070

AG242 **30 CLINTON PLACE OWNERS INC.** **NY UST U003855209**
ESE **30 CLINTON PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1208 ft. **Site 3 of 11 in cluster AG**

Relative: **Lower**
Actual: **89 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-078727 / Active
Operator Name:	Archer Property Management
Owner Name:	30 Clinton Place Owners Inc.
Owner Street:	105 Calvert Street
Owner Address2:	c/o Archer Property Management
Owner City:	Harrison
Owner State:	NY
Owner Zipcode:	10528
GDS Number:	Not reported
Tank Number:	1old

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	07/01/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

WESTCHESTER CO. AST:

PBS Number:	3-078727
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Archer Property Management
Owner Name:	30 Clinton Place Owners Inc.
Owner Street:	105 Calvert Street
Owner Address2:	c/o Archer Property Management
Owner City/State/Zip:	Harrison, NY 10528

Tank Number:	001
Status:	1. In-Service
Date Installation:	10/01/1996
Capacity:	3500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	4. Closed - in place
Date Installation:	01/01/1996
Capacity:	4200

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AG243 **CO-OP** **NY LTANKS** **S101658613**
ESE **30 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.229 mi.
1208 ft. **Site 4 of 11 in cluster AG**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Facility ID:	9504589
Site ID:	189169
Closed Date:	1997-04-15
Spill Number:	9504589
Spill Date:	1995-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-20
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	MERILITH MNGT.
Spiller Address:	1101 MIDLAND AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157941
DEC Memo:	""

CO-OP (Continued) **S101658613**

Remarks: "OIL SEEPING INTO BASEMENT POSSIBLE TANK FAILURE SOME OIL GOT INTO SUMP PIT AND DISCHARGED OUT SUMP PUMP TAKEN OFF LINE"

All TTF:

Facility ID:	9504589
Spill Number:	9504589
Spill Tank Test:	1544004
Site ID:	189169
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	189169
Operable Unit ID:	1019355
Operable Unit:	01
Material ID:	366101
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AG244 **CON EDISON** **NY MANIFEST** **S117538379**
ESE **150 NORTH AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1210 ft. **Site 5 of 11 in cluster AG**

Relative:
Lower

Actual:
89 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004710497
Facility Status:	Not reported
Location Address 1:	150 NORTH AV
Code:	BP
Location Address 2:	SB2044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004710497

CON EDISON (Continued) **S117538379**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004710497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774700JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117538379**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AG245 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016971500**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004452439**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.232 mi.
1223 ft. **Site 6 of 11 in cluster AG**

Relative:
Lower

Actual:
89 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/26/2014
Facility name: CON EDISON SERVICE BOX: 2040
Facility address: NORTH AVE & CLINTON PL
NEW ROCHELLE, NY 10805
EPA ID: NYP004452439
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/26/2014
Site name: CON EDISON SERVICE BOX: 2040
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

EPA ID: NYP004452439
Facility Status: Not reported
Location Address 1: NORTH AVE & CLINTON PLS
Code: BP
Location Address 2: SB2040
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004452439
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2014
Trans1 Recv Date: 02/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004452439
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772758JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AG246 **CON EDISON MANHOLE: 2042** **RCRA NonGen / NLR** **1016970603**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004443198**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.232 mi.
1223 ft. **Site 7 of 11 in cluster AG**

Relative:
Lower

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON MANHOLE: 2042
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10804
EPA ID:	NYP004443198
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2014
Site name: CON EDISON MANHOLE: 2042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004443198
Facility Status: Not reported
Location Address 1: NORTH AVE & CLINTON PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004443198
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004443198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772860JJK
Import Indicator: N

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL247 **NEW ROCHELLE FIRE STATION # 1** **NY UST U003994763**
ENE **45 HARRISON STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1225 ft. **Site 1 of 20 in cluster AL**

Relative: **Lower**

Actual: **74 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-600407 / Active
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	FS101
Status:	1. In-Service
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1966
Date Perm Closure:	01/01/1900

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	FS102
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	FS103
Status:	3. Closed - Removed
Capacity:	250
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

WESTCHESTER CO. AST:

PBS Number:	3-600407
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	FS104
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	4000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,2. Sacrificial Anode (no retrofit)
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	FS105
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	280
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	0. None

AL248 **CON EDISON** **NJ MANIFEST** **S120669623**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1225 ft. **Site 2 of 20 in cluster AL**

Relative:
Lower

Actual:
74 ft.

NJ MANIFEST:

EPA Id:	NYP004758215
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091127JJK
EPA ID:	NYP004758215
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669623**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL249 **CON EDISON** **NY MANIFEST** **S118088270**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1225 ft. **Site 3 of 20 in cluster AL**

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004758215
Facility Status:	Not reported
Location Address 1:	45 HARRISON ST
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758215
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758215
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

CON EDISON (Continued) **S118088270**

Manifest Tracking Number:	014091127JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL250 **CON EDISON** **RCRA NonGen / NLR** **1018280911**
ENE **45 HARRISON ST** **FINDS** **NYP004758215**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.232 mi.
1225 ft. **Site 4 of 20 in cluster AL**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	03/26/2015
Facility name:	CON EDISON
Facility address:	45 HARRISON ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004758215
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
74 ft.

CON EDISON (Continued) **1018280911**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 03/26/2015
- Site name: CON EDISON
- Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067684303

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1018280911
- Registry ID: 110067684303
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067684303

AL251 **CITY OF NEW ROCHELLE** **NY LTANKS** **S107658678**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1225 ft. **Site 5 of 20 in cluster AL**

Relative: **Lower**
Actual: **74 ft.**

LTANKS:
- Facility ID: 0513733
- Site ID: 360263
- Closed Date: 2006-06-21
- Spill Number: 0513733
- Spill Date: 2006-02-28

CITY OF NEW ROCHELLE (Continued) **S107658678**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-02-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-28
Spill Record Last Update:	2006-06-21
Spiller Name:	DEE LESTER
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	45 HARRISON STREET
Spiller County:	001
Spiller Contact:	DEE LESTER
Spiller Phone:	(914) 654-2072
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310380
DEC Memo:	"Tank passed retest after piping was replaced. NFA"
Remarks:	"TANK SIZE IS 5000 GALLON, TEST METHOD WAS EZ3 LOCATOR PLUS,"

All Materials:

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107948
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AA252 **100-102 UNION AVENUE** **NY LTANKS** **S104514442**
West **100-102 UNION AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1229 ft. **Site 3 of 7 in cluster AA**

Relative: **Lower**

Actual: **95 ft.**

LTANKS:

Facility ID:	9608199
Site ID:	166425
Closed Date:	1996-11-08
Spill Number:	9608199
Spill Date:	1996-10-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-01
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-01
Spill Record Last Update:	1996-12-10
Spiller Name:	LJ NJ ASSOC
Spiller Company:	100-102 UNION AVENUE
Spiller Address:	100-102 UNION AVENUE
Spiller County:	001
Spiller Contact:	LJ NJ ASSOC
Spiller Phone:	(914) 636-7297
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140217
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/96 LETTER SENT BASED ON CLOSURE REPORT NFA"
Remarks:	"caller pulled tank and found contaminated soil."

All Materials:

Site ID:	166425
Operable Unit ID:	1036474
Operable Unit:	01
Material ID:	343940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AA253 **LJNJ ASSOCIATES** **NY UST** **U003884659**
West **100-102 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1229 ft. **Site 4 of 7 in cluster AA**

Relative: **Lower**

Actual: **95 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-601056 / Unregulated: <1101 gal. PBS
Operator Name:	Bob Rossi
Owner Name:	Ljnj Associates
Owner Street:	133 Meadow Lane
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported

Tank Number:	1
Status:	0. Administratively closed
Capacity:	1080
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1959
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	2
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

LJNJ ASSOCIATES (Continued) **U003884659**

Tank Number:	3
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/01/1996
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	5
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None

LJNJ ASSOCIATES (Continued) **U003884659**

Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AA254 **KAGEL HOME** **NY LTANKS** **S107658662**
West **99 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1232 ft. **Site 5 of 7 in cluster AA**

Relative: **Lower**
Actual: **95 ft.**

LTANKS:

Facility ID:	0513684
Site ID:	360201
Closed Date:	2006-03-09
Spill Number:	0513684
Spill Date:	2006-02-27
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	2006-03-06
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-27
Spill Record Last Update:	2006-03-09
Spiller Name:	ANDREW KAGEL
Spiller Company:	KAGEL HOME
Spiller Address:	99 UNION AVE
Spiller County:	001
Spiller Contact:	ANDREW KAGEL
Spiller Phone:	(914) 403-2881
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310321
DEC Memo:	"Homeowner waiting on proposal from N.E. to finish job. 3/6/06 Northeast Environmental reported that the tank was removed along with eight drums of petroleum impacted soil. NFA. TG"
Remarks:	"55o gallon tank had holes and found contaminated soil;"

All Materials:

Site ID:	360201
Operable Unit ID:	1117385
Operable Unit:	01
Material ID:	2107892
Material Code:	0001A

KAGEL HOME (Continued) **S107658662**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL255 **CON EDISON** **RCRA NonGen / NLR** **1018281062**
ENE **HARRISON ST & CEDER ST** **FINDS** **NYP004759924**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.233 mi.
1232 ft. **Site 6 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/29/2015
Facility name:	CON EDISON
Facility address:	HARRISON ST & CEDER ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004759924
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/29/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

CON EDISON (Continued) **1018281062**

FINDS:

Registry ID: 110067686793

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281062
Registry ID: 110067686793
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067686793

AL256 **CON ED** **NY MANIFEST** **S118088428**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1232 ft. **Site 7 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004759924
Facility Status: Not reported
Location Address 1: HARRISON ST & CEDAR ST
Code: BP
Location Address 2: MH 8003
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004759924
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON ED (Continued) **S118088428**

Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091107JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL257 **CON EDISON** **NJ MANIFEST** **S120669767**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1232 ft. **Site 8 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYP004759924
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091107JJK
EPA ID:	NYP004759924
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669767**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AE258 **125** **NY LTANKS** **S104621592**
SSE **CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.234 mi.
1233 ft. **Site 4 of 5 in cluster AE**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Facility ID:	0001835
Site ID:	205498
Closed Date:	2000-05-15
Spill Number:	0001835
Spill Date:	2000-05-12
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-12
CID:	196
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-12
Spill Record Last Update:	2000-06-21
Spiller Name:	UNKNOWN
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	OPERATOR 631
Spiller Phone:	(914) 595-5901
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170636
DEC Memo:	""
Remarks:	"TANK OVER FILL AT THIS LOCATION. 10 GALLONS SPILLED AND THE SPILL WAS CLEANED UP BY THE FIRE DEPT. THE SPILL IS AT THE CHURCH BLESSED SACRMENT CHURCH. BABR MCDONALD FROM COUNTY HEATH DEPT. 637-4890 WAS CALLED TO THE SCENE ALSO."

All Materials:

Site ID:	205498
Operable Unit ID:	823753
Operable Unit:	01
Material ID:	290047

125 (Continued) **S104621592**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AH259 **CON EDISON** **NJ MANIFEST** **S120676674**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1234 ft. **Site 5 of 12 in cluster AH**

Relative:
Lower

Actual:
78 ft.

NJ MANIFEST:

EPA Id:	NYP004838332
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472178JJK
EPA ID:	NYP004838332
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120676674**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AH260 **CON EDISON** **RCRA NonGen / NLR** **1019907792**
North **LOCKWOOD AVE & NORTH AVE** **NYP004838332**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1234 ft. **Site 6 of 12 in cluster AH**

Relative: **Lower**

Actual: **78 ft.**

RCRA NonGen / NLR:

Date form received by agency:	09/14/2015
Facility name:	CON EDISON
Facility address:	LOCKWOOD AVE & NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004838332
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON (Continued) **1019907792**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/14/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

AH261 **CON EDISON TRANSFORMER MANHOLE: 1552** **RCRA NonGen / NLR** **1016964344**
North **LOCKWOOD AVE & NORTH ST** **NY MANIFEST** **NYP004372751**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.234 mi.
1234 ft. **Site 7 of 12 in cluster AH**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 11/10/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 1552
Facility address: LOCKWOOD AVE & NORTH ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004372751
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/10/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1552
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004372751
Facility Status: Not reported
Location Address 1: LOCKWOOD AVE & NORTH ST
Code: BP
Location Address 2: TM 1552
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004372751
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/10/2013
Trans1 Recv Date: 10/10/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004372751
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011693714JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH262 **CON EDISON MANHOLE 1562** **RCRA NonGen / NLR** **1014918646**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004222626**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.234 mi.
1234 ft. **Site 8 of 12 in cluster AH**

Relative: **Lower**
Actual: **78 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/30/2011
Facility name:	CON EDISON MANHOLE 1562
Facility address:	NORTH AVE & LOCKWOOD AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004222626
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2010
Site name: CON EDISON MANHOLE 1562
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004222626
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DONALD SENNO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655578JJK
EPA ID: NYP004222626
Date Shipped: 12/31/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 12/31/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/04/2011

CON EDISON MANHOLE 1562 (Continued) **1014918646**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	150 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004222626
Facility Status:	Not reported
Location Address 1:	NORTH AVE & LOCKHEED
Code:	BP
Location Address 2:	MH 1962
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004222626
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Trans2 State ID:	Not reported
Generator Ship Date:	12/31/2010
Trans1 Recv Date:	12/31/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/04/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004222626
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655578JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH263 **CON EDISON MANHOLE 1545** **RCRA NonGen / NLR** **1014918224**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004218356**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.234 mi.
1234 ft. **Site 9 of 12 in cluster AH**

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 11/18/2010
Actual: Facility name: CON EDISON MANHOLE 1545
78 ft. Facility address: NORTH AVE & LOCKWOOD AVE
NEW ROCHELLE, NY 10801

CON EDISON MANHOLE 1545 (Continued) **1014918224**

EPA ID: NYP004218356
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2010
Site name: CON EDISON MANHOLE 1545
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004218356
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CHRISTOPHER BLAICH
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874846JJK

CON EDISON MANHOLE 1545 (Continued) **1014918224**

EPA ID:	NYP004218356
Date Shipped:	10/19/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/19/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/20/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2000 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004218356
Facility Status:	Not reported
Location Address 1:	NORTH AV OPP LOCKWOOD
Code:	BP
Location Address 2:	MH 1545
Total Tanks:	Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004218356
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2010
Trans1 Recv Date:	10/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004218356
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874846JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH264 **CON EDISON** **NY MANIFEST** **S118259837**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1234 ft. **Site 10 of 12 in cluster AH**

Relative:
Lower

Actual:
78 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004838332
Facility Status:	Not reported
Location Address 1:	LOCKWOOD AVE & NORTH AVE
Code:	BP
Location Address 2:	TM 1552
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004838332
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2015
Part A Recv Date:	Not reported

CON EDISON (Continued) **S118259837**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004838332
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472178JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH265 **368 NORTH AVE MGMT CO. INC.** **NY UST** **U003994274**
North **368 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1237 ft. **Site 11 of 12 in cluster AH**

Relative: WESTCHESTER CO. UST:
Lower

Actual: Id/Status:	3-600272 / Unregulated: <1101 gal. PBS
79 ft. Operator Name:	Barry Shapiro
Owner Name:	368 North Ave Mgmt Co. Inc.
Owner Street:	27 Country Ridge Road
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported

368 NORTH AVE MGMT CO. INC. (Continued) **U003994274**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/24/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AK266 **GHP 145 HUGUENOT DELAWARE, LLC** **NY AST** **U003994574**
NE **145 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1250 ft. **Site 3 of 6 in cluster AK**

Relative: **Lower**

Actual: **70 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-497436
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Clemente
Owner Name:	GHP 145 Huguenot Delaware, LLC
Owner Street:	4 West Red Oak Lane, Suite 200
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10604

Tank Number:	3-497436
Status:	1. In-Service
Date Installation:	07/01/1989
Capacity:	6000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

AK267 **LONGINES WITTNAUER WATCH CO** **RCRA NonGen / NLR** **1000235411**
NE **145 HUGUENOT ST** **FINDS** **NYD001317221**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.237 mi. **NY MANIFEST**
1250 ft. **Site 4 of 6 in cluster AK**

Relative:
Lower

Actual:
70 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	LONGINES WITTNAUER WATCH CO
Facility address:	145 HUGUENOT ST NEW ROCHELLE, NY 10802
EPA ID:	NYD001317221
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact:	Not reported
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 03/11/1985
Site name: LONGINES WITTNAUER WATCH CO
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P013
. Waste name: BARIUM CYANIDE

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P097
. Waste name: FAMPHUR (OR) PHOSPHOROTHIOIC ACID
O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/17/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/19/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:

Registry ID: 110004333720

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000235411
Registry ID:	110004333720
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004333720

NY MANIFEST:

Country:	USA
EPA ID:	NYD001317221
Facility Status:	Not reported
Location Address 1:	145 HUGUENOT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001317221
Mailing Name:	LONGINES WITTHAVER WATCH COMPANY
Mailing Contact:	LONGINES WITTHAVER WATCH COMPANY
Mailing Address 1:	145 HUGUENOT STREET
Mailing Address 2:	Not reported
Mailing City:	NEW RTOCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9145761000

NY MANIFEST:

Document ID:	NJA0309928
Manifest Status:	C
seq:	Not reported
Year:	1987
Trans1 State ID:	NJDEP#S10
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1987

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Trans1 Recv Date:	08/19/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/20/1987
Part A Recv Date:	08/28/1987
Part B Recv Date:	08/27/1987
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD089216790
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00224
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	021
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00450
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	P106 - SODIUM CYANIDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00064
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00036
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

AK268 **GALESI ENTERPRICES** **NY LTANKS** **S105236833**
NE **145 HUGUENOT ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1250 ft. **Site 5 of 6 in cluster AK**

Relative: **Lower**

Actual: **70 ft.**

LTANKS:

Facility ID:	8901038
Site ID:	259815
Closed Date:	1989-06-01
Spill Number:	8901038
Spill Date:	1989-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1989-06-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212473
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. "
Remarks:	"8K, -.116"

GALESI ENTERPRICES (Continued) **S105236833**

All TTF:

Facility ID:	8901038
Spill Number:	8901038
Spill Tank Test:	1535410
Site ID:	259815
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	259815
Operable Unit ID:	927170
Operable Unit:	01
Material ID:	452349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0109500
Facility Type:	ER
Spill Number:	0109500
DER Facility ID:	212473
Site ID:	259813
DEC Region:	3
Closed Date:	2001-12-28
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2001-12-28
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-12-28
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

GALESI ENTERPRICES (Continued) **S105236833**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-28
Spill Record Last Update:	2002-01-03
Spiller Name:	CHRIS LALAK
Spiller Company:	HEALTH DEPT OFFICE
Spiller Address:	145 HUGUENOT ST
Spiller Company:	001
Contact Name:	CHRIS LALAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 12/28/2001 C. LALAK @ WCDOH HANDLED. SPILL CLEANED UP. NO FURTHER ACTION."
Remarks:	"all cleaned up less than 1 oz"

All Materials:

Site ID:	259813
Operable Unit ID:	846776
Operable Unit:	01
Material ID:	527159
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	0308837
Facility Type:	ER
Spill Number:	0308837
DER Facility ID:	212473
Site ID:	259814
DEC Region:	3
Closed Date:	2003-11-19
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2003-11-19
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-11-19
CID:	322
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-19
Spill Record Last Update:	2003-12-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown

GALESI ENTERPRICES (Continued) **S105236833**

Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 11/19/03: Spill is unrecoverable per C. Lalak, WCDOH. Recommends NFA at this time."
Remarks:	"approx 10 gal unk oil on roadway - highway dept placing sand "

All Materials:

Site ID:	259814
Operable Unit ID:	875003
Operable Unit:	01
Material ID:	571327
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0909155
Facility Type:	ER
Spill Number:	0909155
DER Facility ID:	212473
Site ID:	421828
DEC Region:	3
Closed Date:	2009-11-16
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-16
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

GALESI ENTERPRICES (Continued) **S105236833**

All Materials:

Site ID:	421828
Operable Unit ID:	1177706
Operable Unit:	01
Material ID:	2170525
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Facility ID:	0909156
Facility Type:	ER
Spill Number:	0909156
DER Facility ID:	212473
Site ID:	421829
DEC Region:	3
Closed Date:	2009-11-16
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-16
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

All Materials:

Site ID:	421829
Operable Unit ID:	1177707
Operable Unit:	01
Material ID:	2170526
Material Code:	0001A

GALESI ENTERPRICES (Continued) **S105236833**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AL269 **CON EDISON** **NY MANIFEST** **S118089345**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 9 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004769477
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP
Location Address 2:	SB 8007
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769477
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

CON EDISON (Continued) **S118089345**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002660844GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL270 **CON EDISON** **NJ MANIFEST** **S120669628**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 10 of 20 in cluster AL**

Relative: NJ MANIFEST:
Lower

Actual:
75 ft.

EPA Id:	NYP004758272
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **S120669628**

Date Change: Not reported

Manifest:

Manifest Number:	014091128JJK
EPA ID:	NYP004758272
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL271 **CON EDISON** **NY MANIFEST** **S118089335**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 11 of 20 in cluster AL**

Relative: NY MANIFEST:
Lower

Country:	USA
EPA ID:	NYP004769345
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP

Actual:
75 ft.

CON EDISON (Continued) **S118089335**

Location Address 2:	MH 8008
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769345
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769345
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660843GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500

CON EDISON (Continued) **S118089335**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL272 **CON ED** **NY MANIFEST** **S118088390**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 12 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004759510
Facility Status:	Not reported
Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759510
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported

CON ED (Continued) **S118088390**

TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091122JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL273 **CON EDISON** **RCRA NonGen / NLR** **1018280916**
ENE **HARRISON ST & FOUNTAIN PL** **FINDS** **NYP004758272**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.237 mi.
1251 ft. **Site 13 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/26/2015
Facility name:	CON EDISON
Facility address:	HARRISON ST & FOUNTAIN PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004758272
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

CON EDISON (Continued) **1018280916**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/26/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067684358

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018280916
Registry ID: 110067684358
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067684358

AL274 **CON EDISON** **RCRA NonGen / NLR** **1019902084**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769477**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 14 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/16/2015
Facility name:	CON EDISON
Facility address:	FOUNTAIN PL & HARRISON ST SB8007 NEW ROCHELLE, NY 10801
EPA ID:	NYP004769477
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/16/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

AL275 **CON EDISON SERVICE BOX: 8007** **RCRA NonGen / NLR** **1016963705**
ENE **FOUNTAIN PL & HARRISON ST 136** **NY MANIFEST** **NYP004366886**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 15 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/26/2013
Facility name:	CON EDISON SERVICE BOX: 8007
Facility address:	FOUNTAIN PL & HARRISON ST 136 FEET E OF

CON EDISON SERVICE BOX: 8007 (Continued) **1016963705**

NEW ROCHELLE, NY 10801
EPA ID: NYP004366886
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/26/2013
Site name: CON EDISON SERVICE BOX: 8007
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004366886
Facility Status: Not reported
Location Address 1: FOUNTAIN PL 136 E. HARRISON ST
Code: BP
Location Address 2: SB8007
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004366886
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported

CON EDISON SERVICE BOX: 8007 (Continued) **1016963705**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/2013
Trans1 Recv Date:	09/26/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004366886
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694647JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON SERVICE BOX: 8007 (Continued) **1016963705**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL276 **CON EDISON** **NY MANIFEST** **S118088276**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 16 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004758272
Facility Status:	Not reported
Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	SB 8044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758272
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091128JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S118088276**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL277 **CON EDISON** **NJ MANIFEST** **S120670610**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 17 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYP004769477
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660844GBF
EPA ID:	NYP004769477

CON EDISON (Continued) **S120670610**

Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL278 **CON EDISON** **RCRA NonGen / NLR** **1019902074**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769345**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 18 of 20 in cluster AL**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	04/16/2015
Facility name:	CON EDISON
Facility address:	FOUNTAIN PL & HARRISON ST MH8008 NEW ROCHELLE, NY 10801
EPA ID:	NYP004769345
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

Actual:
75 ft.

CON EDISON (Continued) **1019902074**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/16/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

AL279 **CON EDISON** **NJ MANIFEST** **S120670602**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1251 ft. **Site 19 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:
EPA Id: NYP004769345
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002660843GBF

CON EDISON (Continued) **S120670602**

EPA ID:	NYP004769345
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AC280 **MONROE COLLEGE** **NY LTANKS** **S106124169**
East **5 FRANKLIN AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1252 ft. **Site 3 of 3 in cluster AC**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:

Facility ID:	0307536
Site ID:	165556
Closed Date:	2005-03-27
Spill Number:	0307536
Spill Date:	2003-10-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported

MONROE COLLEGE (Continued) **S106124169**

SWIS:	6000
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-10-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-16
Spill Record Last Update:	2005-03-27
Spiller Name:	JIM MOORE
Spiller Company:	MONROE COLLEGE
Spiller Address:	5 FRANKLIN AVE
Spiller County:	001
Spiller Contact:	JIM MOORE
Spiller Phone:	(914) 403-3458
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	278527
DEC Memo:	"03/27/05 CLEAN UP COMPLETED. SPILL FILE CLOSED BY OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod As per email from WCHD: 03-07536 5 Franklin Ave, NEw Rochelle, NY (also known as 420 Main St, New Rochelle) Tank removed from basement, soil disposed of. NFA"
Remarks:	"recomend repair retest"

All TTF:

Facility ID:	0307536
Spill Number:	0307536
Spill Tank Test:	1528740
Site ID:	165556
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	165556
Operable Unit ID:	873930
Operable Unit:	01
Material ID:	501063
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

MONROE COLLEGE (Continued) **S106124169**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AA281 **TANK TEST FAILURE** **NY LTANKS** **S111239332**
West **50 WALNUT ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.240 mi.
1265 ft. **Site 6 of 7 in cluster AA**

Relative: LTANKS:
Lower

Facility ID:	1107925
Site ID:	455637
Closed Date:	2013-02-05
Spill Number:	1107925
Spill Date:	2011-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-21
Spill Record Last Update:	2013-02-06
Spiller Name:	Not reported
Spiller Company:	SAL VIGNA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KEN RONK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	410212
DEC Memo:	"9-21-11 Owner is Pietro Vigna and doesn't speak english. Sal is his son. Sal cell: (914)424-2239. Sal has Eastern Env coming out Wed to investigate further. jc 2/6/13: Northeast Environmental disposed of LUST and a total of 21.05 tons of petroleum contaminated soil. Exit sample results showed residual contamination over CP-51 Guidance values. Additional excavation of contaminted soil is not possible with causing possible structural damage to the building foundations. Based upon the information provided, this Department requires no further action at this time. Closed - doesn not meet standarsds. jod"
Remarks:	"tank test failure"

All Materials:

TANK TEST FAILURE (Continued) **S111239332**

Site ID:	455637
Operable Unit ID:	1205789
Operable Unit:	01
Material ID:	2202749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AF282 **DOMENICO PROCOPIO** **NY UST U003988536**
SSW **618 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.242 mi.
1278 ft. **Site 2 of 4 in cluster AF**

Relative: **Lower**
Actual: **87 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-800233 / Unregulated: <1101 gal. PBS
Operator Name:	Domenico Procopio
Owner Name:	Domenico Procopio
Owner Street:	126 Liberty Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/24/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

WESTCHESTER CO. AST:

PBS Number:	3-800233
Site Status:	Unregulated: <1101 gal. PBS
GDS Number:	Not reported
Operator Name:	Domenico Procopio

DOMENICO PROCOPIO (Continued) **U003988536**

Owner Name:	Domenico Procopio
Owner Street:	126 Liberty Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10805
Tank Number:	2
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

AF283 **DOMINIC PROCOPIO** **NY LTANKS** **S103558292**
SSW **618 MAIN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.242 mi.
1278 ft. **Site 3 of 4 in cluster AF**

Relative:
Lower

Actual:
87 ft.

LTANKS:

Facility ID:	9809866
Site ID:	278454
Closed Date:	2004-03-30
Spill Number:	9809866
Spill Date:	1998-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-05
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-05
Spill Record Last Update:	2004-03-30
Spiller Name:	DOMINIC PROCOPIO
Spiller Company:	DOMINIC PROCOPIO
Spiller Address:	10 MAPLE AVE
Spiller County:	001
Spiller Contact:	DOMINIC PROCOPIO
Spiller Phone:	(914) 576-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	226099
DEC Memo:	""
Remarks:	"CHECK PIPING AND RETEST"

All TTF:

Facility ID:	9809866
Spill Number:	9809866
Spill Tank Test:	1546499
Site ID:	278454
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

DOMINIC PROCOPIO (Continued) **S103558292**

All Materials:

Site ID:	278454
Operable Unit ID:	1067125
Operable Unit:	01
Material ID:	313759
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0408557
Facility Type:	ER
Spill Number:	0408557
DER Facility ID:	226099
Site ID:	333327
DEC Region:	3
Closed Date:	2005-03-17
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2004-11-03
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2004-11-03
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-03
Spill Record Last Update:	2005-04-05
Spiller Name:	DOMINICKO PROCOPIO
Spiller Company:	Not reported
Spiller Address:	618 MAIN ST
Spiller Company:	001
Contact Name:	DOMINICKO PROCOPIO
DEC Memo:	"PBS #3-800233 11/16/2004 Stephan Goreau of WCDOH spill update -- several inches in basement of sewer/oil mix---BHY 4/4/05: Letter to Vincent Rippa, Domenico Procopio Property from Stefan Goreau, WCDOH dated 17Mar2005. WCDOH requires NFA at this time."
Remarks:	"Imporperly Abondoned tank."

All Materials:

Site ID:	333327
Operable Unit ID:	1095482
Operable Unit:	01

DOMINIC PROCOPIO (Continued) **S103558292**

Material ID:	575615
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH284 **CASANOVA BROS. REALTY** **NY UST** **U003884076**
North **370 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.243 mi.
1281 ft. **Site 12 of 12 in cluster AH**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-800088 / Unregulated: <1101 gal. PBS
Operator Name:	Israel Estrada
Owner Name:	Casanova Bros. Realty
Owner Street:	370 North Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/14/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Actual:
79 ft.

AA285 **ROBERTS HOME** **NY LTANKS** **S108298719**
West **58 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.243 mi.
1283 ft. **Site 7 of 7 in cluster AA**

Relative: **Lower**
Actual: **95 ft.**

LTANKS:

Facility ID:	0608623
Site ID:	372634
Closed Date:	2012-08-17
Spill Number:	0608623
Spill Date:	2006-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2012-08-17
Spiller Name:	TOM ROBERTS
Spiller Company:	ROBERTS HOME
Spiller Address:	58 WALNUT STREET
Spiller County:	001
Spiller Contact:	TOM ROBERTS
Spiller Phone:	(914) 755-9816
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	322369
DEC Memo:	"8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M"
Remarks:	""

All TTF:

Facility ID:	0608623
Spill Number:	0608623
Spill Tank Test:	1550391
Site ID:	372634
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

ROBERTS HOME (Continued) **S108298719**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 372634
Operable Unit ID: 1130371
Operable Unit: 01
Material ID: 2120048
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

AM286 @ **NY LTANKS** **S106971852**
West **60 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.244 mi.
1289 ft. **Site 1 of 3 in cluster AM**

Relative: LTANKS:
Lower
Facility ID: 0502010
Actual: Site ID: 346287
95 ft. Closed Date: 2005-07-17
Spill Number: 0502010
Spill Date: 2005-05-19
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-05-19
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-05-19
Spill Record Last Update: 2005-07-17
Spiller Name: MR. GALLERO
Spiller Company: Not reported
Spiller Address: 60 WALNUT STREET
Spiller County: 001
Spiller Contact: MR. GALLERO
Spiller Phone: (914) 469-7160
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 292543

@ (Continued) **S106971852**

DEC Memo: "July 17, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 33.65 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "1000 GALLON TANK HAD HOLES IN IT:"

All Materials:
Site ID: 346287
Operable Unit ID: 1104017
Operable Unit: 01
Material ID: 584224
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

AF287 **VACANT** **NY UST U004177556**
SSW **399 HUGUENOT STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1294 ft. **Site 4 of 4 in cluster AF**

Relative: **Lower**
Actual: **83 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-801616 / Unregulated
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City: New York
Owner State: NY
Owner Zipcode: 10017
GDS Number: Not reported

Tank Number: 5
Status: 3. Closed - Removed
Capacity: 1500
Product Stored: 0002. #4 Fuel Oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

VACANT (Continued) **U004177556**

Tank Number: 6
Status: 4. Closed - in place
Capacity: 1000
Product Stored: 0002. #4 Fuel Oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 7
Status: 3. Closed - Removed
Capacity: 1000
Product Stored: 0009. Gasoline
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-801616
Site Status: Unregulated
GDS Number: Not reported
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City/State/Zip: New York, NY 10017

Tank Number: 1
Status: 3. Closed - Removed
Date Installation: 01/01/1900
Capacity: 275

VACANT (Continued) **U004177556**

Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	2
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	750
Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	3
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported

VACANT (Continued) **U004177556**

Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	4
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

AG288 **OFF-SITE FLAMINGO CLEANERS** **NY BROWNFIELDS** **S110043637**
ESE **149 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1298 ft. **Site 8 of 11 in cluster AG**

Relative: **Lower**

Actual: **89 ft.**

BROWNFIELDS:

Program:	BCP
Site Code:	414661
Acres:	Not reported
HW Code:	C360078A
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/03/2009
Record Updated Date:	03/08/2017
Update By:	DACROSBY
Site Description:	Location: This site is the off-site component of the former Flamingo Dry Cleaners site (C360078). The site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site itself is a one-story commercial building which includes four stores including the vacant dry cleaners. This off-site component is comprised of immediately-surrounding areas. Current Zoning/Uses: Surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a college, a medical facility, and a church. Historical Uses: The on-site building was constructed in 1941 and used for retail. Flamingo Cleaners began operations in 1958 and ran until 2005 when all dry-cleaning equipment

OFF-SITE FLAMINGO CLEANERS (Continued) **S110043637**

	was removed. On-site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). A referral for off-site work was completed in December 2007 and a SSF RI/FS Work assignment was approved in March 2009. The RI field work was conducted in the summer of 2009 and fall of 2009. Additional round of gw analyses occurred in spring 2010. The on-going off-site investigation thus far indicates that PCE is not present in environmental media above standards in the area surrounding the site. Site Geology/Hydrogeology: The area surrounding the site is underlain by glacial till which sit atop highly weathered bedrock. Area bedrock ranges from 5-25 feet below ground surface. The water table ranges from 5-11 feet below ground surface. Groundwater flow direction is dominantly to the south-southwest toward Long Island Sound, but site specific groundwater flow direction is radial and seasonally affected.
Env Problem:	Nature and Extent of Contamination: Based on investigations to date, the primary contaminant of concern at the site is tetracholoroethylene (PCE), a dry cleaning solvent. On-site, PCE has been detected in soils, soil vapor, indoor air, and groundwater. The off-site investigation to date indicates that there are no off-site impacts. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2/27/2010 1:25:00 PM
Record Upd:	10/18/2012 2:41:00 PM
Updated By:	ldennist
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AG289 **COLONIAL CLEANERS CORP** **RCRA NonGen / NLR** **1000338874**
ESE **149 NORTH AVE** **NYD982718058**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1298 ft. **Site 9 of 11 in cluster AG**

Relative:
Lower

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	COLONIAL CLEANERS CORP
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801-7405
EPA ID:	NYD982718058
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	COLONIAL CLEANERS CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	COLONIAL CLEANERS CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

COLONIAL CLEANERS CORP (Continued) **1000338874**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	COLONIAL CLEANERS CORP
Classification:	Not a generator, verified
Date form received by agency:	07/08/1999
Site name:	COLONIAL CLEANERS CORP
Classification:	Not a generator, verified
Date form received by agency:	11/30/1988
Site name:	COLONIAL CLEANERS CORP
Classification:	Small Quantity Generator
. Waste code:	F002
. Waste name:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Violation Status:	No violations found

AG290 **FLAMINGO CLEANERS** **RCRA-LQG** **1000299848**
ESE **149 NORTH AVE** **NY BROWNFIELDS** **NYD012946885**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.246 mi.
1298 ft. **Site 10 of 11 in cluster AG**

Relative: **Lower**
Actual: **89 ft.**

RCRA-LQG:

Date form received by agency:	07/10/2012
Facility name:	FLAMINGO CLEANERS
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD012946885
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	RICHARD H DORAN
Contact address:	DORSON ENVIRONMENTAL MGMT INC 45 KNOLLWOOD RD SUITE 300 ELMSFORD, NY 10523
Contact country:	US
Contact telephone:	914-592-3117
Contact email:	RDORAN@DORSON.COM
EPA Region:	02
Land type:	Private

FLAMINGO CLEANERS (Continued) **1000299848**

Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: TAEYOON KIM
Owner/operator address: 149 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-235-1591
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TAEYOON KIM
Owner/operator address: 149 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-235-1591
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: V & V CAPITAL LLC
Owner/operator address: PHILLIPS HILL RD
NEW CITY, NY 10956
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/14/2011
Owner/Op end date: Not reported

Owner/operator name: LUIGI LLESHAJ
Owner/operator address: Not reported
Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/14/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

FLAMINGO CLEANERS (Continued) **1000299848**

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/01/2007
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/21/1991
Site name: FLAMINGO CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/10/2006
Date achieved compliance: 08/18/2006

FLAMINGO CLEANERS (Continued) **1000299848**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/03/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/10/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 08/18/2006
Evaluation lead agency: State

BROWNFIELDS:
Program: BCP
Site Code: 335220
Acres: 0.122
HW Code: C360078
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 12/16/2004
Record Updated Date: 12/30/2016
Update By: DACROSBY
Site Description: Location: The Flamingo Cleaners site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site is a one-story commercial building with a full basement. The building is divided into four tenant spaces which include a bar/lounge, beauty salon, and two vacant spaces that previously housed a travel agency and a dry-cleaner. Current Zoning/use(s): The site consists of four retail spaces, two of which are currently occupied. The site is zoned for commercial use. The surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a medical center, and a church. The dry cleaning operation is no longer active and the space is currently vacant. Past Uses of the Site: The existing building was constructed in 1941 and used for retail. Flamingo Cleaners began dry cleaning operations in 1958, and ran until 2005 when all dry-cleaning equipment was removed. Site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). Prior completed investigations include a Phase I Investigation in October of 2003 and a Phase II Investigation completed in March of 2004. The Volunteer entered into a Brownfield Cleanup Agreement in April 2005. A Decision Document was issued in March 2012 for a remedy involving source soil removal and in situ chemical oxidation treatment of groundwater. Based on the extent of the site contamination, a referral to State Superfund for an off-site investigation was completed in December 2007. The groundwater plume was found to be isolated to immediately behind the building and little to no off-site impacts were noted in groundwater, soils, nor in soil vapor. Site Geology/hydrogeology: The site is underlain by glacial till which sits atop highly weathered bedrock. Bedrock ranges from 5 - 22 feet below ground surface. The water table is between 5 -

FLAMINGO CLEANERS (Continued) **1000299848**

	11 feet below ground surface. Groundwater flow direction dominantly to the south-southeast toward Long Island Sound, however, site specific groundwater flow direction is radial, and seasonally affected.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE or perc) which was present in soils, groundwater, and indoor air. PCE breakdown products Trichloroethene (TCE) and 1,2-dichloroethene (1,2-DCE), vinyl chloride, as well as 1,1,1 trichloroethane (1,1,1 TCA), were also present at the site. Remedial actions have removed source soils, treated groundwater, and have prevented contaminants from entering the indoor air. Residual contamination in the soil, groundwater, and indoor air is being managed under a Site Management Plan.
Health Problem:	Measures are in place to control the potential for coming in contact with subsurface soil and ground water contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater and/or soil may move into the soil vapor (air space within the soil), which in turn may move into overlying building and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilate/remove the air beneath the building) has been installed in the on-site building to prevent the indoor air quality from being affected by the contamination in the soil vapor beneath the building. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:90’830 / 73:77’928
Dell:	False
Record Add:	12/16/2004 12:46:00 PM
Record Upd:	10/25/2013 4:35:00 PM
Updated By:	BXANDERS
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	JO-ANNE LATINO
Owner Company:	JAMM North Avenue Realty, LLC.
Owner Address:	31 Green St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Charlestown, MA 02129

FLAMINGO CLEANERS (Continued) **1000299848**

Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	09
Owner Name:	Abbas A. Alsaidi
Owner Company:	New Rock Mini Mart & Deli Inc.
Owner Address:	149 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Luigi Tush Lleshaj
Owner Company:	V & V Capital LLC
Owner Address:	369 Phillips Hill Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michael Knipfing
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	149-155 North Corp.
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Luigi Lleshaj
Owner Company:	V&V Capital LLC
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	new City, NY 10956
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Not reported
Owner Company:	Luigi Lleshaj
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	The Estate of Dorothy Kettner
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America

FLAMINGO CLEANERS (Continued) **1000299848**

HW Code:	C360078
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	0905638
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	7/12/2016 12:27:00 PM
Record Updated:	7/12/2016 12:27:00 PM
Updated By:	JBODEE
Crossref ID:	W3-1058-05-03
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	12/5/2016 12:19:00 PM
Record Updated:	12/5/2016 12:19:00 PM
Updated By:	KATHOMPS
Crossref ID:	561793593
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	11/4/2016 10:40:00 AM
Record Updated:	11/4/2016 10:40:00 AM
Updated By:	KATHOMPS
Crossref ID:	1203976
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.

FLAMINGO CLEANERS (Continued) **1000299848**

Record Added Date:	7/23/2012 4:23:00 PM
Record Updated:	7/23/2012 4:23:00 PM
Updated By:	JPCUMMIN

NY MANIFEST:

Country:	USA
EPA ID:	NYD012946885
Facility Status:	Not reported
Location Address 1:	149 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012946885
Mailing Name:	V & V CAPITAL LLC
Mailing Contact:	V&V CAPITAL LLC - FORMER FLAMINGO CLEANERS
Mailing Address 1:	149 NORTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3615865900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2013
Trans1 Recv Date:	01/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX168000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	008835161JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	6160
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	F002
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
62 additional NY_MANIFEST: record(s) in the EDR Site Report.

AG291 **FLAMINGO/TYK CLEANERS** **NY DRYCLEANERS** **S110246604**
ESE **149 NORTH AV.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1298 ft. **Site 11 of 11 in cluster AG**

Relative: **Lower**
Actual: **89 ft.**

DRYCLEANERS:

Facility ID:	3-5510-00335
Phone Number:	914-235-1591
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	08SEP19
Install Date:	94/08
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AE292 **BLESSED SACREMENT CHURCH** **NY LTANKS** **S105996474**
South **15 SHEA PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.246 mi.
1301 ft. **Site 5 of 5 in cluster AE**

Relative: **Higher**
Actual: **98 ft.**

LTANKS:

Facility ID:	0204856
Site ID:	167332
Closed Date:	2003-10-03
Spill Number:	0204856
Spill Date:	2002-08-07

BLESSED SACREMENT CHURCH (Continued) **S105996474**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	BLESSED SACREMENT CHURCH
Spiller Address:	15 SHEA PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140984
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"DRY LEAK"

All TTF:

Facility ID:	0204856
Spill Number:	0204856
Spill Tank Test:	1527358
Site ID:	167332
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	167332
Operable Unit ID:	856138
Operable Unit:	01
Material ID:	519078

BLESSED SACREMENT CHURCH (Continued) **S105996474**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AN293 **MAY PARTNERS, LLC** **NY AST** **A100355569**
NNW **35-45 MAY STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.248 mi.
1309 ft. **Site 1 of 2 in cluster AN**

Relative: **Lower**

Actual: **79 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-600544
Site Status:	Active
GDS Number:	Not reported
Operator Name:	May Partners, LLC
Owner Name:	May Partners, LLC c/o Andover Properties
Owner Street:	25 East Spring Valley Avenue, Suite 280
Owner Address2:	Not reported
Owner City/State/Zip:	Maywood, NJ 07607
Tank Number:	001
Status:	3. Closed - Removed
Date Installation:	Not reported
Capacity:	4800
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	Not reported
Tank Location:	4. Aboveground: w/ 10% or more below ground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	3. Gravity
Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron

MAY PARTNERS, LLC (Continued) **A100355569**

Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	0. None

AL294 **FIREHOUSE** **NY LTANKS** **S103037428**
ENE **HARRISON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.252 mi.
1333 ft. **Site 20 of 20 in cluster AL**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:

Facility ID:	9713840
Site ID:	252028
Closed Date:	1998-03-27
Spill Number:	9713840
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALELLO
Spiller Phone:	(914) 654-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED. SYSTEM PASSED. NFA"
Remarks:	""

All TTF:

FIREHOUSE (Continued) **S103037428**

Facility ID:	9713840
Spill Number:	9713840
Spill Tank Test:	1545673
Site ID:	252028
Tank Number:	2
Tank Size:	5000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	252028
Operable Unit ID:	1059801
Operable Unit:	01
Material ID:	324831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK295 **BERGMAN REALTY SERVICES** **NY LTANKS** **S106972591**
NE **140 HUGUENOT STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.253 mi.
1336 ft. **Site 6 of 6 in cluster AK**

Relative: **Lower**
Actual: **67 ft.**

LTANKS:

Facility ID:	0505137
Site ID:	350100
Closed Date:	2007-11-07
Spill Number:	0505137
Spill Date:	2005-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	WCDOH
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

BERGMAN REALTY SERVICES (Continued) **S106972591**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2007-11-07
Spiller Name:	STEVE RING
Spiller Company:	RING HOME
Spiller Address:	140 HUGINOT STREET
Spiller County:	001
Spiller Contact:	STEVE RING
Spiller Phone:	(732) 855-8600
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	296544
DEC Memo:	"10/13/05 Closure letter sent to the RP from Danielle Jackson of the WCHD based on information submitted in a tank closure report. NFA TG"
Remarks:	""

All TTF:

Facility ID:	0505137
Spill Number:	0505137
Spill Tank Test:	1549133
Site ID:	350100
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	350100
Operable Unit ID:	1107682
Operable Unit:	01
Material ID:	2097572
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM296 **APARTMENT BLDG.** **NY LTANKS** **S104950549**
West **114 UNION AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1395 ft. **Site 2 of 3 in cluster AM**

Relative: **Lower**

Actual: **92 ft.**

LTANKS:

Facility ID:	0011198
Site ID:	151446
Closed Date:	2001-04-06
Spill Number:	0011198
Spill Date:	2001-01-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-14
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-14
Spill Record Last Update:	2001-04-24
Spiller Name:	Not reported
Spiller Company:	ALBINO FUELS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128711
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE SEE ONE PAGE UDATE BY V. MCCABE 04/06/2001 NORTHEAST COMPLETED CLEANUP. DISPOSED OF 4 DRUMS OF CONTAMINATION. SPILL INFORMATION FORWARDED TO LAW ENFORCEMENT FOR FURTHER ACTION. SPILLS - NO FURTHER ACTION."
Remarks:	"tank overfilled caused spill - spill is contained in a parking lot spiller is - albano fuel - 667-0900 (914)-clean up crew on site at this time"

All Materials:

Site ID:	151446
Operable Unit ID:	832582
Operable Unit:	01
Material ID:	541520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00

APARTMENT BLDG. (Continued) **S104950549**

Oxygenate:	Not reported
Facility ID:	9414493
Site ID:	238808
Closed Date:	1995-02-14
Spill Number:	9414493
Spill Date:	1995-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-02-06
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-03-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"ESTIMATED WRONG TANK SIZE SPILL CONTAINED NATL.ENVIR.CO. SPILL CREW ON WAY ENV PROD. AND SERVICES HIRED TO CLEAN UP. WILL EXCAVATE DRYWELL."

All Materials:

Site ID:	238808
Operable Unit ID:	1012066
Operable Unit:	01
Material ID:	373228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	175.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

APARTMENT BLDG. (Continued) **S104950549**

Facility ID:	9414511
Facility Type:	ER
Spill Number:	9414511
DER Facility ID:	196552
Site ID:	238809
DEC Region:	3
Closed Date:	1995-02-13
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	1995-02-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-02-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-02-13
Spiller Name:	Not reported
Spiller Company:	REGENT OIL
Spiller Address:	53 CHARLES STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SPILLER MAKING DELIVERY FILLED WRONG HOLE FD & CLEAN UP CREW ON SCENE TANK OVERFILL EP & S HIRED BY SPILLER AND ON SCENE CONTACTED WCHD WILL RESPOND SEE SPILL #94-14493"

All Materials:

Site ID:	238809
Operable Unit ID:	1008085
Operable Unit:	01
Material ID:	373246
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AN297 **DIMATTOE TTF** **NY LTANKS** **S113820294**
NNW **55 MAY STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.267 mi.
1412 ft. **Site 2 of 2 in cluster AN**

Relative: **Lower**

Actual: **79 ft.**

LTANKS:

Facility ID:	1301890
Site ID:	482303
Closed Date:	2013-08-08
Spill Number:	1301890
Spill Date:	2013-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2013-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-23
Spill Record Last Update:	2013-08-08
Spiller Name:	Not reported
Spiller Company:	DIMATTOE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	AMELIO DIMATTOE
Spiller Phone:	(914) 403-1942
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	437556
DEC Memo:	"5/23/13 left message on homeowner's phone. Spoke to Kathy, at US Tank Tech Tank is 1000 gal. Real estate transaction, and plans are to retest. dw 07/31/13 Northeast Environmental reported that they cut & cleaned the tank and obtained a soil sample from beneath the tank. The soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"repair/retest pending"

All TTF:

Facility ID:	1301890
Spill Number:	1301890
Spill Tank Test:	2493480
Site ID:	482303
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus

DIMATTOE TTF (Continued) **S113820294**

Leak Rate: .70
Gross Fail: Not reported
Modified By: jbodee
Last Modified Date: Not reported

All Materials:
Site ID: 482303
Operable Unit ID: 1232041
Operable Unit: 01
Material ID: 2230831
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

298
ENE
1/4-1/2
0.268 mi.
1415 ft.

CITY OF NEW ROCHELLE FIRE **NY LTANKS** **S105995871**
1 HARRISON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
72 ft.

LTANKS:
Facility ID: 0201696
Site ID: 75380
Closed Date: 2002-09-18
Spill Number: 0201696
Spill Date: 2002-05-15
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-05-15
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-05-15
Spill Record Last Update: 2002-09-23
Spiller Name: SAME
Spiller Company: NEW ROCHELLE FIRE DEPT
Spiller Address: 1 HARRISON STREET
Spiller County: 001
Spiller Contact: FRANK GALLELLO-FIRE DEPT
Spiller Phone: (914) 654-2316
Spiller Extention: Not reported

CITY OF NEW ROCHELLE FIRE (Continued) **S105995871**

DEC Region:	3
DER Facility ID:	70557
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST.PBS 3-600407 "

All TTF:

Facility ID:	0201696
Spill Number:	0201696
Spill Tank Test:	1527133
Site ID:	75380
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	75380
Operable Unit ID:	854864
Operable Unit:	01
Material ID:	523106
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

299
SSW
1/4-1/2
0.269 mi.
1418 ft.

CUMBERLAND FARM **NY LTANKS** **1000553075**
635 MAIN STREET **NY Spills** **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
85 ft.

LTANKS:

Facility ID:	9206930
Site ID:	140421
Closed Date:	2005-03-11
Spill Number:	9206930
Spill Date:	1992-09-16
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported

CUMBERLAND FARM (Continued) **1000553075**

Reported to Dept:	1992-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-03-12
Spiller Name:	Not reported
Spiller Company:	EXXON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	119925
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/11/05 per contractors report 7 tanks removes all in good condition (no evidence of holes or cracks; no detect in post excavation samples--close "
Remarks:	"DURING TANK REMOVAL CONTAMINATED SOIL DISCOVERED WILL TEST"

All Materials:

Site ID:	140421
Operable Unit ID:	970699
Operable Unit:	01
Material ID:	407611
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0514511
Facility Type:	ER
Spill Number:	0514511
DER Facility ID:	119925
Site ID:	361248
DEC Region:	3
Closed Date:	2006-03-20
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-20
Investigator:	RXAMATO
Referred To:	WCDOH
Reported to Dept:	2006-03-20
CID:	444

CUMBERLAND FARM (Continued) **1000553075**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-31
Spiller Name:	MELISSA GLIDEN
Spiller Company:	CUMBERLAND FARM
Spiller Address:	635 MAIN STREET
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
DEC Memo:	"03/21/06: Closed - NFA R. Amato"
Remarks:	"water in the dispenser pan and tyree enroute to clean up"

Facility ID:	1405322
Facility Type:	ER
Spill Number:	1405322
DER Facility ID:	119925
Site ID:	498745
DEC Region:	3
Closed Date:	Not reported
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2014-08-15
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-08-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-08-15
Spill Record Last Update:	2017-05-04
Spiller Name:	Not reported
Spiller Company:	CUMBERLAND FARMS 70288
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOHN
DEC Memo:	"8-15-14 Spoke with Angela Pimento at CF. She will have John return call to dispatch desk. jm Recv'd callback from Chris Lalak - WCDOH. He has spoken with John. Double wall fiberglass piping from dispensers to tanks. Leak is contained in tanktop sump. System has has been shut down at this time until they figure out what they are going to do. They believe they will probably replace lines. Chris says no leak to environment and he will be taking lead. jm 5-15 new

CUMBERLAND FARM (Continued) **1000553075**

spill 15-01325; Phase 2report 10-15-15 email status request sent to WCHD & Cumby RDB 10-22-15, from Cumby In response to the line failure, CFI engaged Island Pump & Tank (IPT) to perform the repairs. In lieu of replacing the product piping, IPT installed a siphon bar on the regular tanks and removed the submersible pump from the regular tank that had the failed product piping. IPT then removed and capped the regular product piping that had failed. The secondary line was tested and the dispenser pans and STP sumps were hydrostatically tested and passed. RDB 2-16 new SPills 15-10746 3-8-16 during meeting with WCHD, Singh, his att, his consultant, Cumby, their consultant and att, taking place in New Rochelle. Closure was denied on spills 14-05322 & 15-01325and RPs agreed to a scope of work by March 16. RDB 5-4-17 Work completed, waiting for closure report. GHP"

Remarks: "spill to containment/clean up complete"

All Materials:

Site ID:	498745
Operable Unit ID:	1248186
Operable Unit:	01
Material ID:	2249583
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

---

300 South 1/4-1/2 0.270 mi. 1424 ft. **NEW ROCHELLE CATH MIDDLE** **NY LTANKS S102154123**
24 MAPLE AV **NY Spills N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 94 ft.

LTANKS:

Facility ID:	0204857
Site ID:	80066
Closed Date:	2003-10-03
Spill Number:	0204857
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE CATH MIDDLE
Spiller Address:	24 MAPLE AV
Spiller County:	001
Spiller Contact:	MARV
Spiller Phone:	(914) 637-7505
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74246
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks:	""

All TTF:

Facility ID:	0204857
Spill Number:	0204857
Spill Tank Test:	1527359
Site ID:	80066
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	80066
Operable Unit ID:	856140
Operable Unit:	01
Material ID:	519079
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9008354
Facility Type:	ER
Spill Number:	9008354
DER Facility ID:	107755
Site ID:	124420

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

DEC Region:	3
Closed Date:	1990-11-26
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1990-10-30
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-10-31
Cleanup Meets Std:	True
Last Inspection:	1990-10-31
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-06
Spill Record Last Update:	1990-11-26
Spiller Name:	Not reported
Spiller Company:	CASTLE FUEL
Spiller Address:	290 LOCUST AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE BURST DURING DELIVERY WC FIRE CONTROL ON SCENE ABSORBANT PADS HAVE BEEN PUT DOWN CHIEF MCCAFFREY CONTACTED BUT HE WASN'T ON SCENE HAS NO INFO."

All Materials:

Site ID:	124420
Operable Unit ID:	945552
Operable Unit:	01
Material ID:	432188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9111148
Facility Type:	ER
Spill Number:	9111148
DER Facility ID:	107755
Site ID:	124421
DEC Region:	3
Closed Date:	1992-03-17
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1992-01-29

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1992-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1992-02-05
Cleanup Meets Std:	True
Last Inspection:	1992-02-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-30
Spill Record Last Update:	1992-03-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL DISCOVERED SEEPING OUT OF GROUND/BLACKTOP WALKWAY (BETWEEN SCHOOL AND BEAUTY SALON) SUSPECT BROKEN RETURN LINE APPROX 30' FROM TANK TO BURNER - 2K TANK AL EASTMAN TO EIR CASTLE OIL CREW ENROUTE"

All Materials:

Site ID:	124421
Operable Unit ID:	964875
Operable Unit:	01
Material ID:	416206
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AO301 **COMMERCIAL SITE** **NY LTANKS** **U003857828**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1441 ft. **Site 1 of 3 in cluster AO**

Relative: **Lower**
Actual: **89 ft.**

LTANKS:

Facility ID:	0408593
Site ID:	333366
Closed Date:	2005-02-13
Spill Number:	0408593
Spill Date:	2004-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee

COMMERCIAL SITE (Continued) **U003857828**

Referred To:	WCHD
Reported to Dept:	2004-11-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-05
Spill Record Last Update:	2005-02-13
Spiller Name:	BARRY SHAPIRO
Spiller Company:	COMMERCIAL SITE
Spiller Address:	38 LOCUS AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"02/13/05 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-800080 "
Facility ID:	0206043
Site ID:	239569
Closed Date:	2002-09-26
Spill Number:	0206043
Spill Date:	2002-09-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-10-29
Spiller Name:	BARRY SHAPIRO
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	38 LOCUST AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3

COMMERCIAL SITE (Continued) **U003857828**

DER Facility ID: 197040
DEC Memo: ""
Remarks: "RECOMMENDATION IS TO UNCOVER - REPAIR - AND RE-TEST."

All TTF:
Facility ID: 0206043
Spill Number: 0206043
Spill Tank Test: 1527440
Site ID: 239569
Tank Number: 1
Tank Size: 3000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 239569
Operable Unit ID: 857630
Operable Unit: 01
Material ID: 571516
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AO302 **COMMERCIAL PROPERTY** **NY LTANKS** **S112810152**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1441 ft. **Site 2 of 3 in cluster AO**

Relative: **Lower**
Actual: **89 ft.**

LTANKS:
Facility ID: 1213228
Site ID: 476407
Closed Date: 2013-02-04
Spill Number: 1213228
Spill Date: 2012-12-10
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2012-12-10

COMMERCIAL PROPERTY (Continued) **S112810152**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-10
Spill Record Last Update:	2013-02-04
Spiller Name:	Not reported
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	HAL SHAPIRO
Spiller Phone:	(914) 355-5350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"12-10-12 PBS site. Tank failed with popping. US Tank Tech has been testing since '98. Super was at site during test and Shapiro notified by phone. jc 12/19/12: Update from WCDoH PBS: >>> Lalak, Chris >>cjl1@westchestergov.com> 12/11/2012 4:23 PM >>> 1213228 38 Locust, new Rochelle PBS 3-800080 TTF 3K tank from 84 Tyra/Carlos Lead jod 2/4/2013: Tank passed a retest after piping was repaired. Report entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"1211 THE CALLER IS REPORTING A FAILED TANK TEST."

All Materials:

Site ID:	476407
Operable Unit ID:	1226235
Operable Unit:	01
Material ID:	2223616
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AP303 **DEMELIA - TTF** **NY LTANKS** **S117364514**
WNW **95 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.275 mi.
1453 ft. **Site 1 of 2 in cluster AP**

Relative: **Lower**
Actual: **90 ft.**

LTANKS:

Facility ID:	1406916
Site ID:	500408
Closed Date:	2015-04-14
Spill Number:	1406916
Spill Date:	2014-10-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

DEMELIA - TTF (Continued) **S117364514**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-01
Spill Record Last Update:	2015-04-14
Spiller Name:	ROSEMARIE DEMELIA
Spiller Company:	Estate of DeMelia
Spiller Address:	95 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455413
DEC Memo:	"This house is the estate of R Demellia's late mother. Tank failed with only hissing, maybe a line leak but cant be sure. House is being prep'ed for sale....mm 12/08/14: From Envirostar: We pulled a 550 UST at 95 Washington Ave New Rochelle that had previously failed a tank test (spill # 1406916). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Chuck LiVecchi 95 Washington Ave New Rochelle NY jod 3/20/15: Update from Envirostar via email: We removed 6 containers of contaminated soil Between march 12th and yesterday we took samples and back filled the hole. We will Submit for closure. jod 4/13/15: Report with request for closure entered into DecDocs. Post-Ex soil samples show contamination in excess of CP-51 Guidance. Additional information being requested from Envirostar. jod 4/14/2015: Envirostar removed and disposed of the leaking UST and a total of 108.96 tons of petroleum contaminated soil. Some residual contamination over CP-51 Guidance could not be excavated from along the foundation and due to safety concerns with buried utility lines. No evidence of ground water impact noted. Based upon information provided, no further action required at this time. jod"
Remarks:	"550 test failure"

All TTF:

Facility ID:	1406916
Spill Number:	1406916
Spill Tank Test:	2496432
Site ID:	500408
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01

DEMELIA - TTF (Continued) **S117364514**

Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	500408
Operable Unit ID:	1249816
Operable Unit:	01
Material ID:	2251444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ304 **SPILL NUMBER 0208792** **NY LTANKS** **S105997404**
North **386 NORTH AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.276 mi.
1456 ft. **Site 1 of 5 in cluster AQ**

Relative: LTANKS:
Lower

Actual:
75 ft.

Facility ID:	0208792
Site ID:	71430
Closed Date:	2002-11-26
Spill Number:	0208792
Spill Date:	2002-11-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-11-26
Spiller Name:	ROBERT CRIILLO
Spiller Company:	WILCO
Spiller Address:	95 PLAIN AV
Spiller County:	001
Spiller Contact:	CARTER RESIDENCE

SPILL NUMBER 0208792 (Continued) **S105997404**

Spiller Phone:	(914) 632-6577
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67588
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 SPILL CLEANUP TO BE COMPLETED TOMORROW."
Remarks:	"take pride environmental enroute to clean up the soil"

All Materials:

Site ID:	71430
Operable Unit ID:	861979
Operable Unit:	01
Material ID:	515786
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

305 SE 1/4-1/2 0.281 mi. 1486 ft. **RESIDENCE** **NY LTANKS** **S106971497**
64 CHURCH ST **N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 86 ft.

LTANKS:

Facility ID:	0408510
Site ID:	333255
Closed Date:	2008-05-01
Spill Number:	0408510
Spill Date:	2004-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-02
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-02-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2008-05-01
Spiller Name:	RAMONE OCEGUERA
Spiller Company:	Not reported
Spiller Address:	64 CHURCH ST
Spiller County:	001
Spiller Contact:	RAMONE OCEGUERA

RESIDENCE (Continued) **S106971497**

Spiller Phone: (914) 396-7293
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 268502
DEC Memo: "11/22/04 AST ON GROUND UNDER DECK. TANK LOST APPROX 150 GALLONS AFTER TEST. FREE PRODUCT IN SUMP PIT IN BASEMENT. FURTHER INVESTIGATION TO BE DONE BY ADVANCED ENVIRONMENTAL. jod 5/1/2008: Advanced Environmental disposed of LUST and 26.15 tons of contaminated soil. Ground water was impacted and sampled. Spill closure report from ECC submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks: "tank test failed."

All TTF:
Facility ID: 0408510
Spill Number: 0408510
Spill Tank Test: 1548304
Site ID: 333255
Tank Number: 1
Tank Size: 275
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 333255
Operable Unit ID: 1095424
Operable Unit: 01
Material ID: 575563
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AR306 **CANDREA/GALLETTA RESIDENCE** **NY LTANKS** **S112148789**
WSW **35 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.287 mi.
1517 ft. **Site 1 of 2 in cluster AR**

Relative:
Lower

Actual:
92 ft.

LTANKS:

Facility ID:	1202322
Site ID:	465083
Closed Date:	2012-09-13
Spill Number:	1202322
Spill Date:	2012-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-07
Spill Record Last Update:	2012-09-13
Spiller Name:	Not reported
Spiller Company:	GALETTA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	GALETTA
Spiller Phone:	914-497-9141
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	419452
DEC Memo:	"6-7-12 Kathy already notified owner. Spoke with Anthony, owners son-in-law. Told him to forward passing retest to office for spill to be closed. He asked for email to that affect. I sent. jc 6/18/12- US Tank reports that retest failed. Unknown further action. DT 09/13/12 Castlton Environmental reported that they excavated and removed the tank along with 21.04 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"550 gal ust"

All Materials:

Site ID:	465083
Operable Unit ID:	1215116
Operable Unit:	01
Material ID:	2213205
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported

CANDREA/GALLETTA RESIDENCE (Continued) **S112148789**

Oxygenate: Not reported

AM307 **SPILL NUMBER 0007965** **NY LTANKS** **S104782459**
West **45 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.290 mi.
1530 ft. **Site 3 of 3 in cluster AM**

Relative: **Lower**

Actual: **92 ft.**

LTANKS:

Facility ID:	0007965
Site ID:	61314
Closed Date:	2000-10-26
Spill Number:	0007965
Spill Date:	2000-10-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-06
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-06
Spill Record Last Update:	2000-11-07
Spiller Name:	Not reported
Spiller Company:	ALBANO FUEL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ALBANO FUEL
Spiller Phone:	(914) 667-0900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/26/2000 TRI-STATE COMPLETED CLEANUP AFTER DEC INSPECTION. INITIAL SPILL BY ALBANO FUEL WAS NEVER REPORTED. NFA"
Remarks:	"SPILL OCCURRED DURING FILL. TRI STATE WAS CONTRACTED FOR CLEAN UP."

All Materials:

Site ID:	61314
Operable Unit ID:	830442
Operable Unit:	01
Material ID:	545482
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G

SPILL NUMBER 0007965 (Continued) **S104782459**

Recovered: .00
Oxygenate: Not reported

AS308 **RUSH MFG CORP** **CORRACTS** **1000201737**
SW **10-12 PINE CT** **RCRA-CESQG** **NYD075436394**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY Spills**
0.291 mi. **FINDS**
1534 ft. **Site 1 of 4 in cluster AS** **ECHO**
RI MANIFEST
Relative: **NJ MANIFEST**
Lower

Actual: **56 ft.**

CORRACTS:

EPA ID: NYD075436394
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19940503
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD075436394
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19920922
Action: CA050 - RFA Completed
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-CESQG:

Date form received by agency: 01/01/2007
Facility name: RUSH MANUFACTURING CORP
Facility address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
EPA ID: NYD075436394
Mailing address: PINE CT
NEW ROCHELLE, NY 10801
Contact: DENNIS MCNAMARA
Contact address: PINE CT
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: 914-636-2700
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar

RUSH MFG CORP (Continued) **1000201737**

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	RUSH MANUFACTURING CORP
Owner/operator address:	10-12 PINE CT NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-636-2700
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	10-12 PINE COURT OPERCITY, NY 99999
Owner/operator country:	US
Owner/operator telephone:	914-632-2200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

RUSH MFG CORP (Continued) **1000201737**

Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/09/1997
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238

RUSH MFG CORP (Continued) **1000201737**

. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 02/25/1992
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980
Site name: RUSH MANUFACTURING CORP
Classification: Not a generator, verified

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 12/31/1979
Site name: RUSH MANUFACTURING CORP
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 09/22/1992

RUSH MFG CORP (Continued) **1000201737**

Event: RFA COMPLETED

Event date: 05/03/1994
Event: CA PRIORITIZATION-LOW CA PRIORITY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/26/1990
Date achieved compliance: 05/02/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/12/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/23/1989
Date achieved compliance: 05/12/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/16/1988
Date achieved compliance: 11/17/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/09/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/27/1987
Date achieved compliance: 11/17/1988
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

RUSH MFG CORP (Continued) **1000201737**

Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/19/1986
Date achieved compliance: 05/27/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/15/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/23/1984
Date achieved compliance: 10/07/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/26/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/02/1990
Evaluation lead agency: State

Evaluation date: 02/23/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/12/1989
Evaluation lead agency: State

Evaluation date: 03/16/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: State

Evaluation date: 03/11/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

RUSH MFG CORP (Continued) **1000201737**

Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: EPA

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/27/1986
Evaluation lead agency: State

Evaluation date: 02/23/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/07/1985
Evaluation lead agency: State

SPILLS:
Facility ID: 0804532
Facility Type: ER
Spill Number: 0804532
DER Facility ID: 350696
Site ID: 401456
DEC Region: 3
Closed Date: 2008-09-26
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 2008-07-21
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2008-07-21
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-07-21
Spill Record Last Update: 2008-09-26
Spiller Name: MICHEAL
Spiller Company: COMMERCIAL MACHINE SHOP
Spiller Address: 10-12 PINE COURT
Spiller Company: 001
Contact Name: MICHEAL
DEC Memo: "08/01/08 Conklin Services & Construction submitted a Limited Subsurface Investigation Report. Four geoprobe borings were placed around an abandoned tank. Slight soil contamination exists in borings 1 and 2, however the levels are below DEC TAGM guidance values. NFA TG"
Remarks: "SOIL BORINGS SHOWED CONTAMINATED SHOP"

All Materials:

RUSH MFG CORP (Continued) **1000201737**

Site ID:	401456
Operable Unit ID:	1158245
Operable Unit:	01
Material ID:	2149301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0901536
Facility Type:	ER
Spill Number:	0901536
DER Facility ID:	350696
Site ID:	413531
DEC Region:	3
Closed Date:	2009-06-22
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2009-05-07
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-06-22
Spiller Name:	Not reported
Spiller Company:	ALPHA MEDICAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NIKI
DEC Memo:	"5/7/09 At a construction site, contaminated soils were encountered, which was confirmed by soil tests done by Northeast. They will be doing the site remediation and will submit a cleanup report. dw 06/12/09 Northeast Environmental provided oversight activity when petroleum impacted soil was discovered and need to be removed. Remediation consisted of the removal of 425.66 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were all below DEC guidance values. NFA required. TG"
Remarks:	"1231 The caller advised dispatch North East Environmental will conduct the clean up. The caller requested a call back. No water ways affected."

RUSH MFG CORP (Continued) **1000201737**

All Materials:

Site ID:	413531
Operable Unit ID:	1169955
Operable Unit:	01
Material ID:	2161660
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

FINDS:

Registry ID: 110009468343

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000201737
Registry ID:	110009468343
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009468343

RI MANIFEST:

EPA Id:	NYD075436394
Manifest Document Number:	CTC0168898
GEN Cert Date:	10/7/1991
TSDF Id:	CTD021816889
TSDF Name:	UNITED
TSDF Date:	Not reported
Transporter 2 Id:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Transporter 2 Name:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported

Details:

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991
Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991
Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

NJ MANIFEST:

EPA Id:	NYD075436394
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Manifest:

Manifest Number:	001619722SKS
EPA ID:	NYD075436394
Date Shipped:	02/23/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/26/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	002115978SKS
EPA ID:	NYD075436394
Date Shipped:	10/01/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	5 G

Manifest Number:	001803673SKS
EPA ID:	NYD075436394
Date Shipped:	05/08/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001811141SKS
EPA ID:	NYD075436394
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

Manifest Number:	002486638SKS
EPA ID:	NYD075436394
Date Shipped:	01/29/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/01/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H020
Quantity: 7 G

Manifest Number: 000266181CEX
EPA ID: NYD075436394
Date Shipped: 10/30/2009
TSDF EPA ID: NJD982270506
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/30/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/05/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 9 G

RUSH MFG CORP (Continued) **1000201737**

Manifest Number:	001819324SKS
EPA ID:	NYD075436394
Date Shipped:	07/16/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

Manifest Number:	001632477SKS
EPA ID:	NYD075436394
Date Shipped:	01/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

RUSH MFG CORP (Continued) **1000201737**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

AS309 **GKIDS REALTY** **NY LTANKS** **S105995601**
SW **10/12 PINE COURT** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.291 mi.
1534 ft. **Site 2 of 4 in cluster AS**

Relative: **Lower**
Actual: **56 ft.**

LTANKS:

Facility ID:	0200337
Site ID:	235436
Closed Date:	2003-12-09
Spill Number:	0200337
Spill Date:	2002-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD

GKIDS REALTY (Continued) **S105995601**

Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-04-10
CID:	204
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-10
Spill Record Last Update:	2003-12-10
Spiller Name:	GKIDS REALTY
Spiller Company:	GKIDS REALTY
Spiller Address:	10/12 PINE COURT
Spiller County:	001
Spiller Contact:	MICHAEL GOLD
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193919
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER #2 PBS 3-504998 handled by WCHD 12/09/03 TANK CLOSED IN PLACE, SAMPLE RESULTS BELOW TAGM. SPILL CLOSED BY WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE - RECOMMEND TO ISOLATE PIPING AND RETEST "

All TTF:

Facility ID:	0200337
Spill Number:	0200337
Spill Tank Test:	1527023
Site ID:	235436
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235436
Operable Unit ID:	851333
Operable Unit:	01
Material ID:	525339
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

GKIDS REALTY (Continued) **S105995601**

Recovered: .00
Oxygenate: Not reported

AP310 **BRAM REALTY** **NY LTANKS** **S109583709**
WNW **105 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AP**

Relative: **Lower**
Actual: **85 ft.**

LTANKS:

Facility ID:	0902464
Site ID:	414506
Closed Date:	2010-02-01
Spill Number:	0902464
Spill Date:	2009-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-01
Spill Record Last Update:	2010-02-01
Spiller Name:	HAL SHAPIRO
Spiller Company:	BRAM REALTY
Spiller Address:	105 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	363644
DEC Memo:	"6-1-09: V.Mc.^ Hal/BRAM REALTY: Left Mess: Req.Callbk. to dispt &/or J.O'Dee. 6-3-09: HAL SHAPIRO CALLED AND STATED IS WAS AWARE OF PROPER PROCEDURES TO FOLLOW. HE WILL CONTACT HIS OIL CO. FOR DIRECTION AND NOTIFY DEC OF OUTCOME. 01/25/10 Enviroshield reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was obseved in the tank excavation. NFA TG "
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST UNK IF ANY PRODUCT WAS SPILLED."

All Materials:

Site ID:	414506
Operable Unit ID:	1170891
Operable Unit:	01
Material ID:	2162674
Material Code:	0001A

BRAM REALTY (Continued) **S109583709**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AR311 **MERLUCCI RESIDENCE** **NY LTANKS** **S111063886**
WSW **30 CHARLES STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AR**

Relative: LTANKS:
Lower

Actual:
92 ft.

Facility ID:	1103221
Site ID:	450778
Closed Date:	2011-11-14
Spill Number:	1103221
Spill Date:	2011-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-22
Spill Record Last Update:	2011-11-14
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MR MERLUCCI
Spiller Phone:	(914) 632-2099
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	405335
DEC Memo:	"6/22/11 UST is 62 years old, according to Ms. Merlucci. House is for sale. US Tank Tech has notified Town & Country Oil not evacuate tank prior to further action (repair, retest, tank pull) of owner. dw 11/14/11: UST removed by JM Associates. Report states tank was inspected and no corrosion holes were found. Soil samples taken from tank grave showed minor amounts of contamination, most below CP-51 with a few slight exceedences of SVOCs. Excavation was backfilled. Report will be entered into eDocs. jod"
Remarks:	"repair retest pending or removal"

MERLUCCI RESIDENCE (Continued) **S111063886**

All Materials:

Site ID:	450778
Operable Unit ID:	1200979
Operable Unit:	01
Material ID:	2197455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ312 **KGM PROPERTY ASSOC.** **NY LTANKS** **U003647638**
North **394 N. AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.296 mi.
1561 ft. **Site 2 of 5 in cluster AQ**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Facility ID:	9202033
Site ID:	69270
Closed Date:	1993-01-27
Spill Number:	9202033
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-20
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65872
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."

KGM PROPERTY ASSOC. (Continued) **U003647638**

Remarks: "TANK IS 38 YEARS OLD THIS TANK WAS ORIGINAL REPORTED UNDER #9201744 BUT IS LOCATED AT DIFFERENT ADDRESS PETRO-TITE -.422 GPH"

All TTF:

Facility ID:	9202033
Spill Number:	9202033
Spill Tank Test:	1540014
Site ID:	69270
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	69270
Operable Unit ID:	966124
Operable Unit:	01
Material ID:	557154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AQ313 **KGM REALTY CO.** **NY LTANKS** **S100493525**
North **396 NORTH AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.297 mi.
1569 ft. **Site 3 of 5 in cluster AQ**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Facility ID:	9201744
Site ID:	89642
Closed Date:	1993-01-27
Spill Number:	9201744
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported

KGM REALTY CO. (Continued) **S100493525**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-13
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK #1 IS 64 YEARS OLD AND TANK #2 IS 38 YEARS OLD WILL EIR TANK #2 NEXT WEEK"

All TTF:

Facility ID:	9201744
Spill Number:	9201744
Spill Tank Test:	1539987
Site ID:	89642
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	89642
Operable Unit ID:	969160
Operable Unit:	01
Material ID:	413039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AQ314 **GETTY# 677** **NY LTANKS** **S103482965**
North **381 NORTH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.299 mi.
1580 ft. **Site 4 of 5 in cluster AQ**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Facility ID:	0400912
Site ID:	242546
Closed Date:	2005-01-18
Spill Number:	0400912
Spill Date:	2004-04-27
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-04-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-27
Spill Record Last Update:	2005-01-18
Spiller Name:	STEVEN PHELTS
Spiller Company:	GETTY# 677
Spiller Address:	381 NORTH AVE
Spiller County:	001
Spiller Contact:	STEVEN PHELTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 1/18/2005 close and handle under existing spill 9003146 "
Remarks:	"FOUND CONTAMINATED SOIL WHILE REMOVING TANK: "

All Materials:

Site ID:	242546
Operable Unit ID:	882894
Operable Unit:	01
Material ID:	555170
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

SPILLS:

Facility ID:	1012947
Facility Type:	ER
Spill Number:	1012947
DER Facility ID:	401849
Site ID:	447247
DEC Region:	3
Closed Date:	2011-03-31
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6038
Spill Date:	2011-03-29
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2011-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-29
Spill Record Last Update:	2011-03-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"3-29-11 Called and left message for Mike to return call to dispatch desk. jm 3-31-11 Spoke with Mike. Spill was as stated and cleanup completed. jm"
Remarks:	"contained to bay floor, clean up"

All Materials:

Site ID:	447247
Operable Unit ID:	1197384
Operable Unit:	01
Material ID:	2193703
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	0900607
Facility Type:	ER
Spill Number:	0900607
DER Facility ID:	199318
Site ID:	412555

GETTY# 677 (Continued) **S103482965**

DEC Region:	3
Closed Date:	2009-04-16
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-04-16
Investigator:	RXAMATO
Referred To:	Not reported
Reported to Dept:	2009-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-16
Spill Record Last Update:	2009-04-16
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/17/09: Vac truck pumped out dispenser sump...close/nfa..ra"
Remarks:	"DUE TO POOR HOUSEKEEPING A HALF GALLON OF PRODUCT WAS SPILLED TO CONRETE BAY FLOORS. CLEAN UP WAS DONE."

All Materials:

Site ID:	412555
Operable Unit ID:	1169019
Operable Unit:	01
Material ID:	2160665
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	.50
Oxygenate:	Not reported

Facility ID:	1001015
Facility Type:	ER
Spill Number:	1001015
DER Facility ID:	199318
Site ID:	433723
DEC Region:	3
Closed Date:	2010-04-27
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-04-27
Investigator:	kabrowne
Referred To:	Not reported

GETTY# 677 (Continued) **S103482965**

Reported to Dept:	2010-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-04-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-05-10
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/27/10 - Spill cleaned up. NFA. KAB 5/10/10: Update from Denise Heinzinger of WCDOH who inspected: #1001015 small spill onto concrete at 381 North Ave, New Rochelle, clean up performed jod"
Remarks:	"1 pint onto concrete. Clean up complete"

All Materials:

Site ID:	433723
Operable Unit ID:	1184583
Operable Unit:	01
Material ID:	2178854
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	9805150
Facility Type:	ER
Spill Number:	9805150
DER Facility ID:	199318
Site ID:	242548
DEC Region:	3
Closed Date:	1998-07-27
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1998-07-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-24
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

GETTY# 677 (Continued) **S103482965**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-24
Spill Record Last Update:	1998-08-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ORLANDO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 SITE INSPECTED BY J. O'DEE. TYREE IN PROCESS OF INSTALLING A MONITORING WELL AT 381 NORTH AVE., NEW ROCHELLE. IT APPEARS A RESIDENT PARKED CAR OVER STORM DRAIN WHILE CHANGING OIL. THE S/S EMPLOYEES WILL OBSERVE THE AREA AND CONTACT DEC IF ANY ADDITIONAL DUMPING OCCURS. NFA."
Remarks:	"FOUND OIL SPILLED INTO SEWER IN REAR OF GAS STATION"

All Materials:

Site ID:	242548
Operable Unit ID:	1063026
Operable Unit:	01
Material ID:	319903
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	90.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0503897
Facility Type:	ER
Spill Number:	0503897
DER Facility ID:	199318
Site ID:	348603
DEC Region:	3
Closed Date:	2006-12-19
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	2005-07-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-07-01
CID:	409
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

GETTY# 677 (Continued) **S103482965**

Date Entered In Computer:	2005-07-01
Spill Record Last Update:	2006-12-19
Spiller Name:	UNKNOWN
Spiller Company:	CUSTOMER TANK OVERFILL
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	""
Remarks:	"1 cup and has been cleaned up."

All Materials:

Site ID:	348603
Operable Unit ID:	1106254
Operable Unit:	01
Material ID:	1971181
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	0912229
Facility Type:	ER
Spill Number:	0912229
DER Facility ID:	199318
Site ID:	425106
DEC Region:	3
Closed Date:	2010-02-23
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-02-23
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-02-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-23
Spill Record Last Update:	2010-03-30
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"2/23/10 confirmed clean up, nfa...mm"
Remarks:	"HALF GALLON OF WASTE OIL TO CONCRETE CLEAN UP WAS DONE."

GETTY# 677 (Continued) **S103482965**

All Materials:

Site ID:	425106
Operable Unit ID:	1180837
Operable Unit:	01
Material ID:	2174836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	1005811
Facility Type:	ER
Spill Number:	1005811
DER Facility ID:	199318
Site ID:	439142
DEC Region:	3
Closed Date:	2010-08-25
Spill Cause:	Housekeeping
Spill Class:	D4
SWIS:	6010
Spill Date:	2010-08-25
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-08-25
Spill Record Last Update:	2010-08-25
Spiller Name:	MIKE CARR
Spiller Company:	GETTY
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"8/25/10 Confirmed clean up with caller, nfa...mm"
Remarks:	"Caller stated they had spilt waste oil on concrete, Are has been cleaned up."

All Materials:

Site ID:	439142
Operable Unit ID:	1189791
Operable Unit:	01
Material ID:	2184749
Material Code:	0022
Material Name:	waste oil/used oil

GETTY# 677 (Continued) **S103482965**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AO315 **APT. BUILDING** **NY LTANKS** **S102660713**
ESE **55-59 LOCUST AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.300 mi.
1586 ft. **Site 3 of 3 in cluster AO**

Relative:
Lower

Actual:
90 ft.

LTANKS:

Facility ID:	9200639
Site ID:	168647
Closed Date:	1992-06-26
Spill Number:	9200639
Spill Date:	1992-04-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-05-12
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1992-05-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	1998-01-14
Spiller Name:	Not reported
Spiller Company:	N.Y. PROPERTIES CO.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142042
DEC Memo:	""
Remarks:	"TWO UC TANKS WERE BURIED RAIN FORCES OIL UP THROUGH BLACKTOP MGNT. CO.APPLIES SPEEDI-DRY BUT DOES NOT REPORT OR REPAIR"

All Materials:

Site ID:	168647
Operable Unit ID:	964508
Operable Unit:	01
Material ID:	415419
Material Code:	0002A
Material Name:	#4 fuel oil

APT. BUILDING (Continued) **S102660713**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AT316 **BLESSED SACRAMENT HS** **NY LTANKS** **S113494296**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.305 mi.
1613 ft. **Site 1 of 3 in cluster AT**

Relative: **Lower**
Actual: **91 ft.**

LTANKS:

Facility ID:	1300960
Site ID:	481320
Closed Date:	Not reported
Spill Number:	1300960
Spill Date:	2013-04-29
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-04-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-04-29
Spill Record Last Update:	2017-11-16
Spiller Name:	ED SULLIVAN
Spiller Company:	HIGH SCHOOL
Spiller Address:	24 SHEA PLACE
Spiller County:	999
Spiller Contact:	ED SULLIVAN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"This is a 1K ust. Testing done every year. Appears to be a piping problem, will uncover, repair and retest. WCDOH has been notified....mm 8/5/13 Failed retest. Spoke to Kathy Morgan at US Tank Test. dw 11-16-2017 A consultant called-in to say they will submit a closure report today. BTR"
Remarks:	"tank test failure"

All TTF:

Facility ID:	1300960
Spill Number:	1300960
Spill Tank Test:	2493383

BLESSED SACRAMENT HS (Continued) **S113494296**

Site ID:	481320
Tank Number:	0
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2229789
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2230143
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AT317 **BLESSED SACRAMENT HIGH SC** **NY LTANKS** **S106385926**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.306 mi.
1614 ft. **Site 2 of 3 in cluster AT**

Relative: LTANKS:
Lower

Facility ID:	0400709
Site ID:	249284
Closed Date:	2004-07-06
Spill Number:	0400709
Spill Date:	2004-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal

Actual:
91 ft.

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-04-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-21
Spill Record Last Update:	2004-07-06
Spiller Name:	LARRY HANSEN
Spiller Company:	BLESSED SACRAMENT HIGH SC
Spiller Address:	24 SHEA PLACE
Spiller County:	001
Spiller Contact:	LARRY HANSEN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 07/06/04 TANK PASSED RETEST."
Remarks:	"FAILED SUBLINGS RECOMMEND UNCOVER REPAIR & RETEST OR REMOVE: "

All TTF:

Facility ID:	0400709
Spill Number:	0400709
Spill Tank Test:	1529181
Site ID:	249284
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	249284
Operable Unit ID:	884909
Operable Unit:	01
Material ID:	491955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AU318 **BLESSED SACRAMENT CHURCH** **NY LTANKS** **S100165619**
SSE **SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.309 mi.
1629 ft. **Site 1 of 3 in cluster AU**

Relative: **Lower**
Actual: **91 ft.**

LTANKS:
Facility ID: 8704259
Site ID: 324974
Closed Date: 1987-11-20
Spill Number: 8704259
Spill Date: 1987-08-02
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 1987-11-20
SWIS: 6010
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 1987-08-02
CID: Not reported
Water Affected: NONE
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1987-09-30
Spill Record Last Update: 1987-11-20
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 261780
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST. / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST RETEST PASSED.NFA. "
Remarks: "TTTF-TWO TANKS FAILED"

All TTF:
Facility ID: 8704259
Spill Number: 8704259
Spill Tank Test: 1531452
Site ID: 324974
Tank Number: Not reported
Tank Size: 0
Material: 0001

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	324974
Operable Unit ID:	908133
Operable Unit:	01
Material ID:	466902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV319 **PROFESSIONAL BUILDING COP** **NY LTANKS** **S108982494**
SSW **421 HUGUENOT STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.311 mi.
1642 ft. **Site 1 of 2 in cluster AV**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Facility ID:	0606014
Site ID:	369299
Closed Date:	2007-01-29
Spill Number:	0606014
Spill Date:	2006-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-08-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-24
Spill Record Last Update:	2007-01-29
Spiller Name:	GERRI SEENY

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Spiller Company:	PROFESSIONAL OFFICE CORP
Spiller Address:	421 HUGUENOT STREET
Spiller County:	001
Spiller Contact:	GERRI SEENY
Spiller Phone:	(914) 632-3400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	319185
DEC Memo:	"RECOMMENDING ISOLATION. 0606014 - 421 Huguenot St, New Rochelle - removed petrometer and remote fill from system and retested, passed. NFA. 10/23/06 test date"
Remarks:	""

All TTF:

Facility ID:	0606014
Spill Number:	0606014
Spill Tank Test:	1550220
Site ID:	369299
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	369299
Operable Unit ID:	1127138
Operable Unit:	01
Material ID:	2116724
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0711337
Facility Type:	ER
Spill Number:	0711337
DER Facility ID:	319185
Site ID:	392804
DEC Region:	3
Closed Date:	2008-06-24
Spill Cause:	Equipment Failure
Spill Class:	C3

PROFESSIONAL BUILDING COP (Continued) **S108982494**

SWIS:	6010
Spill Date:	2008-01-28
Investigator:	WCHD
Referred To:	SCHNEIDER
Reported to Dept:	2008-01-28
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2008-06-24
Spiller Name:	GERRY
Spiller Company:	PROFESSIONAL BUILDING COP
Spiller Address:	421 HUGUENOT STREET
Spiller Company:	001
Contact Name:	GERRY
DEC Memo:	"Spoke to Gerry. Danielle Jackson of WCHD may be handling. WCHD to inspect today. 06/24/08 Wayne Schneider WCHD reported 421 Huguenot St, New Rochelle - leaking tank. Contaminated soil remediated. See attached NFA TG "
Remarks:	"HOLES AND CONTAMINATED SOIL"

All TTF:

Facility ID:	0711337
Spill Number:	0711337
Spill Tank Test:	2384563
Site ID:	392804
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	392804
Operable Unit ID:	1149789
Operable Unit:	01
Material ID:	2140347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Units: G
Recovered: .00
Oxygenate: Not reported

---

320 West 1/4-1/2 0.311 mi. 1644 ft. **FRANKA INC.** **NY LTANKS** **S104276153**
132-143 UNION AVE. **N/A**
NEW ROCHELLE, NY

Relative: Lower
Actual: 90 ft.

LTANKS:
Facility ID: 9312205
Site ID: 176106
Closed Date: 1995-11-09
Spill Number: 9312205
Spill Date: 1994-01-17
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: 1995-11-09
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1994-01-17
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 1995-11-08
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-01-24
Spill Record Last Update: 1995-11-27
Spiller Name: Not reported
Spiller Company: REGENT OIL CO.
Spiller Address: 53 CHARLES STREET
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 148008
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/95 FINAL INSPECTION PERFORMED TRENCH IS OIL FREE SUMP PIT IS OIL FREE BASEMENT IS FREE OF PETROLEUM NO OIL STAIN ON SIDEWALK"
Remarks: "1K TANK UNDERGROUND POSSIBLE LEAK CLEAN UP CREW ENROUTE"

All Materials:
Site ID: 176106
Operable Unit ID: 994225
Operable Unit: 01
Material ID: 391197
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported

FRANKA INC. (Continued) **S104276153**

Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU321 **APARTMENT HOUSE** **NY LTANKS** **S106385339**
SSE **156-168 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1651 ft. **Site 2 of 3 in cluster AU**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Facility ID:	0312650
Site ID:	267104
Closed Date:	2004-04-22
Spill Number:	0312650
Spill Date:	2004-02-13
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-02-13
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-13
Spill Record Last Update:	2004-04-22
Spiller Name:	JIM DONELAN
Spiller Company:	PROTEST
Spiller Address:	PO BOX 1937
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 698-4100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217585
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 04/22/04 TANK PASSED A RETEST ON 3-22-04. NFA jbo"
Remarks:	"Failed tank test"

All TTF:

Facility ID:	0312650
Spill Number:	0312650
Spill Tank Test:	1528979
Site ID:	267104
Tank Number:	1
Tank Size:	10000
Material:	Not reported

APARTMENT HOUSE (Continued) **S106385339**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AU322 **FAILED TANK TEST** **NY LTANKS** **S114561821**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1651 ft. **Site 3 of 3 in cluster AU**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Facility ID:	1308221
Site ID:	488939
Closed Date:	Not reported
Spill Number:	1308221
Spill Date:	2013-11-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-11-12
Spill Record Last Update:	2013-11-22
Spiller Name:	WILLIE
Spiller Company:	FAILED TANK TEST
Spiller Address:	156 CENTRE AVE
Spiller County:	999
Spiller Contact:	WILLIE
Spiller Phone:	(914) 774-2508
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	"11/12/13: Residential tank test failure. No indication of a release at this time. Message sent to Elite requesting additional information on the owner, or their realtor. jod 11/12/13: Update received from Chris Lalak. This is not a residential tank. This is a 10K #4 Oil tank, PBS 3-600412. Wayne Schneider will follow up on retest. jod"
Remarks:	"Tank test failure"

FAILED TANK TEST (Continued) **S114561821**

All TTF:

Facility ID:	1308221
Spill Number:	1308221
Spill Tank Test:	2494704
Site ID:	488939
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	488939
Operable Unit ID:	1238546
Operable Unit:	01
Material ID:	2238468
Material Code:	9999
Material Name:	other - failed tank test
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ323 **DIPASQUALE PROPERTY** **NY LTANKS** **S111063882**
North **400 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1681 ft. **Site 5 of 5 in cluster AQ**

Relative: LTANKS:
Lower

Actual: Facility ID:	1103122
70 ft. Site ID:	450672
Closed Date:	2012-04-26
Spill Number:	1103122
Spill Date:	2011-06-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

DIPASQUALE PROPERTY (Continued) **S111063882**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-20
Spill Record Last Update:	2012-04-26
Spiller Name:	MR CHARLIE DIPASQUALE
Spiller Company:	NDR GROUP
Spiller Address:	400 NORTH AVE
Spiller County:	999
Spiller Contact:	MR DIPASQUALE
Spiller Phone:	(914) 633-7092
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	404310
DEC Memo:	"6/20/11: This spill initially reported as a residential TTF. Property is actually a commercial office building with apartments on the second floor. Previous Spill number for this site is 1102214 which was reported on May 27th. Owner informed US Tank Tech of the prior Phase I site investigation, but apparently did not inform them of the Phase II which found high levels of contamination. US Tank Tech reports they were hired to test the in-service 550 gallon heating oil tank, and perform a site investigation to locate a second, out-of-service tank. The 550 failed the vaccuum test, petroleum odors evident in the well point. US Tank Tech also reports they believe the second out-of-service tank may be located under the office building. Owner states the second tank is a 275 gallon heating oil, but that can not be confirmed at this time. US Tank Tech also reports there are at least two additional sets of fill and vent pipes, for other out-of-service or abandoned USTs. Tester also noted petroleum odors from the basement sump pit. jod 6/21/11: US Tank Tech reported that the owner says he hired Northeast Environmental to address these two spills issues. Message sent to Northeast asking for confirmation. jod 9/29/11: Northeast reports the owner has hired them to begin investigation and remediation. jod 10/21/11: The UST has been removed by Northeast and contaminated soil is evident. Remediation work is being scheduled. jod 4/26/2012: Closure report from Northeast Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"
Remarks:	"repair/retest pending"

All Materials:

Site ID:	450672
Operable Unit ID:	1200876
Operable Unit:	01
Material ID:	2197327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AS324
SW
1/4-1/2
0.320 mi.
1691 ft.

Relative:
Lower

Actual:
49 ft.

BAKERS PRIDE OVEN CO INC
30 PINE ST.
NEW ROCHELLE, NY 10801

Site 3 of 4 in cluster AS

Database(s): RCRA-LQG, NY SHWS, NY Spills, FINDS, ECHO, NJ MANIFEST, NY MANIFEST

EDR ID Number: 1004571492
EPA ID Number: NYD986925808

RCRA-LQG:

Date form received by agency:	06/27/2012
Facility name:	INDUSTRIAL OVERALL SERVICES FORMER
Facility address:	30 PINE ST NEW ROCHELLE, NY 10805
EPA ID:	NYD986925808
Mailing address:	PINE ST NEW ROCHELLE, NY 10805
Contact:	BURT DORFMAN
Contact address:	BARTELS AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	845-353-3500
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	BARTELS AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	845-353-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/01/2010
Owner/Op end date:	Not reported

Owner/operator name:	NYS DEPT ENVIRONMENTAL CONSERVATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 12/13/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 12/16/2008
Site name: BAKERS PRIDE OVEN
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: BAKERS PRIDE OVEN CO INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/12/1994
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/14/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SHWS:
Program: HW
Site Code: 355304
Classification: N
Region: 3
Acres: 3.75
HW Code: 360087
Record Add: 11/08/2005
Record Upd: 07/21/2009
Updated By: RXKEATIN
Site Description: The Baker?s Pride site is located at 30 Pine Street in the City of New Rochelle, Westchester County, NY. The surrounding area is urban with commercial and residential establishments mixed in between the commercial businesses. The Baker?s Pride site is an approximately 3.75 acre flat to severely sloping irregularly shaped parcel. The Baker?s Pride building occupies approximately 111,450 sf of building space and occupies the majority of the property. Baker?s Pride owns the Bakers Pride Oven Company Inc and is engaged in the production of restaurant/commercial grade ovens and broilers. The site is bordered

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

by Metro North railroad tracks to the west and northwest, a mix of commercial and residential properties to the northeast, east, and south. Interstate (I-95) is located to the west of the Metro North railroad tracks. In 2005, a Phase II Environmental Assessment report was completed by Enercon as part of closure proceedings for a 3,000 gallon fuel oil UST that was closed in place and a 10,000 gallon fuel oil UST that was removed. Monitoring wells installed as part of this assessment revealed the presence of PCE in groundwater at levels up to 1,430 ppb. (The State groundwater standard for PCE is 5 ppb.) Also, this report noted chemical storage for cutting oils, lubricants, solvents and paints. No products were indicated that contained PCE. In 2007 a follow up report was conducted which revealed PCE in groundwater at levels up to 1,700 ppb. The site was added as a potential inactive hazardous waste disposal site ("P site") in 2007. A State funded site characterization was initiated in 2008 to determine the source of the PCE groundwater plume. A total of 9 monitoring wells were installed in the fall of 2008. Groundwater contaminated with PCE showed higher levels of PCE in wells upgradient from the Baker?s Pride facility. The PCE concentrations were as high as 3,700 ppb in MW-13 which is located about 300 feet upgradient from the Baker?s Pride facility. This prompted the State to do a second round of groundwater sampling further upgradient of MW-13. Two additional wells (MW-24 and MW-25) were installed about 150 feet upgradient of MW-13 in the winter of 2009. MW-24 revealed PCE at 5,300 ppb. The second round of sampling further defined a groundwater plume with a source area upgradient from the Bakers Pride site. Since the site information for Baker?s Pride indicates that the plume of PCE is coming from an off-site source, the Baker?s Pride site (360087) will not be listed in the Registry of Inactive Hazardous Waste Disposal sites. A separate site was added to the Registry to address the source of the PCE plume (See site #360109.)

Env Problem: Based upon investigations to date, the primary contaminants of concern at the site include tetrachloroetylene (PCE) and its associated breakdown products. PCE was detected in upgradient groundwater as well as on-site and also in indoor air in residences upgradient of the site. PCE was detected on-site in groundwater from non-detect up to 3,200 parts per billion (ppb) at MW-1) above the respective groundwater standard of 5 ppb. Upgradient off-site levels of PCE were as high as 5,300 ppb. Indoor air was impacted in two residences with the highest level being 530 micrograms per cubic meter (ug/m3) at a property on Bartels Place. Since the highest levels of PCE were identified in the groundwater upgradient of the site this suggests an off-site source that is impacting the Baker?s Pride site. The source of this contamination is the Industrial Overall Service Corp. Class 2 site (#360109)

Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Facility ID:	9404759
Facility Type:	ER
Spill Number:	9404759
DER Facility ID:	122872
Site ID:	144128
DEC Region:	3
Closed Date:	2003-10-08
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	1994-07-07
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1994-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-11
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 10/17/03: Letter to Mark Fogarty, Baker's Pride from Danielle

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Jackson, dated 10/8/2003. Closure report by Env. Products & Services and sample results have been reviewed. While there is some contamination remaining, WCDOH does not see the contamination as a risk to human health. WCDOH recommends NFA at this time."

Remarks: "SOIL STOCKPILED BOB SPERONI WAS ON SITE FAXED TO TARRYTOWN & WCHD"

All Materials:

Site ID:	144128
Operable Unit ID:	1001834
Operable Unit:	01
Material ID:	381361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110002092949

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004571492
Registry ID:	110002092949
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002092949

NJ MANIFEST:

EPA Id:	NYD986925808
Mail Address:	30 PINE ST

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Mail City/State/Zip:	NEW ROCHELLE 10801
Facility Phone:	9145760200
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008921150JJK
EPA ID:	NYD986925808
Date Shipped:	7/2/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,815.00 gallons

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	008923039JJK
EPA ID:	NYD986925808
Date Shipped:	7/31/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	150.00 Pounds

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Manifest Number:	008923493JJK
EPA ID:	NYD986925808
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,800.00 Pounds

Manifest Number:	NJA4033255
EPA ID:	NYD986925808
Date Shipped:	04/02/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/02/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030425
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYD986925808
Facility Status:	Not reported
Location Address 1:	30 PINE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986925808
Mailing Name:	INDUSTIRAL OVERALL UNIFORM
Mailing Contact:	IRA NEVIN
Mailing Address 1:	30 PINE ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Mailing Phone: 5184029564

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2014
Trans1 Recv Date:	05/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012352197JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	D007
Waste Code 1_4:	D008
Waste Code 1_5:	D009
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
25 additional NY_MANIFEST: record(s) in the EDR Site Report.

AT325 **APT. BUILDING** **NY LTANKS** **S102241692**
South **47 MAPLE AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.323 mi.
1704 ft. **Site 3 of 3 in cluster AT**

Relative:
Lower

Actual:
87 ft.

LTANKS:

Facility ID:	9603128
Site ID:	178537
Closed Date:	1996-06-14
Spill Number:	9603128
Spill Date:	1996-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-05
Spill Record Last Update:	1996-09-04
Spiller Name:	A D VANDROFF
Spiller Company:	A D VANDROFF
Spiller Address:	47 MAPLE AVENUE
Spiller County:	001
Spiller Contact:	A D VANDROFF
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/14/96 SEE SPILL # 9603064"
Remarks:	"gross failure of tank."

SPILLS:

Facility ID:	9603064
Facility Type:	ER
Spill Number:	9603064
DER Facility ID:	248269
Site ID:	307417
DEC Region:	3
Closed Date:	1996-08-12
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1996-06-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-04
CID:	349

APT. BUILDING (Continued) **S102241692**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-06-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-04
Spill Record Last Update:	1996-10-21
Spiller Name:	OWNER - ARTHUR DANDROFF
Spiller Company:	Not reported
Spiller Address:	47 MAPLE AV
Spiller Company:	001
Contact Name:	OWNER - ARTHUR DANDROFF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/04/96 WCHD TO INSPECT 06/14/96 SEE SPILL # 9603128 08/12/96 CONTENTS GONE IN FOUR DAYS AFTER FILL UP TANK REMOVED LINES TESTED NO LEAKS FOUND FROM TESTS SMALL HOLES FOUND IN TANKS VERY MINIMAL CONTAMINATION "
Remarks:	"APARTMENT BLDG - SUPERINTENDENT MRS CHURCHILL 914-636-4142 - RECIEVED 900 GALLONS ON THURSDAY - NOW ITS IS EMPTY - CHECK OF AREA INCLUDING SEWERS NO ODOR - FD ON SCENE - WILL BE TESTING W/WATER - TEMP. TANK TO BE PUT IN"

All Materials:

Site ID:	307417
Operable Unit ID:	1030609
Operable Unit:	01
Material ID:	349302
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

326
ENE
1/4-1/2
0.323 mi.
1707 ft.

SPILL 0106072 / PBS 3-800919 **NY LTANKS** **S105135128**
370 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
60 ft.

LTANKS:

Facility ID:	0106072
Site ID:	133647
Closed Date:	2001-11-13
Spill Number:	0106072
Spill Date:	2001-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2014-08-15
Spiller Name:	STEVEN WOODS
Spiller Company:	Monroe College
Spiller Address:	370 MAIN ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114844
DEC Memo:	"09/07/2001 PROPERTY FOR SALE. TANK TESTED BY POTENTIAL BUYER. SELLER TO REMOVE OR RETEST. 11/13/2001 TANK PASSED A RETEST AFTER REFIT. NO FURTHER ACTION. 8/15/14: Hard copy file pulled for FOIL. File scanned to PDF, will wiil entered into DecDocs. Paper file discarded. NOTE: WCDoH PBS records indicate this UST was Closed - in place and the site listed as Unregulated 7/30/2002. jod"
Remarks:	"will fill tank with sand and abandoned it"

All TTF:

Facility ID:	0106072
Spill Number:	0106072
Spill Tank Test:	2495803
Site ID:	133647
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	04
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	133647
Operable Unit ID:	844476
Operable Unit:	01
Material ID:	530955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AW327 **COMMERCIAL BUILDING** **NY LTANKS** **S104276178**
WSW **88-90 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 1 of 2 in cluster AW**

Relative:
Lower

Actual:
91 ft.

LTANKS:

Facility ID:	9411598
Site ID:	113133
Closed Date:	2010-04-28
Spill Number:	9411598
Spill Date:	1994-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	98741
DEC Memo:	"4/28/10 16 year old TTF NFA JO'M"
Remarks:	"TANK TEST FAILURE PETRO-TITE II VISUAL"

All TTF:

Facility ID:	9411598
Spill Number:	9411598
Spill Tank Test:	1543402
Site ID:	113133
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported

COMMERCIAL BUILDING (Continued) **S104276178**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	113133
Operable Unit ID:	1005335
Operable Unit:	01
Material ID:	373942
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AW328 **BUSINESS** **NY LTANKS** **S101341432**
WSW **88 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 2 of 2 in cluster AW**

Relative: **Lower**

Actual: **91 ft.**

LTANKS:

Facility ID:	9411669
Site ID:	172950
Closed Date:	2010-04-28
Spill Number:	9411669
Spill Date:	1994-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	MR. OGMAN

BUSINESS (Continued) **S101341432**

Spiller Address: 88 GROVE AVE.
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 145542
DEC Memo: "4/28/10 16 year old TTF No further info NFA JO'M "
Remarks: "WILL EXPLORE IT NEXT"

All TTF:
Facility ID: 9411669
Spill Number: 9411669
Spill Tank Test: 1543408
Site ID: 172950
Tank Number: Not reported
Tank Size: 0
Material: 0066A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 172950
Operable Unit ID: 1005375
Operable Unit: 01
Material ID: 374006
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

---

329 **ANON** **NY LTANKS** **S106124350**
WNW **108 VAN GUILDER AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.335 mi.
1769 ft.

Relative:
Lower

Actual:
77 ft.

LTANKS:
Facility ID: 0308565
Site ID: 214235
Closed Date: 2005-02-12
Spill Number: 0308565
Spill Date: 2003-11-13
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling

ANON (Continued) **S106124350**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-11-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-13
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RICHARD KLING
Spiller Phone:	(914) 636-0076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177496
DEC Memo:	"03/24/04 TANK IS IN A CRAWL SPACE UNDER THE FOUNDATION AND CANNOT BE REMOVED. ROYAL ENVIRONMENTAL INSPECTED TANK AND FOUND NO EVIDENCE OF CONTAMINATION. ROYAL INSTALLED A NEW 275 AST BUT HAS NOT YET PUT THAT TANK IN SERVICE, AWAITING INSPECTION FROM NEW ROCHELLE FIRE DEPT. ONCE AST IS IN SERVICE, ROYAL IS TO CUT AND CLEAN 550 UST AND OBTAIN A SOIL SAMPLE FROM BENEATH TANK. SAMPLE RESULTS TO BE FORWARDED TO DEC. ADDITIONAL SPILL NUMBERS CALLED IN: 03-13745 AND 03-14031. jbo"
Remarks:	"uncover / repair / retest"

All TTF:

Facility ID:	0308565
Spill Number:	0308565
Spill Tank Test:	1528806
Site ID:	214235
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	214235
Operable Unit ID:	874811
Operable Unit:	01

ANON (Continued) **S106124350**

Material ID:	502049
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0313745
Facility Type:	ER
Spill Number:	0313745
DER Facility ID:	177496
Site ID:	214236
DEC Region:	3
Closed Date:	2004-03-24
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	6010
Spill Date:	2004-03-16
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2005-02-12
Spiller Name:	DR RICHARD KLEIN
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	DR RICHARD KLEIN
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo"
Remarks:	"CALLER STATES THAT THERE IS A VERY STRONG ODOR AT THE DOCTOR'S OFFICE AND SHE CAN SMELL IT AT HER HOME. SOMETIMES ODOR IS VERY OVERWELMING: A LARGE CONTAINER IS IN THE BACK YARD OF DOCTOR'S OFFICE: SHE JUST WANTED SOMEONE TO CHECK OUT: *****UPDATE***** SHE CALLED BACK AND SAID THAT SOMEONE TOLD HER THAT A COMPANY CAME IN A CHECKED IT OUT- ROYAL IN PELHAM NY*"

All Materials:

Site ID:	214236
Operable Unit ID:	879034
Operable Unit:	01
Material ID:	495337
Material Code:	0001A

ANON (Continued) **S106124350**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0314031
Facility Type:	ER
Spill Number:	0314031
DER Facility ID:	177496
Site ID:	214237
DEC Region:	3
Closed Date:	2004-03-24
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	6010
Spill Date:	2004-03-24
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-24
CID:	407
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-24
Spill Record Last Update:	2005-02-12
Spiller Name:	RICHARD KLING MD
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	RICHARD KLING MD
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo 03/30/04 SITE INSPECTED BY STEFAN GOREAU OF WCHD. jbo"
Remarks:	"unknown if spill, caller refused to give name, detected odor of gas/oil from neighbors building, renovation ongoing at building, caller believed odor was related to work."

All Materials:

Site ID:	214237
Operable Unit ID:	880985
Operable Unit:	01
Material ID:	495617
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00

ANON (Continued) **S106124350**

Oxygenate: Not reported

AS330 **BELIVE HOME** **NY LTANKS** **S106869214**
SW **20 PINE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.337 mi.
1779 ft. **Site 4 of 4 in cluster AS**

Relative: **Lower**

Actual: **47 ft.**

LTANKS:

Facility ID:	0500819
Site ID:	343902
Closed Date:	2005-05-22
Spill Number:	0500819
Spill Date:	2005-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2005-05-22
Spiller Name:	JOHN BELIVE
Spiller Company:	BELIVE HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOHN BELIVE
Spiller Phone:	(914) 253-8449
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"05/22/05 PREVIOUSLY REPORTED TTF IS 04-13182. NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 34.56 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 gallon , found holes and contaminated soil:"

All Materials:

Site ID:	343902
Operable Unit ID:	1102568
Operable Unit:	01
Material ID:	582785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

BELIVE HOME (Continued) **S106869214**

Units:	G
Recovered:	.00
Oxygenate:	Not reported
Facility ID:	0413182
Site ID:	339043
Closed Date:	2005-05-22
Spill Number:	0413182
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-22
Spiller Name:	JOE PONSERELLA
Spiller Company:	PONSERELLA HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOE PONSERELLA
Spiller Phone:	(914) 760-6684
Spiller Extention:	CELL
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"5/22/05 See spill 05-00819. NFA this number. jod"
Remarks:	""

All TTF:

Facility ID:	0413182
Spill Number:	0413182
Spill Tank Test:	1548700
Site ID:	339043
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

BELIVE HOME (Continued) **S106869214**

All Materials:

Site ID:	339043
Operable Unit ID:	1100961
Operable Unit:	01
Material ID:	581111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

331
NE
1/4-1/2
0.340 mi.
1796 ft.

CON EDISON-CEDAR ST WORKS-NEWROCH'LE MGP **EDR MGP** **1008407973**
ONE RAMADA PLAZA **N/A**
NEW ROCHELLE, NY 10801

Relative:
Lower

Actual:
50 ft.

Manufactured Gas Plants:
No additional information available

332
ESE
1/4-1/2
0.341 mi.
1799 ft.

CHURCH OF LATTER DAY SAIN **NY LTANKS** **S106471932**
111 NORTH AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Facility ID:	0403126
Site ID:	266466
Closed Date:	2004-09-21
Spill Number:	0403126
Spill Date:	2004-06-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-06-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22
Spill Record Last Update:	2004-09-21

CHURCH OF LATTER DAY SAIN (Continued) **S106471932**

Spiller Name:	MATT SCHIEFERSTEIN
Spiller Company:	CHURCH OF LATTER DAY SAIN
Spiller Address:	111 NORTH AVE
Spiller County:	001
Spiller Contact:	MATT SCHIEFERSTEIN
Spiller Phone:	(631) 351-3555
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217081
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/23/04 APPROXIMATELY 200 TONS OF CONTAMINATED SOIL REMOVED. CLOSURE REPORT TO FOLLOW. jbo 09/21/04 ANSON ENVIRONMENTAL DISPOSED OF LUST AND 168.02 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"WHILE DIGGING A FOUNDATION FOUND A TANK: CONTAMINATED SOIL ALSO: "

All Materials:

Site ID:	266466
Operable Unit ID:	885085
Operable Unit:	01
Material ID:	490726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

333
ESE
1/4-1/2
0.345 mi.
1823 ft.

APARTMENT BUILDING **NY LTANKS** **S110611357**
67-70 LOCUST AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Facility ID:	1008207
Site ID:	441682
Closed Date:	2011-03-10
Spill Number:	1008207
Spill Date:	2010-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

APARTMENT BUILDING (Continued) **S110611357**

Remediation Phase:	0
Date Entered In Computer:	2010-11-04
Spill Record Last Update:	2011-03-10
Spiller Name:	ABRAHAM WATHCELL
Spiller Company:	UNKNOWN
Spiller Address:	67- 70 LOCUST AVE
Spiller County:	999
Spiller Contact:	ABRAHAM WATHCELL
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396710
DEC Memo:	"Left message for callback. DT 11/4/10 11/5/10: Call back from Abraham Wathcell of NY Tank Testing to dispatch desk. This was a test failure of an 8K heating oil tank at a co-op. PBS #3-413925 will handled by WCDOH. Mr Wathcell stated he had discussed the results with the management compny and was recommending removal of the tank rather than retest. jod 3/10/11 As per WCDOH eplaced fill pipe, manway gasket and repaired gauge. Passed retest on 2/14/11. NFA JO'M "
Remarks:	Not reported ""

All TTF:

Facility ID:	1008207
Spill Number:	1008207
Spill Tank Test:	2489743
Site ID:	441682
Tank Number:	1
Tank Size:	8000
Material:	0003
EPA UST:	False
UST:	True
Cause:	00
Source:	99
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	441682
Operable Unit ID:	1192229
Operable Unit:	01
Material ID:	2187465
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AV334
SSW
1/4-1/2
0.348 mi.
1835 ft.

SPILL NUMBER 9908602
HUGUENOT ST & SOUTH PLAZA
NEW ROCHELLE, NY

Site 2 of 2 in cluster AV

NY LTANKS **S104620556**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Facility ID:	9908602
Site ID:	283271
Closed Date:	2000-09-14
Spill Number:	9908602
Spill Date:	1999-10-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1999-10-15
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-10-15
Spill Record Last Update:	2000-09-26
Spiller Name:	CITY OF NEW ROCHELLE
Spiller Company:	Not reported
Spiller Address:	HUGUENOT ST
Spiller County:	001
Spiller Contact:	CITY OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229755
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 10/15/99 DELUXE TAXICAB SITE; TANKS HAD BEEN REMOVED BUT CONTAMINATED SOIL; SOIL BEING REMOVED--WILL SUBMIT REPORT. 12/09/99 LETTER SENT TO N. RECCHIA; MUST BETTER DEFINE THE EXTENT OF CONTAMINATION IN THE OVERBURDEN SOIL & GROUNDWATER 05/18/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; ADDITIONAL INVESTIGATION IS REQUIRED AT THIS SITE 09/14/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; BASED ON RESULTS REPORTED BY THE ENERGY & ENVIRONMENTAL ANLAYSISTS, INC. IN AUGUST 2000, THIS SPILL IS CLOSED. "
Remarks:	"VACANT LOT AND DURING EXCAVATION - CONTAMINATED SOIL FOUND"

All Materials:

Site ID:	283271
Operable Unit ID:	1087287
Operable Unit:	01
Material ID:	297711
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

SPILL NUMBER 9908602 (Continued) **S104620556**

Units: G
Recovered: .00
Oxygenate: Not reported

335
SW
1/4-1/2
0.357 mi.
1885 ft.

BUSINESS COMPLEX **NY LTANKS** **S104516367**
55 WEBSTER AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
54 ft.

LTANKS:

Facility ID:	9912136
Site ID:	86196
Closed Date:	2000-05-11
Spill Number:	9912136
Spill Date:	2000-01-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2000-01-20
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2004-11-23
Spiller Name:	MR LIBERETT
Spiller Company:	BUSINESS COMPLEX
Spiller Address:	55 WEBSTER AVE
Spiller County:	001
Spiller Contact:	MR LIBERETT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79113
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/09/2000 ACCORDING TO MR. BOB ALERES PHASE 11 REPORT COMPLETED. WILL SUBMIT COPY TO T. GHIOSAY. 05/11/00 - Spill closure letter sent by J. O'Mara to: DL Rothberg & Associates PC 1350 Broadway Suite 1711 NY NY 10018 Attention Debra Rothberg, Esq"
Remarks:	"THEY REMOVED A 3,000 GALLON TANK AND PUT IN A NEW 1,000 GALLON TANK THEY SUSPECT THE 3,000 GALLON HAD LEAKED UNKNOWN MATERIAL INTO THE GROUND.THEY GOT THE LAB RESULTS BACK YESTERDAY.THEY SUSPECT IT MAY BE HEATING OIL BUT ARE NOT SURE."

All Materials:

Site ID:	86196
Operable Unit ID:	1086666
Operable Unit:	01

BUSINESS COMPLEX (Continued) **S104516367**

Material ID:	294030
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX336 **APARTMENT BLDG** **NY LTANKS** **S104515070**
North **1 THE BOULEVARD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.360 mi.
1902 ft. **Site 1 of 2 in cluster AX**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Facility ID:	9809315
Site ID:	303319
Closed Date:	1999-10-14
Spill Number:	9809315
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-10-26
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	1999-11-22
Spiller Name:	ELJAK REALTY
Spiller Company:	APT BLDG
Spiller Address:	1 THE BLVD
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	245085
DEC Memo:	""
Remarks:	"EXCAVATE PIPING AND RETEST"

All TTF:

Facility ID:	9809315
Spill Number:	9809315
Spill Tank Test:	1546451
Site ID:	303319

APARTMENT BLDG (Continued) **S104515070**

Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	303319
Operable Unit ID:	1070412
Operable Unit:	01
Material ID:	316775
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX337 **PRIVATE DWELLING** **NY LTANKS** **S108765819**
North **19 ROCHELLE PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.364 mi.
1920 ft. **Site 2 of 2 in cluster AX**

Relative: **Lower**

Actual: **68 ft.**

LTANKS:

Facility ID:	0706958
Site ID:	387568
Closed Date:	2008-02-01
Spill Number:	0706958
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0

PRIVATE DWELLING (Continued) **S108765819**

Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2008-02-01
Spiller Name:	ROLAND ANDRALOISKI
Spiller Company:	Not reported
Spiller Address:	19 ROCHELLE PLACE
Spiller County:	001
Spiller Contact:	ROLAND ANDRALOISKI
Spiller Phone:	(914) 774-7362
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	336995
DEC Memo:	"To uncover and retest. 12/05/08 Northeast Environmental reported that the tank was excavated and removed. Noe cotaminated soil was observed in the tank grave. TAGM soil sample results were below DEC guidance values. NFA. TG "
Remarks:	""

All TTF:

Facility ID:	0706958
Spill Number:	0706958
Spill Tank Test:	1764128
Site ID:	387568
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387568
Operable Unit ID:	1144768
Operable Unit:	01
Material ID:	2135078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY338 **RESIDENCE** **NY LTANKS** **S102448122**
NE **14 REVERE RD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.365 mi.
1925 ft. **Site 1 of 2 in cluster AY**

Relative: **Lower**
Actual: **34 ft.**

LTANKS:

Facility ID:	9611129
Site ID:	69656
Closed Date:	1996-12-11
Spill Number:	9611129
Spill Date:	1996-12-09
Spill Cause:	Tank Failure
Spill Source:	Tank Truck
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-09
CID:	233
Water Affected:	CARPENTERS POND
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-09
Spill Record Last Update:	1997-01-02
Spiller Name:	Not reported
Spiller Company:	FRED M. SCHILDWACHLER &
Spiller Address:	SONS
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	66210
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/10/96 WCHD AT SITE."
Remarks:	"DRIVER OVERFILLED TANK OIL INTO BROOK BROOK RUNS TO A POND (CARPENTERS POND) FD ON SCENE CELL # FOR CHIEF 914-263-2302 WESTCHESTER FIRE CONTROL 914-593-5905"

All Materials:

Site ID:	69656
Operable Unit ID:	1042681
Operable Unit:	01
Material ID:	343331
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

339
NW
1/4-1/2
0.366 mi.
1931 ft.

NEW ROCHELLE RADIOLOGY
150 LOCKWOOD AV
NEW ROCHELLE, NY

NY LTANKS **S105997625**
NY Spills **N/A**

Relative:
Lower

Actual:
85 ft.

LTANKS:

Facility ID:	0209497
Site ID:	221207
Closed Date:	2005-03-18
Spill Number:	0209497
Spill Date:	2002-12-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-12-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2005-04-05
Spiller Name:	RICK TROY
Spiller Company:	RICK TROY
Spiller Address:	150 LOCKWOOD AV
Spiller County:	001
Spiller Contact:	RICK TROY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	182943
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 12/16/02: WCDOH ON SITE. 140 TONS SOIL REMOVED. CLOSURE REPORT PENDING. 04/08/03: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 3/26/2003. Closure report from GFE has been reviewed. Groundwater samples must be collected. Result submitted to WCHD by May 12, 2003. PBS #3-601067 & 3-601068. 08/13/02: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 7/21/03. Further remediation and quarterly sampling is required. Results of sampling are to be submitted to WCDOH quarterly. First report due by 9/01/2003. 5/25/04: Letter to Lockwood Realty, LLC, from Christopher Lalak, WCDOH, dated 25May2004. Two rounds of sampling have been received, third is overdue. Third round must be received by 25Jun2004. 11/22/04: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 17Nov2004. Based on groundwater sampling results, closure report and inspections, sampling must continue for the next year on a quarterly basis. After sampling, site will be reviewed. Next results due 28Feb2005. 4/4/05: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 18Mar2005. Spill has been satisfactorily remediated. WCDOH requires NFA."
Remarks:	"CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL"

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

All Materials:

Site ID:	221207
Operable Unit ID:	860802
Operable Unit:	01
Material ID:	512920
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0209877
Facility Type:	ER
Spill Number:	0209877
DER Facility ID:	182943
Site ID:	221208
DEC Region:	3
Closed Date:	2003-03-28
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	2002-12-27
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-30
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"CALLER WENT TO HAVE A MAMMOGRAM DONE & SHE STAATED THE ENTIRE BLDG SMELLED LIKE FUEL OIL - UNK IF IT HAD TO DO WITH THE CONSTRUCTION THAT WAS GOING ON IN THE PARKING LOT OR NOT"

All Materials:

Site ID:	221208
Operable Unit ID:	861114
Operable Unit:	01
Material ID:	513296

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

340
SE
1/4-1/2
0.368 mi.
1942 ft.

NICK MAZZA RESIDENCE
20 DAVIS AVE
NEW ROCHELLE, NY

NY LTANKS **S104621408**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Facility ID:	0000532
Site ID:	211468
Closed Date:	2000-04-20
Spill Number:	0000532
Spill Date:	2000-04-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-13
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-13
Spill Record Last Update:	2000-05-03
Spiller Name:	N/A
Spiller Company:	NICK MAZZA
Spiller Address:	20 DAVIS AVE
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/14/2000 ENVIROSTAR REPAIRED; U.S. TANK TO RETEST ON 4/17/2000. 04/20/2000 U.S. TANK TECH RETESTED TANK AFTER ENVIROSTAR REPLACED PIPING. TANK PASSED RETEST. NFA"
Remarks:	"tank failed the test. he did not have the homeowners name or phone number "

All TTF:

Facility ID:	0000532

NICK MAZZA RESIDENCE (Continued) **S104621408**

Spill Number:	0000532
Spill Tank Test:	1525485
Site ID:	211468
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	18
Test Method 2:	Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	211468
Operable Unit ID:	822249
Operable Unit:	01
Material ID:	288777
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AZ341 **SHERIDEN PLAZA** **NY LTANKS** **S100138278**
NE **1 SHERIDEN PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.371 mi.
1957 ft. **Site 1 of 2 in cluster AZ**

Relative: **Lower**
Actual: **36 ft.**

LTANKS:

Facility ID:	8909204
Site ID:	80178
Closed Date:	1990-03-07
Spill Number:	8909204
Spill Date:	1989-12-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-12-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

SHERIDEN PLAZA (Continued) **S100138278**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-12-21
Spill Record Last Update:	1992-02-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74339
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATION FOUND DURING TANK REMOVAL SOIL TO BE STOCKPILED ON PLASTIC DEC TO INSPECT TANK HOLE TYREE VACING OUT HOLE"

All Materials:

Site ID:	80178
Operable Unit ID:	934143
Operable Unit:	01
Material ID:	442378
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BA342 **JASON PARTNERS LTD** **NY LTANKS** **S105998096**
SSW **675 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.373 mi.
1967 ft. **Site 1 of 3 in cluster BA**

Relative: **Lower**
Actual: **65 ft.**

LTANKS:

Facility ID:	0211105
Site ID:	86967
Closed Date:	2003-03-26
Spill Number:	0211105
Spill Date:	2003-02-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-02-05
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

JASON PARTNERS LTD (Continued) **S105998096**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-05
Spill Record Last Update:	2003-04-09
Spiller Name:	JAMIE MIZRAHI
Spiller Company:	JASON PARTNERS LTD
Spiller Address:	675 MAIN ST
Spiller County:	001
Spiller Contact:	JAMIE MIZRAHI
Spiller Phone:	(914) 682-6664
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79721
DEC Memo:	""
Remarks:	"CALLERS COMPANY HIRED TO REMOVE A 3000 GAL INGROUND TANK AT THE ABOVE LOCATION, AFTER TANK WAS REMOVED, HOLE WERE FOUND IN TANK AND CONTAMINATED SOIL WAS DISCOVERED - DIRT IS BEING REMOVED AND STORED ON PLASTIC"

All Materials:

Site ID:	86967
Operable Unit ID:	862143
Operable Unit:	01
Material ID:	514466
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BB343 **ABANDONED GAS STATION** **NY LTANKS** **S102660200**
West **197 WEBSTER AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.377 mi.
1989 ft. **Site 1 of 2 in cluster BB**

Relative: **Lower**
Actual: **79 ft.**

LTANKS:

Facility ID:	9707099
Site ID:	231589
Closed Date:	2001-07-19
Spill Number:	9707099
Spill Date:	1997-09-15
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-09-15
CID:	211
Water Affected:	Not reported

ABANDONED GAS STATION (Continued) **S102660200**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-09-15
Spill Record Last Update:	2001-08-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	EDWARD SELLIAN
Spiller Phone:	(561) 221-1754
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	190875
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/19/2001 LETTER SENT TO IRA CONKLIN & SONS BY T. GHIOSAY; BASED ON SUBSURFACE INVESTIGATION REPORT, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL LISTED AS CLOSED."
Remarks:	"CALLER REMOVING TANKS AND FOUND SOIL CONTAMINATION"

All Materials:

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AZ344 **POST MARINE SUPPLY** **NY LTANKS** **S104193116**
NE **65 RIVER ST** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.380 mi.
2004 ft. **Site 2 of 2 in cluster AZ**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Facility ID:	8707334
Site ID:	286036
Closed Date:	1988-02-18
Spill Number:	8707334
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-25
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-01
Spill Record Last Update:	1988-03-11
Spiller Name:	HUGH GEORGE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : WILL RETEST. / / : TANKS REMOVED. LR 02-18-88 N F A. "
Remarks:	"TTTF-4K TANK;-0.7584 GPH,4K TANK;-0.3312 GPH"

All TTF:

Facility ID:	8707334
Spill Number:	8707334
Spill Tank Test:	1532438
Site ID:	286036
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

POST MARINE SUPPLY (Continued) **S104193116**

Last Modified Date: Not reported

All Materials:

Site ID:	286036
Operable Unit ID:	911503
Operable Unit:	01
Material ID:	466293
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	8708530
Site ID:	286037
Closed Date:	1988-02-18
Spill Number:	8708530
Spill Date:	1988-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	HUGH GEORGE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANKS REMOVED 02-18-88 LR N F A. "
Remarks:	"5K (RETEST) 1.34GPH TO PUMP & PULL TANK"

All TTF:

Facility ID:	8708530
Spill Number:	8708530
Spill Tank Test:	1532919

POST MARINE SUPPLY (Continued) **S104193116**

Site ID:	286037
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286037
Operable Unit ID:	913194
Operable Unit:	01
Material ID:	570954
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9904805
Facility Type:	ER
Spill Number:	9904805
DER Facility ID:	118852
Site ID:	139056
DEC Region:	3
Closed Date:	1999-07-22
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-07-22
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1999-07-22
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-22

POST MARINE SUPPLY (Continued) **S104193116**

Spill Record Last Update:	1999-09-10
Spiller Name:	NASER JABER
Spiller Company:	POST MARINE SUPPLY
Spiller Address:	65 RIVER ST
Spiller Company:	001
Contact Name:	NASER JABER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA "
Remarks:	"CALLER STATES THAT HE WITTNESSED SUBJ DUMPING GAS INTO A STORM DRAIN. JOHN O'MARA (REGION 3 SPILLS) NOTIFIED AND ALSO ENCON POLICE"

All Materials:

Site ID:	139056
Operable Unit ID:	1079250
Operable Unit:	01
Material ID:	301132
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9908179
Facility Type:	ER
Spill Number:	9908179
DER Facility ID:	118852
Site ID:	139057
DEC Region:	3
Closed Date:	1999-10-18
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1999-10-05
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-05
Spill Record Last Update:	1999-11-04
Spiller Name:	MICHAEL GRAVANESE
Spiller Company:	POST MARINE SUPLLY
Spiller Address:	65 RIVER SR
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

POST MARINE SUPPLY (Continued) **S104193116**

Remarks: O'DEE 10/18/99 DEC INSPECTED SITE. ONE LEAKY BATTERY FOUND NEXT TO DIESEL TANKS. BATTERIES TO BE REMOVED LATER TODAY. NFA"
"CALLER IS AN EX EMPLOYEE REPORTING BATTERIES BEING STORED NEXT TO GASOLINE TANKS AND BELIEVES THEY MIGHT BE LEAKING BATTERY ACID."

All Materials:

Site ID:	139057
Operable Unit ID:	1082477
Operable Unit:	01
Material ID:	300856
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC345 **GETTY 58114** **NY LTANKS S107657288**
ENE **340 MAIN STREET** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.380 mi.
2008 ft. **Site 1 of 6 in cluster BC**

Relative: **Lower**
Actual: **38 ft.**

LTANKS:

Facility ID:	0913713
Site ID:	426673
Closed Date:	2010-04-29
Spill Number:	0913713
Spill Date:	2010-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2010-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-26
Spill Record Last Update:	2018-01-24
Spiller Name:	ROBERT O'KEEFE
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TOM ANDERSON
Spiller Phone:	(845) 216-8064
Spiller Extention:	Not reported
DEC Region:	3

GETTY 58114 (Continued) **S107657288**

DER Facility ID: 310476
DEC Memo: "3/26/10 Tyree to go there on Mon. 3/29 to do repairs. dw 4/29/10 Getty 340 Main St New Rochelle line test failed do to faulty check valve. Tyree replaced check valve. Passed retest on 4/12/10 NFA JO'M 10-23-17 SEND OUT 30 day tank letter- RDB 10-25-17 call from Raul Naube @ 5168027171; retuned call; explained the current situation. offered to remove tanks for him. he is waiting for a court case, I advised him that he is in violation of the NYS CRRR pertaining to tanks, he has other sites on Long Island. Never in Westchester, I welcomed him to region; he will move forward with the permits and intends to remove the tanks- RDB 12-12-17 Rahul@lotusmgmt.com 340 Main Street Realty Inc. 25 Newbridge Road, Suite 312, Hicksville, NY 11801 _RDB 12-12-17 called and left another message RDB 12-18-17 email sent, I called your office last week and left a message. The tanks at your facility need to be removed. Please contact me today and discuss the schedule for the tank s removal or this case will be referred to Region 3, Regional Attorney for enforcement. RDB 1-3-18 email from Cider, The owner of the above referenced property has received the permit for removal of the USTs (NR BD/NR FM).We are only waiting on the contractors schedule.In the meantime, we wanted to confirm that there is nothing else required by your department?As soon as the schedule is confirmed, we will let you know. RDB 1-4-18 response, Thanks for the email and call. Who is the contractor for the tank removal? Do you have a guesstimate for the removal date? As I have explained to Rahul, this site is progressing towards enforcement and penalties. RDB 1-4-18, The contractor for the tank removals will be Felik s and Sons. Rahul is pushing them to get out there as soon as possible. My guestimate would be about two/three weeks to begin. As soon as we get the schedule from the contractor/Rahul, I will let you know. RDB Tank removal began. New Spill called in 17-09698 This spill closed- RDB "
Remarks: "in line problem - Tyree notified - cleanup and repair pending"

All Materials:
Site ID: 426673
Operable Unit ID: 1182349
Operable Unit: 01
Material ID: 2176532
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Facility ID: 0513793
Facility Type: ER
Spill Number: 0513793
DER Facility ID: 310476
Site ID: 360340
DEC Region: 3
Closed Date: 2006-03-02
Spill Cause: Housekeeping

GETTY 58114 (Continued) **S107657288**

Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-01
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2006-03-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-01
Spill Record Last Update:	2006-03-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"Some staining - Cleaned up NFA"
Remarks:	"LESS THAN A GAL OF BOTH HAS BEEN CLEANED UP."

All Materials:

Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108025
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108026
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	0600016
Facility Type:	ER
Spill Number:	0600016
DER Facility ID:	310476

GETTY 58114 (Continued) **S107657288**

Site ID:	361935
DEC Region:	3
Closed Date:	2006-04-01
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-01
CID:	41
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-01
Spill Record Last Update:	2006-04-04
Spiller Name:	Not reported
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"04/04/06: closed NFA"
Remarks:	"LESS THAN ONE GALLON OF EACH - ON ALPHALT - CLEANED UP"

All Materials:

Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01
Material ID:	2109530
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01
Material ID:	2109529
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

GETTY 58114 (Continued) **S107657288**

Facility ID:	0606253
Facility Type:	ER
Spill Number:	0606253
DER Facility ID:	310476
Site ID:	369567
DEC Region:	3
Closed Date:	2006-09-03
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-08-30
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-30
CID:	77
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-31
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"1 qt of waste oil spilled onto asphalt, speedy dry applied."

All Materials:

Site ID:	369567
Operable Unit ID:	1127402
Operable Unit:	01
Material ID:	2117000
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0606306
Facility Type:	ER
Spill Number:	0606306
DER Facility ID:	310476
Site ID:	369636
DEC Region:	3
Closed Date:	2006-09-03
Spill Cause:	Housekeeping
Spill Class:	C4

GETTY 58114 (Continued) **S107657288**

SWIS:	6010
Spill Date:	2006-09-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-01
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"LESS THAN A GAL OF BOTH ABND THEY HAVE BEEN CLEANED UP."

All Materials:

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117068
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117069
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	0603586
Facility Type:	ER
Spill Number:	0603586
DER Facility ID:	310476
Site ID:	366335

GETTY 58114 (Continued) **S107657288**

DEC Region:	3
Closed Date:	2006-07-03
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-06-30
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2006-06-30
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-30
Spill Record Last Update:	2006-07-11
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"COMBINED TOTAL OF LESS THAN A GAL. HAS BEEN CLEANED UP."

All Materials:

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113775
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113776
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	0602340

GETTY 58114 (Continued) **S107657288**

Facility Type:	ER
Spill Number:	0602340
DER Facility ID:	310476
Site ID:	364789
DEC Region:	3
Closed Date:	2006-06-07
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-06-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-06-01
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-01
Spill Record Last Update:	2006-06-07
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"SPEEDI DRI DOWN STAINING ONLY"

All Materials:

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112286
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

GETTY 58114 (Continued) **S107657288**

Oxygenate:	Not reported
Facility ID:	0601041
Facility Type:	ER
Spill Number:	0601041
DER Facility ID:	310476
Site ID:	363188
DEC Region:	3
Closed Date:	2006-04-27
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-27
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2006-04-27
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-27
Spill Record Last Update:	2006-05-02
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"5/2/06: Staining - cleaned up NFA"
Remarks:	"speedi dri applied and cleaned up"

All Materials:

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110750
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110748
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

GETTY 58114 (Continued) **S107657288**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY346 **SUNOCO** **NY LTANKS** **S102233475**
ENE **71 HUGUENOT ST** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.382 mi.
2019 ft. **Site 2 of 2 in cluster AY**

Relative: LTANKS:
Lower

Actual: Facility ID:	9514850
32 ft. Site ID:	255332
Closed Date:	1996-07-26
Spill Number:	9514850
Spill Date:	1996-02-20
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-20
Spill Record Last Update:	1996-09-05
Spiller Name:	RUSSELL HAMMOND
Spiller Company:	SUNOCO / A-PLUS
Spiller Address:	71 HUGUENOT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

SUNOCO (Continued) **S102233475**

DER Facility ID: 209140
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/26/96 EPS SUBMITTED G.W. INVESTIAGATION WHICH INDICATES THAT SUNOCO IS THE SOURCE OF G.W. CONTAM. ON 15 RIVER ST. "
Remarks: "soil boring for assessment for station upgrade - head space reading indicates potential of petroleum release"

All Materials:
Site ID: 255332
Operable Unit ID: 1025945
Operable Unit: 01
Material ID: 354972
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 9610201
Facility Type: ER
Spill Number: 9610201
DER Facility ID: 201279
Site ID: 245037
DEC Region: 3
Closed Date: 2005-01-20
Spill Cause: Unknown
Spill Class: B3
SWIS: 6010
Spill Date: 1996-02-28
Investigator: jghardy
Referred To: Not reported
Reported to Dept: 1996-11-15
CID: 366
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-11-15
Spill Record Last Update: 2005-01-21
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: RUSSELL HAMMOND
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 11/15/96 PETROLEUM FOUND DURING WELL SAMPLING; 09/22/97 LETTER SENT; REMEDIATION IS REQUIRED AT THIS SITE; 01/02/98 LETTER SENT;

SUNOCO (Continued) **S102233475**

REMEDIATION PROPOSAL IS APPROVED; WORK MUST START WITHIN THIRTY DAYS; 12/30/99 LETTER SENT TO SUN COMPANY; PROPOSAL TO INSTALL HI-VAC SYSTEM AT THIS SITE IS APPROVED & REQUIRED 1/20/05 nfa letter has been sent do to low and declining groundwater contamination--close 05/18/00 LETTER SENT TO MATRIX ENV. BY J. HARDY; REMEDIAL ACTION PLAN OF 1/12/00 IS APPROVED AND REQUIRED 04/19/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; YOU ARE AUTHOR IZED TO OPERATE REMEDIAL SYSTEMS FOR 90 DAYS WHILE DISCHARGE PERMIT APPLICATIONS ARE BEING PROCESSED 06/22/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; AUTHORIZED BY WCDOH TO OPERATE SYSTEM FOR 90 DAYS WHILE PERMITTING IS IN PROGRESS 05/09/03: Letter sent to Matrix Env. Tech. by J. Hardy; Report submitted dated March 20, 2003. Next report due after completion of one year monitoring period. 2/12/04: Letter sent to Matrix Env. Tech. by J. Hardy. No further action is required at this time. Spill cannot be closed due to BTEX levels in monitoring wells 2 & 4."

Remarks: "while removing old tanks discovered contaminated soil. caller's company is cleaning. "

All Materials:

Site ID:	245037
Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	342418
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	245037
Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	2096838
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BA347 **6 WEBSTER** **NY LTANKS** **S106472061**
SSW **6 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.384 mi.
2025 ft. **Site 2 of 3 in cluster BA**

Relative: **Lower**

Actual: **60 ft.**

LTANKS:

Facility ID:	0403816
Site ID:	81655
Closed Date:	2004-10-08
Spill Number:	0403816
Spill Date:	2004-07-09

6 WEBSTER (Continued) **S106472061**

Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-07-09
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-09
Spill Record Last Update:	2004-10-08
Spiller Name:	SANDRA
Spiller Company:	Not reported
Spiller Address:	6 WEBSTER AVE
Spiller County:	001
Spiller Contact:	SANDRA
Spiller Phone:	(914) 738-4106
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75517
DEC Memo:	"10/08/04 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. SPILL CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NFA REQUIRED AT THIS TIME. jbo "
Remarks:	"tank test failed.uncover the tank isolate,and retest"

All TTF:

Facility ID:	0403816
Spill Number:	0403816
Spill Tank Test:	1529427
Site ID:	81655
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	81655
Operable Unit ID:	886220
Operable Unit:	01
Material ID:	491374
Material Code:	0001A

6 WEBSTER (Continued) **S106472061**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BD348 **SPILL NUMBER 0314082** **NY LTANKS** **S106385679**
WNW **136 VANGUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.386 mi.
2040 ft. **Site 1 of 2 in cluster BD**

Relative:
Lower

Actual:
76 ft.

LTANKS:

Facility ID:	0314082
Site ID:	80232
Closed Date:	2004-06-08
Spill Number:	0314082
Spill Date:	2004-03-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-25
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-25
Spill Record Last Update:	2004-06-08
Spiller Name:	SILVANA CARRUSA
Spiller Company:	Not reported
Spiller Address:	136 VANGUILDER AVE
Spiller County:	001
Spiller Contact:	SILVANA CARRUSA
Spiller Phone:	(914) 654-1101
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74387
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/08/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 43.55 TONS OF CONTAMINATED SOIL. NFA REQUIRED. jbo"
Remarks:	"tank test failed. repair and retest and remove"

All TTF:

Facility ID:	0314082
Spill Number:	0314082
Spill Tank Test:	1529072
Site ID:	80232

SPILL NUMBER 0314082 (Continued) **S106385679**

Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	80232
Operable Unit ID:	881015
Operable Unit:	01
Material ID:	495664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE349 **STEWART DWELLING** **NY LTANKS** **S109414263**
NW **100 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.388 mi.
2049 ft. **Site 1 of 6 in cluster BE**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Facility ID:	1200264
Site ID:	462885
Closed Date:	2012-08-13
Spill Number:	1200264
Spill Date:	2012-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-04-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

STEWART DWELLING (Continued) **S109414263**

Date Entered In Computer:	2012-04-10
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	STEWART
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	STEWART
Spiller Phone:	914-235-6390
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	326980
DEC Memo:	"4-10-12 Spoke with Kathy. Failed with a popping sound. They have recommended a retest because this sound usually means piping or fitting leak. Homeowner is elderly so they are dealing with her daughter, Eunice at 914-715-1040. jm 8/13/2012: Envirostar removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"550gal ust"

All Materials:

Site ID:	462885
Operable Unit ID:	1212990
Operable Unit:	01
Material ID:	2210869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	0612561
Facility Type:	ER
Spill Number:	0612561
DER Facility ID:	326980
Site ID:	377421
DEC Region:	3
Closed Date:	2007-03-12
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2007-02-19
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-02-19
CID:	410
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

STEWART DWELLING (Continued) **S109414263**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-20
Spill Record Last Update:	2007-03-12
Spiller Name:	SUZANNE LUGO
Spiller Company:	TOWN AND COUNTRY OIL
Spiller Address:	275 EAST 7TH STREET
Spiller Company:	001
Contact Name:	NECOLA STEWART
DEC Memo:	""
Remarks:	"SPILL WAS LESS THAN ONE GALLON ON ICE OUTSIDE OF RESIDENCE: CLEANUP IN PROGRESS: MATERIAL CAME OUT OF VENT PIPE:"

All Materials:

Site ID:	377421
Operable Unit ID:	1134955
Operable Unit:	01
Material ID:	2124838
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0811178
Facility Type:	ER
Spill Number:	0811178
DER Facility ID:	326980
Site ID:	408736
DEC Region:	3
Closed Date:	2009-01-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-01-09
Investigator:	dxweitz
Referred To:	Not reported
Reported to Dept:	2009-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-09
Spill Record Last Update:	2009-01-09
Spiller Name:	SUE LUGO
Spiller Company:	TOWN & COUNTRY OIL
Spiller Address:	Not reported

STEWART DWELLING (Continued) **S109414263**

Spiller Company:	999
Contact Name:	NECOLA STEWART
DEC Memo:	"1/9/09 Problem with the vent whistle. Town and Country is there fixing the vent, and cleaning up the 1 gal spill. NFA dw"
Remarks:	"Caller states during a fill some oil sprayed out of the vent pipe onto soil. Spill was cleaned."

All Materials:

Site ID:	408736
Operable Unit ID:	1165255
Operable Unit:	01
Material ID:	2156662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BB350 **CITGO WEBSTER FOOD MART** **NY LTANKS** **S103568792**
West **210 WEBSTER AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2090 ft. **Site 2 of 2 in cluster BB**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:

Facility ID:	1311416
Site ID:	492314
Closed Date:	2017-04-06
Spill Number:	1311416
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2017-04-06
Spiller Name:	Not reported
Spiller Company:	LINE TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	VISHAL KUMAR
Spiller Phone:	(914) 632-2364

CITGO WEBSTER FOOD MART (Continued) **S103568792**

Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	216842
DEC Memo:	"Wanye Schneider, WCDOH, is handling...mm 4-5-17 ask American for update"
Remarks:	"regular and super product line test failure - repair/retest pending"

All Materials:

Site ID:	492314
Operable Unit ID:	1241846
Operable Unit:	01
Material ID:	2242337
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	8906053
Facility Type:	ER
Spill Number:	8906053
DER Facility ID:	216842
Site ID:	266088
DEC Region:	3
Closed Date:	1989-09-21
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1989-07-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-09-19
Cleanup Meets Std:	True
Last Inspection:	1989-09-19
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	MAR-LAP SVC CNTR
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED

CITGO WEBSTER FOOD MART (Continued) **S103568792**

SOIL."
Remarks: "HAVE EXCAVATED AND REMOVED GAS CONTAMINATED SOIL FROM AROUND 3 5ANKS. SOIL BEING REMOVED TODAY BY E.E.S. NFA"

All Materials:
Site ID: 266088
Operable Unit ID: 931218
Operable Unit: 01
Material ID: 446446
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Facility ID: 0600746
Facility Type: ER
Spill Number: 0600746
DER Facility ID: 216842
Site ID: 362821
DEC Region: 3
Closed Date: 2006-08-15
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 2006-04-19
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2006-04-19
CID: 409
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Tank Tester
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 2006-04-19
Spill Record Last Update: 2006-12-28
Spiller Name: SEBASTIAN BELLAFONTE
Spiller Company: CITGO STATION.
Spiller Address: 210 WEBSTER AVE
Spiller Company: 001
Contact Name: SEBASTIAN BELLAFONTE
DEC Memo: "04/25/06: refer to WC PBS. 12/21/06 - Letter from Barbara McDonald from WCDOH to Sebastian Bulfamonte, SSN Realty 94 1st Street, New Rochelle, NY 10801, states that documentation is acceptable to the Westchester County Department of Health and the work permits issued 5/11/06 and 6/6/06 are closed. NFA."
Remarks: "FOUND THE MATERIAL BETWEEN THE INTERSTIAL SPACE OF THE TWO TANKS. 4000 GAL TANKS. PBS 3-180092"

CITGO WEBSTER FOOD MART (Continued) **S103568792**

All Materials:

Site ID:	362821
Operable Unit ID:	1120900
Operable Unit:	01
Material ID:	2110381
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1200103
Facility Type:	ER
Spill Number:	1200103
DER Facility ID:	216842
Site ID:	462718
DEC Region:	3
Closed Date:	2013-11-06
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2012-04-04
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2012-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-04
Spill Record Last Update:	2013-11-06
Spiller Name:	MR KUMAR
Spiller Company:	SSN REALTY
Spiller Address:	210 WEBSTER AVE
Spiller Company:	999
Contact Name:	MR KUMAR
DEC Memo:	"4-4-12: V.Mc. call to Mr.Kumar: Phone # no longer is service. 4-4-12: V.Mc. call to SEBASTIAN/WCHD: Left Mess.: Req. callbk. to Dispt. Update from WCDOH: greater than greater than greater than Bimonte, Sebastian greater than spb4@westchestergov.com greater than 4/5/2012 9:46 AM greater than greater than greater than John, SSN Realty 210 Webster Ave New Rochelle NY Super Tank product in interstitial space. Manual check during PBS inspection yesterday. Product clear no water or dirt. Diesel Tank product in interstitial space. Manual check during PBS Inspection yesterday. Product clear no water of dirt. Tanks One was hired to test inner and outer tanks. Super, inner wall passed, outer wall failed. Diesel inner wall

CITGO WEBSTER FOOD MART (Continued) **S103568792**

failed, outer wall passed. Both tanks should be pumped out by today. Sebastian Bimonte jod 5/23/2012 -- After a meeting in NPO among owner, tank maintenance contractor, Mr. Nesci (attorney), WC DOH, and CK last Friday (5/18), Ispoke to Rachel at Hydro Environmental about a site assessment. Work plan to be submitted shortly. ELM 6/05/12: Update received from Sebastian Bimonte of WCDOH PBS: 1200103: SNN Realty in Mount Vernon. This was product in the interstitial during PBS inspection. No release to environment. Tank repaired NOH issued and can be closed. jod 6/5/2012 -- Site assessment being conducted at my request: field work on 210 Webster Ave in New Rochelle on Tuesday, June 12, 2012 per email from Hydro Enviro. ELM 7/31/2012 -- RI report clearly shows groundwater contamination (BETX/MTBE) around the tank field and dispensers. Need further delineation and RAP. Nothing in unsaturated soils. ELM 8/22/2012 -- Contractor working on a Phase II RI work plan. ELM 9/19/2012 -- Approved an RI work plan. Except that they did include the schedule and failed to mention RAP possibilities. ELM 1/22/2013 -- HydroTech informed me that they have the permit needed from the muny to perform the remediation. ELM 2/21/2013 -- Still no word on mobilizing for remediation. ELM 11-6-13 email from county, There is a whole history here.The 1200103 was for product in the interstitial. Sebastian and Carlos worked with Ed Moore on it.Basically double walled tanks leaked into the interstitial. It appear to be the striker plate were missing and from sticking the tanks they wore out. Eastmond lined the tanks and had trouble removing the product from the IS (completely). We requested spill closure and Ed Moore kept the spill open and continued to work on the PBS issues. They are replacing all tanks now. American Petroleum (Ed- Thank You for making this happen)Wayne Schneider is inspected the site this afternoon and will handle the spill. I suggest we close out spill 1200103 and keep 1307998.(Wayne please provide a brief update to all after your inspection today.) 11-6-13 tanks yanked, new spill 13-07998, close this one RDB "

Remarks: "12 oz per product found during investigation on inter.cont., on the super tank and diesel tank."

All Materials:

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210675
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

CITGO WEBSTER FOOD MART (Continued) **S103568792**

Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	0413599
Facility Type:	ER
Spill Number:	0413599
DER Facility ID:	289079
Site ID:	342744
DEC Region:	3
Closed Date:	2005-03-30
Spill Cause:	Other
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"IT WAS SOME RESIDEU IN A SPILL BUCKET ALL CLEANED UP:"

All Materials:

Site ID:	342744
Operable Unit ID:	1101460
Operable Unit:	01
Material ID:	581627
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0413600
Facility Type:	ER
Spill Number:	0413600
DER Facility ID:	289079

CITGO WEBSTER FOOD MART (Continued) **S103568792**

Site ID:	342745
DEC Region:	3
Closed Date:	2005-03-30
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"WHILE CHANGING OIL THEY KICKED A BUCKET OVER AND IN PROCESS OF CLEANING UP AT THIS TIME;"

All Materials:

Site ID:	342745
Operable Unit ID:	1101461
Operable Unit:	01
Material ID:	581628
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

351 **SPILL NUMBER 0302495** **NY LTANKS S105999167**
SE **85 NORTH AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2097 ft.

Relative: **Lower**
Actual: **69 ft.**

LTANKS:

Facility ID:	0302495
Site ID:	114935
Closed Date:	2003-08-12
Spill Number:	0302495
Spill Date:	2003-06-09

SPILL NUMBER 0302495 (Continued) **S105999167**

Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-09
CID:	405
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-08-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	85 NORTH AVE
Spiller County:	001
Spiller Contact:	DISPATCHER 629
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	""
Remarks:	"caller states that there is an overspill at the above address - some has gone into the sewer - cell # 914-760-1305 is for the fire chief on scene - unknown if the spill is stopped or not"

All Materials:

Site ID:	114935
Operable Unit ID:	869316
Operable Unit:	01
Material ID:	506969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0507677
Site ID:	353132
Closed Date:	2009-10-09
Spill Number:	0507677
Spill Date:	2005-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jkomara

SPILL NUMBER 0302495 (Continued) **S105999167**

Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2009-10-09
Spiller Name:	FRANK
Spiller Company:	GAS STATION
Spiller Address:	85 NORTH AVE.
Spiller County:	001
Spiller Contact:	FRANK
Spiller Phone:	(914) 632-2109
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	"9/28/05 Also see spills 03-04446, 05-11827 and 05-07653. jod Closure report received and site visit with WCHD performed. NFA if no money State money spent on Spill # 0304446 pin # 03236. 4/5/07 JO'M 10/9/09 Closed this spill refer to 0304446 JO'M"
Remarks:	"LINE FAILURE."

All Materials:

Site ID:	353132
Operable Unit ID:	1110599
Operable Unit:	01
Material ID:	2100636
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0507653
Facility Type:	ER
Spill Number:	0507653
DER Facility ID:	100200
Site ID:	353098
DEC Region:	3
Closed Date:	2005-10-07
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2005-09-26
Investigator:	JKOMARA
Referred To:	WCDOH
Reported to Dept:	2005-09-26

SPILL NUMBER 0302495 (Continued) **S105999167**

CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2005-10-07
Spiller Name:	FRANK
Spiller Company:	FRANKIES AUTO
Spiller Address:	85 NORTH AVE.
Spiller Company:	001
Contact Name:	FRANK
DEC Memo:	"9/28/05 Also see spills 03-04446, 03-11827 and 05-07677. jod 10/07/05 Refer to spill 05-07677 for all updates. This spill number closed. jod"
Remarks:	"GASOLINE IN SANITARY SEWER NEXT TO STATION AND ODORS: PLEASE CALL DOH ON THIS ISSUE"

All Materials:

Site ID:	353098
Operable Unit ID:	1110568
Operable Unit:	01
Material ID:	2100602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF352 **MICELI HOME** **NY LTANKS** **S108059468**
SSE **194 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2098 ft. **Site 1 of 4 in cluster BF**

Relative: LTANKS:
Lower

Facility ID:	0604103
Site ID:	366997
Closed Date:	2006-10-22
Spill Number:	0604103
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-07-13

Actual:
78 ft.

MICELI HOME (Continued) **S108059468**

CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-10-22
Spiller Name:	MARIO MICELI
Spiller Company:	MICELI HOME
Spiller Address:	194 CENTRE AVE
Spiller County:	001
Spiller Contact:	MARIO MICELI
Spiller Phone:	(914) 235-2198
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317018
DEC Memo:	"CLOSING REPORT TO JOHN O'DEE. October 22, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 23.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 gallon tank had holes"

All Materials:

Site ID:	366997
Operable Unit ID:	1124924
Operable Unit:	01
Material ID:	2114431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC353 **JEROME RESIDENCE** **NY LTANKS** **S106702572**
ENE **33 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.398 mi.
2099 ft. **Site 2 of 6 in cluster BC**

Relative: **Lower**
Actual: **35 ft.**

LTANKS:

Facility ID:	0405389
Site ID:	235222
Closed Date:	2005-02-13
Spill Number:	0405389
Spill Date:	2004-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee

JEROME RESIDENCE (Continued) **S106702572**

Referred To:	Not reported
Reported to Dept:	2004-08-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-17
Spill Record Last Update:	2005-02-13
Spiller Name:	MARK JEROME
Spiller Company:	JEROME RESIDENCE
Spiller Address:	33 ECHO AVE
Spiller County:	001
Spiller Contact:	MARK JEROME
Spiller Phone:	(914) 632-5400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193747
DEC Memo:	"02/13/05 MILLER ENVIRONMENTAL REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- ISOLATION & RETEST"

All TTF:

Facility ID:	0405389
Spill Number:	0405389
Spill Tank Test:	1529557
Site ID:	235222
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489552
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

JEROME RESIDENCE (Continued) **S106702572**

Oxygenate:	Not reported
Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BE354 **BRIEN-AMIE RESIDENCE** **NY LTANKS** **S105999591**
NW **105 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.398 mi.
2100 ft. **Site 2 of 6 in cluster BE**

Relative: **Lower**

Actual: **68 ft.**

LTANKS:

Facility ID:	0304963
Site ID:	219644
Closed Date:	2004-02-02
Spill Number:	0304963
Spill Date:	2003-08-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-08-11
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-11
Spill Record Last Update:	2004-02-02
Spiller Name:	BRIEN-AMIE RESIDENCE
Spiller Company:	Not reported
Spiller Address:	105 SICKLES AVE
Spiller County:	001
Spiller Contact:	BRIEN-AMIE RESIDENCE
Spiller Phone:	(914) 576-6823
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181652
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/11/03: 1000 gal. underground tank. 02/02/04 DUTCHESS DISPOSED OF LUST AND 75.35 TONS OF CONTAMINATED SOIL. SAMPLE RESULTS

BRIEN-AMIE RESIDENCE (Continued) **S105999591**

BELOW TAGM LIMITS. NFA jbo"
Remarks: "they were doing an inplace closure tank abandonment & encountered contaminated soil from the 550 gal underground tank - unk about soil removal at this point"

All Materials:
Site ID: 219644
Operable Unit ID: 873280
Operable Unit: 01
Material ID: 502238
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BC355 **POWERTEST,ECHO & MAIN** **NY LTANKS** **S100139866**
ENE **36 ECHO AVE @ MAIN ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2112 ft. **Site 3 of 6 in cluster BC**

Relative: **Lower**
Actual: **33 ft.**

LTANKS:
Facility ID: 8709260
Site ID: 283199
Closed Date: 1988-02-11
Spill Number: 8709260
Spill Date: 1988-01-30
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: D3
Cleanup Ceased: 1988-02-11
SWIS: 6010
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-01-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1988-02-01
Spill Record Last Update: 1988-06-13
Spiller Name: Not reported
Spiller Company: HACKER,JOSHUA;POWERTEST
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3

POWERTEST,ECHO & MAIN (Continued) **S100139866**

DER Facility ID: 229700
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 02-01-88 TANK REPLACED 5 YRS.AGO. AS PER DEPUTY CHIEF WILLIAM COMVERY,BASEMENT ODORS GREATLY DISSAPATED, ONCE VENTED. 02/11/88: CHECKED STATION; SEEMS TO BE ODOR PROBLEM DURING DELIVERIES. 11/29/95: This is additional information about material spilled from the translation of the old spill file: FUMES."
Remarks: "DELIVERY THIS MORNING, ONGOING PROBLEM, EXPLOSIVE READING IN BASEMENT. NEW ROCHELLE F.D. HAS VENTED BASEMENT AND WILL MONITOR."

All Materials:
Site ID: 283199
Operable Unit ID: 914517
Operable Unit: 01
Material ID: 464589
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BE356 **POINVIL RESIDENCE** **NY LTANKS** **S111160012**
NW **107 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.401 mi.
2115 ft. **Site 3 of 6 in cluster BE**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:
Facility ID: 1104844
Site ID: 452458
Closed Date: 2014-11-05
Spill Number: 1104844
Spill Date: 2011-07-28
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: Unassigned
Referred To: Not reported
Reported to Dept: 2011-07-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2011-07-28
Spill Record Last Update: 2017-08-10
Spiller Name: HENRY POINVILE
Spiller Company: POINVILE
Spiller Address: 107 SICKLES AVE

POINVIL RESIDENCE (Continued) **S111160012**

Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	407046
DEC Memo:	"7-28-11 Spoke with Kathy Morgan, This a is a real estate transaction. The plan at this time is to uncover, isolate and retest. The tank is 1080 gallon UST that is probably the original tank - age unknown. jm 2/17/12: Residential TTF, DEC Lead changed to unassigned. jod 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M 08/10/17 Spoke to the present homeowner who stated that she is attempting to sell the house and that this TTF came up during the transaction. She stated that she not informed by the previous owner that the tank failed a tank test. She is planning to have the tank removed. She was advised to speak to her attorney about the previous owners statement that nothing was wrong with the tank. TG"
Remarks:	"repair/retest pending -"

All Materials:

Site ID:	452458
Operable Unit ID:	1202639
Operable Unit:	01
Material ID:	2199228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BA357 **AMOCO SERVICE STATION #736** **NY LTANKS** **1001128018**
SSW **690 MAIN ST** **NY Spills** **NYR000036855**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.403 mi. **NY MANIFEST**
2127 ft. **Site 3 of 3 in cluster BA**

Relative: **Lower**

Actual: **64 ft.**

LTANKS:

Facility ID:	0209490
Site ID:	274754
Closed Date:	2002-12-16
Spill Number:	0209490
Spill Date:	2002-12-16
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-16
CID:	246
Water Affected:	Not reported
Spill Notifier:	Fire Department

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2002-12-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	DAVE BERRY
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"Tanker overfilled tank and material spilled at location. Approx 10 gal went into storm drain and sewer. Fire dept on scene now speedy dry applied"

All Materials:

Site ID:	274754
Operable Unit ID:	862563
Operable Unit:	01
Material ID:	512914
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

Facility ID:	0212950
Site ID:	274755
Closed Date:	2003-04-01
Spill Number:	0212950
Spill Date:	2003-03-31
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-03-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-31

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	WESTCHESTER CO 911
Spiller Phone:	(914) 231-1904
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"PRODUCT DID ENTER CONTAINMENT AREA - NO CLEAN UP"

All Materials:

Site ID:	274755
Operable Unit ID:	863771
Operable Unit:	01
Material ID:	512669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	8604411
Site ID:	274757
Closed Date:	1987-01-14
Spill Number:	8604411
Spill Date:	1986-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1987-01-14
SWIS:	6010
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-01-14
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-10-16
Spill Record Last Update:	1998-03-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

DEC Region: 3
DER Facility ID: 223479
DEC Memo: ""
Remarks: "TTTF"

All TTF:
Facility ID: 8604411
Spill Number: 8604411
Spill Tank Test: 1530280
Site ID: 274757
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 274757
Operable Unit ID: 901332
Operable Unit: 01
Material ID: 477220
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 0002007
Facility Type: ER
Spill Number: 0002007
DER Facility ID: 223479
Site ID: 274753
DEC Region: 3
Closed Date: 2000-05-17
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6010
Spill Date: 2000-05-17
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2000-05-17
CID: 257
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-05-17
Spill Record Last Update:	2000-07-17
Spiller Name:	ALFRED
Spiller Company:	AM0CO STATION 736
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ALFRED
DEC Memo:	""
Remarks:	"maintance crew on the way for cleanup and repairs"

All Materials:

Site ID:	274753
Operable Unit ID:	823636
Operable Unit:	01
Material ID:	550387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0305414
Facility Type:	ER
Spill Number:	0305414
DER Facility ID:	223479
Site ID:	274756
DEC Region:	3
Closed Date:	2003-10-29
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2003-08-21
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-08-21
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2003-10-29

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spiller Name:	Not reported
Spiller Company:	USA PETRO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	CINDY BADOLATO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BADOLATO 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED AS OF 9/12/03"
Remarks:	"leaking valve on a pump - pbs #3-183660 - pump taken out of service"

All Materials:

Site ID:	274756
Operable Unit ID:	873709
Operable Unit:	01
Material ID:	502669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9613029
Facility Type:	ER
Spill Number:	9613029
DER Facility ID:	223479
Site ID:	274758
DEC Region:	3
Closed Date:	2013-04-26
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1997-01-29
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1997-02-04
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-04
Spill Record Last Update:	2013-04-26
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY ALSO SEE SPILL 91-11342. 02/07/97 AS PART OF AN ONGOING

AMOCO SERVICE STATION #736 (Continued) **1001128018**

REMEDIATION THEY FOUND NEWER PRODUCT INFLUENCING THEIR CLEAN UP. 04/24/97 LETTER & STIPULATION AGREEMENT SENT TO BE SIGNED. 12/10/97 COPY OF SIGNED STIPULATION SENT BACK 08/11/98 LETTER SENT; IMMEDIATE ACTION TOWARD AUTOMATED PRODUCT REMOVAL AND GROUNDWATER CONTROL AT SITE IS REQUIRED. 12/07/00 LETTER SENT TO DELTA ENVIRONMENTAL BY J. HARDY; PROPOSE A REMEDIAL ACTION PLAN WHICH IS SUBSTANTIALLY MORE AGRESSIVE THAN THE ONE EXISTING AT THIS TIME. 01/11/01 LETTER SENT TO DELTA ENV. BY J. HARDY; CONCEPTUAL REMEDIAL ACTION PLAN OF 12/13/00 IS APPROVED & REQUIRED. 4/23/04: Letter to Aaron Lapine, Delta Env. Consultants by J. Hardy. Submit one report per year. Include operating data and GW monitoring data in same report. 8/9/04: Letter to A. Lapine, Delta Env. from J Hardy. Reduce monitor well sampling to semi-annual. Report annually. 6/15/09 annual submitted 6/9/09 shows relatively stable groundwater levels but no info as to system operation--sent email to envirotrac to submit operation info jh 4/20/10 site in remediation as system has been operating for many years. Original impacts to adjoining restaurant have also been resolved for years so it seems spill is contained; spill cannot be closed however as there is still significant contamination jh 07/02/12 Contaminated soils on the station have been excavated down to bedrock. 4 gw wells remain, 1 on-site upgradient, 2 off-site downgradient , 1 in the tank field. After review of the documentation and a phone conversation, consultant will submit a quarterly groundwater monitoring plan for the next year, after which time the monitoring frequency may be adjusted based on results. It appears the source has been removed. mt 4/26/13 Spill Closed, asymptptic conditions approaching gw standards in final well. no further action required. mt "

Remarks: "THEY HAVE A 1991 SPILL NUMBER, BUT THIS APPEARS TO BE A FRESH SPILL UNK IF SAME"

All Materials:

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	2096843
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	341679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Facility ID:	9806161
Facility Type:	ER
Spill Number:	9806161
DER Facility ID:	223479
Site ID:	274759
DEC Region:	3
Closed Date:	2005-02-14
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-08-18
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-08-18
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-18
Spill Record Last Update:	2005-02-14
Spiller Name:	ERIC LISMANIS
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ERIC LISMANIS
DEC Memo:	"2/14/05 HANDLE AS PART OF 9613029--CLSOE"
Remarks:	"PUMP MALFUNCTION FOR UNDERGROUND STORAGE TANK / NO CLEAN UP"

All Materials:

Site ID:	274759
Operable Unit ID:	1067358
Operable Unit:	01
Material ID:	317336
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9111342
Facility Type:	ER
Spill Number:	9111342
DER Facility ID:	101511
Site ID:	116684
DEC Region:	3
Closed Date:	1997-12-10
Spill Cause:	Unknown
Spill Class:	B3

AMOCO SERVICE STATION #736 (Continued) **1001128018**

SWIS:	6010
Spill Date:	1992-02-03
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1992-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-02-04
Spill Record Last Update:	2004-08-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 09/26/97 LETTER SENT; VES SYSTEM MUST BE OPERATING WITHIN ONE WEEK OR EXPLAIN WHY IT ISN'T GOING TO BE 12/10/97 LETTER & SIGNED STIPULATION SENT; NFA. SEE SPILL 96-13029 FOR UPDATES. jod"
Remarks:	"BALTEC ASSOC. ON SITE PERFORMING SOIL SURVEY TOOK SAMPLE BELOW GRADE AND FOUND FREE PRODUCT NO CALL BACK NEEDED"

All Materials:

Site ID:	116684
Operable Unit ID:	961469
Operable Unit:	01
Material ID:	416381
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9313209
Facility Type:	ER
Spill Number:	9313209
DER Facility ID:	101511
Site ID:	116685
DEC Region:	3
Closed Date:	1994-02-28
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	1994-02-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-07

AMOCO SERVICE STATION #736 (Continued) **1001128018**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	1994-06-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/03/94: NO DEC RESPONSE. "
Remarks:	"ICE IN FILL BOX SORBENTS USED TO CLEAN UP"

All Materials:

Site ID:	116685
Operable Unit ID:	995095
Operable Unit:	01
Material ID:	388600
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AMOCO SERVICE STATION #736
Facility address:	690 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYR000036855
Mailing address:	OLD POST RD BALTEZ ASSOCIATES INC BEDFORD, NY 10506
Contact:	Not reported
Contact address:	OLD POST RD BEDFORD, NY 10506
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	AMOCO CORP

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: 201-331-7000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: 201-331-7000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AMOCO SERVICE STATION #736
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: AMOCO SERVICE STATION #736
Classification: Small Quantity Generator

Date form received by agency: 03/21/1997
Site name: AMOCO SERVICE STATION #736
Classification: Large Quantity Generator

. Waste code: D001

AMOCO SERVICE STATION #736 (Continued) **1001128018**

. Waste name: IGNITABLE WASTE

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000036855
Facility Status: Not reported
Location Address 1: 690 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000036855
Mailing Name: AMOCO SERVICE STATION #736
Mailing Contact: JONATHAN LANDAU
Mailing Address 1: 130 BUSINESS PARK DR
Mailing Address 2: Not reported
Mailing City: ARMONK
Mailing State: NY
Mailing Zip: 10504
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142349580

NY MANIFEST:
Document ID: NYG0063774
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 04/27/1998
Trans1 Recv Date: 04/27/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000036855
Trans1 EPA ID: NJD986607380
Trans2 EPA ID: Not reported
TSDF ID 1: GAD093380814
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

BG358 **RESIDENCE** **NY LTANKS** **S107523528**
ENE **10 LAFAYETTE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2132 ft. **Site 1 of 3 in cluster BG**

Relative: LTANKS:
Lower

Facility ID:	0512638
Site ID:	358990
Closed Date:	2006-03-15
Spill Number:	0512638
Spill Date:	2006-02-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-01
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

Actual:
47 ft.

RESIDENCE (Continued) **S107523528**

Date Entered In Computer:	2006-02-01
Spill Record Last Update:	2006-03-15
Spiller Name:	MARIO KOTLAR
Spiller Company:	RESIDENCE
Spiller Address:	10 LAFFEYTE ST
Spiller County:	001
Spiller Contact:	MARIO KOTLAR
Spiller Phone:	(914) 235-8882
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308993
DEC Memo:	"Northeast to return 2/3/06 for soil excavation & sampling. March 15, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 42.57 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallon."

All Materials:

Site ID:	358990
Operable Unit ID:	1116216
Operable Unit:	01
Material ID:	2106363
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD359 **YOUNG ADULT INSTITUTE** **NY LTANKS** **S107410752**
WNW **150 VAN GUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 2 of 2 in cluster BD**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Facility ID:	0507808
Site ID:	353295
Closed Date:	2005-12-18
Spill Number:	0507808
Spill Date:	2005-09-29
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-29
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

YOUNG ADULT INSTITUTE (Continued) **S107410752**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-29
Spill Record Last Update:	2005-12-18
Spiller Name:	MARGARET FORC
Spiller Company:	YOUNG ADULT INSTITUTE
Spiller Address:	150 VAN GUILDER AVE
Spiller County:	001
Spiller Contact:	MARGARET FORC
Spiller Phone:	(212) 273-6172
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300615
DEC Memo:	"Left message with contact. Robison returning to clean up fuel in street. New England was removing UST and some product leaked out of tank on ground. Area roped off by Fire Marshal. December 18, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 13.63 TONS OF CONTAMINATED SOIL. CLEAN UP COMPLETED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. DISPOSAL RECEIPT FORWARDED TO BECI. jod"
Remarks:	"550 GALLON TANK AND FOUND HOLES: FIRE MARSHALL ON SCENE"

All Materials:

Site ID:	353295
Operable Unit ID:	1110757
Operable Unit:	01
Material ID:	2100797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH360 **COMMERCIAL-TTF** **NY LTANKS** **S117975659**
West **172 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 1 of 3 in cluster BH**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Facility ID:	1502358
Site ID:	508618
Closed Date:	Not reported
Spill Number:	1502358
Spill Date:	2015-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported

COMMERCIAL-TTF (Continued) **S117975659**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2015-08-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	463301
DEC Memo:	"6/3/15 Spoke to Mr. Scorzelli, who did not have contact info for owner at that time, and does not know what owner will be doing. dw "
Remarks:	"TEST FAILURE"

All Materials:

Site ID:	508618
Operable Unit ID:	1257927
Operable Unit:	01
Material ID:	2260991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BE361 **TAHIR RESIDENCE** **NY LTANKS** **S108299038**
NW **112 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2149 ft. **Site 4 of 6 in cluster BE**

Relative: **Lower**
Actual: **69 ft.**

LTANKS:

Facility ID:	0610140
Site ID:	374522
Closed Date:	2007-10-24
Spill Number:	0610140
Spill Date:	2006-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-12-06
CID:	444

TAHIR RESIDENCE (Continued) **S108299038**

Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-06
Spill Record Last Update:	2007-10-24
Spiller Name:	ISMAIL GALVAN
Spiller Company:	Not reported
Spiller Address:	112 SICKLES AVE
Spiller County:	001
Spiller Contact:	ISMAIL GALVAN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	324199
DEC Memo:	"09/18/07 Dutchess Environmental reported that the 550 gallon tank was removed and that no sign of oil contamination was observed in the tank grave. NFA TG"
Remarks:	"UNCOVER REPAIR AND TEST OR REMOVE"

All TTF:

Facility ID:	0610140
Spill Number:	0610140
Spill Tank Test:	1550484
Site ID:	374522
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	374522
Operable Unit ID:	1132196
Operable Unit:	01
Material ID:	2121918
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

TAHIR RESIDENCE (Continued) **S108299038**

SPILLS:

Facility ID:	0911724
Facility Type:	ER
Spill Number:	0911724
DER Facility ID:	324199
Site ID:	424559
DEC Region:	3
Closed Date:	2010-03-22
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	6010
Spill Date:	2010-02-02
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2010-02-12
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2010-03-22
Spiller Name:	CHRIS
Spiller Company:	PARADISE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ISHMAEL TAHIR
DEC Memo:	"2/3/10 homeowner, Mr. Tahir, is satisfied with cleanup done by Paradise Oil Co., both inside and outside the house. NFA dw 2/12/10: Spill re-opened. WCDOH reported this spill, after complaints by home owner that the oil company had taken no action. Marc Grazioli re-inspected the site today and reports the spill has still not been remediated. jod 2/17/10: Update from Marc Grazioli: The outside portion of the spill was handled before the big snow that came last week. I was only able to look into the basement through an open window since no one was home when I was there. There was absorbent on the ground and I would guess it was the second round of cleanup because it appeared dry. jod 3/22/10: DEC requires no further action at this time. jod"
Remarks:	"5gals oil to basement area/10 gals to out side,driveway. Clean up complete"

All Materials:

Site ID:	424559
Operable Unit ID:	1180325
Operable Unit:	01
Material ID:	2174200
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00

TAHIR RESIDENCE (Continued) **S108299038**

Units: G
Recovered: Not reported
Oxygenate: Not reported

BC362 **DAVENPORT AUTO / WEST PLAINS SERVICE** **NY LTANKS** **S110309404**
ENE **44 ECHO AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2151 ft. **Site 4 of 6 in cluster BC**

Relative: **Lower**
Actual: **32 ft.**

LTANKS:

Facility ID:	1001469
Site ID:	434525
Closed Date:	2010-11-01
Spill Number:	1001469
Spill Date:	2010-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-07
Spill Record Last Update:	2010-11-01
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	INA -
Spiller Phone:	(914) 235-8073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"5/7/10 Metro Env. tested UST, and it failed a TT. Davenport Auto thinks it may be fuel lines, and got list of contractors to examine problem more closely, and to determine remedial actions. Site is a WCHD-PBS site# 3-137480 Tank was tank #6- 550 gal. dw 11/1/10 As per WCDOH Two tanks pulled, reviewed TCR, recommend NFA. NFA JOM "
Remarks:	"tank test - cleanup pending"

All Materials:

Site ID:	434525
Operable Unit ID:	1185347
Operable Unit:	01
Material ID:	2179667
Material Code:	0001A
Material Name:	#2 fuel oil

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported
Facility ID:	9210810
Site ID:	130489
Closed Date:	1995-02-09
Spill Number:	9210810
Spill Date:	1992-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1995-02-09
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E.I.R. PETRO-TITE"

All TTF:

Facility ID:	9210810
Spill Number:	9210810
Spill Tank Test:	1540972
Site ID:	130489
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130489
Operable Unit ID:	975022
Operable Unit:	01
Material ID:	404252
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9201557
Site ID:	130487
Closed Date:	2006-02-17
Spill Number:	9201557
Spill Date:	1992-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	1992-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/17/06 SEE SPILLS 92-10118 AND 92-10810. jod"
Remarks:	"FOUND LINE LEAKING AT DISPENSER GASOLINE TANK IS OK MAIN & ELMSFORD TO POSS. REPAIR MONDAY WILLIAMS SUGGESTED TO MAIN & ELMSFORD CO. THAT

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

THEUY SHUT THIS PUMP DOWN UNTIL REPAIRS ARE MADE SPOKE W/ WILL"

All TTF:

Facility ID:	9201557
Spill Number:	9201557
Spill Tank Test:	1539973
Site ID:	130487
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130487
Operable Unit ID:	968828
Operable Unit:	01
Material ID:	412859
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9210118
Facility Type:	ER
Spill Number:	9210118
DER Facility ID:	309856
Site ID:	130488
DEC Region:	3
Closed Date:	1997-11-07
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1992-12-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-15
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"GASOLINE ODOR IN BASEMENT OF APARTMENT BUILDING NEXT DOOR TO GAS STATION GAS STATION RECEIVED A DELIVERY AT 8:00 A.M. T. GHIOSAY RESPONDED"

All Materials:

Site ID:	130488
Operable Unit ID:	976578
Operable Unit:	01
Material ID:	407123
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1310365
Facility Type:	ER
Spill Number:	1310365
DER Facility ID:	389397
Site ID:	491212
DEC Region:	3
Closed Date:	2016-07-26
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2014-01-29
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-29
Spill Record Last Update:	2016-07-26

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Spiller Name:	Not reported
Spiller Company:	WEST PLAINS SERVICE INC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHAEL BURNSTEIN
DEC Memo:	"Chris Lalak called duty desk. American Petro is pulling tanks today. WCDOH is handling this and will do follow up...mm 1/29/2014 -- Called Pat Dunn @ APECCO to get some details. Dispensers had no sumps; discovered soil contamination under a dispenser. Trench along side dispenser is clean to 2 1/2 feet below grade; they expect limited dig and haul. ELM 2-11-14 lyt was not a tank pull as originally noted by WCHD only line and dispenser replacement. RDB 2-13-14, spill #13-09599 was closed and referred to this one, the line test failure led to thic contamination RDB 03-14 contamination deep in excavation under former dispenser. crews worried about garage and building under neath, met on site with Gary and owner, advised them additional soil needed removal. 03-10-14 Using a Hydro Vac to get the remaining contaminated soils from excavation. 03-18-14 status report in edocs 05-13-14 email from Gary, Work done, report done,plan on forwarding report to you today once we get payment. RDB 07-22-14 gary looking for closure, I am looking for closure report.sent email requesting RDB 7-25-16 TCR submitted- Spill closed RDB"
Remarks:	"cleanup in progress"

All Materials:

Site ID:	491212
Operable Unit ID:	1240767
Operable Unit:	01
Material ID:	2240992
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BC363 **GAS STATION** **NY LTANKS** **S116156793**
ENE **44 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2151 ft. **Site 5 of 6 in cluster BC**

Relative: **Lower**
Actual: **32 ft.**

LTANKS:

Facility ID:	1309599
Site ID:	490405
Closed Date:	2014-02-13
Spill Number:	1309599
Spill Date:	2014-01-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported

GAS STATION (Continued) **S116156793**

Reported to Dept:	2014-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-02
Spill Record Last Update:	2014-02-13
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CARLOS TORREZ
Spiller Phone:	(914) 424-5927
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"1/2/14 - WCDOH is oversight the ongoing tank tests. KAB 1/2/2014 -- APECCO hired by new operator (lease signed within past 6 weeks). Piping and dispensers and electronic leak monitoring equipment to be replaced. Based on lack of leak detection records for past 10 to 12 years, DEC requested TT and IS tests and system check of electronics. Tanks are probably suitable for service, but testing required for confirmation. It appears to be loose fittings. Electronics recently rewired at the computer console within past couple of weeks, but wiring ended near the top of the tanks. No probes in the interstitial space, just loose wiring near top of tank. Owner's representative took electronic system wire ends from the site despite WCDOH's request to take custody. ELM 2-13-14 closed and referred to spill 13-10365 which revealed contaminated soils when the failed lines were removed. RDB"
Remarks:	"repair/retest pending - to Ed Moore (waiting for results)"

All Materials:

Site ID:	490405
Operable Unit ID:	1239966
Operable Unit:	01
Material ID:	2240056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BF364 **200 CENTRA CORP** **NY LTANKS** **S108059537**
SSE **200 CENTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.412 mi.
2174 ft. **Site 2 of 4 in cluster BF**

Relative: **Lower**

Actual: **77 ft.**

LTANKS:

Facility ID:	0604650
Site ID:	367663
Closed Date:	2007-12-12
Spill Number:	0604650
Spill Date:	2006-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-07-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-25
Spill Record Last Update:	2007-12-12
Spiller Name:	SHARON ROURKE
Spiller Company:	200 CENTRA CORP
Spiller Address:	200 CENTRE AVE
Spiller County:	001
Spiller Contact:	SHARON ROURKE
Spiller Phone:	(203) 557-3600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317637
DEC Memo:	"12/04/06 Tank removed and samples ok according to D Jackson - WCHD. TG"
Remarks:	"PBS No: 3-800237 -PBS No. not found in UIS, may be invalid. UNCOVER REPAIR AND TEST"

All TTF:

Facility ID:	0604650
Spill Number:	0604650
Spill Tank Test:	1550151
Site ID:	367663
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

200 CENTRA CORP (Continued) **S108059537**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 367663
Operable Unit ID: 1125568
Operable Unit: 01
Material ID: 2115091
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

BC365 **CONSOLIDATED EDISON - ECHO AVE. SITE** **NY SHWS** **S101008407**
ENE **ECHO AVENUE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.413 mi.
2179 ft. **Site 6 of 6 in cluster BC**

Relative:
Lower

Actual:
30 ft.

SHWS:
Program: HW
Site Code: 56077
Classification: P
Region: 3
Acres: 3
HW Code: 360016
Record Add: 11/18/1999
Record Upd: 05/01/2017
Updated By: GWHEITZM
Site Description: Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. This 3 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed, and the whole site has been levelled, top-soiled and grassed. Current Use The site is currently vacant Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. PCBs transformers were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. The soil on site and the sediment in the Bay were contaminated with PCBs.
Env Problem: Prior to remediation the contaminant of concern was PCBs. Remediation of the site is complete. The cleanup of PCBs and other incidentally detected contaminants has mitigated the threat to the environment, and in particular to the natural habitat in the bay.
Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

BH366 **FIRST ASSEMBLY OF GOD** **NY LTANKS** **S110490783**
West **177 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.414 mi.
2186 ft. **Site 2 of 3 in cluster BH**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:

Facility ID:	1002183
Site ID:	435290
Closed Date:	2010-08-30
Spill Number:	1002183
Spill Date:	2010-05-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-26
Spill Record Last Update:	2010-08-30
Spiller Name:	Not reported
Spiller Company:	BARNABY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BARNABY
Spiller Phone:	(914) 632-0031
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	390193
DEC Memo:	"7/1/10: No call backs made by dispatch desk. No indication of contamination at the time of the report. Unknown action at this time. jod 08/19/10 Northeast Environmental reported that they excavated and removed the LUST along with 40.92 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA. TG"
Remarks:	"550gal ust"

All Materials:

Site ID:	435290
Operable Unit ID:	1186074
Operable Unit:	01
Material ID:	2180843
Material Code:	0001A
Material Name:	#2 fuel oil

FIRST ASSEMBLY OF GOD (Continued) **S110490783**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

367
WSW
1/4-1/2
0.415 mi.
2193 ft.

48 1ST STREET **NY LTANKS** **S104279084**
48 1ST STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:

Facility ID:	9911183
Site ID:	116893
Closed Date:	1999-12-22
Spill Number:	9911183
Spill Date:	1999-12-22
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	PJDECICC
Referred To:	Not reported
Reported to Dept:	1999-12-22
CID:	389
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-22
Spill Record Last Update:	1999-12-30
Spiller Name:	CALLER
Spiller Company:	CASTLE OIL CORPORTATION
Spiller Address:	290 LOCUST AVENUE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	101696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO "
Remarks:	"caller reporting a spill of material from a tank overfill clean up was done no callback is necessary"

All Materials:

Site ID:	116893
Operable Unit ID:	1089889
Operable Unit:	01
Material ID:	296651
Material Code:	0001A

48 1ST STREET (Continued) **S104279084**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BG368 **GONCALVES RESIDENCE** **NY LTANKS** **S102674341**
ENE **1 LAFFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2197 ft. **Site 2 of 3 in cluster BG**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Facility ID:	9410991
Site ID:	156301
Closed Date:	1994-11-29
Spill Number:	9410991
Spill Date:	1994-11-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-11-29
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132292
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED 100 GAL. COULDN'T FIT BEING CLEANED NOW SPEEDI-DRI AND PADS COMPLETED"

All Materials:

Site ID:	156301
Operable Unit ID:	1008868
Operable Unit:	01
Material ID:	376855

GONCALVES RESIDENCE (Continued) **S102674341**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG369 **GONCALVES RESIDENCE** **NY LTANKS** **S108298870**
ENE **1 LAFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2197 ft. **Site 3 of 3 in cluster BG**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Facility ID:	0609401
Site ID:	373629
Closed Date:	2007-01-10
Spill Number:	0609401
Spill Date:	2006-11-15
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-11-15
CID:	410
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-15
Spill Record Last Update:	2007-01-10
Spiller Name:	ED ALLEN
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323367
DEC Memo:	""
Remarks:	"CLEANUP IN PROGRESS:"

All Materials:

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121025
Material Code:	0001A

GONCALVES RESIDENCE (Continued) **S108298870**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

BE370 **RESIDENCE** **NY LTANKS** **S107410404**
NW **7 PRINCE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.417 mi.
2200 ft. **Site 5 of 6 in cluster BE**

Relative: **Lower**
Actual: **67 ft.**

LTANKS:

Facility ID:	0506424
Site ID:	351640
Closed Date:	2005-10-29
Spill Number:	0506424
Spill Date:	2005-08-24
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-24
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-24
Spill Record Last Update:	2005-10-29
Spiller Name:	JOHN BROWN
Spiller Company:	RESIDENCE
Spiller Address:	7 PRINCE ST
Spiller County:	001
Spiller Contact:	JOHN BROWN
Spiller Phone:	(914) 879-7900

RESIDENCE (Continued) **S107410404**

Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	298912
DEC Memo:	"Report to John O'Dee -RA October 29, 2005: CASTLTON DISPOSED OF LUST AND 57.27 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

All Materials:

Site ID:	351640
Operable Unit ID:	1109140
Operable Unit:	01
Material ID:	2099127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE371 **RENTAL HOUSE** **NY LTANKS** **S100153568**
NW **119 SICKLES AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.421 mi.
2223 ft. **Site 6 of 6 in cluster BE**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Facility ID:	9107320
Site ID:	119461
Closed Date:	1991-11-25
Spill Number:	9107320
Spill Date:	1991-10-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	HOULIHAN & LAWRENCE RLTY.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported

RENTAL HOUSE (Continued) **S100153568**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103766
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DISCOVERED SEEPAGE FROM TANK ON BASEMENT CONCRETE FLOOR APPLIED SPEEDI-DRY SPILLER WILL CONTACT LUZON OIL FOR CLEAN UP"

All Materials:

Site ID:	119461
Operable Unit ID:	961556
Operable Unit:	01
Material ID:	419532
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BI372 **SPILL NUMBER 0104402** **NY LTANKS** **S105135031**
NE **30 LINCOLN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.426 mi.
2249 ft. **Site 1 of 2 in cluster BI**

Relative: **Lower**

Actual: **27 ft.**

LTANKS:

Facility ID:	0104402
Site ID:	328750
Closed Date:	2001-11-14
Spill Number:	0104402
Spill Date:	2001-07-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-07-25
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-25
Spill Record Last Update:	2002-02-07
Spiller Name:	OWNER
Spiller Company:	AVALLONE
Spiller Address:	30 LINCOLN ST
Spiller County:	001

SPILL NUMBER 0104402 (Continued) **S105135031**

Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	264577
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/14/2001 G.C. RELIABLE PULLED TANK. NO LEAK OR DISCHARGE EVIDENT. NO FURTHER ACTION."
Remarks:	"failed test"

All TTF:

Facility ID:	0104402
Spill Number:	0104402
Spill Tank Test:	1526481
Site ID:	328750
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	328750
Operable Unit ID:	841036
Operable Unit:	01
Material ID:	532897
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH373 **SPILL NUMBER 0210366** **NY LTANKS** **S105997907**
West **182 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.427 mi.
2253 ft. **Site 3 of 3 in cluster BH**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:

Facility ID:	0210366
Site ID:	282696
Closed Date:	2003-03-03
Spill Number:	0210366
Spill Date:	2003-01-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling

SPILL NUMBER 0210366 (Continued) **S105997907**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-14
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229505
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Jan 2003 - 1000 gallon tank was removed from the property. 100 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environemtal Assessement. NFA. TG"
Remarks:	"SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL AT ABOVE LOCATION. PROPTERY IS OWNED BY THE CITY OF NEW ROCHELLE AND CALLER IS A CONTRACTOR FOR THE CITY. TANK APPEARS TO HAVE BEEN ABANDONED YEARDS AGO. "

All Materials:

Site ID:	282696
Operable Unit ID:	861605
Operable Unit:	01
Material ID:	513753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BJ374 **PLASTIC WORKS** **NY LTANKS** **S103824027**
NNE **115 CEDAR ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.430 mi.
2272 ft. **Site 1 of 2 in cluster BJ**

Relative: **Lower**
Actual: **50 ft.**

LTANKS:

Facility ID:	9812998
Site ID:	163894
Closed Date:	1999-02-22
Spill Number:	9812998
Spill Date:	1999-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	1999-03-01
Spiller Name:	GARY STRUTTEN
Spiller Company:	PLASTIC WORKS
Spiller Address:	115 CEDAR ST
Spiller County:	001
Spiller Contact:	GARY STRUTTEN
Spiller Phone:	(914) 576-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	138224
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER'S COMPANY WAS PULLING A 550GAL UST - TANK WAS FULL OF HOLES"

All Materials:

Site ID:	163894
Operable Unit ID:	1073438
Operable Unit:	01
Material ID:	313271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF375 **APT. BUILDING** **NY LTANKS** **S102674170**
SSE **208 CENTER AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2277 ft. **Site 3 of 4 in cluster BF**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Facility ID:	9314003
Site ID:	215702
Closed Date:	1994-03-11
Spill Number:	9314003
Spill Date:	1994-02-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1994-03-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-11
Spill Record Last Update:	1995-01-05
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK WAS OVERFILLED CASTLE CREW TO CLEAN UP"

All Materials:

Site ID:	215702
Operable Unit ID:	996014
Operable Unit:	01
Material ID:	389350
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9315255
Site ID:	215703

APT. BUILDING (Continued) **S102674170**

Closed Date:	1994-04-11
Spill Number:	9315255
Spill Date:	1994-03-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-04-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-11
Spill Record Last Update:	1995-01-04
Spiller Name:	Not reported
Spiller Company:	WRG
Spiller Address:	420 WESTCHESTER AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY GUAGE RESULTED IN OVERFILL WCHD NOTIFIED CASTLE OIL WILL CLEAN UP"

All Materials:

Site ID:	215703
Operable Unit ID:	997178
Operable Unit:	01
Material ID:	387016
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0202241
Facility Type:	ER
Spill Number:	0202241
DER Facility ID:	177797
Site ID:	214599
DEC Region:	3

APT. BUILDING (Continued) **S102674170**

Closed Date:	2002-08-12
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2002-06-01
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-06-01
CID:	257
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-01
Spill Record Last Update:	2002-09-26
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	208 CENTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"bad gauge - contained - cleanup to be done by castleton enviromental" Not reported

All Materials:

Site ID:	214599
Operable Unit ID:	855230
Operable Unit:	01
Material ID:	520107
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI376 **SPILL NUMBER 0300463** **NY LTANKS** **S105998684**
NE **52 LINCOLN ST** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.432 mi.
2282 ft. **Site 2 of 2 in cluster BI**

Relative: **Lower**

Actual: **27 ft.**

LTANKS:

Facility ID:	0300463
Site ID:	202585
Closed Date:	2003-04-14
Spill Number:	0300463
Spill Date:	2003-04-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial

SPILL NUMBER 0300463 (Continued) **S105998684**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-22
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	168519
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"Above material reported spilled at above location due to tank overfill. Crew is on site and cleanup is in progress at time of call. All material is expected to be recovered."

All Materials:

Site ID:	202585
Operable Unit ID:	868761
Operable Unit:	01
Material ID:	508540
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0806544
Facility Type:	ER
Spill Number:	0806544
DER Facility ID:	168519
Site ID:	403827
DEC Region:	3
Closed Date:	2008-12-26
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010

SPILL NUMBER 0300463 (Continued) **S105998684**

Spill Date:	2008-09-10
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-09-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-11
Spill Record Last Update:	2008-12-26
Spiller Name:	LOUIS VACCARO
Spiller Company:	LOIS VACCARO
Spiller Address:	52 LINCOLN ST
Spiller Company:	999
Contact Name:	LOUIS VACCARO
DEC Memo:	"11/16/08 New England Tank Services reported that they removed one 550 gallon tank along with 7.09 tons of petroleum contaminated soil. NFA TG"
Remarks:	"Callers company was removing a 550 gallon tank and found it had holes in it. Unknown how much fuel had been leaking or for how long. Clean up will start within the next few days."

All Materials:

Site ID:	403827
Operable Unit ID:	1160514
Operable Unit:	01
Material ID:	2151689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BJ377 **I-95 EXIT 16** **NY LTANKS** **S102673537**
NNE **OPP. 111 CEDAR ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.437 mi.
2305 ft. **Site 2 of 2 in cluster BJ**

Relative: LTANKS:
Lower

Facility ID:	9001240
Site ID:	244221
Closed Date:	1990-08-01
Spill Number:	9001240
Spill Date:	1990-05-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Not reported

Actual:
62 ft.

I-95 EXIT 16 (Continued) **S102673537**

Cleanup Ceased:	1990-08-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	MIGOYA CONST. CO. ?
Spiller Address:	3520 DELAVAL AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	200593
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : N.F.A. 09/27/95: This is additional information about material spilled from the translation of the old spill file: POSS. WASTE OIL."
Remarks:	"DIESEL SPILLED WHILE FILLING HEAVY CONSTRUCTION EQUIPMENT ALSO APPEARSTHAT THEY HAVE CHANGED THEIR CRANKCASE OIL BY DRAINING ONTO GROUND A USED OIL FILTER WAS FOUND THERE ALSO"

All Materials:

Site ID:	244221
Operable Unit ID:	941067
Operable Unit:	01
Material ID:	439592
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BK378 **SPILL NUMBER 0009195** **NY LTANKS** **S104877181**
SSE **17 POPLAR PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.439 mi.
2316 ft. **Site 1 of 3 in cluster BK**

Relative: LTANKS:
Lower

Facility ID:	0009195
Site ID:	63217
Closed Date:	2001-01-08
Spill Number:	0009195

Actual:
74 ft.

SPILL NUMBER 0009195 (Continued) **S104877181**

Spill Date:	2000-11-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-09
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-09
Spill Record Last Update:	2001-02-02
Spiller Name:	DESIGN BUILDERS GROUP
Spiller Company:	Not reported
Spiller Address:	17 POPLAR PL
Spiller County:	001
Spiller Contact:	DESIGN BUILDERS GROUP
Spiller Phone:	(914) 948-9785
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	61128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/17/2000 TANK TEST FAILURE LETTER SENT. TANK SCHEDULED FOR RETEST ON 11/20/00. 01/08/2001 ENVIROSTAR PULLED TANK. TANK WAS SOUND, NO RELEASE. EVIROSTAR REPORTS TANK FAILED DUE TO FAULTY OIL LINES. NO CONTAMINATION FOUND. NO FURTHER ACTION REQUIRED."
Remarks:	"uncover repair retest"

All Materials:

Site ID:	63217
Operable Unit ID:	831505
Operable Unit:	01
Material ID:	543152
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF379 **RESIDENCE** **NY LTANKS** **S106124419**
SSE **6 POPLAR ROAD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.439 mi.
2320 ft. **Site 4 of 4 in cluster BF**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Facility ID:	0310014
Site ID:	82997
Closed Date:	2012-08-13
Spill Number:	0310014
Spill Date:	2003-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-11-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RUDY TAYLOR
Spiller Phone:	(914) 833-0287
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76439
DEC Memo:	"7/29/10 Homeowner TTF JO'M 7/25/12: There is no such address as 6 Poplar Road in New Rochelle. This should either be 6 Poplar Road in Larchmont, or 6 Poplar Place in New Rochelle. jod 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"
Remarks:	""

All TTF:

Facility ID:	0310014
Spill Number:	0310014
Spill Tank Test:	1528823
Site ID:	82997
Tank Number:	1
Tank Size:	500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

RESIDENCE (Continued) **S106124419**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 82997
Operable Unit ID: 875149
Operable Unit: 01
Material ID: 498967
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

---

380 South 1/4-1/2 0.442 mi. 2333 ft. **LIPMAN RESIDENCE** **NY LTANKS** **S106971579**
54 LIBERTY AVE **N/A**
NEW ROCHELLE, NY

Relative: Lower
Actual: 48 ft.

LTANKS:
Facility ID: 0409061
Site ID: 333699
Closed Date: 2005-04-02
Spill Number: 0409061
Spill Date: 2004-11-16
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2004-11-16
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-11-16
Spill Record Last Update: 2005-04-02
Spiller Name: JOSH LITSMAN
Spiller Company: LISTMAN RESIDENCE
Spiller Address: 54 LIBERTY AVE
Spiller County: 001
Spiller Contact: JOSH LITSMAN
Spiller Phone: (914) 813-5024
Spiller Extention: Not reported

LIPMAN RESIDENCE (Continued) **S106971579**

DEC Region: 3
DER Facility ID: 268950
DEC Memo: "02/18/04 ZURICH CLAIM BEING HANDLED BY LEWIS ENVIRONMENTAL. SMALL AMOUNT OF CONTAMINATION UNDER PUBLIC SIDEWALK/ROADWAY CANNOT BE REMOVED SAFELY. DEC SPOKE WITH LEWIS (BOB KRAUSE) ABOUT SAMPLING REQUIREMENTS. REPORT TO FOLLOW. jod 04/02/05 LEWIS ENVIRONMENTAL DISPOSED OF LUST AND 82.08 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "SOILTEST CAME BACK OVER THE LIMIT:"

BL381 **TELEDYNE HYDRA-POWER** **NY SWF/LF** **1000201735**
ENE **310 MAIN ST** **NY Spills** **NYD001650209**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.442 mi. **FINDS**
2336 ft. **Site 1 of 2 in cluster BL** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
21 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[60J11]
Active:	No
East Coordinate:	603184
North Coordinate:	4529831
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Facility ID:	0713299
Facility Type:	ER
Spill Number:	0713299
DER Facility ID:	344570
Site ID:	395027
DEC Region:	3

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Closed Date:	2010-11-30
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-03-17
Investigator:	jkomara
Referred To:	WCDOH - PBS
Reported to Dept:	2008-03-17
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-17
Spill Record Last Update:	2010-11-30
Spiller Name:	MIMI
Spiller Company:	CAR DEALER
Spiller Address:	310 MAIN STREET
Spiller Company:	001
Contact Name:	MIMI
DEC Memo:	"11/30/10 No Info 3 years old spills will nbot be following up NFA JO'M "
Remarks:	"DURING SOIL BORINGS FOUND CONTAMINTAED SOIL"

All Materials:

Site ID:	395027
Operable Unit ID:	1151973
Operable Unit:	01
Material ID:	2142744
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1408123
Facility Type:	ER
Spill Number:	1408123
DER Facility ID:	456652
Site ID:	501675
DEC Region:	3
Closed Date:	2014-11-06
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2014-11-06
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2014-11-06

TELEDYNE HYDRA-POWER (Continued) **1000201735**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2014-11-06
Spiller Name:	MIKE TASHENT
Spiller Company:	M TECH MOTORS
Spiller Address:	310 MAIN ST REAR
Spiller Company:	999
Contact Name:	MIKE TASHENT
DEC Memo:	"11/6/14- Spoke to caller. He was on site and noted where auto shop flushed some waste oil to roadside curb. Cleanup completed by spiller with speedidry. Caller states cleanup is complete. NFA DT"
Remarks:	"loss to sewer and roadway. C/u in progress"

All Materials:

Site ID:	501675
Operable Unit ID:	1251062
Operable Unit:	01
Material ID:	2252898
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	TELEDYNE HYDRA-POWER
Facility address:	310 MAIN ST NEW ROCHELLE, NY 10801-5716
EPA ID:	NYD001650209
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Owner/Operator Summary:

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST
	NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-2200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST
	OPERCITY, NY 99999
Owner/operator country:	US
Owner/operator telephone:	914-632-2200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	TELEDYNE HYDRA-POWER
Classification:	Not a generator, verified

Date form received by agency:	07/08/1999
Site name:	TELEDYNE HYDRA-POWER
Classification:	Not a generator, verified

Date form received by agency:	11/19/1980
Site name:	TELEDYNE HYDRA-POWER
Classification:	Not a generator, verified

TELEDYNE HYDRA-POWER (Continued) **1000201735**

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 08/18/1980
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004335808

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000201735
Registry ID: 110004335808
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004335808

NY MANIFEST:

Country: USA
EPA ID: NYD001650209
Facility Status: Not reported
Location Address 1: 310 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: 5716

NY MANIFEST:

EPAID: NYD001650209
Mailing Name: TELEDYNE HYDRA POWER INC
Mailing Contact: RICHARD C. SNYDER
Mailing Address 1: 10-12 PINE COURT
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146322200

TELEDYNE HYDRA-POWER (Continued) **1000201735**

NY MANIFEST:

Document ID:	PAC6193121
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	PAAH0421
Trans2 State ID:	Not reported
Generator Ship Date:	01/21/1993
Trans1 Recv Date:	01/21/1993
Trans2 Recv Date:	01/22/1993
TSD Site Recv Date:	01/22/1993
Part A Recv Date:	02/02/1993
Part B Recv Date:	02/04/1993
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	CTD983883745
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
28 additional NY_MANIFEST: record(s) in the EDR Site Report.

382
NW
1/4-1/2
0.443 mi.
2337 ft.

WALTON RESIDENCE **NY LTANKS** **S108639866**
129 SICKLES AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
67 ft.

LTANKS:

Facility ID:	0703375
Site ID:	383296
Closed Date:	2007-08-28

WALTON RESIDENCE (Continued) **S108639866**

Spill Number:	0703375
Spill Date:	2007-06-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-06-22
CID:	408
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2007-06-28
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-22
Spill Record Last Update:	2007-08-28
Spiller Name:	MARGRET WALTON
Spiller Company:	PRIVATE HOME
Spiller Address:	129 SICKLES AVE
Spiller County:	001
Spiller Contact:	MARGRET WALTON
Spiller Phone:	(914) 235-5241
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	332760
DEC Memo:	"6/29/07: Envirotrac is consultant for insurance company. Report to follow. jod 08/08/07 Northeast Environmental reported that the tank was excavated and removed along with 19.85 tons of impacted soil. NFA TG"
Remarks:	"soil contamination found during tank removal; NOT YET CONTAINED OR CLEANED;"

All Materials:

Site ID:	383296
Operable Unit ID:	1140659
Operable Unit:	01
Material ID:	2130748
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

383
East
1/4-1/2
0.444 mi.
2344 ft.

FIUMFREDO RESIDENCE
12 BAYVIEW AVE
NEW ROCHELLE, NY

NY LTANKS **S111012239**
N/A

Relative:
Lower

Actual:
47 ft.

LTANKS:

Facility ID:	1100096
Site ID:	447470
Closed Date:	2011-09-22
Spill Number:	1100096
Spill Date:	2011-04-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D2
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2011-08-08
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-04
Spill Record Last Update:	2011-09-22
Spiller Name:	ROSE FIUMFREDO
Spiller Company:	ROSE FIUMFREDO
Spiller Address:	12 DAYVIEW AVE
Spiller County:	999
Spiller Contact:	ROSE FIUMFREDO
Spiller Phone:	(914) 632-0496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402070
DEC Memo:	"4/4/11 - To retest tank. KAB 4/28/11 Morris called in for follow up. Tank failed again. He said tank top was exposed for most of length and one side and some samples taken. Morris said whoever did repairs, sounds like they only put a new vent riser on. Did not check piping, which is heavily crusted. jc 5-6-11 Failed 2nd retest today. Owner giving Kathy a hard time. Morris will retest again next week. Kathy said road name should be Bayview not Dayview, made change. jc 5/13/11 Tank failed for a 3rd time. Plan to pull, according to Tank Tech. dw 8-4-11 Homeowner called dispatch desk. He wants to remove the tank himself and do ALL of the work. He says he would cut open the tank and clean with speedi dri, dispose of tank at scrap yard, etc. I recommended that he hire an environmental consultant to AT LEAST oversee project because the DEC will need a TCR which would include soil samples, manifests, disposal receipts, etc. I told him that this spill will not be closed out until a proper and acceptable Tank Closure Report has been submitted to this office for review. I told him to contact J O'Dee in White Plains for further info. This guy seems bent on doing everything himself even though it was recommended that he hire a consultant to oversee the project. jm 8/4/11: Recieved call from Sandy Perratta 914-557-0142. He is the same individual who

FIUMFREDO RESIDENCE (Continued) **S111012239**

called the dispatch desk earlier today. He is not the property owner but a friend of the owner. States he is in the construction business and he can remove the tank himself. He states he has the OSHA 30-hour training and also states he knows that he doesn't need confined space entry training if the tank is less than 4 feet below ground . I again stated he should have a professional contractor do the work for safety reasons. jod 8/8/11: Received voice-mail message from Mr Perratta stating he had removed the tank and it was on the lawn awaiting a DEC drive-by inspection. I met New Rochelle Fire Captain Henry Senno on site. The tank was cut and cleaned and is on plastic. The excavation is open and is not fenced or secured. There is no evidence of any holes in the tank, and no evidence of any leak or contamination. Captain Senno states he will follow up with the owner, as no permits were filed for the removal as required in New Rochelle. DEC Spills requires no further action at this time. jod 9/8/11: I left this spill open after discussing the situation with Capt Senno on either August 9th or 10th. There was still a 55-gallon drum of heating oil and heating oil sludge that was removed from the tank remaining on the site. On either Aug 11th or 12th I spoke with Mr Perrotta and stated the spill would be left open until he submitted a disposal receipt to DEC for proper disposal of that waste drum. To date, Mr Perrotta has submitted a disposal recipt for the tank (entered in eDocs) but has not submitted a disposal receipt for the drum. jod 9/22/11: Letter from Linda Enes forwarded to DEC. She states she is in posesseion of the 55-gallon drum, and is using it to fuel a space heater. I called her this morning and she states her husband transported the drum in his pick-up truck from New Rochelle to their home in Dover Plains NY. Letter has been entered into eDocs. DEC requires no further action. jod"

Remarks: "repair/retest pending"

All Materials:

Site ID:	447470
Operable Unit ID:	1197626
Operable Unit:	01
Material ID:	2193927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

---

384 **WILLIAMS TTF** **NY LTANKS** **S104276929**
WSW **23 1ST ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.447 mi.
2360 ft.

Relative: LTANKS:
Lower

Actual: Facility ID:	9702187
57 ft. Site ID:	102476
Closed Date:	1999-06-10
Spill Number:	9702187
Spill Date:	1997-05-20

WILLIAMS TTF (Continued) **S104276929**

Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-20
CID:	369
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-20
Spill Record Last Update:	2018-01-24
Spiller Name:	Not reported
Spiller Company:	MR WILLIAMS
Spiller Address:	23 FIRST ST
Spiller County:	001
Spiller Contact:	BRIAN SCHUG
Spiller Phone:	(914) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90745
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING SITE EVALUATION-CALLER WILL REMOVE SOIL-CLEANUP IN PROGRESS"

All Materials:

Site ID:	102476
Operable Unit ID:	1048062
Operable Unit:	01
Material ID:	335128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

385
SW
1/4-1/2
0.448 mi.
2366 ft.

RESIDENCE **NY LTANKS** **S102660166**
38 BEECHWOOD AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
37 ft.

LTANKS:

Facility ID:	9705244
Site ID:	105369
Closed Date:	1997-11-10
Spill Number:	9705244

RESIDENCE (Continued) **S102660166**

Spill Date:	1997-07-31
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-31
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-31
Spill Record Last Update:	1998-02-05
Spiller Name:	MARVIN KAPUS
Spiller Company:	Not reported
Spiller Address:	38 BEECHWOOD AVE
Spiller County:	001
Spiller Contact:	MARVIN KAPUS
Spiller Phone:	(914) 738-1351
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92963
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/31/97 CONTAMINATED SOIL BEING REMOVED & STOCKPILED; 08/01/97 TANK FOUND DURING DEMOLITION OF HOUSE; TANK AND CONTAMINATION REMOVED; "
Remarks:	"demolition of building - ust 550 gal tank - tank had holes in it contaminated soil found "

All Materials:

Site ID:	105369
Operable Unit ID:	1048510
Operable Unit:	01
Material ID:	334464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL386 **DEFENDER MARINE SUPPLY** **NY LTANKS** **S103479285**
ENE **309 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.449 mi.
2369 ft. **Site 2 of 2 in cluster BL**

Relative: **Lower**
Actual: **25 ft.**

LTANKS:

Facility ID:	9806235
Site ID:	93459
Closed Date:	2002-09-19
Spill Number:	9806235
Spill Date:	1998-08-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-08-19
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-19
Spill Record Last Update:	2002-09-19
Spiller Name:	WILLIAM GOING
Spiller Company:	DEFENDER MARINE SUPPLY
Spiller Address:	309 MAIN ST
Spiller County:	001
Spiller Contact:	WILLIAM GOING
Spiller Phone:	(914) 744-3705
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83786
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/19/98 WCHD NOTIFIED. 09/14/02 - 8 TO 10 YARDS OF SOIL STOCKPILED. CLOSURE REPORT TO FOLLOW ONCE SAMPLE RESULTS RECEIVED. 09/19/02 CLOSURE REPORT RECEIVED FROM WILLIAM GOING. DISPOSAL OF TANK AND 10.45 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"during a tank removal caller found contamined soil"

All Materials:

Site ID:	93459
Operable Unit ID:	1067422
Operable Unit:	01
Material ID:	317407
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BK387 **FUNICELOLO HOME** **NY LTANKS** **S107489124**
SSE **24 POPLAR PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.450 mi.
2375 ft. **Site 2 of 3 in cluster BK**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Facility ID:	0509719
Site ID:	355533
Closed Date:	2006-11-19
Spill Number:	0509719
Spill Date:	2005-11-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-11-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-14
Spill Record Last Update:	2006-11-19
Spiller Name:	FUNICEOLO HOME
Spiller Company:	FUNICELOLO HOME
Spiller Address:	24 POPULAR PLACE
Spiller County:	001
Spiller Contact:	FUNICEOLO HOME
Spiller Phone:	(914) 636-5043
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305561
DEC Memo:	"PLAN WAS TO ABANDON BUT FOUND HOLES SO NOWTHEY WILL REMOVE NO KNOWN EXPERTS AT THIS TIME November 19, 2006: ONE HOLE FOUND ON TOP OF TANK. TANK CANNOT BE REMOVED DUE TO SAFETY AND STRUCTURAL CONSIDERATIONS. MUNICIPAL WATER AND SEWER. ROYAL ENVIRONMENTAL TOOK A GROUND WATER SAMPLE BENATH TANK, ALL ANALYTES NON-DETECT. TANK ABANDONED IN PLACE WITH SLURRY. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES FOUND IN A 1000 GALLON TANK;"

All Materials:

Site ID:	355533
Operable Unit ID:	1112888
Operable Unit:	01
Material ID:	2102930
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00

FUNICELOLO HOME (Continued) **S107489124**

Oxygenate: Not reported

BK388 **LABELLA RESIDENCE** **NY LTANKS** **S107789449**
SSE **219 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.454 mi.
2397 ft. **Site 3 of 3 in cluster BK**

Relative:
Lower

Actual:
72 ft.

LTANKS:

Facility ID:	0601959
Site ID:	364328
Closed Date:	2009-09-01
Spill Number:	0601959
Spill Date:	2006-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2009-09-01
Spiller Name:	LARRY LABELLA
Spiller Company:	LABELLA RESIDENCE
Spiller Address:	219 CENTRAL AVE
Spiller County:	001
Spiller Contact:	LARRY LABELLA
Spiller Phone:	(914) 654-0719
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	314554
DEC Memo:	"05/24/06: Soil samples clean. US Tank Tech will be repairing and retesting. 9/1/09: Tank passed a retest in isolation on 6-13-06. At that time, new fuel lines had been run from the tank to the boiler room but were not hooked up at the time of the test. A full system test was performed 7-24-09 with the lines connected. The tank system passed this retest. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"UNCOVER REPAIR AND RETEST."

All TTF:

Facility ID:	0601959
Spill Number:	0601959
Spill Tank Test:	1550008
Site ID:	364328
Tank Number:	1
Tank Size:	1000

LABELLA RESIDENCE (Continued) **S107789449**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	364328
Operable Unit ID:	1122357
Operable Unit:	01
Material ID:	2111830
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

389
West
1/4-1/2
0.459 mi.
2423 ft.

SPILL NUMBER 0210080 **NY LTANKS** **S105997807**
196 UNION AV **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
71 ft.

LTANKS:

Facility ID:	0210080
Site ID:	155360
Closed Date:	2003-03-03
Spill Number:	0210080
Spill Date:	2003-01-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-06
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-06
Spill Record Last Update:	2003-03-04

SPILL NUMBER 0210080 (Continued) **S105997807**

Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131601
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Dec. 2002 - One 1200 gallon tank was removed from the property. 300 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environmetnal Assessment. NFA. TG"
Remarks:	"1200 GAL UNDERGROUND STORAGE TANK - 4 OTHER SPILL #'S ON THIS SAME SITE - DELORES FROM DEC SAYS THEY NEED ANOTHER NEW SPILL #"

All Materials:

Site ID:	155360
Operable Unit ID:	861323
Operable Unit:	01
Material ID:	513483
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM390 **RESIDENCE** **NY LTANKS** **S105230245**
South **98 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2426 ft. **Site 1 of 4 in cluster BM**

Relative: **Lower**
Actual: **46 ft.**

LTANKS:

Facility ID:	0107187
Site ID:	204562
Closed Date:	2002-01-11
Spill Number:	0107187
Spill Date:	2001-10-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-10-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

RESIDENCE (Continued) **S105230245**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-11
Spill Record Last Update:	2002-03-22
Spiller Name:	REALTOR
Spiller Company:	MR GAMIANO
Spiller Address:	98 LIBERTY AVE
Spiller County:	001
Spiller Contact:	CAROL MASCOLINO-REALTOR
Spiller Phone:	(914) 576-1112
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170048
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/11/2002 ADVANCED PULLED TANK AND 99.6 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"PETROLEUM ODOR AND STAINING IN THE SOIL-RECOMMEND TANK REMOVAL"

All TTF:

Facility ID:	0107187
Spill Number:	0107187
Spill Tank Test:	1526660
Site ID:	204562
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	204562
Operable Unit ID:	844253
Operable Unit:	01
Material ID:	532018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

391
WNW
1/4-1/2
0.462 mi.
2441 ft.

MANONE PLACE
15 COLONIAL PLACE
NEW ROCHELLE, NY

NY LTANKS **S107523607**
N/A

Relative:
Lower

Actual:
84 ft.

LTANKS:

Facility ID:	0513004
Site ID:	359413
Closed Date:	2006-05-08
Spill Number:	0513004
Spill Date:	2006-02-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-09
Spill Record Last Update:	2006-05-08
Spiller Name:	FLORENCE MANONE
Spiller Company:	MANONE PLACE
Spiller Address:	15 COLONIAL PLACE
Spiller County:	001
Spiller Contact:	FLORENCE MANONE
Spiller Phone:	(914) 633-7791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309466
DEC Memo:	"John O'Dee is lead and will/has contacted. May 8, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND FIVE DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 GALLON TANK, HOLES AND CONTAMINATION, WOULD LIKE A CALL BACK PERTAINING TO THIS PROPERTY"

All Materials:

Site ID:	359413
Operable Unit ID:	1116622
Operable Unit:	01
Material ID:	2107064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

392
SSE
1/4-1/2
0.466 mi.
2463 ft.

APT BLDG
25 TRINITY PLACE
NEW ROCHELLE, NY

NY LTANKS

S109416298
N/A

Relative:
Lower

Actual:
70 ft.

LTANKS:

Facility ID:	8905211
Site ID:	283512
Closed Date:	1992-07-30
Spill Number:	8905211
Spill Date:	1989-08-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ANN JASLOCKI
Spiller Address:	REAL ESTATE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"4K PETRO TITE, -.234 GPH"

All TTF:

Facility ID:	8905211
Spill Number:	8905211
Spill Tank Test:	1535913
Site ID:	283512
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

APT BLDG (Continued) **S109416298**

Last Modified Date: Not reported

All Materials:

Site ID:	283512
Operable Unit ID:	932936
Operable Unit:	01
Material ID:	445651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0811859
Site ID:	409448
Closed Date:	2009-04-22
Spill Number:	0811859
Spill Date:	2009-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-30
Spill Record Last Update:	2009-04-22
Spiller Name:	WILLY SILSDORF
Spiller Company:	TRINITY ARMS LTD
Spiller Address:	25 TRINITY PLACE
Spiller County:	999
Spiller Contact:	LARRY BOYD
Spiller Phone:	(914) 682-5676
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Spoke to W. Silsdorf. Think it may be leak in piping or fitting. Will probably Uncover, repair and retest. dvw 04/21/09 Wayne Schnieder reported ttf 1/3/09. passing retest after line replacement. No contamination. NFA TG "
Remarks:	"Caller states he performed a EZ-3 test and had a failure. Caller does not believe a spill or resources are affected."

All Materials:

APT BLDG (Continued) **S109416298**

Site ID:	409448
Operable Unit ID:	1165955
Operable Unit:	01
Material ID:	2157389
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BN393 **SPILL NUMBER 9814027** **NY LTANKS** **S104619985**
NW **48 REMINGTON PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.471 mi.
2489 ft. **Site 1 of 2 in cluster BN**

Relative: LTANKS:
Lower

Facility ID:	9814027
Site ID:	80830
Closed Date:	1999-02-19
Spill Number:	9814027
Spill Date:	1999-02-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-19
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-19
Spill Record Last Update:	1999-03-01
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AV
Spiller County:	001
Spiller Contact:	MAMMY JONES
Spiller Phone:	(914) 636-5128
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74863
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"STORAGE TANK OVERFILL - TANK IS OUTSIDE UNDERGROUND - CONTAMINATED SOIL WAS REMOVED & REPLACED WITH FRESH SOIL"

Actual:
75 ft.

SPILL NUMBER 9814027 (Continued) **S104619985**

All Materials:

Site ID:	80830
Operable Unit ID:	1071478
Operable Unit:	01
Material ID:	310733
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

394
NE
1/4-1/2
0.472 mi.
2492 ft.

RITACCO HOME
24 JACKSON STREET
NEW ROCHELLE, NY

NY LTANKS **S107789088**
N/A

Relative:
Lower

Actual:
24 ft.

LTANKS:

Facility ID:	0600187
Site ID:	362141
Closed Date:	2006-07-28
Spill Number:	0600187
Spill Date:	2006-04-06
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-06
Spill Record Last Update:	2006-07-28
Spiller Name:	RITACCO HOME
Spiller Company:	RITACCO HOME
Spiller Address:	24 JACKSON STREET
Spiller County:	001
Spiller Contact:	RITACCO HOME
Spiller Phone:	(914) 576-1430
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	312378
DEC Memo:	"04/10/06: Northeast to continue remediation. No GW involved as of now. July 28, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.00 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO

RITACCO HOME (Continued) **S107789088**

DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "HOLES IN A 550 GALLON AND CONTAMINATED SOIL;"

All Materials:
Site ID: 362141
Operable Unit ID: 1120244
Operable Unit: 01
Material ID: 2109739
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

---

395 SSW 1/4-1/2 0.474 mi. 2501 ft. **COMMERICAL BUILIDING** **NY LTANKS** **S106472134**
719 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative: Lower
Actual: 59 ft.

LTANKS:
Facility ID: 0404182
Site ID: 301693
Closed Date: 2004-10-28
Spill Number: 0404182
Spill Date: 2004-07-19
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2004-07-19
CID: 405
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-07-19
Spill Record Last Update: 2004-10-28
Spiller Name: JOHN DEURANTE
Spiller Company: COMMERICAL BUILIDING
Spiller Address: 719 MAIN ST.
Spiller County: 001
Spiller Contact: JOHN DEURANTE
Spiller Phone: (914) 632-4222
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 243806
DEC Memo: "10/28/04 TANK PASSED RETEST AFTER PIPING WAS REPLACED. BASED UPON

COMMERICAL BUILIDING (Continued) **S106472134**

THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks: "RECOMMEND, UNCOVER, REPAIR, RETEST"

All TTF:
Facility ID: 0404182
Spill Number: 0404182
Spill Tank Test: 1529456
Site ID: 301693
Tank Number: 1
Tank Size: 1080
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

396
East
1/4-1/2
0.475 mi.
2506 ft.

CONSOLIDATED EDISON-ECHO AVE. SITE
ECHO AVE
NEW ROCHELLE, NY 10801

SEMS-ARCHIVE **1000111631**
RCRA-CESQG **NYD981141252**
NY Spills
NY MANIFEST

Relative:
Lower

Actual:
17 ft.

SEMS Archive:
Site ID: 202659
EPA ID: NYD981141252
Cong District: 20
FIPS Code: 36119
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:
Region: 2
Site ID: 202659
EPA ID: NYD981141252
Site Name: CONSOLIDATED EDISON-ECHO AVE. SITE
NPL: N
FF: N
OU: 0
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1992-09-30 00:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 2
Site ID: 202659
EPA ID: NYD981141252
Site Name: CONSOLIDATED EDISON-ECHO AVE. SITE

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

NPL:	N
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1992-09-30 00:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1988-04-19 00:00:00
Finish Date:	1988-04-19 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	CON EDISON - ECHO AVENUE SUBSTATION
Facility address:	ECHO AVENUE NEW ROCHELLE, NY 10801
EPA ID:	NYD981141252
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1951
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1951
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Date form received by agency: 01/01/2001
Site name: ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Small Quantity Generator

Date form received by agency: 03/29/1996
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 11/19/1985
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Large Quantity Generator

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

SPILLS:
Facility ID: 9711031
Facility Type: ER
Spill Number: 9711031
DER Facility ID: 101608
Site ID: 116789
DEC Region: 3
Closed Date: 1998-01-06
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 1998-01-01
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-01-01
CID: 204
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-01
Spill Record Last Update: 1998-01-29
Spiller Name: STEVE ROMERO
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: STEVE ROMERO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/01/98 OIL/WATER SEPARATOR OVERFLOWED; SUSPECTS OUTLET PIPE BECAME CLOGGED OR FROZEN CAUSING OVERFLOW; 01/02/98 3,300 GAL CONTAINED IN DIKED AREA; 100 GAL OVERFLOWED DIKE ONTO SOIL AND INTO DRAIN; 01/06/98 SPILL CLEANED UP BY CON ED; H2O HAS LESS THAN 1 PPM

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

PCB "
Remarks: "OIL / WATER SEPARATOR MALFUNCTIONED 3300 IN CONTAINMENT AREA"

All Materials:
Site ID: 116789
Operable Unit ID: 1053908
Operable Unit: 01
Material ID: 329298
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 3400.00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYD981141252
Facility Status: Not reported
Location Address 1: ECHO AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981141252
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYB9791883
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: AE50394PA
Trans2 State ID: Not reported
Generator Ship Date: 01/20/2003
Trans1 Recv Date: 01/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B004 - PCB ARTICLES WITH 50 PPM BUT < 500 PPM
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	08210
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
41 additional NY_MANIFEST: record(s) in the EDR Site Report.

BM397 **SPILL NUMBER 9803423** **NY LTANKS** **S104619561**
South **106 LIBERTY AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.482 mi.
2546 ft. **Site 2 of 4 in cluster BM**

Relative: LTANKS:
Lower

Facility ID:	9803423
Site ID:	140786
Closed Date:	1998-08-18
Spill Number:	9803423
Spill Date:	1998-06-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-17
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

Actual:
45 ft.

SPILL NUMBER 9803423 (Continued) **S104619561**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-17
Spill Record Last Update:	1998-10-02
Spiller Name:	MARGURITE FINCH
Spiller Company:	Not reported
Spiller Address:	106 LIBERTY AV
Spiller County:	001
Spiller Contact:	MARGURITE FINCH
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	120231
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PULLED THE TANK TODAY & FOUND IT TO BE LEAKING - CONTAMINATED SOIL IS BEING DUG UP & STOCK PILED"

All Materials:

Site ID:	140786
Operable Unit ID:	1064251
Operable Unit:	01
Material ID:	566529
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

398
NE
1/4-1/2
0.485 mi.
2560 ft.

TTF AT RESIDENCE **NY LTANKS** **S108957764**
68 JACKSON ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
25 ft.

LTANKS:

Facility ID:	0707955
Site ID:	388761
Closed Date:	2008-03-26
Spill Number:	0707955
Spill Date:	2007-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-10-20
CID:	79
Water Affected:	Not reported
Spill Notifier:	Responsible Party

TTF AT RESIDENCE (Continued) **S108957764**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-22
Spill Record Last Update:	2008-03-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MR JOHNSON
Spiller Phone:	(914) 235-1496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	338305
DEC Memo:	"March 26, 2008: ENVIROSTAR REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"TEST FAILED DUE TO BUBBLING. HORNER EASY 3 TEST,"

All Materials:

Site ID:	388761
Operable Unit ID:	1145917
Operable Unit:	01
Material ID:	2136260
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM399 **COLLEGE OF NEW ROCHELLE** **NY LTANKS** **S104619776**
South **103 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.486 mi.
2564 ft. **Site 3 of 4 in cluster BM**

Relative: **Lower**
Actual: **44 ft.**

LTANKS:

Facility ID:	9809357
Site ID:	118985
Closed Date:	2005-04-17
Spill Number:	9809357
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-10-26
CID:	281
Water Affected:	Not reported

COLLEGE OF NEW ROCHELLE (Continued) **S104619776**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	2005-04-17
Spiller Name:	UNKNOWN
Spiller Company:	COLLEGE OF NEW ROCHELLE
Spiller Address:	103 LIBERTY AVE
Spiller County:	001
Spiller Contact:	COLLEGE OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103367
DEC Memo:	"02/23/99 Letter sent to tank owner requesting information 04/17/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF RESULTS. NO CALL BACK REQUESTED AT TIME OF CALL."

All TTF:

Facility ID:	9809357
Spill Number:	9809357
Spill Tank Test:	1546454
Site ID:	118985
Tank Number:	1
Tank Size:	1080
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	118985
Operable Unit ID:	1066630
Operable Unit:	01
Material ID:	316813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

400 ESE 1/4-1/2 0.486 mi. 2566 ft. | **CIUSSETELLI RESIDENCE**
4 FAIRVIEW PLACE
NEW ROCHELLE, NY | **NY LTANKS** | **S105996325**
N/A

Relative: Lower

Actual: 40 ft.

LTANKS:

Facility ID:	0204230
Site ID:	161898
Closed Date:	2010-07-13
Spill Number:	0204230
Spill Date:	2002-07-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-07-23
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2010-07-13
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	RON CIUSSETELLI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136674
DEC Memo:	"7/13/10: Report of a residential tank test failure. No indication of contamination noted on initial report. Report indicates all exterior piping loose, multiple vents and fills. Probable air leak. No further information received. jod"
Remarks:	"all exterior piping loose...multiple vents and fille..and questions contact caller."

All TTF:

Facility ID:	0204230
Spill Number:	0204230
Spill Tank Test:	1527307
Site ID:	161898
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 161898
Operable Unit ID: 857023
Operable Unit: 01
Material ID: 518487
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BO401 **FORMER MANCUSO MARINA** **US BROWNFIELDS** **1006975972**
ENE **HUNTINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.487 mi.
2571 ft. **Site 1 of 2 in cluster BO**

Relative:
Lower

Actual:
14 ft.

US BROWNFIELDS:
Property Name: FORMER MANCUSO MARINA
Recipient Name: R2 Brownfields TBA (previously Superfund TBA)
Grant Type: TBA
Property Number: Not reported
Parcel size: 1.23
Latitude: 40.912585
Longitude: -73.773854
HCM Label: Not reported
Map Scale: Not reported
Point of Reference: Not reported
Highlights: Not reported
Datum: Not reported
Acres Property ID: 10127
IC Data Access: Not reported
Start Date: Not reported
Redev Completition Date: Not reported
Completed Date: Not reported
Acres Cleaned Up: Not reported
Cleanup Funding: Not reported
Cleanup Funding Source: Not reported
Assessment Funding: 11217
Assessment Funding Source: US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding: Not reported
Redev. Funding Source: Not reported
Redev. Funding Entity Name: Not reported
Redevelopment Start Date: Not reported
Assessment Funding Entity: Not reported
Cleanup Funding Entity: Not reported
Grant Type: Hazardous
Accomplishment Type: Phase I Environmental Assessment

FORMER MANCUSO MARINA (Continued) **1006975972**

Accomplishment Count:	1
Cooperative Agreement Number:	n/a
Start Date:	03/01/2003 00:00:00
Ownership Entity:	Not reported
Completion Date:	03/01/2003 00:00:00
Current Owner:	City of New Rochelle, NY
Did Owner Change:	N
Cleanup Required:	Not reported
Video Available:	N
Photo Available:	N
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported

FORMER MANCUSO MARINA (Continued) **1006975972**

Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	marina and boat storage facility
Below Poverty Number:	1670
Below Poverty Percent:	18.4%
Meidan Income:	9092
Meidan Income Number:	3667
Meidan Income Percent:	40.5%
Vacant Housing Number:	349
Vacant Housing Percent:	8.6%
Unemployed Number:	334
Unemployed Percent:	3.7%

BM402 **BLANCO RESIDENCE** **NY LTANKS** **S103238839**
South **30 LINDEN PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.488 mi.
2574 ft. **Site 4 of 4 in cluster BM**

Relative: **Lower**
Actual: **50 ft.**

LTANKS:

Facility ID:	9802704
Site ID:	227988
Closed Date:	1998-07-30
Spill Number:	9802704
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-01
Spill Record Last Update:	1998-08-04
Spiller Name:	FRANK BLANCO
Spiller Company:	BLANCO RESIDENCE
Spiller Address:	30 LINDEN PLACE
Spiller County:	001
Spiller Contact:	FRANK BLANCO
Spiller Phone:	(914) 633-7605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 LETTER REC'D FROM NES,INC. INDICATING TANK AND APPROX. 21.86 TONS CONTAMINATED SOIL WAS REMOVED. NFA."
Remarks:	"CALLERS AGENCY CALLED FOR NO HOT WATER - SERVICE MAN FOUND TANK EMPTY - POSSIBLY A TANK LEAK OR LINE FAILURE"

All Materials:

Site ID:	227988
Operable Unit ID:	1063369
Operable Unit:	01
Material ID:	321024
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO403 **NELSTAD MATERIAL CORP** **NY LTANKS** **S102154943**
ENE **40 HUNTINGTON PL** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY SPDES**
0.488 mi.
2574 ft. **Site 2 of 2 in cluster BO**

Relative: **Lower**
Actual: **13 ft.**

LTANKS:

Facility ID:	0208898
Site ID:	200280
Closed Date:	2004-05-03
Spill Number:	0208898
Spill Date:	2002-11-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-27
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-11-27
Spill Record Last Update:	2004-05-19
Spiller Name:	JOHN CAPOSELLA
Spiller Company:	NELSTAD CONCRETE
Spiller Address:	40 HUNTINGTON PL
Spiller County:	001
Spiller Contact:	JOHN CAPOSELLA
Spiller Phone:	(914) 636-8090
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	166657
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MANCINI 5/11/04: Letter to Nelstadt Materials Corp from Joe Mancini, WCDOH dated 3May2004. Closure report by Ira D Conklin has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"1000 UST LEAKING - CALLER DOING ABANDONMENT ON TANK AND DISCOVERED WATER IN IT"

All Materials:

Site ID:	200280
Operable Unit ID:	862078
Operable Unit:	01
Material ID:	515890
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

SPILLS:

Facility ID:	9400648
Facility Type:	ER
Spill Number:	9400648
DER Facility ID:	126495
Site ID:	148664
DEC Region:	3
Closed Date:	1994-04-20
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010
Spill Date:	1994-04-14
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-14
CID:	Not reported
Water Affected:	L.I. SOUND
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-20
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE LEAKING OIL INTO SOUND COAST GUARD WILL RESPOND PO NOWACK STORM DRAIN OUTFALL SHEEN PRESENTED BUT NOT RECOVERABLE RECURRING PROBLEM"

All Materials:

Site ID:	148664
Operable Unit ID:	994366
Operable Unit:	01
Material ID:	558757
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Permit Number:	NYR00D345
State-Region:	03
Expiration Date:	03/31/2012

NELSTAD MATERIAL CORP (Continued) **S102154943**

Current Major Minor Status:	Minor
Primary Facility SIC Code:	3273
State Water Body Name:	ECHO BAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.912861 / -73.772611
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP
Non-Gov Permit Street Address:	NELSTAD MATERIAL CORP
Non-Gov Permit Supplemental Location:	40 HUNTINGTON PL
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Permit Street Address:	40 HUNTINGTON PL
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported

404
SW
1/4-1/2
0.489 mi.
2583 ft.

NEW ROCHELLE LEAF TS **NY SWF/LF** **S103592520**
85 BEECHWOOD AVE **N/A**
NEW ROCHELLE, NY 10801

Relative:
Lower

Actual:
57 ft.

SWF/LF:

Flag:	ACTIVE
Region Code:	3
Phone Number:	9146542129
Owner Name:	Westchester County
Owner Type:	Municipal
Owner Address:	270 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Email:	Not reported
Owner Phone:	9146373031
Contact Name:	Alexander Tergis
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	atergis@newrochelleny.com
Contact Phone:	9146542136
Activity Desc:	Transfer station - registration
Activity Number:	[60R19]
Active:	Yes
East Coordinate:	603779
North Coordinate:	4529858
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Yard Waste;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #:	60R19
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	City Of New Rochelle
Operator Type:	Not reported
Laste Date:	Not reported

405
SE
1/4-1/2
0.490 mi.
2587 ft.

NORTH EVARTS
44 NORTH EVARTS AVE
ELSMFORD, NY

NY LTANKS

S104620864
N/A

Relative:
Lower

Actual:
40 ft.

LTANKS:

Facility ID:	9913333
Site ID:	74554
Closed Date:	2005-02-26
Spill Number:	9913333
Spill Date:	2000-02-24
Spill Cause:	Tank Failure
Spill Source:	Vessel
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	True
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2005-02-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	44 NORTH EVARTS AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	69944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 2/26/05 surface spill from bilge tank on boat--j omara handled-close "
Remarks:	"bilge tank on boat ruptured - spill to soil and some contained in a catch basin - ny boat reg ny4947ju - fire dept and haz mat on scene- "
	Not reported

All Materials:

Site ID:	74554
Operable Unit ID:	1087874
Operable Unit:	01
Material ID:	295189
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BN406 **HERNANDEZ - TTF** **NY LTANKS** **S117853761**
NW **70 REMINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.491 mi.
2590 ft. **Site 2 of 2 in cluster BN**

Relative: **Lower**
Actual: **94 ft.**

LTANKS:

Facility ID:	1411959
Site ID:	505764
Closed Date:	2015-06-16
Spill Number:	1411959
Spill Date:	2015-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-23
Spill Record Last Update:	2015-06-17
Spiller Name:	DAISE Hernandez
Spiller Company:	Hernandez
Spiller Address:	70 REMINGTON PLACE
Spiller County:	999
Spiller Contact:	DAISE FENANDEZ
Spiller Phone:	(914) 563-3381
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	460572
DEC Memo:	"3-23-15: V.Mc call to Ms.Fenandez: Parents house, will speak w/Mom and try to find out age of house/UST and callbk w/update. Noted: gen. life time of UST 20 to 25 years, re-test Vs. remove. 6/16/15: UST removed by Envirostar. No evidence of leak or contamination was found. Tank Closure report entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
	Not reported
Remarks:	"caller reporting a failed tank test, tank is a 550 gallon tank. repair and retest tank"

All Materials:

Site ID:	505764
Operable Unit ID:	1255071
Operable Unit:	01
Material ID:	2257761
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported

HERNANDEZ - TTF (Continued) **S117853761**

Recovered: Not reported
Oxygenate: Not reported

407
NNE
1/4-1/2
0.491 mi.
2590 ft.

7-UP BOTTLING CO **NY LTANKS** **S100560336**
PALMER AVE & CEDAR ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
28 ft.

LTANKS:

Facility ID:	9302874
Site ID:	60684
Closed Date:	1999-08-02
Spill Number:	9302874
Spill Date:	1993-06-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-12-08
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1993-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-08
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59196
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/08/94: CONTRACTOR WAS FENLEY AND NICOL. TANK PULLED AND CONTA. SOIL REMOVEDFROM PIT. TANK REMOVAL REPORT WAS REQUESTED BUT NOT RECIEVED. 08/02/99: FINAL CLOSURE REPORT RECEIVED FROM GIBSON, DUNN & CRUTCHER ON 7/27/99; SENT TO TARRYTOWN OFFICE. "
Remarks:	"TANK PULL DEC (TODD) IS AWARE OF AND HANDLING SPILL"

All Materials:

Site ID:	60684
Operable Unit ID:	981198
Operable Unit:	01
Material ID:	399984
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported

7-UP BOTTLING CO (Continued) **S100560336**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Count: 8 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NEW ROCHELLE	1007740476	NEW ROCHELLE CREEK CABLES	ADJACENT TO GLEN ISLAND BRIDGE	10804	FINDS
NEW ROCHELLE	S108467789	SIDEWALK / IN FRONT OF NE	HARRISON STREET		NY LTANKS
NEW ROCHELLE	S118707739	APARTMENT BUILDING	60-70 LOCUST AVE		NY LTANKS
NEW ROCHELLE	S100153602	N.SHORE LONG ISLAND SOUND	NEW ROCHELLE TO DANBURY		NY LTANKS
NEW ROCHELLE	S110248231	VALU CLEAN CLEANERS	1335 A NORTH AVE.	10804	NY DRYCLEANERS
NEW ROCHELLE	S105684699	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY VCP
NEW ROCHELLE	S113916612	MEARL CORP.	PALMER AVE	10801	NY SHWS
NEW ROCHELLE	S117975694	MM 5.4 LEFT LANE	I-95 SOUTHBOUND		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 04/16/2018
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 04/16/2018
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 01/05/2018
Next Scheduled EDR Contact: 04/16/2018
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 21

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 04/30/2018
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 21

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 04/30/2018
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/22/2017
Date Data Arrived at EDR: 06/13/2017
Date Made Active in Reports: 09/15/2017
Number of Days to Update: 94

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/09/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/13/2017
Date Data Arrived at EDR: 11/27/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 74

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 11/13/2017
Date Data Arrived at EDR: 11/27/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 74

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 01/16/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 63

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/13/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/25/2017
Date Data Arrived at EDR: 11/07/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 31

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/01/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/14/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/14/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/26/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/24/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/16/2018
Number of Days to Update: 30
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/09/2018
Next Scheduled EDR Contact: 04/23/2018
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/22/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/22/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/22/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/22/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/26/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 05/02/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/13/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/14/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/06/2017
Number of Days to Update: 71

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Semi-Annually

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/24/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 134

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/01/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/25/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 78

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/23/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/22/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 34
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 06/27/2017
Date Data Arrived at EDR: 09/21/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 1
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 10/04/2017
Date Data Arrived at EDR: 10/06/2017
Date Made Active in Reports: 11/13/2017
Number of Days to Update: 38

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/15/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 01/19/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 12/12/2017
Date Data Arrived at EDR: 12/14/2017
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/30/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/22/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 02/02/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 01/19/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 16

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 16

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/16/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 39

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 02/05/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 01/19/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 63

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/16/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/21/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/13/2017
Next Scheduled EDR Contact: 01/22/2018
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/11/2017
Next Scheduled EDR Contact: 01/22/2018
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/16/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 01/11/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/31/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/08/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/25/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 21

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/09/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 11/02/2017
Date Data Arrived at EDR: 11/17/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2017
Date Data Arrived at EDR: 06/09/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 126

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/12/2018
Next Scheduled EDR Contact: 04/23/2018
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 01/09/2018
Next Scheduled EDR Contact: 04/23/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 03/09/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/06/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/26/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/02/2017
Date Data Arrived at EDR: 10/05/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/05/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 11/10/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 63

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/09/2018
Next Scheduled EDR Contact: 04/23/2018
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 12/23/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/17/2017
Number of Days to Update: 52

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/19/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 24

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 02/06/2018
Next Scheduled EDR Contact: 05/21/2018
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 10/29/2017
Date Data Arrived at EDR: 11/28/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 45

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/28/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/20/2017
Date Data Arrived at EDR: 12/21/2017
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 92

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/21/2018
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 28

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 06/27/2017
Date Data Arrived at EDR: 11/21/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2016
Date Data Arrived at EDR: 10/31/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 73

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/02/2018
Next Scheduled EDR Contact: 04/30/2018
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/13/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/20/2018
Date Data Arrived at EDR: 02/21/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 30

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/21/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 02/07/2018
Date Data Arrived at EDR: 02/13/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/22/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 09/25/2017
Date Data Arrived at EDR: 09/26/2017
Date Made Active in Reports: 10/12/2017
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 11/22/2017
Date Data Arrived at EDR: 12/14/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 46

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 10/31/2017
Date Data Arrived at EDR: 12/20/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 40

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 12/01/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 03/09/2017
Date Data Arrived at EDR: 04/12/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 184

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/31/2018
Date Made Active in Reports: 03/09/2018
Number of Days to Update: 37

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/31/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/25/2017
Date Data Arrived at EDR: 10/27/2017
Date Made Active in Reports: 11/28/2017
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 03/14/2018
Next Scheduled EDR Contact: 05/07/2018
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2018
Date Data Arrived at EDR: 02/15/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/15/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/04/2018
Date Data Arrived at EDR: 03/08/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/08/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/01/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/01/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/05/2018
Date Data Arrived at EDR: 02/20/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 35
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Semi-Annually

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/05/2018
Date Data Arrived at EDR: 02/20/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 35

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/29/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 01/03/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/22/2018
Number of Days to Update: 36

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/14/2018
Next Scheduled EDR Contact: 05/28/2018
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/11/2017
Date Made Active in Reports: 07/27/2017
Number of Days to Update: 107

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/05/2018
Next Scheduled EDR Contact: 04/23/2018
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 07/25/2017
Date Made Active in Reports: 09/25/2017
Number of Days to Update: 62

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/16/2018
Next Scheduled EDR Contact: 04/30/2018
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/21/2018
Next Scheduled EDR Contact: 06/04/2018
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 01/12/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 02/13/2018
Number of Days to Update: 25

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/12/2018
Next Scheduled EDR Contact: 04/30/2018
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/13/2017
Date Made Active in Reports: 07/14/2017
Number of Days to Update: 92

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/08/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

BLACKSTONE
CONSULTING LLC

FANNIE MAE
PHASE I ENVIRONMENTAL SITE ASSESSMENT

La Rochelle
255 and 275 Huguenot Street
New Rochelle, Westchester County, New York 10801

Prepared For:

Walker & Dunlop
Atlanta, Georgia

Prepared By:

Blackstone Consulting LLC
Project No. WALKGA136.01

June 3, 2016

TABLE OF CONTENTS

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS i
EXECUTIVE SUMMARY ii
1.0 INTRODUCTION 1
1.1 Purpose 1
1.2 Special Terms and Conditions 2
1.3 Scope of Services 2
1.4 Significant Assumptions and Data Gaps 3
2.0 USER PROVIDED INFORMATION 5
2.1 Reason For Performing the Phase I ESA 5
2.2 Environmental Liens and Activity Use And Limitations (AULs) 5
2.3 Specialized Knowledge, Commonly Known & Degree of Obviousness 6
2.4 Value Reduction for Environmental Issues 6
2.5 Owner, Key Site Manager, and Occupant Information 6
2.6 Past Owners, Operators and Occupant Interviews 7
2.7 Reliance 7
3.0 SITE DESCRIPTION 8
3.1 Site Characteristics and Features 8
3.2 Utilities 9
4.0 VICINITY RECONNAISSANCE 11
5.0 PHYSICAL SETTING 12
6.0 HISTORICAL INFORMATION REVIEW 13
6.1 Historical Fire Insurance Maps 13
6.2 Aerial Photographs 15
6.3 Historical Topographic Maps 16
6.4 Agency Records, Interviews and Other Historical Sources 16
6.5 City Directories 17
6.6 Environmental Lien/AUL Search 18
6.7 Previous Environmental Reports 18
6.8 Historical Information Conclusions 18
7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW 20
7.1 Federal, State, Local, Tribal and Proprietary Databases 20
7.2 Unmappable Facilities 25
7.3 Affirmation 25
7.4 Environmental Database Search and Review Conclusions 25
8.0 SITE INSPECTION 26
8.1 Underground Storage Tanks (USTs) 26
8.2 Aboveground Storage Tanks (ASTs) 26
8.3 Chemicals and Materials Usage 27
8.4 Hazardous Wastes 27
8.5 Non-Hazardous Wastes 27
8.6 Polychlorinated Biphenyls (PCBs) 28
8.7 Wastewater Discharges 29
8.8 Stormwater Discharges 29
8.9 Pits, Ponds, and Lagoons (On-site Process Water Discharge) 29

8.10 Wells 29
8.11 Underground Product Pipelines 30
8.12 Odors 30
8.13 Pools of Liquid 30
8.14 Stressed Vegetation or Stained Surfaces 30
8.15 Site Inspection Conclusions 31
9.0 ASTM NON-SCOPE CONSIDERATIONS 32
9.1 Asbestos-Containing Materials (ACM) 32
9.2 Lead-Based Paint (LBP) 32
9.3 Radon Gas 32
9.4 Apparent Mold Growth (AMG) 33
9.5 Lead In Drinking Water 33
9.6 Wetlands 33
10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS 35

APPENDICES

Appendix A: Site Maps, Plans and Photographs
- Site Location Map
- Site Plan
- Site Photographs

Appendix B: Historical Sources
- Historical Fire Insurance Maps
- Historical Aerial Photographs
- Historical Topographic Maps


Appendix C: Environmental Database Search Report
Appendix D: Qualifications of Professionals

SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

This Phase I Environmental Site Assessment (ESA) Report documents the research methodology used by qualified environmental professionals of Blackstone to identify recognized environmental conditions using the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone.


We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR 312, and we have the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Prepared By:




John O'Connor — 06/03/16
Senior Project Manager — Date

Technical Review and Concurrence By:



Allan S. Coffee — 06/03/16
Senior Associate — Date

Principal Review By:



Stephen E. Manelis — 06/03/16
Principal — Date

dd

EXECUTIVE SUMMARY

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the La Rochelle located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York (site). The purpose of the Phase I ESA is to identify recognized environmental conditions (RECs) in general accordance with ASTM Standard E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide, dated April 29, 2011 (Fannie Mae DUS Guidelines), and other agreed-upon ASTM *Non-Scope Considerations (Business Environmental Risk Issues)*. It is understood that the site is being evaluated for loan considerations.

SITE INSPECTION

Name of Inspector: John O'Connor

Date of Inspection: May 25, 2016

Site Representative: Ms. Kimberly Periard, Community Manager, and Mr. Lennie Dawson, Maintenance Technician

SITE DESCRIPTION

Street Address: 255 and 275 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Tax Map Identification Numbers: 1-234-0001 (Apartment Building) and 2-418-0001 (Parking Garage)

Owner: New Rochelle Ind. Development Agency (Apartment Building)
Avalon Bay Communities Inc. (Parking Garage)

Site Size: Approximately 2.3 acres

Site Use: The site is developed with a 24-story apartment building, containing 412 total dwelling units, and a five-story parking structure. The site apartment building includes basement and penthouse mechanical levels, four street level commercial tenant spaces, and a single-story building extension containing the apartment amenities. Two of the commercial spaces are currently vacant and the remaining two are currently occupied by Sound Drycleaners (drop-off/pick-up only) and Metro Market (convenience store). The site property is bisected by Memorial Highway, which separates the parking garage from the apartment tower building; however, the apartment building and parking

garage are connected via a covered, elevated walkway over Memorial Highway.

Year Built: 2001

Structures	***Location On Site***	***Number of Stories***	***Size (approx. square feet)***
Apartment Building	Northern	24 with basement and penthouse mechanical levels	431,125 SF
Parking Garage	Southern	5	180,000

Other Site Features: Amenities and additional features at the site include a leasing/management office, a club room, a conference room, a common tenant laundry room, a fitness center, a yoga room, a tot room, an outdoor in-ground swimming pool, a picnic area, and a playground. Vertical transportation for the apartment building is provided by four cable-driven elevators. The remainder of the site consists concrete pedestrian walkways and moderate landscape features.

HISTORICAL INFORMATION

Reasonably ascertainable historical information indicates the site was initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. Historical commercial uses of the site included hotels, office space, retail stores, restaurants, a post office, a bowling alley, a theater, a "Chinese laundry" (1911 only), an auto sales and service facility (southwest corner from the 1930s until the 1980s), and surface parking lots. The former site structures were demolished between the early and mid-1990s, and the site was redeveloped with the present-day high rise apartment building and the present-day parking garage in 2001.

The site was identified with a small "Chinese laundry" facility in 1911. This type of facility in this era was typically a hand washing operation. The use of chlorinated solvents was not introduced into the dry cleaning industry until the late 1930s, and its use became widespread in the late 1940s following World War II. No addition historic cleaners or dry cleaning operations are identified on the site. Based on the era of operation and the duration of time since the facility was identified on the site (over 100 years), this laundry facility is not considered a REC.

Sound Drycleaning has been located at the site since at least the mid-2000s. However, this tenant only operated as a drop-off/pick-up only location, and is not involved in active drycleaning activities. This site tenant is not identified on any databases indicative of the generation or

disposal of hazardous wastes typically associated with an active drycleaning facility. As such, the site drycleaner tenant is not considered a REC.

The site historically contained an auto sales and service facility in the southwest corner of the site between at least the 1930s and the 1980s. This facility is not identified on any databases indicative of the generation, disposal or release of hazardous materials and/or waste, nor the operation of underground storage tanks (USTs). The site area where this facility was located is directly beneath the present-day site parking garage. There was no report of impacted soil or other remnants of the auto service operation encountered during the development of the site parking structure in 2001. Considering the current regulatory status (no reports releases), the amount of time that has passed since this facility was active (approximately 30 years), and that this site area has been redeveloped with a multi-story parking garage that would have necessitated significant excavation during construction, the historical presence of the auto sales and service facility in the southwest corner of the site is not considered a REC.

Historical information reviewed identified a 2000-gallon gasoline UST on the central-western area of the site, near the intersection of Memorial Highway and Railroad Place. According to the regulatory database, the UST was removed from the site on February 1, 2000, with some impacted soil discovered during removal. Based on the minor soil impacts discovered during removal, the site was listed with a Spills case. However, following the over-excavation of the UST area, all of the impacted soil was removed, the cleanup work was identified as having met applicable standards, and the case was issued regulatory closure on April 4, 2000. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current status (UST and impacted soil removed, regulatory closure issued and that the area of the UST has since been redeveloped with a high-rise apartment building with a basement level that required significant site excavation to develop, the historical presence of the UST at the site is not considered a REC.

The north and east-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures between the late 1800s and the late 1900s, including a drycleaning facility in the 1930s in the southern portion of the east-adjoining property, prior to the construction of the present-day improvements. The present-day surface parking lot to the adjoining east was constructed in the 1970s. The present-day Ruby Dee Park on Library Green was developed in the 2000s, the present-day Halstead New Rochelle apartment building to the adjoining east was constructed in the late 2000s, and the commercial development located in the southern portion of the east-adjoining property was constructed in the mid-1900s. The present-day Trinity St. Paul Anglican Episcopal Church to the adjoining south beyond Division Street was reportedly constructed in the 1860s. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

A "Chinese laundry" facility was historically located to the adjoining north in at least 1911 and a drycleaning facility was located in the southern portion of the east-adjoining property in at least the 1930s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. As stated previously, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. No addition cleaners or dry cleaning operations are identified on adjacent properties. Based on the era of operation and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities on the adjoining properties is not considered a REC.

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*) in connection with the site. No further investigation is recommended.

This section is only intended to represent a brief summary of our findings, and is not a detailed account of all the information provided in this report. The report should be reviewed in its entirety prior to drawing any final conclusions as to potential environmental conditions associated with the site.

1.0 INTRODUCTION

1.1 PURPOSE

Blackstone Consulting LLC (Blackstone) performed a Phase I Environmental Site Assessment (Phase I ESA) of the La Rochelle located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York (site).

The purpose of this Phase I ESA is to investigate and identify *recognized environmental conditions* (*RECs*) associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines RECs as:

The presence or likely presence of any hazardous substances or petroleum products in, on, or at a property due to any release to the environment, under conditions indicative of a release to the environment, or under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions.

A *de minimis condition* is a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

Additionally, this Phase I ESA was conducted to identify *controlled recognized environmental conditions (CRECs)* associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines CRECs as:

A recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by a regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This Phase I ESA also was conducted to identify *historical recognized environmental conditions* (*HRECs*) associated with the site and/or surrounding properties. ASTM Standard Practice E 1527-13 defines HRECs as:

A past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

This practice is generally intended for the User to satisfy one of the requirements to qualify for the *innocent landowner, contiguous property owner,* or *bona fide prospective purchaser* limitations on CERCLA liability; that is, this practice constitutes all appropriate inquiries (AAI) into the

previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312.

ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) are detailed in Section 1.3 and outlined in the accepted scope detailed in the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone.

1.2 SPECIAL TERMS AND CONDITIONS

This Phase I ESA has been conducted in accordance with ASTM Standard Practice E 1527-13, the regulations at 40 CFR Part 312, and the Agreement between Walker & Dunlop and Blackstone. In addition, this Phase I ESA was conducted in accordance with the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide, dated April 29, 2011 (Fannie Mae DUS Guidelines). Qualifications of the professionals conducting this assessment have been provided in Appendix D.

Blackstone performed the professional services, obtained findings, rendered conclusions, and prepared recommendations in accordance with generally accepted practices of other environmental consultants undertaking similar assessments at the same time in the same geographical area.

Historical and environmental information pertaining to the site has been included in this report to the extent that such information is *practically reviewable*, as defined in the above-referenced standard practice.

1.3 SCOPE OF SERVICES

As detailed in the Agreement, this Phase I ESA was conducted in accordance with the industry standard ASTM Standard Practice E 1527-13 and as such in accordance with all appropriate inquiries (AAI) into the previous ownership and uses of the site consistent with good commercial or customary practice as defined at 42 U.S.C. §9601(35)(B) and the regulations at 40 CFR Part 312. In addition, this Phase I ESA was conducted in accordance with the Fannie Mae DUS Guidelines. The Phase I ESA presented herein may vary from "guidelines" or "standards" required by organizations other than ASTM and Fannie Mae. This Phase I ESA included the following services:

1. A site inspection to identify and evaluate potential sources of RECs such as underground storage tanks (USTs), aboveground storage tanks (ASTs), equipment containing polychlorinated biphenyls (PCBs), waste and chemical storage areas, and wastewater and storm water discharges. The inspection included observations for evidence of chemical spills, releases, or on site waste disposal.

2. A review of site records and interviews with site representatives with regard to current and former site operations to identify known or potential environmental concerns.

3. A visual survey of the properties in the vicinity of the site to evaluate the potential for RECs at the site from these properties.

4. A review of historical information to identify RECs at the site from historic on-site and off-site uses. To the extent feasible under the conditions of the assessment, the historical information obtained included verbal information from site and/or local agency representatives. In addition, some or all of the following records, where *publicly available* and *practically reviewable*, were reviewed: construction plans, zoning maps, building permits, property record cards, topographic maps, fire insurance maps, historical city directories, and aerial photographs.

5. A review of State and Federal environmental database information.

Blackstone also performed the following activities to identify *Business Environmental Risk Issues* in addition to the ASTM requirements and as required by the Fannie Mae DUS Guidelines, and as required per the Agreement:

Document research, visual and/or sampling surveys, and interviews for the presence of:

- Asbestos-containing materials (ACM),
- Lead-based paint (LBP),
- Radon,
- Apparent mold growth (AMG),
- Lead in Drinking Water, and
- Wetlands.

The scope of this Phase I ESA did not include surface water, soil, soil vapor, or groundwater sampling. Consequently, conclusions provided with regard to surface water, soil, soil vapor, and groundwater impacts are limited to those that can be formed based on a non-intrusive investigation. The absence of environmental hazards in the subsurface cannot be guaranteed based on conditions observed on the surface.

Where performed, the limited ACM, LBP, AMG, and radon surveys are intended to provide an indication of the potential for significant environmental issues associated with these ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*). Hidden materials or locations such as those inside walls, inaccessible attics, crawl spaces, and inside ductwork and piping were not evaluated. As such, these surveys should not be regarded as comprehensive surveys for demolition or renovation purposes or indoor air quality health risk assessments, vapor intrusion into buildings, or explosion hazards.

1.4 SIGNIFICANT ASSUMPTIONS AND DATA GAPS

The site inspection consisted of a walkover of the site perimeter and exterior site areas, and a walk-through of the leasing office, common areas, maintenance/storage areas, mechanical rooms, parking garage, the commercial tenant spaces, and 42 representative dwelling units selected by Blackstone (Units 107, 117, 201, 202, 204, 310, 316, 402, 405, 410, 415, 1601, 1604, 1608, 1616, 1703,

1718, 1803, 1806, 1816, 1902, 1903, 1909, 1915, 2005, 2006, 2013, 2017, 2105, 2109, 2114, 2203, 2217, 2315, 2316, 2409, 2411, 2418, 2507, 2508, 2511, and 2516). The building interior was walked through at the direction of the Site Representative. Not all dwelling units were entered nor were all common and/or storage areas observed. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within the elevator pits. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

The historical information reviewed did not confirm the first developed use of the site. *Data failure*, as defined by ASTM, has occurred in attempting to identify obvious uses of the site back to the first developed use, or back to 1940, whichever is earlier. Information regarding the use of the site prior to 1887 was not available from the *standard historical sources* (including available aerial photographs, fire insurance maps, property tax files, recorded land title records, USGS topographic maps, local street directories, building department records, or zoning/land use records). There were no other reasonably ascertainable historical sources available for review that were considered sufficiently useful. It is the opinion of Blackstone that the data failure does not represent a significant data gap that impacts our ability to identify RECs.

Conclusions stated herein are based upon publicly available information and other documented sources. Blackstone has assumed, where reasonable, that the information reviewed is true and accurate. Blackstone assumes no responsibility for inaccurate information that is not otherwise obvious in light of information of which Blackstone has actual knowledge. Blackstone's site observations are of the conditions observed at the time of the assessment.

Blackstone reviewed an environmental database search report. Blackstone's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, Blackstone's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site.

This report provides an estimation of groundwater flow direction at the site based on visual observations and topographical data. This assessment did not include groundwater sampling and water table elevation measurement. True groundwater flow direction can only be determined through direct measurement of groundwater elevations from properly installed on-site groundwater monitoring wells. The groundwater flow direction estimation should not be considered a true measurement of groundwater flow direction.

2.0 USER PROVIDED INFORMATION

As defined under ASTM Standard Practice E 1527-13, Walker & Dunlop and Fannie Mae are considered the "User" of this Phase I ESA report. To qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002 (the "*Brownfields Amendments")*, the User must provide certain information based on their relationship to the purpose of the due diligence and as required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31.

As part of this Phase I ESA, Blackstone requested certain information from the User. The User did not provide the requested information to Blackstone pursuant to the User's Responsibilities described in ASTM Standard Practice E 1527-13 (Section 6.0) and as outlined below in Sections 2.2 through 2.4. However, there is no reason to believe that the absence of the User provided information would significantly alter the findings or recommendations set forth in this report or be considered a significant data gap.

The owner's representatives, Ms. Kimberly Periard, Community Manager, and Mr. Lennie Dawson, Maintenance Technician (collectively "Site Representative"), provided information about the site. The information requested and associated responses are outlined below in Section 2.5.

2.1 REASON FOR PERFORMING THE PHASE I ESA

Blackstone understands that this assessment was performed for Walker & Dunlop for financing purposes. In addition, this assessment was performed for Fannie Mae in consideration of making a potential loan secured by the site. As such, this Phase I ESA was performed as an appropriate risk management and environmental due diligence review associated with a potential real-estate collateralized lending transaction.

2.2 ENVIRONMENTAL LIENS AND ACTIVITY USE AND LIMITATIONS (AULS)

With reference to environmental liens that are filed or recorded against the site (40 CFR 312.25) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an environmental lien search as part of the scope of work.

With reference to activity and use limitations (AULs) that are in place on the site or that have been filed or recorded against the site (40 CFR 312.26(a)(1)(v) and (vi)) in recorded land title records or judicial records, the User did not provide this information to Blackstone or request Blackstone to perform an AUL search as part of the scope of work. In accordance with ASTM E 1527-13, Blackstone reviewed an environmental database search report that included a search of institutional control and engineering control databases as further discussed in Section 7.0.

2.3 SPECIALIZED KNOWLEDGE, COMMONLY KNOWN & DEGREE OF OBVIOUSNESS

With reference to specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28), the User did not provide any information to Blackstone regarding specialized knowledge or experience related to the site or nearby properties.

With reference to commonly known or *reasonably ascertainable* information about the site (40 CFR 312.30), the User did not provide any information to Blackstone regarding commonly known or *reasonably ascertainable* information about the site that would help the *environmental professional* to identify conditions indicative of releases or threatened releases, such as:

1. Past uses of the site;
2. Specific chemicals that are present or once were present at the site;
3. Spills or other chemical releases that have taken place at the site; and
4. Environmental cleanups that have taken place at the site.

The User provided Blackstone with a prior environmental report for the site, which is further discussed in Section 6.7.

With reference to the degree of obviousness of the presence or likely presence of releases or threatened releases at the site, and the ability to detect releases or threatened releases by appropriate investigation (40 CFR 312.31), the User did not provide any information to Blackstone regarding *obvious* indicators that point to the presence or likely presence of releases at the site.

2.4 VALUE REDUCTION FOR ENVIRONMENTAL ISSUES

The User did not provide information with reference to the relationship of the purchase price to the fair market value of the site if contamination is known or believed to be present at the site (40 CFR 312.29).

2.5 OWNER, KEY SITE MANAGER, AND OCCUPANT INFORMATION

Blackstone interviewed the Site Representative (including the Key Site Manager) regarding environmental conditions at the site. The Site Representative was not aware of: (1) pending, threatened, or past litigation relevant to environmental conditions on the site; (2) any pending, threatened, or past administrative proceedings relevant to environmental conditions in, on, or from the site; and (3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to environmental conditions on the site.

The site owner was not available to provide information regarding the environmental conditions at the site. In addition, as the site is used for multi-family residential purposes, the occupants were not interviewed.

2.6 PAST OWNERS, OPERATORS AND OCCUPANT INTERVIEWS

In accordance with ASTM Standard Practice E 1527-13, interviews with past owners, operators, and occupants shall be conducted to the extent that they have been identified and that the information likely to be obtained is not duplicative of information already obtained. There is no reason to believe that such interviews were necessary for this site or would alter the findings or recommendations set forth in this report.

2.7 RELIANCE

Blackstone performed this Phase I ESA on behalf of and exclusively for Walker & Dunlop and Fannie Mae and each of their affiliates, attorneys, lenders, investors, successors and each of their assigns subject to the terms and conditions of the Agreement between Walker & Dunlop and Blackstone. This report is addressed to Walker & Dunlop and its affiliates. Walker & Dunlop and its affiliates, their respective successors and assigns (including, without limitation, investors who purchase the mortgage loan or a participation interest in the mortgage loan and the trustee in a securitization that includes the mortgage loan), each servicer of the mortgage loan, and all rating agencies involved in any sale, securitization or syndication involving the mortgage loan may use and rely upon this Report, including, without limitation, utilizing selected information from the Report in the offering materials (either in electronic or hard copy format) relating to any sale, securitization or syndication involving the mortgage loan. The Assessor agrees to cooperate in answering questions by any of the above parties in connection with the sale, securitization or syndication, as communicated by Walker & Dunlop personnel.

In addition, this assessment is subject to the stated limitations of the above-referenced Fannie Mae DUS Guidelines and other qualifications as described within the report. Any reliance upon this report by third parties beyond its intended purpose shall be at the parties' sole risk.

3.0 SITE DESCRIPTION

The site is located at 255 and 275 Huguenot Street in New Rochelle, Westchester County, New York. A Site Location Map, depicted on the U.S. Geological Survey (USGS) *Mount Vernon, New York* topographic quadrangle, is included in Appendix A.

3.1 SITE CHARACTERISTICS AND FEATURES

Street Address: 255 and 275 Huguenot Street

City and State: New Rochelle, New York

County: Westchester

Legal Description: City of New Rochelle Tax Map Identification Numbers: 1-234-0001 (Apartment Building) and 2-418-0001 (Parking Garage)

Owner: New Rochelle Ind. Development Agency (Apartment Building)
Avalon Bay Communities Inc. (Parking Garage)

Site Size: Approximately 2.3 acres

Zoning: DMUR (Downtown Mixed Use Urban Renewal District) and is located with the Central Parking Area Overlay District

Site Use: The site is developed with a 24-story apartment building, containing 412 total dwelling units, and a five-story parking structure. The site apartment building includes basement and penthouse mechanical levels, four street level commercial tenant spaces, and a single-story building extension containing the apartment amenities. Two of the commercial spaces are currently vacant and the remaining two are currently occupied by Sound Drycleaners (drop-off/pick-up only) and Metro Market (convenience store). The site property is bisected by Memorial Highway, which separates the parking garage from the apartment tower building; however, the apartment building and parking garage are connected via a covered, elevated walkway over Memorial Highway.

Year Built: 2001

Structure	***Location On Site***	***Number of Stories***	***Size (approx. square feet)***
Apartment Building	Northern	24 with basement and penthouse mechanical levels	431,125 SF
Parking Garage	Southern	5	180,000

Construction Materials	
Apartment Building	The apartment building is structural steel and concrete framed with reinforced concrete beams, columns and floor decks. The foundation systems are presumed to be constructed of a concrete slab below grade with piers at column locations and perimeter grade beams with reinforced concrete foundation walls. The building exterior finishes consist of brick veneer with decorative aluminum elements at the window openings. The low-slope roofs are concrete framed and are primarily covered with IRMA (inverted roof membrane assembly) membranes; the mechanical penthouse low-slope roof is covered with modified bitumen cap sheets.
Parking Garage	The parking garage is reinforced concrete framed with reinforced concrete floor decks.
Heating/Cooling Systems:	Heating is provided by five central, natural gas-fired low-pressure boilers which distribute heated water to individual thru-wall mounted PTAC units within the dwelling units. The PTAC units also contain integral compressors/condensers for cooling. Domestic hot water is provided by four total central, natural gas-fired low-pressure boilers with external storage tanks.
Other Site Features:	Amenities and additional features at the site include a leasing/management office, a club room, a conference room, a common tenant laundry room, a fitness center, a yoga room, a tot room, an outdoor in-ground swimming pool, a picnic area, and a playground. Vertical transportation for the apartment building is provided by four cable-driven elevators. The remainder of the site consists concrete pedestrian walkways and moderate landscape features.

A Site Plan and Site Photographs are provided in Appendix A.

3.2 UTILITIES

Electricity Provider: Con Edison

Natural Gas Provider: Con Edison

Potable Water: United Water New York

Sewer Services: City of New Rochelle

According to the Site Representative, the site has been connected to the municipal systems for sanitary sewage disposal and potable water supply since construction was completed in 2001. The site was previously developed with multiple commercial and residential structures since at least the 1880s. The City of New Rochelle water and sewer systems date back to at least the late 1800s; therefore, it is likely that the former site buildings were connected to the municipal potable water and sanitary sewer systems.

No RECs were identified as a result of the review of the site as described in this section of the report.

4.0 VICINITY RECONNAISSANCE

The site is located in the City of New Rochelle, New York, within an area characterized by urban commercial development. Adjoining property use is summarized as follows:

North: Bridge Street followed by Chase Bank office building (270 North Avenue)

East: Huguenot Street followed by a surface parking lot, the Ruby Dee Park on Library Green, the Halstead New Rochelle apartments (40 Memorial Highway), and commercial development (multiple addresses along Huguenot Street, uses include a florist, a restaurant, and a market)

South: Division Street followed by the Trinity St. Paul Anglican Episcopal Church (311 Huguenot Street)

West: Station Plaza South followed by the New Rochelle train station, parking garage and associated railroad tracks

Source	Findings
Field observations	Blackstone observed no industrial, manufacturing or military operations such as outdoor chemical or hazardous waste storage or handling activities that may impact the site and no evidence of chemical spills, releases, or waste disposal was observed. From accessible vantage points, Blackstone identified no outdoor chemical or waste storage, wastewater treatment facilities, or other operations that may impact the site and no pits, ponds or lagoons for apparent discharge and/or treatment of process water.
Environmental databases search	Adjoining and/or nearby properties identified in the environmental databases searched are further discussed in Section 7.0.

No RECs were identified as a result of the vicinity reconnaissance.

5.0 PHYSICAL SETTING

	Findings	*Sources of Findings*
Surficial Soils Beneath Site	Urban land	EDR Report
Depth to Bedrock	Between 5 and 50 feet bgs	EDR Report
Topography	The site is relatively flat with an overall area declination to the east.	Site observations, USGS *Mount Vernon, New York,* topographic map and EDR Report
Elevation	Approximately 84 feet NAVD	USGS *Mount Vernon, New York,* topographic map and EDR Report
Depth to Shallow Groundwater	Approximately 10-30 feet bgs	EDR Report
Estimated Groundwater Flow Direction	East	USGS *Mount Vernon, New York,* topographic map and EDR Report

bgs: below ground surface
EDR Report: Environmental Data Resources Database Report with GeoCheck®
NAVD: North American Vertical Datum, 1988-1990
USGS: United States Geological Survey

No RECs were identified as a result of the physical setting records review.

6.0 HISTORICAL INFORMATION REVIEW

As part of this Phase I ESA, Blackstone reviewed historical information to identify RECs associated with the historical use of the site and surrounding properties. Blackstone obtained historical information from interviews with site representatives and other individuals familiar with the site as well as aerial photographs, historical maps, and other *practically reviewable* standard historical sources that are considered *reasonably ascertainable*.

6.1 HISTORICAL FIRE INSURANCE MAPS

Environmental Data Resources, Inc. (EDR) conducted a search of available historical fire insurance maps for the site and site vicinity. Historical fire insurance maps are scaled drawings that indicate the location and use of building structures present in a given area from as early as the late 1800s. The maps provide information regarding the development and historical use of site structures and can indicate the historical presence of tanks at the site and other potential environmental concerns.

Sanborn Fire Insurance Company maps were available for the site from EDR. Select Sanborn maps are reproduced in Appendix B and are summarized as follows:

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	Site	Adjoining Properties
1887	The site is depicted with three residential dwellings.	The north and east adjoining properties are depicted with residential and commercial development. The west-adjoining property is depicted with railroad tracks and a railroad passenger depot. The present-day church is depicted to the adjoining south.
1892	Multiple commercial structures are depicted along the northern perimeter of the site.	A portion of the east-adjoining property is depicted with a hospital.
1896	Additional commercial development is depicted at the site, including a hotel, several restaurants, a post office, and multiple offices.	The hospital is no longer depicted to the adjoining east.
1903	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1911	The site is depicted with multiple commercial structures, including a theater and a "Chinese laundry".	The north and east adjoining properties are depicted with urban commercial development. A "Chinese laundry" is depicted to the adjoining north.
1931	The site is depicted with multiple commercial structures, including a bowling alley. A used car sales and storage structure is depicted in the southwest corner of the site.	The north and east adjoining properties are depicted with urban commercial development. A drycleaning facility is depicted to the adjoining east.

SUMMARY OF HISTORICAL SANBORN MAP REVIEW

Year	Site	Adjoining Properties
1942	The former used car storage structure is identified as Hill Motors Corporation Chevrolet.	The adjoining properties are depicted as similar to the previous Sanborn map. The former drycleaning facility is no longer depicted to the adjoining east.
1951	Several surface parking lots are depicted in the northwest corner of the site.	The adjoining properties are depicted as similar to the previous Sanborn map.
1990	The site is depicted with multiple commercial structures and surface parking lots. A gas tank is depicted along the western perimeter of the site, near the intersection of Memorial Highway and Railroad Place (location of the present-day apartment building) adjoining a small retail building (identified with three retail stores).	The present-day office building is depicted to the adjoining north. Commercial development and surface parking lots are depicted to the adjoining east. The present-day church is depicted to the adjoining south. The present-day railroad station is depicted to the adjoining west.
1991	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1992	The site is primarily vacant land and surface parking lots, with one three-tenant retail structure and the adjoining gas tank remaining depicted along the western perimeter.	The adjoining properties are depicted as similar to the previous Sanborn map.
1993	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1994	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1995	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
1996	The site is depicted as similar to the previous Sanborn map.	The adjoining properties are depicted as similar to the previous Sanborn map.
2003	The site is depicted with the present-day apartment building and parking garage. None of the former improvement remain.	The present-day park is depicted to the adjoining east. The location of the present-day apartment building to the adjoining east is depicted as vacant land.

Findings: As further discussed in Section 6.8, the former auto sales and service facility, "Chinese laundry", and gas tank depicted on the site are not considered RECs, and the historical north adjoining "Chinese laundry" and east-adjoining drycleaning facility are not considered a REC. No RECs were identified as a result of the review of historical fire insurance maps.

6.2 AERIAL PHOTOGRAPHS

Aerial photographs of the site area were obtained from EDR. The aerial photographs are reproduced in Appendix B and are summarized as follows:

Year	Aerial Photographs: Development/Land Uses	
	Site	*Adjoining Properties*
1951	The site appears to be developed with multiple commercial structures. The northwest corner of the site appears to be a surface parking lot.	Urban commercial development is visible to the adjoining north and east. The present-day church structure is visible to the adjoining south. Railroad tracks and a presumed rail station are visible to the adjoining west.
1954	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1961	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1966	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1974	The site appears similar to the previous aerial photograph.	The present-day bank structure is visible to the adjoining north. The present-day surface parking lot is visible to the adjoining east.
1980	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1985	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.
1994	The site is primarily vacant land, with a surface parking lot visible in the northeast corner of the site and a small commercial-type structure along the western perimeter.	The adjoining properties appear similar to the previous aerial photograph.
2006	The site is developed with the present-day apartment building and parking garage.	The present-day park area is visible to the adjoining east. The present-day east-adjoining apartment building appears to be undergoing development.
2009	The site appears similar to the previous aerial photograph.	The present-day apartment building to the adjoining east is visible.
2011	The site appears similar to the previous aerial photograph.	The adjoining properties appear similar to the previous aerial photograph.

Findings: No RECs were identified as a result of the review of historical aerial photographs.

6.3 HISTORICAL TOPOGRAPHIC MAPS

Historical topographic maps of the site area were obtained from EDR. The historical topographic maps are included in Appendix B and are summarized as follows:

Year	Historical Topographic Maps: Development/Land Uses	
	Site	*Adjoining Properties*
1897	The site is depicted with areas of black shading (indicative of areas covered with buildings).	The adjoining properties are depicted with areas of black shading. Railroad tracks are depicted to the adjoining west.
1898	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1900	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1947	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1956	The site is depicted with pink shading (indicative of dense urban development).	The adjoining properties are depicted with pink shading. Railroad tracks are depicted to the adjoining west.
1966	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1979	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
1995	The site is depicted as similar to the previous topographic map.	The adjoining properties are depicted as similar to the previous topographic map.
2013	The 2013 topographic map does not include structures or shading (similar to a street map, except with contour lines).	

Findings: No RECs were identified as a result of the review of historical topographic maps.

6.4 AGENCY RECORDS, INTERVIEWS AND OTHER HISTORICAL SOURCES

In accordance with ASTM E1527-13, Blackstone requested site history and/or regulatory information regarding the site from federal, state and/or local government officials. Information regarding the site is obtained from regulatory agency officials either by:

1) Conducting interviews by telephone or in-person at various federal, state and/or local agencies; or

2) Requesting file information via submission of an open records request to the appropriate agency contact based upon applicable agency requirements, and in accordance with the Freedom of Information Act (FOIA).

Findings from the interviews/records review are summarized below:

Agency Records, Interviews and Other Historical Sources		
Source	*Information Requested*	*Findings*
City of New Rochelle Tax Assessor website	On-line query for development, ownership information, and tax assessment data.	No environmental concerns were identified. Typical site ownership and tax assessment data were obtained.
City of New Rochelle, City Clerk, FOIL Request Form, via email cityclerkinfo@newrochelleny.com	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any emergency environmental responses or incidents	A FOIA request was submitted to this agency. A response has not been received to date and is not considered reasonably ascertainable for inclusion in this report.
Zoning Map of the City of New Rochelle, New York, revised December 14, 2010	Zoning information	The site is zoned DMUR (Downtown Mixed Use Urban Renewal District) and is located with the Central Parking Area Overlay District.
New York State Department of Environmental Conservation (NYSDEC), online database	On-line spills incident, Petroleum Bulk Storage (PBS), and remediation database	Information obtained from the NYSDEC database is discussed in pertinent sections of the report.
NYSDEC FOIL Coordinator, via email (no name provided) access.records@dec.ny.gov	Aboveground and/or underground storage tanks, past hazardous materials spills, and/or any records of emergency environmental responses or incidents	A FOIA request was submitted to this agency. To date a response has not been received and available records are not considered reasonably ascertainable for inclusion in this report.

Findings: No RECs were identified from the review of the local agency records, interviews, or other readily available historical sources.

6.5 CITY DIRECTORIES

Blackstone requested a city directory review for the site address from EDR. City directories were reviewed at approximately five-year intervals for the years spanning 1972 through 2013. The present-day site address of 255 Huguenot Street was identified as the Portuguese American Club in the 1987 city directory and as the Avalon on the Sound Apartments with multiple residential listings in the city directories dated between 2003 and 2013. The present-day site address of 275 Huguenot Street was not identified in the city directories provided for review. The historical site addresses of 245-295 Huguenot Street (odd), 58-73 Memorial Highway (odd and even) and 55-65 Division Street (odd) was primarily identified with multiple commercial listings, including restaurants, offices, and retail outlets, in the city directories dated between 1972 and 1992. No listings of environmental concern were identified for the site.

The north-adjoining property at 270 North Avenue was identified as the National Bank of Westchester and professional office listings in the city directories dated between 1972 and 1982 and as Chase Bank and professional office listings in the city directories dated between 1987 and

2013. The east-adjoining properties are primarily identified with commercial listings in the city directories dated between 1972 and 2013. The east-adjoining property at 40 Memorial Highway is identified with multiple residential listings in the 2013 city directory. The south-adjoining property at 311 Huguenot Street is identified as the Trinity Episcopal Church in the city directories dated between 1972 and 2013. No listings of environmental concern were identified for the site.

No RECs were identified during the review of city directories.

6.6 ENVIRONMENTAL LIEN/AUL SEARCH

As previously discussed in Section 2.2, an environmental lien and activity & use limitation (AUL) search was not included in the scope of this assessment and was not provided to Blackstone for review by the User.

6.7 PREVIOUS ENVIRONMENTAL REPORTS

Blackstone was not provided with any previous environmental reports for review regarding the site.

6.8 HISTORICAL INFORMATION CONCLUSIONS

Reasonably ascertainable historical information indicates the site was initially developed with residential structures prior to 1887. By 1900, the northern majority of the site was developed with commercial buildings, and by 1930, the entire site was densely developed with numerous commercial structures containing multiple small businesses, primarily retail storefronts, with commercial businesses and hotels on the upper floors. Historical commercial uses of the site included hotels, office space, retail stores, restaurants, a post office, a bowling alley, a theater, a "Chinese laundry" (1911 only), an auto sales and service facility (southwest corner from the 1930s until the 1980s), and surface parking lots. The former site structures were demolished between the early and mid-1990s, and the site was redeveloped with the present-day high rise apartment building and the present-day parking garage in 2001.

The site was identified with a small "Chinese laundry" facility in 1911. This type of facility in this era was typically a hand washing operation. The use of chlorinated solvents was not introduced into the dry cleaning industry until the late 1930s, and its use became widespread in the late 1940s following World War II. No addition historic cleaners or dry cleaning operations are identified on the site. Based on the era of operation and the duration of time since the facility was identified on the site (over 100 years), this laundry facility is not considered a REC.

Sound Drycleaning has been located at the site since at least the mid-2000s. However, this tenant only operated as a drop-off/pick-up only location, and is not involved in active drycleaning activities. This site tenant is not identified on any databases indicative of the generation or disposal of hazardous wastes typically associated with an active drycleaning facility. As such, the site drycleaner tenant is not considered a REC.

The site historically contained an auto sales and service facility in the southwest corner of the site between at least the 1930s and the 1980s. This facility is not identified on any databases indicative of the generation, disposal or release of hazardous materials and/or waste, nor the operation of underground storage tanks (USTs). The site area where this facility was located is directly beneath the present-day site parking garage. There was no report of impacted soil or other remnants of the auto service operation encountered during the development of the site parking structure in 2001. Considering the current regulatory status (no reports releases), the amount of time that has passed since this facility was active (approximately 30 years), and that this site area has been redeveloped with a multi-story parking garage that would have necessitated significant excavation during construction, the historical presence of the auto sales and service facility in the southwest corner of the site is not considered a REC.

The Sanborn maps from the 1990s included the depiction of a gasoline tank on the western portion of the site. As further discussed in Section 7.1, a 2000-gallon UST was removed from this area of the site in February 2000, during redevelopment activities. Some minor soil impacts were identified and excavated during the UST removal process, and the UST closure was approved by the lead regulatory agency; therefore, the historical presence of the UST at the site is not considered a REC.

The north and east-adjoining properties have consisted of urban residential and commercial development since at least the late 1800s. The north-adjoining property beyond Bridge Street consisted of multiple commercial structures, including a "Chinese laundry" in 1911, prior to the construction of the present-day Chase Bank office building in the early 1970s. The east-adjoining properties beyond Huguenot Street consisted of multiple commercial structures between the late 1800s and the late 1900s, including a drycleaning facility in the 1930s in the southern portion of the east-adjoining property, prior to the construction of the present-day improvements. The present-day surface parking lot to the adjoining east was constructed in the 1970s. The present-day Ruby Dee Park on Library Green was developed in the 2000s, the present-day Halstead New Rochelle apartment building to the adjoining east was constructed in the late 2000s, and the commercial development located in the southern portion of the east-adjoining property was constructed in the mid-1900s. The present-day Trinity St. Paul Anglican Episcopal Church to the adjoining south beyond Division Street was reportedly constructed in the 1860s. The present-day railroad tracks to the adjoining west beyond Station Plaza South were developed prior to 1887 and the present-day New Rochelle station was constructed in the early 1900s.

A "Chinese laundry" facility was historically located to the adjoining north in at least 1911 and a drycleaning facility was located in the southern portion of the east-adjoining property in at least the 1930s. These facilities are not identified on any databases indicative of the generation or disposal of hazardous waste. As stated previously, the use of chlorinated solvents was not introduced into the dry cleaning industry until the 1930s, and its use became widespread in the late 1940s following World War II. No addition cleaners or dry cleaning operations are identified on adjacent properties. Based on the era of operation and the duration of time since these facilities were identified (over 80 years), the historical presence of these facilities on the adjoining properties is not considered a REC.

No RECs were identified as a result of the historical records review.

7.0 ENVIRONMENTAL DATABASE SEARCH AND REVIEW

EDR provided Blackstone a search report of federal, state, local, tribal and proprietary environmental databases to determine the environmental regulatory status of the site, adjoining facilities, and facilities identified within the specified approximate minimum search distance (AMSD) of the site. ASTM Standard E 1527-13 establishes the distance from the site that each database is searched. The database search report, including the date and a detailed description of each database searched, is provided in Appendix C.

The federal, state, local, tribal and proprietary databases searched, the search distances specified for each database, and the results of the environmental database search are summarized as follows:

7.1 FEDERAL, STATE, LOCAL, TRIBAL AND PROPRIETARY DATABASES

Blackstone reviewed the following databases:

Standard Environmental Record Sources	*Search Distance*
Federal Databases	
NPL: National Priority List Sites	1.0 mile
Proposed NPL: Proposed National Priority List Sites	1.0 mile
Delisted NPL: National Priority List Deletions	0.5 mile
NPL Liens: Federal Superfund Liens	Site only
FEDERAL FACILITY: Federal Facility Site Information Listing	1.0 mile
SEMS: Superfund Enterprise Management System	0.5 mile
SEMS-ARCHIVE: Superfund Enterprise Management System Archive	0.5 mile
RCRA CORRACTS: Resource Conservation and Recovery Act - Corrective Action Sites	1.0 mile
RCRA TSDF: RCRA – Treatment, Storage and Disposal Facilities	0.5 mile
RCRA LQGs: RCRA - Large-Quantity Generators	Site and adjoining
RCRA SQGs: RCRA - Small-Quantity Generators	Site and adjoining
RCRA CESQG: RCRA – Conditionally Exempt Small-Quantity Generators	Site and adjoining
US ENG CONTROLS: Engineering Controls Sites List	Site only
US INST CONTROL: Sites with Institutional Controls	Site only
LUCIS: Land Use Control Information System	0.5 mile
ERNS: Emergency Response Notification System	Site only
FEMA UST: FEMA Owned UST Listing	Site and adjoining
State and Tribal Databases	
NY SHWS: Inactive Hazardous Waste Disposal Sites in New York State	1.0 mile
NY VAPOR REPOPENED: Vapor Intrusion Legacy Site List	1.0 mile

Standard Environmental Record Sources	*Search Distance*
NY SWF/LF: Solid Waste Facilities & Landfill Sites	0.5 mile
NY LTANKS: Leaking Storage Tank Incident Reports	0.5 mile
NY HIST LTANKS: Historical Leaking Storage Tanks	0.5 mile
INDIAN LUST: Leaking Underground Storage Tanks on Indian Lands	0.5 mile
NY UST: Registered Underground Storage Tanks	Site and adjoining
NY CBS UST: Chemical Bulk Underground Storage Tank Database	Site and adjoining
NY MOSF UST: Major Oil Underground Storage Tank Facilities	Site and adjoining
NY AST: Registered Petroleum Bulk Aboveground Storage Tank	Site and adjoining
NY CBS AST: Chemical Bulk Aboveground Storage Tank Database	Site and adjoining
NY MOSF AST: Major Oil Aboveground Storage Tank Facilities	Site and adjoining
NY MOSF: Major Oil Storage Facilities Database	Site and adjoining
NY CBS: Chemical Bulk Storage Site Listings	Site and adjoining
INDIAN UST: Underground Storage Tanks on Indian Lands	Site and adjoining
NY ENG CONTROLS: Registry of Engineering Controls	Site only
NY INST CONTROL: Registry of Institutional Controls	Site only
NY RES DECL: Restrictive Declarations Listing	Site only
NY VCP: Voluntary Cleanup Agreements	0.5 mile
INDIAN VCP: Voluntary Cleanup Priority sites on Indian Lands	0.5 mile
NY ERP: Environmental Restoration Program Listing	0.5 mile
NY BROWNFIELDS: Brownfields Assessment Sites	0.5 mile

Additional Environmental Record Sources	*Search Distance*
Federal Databases	
US BROWNFIELDS: Listing of Brownfields Sites	0.5 mile
ODI: Open Dump Inventory	0.5 mile
DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations	0.5 mile
US CDL: United States Clandestine Drug Labs	Site only
US HIST CDL: National Clandestine Laboratory Register	Site only
LIENS 2: CERCLA Lien Information	Site only
HMIRS: Hazardous Materials Information Reporting System	Site only
RCRA Non-Gen: RCRA – Non Generators	Site and adjoining
DOT OPS: Department of Transportation Incident and Accident Data	Site only
DOD: Department of Defense Sites	1.0 mile
FUDS: Formerly Used Defense Sites	1.0 mile
CONSENT: Superfund (CERCLA) Consent Decrees	1.0 mile
ROD: Records of Decision	1.0 mile

Additional Environmental Record Sources	*Search Distance*
UMTRA: Uranium Mill Tailings Sites	0.5 mile
MINES: Mines Master Index File	0.25 mile
TRIS: Toxic Chemical Release Inventory System	Site only
TSCA: Toxic Substances Control Act	Site only
FTTS: Federal Insecticide, Fungicide & Rodenticide Act (FIFRA)/TSCA Tracking System	Site only
HIST FTTS: Historic FIFRA/TSCA Tracking System Listings	Site only
SSTS: Section 7 Tracking System	Site only
ICIS: Integrated Compliance Information System	Site only
PADS: PCB (Polychlorinated Biphenyl) Activity Database System	Site only
MLTS: Material Licensing Tracking System	Site only
RADINFO: Radiation Information Database	Site only
FINDS: Facility Index System/Facility Identification Initiative Program Summary	Site only
RAATS: RCRA Administrative Action Tracking System	Site only
RMP: Risk Management Plans	Site only
SCRD DRYCLEANERS: State Coalition For Remediation of Drycleaners Listing	0.5 mile
PCB TRANSFORMER: PCB Transformer Registration Database	Site only
COAL ASH EPA: Coal Combustion Residues Surface Impoundments List	0.5 mile
COAL ASH DOE: Steam-Electric Plant Operation Data – Power Plants	Site only
EPA WATCH LIST: EPA Watch List	Site only
2020 CORRECTIVE ACTION: 2020 Corrective Action Program List - RCRA	0.25 mile
US FIN ASSUR: Financial Assurance Information	Site only
PRP: Potentially Responsible Parties	Site only
US AIRS: Aerometric Information Retrieval System Facility Subsystem	Site only
LEAD SMELTERS: Lead Smelter Sites	Site only
UXO: Unexploded Ordnance Sites	1.0 mile
DOCKET HWC: Hazardous Waste Compliance Docket Listing	Site only
FUSRAP: Formerly Utilized Sites Remedial Action Program	1.0 mile
FUELS PROGRAM: EPA Fuels Program Registered Listing	0.25 mile
ECHO: Enforcement & Compliance History Information	Site only
State, Local and Tribal Databases	
NY SWTIRE: Registered Waste Tire Storage & Facility List	0.5 mile
NY SWRCY: Registered Recycling Facility List	0.5 mile
NY DEL SHWS: Delisted Registry Sites	1.0 mile
NY HIST UST: Historical Petroleum Bulk Underground Storage Tank Database	Site and adjoining
NY HIST AST: Historical Petroleum Bulk Aboveground Storage Tank Database	Site and adjoining
NY SPILLS: Spills Information Database	Site only
NY SPILLS 80: SPILLS 80 data from FirstSearch	Site only
NY SPILLS 90: SPILLS 90 data from FirstSearch	Site only
NY HIST SPILLS: Historical Spills Database	Site only
NY HSWDS: Hazardous Substance Waste Disposal Site Inventory	0.5 mile
NY UIC: Underground Injection Control Wells	Site only
NY MANIFEST: Facility & Manifest Data	0.25 mile
NY DRYCLEANERS: Registered Drycleaners	0.25 mile
NY NPDES: New York Pollutant Discharge Elimination System	Site only

Additional Environmental Record Sources	*Search Distance*
NY AIRS: Air Emissions Data	Site only
NY E DESIGNATION: E Designation Site Listing	Site only
NY FINANCIAL ASSURANCE: Financial Assurance Information Listing	Site only
NY COAL ASH: Coal Ash Disposal Site Listing	0.5 mile
INDIAN RESERV: Indian Reservations	1.0 mile
INDIAN ODI: Status of Open Dumps on Indian Lands	0.5 mile

EDR Proprietary Databases	*Search Distance*
MGP: Manufactured Gas Plants Database	1.0 mile
Historical Auto Stations	0.25 mile
Historical Cleaners	0.25 mile

EDR Recovered Government Archives	*Search Distance*
RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List	Site only
RGA LF: Recovered Government Archive Solid Waste Facilities List	Site only

The results of the database search are summarized as follows:

SITE:
The site, under the name Office Building at 8-10 Railroad Place, is identified on the Spills database. Review of the available Spills information indicates that the site dates to November 28, 1990, pertained to a release of gasoline from an underground storage tank (UST) that appeared to be leaking, the cleanup work was identified as having met standard, and the case was issued regulatory closure on May 8, 1991. Review of information on the New York State Department of Environmental Conservation (NYSDEC) Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 25 years), and that the site has since been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listing on the Spills database is not considered a REC.

The site, under the name Sound Cleaners at 255 Huguenot Street/63 Memorial Highway, is identified on the EDR Historical Cleaners and Drycleaners databases. The site address is identified Sound Cleaners between 2009 and 2012. The EDR Historical Cleaners database is a proprietary database compiled exclusively from EDRs internal review of historical city directories and names potentially associated with dry cleaning related businesses, and is not indicative of a confirmed business location or operation. This site tenant is not identified on any additional databases indicative of the generation or disposal of hazardous wastes typically associated with an active drycleaning facility. Based on the site inspection and interviews, this facility has only been occupied as a drop off/pick up location, and dry cleaning performed on the site. As such, the site drycleaner listing is not considered a REC.

The site, under the name AvalonBay Communities/Avalon on the Sound at Memorial Highway and Huguenot Street, is identified on the UST and Spills databases. According to the UST database, a 2,000-gallon UST was removed from the site on February 1, 2000. Review of the available Spills information indicates that the spill dates to February 4, 2000, and pertained to the discovery of impacted soils during the removal of a UST, the cleanup work was identified as having met standard, and the case was issued regulatory closure on April 4, 2000. Review of information on the NYSDEC Spills Incident Database confirmed that the case has been issued regulatory closure. Considering the current regulatory status, the amount of time that has passed since the case was active (over 15 years), and that the site has since

been redeveloped with a high-rise apartment building and a parking garage that required significant site excavation, the site listings on the UST and Spills databases are not considered a REC.

ADJOINING OR FACILITIES IN CLOSE PROXIMITY:

Vacant Lot (Huguenot Street/Division Street) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 2005, pertained to the discovery of a release during a UST removal, cleanup work was performed, and the case was issued regulatory on March 15, 2006. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered a REC.

Shoreline Oil (296 Huguenot Street Rear) is located approximately 100 feet to the adjoining east of the site and downgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the LTANKS database. According to the LTANKS database, the case dates to 1988, pertained to a tank overfill, cleanup work was performed, and the case was issued regulatory on April 6, 1988. Considering the current regulatory status and the downgradient position in relationship to the site, this facility is not considered a REC.

Jones Residence/Trinity St. Paul's Episcopal Church (311 Huguenot Street) is located approximately 100 feet to the adjoining south of the site and crossgradient of the site relative to the inferred groundwater flow direction. This facility is identified on the UST and LTANKS databases. Review of the available UST information indicates that this facility previously contained a UST that was closed in place in 2005. According to the LTANKS database, the case dates to 2004, pertained to the closure of a UST, no contamination was discovered in the soil samples obtained, and the case was issued regulatory on September 11, 2005. Considering the current regulatory status and the crossgradient position in relationship to the site, this facility is not considered a REC.

Con Edison (Memorial Highway and Huguenot Street/Division Street and Huguenot Street) is located to the adjoining east and downgradient of the site based on inferred direction of groundwater flow. This facility is listed on the RCRA-LQG, RCRA Non Gen/NLR, and Manifest databases. Con Edison has at least eight listings for the east-adjoining roadways on the Manifest database, presumably for the replacement of electrical transformers, that date to between 2007 and 2014. Con Edison is identified as a large quantity generator of hazardous waste in the form of lead and was previously a non-generator of hazardous waste. No RCRA violations have been identified. Based on the current regulatory status, this west adjoining facility is not considered a REC.

NON-ADJOINING FACILITIES WITHIN APPROXIMATE MINIMUM SEARCH DISTANCE:

As detailed in the EDR Report, several other facilities on various databases are within the Fannie Mae designated search parameters and the ASTM E 1527-13 Approximate Minimum Search Distance (AMSD). Based on factors such as distance to the site, topography, media affected (surface water, soil, soil vapor, groundwater, or air), depth to groundwater, anticipated and reported groundwater flow direction away from the site, hydrological separation, and/or a "Closed Out" and/or "No Further Action (NFA)" regulatory status, these non-adjoining facilities within the Fannie Mae designated search parameters and the AMSD are unlikely to have current or former releases of hazardous substances and/or petroleum products that could migrate to the site and are not considered RECs.

7.2 UNMAPPABLE FACILITIES

Due to inadequate address information or other erroneous facility information, several facilities listed in the environmental databases searched could not be plotted by EDR on a radius map. However, these facilities are still identified in the EDR report by grouping them into an unmappable facility summary. Blackstone reviewed this summary to determine if any of the listed facilities include or adjoin the site. The unmappable facility listings are summarized as follows:

SITE:
Not listed

ADJOINING FACILITIES:
None listed

7.3 AFFIRMATION

Blackstone's conclusions based on the EDR report are limited to the accuracy of that report. To the extent possible, field observations are used by Blackstone to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the site. The database reviewed is sufficiently complete and current to be used as a source to satisfy the regulatory database requirements outlined in ASTM Standard E1527-13.

7.4 ENVIRONMENTAL DATABASE SEARCH AND REVIEW CONCLUSIONS

Based upon Blackstone's review of the EDR database report, no regulatory file reviews are warranted. No RECs were identified as a result of the environmental database search and review.

8.0 SITE INSPECTION

Name of Inspector: John O'Connor
Date of Site Inspection: May 25, 2016

SITE REPRESENTATIVE		
Name	*Title or Association with Site*	*Years Associated with Site*
Ms. Kimberly Periard	Community Manager	2.5 years
Mr. Lennie Dawson	Maintenance Technician	1 year

The site inspection consisted of a walkover of the site perimeter and exterior site areas, and a walk-through of the leasing office, common areas, maintenance/storage areas, mechanical rooms, parking garage, the commercial tenant spaces, and 42 representative dwelling units selected by Blackstone (Units 107, 117, 201, 202, 204, 310, 316, 402, 405, 410, 415, 1601, 1604, 1608, 1616, 1703, 1718, 1803, 1806, 1816, 1902, 1903, 1909, 1915, 2005, 2006, 2013, 2017, 2105, 2109, 2114, 2203, 2217, 2315, 2316, 2409, 2411, 2418, 2507, 2508, 2511, and 2516). The building interior was walked through at the direction of the Site Representative. Not all dwelling units were entered nor were all common and/or storage areas observed. Furthermore, during the site inspection, Blackstone did not inspect inaccessible areas of the site including beneath parked motor vehicles, under manholes, or within the elevator pits. The adjoining properties were visually observed from curbside without being entered. There is no reason to believe the inability to inspect these areas would alter the findings or recommendations set forth in this report or be considered a significant data gap.

8.1 UNDERGROUND STORAGE TANKS (USTS)

Number of USTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
None					No

No physical evidence of current or former USTs was identified during the site inspection. The Site Representative was unaware of current or former USTs.

8.2 ABOVEGROUND STORAGE TANKS (ASTS)

Number of ASTs	*Capacity (gallons)*	*Contents*	*Location*	*Status/Notes*	*REC*
1	175	Diesel	Exterior northern side of apartment building	Fuels emergency generator; registration not required. Equipment is owned by the site. No visible evidence of leaks or spills was observed. No concerns were identified.	No

No physical evidence of other current or former ASTs was identified during the site inspection. The Site Representative was unaware of any other current or former ASTs.

8.3 CHEMICALS AND MATERIALS USAGE

The following section describes non-bulk (55-gallons or less) chemical and petroleum storage at the site. Where applicable, all bulk fixed chemical and petroleum product storage (i.e. USTs and/or ASTs) is discussed in Sections 8.1 and 8.2.

Chemical or Material	*Use*	*Container Type*	*Location*	*REC*
Cleaning supplies	General maintenance	5-gallons or smaller	Maintenance storage areas and dwelling units	No
Pool chemicals	Pool maintenance	5-gallons or smaller	Pool equipment enclosure	No
General maintenance supplies (paints, cleaners, degreasers, adhesives, etc.)	General maintenance	5-gallons or smaller	Maintenance storage areas	No

No evidence of surface staining, spills, or releases was apparent in the chemical storage areas. All chemicals were observed to be properly stored. According to the Site Representative, no releases of chemicals or materials requiring emergency response and/or agency notification have occurred at the site.

8.4 HAZARDOUS WASTES

Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
None					No

No physical evidence of on-site hazardous waste generation, storage, or disposal was identified during the site inspection. The Site Representative was unaware of any on-site hazardous waste generation, storage, or disposal.

8.5 NON-HAZARDOUS WASTES

Non-Hazardous Waste	*Generated By*	*Storage Container*	*Storage Location*	*Disposal Details*	*REC*
General refuse and recyclables	Residents and employees	Trash compactor	Trash room in the apartment building	Emptied regularly by contracted waste hauler	No

No physical evidence of on-site non-hazardous waste disposal was identified during the site inspection. The refuse area was observed in good condition. The Site Representative was unaware of any on-site non-hazardous waste disposal.

8.6 POLYCHLORINATED BIPHENYLS (PCBS)

PCBs can be present in coolants or lubricating oils used in older electrical transformers, hydraulic systems, and other similar equipment. The 1976 Toxic Substances Control Act (TSCA) extended regulatory control over the use of PCBs to the United States Environmental Protection Agency (USEPA). In November 1979, the USEPA generally prohibited the domestic manufacture of PCBs in electromagnets, transformers, and heat-transfer and hydraulic equipment.

Equipment	*Location*	*Owner*	*Status/Notes*	*REC*
Vaulted transformers	Presumed to be under the sidewalk site perimeters	Con Edison	See discussion below	No
Trash compactor	Eastern portion of the site	Site	See discussion below	No
Hydraulic elevator	Parking garage	Site	See discussion below	No

Blackstone did not observe any pad or pole-mounted transformers on the site, and it is assumed that the transformers serving the site are vaulted (presumed to be located under the sidewalk along the site perimeters). Based on the date the site buildings were constructed (2001), the presence of PCB-containing fluid is unlikely. In addition, should fluid spills or releases from an electrical transformer occur, associated remediation efforts are typically the responsibility of the transformer owner (Con Edison) per Federal regulation (40 CFR 761.125). As such, the transformers are not considered a REC.

The site contains a hydraulic trash compactor within a trash room in the apartment building. The compactor is owned by the site and is maintained and regularly emptied by a contracted waste disposal firm. The compactor hydraulic reservoir was observed in generally good condition, with no signs of staining or leakage beneath the reservoirs. Considering the presumed installation date of the compactor (2001), the presence of PCB-containing fluid is unlikely. As such, the hydraulic compactor is not considered a REC.

The site contains a hydraulic elevator that is located within the site parking garage. According to the Site Representative, the site elevator is are regularly maintained by a contracted service firm. No visible evidence of leakage was observed in connection with the hydraulic equipment. The elevator pit was not available for inspection. Based on the reported date of installation and the absence of observed leaks, the hydraulic elevator is not considered a REC.

8.7 WASTEWATER DISCHARGES

Type	*Generated By*	*Discharged To*	*Status/Notes*	*REC*
Sanitary	Residents and staff	Municipal sewer	No concerns noted	No

No physical evidence of septic systems, cesspools, clarifiers, or oil/water separators was observed during the site inspection. The Site Representative was unaware of other such features on the site.

8.8 STORMWATER DISCHARGES

Discharged From	*Discharged To*	*Status/Notes*	*REC*
Roof through internal inlets	Direct discharge to the municipal stormwater system	No concerns noted	No
Parking garage	Trench drains, with eventual discharge to the municipal stormwater system	No concerns noted	No
Exterior site surfaces	Directed to the adjoining streets and municipal stormwater system	No concerns noted	No

No stormwater retention ponds were observed on the site. No environmental issues were observed associated with the on-site stormwater flow. The Site Representative was unaware of any stormwater issues on the site.

8.9 PITS, PONDS, AND LAGOONS (ON-SITE PROCESS WATER DISCHARGE)

Type	*Contents*	*Location*	*Status/Notes*	*REC*
Grease trap (aboveground)	Cooking grease	Metro Market commercial tenant space	The grease trap is emptied on a monthly basis. No concerns were identified.	No

No other pits, ponds or lagoons used for process water discharge were observed at the site. The Site Representative was unaware of other such features on the site.

8.10 WELLS

Type	*Location*	*Status/Notes*	*REC*
None			No

No physical evidence of groundwater monitoring wells, injection wells, extraction wells, vapor wells, drywells, or groundwater production wells was identified during the site inspection. The Site Representative was unaware of any on-site wells.

8.11 UNDERGROUND PRODUCT PIPELINES

Type	*Location*	*Status/Notes*	*REC*
None			No

No physical evidence of underground product pipelines carrying petroleum or other hazardous substances was identified during the site inspection. The Site Representative was unaware of on-site product pipelines.

8.12 ODORS

Odors	*Location*	*Status/Notes*	*REC*
None			No

No unusual odors indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of such odors at the site.

8.13 POOLS OF LIQUID

Pools of Liquid	*Location*	*Status/Notes*	*REC*
None			No

No pools or sumps containing liquids indicative of environmental concerns were identified during the site inspection. The Site Representative was unaware of pools or sumps containing liquids at the site.

8.14 STRESSED VEGETATION OR STAINED SURFACES

Stressed Vegetation or Stained Surfaces	*Location*	*Status/Notes*	*REC*
None			No

No stained soils or stressed vegetation were observed by Blackstone. The Site Representative was unaware of stressed vegetation or stained surfaces.

8.15 SITE INSPECTION CONCLUSIONS

No evidence of RECs was identified in connection with the site as a result of the site inspection.

9.0 ASTM NON-SCOPE CONSIDERATIONS

Blackstone performed the following client-specific activities to identify ASTM *Non-Scope Considerations* (*Business Environmental Risk Issues*) in addition to the ASTM and as required per the Agreement and Fannie Mae.

9.1 ASBESTOS-CONTAINING MATERIALS (ACM)

Frequently encountered types of ACM used in building construction include floor tile and mastic, spray-applied fireproofing, acoustical/decorative ceiling plaster, wallboard and joint compound, insulation, and many other building materials in common use prior to 1981. Materials that contain greater than one percent asbestos fibers are considered regulated ACM and must be handled according to USEPA and Occupational Safety and Health Administration (OSHA) regulations.

Based on the construction date of the site buildings (2001) and in accordance with the Fannie Mae DUS Guidelines, no bulk samples were collected and the presence of regulated ACM is unlikely. No further evaluation of ACM is recommended.

This limited survey should not be construed as a comprehensive asbestos survey for pre-demolition or pre-renovation purposes. As such, prior to demolition or renovation activities at the site, additional sampling of the specific materials to be disturbed will be necessary to satisfy National Emissions Standards for Hazardous Air Pollutants (NESHAPs) and state regulations. Furthermore, all regulated ACM must be handled in accordance with applicable regulations. These regulations may include removal of certain ACMs prior to renovation activities.

9.2 LEAD-BASED PAINT (LBP)

Considering the site buildings were developed after the recognized 1978 LBP determination date, the presence of LBP is unlikely and sampling of painted surfaces was not conducted as part of the scope of this assessment. No further evaluation of LBP is recommended.

9.3 RADON GAS

A review of records regarding radon concentrations in Westchester County, New York, was conducted to determine if concentrations of radon in the general area of the site are within the USEPA guidelines. The USEPA uses a continuous exposure level of 4.0 pCi/L (picoCuries per liter of air) or greater as a guidance level at which further evaluation and potential remedial actions are recommended.

According to USEPA Office of Radiation and Indoor Air information/mapping, the site is located within a Radon Zone Level 3. This zone has a predicted average indoor radon gas screening level less than 2.0 pCi/L, which is within USEPA guidance levels.

Based on the absence of ground-floor (on-slab) residential units, radon screening was not conducted at the site. No further evaluation of radon is recommended.

9.4 APPARENT MOLD GROWTH (AMG)

As part of this site assessment, Blackstone performed the following tasks: looked for evidence of AMG in the areas surveyed during the site assessment; made inquiries of property management regarding past and current leaks or known mold issues; made inquiries of property management whether there have been tenant complaints regarding health problems, musty odors or water leaks; observed areas where significant leaks were reported; and conducted a representative visual/olfactory survey for evidence of current or past water leakage and/or mold.

No AMG was observed within the dwelling units or common areas accessed. The Site Representative was not aware of AMG issues at the site and no tenant complaints were reported. As such, no further evaluation is recommended.

The limited AMG visual survey is intended to provide an indication of the potential for significant environmental issues associated with AMG. Due to the size of the site, all apartment units could not be examined for AMG. In addition, inaccessible areas such as behind walls, in crawl spaces, and inside ductwork were not inspected. As such, the limited AMG visual survey should not be regarded as a comprehensive survey.

9.5 LEAD IN DRINKING WATER

United Water New York provides drinking water to the site. The United Water New York 2015 Annual Water Quality Report indicates the municipal water system meets the requirements as established by the USEPA, state, and local authorities for lead content in drinking water. As such, no further investigation is recommended.

9.6 WETLANDS

As defined by the USEPA and U.S. Army Corps of Engineers (USACE), wetlands are "those areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions."


Wetlands possess three essential characteristics: (1) hydrophytic vegetation; (2) hydric soils; and (3) hydrology. All three characteristics must be prevalent to document an area as a jurisdictional wetland.

Wetlands	
Information Source	***Findings***
National Wetlands Inventory (NWI) on-line Wetland Mapper:	No mapped federal wetlands are located at the site.

Wetlands	
Information Source	***Findings***
(http://www.fws.gov/wetlands/Data/Mapper.html)	
Field observations	No vegetation or ponded areas that are characteristic of wetlands were observed at the site.

10.0 CONCLUSIONS, RECOMMENDATIONS AND O&M PROGRAMS

Blackstone performed a Phase I ESA of the site in conformance with the scope and limitations of ASTM Standard Practice E 1527-13, the Fannie Mae Multifamily/Delegated Underwriting and Servicing Guide (April 29, 2011), and the May 23, 2016 proposal (Agreement) between Walker & Dunlop and Blackstone. Any exceptions to or deletions from this practice are described in Sections 1.2 through 1.4 of this report. This assessment has revealed no evidence of *recognized environmental conditions* (*RECs*) in connection with the site. No further investigation is recommended.



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York


Site Location Map

(USGS Mount Vernon, NY, Topographic Map, 1995)

N
W E
S

miles 0 0.5 1.0

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

Site Plan

(Not to Scale)

N
W E
S

BLACKSTONE CONSULTING LLC



PHOTOGRAPH 1
Site Signage



PHOTOGRAPH 2
Site Apartment Building Exterior



PHOTOGRAPH 3
Site Apartment Building Exterior



PHOTOGRAPH 4
Typical Dwelling Unit Interior



PHOTOGRAPH 5
Typical Dwelling Unit Interior



PHOTOGRAPH 6
Typical Site Water Boilers



PHOTOGRAPH 7
Typical Dwelling Unit HVAC Unit



PHOTOGRAPH 8
Hazardous Material Storage



PHOTOGRAPH 9
Site Swimming Pool



PHOTOGRAPH 10
Site Drycleaner Tenant Space (Pick-Up/Drop-Off Only)



PHOTOGRAPH 11
Emergency Generator with Integrated Aboveground Storage Tank for Diesel Fuel Storage



PHOTOGRAPH 12
Grease Trap in Commercial Tenant Space



PHOTOGRAPH 13
Parking Garage Exterior



PHOTOGRAPH 14
Parking Garage Interior



PHOTOGRAPH 15
Hydraulic Elevator Equipment Located within Parking Garage



PHOTOGRAPH 16
Elevated Walkway Between Parking Garage and Apartment Building



PHOTOGRAPH 17
North-Adjoining Property



PHOTOGRAPH 18
East-Adjoining Property



PHOTOGRAPH 19
West-Adjoining Property



PHOTOGRAPH 20
South-Adjoining Property




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2003 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1996 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1995 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1994 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1993 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1992 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1991 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1990 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1951 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1942 Sanborn Map

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1931 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1911 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1903 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1896 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC




Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1892 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1887 Sanborn Map

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2011 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

2009 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

2006 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1994 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1985 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1980 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1974 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1966 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1961 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01


La Rochelle
New Rochelle, Westchester County, New York

1954 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC



Project No. WALKGA136.01

La Rochelle
New Rochelle, Westchester County, New York

1951 Aerial Photograph

(Approximate Scale: 1 inch = 500 feet)

N
W E
S

BLACKSTONE CONSULTING LLC

La Rochelle

255 Huguenot Street

New Rochelle, NY 10801

Inquiry Number: 4628045.4

May 24, 2016


EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Historical Topo Map

2013



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1979, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1966, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Mount Vernon, 1956, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

Historical Topo Map

1947



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mt Vernon, 1947, 7.5-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute

SITE NAME: La Rochelle
ADDRESS: 255 Huguenot Street
New Rochelle, NY 10801
CLIENT: Blackstone Consulting, LLC

N

La Rochelle
255 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 4628045.2s
May 24, 2016

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	776
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

COORDINATES

Latitude (North):	40.9108080 - 40° 54' 38.90''
Longitude (West):	73.7835360 - 73° 47' 0.72''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602448.1
UTM Y (Meters):	4529356.5
Elevation:	84 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20110710
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1		255 HUGUENOT ST	EDR Hist Cleaner		TP
A2	OFFICE BUILDING	8-10 RAILROAD PLACE	NY Spills	Lower	1 ft.
A3		63 MEMORIAL HWY	EDR Hist Cleaner	Lower	6, 0.001, WSW
A4	SOUND CLEANER	63 MEMORIAL HWY	NY DRYCLEANERS	Lower	6, 0.001, WSW
B5	RESIDENCE	129 DIVISON ST	NY Spills	Higher	34, 0.006, SSW
A6	CONSOLIDATED EDISON	MEMORIAL HIGHWAY & H	NY MANIFEST	Higher	39, 0.007, South
B7	CON EDISON	HUGENOT & DIVISION S	NY MANIFEST	Higher	48, 0.009, SSW
B8	CON EDISON MANHOLE:	HUGENOT AVE & DIVISI	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	48, 0.009, SSW
B9	CON ED	DIVISION ST & HUGENO	NY MANIFEST	Higher	48, 0.009, SSW
B10	CON EDISON - TRANSFO	DIVISION ST AND HUGE	RCRA-LQG	Higher	48, 0.009, SSW
B11	CON EDISON	DIVISION & HUGUENOT	NY MANIFEST	Higher	48, 0.009, SSW
B12	CON EDISON	HUGENOT ST & DIVISIO	NY MANIFEST	Higher	48, 0.009, SSW
B13	CON EDISON TRANSFORM	DIVISION ST & HUGUEN	RCRA NonGen / NLR	Higher	48, 0.009, SSW
B14	NYSDOT BIN 1049890	DIVISION ST OVER MET	RCRA NonGen / NLR	Higher	52, 0.010, SSW
C15	METRO NORTH TRACKS	EAST OF NEW ROCHELLE	NY Spills	Lower	53, 0.010, WSW
C16	METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	NY Spills	Lower	53, 0.010, WSW
A17	MH1204	HUGUENOT AVE/LAWTON	NY Spills	Higher	100, 0.019, ESE
B18	MEMORIAL HIGHWAY AND	HUGUNOT ST	NY Spills	Higher	114, 0.022, South
B19	AVALON ON THE SOUND	HUGUENOT STREET AND	NY UST	Higher	116, 0.022, South
B20	VACANT LOT	HUGUENOT ST/DIVISION	NY LTANKS	Higher	165, 0.031, South
B21	ROAD	HUGUENOT ST/DIVISION	NY Spills	Higher	165, 0.031, South
B22	SHORELINE OIL	296 HUGENOT ST,REAR	NY LTANKS	Higher	174, 0.033, SSW
B23	LILLIAN VERNON CO.	WESTCHESTER PLACE	NY LTANKS	Higher	181, 0.034, South
C24	NYSDOT BIN 1091390	DIVISION ST OVER I 9	RCRA NonGen / NLR	Lower	190, 0.036, WSW
B25	NEW ROCHELLE IRISH B	38 DIVISION STREET	NY UST	Higher	208, 0.039, South
B26	JONES RESIDENCE	311 HUGUENOT STREET	NY LTANKS	Higher	239, 0.045, SSW
B27	TRINITY-ST. PAUL'S E	311 HUGUENOT STREET	NY UST	Higher	239, 0.045, SSW
D28	HUGUENOT AND NORTH A	HUGUENOT AND NORTH A	NY Spills	Higher	243, 0.046, NE
D29	CON EDISON MANHOLE:	HUGUENOT AVE & NORTH	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	243, 0.046, NE
D30	CON EDISON TRANSFORM	NORTH AVE & HUGUENOT	RCRA NonGen / NLR, NY MANIFEST	Higher	243, 0.046, NE
D31	CON EDISON MANHOLE:	HUGENUOT ST & NORTH	RCRA NonGen / NLR	Higher	243, 0.046, NE
E32	MAIN LIBRARY	LAWTON ST	NY LTANKS	Higher	243, 0.046, ESE
E33	ACCESSOCRAFT PRODUCT	48 LAWTON ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	245, 0.046, SE
F34	SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	NY Spills	Lower	261, 0.049, WSW
D35	UNITED STATES POST O	255 NORTH AVENUE	NY UST	Higher	261, 0.049, ENE
D36	US POSTAL SERVICE	255 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	261, 0.049, ENE
B37	CERUSSI AND VERE	306 HUGUENOT ST	NY UST	Higher	270, 0.051, SSW
B38	306 HUGUENOT STREET	306 HUGUENOT STREET	NY AST	Higher	270, 0.051, SSW
D39	KAUFMAN HUGUENOT COM	271 NORTH AVENUE	NY UST, NY AST	Higher	290, 0.055, NE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	PAVEMENT	41 LAWTON STREET	NY Spills	Higher	294, 0.056, ESE
E41	LAWTON STREET REALTY	41-43 LAWTON STREET	NY UST	Higher	294, 0.056, ESE
D42	FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	RCRA NonGen / NLR	Higher	295, 0.056, East
G43		24 STATION PLZ N	EDR Hist Cleaner	Lower	302, 0.057, NW
G44		24 STATION PLZ	EDR Hist Cleaner	Lower	302, 0.057, NW
H45	CABLE	29 DIVISION STREET	NY Spills	Higher	303, 0.057, South
I46	NORTH BROOK REALTY A	270 NORTH AVENUE - U	NY UST	Lower	329, 0.062, NNE
I47	277 NORTH LLC	277 NORTH AVENUE	NY LTANKS	Lower	382, 0.072, NNE
I48	CON EDISON MANHOLE:	277 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	382, 0.072, NNE
I49	BUSINESS	277 NORTH AVENUE	NY LTANKS	Lower	382, 0.072, NNE
I50	277 NORTH LLC	277 NORTH AVENUE	NY UST	Lower	382, 0.072, NNE
I51	EAST RIVER SAVINGS B	277 NORTH AVE.	NY LTANKS	Lower	382, 0.072, NNE
F52		107 DIVISION ST	EDR Hist Auto	Higher	392, 0.074, West
H53	ARIEL CABLE	19 DIVISION STREET/W	NY Spills	Higher	422, 0.080, South
J54	5 ANDERSON ST	5 ANDERSON ST	NY LTANKS	Higher	427, 0.081, East
J55	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY AST	Higher	427, 0.081, East
J56	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY UST	Higher	427, 0.081, East
E57	CON EDISON TRANSFORM	NORTH AVE & ANDERSON	RCRA NonGen / NLR, NY MANIFEST	Higher	428, 0.081, East
E58	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	428, 0.081, East
E59	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	428, 0.081, East
E60	CON EDISON	ANDERSON ST & NORTH	NY MANIFEST	Higher	428, 0.081, East
E61	MKM EQUITY, LLC	230 NORTH AVENUE	NY AST	Higher	447, 0.085, East
E62	CONCRETE FLOORING WI	230 NORTH AVENUE	NY Spills	Higher	447, 0.085, East
H63	COMM/RESIDENT. PROPE	15 DIVISION STREET	NY LTANKS	Higher	468, 0.089, South
E64	NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	NY LTANKS	Higher	486, 0.092, ESE
K65	APARTMENT BLDG	54 CENTRE AVE	NY LTANKS	Higher	487, 0.092, SSW
K66	CEMENT COURT YARD	54 CENTER AVE	NY Spills	Higher	487, 0.092, SSW
K67	SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	NY UST	Higher	487, 0.092, SSW
68		35 UNION AVE	EDR Hist Auto	Higher	519, 0.098, West
K69	CON EDISON	HUGUENOT ST & CENTRE	RCRA NonGen / NLR	Higher	521, 0.099, SSW
K70	CON EDISON	CENTER & HUGUENOT	NY MANIFEST	Higher	521, 0.099, SSW
K71	CON EDISON	CENTRE AVE & HUGUENO	NY MANIFEST	Higher	521, 0.099, SSW
K72	CON EDISON	HUGENOT & CENTRE ST	NY MANIFEST	Higher	521, 0.099, SSW
J73	CVS PHARMACY #8447	222 NORTH AVE	RCRA-LQG, NY MANIFEST	Higher	523, 0.099, ESE
L74	DELUXE TAXI	10 STATION PLAZA	NY UST	Lower	529, 0.100, North
I75	DEVELOPMENT SITE	175 HUGUENOT STREET	NY LTANKS, NY Spills	Higher	536, 0.102, NE
K76	M.J. HACKER & SONS I	64 CENTRE AVE	NY UST	Higher	538, 0.102, South
H77	RPM REALTY INC	9-15 DIVISION STREET	NY AST	Higher	543, 0.103, SSE
H78	RPM REALTY INC	9-15 DIVISION STREET	NY UST	Higher	543, 0.103, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K79	ERIC S TURNER & CO I	33-35 CENTRE AVE	RCRA-CESQG, NJ MANIFEST, NY MANIFEST	Higher	545, 0.103, SSW
M80	P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	NY Spills	Lower	560, 0.106, SW
M81	I-95	I-95EB MP54	NY Spills	Lower	560, 0.106, SW
N82	DEPOT PLACE LLC	1 DEPOT PLACE	NY UST	Lower	560, 0.106, NW
N83	STATION CLEANERS	1 DEPOT PLAZA #1	NY DRYCLEANERS	Lower	560, 0.106, NW
K84	GREEN HEAVEN/CENTRE	62 CENTRE AVE.	NY DRYCLEANERS	Higher	574, 0.109, SSW
K85		62 CENTRE AVE	EDR Hist Cleaner	Higher	574, 0.109, SSW
K86	SIMONETTI CLEANERS	62 CENTRE ST	RCRA-CESQG, US AIRS, FINDS, NY MANIFEST, ECHO	Higher	574, 0.109, SSW
K87	COMMERCIAL PROPERTY	64 CENTRE AVE	NY LTANKS	Higher	585, 0.111, SSW
O88	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	594, 0.112, SW
O89	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	594, 0.112, SW
P90	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	594, 0.112, NE
P91	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	594, 0.112, NE
P92	CON EDISON	HUGENOT ST & LECOUNT	NY MANIFEST	Higher	594, 0.112, NE
K93	NYNEX LOCATION	342 HUEGNOT ST	NY LTANKS	Higher	598, 0.113, SSW
J94	SPEEDY CLEANERS	217 NORTH AVENUE	US AIRS, FINDS, NY DRYCLEANERS, ECHO	Higher	598, 0.113, ESE
L95	SPOKEN ARTS BUILDING	310 NORTH AVENUE	NY UST	Lower	603, 0.114, North
J96	MACYS NEW ROCHELLE	THE MALL	NY UST	Higher	616, 0.117, East
L97	NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	NY UST	Lower	618, 0.117, North
O98	APPAREL PLUS	27 CENTRE AVE	NY Spills	Higher	624, 0.118, SW
Q99	SIDNEY FURNITURE	535 MAIN ST	NY Spills	Higher	632, 0.120, SSE
Q100	SPILL NUMBER 9900400	535 MAIN ST	NY Spills	Higher	632, 0.120, SSE
N101		35 GRAND ST	EDR Hist Auto	Lower	639, 0.121, NW
Q102	LILLIAN VERNON CORP.	543 MAIN STREET	NY LTANKS, NY Spills	Higher	649, 0.123, South
Q103	LILLIAN VERNON CORPO	543-549 MAIN STREET	NY UST	Higher	649, 0.123, South
Q104	543 MAIN STREET	543 MAIN STREET	NY UST	Higher	649, 0.123, South
K105	NEW YORK TELEPHONE C	342 HUGUENOT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	650, 0.123, SSW
K106	VERIZON	342 HUGUENOT ST	NY Spills	Higher	650, 0.123, SSW
K107	VERIZON NEW YORK INC	342 HUGUENOT STREET	NY UST, NY AST	Higher	650, 0.123, SSW
Q108	CON EDISON	S DIVSION ST & MAIN	NY MANIFEST	Higher	653, 0.124, SSE
Q109	CONSOLIDATED EDISON	DIVISION & MAIN	NY MANIFEST	Higher	653, 0.124, SSE
L110	CON EDISON MANHOLE:	313 NORTH AVE FRONT	RCRA NonGen / NLR	Lower	658, 0.125, North
R111	CON EDISON	208 NORTH AVE	NY MANIFEST	Higher	659, 0.125, ESE
K112	75 CENTRE AVENUE LLC	75 CENTRE AVENUE	NY UST, NY AST	Higher	662, 0.125, SSW
J113	MACYS	33 LE COUNT PLACE	NY MANIFEST	Higher	672, 0.127, East
L114	4 STORY APARTMENT BU	320 NORTH AVENUE	NY UST	Lower	674, 0.128, North
Q115	COMMERCIAL PROPERTY	522 MAIN STREET	NY LTANKS	Higher	681, 0.129, SSE
K116	COCO RESIDENCE	81 CENTRE AVE	NY LTANKS	Higher	684, 0.130, South
S117	COMMERCIAL BUILDING	507 MAIN STREET	NY LTANKS	Higher	690, 0.131, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q118	CON EDISON TRANSFORM	CHURCH ST & MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q119	CON EDISON TRANSFORM	MAIN ST & CHRUCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q120	CON EDISON MANHOLE:	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	691, 0.131, SSE
Q121	CON EDISON	MAIN ST & CHURCH ST	NY MANIFEST	Higher	691, 0.131, SSE
K122	HUGUENOT HOLDINGS, L	347 HUGUENOT STREET	NY AST	Higher	702, 0.133, SSW
R123	CATHOLIC NEWS PUBLIS	210 NORTH AVE	NY LTANKS	Higher	723, 0.137, ESE
Q124	OFFICE BLDG	542 MAIN STREET	NY LTANKS	Higher	728, 0.138, South
Q125	542 MAIN STREET LLC	542 MAIN STREET	NY UST	Higher	728, 0.138, South
S126	NEW ROCHELLE PUBLIC	ONE LIBRARY PLAZA	NY UST	Higher	730, 0.138, SE
L127	CON EDISON MANHOLE:	NORTH ST & GARDEN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L128	CON EDISON MANHOLE 4	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L129	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L130	CON EDISON SERVICE B	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, North
L131	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, FINDS, ECHO	Lower	732, 0.139, North
L132	CON EDISON - MANHOLE	GARDEN ST AND NORTH	RCRA-LQG, NY MANIFEST	Lower	732, 0.139, North
T133	BLOOMINGDALE PARKING	554 MAIN ST	NY UST	Higher	734, 0.139, South
R134	BARON MANAGEMENT	200 NORTH AVENUE	NY UST	Higher	736, 0.139, ESE
S135	BARCLAYS BANK OF NY/	491 MAIN ST.	NY LTANKS	Higher	749, 0.142, SE
S136	J P MORGAN CHASE BAN	491 MAIN STREET	NY UST, NY AST	Higher	749, 0.142, SE
S137	NEW ROCHELLE PUBLIC	1 LAWTON	NY LTANKS	Higher	751, 0.142, SE
N138	CIOTTI RESIDENCE	60 GRAND STREET	NY LTANKS, NY Spills	Lower	752, 0.142, NW
O139	MR CHIMNEY CLEAN	32 RELYEA PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	758, 0.144, SSW
Q140	NEW ROCHELLE SUPERMA	538 MAIN STREET	NY AST	Higher	770, 0.146, SSE
T141	HANGERS CLEANERS	562-564 MAIN STREET	NY DRYCLEANERS	Higher	777, 0.147, South
S142	ADREAN PRINTING CO	490 MAIN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	778, 0.147, SE
O143	PRO AUTO PARTS	41 REYLEA PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	780, 0.148, SW
U144	NYS THRUWAY AUTH	THRUWAY BRIDGE MP 60	RCRA NonGen / NLR, NY MANIFEST	Lower	784, 0.148, North
V145	FIRST METRO SERVICES	357 HUGONOT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	787, 0.149, SSW
N146	GUIDANCE CENTER INC	70 GRAND ST	NY LTANKS	Lower	789, 0.149, NW
T147	CENTRE MAIN EQUITIES	573-579 MAIN STREET	NY UST, NY AST	Higher	793, 0.150, South
T148	CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	NY LTANKS	Higher	802, 0.152, South
O149	INDUST OVERALL SERVI	10 BARTELS PLACE	NY LTANKS	Higher	806, 0.153, SW
O150	INDUSTRIAL OVERALL S	10 BARTELLS PLACE	NY UST	Higher	806, 0.153, SW
O151	INDUSTRIAL OVERALL S	10 BARTELS PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	806, 0.153, SW
O152	INDUSTRIAL OVERALL S	10 BARTELS PLACE	NY SHWS, NY CBS	Higher	806, 0.153, SW
O153	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY CBS AST	Higher	806, 0.153, SW
R154	RETTNER MANAGEMENT C	481 MAIN ST	NY UST	Higher	816, 0.155, SE
T155	CON EDISON TRANSFORM	CENTRE AVE & MAIN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	821, 0.155, South
T156	CON EDISON	MAIN ST & CENTRE ST	NY MANIFEST	Higher	821, 0.155, South

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
T157	CON ED	CENTRE AVE & MAIN ST	NY MANIFEST	Higher	821, 0.155, South
158	RITZCOVAN - TTF	22 BURLING LANE	NY LTANKS	Lower	827, 0.157, NNW
U159	CON EDISON MANHOLE:	NORTH AVE & BURLING	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	830, 0.157, North
W160	CASARRA RESIDENCE	9 BADEAU PL	NY LTANKS	Higher	869, 0.165, West
V161	STORAGE USA	363 HUGUENOT STREET	NY UST	Higher	869, 0.165, SSW
X162	DRIVE IT YOURSELF	20 GARDEN STREET	NY UST	Lower	922, 0.175, North
Y163	NYNEX	40 WASHINGTON AVE	NY LTANKS	Higher	924, 0.175, WNW
Z164	ROTH CLEANERS	1 LEROY PL	RCRA NonGen / NLR, FINDS, NY DRYCLEANERS, NY...	Higher	938, 0.178, SSE
Z165	CONSOLIDATED EDISON	DIVISION ST & LEROY	NY MANIFEST	Higher	957, 0.181, SSE
AA166	CON ED-V37	LECOUNT PL & MAIN ST	NY MANIFEST	Higher	959, 0.182, ESE
AA167	CON ED-V14	LECOUNT PL & MAIN ST	NY MANIFEST	Higher	959, 0.182, ESE
W168	RESIDENCE	18 BADEAU PLACE	NY LTANKS	Higher	964, 0.183, West
AB169	J B & FRANKS	27 BARTELS PL	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	977, 0.185, SW
Y170	ST GABRIEL SCHOOL	50 WASHINGTON AVE	NY LTANKS	Higher	985, 0.187, WNW
Y171	SAINT GABRIEL HIGH S	50 WASHINGTON AVENUE	NY UST	Higher	985, 0.187, WNW
Y172	50 WASHINTON AVE	50 WASHINTON AVE	NY LTANKS	Higher	985, 0.187, WNW
V173	CON EDISON	HUGENOT AVE & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
V174	CON EDISON	HUGUENOT ST & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
V175	CON EDISON	HUGENOT ST & COLUMBU	NY MANIFEST	Higher	990, 0.188, SSW
X176	FURNITURE RESTORNATI	26 GARDEN ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	993, 0.188, NNE
W177	DIIORGI HOME	47 WARREN STREET	NY LTANKS	Higher	999, 0.189, WSW
U178	CON EDISON MANHOLE:	350 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1018, 0.193, North
AB179	CON EDISON	35 BARTELS PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1020, 0.193, SW
AB180	CON EDISON	35 BARTELS PL	NY MANIFEST	Lower	1020, 0.193, SW
AC181	BARRAGAN RESIDENCE	40 WARREN ST	NY LTANKS, NY Spills	Higher	1022, 0.194, WSW
AD182	CON EDISON TRANSFORM	595 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1035, 0.196, SSW
AB183	RUSH MFG CORP	18 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1054, 0.200, SSW
W184	NYNEX	UNION AVENUE AND WAR	NY MANIFEST	Higher	1063, 0.201, West
AD185	CON EDISON TRANSFORM	592 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1066, 0.202, South
186	CITIZEN	33 GROVE ST	NY LTANKS	Higher	1067, 0.202, WSW
AE187	THE MALL	MAIN STREET	NY LTANKS	Lower	1079, 0.204, East
AF188	175 MEMORIAL HWY. RE	175 MEMORIAL HWY.	NY UST	Higher	1079, 0.204, NW
AG189	CON EDISON SERVICE B	CENTRE AVE & LEROY	RCRA NonGen / NLR, FINDS	Higher	1085, 0.205, South
AG190	CON EDISON SERVICE B	LEROY PL & CENTER AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1085, 0.205, South
AG191	CON EDISON	CENTRE AVE & LEROY	NY MANIFEST	Higher	1085, 0.205, South
AH192	CON EDISON SERVICE B	174 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1093, 0.207, SE
AI193	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1098, 0.208, NNW
AI194	MAYCO, LLC	18-20 MAY ST	NY AST	Lower	1115, 0.211, NNW
AJ195	NEW ROCHELLE HOSPITA	COVION PLACE	NY LTANKS	Higher	1116, 0.211, NW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AI196	SCHMUCKLERS CLEANERS	360 NORTH AVE	RCRA-CESQG, NY MANIFEST	Lower	1117, 0.212, NNW
AI197	SCHMUKLER'S CLEANERS	360 NORTH AVE.	NY DRYCLEANERS	Lower	1117, 0.212, NNW
AE198	NEW ROCHELLE MALL	425 MAIN STREET	NY UST	Lower	1118, 0.212, East
AJ199	MONTEFIORE - NEW ROC	16 GUION PLACE	NY UST, NY AST	Higher	1143, 0.216, NW
AJ200	SOUND SHORE MEDICAL	16 GUION PL	PA MANIFEST	Higher	1143, 0.216, NW
AJ201	SOUTH SHORE MED CENT	16 GUION PLACE	NY LTANKS	Higher	1143, 0.216, NW
AJ202	SOUND SHORE MEDICAL	16 GUION PL	RCRA-SQG, FINDS, NY MANIFEST, ECHO	Higher	1143, 0.216, NW
203	RESIDENCE	79 WARREN ST	NY LTANKS	Higher	1145, 0.217, West
AF204	66 MEMORIAL BLVD	66 MEMORIAL BLVD	NY LTANKS	Higher	1146, 0.217, NW
AK205	LEXINGTON CENTER FOR	3 COTTAGE PL	NJ MANIFEST	Lower	1147, 0.217, NNE
AK206	LEXINGTON CENTER FOR	3 COTTAGE PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1147, 0.217, NNE
207	CON EDISON	46 CLINTON PL	RCRA-CESQG, NY MANIFEST	Higher	1156, 0.219, SE
AE208	MONROE COLLEGE	420 MAIN STREET	NY AST	Lower	1179, 0.223, East
AD209	CON EDISON	MAIN ST & MAPLE AVE	NY MANIFEST	Higher	1191, 0.226, SSW
AD210	CON EDISON	MAPLE AVE & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST	Higher	1191, 0.226, SSW
AD211	CON EDISON MANHOLE:	MAIN ST & MAPLE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1191, 0.226, SSW
AL212	CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NY MANIFEST	Lower	1192, 0.226, NE
AL213	CON EDISON MANHOLE 1	HUGEONOT ST & HARRIS	RCRA NonGen / NLR, NJ MANIFEST	Lower	1192, 0.226, NE
AC214	PREFERRED CLEANERS	95 UNION AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Higher	1193, 0.226, West
AH215	SINNOTT MANAGEMENT C	35 CLINTON PLACE	NY AST	Higher	1198, 0.227, SE
AB216	ALL AMERICAN SPORTS	44 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1205, 0.228, SW
AH217	30 CLINTON PLACE OWN	30 CLINTON PLACE	NY UST, NY AST	Higher	1208, 0.229, SE
AH218	CO-OP	30 CLINTON PLACE	NY LTANKS	Higher	1208, 0.229, SE
AH219	CON EDISON	150 NORTH AV	NY MANIFEST	Higher	1211, 0.229, SE
AM220	NEW ROCHELLE FIRE ST	45 HARRISON STREET	NY UST, NY AST	Lower	1223, 0.232, ENE
AM221	CITY OF NEW ROCHELLE	45 HARRISON STREET	NY LTANKS	Lower	1223, 0.232, ENE
AM222	CON EDISON	45 HARRISON ST	NY MANIFEST	Lower	1223, 0.232, ENE
AH223	CON EDISON MANHOLE:	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1224, 0.232, SE
AH224	CON EDISON SERVICE B	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1224, 0.232, SE
AC225	100-102 UNION AVENUE	100-102 UNION AVENUE	NY LTANKS	Higher	1229, 0.233, West
AC226	LJNJ ASSOCIATES	100-102 UNION AVE	NY UST	Higher	1229, 0.233, West
AI227	CON EDISON TRANSFORM	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR, NY MANIFEST	Lower	1230, 0.233, NNW
AI228	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1230, 0.233, NNW
AI229	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1230, 0.233, NNW
AI230	CON EDISON	LOCKWOOD AVE & NORTH	NY MANIFEST	Lower	1230, 0.233, NNW
AM231	CON ED	HARRISON ST & CEDAR	NY MANIFEST	Lower	1231, 0.233, ENE
AC232	KAGEL HOME	99 UNION AVE	NY LTANKS	Higher	1232, 0.233, West
AG233	125	CENTRE AVE	NY LTANKS	Higher	1233, 0.234, South
AI234	368 NORTH AVE MGMT C	368 NORTH AVENUE	NY UST	Lower	1234, 0.234, NNW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL235	GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NY AST	Lower	1247, 0.236, NE
AL236	LONGINES WITTNAUER W	145 HUGUENOT ST	RCRA NonGen / NLR, FINDS, NY MANIFEST, ECHO	Lower	1247, 0.236, NE
AL237	GALESI ENTERPRICES	145 HUGUENOT ST	NY LTANKS, NY Spills	Lower	1247, 0.236, NE
AM238	CON ED	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1250, 0.237, ENE
AM239	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1250, 0.237, ENE
AM240	CON EDISON	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1250, 0.237, ENE
AM241	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1250, 0.237, ENE
AE242	MONROE COLLEGE	5 FRANKLIN AVE	NY LTANKS	Lower	1252, 0.237, East
AI243	CASANOVA BROS. REALT	370 NORTH AVENUE	NY UST	Lower	1257, 0.238, NNW
AC244	TANK TEST FAILURE	50 WALNUT ST	NY LTANKS	Higher	1265, 0.240, WSW
AN245	DOMENICO PROCOPIO PR	618 MAIN ST	NY LTANKS, NY Spills	Higher	1279, 0.242, SSW
AN246	DOMENICO PROCOPIO	618 MAIN STREET	NY UST, NY AST	Higher	1279, 0.242, SSW
AC247	ROBERTS HOME	58 WALNUT STREET	NY LTANKS	Higher	1283, 0.243, WSW
AO248	@	60 WALNUT STREET	NY LTANKS	Higher	1289, 0.244, WSW
AN249	VACANT	399 HUGUENOT STREET	NY UST, NY AST	Lower	1295, 0.245, SSW
AH250	COLONIAL CLEANERS CO	149 NORTH AVE	RCRA NonGen / NLR	Higher	1299, 0.246, SE
AH251	FLAMINGO/TYK CLEANER	149 NORTH AV.	NY DRYCLEANERS	Higher	1299, 0.246, SE
AH252	FLAMINGO CLEANERS	149 NORTH AVE	RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Higher	1299, 0.246, SE
AH253	OFF-SITE FLAMINGO CL	149 NORTH AVENUE	NY BROWNFIELDS	Higher	1299, 0.246, SE
AP254	MAY PARTNERS, LLC	35-45 MAY STREET	NY AST	Lower	1306, 0.247, NNW
AM255	FIREHOUSE	HARRISON ST	NY LTANKS	Lower	1332, 0.252, ENE
AL256	BERGMAN REALTY SERVI	140 HUGUENOT STREET	NY LTANKS	Lower	1334, 0.253, ENE
AQ257	BLESSED SACREMENT CH	15 SHEA PL	NY LTANKS	Higher	1393, 0.264, South
AO258	APARTMENT BLDG.	114 UNION AVE.	NY LTANKS, NY Spills	Higher	1395, 0.264, West
AP259	DIMATTOE TTF	55 MAY STREET	NY LTANKS	Lower	1409, 0.267, NNW
260	CITY OF NEW ROCHELLE	1 HARRISON STREET	NY LTANKS	Lower	1414, 0.268, East
AN261	CUMBERLAND FARM	635 MAIN STREET	NY LTANKS, NY Spills	Higher	1419, 0.269, SSW
262	NEW ROCHELLE CATH MI	24 MAPLE AV	NY LTANKS, NY Spills	Higher	1425, 0.270, South
AR263	COMMERCIAL PROPERTY	38 LOCUST AVE	NY LTANKS	Higher	1442, 0.273, ESE
AR264	COMMERCIAL SITE	38 LOCUST AVE	NY LTANKS	Higher	1442, 0.273, ESE
AS265	SPILL NUMBER 0208792	386 NORTH AV	NY LTANKS	Lower	1452, 0.275, NNW
AT266	DEMELIA - TTF	95 WASHINGTON AVE	NY LTANKS	Higher	1453, 0.275, West
AQ267	BLESSED SACRAMENT HI	24 SHEA PLACE	NY LTANKS	Higher	1466, 0.278, South
AQ268	BLESSED SACRAMENT HS	24 SHEA PLACE	NY LTANKS	Higher	1466, 0.278, South
269	RESIDENCE	64 CHURCH ST	NY LTANKS	Higher	1486, 0.281, SSE
AU270	CANDREA/GALLETTA RES	35 CHARLES ST	NY LTANKS	Higher	1517, 0.287, WSW
AO271	SPILL NUMBER 0007965	45 CHARLES ST	NY LTANKS	Higher	1530, 0.290, WSW
AV272	RUSH MFG. CORP.	10-12 PINE CT	CORRACTS, RCRA-CESQG, NY Spills, FINDS, NJ...	Lower	1535, 0.291, SW
AV273	GKIDS REALTY	10/12 PINE COURT	NY LTANKS	Lower	1535, 0.291, SW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AT274	BRAM REALTY	105 WASHINGTON AVE	NY LTANKS	Higher	1553, 0.294, West
AU275	MERLUCCI RESIDENCE	30 CHARLES STREET	NY LTANKS	Higher	1553, 0.294, WSW
AS276	KGM PROPERTY ASSOC.	394 N. AVE.	NY LTANKS	Lower	1557, 0.295, NNW
AS277	KGM REALTY CO.	396 NORTH AVE.	NY LTANKS	Lower	1566, 0.297, NNW
AS278	GETTY# 677	381 NORTH AVE	NY LTANKS, NY Spills	Lower	1577, 0.299, NNW
AR279	APT. BUILDING	55-59 LOCUST AVE.	NY LTANKS	Higher	1587, 0.301, ESE
AW280	BLESSED SACRAMENT CH	SHEA PLACE	NY LTANKS	Higher	1629, 0.309, SSE
AX281	PROFESSIONAL BUILDIN	421 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	1642, 0.311, SSW
282	FRANKA INC.	132-143 UNION AVE.	NY LTANKS	Higher	1644, 0.311, West
AW283	APARTMENT HOUSE	156-168 CENTRE AVE	NY LTANKS	Higher	1652, 0.313, SSE
AW284	FAILED TANK TEST	156 CENTRE AVE	NY LTANKS	Higher	1652, 0.313, SSE
AS285	DIPASQUALE PROPERTY	400 NORTH AVE	NY LTANKS	Lower	1677, 0.318, NNW
AV286	INDUSTRIAL OVERALL S	30 PINE ST	RCRA-LQG, NY SHWS, NY Spills, FINDS, NJ MANIFEST,...	Lower	1691, 0.320, SW
287	POGLIA RES	119 WASHINGTON AVE	NY LTANKS	Lower	1698, 0.322, West
288	APT. BUILDING	47 MAPLE AV	NY LTANKS, NY Spills	Higher	1705, 0.323, South
289	SPILL 0106072 / PBS	370 MAIN ST	NY LTANKS	Lower	1706, 0.323, East
AY290	BUSINESS	88 GROVE AVE.	NY LTANKS	Higher	1715, 0.325, WSW
AY291	COMMERCIAL BUILDING	88-90 GROVE AVE.	NY LTANKS	Higher	1715, 0.325, WSW
292	ANON	108 VAN GUILDER AVE	NY LTANKS, NY Spills	Lower	1769, 0.335, WNW
AV293	BELIVE HOME	20 PINE STREET	NY LTANKS	Lower	1780, 0.337, SW
294	CON EDISON-CEDAR ST	ONE RAMADA PLAZA	EDR MGP	Lower	1794, 0.340, NE
295	CHURCH OF LATTER DAY	111 NORTH AVE	NY LTANKS	Lower	1799, 0.341, SE
296	APARTMENT BUILDING	67-70 LOCUST AVE	NY LTANKS	Lower	1824, 0.345, SE
AX297	SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	NY LTANKS	Lower	1836, 0.348, SSW
298	BUSINESS COMPLEX	55 WEBSTER AVE	NY LTANKS	Lower	1885, 0.357, SW
AZ299	APARTMENT BLDG	1 THE BOULEVARD	NY LTANKS	Lower	1898, 0.359, North
BA300	GETTY S/S	ECHO & BOSTON POST R	NY LTANKS	Lower	1913, 0.362, ENE
AZ301	PRIVATE DWELLING	19 ROCHELLE PLACE	NY LTANKS	Lower	1917, 0.363, NNW
BB302	RESIDENCE	14 REVERE RD	NY LTANKS	Lower	1923, 0.364, ENE
303	NEW ROCHELLE RADIOLO	150 LOCKWOOD AV	NY LTANKS, NY Spills	Higher	1933, 0.366, WNW
304	NICK MAZZA RESIDENCE	20 DAVIS AVE	NY LTANKS	Lower	1943, 0.368, SSE
BC305	SHERIDEN PLAZA	1 SHERIDEN PLAZA	NY LTANKS	Lower	1955, 0.370, NE
BD306	JASON PARTNERS LTD	675 MAIN ST	NY LTANKS	Lower	1968, 0.373, SSW
BE307	ABANDONED GAS STATIO	197 WEBSTER AV	NY LTANKS	Lower	1989, 0.377, West
BC308	MUTUAL BISCUIT COMPA	65 RIVER ST.	NY LTANKS, NY Spills	Lower	2002, 0.379, NE
BA309	GETTY 58114	340 MAIN STREET	NY LTANKS, NY Spills	Lower	2007, 0.380, ENE
BB310	SUNOCO / A-PLUS	71 HUGUENOT	NY LTANKS, NY Spills	Lower	2017, 0.382, ENE
BD311	6 WEBSTER	6 WEBSTER AVE	NY LTANKS	Lower	2025, 0.384, SSW
BF312	SPILL NUMBER 0314082	136 VANGUILDER AVE	NY LTANKS	Lower	2040, 0.386, West

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BG313	STEWART RESIDENCE	100 SICKLES AVE	NY LTANKS, NY Spills	Lower	2047, 0.388, NW
BE314	CITGO STATION	210 WEBSTER AVE	NY LTANKS, NY Spills	Lower	2090, 0.396, West
315	SPILL NUMBER 0302495	85 NORTH AVE	NY LTANKS, NY Spills	Lower	2097, 0.397, SE
BA316	JEROME RESIDENCE	33 ECHO AVE	NY LTANKS	Lower	2097, 0.397, ENE
BG317	BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NY LTANKS	Lower	2098, 0.397, NW
BH318	MICELI HOME	194 CENTRE AVE	NY LTANKS	Lower	2098, 0.397, SSE
BA319	POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	NY LTANKS	Lower	2111, 0.400, ENE
BG320	POINVIL RESIDENCE	107 SICKLES AVE	NY LTANKS	Lower	2113, 0.400, NW
BD321	AMOCO SERVICE STATIO	690 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	2128, 0.403, SSW
BI322	RESIDENCE	10 LAFAYETTE ST	NY LTANKS	Lower	2132, 0.404, East
BF323	YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	NY LTANKS	Lower	2133, 0.404, West
BJ324	COMMERCIAL-TTF	172 UNION AVE	NY LTANKS	Lower	2133, 0.404, West
BG325	TAHIR RESIDENCE	112 SICKLES AVE	NY LTANKS, NY Spills	Lower	2147, 0.407, NW
BK326	GAS STATION	44 ECHO AVE	NY LTANKS	Lower	2150, 0.407, ENE
BK327	DAVENPORT AUTO / WES	44 ECHO AVE	NY LTANKS, NY Spills	Lower	2150, 0.407, ENE
328	SPILL NUMBER 0012427	22 LAUREL PL	NY LTANKS	Lower	2158, 0.409, SSW
BH329	200 CENTRA CORP	200 CENTER AVE	NY LTANKS	Lower	2175, 0.412, SSE
BK330	CONSOLIDATED EDISON	ECHO AVENUE	NY SHWS	Lower	2178, 0.412, ENE
BJ331	FIRST ASSEMBLY OF GO	177 UNION AVE	NY LTANKS	Lower	2186, 0.414, West
332	48 1ST STREET	48 1ST STREET	NY LTANKS	Lower	2193, 0.415, WSW
BI333	GONCALVES RESIDENCE	1 LAFAYETTE STREET	NY LTANKS	Lower	2196, 0.416, East
BI334	GONCALVES RESIDENCE	1 LAFFAYETTE STREET	NY LTANKS	Lower	2196, 0.416, East
BG335	RESIDENCE	7 PRINCE ST	NY LTANKS	Lower	2198, 0.416, NW
BJ336	SPILL NUMBER 0210119	68 FIRST STREET	NY LTANKS	Lower	2212, 0.419, WSW
BG337	RENTAL HOUSE	119 SICKLES AVE.	NY LTANKS	Lower	2221, 0.421, NW
BL338	SPILL NUMBER 0104402	30 LINCOLN ST	NY LTANKS	Lower	2247, 0.426, NE
BJ339	SPILL NUMBER 0210366	182 UNION AV	NY LTANKS	Lower	2253, 0.427, West
BM340	PLASTIC WORKS	115 CEDAR ST	NY LTANKS	Lower	2268, 0.430, NNE
BH341	SPILL NUMBER 0202241	208 CENTER AVE	NY LTANKS, NY Spills	Lower	2277, 0.431, SSE
BL342	SPILL NUMBER 0300463	52 LINCOLN ST	NY LTANKS, NY Spills	Lower	2279, 0.432, NE
BM343	I-95 EXIT 16	OPP. 111 CEDAR ST.	NY LTANKS	Lower	2300, 0.436, NNE
BN344	SPILL NUMBER 0009195	17 POPLAR PL	NY LTANKS	Lower	2316, 0.439, SSE
BH345	RESIDENCE	6 POPLAR ROAD	NY LTANKS	Lower	2321, 0.440, SSE
346	LIPMAN RESIDENCE	54 LIBERTY AVE	NY LTANKS	Lower	2334, 0.442, South
BO347	TELEDYNE HYDRA-POWER	310 MAIN ST	NY SWF/LF, NY Spills, RCRA NonGen / NLR, FINDS, NY...	Lower	2335, 0.442, ENE
348	WALTON RESIDENCE	129 SICKLES AVE	NY LTANKS	Lower	2336, 0.442, NW
349	FIUMFREDO RESIDENCE	12 BAYVIEW AVE	NY LTANKS	Lower	2344, 0.444, East
350	CONTAMINATRED SOIL	23 FIRST ST	NY LTANKS	Lower	2360, 0.447, WSW
351	RESIDENCE	38 BEECHWOOD AVE	NY LTANKS	Lower	2367, 0.448, SW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BO352	DEFENDER MARINE SUPP	309 MAIN ST	NY LTANKS	Lower	2367, 0.448, ENE
BN353	FUNICELOLO HOME	24 POPLAR PLACE	NY LTANKS	Lower	2375, 0.450, SSE
BN354	LABELLA RESIDENCE	219 CENTRE AVE	NY LTANKS	Lower	2397, 0.454, SSE
355	SPILL NUMBER 0210080	196 UNION AV	NY LTANKS	Lower	2423, 0.459, West
BP356	RESIDENCE	98 LIBERTY AVE	NY LTANKS	Lower	2426, 0.459, South
357	MANONE PLACE	15 COLONIAL PLACE	NY LTANKS	Higher	2443, 0.463, WNW
358	TRINITY ARMS APARTME	25 TRINITY PLACE	NY LTANKS	Lower	2463, 0.466, SSE
BQ359	SPILL NUMBER 9814027	48 REMINGTON PL	NY LTANKS	Lower	2488, 0.471, NW
360	RITACCO HOME	24 JACKSON STREET	NY LTANKS	Lower	2490, 0.472, ENE
361	COMMERICAL BUILIDING	719 MAIN ST	NY LTANKS	Lower	2502, 0.474, SSW
362	CONSOLIDATED EDISON-	ECHO AVE	SEMS-ARCHIVE, RCRA-CESQG, NY Spills, NY MANIFEST	Lower	2505, 0.474, East
BP363	SPILL NUMBER 9803423	106 LIBERTY AV	NY LTANKS	Lower	2547, 0.482, South
364	TTF AT RESIDENCE	68 JACKSON ST	NY LTANKS	Lower	2558, 0.484, NE
BP365	COLLEGE OF NEW ROCHE	103 LIBERTY AVE	NY LTANKS	Lower	2565, 0.486, South
366	CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	NY LTANKS	Lower	2567, 0.486, SE
367	NELSTAD MATERIAL COR	40 HUNTINGTON PL	NY LTANKS, NY Spills, NY SPDES	Lower	2573, 0.487, ENE
BP368	BLANCO RESIDENCE	30 LINDEN PLACE	NY LTANKS	Lower	2575, 0.488, South
369	NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	NY SWF/LF	Lower	2583, 0.489, SW
370	7-UP BOTTLING CO	PALMER AVE & CEDAR S	NY LTANKS	Lower	2587, 0.490, NNE
371	NORTH EVARTS	44 NORTH EVARTS AVE	NY LTANKS	Lower	2588, 0.490, SE
BQ372	HERNANDEZ - TTF	70 REMINGTON PLACE	NY LTANKS	Higher	2588, 0.490, NW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
255 HUGUENOT ST 255 HUGUENOT ST NEW ROCHELLE, NY 10801	EDR Hist Cleaner	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent CERCLIS

NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

State and tribal leaking storage tank lists

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---- Underground Storage Tank Listing
NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF UST ---- Major Oil Storage Facilities Database
NY MOSF ---- Major Oil Storage Facility Site Listing
NY MOSF AST ---- Major Oil Storage Facilities Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing
NY ENG CONTROLS ---- Registry of Engineering Controls
NY INST CONTROL ---- Registry of Institutional Controls

State and tribal voluntary cleanup sites

NY VCP ---- Voluntary Cleanup Agreements
INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---- Registered Recycling Facility List
NY SWTIRE ---- Registered Waste Tire Storage & Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---- Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database

NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY UIC ---- Underground Injection Control Wells
FUELS PROGRAM ---- EPA Fuels Program Registered Listing

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 03/07/2016 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON-	***ECHO AVE***	***E 1/4 - 1/2 (0.474 mi.)***	***362***	***749***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/09/2015 has revealed that there is 1

CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSH MFG. CORP.	***10-12 PINE CT***	***SW 1/4 - 1/2 (0.291 mi.)***	***AV272***	***531***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 4 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO	DIVISION ST AND HUGE	SSW 0 - 1/8 (0.009 mi.)	B10	16
CVS PHARMACY #8447	***222 NORTH AVE***	***ESE 0 - 1/8 (0.099 mi.)***	***J73***	***93***
FLAMINGO CLEANERS	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***L132***	***210***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/09/2015 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ202***	***375***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 4 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ERIC S TURNER & CO I	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
SIMONETTI CLEANERS	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***K86***	***133***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***207***	***399***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***NNW 1/8 - 1/4 (0.212 mi.)***	***AI196***	***348***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.153 mi.)***	***O152***	***257***
Site Code: 413917				
Class Code: Significant threat to the public health or environment - action required.				

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***30 PINE ST***	***SW 1/4 - 1/2 (0.320 mi.)***	***AV286***	***580***
Site Code: 355304				
CONSOLIDATED EDISON	ECHO AVENUE	ENE 1/4 - 1/2 (0.412 mi.)	BK330	693
Site Code: 56077				

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 01/05/2016 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELEDYNE HYDRA-POWER	***310 MAIN ST***	***ENE 1/4 - 1/2 (0.442 mi.)***	***BO347***	***716***
NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	SW 1/4 - 1/2 (0.489 mi.)	369	771

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 163 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VACANT LOT Spill Number/Closed Date: 0510542 / 2006-03-15 Site ID: 356539 Program Number: 0510542	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B20	27
SHORELINE OIL Spill Number/Closed Date: 8709425 / 1988-04-06 Site ID: 83347 Program Number: 8709425	296 HUGENOT ST,REAR	SSW 0 - 1/8 (0.033 mi.)	B22	29
LILLIAN VERNON CO. Spill Number/Closed Date: 9213055 / 1995-03-16 Site ID: 201286 Program Number: 9213055	WESTCHESTER PLACE	S 0 - 1/8 (0.034 mi.)	B23	31
JONES RESIDENCE Spill Number/Closed Date: 0410335 / 2005-09-11 Site ID: 335236 Program Number: 0410335	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	B26	34
MAIN LIBRARY Spill Number/Closed Date: 9713843 / 1998-03-27 Site ID: 273025 Program Number: 9713843	LAWTON ST	ESE 0 - 1/8 (0.046 mi.)	E32	41
5 ANDERSON ST Spill Number/Closed Date: 9812585 / 1999-07-12 Spill Number/Closed Date: 8803214 / 1989-11-30 Spill Number/Closed Date: 9812584 / 1999-07-12 Site ID: 68771 Site ID: 68769 Site ID: 68770 Program Number: 9812585 Program Number: 8803214 Program Number: 9812584	5 ANDERSON ST	E 0 - 1/8 (0.081 mi.)	J54	68
COMM/RESIDENT. PROPE Spill Number/Closed Date: 9405558 / 2005-02-10 Site ID: 119901 Program Number: 9405558	15 DIVISION STREET	S 0 - 1/8 (0.089 mi.)	H63	81
NEW ROCHELLE PUBLIC Spill Number/Closed Date: 9111450 / 1992-02-06 Site ID: 306853 Program Number: 9111450	MEMORIAL HIGHWAY	ESE 0 - 1/8 (0.092 mi.)	E64	82
APARTMENT BLDG Spill Number/Closed Date: 0206558 / 2005-02-27	54 CENTRE AVE	SSW 0 - 1/8 (0.092 mi.)	K65	83

Spill Number/Closed Date: 0403405 / 2004-12-10
Site ID: 254563
Site ID: 84302
Program Number: 0206558
Program Number: 0403405

DEVELOPMENT SITE ***175 HUGUENOT STREET*** ***NE 0 - 1/8 (0.102 mi.)*** ***I75*** ***111***
Spill Number/Closed Date: 0512575 / 2006-03-08
Site ID: 358910
Program Number: 0512575

COMMERCIAL PROPERTY 64 CENTRE AVE SSW 0 - 1/8 (0.111 mi.) K87 145
Spill Number/Closed Date: 1308480 / 2015-04-28
Site ID: 489220
Program Number: 1308480

NYNEX LOCATION 342 HUEGNOT ST SSW 0 - 1/8 (0.113 mi.) K93 157
Spill Number/Closed Date: 9708146 / 1997-10-10
Site ID: 270876
Program Number: 9708146

LILLIAN VERNON CORP. ***543 MAIN STREET*** ***S 0 - 1/8 (0.123 mi.)*** ***Q102*** ***167***
Spill Number/Closed Date: 0308082 / 2004-05-12
Site ID: 94435
Program Number: 0308082

COMMERCIAL PROPERTY 522 MAIN STREET SSE 1/8 - 1/4 (0.129 mi.) Q115 187
Spill Number/Closed Date: 1100723 / 2011-06-06
Site ID: 448142
Program Number: 1100723

COCO RESIDENCE 81 CENTRE AVE S 1/8 - 1/4 (0.130 mi.) K116 188
Spill Number/Closed Date: 0311339 / 2005-01-10
Site ID: 313391
Program Number: 0311339

COMMERCIAL BUILDING 507 MAIN STREET SSE 1/8 - 1/4 (0.131 mi.) S117 189
Spill Number/Closed Date: 9110835 / 1992-03-10
Site ID: 286303
Program Number: 9110835

CATHOLIC NEWS PUBLIS 210 NORTH AVE ESE 1/8 - 1/4 (0.137 mi.) R123 197
Spill Number/Closed Date: 0503023 / 2005-08-28
Site ID: 347516
Program Number: 0503023

OFFICE BLDG 542 MAIN STREET S 1/8 - 1/4 (0.138 mi.) Q124 199
Spill Number/Closed Date: 0509995 / 2006-03-22
Site ID: 355877
Program Number: 0509995

BARCLAYS BANK OF NY/ 491 MAIN ST. SE 1/8 - 1/4 (0.142 mi.) S135 214
Spill Number/Closed Date: 8905129 / 1991-03-25
Site ID: 299548
Program Number: 8905129

NEW ROCHELLE PUBLIC 1 LAWTON SE 1/8 - 1/4 (0.142 mi.) S137 216
Spill Number/Closed Date: 1311408 / Not Reported
Spill Number/Closed Date: 0201697 / 2002-09-18
Site ID: 492304
Site ID: 306611
Program Number: 1311408

Program Number: 0201697

CENTRE-MAIN ASSOCIAT Spill Number/Closed Date: 0311823 / 2004-12-30 Site ID: 149369 Program Number: 0311823	75 - 77 CENTER AVE	S 1/8 - 1/4 (0.152 mi.)	T148	240
INDUST OVERALL SERVI Spill Number/Closed Date: 1400928 / Not Reported Site ID: 494186 Program Number: 1400928	10 BARTELS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O149	242
CASARRA RESIDENCE Spill Number/Closed Date: 0209171 / 2003-02-05 Site ID: 157707 Program Number: 0209171	9 BADEAU PL	W 1/8 - 1/4 (0.165 mi.)	W160	271
NYNEX Spill Number/Closed Date: 8803234 / 1988-07-22 Site ID: 60528 Program Number: 8803234	40 WASHINGTON AVE	WNW 1/8 - 1/4 (0.175 mi.)	Y163	273
RESIDENCE Spill Number/Closed Date: 9609269 / 1996-10-24 Site ID: 177416 Program Number: 9609269	18 BADEAU PLACE	W 1/8 - 1/4 (0.183 mi.)	W168	288
ST GABRIEL SCHOOL Spill Number/Closed Date: 0302359 / 2003-12-12 Site ID: 314440 Program Number: 0302359	50 WASHINGTON AVE	WNW 1/8 - 1/4 (0.187 mi.)	Y170	291
50 WASHINTON AVE Spill Number/Closed Date: 0305820 / 2003-12-23 Site ID: 280324 Program Number: 0305820	50 WASHINTON AVE	WNW 1/8 - 1/4 (0.187 mi.)	Y172	294
DIIORGI HOME Spill Number/Closed Date: 0500295 / 2005-08-28 Site ID: 343230 Program Number: 0500295	47 WARREN STREET	WSW 1/8 - 1/4 (0.189 mi.)	W177	303
BARRAGAN RESIDENCE Spill Number/Closed Date: 0109254 / 2001-12-19 Spill Number/Closed Date: 0812107 / 2009-03-03 Site ID: 150939 Site ID: 409713 Program Number: 0109254 Program Number: 0812107	***40 WARREN ST***	***WSW 1/8 - 1/4 (0.194 mi.)***	***AC181***	***317***
CITIZEN Spill Number/Closed Date: 8708588 / 1989-11-28 Site ID: 135309 Program Number: 8708588	33 GROVE ST	WSW 1/8 - 1/4 (0.202 mi.)	186	335
NEW ROCHELLE HOSPITA Spill Number/Closed Date: 9003911 / 1991-03-15 Site ID: 136814 Program Number: 9003911	COVION PLACE	NW 1/8 - 1/4 (0.211 mi.)	AJ195	347
SOUTH SHORE MED CENT Spill Number/Closed Date: 0512440 / 2006-12-19 Site ID: 358758	16 GUION PLACE	NW 1/8 - 1/4 (0.216 mi.)	AJ201	373

Program Number: 0512440				
RESIDENCE Spill Number/Closed Date: 0510555 / 2006-03-28 Site ID: 356553 Program Number: 0510555	79 WARREN ST	W 1/8 - 1/4 (0.217 mi.)	203	392
66 MEMORIAL BLVD Spill Number/Closed Date: 0002907 / 2000-10-24 Site ID: 59397 Program Number: 0002907	66 MEMORIAL BLVD	NW 1/8 - 1/4 (0.217 mi.)	AF204	393
CO-OP Spill Number/Closed Date: 9504589 / 1997-04-15 Site ID: 189169 Program Number: 9504589	30 CLINTON PLACE	SE 1/8 - 1/4 (0.229 mi.)	AH218	426
100-102 UNION AVENUE Spill Number/Closed Date: 9608199 / 1996-11-08 Site ID: 166425 Program Number: 9608199	100-102 UNION AVENUE	W 1/8 - 1/4 (0.233 mi.)	AC225	438
KAGEL HOME Spill Number/Closed Date: 0513684 / 2006-03-09 Site ID: 360201 Program Number: 0513684	99 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AC232	452
125 Spill Number/Closed Date: 0001835 / 2000-05-15 Site ID: 205498 Program Number: 0001835	CENTRE AVE	S 1/8 - 1/4 (0.234 mi.)	AG233	453
TANK TEST FAILURE Spill Number/Closed Date: 1107925 / 2013-02-05 Site ID: 455637 Program Number: 1107925	50 WALNUT ST	WSW 1/8 - 1/4 (0.240 mi.)	AC244	475
DOMENICO PROCOPIO PR Spill Number/Closed Date: 9809866 / 2004-03-30 Site ID: 278454 Program Number: 9809866	***618 MAIN ST***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN245***	***476***
ROBERTS HOME Spill Number/Closed Date: 0608623 / 2012-08-17 Site ID: 372634 Program Number: 0608623	58 WALNUT STREET	WSW 1/8 - 1/4 (0.243 mi.)	AC247	480
@ Spill Number/Closed Date: 0502010 / 2005-07-17 Site ID: 346287 Program Number: 0502010	60 WALNUT STREET	WSW 1/8 - 1/4 (0.244 mi.)	AO248	481
BLESSED SACREMENT CH Spill Number/Closed Date: 0204856 / 2003-10-03 Site ID: 167332 Program Number: 0204856	15 SHEA PL	S 1/4 - 1/2 (0.264 mi.)	AQ257	506
APARTMENT BLDG. Spill Number/Closed Date: 9414493 / 1995-02-14 Spill Number/Closed Date: 0011198 / 2001-04-06 Site ID: 238808 Site ID: 151446 Program Number: 9414493	***114 UNION AVE.***	***W 1/4 - 1/2 (0.264 mi.)***	***AO258***	***507***

Program Number: 0011198

CUMBERLAND FARM	***635 MAIN STREET***	***SSW 1/4 - 1/2 (0.269 mi.)***	***AN261***	***513***
Spill Number/Closed Date: 9206930 / 2005-03-11				
Site ID: 140421				
Program Number: 9206930				
NEW ROCHELLE CATH MI	***24 MAPLE AV***	***S 1/4 - 1/2 (0.270 mi.)***	***262***	***516***
Spill Number/Closed Date: 0204857 / 2003-10-03				
Site ID: 80066				
Program Number: 0204857				
COMMERCIAL PROPERTY	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AR263	519
Spill Number/Closed Date: 1213228 / 2013-02-04				
Site ID: 476407				
Program Number: 1213228				
COMMERCIAL SITE	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AR264	520
Spill Number/Closed Date: 0206043 / 2002-09-26				
Spill Number/Closed Date: 0408593 / 2005-02-13				
Site ID: 239569				
Site ID: 333366				
Program Number: 0206043				
Program Number: 0408593				
DEMELIA - TTF	95 WASHINGTON AVE	W 1/4 - 1/2 (0.275 mi.)	AT266	523
Spill Number/Closed Date: 1406916 / 2015-04-14				
Site ID: 500408				
Program Number: 1406916				
BLESSED SACRAMENT HI	24 SHEA PLACE	S 1/4 - 1/2 (0.278 mi.)	AQ267	525
Spill Number/Closed Date: 0400709 / 2004-07-06				
Site ID: 249284				
Program Number: 0400709				
BLESSED SACRAMENT HS	24 SHEA PLACE	S 1/4 - 1/2 (0.278 mi.)	AQ268	526
Spill Number/Closed Date: 1300960 / Not Reported				
Site ID: 481320				
Program Number: 1300960				
RESIDENCE	64 CHURCH ST	SSE 1/4 - 1/2 (0.281 mi.)	269	528
Spill Number/Closed Date: 0408510 / 2008-05-01				
Site ID: 333255				
Program Number: 0408510				
CANDREA/GALLETTA RES	35 CHARLES ST	WSW 1/4 - 1/2 (0.287 mi.)	AU270	529
Spill Number/Closed Date: 1202322 / 2012-09-13				
Site ID: 465083				
Program Number: 1202322				
SPILL NUMBER 0007965	45 CHARLES ST	WSW 1/4 - 1/2 (0.290 mi.)	AO271	530
Spill Number/Closed Date: 0007965 / 2000-10-26				
Site ID: 61314				
Program Number: 0007965				
BRAM REALTY	105 WASHINGTON AVE	W 1/4 - 1/2 (0.294 mi.)	AT274	560
Spill Number/Closed Date: 0902464 / 2010-02-01				
Site ID: 414506				
Program Number: 0902464				
MERLUCCI RESIDENCE	30 CHARLES STREET	WSW 1/4 - 1/2 (0.294 mi.)	AU275	561
Spill Number/Closed Date: 1103221 / 2011-11-14				
Site ID: 450778				

Program Number: 1103221

APT. BUILDING	55-59 LOCUST AVE.	ESE 1/4 - 1/2 (0.301 mi.)	AR279	571
Spill Number/Closed Date: 9200639 / 1992-06-26				
Site ID: 168647				
Program Number: 9200639				
BLESSED SACRAMENT CH	SHEA PLACE	SSE 1/4 - 1/2 (0.309 mi.)	AW280	572
Spill Number/Closed Date: 8704259 / 1987-11-20				
Site ID: 324974				
Program Number: 8704259				
FRANKA INC.	132-143 UNION AVE.	W 1/4 - 1/2 (0.311 mi.)	282	575
Spill Number/Closed Date: 9312205 / 1995-11-09				
Site ID: 176106				
Program Number: 9312205				
APARTMENT HOUSE	156-168 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AW283	577
Spill Number/Closed Date: 0312650 / 2004-04-22				
Site ID: 267104				
Program Number: 0312650				
FAILED TANK TEST	156 CENTRE AVE	SSE 1/4 - 1/2 (0.313 mi.)	AW284	578
Spill Number/Closed Date: 1308221 / Not Reported				
Site ID: 488939				
Program Number: 1308221				
APT. BUILDING	***47 MAPLE AV***	***S 1/4 - 1/2 (0.323 mi.)***	***288***	***602***
Spill Number/Closed Date: 9603128 / 1996-06-14				
Site ID: 178537				
Program Number: 9603128				
BUSINESS	88 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AY290	605
Spill Number/Closed Date: 9411669 / 2010-04-28				
Site ID: 172950				
Program Number: 9411669				
COMMERCIAL BUILDING	88-90 GROVE AVE.	WSW 1/4 - 1/2 (0.325 mi.)	AY291	607
Spill Number/Closed Date: 9411598 / 2010-04-28				
Site ID: 113133				
Program Number: 9411598				
NEW ROCHELLE RADIOLO	***150 LOCKWOOD AV***	***WNW 1/4 - 1/2 (0.366 mi.)***	***303***	***623***
Spill Number/Closed Date: 0209497 / 2005-03-18				
Site ID: 221207				
Program Number: 0209497				
MANONE PLACE	15 COLONIAL PLACE	WNW 1/4 - 1/2 (0.463 mi.)	357	743
Spill Number/Closed Date: 0513004 / 2006-05-08				
Site ID: 359413				
Program Number: 0513004				
HERNANDEZ - TTF	70 REMINGTON PLACE	NW 1/4 - 1/2 (0.490 mi.)	BQ372	774
Spill Number/Closed Date: 1411959 / 2015-06-16				
Site ID: 505764				
Program Number: 1411959				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
277 NORTH LLC	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I47	60
Spill Number/Closed Date: 0611648 / 2008-12-04				
Site ID: 376329				

Program Number: 0611648				
BUSINESS Spill Number/Closed Date: 0611580 / 2008-12-04 Site ID: 376243 Program Number: 0611580	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I49	63
EAST RIVER SAVINGS B Spill Number/Closed Date: 8912285 / 1991-01-16 Site ID: 271129 Program Number: 8912285	277 NORTH AVE.	NNE 0 - 1/8 (0.072 mi.)	I51	65
CIOTTI RESIDENCE Spill Number/Closed Date: 0407555 / 2004-10-07 Site ID: 332054 Program Number: 0407555	***60 GRAND STREET***	***NW 1/8 - 1/4 (0.142 mi.)***	***N138***	***219***
GUIDANCE CENTER INC Spill Number/Closed Date: 9613894 / 1997-10-03 Site ID: 77017 Program Number: 9613894	70 GRAND ST	NW 1/8 - 1/4 (0.149 mi.)	N146	238
RITZCOVAN - TTF Spill Number/Closed Date: 1506693 / Not Reported Site ID: 514123 Program Number: 1506693	22 BURLING LANE	NNW 1/8 - 1/4 (0.157 mi.)	158	267
THE MALL Spill Number/Closed Date: 9010648 / 1991-01-04 Site ID: 326514 Program Number: 9010648	MAIN STREET	E 1/8 - 1/4 (0.204 mi.)	AE187	336
CITY OF NEW ROCHELLE Spill Number/Closed Date: 0513733 / 2006-06-21 Site ID: 360263 Program Number: 0513733	45 HARRISON STREET	ENE 1/8 - 1/4 (0.232 mi.)	AM221	431
GALESI ENTERPRICES Spill Number/Closed Date: 8901038 / 1989-06-01 Site ID: 259815 Program Number: 8901038	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL237***	***461***
MONROE COLLEGE Spill Number/Closed Date: 0307536 / 2005-03-27 Site ID: 165556 Program Number: 0307536	5 FRANKLIN AVE	E 1/8 - 1/4 (0.237 mi.)	AE242	473
FIREHOUSE Spill Number/Closed Date: 9713840 / 1998-03-27 Site ID: 252028 Program Number: 9713840	HARRISON ST	ENE 1/4 - 1/2 (0.252 mi.)	AM255	503
BERGMAN REALTY SERVI Spill Number/Closed Date: 0505137 / 2007-11-07 Site ID: 350100 Program Number: 0505137	140 HUGUENOT STREET	ENE 1/4 - 1/2 (0.253 mi.)	AL256	505
DIMATTOE TTF Spill Number/Closed Date: 1301890 / 2013-08-08 Site ID: 482303 Program Number: 1301890	55 MAY STREET	NNW 1/4 - 1/2 (0.267 mi.)	AP259	510
CITY OF NEW ROCHELLE	1 HARRISON STREET	E 1/4 - 1/2 (0.268 mi.)	260	512

Spill Number/Closed Date: 0201696 / 2002-09-18
Site ID: 75380
Program Number: 0201696

SPILL NUMBER 0208792 — 386 NORTH AV — NNW 1/4 - 1/2 (0.275 mi.) — AS265 — 522
Spill Number/Closed Date: 0208792 / 2002-11-26
Site ID: 71430
Program Number: 0208792

GKIDS REALTY — 10/12 PINE COURT — SW 1/4 - 1/2 (0.291 mi.) — AV273 — 558
Spill Number/Closed Date: 0200337 / 2003-12-09
Site ID: 235436
Program Number: 0200337

KGM PROPERTY ASSOC. — 394 N. AVE. — NNW 1/4 - 1/2 (0.295 mi.) — AS276 — 562
Spill Number/Closed Date: 9202033 / 1993-01-27
Site ID: 69270
Program Number: 9202033

KGM REALTY CO. — 396 NORTH AVE. — NNW 1/4 - 1/2 (0.297 mi.) — AS277 — 563
Spill Number/Closed Date: 9201744 / 1993-01-27
Site ID: 89642
Program Number: 9201744

GETTY# 677 — ***381 NORTH AVE*** — ***NNW 1/4 - 1/2 (0.299 mi.)*** — ***AS278*** — ***565***
Spill Number/Closed Date: 0400912 / 2005-01-18
Site ID: 242546
Program Number: 0400912

PROFESSIONAL BUILDIN — ***421 HUGUENOT STREET*** — ***SSW 1/4 - 1/2 (0.311 mi.)*** — ***AX281*** — ***573***
Spill Number/Closed Date: 0606014 / 2007-01-29
Site ID: 369299
Program Number: 0606014

DIPASQUALE PROPERTY — 400 NORTH AVE — NNW 1/4 - 1/2 (0.318 mi.) — AS285 — 579
Spill Number/Closed Date: 1103122 / 2012-04-26
Site ID: 450672
Program Number: 1103122

POGLIA RES — 119 WASHINGTON AVE — W 1/4 - 1/2 (0.322 mi.) — 287 — 601
Spill Number/Closed Date: 0109023 / 2002-03-06
Site ID: 317087
Program Number: 0109023

SPILL 0106072 / PBS — 370 MAIN ST — E 1/4 - 1/2 (0.323 mi.) — 289 — 604
Spill Number/Closed Date: 0106072 / 2001-11-13
Site ID: 133647
Program Number: 0106072

ANON — ***108 VAN GUILDER AVE*** — ***WNW 1/4 - 1/2 (0.335 mi.)*** — ***292*** — ***608***
Spill Number/Closed Date: 0308565 / 2005-02-12
Site ID: 214235
Program Number: 0308565

BELIVE HOME — 20 PINE STREET — SW 1/4 - 1/2 (0.337 mi.) — AV293 — 611
Spill Number/Closed Date: 0500819 / 2005-05-22
Spill Number/Closed Date: 0413182 / 2005-05-22
Site ID: 343902
Site ID: 339043
Program Number: 0500819
Program Number: 0413182

CHURCH OF LATTER DAY — 111 NORTH AVE — SE 1/4 - 1/2 (0.341 mi.) — 295 — 614

Spill Number/Closed Date: 0403126 / 2004-09-21
Site ID: 266466
Program Number: 0403126

APARTMENT BUILDING	67-70 LOCUST AVE	SE 1/4 - 1/2 (0.345 mi.)	296	615
Spill Number/Closed Date: 1008207 / 2011-03-10				
Site ID: 441682				
Program Number: 1008207				
SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	SSW 1/4 - 1/2 (0.348 mi.)	AX297	616
Spill Number/Closed Date: 9908602 / 2000-09-14				
Site ID: 283271				
Program Number: 9908602				
BUSINESS COMPLEX	55 WEBSTER AVE	SW 1/4 - 1/2 (0.357 mi.)	298	617
Spill Number/Closed Date: 9912136 / 2000-05-11				
Site ID: 86196				
Program Number: 9912136				
APARTMENT BLDG	1 THE BOULEVARD	N 1/4 - 1/2 (0.359 mi.)	AZ299	618
Spill Number/Closed Date: 9809315 / 1999-10-14				
Site ID: 303319				
Program Number: 9809315				
GETTY S/S	ECHO & BOSTON POST R	ENE 1/4 - 1/2 (0.362 mi.)	BA300	620
Spill Number/Closed Date: 8602124 / 1989-11-28				
Site ID: 124816				
Program Number: 8602124				
PRIVATE DWELLING	19 ROCHELLE PLACE	NNW 1/4 - 1/2 (0.363 mi.)	AZ301	621
Spill Number/Closed Date: 0706958 / 2008-02-01				
Site ID: 387568				
Program Number: 0706958				
RESIDENCE	14 REVERE RD	ENE 1/4 - 1/2 (0.364 mi.)	BB302	622
Spill Number/Closed Date: 9611129 / 1996-12-11				
Site ID: 69656				
Program Number: 9611129				
NICK MAZZA RESIDENCE	20 DAVIS AVE	SSE 1/4 - 1/2 (0.368 mi.)	304	626
Spill Number/Closed Date: 0000532 / 2000-04-20				
Site ID: 211468				
Program Number: 0000532				
SHERIDEN PLAZA	1 SHERIDEN PLAZA	NE 1/4 - 1/2 (0.370 mi.)	BC305	627
Spill Number/Closed Date: 8909204 / 1990-03-07				
Site ID: 80178				
Program Number: 8909204				
JASON PARTNERS LTD	675 MAIN ST	SSW 1/4 - 1/2 (0.373 mi.)	BD306	628
Spill Number/Closed Date: 0211105 / 2003-03-26				
Site ID: 86967				
Program Number: 0211105				
ABANDONED GAS STATIO	197 WEBSTER AV	W 1/4 - 1/2 (0.377 mi.)	BE307	629
Spill Number/Closed Date: 9707099 / 2001-07-19				
Site ID: 231589				
Program Number: 9707099				
MUTUAL BISCUIT COMPA	***65 RIVER ST.***	***NE 1/4 - 1/2 (0.379 mi.)***	***BC308***	***630***
Spill Number/Closed Date: 8707334 / 1988-02-18				
Spill Number/Closed Date: 8708530 / 1988-02-18				
Site ID: 286036				

Site ID: 286037
Program Number: 8707334
Program Number: 8708530

GETTY 58114	***340 MAIN STREET***	***ENE 1/4 - 1/2 (0.380 mi.)***	***BA309***	***635***
Spill Number/Closed Date: 0913713 / 2010-04-29 Site ID: 426673 Program Number: 0913713				
SUNOCO / A-PLUS	***71 HUGUENOT***	***ENE 1/4 - 1/2 (0.382 mi.)***	***BB310***	***642***
Spill Number/Closed Date: 9514850 / 1996-07-26 Site ID: 255332 Program Number: 9514850				
6 WEBSTER	6 WEBSTER AVE	SSW 1/4 - 1/2 (0.384 mi.)	BD311	645
Spill Number/Closed Date: 0403816 / 2004-10-08 Site ID: 81655 Program Number: 0403816				
SPILL NUMBER 0314082	136 VANGUILDER AVE	W 1/4 - 1/2 (0.386 mi.)	BF312	646
Spill Number/Closed Date: 0314082 / 2004-06-08 Site ID: 80232 Program Number: 0314082				
STEWART RESIDENCE	***100 SICKLES AVE***	***NW 1/4 - 1/2 (0.388 mi.)***	***BG313***	***647***
Spill Number/Closed Date: 1200264 / 2012-08-13 Site ID: 462885 Program Number: 1200264				
CITGO STATION	***210 WEBSTER AVE***	***W 1/4 - 1/2 (0.396 mi.)***	***BE314***	***650***
Spill Number/Closed Date: 1311416 / Not Reported Site ID: 492314 Program Number: 1311416				
SPILL NUMBER 0302495	***85 NORTH AVE***	***SE 1/4 - 1/2 (0.397 mi.)***	***315***	***657***
Spill Number/Closed Date: 0507677 / 2009-10-09 Spill Number/Closed Date: 0302495 / 2003-08-12 Site ID: 353132 Site ID: 114935 Program Number: 0507677 Program Number: 0302495				
JEROME RESIDENCE	33 ECHO AVE	ENE 1/4 - 1/2 (0.397 mi.)	BA316	660
Spill Number/Closed Date: 0405389 / 2005-02-13 Site ID: 235222 Program Number: 0405389				
BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NW 1/4 - 1/2 (0.397 mi.)	BG317	662
Spill Number/Closed Date: 0304963 / 2004-02-02 Site ID: 219644 Program Number: 0304963				
MICELI HOME	194 CENTRE AVE	SSE 1/4 - 1/2 (0.397 mi.)	BH318	663
Spill Number/Closed Date: 0604103 / 2006-10-22 Site ID: 366997 Program Number: 0604103				
POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	ENE 1/4 - 1/2 (0.400 mi.)	BA319	664
Spill Number/Closed Date: 8709260 / 1988-02-11 Site ID: 283199 Program Number: 8709260				
POINVIL RESIDENCE	107 SICKLES AVE	NW 1/4 - 1/2 (0.400 mi.)	BG320	665

Spill Number/Closed Date: 1104844 / 2014-11-05
Site ID: 452458
Program Number: 1104844

AMOCO SERVICE STATIO	***690 MAIN ST***	***SSW 1/4 - 1/2 (0.403 mi.)***	***BD321***	***667***
Spill Number/Closed Date: 0209490 / 2002-12-16 Spill Number/Closed Date: 0212950 / 2003-04-01 Spill Number/Closed Date: 8604411 / 1987-01-14 Site ID: 274754 Site ID: 274755 Site ID: 274757 Program Number: 0209490 Program Number: 0212950 Program Number: 8604411				
RESIDENCE	10 LAFAYETTE ST	E 1/4 - 1/2 (0.404 mi.)	BI322	678
Spill Number/Closed Date: 0512638 / 2006-03-15 Site ID: 358990 Program Number: 0512638				
YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	W 1/4 - 1/2 (0.404 mi.)	BF323	679
Spill Number/Closed Date: 0507808 / 2005-12-18 Site ID: 353295 Program Number: 0507808				
COMMERCIAL-TTF	172 UNION AVE	W 1/4 - 1/2 (0.404 mi.)	BJ324	680
Spill Number/Closed Date: 1502358 / Not Reported Site ID: 508618 Program Number: 1502358				
TAHIR RESIDENCE	***112 SICKLES AVE***	***NW 1/4 - 1/2 (0.407 mi.)***	***BG325***	***681***
Spill Number/Closed Date: 0610140 / 2007-10-24 Site ID: 374522 Program Number: 0610140				
GAS STATION	44 ECHO AVE	ENE 1/4 - 1/2 (0.407 mi.)	BK326	684
Spill Number/Closed Date: 1309599 / 2014-02-13 Site ID: 490405 Program Number: 1309599				
DAVENPORT AUTO / WES	***44 ECHO AVE***	***ENE 1/4 - 1/2 (0.407 mi.)***	***BK327***	***685***
Spill Number/Closed Date: 9201557 / 2006-02-17 Spill Number/Closed Date: 9210810 / 1995-02-09 Spill Number/Closed Date: 1001469 / 2010-11-01 Site ID: 130487 Site ID: 130489 Site ID: 434525 Program Number: 9201557 Program Number: 9210810 Program Number: 1001469				
SPILL NUMBER 0012427	22 LAUREL PL	SSW 1/4 - 1/2 (0.409 mi.)	328	691
Spill Number/Closed Date: 0012427 / 2001-05-10 Site ID: 104510 Program Number: 0012427				
200 CENTRA CORP	200 CENTER AVE	SSE 1/4 - 1/2 (0.412 mi.)	BH329	692
Spill Number/Closed Date: 0604650 / 2007-12-12 Site ID: 367663 Program Number: 0604650				
FIRST ASSEMBLY OF GO	177 UNION AVE	W 1/4 - 1/2 (0.414 mi.)	BJ331	695

Spill Number/Closed Date: 1002183 / 2010-08-30
Site ID: 435290
Program Number: 1002183

48 1ST STREET	48 1ST STREET	WSW 1/4 - 1/2 (0.415 mi.)	332	696
Spill Number/Closed Date: 9911183 / 1999-12-22 Site ID: 116893 Program Number: 9911183				
GONCALVES RESIDENCE	1 LAFAYETTE STREET	E 1/4 - 1/2 (0.416 mi.)	BI333	697
Spill Number/Closed Date: 0609401 / 2007-01-10 Site ID: 373629 Program Number: 0609401				
GONCALVES RESIDENCE	1 LAFFAYETTE STREET	E 1/4 - 1/2 (0.416 mi.)	BI334	698
Spill Number/Closed Date: 9410991 / 1994-11-29 Site ID: 156301 Program Number: 9410991				
RESIDENCE	7 PRINCE ST	NW 1/4 - 1/2 (0.416 mi.)	BG335	699
Spill Number/Closed Date: 0506424 / 2005-10-29 Site ID: 351640 Program Number: 0506424				
SPILL NUMBER 0210119	68 FIRST STREET	WSW 1/4 - 1/2 (0.419 mi.)	BJ336	701
Spill Number/Closed Date: 0210119 / 2003-03-03 Site ID: 267616 Program Number: 0210119				
RENTAL HOUSE	119 SICKLES AVE.	NW 1/4 - 1/2 (0.421 mi.)	BG337	702
Spill Number/Closed Date: 9107320 / 1991-11-25 Site ID: 119461 Program Number: 9107320				
SPILL NUMBER 0104402	30 LINCOLN ST	NE 1/4 - 1/2 (0.426 mi.)	BL338	703
Spill Number/Closed Date: 0104402 / 2001-11-14 Site ID: 328750 Program Number: 0104402				
SPILL NUMBER 0210366	182 UNION AV	W 1/4 - 1/2 (0.427 mi.)	BJ339	704
Spill Number/Closed Date: 0210366 / 2003-03-03 Site ID: 282696 Program Number: 0210366				
PLASTIC WORKS	115 CEDAR ST	NNE 1/4 - 1/2 (0.430 mi.)	BM340	705
Spill Number/Closed Date: 9812998 / 1999-02-22 Site ID: 163894 Program Number: 9812998				
SPILL NUMBER 0202241	***208 CENTER AVE***	***SSE 1/4 - 1/2 (0.431 mi.)***	***BH341***	***706***
Spill Number/Closed Date: 9314003 / 1994-03-11 Spill Number/Closed Date: 9315255 / 1994-04-11 Site ID: 215702 Site ID: 215703 Program Number: 9314003 Program Number: 9315255				
SPILL NUMBER 0300463	***52 LINCOLN ST***	***NE 1/4 - 1/2 (0.432 mi.)***	***BL342***	***709***
Spill Number/Closed Date: 0300463 / 2003-04-14 Site ID: 202585 Program Number: 0300463				
I-95 EXIT 16	OPP. 111 CEDAR ST.	NNE 1/4 - 1/2 (0.436 mi.)	BM343	712

Spill Number/Closed Date: 9001240 / 1990-08-01 Site ID: 244221 Program Number: 9001240				
SPILL NUMBER 0009195 Spill Number/Closed Date: 0009195 / 2001-01-08 Site ID: 63217 Program Number: 0009195	17 POPLAR PL	SSE 1/4 - 1/2 (0.439 mi.)	BN344	713
RESIDENCE Spill Number/Closed Date: 0310014 / 2012-08-13 Site ID: 82997 Program Number: 0310014	6 POPLAR ROAD	SSE 1/4 - 1/2 (0.440 mi.)	BH345	714
LIPMAN RESIDENCE Spill Number/Closed Date: 0409061 / 2005-04-02 Site ID: 333699 Program Number: 0409061	54 LIBERTY AVE	S 1/4 - 1/2 (0.442 mi.)	346	715
WALTON RESIDENCE Spill Number/Closed Date: 0703375 / 2007-08-28 Site ID: 383296 Program Number: 0703375	129 SICKLES AVE	NW 1/4 - 1/2 (0.442 mi.)	348	731
FIUMFREDO RESIDENCE Spill Number/Closed Date: 1100096 / 2011-09-22 Site ID: 447470 Program Number: 1100096	12 BAYVIEW AVE	E 1/4 - 1/2 (0.444 mi.)	349	732
CONTAMINATRED SOIL Spill Number/Closed Date: 9702187 / 1999-06-10 Site ID: 102476 Program Number: 9702187	23 FIRST ST	WSW 1/4 - 1/2 (0.447 mi.)	350	734
RESIDENCE Spill Number/Closed Date: 9705244 / 1997-11-10 Site ID: 105369 Program Number: 9705244	38 BEECHWOOD AVE	SW 1/4 - 1/2 (0.448 mi.)	351	735
DEFENDER MARINE SUPP Spill Number/Closed Date: 9806235 / 2002-09-19 Site ID: 93459 Program Number: 9806235	309 MAIN ST	ENE 1/4 - 1/2 (0.448 mi.)	BO352	736
FUNICELOLO HOME Spill Number/Closed Date: 0509719 / 2006-11-19 Site ID: 355533 Program Number: 0509719	24 POPLAR PLACE	SSE 1/4 - 1/2 (0.450 mi.)	BN353	738
LABELLA RESIDENCE Spill Number/Closed Date: 0601959 / 2009-09-01 Site ID: 364328 Program Number: 0601959	219 CENTRE AVE	SSE 1/4 - 1/2 (0.454 mi.)	BN354	739
SPILL NUMBER 0210080 Spill Number/Closed Date: 0210080 / 2003-03-03 Site ID: 155360 Program Number: 0210080	196 UNION AV	W 1/4 - 1/2 (0.459 mi.)	355	740
RESIDENCE Spill Number/Closed Date: 0107187 / 2002-01-11 Site ID: 204562 Program Number: 0107187	98 LIBERTY AVE	S 1/4 - 1/2 (0.459 mi.)	BP356	741
TRINITY ARMS APARTME	25 TRINITY PLACE	SSE 1/4 - 1/2 (0.466 mi.)	358	744

Spill Number/Closed Date: 0811859 / 2009-04-22
Spill Number/Closed Date: 8905211 / 1992-07-30
Site ID: 409448
Site ID: 283512
Program Number: 0811859
Program Number: 8905211

SPILL NUMBER 9814027	48 REMINGTON PL	NW 1/4 - 1/2 (0.471 mi.)	BQ359	746
Spill Number/Closed Date: 9814027 / 1999-02-19				
Site ID: 80830				
Program Number: 9814027				
RITACCO HOME	24 JACKSON STREET	ENE 1/4 - 1/2 (0.472 mi.)	360	747
Spill Number/Closed Date: 0600187 / 2006-07-28				
Site ID: 362141				
Program Number: 0600187				
COMMERICAL BUILIDING	719 MAIN ST	SSW 1/4 - 1/2 (0.474 mi.)	361	748
Spill Number/Closed Date: 0404182 / 2004-10-28				
Site ID: 301693				
Program Number: 0404182				
SPILL NUMBER 9803423	106 LIBERTY AV	S 1/4 - 1/2 (0.482 mi.)	BP363	762
Spill Number/Closed Date: 9803423 / 1998-08-18				
Site ID: 140786				
Program Number: 9803423				
TTF AT RESIDENCE	68 JACKSON ST	NE 1/4 - 1/2 (0.484 mi.)	364	763
Spill Number/Closed Date: 0707955 / 2008-03-26				
Site ID: 388761				
Program Number: 0707955				
COLLEGE OF NEW ROCHE	103 LIBERTY AVE	S 1/4 - 1/2 (0.486 mi.)	BP365	764
Spill Number/Closed Date: 9809357 / 2005-04-17				
Site ID: 118985				
Program Number: 9809357				
CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	SE 1/4 - 1/2 (0.486 mi.)	366	765
Spill Number/Closed Date: 0204230 / 2010-07-13				
Site ID: 161898				
Program Number: 0204230				
NELSTAD MATERIAL COR	***40 HUNTINGTON PL***	***ENE 1/4 - 1/2 (0.487 mi.)***	***367***	***766***
Spill Number/Closed Date: 0208898 / 2004-05-03				
Site ID: 200280				
Program Number: 0208898				
BLANCO RESIDENCE	30 LINDEN PLACE	S 1/4 - 1/2 (0.488 mi.)	BP368	770
Spill Number/Closed Date: 9802704 / 1998-07-30				
Site ID: 227988				
Program Number: 9802704				
7-UP BOTTLING CO	PALMER AVE & CEDAR S	NNE 1/4 - 1/2 (0.490 mi.)	370	772
Spill Number/Closed Date: 9302874 / 1999-08-02				
Site ID: 60684				
Program Number: 9302874				
NORTH EVARTS	44 NORTH EVARTS AVE	SE 1/4 - 1/2 (0.490 mi.)	371	773
Spill Number/Closed Date: 9913333 / 2005-02-26				
Site ID: 74554				
Program Number: 9913333				

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 03/29/2016 has revealed that there are 44 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AVALON ON THE SOUND Status: 5. Closed - removed Id/Status:: 3-800626 Site Status: Unregulated: <1101 gal. PBS	HUGUENOT STREET AND	S 0 - 1/8 (0.022 mi.)	B19	27
NEW ROCHELLE IRISH B Status: 5. Closed - removed Id/Status:: 3-600097 Site Status: Unregulated	38 DIVISION STREET	S 0 - 1/8 (0.039 mi.)	B25	33
TRINITY-ST. PAUL'S E Status: 4. Closed - in place Id/Status:: 3-801006 Site Status: Unregulated: <1101 gal. PBS	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	B27	35
UNITED STATES POST O Status: 0. Administratively closed Status: 1. In-Service Id/Status:: 3-448699 Site Status: Unregulated: <1101 gal. PBS	255 NORTH AVENUE	ENE 0 - 1/8 (0.049 mi.)	D35	49
CERUSSI AND VERE Status: 0. Administratively closed Id/Status:: 3-078360 Site Status: Administratively Closed	306 HUGUENOT ST	SSW 0 - 1/8 (0.051 mi.)	B37	52
KAUFMAN HUGUENOT COM Status: 4. Closed - in place Id/Status:: 3-183776 Site Status: Active	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D39***	***54***
LAWTON STREET REALTY Status: 1. In-Service Id/Status:: 3-801435 Site Status: Active	41-43 LAWTON STREET	ESE 0 - 1/8 (0.056 mi.)	E41	56
ANDERSON DEVELOPMENT Status: 5. Closed - removed Id/Status:: 3-185515 Site Status: Unregulated	5 ANDERSON STREET	E 0 - 1/8 (0.081 mi.)	J56	72
SEASONWEIN MANAGEMEN Status: 1. In-Service Id/Status:: 3-169773 Site Status: Active	54 CENTRE AVENUE	SSW 0 - 1/8 (0.092 mi.)	K67	88
M.J. HACKER & SONS I Status: 8. Unregistered Status: 5. Closed - removed Status: 3. Closed - Prior to 04/1991	64 CENTRE AVE	S 0 - 1/8 (0.102 mi.)	K76	114

Id/Status:: 3-137979 Site Status: Unregulated				
RPM REALTY INC Status: 5. Closed - removed Id/Status:: 3-166189 Site Status: Active	9-15 DIVISION STREET	SSE 0 - 1/8 (0.103 mi.)	H78	118
MACYS NEW ROCHELLE Status: 4. Closed - in place Id/Status:: 3-167037 Site Status: Unregulated: <1101 gal. PBS	THE MALL	E 0 - 1/8 (0.117 mi.)	J96	160
LILLIAN VERNON CORPO Status: 5. Closed - removed Id/Status:: 3-600279 Site Status: Unregulated: <1101 gal. PBS	543-549 MAIN STREET	S 0 - 1/8 (0.123 mi.)	Q103	169
543 MAIN STREET Status: 5. Closed - removed Id/Status:: 3-801106 Site Status: Unregulated: <1101 gal. PBS	543 MAIN STREET	S 0 - 1/8 (0.123 mi.)	Q104	170
VERIZON NEW YORK INC Status: 5. Closed - removed Status: 1. In-Service Id/Status:: 3-184586 Site Status: Active	***342 HUGUENOT STREET***	***SSW 0 - 1/8 (0.123 mi.)***	***K107***	***175***
75 CENTRE AVENUE LLC Status: 5. Closed - removed Id/Status:: 3-800240 Site Status: Active	***75 CENTRE AVENUE***	***SSW 1/8 - 1/4 (0.125 mi.)***	***K112***	***183***
542 MAIN STREET LLC Status: 1. In-Service Id/Status:: 3-800617 Site Status: Active	542 MAIN STREET	S 1/8 - 1/4 (0.138 mi.)	Q125	200
NEW ROCHELLE PUBLIC Status: 1. In-Service Id/Status:: 3-601216 Site Status: Active	ONE LIBRARY PLAZA	SE 1/8 - 1/4 (0.138 mi.)	S126	201
BLOOMINGDALE PARKING Status: 4. Closed - in place Id/Status:: 3-600330 Site Status: Unregulated: <1101 gal. PBS	554 MAIN ST	S 1/8 - 1/4 (0.139 mi.)	T133	212
BARON MANAGEMENT Status: 0. Administratively closed Id/Status:: 3-167843 Site Status: Administratively Closed	200 NORTH AVENUE	ESE 1/8 - 1/4 (0.139 mi.)	R134	213
J P MORGAN CHASE BAN Status: 4. Closed - in place Id/Status:: 3-164372 Site Status: Active	***491 MAIN STREET***	***SE 1/8 - 1/4 (0.142 mi.)***	***S136***	***215***
CENTRE MAIN EQUITIES Status: 5. Closed - removed Id/Status:: 3-800238 Site Status: Active	***573-579 MAIN STREET***	***S 1/8 - 1/4 (0.150 mi.)***	***T147***	***239***
INDUSTRIAL OVERALL S	10 BARTELLS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O150	243

Status: 0. Administratively closed Status: 5. Closed - removed Id/Status:: 3-025453 Site Status: Unregulated				
RETTNER MANAGEMENT C Status: 0. Administratively closed Status: 1. In-Service Id/Status:: 3-255033 Site Status: Active	481 MAIN ST	SE 1/8 - 1/4 (0.155 mi.)	R154	261
STORAGE USA Status: 5. Closed - removed Id/Status:: 3-801137 Site Status: Administratively Closed	363 HUGUENOT STREET	SSW 1/8 - 1/4 (0.165 mi.)	V161	272
SAINT GABRIEL HIGH S Status: 5. Closed - removed Status: 1. In-Service Id/Status:: 3-058122 Site Status: Active	50 WASHINGTON AVENUE	WNW 1/8 - 1/4 (0.187 mi.)	Y171	292
175 MEMORIAL HWY. RE Status: 4. Closed - in place Id/Status:: 3-800711 Site Status: Unregulated: <1101 gal. PBS	175 MEMORIAL HWY.	NW 1/8 - 1/4 (0.204 mi.)	AF188	338
MONTEFIORE - NEW ROC Status: 1. In-Service Status: 5. Closed - removed Status: 4. Closed - in place Id/Status:: 3-123269 Site Status: Active	***16 GUION PLACE***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ199***	***365***
30 CLINTON PLACE OWN Status: 5. Closed - removed Id/Status:: 3-078727 Site Status: Active	***30 CLINTON PLACE***	***SE 1/8 - 1/4 (0.229 mi.)***	***AH217***	***425***
LJNJ ASSOCIATES Status: 0. Administratively closed Status: 5. Closed - removed Id/Status:: 3-601056 Site Status: Unregulated: <1101 gal. PBS	100-102 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AC226	439
DOMENICO PROCOPIO Status: 5. Closed - removed Id/Status:: 3-800233 Site Status: Unregulated: <1101 gal. PBS	***618 MAIN STREET***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN246***	***478***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NORTH BROOK REALTY A Status: 1. In-Service Id/Status:: 3-600117 Site Status: Active	270 NORTH AVENUE - U	NNE 0 - 1/8 (0.062 mi.)	I46	59
277 NORTH LLC Status: 1. In-Service Status: 5. Closed - removed Id/Status:: 3-502049	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	I50	64

Site Status: Active				
DELUXE TAXI Status: 5. Closed - removed Id/Status:: 3-600004 Site Status: Unregulated: <1101 gal. PBS	10 STATION PLAZA	N 0 - 1/8 (0.100 mi.)	L74	109
DEPOT PLACE LLC Status: 4. Closed - in place Id/Status:: 3-801085 Site Status: Unregulated: <1101 gal. PBS	1 DEPOT PLACE	NW 0 - 1/8 (0.106 mi.)	N82	131
SPOKEN ARTS BUILDING Status: 5. Closed - removed Id/Status:: 3-600705 Site Status: Unregulated: <1101 gal. PBS	310 NORTH AVENUE	N 0 - 1/8 (0.114 mi.)	L95	159
NORTH GARDEN ASSOCIA Status: 1. In-Service Id/Status:: 3-496928 Site Status: Active	309-311 NORTH AVENUE	N 0 - 1/8 (0.117 mi.)	L97	161
4 STORY APARTMENT BU Status: 5. Closed - removed Id/Status:: 3-600732 Site Status: Unregulated: <1101 gal. PBS	320 NORTH AVENUE	N 1/8 - 1/4 (0.128 mi.)	L114	185
DRIVE IT YOURSELF Status: 5. Closed - removed Id/Status:: 3-494380 Site Status: Unregulated	20 GARDEN STREET	N 1/8 - 1/4 (0.175 mi.)	X162	272
NEW ROCHELLE MALL Status: 4. Closed - in place Id/Status:: 3-600042 Site Status: Unregulated: <1101 gal. PBS	425 MAIN STREET	E 1/8 - 1/4 (0.212 mi.)	AE198	364
NEW ROCHELLE FIRE ST Status: 1. In-Service Status: 5. Closed - removed Id/Status:: 3-600407 Site Status: Active	***45 HARRISON STREET***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AM220***	***429***
368 NORTH AVE MGMT C Status: 5. Closed - removed Id/Status:: 3-600272 Site Status: Unregulated: <1101 gal. PBS	368 NORTH AVENUE	NNW 1/8 - 1/4 (0.234 mi.)	AI234	454
CASANOVA BROS. REALT Status: 4. Closed - in place Id/Status:: 3-800088 Site Status: Unregulated: <1101 gal. PBS	370 NORTH AVENUE	NNW 1/8 - 1/4 (0.238 mi.)	AI243	474
VACANT Status: 5. Closed - removed Status: 4. Closed - in place Id/Status:: 3-801616 Site Status: Unregulated	***399 HUGUENOT STREET***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AN249***	***482***

EXECUTIVE SUMMARY

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 03/29/2016 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL S	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.153 mi.)***	***O152***	***257***
Facility Status: Unregulated/Closed CBS Number: 3-000235				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 03/29/2016 has revealed that there are 21 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
306 HUGUENOT STREET Status: 1. In-Service PBS Number: 3-800236	306 HUGUENOT STREET	SSW 0 - 1/8 (0.051 mi.)	B38	53
KAUFMAN HUGUENOT COM Status: 1. In-Service PBS Number: 3-183776	***271 NORTH AVENUE***	***NE 0 - 1/8 (0.055 mi.)***	***D39***	***54***
ANDERSON DEVELOPMENT Status: 6. Closed - Work Permit Open PBS Number: 3-185515	5 ANDERSON STREET	E 0 - 1/8 (0.081 mi.)	J55	71
MKM EQUITY, LLC Status: 5. Closed - removed PBS Number: 3-600105	230 NORTH AVENUE	E 0 - 1/8 (0.085 mi.)	E61	79
RPM REALTY INC Status: 1. In-Service PBS Number: 3-166189	9-15 DIVISION STREET	SSE 0 - 1/8 (0.103 mi.)	H77	117
VERIZON NEW YORK INC Status: 1. In-Service PBS Number: 3-184586	***342 HUGUENOT STREET***	***SSW 0 - 1/8 (0.123 mi.)***	***K107***	***175***
75 CENTRE AVENUE LLC Status: 1. In-Service PBS Number: 3-800240	***75 CENTRE AVENUE***	***SSW 1/8 - 1/4 (0.125 mi.)***	***K112***	***183***
HUGUENOT HOLDINGS, L Status: 1. In-Service PBS Number: 3-502626	347 HUGUENOT STREET	SSW 1/8 - 1/4 (0.133 mi.)	K122	197
J P MORGAN CHASE BAN Status: 1. In-Service PBS Number: 3-164372	***491 MAIN STREET***	***SE 1/8 - 1/4 (0.142 mi.)***	***S136***	***215***
NEW ROCHELLE SUPERMA Status: 5. Closed - removed PBS Number: 3-166995	538 MAIN STREET	SSE 1/8 - 1/4 (0.146 mi.)	Q140	225
CENTRE MAIN EQUITIES	***573-579 MAIN STREET***	***S 1/8 - 1/4 (0.150 mi.)***	***T147***	***239***

Status: 1. In-Service PBS Number: 3-800238				
MONTEFIORE - NEW ROC Status: 1. In-Service Status: 5. Closed - removed PBS Number: 3-123269	***16 GUION PLACE***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ199***	***365***
SINNOTT MANAGEMENT C Status: 1. In-Service PBS Number: 3-078646	35 CLINTON PLACE	SE 1/8 - 1/4 (0.227 mi.)	AH215	421
30 CLINTON PLACE OWN Status: 4. Closed - in place Status: 1. In-Service PBS Number: 3-078727	***30 CLINTON PLACE***	***SE 1/8 - 1/4 (0.229 mi.)***	***AH217***	***425***
DOMENICO PROCOPIO Status: 0. Administratively closed PBS Number: 3-800233	***618 MAIN STREET***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AN246***	***478***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAYCO, LLC Status: 1. In-Service PBS Number: 3-175447	18-20 MAY ST	NNW 1/8 - 1/4 (0.211 mi.)	AI194	346
MONROE COLLEGE Status: 0. Administratively closed Status: 5. Closed - removed Status: 1. In-Service PBS Number: 3-800251	420 MAIN STREET	E 1/8 - 1/4 (0.223 mi.)	AE208	401
NEW ROCHELLE FIRE ST Status: 1. In-Service PBS Number: 3-600407	***45 HARRISON STREET***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AM220***	***429***
GHP 145 HUGUENOT DEL Status: 1. In-Service PBS Number: 3-497436	145 HUGUENOT STREET	NE 1/8 - 1/4 (0.236 mi.)	AL235	455
VACANT Status: 5. Closed - removed PBS Number: 3-801616	***399 HUGUENOT STREET***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AN249***	***482***
MAY PARTNERS, LLC Status: 5. Closed - removed Status: 1. In-Service PBS Number: 3-600544	35-45 MAY STREET	NNW 1/8 - 1/4 (0.247 mi.)	AP254	502

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	10 BARTELS PLACE	SW 1/8 - 1/4 (0.153 mi.)	O153	261

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/17/2016 has revealed that there are 3 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FLAMINGO CLEANERS Site Code: 335220	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***
OFF-SITE FLAMINGO CL Site Code: 414661	149 NORTH AVENUE	SE 1/8 - 1/4 (0.246 mi.)	AH253	501

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLER'S DRY CLE Site Code: 357446	358-364 NORTH AVENUE	NNW 1/8 - 1/4 (0.208 mi.)	AI193	344

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/17/2016 has revealed that there are 22 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Spill Number/Closed Date: 0810056 / 2010-05-04 spillno: 0810056 Site ID: 407567	129 DIVISON ST	SSW 0 - 1/8 (0.006 mi.)	B5	10
MH1204 Spill Number/Closed Date: 9912755 / 2000-02-14 spillno: 9912755 Site ID: 262084	HUGUENOT AVE/LAWTON	ESE 0 - 1/8 (0.019 mi.)	A17	24
MEMORIAL HIGHWAY AND Spill Number/Closed Date: 9912617 / 2000-04-04 spillno: 9912617 Site ID: 254637	HUGUNOT ST	S 0 - 1/8 (0.022 mi.)	B18	25
ROAD	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B21	28

Spill Number/Closed Date: 0606187 / 2006-09-03 spillno: 0606187 Site ID: 369495				
HUGUENOT AND NORTH A Spill Number/Closed Date: 0310260 / 2005-03-05 spillno: 0310260 Site ID: 313618	HUGUENOT AND NORTH A	NE 0 - 1/8 (0.046 mi.)	D28	36
PAVEMENT Spill Number/Closed Date: 1203965 / 2012-07-23 spillno: 1203965 Site ID: 466814	41 LAWTON STREET	ESE 0 - 1/8 (0.056 mi.)	E40	55
CABLE Spill Number/Closed Date: 0804961 / 2008-07-30 spillno: 0804961 Site ID: 401965	29 DIVISION STREET	S 0 - 1/8 (0.057 mi.)	H45	58
ARIEL CABLE Spill Number/Closed Date: 0804960 / 2008-08-16 spillno: 0804960 Site ID: 401964	19 DIVISION STREET/W	S 0 - 1/8 (0.080 mi.)	H53	67
CONCRETE FLOORING WI Spill Number/Closed Date: 1400277 / Not Reported spillno: 1400277 Site ID: 493512	230 NORTH AVENUE	E 0 - 1/8 (0.085 mi.)	E62	79
CEMENT COURT YARD Spill Number/Closed Date: 9908117 / 1999-10-04 Spill Number/Closed Date: 9804849 / 2002-07-15 spillno: 9804849 spillno: 9908117 Site ID: 114515 Site ID: 114516	54 CENTER AVE	SSW 0 - 1/8 (0.092 mi.)	K66	86
DEVELOPMENT SITE Spill Number/Closed Date: 0510932 / 2005-12-19 Spill Number/Closed Date: 0504821 / 2006-03-08 spillno: 0504821 spillno: 0510932 Site ID: 349739 Site ID: 356986	***175 HUGUENOT STREET***	***NE 0 - 1/8 (0.102 mi.)***	***I75***	***111***
APPAREL PLUS Spill Number/Closed Date: 1309988 / 2014-01-14 spillno: 1309988 Site ID: 490810	27 CENTRE AVE	SW 0 - 1/8 (0.118 mi.)	O98	161
SIDNEY FURNITURE Spill Number/Closed Date: 1509029 / 2015-12-04 spillno: 1509029 Site ID: 517634	535 MAIN ST	SSE 0 - 1/8 (0.120 mi.)	Q99	163
SPILL NUMBER 9900400 Spill Number/Closed Date: 9900400 / 1999-07-09 Spill Number/Closed Date: 9415294 / 1995-03-03 spillno: 9415294 spillno: 9900400 Site ID: 251083	535 MAIN ST	SSE 0 - 1/8 (0.120 mi.)	Q100	164

Site ID: 81102

LILLIAN VERNON CORP.	***543 MAIN STREET***	***S 0 - 1/8 (0.123 mi.)***	***Q102***	***167***
Spill Number/Closed Date: 9212475 / 2004-05-12 spillno: 9212475 Site ID: 125220				
VERIZON	342 HUGUENOT ST	SSW 0 - 1/8 (0.123 mi.)	K106	174
Spill Number/Closed Date: 0413326 / 2005-09-11 spillno: 0413326 Site ID: 342403				

Lower Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING	8-10 RAILROAD PLACE	0 - 1/8 (0.000 mi.)	A2	8
Spill Number/Closed Date: 9009493 / 1991-05-07 spillno: 9009493 Site ID: 220275				
METRO NORTH TRACKS	EAST OF NEW ROCHELLE	WSW 0 - 1/8 (0.010 mi.)	C15	22
Spill Number/Closed Date: 0308130 / 2004-07-16 spillno: 0308130 Site ID: 279322				
METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	WSW 0 - 1/8 (0.010 mi.)	C16	23
Spill Number/Closed Date: 8903573 / 1989-07-19 spillno: 8903573 Site ID: 104107				
SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	WSW 0 - 1/8 (0.049 mi.)	F34	48
Spill Number/Closed Date: 9803949 / 1998-06-29 spillno: 9803949 Site ID: 166821				
P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	SW 0 - 1/8 (0.106 mi.)	M80	128
Spill Number/Closed Date: 0308809 / 2003-11-26 spillno: 0308809 Site ID: 329742				
I-95	I-95EB MP54	SW 0 - 1/8 (0.106 mi.)	M81	130
Spill Number/Closed Date: 8700158 / 1987-04-07 spillno: 8700158 Site ID: 121121				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/09/2015 has revealed that there are 59 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE:	***HUGENOT AVE & DIVISI***	***SSW 0 - 1/8 (0.009 mi.)***	***B8***	***13***
CON EDISON TRANSFORM	DIVISION ST & HUGUEN	SSW 0 - 1/8 (0.009 mi.)	B13	20

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1049890	DIVISION ST OVER MET	SSW 0 - 1/8 (0.010 mi.)	B14	21
CON EDISON MANHOLE:	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D29***	***37***
CON EDISON TRANSFORM	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D30***	***39***
CON EDISON MANHOLE:	HUGENUOT ST & NORTH	NE 0 - 1/8 (0.046 mi.)	D31	41
ACCESSOCRAFT PRODUCT	***48 LAWTON ST***	***SE 0 - 1/8 (0.046 mi.)***	***E33***	***43***
US POSTAL SERVICE	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D36***	***50***
FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	E 0 - 1/8 (0.056 mi.)	D42	57
CON EDISON TRANSFORM	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.081 mi.)***	***E57***	***73***
CON EDISON	HUGUENOT ST & CENTRE	SSW 0 - 1/8 (0.099 mi.)	K69	89
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O88***	***146***
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O89***	***148***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
NEW YORK TELEPHONE C	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.123 mi.)***	***K105***	***170***
CON EDISON TRANSFORM	***CHURCH ST & MAIN ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q118***	***190***
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q119***	***192***
CON EDISON MANHOLE:	***MAIN ST & CHURCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q120***	***194***
MR CHIMNEY CLEAN	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.144 mi.)***	***O139***	***222***
ADREAN PRINTING CO	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S142***	***226***
PRO AUTO PARTS	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***O143***	***230***
FIRST METRO SERVICES	***357 HUGONOT ST***	***SSW 1/8 - 1/4 (0.149 mi.)***	***V145***	***236***
INDUSTRIAL OVERALL S	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.153 mi.)***	***O151***	***244***
CON EDISON TRANSFORM	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***T155***	***262***
ROTH CLEANERS	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
CON EDISON TRANSFORM	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD182***	***320***
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AD185***	***333***
CON EDISON SERVICE B	***CENTRE AVE & LEROY***	***S 1/8 - 1/4 (0.205 mi.)***	***AG189***	***338***
CON EDISON SERVICE B	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG190***	***339***
CON EDISON SERVICE B	***174 NORTH AVE***	***SE 1/8 - 1/4 (0.207 mi.)***	***AH192***	***342***
CON EDISON	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD210***	***403***
CON EDISON MANHOLE:	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD211***	***406***
PREFERRED CLEANERS	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AC214***	***411***
CON EDISON MANHOLE:	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH223***	***434***
CON EDISON SERVICE B	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH224***	***436***
COLONIAL CLEANERS CO	149 NORTH AVE	SE 1/8 - 1/4 (0.246 mi.)	AH250	485

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1091390	DIVISION ST OVER I 9	WSW 0 - 1/8 (0.036 mi.)	C24	32
CON EDISON MANHOLE:	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***I48***	***61***
CON EDISON MANHOLE:	313 NORTH AVE FRONT	N 0 - 1/8 (0.125 mi.)	L110	181
CON EDISON MANHOLE:	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***L127***	***201***
CON EDISON MANHOLE 4	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L128***	***203***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L129***	***205***
CON EDISON SERVICE B	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L130***	***207***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L131***	***208***
NYS THRUWAY AUTH	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.148 mi.)***	***U144***	***232***
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.157 mi.)***	***U159***	***268***
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***AB169***	***289***
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***X176***	***298***
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.193 mi.)***	***U178***	***304***
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB179***	***306***
RUSH MFG CORP	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AB183***	***322***
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK206***	***396***
CON EDISON MANHOLE 1	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AL213***	***409***
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AB216***	***422***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TRANSFORM	***LOCKWOOD AVE & NORTH***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI227***	***441***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***
LONGINES WITTNAUER W	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL236***	***455***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 10/16/2015 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREEN HEAVEN/CENTRE Facility Id: 3-5510-00298	62 CENTRE AVE.	SSW 0 - 1/8 (0.109 mi.)	K84	132
SPEEDY CLEANERS Facility Id: 3-5510-00344	***217 NORTH AVENUE***	***ESE 0 - 1/8 (0.113 mi.)***	***J94***	***158***
HANGERS CLEANERS Facility Id: 3-5510-00358	562-564 MAIN STREET	S 1/8 - 1/4 (0.147 mi.)	T141	225
ROTH CLEANERS Facility Id: 3-5510-00292	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
FLAMINGO/TYK CLEANER Facility Id: 3-5510-00335	149 NORTH AV.	SE 1/8 - 1/4 (0.246 mi.)	AH251	487

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANER	63 MEMORIAL HWY	WSW 0 - 1/8 (0.001 mi.)	A4	9
STATION CLEANERS Facility Id: ---	1 DEPOT PLAZA #1	NW 0 - 1/8 (0.106 mi.)	N83	131
SCHMUKLER'S CLEANERS Facility Id: 3-5510-00327	360 NORTH AVE.	NNW 1/8 - 1/4 (0.212 mi.)	AI197	364

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there are 92 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004151221	MEMORIAL HIGHWAY & H	S 0 - 1/8 (0.007 mi.)	A6	11
CON EDISON EPA ID: NYP004677548	HUGENOT & DIVISION S	SSW 0 - 1/8 (0.009 mi.)	B7	12
CON EDISON MANHOLE: EPA ID: NYP004317285	***HUGENOT AVE & DIVISI***	***SSW 0 - 1/8 (0.009 mi.)***	***B8***	***13***
CON ED EPA ID: NYP004353199	DIVISION ST & HUGENO	SSW 0 - 1/8 (0.009 mi.)	B9	15
CON EDISON	DIVISION & HUGUENOT	SSW 0 - 1/8 (0.009 mi.)	B11	18

EPA ID: NYP004676847				
CON EDISON EPA ID: NYP004677894	HUGENOT ST & DIVISIO	SSW 0 - 1/8 (0.009 mi.)	B12	19
CON EDISON MANHOLE: EPA ID: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.046 mi.)***	***D29***	***37***
CON EDISON TRANSFORM EPA ID: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.046 mi.)***	***D30***	***39***
ACCESSOCRAFT PRODUCT EPA ID: NYR000014753	***48 LAWTON ST***	***SE 0 - 1/8 (0.046 mi.)***	***E33***	***43***
US POSTAL SERVICE EPA ID: NYR000106369	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D36***	***50***
CON EDISON TRANSFORM EPA ID: NYP004367611	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.081 mi.)***	***E57***	***73***
CON EDISON EPA ID: NYP004683272	NORTH AVE & ANDERSON	E 0 - 1/8 (0.081 mi.)	E58	75
CON EDISON EPA ID: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.081 mi.)	E59	76
CON EDISON EPA ID: NYP004709622	ANDERSON ST & NORTH	E 0 - 1/8 (0.081 mi.)	E60	78
CON EDISON EPA ID: NYP004676839	CENTER & HUGUENOT	SSW 0 - 1/8 (0.099 mi.)	K70	89
CON EDISON EPA ID: NYP004332961	CENTRE AVE & HUGUENO	SSW 0 - 1/8 (0.099 mi.)	K71	90
CON EDISON EPA ID: NYP004677530	HUGENOT & CENTRE ST	SSW 0 - 1/8 (0.099 mi.)	K72	91
CVS PHARMACY #8447 EPA ID: NYR000194654	***222 NORTH AVE***	***ESE 0 - 1/8 (0.099 mi.)***	***J73***	***93***
ERIC S TURNER & CO I EPA ID: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
SIMONETTI CLEANERS EPA ID: NYD982531634	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***K86***	***133***
CON EDISON TRANSFORM EPA ID: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O88***	***146***
CON EDISON TRANSFORM EPA ID: NYP004365318	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O89***	***148***
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
CON EDISON EPA ID: NYP004837407	HUGENOT ST & LECOUNT	NE 0 - 1/8 (0.112 mi.)	P92	156
NEW YORK TELEPHONE C EPA ID: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.123 mi.)***	***K105***	***170***
CON EDISON EPA ID: NYP004872319	S DIVSION ST & MAIN	SSE 0 - 1/8 (0.124 mi.)	Q108	178
CONSOLIDATED EDISON	DIVISION & MAIN	SSE 0 - 1/8 (0.124 mi.)	Q109	179

EPA ID: NYP004123873				
CON EDISON EPA ID: NYP004772265	208 NORTH AVE	ESE 0 - 1/8 (0.125 mi.)	R111	182
MACYS EPA ID: NYP000890137	33 LE COUNT PLACE	E 1/8 - 1/4 (0.127 mi.)	J113	185
CON EDISON TRANSFORM EPA ID: NYP004478517	***CHURCH ST & MAIN ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q118***	***190***
CON EDISON TRANSFORM EPA ID: NYP004364576	***MAIN ST & CHRUCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q119***	***192***
CON EDISON MANHOLE: EPA ID: NYP004478624	***MAIN ST & CHURCH ST***	***SSE 1/8 - 1/4 (0.131 mi.)***	***Q120***	***194***
CON EDISON EPA ID: NYP004680070	MAIN ST & CHURCH ST	SSE 1/8 - 1/4 (0.131 mi.)	Q121	196
MR CHIMNEY CLEAN EPA ID: NYD987011855	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.144 mi.)***	***O139***	***222***
ADREAN PRINTING CO EPA ID: NY0000233981	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S142***	***226***
PRO AUTO PARTS EPA ID: NYR000016535	***41 REYLEA PL***	***SW 1/8 - 1/4 (0.148 mi.)***	***O143***	***230***
INDUSTRIAL OVERALL S EPA ID: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.153 mi.)***	***O151***	***244***
CON EDISON TRANSFORM EPA ID: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***T155***	***262***
CON EDISON EPA ID: NYP004658019	MAIN ST & CENTRE ST	S 1/8 - 1/4 (0.155 mi.)	T156	264
CON ED EPA ID: NYP004760815	CENTRE AVE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	T157	265
ROTH CLEANERS EPA ID: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.178 mi.)***	***Z164***	***274***
CONSOLIDATED EDISON EPA ID: NYP004124210	DIVISION ST & LEROY	SSE 1/8 - 1/4 (0.181 mi.)	Z165	286
CON ED-V37 EPA ID: NYP004027967	LECOUNT PL & MAIN ST	ESE 1/8 - 1/4 (0.182 mi.)	AA166	287
CON ED-V14 EPA ID: NYP004028122	LECOUNT PL & MAIN ST	ESE 1/8 - 1/4 (0.182 mi.)	AA167	287
CON EDISON EPA ID: NYP004677621	HUGENOT AVE & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	V173	295
CON EDISON EPA ID: NYP004687802	HUGUENOT ST & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	V174	296
CON EDISON EPA ID: NYP004677837	HUGENOT ST & COLUMBU	SSW 1/8 - 1/4 (0.188 mi.)	V175	297
CON EDISON TRANSFORM EPA ID: NYP004464459	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD182***	***320***
NYNEX EPA ID: NYP000932509	UNION AVENUE AND WAR	W 1/8 - 1/4 (0.201 mi.)	W184	333
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.202 mi.)***	***AD185***	***333***

EPA ID: NYP004357059				
CON EDISON SERVICE B EPA ID: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG190***	***339***
CON EDISON EPA ID: NYP004517694	CENTRE AVE & LEROY	S 1/8 - 1/4 (0.205 mi.)	AG191	341
CON EDISON SERVICE B EPA ID: NYP004442943	***174 NORTH AVE***	***SE 1/8 - 1/4 (0.207 mi.)***	***AH192***	***342***
SOUND SHORE MEDICAL EPA ID: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ202***	***375***
CON EDISON EPA ID: NYP004157665	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.219 mi.)***	***207***	***399***
CON EDISON EPA ID: NYP004674354	MAIN ST & MAPLE AVE	SSW 1/8 - 1/4 (0.226 mi.)	AD209	402
CON EDISON MANHOLE: EPA ID: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD211***	***406***
PREFERRED CLEANERS EPA ID: NYD050275254	***95 UNION AVE***	***W 1/8 - 1/4 (0.226 mi.)***	***AC214***	***411***
CON EDISON EPA ID: NYP004710497	150 NORTH AV	SE 1/8 - 1/4 (0.229 mi.)	AH219	428
CON EDISON MANHOLE: EPA ID: NYP004443198	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH223***	***434***
CON EDISON SERVICE B EPA ID: NYP004452439	***NORTH AVE & CLINTON***	***SE 1/8 - 1/4 (0.232 mi.)***	***AH224***	***436***
FLAMINGO CLEANERS EPA ID: NYD012946885	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH252***	***487***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***I48***	***61***
CON EDISON MANHOLE: EPA ID: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.139 mi.)***	***L127***	***201***
CON EDISON MANHOLE 4 EPA ID: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L128***	***203***
CON EDISON MANHOLE: EPA ID: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L129***	***205***
CON EDISON SERVICE B EPA ID: NYP004463667	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.139 mi.)***	***L130***	***207***
CON EDISON - MANHOLE EPA ID: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.139 mi.)***	***L132***	***210***
NYS THRUWAY AUTH EPA ID: NYD986963445	***THRUWAY BRIDGE MP 60***	***N 1/8 - 1/4 (0.148 mi.)***	***U144***	***232***
CON EDISON MANHOLE: EPA ID: NYP004307492	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.157 mi.)***	***U159***	***268***
J B & FRANKS EPA ID: NYD986884732	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.185 mi.)***	***AB169***	***289***
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***X176***	***298***

EPA ID: NYD987034998				
CON EDISON MANHOLE: EPA ID: NYP004432886	***350 NORTH AVE***	***N 1/8 - 1/4 (0.193 mi.)***	***U178***	***304***
CON EDISON EPA ID: NYP004205654	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB179***	***306***
CON EDISON EPA ID: NYP004744074	35 BARTELS PL	SW 1/8 - 1/4 (0.193 mi.)	AB180	308
RUSH MFG CORP EPA ID: NYD981185051	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AB183***	***322***
SCHMUCKLERS CLEANERS EPA ID: NYD012950770	***360 NORTH AVE***	***NNW 1/8 - 1/4 (0.212 mi.)***	***AI196***	***348***
LEXINGTON CENTER FOR EPA ID: NYR000193854	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK206***	***396***
CONSOLIDATED EDISON EPA ID: NYP004219572	HUGUENOT ST & HARRIS	NE 1/8 - 1/4 (0.226 mi.)	AL212	408
ALL AMERICAN SPORTS EPA ID: NYD002182897 EPA ID: NYR000040113	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AB216***	***422***
CON EDISON EPA ID: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.232 mi.)	AM222	432
CON EDISON TRANSFORM EPA ID: NYP004372751	***LOCKWOOD AVE & NORTH***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI227***	***441***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***
CON EDISON EPA ID: NYP004838332	LOCKWOOD AVE & NORTH	NNW 1/8 - 1/4 (0.233 mi.)	AI230	449
CON ED EPA ID: NYP004759924	HARRISON ST & CEDAR	ENE 1/8 - 1/4 (0.233 mi.)	AM231	450
LONGINES WITTNAUER W EPA ID: NYD001317221	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL236***	***455***
CON ED EPA ID: NYP004759510	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AM238	466
CON EDISON EPA ID: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AM239	468
CON EDISON EPA ID: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.237 mi.)	AM240	469
CON EDISON EPA ID: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.237 mi.)	AM241	471

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL Generator EPA Id: NYD075431502	16 GUION PL	NW 1/8 - 1/4 (0.216 mi.)	AJ200	371

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 02/01/2016 has revealed that there are 8 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ERIC S TURNER & CO I EPA ID: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.103 mi.)***	***K79***	***118***
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P90***	***150***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***P91***	***153***
CON EDISON EPA Id: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.226 mi.)***	***AD210***	***403***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LEXINGTON CENTER FOR EPA Id: NYR000193854	3 COTTAGE PL	NNE 1/8 - 1/4 (0.217 mi.)	AK205	394
CON EDISON MANHOLE 1 EPA Id: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.226 mi.)***	***AL213***	***409***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI228***	***443***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***NNW 1/8 - 1/4 (0.233 mi.)***	***AI229***	***446***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within

approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON-CEDAR ST	ONE RAMADA PLAZA	NE 1/4 - 1/2 (0.340 mi.)	294	613

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	107 DIVISION ST	W 0 - 1/8 (0.074 mi.)	F52	67
Not reported	35 UNION AVE	W 0 - 1/8 (0.098 mi.)	68	88
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
Not reported	35 GRAND ST	NW 0 - 1/8 (0.121 mi.)	N101	166

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	62 CENTRE AVE	SSW 0 - 1/8 (0.109 mi.)	K85	132
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
Not reported	63 MEMORIAL HWY	WSW 0 - 1/8 (0.001 mi.)	A3	9
Not reported	24 STATION PLZ N	NW 0 - 1/8 (0.057 mi.)	G43	58
Not reported	24 STATION PLZ	NW 0 - 1/8 (0.057 mi.)	G44	58

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 7 records.

Site Name	Database(s)
MEARL CORP.	NY SHWS
VALU CLEAN CLEANERS	NY DRYCLEANERS
SIDEWALK / IN FRONT OF NE	NY LTANKS
N.SHORE LONG ISLAND SOUND	NY LTANKS
MM 5.4 LEFT LANE	NY LTANKS
NEW ROCHELLE CREEK CABLES	FINDS, ECHO
CE-CEDAR ST MGP NEW ROCHELLE	NY VCP

OVERVIEW MAP - 4628045.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: La Rochelle	CLIENT: Blackstone Consulting, LLC
ADDRESS: 255 Huguenot Street New Rochelle NY 10801	CONTACT: Amy Stanton
LAT/LONG: 40.910808 / 73.783536	INQUIRY #: 4628045.2s DATE: May 24, 2016 1:06 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 4628045.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- 100-year flood zone
- 500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
		INQUIRY #:	4628045.2s
LAT/LONG:	40.910808 / 73.783536	DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	1	0	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	2	NR	NR	NR	4
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		2	2	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	1	2	0	NR	3
NY VAPOR REOPENED	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		16	36	111	NR	NR	163
NY HIST LTANKS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		21	23	NR	NR	NR	44
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	15	NR	NR	NR	21
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	3	0	NR	NR	3
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		22	NR	NR	NR	NR	22
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		19	40	NR	NR	NR	59
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		4	4	NR	NR	NR	8
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		30	62	NR	NR	NR	92
RI MANIFEST	0.250		0	0	NR	NR	NR	0
PA MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250		3	5	NR	NR	NR	8
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		3	NR	NR	NR	NR	3
EDR Hist Cleaner	0.125	1	4	NR	NR	NR	NR	5
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		1	132	197	118	0	0	448

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target Property **255 HUGUENOT ST**
NEW ROCHELLE, NY 10801

EDR Hist Cleaner **1015029078**
N/A

Site 1 of 6 in cluster A

Actual:
84 ft.

EDR Historical Cleaners:

Name:	SOUND CLEANERS
Year:	2009
Address:	255 HUGUENOT ST

A2
OFFICE BUILDING
8-10 RAILROAD PLACE
NEW ROCHELLE, NY

NY Spills **S102154161**
N/A

< 1/8
1 ft.

Site 2 of 6 in cluster A

Relative:
Lower

Actual:
81 ft.

SPILLS:

Facility ID:	9009493
Facility Type:	ER
DER Facility ID:	182194
Site ID:	220275
DEC Region:	3
Spill Date:	1990-11-28
Spill Number/Closed Date:	9009493 / 1991-05-07
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1990-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-03-18
Cleanup Meets Std:	True
Last Inspection:	1991-03-18
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-12-06
Spill Record Last Update:	1991-05-08
Spiller Name:	Not reported
Spiller Company:	8 RAILROAD PLACE CORP.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"UNDERGROUND TANK SYSTEM APPEARS TO BE LEAKING ACCORDING TO READINGS MAPLE MAINTENANCE LAGRANGEVILLE NO ODORS NO PRODUCT IN VIEW CALLED JOHN TENORE MAPLE MAINT. WILL BE DOING A TANK TEST MAYBE ONLY 100"

Material:

Site ID:	220275
Operable Unit ID:	946581
Operable Unit:	01

OFFICE BUILDING (Continued) **S102154161**

Material ID:	429706
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	800.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

A3 **EDR Hist Cleaner** **1015082888**
WSW **63 MEMORIAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.001 mi.
6 ft. **Site 3 of 6 in cluster A**

Relative:
Lower

Actual:
83 ft.

EDR Historical Cleaners:

Name:	SOUND CLEANERS
Year:	2010
Address:	63 MEMORIAL HWY
Name:	SOUND CLEANERS
Year:	2011
Address:	63 MEMORIAL HWY
Name:	SOUND CLEANERS
Year:	2012
Address:	63 MEMORIAL HWY

A4 **SOUND CLEANER** **NY DRYCLEANERS** **S110247943**
WSW **63 MEMORIAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.001 mi.
6 ft. **Site 4 of 6 in cluster A**

Relative:
Lower

Actual:
83 ft.

DRYCLEANERS:

Facility ID:	Not reported
Phone Number:	Not reported
Region:	3
Registration Effective Date:	Not reported
Inspection Date:	Not reported
Install Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

B5 **RESIDENCE** **NY Spills** **S109413260**
SSW **129 DIVISON ST** **N/A**
< 1/8 **TARRYTOWN, NY**
0.006 mi.
34 ft. **Site 1 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Facility ID:	0810056
Facility Type:	ER
DER Facility ID:	356816
Site ID:	407567
DEC Region:	3
Spill Date:	2008-12-09
Spill Number/Closed Date:	0810056 / 2010-05-04
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6026
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-09
Spill Record Last Update:	2010-08-27
Spiller Name:	Not reported
Spiller Company:	3RD PARTY SPILL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT
Contact Phone:	(212) 580-8383
DEC Memo:	"12/09/2008: Con Ed reports that this location is the former GM site that was/is a Brownsfield site. Con Ed was laying a gas line when stained soils was found in the trench...ra 08/27/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	"CALLER STATES THAT THEY RECIEVED A 3RD PARTY CALLL STATING THAT THEY FOUND AN UNK PETROLEUM PRODUCT DURING AN EXCAVATION. CLEAN UP IS PENDING."

Material:

Site ID:	407567
Operable Unit ID:	1164107
Operable Unit:	01
Material ID:	2155468
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	Not reported

RESIDENCE (Continued) **S109413260**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

A6 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650791**
South **MEMORIAL HIGHWAY & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.007 mi.
39 ft. **Site 5 of 6 in cluster A**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:
EPA ID: NYP004151221
Country: USA
Location Address 1: MEMORIAL HIGHWAY & HUGUENOT ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 06/21/2007
Trans1 Recv Date: 06/21/2007
Trans2 Recv Date: 06/22/2007
TSD Site Recv Date: 06/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004151221
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 1820
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000174983GBF
Import Ind: N
Export Ind: N

CONSOLIDATED EDISON (Continued) **S108650791**

Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H129

B7 **CON EDISON** **NY MANIFEST** **S117535593**
SSW **HUGENOT & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 2 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004677548
Country:	USA
Location Address 1:	HUGENOT & DIVISION ST
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677548
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014

CON EDISON (Continued) **S117535593**

Manifest Tracking Num:	012774875JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

B8 **CON EDISON MANHOLE: 1215** **RCRA NonGen / NLR** **1016678044**
SSW **HUGENOT AVE & DIVISION ST NE** **FINDS** **NYP004317285**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.009 mi. **ECHO**
48 ft.

Site 3 of 20 in cluster B

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/30/2013
Facility name:	CON EDISON MANHOLE: 1215
Facility address:	HUGENOT AVE & DIVISION ST NE COR NEW ROCHELLE, NY 10801
EPA ID:	NYP004317285
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/30/2013

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Site name: CON EDISON MANHOLE: 1215
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058874865

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004317285
Country: USA
Location Address 1: DIVISION ST & HUGUENOT ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/30/2013
Trans1 Recv Date: 05/30/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/30/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004317285
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010842831JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

Envid:	1016678044
Registry ID:	110058874865
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058874865

B9 **CON ED** **NY MANIFEST** **1016962307**
SSW **DIVISION ST & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 4 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004353199
Country:	USA
Location Address 1:	DIVISION ST AND HUGENOT ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2013
Trans1 Recv Date:	08/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON ED (Continued) **1016962307**

Generator EPA ID:	NYP004353199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011694814JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

B10 **CON EDISON - TRANSFORMER MANHOLE 1154** **RCRA-LQG** **1016962308**
SSW **DIVISION ST AND HUGENOT ST** **NYP004353199**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
48 ft. **Site 5 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - TRANSFORMER MANHOLE 1154
Facility address:	DIVISION ST AND HUGENOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004353199
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/29/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/29/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D008
. Waste name:	LEAD

Historical Generators:

Date form received by agency:	09/29/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 1154
Classification:	Not a generator, verified

Date form received by agency:	08/29/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 1154
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B11
SSW
< 1/8
0.009 mi.
48 ft.

Relative:
Higher

Actual:
101 ft.

CON EDISON
DIVISION & HUGUENOT
NEW ROCHELLE, NY

Site 6 of 20 in cluster B

NY MANIFEST **S117319604**
N/A

NY MANIFEST:

EPA ID:	NYP004676847
Country:	USA
Location Address 1:	DIVISION & HUGUENOT
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770952JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117319604**

Mgmt Method Type Code: H110

B12
SSW
< 1/8
0.009 mi.
48 ft.

Relative: Higher

Actual: 101 ft.

CON EDISON **NY MANIFEST** **S117535602**
HUGENOT ST & DIVISION ST **N/A**
NEW ROCHELLE, NY 10802

Site 7 of 20 in cluster B

NY MANIFEST:

EPA ID:	NYP004677894
Country:	USA
Location Address 1:	HUGENOT ST & DIVISION ST
Location Address 2:	MH 1218
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677894
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774861JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

CON EDISON (Continued) **S117535602**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

B13 **CON EDISON TRANSFORMER MANHOLE: 1154** **RCRA NonGen / NLR** **1016961985**
SSW **DIVISION ST & HUGUENOT ST** **NYP004349395**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
48 ft. **Site 8 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/21/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 1154
Facility address: DIVISION ST & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004349395
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

B14
SSW
< 1/8
0.010 mi.
52 ft.

NYSDOT BIN 1049890
DIVISION ST OVER METRO NORTH
NEW ROCHELLE, NY 10803

Site 9 of 20 in cluster B

RCRA NonGen / NLR | **1000789726** | **NYD987011897**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1049890
Facility address:	DIVISION ST OVER METRO NORTH NEW ROCHELLE, NY 10803
EPA ID:	NYD987011897
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	(914) 431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

NYSDOT BIN 1049890 (Continued) **1000789726**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

Date form received by agency: 08/12/1992
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

C15 **METRO NORTH TRACKS** **NY Spills** **S106126232**
WSW **EAST OF NEW ROCHELLE STAT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.010 mi.
53 ft. **Site 1 of 3 in cluster C**

Relative:
Lower

Actual:
81 ft.

SPILLS:
Facility ID: 0308130
Facility Type: ER
DER Facility ID: 226808
Site ID: 279322
DEC Region: 3
Spill Date: 2003-10-31
Spill Number/Closed Date: 0308130 / 2004-07-16
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2003-10-31
CID: 418
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-10-31
Spill Record Last Update: 2004-07-16
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -

METRO NORTH TRACKS (Continued) **S106126232**

Spiller Company:	001
Contact Name:	JOANNE REILLEY
Contact Phone:	(212) 340-3342
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/5/03 Joanne Reilly stated that the area is inaccessible to work in because of hi speed train taffic. Requested permission to cleanup during a planned closure for a capital project scheduled in 2004. Will submit request in writing to TG. TG 07-15-04 Letter rec'd from Metro North claiming cleanup has been completed. NFA. TG."
Remarks:	"caller states that spill is between 2 tracks and currently have a company rep enroute to the scene"

Material:

Site ID:	279322
Operable Unit ID:	874415
Operable Unit:	01
Material ID:	501652
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

C16 **METRO NORTH TRAIN STATION** **NY Spills** **S102153509**
WSW **NEW HAVEN LINE &R/R PLAZA** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.010 mi.
53 ft. **Site 2 of 3 in cluster C**

Relative:
Lower

Actual:
81 ft.

SPILLS:

Facility ID:	8903573
Facility Type:	ER
DER Facility ID:	92033
Site ID:	104107
DEC Region:	3
Spill Date:	1989-07-10
Spill Number/Closed Date:	8903573 / 1989-07-19
Spill Cause:	Vandalism
Spill Class:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-07-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-07-10
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False

METRO NORTH TRAIN STATION (Continued) **S102153509**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-19
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	METRO NORTH TRAIN STATION
Spiller Address:	NEW HAVEN LINE &R/R PLAZA
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"SOMEONE PUT STEEL BAR ON TRACK. TRAIN HIT BAR, PUNCTURED SMALL HOLE IN TRANFORMER. CAR #8669, EMPLOYEE WALKED TRACK. CLEAN UP IN PROGRESS. WCHD WILL INVESTIGATE, AMER. ENV. TECH, RCIHFIELD CT, NFA"

Material:

Site ID:	104107
Operable Unit ID:	928993
Operable Unit:	01
Material ID:	447657
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

A17 **MH1204** **NY Spills** **S104509750**
ESE **HUGUENOT AVE/LAWTON AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.019 mi.
100 ft. **Site 6 of 6 in cluster A**

Relative:
Higher

Actual:
91 ft.

SPILLS:

Facility ID:	9912755
Facility Type:	ER
DER Facility ID:	214030
Site ID:	262084
DEC Region:	3
Spill Date:	2000-02-09
Spill Number/Closed Date:	9912755 / 2000-02-14
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-02-09
CID:	270
Water Affected:	Not reported

MH1204 (Continued) **S104509750**

Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2000-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/09/2000 SOURCE UNKNOWN-NO OIL FILLED CONED EQUIPMENT NEARBY. VAC TRUCK BEING SENT TO SITE. WILL CALL WITH RESULTS OF PRODUCT I.D. SPILL VOLUME DOWNGRADED TO 3 GALLONS. 02/14/2000 CLEANUP REPORT SENT TO TARRYTOWN OFFICE. AMOUNT SPILLED WAS ACTUALLY 3 GALLONS. NFA"
Remarks:	"OIL STAGNANT SAMPLES WILL BE TAKEN CLEAN UP PENDING"

Material:

Site ID:	262084
Operable Unit ID:	1091472
Operable Unit:	01
Material ID:	294626
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B18 **MEMORIAL HIGHWAY AND** **NY Spills** **S104509646**
South **HUGUNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.022 mi.
114 ft. **Site 10 of 20 in cluster B**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9912617
Facility Type:	ER
DER Facility ID:	208558
Site ID:	254637
DEC Region:	3
Spill Date:	2000-02-04
Spill Number/Closed Date:	9912617 / 2000-04-04
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

MEMORIAL HIGHWAY AND (Continued) **S104509646**

	Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-02-04
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-04
Spill Record Last Update:	2000-04-14
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	AVALONBAY COMMUNITIES
Contact Phone:	(914) 576-3005
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/04/2000 STEVE AT AKRF. NEW ROCHELLE F.D. HAS BEEN ON SITE AS WELL AS T. GHIOSAY 04/04/2000 LETTER SENT TO AKRF BY T. GHIOSAY; CLEANUP SATISFACTORY - SPILL FILE CLOSED."
Remarks:	"CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL"

Material:

Site ID:	254637
Operable Unit ID:	1091315
Operable Unit:	01
Material ID:	294499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B19 **AVALON ON THE SOUND** **NY UST** **U003994344**
South **HUGUENOT STREET AND MEMORAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.022 mi.
116 ft. **Site 11 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800626 / Unregulated: <1101 gal. PBS
Operator Name:	Avalonbay
Owner Name:	Avalonbay Redevelopment LLC
Owner Street:	535 Fifth Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10017
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/01/2000
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

B20 **VACANT LOT** **NY LTANKS** **S107489335**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 12 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	356539
Spill Number/Closed Date:	0510542 / 2006-03-15
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported

VACANT LOT (Continued) **S107489335**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-15
Spiller Name:	STEVE GRENS
Spiller Company:	VACANT LOT
Spiller Address:	HUGUENOT ST/DIVISION ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVE GRENS
Spiller Phone:	(914) 806-5650
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306600
DEC Memo:	"March 15, 2006: BROOKSIDE ENVIRONMENTAL DISPOSED OF LUST AND 5.62 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM AKRF. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallons."

Material:

Site ID:	356539
Operable Unit ID:	1113840
Operable Unit:	01
Material ID:	2103900
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B21 **ROAD** **NY Spills** **S108130430**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
165 ft. **Site 13 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Facility ID:	0606187
Facility Type:	ER
DER Facility ID:	306600
Site ID:	369495
DEC Region:	3
Spill Date:	2006-08-29
Spill Number/Closed Date:	0606187 / 2006-09-03
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

ROAD (Continued) **S108130430**

	Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-29
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-29
Spill Record Last Update:	2006-09-03
Spiller Name:	JEFF CULLEN
Spiller Company:	GC RELIABLE SERVICE COMPA
Spiller Address:	80 GROVE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	WESTCHESTER FIRE CONTROL
Contact Phone:	(914) 231-1905
DEC Memo:	"DPW sanded road. No product to recover. jod"
Remarks:	"SPILL SPANS FOR FIVE BLOCKS BETWEEN THE TWO STREETS GIVEN IN LOCATION: CLEANUP IN PROGRESS: DPW ON SCENE:"

Material:

Site ID:	369495
Operable Unit ID:	1127329
Operable Unit:	01
Material ID:	2116923
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B22 **SHORELINE OIL** **NY LTANKS** **S102674768**
SSW **296 HUGENOT ST,REAR OF** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.033 mi.
174 ft. **Site 14 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	83347
Spill Number/Closed Date:	8709425 / 1988-04-06
Spill Date:	1988-02-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial

SHORELINE OIL (Continued) **S102674768**

Spill Class:	Not reported
Cleanup Ceased:	1988-04-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1988-05-02
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	1988-05-05
Spiller Name:	Not reported
Spiller Company:	SHORELINE OIL
Spiller Address:	34 EVANS ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10805
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76706
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : SITE INSPECT:NO EVIDENCE OF CONTAMINATION FROM OUTSIDE LOCKED GATE. N.F.A. T.D. 05/03/88: NO EVIDENCE OF CONTAMINATION OBSERVED DURING INSPECTION. NFA. "
Remarks:	"OIL INTO PRIVATE DRAIN, TO SUMP,TO SEWER,FROM CAPT.O'CONNOR NRFD(914-654-2215). COMPANY CLEANING UP. DEC TO INVESIGATE & VERIFY CLEAN UP. N.F.A. SEE UPDATE."

Material:

Site ID:	83347
Operable Unit ID:	914524
Operable Unit:	01
Material ID:	464747
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

B23
South
< 1/8
0.034 mi.
181 ft.

LILLIAN VERNON CO.
WESTCHESTER PLACE
NEW ROCHELLE, NY

Site 15 of 20 in cluster B

NY LTANKS **S100494788**
N/A

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	201286
Spill Number/Closed Date:	9213055 / 1995-03-16
Spill Date:	1993-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-03-16
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-23
Spill Record Last Update:	1995-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	167465
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO HAVE MEETING TO DISCUSS FURTHER ACTION TANK IS BEING PUMPED DOWN TEMP TANK BEING SET UP AES SYSTEM II"

Material:

Site ID:	201286
Operable Unit ID:	977443
Operable Unit:	01
Material ID:	570289
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

LILLIAN VERNON CO. (Continued) **S100494788**

Tank Test:

Site ID:	201286
Spill Tank Test:	1541204
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

C24 **NYSDOT BIN 1091390** **RCRA NonGen / NLR** **1000790435**
WSW **DIVISION ST OVER I 95** **NYD987019197**
< 1/8 **NEW ROCHELLE, NY 10803**
0.036 mi.
190 ft. **Site 3 of 3 in cluster C**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYSDOT BIN 1091390
Facility address:	DIVISION ST OVER I 95 NEW ROCHELLE, NY 10803
EPA ID:	NYD987019197
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	(914) 431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	4 BURNETT BLVD POUGHKEEPSIE, NY 12603
Owner/operator country:	US
Owner/operator telephone:	(914) 431-5743
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	4 BURNETT BLVD POUGHKEEPSIE, NY 12603
Owner/operator country:	US
Owner/operator telephone:	(914) 431-5743
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

NYSDOT BIN 1091390 (Continued) **1000790435**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

Date form received by agency: 09/25/1992
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

B25 **NEW ROCHELLE IRISH BENEVOLENT SOCIETY** **NY UST** **U003884840**
South **38 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.039 mi.
208 ft. **Site 16 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-600097 / Unregulated
Operator Name: New Rochelle Irish Benevolent Society
Owner Name: New Rochelle Irish Benevolent Society
Owner Street: 38 Division Street
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 26051652
Status: 5. Closed - removed
Capacity: 2000
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1940

NEW ROCHELLE IRISH BENEVOLENT SOCIETY (Continued) **U003884840**

Date Perm Closure:	01/09/2015
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	8. Wrapped (Piping)
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	9. Copper
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

B26 **JONES RESIDENCE** **NY LTANKS** **S106737602**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
239 ft. **Site 17 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	335236
Spill Number/Closed Date:	0410335 / 2005-09-11
Spill Date:	2004-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-12-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-17
Spill Record Last Update:	2005-09-11
Spiller Name:	DARRYL JONES
Spiller Company:	JONES RESIDENCE
Spiller Address:	311 HUGENOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DARRYL JONES
Spiller Phone:	(914) 632-5368
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	270458
DEC Memo:	"12/21/04 PBS FACILITY: 3-801006. jbo September 11, 2005: TANK CLOSED IN PLACE. FIVE SAMPLES TAKEN, NO CONTAMINATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-801006 "

JONES RESIDENCE (Continued) **S106737602**

Material:

Site ID:	335236
Operable Unit ID:	1097307
Operable Unit:	01
Material ID:	577292
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	335236
Spill Tank Test:	1548406
Tank Number:	1
Tank Size:	1500
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

B27 **TRINITY-ST. PAUL'S EPISCOPAL CHURCH** **NY UST** **U003995010**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
239 ft. **Site 18 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801006 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Trinity Episcopal Church
Owner Street:	311 Huguenot Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	03/23/2005
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

TRINITY-ST. PAUL'S EPISCOPAL CHURCH (Continued) **U003995010**

Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

D28 **HUGUENOT AND NORTH AVE** **NY Spills** **S106126832**
NE **HUGUENOT AND NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
243 ft. **Site 1 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

SPILLS:

Facility ID:	0310260
Facility Type:	ER
DER Facility ID:	252866
Site ID:	313618
DEC Region:	3
Spill Date:	2003-12-03
Spill Number/Closed Date:	0310260 / 2005-03-05
Spill Cause:	Traffic Accident
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-03
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-09
Spill Record Last Update:	2005-03-05
Spiller Name:	CARLOS TORRES
Spiller Company:	HUGUENOT AND NORTH AVE
Spiller Address:	HUGUENOT AND NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller Company:	001
Contact Name:	CARLOS TORRES
Contact Phone:	(914) 813-5166
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 3/5/05 5gallon surface spill--close "
Remarks:	"a tow truck carrying a dump truck . the dump truck ruptured and spilled about 5 to 6 gallons of fuel"

Material:

Tank Test:

D29
NE
< 1/8
0.046 mi.
243 ft.

CON EDISON MANHOLE: 5071
HUGUENOT AVE & NORTH AVE
NEW ROCHELLE, NY 10805

Site 2 of 8 in cluster D

RCRA NonGen / NLR
FINDS
NY MANIFEST
ECHO

1016677599
NYP004312476

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/14/2013
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGUENOT AVE & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004312476
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/14/2013
Site name:	CON EDISON MANHOLE: 5071
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110058876550

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

NY MANIFEST:

EPA ID:	NYP004312476
Country:	USA
Location Address 1:	HUGUENOT & NORTH AVE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007658348JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Envid: 1016677599
Registry ID: 110058876550
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110058876550

D30 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963620**
NE **NORTH AVE & HUGUENOT ST** **NY MANIFEST** **NYP004366100**
< 1/8 **NEW ROCHELLE, NY 10801**
0.046 mi.
243 ft. **Site 3 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:
Date form received by agency: 10/25/2013
Facility name: CON EDISON TRANSFORMER MANHOLE: 5042
Facility address: NORTH AVE & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004366100
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/25/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004366100
Country: USA
Location Address 1: NOAR/HUGUNOT ST
Location Address 2: MH5042

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/25/2013
Trans1 Recv Date: 09/25/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004366100
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 150
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694648JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

D31 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016968295**
NE **HUGENUOT ST & NORTH AVE** **NYP004419065**
< 1/8 **NEW ROCHELLE, NY 10805**
0.046 mi.
243 ft. **Site 4 of 8 in cluster D**

Relative:
Higher

Actual:
85 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/15/2014
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGENUOT ST & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004419065
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2014
Site name:	CON EDISON MANHOLE: 5071
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

E32 **MAIN LIBRARY** **NY LTANKS** **S103037429**
ESE **LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.046 mi.
243 ft. **Site 1 of 11 in cluster E**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	273025
Spill Number/Closed Date:	9713843 / 1998-03-27
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

MAIN LIBRARY (Continued) **S103037429**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	FRANK GALLELLO
Spiller Phone:	(914) 654-2315
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222185
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED - SYSTEM PASSED. NFA."
Remarks:	""

Material:

Site ID:	273025
Operable Unit ID:	1056692
Operable Unit:	01
Material ID:	324833
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	273025
Spill Tank Test:	1545675
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

MAIN LIBRARY (Continued) **S103037429**

Last Modified: Not reported
Test Method: Horner EZ Check I or II

E33 **ACCESSOCRAFT PRODUCTS INC** **RCRA NonGen / NLR** **1001079768**
SE **48 LAWTON ST** **FINDS** **NYR000014753**
< 1/8 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.046 mi. **ECHO**
245 ft. **Site 2 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ACCESSOCRAFT PRODUCTS INC
Facility address: 48 LAWTON ST
NEW ROCHELLE, NY 10802
EPA ID: NYR000014753
Mailing address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact: Not reported
Contact address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 654-2163
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 654-2163
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

Date form received by agency: 05/10/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 03/06/1996
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 10/11/1995
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Violation Status: No violations found

FINDS:

Registry ID: 110000849672

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000014753
Country: USA
Location Address 1: 48 LAWTON STREET
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: ACCESSOCRAFT INC
Contact: PAUL STEINMAN
Address: 48 LAWTON STREET
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-632-2411

Manifest:

Document ID: RIC0034295
Manifest Status: Completed copy

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Trans1 State ID:	RI49238
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1996
Trans1 Recv Date:	01/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/23/1996
Part A Recv Date:	02/01/1996
Part B Recv Date:	02/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	RID059735761
Trans2 EPA ID:	Not reported
TSDF ID:	RID059735761
Waste Code:	F009 - UNKNOWN
Quantity:	00148
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Quantity:	00160
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity:	00152
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NYB6969834
Manifest Status:	Completed copy
Trans1 State ID:	NYPP5193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/1995
Trans1 Recv Date:	10/23/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/23/1995
Part A Recv Date:	02/22/1996
Part B Recv Date:	11/07/1995
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00195
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: NYB6969807
Manifest Status: Completed copy
Trans1 State ID: PD1011
Trans2 State ID: Not reported
Generator Ship Date: 10/19/1995
Trans1 Recv Date: 10/19/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 10/19/1995
Part A Recv Date: 02/22/1996
Part B Recv Date: 11/07/1995
Generator EPA ID: NYR000014753
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: F006 - WW TREAT SL FM ELECTROPLATING OPER
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1995

Document ID: NYB7484175
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: LB49775QC
Generator Ship Date: 12/19/1995
Trans1 Recv Date: 12/19/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 12/20/1995
Part A Recv Date: 01/04/1996

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Part B Recv Date:	01/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	NYD986909752
Trans2 EPA ID:	Not reported
TSDF ID:	CDD980756415
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Quantity:	07496
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1995

ECHO:

Envid:	1001079768
Registry ID:	110000849672
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110000849672

F34 **SPILL NUMBER 9803949** **NY Spills** **S104647160**
WSW **MILEPOST 5.5 SB I95** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.049 mi.
261 ft. **Site 1 of 2 in cluster F**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	9803949
Facility Type:	ER
DER Facility ID:	140562
Site ID:	166821
DEC Region:	3
Spill Date:	1998-06-29
Spill Number/Closed Date:	9803949 / 1998-06-29
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-29
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-29
Spill Record Last Update:	1998-07-02
Spiller Name:	MR STEPHEN WELDON
Spiller Company:	STEPHENS TRANSP INC
Spiller Address:	60 JOFFRE
Spiller City,St,Zip:	AUBURN, ME 04210-
Spiller Company:	001

SPILL NUMBER 9803949 (Continued) **S104647160**

Contact Name: SGT POWELL
Contact Phone: (800) 635-8856
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "drive shaft broke on trk rupturing the saddle tank - cleanup in progress"

Material:
Site ID: 166821
Operable Unit ID: 1064663
Operable Unit: 01
Material ID: 322269
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

D35 **UNITED STATES POST OFFICE** **NY UST** **U004177544**
ENE **255 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.049 mi.
261 ft. **Site 5 of 8 in cluster D**

Relative: Higher

Actual: 87 ft.

WESTCHESTER CO. UST:
Id/Status: 3-448699 / Unregulated: <1101 gal. PBS
Operator Name: U.S. Postal Service
Owner Name: U.s. Postal Service
Owner Street: 255 North Ave.
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10802
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 05/01/2003
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: Not reported
Piping Type: 2. Galvanized steel
Piping External Protection: 0. None

UNITED STATES POST OFFICE (Continued) **U004177544**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

D36 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1005444315**
ENE **255 NORTH AVE** **NY MANIFEST** **NYR000106369**
< 1/8 **NEW ROCHELLE, NY 10801**
0.049 mi.
261 ft. **Site 6 of 8 in cluster D**

Relative:
Higher

Actual:
87 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	US POSTAL SERVICE
Facility address:	255 NORTH AVE NEW ROCHELLE, NY 108019998
EPA ID:	NYR000106369
Mailing address:	WESTCHESTER AVE WHITE PLAINS, NY 106109111
Contact:	JOANNE KUNNY
Contact address:	WESTCHESTER AVE WHITE PLAINS, NY 106109111
Contact country:	US
Contact telephone:	(914) 697-7074
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	255 NORTH AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 632-5906

US POSTAL SERVICE (Continued) **1005444315**

Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: US POSTAL SERVICE
Owner/operator address: 255 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-5906
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: US POSTAL SERVICE
Classification: Not a generator, verified

Date form received by agency: 05/17/2002
Site name: US POSTAL SERVICE
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000106369
Country: USA
Location Address 1: 255 NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:

US POSTAL SERVICE (Continued) **1005444315**

Name: US POSTAL SERVICE
Contact: RICHARD FERRARI
Address: 255 NORTH AVENUE
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-697-7074

Manifest:

Document ID: NYG2937357
Manifest Status: Not reported
Trans1 State ID: 27571PANY
Trans2 State ID: PW8913
Generator Ship Date: 05/29/2002
Trans1 Recv Date: 05/29/2002
Trans2 Recv Date: 05/30/2002
TSD Site Recv Date: 05/31/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000106369
Trans1 EPA ID: NYD986908085
Trans2 EPA ID: NYD082785429
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00060
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

B37 **CERUSSI AND VERE** **NY UST** **U004187246**
SSW **306 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 19 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:
Id/Status: 3-078360 / Administratively Closed
Operator Name: Not reported
Owner Name: Michael A Cerussi & F G Vere
Owner Street: 88 Woodlands Rd
Owner Address2: Not reported
Owner City: Harrison
Owner State: NY
Owner Zipcode: 10528
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 1500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1986
Date Perm Closure: 12/01/2001

CERUSSI AND VERE (Continued) **U004187246**

Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

B38 **306 HUGUENOT STREET CORP.** **NY AST** **U004187406**
SSW **306 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 20 of 20 in cluster B**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. AST:

PBS Number:	3-800236
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	306 Huguenot Street Corp.
Owner Street:	P.O. Box 196
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	001
Status:	1. In-Service
Date Installation:	12/01/1986
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	Not reported
Dispenser:	3. Gravity

D39 **KAUFMAN HUGUENOT COMPANY** **NY UST** **U003994672**
NE **271 NORTH AVENUE** **NY AST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
290 ft. **Site 7 of 8 in cluster D**

Relative:
Higher

Actual:
84 ft.

WESTCHESTER CO. UST:

Id/Status:	3-183776 / Active
Operator Name:	David Rabius
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10123
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1900
Date Perm Closure:	01/01/2011
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-183776
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Rabius
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10123
Tank Number:	002
Status:	1. In-Service
Date Installation:	08/01/2007
Capacity:	5000
Product Stored:	4. No. 6 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

KAUFMAN HUGUENOT COMPANY (Continued) **U003994672**

Tank Leak Detection:	4. Groundwater Well
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	2. Transfer Station Containment
Dispenser:	2. Suction

E40 **PAVEMENT** **NY Spills** **S112147960**
ESE **41 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.056 mi.
294 ft. **Site 3 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Facility ID:	1203965
Facility Type:	ER
DER Facility ID:	421153
Site ID:	466814
DEC Region:	3
Spill Date:	2012-07-23
Spill Number/Closed Date:	1203965 / 2012-07-23
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2012-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-23
Spill Record Last Update:	2012-07-23
Spiller Name:	BADGE 620
Spiller Company:	UNKNOWN
Spiller Address:	41 LAWTON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	BADGE 620
Contact Phone:	(914) 231-1905
DEC Memo:	"7-23-12 FD cleaned up. jc"
Remarks:	"Possibly from garbage truck. Fire Dept. Clean up."

Material:

Site ID:	466814
Operable Unit ID:	1216796

PAVEMENT (Continued) **S112147960**

Operable Unit:	01
Material ID:	2215011
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

E41 **LAWTON STREET REALTY CORP.** **NY UST** **U004176798**
ESE **41-43 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
294 ft. **Site 4 of 11 in cluster E**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801435 / Active
Operator Name:	Lawton Street Realty Corp.
Owner Name:	Lawton Street Realty Corp.
Owner Street:	4391 Boston Post Road
Owner Address2:	Not reported
Owner City:	Pelham Manor
Owner State:	NY
Owner Zipcode:	10803
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	06/01/1927
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

D42 **FEDERAL PROPERTY MAINTENANCE CORP** **RCRA NonGen / NLR** **1012186472**
East **244 NORTH AVE SUITE 153** **NYR000163337**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
295 ft. **Site 8 of 8 in cluster D**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/23/2009
Facility name:	FEDERAL PROPERTY MAINTENANCE CORP
Facility address:	244 NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
EPA ID:	NYR000163337
Mailing address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact:	KRISTIE EFFEREN
Contact address:	NORTH AVE SUITE 153 NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 355-2226
Contact email:	FEDERALPMC@AOL
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KRISTIE EFFEREN
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/24/2005
Owner/Op end date:	Not reported

Owner/operator name:	ANTHONY VALENTINO
Owner/operator address:	GRANT AVE HARRISON, NY 10528
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/20/1978
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

G43 **EDR Hist Cleaner** **1015025386**
NW **24 STATION PLZ N** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
302 ft. **Site 1 of 2 in cluster G**

Relative:
Lower

Actual:
71 ft.

EDR Historical Cleaners:
Name: GREEN TRAIN CLEANERS
Year: 2011
Address: 24 STATION PLZ N

G44 **EDR Hist Cleaner** **1015025387**
NW **24 STATION PLZ** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
302 ft. **Site 2 of 2 in cluster G**

Relative:
Lower

Actual:
71 ft.

EDR Historical Cleaners:
Name: STATION CLEANERS
Year: 2006
Address: 24 STATION PLZ

Name: M & E DRY CLEANERS
Year: 2012
Address: 24 STATION PLZ

H45 **CABLE** **NY Spills** **S109206706**
South **29 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.057 mi.
303 ft. **Site 1 of 5 in cluster H**

Relative:
Higher

Actual:
101 ft.

SPILLS:
Facility ID: 0804961
Facility Type: ER
DER Facility ID: 351170
Site ID: 401965
DEC Region: 3
Spill Date: 2008-07-30
Spill Number/Closed Date: 0804961 / 2008-07-30
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: jpcummin
Referred To: Not reported
Reported to Dept: 2008-07-30
CID: 444
Water Affected: Not reported

CABLE (Continued) **S109206706**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-07-31
Spiller Name:	ERTSDESK
Spiller Company:	CABLE
Spiller Address:	29 DIVISION STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERTSDESK
Contact Phone:	(212) 580-8383
DEC Memo:	"SEE SP: 0804960. -- NFA"
Remarks:	"8 OUNCES AND ON GOING AND WONT MAKE 2 HOUR CLEAN UP"

Material:

Site ID:	401965
Operable Unit ID:	1158737
Operable Unit:	01
Material ID:	2149827
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

I46 **NORTH BROOK REALTY ASSOCIATES** **NY UST** **U003994769**
NNE **270 NORTH AVENUE - UNDERGROUND** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.062 mi.
329 ft. **Site 1 of 7 in cluster I**

Relative:
Lower

Actual:
80 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600117 / Active
Operator Name:	North Brook Realty Associates
Owner Name:	270 North Avenue Realty Corp.
Owner Street:	270 North Avenue, Suite 200
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	15000

NORTH BROOK REALTY ASSOCIATES (Continued) **U003994769**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

I47 **277 NORTH LLC** **NY LTANKS** **S108467546**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 2 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	376329
Spill Number/Closed Date:	0611648 / 2008-12-04
Spill Date:	2007-01-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-19
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE MOSES
Spiller Company:	277 NORTH LLC
Spiller Address:	277 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	BRUCE MOSES
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11580 12/4/08: Northeast

277 NORTH LLC (Continued) **S108467546**

Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"

Remarks: "EZ 3 LP WAS TEST USED: TANK IS BEING VACCED OUT AND TEMP TANK PUT IN PLACE: ARRANGEMENTS FOR FURTHER TESTING ARE BEING MADE:"

Material:

Site ID:	376329
Operable Unit ID:	1133914
Operable Unit:	01
Material ID:	2123743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	376329
Spill Tank Test:	1550579
Tank Number:	1
Tank Size:	10000
Test Method:	99
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v

I48 **CON EDISON MANHOLE: 11295** **RCRA NonGen / NLR** **1016960384**
NNE **277 NORTH AVE** **NY MANIFEST** **NYP004323457**
< 1/8 **NEW ROCHELLE, NY 10802**
0.072 mi.
382 ft. **Site 3 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2013
Facility name:	CON EDISON MANHOLE: 11295
Facility address:	277 NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004323457
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/28/2013
Site name:	CON EDISON MANHOLE: 11295
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004323457
Country:	USA
Location Address 1:	FO 277 NORTH AVE
Location Address 2:	MH #11295
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2013
Trans1 Recv Date:	06/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004323457

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011693229JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

I49 **BUSINESS** **NY LTANKS** **S108467526**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 4 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	376243
Spill Number/Closed Date:	0611580 / 2008-12-04
Spill Date:	2007-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-18
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE
Spiller Company:	BUSINESS
Spiller Address:	277 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

BUSINESS (Continued) **S108467526**

Spiller Contact:	BRUCE
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11648 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"PIN HOLE IN TANK"

Material:

Site ID:	376243
Operable Unit ID:	1133835
Operable Unit:	01
Material ID:	2123664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	376243
Spill Tank Test:	1550567
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

I50 **277 NORTH LLC** **NY UST** **U003994270**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.072 mi.
382 ft. **Site 5 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

WESTCHESTER CO. UST:

Id/Status:	3-502049 / Active
Operator Name:	Bruce J. Moses
Owner Name:	Robert J. Leaf
Owner Street:	3720 South Ocean Blvd
Owner Address2:	#1606
Owner City:	Highland Beach
Owner State:	FL
Owner Zipcode:	33487
GDS Number:	Not reported

277 NORTH LLC (Continued) **U003994270**

Tank Number:	1
Status:	5. Closed - removed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	01/01/1900
Date Perm Closure:	10/10/2007
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	10/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	7. Jacketed (tank),9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	10. Flexible Piping
Piping External Protection:	8. Wrapped (Piping),9. Urethane
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

I51 **EAST RIVER SAVINGS BANK** **NY LTANKS** **U003647446**
NNE **277 NORTH AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
382 ft. **Site 6 of 7 in cluster I**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Site ID:	271129
Spill Number/Closed Date:	8912285 / 1991-01-16
Spill Date:	1990-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True

EAST RIVER SAVINGS BANK (Continued) **U003647446**

SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-03-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-29
Spill Record Last Update:	1991-03-19
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220684
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/19/91: TANK WAS REKINED AND PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK WAS ISOLATED AND THEY WILL RETEST PETRO-TITE -.3385 GPH"

Material:

Site ID:	271129
Operable Unit ID:	937979
Operable Unit:	01
Material ID:	441756
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	271129
Spill Tank Test:	1536885
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

F52
West
< 1/8
0.074 mi.
392 ft.

107 DIVISION ST — **EDR Hist Auto** — **1015143779** / **N/A**
NEW ROCHELLE, NY 10801

Site 2 of 2 in cluster F

Relative: Higher

Actual: 89 ft.

EDR Historical Auto Stations:

Name:	VARIEDADES CENTER REPAIR
Year:	2012
Address:	107 DIVISION ST

H53
South
< 1/8
0.080 mi.
422 ft.

ARIEL CABLE — **NY Spills** — **S109206705** / **N/A**
19 DIVISION STREET/WASHIN
NEW ROCHELLE, NY

Site 2 of 5 in cluster H

Relative: Higher

Actual: 100 ft.

SPILLS:

Facility ID:	0804960
Facility Type:	ER
DER Facility ID:	351169
Site ID:	401964
DEC Region:	3
Spill Date:	2008-07-30
Spill Number/Closed Date:	0804960 / 2008-08-16
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-08-16
Spiller Name:	ERTSDESK
Spiller Company:	ARIEL CABLE
Spiller Address:	19 DIVISION STREET/WASHIN
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERTSDESK
Contact Phone:	(212) 580-8383
DEC Memo:	"CONTRACTOR ENROUTE"
Remarks:	"6 OUNCES AND ONGOING AND CRW WILL BE ENROUTE"

Material:

Site ID:	401964
Operable Unit ID:	1158736
Operable Unit:	01
Material ID:	2149826
Material Code:	0541A

ARIEL CABLE (Continued) **S109206705**

Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

J54 **5 ANDERSON ST** **NY LTANKS** **S103559119**
East **5 ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.081 mi.
427 ft. **Site 1 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	68771
Spill Number/Closed Date:	9812585 / 1999-07-12
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	1999-09-07
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

Material:

Site ID:	68771
Operable Unit ID:	1069838

5 ANDERSON ST (Continued) **S103559119**

Operable Unit:	01
Material ID:	312860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	68771
Spill Tank Test:	1546739
Tank Number:	2
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Site ID:	68769
Spill Number/Closed Date:	8803214 / 1989-11-30
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-28
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	YOSHIAKI KOWANISHA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	281826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

5 ANDERSON ST (Continued) **S103559119**

OKESSON "
Remarks: "2K FAILED 4-GAL. PER HOUR"

Material:
Site ID: 68769
Operable Unit ID: 918394
Operable Unit: 01
Material ID: 458777
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 68769
Spill Tank Test: 1534286
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

Site ID: 68770
Spill Number/Closed Date: 9812584 / 1999-07-12
Spill Date: 1999-01-12
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1999-01-12
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-01-12
Spill Record Last Update: 2003-07-01
Spiller Name: YOSHIAKI KAWANISHA
Spiller Company: 5 ANDERSON ST

5 ANDERSON ST (Continued) **S103559119**

Spiller Address:	5 ANDERSON ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

Material:

Site ID:	68770
Operable Unit ID:	1069836
Operable Unit:	01
Material ID:	557973
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	68770
Spill Tank Test:	1546738
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

J55 **ANDERSON DEVELOPMENT GROUP** **NY AST** **A100276594**
East **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 2 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:

PBS Number:	3-185515
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Yonkers, NY 10701
Tank Number:	01
Status:	6. Closed - Work Permit Open

ANDERSON DEVELOPMENT GROUP (Continued) **A100276594**

Date Installation:	04/01/1999
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	02/10/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access),5. Synthetic Liner
Piping Location:	1. Aboveground
Piping Type:	2. Galvanized Steel
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	7. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

J56 **ANDERSON DEVELOPMENT GROUP** **NY UST** **U003994331**
East **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
427 ft. **Site 3 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. UST:

Id/Status:	3-185515 / Unregulated
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	7. Excavation/trench Liner system
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

ANDERSON DEVELOPMENT GROUP (Continued) **U003994331**

Tank Number:	2
Status:	5. Closed - removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

E57 **CON EDISON TRANSFORMER MANHOLE: 3585** **RCRA NonGen / NLR** **1016963788**
East **NORTH AVE & ANDERSON ST** **NY MANIFEST** **NYP004367611**
< 1/8 **NEW ROCHELLE, NY 10802**
0.081 mi.
428 ft. **Site 5 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/29/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3585
Facility address:	NORTH AVE & ANDERSON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004367611
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 3585
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004367611
Country: USA
Location Address 1: NORTH AVE & ANDERSON ST
Location Address 2: TM3585
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2013
Trans1 Recv Date: 09/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004367611
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694650JJK
Import Ind: N
Export Ind: N

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E58 **CON EDISON** **NY MANIFEST** **S113920666**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 6 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004683272
Country:	USA
Location Address 1:	NORTH AVE & ANDERSON ST
Location Address 2:	TM3585
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2014
Trans1 Recv Date:	10/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S113920666**

Year:	2014
Manifest Tracking Num:	012773173JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E59 **CON EDISON** **NY MANIFEST** **S118088384**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.081 mi.
428 ft. **Site 7 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004759452
Country:	USA
Location Address 1:	NORTH AVE & ANDERSON ST
Location Address 2:	TM 3585
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S118088384**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091137JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091137JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

E60 **CON EDISON** **NY MANIFEST** **S117538298**
East **ANDERSON ST & NORTH AV** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
428 ft. **Site 8 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004709622
Country:	USA
Location Address 1:	ANDERSON ST & NORTH AV
Location Address 2:	SB2063
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709622
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012773453JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117538298**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

E61 **MKM EQUITY, LLC** **NY AST** **A100365275**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.085 mi.
447 ft. **Site 9 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:

PBS Number:	3-600105
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MKM Equity, LLC c/o Cornell Pace Inc.
Owner Street:	542 Main Street, Ste. 2
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	5. Closed - removed
Date Installation:	08/01/1931
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2014
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	0. None

E62 **CONCRETE FLOORING WITH CRACKS** **NY Spills** **S116554293**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.085 mi.
447 ft. **Site 10 of 11 in cluster E**

Relative:
Higher

Actual:
90 ft.

SPILLS:

Facility ID:	1400277
Facility Type:	ER
DER Facility ID:	448397
Site ID:	493512
DEC Region:	3
Spill Date:	2014-04-08
Spill Number/Closed Date:	1400277 / Not Reported
Spill Cause:	Equipment Failure

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	WCDOH PBS
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2014-04-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2014-04-10
Spiller Name:	Not reported
Spiller Company:	STERLING SOLUTIONS
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	FRANK LANZELLI
Contact Phone:	(914) 666-4328
DEC Memo:	"4-9-14 Last night I traded voicemails with Jerry. He said that he didn't know anymore than provided to the Hotline and I should talk to Frank in the morning. This morning I spoke to Frank. Location has a 1500 gallon vaulted tank with a remote fill at curb. There is currently some oil in the basement sump. Sump is unplugged and it doesn't appear any was pumped out. Frank doesn't know where oil came from, but vault sounds inaccessible. Frank is trying to contact management company to let them know tank needs to be tested. Management Company: Sterling Solutions, 914/437-6245, Aurora is Almeada contact Owner: Milka Iwanow, 914/409-6513 jc 4/09/14: Email received this morning from Chris Lalak: Sebastian went to this one and will follow up. It is a block away from my office. The tank in a vaulted AST (1500 gallon from 1931). There is a spill across the floor and in cracks in the floor getting to a sump pump. The sump goes to the sanitary. The spill may have been going on for so time, the super was very vague. The AST is visible except for a small area that sticks into the floor of the vault. The tank is not visibly leaking. Almeida replaced the underground lines with above ground lines recently. The between the tank, the former underground lines, and the sump is some distance and they will need to excavate the floor. The building has hired Dutchess. Pumping out the tank is not simple. The building has natural gas and oil. jod 04-09-14 followup email, After a second look at this one with a plumber,It looks like the old lines might be leaking. The plumber will uncover the old lines. The tank is not being pumped out at this time. The bottom of the tank is visible for the most part. (the plumber went in the vault, before we were there).Possibly, the remote fill is also an issue. They will replace the tank with an unregulated tank. Sebastian will continue to handle the spill. The floor will be opened up tomorrow to investigate. RDB "
Remarks:	"Caller advised unknown amount of oil spilled onto concrete floor with cracks. Clean up is pending."

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Material:

Site ID:	493512
Operable Unit ID:	1243015
Operable Unit:	01
Material ID:	2243651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

H63 **COMM/RESIDENT. PROPERTY** **NY LTANKS** **S101341321**
South **15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.089 mi.
468 ft. **Site 3 of 5 in cluster H**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	119901
Spill Number/Closed Date:	9405558 / 2005-02-10
Spill Date:	1994-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104134

COMM/RESIDENT. PROPERTY (Continued) **S101341321**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. Tank taken out of service by Royal Environmental. "
Remarks: "TANK TEST ON 7/21/94"

Material:
Site ID: 119901
Operable Unit ID: 1002771
Operable Unit: 01
Material ID: 382138
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 119901
Spill Tank Test: 1542973
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

E64 **NEW ROCHELLE PUBLIC LIBR.** **NY LTANKS** **S100177858**
ESE **MEMORIAL HIGHWAY** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
486 ft. **Site 11 of 11 in cluster E**

Relative:
Higher

Actual:
93 ft.

LTANKS:
Site ID: 306853
Spill Number/Closed Date: 9111450 / 1992-02-06
Spill Date: 1992-02-06
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-02-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported

NEW ROCHELLE PUBLIC LIBR. (Continued) **S100177858**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247822
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SOME ON PAVEMENT,SOME IN STORM DRAIN F.D.HAZMAT USED SORBENT TO CONTAIN AND VENTED BUILING SPOKE WITH DEP. CHIEF STONE"

Material:

Site ID:	306853
Operable Unit ID:	965176
Operable Unit:	01
Material ID:	416486
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

K65 **APARTMENT BLDG** **NY LTANKS** **S105996855**
SSW **54 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
487 ft. **Site 1 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	254563
Spill Number/Closed Date:	0206558 / 2005-02-27
Spill Date:	2002-09-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D

APARTMENT BLDG (Continued) **S105996855**

Reported to Dept:	2002-09-24
CID:	390
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2005-02-27
Spiller Name:	ENERITO GONZALEZ
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AV
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	ENERITO GONZALEZ
Spiller Phone:	(914) 309-2775
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208499
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 2/27/05 #4 overfill to surface--close "
Remarks:	"spill was noticed on 9/6 - unk when it occurred"

Material:

Site ID:	254563
Operable Unit ID:	858169
Operable Unit:	01
Material ID:	517160
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	84302
Spill Number/Closed Date:	0403405 / 2004-12-10
Spill Date:	2004-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-06-29
CID:	406

APARTMENT BLDG (Continued) **S105996855**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-29
Spill Record Last Update:	2004-12-10
Spiller Name:	BASSAM MABER
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BASSAM MABER
Spiller Phone:	(914) 645-6420
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77542
DEC Memo:	"12/10/04 PBS facility. Tank passed a retest after piping was repaired. Spill file closed by Danielle Jackson of the Westchester County Health Dept. No further action is required at this time. jbo"
Remarks:	"Tank Test Failure. Reccommend Retest."

Material:

Site ID:	84302
Operable Unit ID:	886824
Operable Unit:	01
Material ID:	490990
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	84302
Spill Tank Test:	1529391
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

K66 **CEMENT COURT YARD** **NY Spills** **S104282704**
SSW **54 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
487 ft. **Site 2 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Facility ID:	9908117
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114516
DEC Region:	3
Spill Date:	1999-10-04
Spill Number/Closed Date:	9908117 / 1999-10-04
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1999-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-04
Spill Record Last Update:	1999-10-06
Spiller Name:	Not reported
Spiller Company:	CEMENT COURT YARD
Spiller Address:	54 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 10/4/99 SPILLER CLEANED UP. NFA"
Remarks:	"BLDG SUPER OVERORDERED - CLEANED UP"

Material:

Site ID:	114516
Operable Unit ID:	1082403
Operable Unit:	01
Material ID:	555958
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	Gallons
Recovered:	6.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CEMENT COURT YARD (Continued) **S104282704**

Tank Test:

Facility ID:	9804849
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114515
DEC Region:	3
Spill Date:	1998-07-18
Spill Number/Closed Date:	9804849 / 2002-07-15
Spill Cause:	Deliberate
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-18
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-18
Spill Record Last Update:	2002-07-15
Spiller Name:	Not reported
Spiller Company:	NABER REALTY INC
Spiller Address:	BOX 156H
Spiller City,St,Zip:	SCARSDALE, NY 10583-
Spiller Company:	001
Contact Name:	CAPT DIMEGLIA
Contact Phone:	(914) 654-2215
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"fd called to an odor of fuel oil in a residence- upon arrival in basement it appeared were working on the oil boiler and were pumping product into sewer thru sump pumps"

Material:

Site ID:	114515
Operable Unit ID:	1065894
Operable Unit:	01
Material ID:	319611
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CEMENT COURT YARD (Continued) **S104282704**

Tank Test:

K67 **SEASONWEIN MANAGEMENT LLC** **NY UST** **U003994353**
SSW **54 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.092 mi.
487 ft. **Site 3 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

WESTCHESTER CO. UST:

Id/Status:	3-169773 / Active
Operator Name:	Matt Seasonwein
Owner Name:	Seasonwein Management LLC
Owner Street:	300 Gramatan Avenue
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10552
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1928
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

---

68 **EDR Hist Auto** **1015441959**
West **35 UNION AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
519 ft.

Relative:
Higher

Actual:
101 ft.

EDR Historical Auto Stations:

Name:	RANILLAS AUTO BODY SHOP
Year:	2007
Address:	35 UNION AVE

K69 **CON EDISON** **RCRA NonGen / NLR** **1014398803**
SSW **HUGUENOT ST & CENTRE ST** **NYP004211728**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 4 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/19/2010
Facility name:	CON EDISON
Facility address:	HUGUENOT ST & CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004211728
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

K70 **CON EDISON** **NY MANIFEST** **S117319603**
SSW **CENTER & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.099 mi.
521 ft. **Site 5 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

EPA ID:	NYP004676839
Country:	USA
Location Address 1:	CENTER & HUGUENOT
Location Address 2:	MH 1230
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON

CON EDISON (Continued) **S117319603**

Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770954JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K71 **CON EDISON** **NY MANIFEST** **S113917500**
SSW **CENTRE AVE & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 6 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

EPA ID:	NYP004332961
Country:	USA
Location Address 1:	CENTRE AVE & HUGUENOT ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801

CON EDISON (Continued) **S113917500**

Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2013
Trans1 Recv Date: 07/22/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004332961
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011695949JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

K72 **CON EDISON** **NY MANIFEST** **S117535592**
SSW **HUGENOT & CENTRE ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 7 of 20 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:
EPA ID: NYP004677530
Country: USA
Location Address 1: HUGENOT & CENTRE ST
Location Address 2: MH 1230

CON EDISON (Continued) **S117535592**

Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/14/2014
Trans1 Recv Date: 10/14/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677530
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012774876JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

J73 **CVS PHARMACY #8447** **RCRA-LQG** **1014958220**
ESE **222 NORTH AVE** **NY MANIFEST** **NYR000194654**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
523 ft. **Site 4 of 7 in cluster J**

Relative:
Higher

Actual:
91 ft.

RCRA-LQG:

Date form received by agency:	03/17/2014
Facility name:	CVS PHARMACY #8447
Facility address:	222 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYR000194654
Mailing address:	CVS DR 23062A WOONSOCKET, RI 02895
Contact:	WENDY BRANT
Contact address:	CVS DR WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	(401) 765-1500
Contact email:	WENDY.BRANT@CVSCAREMARK.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	45 SOUTH MAIN STREET CORP
Owner/operator address:	GLEN OAKS DR RYE, NY 10580
Owner/operator country:	US
Owner/operator telephone:	(917) 757-4922
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/20/2011
Owner/Op end date:	Not reported

Owner/operator name:	45 SOUTH MAIN STREET CORP
Owner/operator address:	GLEN OAKS DRIVE RYE, NY 10580
Owner/operator country:	US
Owner/operator telephone:	(917) 757-4922
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/20/2011
Owner/Op end date:	Not reported

Owner/operator name:	CVS ALBANY, L.L.C.
Owner/operator address:	GLEN OAKS DRIVE RYE, NY 10580

CVS PHARMACY #8447 (Continued) **1014958220**

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D010
. Waste name: SELENIUM

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL--YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

CVS PHARMACY #8447 (Continued) **1014958220**

Historical Generators:
Date form received by agency: 07/01/2013
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Date form received by agency: 03/05/2012
Site name: CVS PHARMACY #8447
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081

CVS PHARMACY #8447 (Continued) **1014958220**

. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000194654
Country: USA
Location Address 1: 222 NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CVS PHARMACY #8447
Contact: CVS PHARMACY #8447
Address: 222 NORTH AVE
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-637-7591

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJR000063677
Generator Ship Date: 05/13/2015
Trans1 Recv Date: 05/13/2015
Trans2 Recv Date: 05/19/2015
TSD Site Recv Date: 05/21/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID040098352
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 007425277FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

CVS PHARMACY #8447 (Continued) **1014958220**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/13/2015
Trans1 Recv Date:	05/13/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	05/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	17
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007425277FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/17/2015
Trans1 Recv Date:	10/17/2015
Trans2 Recv Date:	10/23/2015
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	6
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

CVS PHARMACY #8447 (Continued) **1014958220**

Year:	2015
Manifest Tracking Num:	008652237FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/13/2015
Trans1 Recv Date:	05/13/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	06/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007425276FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/17/2015
Trans1 Recv Date:	10/17/2015

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 Recv Date:	10/23/2015
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008652238FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	03/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007385576FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	03/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007385576FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	07/30/2015
TSD Site Recv Date:	08/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	2
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006428508FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJR000063677
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	07/30/2015
TSD Site Recv Date:	08/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	7
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006428508FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJR000063677
Generator Ship Date: 02/24/2015
Trans1 Recv Date: 02/24/2015
Trans2 Recv Date: 02/26/2015
TSD Site Recv Date: 03/25/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 0.04
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 007385576FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 09/09/2014
Trans1 Recv Date: 09/09/2014
Trans2 Recv Date: 09/23/2014
TSD Site Recv Date: 10/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 5
Units: P - Pounds
Number of Containers: 1

CVS PHARMACY #8447 (Continued) **1014958220**

Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	Not reported
Quantity:	6
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274057FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924

CVS PHARMACY #8447 (Continued) **1014958220**

Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	Not reported
Quantity:	3
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274057FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	PAD982661381
Generator Ship Date:	12/08/2014
Trans1 Recv Date:	12/08/2014
Trans2 Recv Date:	12/15/2014
TSD Site Recv Date:	01/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007292048FLE
Import Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	PAD982661381
Generator Ship Date:	12/08/2014
Trans1 Recv Date:	12/08/2014
Trans2 Recv Date:	12/15/2014
TSD Site Recv Date:	01/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	4
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007292048FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/09/2014
Part A Recv Date:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/23/2014
TSD Site Recv Date:	10/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007274056FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

CVS PHARMACY #8447 (Continued) **1014958220**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	06/16/2014
Trans1 Recv Date:	06/16/2014
Trans2 Recv Date:	06/19/2014
TSD Site Recv Date:	06/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.01
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007211387FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	03/28/2014
Trans1 Recv Date:	03/28/2014
Trans2 Recv Date:	04/03/2014
TSD Site Recv Date:	04/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Quantity:	27
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	006441835FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164
Generator Ship Date:	03/28/2014
Trans1 Recv Date:	03/28/2014
Trans2 Recv Date:	04/03/2014
TSD Site Recv Date:	04/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	INR000110197
Waste Code:	Not reported
Quantity:	0.04
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	006441835FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

L74 **DELUXE TAXI** **NY UST** **U001736524**
North **10 STATION PLAZA** **N/A**
< 1/8 **NEW ROCHELLE - WESCHESTER, NY 10801**
0.100 mi.
529 ft. **Site 1 of 11 in cluster L**

Relative:
Lower

Actual:
77 ft.

UST:

Id/Status:	2-601600 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	566353.87500
UTM Y:	4486105.00000
Site Type:	Unknown

Affiliation Records:

Site Id:	23562
Affiliation Type:	Facility Owner
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Mail Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	On-Site Operator
Company Name:	DELUXE TAXI
Contact Type:	Not reported
Contact Name:	ROCHELLE DELUXE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

DELUXE TAXI (Continued) **U001736524**

Zip Code:	Not reported
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Emergency Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	JOHN TENORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 632-2108
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47103
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	05/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

I00 - Overfill - None
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron

DELUXE TAXI (Continued) **U001736524**

WESTCHESTER CO. UST:

Id/Status:	3-600004 / Unregulated: <1101 gal. PBS
Operator Name:	Rochell Deluxe Taxi, Inc.
Owner Name:	8 Railroad Place Corporation
Owner Street:	8 Station Plaza South
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	11/03/1993
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

I75 **DEVELOPMENT SITE** **NY LTANKS S107522540**
NE **175 HUGUENOT STREET** **NY Spills N/A**
< 1/8 **NEW ROCHELLE, NY**
0.102 mi.
536 ft. **Site 7 of 7 in cluster I**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	358910
Spill Number/Closed Date:	0512575 / 2006-03-08
Spill Date:	2006-01-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-01-30
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

DEVELOPMENT SITE (Continued) **S107522540**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-30
Spill Record Last Update:	2006-03-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JOHN MANFREDI
Spiller Phone:	(914) 241-3795
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	307023
DEC Memo:	"3/08/06 See JM associates spill closure report for 05-04821. TG"
Remarks:	""

Material:

Site ID:	358910
Operable Unit ID:	1116137
Operable Unit:	01
Material ID:	2106280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0510932
Facility Type:	ER
DER Facility ID:	307023
Site ID:	356986
DEC Region:	3
Spill Date:	2005-12-19
Spill Number/Closed Date:	0510932 / 2005-12-19
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

DEVELOPMENT SITE (Continued) **S107522540**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2006-03-08
Spiller Name:	SEAN MCKAY
Spiller Company:	TRUMP PLAZA
Spiller Address:	175 HUEGOTNOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEAN MCKAY
Contact Phone:	(646) 772-6987
DEC Memo:	"CONFIRMED CLEANUP WITH WCDOH 3/8/06 See spill JM Associates closure report for 05-04821"
Remarks:	"SPILL AROUND GENERATOR AND IN PROCESS OF BEING CLEANED UP;"

Material:

Site ID:	356986
Operable Unit ID:	1114275
Operable Unit:	01
Material ID:	2104355
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0504821
Facility Type:	ER
DER Facility ID:	307023
Site ID:	349739
DEC Region:	3
Spill Date:	2005-07-20
Spill Number/Closed Date:	0504821 / 2006-03-08
Spill Cause:	Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

DEVELOPMENT SITE (Continued) **S107522540**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2006-03-08
Spiller Name:	JOHN MANFREDIE
Spiller Company:	NEW ROCHELLE #1A
Spiller Address:	HUGIGNOT /LAACONTA
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	JOHN MANFREDIE
Contact Phone:	(914) 241-3795
DEC Memo:	"3/02/06 UST removal report submitted by JM Associates including information about two other spill reports listed for the same parcel, 05-10932 and 05-12575. A total of 5 UST's were removed along with 3,351.05 tons of petroleum impacted soil. Based on the information contained in the report, no further action is required. TG"
Remarks:	"DURING EXCAVATION FOUND AN ABANDON TANK: AND FOUND CONTAMINATED SOIL"
	Not reported

Material:

Site ID:	349739
Operable Unit ID:	1107327
Operable Unit:	01
Material ID:	2097217
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

K76 **M.J. HACKER & SONS INC.** **NY UST** **U004176847**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
538 ft. **Site 8 of 20 in cluster K**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-137979 / Unregulated
Operator Name:	Steve Mangels
Owner Name:	Steve Mangels
Owner Street:	64 Centre Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Prior to 04/1991
Capacity:	4000
Product Stored:	7. Gasoline

M.J. HACKER & SONS INC. (Continued) **U004176847**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1973
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	002
Status:	3. Closed - Prior to 04/1991
Capacity:	2000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1980
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	003
Status:	8. Unregistered
Capacity:	500
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported

M.J. HACKER & SONS INC. (Continued) **U004176847**

Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 004
Status: 5. Closed - removed
Capacity: 750
Product Stored: 13. Waste/Used Oil
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: 01/01/1900
Date Perm Closure: 05/12/2014
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: Not reported
Tank External Protection: Not reported
Tank Secondary Containment: Not reported
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: Not reported
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 005
Status: 5. Closed - removed
Capacity: Not reported
Product Stored: 7. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 05/14/2014
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: Not reported

Tank Number: 4
Status: 5. Closed - removed
Capacity: 550
Product Stored: 13. Waste/Used Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 06/01/1979
Date Perm Closure: 03/06/2014

M.J. HACKER & SONS INC. (Continued) **U004176847**

Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

H77 **RPM REALTY INC** **NY AST** **A100412045**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 4 of 5 in cluster H**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. AST:

PBS Number:	3-166189
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536

Tank Number:	2
Status:	1. In-Service
Date Installation:	06/01/1997
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

H78 **RPM REALTY INC** **NY UST** **U004240676**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.103 mi.
543 ft. **Site 5 of 5 in cluster H**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-166189 / Active
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City:	Katonah
Owner State:	NY
Owner Zipcode:	10536
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	Not reported
Date Perm Closure:	06/17/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

K79 **ERIC S TURNER & CO INC.** **RCRA-CESQG** **1007204937**
SSW **33-35 CENTRE AVE** **NJ MANIFEST** **NYD002015402**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.103 mi.
545 ft. **Site 9 of 20 in cluster K**

Relative:
Higher

Actual:
94 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	ERIC S TURNER & CO INC.
Facility address:	33-35 CENTRE AVE NEW ROCHELLE, NY 108010000
EPA ID:	NYD002015402
Mailing address:	PO BOX #816 NEW ROCHELLE, NY 108010000
Contact:	WILLIAM TURNER
Contact address:	PO BOX #816 NEW ROCHELLE, NY 108010000
Contact country:	US
Contact telephone:	(914) 235-7114
Telephone ext.:	9999
Contact email:	Not reported
EPA Region:	02

ERIC S TURNER & CO INC. (Continued) **1007204937**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ERIC S TURNER & CO INC.
Classification: Small Quantity Generator

Date form received by agency: 03/18/2005
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Date form received by agency: 03/21/1994
Site name: ERIC S TURNER & CO INC.
Classification: Large Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYD002015402
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: 9142357114
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5224399
EPA ID:	NYD002015402
Date Shipped:	12/06/2004
TSDF EPA ID:	NJR000022442
Transporter EPA ID:	NJR000023325
Transporter 2 EPA ID:	OHD009865825
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/06/2004
Date Trans2 Transported Waste:	12/07/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01250521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NY MANIFEST:

EPA ID:	NYD002015402
Country:	USA
Location Address 1:	33-35 CENTRE AVE

ERIC S TURNER & CO INC. (Continued) **1007204937**

Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: ERIC S TURNER & CO INC.
Contact: W V TURNER PRESIDENT
Address: P. O. BOX 816
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-235-7114

Manifest:

Document ID: NJA5224399
Manifest Status: Not reported
Trans1 State ID: NJAF906B
Trans2 State ID: 58746
Generator Ship Date: 12/06/2004
Trans1 Recv Date: 12/06/2004
Trans2 Recv Date: 12/07/2004
TSD Site Recv Date: 12/08/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002015402
Trans1 EPA ID: NJR000023325
Trans2 EPA ID: Not reported
TSDF ID: NJR000022
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2004

Document ID: MAQ0630594
Manifest Status: Not reported
Trans1 State ID: NJAF906B
Trans2 State ID: Not reported
Generator Ship Date: 12/06/2004
Trans1 Recv Date: 12/06/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/06/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

Generator EPA ID: NYD002015402
Trans1 EPA ID: NJR000023325
Trans2 EPA ID: Not reported
TSDF ID: MAD047075
Waste Code: D007 - CHROMIUM 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2004

Document ID: NYB7375383
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GE9561
Trans2 State ID: Not reported
Generator Ship Date: 11/13/1995
Trans1 Recv Date: 11/13/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/13/1995
Part A Recv Date: 11/27/1995
Part B Recv Date: 12/11/1995
Generator EPA ID: NYD002015402
Trans1 EPA ID: NYD981182769
Trans2 EPA ID: Not reported
TSDF ID: NYD981182769
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1995

Document ID: PAE1357226
Manifest Status: Completed copy
Trans1 State ID: PAAH0317
Trans2 State ID: Not reported
Generator Ship Date: 12/12/1994
Trans1 Recv Date: 12/12/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 12/14/1994
Part A Recv Date: / /
Part B Recv Date: 01/03/1995
Generator EPA ID: NYD002015402
Trans1 EPA ID: PAD982661381
Trans2 EPA ID: Not reported
TSDF ID: PAD085690592
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)

ERIC S TURNER & CO INC. (Continued) **1007204937**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1994

Document ID:	PAE0182103
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PAAH0317
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/1993
Trans1 Recv Date:	09/02/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/10/1993
Part A Recv Date:	10/15/1993
Part B Recv Date:	10/04/1993
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00225
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00155
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1993

Document ID:	NYA1234098
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS632
Trans2 State ID:	Not reported
Generator Ship Date:	10/11/1984
Trans1 Recv Date:	10/11/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/11/1984
Part A Recv Date:	10/16/1984
Part B Recv Date:	10/19/1984
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279

ERIC S TURNER & CO INC. (Continued) **1007204937**

Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1984

Document ID:	NYB2551311
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GX6293
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/1991
Trans1 Recv Date:	10/10/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/11/1991
Part A Recv Date:	10/18/1991
Part B Recv Date:	11/06/1991
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1991

Document ID:	NYB2109852
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GX6293
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/1990
Trans1 Recv Date:	04/30/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/07/1990
Part A Recv Date:	11/01/1990
Part B Recv Date:	06/22/1990
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	01500

ERIC S TURNER & CO INC. (Continued) **1007204937**

Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1990

Document ID: NYB2111013
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GX6293
Trans2 State ID: Not reported
Generator Ship Date: 04/30/1990
Trans1 Recv Date: 04/30/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 05/07/1990
Part A Recv Date: 11/01/1990
Part B Recv Date: 06/22/1990
Generator EPA ID: NYD002015402
Trans1 EPA ID: NYD000691949
Trans2 EPA ID: Not reported
TSDF ID: NYD000691949
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00600
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1990

Document ID: NYA7204554
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000

ERIC S TURNER & CO INC. (Continued) **1007204937**

Generator Ship Date:	03/29/1989
Trans1 Recv Date:	03/29/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/29/1989
Part A Recv Date:	04/04/1989
Part B Recv Date:	04/12/1989
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000691949
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1989

Document ID:	NJA0009467
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS632
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1985
Trans1 Recv Date:	02/28/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1985
Part A Recv Date:	06/03/1985
Part B Recv Date:	03/07/1985
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1985

Document ID:	NYO1552698
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	08/09/1984
Trans1 Recv Date:	08/09/1984
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/09/1984
Part A Recv Date:	08/30/1984
Part B Recv Date:	09/05/1984
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

TSDF ID:	NJD048810279
Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1984

Document ID:	NJA2870118
Manifest Status:	Not reported
Trans1 State ID:	50163
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/1998
Trans1 Recv Date:	09/16/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJR000023325
Trans2 EPA ID:	Not reported
TSDF ID:	NJR000022442
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5591092
Manifest Status:	Not reported
Trans1 State ID:	ILP39038
Trans2 State ID:	564TUH
Generator Ship Date:	06/16/1999
Trans1 Recv Date:	06/16/1999
Trans2 Recv Date:	06/18/1999
TSD Site Recv Date:	06/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	NYD000708198
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP

ERIC S TURNER & CO INC. (Continued) **1007204937**

Quantity:	00004
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	PAC0336453
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0278
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1992
Trans1 Recv Date:	07/22/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/23/1992
Part A Recv Date:	08/05/1992
Part B Recv Date:	07/30/1992
Generator EPA ID:	NYD002015402
Trans1 EPA ID:	NJD000813477
Trans2 EPA ID:	Not reported
TSDF ID:	PAD087561015
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	02900
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1992

M80 **P&D TRANSPORT - HOT TAR** **NY Spills** **S106126552**
SW **I-95 NB @ MM 5.4** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 1 of 2 in cluster M**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	0308809
Facility Type:	ER
DER Facility ID:	265298
Site ID:	329742
DEC Region:	3
Spill Date:	2003-11-18
Spill Number/Closed Date:	0308809 / 2003-11-26
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
SWIS:	6010
Investigator:	tdghiosa

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

Referred To:	Not reported
Reported to Dept:	2003-11-18
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-18
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	P&D TRANSPORT
Spiller Address:	171 BROWNSTONE AVE
Spiller City,St,Zip:	PORTLAND, CT 06480-
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11-18-03 P&D Transport trailer carrying 5000 gallons of a hot tar product developed several leaks from seams and holes beneath the trailer. The driver, John Culbreath, pulled the vehicle to the shoulder of I-95 NB at mm 5.4 in New Rochelle. The trailer drained hot tar to the road shoulder where it flowed downhill until it cooled and solidified. Approximatley 200 feet of shoulder where affected before the trailer could be offloaded. DEC called out Castlton Environmental contractors when a company Rep stated that he/she would not sent a second truck to offload the damaged trailer. Castlton contacted Mystic Bulk Carriers and requested their assistance. Mystic provided a heated truck, suitable to offload the cargo and return it to Ownes Corning in Kearny where the load was originally picked up. The P&D damaged trailer was towed off the road to a spot near the I-95 toll plaza. Castlton performed the removal of the solidified tar several days later as they were delayed by heavy rain which created hazardous working conditions on busily traveled I-95. As of 11-18-03, Portland Asphalt indicated that they would pay Caslton directly for the cost of the cleanup. "
Remarks:	"material goes into a manhole which leads to a water way. poss hutchinson river. spill not controlled yet. caller req call back from rep"

Material:

Site ID:	329742
Operable Unit ID:	877435
Operable Unit:	01
Material ID:	498725
Material Code:	0018A
Material Name:	tar
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

Tank Test:

M81 **I-95** **NY Spills** **S102152708**
SW **I-95EB MP54** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 2 of 2 in cluster M**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Facility ID:	8700158
Facility Type:	ER
DER Facility ID:	105126
Site ID:	121121
DEC Region:	3
Spill Date:	1987-04-07
Spill Number/Closed Date:	8700158 / 1987-04-07
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	6010
Investigator:	WEED
Referred To:	Not reported
Reported to Dept:	1987-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	1987-04-07
Cleanup Meets Std:	True
Last Inspection:	1987-04-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-04-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	""

Material:

Site ID:	121121
Operable Unit ID:	904779
Operable Unit:	01
Material ID:	473726
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

I-95 (Continued) **S102152708**

Oxygenate: Not reported

Tank Test:

N82 **DEPOT PLACE LLC** **NY UST** **U003994482**
NW **1 DEPOT PLACE** **N/A**
< 1/8 **MAMARONECK (T), NY**
0.106 mi.
560 ft. **Site 1 of 5 in cluster N**

Relative:
Lower

Actual:
72 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801085 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Depot LLC
Owner Street:	1 Depot Place
Owner Address2:	Not reported
Owner City:	Mamaroneck
Owner State:	NY
Owner Zipcode:	Not reported
GDS Number:	Not reported
Tank Number:	001
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/21/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

N83 **STATION CLEANERS** **NY DRYCLEANERS** **S110247994**
NW **1 DEPOT PLAZA #1** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.106 mi.
560 ft. **Site 2 of 5 in cluster N**

Relative:
Lower

Actual:
72 ft.

DRYCLEANERS:

Facility ID:	---
Phone Number:	Not reported
Region:	3
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported

STATION CLEANERS (Continued) **S110247994**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: ???

K84 **GREEN HEAVEN/CENTRE CLEANERS** **NY DRYCLEANERS** **S106437149**
SSW **62 CENTRE AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
574 ft. **Site 10 of 20 in cluster K**

Relative: Higher

Actual: 98 ft.

DRYCLEANERS:
Facility ID: 3-5510-00298
Phone Number: 914-636-5350
Region: Not reported
Registration Effective Date: 9/24/2003 13:22:51:203
Inspection Date: 11SEP8
Install Date: 88/98
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF2000
Current Business: Not reported

K85 **EDR Hist Cleaner** **1015081768**
SSW **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
574 ft. **Site 11 of 20 in cluster K**

Relative: Higher

Actual: 98 ft.

EDR Historical Cleaners:
Name: CENTRE CLEANERS TAILORS INCORPORATED
Year: 2000
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2001
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2002
Address: 62 CENTRE AVE

Name: CTR CLEANERS TAILORS INC
Year: 2003
Address: 62 CENTRE AVE

Name: CENTER CLEANERS
Year: 2007
Address: 62 CENTRE AVE

Name: CENTER CLEANERS
Year: 2008
Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORS INC
Year: 2010

(Continued) **1015081768**

Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORING INC
Year: 2011
Address: 62 CENTRE AVE

Name: CENTRE CLEANERS TAILORS
Year: 2012
Address: 62 CENTRE AVE

K86 **SIMONETTI CLEANERS** **RCRA-CESQG** **1000338662**
SSW **62 CENTRE ST** **US AIRS** **NYD982531634**
< 1/8 **NEW ROCHELLE, NY 10801** **FINDS**
0.109 mi. **NY MANIFEST**
574 ft. **Site 12 of 20 in cluster K** **ECHO**

Relative:
Higher

Actual:
98 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: SIMONETTI CLEANERS
Facility address: 62 CENTRE ST
NEW ROCHELLE, NY 10801
EPA ID: NYD982531634
Mailing address: CENTRE ST
NEW ROCHELLE, NY 10801
Contact: KWANG YUN
Contact address: CENTRE ST
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 636-5350
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: KWANG YUN
Owner/operator address: 24 SUMMIT AVE
MOUNT VERNON, NY 10550
Owner/operator country: US
Owner/operator telephone: (914) 665-0274
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Owner/operator name: KWANG YUN
Owner/operator address: 24 SUMMIT AVE
MOUNT VERNON, NY 10550
Owner/operator country: US
Owner/operator telephone: (914) 665-0274
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SIMONETTI CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/21/1996
Site name: SIMONETTI CLEANERS
Classification: Small Quantity Generator

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

SIMONETTI CLEANERS (Continued) **1000338662**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

US AIRS MINOR:

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR 020000003606156000
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR NY0000NY3551000298
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012174805

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

SIMONETTI CLEANERS (Continued) **1000338662**

AIR MINOR

NY MANIFEST:

EPA ID:	NYD982531634
Country:	USA
Location Address 1:	62 CENTRE AVENUE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SIMONETTI CLEANERS
Contact:	SIMONETTI CLEANERS
Address:	62 CENTRE AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-636-5350

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000664906
Trans2 State ID:	CDX761010010
Generator Ship Date:	01/10/2009
Trans1 Recv Date:	01/10/2009
Trans2 Recv Date:	01/16/2009
TSD Site Recv Date:	01/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX107000000
Waste Code:	Not reported
Quantity:	390.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	004562249JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

SIMONETTI CLEANERS (Continued) **1000338662**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/12/2007
Trans1 Recv Date:	05/12/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000497613SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	NYC7340343
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	T19L8DNJ
Generator Ship Date:	05/03/2004
Trans1 Recv Date:	05/03/2004
Trans2 Recv Date:	05/05/2004
TSD Site Recv Date:	05/06/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

SIMONETTI CLEANERS (Continued) **1000338662**

Year: 2004

Document ID: NYC7459705
Manifest Status: Not reported
Trans1 State ID: NY49455JF
Trans2 State ID: T470GL
Generator Ship Date: 11/29/2004
Trans1 Recv Date: 11/29/2004
Trans2 Recv Date: 12/01/2004
TSD Site Recv Date: 12/03/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID: OHD980587
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYC7252356
Manifest Status: Not reported
Trans1 State ID: NYCF7875
Trans2 State ID: NJ044
Generator Ship Date: 12/29/2003
Trans1 Recv Date: 12/29/2003
Trans2 Recv Date: 12/30/2003
TSD Site Recv Date: 01/05/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00300
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7086767
Manifest Status: Not reported
Trans1 State ID: NYCR3164
Trans2 State ID: AH0697
Generator Ship Date: 05/16/2003
Trans1 Recv Date: 05/16/2003

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 Recv Date:	05/21/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7019346
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	T25L8DNJ
Generator Ship Date:	01/24/2003
Trans1 Recv Date:	01/24/2003
Trans2 Recv Date:	01/29/2003
TSD Site Recv Date:	01/30/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC6663240
Manifest Status:	Not reported
Trans1 State ID:	DW9495
Trans2 State ID:	NJT51G9T
Generator Ship Date:	02/26/2002
Trans1 Recv Date:	02/26/2002
Trans2 Recv Date:	03/04/2002
TSD Site Recv Date:	03/05/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

SIMONETTI CLEANERS (Continued) **1000338662**

Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6873568
Manifest Status: Not reported
Trans1 State ID: NY49455JF
Trans2 State ID: T53G9TNJ
Generator Ship Date: 09/30/2002
Trans1 Recv Date: 09/30/2002
Trans2 Recv Date: 10/02/2002
TSD Site Recv Date: 10/03/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6494207
Manifest Status: Not reported
Trans1 State ID: 19952JF
Trans2 State ID: NJ044
Generator Ship Date: 11/06/2001
Trans1 Recv Date: 11/06/2001
Trans2 Recv Date: 11/12/2001
TSD Site Recv Date: 11/13/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

SIMONETTI CLEANERS (Continued) **1000338662**

Document ID:	NYC5750392
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2001
Trans1 Recv Date:	04/24/2001
Trans2 Recv Date:	04/27/2001
TSD Site Recv Date:	04/28/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	MOD095038998
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NYC6083190
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	03/08/2000
Trans1 Recv Date:	03/08/2000
Trans2 Recv Date:	03/09/2000
TSD Site Recv Date:	03/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6190817
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/28/2000
Trans1 Recv Date:	06/28/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC6304983
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: TNT218034
Generator Ship Date: 12/06/2000
Trans1 Recv Date: 12/06/2000
Trans2 Recv Date: 12/06/2000
TSD Site Recv Date: 12/11/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC5974018
Manifest Status: Not reported
Trans1 State ID: NYR2436
Trans2 State ID: T422NXNJ
Generator Ship Date: 11/10/1999
Trans1 Recv Date: 11/10/1999
Trans2 Recv Date: 11/15/1999
TSD Site Recv Date: 11/19/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001

SIMONETTI CLEANERS (Continued) **1000338662**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5644552
Manifest Status: Not reported
Trans1 State ID: NYCR243
Trans2 State ID: T422NXNY
Generator Ship Date: 05/28/1999
Trans1 Recv Date: 05/28/1999
Trans2 Recv Date: 06/01/1999
TSD Site Recv Date: 06/03/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5849605
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: T104414IL
Generator Ship Date: 07/20/1999
Trans1 Recv Date: 07/20/1999
Trans2 Recv Date: 07/22/1999
TSD Site Recv Date: 07/26/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982531634
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: NYC5520666
Manifest Status: Not reported
Trans1 State ID: NYCR2436

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	CTF0671288
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1998
Trans1 Recv Date:	01/08/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0688517
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/1998
Trans1 Recv Date:	03/06/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	ILD984908202

SIMONETTI CLEANERS (Continued) **1000338662**

Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00140
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

ECHO:

Envid:	1000338662
Registry ID:	110012174805
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110012174805

K87 **COMMERCIAL PROPERTY** **NY LTANKS** **S116156733**
SSW **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.111 mi.
585 ft. **Site 13 of 20 in cluster K**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	489220
Spill Number/Closed Date:	1308480 / 2015-04-28
Spill Date:	2013-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-20
Spill Record Last Update:	2015-05-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	64 CENTRE AVE
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	STEVE MANGELS
Spiller Phone:	(914) 632-2610
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444316
DEC Memo:	"11-20-13: Chris/WCHD call to V.Mc./Dispt.: Closed Unreg. PBS faciliy. Wayne/WCHD to handle. 11/20/2013 1:48:33 PM:: From Chris

COMMERCIAL PROPERTY (Continued) **S116156733**

Lalak to Wayne Schneider via email:: Wayne, Former PBS site 3-137979 Expired in 1992 (removed gasoline tanks) TTF for Underground waste oil tank estimated as a 550 (Ullage leak and they plan to remove the tank.) The Facility is: M. Hacker and Sons. Please get them to register and deal with the TTF jod 04/23/15 HydroEnvironmental Solutions submitted a report documenting the installation of a temporary monitoring well in the location were the LUST was removed. (See report in DecDocs) Trace levels of VOCs & SVOCs in the sample. TG 4-28-15 closed NFA -RDB"

Remarks: ""

Material:

Site ID:	489220
Operable Unit ID:	1238809
Operable Unit:	01
Material ID:	2238759
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

O88 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016965006**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004379020**
< 1/8 **NEW ROCHELLE, NY 10802**
0.112 mi.
594 ft. **Site 1 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10802
EPA ID:	NYP004379020
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/23/2013
Site name:	CON EDISON TRANSFORMER MANHOLE: 4319
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004379020
Country:	USA
Location Address 1:	CENTRE AVE & RELYEA PL
Location Address 2:	SB4314
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	011693664JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

O89 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016963532**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004365318**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
594 ft. **Site 2 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/24/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004365318
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/24/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 4319
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004365318
Country: USA
Location Address 1: CENTRE AVE & RELYEA PL
Location Address 2: TM 4319
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/24/2013
Trans1 Recv Date: 09/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004365318
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694707JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

P90 **CON EDISON MANHOLE 1181** **RCRA NonGen / NLR** **1014918324**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219380**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
594 ft. **Site 1 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/02/2010
Facility name:	CON EDISON MANHOLE 1181
Facility address:	HUGUENOT ST & LECOUNT PL MH 1181 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219380
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/02/2010
Site name:	CON EDISON MANHOLE 1181
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON MANHOLE 1181 (Continued) **1014918324**

NJ MANIFEST:

EPA Id:	NYP004219380
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874911JJK
EPA ID:	NYP004219380
Date Shipped:	11/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

NY MANIFEST:
EPA ID: NYP004219380
Country: USA
Location Address 1: HUGENOT ST & LE COURT
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON - MH 1181
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/02/2010
Trans1 Recv Date: 11/02/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004219380
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874911JJK
Import Ind: N
Export Ind: N

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

P91 **CON EDISON MANHOLE 1178** **RCRA NonGen / NLR** **1014918331**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219455**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
594 ft. **Site 2 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/03/2010
Facility name:	CON EDISON MANHOLE 1178
Facility address:	HUGUENOT ST & LECOUNT PL MH 1178 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219455
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/03/2010
Site name:	CON EDISON MANHOLE 1178
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004219455
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874912JJK
EPA ID:	NYP004219455
Date Shipped:	11/03/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

NY MANIFEST:
EPA ID: NYP004219455
Country: USA
Location Address 1: HUGUENOT ST & LE COURT
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON - MH 1178
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/03/2010
Trans1 Recv Date: 11/03/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004219455
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874912JJK
Import Ind: N

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

P92 **CON EDISON** **NY MANIFEST** **S118259788**
NE **HUGENOT ST & LECOUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.112 mi.
594 ft. **Site 3 of 3 in cluster P**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:

EPA ID:	NYP004837407
Country:	USA
Location Address 1:	HUGENOT ST & LECOUNT PL
Location Address 2:	V 7723
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/2015
Trans1 Recv Date:	09/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837407
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S118259788**

Year:	2015
Manifest Tracking Num:	014472144JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K93 **NYNEX LOCATION** **NY LTANKS** **S102660218**
SSW **342 HUEGNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.113 mi.
598 ft. **Site 14 of 20 in cluster K**

Relative:
Higher

Actual:
99 ft.

LTANKS:

Site ID:	270876
Spill Number/Closed Date:	9708146 / 1997-10-10
Spill Date:	1997-10-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1997-11-12
Spiller Name:	RICH KALISTA
Spiller Company:	BELL ATLANTIC
Spiller Address:	2203 MCCONNELL ST
Spiller City,St,Zip:	BELLMORE, NY
Spiller County:	001
Spiller Contact:	TOM MUFF
Spiller Phone:	(914) 449-5321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220510
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DOING AN UPGRADE FOR A NYNEX LOCATION AND REMOVING 2 UNDERGROUND TANKS FROM A BASEMENT - TANKS WERE ENCASED BY SAND & WHEN REMOVED THE SAND WAS CONTAMINATED - THEY HAVE REMOVED SAND."

NYNEX LOCATION (Continued) **S102660218**

Material:

Site ID:	270876
Operable Unit ID:	1051372
Operable Unit:	01
Material ID:	330133
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

J94 **SPEEDY CLEANERS** **US AIRS** **1006295756**
ESE **217 NORTH AVENUE** **FINDS** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801** **NY DRYCLEANERS**
0.113 mi. **ECHO**
598 ft. **Site 5 of 7 in cluster J**

Relative:
Higher

Actual:
91 ft.

US AIRS MINOR:

Envid:	1006295756
Region Code:	02
Programmatic ID:	AIR NY0000NY3551000344
Facility Registry ID:	110012166921
D and B Number:	Not reported
Primary SIC Code:	7212
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012166921

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking

SPEEDY CLEANERS (Continued) **1006295756**

environmental facility information found across the State.

AIR MINOR

DRYCLEANERS:

Facility ID:	3-5510-00344
Phone Number:	914-654-9082
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	03DEC31
Install Date:	00/03
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

ECHO:

Envid:	1006295756
Registry ID:	110012166921
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110012166921

L95 **SPOKEN ARTS BUILDING (FORMER)** **NY UST** **U003885171**
North **310 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.114 mi.
603 ft. **Site 2 of 11 in cluster L**

Relative:
Lower

Actual:
75 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600705 / Unregulated: <1101 gal. PBS
Operator Name:	Mr. Anthony Blaise
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1994
Date Perm Closure:	09/01/1994
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported

SPOKEN ARTS BUILDING (FORMER) (Continued) **U003885171**

Spill Prevention: 0. None
Dispenser: 0. None

J96 **MACYS NEW ROCHELLE** **NY UST** **U003856957**
East **THE MALL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.117 mi.
616 ft. **Site 6 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. UST:
Id/Status: 3-167037 / Unregulated: <1101 gal. PBS
Operator Name: Macys New York
Owner Name: Macys New York
Owner Street: The Mall
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 4. Closed - in place
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1967
Date Perm Closure: 09/26/1997
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 2
Status: 4. Closed - in place
Capacity: 10000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 12/01/1967
Date Perm Closure: 09/26/1997
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None

MACYS NEW ROCHELLE (Continued) **U003856957**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

L97 **NORTH GARDEN ASSOCIATES LLC** **NY UST** **U004177039**
North **309-311 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.117 mi.
618 ft. **Site 3 of 11 in cluster L**

Relative:
Lower

Actual:
74 ft.

WESTCHESTER CO. UST:

Id/Status:	3-496928 / Active
Operator Name:	Harrin Platzner
Owner Name:	North Garden Associates LLC
Owner Street:	P.O Box 111
Owner Address2:	309-311 North Avenue
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/15/1947
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	9. Copper
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	2. Suction

O98 **APPAREL PLUS** **NY Spills** **S116156116**
SW **27 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.118 mi.
624 ft. **Site 3 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

SPILLS:

Facility ID:	1309988
Facility Type:	ER
DER Facility ID:	445839
Site ID:	490810
DEC Region:	3
Spill Date:	2014-01-14

APPAREL PLUS (Continued) **S116156116**

Spill Number/Closed Date:	1309988 / 2014-01-14
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	DXWEITZ
Referred To:	Not reported
Reported to Dept:	2014-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-14
Spill Record Last Update:	2014-01-14
Spiller Name:	CHRIS LALAK
Spiller Company:	APPAREL PLUS LAUNDRY
Spiller Address:	27 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CHRIS LALAK
Contact Phone:	(914) 224-7649
DEC Memo:	"1/14/14 Chris Lalak from WCHD called and said that this was motor oil from a truck in the parking lot. People at the laundry did the cleanup. According to Chris Lalak, the spill can be closed. They were there for other reasons. NFA dw"
Remarks:	"loss to sewer. c/u in progress"

Material:

Site ID:	490810
Operable Unit ID:	1240364
Operable Unit:	01
Material ID:	2240510
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q99 **SIDNEY FURNITURE** **NY Spills** **S118460140**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 1 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	1509029
Facility Type:	ER
DER Facility ID:	75076
Site ID:	517634
DEC Region:	3
Spill Date:	2015-12-03
Spill Number/Closed Date:	1509029 / 2015-12-04
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-04
Spill Record Last Update:	2015-12-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MICHELLE GUERRERO
Contact Phone:	(347) 982-5522
DEC Memo:	"12/04/15: Caller states she is at work, states she is pregnant, and states that they were working on the furnace and there was a small oil spill. She wanted to know if oil spills are hazardous. I was in the process of answering her questions and she hung up. Westchester County Dept of Health notified. No further DEC action. jod"
Remarks:	"Caller advised aprx 1/2 gal of oil spilled onto carpet. Clean up is pending. Caller is requesting a call back"

Material:

Site ID:	517634
Operable Unit ID:	1266703
Operable Unit:	01
Material ID:	2270652
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons

SIDNEY FURNITURE (Continued) **S118460140**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Q100 **SPILL NUMBER 9900400** **NY Spills** **S104648843**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
632 ft. **Site 2 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Facility ID:	9900400
Facility Type:	ER
DER Facility ID:	75076
Site ID:	81102
DEC Region:	3
Spill Date:	1999-04-08
Spill Number/Closed Date:	9900400 / 1999-07-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-04-12
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-12
Spill Record Last Update:	2004-02-24
Spiller Name:	MR GOLDBERG
Spiller Company:	MR GOLDBERG
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	001
Contact Name:	MR GOLDBERG
Contact Phone:	(212) 370-1333
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/9/99 SPILL CLEANED BY TOWN & COUNTRYF OIL. NFA"
Remarks:	"FAULTY VENT ALARM - SPILLED LESS THAN 1 GAL - CLEANED UP - TENANTS STILL COMPLAINING OF ODORS"

Material:

Site ID:	81102
Operable Unit ID:	1075164
Operable Unit:	01
Material ID:	307538
Material Code:	0001A

SPILL NUMBER 9900400 (Continued) **S104648843**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9415294
Facility Type:	ER
DER Facility ID:	205781
Site ID:	251083
DEC Region:	3
Spill Date:	1995-02-17
Spill Number/Closed Date:	9415294 / 1995-03-03
Spill Cause:	Human Error
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER DID NOT HEAR VENT ALARM AND OVERFILLED TANK REGENT OIL CLEANED UP"

Material:

Site ID:	251083
Operable Unit ID:	1012611
Operable Unit:	01
Material ID:	370473
Material Code:	0001A

SPILL NUMBER 9900400 (Continued) **S104648843**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

N101 **EDR Hist Auto** **1015441746**
NW **35 GRAND ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.121 mi.
639 ft. **Site 3 of 5 in cluster N**

Relative:
Lower

Actual:
76 ft.

EDR Historical Auto Stations:

Name:	EAST COAST AUTO TRIM
Year:	1999
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2000
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2001
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2002
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2003
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2004
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM
Year:	2005
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2006
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2007
Address:	35 GRAND ST
Name:	EAST COAST AUTO TRIM INC
Year:	2009

(Continued) **1015441746**

Address: 35 GRAND ST

Q102 **LILLIAN VERNON CORP.** **NY LTANKS** **S102152290**
South **543 MAIN STREET** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
649 ft. **Site 3 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	94435
Spill Number/Closed Date:	0308082 / 2004-05-12
Spill Date:	2003-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-10-30
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-05-19
Spiller Name:	JEFF WEIR
Spiller Company:	BLUE GILL REALTY
Spiller Address:	543 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	JEFF WEIR
Spiller Phone:	(646) 435-8110
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	84546
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MAGNUSON 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #9212475. Letter has PBS #3-801106."
Remarks:	"TANK HAS BEEN REMOVED."

Material:

Site ID:	94435
Operable Unit ID:	876585
Operable Unit:	01
Material ID:	501599
Material Code:	0001A
Material Name:	#2 fuel oil

LILLIAN VERNON CORP. (Continued) **S102152290**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	94435
Spill Tank Test:	1528780
Tank Number:	1
Tank Size:	2500
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	9212475
Facility Type:	ER
DER Facility ID:	108333
Site ID:	125220
DEC Region:	3
Spill Date:	1993-02-03
Spill Number/Closed Date:	9212475 / 2004-05-12
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2004-05-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

LILLIAN VERNON CORP. (Continued) **S102152290**

GHIOSAY 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #0308082."

Remarks: "FUEL OIL LINE HAS PIN HOLE LEAK DISCOVERED IN EXCAVATION BY EMER.ENVIRO. SERVICE TODAY REMOTE FILL LINE 2 VERY BADLY PITTED AND CORRODED WILL DRILL WELL 2/4/93"

Material:

Site ID:	125220
Operable Unit ID:	976940
Operable Unit:	01
Material ID:	402326
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q103 **LILLIAN VERNON CORPORATION** **NY UST** **U003994695**
South **543-549 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 4 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600279 / Unregulated: <1101 gal. PBS
Operator Name:	Joseph F. Dimicco
Owner Name:	Lillian Vernon Corp.
Owner Street:	510 South Fulton Ave
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10550
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground

LILLIAN VERNON CORPORATION (Continued) **U003994695**

Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Q104 **543 MAIN STREET** **NY UST** **U003994286**
South **543 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
649 ft. **Site 5 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801106 / Unregulated: <1101 gal. PBS
Operator Name:	Paul Risse
Owner Name:	Bluegill Realty, LLC
Owner Street:	250 West 30th Street
Owner Address2:	Not reported
Owner City:	NY
Owner State:	NY
Owner Zipcode:	10001
GDS Number:	Not reported
Tank Number:	001
Status:	5. Closed - removed
Capacity:	2500
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/07/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

K105 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000553730**
SSW **342 HUGUENOT ST** **NY MANIFEST** **NYD986961605**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
650 ft. **Site 15 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NEW YORK TELEPHONE CO
Facility address:	342 HUGUENOT ST
	NEW ROCHELLE, NY 10801

NEW YORK TELEPHONE CO (Continued) **1000553730**

EPA ID: NYD986961605
Mailing address: NINTH AVE
NEW YORK, NY 10001
Contact: CATHERINE ROM
Contact address: NINTH AVE
NEW YORK, NY 10001
Contact country: US
Contact telephone: (212) 502-7694
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-9964
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: 342 HUGUENOT ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-9964
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

NEW YORK TELEPHONE CO (Continued) **1000553730**

Date form received by agency: 07/02/1991
Site name: NEW YORK TELEPHONE CO
Classification: Small Quantity Generator

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986961605
Country: USA
Location Address 1: 342 HUGANAUGHT STREET
Location Address 2: Not reported
Location City: WESTCHESTER
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: TELESECTOR RESOURCES GROUP
Contact: WAYNE SEBRO
Address: 441 9TH AVENUE 5TH FLOOR
City/State/Zip: NEW YORK, NY 10001
Country: USA
Phone: 212-502-7694

Manifest:

Document ID: ILA7651009
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 1478
Trans2 State ID: 2075
Generator Ship Date: 10/23/1997
Trans1 Recv Date: 10/23/1997
Trans2 Recv Date: 10/23/1997
TSD Site Recv Date: 10/29/1997
Part A Recv Date: 11/26/1997
Part B Recv Date: 11/20/1997
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: NJD000813477
TSDF ID: ILD000608471
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

NEW YORK TELEPHONE CO (Continued) **1000553730**

Year: 1997

Document ID: MAF3478760
Manifest Status: Completed copy
Trans1 State ID: 50C143OH
Trans2 State ID: 50C143OH
Generator Ship Date: 07/11/1991
Trans1 Recv Date: 07/11/1991
Trans2 Recv Date: 07/12/1991
TSD Site Recv Date: 07/15/1991
Part A Recv Date: 07/26/1991
Part B Recv Date: 07/26/1991
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: MAD039322250
TSDF ID: MAD053452637
Waste Code: B005 - PCB ARTICLES WITH 500 PPM OR > PCB
Quantity: 00364
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1991

Document ID: MAH2671330
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: MA970642
Trans2 State ID: Not reported
Generator Ship Date: 11/23/1993
Trans1 Recv Date: 11/23/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 11/24/1993
Part A Recv Date: / /
Part B Recv Date: 12/20/1993
Generator EPA ID: NYD986961605
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID: MAD980523203
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00004
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

K106 **VERIZON** **NY Spills** **S106867403**
SSW **342 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
650 ft. **Site 16 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

SPILLS:

Facility ID:	0413326
Facility Type:	ER
DER Facility ID:	288752
Site ID:	342403
DEC Region:	3
Spill Date:	2005-03-22
Spill Number/Closed Date:	0413326 / 2005-09-11
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-22
Spill Record Last Update:	2005-09-11
Spiller Name:	CLAUDIA
Spiller Company:	VERIZON
Spiller Address:	342 HUGUENOT ST.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CLAUDIA
Contact Phone:	Not reported
DEC Memo:	"September 11, 2005: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank is tight has a bad vent line. Will be replacing the vent line."

Material:

Site ID:	342403
Operable Unit ID:	1101130
Operable Unit:	01
Material ID:	581261
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

VERIZON (Continued) **S106867403**

Tank Test:

Site ID:	342403
Spill Tank Test:	1548716
Tank Number:	6
Tank Size:	6000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

K107 **VERIZON NEW YORK INC. (NY96332)** **NY UST U003949914**
SSW **342 HUGUENOT STREET** **NY AST N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
650 ft. **Site 17 of 20 in cluster K**

Relative:
Higher

Actual:
95 ft.

WESTCHESTER CO. UST:

Id/Status:	3-184586 / Active
Operator Name:	Verizon New York Inc.
Owner Name:	Verizon New York Inc.
Owner Street:	140 West Street
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10007
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	01/01/1990
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported

VERIZON NEW YORK INC. (NY96332) (Continued) **U003949914**

Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	11/01/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	11/01/1997
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	4
Status:	5. Closed - removed
Capacity:	550
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	09/01/1997
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported

VERIZON NEW YORK INC. (NY96332) (Continued) **U003949914**

Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	6
Status:	1. In-Service
Capacity:	6000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	11/01/1997
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	6. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	99. Other
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-184586
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Verizon New York Inc.
Owner Name:	Verizon New York Inc.
Owner Street:	140 West Street
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10007

Tank Number:	5
Status:	1. In-Service
Date Installation:	09/01/1997
Capacity:	300
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	0. None
Dispenser:	2. Suction

Q108 **CON EDISON** **NY MANIFEST** **S118464238**
SSE **S DIVSION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
653 ft. **Site 6 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

EPA ID:	NYP004872319
Country:	USA
Location Address 1:	S DIVSION ST & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/23/2015
Trans1 Recv Date:	11/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004872319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	9020
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	013245368JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118464238**

Mgmt Method Type Code: H110

Q109 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243060**
SSE **DIVISION & MAIN** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.124 mi.
653 ft. **Site 7 of 15 in cluster Q**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

EPA ID:	NYP004123873
Country:	USA
Location Address 1:	DIVISION & MAIN
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON
Contact:	FRANKLIN MURRAY
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-2808

Manifest:

Document ID:	NYE1274139
Manifest Status:	Not reported
Trans1 State ID:	46207JMNY
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2004
Trans1 Recv Date:	08/22/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/23/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	01400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2004

CONSOLIDATED EDISON (Continued) **1009243060**

Document ID:	NYE1309977
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2004
Trans1 Recv Date:	08/28/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00001
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYE1308411
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/23/2004
Trans1 Recv Date:	08/23/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYE1308357
Manifest Status:	Not reported
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/25/2004
Trans1 Recv Date:	08/25/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/25/2004
Part A Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **1009243060**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00008
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

L110 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016963395**
North **313 NORTH AVE FRONT OF** **NYP004364030**
< 1/8 **NEW ROCHELLE, NY 10801**
0.125 mi.
658 ft. **Site 4 of 11 in cluster L**

Relative:
Lower

Actual:
74 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/20/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	313 NORTH AVE FRONT OF NEW ROCHELLE, NY 10801
EPA ID:	NYP004364030
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/20/2013

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

Site name: CON EDISON MANHOLE: 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

R111 **CON EDISON** **NY MANIFEST** **S118089619**
ESE **208 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.125 mi.
659 ft. **Site 1 of 4 in cluster R**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:
EPA ID: NYP004772265
Country: USA
Location Address 1: 208 NORTH AVE
Location Address 2: SB 2029
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/22/2015
Trans1 Recv Date: 04/22/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004772265
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014454078JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N

CON EDISON (Continued) **S118089619**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014454078JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

K112 **75 CENTRE AVENUE LLC** **NY UST U004175967**
SSW **75 CENTRE AVENUE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.125 mi.
662 ft. **Site 18 of 20 in cluster K**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800240 / Active
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	52 North Central Ave.
Owner Address2:	Not reported
Owner City:	Elmsford
Owner State:	NY
Owner Zipcode:	10523

75 CENTRE AVENUE LLC (Continued) **U004175967**

GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

WESTCHESTER CO. AST:
PBS Number: 3-800240
Site Status: Active
GDS Number: Not reported
Operator Name: Dino Rentoulis
Owner Name: John & Dino Rentoulis
Owner Street: 52 North Central Ave.
Owner Address2: Not reported
Owner City/State/Zip: Elmsford, NY 10523

Tank Number: 002
Status: 1. In-Service
Date Installation: 09/01/2004
Capacity: 1500
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 1. Aboveground (contact w/ soil)
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 1. Diking (aboveground only)
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

J113 **MACYS** **NY MANIFEST** **1009232715**
East **33 LE COUNT PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.127 mi.
672 ft. **Site 7 of 7 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP000890137
Country:	USA
Location Address 1:	33 LE COUNT PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	MACYS
Contact:	MACYS
Address:	33 LE COUNT PLACE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-633-7700

Manifest:

Document ID:	NYA7026894
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	06/22/1989
Trans1 Recv Date:	06/22/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/22/1989
Part A Recv Date:	08/03/1989
Part B Recv Date:	06/29/1989
Generator EPA ID:	NYP000890137
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1989

L114 **4 STORY APARTMENT BUILDING** **NY UST** **U003883840**
North **320 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.128 mi.
674 ft. **Site 5 of 11 in cluster L**

Relative:
Lower

Actual:
72 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600732 / Unregulated: <1101 gal. PBS
Operator Name:	City Of New Rochelle
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue

4 STORY APARTMENT BUILDING (Continued) **U003883840**

Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1961
Date Perm Closure:	02/28/1995
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	12. Cut-off Walls
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	2
Status:	5. Closed - removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1949
Date Perm Closure:	02/28/1995
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Q115
SSE
1/8-1/4
0.129 mi.
681 ft.

COMMERCIAL PROPERTY
522 MAIN STREET
NEW ROCHELLE, NY

Site 8 of 15 in cluster Q

NY LTANKS **S111012266**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	448142
Spill Number/Closed Date:	1100723 / 2011-06-06
Spill Date:	2011-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-20
Spill Record Last Update:	2011-06-06
Spiller Name:	PETER OH
Spiller Company:	ADELPHI
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JEFF
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402739
DEC Memo:	"Spoke to Georgia at Advanced. Soil boring had field evidence of petroleum impact. DT 4/20/11 6/6/11: Report from Preferred Environmental entered into eDocs. NFA jod"
Remarks:	"1721 THE CALLER ADVISED DISPATCH THEY ARE AWAITING TANK TEST RESULTS."

Material:

Site ID:	448142
Operable Unit ID:	1198388
Operable Unit:	01
Material ID:	2194662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported

COMMERCIAL PROPERTY (Continued) **S111012266**

Oxygenate: Not reported

Tank Test:

K116 **COCO RESIDENCE** **NY LTANKS** **S106123934**
South **81 CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
684 ft. **Site 19 of 20 in cluster K**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	313391
Spill Number/Closed Date:	0311339 / 2005-01-10
Spill Date:	2004-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-07
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-07
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	ED COCO
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 01/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson dated 9Feb2004(?). WCDOH requires NFA at this time."
Remarks:	"Failed test. Unknown if the tank is leaking"

Material:

Site ID:	313391
Operable Unit ID:	878986
Operable Unit:	01
Material ID:	500153
Material Code:	0001A
Material Name:	#2 fuel oil

COCO RESIDENCE (Continued) **S106123934**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	313391
Spill Tank Test:	1528899
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

S117 **COMMERCIAL BUILDING** **NY LTANKS** **S100177795**
SSE **507 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.131 mi.
690 ft. **Site 1 of 6 in cluster S**

Relative:
Higher

Actual:
96 ft.

LTANKS:

Site ID:	286303
Spill Number/Closed Date:	9110835 / 1992-03-10
Spill Date:	1992-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-02-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	1992-02-06
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-23
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	EPHRAIM ASSOC.
Spiller Address:	300 EAST 74TH STREET
Spiller City,St,Zip:	NEW YORK, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

COMMERCIAL BUILDING (Continued) **S100177795**

DEC Region: 3
DER Facility ID: 232045
DEC Memo: ""
Remarks: "BANK AGREEMENT ASSESMENT REVEALED 1K #2 FUEL TANK 12 IN CONCRETE REMAINDER A/G IN BRICK VAULT TANK PULLED TODAY WITH ONE HOLE IN BOTTOM CONCRETE SLAB NOT CRACKED WILL PULL AND INSPECT ON MONDAY"

Material:
Site ID: 286303
Operable Unit ID: 960971
Operable Unit: 01
Material ID: 415913
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Q118 **CON EDISON TRANSFORMER MANHOLE: 3586** **RCRA NonGen / NLR** **1016974043**
SSE **CHURCH ST & MAIN ST** **NY MANIFEST** **NYP004478517**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.131 mi.
691 ft. **Site 9 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/25/2014
Facility name: CON EDISON TRANSFORMER MANHOLE: 3586
Facility address: CHURCH ST & MAIN ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004478517
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/25/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 3586
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004478517
Country: USA
Location Address 1: CHURCH MAIN ST
Location Address 2: SB3586
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/25/2014
Trans1 Recv Date: 03/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004478517
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012770521JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Q119 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963458**
SSE **MAIN ST & CHRUCH ST** **NY MANIFEST** **NYP004364576**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
691 ft. **Site 10 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5042
Facility address:	MAIN ST & CHRUCH ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004364576
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Historical Generators:
Date form received by agency: 09/23/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004364576
Country: USA
Location Address 1: MAINS T & CHURCH ST
Location Address 2: TM 5042
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/23/2013
Trans1 Recv Date: 09/23/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004364576
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 120
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011694706JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Q120 **CON EDISON MANHOLE: 12758** **RCRA NonGen / NLR** **1016974052**
SSE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004478624**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.131 mi.
691 ft. **Site 11 of 15 in cluster Q**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/25/2014
Facility name: CON EDISON MANHOLE: 12758
Facility address: MAIN ST & CHURCH ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004478624
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/25/2014
Site name: CON EDISON MANHOLE: 12758
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004478624
Country: USA
Location Address 1: MAIN & CHURCH ST

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Location Address 2: SB12758
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/25/2014
Trans1 Recv Date: 03/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004478624
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012770524JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Q121
SSE
1/8-1/4
0.131 mi.
691 ft.

CON EDISON
MAIN ST & CHURCH ST
OSSINING, NY 10801

Site 12 of 15 in cluster Q

NY MANIFEST **S117535683**
N/A

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP004680070
Country:	USA
Location Address 1:	MAIN ST & CHURCH ST
Location Address 2:	MH2419
Location City:	OSSINING
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2014
Trans1 Recv Date:	10/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680070
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774891JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117535683**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

K122 **HUGUENOT HOLDINGS, LLC** **NY AST** **A100359858**
SSW **347 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.133 mi.
702 ft. **Site 20 of 20 in cluster K**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. AST:

PBS Number:	3-502626
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Owen Henry (Super)
Owner Name:	Huguenot Holdings, LLC
Owner Street:	1333 A North Avenue
Owner Address2:	#419
Owner City/State/Zip:	New Rochelle, NY 10583
Tank Number:	1
Status:	1. In-Service
Date Installation:	06/01/1995
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

R123 **CATHOLIC NEWS PUBLISHING** **NY LTANKS** **S106972587**
ESE **210 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.137 mi.
723 ft. **Site 2 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	347516
Spill Number/Closed Date:	0503023 / 2005-08-28
Spill Date:	2005-06-13
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported

CATHOLIC NEWS PUBLISHING (Continued) **S106972587**

Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-13
CID:	44
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-13
Spill Record Last Update:	2005-08-28
Spiller Name:	MYLES RIDDER
Spiller Company:	CATHOLIC NEWS PUBLISHING
Spiller Address:	210 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MYLES RIDDER
Spiller Phone:	(914) 632-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293840
DEC Memo:	"August 28, 2005: NORTHEAT DISPOSED OF LUST AND 48.90 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK AND HOLES IN TANK"

Material:

Site ID:	347516
Operable Unit ID:	1105241
Operable Unit:	01
Material ID:	1502620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Q124 **OFFICE BLDG** **NY LTANKS** **S107489194**
South **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.138 mi.
728 ft. **Site 13 of 15 in cluster Q**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Site ID:	355877
Spill Number/Closed Date:	0509995 / 2006-03-22
Spill Date:	2005-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2005-11-21
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-03-22
Spiller Name:	UNKNOWN
Spiller Company:	OFFICE BLDG
Spiller Address:	542 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305921
DEC Memo:	"March 22, 2006 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	""

Material:

Site ID:	355877
Operable Unit ID:	1113209
Operable Unit:	01
Material ID:	2103275
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

OFFICE BLDG (Continued) **S107489194**

Tank Test:

Site ID:	355877
Spill Tank Test:	1549528
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Q125 **542 MAIN STREET LLC** **NY UST** **U003917838**
South **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
728 ft. **Site 14 of 15 in cluster Q**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800617 / Active
Operator Name:	Cornell Pace Inc.
Owner Name:	542 Main Street LLC
Owner Street:	542 Main Street, 2nd Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1904
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	2. Rubber liner
Tank External Protection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

S126 **NEW ROCHELLE PUBLIC LIBRARY** **NY UST** **U004177022**
SE **ONE LIBRARY PLAZA** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
730 ft. **Site 2 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-601216 / Active
Operator Name:	Thomas Geoffino
Owner Name:	New Rochelle Public Library
Owner Street:	One Library Plaza
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	LIB 1
Status:	1. In-Service
Capacity:	10000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

L127 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016677331**
North **NORTH ST & GARDEN ST** **NY MANIFEST** **NYP004309076**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
732 ft. **Site 6 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/08/2013
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	NORTH ST & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004309076
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/08/2013
Site name:	CON EDISON MANHOLE: 4175
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004309076
Country:	USA
Location Address 1:	NORTH AVE & GARDEN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2013
Trans1 Recv Date:	05/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004309076

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007655511JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

L128 **CON EDISON MANHOLE 4175** **RCRA NonGen / NLR** **1014918789**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004224085**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
732 ft. **Site 7 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/14/2011
Facility name:	CON EDISON MANHOLE 4175
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004224085
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2011
Site name:	CON EDISON MANHOLE 4175
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004224085
Country:	USA
Location Address 1:	NORTH AV & GARDEN ST
Location Address 2:	MH 4175
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-2757

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/15/2011
Trans1 Recv Date:	01/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224085
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2011

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Manifest Tracking Num:	007655781JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

L129 **CON EDISON MANHOLE: 4177** **RCRA NonGen / NLR** **1016451046**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004300836**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
732 ft. **Site 8 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/11/2013
Facility name:	CON EDISON MANHOLE: 4177
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004300836
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/11/2013
Site name:	CON EDISON MANHOLE: 4177
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004300836
Country: USA
Location Address 1: NORTH AVE C/O GARDEN ST
Location Address 2: MH 4177
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2013
Trans1 Recv Date: 04/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004300836
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 010707795JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

L130 **CON EDISON SERVICE BOX: 1539** **RCRA NonGen / NLR** **1016972589**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004463667**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.139 mi.
732 ft. **Site 9 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/11/2014
Facility name:	CON EDISON SERVICE BOX: 1539
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004463667
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/11/2014
Site name:	CON EDISON SERVICE BOX: 1539
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004463667
Country:	USA
Location Address 1:	NO AVE 48 AND 48 GARDEN ST
Location Address 2:	SB 1539
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/11/2014
Trans1 Recv Date: 03/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004463667
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 20
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012772800JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

L131 **CON EDISON MANHOLE: 20274** **RCRA NonGen / NLR** **1016677685**
North **NORTH AVE & GARDEN ST** **FINDS** **NYP004313615**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.139 mi.
732 ft. **Site 10 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/15/2013
Facility name: CON EDISON MANHOLE: 20274
Facility address: NORTH AVE & GARDEN ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004313615
Mailing address: VING PL, RM 828

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/15/2013
Site name: CON EDISON MANHOLE: 20274
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877390

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1016677685
Registry ID: 110058877390
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110058877390

L132 **CON EDISON - MANHOLE 1535** **RCRA-LQG** **1016451189**
North **GARDEN ST AND NORTH AVE** **NY MANIFEST** **NYP004302303**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
732 ft. **Site 11 of 11 in cluster L**

Relative:
Lower

Actual:
71 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 1535
Facility address:	GARDEN ST AND NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004302303
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/17/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/17/2013
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 05/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Not a generator, verified

Date form received by agency: 04/17/2013
Site name: CON EDISON MANHOLE: 1535
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004302303
Country: USA
Location Address 1: GARDEN ST AND NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/17/2013
Trans1 Recv Date: 04/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2013

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004302303
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010456840JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

T133 **BLOOMINGDALE PARKING LOT** **NY UST** **U003884000**
South **554 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
734 ft. **Site 1 of 7 in cluster T**

Relative:
Higher

Actual:
102 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600330 / Unregulated: <1101 gal. PBS
Operator Name:	Mel Watson
Owner Name:	Fraydun Enterprises
Owner Street:	3 New York Plaza
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10004
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing

BLOOMINGDALE PARKING LOT (Continued) **U003884000**

Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	4. Closed - in place
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

R134 **BARON MANAGEMENT** **NY UST** **U004187277**
ESE **200 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
736 ft. **Site 3 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Id/Status:	3-167843 / Administratively Closed
Operator Name:	Segundo Tirado
Owner Name:	Ronald Rettner
Owner Street:	481 Main Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	03/05/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

BARON MANAGEMENT (Continued) **U004187277**

Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

S135 **BARCLAYS BANK OF NY/NA** **NY LTANKS** **S100140601**
SE **491 MAIN ST.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
749 ft. **Site 3 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	299548
Spill Number/Closed Date:	8905129 / 1991-03-25
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	1997-02-12
Spiller Name:	Not reported
Spiller Company:	BARCLAYS BANK OF NY/NA
Spiller Address:	604 BROAD HOLLOW RD.
Spiller City,St,Zip:	MELVILLE, NY 11747
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	242324
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 10/06/89: GND INC. (516) 933-1085 NAT MOSER: 1500 GAL #2 FAILED RETEST -.132GPH. TANK TO BE RELINED OR REPLACED. 03/25/91: TANK REMOVED. "
Remarks:	"NAT MOSER (TELECOM 8-23, 1615) WILL CALL BACK AFTER CONTACTING BARCLAYS AND REVIEWING OPTIONS. PETRO TITE 2K 4 GPH"

Material:

Site ID:	299548

BARCLAYS BANK OF NY/NA (Continued) **S100140601**

Operable Unit ID:	930451
Operable Unit:	01
Material ID:	445568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	299548
Spill Tank Test:	1535898
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

S136 **J P MORGAN CHASE BANK N.A.** **NY UST U003885235**
SE **491 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.142 mi.
749 ft. **Site 4 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Id/Status:	3-164372 / Active
Operator Name:	Domenick Margotta
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard
Owner Address2:	14th Floor
Owner City:	Jersey City
Owner State:	NJ
Owner Zipcode:	07310
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/05/1990
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing

J P MORGAN CHASE BANK N.A. (Continued) **U003885235**

Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-164372
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Domenick Margotta
Owner Name:	J P Morgan Chase Bank N.A.
Owner Street:	575 Washington Boulevard
Owner Address2:	14th Floor
Owner City/State/Zip:	Jersey City, NJ 07310
Tank Number:	02
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	1500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	Not reported
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

S137 **NEW ROCHELLE PUBLIC LIBRARY** **NY LTANKS** **S105995872**
SE **1 LAWTON** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
751 ft. **Site 5 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	492304
Spill Number/Closed Date:	1311408 / Not Reported
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2015-10-16
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE PUBLIC LIBRARY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	ROB
Spiller Phone:	(914) 473-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	447251
DEC Memo:	"Tank failed with a dry leak. Will most likely be uncovering, repairing and retesting. WCDOH has been notified...mm 10-15-15 email update request sent to WCHD RDB 10-16-15 Wayne is handling and will forward an update"
Remarks:	""

Material:

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242328
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242331
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Tank Test:

Site ID:	492304
Spill Tank Test:	2495159
Tank Number:	1
Tank Size:	10000
Test Method:	21
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MBMASTRO
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

Site ID:	306611
Spill Number/Closed Date:	0201697 / 2002-09-18
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE LIBRARY
Spiller Address:	1 LAWTON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	FRANK GALLELO
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	274126
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST "

Material:

Site ID:	306611
Operable Unit ID:	852656
Operable Unit:	01
Material ID:	523107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	306611
Spill Tank Test:	1527134
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

N138 **CIOTTI RESIDENCE** **NY LTANKS S107788125**
NW **60 GRAND STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
752 ft. **Site 4 of 5 in cluster N**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Site ID:	332054
Spill Number/Closed Date:	0407555 / 2004-10-07
Spill Date:	2004-10-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2004-10-07
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-07
Spill Record Last Update:	2004-11-01
Spiller Name:	ROB HILL
Spiller Company:	RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 579-3414
Spiller Extention:	Not reported

CIOTTI RESIDENCE (Continued) **S107788125**

DEC Region: 3
DER Facility ID: 267201
DEC Memo: ""
Remarks: "TRUCK DIRVER OVERFILLED AND BLEW A LINE. CREWS ARE IN ROUTE."

Material:
Site ID: 332054
Operable Unit ID: 1094311
Operable Unit: 01
Material ID: 574419
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

SPILLS:
Facility ID: 0602271
Facility Type: ER
DER Facility ID: 267201
Site ID: 364705
DEC Region: 3
Spill Date: 2006-05-31
Spill Number/Closed Date: 0602271 / 2007-02-16
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-05-31
CID: 444
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-31
Spill Record Last Update: 2007-02-16
Spiller Name: ROBERT CIOTTI
Spiller Company: CIOTTI RESIDENCE
Spiller Address: 60 GRAND STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: ROBERT CIOTTI

CIOTTI RESIDENCE (Continued) **S107788125**

Contact Phone: (914) 479-8680
DEC Memo: ""
Remarks: "TESTED THE REMOTE FILL PIPE AND FOUND IT NOT WORKING: 02/15/07 Northeast Envoronmental reported that they excavated 12.31 tons of petroleum impacted soil. NFA TG"

Material:
Site ID: 364705
Operable Unit ID: 1122726
Operable Unit: 01
Material ID: 2112202
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0601618
Facility Type: ER
DER Facility ID: 267201
Site ID: 363896
DEC Region: 3
Spill Date: 2006-05-12
Spill Number/Closed Date: 0601618 / 2006-11-07
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-05-12
CID: 408
Water Affected: STORM DRAINS ON GRAN
Spill Source: Private Dwelling
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-12
Spill Record Last Update: 2006-11-07
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: WAYNE SCHNEIDER
Contact Phone: (914) 813-5972

CIOTTI RESIDENCE (Continued) **S107788125**

DEC Memo: "05/12/06 Friday Stefan Goreau reported from the field that the spilled oil resembled motor oil rather than fuel oil, so he doesn't believe that the spill came from the residence. Northeast Environmental was called by the homeowner to do the cleanup but now the homeowner is not considered the RP. Since rain is imminent and Northeast has a vac truck on site, NE was advised to pump the oil out of the drains. DEC to pick up the expense. TG 11/07/06 IRS completed. TG"
Remarks: "CAUSE IS EITHER TANK OVERFILL OR CHECK VALVE FAILURE."

Material:
Site ID: 363896
Operable Unit ID: 1121950
Operable Unit: 01
Material ID: 2111430
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

O139 **MR CHIMNEY CLEAN** **RCRA NonGen / NLR** **1004758604**
SSW **32 RELYEA PL** **FINDS** **NYD987011855**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.144 mi. **ECHO**
758 ft. **Site 4 of 10 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MR CHIMNEY CLEAN
Facility address: 32 RELYEA PL
NEW ROCHELLE, NY 10801
EPA ID: NYD987011855
Mailing address: RELYEA PL
NEW ROCHELLE, NY 10801
Contact: MAURICE MCKENNA
Contact address: RELYEA PL
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 632-6660
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NAUAL MOTION PICTURES
Owner/operator address: 270 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US

MR CHIMNEY CLEAN (Continued) **1004758604**

Owner/operator telephone: (914) 632-2406
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NAUAL MOTION PICTURES
Owner/operator address: 270 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 632-2406
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MR CHIMNEY CLEAN
Classification: Not a generator, verified

Date form received by agency: 06/01/1994
Site name: MR CHIMNEY CLEAN
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:

Registry ID: 110004493922

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

MR CHIMNEY CLEAN (Continued) **1004758604**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD987011855
Country:	USA
Location Address 1:	270 MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NAVAL MOTION PICTURE SERVICE
Contact:	PAUL RAMOS
Address:	270 MAIN ST
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	000-000-0000

Manifest:

Document ID:	CTF0276746
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/1994
Trans1 Recv Date:	06/23/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/27/1994
Part A Recv Date:	/ /
Part B Recv Date:	07/11/1994
Generator EPA ID:	NYD987011855
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported
TSDF ID:	CTD000604488
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1994

ECHO:

Envid:	1004758604
Registry ID:	110004493922
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004493922

Q140 **NEW ROCHELLE SUPERMARKET CORP.** **NY AST** **A100204374**
SSE **538 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.146 mi.
770 ft. **Site 15 of 15 in cluster Q**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. AST:

PBS Number:	3-166995
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Andrew Taveras
Owner Name:	New Rochelle Supermarket Corp.
Owner Street:	538 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/09/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

T141 **HANGERS CLEANERS** **NY DRYCLEANERS** **S110246761**
South **562-564 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.147 mi.
777 ft. **Site 2 of 7 in cluster T**

Relative:
Higher

Actual:
102 ft.

DRYCLEANERS:

Facility ID:	3-5510-00358
Phone Number:	914-235-0300
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	04MAR23
Install Date:	02
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	CO2
Current Business:	Not reported

S142 **ADREAN PRINTING CO** **RCRA NonGen / NLR** **1004755683**
SE **490 MAIN ST** **FINDS** **NY0000233981**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.147 mi. **ECHO**
778 ft. **Site 6 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ADREAN PRINTING CO
Facility address:	490 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NY0000233981
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	MICHAEL GOLDBERGER
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 636-0200
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 636-0200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MICHAEL GOLDBERGER
Owner/operator address:	490 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 636-0200
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

ADREAN PRINTING CO (Continued) **1004755683**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ADREAN PRINTING CO
Classification: Not a generator, verified

Date form received by agency: 04/21/1994
Site name: ADREAN PRINTING CO
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004314297

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NY0000233981
Country: USA
Location Address 1: 490 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: ADREAN PRINTING
Contact: WILLIAM C WHITE
Address: 490 MAIN ST
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-636-0200

Manifest:

Document ID: NYB8521299
Manifest Status: Completed copy
Trans1 State ID: PW2414

ADREAN PRINTING CO (Continued) **1004755683**

Trans2 State ID:	Not reported
Generator Ship Date:	01/16/1997
Trans1 Recv Date:	01/16/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/16/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/31/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYG0919566
Manifest Status:	Completed copy
Trans1 State ID:	PW2414
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/28/1997
Part A Recv Date:	/ /
Part B Recv Date:	09/19/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYB6575904
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/1994
Trans1 Recv Date:	11/11/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/11/1994
Part A Recv Date:	11/21/1994
Part B Recv Date:	12/05/1994
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769

ADREAN PRINTING CO (Continued) **1004755683**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1994

Document ID:	NYB7902711
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	05/25/1995
Trans1 Recv Date:	05/25/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/25/1995
Part A Recv Date:	06/16/1995
Part B Recv Date:	06/07/1995
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1995

Document ID:	NYB7750935
Manifest Status:	Completed copy
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/1996
Trans1 Recv Date:	04/16/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/16/1996
Part A Recv Date:	05/01/1996
Part B Recv Date:	05/03/1996
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

ADREAN PRINTING CO (Continued) **1004755683**

Year: 1996

ECHO:
Envid: 1004755683
Registry ID: 110004314297
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004314297

O143 **PRO AUTO PARTS** **RCRA NonGen / NLR** **1001079946**
SW **41 REYLEA PL** **FINDS** **NYR000016535**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.148 mi. **ECHO**
780 ft. **Site 5 of 10 in cluster O**

Relative:
Higher

Actual:
87 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: PRO AUTO PARTS
Facility address: 41 REYLEA PL
NEW ROCHELLE, NY 108016918
EPA ID: NYR000016535
Mailing address: SUMMERFIELD ST
SCARSDALE, NY 10853
Contact: Not reported
Contact address: SUMMERFIELD ST
SCARSDALE, NY 10853
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PRO AUTO PARTS CORP
Owner/operator address: 135 SUMMER FIELD ST
SCARSDALE, NY 10853
Owner/operator country: US
Owner/operator telephone: (914) 772-4871
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PRO AUTO PARTS CORP
Owner/operator address: 135 SUMMER FIELD ST
SCARSDALE, NY 10853
Owner/operator country: US
Owner/operator telephone: (914) 772-4871
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

PRO AUTO PARTS (Continued) **1001079946**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 11/16/1995
Site name: PRO AUTO PARTS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

FINDS:

Registry ID: 110004520377

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000016535
Country: USA
Location Address 1: 41 REYLEA PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY

PRO AUTO PARTS (Continued) **1001079946**

Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: PRO AUTO PARTS
Contact: PHILIP A MORRIS JR
Address: 135 SUMMERFIELD ROAD
City/State/Zip: SCARSDALE, NY 10583
Country: USA
Phone: 914-793-3336

Manifest:

Document ID: NYB7350417
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 12/21/1995
Trans1 Recv Date: 12/21/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 12/21/1995
Part A Recv Date: 01/05/1996
Part B Recv Date: 01/03/1996
Generator EPA ID: NYR000016535
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00130
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 089
Year: 1995

ECHO:
Envid: 1001079946
Registry ID: 110004520377
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004520377

U144 **NYS THRUWAY AUTH** **RCRA NonGen / NLR** **1000553909**
North **THRUWAY BRIDGE MP 605.75** **NY MANIFEST** **NYD986963445**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.148 mi.
784 ft. **Site 1 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYS THRUWAY AUTH
Facility address: THRUWAY BRIDGE MP 605.75
NEW ROCHELLE, NY 10801
EPA ID: NYD986963445
Mailing address: S BROADWAY
TARRYTOWN, NY 105915697
Contact: Not reported
Contact address: S BROADWAY

NYS THRUWAY AUTH (Continued) **1000553909**

TARRYTOWN, NY 105915697
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYS THRUWAY AUTH
Owner/operator address: PO BOX 189
ALBANY, NY 12201
Owner/operator country: US
Owner/operator telephone: (518) 436-2811
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYS THRUWAY AUTH
Owner/operator address: PO BOX 189
ALBANY, NY 12201
Owner/operator country: US
Owner/operator telephone: (518) 436-2811
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 02/19/1992

NYS THRUWAY AUTH (Continued) **1000553909**

Site name: NYS THRUWAY
Classification: Large Quantity Generator

Date form received by agency: 07/12/1991
Site name: NYS THRUWAY AUTH
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986963445
Country: USA
Location Address 1: I-95 NORTH & NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: NEW YORK STATE THRUWAY AUTHORITY
Contact: NEW YORK STATE THRUWAY AUTHORITY
Address: 333 SOUTH BROADWAY
City/State/Zip: TARRYTOWN, NY 10591
Country: USA
Phone: 000-000-0000

Manifest:

Document ID: MIA2285792
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: MI5808
Trans2 State ID: Not reported
Generator Ship Date: 04/23/1992
Trans1 Recv Date: 04/23/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 04/24/1992
Part A Recv Date: / /
Part B Recv Date: 06/02/1992
Generator EPA ID: NYD986963445
Trans1 EPA ID: PAD064375470
Trans2 EPA ID: Not reported
TSDF ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1992

NYS THRUWAY AUTH (Continued) **1000553909**

Document ID:	MIA2540754
Manifest Status:	Completed copy
Trans1 State ID:	5825
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/1992
Trans1 Recv Date:	05/26/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/27/1992
Part A Recv Date:	/ /
Part B Recv Date:	06/16/1992
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	PAD064375470
Trans2 EPA ID:	Not reported
TSDF ID:	MID000724831
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1992

Document ID:	NJA1042129
Manifest Status:	Completed copy
Trans1 State ID:	46403ANY
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/1991
Trans1 Recv Date:	08/06/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1991
Part A Recv Date:	/ /
Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	22400
Units:	P - Pounds
Number of Containers:	028
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1042128
Manifest Status:	Completed copy
Trans1 State ID:	S7246
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/1991
Trans1 Recv Date:	08/06/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1991
Part A Recv Date:	/ /

NYS THRUWAY AUTH (Continued) **1000553909**

Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	32800
Units:	P - Pounds
Number of Containers:	041
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1042127
Manifest Status:	Completed copy
Trans1 State ID:	39413BNY
Trans2 State ID:	Not reported
Generator Ship Date:	08/02/1991
Trans1 Recv Date:	08/02/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/02/1991
Part A Recv Date:	/ /
Part B Recv Date:	08/19/1991
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	040
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1991

V145 **FIRST METRO SERVICES** **RCRA NonGen / NLR** **1004759815**
SSW **357 HUGONOT ST** **FINDS** **NYR000022053**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.149 mi.
787 ft. **Site 1 of 5 in cluster V**

Relative:
Higher

Actual:
92 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FIRST METRO SERVICES
Facility address:	357 HUGONOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYR000022053
Mailing address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact:	BILL LIVANOS
Contact address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact country:	US
Contact telephone:	(914) 576-7210
Contact email:	Not reported

FIRST METRO SERVICES (Continued) **1004759815**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: (914) 632-9692
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LEO SATALICH
Owner/operator address: 19 LYON PL
NEW ROCHELLE, NY 10805
Owner/operator country: US
Owner/operator telephone: (914) 632-9692
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FIRST METRO SERVICES
Classification: Not a generator, verified

Date form received by agency: 04/09/1996
Site name: FIRST METRO SERVICES
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D006
. Waste name: CADMIUM

FIRST METRO SERVICES (Continued) **1004759815**

Violation Status: No violations found

FINDS:

Registry ID: 110004523882

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:

Envid:	1004759815
Registry ID:	110004523882
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004523882

N146 **GUIDANCE CENTER INC** **NY LTANKS** **S102556009**
NW **70 GRAND ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.149 mi.
789 ft. **Site 5 of 5 in cluster N**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Site ID:	77017
Spill Number/Closed Date:	9613894 / 1997-10-03
Spill Date:	1997-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-26
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-02-26
Spill Record Last Update:	1997-10-22
Spiller Name:	STEVEN SMITH
Spiller Company:	GUIDANCE CENTER INC
Spiller Address:	70 GRAND ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVEN SMITH
Spiller Phone:	(914) 636-4440
Spiller Extention:	250
DEC Region:	3

GUIDANCE CENTER INC (Continued) **S102556009**

DER Facility ID: 71920
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/03/97 LETTER SENT; BASED ON TANK REMOVAL REPORT, NFA; "
Remarks: "OLD GASOLINE TANK FOUND UNDER THE GROUND - FOUND CONTAMINATED SOIL PHASE 2 COMPLETED - NO REMEDATION STARTED OWNER OF PROPERTY WILL AWAIT DIRECTION FROM DEC ABOUT TANK REMOVAL"

Material:
Site ID: 77017
Operable Unit ID: 1041477
Operable Unit: 01
Material ID: 339001
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

T147 **CENTRE MAIN EQUITIES LLC** **NY UST U004176186**
South **573-579 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.150 mi.
793 ft. **Site 3 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800238 / Active
Operator Name: Pedro Benoit
Owner Name: Centre Main Equities LLC
Owner Street: 542 Main Street, 2nd Floor
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron

CENTRE MAIN EQUITIES LLC (Continued) **U004176186**

Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

WESTCHESTER CO. AST:
PBS Number: 3-800238
Site Status: Active
GDS Number: Not reported
Operator Name: Pedro Benoit
Owner Name: Centre Main Equities LLC
Owner Street: 542 Main Street, 2nd Floor
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 001
Status: 1. In-Service
Date Installation: 09/01/2004
Capacity: 2000
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 6. Aboveground in subterranean vault with access for inspections
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating,99. Other
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 0. None
Dispenser: 2. Suction

T148 **CENTRE-MAIN ASSOCIATES** **NY LTANKS** **S106123770**
South **75 - 77 CENTER AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.152 mi.
802 ft. **Site 4 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

LTANKS:
Site ID: 149369
Spill Number/Closed Date: 0311823 / 2004-12-30
Spill Date: 2004-01-21
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: WESTCHESTER CNTY HEALTH D

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

Reported to Dept:	2004-01-21
CID:	44
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2005-01-10
Spiller Name:	ED
Spiller Company:	Not reported
Spiller Address:	75 - 77 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ED
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127066
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 1/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson, WCDOH dated 30Dec2004. WCDOH requires NFA at this time."
Remarks:	"recommend, uncover repair and retest. Tank is bolted in basement."

Material:

Site ID:	149369
Operable Unit ID:	877137
Operable Unit:	01
Material ID:	497066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	149369
Spill Tank Test:	1528926
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

O149 **INDUST OVERALL SERVICE CORP** **NY LTANKS** **S116555778**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.153 mi.
806 ft. **Site 6 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

LTANKS:

Site ID:	494186
Spill Number/Closed Date:	1400928 / Not Reported
Spill Date:	2014-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	ELMOORE
Referred To:	Not reported
Reported to Dept:	2014-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-04-28
Spill Record Last Update:	2014-06-19
Spiller Name:	BOB OBRIEN
Spiller Company:	INDUSTRIAL OVERALL SERV CORP
Spiller Address:	10 BARTELL PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	BOB OBRIEN
Spiller Phone:	(914) 235-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449117
DEC Memo:	"4-28-14: Chris/WCHD call to Dispt./V.Mc.: Heating oil tank, out of service, failed test."
Remarks:	"tank 2 5000 gallon"

Material:

Site ID:	494186
Operable Unit ID:	1243715
Operable Unit:	01
Material ID:	2244419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Tank Test:

Site ID:	494186
Spill Tank Test:	2495577
Tank Number:	1
Tank Size:	4000
Test Method:	99
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v
Site ID:	494186
Spill Tank Test:	2495578
Tank Number:	2
Tank Size:	5000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

O150 **INDUSTRIAL OVERALL SERVICE CORP.** **NY UST** **U004176640**
SW **10 BARTELLS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 7 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

WESTCHESTER CO. UST:

Id/Status:	3-025453 / Unregulated
Operator Name:	Robert O'Brien
Owner Name:	Industrial Overall Service Corp.
Owner Street:	10 Bartels Place
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	4000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	03/11/2003
Tank Location:	5. Underground
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **U004176640**

Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1980
Date Perm Closure:	08/26/2014
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	0. None

O151 **INDUSTRIAL OVERALL SERVICE CORP** **RCRA NonGen / NLR** **1016678149**
SW **10 BARTELS PL** **FINDS** **NYR000208967**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.153 mi. **ECHO**
806 ft. **Site 8 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/09/2014
Facility name:	INDUSTRIAL OVERALL SERVICE CORP
Facility address:	10 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000208967
Mailing address:	BARTELS PL NEW ROCHELLE, NY 10801
Contact:	ROBERT R OBRIEN
Contact address:	BUSHNELL ST ESSEX, CT 06426
Contact country:	US
Contact telephone:	(914) 235-1220
Contact email:	BOB@LINENGUY.COM
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/01/1950
Owner/Op end date: Not reported

Owner/operator name: INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address: BARTELS PL
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 235-1220
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/23/2010
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Historical Generators:
Date form received by agency: 03/31/2014
Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Small Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/14/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 12000

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Paid penalty amount: 12000

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 04/15/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 10000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 03/18/2014
Date achieved compliance: 07/08/2014
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/31/2014
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/08/2014
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/01/2014
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Listing - General
Date achieved compliance: 07/08/2014
Evaluation lead agency: State

Evaluation date: 03/18/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 07/08/2014
Evaluation lead agency: State

FINDS:

Registry ID: 110058881152

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000208967
Country:	USA
Location Address 1:	10 BARTELS PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Contact:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address:	10 BARTELS PL
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	7500
Units:	P - Pounds
Number of Containers:	15
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/09/2015
Trans1 Recv Date: 04/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/09/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200
Units: P - Pounds
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 000959895GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/26/2015
Trans1 Recv Date: 01/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/26/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 700
Units: P - Pounds

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 010914098JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/29/2015
Trans1 Recv Date: 10/29/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/29/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000208967
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 800
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014168256JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014168256JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2014
Trans1 Recv Date:	06/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	32440
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133085JJK

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	05/14/2014
Trans1 Recv Date:	05/14/2014
Trans2 Recv Date:	05/19/2014
TSD Site Recv Date:	05/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID040098352
Waste Code:	Not reported
Quantity:	6000
Units:	P - Pounds
Number of Containers:	3
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007176740FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2014
Trans1 Recv Date:	06/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	39860
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133084JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2014
Trans1 Recv Date:	06/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	40340
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133058JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	38940
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133056JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Waste Code:	Not reported
Quantity:	30
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133055JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2014
Trans1 Recv Date:	06/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	39060
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013132604JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2014
Trans1 Recv Date:	06/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	38380
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	013133054JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	7500
Units:	P - Pounds
Number of Containers:	15
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	000959895GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2015
Trans1 Recv Date:	01/26/2015

INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	010914098JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1016678149
Registry ID:	110058881152
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058881152

O152 **INDUSTRIAL OVERALL SERVICE CORP.** **NY SHWS** **S110043643**
SW **10 BARTELS PLACE** **NY CBS** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 9 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

SHWS:

Program:	HW
Site Code:	413917
Classification:	Significant threat to the public health or environment - action required.
Region:	3
Acres:	0.42
HW Code:	360109
Record Add:	05/15/2009
Record Upd:	09/18/2015
Updated By:	DACROSBY

Site Description: Location: The Industrial Overall Service Corporation site is located at 10 Bartels Place in the City of New Rochelle, Westchester County, NY. The site is located east of I-95 and west of US-1 (Huguenot Street) and it is bounded by Reylea Place, Bartels Place, Centre Avenue and the Metro North railroad property and tracks. Site Features: The site is 0.42 acres in size and resides on a slightly

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

sloping irregularly shaped parcel. The main site feature includes a six-sided building which occupies the majority of the property and a small parking area located to the south and southwest of the building. The surrounding area is urban with a mix of commercial and residential establishments mixed in between the commercial businesses. Current Zoning/ Uses: This property is zoned for commercial use. The building is the location of two active businesses, Workingmans Closet and Apparel +Plus. The Workingmans Closet business uses the business address of 27 Centre Street. Historic Uses: Industrial Overall Services has been operating at the current location as a uniform and industrial clothing laundering facility, historically cleaning heavily soiled clothing from auto body and gasoline dispensing businesses since 1939. Based on a Sanborn Fire Insurance Map form 1931, the site previously operated as an automobile garage. In 1980, Workingmans Closet which sells new and reclaimed work clothes, was opened, and a dry cleaning facility operated there for a short time in the same decade. Today, Workingmans Closet launders linens and uniforms for restaurants and other businesses, and Apparel +Plus is a retail uniform business. Laundry operations on the site have used various cleaning products in the past. A remedial investigation conducted at the site has measured high concentrations of the dry cleaning chemical tetrachloroethylene (PCE) and its degradation products which is migrating from two sources: the subsurface lint trap located within the site building, and a debris and waste disposal area on the ground surface on site and on the adjacent Metro North Railroad property. Contamination migrating from these sources has impacted groundwater in the bedrock and overburden aquifers and has developed a plume extending downgradient (southwest) from the site over 1900 feet, as well as the bedrock itself.Site Geology and Hydrology: Groundwater is found in the overburden and in the bedrock. Groundwater is generally found 10 to 15 feet below ground surface and flows in a southwesterly direction. Overburden in the vicinity ranges in thickness from 2.2 feet to 32 feet, and consists of fill material (1-5 feet in thickness) and varied amounts of fine to coarse sand with varying amounts of silt. Deeper overburden is described as having till-like characteristics (higher density, well consolidated, and lower moisture content). Bedrock in the vicinity is a highly weathered gneissic/schistosic rock which is undulating in nature and is generally more transmissive than the till-like overburden material directly above.

Env Problem: Nature and Extent of Contamination: The primary contaminants of concern at the site include tetrachloroethylene (PCE) and its associated breakdown products. PCE was detected in groundwater at the site and downgradient off-site. On-site PCE in groundwater was noted at greater than 5,300 parts per billion (ppb) in site. The levels of PCE appear to diminish from the 1,000's of ppb of PCE to non detectable approximately 1000 feet to the southwest of the site. However, a high (PCE) concentration of 200 ppm was documented by within the adjoining Metro North railway property. Trichloroethylene (TCE) and TCA, were also detected in the groundwater both downgradient and on the site. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. No significant environmental resources have been identified near the site. Significant Threat: The site presents a significant threat to the environment and a potential threat to human health due to the ongoing release of contamination from the site and from adjoining

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Metro North property into groundwater and soil vapor.

Health Problem: Direct contact with contaminants in groundwater is unlikely because the area is served by an uncontaminated public water supply. While the majority of the site is covered with buildings and pavement, trespassers or employees may come in direct contact with some contaminated surficial soils on site and on the adjacent Metro North Railroad property. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion (SVI). Inhalation of site contaminants in indoor air due to soil vapor intrusion is unknown because the on-site building is an active laundry facility. However, an evaluation to determine the potential for soil vapor intrusion to occur, will be needed should the current site use of the building or chemical use change in the future. Sub-slab depressurization systems have been installed in two off-site buildings to prevent the inhalation of site-related contamination. In addition, air monitoring is on-going at four additional off-site buildings to verify further actions are not needed. Sampling indicates soil vapor intrusion may be a concern for additional off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: UNKNOWN
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 6/11/2009 3:11:00 PM
Record Upd: 8/10/2015 11:09:00 AM
Updated By: KATHOMPS
Own Op: On-Site Operator
Sub Type: 08
Owner Name: Robert R. O'Brien
Owner Company: Apparel + Plus Textile Rental, LLC
Owner Address: 27 Centre Avenue/10 Bartells Place
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: ROBERT O'BRIEN
Owner Company: WORKING MAN'S CLOSET, INC
Owner Address: 3 KOLBERT DRIVE
Owner Addr2: Not reported
Owner City,St,Zip: SCARSDALE, NY 10583

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Region 3 Headquarters
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	21 South Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Mr Burton Dorfman, Esq.
Owner Company:	Industrial Overall Services, Inc.(IOS)
Owner Address:	10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	360109
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	360087
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	5/21/2009 3:07:00 PM
Record Updated:	5/21/2009 3:07:00 PM
Updated By:	RXKEATIN
Crossref ID:	1309988
Cross Ref Type Code:	01

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **S110043643**

Cross Ref Type: Spill No.
Record Added Date: 4/14/2014 11:03:00 AM
Record Updated: 4/14/2014 11:03:00 AM
Updated By: RDBENDEL
Crossref ID: 1310684
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2/14/2014 8:19:00 AM
Record Updated: 2/14/2014 8:19:00 AM
Updated By: ELMOORE

CBS:
CBS Number: 3-000235
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 3
UTMX: 602235.14737
UTMY: 4529262.58924

O153 **INDUSTRIAL OVERALL** **NY CBS AST** **S105455801**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
806 ft. **Site 10 of 10 in cluster O**

Relative:
Higher

Actual:
84 ft.

R154 **RETTNER MANAGEMENT CORP** **NY UST** **U004177201**
SE **481 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
816 ft. **Site 4 of 4 in cluster R**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:
Id/Status: 3-255033 / Active
Operator Name: Arnoldo Diaz
Owner Name: Rettner Main Street, LLC
Owner Street: 374 McLean Avenue
Owner Address2: Not reported
Owner City: Yonkers
Owner State: NY
Owner Zipcode: 10705
GDS Number: Not reported

Tank Number: 1
Status: 0. Administratively closed
Capacity: 3000
Product Stored: 7. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 09/01/2002
Tank Location: Not reported
Tank Type: 1. Steel/Carbon steel/Iron

RETTNER MANAGEMENT CORP (Continued) **U004177201**

Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	2500
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/01/1970
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

T155 **CON EDISON TRANSFORMER MANHOLE: 2750** **RCRA NonGen / NLR** **1016677840**
South **CENTRE AVE & MAIN ST** **FINDS** **NYP004315198**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.155 mi. **ECHO**
821 ft. **Site 5 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/21/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2750
Facility address:	CENTRE AVE & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004315198
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/21/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2750
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058871369

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004315198
Country: USA
Location Address 1: CENTRE ST & MAIN
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/2013
Trans1 Recv Date:	05/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004315198
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	007019053JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

ECHO:

Envid:	1016677840
Registry ID:	110058871369
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058871369

T156 **CON EDISON** **NY MANIFEST** **S117318285**
South **MAIN ST & CENTRE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
821 ft. **Site 6 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

EPA ID:	NYP004658019
Country:	USA
Location Address 1:	MAIN ST & CENTRE ST
Location Address 2:	MH734
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON

CON EDISON (Continued) **S117318285**

Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/16/2014
Trans1 Recv Date: 09/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/19/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004658019
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012771786JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

T157 **CON ED** **NY MANIFEST** **S118088511**
South **CENTRE AVE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
821 ft. **Site 7 of 7 in cluster T**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:
EPA ID: NYP004760815
Country: USA
Location Address 1: CENTRE AVE & MAIN ST
Location Address 2: TM 2750
Location City: NEW ROCHELLE
Location State: NY

CON ED (Continued) **S118088511**

Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/31/2015
Trans1 Recv Date: 03/31/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004760815
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091694JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/31/2015
Trans1 Recv Date: 03/31/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2015

CON ED (Continued) **S118088511**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760815
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091694JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

158
NNW
1/8-1/4
0.157 mi.
827 ft.

RITZCOVAN - TTF **NY LTANKS** **S118263505**
22 BURLING LANE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	514123
Spill Number/Closed Date:	1506693 / Not Reported
Spill Date:	2015-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2015-10-09
Spiller Name:	Not given

RITZCOVAN - TTF (Continued) **S118263505**

Spiller Company:	Ritzcovan (Owner)
Spiller Address:	22 BURLING LANE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	BRUCE
Spiller Phone:	9147120600
Spiller Extention:	1
DEC Region:	3
DER Facility ID:	468599
DEC Memo:	"9/24/15 Spoke to Bruce, the contact, who is trying to arrange tank removal, as he is tentatively purchasing the property from Ritzcovan. I gave him a list of contractors in Westchester. dw"
Remarks:	"unknown whether contaminated. option recover & repair, or remove; unknown at this time"

Material:

Site ID:	514123
Operable Unit ID:	1263331
Operable Unit:	01
Material ID:	2267021
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	514123
Spill Tank Test:	2498471
Tank Number:	Not reported
Tank Size:	275
Test Method:	NN
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	DXWEITZ
Last Modified:	Not reported
Test Method:	Testing Not Required

U159 **CON EDISON MANHOLE: 12245** **RCRA NonGen / NLR** **1016677186**
North **NORTH AVE & BURLING LANE** **FINDS** **NYP004307492**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.157 mi. **ECHO**
830 ft. **Site 2 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/06/2013
Facility name:	CON EDISON MANHOLE: 12245
Facility address:	NORTH AVE & BURLING LANE NEW ROCHELLE, NY 10801
EPA ID:	NYP004307492
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Contact: GINO FRABASILE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/06/2013
Site name: CON EDISON MANHOLE: 12245
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877531

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYP004307492
Country: USA
Location Address 1: NORTH AVE & BURLING LANE
Location Address 2: MH 12245
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10580
Location Zip Code 4: Not reported

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	05/07/2013
TSD Site Recv Date:	05/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307492
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	004816866FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1016677186
Registry ID:	110058877531
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058877531

W160 **CASARRA RESIDENCE** **NY LTANKS** **S105997517**
West **9 BADEAU PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.165 mi.
869 ft. **Site 1 of 4 in cluster W**

Relative:
Higher

Actual:
104 ft.

LTANKS:

Site ID:	157707
Spill Number/Closed Date:	0209171 / 2003-02-05
Spill Date:	2002-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-12-06
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-06
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	9 BADEAU PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SAL CASARRA
Spiller Phone:	(914) 235-0620
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/05/2003 Northeast Environmental removed the tank and reported that no contamination was present. NFA TG"
Remarks:	"uncover repair and retest"

Material:

Site ID:	157707
Operable Unit ID:	860605
Operable Unit:	01
Material ID:	516149
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CASARRA RESIDENCE (Continued) **S105997517**

Tank Test:

V161 **STORAGE USA** **NY UST** **U003949850**
SSW **363 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.165 mi.
869 ft. **Site 2 of 5 in cluster V**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801137 / Administratively Closed
Operator Name:	Narine Nathu
Owner Name:	SUSA Partnership, L.P.
Owner Street:	175 Toyota Plaza
Owner Address2:	Not reported
Owner City:	Memphis
Owner State:	TN
Owner Zipcode:	38103
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1934
Date Perm Closure:	03/15/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

X162 **DRIVE IT YOURSELF** **NY UST** **U004176354**
North **20 GARDEN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.175 mi.
922 ft. **Site 1 of 2 in cluster X**

Relative:
Lower

Actual:
71 ft.

WESTCHESTER CO. UST:

Id/Status:	3-494380 / Unregulated
Operator Name:	Drive It Yourself
Owner Name:	Ed;edward Jr;tim Tostanowski
Owner Street:	128 Saw Mill River Rd.
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701

DRIVE IT YOURSELF (Continued) **U004176354**

GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	7. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1974
Date Perm Closure:	02/01/1998
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Y163 **NYNEX** **NY LTANKS** **S100164268**
WNW **40 WASHINGTON AVE** **N/A**
1/8-1/4 **GREENBUSH, NY**
0.175 mi.
924 ft. **Site 1 of 4 in cluster Y**

Relative:
Higher

Actual:
112 ft.

LTANKS:

Site ID:	60528
Spill Number/Closed Date:	8803234 / 1988-07-22
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-07-22
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-07-22
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-28
Spill Record Last Update:	1988-09-07
Spiller Name:	Not reported
Spiller Company:	JOHN ALBARANO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

NYNEX (Continued) **S100164268**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 59075
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK PUMED OUT.TO BE REMOVED. "
Remarks: "#2FUEL 5K 1.842 / 4K .170 DIESEL"

Material:
Site ID: 60528
Operable Unit ID: 918404
Operable Unit: 01
Material ID: 458797
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 60528
Spill Tank Test: 1534290
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

Z164 **ROTH CLEANERS** **RCRA NonGen / NLR** **1000237840**
SSE **1 LEROY PL** **FINDS** **NYD078706686**
1/8-1/4 **NEW ROCHELLE, NY 10805** **NY DRYCLEANERS**
0.178 mi. **NY MANIFEST**
938 ft. **Site 1 of 2 in cluster Z** **ECHO**

Relative: Higher

Actual: 100 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ROTH CLEANERS
Facility address: 1 LEROY PL
NEW ROCHELLE, NY 10805
EPA ID: NYD078706686
Mailing address: LEROY PL
NEW ROCHELLE, NY 10805
Contact: BEN ROTH
Contact address: LEROY PL
NEW ROCHELLE, NY 10805
Contact country: US
Contact telephone: (914) 633-7114
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.

ROTH CLEANERS (Continued) **1000237840**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROTH CLEANERS
Classification: Not a generator, verified

Date form received by agency: 08/27/1986
Site name: ROTH CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE

ROTH CLEANERS (Continued) **1000237840**

USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - Manifest
- Date violation determined: 04/24/1987
- Date achieved compliance: 04/26/1987
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 04/24/1987
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 04/24/1987
- Evaluation: NON-FINANCIAL RECORD REVIEW
- Area of violation: Generators - Manifest
- Date achieved compliance: 04/26/1987
- Evaluation lead agency: State

FINDS:

Registry ID: 110004370369

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

DRYCLEANERS:
- Facility ID: 3-5510-00292
- Phone Number: 914-633-7114
- Region: Not reported
- Registration Effective Date: N/A
- Inspection Date: 09JUL16
- Install Date: 98
- Drop Shop: Not reported
- Shutdown: Y
- Alternate Solvent: Not reported
- Current Business: Not reported

ROTH CLEANERS (Continued) **1000237840**

NY MANIFEST:

EPA ID:	NYD078706686
Country:	USA
Location Address 1:	1 LEROY PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10805
Location Zip Code 4:	Not reported

Mailing Info:

Name:	ROTH CLEANERS
Contact:	ROTH CLEANERS
Address:	1 LEROY PLACE
City/State/Zip:	NEW ROCHELLE, NY 10805
Country:	USA
Phone:	914-633-7114

Manifest:

Document ID:	NYC6083291
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	03/08/2000
Trans1 Recv Date:	03/08/2000
Trans2 Recv Date:	03/09/2000
TSD Site Recv Date:	03/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6190896
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/23/2000
Trans1 Recv Date:	06/23/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

ROTH CLEANERS (Continued) **1000237840**

TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6133320
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	05/03/2000
Trans1 Recv Date:	05/03/2000
Trans2 Recv Date:	05/04/2000
TSD Site Recv Date:	05/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6038177
Manifest Status:	Not reported
Trans1 State ID:	NYCR2346
Trans2 State ID:	ILT104414
Generator Ship Date:	01/04/2000
Trans1 Recv Date:	01/04/2000
Trans2 Recv Date:	01/06/2000
TSD Site Recv Date:	01/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

ROTH CLEANERS (Continued) **1000237840**

Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC5558095
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	NJT913LY
Generator Ship Date:	03/02/1999
Trans1 Recv Date:	03/02/1999
Trans2 Recv Date:	03/04/1999
TSD Site Recv Date:	03/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5658401
Manifest Status:	Not reported
Trans1 State ID:	CR2436
Trans2 State ID:	T162VWNJ
Generator Ship Date:	06/22/1999
Trans1 Recv Date:	06/22/1999
Trans2 Recv Date:	06/25/1999
TSD Site Recv Date:	07/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

ROTH CLEANERS (Continued) **1000237840**

Document ID:	NYC5580404
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	NJT913LY
Generator Ship Date:	04/05/1999
Trans1 Recv Date:	04/05/1999
Trans2 Recv Date:	04/08/1999
TSD Site Recv Date:	04/14/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5849730
Manifest Status:	Not reported
Trans1 State ID:	NYC2436
Trans2 State ID:	T604414IL
Generator Ship Date:	07/20/1999
Trans1 Recv Date:	07/20/1999
Trans2 Recv Date:	07/22/1999
TSD Site Recv Date:	07/26/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5520780
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported

ROTH CLEANERS (Continued) **1000237840**

Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: CTF0671298
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 01/08/1998
Trans1 Recv Date: 01/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0680858
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 02/09/1998
Trans1 Recv Date: 02/09/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001

ROTH CLEANERS (Continued) **1000237840**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0688530
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: Not reported
Generator Ship Date: 03/06/1998
Trans1 Recv Date: 03/06/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/12/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0691573
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: Not reported
Generator Ship Date: 03/30/1998
Trans1 Recv Date: 03/30/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/02/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD078706686
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: CTF0712380
Manifest Status: Not reported
Trans1 State ID: NYCR2436

ROTH CLEANERS (Continued) **1000237840**

Trans2 State ID:	Not reported
Generator Ship Date:	05/27/1998
Trans1 Recv Date:	05/27/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0722807
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	06/29/1998
Trans1 Recv Date:	06/29/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/01/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0723823
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1998
Trans1 Recv Date:	08/19/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/31/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202

ROTH CLEANERS (Continued) **1000237840**

Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5443334
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NYNJ
Generator Ship Date:	11/09/1998
Trans1 Recv Date:	11/09/1998
Trans2 Recv Date:	11/12/1998
TSD Site Recv Date:	11/20/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYC5478750
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NXNJ
Generator Ship Date:	12/10/1998
Trans1 Recv Date:	12/10/1998
Trans2 Recv Date:	12/14/1998
TSD Site Recv Date:	12/18/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

ROTH CLEANERS (Continued) **1000237840**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	CTF0622944
Manifest Status:	Completed copy
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/1997
Trans1 Recv Date:	05/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/05/1997
Part A Recv Date:	06/10/1997
Part B Recv Date:	06/19/1997
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	CTF0624862
Manifest Status:	Completed copy
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	04/29/1997
Trans1 Recv Date:	04/29/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/01/1997
Part A Recv Date:	05/13/1997
Part B Recv Date:	05/14/1997
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

ROTH CLEANERS (Continued) **1000237840**

ECHO:
Envid: 1000237840
Registry ID: 110004370369
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004370369

Z165 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243086**
SSE **DIVISION ST & LEROY PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.181 mi.
957 ft. **Site 2 of 2 in cluster Z**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:
EPA ID: NYP004124210
Country: USA
Location Address 1: DIVISION ST & LEROY PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: NYE1309986
Manifest Status: Not reported
Trans1 State ID: 46614JM
Trans2 State ID: Not reported
Generator Ship Date: 08/30/2004
Trans1 Recv Date: 08/30/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/30/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004124210
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00014
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

AA166
ESE
1/8-1/4
0.182 mi.
959 ft.

CON ED-V37
LECOUNT PL & MAIN ST
NEW ROCHELLE, NY 10801

Site 1 of 2 in cluster AA

NY MANIFEST **S109064681**
N/A

Relative:
Higher

Actual:
87 ft.

NY MANIFEST:

EPA ID:	NYP004027967
Country:	USA
Location Address 1:	LECOUNT PL & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	0000

Mailing Info:

Name:	CON ED-V37
Contact:	Not reported
Address:	Not reported
City/State/Zip:	Not reported
Country:	Not reported
Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

AA167
ESE
1/8-1/4
0.182 mi.
959 ft.

CON ED-V14
LECOUNT PL & MAIN ST
NEW ROCHELLE, NY 10801

Site 2 of 2 in cluster AA

NY MANIFEST **S109064677**
N/A

Relative:
Higher

Actual:
87 ft.

NY MANIFEST:

EPA ID:	NYP004028122
Country:	USA
Location Address 1:	LECOUNT PL & MAIN ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	0000

Mailing Info:

Name:	CON ED-V14
Contact:	Not reported
Address:	Not reported
City/State/Zip:	Not reported
Country:	Not reported
Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

W168
West
1/8-1/4
0.183 mi.
964 ft.

RESIDENCE
18 BADEAU PLACE
NEW ROCHELLE, NY

Site 2 of 4 in cluster W

NY LTANKS **S102663947**
N/A

Relative:
Higher

Actual:
104 ft.

LTANKS:

Site ID:	177416
Spill Number/Closed Date:	9609269 / 1996-10-24
Spill Date:	1996-10-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-24
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-24
Spill Record Last Update:	1996-12-05
Spiller Name:	Not reported
Spiller Company:	JULIO VALER
Spiller Address:	18 BADEAU PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JULIO VALER
Spiller Phone:	(914) 636-8917
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149078
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED TOO MUCH OIL. SPILLED ONTO BLACKTOP DRIVEWAY. CLEANED UP."

Material:

Site ID:	177416
Operable Unit ID:	1037374
Operable Unit:	01
Material ID:	345000
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	Gallons
Recovered:	5.00
Resource Affected:	Not reported
Oxygenate:	Not reported

RESIDENCE (Continued) **S102663947**

Tank Test:

AB169 **J B & FRANKS** **RCRA NonGen / NLR** **1000100357**
SW **27 BARTELS PL** **FINDS** **NYD986884732**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.185 mi. **ECHO**
977 ft. **Site 1 of 5 in cluster AB**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: J B & FRANKS
Facility address: 27 BARTELS PL
NEW ROCHELLE, NY 108016901
EPA ID: NYD986884732
Mailing address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact: Not reported
Contact address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

J B & FRANKS (Continued) **1000100357**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 12/01/1989
Site name: J B & FRANKS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004439705

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986884732
Country: USA
Location Address 1: 27 BARTELS PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10804
Location Zip Code 4: Not reported

Mailing Info:
Name: J B FRANKS
Contact: J B FRANKS
Address: 27 BARTELS PLACE
City/State/Zip: NEW ROCHELLE, NY 10804
Country: USA
Phone: 914-636-0570

J B & FRANKS (Continued) **1000100357**

Manifest:

Document ID:	NYA7038792
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	N23008
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/1989
Trans1 Recv Date:	12/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/07/1989
Part A Recv Date:	01/24/1990
Part B Recv Date:	12/18/1989
Generator EPA ID:	NYD986884732
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1989

ECHO:

Envid:	1000100357
Registry ID:	110004439705
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004439705

Y170 **ST GABRIEL SCHOOL** **NY LTANKS** **S105999147**
WNW **50 WASHINGTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.187 mi.
985 ft. **Site 2 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Site ID:	314440
Spill Number/Closed Date:	0302359 / 2003-12-12
Spill Date:	2003-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0

ST GABRIEL SCHOOL (Continued) **S105999147**

Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2003-12-12
Spiller Name:	LARRY
Spiller Company:	ST GABRIEL SCHOOL
Spiller Address:	50 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 12/12/03 ALSO REPORTED AS 03-05820. SEE THAT FILE FOR UPDATES. NFA THIS NUMBER."
Remarks:	""

Material:

Site ID:	314440
Operable Unit ID:	869188
Operable Unit:	01
Material ID:	506840
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	314440
Spill Tank Test:	1528429
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

Y171 **SAINT GABRIEL HIGH SCHOOL** **NY UST** **U003994885**
WNW **50 WASHINGTON AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.187 mi.
985 ft. **Site 3 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

WESTCHESTER CO. UST:

Id/Status:	3-058122 / Active
Operator Name:	Lawrence Baker
Owner Name:	Church of St. Gabriel
Owner Street:	120 Division Street
Owner Address2:	Not reported

SAINT GABRIEL HIGH SCHOOL (Continued) **U003994885**

Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	09/02/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	09/01/2003
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	7. Jacketed (tank)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	10. Flexible Piping
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Y172 **50 WASHINTON AVE** **NY LTANKS** **S105999773**
WNW **50 WASHINTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.187 mi.
985 ft. **Site 4 of 4 in cluster Y**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Site ID:	280324
Spill Number/Closed Date:	0305820 / 2003-12-23
Spill Date:	2003-09-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-09-02
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-02
Spill Record Last Update:	2004-01-08
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller County:	999
Spiller Contact:	MIGEL ROSARIO
Spiller Phone:	(914) 632-0211
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	227605
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 12/12/03 PREVIOUSLY REPORTED AS SPILL 03-02359. 12/26/03: Letter sent to Fr. Patrick V. McNamara, St Gabriel Church-Archdiocese NY from Wayne Schneider, WCDOH dated 23Dec2003. Closure report has been reviewed. WCDOH recommends NFAA at this time."
	Not reported
Remarks:	"ST GABRIELS CHURCH - FR PATRICK MCNAMARA WOULD LIKE A CALL HE CAN BE REACHED AT 914-632-0211 THE CHURCH IS RESPONSIBLE FOR THE SPILL "

Material:

Site ID:	280324
Operable Unit ID:	874264
Operable Unit:	01
Material ID:	503057
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

50 WASHINTON AVE (Continued) **S105999773**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

V173 **CON EDISON** **NY MANIFEST** **S117535594**
SSW **HUGENOT AVE & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 3 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:
EPA ID: NYP004677621
Country: USA
Location Address 1: HUGENOT AVE & COLUMBUS AVE
Location Address 2: MH 3424
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/15/2014
Trans1 Recv Date: 10/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677621
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012774907JJK
Import Ind: N

CON EDISON (Continued) **S117535594**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

V174 **CON EDISON** **NY MANIFEST** **S117536317**
SSW **HUGUENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.188 mi.
990 ft. **Site 4 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

EPA ID:	NYP004687802
Country:	USA
Location Address 1:	HUGUENOT ST & COLUMBUS AVE
Location Address 2:	MH 3424
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2014
Trans1 Recv Date:	10/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004687802
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117536317**

Year:	2014
Manifest Tracking Num:	012773160JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

V175 **CON EDISON** **NY MANIFEST** **S117535600**
SSW **HUGENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 5 of 5 in cluster V**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

EPA ID:	NYP004677837
Country:	USA
Location Address 1:	HUGENOT ST & COLUMBUS AVE
Location Address 2:	MH 3424
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677837
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S117535600**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774864JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

X176 **FURNITURE RESTORNATION CENTER** **RCRA NonGen / NLR** **1000872286**
NNE **26 GARDEN ST** **FINDS** **NYD987034998**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.188 mi. **ECHO**
993 ft. **Site 2 of 2 in cluster X**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FURNITURE RESTORNATION CENTER
Facility address:	26 GARDEN ST NEW ROCHELLE, NY 108014204
EPA ID:	NYD987034998
Mailing address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 633-9292
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Owner/operator telephone: (914) 633-9292
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 06/02/1993
Site name: FURNITURE RESTORNATION CENTER
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/02/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004505287

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD987034998
Country: USA
Location Address 1: 26 GARDEN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: FURNITURE RESTORATION OF NEW ROCHELLE
Contact: HENRY FLAVIC
Address: 166 WEBSTER AVE
City/State/Zip: NEW ROCHELLE, NY 10801 6111
Country: USA
Phone: 914-592-3132

Manifest:

Document ID: NYG1592532
Manifest Status: Not reported
Trans1 State ID: AE53110PA
Trans2 State ID: Not reported
Generator Ship Date: 07/06/2000
Trans1 Recv Date: 07/06/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: PAD987358587
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Quantity:	00935
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	017
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYG1592451
Manifest Status:	Not reported
Trans1 State ID:	AB92108PA
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/1999
Trans1 Recv Date:	12/29/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported
TSDF ID:	OHD066060609
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	MAK4973810
Manifest Status:	Not reported
Trans1 State ID:	MA14654
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/1998
Trans1 Recv Date:	06/10/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/10/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	SCD987574647
Trans2 EPA ID:	Not reported
TSDF ID:	MAD000604447
Waste Code:	F001 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F001 - UNKNOWN
Quantity: 00495
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 016
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F001 - UNKNOWN
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1998

Document ID: NYB7459911
Manifest Status: Not reported
Trans1 State ID: 50059
Trans2 State ID: Not reported
Generator Ship Date: 08/17/1999
Trans1 Recv Date: 08/17/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/27/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: NJD986607380
Trans2 EPA ID: Not reported
TSDF ID: OHD066060609
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00475
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 1999

Document ID: NYB7459101
Manifest Status: Not reported
Trans1 State ID: 50059
Trans2 State ID: Not reported
Generator Ship Date: 04/08/1999
Trans1 Recv Date: 04/08/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/14/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987034998
Trans1 EPA ID: NJD986607380

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Trans2 EPA ID:	Not reported
TSDF ID:	OHD980681571
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

ECHO:

Envid:	1000872286
Registry ID:	110004505287
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004505287

W177 **DIIORGI HOME** **NY LTANKS** **S106869098**
WSW **47 WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.189 mi.
999 ft. **Site 3 of 4 in cluster W**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	343230
Spill Number/Closed Date:	0500295 / 2005-08-28
Spill Date:	2005-04-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2005-08-28
Spiller Name:	ANTHONY DIIORGI
Spiller Company:	DIIORGI HOME
Spiller Address:	47 WARREN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

DIIORGI HOME (Continued) **S106869098**

Spiller Contact: ANTHONY DIIORGI
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 289715
DEC Memo: "August 28, 2005: GC RELIABLE REMOVED LUST AND CONTAMINATED SOIL. NORTHEST ENVIRONMENTAL DISPOSED OF 18 DRUMS OF SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "SHE WILL CALLL BACK WITH MORE INFO:"

Material:
Site ID: 343230
Operable Unit ID: 1101915
Operable Unit: 01
Material ID: 582154
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

U178 **CON EDISON MANHOLE: 4179** **RCRA NonGen / NLR 1016969613**
North **350 NORTH AVE** **NY MANIFEST NYP004432886**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1018 ft. **Site 3 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/04/2014
Facility name: CON EDISON MANHOLE: 4179
Facility address: 350 NORTH AVE
NEW ROCHELLE, NY 10805
EPA ID: NYP004432886
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/04/2014
Site name:	CON EDISON MANHOLE: 4179
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

EPA ID:	NYP004432886
Country:	USA
Location Address 1:	OPP 350 NORTH AVE
Location Address 2:	MH4179
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PLACE
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004432886
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	011692716JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AB179 **CON EDISON** **RCRA NonGen / NLR** **1014398214**
SW **35 BARTELS PL** **NY MANIFEST** **NYP004205654**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.193 mi.
1020 ft. **Site 2 of 5 in cluster AB**

Relative:
Lower

Actual:
67 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2010
Facility name:	CON EDISON
Facility address:	35 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004205654
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	PATRICK HANLEY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(347) 203-1475
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON (Continued) **1014398214**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004205654
Country: USA
Location Address 1: 35 BARTELS PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/19/2010
Trans1 Recv Date: 04/19/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/19/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004205654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 15.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 002012659FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

CON EDISON (Continued) **1014398214**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

AB180 **CON EDISON** **NY MANIFEST** **S117741191**
SW **35 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 3 of 5 in cluster AB**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:
EPA ID: NYP004744074
Country: USA
Location Address 1: 35 BARTELS PL
Location Address 2: DRIP WATER
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/16/2015
Trans1 Recv Date: 03/16/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/18/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 3
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683647FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

CON EDISON (Continued) **S117741191**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683633FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2015
Trans1 Recv Date:	03/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939

CON EDISON (Continued) **S117741191**

Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683630FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2015
Trans1 Recv Date:	03/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	20
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683625FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

CON EDISON (Continued) **S117741191**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2015
Trans1 Recv Date:	03/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	2
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683620FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2015
Trans1 Recv Date:	03/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	4
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117741191**

Year:	2015
Manifest Tracking Num:	008683616FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683680FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/16/2015
Trans1 Recv Date:	03/16/2015

CON EDISON (Continued) **S117741191**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	3
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683647FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683633FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

CON EDISON (Continued) **S117741191**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/06/2015
Trans1 Recv Date: 03/06/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 1
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683630FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/05/2015
Trans1 Recv Date: 03/05/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S117741191**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	20
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683625FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2015
Trans1 Recv Date:	03/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000705939
Waste Code:	Not reported
Quantity:	2
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683620FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S117741191**

Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2015
Trans1 Recv Date: 03/10/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 4
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008683616FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/28/2015
Trans1 Recv Date: 03/28/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/30/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744074
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 1
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1

CON EDISON (Continued) **S117741191**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008683680FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H135

AC181 **BARRAGAN RESIDENCE** **NY LTANKS** **S105230135**
WSW **40 WARREN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.194 mi.
1022 ft. **Site 1 of 7 in cluster AC**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	150939
Spill Number/Closed Date:	0109254 / 2001-12-19
Spill Date:	2001-12-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2001-12-19
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-19
Spill Record Last Update:	2002-01-03
Spiller Name:	Not reported
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	MALLARDI RES
Spiller Phone:	(914) 636-7448
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128278
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "

BARRAGAN RESIDENCE (Continued) **S105230135**

Remarks: "DRIVER OVERFILLED TANK - SPILL CONTAINED WITH PADS - CLEAN UP CREW ENROUTE"

Material:

Site ID:	150939
Operable Unit ID:	846633
Operable Unit:	01
Material ID:	530463
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	409713
Spill Number/Closed Date:	0812107 / 2009-03-03
Spill Date:	2009-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-06
Spill Record Last Update:	2009-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	359905
DEC Memo:	"Piping failure, need to repair and retest - mm 02/20/2009 Passed retest results that came into PBS to J. O'Dee---BHY 3/3/09: Review of

BARRAGAN RESIDENCE (Continued) **S105230135**

report submitted by WCC Tank Technology. Tank was tested by WCC on 1-9-09 for the property owner. The tank passed the test and documentation was submitted to the owner and the New Rochelle FD. Elite Environmental tested the tank for a prospective buyer on 2-6-09 and failed the tank, resulting in this spill report to the DEC. On 2-12-09 WCC again tested the tank with reps from New Rochelle FD and Royal Environmental. The tank passed this test. All three tests were preformed with the Horner Locator Plus system. Based upon the information received as of this date, DEC is requiring No Further Action at this time. jod"

Remarks: "550 gal tank failed test/ failure due to bad fitting"

Material:

Site ID:	409713
Operable Unit ID:	1166213
Operable Unit:	01
Material ID:	2157665
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0908848
Facility Type:	ER
DER Facility ID:	128278
Site ID:	421508
DEC Region:	3
Spill Date:	2009-11-06
Spill Number/Closed Date:	0908848 / 2010-04-08
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-06

BARRAGAN RESIDENCE (Continued) **S105230135**

Spill Record Last Update:	2010-04-08
Spiller Name:	GABREILLE BARRAGAN
Spiller Company:	GABREILLE BARRAGAN
Spiller Address:	40 WARREN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	NIKKI RICKETTS
Contact Phone:	(914) 777-1930
DEC Memo:	"11/06/09: Property was purchased by a new owner within the past year. New owner passed away, his wife was having the tank replaced for sale of the property. Northeast installed a new AST in the basement and pulled this 1K tank. Contamination evident. New Rochelle FD inspected. Northeast will be completing clean up. jod 02/09/10 Northeast Environmental reported that they excavated and removed one tank along with 35.64 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG"
Remarks:	"REMOVAL OF A 1000 GALLON UST SOIL CONTAMINATION FOUND CLEAN UP PENDING."

Material:

Site ID:	421508
Operable Unit ID:	1177396
Operable Unit:	01
Material ID:	2170184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AD182 **CON EDISON TRANSFORMER MANHOLE: 5365** **RCRA NonGen / NLR** **1016972665**
SSW **595 MAIN ST** **NY MANIFEST** **NYP004464459**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.196 mi.
1035 ft. **Site 1 of 5 in cluster AD**

Relative:
Higher

Actual:
93 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/12/2014
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5365
Facility address:	595 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004464459
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/12/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 5365
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004464459
Country: USA
Location Address 1: 595 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10804
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING ST
Address 2: 15TH ST
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/12/2014
Trans1 Recv Date: 03/12/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/12/2014

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004464459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012771156JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AB183 **RUSH MFG CORP** **RCRA NonGen / NLR** **1000238316**
SSW **18 COLUMBUS AVE** **FINDS** **NYD981185051**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.200 mi. **ECHO**
1054 ft. **Site 4 of 5 in cluster AB**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RUSH MFG CORP
Facility address:	18 COLUMBUS AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD981185051
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact:	DENNIS MCNAMARA
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 636-2700
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212

RUSH MFG CORP (Continued) **1000238316**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MATTHEW RUSH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MFG CORP
Classification: Not a generator, verified

Date form received by agency: 03/03/1986
Site name: RUSH MFG CORP
Classification: Small Quantity Generator

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Violation Status: No violations found

FINDS:

Registry ID: 110002092967

Environmental Interest/Information System
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource

RUSH MFG CORP (Continued) **1000238316**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD981185051
Country:	USA
Location Address 1:	381 HUGUENOT STREET
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	RUSH MANUFACTURING CORPORATION
Contact:	RUSH MANUFACTURING CORPORATION
Address:	381 HUGUENOT STREET
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-236-2700

Manifest:

Document ID:	NJA2751945
Manifest Status:	Completed copy
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1997
Trans1 Recv Date:	12/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1997
Part A Recv Date:	01/15/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

Document ID:	NYA3088056
Manifest Status:	Completed copy
Trans1 State ID:	18946GL
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1986
Trans1 Recv Date:	05/13/1986

RUSH MFG CORP (Continued) **1000238316**

Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/13/1986
Part A Recv Date:	05/30/1986
Part B Recv Date:	05/29/1986
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1986

Document ID:	NYB7226073
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PR8562NY
Trans2 State ID:	24269SNY
Generator Ship Date:	10/08/1996
Trans1 Recv Date:	10/08/1996
Trans2 Recv Date:	10/14/1996
TSD Site Recv Date:	10/21/1996
Part A Recv Date:	10/22/1996
Part B Recv Date:	11/14/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NYD013277454
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2295832
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	050060
Trans2 State ID:	50060
Generator Ship Date:	12/30/1996
Trans1 Recv Date:	12/30/1996
Trans2 Recv Date:	12/30/1996
TSD Site Recv Date:	01/16/1997
Part A Recv Date:	/ /
Part B Recv Date:	02/03/1997
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN

RUSH MFG CORP (Continued) **1000238316**

Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2539813
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/1996
Trans1 Recv Date:	04/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/30/1996
Part A Recv Date:	04/29/1996
Part B Recv Date:	05/15/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00508
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2505461
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/1996
Trans1 Recv Date:	07/17/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/22/1996
Part A Recv Date:	07/31/1996
Part B Recv Date:	08/06/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00421
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

RUSH MFG CORP (Continued) **1000238316**

Document ID:	NYC3879944
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/1996
Trans1 Recv Date:	02/12/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/21/1996
Part A Recv Date:	/ /
Part B Recv Date:	03/04/1996
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	CTF0340411
Manifest Status:	Completed copy
Trans1 State ID:	ILP39038
Trans2 State ID:	Not reported
Generator Ship Date:	02/03/1995
Trans1 Recv Date:	02/03/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/06/1995
Part A Recv Date:	02/13/1995
Part B Recv Date:	02/15/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01018
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NYC2078559
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	P39038
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/1995
Trans1 Recv Date:	11/22/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/30/1995
Part A Recv Date:	12/08/1995

RUSH MFG CORP (Continued) **1000238316**

Part B Recv Date:	12/21/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	F001 - UNKNOWN
Quantity:	00844
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	CTF0477109
Manifest Status:	Completed copy
Trans1 State ID:	P188420
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/1995
Trans1 Recv Date:	07/27/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/03/1995
Part A Recv Date:	08/07/1995
Part B Recv Date:	08/18/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01018
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	CTF0477189
Manifest Status:	Completed copy
Trans1 State ID:	ILP39038
Trans2 State ID:	Not reported
Generator Ship Date:	05/05/1995
Trans1 Recv Date:	05/05/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/08/1995
Part A Recv Date:	05/15/1995
Part B Recv Date:	05/19/1995
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001

RUSH MFG CORP (Continued) **1000238316**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0476006
Manifest Status: Completed copy
Trans1 State ID: P39038IL
Trans2 State ID: Not reported
Generator Ship Date: 11/22/1995
Trans1 Recv Date: 11/22/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/27/1995
Part A Recv Date: 12/08/1995
Part B Recv Date: 12/12/1995
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01018
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0300971
Manifest Status: Completed copy
Trans1 State ID: P39038IL
Trans2 State ID: Not reported
Generator Ship Date: 06/03/1994
Trans1 Recv Date: 06/03/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 06/06/1994
Part A Recv Date: / /
Part B Recv Date: 06/17/1994
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01017
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1994

Document ID: CTF0341256
Manifest Status: Completed copy
Trans1 State ID: ILP39038

RUSH MFG CORP (Continued) **1000238316**

Trans2 State ID:	Not reported
Generator Ship Date:	11/04/1994
Trans1 Recv Date:	11/04/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/07/1994
Part A Recv Date:	11/14/1994
Part B Recv Date:	11/21/1994
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01017
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	CTF0232232
Manifest Status:	Completed copy
Trans1 State ID:	P39038ILL
Trans2 State ID:	T748NYNJ
Generator Ship Date:	12/16/1993
Trans1 Recv Date:	12/16/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/17/1993
Part A Recv Date:	12/27/1993
Part B Recv Date:	12/30/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD984908202
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	01017
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1993

Document ID:	NJA1501495
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPES28
Trans2 State ID:	Not reported
Generator Ship Date:	09/07/1993
Trans1 Recv Date:	09/07/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/07/1993
Part A Recv Date:	10/22/1993
Part B Recv Date:	10/04/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544

RUSH MFG CORP (Continued) **1000238316**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1993

Document ID:	CTF0147909
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/1993
Trans1 Recv Date:	04/07/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/13/1993
Part A Recv Date:	04/26/1993
Part B Recv Date:	04/23/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1993

Document ID:	CTF0317142
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	08/04/1993
Trans1 Recv Date:	08/04/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/06/1993
Part A Recv Date:	08/13/1993
Part B Recv Date:	08/20/1993
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F001 - UNKNOWN
Quantity:	00509
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

RUSH MFG CORP (Continued) **1000238316**

Year: 1993

Document ID: CTF0140731
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 01/06/1993
Trans1 Recv Date: 01/06/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 01/07/1993
Part A Recv Date: 01/15/1993
Part B Recv Date: 01/20/1993
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F001 - UNKNOWN
Quantity: 01018
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

Document ID: NJA1212610
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 02/26/1992
Trans1 Recv Date: 02/26/1992
Trans2 Recv Date: / /
TSD Site Recv Date: 03/03/1992
Part A Recv Date: 03/09/1992
Part B Recv Date: 03/18/1992
Generator EPA ID: NYD981185051
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F001 - UNKNOWN
Quantity: 00508
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1992

ECHO:
Envid: 1000238316
Registry ID: 110002092967
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002092967

W184 **NYNEX** **NY MANIFEST** **1009234555**
West **UNION AVENUE AND WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.201 mi.
1063 ft. **Site 4 of 4 in cluster W**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP000932509
Country:	USA
Location Address 1:	UNION AVENUE AND WARREN STREET
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NYNEX
Contact:	V ORCHIER
Address:	221 EAST 37TH STREET
City/State/Zip:	NEW YORK, NY 10016
Country:	USA
Phone:	212-338-7126

Manifest:

Document ID:	MIA4512835
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1996
Trans1 Recv Date:	12/17/1996
Trans2 Recv Date:	12/20/1996
TSD Site Recv Date:	01/03/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/23/1997
Generator EPA ID:	NYP000932509
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574
TSDF ID:	MID096963194
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1996

AD185 **CON EDISON TRANSFORMER MANHOLE: 2806** **RCRA NonGen / NLR** **1016962648**
South **592 MAIN ST** **NY MANIFEST** **NYP004357059**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.202 mi.
1066 ft. **Site 2 of 5 in cluster AD**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/09/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2806
Facility address:	592 MAIN ST NEW ROCHELLE, NY 10804

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

EPA ID: NYP004357059
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/09/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 2806
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004357059
Country: USA
Location Address 1: 592 MAIN ST.
Location Address 2: MH # 2806
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2013
Trans1 Recv Date:	09/09/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004357059
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	010707806JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

---

186 **CITIZEN** **NY LTANKS** **S100165790**
WSW **33 GROVE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.202 mi.
1067 ft.

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	135309
Spill Number/Closed Date:	8708588 / 1989-11-28
Spill Date:	1988-01-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-11-28
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported

CITIZEN (Continued) **S100165790**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-27
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	CAPT. FERGESON
Spiller City,St,Zip:	NEW ROCHELLE F.D., ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK RUPTURE IN CITIZEN'S BASEMENT. TANK TO BE EMPTIED."

Material:

Site ID:	135309
Operable Unit ID:	913258
Operable Unit:	01
Material ID:	463968
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	550.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AE187 **THE MALL** **NY LTANKS** **S100141913**
East **MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.204 mi.
1079 ft. **Site 1 of 4 in cluster AE**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Site ID:	326514
Spill Number/Closed Date:	9010648 / 1991-01-04
Spill Date:	1991-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-01-04
CID:	Not reported

THE MALL (Continued) **S100141913**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-10
Spill Record Last Update:	1992-07-31
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	263025
DEC Memo:	"Administratively closed due to file review and/or information received. If new information arises to contradict this determination DEC reserves the right to reopen this spill without prejudice. Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WATER FOUND IN TANK TO BE PUMPED OUT HONER EASY -.087"

Material:

Site ID:	326514
Operable Unit ID:	947782
Operable Unit:	01
Material ID:	430787
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	326514
Spill Tank Test:	1538129
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AF188 **175 MEMORIAL HWY. REALTY, INC.** **NY UST** **U003994239**
NW **175 MEMORIAL HWY.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.204 mi.
1079 ft. **Site 1 of 2 in cluster AF**

Relative:
Higher

Actual:
85 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800711 / Unregulated: <1101 gal. PBS
Operator Name:	A. Langhitano
Owner Name:	175 Memorial Hwy. Realty, Inc.
Owner Street:	175 Memorial Hwy.
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10802
GDS Number:	Not reported
Tank Number:	175-1
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AG189 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1017773973**
South **CENTRE AVE & LEROY** **FINDS** **NYP004517694**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1085 ft. **Site 1 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/30/2014
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	CENTRE AVE & LEROY NEW ROCHELLE, NY 10801
EPA ID:	NYP004517694
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/30/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063800506

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AG190 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1016973761**
South **LEROY PL & CENTER AVE** **NY MANIFEST** **NYP004475687**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.205 mi.
1085 ft. **Site 2 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/22/2014
Facility name: CON EDISON SERVICE BOX: 3313
Facility address: LEROY PL & CENTER AVE
NEW ROCHELLE, NY 10802
EPA ID: NYP004475687
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Contact:	THOMAS TEELING
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/22/2014
Site name:	CON EDISON SERVICE BOX: 3313
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004475687
Country:	USA
Location Address 1:	SEC LEROY & CENTRE AVE
Location Address 2:	SB3313
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING ST
Address 2:	15TH ST
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2014
Trans1 Recv Date:	03/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004475687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012772784JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AG191 **CON EDISON** **NY MANIFEST** **S117059593**
South **CENTRE AVE & LEROY** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1085 ft. **Site 3 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

EPA ID:	NYP004517694
Country:	USA
Location Address 1:	C/O CENTRE AVE & LEROY PL
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

CON EDISON (Continued) **S117059593**

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004517694
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012772797JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH192 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016970578**
SE **174 NORTH AVE** **NY MANIFEST** **NYP004442943**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1093 ft. **Site 1 of 11 in cluster AH**

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	174 NORTH AVE NEW ROCHELLE, NY 10804
EPA ID:	NYP004442943
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2014
Site name: CON EDISON SERVICE BOX: 2040
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004442943
Country: USA
Location Address 1: FO 174 NORTH AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2014

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004442943
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	011692698JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AI193 **SCHMUCKLER'S DRY CLEANERS** **NY BROWNFIELDS** **S107787044**
NNW **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.208 mi.
1098 ft. **Site 1 of 10 in cluster AI**

Relative:
Lower

Actual:
74 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	357446
Acres:	0.21
HW Code:	C360088
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/29/2005
Record Updated Date:	12/31/2015
Update By:	DACROSBY
Site Description:	Location: The Schmucklers Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. The site is 0.21 acres, most of which is covered by a two-story row building with a full basement. Site Features: In addition to the former dry cleaners, historically located on the first floor, the site also includes an enclosed backyard area to the immediate west of the building. The backyard is mostly covered by lawn, but also includes elevated vegetable beds, and a paved walkway. Current Zoning/Use(s): The site is commercially zoned, and currently has five commercial tenants occupying both the first and second floors. Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commerical uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

is provided from a municipal source.Past Uses of the Site: The building on-site was built in 1891, and operated by Schmucklers Cleaners from 1914 to 2006 on the first floor and basement of the building. Additions were added to the building in 1937, and two in 1987. The site was acquired by the Volunteer, HNJ Realty, LLC, in August 2005, and entered into a BCA in June 2006. An interim remedial measure (IRM) was conducted starting in late 2008 to install a combined soil vapor extraction system/sub-slab depressurization system (SVE/SSDS) in the former dry cleaner to mitigate PCE in indoor air. The IRM was deemed complete in December 2013, but the SVE/SSDS continues to operate. A second IRM work plan was approved in May 2015 to conduct a pilot study of an enhanced biological in situ treatment to remediate contaminants under the on-site building slab. Site Geology and Hydrogeology: The site is underlain by historic fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater at the site flows in a southeasterly direction. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater.

Env Problem:

Based on the investigations conducted to date, the primary contaminants of concern at the site are chlorinated volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE) and its breakdown compounds, in soils, groundwater, sub-slab vapor, and soil gas; petroleum-related VOCs in soils, groundwater, sub-slab vapor, and soil gas; and semi-volatile organic compounds (SVOCs) in groundwater. Soils: Tetrachloroethylene (PCE), trichloroethene (TCE), and multiple petroleum related VOCs were detected in onsite soils underneath the building slab. The highest concentration of PCE at 210 parts per million (ppm), exceeding restricted commercial soil cleanup objectives (SCOs), was located underneath the former dry cleaning equipment room. Other contaminants detected in soils only exceeded the Protection of Groundwater SCOs. These exceedences were largely in soils located downgradient of the dry cleaning equipment room and consisted of: TCE at 1.3 ppm, cis-1,2 dichloroethene (cis-1,2-DCE) at 3 ppm, n-propylbenzene at 16 ppm, m+p xylenes at 15 ppm, ethylbenzene at 6.6 ppm, 1,3,5-trimethylbenzene at 63 ppm, and 1,2,4-trimethylbenzene at 99 ppm. Groundwater: Petroleum-based floating product (LNAPL, or light non-aqueous phase liquid) was observed in groundwater under much of the on-site building slab, a maximum of 6 inches thick under the former dry cleaning equipment room. Also observed were very high concentrations of select VOCs also under the former drycleaning equipment room. The maximum detected PCE was 830,000 parts per billion (ppb), and TCE at 58,000 ppb, indicating the presence of these compounds as free product DNAPLs (dense non-aqueous phase liquid) in groundwater. 25 individual VOCs were also detected in site groundwater samples exceeding NYS Class GA groundwater standards. These include the above-mentioned PCE, TCE, as well as other maximum detected concentrations of PCE breakdown products: cis-1,2-DCE at 8,700 ppb, and vinyl chloride at 28 ppb. BTEX was detected, with benzene at 62 ppb, toluene at 130 ppb, ethylbenzene at 150 ppb, m+p xylene at 520 ppb, and o-xylene at 290 ppb. Other significant concentrations of VOCs detected in groundwater include 1,3,5-trimethylbenzene at 890 ppb, and 1,2,4-trimethylbenzene at 840 ppb. Eight SVOCs were detected over groundwater standards in

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

groundwater under the building slab, including napthalene at a concentration of 1300 ppb, phenanthrene at 2400 ppb, acenapthene at 710 ppb, and antracene at 280 ppb. Bedrock wells were installed off-site in the downgradient, sidegradient, and upgradient directions. Petroleum-based VOCs and SVOCs were detected in the bedrock aquifer at concentrations above groundwater standards. For VOCs, total maximum BTEX concentration of 722 ppb was detected in a downgradient bedrock well. 11 individual SVOC contaminants were detected over groundwater standards in the same downgradient off-site bedrock well, including naphthalene at 4100 ppb, phenanthrene at 2800 ppb, acenapthene at 710 ppb, and antracene at 300 ppb.The extent of groundwater contamination is concentrated underneath the on-site building slab, with petroleum-based VOC and SVOC contaminants and LNAPL extending off-site in the bedrock downgradient or southeast direction. Soil Gas/Soil Vapor: The high concentrations of PCE (787,000 ug/m3), TCE (15,200 ug/m3), cis-1,2-DCE (46,000 ug/m3), and Vinyl Chloride (34 ug/m3) in soil vapor under the slab of the on-site building required the installation and continuing operation of a combined soil vapor extraction and sub-slab mitigation system during a 2008-2013 Interim Remedial Measure (IRM) action. PCE (at 91 ug/m3) and TCE (13.4 ug/m3) were also detected in soil gas outside of the building near the location of a former drywell. Benzene (37 ug/m3), toluene (126 ug/m3), ethylbenzene (85 ug/m3), xylene (555 ug/m3), 1,3,5-trimethylbenzene (3 ug/m3), and 1,2,4-trimethylbenzene (14 ug/m3) were also detected in subslab vapor and soil gas. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.

Health Problem: While direct contact with contaminants in the soil is unlikely because most contaminated soils are found beneath the on-site building, persons who dig below the ground surface adjacent to the building may come into contact with contaminants in subsurface soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. A sub-slab depressurization system was installed in the on-site building to prevent vapors beneath the slab from entering the building. Sampling indicates soil vapor intrusion is not a concern in one adjacent off-site building. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for other nearby off-site buildings.

AI194 **MAYCO, LLC** **NY AST** **A100252337**
NNW **18-20 MAY ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.211 mi.
1115 ft. **Site 2 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

WESTCHESTER CO. AST:

PBS Number:	3-175447
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Alex Hay
Owner Name:	Mayco, LLC
Owner Street:	P.O. Box 1755
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10156
Tank Number:	1

MAYCO, LLC (Continued) **A100252337**

Status:	1. In-Service
Date Installation:	01/01/1980
Capacity:	4000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

AJ195 **NEW ROCHELLE HOSPITAL** **NY LTANKS** **S100141273**
NW **COVION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.211 mi.
1116 ft. **Site 1 of 5 in cluster AJ**

Relative:
Higher

Actual:
102 ft.

LTANKS:

Site ID:	136814
Spill Number/Closed Date:	9003911 / 1991-03-15
Spill Date:	1990-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	1991-04-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

DER Facility ID: 117069
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/15/91: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks: "WILL EIR PBS TO FOLLOW AINLEY +.094"

Material:
Site ID: 136814
Operable Unit ID: 941734
Operable Unit: 01
Material ID: 435036
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 136814
Spill Tank Test: 1537277
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

AI196 **SCHMUCKLERS CLEANERS** **RCRA-CESQG** **1000303485**
NNW **360 NORTH AVE** **NY MANIFEST** **NYD012950770**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1117 ft. **Site 3 of 10 in cluster AI**

Relative:
Lower

Actual:
75 ft.

RCRA-CESQG:
Date form received by agency: 03/31/2008
Facility name: SCHMUCKLERS CLEANERS
Facility address: 360 NORTH AVE
NEW ROCHELLE, NY 10801
EPA ID: NYD012950770
Mailing address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact: HAL I SHAPIRO
Contact address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Contact country: US
Contact telephone: (917) 693-9019
Contact email: HALSHAP@GMAIL.COM
EPA Region: 02
Land type: Private

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: HNJ REALTY LLC
Owner/operator address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2005
Owner/Op end date: Not reported

Owner/operator name: HNJ REALTY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D007
. Waste name: CHROMIUM

SCHMUCKLERS CLEANERS (Continued) **1000303485**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 03/30/2008
Site name: SCHMUCKLERS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: SCHMUKLERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/09/1998
Site name: SCHMUKLERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 10/29/1993

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Site name: SCHMUKLERS
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(3)
Area of violation: Generators - General
Date violation determined: 09/08/2003
Date achieved compliance: 09/18/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/18/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/20/1999
Date achieved compliance: 09/08/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/08/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 09/08/2003
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYD012950770
Country: USA
Location Address 1: 360 NORTH AVENUE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: SHMUCKLERS DRY CLEANERS
Contact: SHMUCKLERS DRY CLEANERS
Address: 360 NORTH AVENUE
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-632-2705

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 06/11/2015
Trans1 Recv Date: 06/12/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/29/2015
Part A Recv Date: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987270725
Waste Code:	Not reported
Quantity:	691
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006197558FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H039

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	2100.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Quantity:	1600.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD000692061
Generator Ship Date:	05/15/2008
Trans1 Recv Date:	05/15/2008
Trans2 Recv Date:	05/28/2008
TSD Site Recv Date:	05/30/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	60.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000136111SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2015
Trans1 Recv Date:	06/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987270725
Waste Code:	Not reported
Quantity:	691
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	006197558FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H039

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	02/09/2007
Trans1 Recv Date:	02/09/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	12
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Year:	2007
Manifest Tracking Num:	000461860SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/15/2007
Trans1 Recv Date:	05/15/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587364
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000472131SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	NYC7242423
Manifest Status:	Not reported
Trans1 State ID:	NY49555JE
Trans2 State ID:	T465GLNJ
Generator Ship Date:	08/05/2004
Trans1 Recv Date:	08/05/2004

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans2 Recv Date:	08/11/2004
TSD Site Recv Date:	08/16/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7301520
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	T364DANJ
Generator Ship Date:	01/20/2004
Trans1 Recv Date:	01/20/2004
Trans2 Recv Date:	01/28/2004
TSD Site Recv Date:	01/29/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7145853

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	044AE381M
Generator Ship Date:	01/07/2004
Trans1 Recv Date:	01/07/2004
Trans2 Recv Date:	01/14/2004
TSD Site Recv Date:	01/15/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7146044
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	NJ044T468
Generator Ship Date:	05/21/2004
Trans1 Recv Date:	05/21/2004
Trans2 Recv Date:	05/26/2004
TSD Site Recv Date:	05/27/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00330
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7228765
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans2 State ID:	T39K7HNJ
Generator Ship Date:	07/14/2004
Trans1 Recv Date:	07/14/2004
Trans2 Recv Date:	07/21/2004
TSD Site Recv Date:	07/22/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC7198380
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	T853MVNJ
Generator Ship Date:	04/02/2004
Trans1 Recv Date:	04/02/2004
Trans2 Recv Date:	04/07/2004
TSD Site Recv Date:	04/08/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Document ID:	NYC7576920
Manifest Status:	Not reported
Trans1 State ID:	NY49455JC
Trans2 State ID:	NJT27L8D
Generator Ship Date:	12/22/2004
Trans1 Recv Date:	12/22/2004
Trans2 Recv Date:	12/29/2004
TSD Site Recv Date:	12/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00440
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NYC6976811
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	FT97358CA
Generator Ship Date:	04/17/2003
Trans1 Recv Date:	04/17/2003
Trans2 Recv Date:	04/23/2003
TSD Site Recv Date:	04/24/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7043872
Manifest Status:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Trans1 State ID:	NYCR3164
Trans2 State ID:	T854MWNJ
Generator Ship Date:	06/10/2003
Trans1 Recv Date:	06/10/2003
Trans2 Recv Date:	06/18/2003
TSD Site Recv Date:	06/19/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC6983008
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	T2L230NJ
Generator Ship Date:	02/21/2003
Trans1 Recv Date:	02/21/2003
Trans2 Recv Date:	02/26/2003
TSD Site Recv Date:	02/27/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Year: 2003

Document ID: NYC7019357
Manifest Status: Not reported
Trans1 State ID: NYCR3164
Trans2 State ID: T25L8DNJ
Generator Ship Date: 01/22/2003
Trans1 Recv Date: 01/22/2003
Trans2 Recv Date: 01/29/2003
TSD Site Recv Date: 01/30/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012950770
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00220
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7150318
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: T83G9TNJ
Generator Ship Date: 11/04/2003
Trans1 Recv Date: 11/04/2003
Trans2 Recv Date: 11/12/2003
TSD Site Recv Date: 11/13/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012950770
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00090
Units: P - Pounds
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

AI197 **SCHMUKLER'S CLEANERS** **NY DRYCLEANERS** **S110247878**
NNW **360 NORTH AVE.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1117 ft. **Site 4 of 10 in cluster AI**

Relative:
Lower

Actual:
75 ft.

DRYCLEANERS:

Facility ID:	3-5510-00327
Phone Number:	914-632-2705
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	07NOV13
Install Date:	98/06
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AE198 **NEW ROCHELLE MALL** **NY UST** **U003857279**
East **425 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.212 mi.
1118 ft. **Site 2 of 4 in cluster AE**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600042 / Unregulated: <1101 gal. PBS
Operator Name:	Unknown
Owner Name:	New Roc Associates
Owner Street:	30 Glenn St.
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10603
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	15000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	05/26/1998
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AJ199 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **NY UST** **U003857945**
NW **16 GUION PLACE** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1143 ft. **Site 2 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Id/Status:	3-123269 / Active
Operator Name:	Thomas Irving
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10467
GDS Number:	Not reported
Tank Number:	2 day
Status:	4. Closed - in place
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1978
Date Perm Closure:	Not reported
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	4
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	07/01/1996
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Tank Number:	5
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1981
Date Perm Closure:	07/19/2006
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5B
Status:	1. In-Service
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	07/01/2006
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	8. Wrapped (Piping)
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	8
Status:	1. In-Service
Capacity:	3000
Product Stored:	6. Diesel
Product Stored Percent:	0
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	10/22/2010
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	10. Urethane clad steel
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	plastic sleeve
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-123269
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Thomas Irving
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10467
Tank Number:	# 8 Day
Status:	1. In-Service
Date Installation:	10/22/2010
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	04
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	2000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1996
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	other
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	99. Other

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	5. Closed - removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 day
Status:	1. In-Service
Date Installation:	06/01/1976
Capacity:	25
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	9. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	5. Closed - removed
Date Installation:	12/01/1967
Capacity:	16000

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1971
Capacity:	30000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3 day
Status:	1. In-Service
Date Installation:	07/01/1980
Capacity:	50
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	5. Closed - removed
Date Installation:	12/01/1981
Capacity:	500
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	9. Copper
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	12/01/2005
Capacity:	700
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/2016

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Capacity:	10000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	7. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AJ200 **SOUND SHORE MEDICAL CENTER** **PA MANIFEST** **S111771577**
NW **16 GUION PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1143 ft. **Site 3 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

Manifest Details:

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U188
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AJ201 **SOUTH SHORE MED CENTER** **NY LTANKS** **S107523501**
NW **16 GUION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1143 ft. **Site 4 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	358758
Spill Number/Closed Date:	0512440 / 2006-12-19
Spill Date:	2006-01-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

SOUTH SHORE MED CENTER (Continued) **S107523501**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-01-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2006-12-22
Spiller Name:	VERONICA
Spiller Company:	SOUND SHORE MED CENTER
Spiller Address:	16 GUION PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	VERONICA
Spiller Phone:	(201) 489-8700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308757
DEC Memo:	"Tank removed, no contamination found. NFA jod 12/22/06 - Letter from Wayne Schneider of WCDOD dated 8/29/06 addressed to Dir. of Engr., Sound Shore Medical Center, has requested NYSDEC to colose this spill #."
Remarks:	"Tank test failure. Ullage leak was detected."

Material:

Site ID:	358758
Operable Unit ID:	1115985
Operable Unit:	01
Material ID:	2106096
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	358758
Spill Tank Test:	1549678
Tank Number:	5
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported

SOUTH SHORE MED CENTER (Continued) **S107523501**

Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AJ202 **SOUND SHORE MEDICAL CENTER** **RCRA-SQG** **1000130172**
NW **16 GUION PL** **FINDS** **NYD075431502**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.216 mi. **ECHO**
1143 ft. **Site 5 of 5 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

RCRA-SQG:
Date form received by agency: 10/31/2013
Facility name: SOUND SHORE MEDICAL CENTER
Facility address: 16 GUION PL
NEW ROCHELLE, NY 10802
EPA ID: NYD075431502
Mailing address: GUION PL
NEW ROCHELLE, NY 10802
Contact: GARRETT T DOERING
Contact address: E 210TH ST
BRONX, NY 10467
Contact country: US
Contact telephone: (717) 920-7600
Contact email: GDOREING@MONTEFIORE.ORG
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 632-5000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: (914) 632-5000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: (914) 378-6300
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/01/2013
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175
YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: (914) 378-6300
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-MET OXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U170
. Waste name: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Historical Generators:
Date form received by agency: 01/01/2007
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/08/1997
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/11/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004368620

Environmental Interest/Information System

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

COMPLIANCE AND EMISSIONS REPORTING

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD075431502
Country:	USA
Location Address 1:	16 GUION PLACE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SOUND SHORE MEDICAL CENTER
Contact:	NEW ROCHELLE HOSPITAL
Address:	16 QUINN PLACE
City/State/Zip:	NEW ROCHELLE, NY 10802
Country:	USA
Phone:	914-632-5000

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	05/19/2015
TSD Site Recv Date:	05/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	31
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213253FLE

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	07/14/2015
TSD Site Recv Date:	07/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	96
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008212114FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	07/21/2015
Trans1 Recv Date:	07/21/2015
Trans2 Recv Date:	07/28/2015
TSD Site Recv Date:	07/30/2015

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	111
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008229168FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	09/08/2015
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	66
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915668FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	09/08/2015
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	19
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915668FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	08/18/2015
Trans1 Recv Date:	08/18/2015
Trans2 Recv Date:	08/25/2015
TSD Site Recv Date:	08/27/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Waste Code:	Not reported
Quantity:	67
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008915884FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	09/15/2015
Trans1 Recv Date:	09/15/2015
Trans2 Recv Date:	09/22/2015
TSD Site Recv Date:	09/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD985073196
Waste Code:	Not reported
Quantity:	96
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008938471FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2015
Trans1 Recv Date:	02/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	31
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007885181FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	03/03/2015
Trans1 Recv Date:	03/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	35
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Year:	2015
Manifest Tracking Num:	008210510FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	14
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008210971FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	16
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211044FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2015
Trans1 Recv Date:	04/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	27
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211112FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2015
Trans1 Recv Date:	04/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	68
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211204FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2015
Trans1 Recv Date:	04/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	42
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008211204FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	13
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008212115FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAC300016672
Trans2 State ID: Not reported
Generator Ship Date: 07/07/2015
Trans1 Recv Date: 07/07/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075431502
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 22
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 008212115FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAC300016672
Trans2 State ID: Not reported
Generator Ship Date: 06/09/2015
Trans1 Recv Date: 06/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/10/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075431502
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 35
Units: P - Pounds
Number of Containers: 1

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213009FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2015
Trans1 Recv Date:	05/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213269FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	33
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213288FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	008213288FLE
Import Ind:	N

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

ECHO:

Envid:	1000130172
Registry ID:	110004368620
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004368620

203
West
1/8-1/4
0.217 mi.
1145 ft.

RESIDENCE **NY LTANKS** **S107489339**
79 WARREN ST **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	356553
Spill Number/Closed Date:	0510555 / 2006-03-28
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-28
Spiller Name:	ISHMAL GALVIN
Spiller Company:	RESIDENCE
Spiller Address:	79 WARREN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	ISHMAL GALVIN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306611
DEC Memo:	"March 28, 2006: GRAZI-1 CORP DISPOSED OF LUST AND 67.95 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER

RESIDENCE (Continued) **S107489339**

ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Tank removal, tank size 550 gallons"

Material:
Site ID: 356553
Operable Unit ID: 1113853
Operable Unit: 01
Material ID: 2103913
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AF204 **66 MEMORIAL BLVD** **NY LTANKS** **S104621761**
NW **66 MEMORIAL BLVD** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.217 mi.
1146 ft. **Site 2 of 2 in cluster AF**

Relative:
Higher

Actual:
90 ft.

LTANKS:
Site ID: 59397
Spill Number/Closed Date: 0002907 / 2000-10-24
Spill Date: 2000-06-08
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2000-06-08
CID: 389
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-06-08
Spill Record Last Update: 2000-11-21
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller City,St,Zip: UNKNOWN, NY
Spiller County: 999
Spiller Contact: CALLER
Spiller Phone: Not reported

66 MEMORIAL BLVD (Continued) **S104621761**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 58153
DEC Memo: ""
Remarks: "caller reporting a spill of material from a tank being hit while escavating land for a basement. no callback is necessary caller is anaymous. clena up is being done at this time."

Material:
Site ID: 59397
Operable Unit ID: 824416
Operable Unit: 01
Material ID: 551247
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: Gallons
Recovered: 10.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AK205 **LEXINGTON CENTER FOR RECOVERY INC** **NJ MANIFEST** **S117987423**
NNE **3 COTTAGE PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1147 ft. **Site 1 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:
EPA Id: NYR000193854
Mail Address: COTTAGE PL
Mail City/State/Zip: NEW ROCHELLE, NY 10801
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: LISA OBRIEN
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 008900746JJK
EPA ID: NYR000193854
Date Shipped: 5/25/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NY0001031814
Transporter 2 EPA ID: Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	30.00 Pounds

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	300.00 Pounds

AK206 **LEXINGTON CENTER FOR RECOVERY INC** **RCRA NonGen / NLR** **1014958140**
NNE **3 COTTAGE PL** **NY MANIFEST** **NYR000193854**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1147 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/27/2012
Facility name:	LEXINGTON CENTER FOR RECOVERY INC
Facility address:	3 COTTAGE PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000193854
Mailing address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact:	LISA OBRIEN
Contact address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	(914) 235-6633
Telephone ext.:	1503
Contact email:	LOBRIEN@LEXINGTONCTR.ORG
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BARRY J JACOBSON
Owner/operator address:	E 40TH ST 8TH FL NEW YORK, NY 10016
Owner/operator country:	US
Owner/operator telephone:	(212) 889-7460
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/02/1983
Owner/Op end date:	Not reported
Owner/operator name:	LEXINGTON CENTER FOR RECOVERY INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/2008
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D009
. Waste name: MERCURY

Historical Generators:
Date form received by agency: 05/18/2012
Site name: LEXINGTON CENTER FOR RECOVERY INC
Classification: Large Quantity Generator

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/19/2014
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYR000193854
Country: USA
Location Address 1: 3 COTTAGE PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: LEXINGTON CENTER FOR RECOVERY INC
Contact: LEXINGTON CENTER FOR RECOVERY INC
Address: 3 COTTAGE PL
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA
Phone: 914-235-6633

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NY0001031814
Trans2 State ID: NJ0000027193
Generator Ship Date: 05/25/2012
Trans1 Recv Date: 05/25/2012
Trans2 Recv Date: 06/01/2012
TSD Site Recv Date: 06/06/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193854

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008900746JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NY0001031814
Trans2 State ID:	NJ0000027193
Generator Ship Date:	05/25/2012
Trans1 Recv Date:	05/25/2012
Trans2 Recv Date:	06/01/2012
TSD Site Recv Date:	06/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000193854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	30.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008900746JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

207
SE
1/8-1/4
0.219 mi.
1156 ft.

CON EDISON
46 CLINTON PL
NEW ROCHELLE, NY 10801

RCRA-CESQG **1012184999**
NY MANIFEST **NYP004157665**

Relative:
Higher

Actual:
91 ft.

RCRA-CESQG:

Date form received by agency:	04/01/2008
Facility name:	CON EDISON
Facility address:	46 CLINTON PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004157665
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1012184999**

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004157665
Country: USA
Location Address 1: 46 CLINTON PLACE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRAMKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/01/2008
Trans1 Recv Date: 04/01/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004157665
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD000705939
Waste Code: Not reported
Quantity: 180.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 6.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 002013408FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

AE208 **MONROE COLLEGE** **NY AST** **A100252339**
East **420 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.223 mi.
1179 ft. **Site 3 of 4 in cluster AE**

Relative:
Lower

Actual:
77 ft.

WESTCHESTER CO. AST:

PBS Number:	3-800251
Site Status:	Active
GDS Number:	Not reported
Operator Name:	James Moore
Owner Name:	Monroe College
Owner Street:	434 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	07/01/2004
Capacity:	3000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	0
Date Perm Closure:	04/13/2004
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity
Tank Number:	001old
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	04/13/2004
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	99. Other
Tank External Protection:	99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	99. Other
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	99. Other
Spill Prevention:	Not reported

MONROE COLLEGE (Continued) **A100252339**

Dispenser: 2. Suction

Tank Number: 1
Status: 0. Administratively closed
Date Installation: 01/01/1900
Capacity: 275
Product Stored: Not reported
Product Stored Percent: Not reported
Date Perm Closure: 11/06/2003
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

AD209 **CON EDISON** **NY MANIFEST** **S117535572**
SSW **MAIN ST & MAPLE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.226 mi.
1191 ft. **Site 3 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:
EPA ID: NYP004674354
Country: USA
Location Address 1: MAIN ST & MAPLE AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 10/07/2014
Trans1 Recv Date: 10/07/2014
Trans2 Recv Date: Not reported

CON EDISON (Continued) **S117535572**

TSD Site Recv Date:	10/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004674354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MAD053452637
Waste Code:	Not reported
Quantity:	559
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007747843FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AD210 **CON EDISON** **RCRA NonGen / NLR** **1014399091**
SSW **MAPLE AVE & MAIN ST** **NJ MANIFEST** **NYP004214680**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.226 mi.
1191 ft. **Site 4 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/01/2010
Facility name:	CON EDISON
Facility address:	MAPLE AVE & MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004214680
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(914) 925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

CON EDISON (Continued) **1014399091**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004214680
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DENNIS ROHRER
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 004086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/01/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 09/02/2010

CON EDISON (Continued) **1014399091**

TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 120 P

Manifest Number: 001086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/01/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 09/02/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported

CON EDISON (Continued) **1014399091**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 120 P

AD211 **CON EDISON MANHOLE: 734** **RCRA NonGen / NLR** **1016969502**
SSW **MAIN ST & MAPLE ST** **NY MANIFEST** **NYP004431706**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.226 mi.
1191 ft. **Site 5 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/01/2014
Facility name: CON EDISON MANHOLE: 734
Facility address: MAIN ST & MAPLE ST
NEW ROCHELLE, NY 10805
EPA ID: NYP004431706
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Date form received by agency: 02/01/2014
Site name: CON EDISON MANHOLE: 734
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004431706
Country: USA
Location Address 1: 591 MAIN ST
Location Address 2: MH 734
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/01/2014
Trans1 Recv Date: 02/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004431706
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 011696225JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AL212 **CONSOLIDATED EDISON - MH 1174** **NY MANIFEST** **S110709396**
NE **HUGUENOT ST & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1192 ft. **Site 1 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

NY MANIFEST:

EPA ID:	NYP004219572
Country:	USA
Location Address 1:	HUGUENOT ST & HARRISON ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CONSOLIDATED EDISON - MH 1174
Contact:	TOM TEELING
Address:	4 IRVING PLACE RM 828
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2010
Trans1 Recv Date:	11/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	006874917JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

CONSOLIDATED EDISON - MH 1174 (Continued) **S110709396**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AL213 **CON EDISON MANHOLE 1174** **RCRA NonGen / NLR** **1014918343**
NE **HUGEONOT ST & HARRISON ST** **NJ MANIFEST** **NYP004219570**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.226 mi.
1192 ft. **Site 2 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:
Date form received by agency: 12/04/2010
Facility name: CON EDISON MANHOLE 1174
Facility address: HUGEONOT ST & HARRISON ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004219570
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/04/2010
Site name: CON EDISON MANHOLE 1174
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004219570
Mail Address: IRVING PL RM 828

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874917JJK
EPA ID:	NYP004219570
Date Shipped:	11/04/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/04/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

AC214 **PREFERRED CLEANERS** **RCRA NonGen / NLR** **1000353766**
West **95 UNION AVE** **FINDS** **NYD050275254**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.226 mi. **ECHO**
1193 ft. **Site 2 of 7 in cluster AC**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PREFERRED CLEANERS
Facility address:	95 UNION AVE NEW ROCHELLE, NY 108016238
EPA ID:	NYD050275254
Mailing address:	UNION AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	UNION AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	(914) 472-6038
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	(914) 472-6038
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

PREFERRED CLEANERS (Continued) **1000353766**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 06/19/1995
Site name: PREFERRED CLEANERS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004357918

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

PREFERRED CLEANERS (Continued) **1000353766**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD050275254
Country:	USA
Location Address 1:	95 UNION AVENUE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	NEBRASKA CLEANERS
Contact:	NEBRASKA CLEANERS
Address:	95 UNION AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	914-636-4937

Manifest:

Document ID:	NYC3571378
Manifest Status:	Completed copy
Trans1 State ID:	GT9066
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1995
Trans1 Recv Date:	07/14/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/14/1995
Part A Recv Date:	/ /
Part B Recv Date:	07/25/1995
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00320
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

PREFERRED CLEANERS (Continued) **1000353766**

Document ID: NYA3828047
Manifest Status: Completed copy
Trans1 State ID: IL009
Trans2 State ID: Not reported
Generator Ship Date: 12/05/1986
Trans1 Recv Date: 12/05/1986
Trans2 Recv Date: / /
TSD Site Recv Date: 12/05/1986
Part A Recv Date: 12/16/1986
Part B Recv Date: 12/16/1986
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1986

Document ID: NYC3571604
Manifest Status: Completed copy
Trans1 State ID: NYGT9060
Trans2 State ID: Not reported
Generator Ship Date: 08/24/1995
Trans1 Recv Date: 08/24/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 08/24/1995
Part A Recv Date: / /
Part B Recv Date: 09/06/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: CTF0452797
Manifest Status: Completed copy
Trans1 State ID: NYLH7543
Trans2 State ID: Not reported
Generator Ship Date: 11/20/1995
Trans1 Recv Date: 11/20/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 11/27/1995
Part A Recv Date: / /

PREFERRED CLEANERS (Continued) **1000353766**

Part B Recv Date: 12/13/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: CTD001156009
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: NYC3341856
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 11/15/1994
Trans1 Recv Date: 11/15/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 11/15/1994
Part A Recv Date: 11/23/1994
Part B Recv Date: 11/28/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3289757
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 10/18/1994
Trans1 Recv Date: 10/18/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 10/18/1994
Part A Recv Date: 10/28/1994
Part B Recv Date: 10/27/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002

PREFERRED CLEANERS (Continued) **1000353766**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3062384
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1994
Trans1 Recv Date: 07/01/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 07/01/1994
Part A Recv Date: 07/14/1994
Part B Recv Date: 07/13/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC2928633
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 06/03/1994
Trans1 Recv Date: 06/03/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 06/03/1994
Part A Recv Date: 06/15/1994
Part B Recv Date: 06/13/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

PREFERRED CLEANERS (Continued) **1000353766**

Specific Gravity: 100
Year: 1994

Document ID: NYC3378047
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 12/12/1994
Trans1 Recv Date: 12/12/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 12/12/1994
Part A Recv Date: 01/09/1995
Part B Recv Date: 12/20/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC3241991
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 09/22/1994
Trans1 Recv Date: 09/22/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 09/22/1994
Part A Recv Date: 10/05/1994
Part B Recv Date: 10/03/1994
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

PREFERRED CLEANERS (Continued) **1000353766**

Document ID:	NYC1263071
Manifest Status:	Completed copy
Trans1 State ID:	DW9495-NY
Trans2 State ID:	Not reported
Generator Ship Date:	11/27/1991
Trans1 Recv Date:	11/27/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/27/1991
Part A Recv Date:	/ /
Part B Recv Date:	12/05/1991
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1991

Document ID:	NYC0617049
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	DW9495NY
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/1991
Trans1 Recv Date:	04/30/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/30/1991
Part A Recv Date:	06/10/1991
Part B Recv Date:	05/14/1991
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1991

Document ID:	NYA9519412
Manifest Status:	Completed copy

PREFERRED CLEANERS (Continued) **1000353766**

Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	11/21/1989
Trans1 Recv Date:	11/21/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/21/1989
Part A Recv Date:	12/11/1989
Part B Recv Date:	11/29/1989
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00080
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYC0546221
Manifest Status:	Completed copy
Trans1 State ID:	NJDEP8690
Trans2 State ID:	Not reported
Generator Ship Date:	11/15/1990
Trans1 Recv Date:	11/15/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/15/1990
Part A Recv Date:	12/06/1990
Part B Recv Date:	12/10/1990
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000708172
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00180
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

PREFERRED CLEANERS (Continued) **1000353766**

Year: 1990

Document ID: NYA5711589
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AV4489
Trans2 State ID: Not reported
Generator Ship Date: 11/23/1987
Trans1 Recv Date: 11/23/1987
Trans2 Recv Date: / /
TSD Site Recv Date: 11/23/1987
Part A Recv Date: 01/04/1988
Part B Recv Date: 11/27/1987
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD000805911
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1987

Document ID: NYA8779825
Manifest Status: Completed copy
Trans1 State ID: DW9495
Trans2 State ID: Not reported
Generator Ship Date: 12/15/1988
Trans1 Recv Date: 12/15/1988
Trans2 Recv Date: / /
TSD Site Recv Date: 12/15/1988
Part A Recv Date: 12/21/1988
Part B Recv Date: 12/22/1988
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080

PREFERRED CLEANERS (Continued) **1000353766**

Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1988

Document ID: NYC3462107
Manifest Status: Completed copy
Trans1 State ID: NYGT9066
Trans2 State ID: Not reported
Generator Ship Date: 02/03/1995
Trans1 Recv Date: 02/03/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 02/03/1995
Part A Recv Date: 02/17/1995
Part B Recv Date: 02/14/1995
Generator EPA ID: NYD050275254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

ECHO:
Envid: 1000353766
Registry ID: 110004357918
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004357918

AH215 **SINNOTT MANAGEMENT COMPANY LLC** **NY AST** **A100359845**
SE **35 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.227 mi.
1198 ft. **Site 2 of 11 in cluster AH**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. AST:
PBS Number: 3-078646
Site Status: Active
GDS Number: Not reported
Operator Name: Norman Avelenda
Owner Name: 35 Clinton Place LLC
Owner Street: 35 Clinton Place, #1B
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 1
Status: 1. In-Service
Date Installation: 12/01/1939
Capacity: 5000
Product Stored: 2. No. 4 fuel oil

SINNOTT MANAGEMENT COMPANY LLC (Continued) **A100359845**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Fiberglass
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	3. Gravity

AB216 **ALL AMERICAN SPORTS CORP** **RCRA NonGen / NLR** **1004760316**
SW **44 COLUMBUS AVE** **FINDS** **NYR000040113**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.228 mi. **ECHO**
1205 ft. **Site 5 of 5 in cluster AB**

Relative:
Lower

Actual:
66 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ALL AMERICAN SPORTS CORP
Facility address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
EPA ID:	NYR000040113
Mailing address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact:	LAMELLE WILLIAMS
Contact address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	(914) 636-7070
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	(914) 636-7070
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	(914) 636-7070

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ALL AMERICAN SPORTS CORP
Classification: Not a generator, verified

Date form received by agency: 05/30/1997
Site name: ALL AMERICAN SPORTS CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004534709

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000040113
Country: USA
Location Address 1: 44 COLUMBUS AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: ALL AMERICAN SPORTS CORP
Contact: LAMELLE WILLIAMS
Address: 44 COLUMBUS AVE
City/State/Zip: NEW ROCHELLE, NY 10802
Country: USA
Phone: 914-636-7070

Manifest:

Document ID: NJA2706453
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 10/13/1997
Trans1 Recv Date: 10/13/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 10/20/1997
Part A Recv Date: 10/29/1997
Part B Recv Date: 11/12/1997
Generator EPA ID: NYR000040113
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F005 - UNKNOWN
Quantity: 00426
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

EPA ID: NYD002182897
Country: USA
Location Address 1: 44 COLUMBUS AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10805
Location Zip Code 4: Not reported

Mailing Info:
Name: RIDDELL ALL AMERICAN
Contact: PERSING MEJIA
Address: 44 COLUMBUS AVE
City/State/Zip: NEW ROCHELLE, NY 10805
Country: USA
Phone: 914-636-7070

NY MANIFEST:
No Manifest Records Available

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

ECHO:
Envid: 1004760316
Registry ID: 110004534709
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004534709

AH217 **30 CLINTON PLACE OWNERS INC.** **NY UST U003855209**
SE **30 CLINTON PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1208 ft. **Site 3 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

WESTCHESTER CO. UST:
Id/Status: 3-078727 / Active
Operator Name: Dave Kuilan
Owner Name: 30 Clinton Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1old
Status: 5. Closed - removed
Capacity: 5000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 07/01/1995
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on Ground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 3. Gravity

WESTCHESTER CO. AST:
PBS Number: 3-078727
Site Status: Active
GDS Number: Not reported
Operator Name: Dave Kuilan
Owner Name: 30 Clinton Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 001
Status: 1. In-Service
Date Installation: 10/01/1996
Capacity: 3500

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	4. Closed - in place
Date Installation:	01/01/1996
Capacity:	4200
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AH218 **CO-OP** **NY LTANKS** **S101658613**
SE **30 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.229 mi.
1208 ft. **Site 4 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	189169
Spill Number/Closed Date:	9504589 / 1997-04-15
Spill Date:	1995-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010

CO-OP (Continued) **S101658613**

Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-20
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	MERILITH MNGT.
Spiller Address:	1101 MIDLAND AVE.
Spiller City,St,Zip:	BRONXVILLE, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157941
DEC Memo:	""
Remarks:	"OIL SEEPING INTO BASEMENT POSSIBLE TANK FAILURE SOME OIL GOT INTO SUMP PIT AND DISCHARGED OUT SUMP PUMP TAKEN OFF LINE"

Material:

Site ID:	189169
Operable Unit ID:	1019355
Operable Unit:	01
Material ID:	366101
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	189169
Spill Tank Test:	1544004
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AH219 **CON EDISON** **NY MANIFEST** **S117538379**
SE **150 NORTH AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1211 ft. **Site 5 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

NY MANIFEST:

EPA ID:	NYP004710497
Country:	USA
Location Address 1:	150 NORTH AV
Location Address 2:	SB2044
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	CON EDISON
Address:	4 IRVING PL
Address 2:	15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	Not reported

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004710497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012774700JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

CON EDISON (Continued) **S117538379**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AM220 **NEW ROCHELLE FIRE STATION # 1** **NY UST** **U003994763**
ENE **45 HARRISON STREET** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1223 ft. **Site 1 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600407 / Active
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	FS101
Status:	1. In-Service
Capacity:	5000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1966
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	FS102
Status:	5. Closed - removed
Capacity:	5000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	FS103
Status:	5. Closed - removed
Capacity:	250
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/18/2004
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

PBS Number:	3-600407
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dispatcher
Owner Name:	City of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801

Tank Number:	FS104
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	4000
Product Stored:	6. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,2. Sacrificial Anode (no retrofit)
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None

NEW ROCHELLE FIRE STATION # 1 (Continued) **U003994763**

Dispenser:	2. Suction
Tank Number:	FS105
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	280
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	0. None

AM221 **CITY OF NEW ROCHELLE** **NY LTANKS** **S107658678**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1223 ft. **Site 2 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

LTANKS:

Site ID:	360263
Spill Number/Closed Date:	0513733 / 2006-06-21
Spill Date:	2006-02-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-02-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-28
Spill Record Last Update:	2006-06-21
Spiller Name:	DEE LESTER
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	45 HARRISON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY

CITY OF NEW ROCHELLE (Continued) **S107658678**

Spiller County:	001
Spiller Contact:	DEE LESTER
Spiller Phone:	(914) 654-2072
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310380
DEC Memo:	"Tank passed retest after piping was replaced. NFA"
Remarks:	"TANK SIZE IS 5000 GALLON, TEST METHOD WAS EZ3 LOCATOR PLUS,"

Material:

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107948
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AM222 **CON EDISON** **NY MANIFEST** **S118088270**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.232 mi.
1223 ft. **Site 3 of 9 in cluster AM**

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

EPA ID:	NYP004758215
Country:	USA
Location Address 1:	45 HARRISON ST
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10802
Location Zip Code 4:	Not reported

Mailing Info:

CON EDISON (Continued) **S118088270**

Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758215
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091127JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758215
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S118088270**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091127JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH223 **CON EDISON MANHOLE: 2042** **RCRA NonGen / NLR** **1016970603**
SE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004443198**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.232 mi.
1224 ft. **Site 6 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/16/2014
Facility name:	CON EDISON MANHOLE: 2042
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10804
EPA ID:	NYP004443198
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2014
Site name: CON EDISON MANHOLE: 2042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004443198
Country: USA
Location Address 1: NORTH AVE & CLINTON PL
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004443198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Manifest Tracking Num:	012772860JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AH224 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016971500**
SE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004452439**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.232 mi.
1224 ft. **Site 7 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/26/2014
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10805
EPA ID:	NYP004452439
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/26/2014
Site name:	CON EDISON SERVICE BOX: 2040

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004452439
Country: USA
Location Address 1: NORTH AVE & CLINTON PLS
Location Address 2: SB2040
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: CON EDISION
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2014
Trans1 Recv Date: 02/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004452439
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 30
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012772758JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Mgmt Method Type Code: H110

AC225 **100-102 UNION AVENUE** **NY LTANKS** **S104514442**
West **100-102 UNION AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1229 ft. **Site 3 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	166425
Spill Number/Closed Date:	9608199 / 1996-11-08
Spill Date:	1996-10-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-01
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-01
Spill Record Last Update:	1996-12-10
Spiller Name:	LJ NJ ASSOC
Spiller Company:	100-102 UNION AVENUE
Spiller Address:	100-102 UNION AVENUE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LJ NJ ASSOC
Spiller Phone:	(914) 636-7297
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140217
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/96 LETTER SENT BASED ON CLOSURE REPORT NFA"
Remarks:	"caller pulled tank and found contaminated soil."

Material:

Site ID:	166425
Operable Unit ID:	1036474
Operable Unit:	01
Material ID:	343940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

100-102 UNION AVENUE (Continued) **S104514442**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AC226
West
1/8-1/4
0.233 mi.
1229 ft.

LJNJ ASSOCIATES **NY UST** **U003884659**
100-102 UNION AVE **N/A**
NEW ROCHELLE, NY 10801

Site 4 of 7 in cluster AC

Relative:
Higher

Actual:
95 ft.

WESTCHESTER CO. UST:

Id/Status:	3-601056 / Unregulated: <1101 gal. PBS
Operator Name:	Bob Rossi
Owner Name:	Ljnj Associates
Owner Street:	133 Meadow Lane
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	1080
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1959
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None
Tank Number:	2
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

LJNJ ASSOCIATES (Continued) **U003884659**

Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	3
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	4
Status:	5. Closed - removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/01/1996
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	5
Status:	0. Administratively closed
Capacity:	275

LJNJ ASSOCIATES (Continued) **U003884659**

Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AI227 **CON EDISON TRANSFORMER MANHOLE: 1552** **RCRA NonGen / NLR** **1016964344**
NNW **LOCKWOOD AVE & NORTH ST** **NY MANIFEST** **NYP004372751**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.233 mi.
1230 ft. **Site 5 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/10/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 1552
Facility address:	LOCKWOOD AVE & NORTH ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004372751
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Used oil transporter: No

Historical Generators:
Date form received by agency: 10/10/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 1552
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004372751
Country: USA
Location Address 1: LOCKWOOD AVE & NORTH ST
Location Address 2: TM 1552
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/10/2013
Trans1 Recv Date: 10/10/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004372751
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 400
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 011693714JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AI228 **CON EDISON MANHOLE 1545** **RCRA NonGen / NLR** **1014918224**
NNW **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004218356**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.233 mi.
1230 ft. **Site 6 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 11/18/2010
Facility name: CON EDISON MANHOLE 1545
Facility address: NORTH AVE & LOCKWOOD AVE
NEW ROCHELLE, NY 10801
EPA ID: NYP004218356
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER BLAICH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2010
Site name: CON EDISON MANHOLE 1545
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004218356

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CHRISTOPHER BLAICH
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874846JJK
EPA ID:	NYP004218356
Date Shipped:	10/19/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/19/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/20/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 2000 P

NY MANIFEST:
EPA ID: NYP004218356
Country: USA
Location Address 1: NORTH AV OPP LOCKWOOD
Location Address 2: MH 1545
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2010
Trans1 Recv Date: 10/19/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004218356
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006874846JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: Y

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AI229 **CON EDISON MANHOLE 1562** **RCRA NonGen / NLR** **1014918646**
NNW **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004222626**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.233 mi.
1230 ft. **Site 7 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/30/2011
Facility name: CON EDISON MANHOLE 1562
Facility address: NORTH AVE & LOCKWOOD AVE
NEW ROCHELLE, NY 10801
EPA ID: NYP004222626
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: DONALD SENNO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (914) 925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2010
Site name: CON EDISON MANHOLE 1562
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

CON EDISON MANHOLE 1562 (Continued) **1014918646**

EPA Id:	NYP004222626
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655578JJK
EPA ID:	NYP004222626
Date Shipped:	12/31/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/31/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/04/2011
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Waste:
- Manifest Year: Not reported
- Waste Code: D008
- Hand Code: H111
- Quantity: 150 P

NY MANIFEST:
- EPA ID: NYP004222626
- Country: USA
- Location Address 1: NORTH AVE & LOCKHEED
- Location Address 2: MH 1962
- Location City: NEW ROCHELLE
- Location State: NY
- Location Zip Code: Not reported
- Location Zip Code 4: Not reported

Mailing Info:
- Name: CONSOLIDATED EDISON
- Contact: DENNIS HUACON
- Address: 4 IRVING PLACE RM 828
- City/State/Zip: NEW YORK, NY 10003
- Country: USA
- Phone: 212-460-2757

Manifest:

- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD006982359
- Trans2 State ID: Not reported
- Generator Ship Date: 12/31/2010
- Trans1 Recv Date: 12/31/2010
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 01/04/2011
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004222626
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID: NJD002200046
- Waste Code: Not reported
- Quantity: 150.0
- Units: P - Pounds
- Number of Containers: 1.0
- Container Type: TT - Cargo tank, tank trucks
- Handling Method: T Chemical, physical, or biological treatment.
- Specific Gravity: 1.0
- Year: 2010
- Manifest Tracking Num: 007655578JJK
- Import Ind: N
- Export Ind: N
- Discr Quantity Ind: N
- Discr Type Ind: Y

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AI230 **CON EDISON** **NY MANIFEST** **S118259837**
NNW **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1230 ft. **Site 8 of 10 in cluster AI**

Relative:
Lower

Actual:
78 ft.

NY MANIFEST:
EPA ID: NYP004838332
Country: USA
Location Address 1: LOCKWOOD AVE & NORTH AVE
Location Address 2: TM 1552
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: Not reported
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2015
Trans1 Recv Date: 09/14/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/21/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004838332
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014472178JJK
Import Ind: N

CON EDISON (Continued) **S118259837**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM231 **CON ED** **NY MANIFEST** **S118088428**
ENE **HARRISON ST & CEDAR ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1231 ft. **Site 4 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004759924
Country:	USA
Location Address 1:	HARRISON ST & CEDAR ST
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON ED (Continued) **S118088428**

Year:	2015
Manifest Tracking Num:	014091107JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091107JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AC232 **KAGEL HOME** **NY LTANKS** **S107658662**
West **99 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1232 ft. **Site 5 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	360201
Spill Number/Closed Date:	0513684 / 2006-03-09
Spill Date:	2006-02-27
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	2006-03-06
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-27
Spill Record Last Update:	2006-03-09
Spiller Name:	ANDREW KAGEL
Spiller Company:	KAGEL HOME
Spiller Address:	99 UNION AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ANDREW KAGEL
Spiller Phone:	(914) 403-2881
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310321
DEC Memo:	"Homeowner waiting on proposal from N.E. to finish job. 3/6/06 Northeast Environmental reported that the tank was removed along with eight drums of petroleum impacted soil. NFA. TG"
Remarks:	"55o gallon tank had holes and found contaminated soil;"

Material:

Site ID:	360201
Operable Unit ID:	1117385
Operable Unit:	01
Material ID:	2107892
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

KAGEL HOME (Continued) **S107658662**

Tank Test:

AG233 **125** **NY LTANKS** **S104621592**
South **CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.234 mi.
1233 ft. **Site 4 of 4 in cluster AG**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Site ID:	205498
Spill Number/Closed Date:	0001835 / 2000-05-15
Spill Date:	2000-05-12
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-12
CID:	196
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-12
Spill Record Last Update:	2000-06-21
Spiller Name:	UNKNOWN
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY 10454-
Spiller County:	001
Spiller Contact:	OPERATOR 631
Spiller Phone:	(914) 595-5901
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170636
DEC Memo:	""
Remarks:	"TANK OVER FILL AT THIS LOCATION. 10 GALLONS SPILLED AND THE SPILL WAS CLEANED UP BY THE FIRE DEPT. THE SPILL IS AT THE CHURCH BLESSED SACRMENT CHURCH. BABR MCDONALD FROM COUNTY HEATH DEPT. 637-4890 WAS CALLED TO THE SCENE ALSO."

Material:

Site ID:	205498
Operable Unit ID:	823753
Operable Unit:	01
Material ID:	290047
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

125 (Continued) **S104621592**

Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AI234 **368 NORTH AVE MGMT CO. INC.** **NY UST** **U003994274**
NNW **368 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.234 mi.
1234 ft. **Site 9 of 10 in cluster AI**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600272 / Unregulated: <1101 gal. PBS
Operator Name:	Barry Shapiro
Owner Name:	368 North Ave Mgmt Co. Inc.
Owner Street:	27 Country Ridge Road
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	1
Status:	5. Closed - removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/24/2003
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AL235 **GHP 145 HUGUENOT DELAWARE, LLC** **NY AST** **U003994574**
NE **145 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 3 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

WESTCHESTER CO. AST:

PBS Number:	3-497436
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Clemente
Owner Name:	GHP 145 Huguenot Delaware, LLC
Owner Street:	4 West Red Oak Lane, Suite 200
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10604
Tank Number:	3-497436
Status:	1. In-Service
Date Installation:	07/01/1989
Capacity:	6000
Product Stored:	1. No. 2 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

AL236 **LONGINES WITTNAUER WATCH CO** **RCRA NonGen / NLR** **1000235411**
NE **145 HUGUENOT ST** **FINDS** **NYD001317221**
1/8-1/4 **NEW ROCHELLE, NY 10802** **NY MANIFEST**
0.236 mi. **ECHO**
1247 ft. **Site 4 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	LONGINES WITTNAUER WATCH CO
Facility address:	145 HUGUENOT ST NEW ROCHELLE, NY 10802
EPA ID:	NYD001317221
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact:	Not reported
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 03/11/1985
Site name: LONGINES WITTNAUER WATCH CO
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P013
. Waste name: BARIUM CYANIDE

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P097
. Waste name: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/17/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/19/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:

Registry ID: 110004333720

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD001317221
Country: USA
Location Address 1: 145 HUGUENOT STREET
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: LONGINES WITTHAVER WATCH COMPANY
Contact: LONGINES WITTHAVER WATCH COMPANY

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Address: 145 HUGUENOT STREET
City/State/Zip: NEW RTOCHELLE, NY 10802
Country: USA
Phone: 914-576-1000

Manifest:

Document ID: NJA0309928
Manifest Status: Completed copy
Trans1 State ID: NJDEP#S10
Trans2 State ID: Not reported
Generator Ship Date: 08/19/1987
Trans1 Recv Date: 08/19/1987
Trans2 Recv Date: / /
TSD Site Recv Date: 08/20/1987
Part A Recv Date: 08/28/1987
Part B Recv Date: 08/27/1987
Generator EPA ID: NYD001317221
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID: NJD089216790
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00224
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 021
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00450
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: P106 - SODIUM CYANIDE
Quantity: 00064
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00036
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 1987

Document ID: NJA0062673
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 04/23/1985

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Trans1 Recv Date:	04/23/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/23/1985
Part A Recv Date:	05/24/1985
Part B Recv Date:	05/15/1985
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00030
Units:	P - Pounds
Number of Containers:	002
Container Type:	CW - Wooden boxes
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1985

Document ID:	NJA0056902
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	04/23/1985
Trans1 Recv Date:	04/23/1985
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/23/1985
Part A Recv Date:	05/24/1985
Part B Recv Date:	05/15/1985
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	X850 - NJ ONLY
Quantity:	00650
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00400
Units:	P - Pounds

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	CW - Wooden boxes
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1985

Document ID:	NJA0309927
Manifest Status:	Completed copy
Trans1 State ID:	NJDEP#S10
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1987
Trans1 Recv Date:	08/19/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/20/1987
Part A Recv Date:	08/28/1987
Part B Recv Date:	08/27/1987
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID:	NJD089216790
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00036
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00004
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	P030 - CYANIDES N.O.S.
Quantity:	00062
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1987

ECHO:

Envid:	1000235411
Registry ID:	110004333720
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110004333720

AL237 **GALESI ENTERPRICES** **NY LTANKS** **S105236833**
NE **145 HUGUENOT ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.236 mi.
1247 ft. **Site 5 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

LTANKS:

Site ID:	259815
Spill Number/Closed Date:	8901038 / 1989-06-01
Spill Date:	1989-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1989-06-01
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212473
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. "
Remarks:	"8K, -.116"

Material:

Site ID:	259815
Operable Unit ID:	927170
Operable Unit:	01
Material ID:	452349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

GALESI ENTERPRICES (Continued) **S105236833**

Tank Test:

Site ID:	259815
Spill Tank Test:	1535410
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0909155
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421828
DEC Region:	3
Spill Date:	2009-11-16
Spill Number/Closed Date:	0909155 / 2009-11-16
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
Contact Phone:	(718) 579-3414
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

Material:

Site ID:	421828
Operable Unit ID:	1177706
Operable Unit:	01
Material ID:	2170525

GALESI ENTERPRICES (Continued) **S105236833**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0909156
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421829
DEC Region:	3
Spill Date:	2009-11-16
Spill Number/Closed Date:	0909156 / 2009-11-16
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, NY
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
Contact Phone:	(718) 579-3414
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

Material:

Site ID:	421829
Operable Unit ID:	1177707
Operable Unit:	01
Material ID:	2170526
Material Code:	0001A

GALESI ENTERPRICES (Continued) **S105236833**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0308837
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259814
DEC Region:	3
Spill Date:	2003-11-19
Spill Number/Closed Date:	0308837 / 2003-11-19
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-11-19
CID:	322
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-19
Spill Record Last Update:	2003-12-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	CHRIS LALAK
Contact Phone:	(914) 424-4679
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 11/19/03: Spill is unrecoverable per C. Lalak, WCDOH. Recommends NFA at this time."
Remarks:	"approx 10 gal unk oil on roadway - highway dept placing sand "

Material:

Site ID:	259814
Operable Unit ID:	875003
Operable Unit:	01
Material ID:	571327
Material Code:	0066A
Material Name:	unknown petroleum

GALESI ENTERPRICES (Continued) **S105236833**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0109500
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259813
DEC Region:	3
Spill Date:	2001-12-28
Spill Number/Closed Date:	0109500 / 2001-12-28
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-12-28
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-28
Spill Record Last Update:	2002-01-03
Spiller Name:	CHRIS LALAK
Spiller Company:	HEALTH DEPT OFFICE
Spiller Address:	145 HUGUENOT ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CHRIS LALAK
Contact Phone:	(917) 578-9269
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 12/28/2001 C. LALAK @ WCDOH HANDLED. SPILL CLEANED UP. NO FURTHER ACTION."
Remarks:	"all cleaned up less than 1 oz"

Material:

Site ID:	259813
Operable Unit ID:	846776
Operable Unit:	01
Material ID:	527159
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976

GALESI ENTERPRICES (Continued) **S105236833**

Material FA:	Hazardous Material
Quantity:	1.00
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AM238 **CON ED** **NY MANIFEST** **S118088390**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1250 ft. **Site 5 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004759510
Country:	USA
Location Address 1:	HARRISON ST & FOUNTAIN PL
Location Address 2:	MH 8003
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON ED
Contact:	TOM TEELING
Address:	4 IRVING PLACE - 15TH FLOOR
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON ED (Continued) **S118088390**

Year:	2015
Manifest Tracking Num:	014091122JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091122JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM239 **CON EDISON** **NY MANIFEST** **S118089335**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1250 ft. **Site 6 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004769345
Country:	USA
Location Address 1:	FOUNTAIN PL & HARRISON ST
Location Address 2:	MH 8008
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769345
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660843GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118089335**

Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 04/16/2015
Trans1 Recv Date: 04/16/2015
Trans2 Recv Date: 04/20/2015
TSD Site Recv Date: 04/20/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004769345
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 002660843GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AM240 **CON EDISON** **NY MANIFEST** **S118088276**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.237 mi.
1250 ft. **Site 7 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:
EPA ID: NYP004758272
Country: USA
Location Address 1: HARRISON ST & FOUNTAIN PL
Location Address 2: SB 8044
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10802
Location Zip Code 4: Not reported

Mailing Info:
Name: CON EDISON
Contact: DENNIS HUACON
Address: 4 IRVING PL 15TH FL

CON EDISON (Continued) **S118088276**

City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Manifest:

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2015
Manifest Tracking Num: 014091128JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2015
Trans1 Recv Date: 03/26/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004758272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported

CON EDISON (Continued) **S118088276**

Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	014091128JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

AM241 **CON EDISON** **NY MANIFEST** **S118089345**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1250 ft. **Site 8 of 9 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004769477
Country:	USA
Location Address 1:	FOUNTAIN PL & HARRISON ST
Location Address 2:	SB 8007
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	Not reported
Location Zip Code 4:	Not reported

Mailing Info:

Name:	CON EDISON
Contact:	DENNIS HUACON
Address:	4 IRVING PL 15TH FL
City/State/Zip:	NEW YORK, NY 10003
Country:	USA
Phone:	212-460-3770

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118089345**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660844GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H110

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	002660844GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON (Continued) **S118089345**

Mgmt Method Type Code: H110

AE242 **MONROE COLLEGE** **NY LTANKS** **S106124169**
East **5 FRANKLIN AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1252 ft. **Site 4 of 4 in cluster AE**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	165556
Spill Number/Closed Date:	0307536 / 2005-03-27
Spill Date:	2003-10-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-10-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-16
Spill Record Last Update:	2005-03-27
Spiller Name:	JIM MOORE
Spiller Company:	MONROE COLLEGE
Spiller Address:	5 FRANKLIN AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JIM MOORE
Spiller Phone:	(914) 403-3458
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	278527
DEC Memo:	"03/27/05 CLEAN UP COMPLETED. SPILL FILE CLOSED BY OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod As per email from WCHD: 03-07536 5 Franklin Ave, NEw Rochelle, NY (also known as 420 Main St, New Rochelle) Tank removed from basement, soil disposed of. NFA"
Remarks:	"recomend repair retest"

Material:

Site ID:	165556
Operable Unit ID:	873930
Operable Unit:	01
Material ID:	501063
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

MONROE COLLEGE (Continued) **S106124169**

Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	165556
Spill Tank Test:	1528740
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AI243 **CASANOVA BROS. REALTY** **NY UST** **U003884076**
NNW **370 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.238 mi.
1257 ft. **Site 10 of 10 in cluster AI**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800088 / Unregulated: <1101 gal. PBS
Operator Name:	Israel Estrada
Owner Name:	Casanova Bros. Realty
Owner Street:	370 North Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/14/2002
Tank Location:	5. Underground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AC244 **TANK TEST FAILURE** **NY LTANKS** **S111239332**
WSW **50 WALNUT ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.240 mi.
1265 ft. **Site 6 of 7 in cluster AC**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	455637
Spill Number/Closed Date:	1107925 / 2013-02-05
Spill Date:	2011-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-21
Spill Record Last Update:	2013-02-06
Spiller Name:	Not reported
Spiller Company:	SAL VIGNA
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	KEN RONK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	410212
DEC Memo:	"9-21-11 Owner is Pietro Vigna and doesn't speak english. Sal is his son. Sal cell: (914)424-2239. Sal has Eastern Env coming out Wed to investigate further. jc 2/6/13: Northeast Environmental disposed of LUST and a total of 21.05 tons of petroleum contaminated soil. Exit sample results showed residual contamination over CP-51 Guidance values. Additional excavation of contaminted soil is not possible with causing possible structural damage to the building foundations. Based upon the information provided, this Department requires no further action at this time. Closed - doesn not meet standarsds. jod"
Remarks:	"tank test failure"

Material:

Site ID:	455637
Operable Unit ID:	1205789
Operable Unit:	01
Material ID:	2202749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

TANK TEST FAILURE (Continued) **S111239332**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AN245 **DOMENICO PROCOPIO PROPERTY** **NY LTANKS** **S103558292**
SSW **618 MAIN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.242 mi.
1279 ft. **Site 1 of 4 in cluster AN**

Relative:
Higher

Actual:
87 ft.

LTANKS:

Site ID:	278454
Spill Number/Closed Date:	9809866 / 2004-03-30
Spill Date:	1998-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-05
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-05
Spill Record Last Update:	2004-03-30
Spiller Name:	DOMINIC PROCOPIO
Spiller Company:	DOMINIC PROCOPIO
Spiller Address:	10 MAPLE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	DOMINIC PROCOPIO
Spiller Phone:	(914) 576-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	226099
DEC Memo:	""
Remarks:	"CHECK PIPING AND RETEST"

Material:

Site ID:	278454
Operable Unit ID:	1067125
Operable Unit:	01
Material ID:	313759
Material Code:	0001A

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 278454
Spill Tank Test: 1546499
Tank Number: 1
Tank Size: 1500
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 0408557
Facility Type: ER
DER Facility ID: 226099
Site ID: 333327
DEC Region: 3
Spill Date: 2004-11-03
Spill Number/Closed Date: 0408557 / 2005-03-17
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2004-11-03
CID: 407
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-11-03
Spill Record Last Update: 2005-04-05
Spiller Name: DOMINICKO PROCOPIO
Spiller Company: Not reported
Spiller Address: 618 MAIN ST
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: DOMINICKO PROCOPIO
Contact Phone: (914) 636-9570

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

DEC Memo: "PBS #3-800233 11/16/2004 Stephan Goreau of WCDOH spill update -- several inches in basement of sewer/oil mix---BHY 4/4/05: Letter to Vincent Rippa, Domenico Procopio Property from Stefan Goreau, WCDOH dated 17Mar2005. WCDOH requires NFA at this time."
Remarks: "Imporperly Abondoned tank."

Material:
Site ID: 333327
Operable Unit ID: 1095482
Operable Unit: 01
Material ID: 575615
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AN246 **DOMENICO PROCOPIO** **NY UST U003988536**
SSW **618 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.242 mi.
1279 ft. **Site 2 of 4 in cluster AN**

Relative: Higher

Actual: 87 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800233 / Unregulated: <1101 gal. PBS
Operator Name: Domenico Procopio
Owner Name: Domenico Procopio
Owner Street: 126 Liberty Avenue
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10805
GDS Number: Not reported

Tank Number: 1
Status: 5. Closed - removed
Capacity: 1500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 11/24/2004
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 9. Copper
Piping External Protection: 0. None
Overfill Prevention: 0. None

DOMENICO PROCOPIO (Continued) **U003988536**

Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 3. Gravity

WESTCHESTER CO. AST:
PBS Number: 3-800233
Site Status: Unregulated: <1101 gal. PBS
GDS Number: Not reported
Operator Name: Domenico Procopio
Owner Name: Domenico Procopio
Owner Street: 126 Liberty Avenue
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10805

Tank Number: 2
Status: 0. Administratively closed
Date Installation: 06/01/1998
Capacity: 330
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported
Piping Location: 1. Aboveground
Piping Type: 9. Copper
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 4. Product Level Gauge (Aboveground Only)
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 3
Status: 0. Administratively closed
Date Installation: 06/01/1998
Capacity: 330
Product Stored: 1. No. 2 fuel oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported
Piping Location: 1. Aboveground
Piping Type: 9. Copper
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 4. Product Level Gauge (Aboveground Only)
Spill Prevention: Not reported

DOMENICO PROCOPIO (Continued) **U003988536**

Dispenser: 2. Suction

AC247 **ROBERTS HOME** **NY LTANKS** **S108298719**
WSW **58 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.243 mi.
1283 ft. **Site 7 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	372634
Spill Number/Closed Date:	0608623 / 2012-08-17
Spill Date:	2006-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2012-08-17
Spiller Name:	TOM ROBERTS
Spiller Company:	ROBERTS HOME
Spiller Address:	58 WALNUT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	TOM ROBERTS
Spiller Phone:	(914) 755-9816
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	322369
DEC Memo:	"8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M"
Remarks:	""

Material:

Site ID:	372634
Operable Unit ID:	1130371
Operable Unit:	01
Material ID:	2120048
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

ROBERTS HOME (Continued) **S108298719**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 372634
Spill Tank Test: 1550391
Tank Number: 1
Tank Size: 550
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AO248 @ **NY LTANKS** **S106971852**
WSW **60 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.244 mi.
1289 ft. **Site 1 of 3 in cluster AO**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Site ID: 346287
Spill Number/Closed Date: 0502010 / 2005-07-17
Spill Date: 2005-05-19
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-05-19
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-05-19
Spill Record Last Update: 2005-07-17
Spiller Name: MR. GALLERO
Spiller Company: Not reported
Spiller Address: 60 WALNUT STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: MR. GALLERO
Spiller Phone: (914) 469-7160
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 292543
DEC Memo: "July 17, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 33.65

@ (Continued) **S106971852**

TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "1000 GALLON TANK HAD HOLES IN IT:"

Material:
Site ID: 346287
Operable Unit ID: 1104017
Operable Unit: 01
Material ID: 584224
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

AN249 **VACANT** **NY UST U004177556**
SSW **399 HUGUENOT STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1295 ft. **Site 3 of 4 in cluster AN**

Relative:
Lower

Actual:
83 ft.

WESTCHESTER CO. UST:
Id/Status: 3-801616 / Unregulated
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City: New York
Owner State: NY
Owner Zipcode: 10017
GDS Number: Not reported

Tank Number: 5
Status: 5. Closed - removed
Capacity: 1500
Product Stored: 2. No. 4 fuel oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None

VACANT (Continued) **U004177556**

Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 6
Status: 4. Closed - in place
Capacity: 1000
Product Stored: 2. No. 4 fuel oil
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 7
Status: 5. Closed - removed
Capacity: 1000
Product Stored: 7. Gasoline
Product Stored Percent: 0
Tank Leak Detection: 0. None
Date Installation: 12/01/1956
Date Perm Closure: 02/01/2010
Tank Location: 5. Underground
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-801616
Site Status: Unregulated
GDS Number: Not reported
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City/State/Zip: New York, NY 10017

VACANT (Continued) **U004177556**

Tank Number:	1
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	13. Waste/Used Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	2
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	750
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	3
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported

VACANT (Continued) **U004177556**

Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	4
Status:	5. Closed - removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	12. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

AH250 **COLONIAL CLEANERS CORP** **RCRA NonGen / NLR** **1000338874**
SE **149 NORTH AVE** **NYD982718058**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 8 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	COLONIAL CLEANERS CORP
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 108017405
EPA ID:	NYD982718058
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

COLONIAL CLEANERS CORP (Continued) **1000338874**

Owner/Operator Summary:
- Owner/operator name: COLONIAL CLEANERS CORP
- Owner/operator address: NOT REQUIRED
  NOT REQUIRED, WY 99999
- Owner/operator country: US
- Owner/operator telephone: (212) 555-1212
- Legal status: Private
- Owner/Operator Type: Owner
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

- Owner/operator name: COLONIAL CLEANERS CORP
- Owner/operator address: NOT REQUIRED
  NOT REQUIRED, WY 99999
- Owner/operator country: US
- Owner/operator telephone: (212) 555-1212
- Legal status: Private
- Owner/Operator Type: Operator
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 01/01/2006
- Site name: COLONIAL CLEANERS CORP
- Classification: Not a generator, verified

- Date form received by agency: 07/08/1999
- Site name: COLONIAL CLEANERS CORP
- Classification: Not a generator, verified

- Date form received by agency: 11/30/1988
- Site name: COLONIAL CLEANERS CORP
- Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

COLONIAL CLEANERS CORP (Continued) **1000338874**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

AH251 **FLAMINGO/TYK CLEANERS** **NY DRYCLEANERS** **S110246604**
SE **149 NORTH AV.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 9 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

DRYCLEANERS:

Facility ID:	3-5510-00335
Phone Number:	914-235-1591
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	08SEP19
Install Date:	94/08
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AH252 **FLAMINGO CLEANERS** **RCRA-LQG** **1000299848**
SE **149 NORTH AVE** **NY BROWNFIELDS** **NYD012946885**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.246 mi.
1299 ft. **Site 10 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA-LQG:

Date form received by agency:	07/10/2012
Facility name:	FLAMINGO CLEANERS
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD012946885
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	RICHARD H DORAN
Contact address:	DORSON ENVIRONMENTAL MGMT INC 45 KNOLLWOOD RD SUITE 300 ELMSFORD, NY 10523
Contact country:	US
Contact telephone:	(914) 592-3117
Contact email:	RDORAN@DORSON.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less

FLAMINGO CLEANERS (Continued) **1000299848**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	TAEYOON KIM
Owner/operator address:	149 NORTH AVE
	NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 235-1591
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	V & V CAPITAL LLC
Owner/operator address:	PHILLIPS HILL RD
	NEW CITY, NY 10956
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/14/2011
Owner/Op end date:	Not reported

Owner/operator name:	LUIGI LLESHAJ
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/14/2011
Owner/Op end date:	Not reported

Owner/operator name:	TAEYOON KIM
Owner/operator address:	149 NORTH AVE
	NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 235-1591
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

FLAMINGO CLEANERS (Continued) **1000299848**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

FLAMINGO CLEANERS (Continued) **1000299848**

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/01/2007
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/21/1991
Site name: FLAMINGO CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/10/2006
Date achieved compliance: 08/18/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/03/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/10/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 08/18/2006
Evaluation lead agency: State

BROWNFIELDS:
Program: BCP
Site Code: 335220

FLAMINGO CLEANERS (Continued) **1000299848**

Acres:	0.12
HW Code:	C360078
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/16/2004
Record Updated Date:	05/28/2015
Update By:	DACROSBY
Site Description:	Location: The Flamingo Cleaners site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site is a one-story commercial building with a full basement. The building is divided into four tenant spaces which include a bar/lounge, beauty salon, and two vacant spaces that previously housed a travel agency and a dry-cleaner.Current Zoning/use(s): The site consists of four retail spaces, two of which are currently occupied. The site is zoned for commercial use. The surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a medical center, and a church. The dry cleaning operation is no longer active and the space is currently vacant.Historical Uses: The existing building was constructed in 1941 and used for retail. Flamingo Cleaners began dry cleaning operations in 1958, and ran until 2005 when all dry-cleaning equipment was removed. Site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE).Prior completed investigations include a Phase I Investigation in October of 2003 and a Phase II Investigation completed in March of 2004. The Volunteer entered into a Brownfield Cleanup Agreement in April 2005. A Decision Document was issued in March 2012 for a remedy involving source soil removal and in situ chemical oxidation treatment of groundwater. Based on the extent of the site contamination, a referral to State Superfund for an off-site investigation was completed in December 2007. The groundwater plume was found to be isolated to immediately behind the building and little to no off-site impacts were noted in groundwater, soils, nor in soil vapor.Site Geology/hydrogeology: The site is underlain by glacial till which sits atop highly weathered bedrock. Bedrock ranges from 5 - 22 feet below ground surface. The water table is between 5 - 11 feet below ground surface. Groundwater flow direction dominantly to the south-southeast toward Long Island Sound, however, site specific groundwater flow direction is radial, and seasonally affected.
Env Problem:	Nature and Extent of Contamination: Based on the investigations conducted to date, the primary contaminant of concern at the site is tetrachloroethylene (PCE or perc), a dry cleaning solvent. PCE has been detected in exceedance of SCGs in on-site soils, soil vapor, on-site indoor air, and on-site groundwater. The off-site investigation to date indicates that there are no off-site impacts.Source area soils contained as much as 1,300 parts per million (ppm) of PCE, which exceeds the 1.3 ppm protection of groundwater soil cleanup objective. Immediately outside of the source area, soil concentrations of PCE ranged from 0.06 ppm - 0.91 ppm and did not exceed the soil cleanup objective for commercial use. PCE in groundwater was found at concentrations ranging from 1,000 parts per billion (ppb) - 19,000 ppb, which greatly exceeds the 5 ppb groundwater standard. PCE concentrations in sub-slab soil gas ranged from 15,700 ug/m3 - 570,000 ug/m3, and PCE in indoor air ranged from 115 ug/m3 - 1,040 ug/m3, exceeding NYDOH ambient air guidance value

FLAMINGO CLEANERS (Continued) **1000299848**

of 100 ug/m3 PCE. Concentrations of other volatile organic compounds (VOCs) including trichloroethene (TCE), 1,2-dichloroethene (1,2-DCE) and 1,1,1 trichloroethane (1,1,1 TCA) also exceeded groundwater standards but to a lesser extent. A state-funded RI/FS of the off-site extent of soil vapor and groundwater contamination was conducted from 2009-2011. The results indicate that the groundwater and soil vapor plumes appear to be limited to immediately below the site.Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater and/or soil may move into the soil vapor (air space within the soil), which in turn may move into overlying building and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilate/remove the air beneath the building) has been installed in the on-site building to prevent the indoor air quality from being affected by the contamination in the soil vapor beneath the building. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

NY MANIFEST:

EPA ID:	NYD012946885
Country:	USA
Location Address 1:	149 NORTH AVE
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	V & V CAPITAL LLC
Contact:	V&V CAPITAL LLC - FORMER FLAMINGO CLEANERS
Address:	149 NORTH AVENUE
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	361-586-5900

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2013
Trans1 Recv Date:	01/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	12000
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835158JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	NJD054126164
Generator Ship Date:	01/30/2013
Trans1 Recv Date:	01/30/2013
Trans2 Recv Date:	01/30/2013
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	12080
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835159JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2013
Trans1 Recv Date:	01/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CDX168000000
Waste Code:	Not reported
Quantity:	6160
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	008835161JJK
Import Ind:	N
Export Ind:	Y
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NYC7146663
Manifest Status:	Not reported
Trans1 State ID:	NYCF7875
Trans2 State ID:	NJ044T468
Generator Ship Date:	05/18/2004
Trans1 Recv Date:	05/18/2004
Trans2 Recv Date:	05/26/2004
TSD Site Recv Date:	05/27/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980587
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150

FLAMINGO CLEANERS (Continued) **1000299848**

Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYC3062226
Manifest Status: Completed copy
Trans1 State ID: GP2381NY
Trans2 State ID: Not reported
Generator Ship Date: 09/07/1994
Trans1 Recv Date: 09/07/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 09/07/1994
Part A Recv Date: 10/03/1994
Part B Recv Date: 09/15/1994
Generator EPA ID: NYD012946885
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD000708172
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00560
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NYC7252402
Manifest Status: Not reported
Trans1 State ID: NYCF7875
Trans2 State ID: NJ044
Generator Ship Date: 12/29/2003
Trans1 Recv Date: 12/29/2003
Trans2 Recv Date: 12/30/2003
TSD Site Recv Date: 01/05/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00156
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: NYC7019403

FLAMINGO CLEANERS (Continued) **1000299848**

Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	619TVANJ
Generator Ship Date:	01/17/2003
Trans1 Recv Date:	01/17/2003
Trans2 Recv Date:	01/23/2003
TSD Site Recv Date:	01/23/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC7072514
Manifest Status:	Not reported
Trans1 State ID:	NYCR3164
Trans2 State ID:	NJ044
Generator Ship Date:	07/29/2003
Trans1 Recv Date:	07/29/2003
Trans2 Recv Date:	08/06/2003
TSD Site Recv Date:	08/07/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC5692331
Manifest Status:	Not reported
Trans1 State ID:	NY43803AV
Trans2 State ID:	NJ044
Generator Ship Date:	06/11/2002
Trans1 Recv Date:	06/11/2002
Trans2 Recv Date:	06/12/2002
TSD Site Recv Date:	06/13/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6809681
Manifest Status: Not reported
Trans1 State ID: NY49455JE
Trans2 State ID: T474GL
Generator Ship Date: 08/06/2002
Trans1 Recv Date: 08/06/2002
Trans2 Recv Date: 08/07/2002
TSD Site Recv Date: 08/08/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2002

Document ID: NYC6422760
Manifest Status: Not reported
Trans1 State ID: NYC2456
Trans2 State ID: Not reported
Generator Ship Date: 04/23/2001
Trans1 Recv Date: 04/23/2001
Trans2 Recv Date: 04/27/2001
TSD Site Recv Date: 04/28/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: MOD095038998
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

FLAMINGO CLEANERS (Continued) **1000299848**

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC6508574
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: NJ044
Generator Ship Date: 09/26/2001
Trans1 Recv Date: 09/26/2001
Trans2 Recv Date: 10/01/2001
TSD Site Recv Date: 10/02/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: NJD071629976
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYC5724303
Manifest Status: Not reported
Trans1 State ID: NYDW9495
Trans2 State ID: T422NYNJ
Generator Ship Date: 01/19/2000
Trans1 Recv Date: 01/19/2000
Trans2 Recv Date: 01/24/2000
TSD Site Recv Date: 01/27/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD012946885
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCR000074591
TSDF ID: OHD980587364
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYC6305040
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Trans2 State ID: T748NYNJ

FLAMINGO CLEANERS (Continued) **1000299848**

Generator Ship Date:	12/06/2000
Trans1 Recv Date:	12/06/2000
Trans2 Recv Date:	12/11/2000
TSD Site Recv Date:	12/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6133296
Manifest Status:	Not reported
Trans1 State ID:	NYRCR2436
Trans2 State ID:	NJT162VW
Generator Ship Date:	05/02/2000
Trans1 Recv Date:	05/02/2000
Trans2 Recv Date:	05/04/2000
TSD Site Recv Date:	05/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC6240633
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	08/15/2000
Trans1 Recv Date:	08/15/2000
Trans2 Recv Date:	08/16/2000
TSD Site Recv Date:	08/18/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

FLAMINGO CLEANERS (Continued) **1000299848**

TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYC5644653
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	T422NXNJ
Generator Ship Date:	05/20/1999
Trans1 Recv Date:	05/20/1999
Trans2 Recv Date:	05/24/1999
TSD Site Recv Date:	05/26/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYC5193562
Manifest Status:	Not reported
Trans1 State ID:	NYRC2745
Trans2 State ID:	FY22NXNJ
Generator Ship Date:	10/13/1999
Trans1 Recv Date:	10/13/1999
Trans2 Recv Date:	10/18/1999
TSD Site Recv Date:	10/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

FLAMINGO CLEANERS (Continued) **1000299848**

Document ID:	NYC5520745
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	TY22NXNJ
Generator Ship Date:	02/03/1999
Trans1 Recv Date:	02/03/1999
Trans2 Recv Date:	02/08/1999
TSD Site Recv Date:	02/10/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	OHD980587364
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00390
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	CTF0671282
Manifest Status:	Not reported
Trans1 State ID:	NYCR2436
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1998
Trans1 Recv Date:	01/08/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

AH253 **OFF-SITE FLAMINGO CLEANERS** **NY BROWNFIELDS** **S110043637**
SE **149 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1299 ft. **Site 11 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	414661
Acres:	Not reported
HW Code:	C360078A

OFF-SITE FLAMINGO CLEANERS (Continued) **S110043637**

SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/03/2009
Record Updated Date:	03/02/2015
Update By:	DACROSBY
Site Description:	Location: This site is the off-site component of the former Flamingo Dry Cleaners site (C360078). The site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site itself is a one-story commercial building which includes four stores including the vacant dry cleaners. This off-site component is comprised of immediately-surrounding areas. Current Zoning/Uses: Surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a college, a medical facility, and a church. Historical Uses: The on-site building was constructed in 1941 and used for retail. Flamingo Cleaners began operations in 1958 and ran until 2005 when all dry-cleaning equipment was removed. On-site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). A referral for off-site work was completed in December 2007 and a SSF RI/FS Work assignment was approved in March 2009. The RI field work was conducted in the summer of 2009 and fall of 2009. Additional round of gw analyses occurred in spring 2010. The on-going off-site investigation thus far indicates that PCE is not present in environmental media above standards in the area surrounding the site.Site Geology/Hydrogeology: The area surrounding the site is underlain by glacial till which sit atop highly weathered bedrock. Area bedrock ranges from 5-25 feet below ground surface. The water table ranges from 5-11 feet below ground surface. Groundwater flow direction is dominantly to the south-southwest toward Long Island Sound, but site specific groundwater flow direction is radial and seasonally affected.(1/13)
Env Problem:	Nature and Extent of Contamination: Based on investigations to date, the primary contaminant of concern at the site is tetracholoroethylene (PCE), a dry cleaning solvent. On-site, PCE has been detected in soils, soil vapor, indoor air, and groundwater. The off-site investigation to date indicates that there are no off-site impacts. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.
Health Problem:	Not reported

AP254 **MAY PARTNERS, LLC** **NY AST** **A100355569**
NNW **35-45 MAY STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.247 mi.
1306 ft. **Site 1 of 2 in cluster AP**

Relative:
Lower

Actual:
79 ft.

WESTCHESTER CO. AST:

PBS Number:	3-600544
Site Status:	Active
GDS Number:	Not reported
Operator Name:	May Partners, LLC
Owner Name:	May Partners, LLC c/o Andover Properties
Owner Street:	25 East Spring Valley Avenue, Suite 280
Owner Address2:	Not reported
Owner City/State/Zip:	Maywood, NJ 07607

MAY PARTNERS, LLC (Continued) **A100355569**

Tank Number:	001
Status:	5. Closed - removed
Date Installation:	Not reported
Capacity:	4800
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	Not reported
Tank Location:	4. Aboveground: w/ 10% or more below ground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	5000
Product Stored:	2. No. 4 fuel oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	0. None

AM255 **FIREHOUSE** **NY LTANKS** **S103037428**
ENE **HARRISON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.252 mi.
1332 ft. **Site 9 of 9 in cluster AM**

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	252028
Spill Number/Closed Date:	9713840 / 1998-03-27
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

FIREHOUSE (Continued) **S103037428**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	FRANK GALELLO
Spiller Phone:	(914) 654-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED. SYSTEM PASSED. NFA"
Remarks:	""

Material:

Site ID:	252028
Operable Unit ID:	1059801
Operable Unit:	01
Material ID:	324831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	252028
Spill Tank Test:	1545673
Tank Number:	2
Tank Size:	5000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported

FIREHOUSE (Continued) **S103037428**

Test Method: Horner EZ Check I or II

AL256 **BERGMAN REALTY SERVICES** **NY LTANKS** **S106972591**
ENE **140 HUGUENOT STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.253 mi.
1334 ft. **Site 6 of 6 in cluster AL**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Site ID:	350100
Spill Number/Closed Date:	0505137 / 2007-11-07
Spill Date:	2005-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	WCDOH
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2007-11-07
Spiller Name:	STEVE RING
Spiller Company:	RING HOME
Spiller Address:	140 HUGINOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVE RING
Spiller Phone:	(732) 855-8600
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	296544
DEC Memo:	"10/13/05 Closure letter sent to the RP from Danielle Jackson of the WCHD based on information submitted in a tank closure report. NFA TG"
Remarks:	""

Material:

Site ID:	350100
Operable Unit ID:	1107682
Operable Unit:	01
Material ID:	2097572
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

BERGMAN REALTY SERVICES (Continued) **S106972591**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 350100
Spill Tank Test: 1549133
Tank Number: 1
Tank Size: 10000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AQ257 **BLESSED SACREMENT CHURCH** **NY LTANKS** **S105996474**
South **15 SHEA PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1393 ft. **Site 1 of 3 in cluster AQ**

Relative:
Higher

Actual:
97 ft.

LTANKS:
Site ID: 167332
Spill Number/Closed Date: 0204856 / 2003-10-03
Spill Date: 2002-08-07
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-08-07
CID: 211
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-08-07
Spill Record Last Update: 2003-12-09
Spiller Name: Not reported
Spiller Company: BLESSED SACREMENT CHURCH
Spiller Address: 15 SHEA PL
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 140984
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

BLESSED SACREMENT CHURCH (Continued) **S105996474**

WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."

Remarks: "DRY LEAK"

Material:

Site ID:	167332
Operable Unit ID:	856138
Operable Unit:	01
Material ID:	519078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	167332
Spill Tank Test:	1527358
Tank Number:	1
Tank Size:	2000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AO258 **APARTMENT BLDG.** **NY LTANKS** **S104950549**
West **114 UNION AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1395 ft. **Site 2 of 3 in cluster AO**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	238808
Spill Number/Closed Date:	9414493 / 1995-02-14
Spill Date:	1995-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-02-06
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-03-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"ESTIMATED WRONG TANK SIZE SPILL CONTAINED NATL.ENVIR.CO. SPILL CREW ON WAY ENV PROD. AND SERVICES HIRED TO CLEAN UP. WILL EXCAVATE DRYWELL."

Material:

Site ID:	238808
Operable Unit ID:	1012066
Operable Unit:	01
Material ID:	373228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	175.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	151446
Spill Number/Closed Date:	0011198 / 2001-04-06
Spill Date:	2001-01-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-14
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-14
Spill Record Last Update:	2001-04-24
Spiller Name:	Not reported
Spiller Company:	ALBINO FUELS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128711
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE SEE ONE PAGE UDATE BY V. MCCABE 04/06/2001 NORTHEAST COMPLETED CLEANUP. DISPOSED OF 4 DRUMS OF CONTAMINATION. SPILL INFORMATION FORWARDED TO LAW ENFORCEMENT FOR FURTHER ACTION. SPILLS - NO FURTHER ACTION."
Remarks:	"tank overfilled caused spill - spill is contained in a parking lot spiller is - albano fuel - 667-0900 (914)-clean up crew on site at this time"

Material:

Site ID:	151446
Operable Unit ID:	832582
Operable Unit:	01
Material ID:	541520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9414511
Facility Type:	ER
DER Facility ID:	196552
Site ID:	238809
DEC Region:	3
Spill Date:	1995-02-02
Spill Number/Closed Date:	9414511 / 1995-02-13
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-02-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-02-13
Spiller Name:	Not reported
Spiller Company:	REGENT OIL
Spiller Address:	53 CHARLES STREET
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SPILLER MAKING DELIVERY FILLED WRONG HOLE FD & CLEAN UP CREW ON SCENE TANK OVERFILL EP & S HIRED BY SPILLER AND ON SCENE CONTACTED WCHD WILL RESPOND SEE SPILL #94-14493"

Material:

Site ID:	238809
Operable Unit ID:	1008085
Operable Unit:	01
Material ID:	373246
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AP259 **DIMATTOE TTF** **NY LTANKS** **S113820294**
NNW **55 MAY STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.267 mi.
1409 ft. **Site 2 of 2 in cluster AP**

Relative:
Lower

Actual:
79 ft.

LTANKS:

Site ID:	482303
Spill Number/Closed Date:	1301890 / 2013-08-08
Spill Date:	2013-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party.

DIMATTOE TTF (Continued) **S113820294**

	Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2013-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-23
Spill Record Last Update:	2013-08-08
Spiller Name:	Not reported
Spiller Company:	DIMATTOE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	AMELIO DIMATTOE
Spiller Phone:	(914) 403-1942
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	437556
DEC Memo:	"5/23/13 left message on homeowner's phone. Spoke to Kathy, at US Tank Tech Tank is 1000 gal. Real estate transaction, and plans are to retest. dw 07/31/13 Northeast Environmental reported that they cut & cleaned the tank and obtained a soil sample from beneath the tank. The soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"repair/retest pending"

Material:

Site ID:	482303
Operable Unit ID:	1232041
Operable Unit:	01
Material ID:	2230831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	482303
Spill Tank Test:	2493480
Tank Number:	1
Tank Size:	1000
Test Method:	21
Leak Rate:	.70
Gross Fail:	Not reported

DIMATTOE TTF (Continued) **S113820294**

Modified By: jbodee
Last Modified: Not reported
Test Method: Horner EZY3/EZY3 Locator Plus

260
East
1/4-1/2
0.268 mi.
1414 ft.

CITY OF NEW ROCHELLE FIRE **NY LTANKS** **S105995871**
1 HARRISON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
72 ft.

LTANKS:

Site ID:	75380
Spill Number/Closed Date:	0201696 / 2002-09-18
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE FIRE DEPT
Spiller Address:	1 HARRISON STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	FRANK GALLELLO-FIRE DEPT
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70557
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST.PBS 3-600407 "

Material:

Site ID:	75380
Operable Unit ID:	854864
Operable Unit:	01
Material ID:	523106
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

CITY OF NEW ROCHELLE FIRE (Continued) **S105995871**

Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 75380
Spill Tank Test: 1527133
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AN261 **CUMBERLAND FARM** **NY LTANKS** **1000553075**
SSW **635 MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.269 mi.
1419 ft. **Site 4 of 4 in cluster AN**

Relative:
Higher

Actual:
85 ft.

LTANKS:
Site ID: 140421
Spill Number/Closed Date: 9206930 / 2005-03-11
Spill Date: 1992-09-16
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 6010
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1992-09-16
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2005-03-12
Spiller Name: Not reported
Spiller Company: EXXON
Spiller Address: Not reported
Spiller City,St,Zip: WESTBURG, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 119925

CUMBERLAND FARM (Continued) **1000553075**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/11/05 per contractors report 7 tanks removes all in good condition (no evidence of holes or cracks; no detect in post excavation samples--close "
Remarks: "DURING TANK REMOVAL CONTAMINATED SOIL DISCOVERED WILL TEST"

Material:
Site ID: 140421
Operable Unit ID: 970699
Operable Unit: 01
Material ID: 407611
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

SPILLS:
Facility ID: 1405322
Facility Type: ER
DER Facility ID: 119925
Site ID: 498745
DEC Region: 3
Spill Date: 2014-08-15
Spill Number/Closed Date: 1405322 / Not Reported
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2014-08-15
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 2014-08-15
Spill Record Last Update: 2016-02-09
Spiller Name: Not reported
Spiller Company: CUMBERLAND FARMS 70288
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999

CUMBERLAND FARM (Continued) **1000553075**

Contact Name:	JOHN
Contact Phone:	Not reported
DEC Memo:	"8-15-14 Spoke with Angela Pimento at CF. She will have John return call to dispatch desk. jm Recv'd callback from Chris Lalak - WCDOH. He has spoken with John. Double wall fiberglass piping from dispensers to tanks. Leak is contained in tanktop sump. System has has been shut down at this time until they figure out what they are going to do. They believe they will probably replace lines. Chris says no leak to environment and he will be taking lead. jm 5-15 new spill 15-01325; Phase 2report 10-15-15 email status request sent to WCHD & Cumby RDB 10-22-15, from Cumby In response to the line failure, CFI engaged Island Pump & Tank (IPT) to perform the repairs. In lieu of replacing the product piping, IPT installed a siphon bar on the regular tanks and removed the submersible pump from the regular tank that had the failed product piping. IPT then removed and capped the regular product piping that had failed. The secondary line was tested and the dispenser pans and STP sumps were hydrostatically tested and passed. RDB 2-16 new SPills 15-10746"
Remarks:	"spill to containment/clean up complete"

Material:

Site ID:	498745
Operable Unit ID:	1248186
Operable Unit:	01
Material ID:	2249583
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0514511
Facility Type:	ER
DER Facility ID:	119925
Site ID:	361248
DEC Region:	3
Spill Date:	2006-03-20
Spill Number/Closed Date:	0514511 / 2006-03-20
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RXAMATO
Referred To:	WCDOH
Reported to Dept:	2006-03-20
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

CUMBERLAND FARM (Continued) **1000553075**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-31
Spiller Name:	MELISSA GLIDEN
Spiller Company:	CUMBERLAND FARM
Spiller Address:	635 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
Contact Phone:	(800) 225-9702 3412
DEC Memo:	"03/21/06: Closed - NFA R. Amato"
Remarks:	"water in the dispenser pan and tyree enroute to clean up"

Material:

Tank Test:

---

262 **NEW ROCHELLE CATH MIDDLE** **NY LTANKS** **S102154123**
South **24 MAPLE AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.270 mi.
1425 ft.

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	80066
Spill Number/Closed Date:	0204857 / 2003-10-03
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE CATH MIDDLE
Spiller Address:	24 MAPLE AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARV
Spiller Phone:	(914) 637-7505

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 74246
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks: ""

Material:
Site ID: 80066
Operable Unit ID: 856140
Operable Unit: 01
Material ID: 519079
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 80066
Spill Tank Test: 1527359
Tank Number: 1
Tank Size: 2000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 9111148
Facility Type: ER
DER Facility ID: 107755
Site ID: 124421
DEC Region: 3
Spill Date: 1992-01-29
Spill Number/Closed Date: 9111148 / 1992-03-17
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6010
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1992-01-29
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: 1992-02-05

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Cleanup Meets Std:	True
Last Inspection:	1992-02-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-30
Spill Record Last Update:	1992-03-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"OIL DISCOVERED SEEPING OUT OF GROUND/BLACKTOP WALKWAY (BETWEEN SCHOOL AND BEAUTY SALON) SUSPECT BROKEN RETURN LINE APPROX 30' FROM TANK TO BURNER - 2K TANK AL EASTMAN TO EIR CASTLE OIL CREW ENROUTE"

Material:

Site ID:	124421
Operable Unit ID:	964875
Operable Unit:	01
Material ID:	416206
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9008354
Facility Type:	ER
DER Facility ID:	107755
Site ID:	124420
DEC Region:	3
Spill Date:	1990-10-30
Spill Number/Closed Date:	9008354 / 1990-11-26
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-10-31
Cleanup Meets Std:	True
Last Inspection:	1990-10-31

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-06
Spill Record Last Update:	1990-11-26
Spiller Name:	Not reported
Spiller Company:	CASTLE FUEL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE BURST DURING DELIVERY WC FIRE CONTROL ON SCENE ABSORBANT PADS HAVE BEEN PUT DOWN CHIEF MCCAFFREY CONTACTED BUT HE WASN'T ON SCENE HAS NO INFO."

Material:

Site ID:	124420
Operable Unit ID:	945552
Operable Unit:	01
Material ID:	432188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AR263 **COMMERCIAL PROPERTY** **NY LTANKS** **S112810152**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1442 ft. **Site 1 of 3 in cluster AR**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	476407
Spill Number/Closed Date:	1213228 / 2013-02-04
Spill Date:	2012-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-12-10
CID:	Not reported
Water Affected:	Not reported

COMMERCIAL PROPERTY (Continued) **S112810152**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-10
Spill Record Last Update:	2013-02-04
Spiller Name:	Not reported
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	HAL SHAPIRO
Spiller Phone:	(914) 355-5350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"12-10-12 PBS site. Tank failed with popping. US Tank Tech has been testing since '98. Super was at site during test and Shapiro notified by phone. jc 12/19/12: Update from WCDoH PBS: >>> Lalak, Chris >>cjl1@westchestergov.com> 12/11/2012 4:23 PM >>> 1213228 38 Locust, new Rochelle PBS 3-800080 TTF 3K tank from 84 Tyra/Carlos Lead jod 2/4/2013: Tank passed a retest after piping was repaired. Report entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"1211 THE CALLER IS REPORTING A FAILED TANK TEST."

Material:

Site ID:	476407
Operable Unit ID:	1226235
Operable Unit:	01
Material ID:	2223616
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AR264 **COMMERCIAL SITE** **NY LTANKS** **U003857828**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1442 ft. **Site 2 of 3 in cluster AR**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	239569
Spill Number/Closed Date:	0206043 / 2002-09-26
Spill Date:	2002-09-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

COMMERCIAL SITE (Continued) **U003857828**

Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-10-29
Spiller Name:	BARRY SHAPIRO
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	38 LOCUST AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	""
Remarks:	"RECOMMENDATION IS TO UNCOVER - REPAIR - AND RE-TEST."

Material:

Site ID:	239569
Operable Unit ID:	857630
Operable Unit:	01
Material ID:	571516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	239569
Spill Tank Test:	1527440
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

COMMERCIAL SITE (Continued) **U003857828**

Site ID:	333366
Spill Number/Closed Date:	0408593 / 2005-02-13
Spill Date:	2004-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-11-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-05
Spill Record Last Update:	2005-02-13
Spiller Name:	BARRY SHAPIRO
Spiller Company:	COMMERCIAL SITE
Spiller Address:	38 LOCUS AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"02/13/05 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-800080 "

Material:

Tank Test:

AS265 **SPILL NUMBER 0208792** **NY LTANKS** **S105997404**
NNW **386 NORTH AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.275 mi.
1452 ft. **Site 1 of 5 in cluster AS**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	71430
Spill Number/Closed Date:	0208792 / 2002-11-26
Spill Date:	2002-11-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported

SPILL NUMBER 0208792 (Continued) **S105997404**

Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-11-26
Spiller Name:	ROBERT CRIILLO
Spiller Company:	WILCO
Spiller Address:	95 PLAIN AV
Spiller City,St,Zip:	NEWROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	CARTER RESIDENCE
Spiller Phone:	(914) 632-6577
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67588
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 SPILL CLEANUP TO BE COMPLETED TOMORROW."
Remarks:	"take pride environmental enroute to clean up the soil"

Material:

Site ID:	71430
Operable Unit ID:	861979
Operable Unit:	01
Material ID:	515786
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AT266 **DEMELIA - TTF** **NY LTANKS** **S117364514**
West **95 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.275 mi.
1453 ft. **Site 1 of 2 in cluster AT**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	500408
Spill Number/Closed Date:	1406916 / 2015-04-14
Spill Date:	2014-10-01
Spill Cause:	Tank Test Failure

DEMELIA - TTF (Continued) **S117364514**

Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-01
Spill Record Last Update:	2015-04-14
Spiller Name:	ROSEMARIE DEMELIA
Spiller Company:	Estate of DeMelia
Spiller Address:	95 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455413
DEC Memo:	"This house is the estate of R Demellia's late mother. Tank failed with only hissing, maybe a line leak but cant be sure. House is being prep'ed for sale....mm 12/08/14: From Envirostar: We pulled a 550 UST at 95 Washington Ave New Rochelle that had previously failed a tank test (spill # 1406916). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Chuck LiVecchi 95 Washington Ave New Rochelle NY jod 3/20/15: Update from Envirostar via email: We removed 6 containers of contaminated soil Between march 12th and yesterday we took samples and back filled the hole. We will Submit for closure. jod 4/13/15: Report with request for closure entered into DecDocs. Post-Ex soil samples show contamination in excess of CP-51 Guidance. Additional information being requested from Envirostar. jod 4/14/2015: Envirostar removed and disposed of the leaking UST and a total of 108.96 tons of petroleum contaminated soil. Some residual contamination over CP-51 Guidance could not be excavated from along the foundation and due to safety concerns with buried utility lines. No evidence of ground water impact noted. Based upon information provided, no further action required at this time. jod"
Remarks:	"550 test failure"

Material:

Site ID:	500408
Operable Unit ID:	1249816
Operable Unit:	01
Material ID:	2251444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

DEMELIA - TTF (Continued) **S117364514**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	500408
Spill Tank Test:	2496432
Tank Number:	1
Tank Size:	550
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AQ267 **BLESSED SACRAMENT HIGH SC** **NY LTANKS** **S106385926**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.278 mi.
1466 ft. **Site 2 of 3 in cluster AQ**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Site ID:	249284
Spill Number/Closed Date:	0400709 / 2004-07-06
Spill Date:	2004-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-04-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-21
Spill Record Last Update:	2004-07-06
Spiller Name:	LARRY HANSEN
Spiller Company:	BLESSED SACRAMENT HIGH SC
Spiller Address:	24 SHEA PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LARRY HANSEN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

DEC Region: 3
DER Facility ID: 204413
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 07/06/04 TANK PASSED RETEST."
Remarks: "FAILED SUBLINGS RECOMMEND UNCOVER REPAIR & RETEST OR REMOVE: "

Material:
Site ID: 249284
Operable Unit ID: 884909
Operable Unit: 01
Material ID: 491955
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 249284
Spill Tank Test: 1529181
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

AQ268 **BLESSED SACRAMENT HS** **NY LTANKS** **S113494296**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.278 mi.
1466 ft. **Site 3 of 3 in cluster AQ**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Site ID: 481320
Spill Number/Closed Date: 1300960 / Not Reported
Spill Date: 2013-04-29
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 6010
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2013-04-29
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester

BLESSED SACRAMENT HS (Continued) **S113494296**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-04-29
Spill Record Last Update:	2013-08-05
Spiller Name:	ED SULLIVAN
Spiller Company:	HIGH SCHOOL
Spiller Address:	24 SHEA PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ED SULLIVAN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"This is a 1K ust. Testing done every year. Appears to be a piping problem, will uncover, repair and retest. WCDOH has been notified....mm 8/5/13 Failed retest. Spoke to Kathy Morgan at US Tank Test. dw "
Remarks:	"tank test failure"

Material:

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2230143
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2229789
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	481320
Spill Tank Test:	2493383
Tank Number:	0
Tank Size:	1000
Test Method:	21

BLESSED SACRAMENT HS (Continued) **S113494296**

Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

---

269 **RESIDENCE** **NY LTANKS** **S106971497**
SSE **64 CHURCH ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.281 mi.
1486 ft.

Relative:
Higher

Actual:
86 ft.

LTANKS:

Site ID:	333255
Spill Number/Closed Date:	0408510 / 2008-05-01
Spill Date:	2004-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-02
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-02-16
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2008-05-01
Spiller Name:	RAMONE OCEGUERA
Spiller Company:	Not reported
Spiller Address:	64 CHURCH ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RAMONE OCEGUERA
Spiller Phone:	(914) 396-7293
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268502
DEC Memo:	"11/22/04 AST ON GROUND UNDER DECK. TANK LOST APPROX 150 GALLONS AFTER TEST. FREE PRODUCT IN SUMP PIT IN BASEMENT. FURTHER INVESTIGATION TO BE DONE BY ADVANCED ENVIRONMENTAL. jod 5/1/2008: Advanced Environmental disposed of LUST and 26.15 tons of contaminated soil. Ground water was impacted and sampled. Spill closure report from ECC submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"tank test failed."

Material:

RESIDENCE (Continued) **S106971497**

Site ID:	333255
Operable Unit ID:	1095424
Operable Unit:	01
Material ID:	575563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	333255
Spill Tank Test:	1548304
Tank Number:	1
Tank Size:	275
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AU270 **CANDREA/GALLETTA RESIDENCE** **NY LTANKS** **S112148789**
WSW **35 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.287 mi.
1517 ft. **Site 1 of 2 in cluster AU**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	465083
Spill Number/Closed Date:	1202322 / 2012-09-13
Spill Date:	2012-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-07
Spill Record Last Update:	2012-09-13

CANDREA/GALLETTA RESIDENCE (Continued) **S112148789**

Spiller Name:	Not reported
Spiller Company:	GALETTA
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	GALETTA
Spiller Phone:	914-497-9141
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	419452
DEC Memo:	"6-7-12 Kathy already notified owner. Spoke with Anthony, owners son-in-law. Told him to forward passing retest to office for spill to be closed. He asked for email to that affect. I sent. jc 6/18/12- US Tank reports that retest failed. Unknown further action. DT 09/13/12 Castlton Environmental reported that they excavated and removed the tank along with 21.04 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"550 gal ust"

Material:

Site ID:	465083
Operable Unit ID:	1215116
Operable Unit:	01
Material ID:	2213205
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AO271 **SPILL NUMBER 0007965** **NY LTANKS** **S104782459**
WSW **45 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.290 mi.
1530 ft. **Site 3 of 3 in cluster AO**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	61314
Spill Number/Closed Date:	0007965 / 2000-10-26
Spill Date:	2000-10-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-06

SPILL NUMBER 0007965 (Continued) **S104782459**

CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-06
Spill Record Last Update:	2000-11-07
Spiller Name:	Not reported
Spiller Company:	ALBANO FUEL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	ALBANO FUEL
Spiller Phone:	(914) 667-0900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/26/2000 TRI-STATE COMPLETED CLEANUP AFTER DEC INSPECTION. INITIAL SPILL BY ALBANO FUEL WAS NEVER REPORTED. NFA"
Remarks:	"SPILL OCCURRED DURING FILL. TRI STATE WAS CONTRACTED FOR CLEAN UP."

Material:

Site ID:	61314
Operable Unit ID:	830442
Operable Unit:	01
Material ID:	545482
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV272 **RUSH MFG. CORP.** **CORRACTS** **1000201737**
SW **10-12 PINE CT** **RCRA-CESQG** **NYD075436394**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY Spills**
0.291 mi. **FINDS**
1535 ft. **Site 1 of 4 in cluster AV** **NJ MANIFEST**
RI MANIFEST
Relative: **NY MANIFEST**
Lower **ECHO**

Actual: CORRACTS:
56 ft.

EPA ID:	NYD075436394
EPA Region:	02
Area Name:	SITEWIDE

RUSH MFG. CORP. (Continued) **1000201737**

Actual Date: 19940503
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: NYD075436394
EPA Region: 02
Area Name: SITEWIDE
Actual Date: 19920922
Action: CA050 - RFA Completed
NAICS Code(s): 336413 332999 336413
Other Aircraft Parts and Auxiliary Equipment Manufacturing
All Other Miscellaneous Fabricated Metal Product Manufacturing
Other Aircraft Parts and Auxiliary Equipment Manufacturing
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: RUSH MANUFACTURING CORP
Facility address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
EPA ID: NYD075436394
Mailing address: PINE CT
NEW ROCHELLE, NY 10801
Contact: DENNIS MCNAMARA
Contact address: PINE CT
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (914) 636-2700
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: TELEDYNE HYDRA-POWER

RUSH MFG. CORP. (Continued) **1000201737**

Owner/operator address: 10-12 PINE COURT
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: (914) 632-2200
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RUSH MANUFACTURING CORP
Owner/operator address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (914) 636-2700
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/09/1997
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE

RUSH MFG. CORP. (Continued) **1000201737**

SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 02/25/1992
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980
Site name: RUSH MANUFACTURING CORP
Classification: Not a generator, verified

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

RUSH MFG. CORP. (Continued) **1000201737**

SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 12/31/1979
Site name: RUSH MANUFACTURING CORP
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 09/22/1992
Event: RFA Completed

Event date: 05/03/1994
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/26/1990
Date achieved compliance: 05/02/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/12/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/23/1989
Date achieved compliance: 05/12/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/16/1988
Date achieved compliance: 11/17/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/09/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/27/1987
Date achieved compliance: 11/17/1988
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/19/1986
Date achieved compliance: 05/27/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/15/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Area of violation: Generators - General
Date violation determined: 02/23/1984
Date achieved compliance: 10/07/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/27/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/26/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/02/1990
Evaluation lead agency: State

Evaluation date: 02/23/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/12/1989
Evaluation lead agency: State

Evaluation date: 03/16/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: State

Evaluation date: 03/11/1988
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/17/1988
Evaluation lead agency: EPA

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/27/1986
Evaluation lead agency: State

Evaluation date: 02/23/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/07/1985
Evaluation lead agency: State

SPILLS:

RUSH MFG. CORP. (Continued) **1000201737**

Facility ID:	0901536
Facility Type:	ER
DER Facility ID:	350696
Site ID:	413531
DEC Region:	3
Spill Date:	2009-05-07
Spill Number/Closed Date:	0901536 / 2009-06-22
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-06-22
Spiller Name:	Not reported
Spiller Company:	ALPHA MEDICAL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	NIKI
Contact Phone:	(914) 777-1930
DEC Memo:	"5/7/09 At a construction site, contaminated soils were encountered, which was confirmed by soil tests done by Northeast. They will be doing the site remediation and will submit a cleanup report. dw 06/12/09 Northeast Environmental provided oversight activity when petroleum impacted soil was discovered and need to be removed. Remediation consisted of the removal of 425.66 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were all below DEC guidance values. NFA required. TG"
Remarks:	"1231 The caller advised dispatch North East Environmental will conduct the clean up. The caller requested a call back. No water ways affected."

Material:

Site ID:	413531
Operable Unit ID:	1169955
Operable Unit:	01
Material ID:	2161660
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Oxygenate: Not reported

Tank Test:

Facility ID:	0804532
Facility Type:	ER
DER Facility ID:	350696
Site ID:	401456
DEC Region:	3
Spill Date:	2008-07-21
Spill Number/Closed Date:	0804532 / 2008-09-26
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-21
Spill Record Last Update:	2008-09-26
Spiller Name:	MICHEAL
Spiller Company:	COMMERCIAL MACHINE SHOP
Spiller Address:	10-12 PINE COURT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MICHEAL
Contact Phone:	(845) 561-1512
DEC Memo:	"08/01/08 Conklin Services & Construction submitted a Limited Subsurface Investigation Report. Four geoprobe borings were placed around an abandoned tank. Slight soil contamination exists in borings 1 and 2, however the levels are below DEC TAGM guidance values. NFA TG"
Remarks:	"SOIL BORINGS SHOWED CONTAMINATED SHOP"

Material:

Site ID:	401456
Operable Unit ID:	1158245
Operable Unit:	01
Material ID:	2149301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

RUSH MFG. CORP. (Continued) **1000201737**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

FINDS:

Registry ID: 110009468343

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

EPA Id:	NYD075436394
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001619722SKS
EPA ID:	NYD075436394
Date Shipped:	02/23/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/26/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	002115978SKS
EPA ID:	NYD075436394
Date Shipped:	10/01/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	5 G

Manifest Number:	001803673SKS
EPA ID:	NYD075436394
Date Shipped:	05/08/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001811141SKS
EPA ID:	NYD075436394
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 8 G

Manifest Number: 002486638SKS
EPA ID: NYD075436394
Date Shipped: 01/29/2010
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/01/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H020
Quantity: 7 G

RUSH MFG. CORP. (Continued) **1000201737**

Manifest Number:	000266181CEX
EPA ID:	NYD075436394
Date Shipped:	10/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	9 G

Manifest Number:	001632477SKS
EPA ID:	NYD075436394
Date Shipped:	01/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001819324SKS
EPA ID:	NYD075436394
Date Shipped:	07/16/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

RI MANIFEST:

EPA Id:	NYD075436394
Manifest Document Number:	CTC0168898
GEN Cert Date:	10/7/1991
TSDF Id:	CTD021816889
TSDF Name:	UNITED
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Transporter 2 Name:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported

Details:

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991

RUSH MFG. CORP. (Continued) **1000201737**

Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Waste Description:	OIL
Quantity:	575
WT/Vol Units:	G
Item Number:	1
Transporter Name:	SEALAND
Transporter EPA ID:	CTD983872748
GEN Cert Date:	10/7/1991
Transporter Receipt Date:	Not reported
Transporter 2 Receipt Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported

NY MANIFEST:

EPA ID:	NYD075436394
Country:	USA
Location Address 1:	10-12 PINE COURT
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	6908

Mailing Info:

Name:	TELEDYNE HYDRA-POWER INC
Contact:	MARCY LATELLA
Address:	10-12 PINE COURT
City/State/Zip:	NEW ROCHELLE, NY 10801 6908
Country:	USA
Phone:	914-636-2700

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/2009
Trans1 Recv Date:	10/01/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	5.0
Units:	G - Gallons (liquids only)* (8.3 pounds)

RUSH MFG. CORP. (Continued) **1000201737**

Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002115978SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	02/23/2009
Trans1 Recv Date:	02/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	7.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001619722SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2009
Trans1 Recv Date:	07/16/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	8.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001819324SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2009
Trans1 Recv Date:	05/08/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	7.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001803673SKS

RUSH MFG. CORP. (Continued) **1000201737**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	08/31/2009
Trans1 Recv Date:	08/31/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	8.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001811141SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2009
Trans1 Recv Date:	10/30/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2009

RUSH MFG. CORP. (Continued) **1000201737**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD982270506
Waste Code:	Not reported
Quantity:	9.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000266181CEX
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2008
Trans1 Recv Date:	08/22/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/22/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	RID084802842
Waste Code:	Not reported
Quantity:	77.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001491827SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

RUSH MFG. CORP. (Continued) **1000201737**

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: CTD1170550
Manifest Status: Not reported
Trans1 State ID: CTJ71372
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2004
Trans1 Recv Date: 09/14/2004
Trans2 Recv Date: 09/16/2004
TSD Site Recv Date: 09/21/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: CTD002593
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: CTF1045117
Manifest Status: Not reported
Trans1 State ID: CTJ11372
Trans2 State ID: V59864CT
Generator Ship Date: 05/25/2004
Trans1 Recv Date: 05/25/2004
Trans2 Recv Date: 05/26/2004
TSD Site Recv Date: 06/01/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: CTD021816889
Trans2 EPA ID: Not reported
TSDF ID: CTD002593
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: CTF1140188
Manifest Status: Not reported

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 State ID:	CT30006A
Trans2 State ID:	VS9864
Generator Ship Date:	06/23/2003
Trans1 Recv Date:	06/23/2003
Trans2 Recv Date:	06/28/2003
TSD Site Recv Date:	07/07/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	CTD021816889
TSDF ID:	CTD002593887
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	NYC5692522
Manifest Status:	Not reported
Trans1 State ID:	NYDW9495
Trans2 State ID:	CAFT97593
Generator Ship Date:	05/21/2002
Trans1 Recv Date:	05/21/2002
Trans2 Recv Date:	05/29/2002
TSD Site Recv Date:	06/01/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	MOD095038998
TSDF ID:	KYD053348108
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NJA4016263
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2001
Trans1 Recv Date:	12/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/12/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA3218557
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	07/26/2001
Trans1 Recv Date:	07/26/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00453
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA3218563
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2001
Trans1 Recv Date:	10/10/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.

RUSH MFG. CORP. (Continued) **1000201737**

Specific Gravity: 01.00
Year: 2001

Document ID: NJA3163834
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 06/14/2001
Trans1 Recv Date: 06/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00430
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NJA3051384
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: H10364
Generator Ship Date: 11/08/2000
Trans1 Recv Date: 11/08/2000
Trans2 Recv Date: 11/09/2000
TSD Site Recv Date: 11/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD075436394
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: SCR000074591
TSDF ID: NJD002182897
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00127
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NJA3084154
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: H10364
Generator Ship Date: 08/03/2000

RUSH MFG. CORP. (Continued) **1000201737**

Trans1 Recv Date:	08/03/2000
Trans2 Recv Date:	08/07/2000
TSD Site Recv Date:	08/09/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00435
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA2819479
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	02/10/2000
Trans1 Recv Date:	02/10/2000
Trans2 Recv Date:	02/14/2000
TSD Site Recv Date:	02/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID:	NJD002182897
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA3009958
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	05/12/1999
Trans1 Recv Date:	05/12/1999
Trans2 Recv Date:	05/13/1999
TSD Site Recv Date:	05/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	NJD002182897

RUSH MFG. CORP. (Continued) **1000201737**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00435
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	1999

Document ID:	NJA2839958
Manifest Status:	Not reported
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	04/21/1998
Trans1 Recv Date:	04/21/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/21/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075436394
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

ECHO:

Envid:	1000201737
Registry ID:	110009468343
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110009468343

AV273 **GKIDS REALTY** **NY LTANKS** **S105995601**
SW **10/12 PINE COURT** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.291 mi.
1535 ft. **Site 2 of 4 in cluster AV**

Relative:
Lower

Actual:
56 ft.

LTANKS:

Site ID:	235436
Spill Number/Closed Date:	0200337 / 2003-12-09
Spill Date:	2002-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

GKIDS REALTY (Continued) **S105995601**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-04-10
CID:	204
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-10
Spill Record Last Update:	2003-12-10
Spiller Name:	GKIDS REALTY
Spiller Company:	GKIDS REALTY
Spiller Address:	10/12 PINE COURT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MICHAEL GOLD
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193919
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER #2 PBS 3-504998 handled by WCHD 12/09/03 TANK CLOSED IN PLACE, SAMPLE RESULTS BELOW TAGM. SPILL CLOSED BY WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE - RECOMMEND TO ISOLATE PIPING AND RETEST "

Material:

Site ID:	235436
Operable Unit ID:	851333
Operable Unit:	01
Material ID:	525339
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	235436
Spill Tank Test:	1527023
Tank Number:	1
Tank Size:	5000
Test Method:	99
Leak Rate:	.00
Gross Fail:	Not reported

GKIDS REALTY (Continued) **S105995601**

Modified By:	Spills
Last Modified:	Not reported
Test Method:	Alternate Test per 613.5a2v

AT274 **BRAM REALTY** **NY LTANKS** **S109583709**
West **105 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
85 ft.

LTANKS:

Site ID:	414506
Spill Number/Closed Date:	0902464 / 2010-02-01
Spill Date:	2009-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-01
Spill Record Last Update:	2010-02-01
Spiller Name:	HAL SHAPIRO
Spiller Company:	BRAM REALTY
Spiller Address:	105 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	363644
DEC Memo:	"6-1-09: V.Mc.^ Hal/BRAM REALTY: Left Mess: Req.Callbk. to dispt &/or J.O'Dee. 6-3-09: HAL SHAPIRO CALLED AND STATED IS WAS AWARE OF PROPER PROCEDURES TO FOLLOW. HE WILL CONTACT HIS OIL CO. FOR DIRECTION AND NOTIFY DEC OF OUTCOME. 01/25/10 Enviroshield reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was obseved in the tank excavation. NFA TG "
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST UNK IF ANY PRODUCT WAS SPILLED."

Material:

Site ID:	414506
Operable Unit ID:	1170891
Operable Unit:	01

BRAM REALTY (Continued) **S109583709**

Material ID:	2162674
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AU275 **MERLUCCI RESIDENCE** **NY LTANKS** **S111063886**
WSW **30 CHARLES STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 2 in cluster AU**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Site ID:	450778
Spill Number/Closed Date:	1103221 / 2011-11-14
Spill Date:	2011-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-22
Spill Record Last Update:	2011-11-14
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	MR MERLUCCI
Spiller Phone:	(914) 632-2099
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	405335
DEC Memo:	"6/22/11 UST is 62 years old, according to Ms. Merlucci. House is for sale. US Tank Tech has notified Town & Country Oil not evacuate tank prior to further action (repair, retest, tank pull) of owner. dw 11/14/11: UST removed by JM Associates. Report states tank was

MERLUCCI RESIDENCE (Continued) **S111063886**

inspected and no corrosion holes were found. Soil samples taken from tank grave showed minor amounts of contamination, most below CP-51 with a few slight exceedences of SVOCs. Excavation was backfilled. Report will be entered into eDocs. jod"

Remarks: "repair retest pending or removal"

Material:

Site ID:	450778
Operable Unit ID:	1200979
Operable Unit:	01
Material ID:	2197455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AS276 **KGM PROPERTY ASSOC.** **NY LTANKS** **U003647638**
NNW **394 N. AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.295 mi.
1557 ft. **Site 2 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	69270
Spill Number/Closed Date:	9202033 / 1993-01-27
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1993-01-27
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-20
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ

KGM PROPERTY ASSOC. (Continued) **U003647638**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65872
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK IS 38 YEARS OLD THIS TANK WAS ORIGINAL REPORTED UNDER #9201744 BUT IS LOCATED AT DIFFERENT ADDRESS PETRO-TITE -.422 GPH"

Material:

Site ID:	69270
Operable Unit ID:	966124
Operable Unit:	01
Material ID:	557154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	69270
Spill Tank Test:	1540014
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AS277 **KGM REALTY CO.** **NY LTANKS** **S100493525**
NNW **396 NORTH AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.297 mi.
1566 ft. **Site 3 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	89642
Spill Number/Closed Date:	9201744 / 1993-01-27
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1993-01-27
Cleanup Meets Standard:	False
SWIS:	6010

KGM REALTY CO. (Continued) **S100493525**

Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-13
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK #1 IS 64 YEARS OLD AND TANK #2 IS 38 YEARS OLD WILL EIR TANK #2 NEXT WEEK"

Material:

Site ID:	89642
Operable Unit ID:	969160
Operable Unit:	01
Material ID:	413039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	89642
Spill Tank Test:	1539987
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AS278 **GETTY# 677** **NY LTANKS** **S103482965**
NNW **381 NORTH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.299 mi.
1577 ft. **Site 4 of 5 in cluster AS**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	242546
Spill Number/Closed Date:	0400912 / 2005-01-18
Spill Date:	2004-04-27
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-04-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-27
Spill Record Last Update:	2005-01-18
Spiller Name:	STEVEN PHELTS
Spiller Company:	GETTY# 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	STEVEN PHELTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 1/18/2005 close and handle under existing spill 9003146 "
Remarks:	"FOUND CONTAMINATED SOIL WHILE REMOVING TANK: "

Material:

Site ID:	242546
Operable Unit ID:	882894
Operable Unit:	01
Material ID:	555170
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

SPILLS:

Facility ID:	1012947
Facility Type:	ER
DER Facility ID:	401849
Site ID:	447247
DEC Region:	3
Spill Date:	2011-03-29
Spill Number/Closed Date:	1012947 / 2011-03-31
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6038
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2011-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-29
Spill Record Last Update:	2011-03-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 786-4945
DEC Memo:	"3-29-11 Called and left message for Mike to return call to dispatch desk. jm 3-31-11 Spoke with Mike. Spill was as stated and cleanup completed. jm"
Remarks:	"contained to bay floor, clean up"

Material:

Site ID:	447247
Operable Unit ID:	1197384
Operable Unit:	01
Material ID:	2193703
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	1005811
Facility Type:	ER
DER Facility ID:	199318
Site ID:	439142
DEC Region:	3
Spill Date:	2010-08-25
Spill Number/Closed Date:	1005811 / 2010-08-25
Spill Cause:	Housekeeping
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-08-25
Spill Record Last Update:	2010-08-25
Spiller Name:	MIKE CARR
Spiller Company:	GETTY
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"8/25/10 Confirmed clean up with caller, nfa...mm"
Remarks:	"Caller stated they had spilt waste oil on concrete, Are has been cleaned up."

Material:

Site ID:	439142
Operable Unit ID:	1189791
Operable Unit:	01
Material ID:	2184749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	1001015
Facility Type:	ER
DER Facility ID:	199318
Site ID:	433723
DEC Region:	3
Spill Date:	2010-04-27
Spill Number/Closed Date:	1001015 / 2010-04-27
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2010-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-04-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-05-10
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CARRIE WILSEY
Contact Phone:	(518) 786-3200
DEC Memo:	"4/27/10 - Spill cleaned up. NFA. KAB 5/10/10: Update from Denise Heinzinger of WCDOH who inspected: #1001015 small spill onto concrete at 381 North Ave, New Rochelle, clean up performed jod"
Remarks:	"1 pint onto concrete. Clean up complete"

Material:

Site ID:	433723
Operable Unit ID:	1184583
Operable Unit:	01
Material ID:	2178854
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

GETTY# 677 (Continued) **S103482965**

Tank Test:

Facility ID:	0912229
Facility Type:	ER
DER Facility ID:	199318
Site ID:	425106
DEC Region:	3
Spill Date:	2010-02-23
Spill Number/Closed Date:	0912229 / 2010-02-23
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-02-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-23
Spill Record Last Update:	2010-03-30
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"2/23/10 confirmed clean up, nfa...mm"
Remarks:	"HALF GALLON OF WASTE OIL TO CONCRETE CLEAN UP WAS DONE."

Material:

Site ID:	425106
Operable Unit ID:	1180837
Operable Unit:	01
Material ID:	2174836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

GETTY# 677 (Continued) **S103482965**

Facility ID:	0900607
Facility Type:	ER
DER Facility ID:	199318
Site ID:	412555
DEC Region:	3
Spill Date:	2009-04-16
Spill Number/Closed Date:	0900607 / 2009-04-16
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RXAMATO
Referred To:	Not reported
Reported to Dept:	2009-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-16
Spill Record Last Update:	2009-04-16
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	CARRIE WILSEY
Contact Phone:	(518) 369-7822
DEC Memo:	"4/17/09: Vac truck pumped out dispenser sump...close/nfa..ra"
Remarks:	"DUE TO POOR HOUSEKEEPING A HALF GALLON OF PRODUCT WAS SPILLED TO CONRETE BAY FLOORS. CLEAN UP WAS DONE."

Material:

Site ID:	412555
Operable Unit ID:	1169019
Operable Unit:	01
Material ID:	2160665
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Gallons
Recovered:	.50
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

AR279 **APT. BUILDING** **NY LTANKS** **S102660713**
ESE **55-59 LOCUST AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.301 mi.
1587 ft. **Site 3 of 3 in cluster AR**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	168647
Spill Number/Closed Date:	9200639 / 1992-06-26
Spill Date:	1992-04-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-05-12
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1992-05-12
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	1998-01-14
Spiller Name:	Not reported
Spiller Company:	N.Y. PROPERTIES CO.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142042
DEC Memo:	""
Remarks:	"TWO UC TANKS WERE BURIED RAIN FORCES OIL UP THROUGH BLACKTOP MGNT. CO.APPLIES SPEEDI-DRY BUT DOES NOT REPORT OR REPAIR"

Material:

Site ID:	168647
Operable Unit ID:	964508
Operable Unit:	01
Material ID:	415419
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

APT. BUILDING (Continued) **S102660713**

Tank Test:

AW280 **BLESSED SACRAMENT CHURCH** **NY LTANKS** **S100165619**
SSE **SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.309 mi.
1629 ft. **Site 1 of 3 in cluster AW**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	324974
Spill Number/Closed Date:	8704259 / 1987-11-20
Spill Date:	1987-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-11-20
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-08-02
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-30
Spill Record Last Update:	1987-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261780
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST. / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST RETEST PASSED.NFA. "
Remarks:	"TTTF-TWO TANKS FAILED"

Material:

Site ID:	324974
Operable Unit ID:	908133
Operable Unit:	01
Material ID:	466902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 324974
Spill Tank Test: 1531452
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Unknown

AX281 **PROFESSIONAL BUILDING COP** **NY LTANKS** **S108982494**
SSW **421 HUGUENOT STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.311 mi.
1642 ft. **Site 1 of 2 in cluster AX**

Relative:
Lower

Actual:
77 ft.

LTANKS:
Site ID: 369299
Spill Number/Closed Date: 0606014 / 2007-01-29
Spill Date: 2006-08-23
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: WCDOH
Reported to Dept: 2006-08-24
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-08-24
Spill Record Last Update: 2007-01-29
Spiller Name: GERRI SEENY
Spiller Company: PROFESSIONAL OFFICE CORP
Spiller Address: 421 HUGUENOT STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: GERRI SEENY
Spiller Phone: (914) 632-3400
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 319185
DEC Memo: "RECOMMENDING ISOLATION. 0606014 - 421 Huguenot St, New Rochelle -

PROFESSIONAL BUILDING COP (Continued) **S108982494**

removed petrometer and remote fill from system and retested, passed. NFA. 10/23/06 test date"
Remarks: ""

Material:
Site ID: 369299
Operable Unit ID: 1127138
Operable Unit: 01
Material ID: 2116724
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 369299
Spill Tank Test: 1550220
Tank Number: 1
Tank Size: 3000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: Not reported
Test Method: Horner EZ Check I or II

SPILLS:
Facility ID: 0711337
Facility Type: ER
DER Facility ID: 319185
Site ID: 392804
DEC Region: 3
Spill Date: 2008-01-28
Spill Number/Closed Date: 0711337 / 2008-06-24
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: WCHD
Referred To: SCHNEIDER
Reported to Dept: 2008-01-28
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Remediation Phase:	0
Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2008-06-24
Spiller Name:	GERRY
Spiller Company:	PROFESSIONAL BUILDING COP
Spiller Address:	421 HUGUENOT STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	GERRY
Contact Phone:	(914) 632-3400
DEC Memo:	"Spoke to Gerry. Danielle Jackson of WCHD may be handling. WCHD to inspect today. 06/24/08 Wayne Schneider WCHD reported 421 Huguenot St, New Rochelle - leaking tank. Contaminated soil remediated. See attached NFA TG "
Remarks:	"HOLES AND CONTAMINATED SOIL"

Material:

Site ID:	392804
Operable Unit ID:	1149789
Operable Unit:	01
Material ID:	2140347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	392804
Spill Tank Test:	2384563
Tank Number:	Not reported
Tank Size:	3000
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Unknown

---

282 West 1/4-1/2 0.311 mi. 1644 ft.

Relative: Higher

Actual: 90 ft.

FRANKA INC. **NY LTANKS** **S104276153**
132-143 UNION AVE. **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	176106
Spill Number/Closed Date:	9312205 / 1995-11-09
Spill Date:	1994-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

FRANKA INC. (Continued) **S104276153**

Cleanup Ceased:	1995-11-09
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1995-11-08
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-24
Spill Record Last Update:	1995-11-27
Spiller Name:	Not reported
Spiller Company:	REGENT OIL CO.
Spiller Address:	53 CHARLES STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148008
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/95 FINAL INSPECTION PERFORMED TRENCH IS OIL FREE SUMP PIT IS OIL FREE BASEMENT IS FREE OF PETROLEUM NO OIL STAIN ON SIDEWALK"
Remarks:	"1K TANK UNDERGROUND POSSIBLE LEAK CLEAN UP CREW ENROUTE"

Material:

Site ID:	176106
Operable Unit ID:	994225
Operable Unit:	01
Material ID:	391197
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AW283 **APARTMENT HOUSE** **NY LTANKS** **S106385339**
SSE **156-168 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1652 ft. **Site 2 of 3 in cluster AW**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	267104
Spill Number/Closed Date:	0312650 / 2004-04-22
Spill Date:	2004-02-13
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-02-13
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-13
Spill Record Last Update:	2004-04-22
Spiller Name:	JIM DONELAN
Spiller Company:	PROTEST
Spiller Address:	PO BOX 1937
Spiller City,St,Zip:	WEST BABYLON, NY 11704
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 698-4100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217585
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 04/22/04 TANK PASSED A RETEST ON 3-22-04. NFA jbo"
Remarks:	"Failed tank test"

Material:

Tank Test:

Site ID:	267104
Spill Tank Test:	1528979
Tank Number:	1
Tank Size:	10000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

AW284 **FAILED TANK TEST** **NY LTANKS** **S114561821**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1652 ft. **Site 3 of 3 in cluster AW**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	488939
Spill Number/Closed Date:	1308221 / Not Reported
Spill Date:	2013-11-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-11-12
Spill Record Last Update:	2013-11-22
Spiller Name:	WILLIE
Spiller Company:	FAILED TANK TEST
Spiller Address:	156 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	WILLIE
Spiller Phone:	(914) 774-2508
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	"11/12/13: Residential tank test failure. No indication of a release at this time. Message sent to Elite requesting additional information on the owner, or their realtor. jod 11/12/13: Update received from Chris Lalak. This is not a residential tank. This is a 10K #4 Oil tank, PBS 3-600412. Wayne Schneider will follow up on retest. jod"
Remarks:	"Tank test failure"

Material:

Site ID:	488939
Operable Unit ID:	1238546
Operable Unit:	01
Material ID:	2238468
Material Code:	9999
Material Name:	other - failed tank test
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

FAILED TANK TEST (Continued) **S114561821**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 488939
Spill Tank Test: 2494704
Tank Number: 1
Tank Size: 10000
Test Method: 21
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: JBODEE
Last Modified: Not reported
Test Method: Horner EZY3/EZY3 Locator Plus

AS285 **DIPASQUALE PROPERTY** **NY LTANKS** **S111063882**
NNW **400 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1677 ft. **Site 5 of 5 in cluster AS**

Relative:
Lower

Actual:
70 ft.

LTANKS:
Site ID: 450672
Spill Number/Closed Date: 1103122 / 2012-04-26
Spill Date: 2011-06-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2011-06-20
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2011-06-20
Spill Record Last Update: 2012-04-26
Spiller Name: MR CHARLIE DIPASQUALE
Spiller Company: NDR GROUP
Spiller Address: 400 NORTH AVE
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 999
Spiller Contact: MR DIPASQUALE
Spiller Phone: (914) 633-7092
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 404310
DEC Memo: "6/20/11: This spill initially reported as a residential TTF. Property is actually a commercial office building with apartments on

DIPASQUALE PROPERTY (Continued) **S111063882**

the second floor. Previous Spill number for this site is 1102214 which was reported on May 27th. Owner informed US Tank Tech of the prior Phase I site investigation, but apparently did not inform them of the Phase II which found high levels of contamination. US Tank Tech reports they were hired to test the in-service 550 gallon heating oil tank, and perform a site investigation to locate a second, out-of-service tank. The 550 failed the vaccuum test, petroleum odors evident in the well point. US Tank Tech also reports they believe the second out-of-service tank may be located under the office building. Owner states the second tank is a 275 gallon heating oil, but that can not be confirmed at this time. US Tank Tech also reports there are at least two additional sets of fill and vent pipes, for other out-of-service or abandoned USTs. Tester also noted petroleum odors from the basement sump pit. jod 6/21/11: US Tank Tech reported that the owner says he hired Northeast Environmental to address these two spills issues. Message sent to Northeast asking for confirmation. jod 9/29/11: Northeast reports the owner has hired them to begin investigation and remediation. jod 10/21/11: The UST has been removed by Northeast and contaminated soil is evident. Remediation work is being scheduled. jod 4/26/2012: Closure report from Northeast Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"

Remarks: "repair/retest pending"

Material:

Site ID:	450672
Operable Unit ID:	1200876
Operable Unit:	01
Material ID:	2197327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV286 **INDUSTRIAL OVERALL SERVICES FORMER** **RCRA-LQG** **1004571492**
SW **30 PINE ST** **NY SHWS** **NYD986925808**
1/4-1/2 **NEW ROCHELLE, NY 10805** **NY Spills**
0.320 mi. **FINDS**
1691 ft. **Site 3 of 4 in cluster AV** **NJ MANIFEST**
NY MANIFEST
Relative: **ECHO**
Lower

Actual: **49 ft.**

RCRA-LQG:

Date form received by agency:	06/27/2012
Facility name:	INDUSTRIAL OVERALL SERVICES FORMER
Facility address:	30 PINE ST NEW ROCHELLE, NY 10805
EPA ID:	NYD986925808
Mailing address:	PINE ST

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

NEW ROCHELLE, NY 10805
Contact: BURT DORFMAN
Contact address: BARTELS AVE
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: (845) 353-3500
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address: BARTELS AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: (845) 353-3500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2010
Owner/Op end date: Not reported

Owner/operator name: NYS DEPT ENVIRONMENTAL CONSERVATION
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 12/13/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 12/16/2008
Site name: BAKERS PRIDE OVEN
Classification: Small Quantity Generator

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/01/2007
Site name: BAKERS PRIDE OVEN CO INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/12/1994
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/14/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SHWS:
Program: HW
Site Code: 355304
Classification: N
Region: 3
Acres: 3.75
HW Code: 360087
Record Add: 11/08/2005
Record Upd: 07/21/2009
Updated By: RXKEATIN
Site Description: The Baker?s Pride site is located at 30 Pine Street in the City of New Rochelle, Westchester County, NY. The surrounding area is urban with commercial and residential establishments mixed in between the commercial businesses. The Baker?s Pride site is an approximately 3.75 acre flat to severely sloping irregularly shaped parcel. The Baker?s Pride building occupies approximately 111,450 sf of building space and occupies the majority of the property. Baker?s Pride owns the Bakers Pride Oven Company Inc and is engaged in the production of restaurant/commercial grade ovens and broilers.The site is bordered by Metro North railroad tracks to the west and northwest, a mix of commercial and residential properties to the northeast, east, and south. Interstate (I-95) is located to the west of the Metro North railroad tracks. In 2005, a Phase II Environmental Assessment report was completed by Enercon as part of closure proceedings for a 3,000 gallon fuel oil UST that was closed in place and a 10,000 gallon fuel oil UST that was removed. Monitoring wells installed as part of this assessment revealed the presence of PCE in groundwater at levels up to 1,430 ppb. (The State groundwater standard for PCE is 5 ppb.) Also, this report noted chemical storage for cutting oils, lubricants, solvents and paints. No products were indicated that contained PCE. In 2007 a follow up report was conducted which revealed PCE in groundwater at levels up to 1,700 ppb. The site was added as a potential inactive hazardous waste disposal site ("P site") in 2007. A State funded site characterization was initiated in 2008 to determine the source of the PCE groundwater plume. A total of 9 monitoring wells were installed in the fall of 2008. Groundwater contaminated with PCE showed higher levels of PCE in wells upgradient from the Baker?s Pride facility. The PCE

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

concentrations were as high as 3,700 ppb in MW-13 which is located about 300 feet upgradient from the Baker?s Pride facility. This prompted the State to do a second round of groundwater sampling further upgradient of MW-13. Two additional wells (MW-24 and MW-25) were installed about 150 feet upgradient of MW-13 in the winter of 2009. MW-24 revealed PCE at 5,300 ppb. The second round of sampling further defined a groundwater plume with a source area upgradient from the Bakers Pride site.Since the site information for Baker?s Pride indicates that the plume of PCE is coming from an off-site source, the Baker?s Pride site (360087) will not be listed in the Registry of Inactive Hazardous Waste Disposal sites. A separate site was added to the Registry to address the source of the PCE plume (See site #360109.)

Env Problem:	Based upon investigations to date, the primary contaminants of concern at the site include tetrachloroetylene (PCE) and its associated breakdown products. PCE was detected in upgradient groundwater as well as on-site and also in indoor air in residences upgradient of the site. PCE was detected on-site in groundwater from non-detect up to 3,200 parts per billion (ppb) at MW-1) above the respective groundwater standard of 5 ppb. Upgradient off-site levels of PCE were as high as 5,300 ppb. Indoor air was impacted in two residences with the highest level being 530 micrograms per cubic meter (ug/m3) at a property on Bartels Place. Since the highest levels of PCE were identified in the groundwater upgradient of the site this suggests an off-site source that is impacting the Baker?s Pride site. The source of this contamination is the Industrial Overall Service Corp. Class 2 site (#360109)
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Updated By: Not reported

SPILLS:

Facility ID:	9404759
Facility Type:	ER
DER Facility ID:	122872
Site ID:	144128
DEC Region:	3
Spill Date:	1994-07-07
Spill Number/Closed Date:	9404759 / 2003-10-08
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1994-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-11
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 10/17/03: Letter to Mark Fogarty, Baker's Pride from Danielle Jackson, dated 10/8/2003. Closure report by Env. Products & Services and sample results have been reviewed. While there is some contamination remaining, WCDOH does not see the contamination as a risk to human health. WCDOH recommends NFA at this time."
Remarks:	"SOIL STOCKPILED BOB SPERONI WAS ON SITE FAXED TO TARRYTOWN & WCHD"

Material:

Site ID:	144128
Operable Unit ID:	1001834
Operable Unit:	01
Material ID:	381361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

FINDS:

Registry ID: 110002092949

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NJ MANIFEST:
EPA Id: NYD986925808
Mail Address: 30 PINE ST
Mail City/State/Zip: NEW ROCHELLE 10801
Facility Phone: 9145760200
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 008921150JJK
EPA ID: NYD986925808
Date Shipped: 7/2/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,815.00 gallons

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	008923493JJK
EPA ID:	NYD986925808
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,800.00 Pounds

Manifest Number:	008923039JJK
EPA ID:	NYD986925808
Date Shipped:	7/31/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	150.00 Pounds

Manifest Number:	NJA4033255
EPA ID:	NYD986925808
Date Shipped:	04/02/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/02/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030425
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

NY MANIFEST:

EPA ID:	NYD986925808
Country:	USA
Location Address 1:	30 PINE ST
Location Address 2:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip Code:	10801
Location Zip Code 4:	Not reported

Mailing Info:

Name:	INDUSTIRAL OVERALL UNIFORM
Contact:	IRA NEVIN
Address:	30 PINE ST
City/State/Zip:	NEW ROCHELLE, NY 10801
Country:	USA
Phone:	518-402-9564

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2014
Trans1 Recv Date:	05/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012352197JJK
Import Ind:	N
Export Ind:	N

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2014
Trans1 Recv Date:	05/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	012352197JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049543SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049543SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 10/15/2009
Trans1 Recv Date: 10/15/2009
Trans2 Recv Date: 10/19/2009
TSD Site Recv Date: 10/25/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986925808
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: Not reported
Quantity: 10.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 002049551SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629926
Generator Ship Date: 10/15/2009
Trans1 Recv Date: 10/15/2009
Trans2 Recv Date: 10/19/2009
TSD Site Recv Date: 10/21/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986925808
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 200.0

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049550SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629926
Generator Ship Date:	10/15/2009
Trans1 Recv Date:	10/15/2009
Trans2 Recv Date:	10/19/2009
TSD Site Recv Date:	10/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	20.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002049550SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/28/2012
Trans1 Recv Date:	12/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1800.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008923493JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2012
Trans1 Recv Date:	07/31/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Manifest Tracking Num:	008923039JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/2012
Trans1 Recv Date:	07/02/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	31.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008921150JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/2012
Trans1 Recv Date:	07/02/2012
Trans2 Recv Date:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

TSD Site Recv Date:	07/02/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	Not reported
Quantity:	1815.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	33.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	008921150JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NJA4033255
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2004
Trans1 Recv Date:	04/02/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00242
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2004

Document ID:	NJA2889530
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Generator Ship Date:	02/09/2001
Trans1 Recv Date:	02/09/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/13/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA2968556
Manifest Status:	Not reported
Trans1 State ID:	50060
Trans2 State ID:	S50060
Generator Ship Date:	08/23/1999
Trans1 Recv Date:	08/23/1999
Trans2 Recv Date:	08/24/1999
TSD Site Recv Date:	08/27/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NJA2295827
Manifest Status:	Not reported
Trans1 State ID:	S50060
Trans2 State ID:	88672
Generator Ship Date:	08/14/1998
Trans1 Recv Date:	08/14/1998
Trans2 Recv Date:	08/26/1998
TSD Site Recv Date:	08/27/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NJA2729357
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	50060
Trans2 State ID:	Not reported
Generator Ship Date:	05/20/1997
Trans1 Recv Date:	05/20/1997
Trans2 Recv Date:	05/23/1997
TSD Site Recv Date:	05/29/1997
Part A Recv Date:	06/10/1997
Part B Recv Date:	07/15/1997
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NJA2590786
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S50060
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1997
Trans1 Recv Date:	12/17/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/18/1997
Part A Recv Date:	01/07/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1997

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Document ID:	NJA2630871
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S50060
Trans2 State ID:	S50060
Generator Ship Date:	11/08/1996
Trans1 Recv Date:	11/08/1996
Trans2 Recv Date:	11/17/1996
TSD Site Recv Date:	11/20/1996
Part A Recv Date:	12/02/1996
Part B Recv Date:	01/31/1997
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2133346
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/1996
Trans1 Recv Date:	06/27/1996
Trans2 Recv Date:	07/05/1996
TSD Site Recv Date:	07/15/1996
Part A Recv Date:	07/16/1996
Part B Recv Date:	08/02/1996
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2630864
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	75818
Trans2 State ID:	S50060
Generator Ship Date:	10/25/1996
Trans1 Recv Date:	10/25/1996
Trans2 Recv Date:	11/05/1996
TSD Site Recv Date:	11/06/1996
Part A Recv Date:	11/12/1996

INDUSTRIAL OVERALL SERVICES FORMER (Continued) **1004571492**

Part B Recv Date:	12/16/1996
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

ECHO:

Envid:	1004571492
Registry ID:	110002092949
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002092949

287
West
1/4-1/2
0.322 mi.
1698 ft.

Relative:
Lower

Actual:
80 ft.

POGLIA RES **NY LTANKS** **S105230529**
119 WASHINGTON AVE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	317087
Spill Number/Closed Date:	0109023 / 2002-03-06
Spill Date:	2001-12-11
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-12-11
CID:	397
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-11
Spill Record Last Update:	2002-03-22
Spiller Name:	CALLER
Spiller Company:	POGLIA RES
Spiller Address:	119 WASHINGTON AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

POGLIA RES (Continued) **S105230529**

DER Facility ID: 255607
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/06/2002 NES DISPOSED OF TANK AND 40 TONS OF CONTAMINATED SOIL. DORSON SUBMITTED CLOSURE REPORT. NO FURTHER ACTION."
Remarks: "callers co was removing tank and discovered the tank failure. in process of being cleaned"

Material:
Site ID: 317087
Operable Unit ID: 847335
Operable Unit: 01
Material ID: 530237
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

---

288 **APT. BUILDING** **NY LTANKS S102241692**
South **47 MAPLE AV** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.323 mi.
1705 ft.

Relative:
Higher

Actual:
87 ft.

LTANKS:
Site ID: 178537
Spill Number/Closed Date: 9603128 / 1996-06-14
Spill Date: 1996-06-05
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1996-06-05
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1996-06-05
Spill Record Last Update: 1996-09-04
Spiller Name: A D VANDROFF
Spiller Company: A D VANDROFF
Spiller Address: 47 MAPLE AVENUE

APT. BUILDING (Continued) **S102241692**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	A D VANDROFF
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/14/96 SEE SPILL # 9603064"
Remarks:	"gross failure of tank."

Material:

Tank Test:

SPILLS:

Facility ID:	9603064
Facility Type:	ER
DER Facility ID:	248269
Site ID:	307417
DEC Region:	3
Spill Date:	1996-06-04
Spill Number/Closed Date:	9603064 / 1996-08-12
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-04
CID:	349
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-06-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-04
Spill Record Last Update:	1996-10-21
Spiller Name:	OWNER - ARTHUR DANDROFF
Spiller Company:	Not reported
Spiller Address:	47 MAPLE AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	OWNER - ARTHUR DANDROFF
Contact Phone:	(941) 954-4445
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/04/96 WCHD TO INSPECT 06/14/96 SEE SPILL # 9603128 08/12/96 CONTENTS GONE IN FOUR DAYS AFTER FILL UP TANK REMOVED LINES TESTED NO LEAKS FOUND FROM TESTS SMALL HOLES FOUND IN TANKS VERY MINIMAL CONTAMINATION "
Remarks:	"APARTMENT BLDG - SUPERINTENDENT MRS CHURCHILL 914-636-4142 -

APT. BUILDING (Continued) **S102241692**

RECIEVED 900 GALLONS ON THURSDAY - NOW ITS IS EMPTY - CHECK OF AREA INCLUDING SEWERS NO ODOR - FD ON SCENE - WILL BE TESTING W/WATER - TEMP. TANK TO BE PUT IN"

Material:

Site ID:	307417
Operable Unit ID:	1030609
Operable Unit:	01
Material ID:	349302
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

289
East
1/4-1/2
0.323 mi.
1706 ft.

SPILL 0106072 / PBS 3-800919 **NY LTANKS** **S105135128**
370 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
60 ft.

LTANKS:

Site ID:	133647
Spill Number/Closed Date:	0106072 / 2001-11-13
Spill Date:	2001-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2014-08-15
Spiller Name:	STEVEN WOODS
Spiller Company:	Monroe College
Spiller Address:	370 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	Not reported

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114844
DEC Memo:	"09/07/2001 PROPERTY FOR SALE. TANK TESTED BY POTENTIAL BUYER. SELLER TO REMOVE OR RETEST. 11/13/2001 TANK PASSED A RETEST AFTER REFIT. NO FURTHER ACTION. 8/15/14: Hard copy file pulled for FOIL. File scanned to PDF, will wiil entered into DecDocs. Paper file discarded. NOTE: WCDoH PBS records indicate this UST was Closed - in place and the site listed as Unregulated 7/30/2002. jod"
Remarks:	"will fill tank with sand and abandoned it"

Material:

Site ID:	133647
Operable Unit ID:	844476
Operable Unit:	01
Material ID:	530955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	133647
Spill Tank Test:	2495803
Tank Number:	1
Tank Size:	2000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AY290 **BUSINESS** **NY LTANKS** **S101341432**
WSW **88 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 1 of 2 in cluster AY**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	172950
Spill Number/Closed Date:	9411669 / 2010-04-28
Spill Date:	1994-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010

BUSINESS (Continued) **S101341432**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	MR. OGMAN
Spiller Address:	88 GROVE AVE.
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	145542
DEC Memo:	"4/28/10 16 year old TTF No further info NFA JO'M "
Remarks:	"WILL EXPLORE IT NEXT"

Material:

Site ID:	172950
Operable Unit ID:	1005375
Operable Unit:	01
Material ID:	374006
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	172950
Spill Tank Test:	1543408
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

AY291 **COMMERCIAL BUILDING** **NY LTANKS** **S104276178**
WSW **88-90 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1715 ft. **Site 2 of 2 in cluster AY**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Site ID:	113133
Spill Number/Closed Date:	9411598 / 2010-04-28
Spill Date:	1994-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	98741
DEC Memo:	"4/28/10 16 year old TTF NFA JO'M"
Remarks:	"TANK TEST FAILURE PETRO-TITE II VISUAL"

Material:

Site ID:	113133
Operable Unit ID:	1005335
Operable Unit:	01
Material ID:	373942
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

COMMERCIAL BUILDING (Continued) **S104276178**

Site ID:	113133
Spill Tank Test:	1543402
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

---

292 WNW 1/4-1/2 0.335 mi. 1769 ft. **ANON** **NY LTANKS S106124350**
108 VAN GUILDER AVE **NY Spills N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 77 ft.

LTANKS:

Site ID:	214235
Spill Number/Closed Date:	0308565 / 2005-02-12
Spill Date:	2003-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-11-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-13
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	RICHARD KLING
Spiller Phone:	(914) 636-0076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177496
DEC Memo:	"03/24/04 TANK IS IN A CRAWL SPACE UNDER THE FOUNDATION AND CANNOT BE REMOVED. ROYAL ENVIRONMENTAL INSPECTED TANK AND FOUND NO EVIDENCE OF CONTAMINATION. ROYAL INSTALLED A NEW 275 AST BUT HAS NOT YET PUT THAT TANK IN SERVICE, AWAITING INSPECTION FROM NEW ROCHELLE FIRE DEPT. ONCE AST IS IN SERVICE, ROYAL IS TO CUT AND CLEAN 550 UST AND OBTAIN A SOIL SAMPLE FROM BENEATH TANK. SAMPLE RESULTS TO BE FORWARDED TO DEC. ADDITIONAL SPILL NUMBERS CALLED IN: 03-13745 AND 03-14031. jbo"

ANON (Continued) **S106124350**

Remarks: "uncover / repair / retest"

Material:

Site ID:	214235
Operable Unit ID:	874811
Operable Unit:	01
Material ID:	502049
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	214235
Spill Tank Test:	1528806
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	0314031
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214237
DEC Region:	3
Spill Date:	2004-03-24
Spill Number/Closed Date:	0314031 / 2004-03-24
Spill Cause:	Unknown
Spill Class:	No spill occured. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-24
CID:	407
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-24
Spill Record Last Update:	2005-02-12

ANON (Continued) **S106124350**

Spiller Name:	RICHARD KLING MD
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	RICHARD KLING MD
Contact Phone:	Not reported
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo 03/30/04 SITE INSPECTED BY STEFAN GOREAU OF WCHD. jbo"
Remarks:	"unknown if spill, caller refused to give name, detected odor of gas/oil from neighbors building, renovation ongoing at building, caller believed odor was related to work."

Material:

Site ID:	214237
Operable Unit ID:	880985
Operable Unit:	01
Material ID:	495617
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0313745
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214236
DEC Region:	3
Spill Date:	2004-03-16
Spill Number/Closed Date:	0313745 / 2004-03-24
Spill Cause:	Unknown
Spill Class:	No spill occured. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2005-02-12
Spiller Name:	DR RICHARD KLEIN

ANON (Continued) **S106124350**

Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	DR RICHARD KLEIN
Contact Phone:	Not reported
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo"
Remarks:	"CALLER STATES THAT THERE IS A VERY STRONG ODOR AT THE DOCTOR'S OFFICE AND SHE CAN SMELL IT AT HER HOME. SOMETIMES ODOR IS VERY OVERWELMING: A LARGE CONTAINER IS IN THE BACK YARD OF DOCTOR'S OFFICE: SHE JUST WANTED SOMEONE TO CHECK OUT: *****UPDATE***** SHE CALLED BACK AND SAID THAT SOMEONE TOLD HER THAT A COMPANY CAME IN A CHECKED IT OUT- ROYAL IN PELHAM NY*"

Material:

Site ID:	214236
Operable Unit ID:	879034
Operable Unit:	01
Material ID:	495337
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AV293 **BELIVE HOME** **NY LTANKS** **S106869214**
SW **20 PINE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.337 mi.
1780 ft. **Site 4 of 4 in cluster AV**

Relative:
Lower

Actual:
47 ft.

LTANKS:

Site ID:	343902
Spill Number/Closed Date:	0500819 / 2005-05-22
Spill Date:	2005-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

BELIVE HOME (Continued) **S106869214**

Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2005-05-22
Spiller Name:	JOHN BELIVE
Spiller Company:	BELIVE HOME
Spiller Address:	20 PINE STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOHN BELIVE
Spiller Phone:	(914) 253-8449
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"05/22/05 PREVIOUSLY REPORTED TTF IS 04-13182. NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 34.56 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 gallon , found holes and contaminated soil:"

Material:

Site ID:	343902
Operable Unit ID:	1102568
Operable Unit:	01
Material ID:	582785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	339043
Spill Number/Closed Date:	0413182 / 2005-05-22
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

BELIVE HOME (Continued) **S106869214**

Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-22
Spiller Name:	JOE PONSERELLA
Spiller Company:	PONSERELLA HOME
Spiller Address:	20 PINE STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOE PONSERELLA
Spiller Phone:	(914) 760-6684
Spiller Extention:	CELL
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"5/22/05 See spill 05-00819. NFA this number. jod"
Remarks:	""

Material:

Site ID:	339043
Operable Unit ID:	1100961
Operable Unit:	01
Material ID:	581111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	339043
Spill Tank Test:	1548700
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

294 **CON EDISON-CEDAR ST WORKS-NEWROCH'LE MGP** **EDR MGP** **1008407973**
NE **ONE RAMADA PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.340 mi.
1794 ft.

Relative:
Lower

Actual:
50 ft.

Manufactured Gas Plants:
No additional information available

295 SE 1/4-1/2 0.341 mi. 1799 ft.

CHURCH OF LATTER DAY SAIN
111 NORTH AVE
NEW ROCHELLE, NY

NY LTANKS **S106471932** **N/A**

Relative: Lower

Actual: 83 ft.

LTANKS:

Site ID:	266466
Spill Number/Closed Date:	0403126 / 2004-09-21
Spill Date:	2004-06-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates a file or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-06-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22
Spill Record Last Update:	2004-09-21
Spiller Name:	MATT SCHIEFERSTEIN
Spiller Company:	CHURCH OF LATTER DAY SAIN
Spiller Address:	111 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MATT SCHIEFERSTEIN
Spiller Phone:	(631) 351-3555
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217081
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/23/04 APPROXIMATELY 200 TONS OF CONTAMINATED SOIL REMOVED. CLOSURE REPORT TO FOLLOW. jbo 09/21/04 ANSON ENVIRONMENTAL DISPOSED OF LUST AND 168.02 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"WHILE DIGGING A FOUNDATION FOUND A TANK: CONTAMINATED SOIL ALSO: "

Material:

Site ID:	266466
Operable Unit ID:	885085
Operable Unit:	01
Material ID:	490726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

CHURCH OF LATTER DAY SAIN (Continued) **S106471932**

Tank Test:

296
SE
1/4-1/2
0.345 mi.
1824 ft.

APARTMENT BUILDING **NY LTANKS** **S110611357**
67-70 LOCUST AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Site ID:	441682
Spill Number/Closed Date:	1008207 / 2011-03-10
Spill Date:	2010-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-04
Spill Record Last Update:	2011-03-10
Spiller Name:	ABRAHAM WATHCELL
Spiller Company:	UNKNOWN
Spiller Address:	67- 70 LOCUST AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ABRAHAM WATHCELL
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396710
DEC Memo:	"Left message for callback. DT 11/4/10 11/5/10: Call back from Abraham Wathcell of NY Tank Testing to dispatch desk. This was a test failure of an 8K heating oil tank at a co-op. PBS #3-413925 will handled by WCDOH. Mr Wathcell stated he had discussed the results with the management compny and was recommending removal of the tank rather than retest. jod 3/10/11 As per WCDOH eplaced fill pipe, manway gasket and repaired gauge. Passed retest on 2/14/11. NFA JO'M "
	Not reported
Remarks:	""

Material:

Site ID:	441682
Operable Unit ID:	1192229
Operable Unit:	01
Material ID:	2187465

APARTMENT BUILDING (Continued) **S110611357**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	441682
Spill Tank Test:	2489743
Tank Number:	1
Tank Size:	8000
Test Method:	21
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified:	Not reported
Test Method:	Horner EZY3/EZY3 Locator Plus

AX297 **SPILL NUMBER 9908602** **NY LTANKS** **S104620556**
SSW **HUGUENOT ST & SOUTH PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.348 mi.
1836 ft. **Site 2 of 2 in cluster AX**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	283271
Spill Number/Closed Date:	9908602 / 2000-09-14
Spill Date:	1999-10-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1999-10-15
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-10-15
Spill Record Last Update:	2000-09-26
Spiller Name:	CITY OF NEW ROCHELLE
Spiller Company:	Not reported
Spiller Address:	HUGUENOT ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001

SPILL NUMBER 9908602 (Continued) **S104620556**

Spiller Contact:	CITY OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229755
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 10/15/99 DELUXE TAXICAB SITE; TANKS HAD BEEN REMOVED BUT CONTAMINATED SOIL; SOIL BEING REMOVED--WILL SUBMIT REPORT. 12/09/99 LETTER SENT TO N. RECCHIA; MUST BETTER DEFINE THE EXTENT OF CONTAMINATION IN THE OVERBURDEN SOIL & GROUNDWATER 05/18/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; ADDITIONAL INVESTIGATION IS REQUIRED AT THIS SITE 09/14/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; BASED ON RESULTS REPORTED BY THE ENERGY & ENVIRONMENTAL ANLAYSISTS, INC. IN AUGUST 2000, THIS SPILL IS CLOSED. "
Remarks:	"VACANT LOT AND DURING EXCAVATION - CONTAMINATED SOIL FOUND"

Material:

Site ID:	283271
Operable Unit ID:	1087287
Operable Unit:	01
Material ID:	297711
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

298
SW
1/4-1/2
0.357 mi.
1885 ft.

BUSINESS COMPLEX **NY LTANKS** **S104516367**
55 WEBSTER AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
54 ft.

LTANKS:

Site ID:	86196
Spill Number/Closed Date:	9912136 / 2000-05-11
Spill Date:	2000-01-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2000-01-20
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other

BUSINESS COMPLEX (Continued) **S104516367**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2004-11-23
Spiller Name:	MR LIBERETT
Spiller Company:	BUSINESS COMPLEX
Spiller Address:	55 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801-
Spiller County:	001
Spiller Contact:	MR LIBERETT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79113
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/09/2000 ACCORDING TO MR. BOB ALERES PHASE 11 REPORT COMPLETED. WILL SUBMIT COPY TO T. GHIOSAY. 05/11/00 - Spill closure letter sent by J. O'Mara to: DL Rothberg & Associates PC 1350 Broadway Suite 1711 NY NY 10018 Attention Debra Rothberg, Esq"
Remarks:	"THEY REMOVED A 3,000 GALLON TANK AND PUT IN A NEW 1,000 GALLON TANK THEY SUSPECT THE 3,000 GALLON HAD LEAKED UNKNOWN MATERIAL INTO THE GROUND.THEY GOT THE LAB RESULTS BACK YESTERDAY.THEY SUSPECT IT MAY BE HEATING OIL BUT ARE NOT SURE."

Material:

Site ID:	86196
Operable Unit ID:	1086666
Operable Unit:	01
Material ID:	294030
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AZ299 **APARTMENT BLDG** **NY LTANKS** **S104515070**
North **1 THE BOULEVARD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.359 mi.
1898 ft. **Site 1 of 2 in cluster AZ**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	303319
Spill Number/Closed Date:	9809315 / 1999-10-14
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known

APARTMENT BLDG (Continued) **S104515070**

	release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-10-26
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	1999-11-22
Spiller Name:	ELJAK REALTY
Spiller Company:	APT BLDG
Spiller Address:	1 THE BLVD
Spiller City,St,Zip:	NEW ROCHELELE, NY 10801-
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	245085
DEC Memo:	""
Remarks:	"EXCAVATE PIPING AND RETEST"

Material:

Site ID:	303319
Operable Unit ID:	1070412
Operable Unit:	01
Material ID:	316775
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	303319
Spill Tank Test:	1546451
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BA300 **GETTY S/S** **NY LTANKS** **S105054437**
ENE **ECHO & BOSTON POST RD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.362 mi.
1913 ft. **Site 1 of 4 in cluster BA**

Relative:
Lower

Actual:
42 ft.

LTANKS:

Site ID:	124816
Spill Number/Closed Date:	8602124 / 1989-11-28
Spill Date:	1986-06-28
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1989-11-28
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1986-06-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	1988-08-19
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-09-21
Spill Record Last Update:	1990-11-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	108052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : 6/29-NEPCCO DRILLED RECOVERY WELLS. / / : 6/29-NEPCCO DRILLED RECOVERY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL. / / : 6/29-NEPCCO DRILLED RECOVERY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL.7/1/86-TANKS MUST BE PETRO-TITE TESTED. / / : 7/1/86-PROBLEM REPAIRED-NFAY WELLS 6/30-PRESSURE TESTS UNSUCCESSFUL.7/1/86-TANKS MUST BE PETRO-TITE TESTED. / / : 7/23/86-NO EXPLOSIVE READINGS IN SEWER.MONITORING WELLS ON SITE HAVE NO FREE PRODUCT. 08/18/88: BAILED ALL WELLS,NO FREE PRODUCT. "
Remarks:	"FD FLUSHED SEWERS.NEPCO DRILLING RECOVERY WELLS. ALL WELLS CLEAN OF FREE PRODUCT."

Material:

Site ID:	124816
Operable Unit ID:	898693
Operable Unit:	01
Material ID:	478579
Material Code:	0009
Material Name:	gasoline

GETTY S/S (Continued) **S105054437**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AZ301 **PRIVATE DWELLING** **NY LTANKS** **S108765819**
NNW **19 ROCHELLE PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.363 mi.
1917 ft. **Site 2 of 2 in cluster AZ**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	387568
Spill Number/Closed Date:	0706958 / 2008-02-01
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2008-02-01
Spiller Name:	ROLAND ANDRALOISKI
Spiller Company:	Not reported
Spiller Address:	19 ROCHELLE PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ROLAND ANDRALOISKI
Spiller Phone:	(914) 774-7362
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	336995
DEC Memo:	"To uncover and retest. 12/05/08 Northeast Environmental reported that the tank was excavated and removed. Noe cotaminated soil was observed in the tank grave. TAGM soil sample results were below DEC guidance values. NFA. TG "
Remarks:	""

PRIVATE DWELLING (Continued) **S108765819**

Material:

Site ID:	387568
Operable Unit ID:	1144768
Operable Unit:	01
Material ID:	2135078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	387568
Spill Tank Test:	1764128
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BB302 **RESIDENCE** **NY LTANKS** **S102448122**
ENE **14 REVERE RD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.364 mi.
1923 ft. **Site 1 of 2 in cluster BB**

Relative:
Lower

Actual:
34 ft.

LTANKS:

Site ID:	69656
Spill Number/Closed Date:	9611129 / 1996-12-11
Spill Date:	1996-12-09
Spill Cause:	Tank Failure
Spill Source:	Tank Truck
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-09
CID:	233
Water Affected:	CARPENTERS POND
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-09
Spill Record Last Update:	1997-01-02

RESIDENCE (Continued) **S102448122**

Spiller Name:	Not reported
Spiller Company:	FRED M. SCHILDWACHLER &
Spiller Address:	SONS
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	66210
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/10/96 WCHD AT SITE."
Remarks:	"DRIVER OVERFILLED TANK OIL INTO BROOK BROOK RUNS TO A POND (CARPENTERS POND) FD ON SCENE CELL # FOR CHIEF 914-263-2302 WESTCHESTER FIRE CONTROL 914-593-5905"

Material:

Site ID:	69656
Operable Unit ID:	1042681
Operable Unit:	01
Material ID:	343331
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	Gallons
Recovered:	50.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

303
WNW
1/4-1/2
0.366 mi.
1933 ft.

NEW ROCHELLE RADIOLOGY **NY LTANKS** **S105997625**
150 LOCKWOOD AV **NY Spills** **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
85 ft.

LTANKS:

Site ID:	221207
Spill Number/Closed Date:	0209497 / 2005-03-18
Spill Date:	2002-12-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-12-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2005-04-05
Spiller Name:	RICK TROY
Spiller Company:	RICK TROY
Spiller Address:	150 LOCKWOOD AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RICK TROY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	182943
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 12/16/02: WCDOH ON SITE. 140 TONS SOIL REMOVED. CLOSURE REPORT PENDING. 04/08/03: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 3/26/2003. Closure report from GFE has been reviewed. Groundwater samples must be collected. Result submitted to WCHD by May 12, 2003. PBS #3-601067 & 3-601068. 08/13/02: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 7/21/03. Further remediation and quarterly sampling is required. Results of sampling are to be submitted to WCDOH quarterly. First report due by 9/01/2003. 5/25/04: Letter to Lockwood Realty, LLC, from Christopher Lalak, WCDOH, dated 25May2004. Two rounds of sampling have been received, third is overdue. Third round must be received by 25Jun2004. 11/22/04: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 17Nov2004. Based on groundwater sampling results, closure report and inspections, sampling must continue for the next year on a quarterly basis. After sampling, site will be reviewed. Next results due 28Feb2005. 4/4/05: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 18Mar2005. Spill has been satisfactorily remediated. WCDOH requires NFA."
Remarks:	"CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL"

Material:

Site ID:	221207
Operable Unit ID:	860802
Operable Unit:	01
Material ID:	512920
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

NEW ROCHELLE RADIOLOGY (Continued) **S105997625**

SPILLS:

Facility ID:	0209877
Facility Type:	ER
DER Facility ID:	182943
Site ID:	221208
DEC Region:	3
Spill Date:	2002-12-27
Spill Number/Closed Date:	0209877 / 2003-03-28
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-30
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"CALLER WENT TO HAVE A MAMMOGRAM DONE & SHE STAATED THE ENTIRE BLDG SMELLED LIKE FUEL OIL - UNK IF IT HAD TO DO WITH THE CONSTRUCTION THAT WAS GOING ON IN THE PARKING LOT OR NOT"

Material:

Site ID:	221208
Operable Unit ID:	861114
Operable Unit:	01
Material ID:	513296
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

304
SSE
1/4-1/2
0.368 mi.
1943 ft.

NICK MAZZA RESIDENCE
20 DAVIS AVE
NEW ROCHELLE, NY

NY LTANKS **S104621408**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	211468
Spill Number/Closed Date:	0000532 / 2000-04-20
Spill Date:	2000-04-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-13
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-13
Spill Record Last Update:	2000-05-03
Spiller Name:	N/A
Spiller Company:	NICK MAZZA
Spiller Address:	20 DAVIS AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/14/2000 ENVIROSTAR REPAIRED; U.S. TANK TO RETEST ON 4/17/2000. 04/20/2000 U.S. TANK TECH RETESTED TANK AFTER ENVIROSTAR REPLACED PIPING. TANK PASSED RETEST. NFA"
Remarks:	"tank failed the test. he did not have the homeowners name or phone number "

Material:

Site ID:	211468
Operable Unit ID:	822249
Operable Unit:	01
Material ID:	288777
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00

NICK MAZZA RESIDENCE (Continued) **S104621408**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 211468
Spill Tank Test: 1525485
Tank Number: 1
Tank Size: 1000
Test Method: 18
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)

BC305 **SHERIDEN PLAZA** **NY LTANKS** **S100138278**
NE **1 SHERIDEN PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.370 mi.
1955 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
36 ft.

LTANKS:
Site ID: 80178
Spill Number/Closed Date: 8909204 / 1990-03-07
Spill Date: 1989-12-19
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
Cleanup Meets Standard: True
SWIS: 6000
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1989-12-19
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1989-12-21
Spill Record Last Update: 1992-02-10
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 74339
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "CONTAMINATION FOUND DURING TANK REMOVAL SOIL TO BE STOCKPILED ON

SHERIDEN PLAZA (Continued) **S100138278**

PLASTIC DEC TO INSPECT TANK HOLE TYREE VACING OUT HOLE"

Material:

Site ID:	80178
Operable Unit ID:	934143
Operable Unit:	01
Material ID:	442378
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BD306 **JASON PARTNERS LTD** **NY LTANKS** **S105998096**
SSW **675 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.373 mi.
1968 ft. **Site 1 of 3 in cluster BD**

Relative:
Lower

Actual:
65 ft.

LTANKS:

Site ID:	86967
Spill Number/Closed Date:	0211105 / 2003-03-26
Spill Date:	2003-02-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-02-05
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-05
Spill Record Last Update:	2003-04-09
Spiller Name:	JAMIE MIZRAHI
Spiller Company:	JASON PARTNERS LTD
Spiller Address:	675 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JAMIE MIZRAHI
Spiller Phone:	(914) 682-6664
Spiller Extention:	Not reported

JASON PARTNERS LTD (Continued) **S105998096**

DEC Region: 3
DER Facility ID: 79721
DEC Memo: ""
Remarks: "CALLERS COMPANY HIRED TO REMOVE A 3000 GAL INGROUND TANK AT THE ABOVE LOCATION, AFTER TANK WAS REMOVED, HOLE WERE FOUND IN TANK AND CONTAMINATED SOIL WAS DISCOVERED - DIRT IS BEING REMOVED AND STORED ON PLASTIC"

Material:
Site ID: 86967
Operable Unit ID: 862143
Operable Unit: 01
Material ID: 514466
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BE307 **ABANDONED GAS STATION** **NY LTANKS** **S102660200**
West **197 WEBSTER AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.377 mi.
1989 ft. **Site 1 of 2 in cluster BE**

Relative:
Lower

Actual:
79 ft.

LTANKS:
Site ID: 231589
Spill Number/Closed Date: 9707099 / 2001-07-19
Spill Date: 1997-09-15
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-09-15
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1997-09-15
Spill Record Last Update: 2001-08-06
Spiller Name: Not reported
Spiller Company: UNKNOWN

ABANDONED GAS STATION (Continued) **S102660200**

Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	EDWARD SELLIAN
Spiller Phone:	(561) 221-1754
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	190875
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/19/2001 LETTER SENT TO IRA CONKLIN & SONS BY T. GHIOSAY; BASED ON SUBSURFACE INVESTIGATION REPORT, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL LISTED AS CLOSED."
Remarks:	"CALLER REMOVING TANKS AND FOUND SOIL CONTAMINATION"

Material:

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BC308 **MUTUAL BISCUIT COMPANY** **NY LTANKS** **S104193116**
NE **65 RIVER ST.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.379 mi.
2002 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	286036
Spill Number/Closed Date:	8707334 / 1988-02-18
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-25
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-01
Spill Record Last Update:	1988-03-11
Spiller Name:	HUGH GEORGE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : WILL RETEST. / / : TANKS REMOVED. LR 02-18-88 N F A. "
Remarks:	"TTTF-4K TANK;-0.7584 GPH,4K TANK;-0.3312 GPH"

Material:

Site ID:	286036
Operable Unit ID:	911503
Operable Unit:	01
Material ID:	466293
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	286036
Spill Tank Test:	1532438
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Last Modified:	Not reported
Test Method:	Unknown
Site ID:	286037
Spill Number/Closed Date:	8708530 / 1988-02-18
Spill Date:	1988-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	HUGH GEORGE
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANKS REMOVED 02-18-88 LR N F A. "
Remarks:	"5K (RETEST) 1.34GPH TO PUMP & PULL TANK"

Material:

Site ID:	286037
Operable Unit ID:	913194
Operable Unit:	01
Material ID:	570954
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Tank Test:

Site ID:	286037
Spill Tank Test:	1532919
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	9908179
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139057
DEC Region:	3
Spill Date:	1999-10-05
Spill Number/Closed Date:	9908179 / 1999-10-18
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-05
Spill Record Last Update:	1999-11-04
Spiller Name:	MICHAEL GRAVANESE
Spiller Company:	POST MARINE SUPLLY
Spiller Address:	65 RIVER SR
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/18/99 DEC INSPECTED SITE. ONE LEAKY BATTERY FOUND NEXT TO DIESEL TANKS. BATTERIES TO BE REMOVED LATER TODAY. NFA"
Remarks:	"CALLER IS AN EX EMPLOYEE REPORTING BATTERIES BEING STORED NEXT TO GASOLINE TANKS AND BELIEVES THEY MIGHT BE LEAKING BATTERY ACID."

Material:

Site ID:	139057
Operable Unit ID:	1082477

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Operable Unit:	01
Material ID:	300856
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9904805
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139056
DEC Region:	3
Spill Date:	1999-07-22
Spill Number/Closed Date:	9904805 / 1999-07-22
Spill Cause:	Deliberate
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1999-07-22
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-22
Spill Record Last Update:	1999-09-10
Spiller Name:	NASER JABER
Spiller Company:	POST MARINE SUPPLY
Spiller Address:	65 RIVER ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	NASER JABER
Contact Phone:	(914) 235-9800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA "
Remarks:	"CALLER STATES THAT HE WITTNESSED SUBJ DUMPING GAS INTO A STORM DRAIN. JOHN O'MARA (REGION 3 SPILLS) NOTIFIED AND ALSO ENCON POLICE"

Material:

Site ID:	139056
Operable Unit ID:	1079250
Operable Unit:	01

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Material ID:	301132
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA309 **GETTY 58114** **NY LTANKS S107657288**
ENE **340 MAIN STREET** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.380 mi.
2007 ft. **Site 2 of 4 in cluster BA**

Relative:
Lower

Actual:
38 ft.

LTANKS:

Site ID:	426673
Spill Number/Closed Date:	0913713 / 2010-04-29
Spill Date:	2010-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-26
Spill Record Last Update:	2010-04-29
Spiller Name:	ROBERT O'KEEFE
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	TOM ANDERSON
Spiller Phone:	(845) 216-8064
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310476
DEC Memo:	"3/26/10 Tyree to go there on Mon. 3/29 to do repairs. dw 4/29/10 Getty 340 Main St New Rochelle line test failed do to faulty check valve. Tyree replaced check valve. Passed retest on 4/12/10 NFA JO'M "
	Not reported

GETTY 58114 (Continued) **S107657288**

Remarks: "in line problem - Tyree notified - cleanup and repair pending"

Material:

Site ID:	426673
Operable Unit ID:	1182349
Operable Unit:	01
Material ID:	2176532
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0606306
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369636
DEC Region:	3
Spill Date:	2006-09-01
Spill Number/Closed Date:	0606306 / 2006-09-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-01
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"LESS THAN A GAL OF BOTH ABND THEY HAVE BEEN CLEANED UP."

GETTY 58114 (Continued) **S107657288**

Material:

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117069
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117068
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0606253
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369567
DEC Region:	3
Spill Date:	2006-08-30
Spill Number/Closed Date:	0606253 / 2006-09-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-30
CID:	77
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-31

GETTY 58114 (Continued) **S107657288**

Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"1 qt of waste oil spilled onto asphalt, speedy dry applied."

Material:

Site ID:	369567
Operable Unit ID:	1127402
Operable Unit:	01
Material ID:	2117000
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0603586
Facility Type:	ER
DER Facility ID:	310476
Site ID:	366335
DEC Region:	3
Spill Date:	2006-06-30
Spill Number/Closed Date:	0603586 / 2006-07-03
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2006-06-30
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-30
Spill Record Last Update:	2006-07-11
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114

GETTY 58114 (Continued) **S107657288**

Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"COMBINED TOTAL OF LESS THAN A GAL. HAS BEEN CLEANED UP."

Material:

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113775
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113776
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0602340
Facility Type:	ER
DER Facility ID:	310476
Site ID:	364789
DEC Region:	3
Spill Date:	2006-06-01
Spill Number/Closed Date:	0602340 / 2006-06-07
Spill Cause:	Housekeeping
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-06-01
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other

GETTY 58114 (Continued) **S107657288**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-01
Spill Record Last Update:	2006-06-07
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	""
Remarks:	"SPEEDI DRI DOWN STAINING ONLY"

Material:

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112286
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0601041
Facility Type:	ER
DER Facility ID:	310476
Site ID:	363188
DEC Region:	3
Spill Date:	2006-04-27
Spill Number/Closed Date:	0601041 / 2006-04-27
Spill Cause:	Housekeeping

GETTY 58114 (Continued) **S107657288**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2006-04-27
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-27
Spill Record Last Update:	2006-05-02
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	MIKE CARR
Contact Phone:	(518) 369-7822
DEC Memo:	"5/2/06: Staining - cleaned up NFA"
Remarks:	"speedi dri applied and cleaned up"

Material:

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110750
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01

GETTY 58114 (Continued) **S107657288**

Material ID:	2110748
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

BB310 **SUNOCO / A-PLUS** **NY LTANKS** **S102233475**
ENE **71 HUGUENOT** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.382 mi.
2017 ft. **Site 2 of 2 in cluster BB**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	255332
Spill Number/Closed Date:	9514850 / 1996-07-26
Spill Date:	1996-02-20
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-20
Spill Record Last Update:	1996-09-05
Spiller Name:	RUSSELL HAMMOND
Spiller Company:	SUNOCO / A-PLUS
Spiller Address:	71 HUGUENOT
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209140
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SUNOCO / A-PLUS (Continued) **S102233475**

Remarks: GHIOSAY 07/26/96 EPS SUBMITTED G.W. INVESTIAGATION WHICH INDICATES THAT SUNOCO IS THE SOURCE OF G.W. CONTAM. ON 15 RIVER ST. " "soil boring for assessment for station upgrade - head space reading indicates potential of petroleum release"

Material:

Site ID:	255332
Operable Unit ID:	1025945
Operable Unit:	01
Material ID:	354972
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9610201
Facility Type:	ER
DER Facility ID:	201279
Site ID:	245037
DEC Region:	3
Spill Date:	1996-02-28
Spill Number/Closed Date:	9610201 / 2005-01-20
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-11-15
CID:	366
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-15
Spill Record Last Update:	2005-01-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	RUSSELL HAMMOND

SUNOCO / A-PLUS (Continued) **S102233475**

Contact Phone: (516) 239-2431
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 11/15/96 PETROLEUM FOUND DURING WELL SAMPLING; 09/22/97 LETTER SENT; REMEDIATION IS REQUIRED AT THIS SITE; 01/02/98 LETTER SENT; REMEDIATION PROPOSAL IS APPROVED; WORK MUST START WITHIN THIRTY DAYS; 12/30/99 LETTER SENT TO SUN COMPANY; PROPOSAL TO INSTALL HI-VAC SYSTEM AT THIS SITE IS APPROVED & REQUIRED 1/20/05 nfa letter has been sent do to low and declining groundwater contamination--close 05/18/00 LETTER SENT TO MATRIX ENV. BY J. HARDY; REMEDIAL ACTION PLAN OF 1/12/00 IS APPROVED AND REQUIRED 04/19/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; YOU ARE AUTHOR IZED TO OPERATE REMEDIAL SYSTEMS FOR 90 DAYS WHILE DISCHARGE PERMIT APPLICATIONS ARE BEING PROCESSED 06/22/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; AUTHORIZED BY WCDOH TO OPERATE SYSTEM FOR 90 DAYS WHILE PERMITTING IS IN PROGRESS 05/09/03: Letter sent to Matrix Env. Tech. by J. Hardy; Report submitted dated March 20, 2003. Next report due after completion of one year monitoring period. 2/12/04: Letter sent to Matrix Env. Tech. by J. Hardy. No further action is required at this time. Spill cannot be closed due to BTEX levels in monitoring wells 2 & 4."
Remarks: "while removing old tanks discovered contaminated soil. caller's company is cleaning. "

Material:
Site ID: 245037
Operable Unit ID: 1038129
Operable Unit: 01
Material ID: 342418
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported
Site ID: 245037
Operable Unit ID: 1038129
Operable Unit: 01
Material ID: 2096838
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BD311 **6 WEBSTER** **NY LTANKS** **S106472061**
SSW **6 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.384 mi.
2025 ft. **Site 2 of 3 in cluster BD**

Relative:
Lower

Actual:
60 ft.

LTANKS:

Site ID:	81655
Spill Number/Closed Date:	0403816 / 2004-10-08
Spill Date:	2004-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-07-09
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-09
Spill Record Last Update:	2004-10-08
Spiller Name:	SANDRA
Spiller Company:	Not reported
Spiller Address:	6 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SANDRA
Spiller Phone:	(914) 738-4106
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75517
DEC Memo:	"10/08/04 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. SPILL CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NFA REQUIRED AT THIS TIME. jbo "
Remarks:	"tank test failed.uncover the tank isolate,and retest"

Material:

Site ID:	81655
Operable Unit ID:	886220
Operable Unit:	01
Material ID:	491374
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

6 WEBSTER (Continued) **S106472061**

Tank Test:

Site ID:	81655
Spill Tank Test:	1529427
Tank Number:	1
Tank Size:	3000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BF312 **SPILL NUMBER 0314082** **NY LTANKS** **S106385679**
West **136 VANGUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.386 mi.
2040 ft. **Site 1 of 2 in cluster BF**

Relative:
Lower

Actual:
76 ft.

LTANKS:

Site ID:	80232
Spill Number/Closed Date:	0314082 / 2004-06-08
Spill Date:	2004-03-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-25
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-25
Spill Record Last Update:	2004-06-08
Spiller Name:	SILVANA CARRUSA
Spiller Company:	Not reported
Spiller Address:	136 VANGUILDER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SILVANA CARRUSA
Spiller Phone:	(914) 654-1101
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74387
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/08/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 43.55 TONS OF CONTAMINATED SOIL. NFA REQUIRED. jbo"
Remarks:	"tank test failed. repair and retest and remove"

SPILL NUMBER 0314082 (Continued) **S106385679**

Material:

Site ID:	80232
Operable Unit ID:	881015
Operable Unit:	01
Material ID:	495664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	80232
Spill Tank Test:	1529072
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BG313 **STEWART RESIDENCE** **NY LTANKS** **S109414263**
NW **100 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.388 mi.
2047 ft. **Site 1 of 6 in cluster BG**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	462885
Spill Number/Closed Date:	1200264 / 2012-08-13
Spill Date:	2012-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-04-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-10

STEWART RESIDENCE (Continued) **S109414263**

Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	STEWART
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	STEWART
Spiller Phone:	914-235-6390
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	326980
DEC Memo:	"4-10-12 Spoke with Kathy. Failed with a popping sound. They have recommended a retest because this sound usually means piping or fitting leak. Homeowner is elderly so they are dealing with her daughter, Eunice at 914-715-1040. jm 8/13/2012: Envirostar removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"550gal ust"

Material:

Site ID:	462885
Operable Unit ID:	1212990
Operable Unit:	01
Material ID:	2210869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0811178
Facility Type:	ER
DER Facility ID:	326980
Site ID:	408736
DEC Region:	3
Spill Date:	2009-01-09
Spill Number/Closed Date:	0811178 / 2009-01-09
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	dxweitz
Referred To:	Not reported
Reported to Dept:	2009-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling

STEWART RESIDENCE (Continued) **S109414263**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-09
Spill Record Last Update:	2009-01-09
Spiller Name:	SUE LUGO
Spiller Company:	TOWN & COUNTRY OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	NN
Spiller Company:	999
Contact Name:	NECOLA STEWART
Contact Phone:	(914) 235-6390
DEC Memo:	"1/9/09 Problem with the vent whistle. Town and Country is there fixing the vent, and cleaning up the 1 gal spill. NFA dw"
Remarks:	"Caller states during a fill some oil sprayed out of the vent pipe onto soil. Spill was cleaned."

Material:

Site ID:	408736
Operable Unit ID:	1165255
Operable Unit:	01
Material ID:	2156662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0612561
Facility Type:	ER
DER Facility ID:	326980
Site ID:	377421
DEC Region:	3
Spill Date:	2007-02-19
Spill Number/Closed Date:	0612561 / 2007-03-12
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-02-19
CID:	410
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party

STEWART RESIDENCE (Continued) **S109414263**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-20
Spill Record Last Update:	2007-03-12
Spiller Name:	SUZANNE LUGO
Spiller Company:	TOWN AND COUNTRY OIL
Spiller Address:	275 EAST 7TH STREET
Spiller City,St,Zip:	MOUNT VERNON, NY 10550
Spiller Company:	001
Contact Name:	NECOLA STEWART
Contact Phone:	(914) 235-6390
DEC Memo:	""
Remarks:	"SPILL WAS LESS THAN ONE GALLON ON ICE OUTSIDE OF RESIDENCE: CLEANUP IN PROGRESS: MATERIAL CAME OUT OF VENT PIPE:"

Material:

Site ID:	377421
Operable Unit ID:	1134955
Operable Unit:	01
Material ID:	2124838
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BE314 **CITGO STATION** **NY LTANKS S103568792**
West **210 WEBSTER AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2090 ft. **Site 2 of 2 in cluster BE**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	492314
Spill Number/Closed Date:	1311416 / Not Reported
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06

CITGO STATION (Continued) **S103568792**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2014-03-06
Spiller Name:	Not reported
Spiller Company:	LINE TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	VISHAL KUMAR
Spiller Phone:	(914) 632-2364
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	216842
DEC Memo:	"Wanye Schneider, WCDOH, is handling...mm"
Remarks:	"regular and super product line test failure - repair/retest pending"

Material:

Site ID:	492314
Operable Unit ID:	1241846
Operable Unit:	01
Material ID:	2242337
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1200103
Facility Type:	ER
DER Facility ID:	216842
Site ID:	462718
DEC Region:	3
Spill Date:	2012-04-04
Spill Number/Closed Date:	1200103 / 2013-11-06
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2012-04-04
CID:	Not reported

CITGO STATION (Continued) **S103568792**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-04
Spill Record Last Update:	2013-11-06
Spiller Name:	MR KUMAR
Spiller Company:	SSN REALTY
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MR KUMAR
Contact Phone:	917 535-6017
DEC Memo:	"4-4-12: V.Mc. call to Mr.Kumar: Phone # no longer is service. 4-4-12: V.Mc. call to SEBASTIAN/WCHD: Left Mess.: Req. callbk. to Dispt. Update from WCDOH: greater than greater than greater than Bimonte, Sebastian greater than spb4@westchestergov.com greater than 4/5/2012 9:46 AM greater than greater than greater than John, SSN Realty 210 Webster Ave New Rochelle NY Super Tank product in interstitial space. Manual check during PBS inspection yesterday. Product clear no water or dirt. Diesel Tank product in interstitial space. Manual check during PBS Inspection yesterday. Product clear no water of dirt. Tanks One was hired to test inner and outer tanks. Super, inner wall passed, outer wall failed. Diesel inner wall failed, outer wall passed. Both tanks should be pumped out by today. Sebastian Bimonte jod 5/23/2012 -- After a meeting in NPO among owner, tank maintenance contractor, Mr. Nesci (attorney), WC DOH, and CK last Friday (5/18), Ispoke to Rachel at Hydro Environmental about a site assessment. Work plan to be submitted shortly. ELM 6/05/12: Update received from Sebastian Bimonte of WCDOH PBS: 1200103: SNN Realty in Mount Vernon. This was product in the interstitial during PBS inspection. No release to environment. Tank repaired NOH issued and can be closed. jod 6/5/2012 -- Site assessment being conducted at my request: field work on 210 Webster Ave in New Rochelle on Tuesday, June 12, 2012 per email from Hydro Enviro. ELM 7/31/2012 -- RI report clearly shows groundwater contamination (BETX/MTBE) around the tank field and dispensers. Need further delineation and RAP. Nothing in unsaturated soils. ELM 8/22/2012 -- Contractor working on a Phase II RI work plan. ELM 9/19/2012 -- Approved an RI work plan. Except that they did include the schedule and failed to mention RAP possibilities. ELM 1/22/2013 -- HydroTech informed me that they have the permit needed from the muny to perform the remediation. ELM 2/21/2013 -- Still no word on mobilizing for remediation. ELM 11-6-13 email from county, There is a whole history here.The 1200103 was for product in the interstitial. Sebastian and Carlos worked with Ed Moore on it.Basically double walled tanks leaked into the interstitial. It appear to be the striker plate were missing and from sticking the tanks they wore out. Eastmond lined the tanks and had trouble removing the product from the IS (completely). We requested spill closure and Ed Moore kept the spill open and continued to work on the PBS issues. They are replacing all tanks now. American Petroleum (Ed- Thank You for making this happen)Wayne Schneider is

CITGO STATION (Continued) **S103568792**

	inspected the site this afternoon and will handle the spill. I suggest we close out spill 1200103 and keep 1307998.(Wayne please provide a brief update to all after your inspection today.) 11-6-13 tanks yanked, new spill 13-07998, close this one RDB "
Remarks:	"12 oz per product found during investigation on inter.cont., on the super tank and diesel tank."

Material:

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210675
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0600746
Facility Type:	ER
DER Facility ID:	216842
Site ID:	362821
DEC Region:	3
Spill Date:	2006-04-19
Spill Number/Closed Date:	0600746 / 2006-08-15
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-04-19
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported

CITGO STATION (Continued) **S103568792**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-04-19
Spill Record Last Update:	2006-12-28
Spiller Name:	SEBASTIAN BELLAFONTE
Spiller Company:	CITGO STATION.
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN BELLAFONTE
Contact Phone:	Not reported
DEC Memo:	"04/25/06: refer to WC PBS. 12/21/06 - Letter from Barbara McDonald from WCDOH to Sebastian Bulfamonte, SSN Realty 94 1st Street, New Rochelle, NY 10801, states that documentation is acceptable to the Westchester County Department of Health and the work permits issued 5/11/06 and 6/6/06 are closed. NFA."
Remarks:	"FOUND THE MATERIAL BETWEEN THE INTERSTIAL SPACE OF THE TWO TANKS. 4000 GAL TANKS. PBS 3-180092"

Material:

Site ID:	362821
Operable Unit ID:	1120900
Operable Unit:	01
Material ID:	2110381
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0413599
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342744
DEC Region:	3
Spill Date:	2005-03-30
Spill Number/Closed Date:	0413599 / 2005-03-30
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6000
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

CITGO STATION (Continued) **S103568792**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN
Contact Phone:	(914) 447-6407
DEC Memo:	""
Remarks:	"IT WAS SOME RESIDEU IN A SPILL BUCKET ALL CLEANED UP:"

Material:

Site ID:	342744
Operable Unit ID:	1101460
Operable Unit:	01
Material ID:	581627
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0413600
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342745
DEC Region:	3
Spill Date:	2005-03-30
Spill Number/Closed Date:	0413600 / 2005-03-30
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6000
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

CITGO STATION (Continued) **S103568792**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	SEBASTIAN
Contact Phone:	(914) 447-6407
DEC Memo:	""
Remarks:	"WHILE CHANGING OIL THEY KICKED A BUCKET OVER AND IN PROCESS OF CLEANING UP AT THIS TIME;"

Material:

Site ID:	342745
Operable Unit ID:	1101461
Operable Unit:	01
Material ID:	581628
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	8906053
Facility Type:	ER
DER Facility ID:	216842
Site ID:	266088
DEC Region:	3
Spill Date:	1989-07-22
Spill Number/Closed Date:	8906053 / 1989-09-21
Spill Cause:	Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-09-19
Cleanup Meets Std:	True
Last Inspection:	1989-09-19

CITGO STATION (Continued) **S103568792**

Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	MAR-LAP SVC CNTR
Spiller Address:	210 WEBSTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL."
Remarks:	"HAVE EXCAVATED AND REMOVED GAS CONTAMINATED SOIL FROM AROUND 3 5ANKS. SOIL BEING REMOVED TODAY BY E.E.S. NFA"

Material:

Site ID:	266088
Operable Unit ID:	931218
Operable Unit:	01
Material ID:	446446
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

315
SE
1/4-1/2
0.397 mi.
2097 ft.

SPILL NUMBER 0302495 **NY LTANKS S105999167**
85 NORTH AVE **NY Spills N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	353132
Spill Number/Closed Date:	0507677 / 2009-10-09
Spill Date:	2005-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jkomara

SPILL NUMBER 0302495 (Continued) **S105999167**

Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2009-10-09
Spiller Name:	FRANK
Spiller Company:	GAS STATION
Spiller Address:	85 NORTH AVE.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FRANK
Spiller Phone:	(914) 632-2109
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	"9/28/05 Also see spills 03-04446, 05-11827 and 05-07653. jod Closure report received and site visit with WCHD performed. NFA if no money State money spent on Spill # 0304446 pin # 03236. 4/5/07 JO'M 10/9/09 Closed this spill refer to 0304446 JO'M"
Remarks:	"LINE FAILURE."

Material:

Site ID:	353132
Operable Unit ID:	1110599
Operable Unit:	01
Material ID:	2100636
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	114935
Spill Number/Closed Date:	0302495 / 2003-08-12
Spill Date:	2003-06-09
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD

SPILL NUMBER 0302495 (Continued) **S105999167**

Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-09
CID:	405
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-08-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	85 NORTH AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DISPATCHER 629
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	""
Remarks:	"caller states that there is an overspill at the above address - some has gone into the sewer - cell # 914-760-1305 is for the fire chief on scene - unknown if the spill is stopped or not"

Material:

Site ID:	114935
Operable Unit ID:	869316
Operable Unit:	01
Material ID:	506969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0507653
Facility Type:	ER
DER Facility ID:	100200
Site ID:	353098
DEC Region:	3
Spill Date:	2005-09-26
Spill Number/Closed Date:	0507653 / 2005-10-07
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010

SPILL NUMBER 0302495 (Continued) **S105999167**

Investigator:	JKOMARA
Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2005-10-07
Spiller Name:	FRANK
Spiller Company:	FRANKIES AUTO
Spiller Address:	85 NORTH AVE.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	FRANK
Contact Phone:	(914) 632-2109
DEC Memo:	"9/28/05 Also see spills 03-04446, 03-11827 and 05-07677. jod 10/07/05 Refer to spill 05-07677 for all updates. This spill number closed. jod"
Remarks:	"GASOLINE IN SANITARY SEWER NEXT TO STATION AND ODORS: PLEASE CALL DOH ON THIS ISSUE"

Material:

Site ID:	353098
Operable Unit ID:	1110568
Operable Unit:	01
Material ID:	2100602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA316 **JEROME RESIDENCE** **NY LTANKS** **S106702572**
ENE **33 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2097 ft. **Site 3 of 4 in cluster BA**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	235222
Spill Number/Closed Date:	0405389 / 2005-02-13
Spill Date:	2004-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

JEROME RESIDENCE (Continued) **S106702572**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-08-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-17
Spill Record Last Update:	2005-02-13
Spiller Name:	MARK JEROME
Spiller Company:	JEROME RESIDENCE
Spiller Address:	33 ECHO AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARK JEROME
Spiller Phone:	(914) 632-5400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193747
DEC Memo:	"02/13/05 MILLER ENVIRONMENTAL REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- ISOLATION & RETEST"

Material:

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489552
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

JEROME RESIDENCE (Continued) **S106702572**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 235222
Spill Tank Test: 1529557
Tank Number: Not reported
Tank Size: 1000
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

BG317 **BRIEN-AMIE RESIDENCE** **NY LTANKS** **S105999591**
NW **105 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2098 ft. **Site 2 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:
Site ID: 219644
Spill Number/Closed Date: 0304963 / 2004-02-02
Spill Date: 2003-08-08
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-08-11
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-08-11
Spill Record Last Update: 2004-02-02
Spiller Name: BRIEN-AMIE RESIDENCE
Spiller Company: Not reported
Spiller Address: 105 SICKLES AVE
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller County: 001
Spiller Contact: BRIEN-AMIE RESIDENCE
Spiller Phone: (914) 576-6823
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 181652
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/11/03: 1000 gal. underground tank. 02/02/04 DUTCHESS

BRIEN-AMIE RESIDENCE (Continued) **S105999591**

DISPOSED OF LUST AND 75.35 TONS OF CONTAMINATED SOIL. SAMPLE RESULTS BELOW TAGM LIMITS. NFA jbo"

Remarks: "they were doing an inplace closure tank abandonment & encountered contaminated soil from the 550 gal underground tank - unk about soil removal at this point"

Material:

Site ID:	219644
Operable Unit ID:	873280
Operable Unit:	01
Material ID:	502238
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH318 **MICELI HOME** **NY LTANKS** **S108059468**
SSE **194 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2098 ft. **Site 1 of 4 in cluster BH**

Relative: **Lower**

Actual: **78 ft.**

LTANKS:

Site ID:	366997
Spill Number/Closed Date:	0604103 / 2006-10-22
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-10-22
Spiller Name:	MARIO MICELI
Spiller Company:	MICELI HOME
Spiller Address:	194 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY

MICELI HOME (Continued) **S108059468**

Spiller County:	001
Spiller Contact:	MARIO MICELI
Spiller Phone:	(914) 235-2198
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317018
DEC Memo:	"CLOSING REPORT TO JOHN O'DEE. October 22, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 23.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 gallon tank had holes"

Material:

Site ID:	366997
Operable Unit ID:	1124924
Operable Unit:	01
Material ID:	2114431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BA319 **POWERTEST,ECHO & MAIN** **NY LTANKS** **S100139866**
ENE **36 ECHO AVE @ MAIN ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2111 ft. **Site 4 of 4 in cluster BA**

Relative:
Lower

Actual:
33 ft.

LTANKS:

Site ID:	283199
Spill Number/Closed Date:	8709260 / 1988-02-11
Spill Date:	1988-01-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1988-02-11
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True

POWERTEST,ECHO & MAIN (Continued) **S100139866**

Remediation Phase:	0
Date Entered In Computer:	1988-02-01
Spill Record Last Update:	1988-06-13
Spiller Name:	Not reported
Spiller Company:	HACKER,JOSHUA;POWERTEST
Spiller Address:	Not reported
Spiller City,St,Zip:	LISK, MA
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229700
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 02-01-88 TANK REPLACED 5 YRS.AGO. AS PER DEPUTY CHIEF WILLIAM COMVERY,BASEMENT ODORS GREATLY DISSAPATED, ONCE VENTED. 02/11/88: CHECKED STATION; SEEMS TO BE ODOR PROBLEM DURING DELIVERIES. 11/29/95: This is additional information about material spilled from the translation of the old spill file: FUMES."
Remarks:	"DELIVERY THIS MORNING, ONGOING PROBLEM, EXPLOSIVE READING IN BASEMENT. NEW ROCHELLE F.D. HAS VENTED BASEMENT AND WILL MONITOR."

Material:

Site ID:	283199
Operable Unit ID:	914517
Operable Unit:	01
Material ID:	464589
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG320 **POINVIL RESIDENCE** **NY LTANKS** **S111160012**
NW **107 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2113 ft. **Site 3 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	452458
Spill Number/Closed Date:	1104844 / 2014-11-05
Spill Date:	2011-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False

POINVIL RESIDENCE (Continued) **S111160012**

SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-28
Spill Record Last Update:	2014-11-05
Spiller Name:	HENRY POINVILE
Spiller Company:	POINVILE
Spiller Address:	107 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NN
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	407046
DEC Memo:	"7-28-11 Spoke with Kathy Morgan, This a is a real estate transaction. The plan at this time is to uncover, isolate and retest. The tank is 1080 gallon UST that is probably the original tank - age unknown. jm 2/17/12: Residential TTF, DEC Lead changed to unassigned. jod 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M"
Remarks:	"repair/retest pending -"

Material:

Site ID:	452458
Operable Unit ID:	1202639
Operable Unit:	01
Material ID:	2199228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BD321 **AMOCO SERVICE STATION #736** **NY LTANKS** **1001128018**
SSW **690 MAIN ST** **NY Spills** **NYR000036855**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.403 mi. **NY MANIFEST**
2128 ft. **Site 3 of 3 in cluster BD**

Relative:
Lower

Actual:
64 ft.

LTANKS:

Site ID:	274754
Spill Number/Closed Date:	0209490 / 2002-12-16
Spill Date:	2002-12-16
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-16
CID:	246
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2002-12-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller County:	999
Spiller Contact:	DAVE BERRY
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"Tanker overfilled tank and material spilled at location. Approx 10 gal went into storm drain and sewer. Fire dept on scene now speedy dry applied"

Material:

Site ID:	274754
Operable Unit ID:	862563
Operable Unit:	01
Material ID:	512914
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	Gallons
Recovered:	15.00
Resource Affected:	Not reported
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Tank Test:

Site ID:	274755
Spill Number/Closed Date:	0212950 / 2003-04-01
Spill Date:	2003-03-31
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-03-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-31
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	WESTCHESTER CO 911
Spiller Phone:	(914) 231-1904
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"PRODUCT DID ENTER CONTAINMENT AREA - NO CLEAN UP"

Material:

Site ID:	274755
Operable Unit ID:	863771
Operable Unit:	01
Material ID:	512669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Site ID:	274757
Spill Number/Closed Date:	8604411 / 1987-01-14
Spill Date:	1986-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1987-01-14
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-01-14
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-10-16
Spill Record Last Update:	1998-03-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	SAME
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"TTTF"

Material:

Site ID:	274757
Operable Unit ID:	901332
Operable Unit:	01
Material ID:	477220
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Pounds
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	274757
Spill Tank Test:	1530280
Tank Number:	Not reported
Tank Size:	0
Test Method:	00

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

SPILLS:

Facility ID:	0305414
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274756
DEC Region:	3
Spill Date:	2003-08-21
Spill Number/Closed Date:	0305414 / 2003-10-29
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-08-21
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2003-10-29
Spiller Name:	Not reported
Spiller Company:	USA PETRO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	CINDY BADOLATO
Contact Phone:	(914) 813-5165
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BADOLATO 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED AS OF 9/12/03"
Remarks:	"leaking valve on a pump - pbs #3-183660 - pump taken out of service"

Material:

Site ID:	274756
Operable Unit ID:	873709
Operable Unit:	01
Material ID:	502669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	0002007
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274753
DEC Region:	3
Spill Date:	2000-05-17
Spill Number/Closed Date:	0002007 / 2000-05-17
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-17
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-05-17
Spill Record Last Update:	2000-07-17
Spiller Name:	ALFRED
Spiller Company:	AM0CO STATION 736
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ALFRED
Contact Phone:	(914) 632-8617
DEC Memo:	""
Remarks:	"maintance crew on the way for cleanup and repairs"

Material:

Site ID:	274753
Operable Unit ID:	823636
Operable Unit:	01
Material ID:	550387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Tank Test:

Facility ID:	9806161
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274759
DEC Region:	3
Spill Date:	1998-08-18
Spill Number/Closed Date:	9806161 / 2005-02-14
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-08-18
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-18
Spill Record Last Update:	2005-02-14
Spiller Name:	ERIC LISMANIS
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	ERIC LISMANIS
Contact Phone:	(914) 273-2626
DEC Memo:	"2/14/05 HANDLE AS PART OF 9613029--CLSOE"
Remarks:	"PUMP MALFUNCTION FOR UNDERGROUND STORAGE TANK / NO CLEAN UP"

Material:

Site ID:	274759
Operable Unit ID:	1067358
Operable Unit:	01
Material ID:	317336
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Facility ID:	9613029
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274758
DEC Region:	3
Spill Date:	1997-01-29
Spill Number/Closed Date:	9613029 / 2013-04-26
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1997-02-04
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-04
Spill Record Last Update:	2013-04-26
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY ALSO SEE SPILL 91-11342. 02/07/97 AS PART OF AN ONGOING REMEDIATION THEY FOUND NEWER PRODUCT INFLUENCING THEIR CLEAN UP. 04/24/97 LETTER & STIPULATION AGREEMENT SENT TO BE SIGNED. 12/10/97 COPY OF SIGNED STIPULATION SENT BACK 08/11/98 LETTER SENT; IMMEDIATE ACTION TOWARD AUTOMATED PRODUCT REMOVAL AND GROUNDWATER CONTROL AT SITE IS REQUIRED. 12/07/00 LETTER SENT TO DELTA ENVIRONMENTAL BY J. HARDY; PROPOSE A REMEDIAL ACTION PLAN WHICH IS SUBSTANTIALLY MORE AGRESSIVE THAN THE ONE EXISTING AT THIS TIME. 01/11/01 LETTER SENT TO DELTA ENV. BY J. HARDY; CONCEPTUAL REMEDIAL ACTION PLAN OF 12/13/00 IS APPROVED & REQUIRED. 4/23/04: Letter to Aaron Lapine, Delta Env. Consultants by J. Hardy. Submit one report per year. Include operating data and GW monitoring data in same report. 8/9/04: Letter to A. Lapine, Delta Env. from J Hardy. Reduce monitor well sampling to semi-annual. Report annually. 6/15/09 annual submitted 6/9/09 shows relatively stable groundwater levels but no info as to system operation--sent email to envirotrac to submit operation info jh 4/20/10 site in remediation as system has been operating for many years. Original impacts to adjoining restaurant have also been resolved for years so it seems spill is contained; spill cannot be closed however as there is still significant contamination jh 07/02/12 Contaminated soils on the station have been excavated down to bedrock. 4 gw wells remain, 1 on-site upgradient, 2 off-site downgradient , 1 in the tank field. After review of the documentation

AMOCO SERVICE STATION #736 (Continued) **1001128018**

and a phone conversation, consultant will submit a quarterly groundwater monitoring plan for the next year, after which time the monitoring frequency may be adjusted based on results. It appears the source has been removed. mt 4/26/13 Spill Closed, asymptptic conditions approaching gw standards in final well. no further action required. mt "

Remarks: "THEY HAVE A 1991 SPILL NUMBER, BUT THIS APPEARS TO BE A FRESH SPILL UNK IF SAME"

Material:

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	2096843
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	341679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Facility ID:	9313209
Facility Type:	ER
DER Facility ID:	101511
Site ID:	116685
DEC Region:	3
Spill Date:	1994-02-07
Spill Number/Closed Date:	9313209 / 1994-02-28
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-07
CID:	Not reported
Water Affected:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	1994-06-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/03/94: NO DEC RESPONSE. "
Remarks:	"ICE IN FILL BOX SORBENTS USED TO CLEAN UP"

Material:

Site ID:	116685
Operable Unit ID:	995095
Operable Unit:	01
Material ID:	388600
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AMOCO SERVICE STATION #736
Facility address:	690 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYR000036855
Mailing address:	OLD POST RD BALTEZ ASSOCIATES INC BEDFORD, NY 10506
Contact:	Not reported
Contact address:	OLD POST RD BEDFORD, NY 10506
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: (201) 331-7000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: (201) 331-7000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AMOCO SERVICE STATION #736
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: AMOCO SERVICE STATION #736
Classification: Small Quantity Generator

Date form received by agency: 03/21/1997
Site name: AMOCO SERVICE STATION #736
Classification: Large Quantity Generator

. Waste code: D001

AMOCO SERVICE STATION #736 (Continued) **1001128018**

. Waste name: IGNITABLE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000036855
Country: USA
Location Address 1: 690 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: AMOCO SERVICE STATION #736
Contact: JONATHAN LANDAU
Address: 130 BUSINESS PARK DR
City/State/Zip: ARMONK, NY 10504
Country: USA
Phone: 914-234-9580

Manifest:

Document ID: CTF0396117
Manifest Status: Completed copy
Trans1 State ID: 7069A
Trans2 State ID: Not reported
Generator Ship Date: 04/24/1997
Trans1 Recv Date: 04/24/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 04/25/1997
Part A Recv Date: 05/21/1997
Part B Recv Date: 05/15/1997
Generator EPA ID: NYR000036855
Trans1 EPA ID: CTD983883745
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00619
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1997

Document ID: NYG0063774
Manifest Status: Not reported
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 04/27/1998
Trans1 Recv Date: 04/27/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Generator EPA ID:	NYR000036855
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID:	GAD093380814
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

BI322 **RESIDENCE** **NY LTANKS** **S107523528**
East **10 LAFAYETTE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2132 ft. **Site 1 of 3 in cluster BI**

Relative:
Lower

Actual:
47 ft.

LTANKS:

Site ID:	358990
Spill Number/Closed Date:	0512638 / 2006-03-15
Spill Date:	2006-02-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-01
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-01
Spill Record Last Update:	2006-03-15
Spiller Name:	MARIO KOTLAR
Spiller Company:	RESIDENCE
Spiller Address:	10 LAFFEYTE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	MARIO KOTLAR
Spiller Phone:	(914) 235-8882
Spiller Extention:	Not reported
DEC Region:	3

RESIDENCE (Continued) **S107523528**

DER Facility ID: 308993
DEC Memo: "Northeast to return 2/3/06 for soil excavation & sampling. March 15, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 42.57 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Tank removal, tank size 1000 gallon."

Material:
Site ID: 358990
Operable Unit ID: 1116216
Operable Unit: 01
Material ID: 2106363
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BF323 **YOUNG ADULT INSTITUTE** **NY LTANKS** **S107410752**
West **150 VAN GUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 2 of 2 in cluster BF**

Relative:
Lower

Actual:
77 ft.

LTANKS:
Site ID: 353295
Spill Number/Closed Date: 0507808 / 2005-12-18
Spill Date: 2005-09-29
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-09-29
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-09-29
Spill Record Last Update: 2005-12-18
Spiller Name: MARGARET FORC
Spiller Company: YOUNG ADULT INSTITUTE
Spiller Address: 150 VAN GUILDER AVE

YOUNG ADULT INSTITUTE (Continued) **S107410752**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARGARET FORC
Spiller Phone:	(212) 273-6172
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300615
DEC Memo:	"Left message with contact. Robison returning to clean up fuel in street. New England was removing UST and some product leaked out of tank on ground. Area roped off by Fire Marshal. December 18, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 13.63 TONS OF CONTAMINATED SOIL. CLEAN UP COMPLETED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. DISPOSAL RECEIPT FORWARDED TO BECI. jod"
Remarks:	"550 GALLON TANK AND FOUND HOLES: FIRE MARSHALL ON SCENE"

Material:

Site ID:	353295
Operable Unit ID:	1110757
Operable Unit:	01
Material ID:	2100797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BJ324 **COMMERCIAL-TTF** **NY LTANKS** **S117975659**
West **172 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2133 ft. **Site 1 of 4 in cluster BJ**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	508618
Spill Number/Closed Date:	1502358 / Not Reported
Spill Date:	2015-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported
Water Affected:	Not reported

COMMERCIAL-TTF (Continued) **S117975659**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2015-08-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	463301
DEC Memo:	"6/3/15 Spoke to Mr. Scorzelli, who did not have contact info for owner at that time, and does not know what owner will be doing. dw "
Remarks:	"TEST FAILURE"

Material:

Site ID:	508618
Operable Unit ID:	1257927
Operable Unit:	01
Material ID:	2260991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG325 **TAHIR RESIDENCE** **NY LTANKS** **S108299038**
NW **112 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2147 ft. **Site 4 of 6 in cluster BG**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Site ID:	374522
Spill Number/Closed Date:	0610140 / 2007-10-24
Spill Date:	2006-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA

TAHIR RESIDENCE (Continued) **S108299038**

Referred To:	Not reported
Reported to Dept:	2006-12-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-06
Spill Record Last Update:	2007-10-24
Spiller Name:	ISMAIL GALVAN
Spiller Company:	Not reported
Spiller Address:	112 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	ISMAIL GALVAN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	324199
DEC Memo:	"09/18/07 Dutchess Environmental reported that the 550 gallon tank was removed and that no sign of oil contamination was observed in the tank grave. NFA TG"
Remarks:	"UNCOVER REPAIR AND TEST OR REMOVE"

Material:

Site ID:	374522
Operable Unit ID:	1132196
Operable Unit:	01
Material ID:	2121918
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	374522
Spill Tank Test:	1550484
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

SPILLS:

Facility ID:	0911724

TAHIR RESIDENCE (Continued) **S108299038**

Facility Type:	ER
DER Facility ID:	324199
Site ID:	424559
DEC Region:	3
Spill Date:	2010-02-02
Spill Number/Closed Date:	0911724 / 2010-03-22
Spill Cause:	Human Error
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2010-02-12
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2010-03-22
Spiller Name:	CHRIS
Spiller Company:	PARADISE OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ISHMAEL TAHIR
Contact Phone:	(914) 563-5682
DEC Memo:	"2/3/10 homeowner, Mr. Tahir, is satisfied with cleanup done by Paradise Oil Co., both inside and outside the house. NFA dw 2/12/10: Spill re-opened. WCDOH reported this spill, after complaints by home owner that the oil company had taken no action. Marc Grazioli re-inspected the site today and reports the spill has still not been remediated. jod 2/17/10: Update from Marc Grazioli: The outside portion of the spill was handled before the big snow that came last week. I was only able to look into the basement through an open window since no one was home when I was there. There was absorbent on the ground and I would guess it was the second round of cleanup because it appeared dry. jod 3/22/10: DEC requires no further action at this time. jod"
Remarks:	"5gals oil to basement area/10 gals to out side,driveway. Clean up complete"

Material:

Site ID:	424559
Operable Unit ID:	1180325
Operable Unit:	01
Material ID:	2174200
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons

TAHIR RESIDENCE (Continued) **S108299038**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BK326 **GAS STATION** **NY LTANKS** **S116156793**
ENE **44 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2150 ft. **Site 1 of 3 in cluster BK**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	490405
Spill Number/Closed Date:	1309599 / 2014-02-13
Spill Date:	2014-01-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-02
Spill Record Last Update:	2014-02-13
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	CARLOS TORREZ
Spiller Phone:	(914) 424-5927
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"1/2/14 - WCDOH is oversight the ongoing tank tests. KAB 1/2/2014 -- APECCO hired by new operator (lease signed within past 6 weeks). Piping and dispensers and electronic leak monitoring equipment to be replaced. Based on lack of leak detection records for past 10 to 12 years, DEC requested TT and IS tests and system check of electronics. Tanks are probably suitable for service, but testing required for confirmation. It appears to be loose fittings. Electronics recently rewired at the computer console within past couple of weeks, but wiring ended near the top of the tanks. No probes in the interstitial space, just loose wiring near top of tank. Owner’s representative took electronic system wire ends from the site despite WCDOH’s

GAS STATION (Continued) **S116156793**

request to take custody. ELM 2-13-14 closed and referred to spill 13-10365 which revealed contaminated soils when the failed lines were removed. RDB"

Remarks: "repair/retest pending - to Ed Moore (waiting for results)"

Material:

Site ID:	490405
Operable Unit ID:	1239966
Operable Unit:	01
Material ID:	2240056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BK327 **DAVENPORT AUTO / WEST PLAINS SERVICE** **NY LTANKS** **S110309404**
ENE **44 ECHO AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2150 ft. **Site 2 of 3 in cluster BK**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Site ID:	130487
Spill Number/Closed Date:	9201557 / 2006-02-17
Spill Date:	1992-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	1992-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/17/06 SEE SPILLS 92-10118 AND 92-10810. jod"
Remarks:	"FOUND LINE LEAKING AT DISPENSER GASOLINE TANK IS OK MAIN & ELMSFORD TO POSS. REPAIR MONDAY WILLIAMS SUGGESTED TO MAIN & ELMSFORD CO. THAT THEUY SHUT THIS PUMP DOWN UNTIL REPAIRS ARE MADE SPOKE W/ WILL"

Material:

Site ID:	130487
Operable Unit ID:	968828
Operable Unit:	01
Material ID:	412859
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	130487
Spill Tank Test:	1539973
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	130489
Spill Number/Closed Date:	9210810 / 1995-02-09
Spill Date:	1992-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1995-02-09
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E.I.R. PETRO-TITE"

Material:

Site ID:	130489
Operable Unit ID:	975022
Operable Unit:	01
Material ID:	404252
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	130489
Spill Tank Test:	1540972
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

Site ID:	434525
Spill Number/Closed Date:	1001469 / 2010-11-01
Spill Date:	2010-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-07
Spill Record Last Update:	2010-11-01
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	INA -
Spiller Phone:	(914) 235-8073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"5/7/10 Metro Env. tested UST, and it failed a TT. Davenport Auto thinks it may be fuel lines, and got list of contractors to examine problem more closely, and to determine remedial actions. Site is a WCHD-PBS site# 3-137480 Tank was tank #6- 550 gal. dw 11/1/10 As per WCDOH Two tanks pulled, reviewed TCR, recommend NFA. NFA JOM "
Remarks:	"tank test - cleanup pending"

Material:

Site ID:	434525
Operable Unit ID:	1185347
Operable Unit:	01
Material ID:	2179667
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	1310365
Facility Type:	ER
DER Facility ID:	389397
Site ID:	491212
DEC Region:	3
Spill Date:	2014-01-29

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Spill Number/Closed Date:	1310365 / Not Reported
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-01-29
Spill Record Last Update:	2014-07-22
Spiller Name:	Not reported
Spiller Company:	WEST PLAINS SERVICE INC
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MICHAEL BURNSTEIN
Contact Phone:	(914) 235-8073
DEC Memo:	"Chris Lalak called duty desk. American Petro is pulling tanks today. WCDOH is handling this and will do follow up...mm 1/29/2014 -- Called Pat Dunn @ APECCO to get some details. Dispensers had no sumps; discovered soil contamination under a dispenser. Trench along side dispenser is clean to 2 1/2 feet below grade; they expect limited dig and haul. ELM 2-11-14 Iyt was not a tank pull as originally noted by WCHD only line and dispenser replacement. RDB 2-13-14, spill #13-09599 was closed and referred to this one, the line test failure led to thic contamination RDB 03-14 contamination deep in excavation under former dispenser. crews worried about garage and building under neath, met on site with Gary and owner, advised them additional soil needed removal. 03-10-14 Using a Hydro Vac to get the remaining contaminated soils from excavation. 03-18-14 status report in edocs 05-13-14 email from Gary, Work done, report done,plan on forwarding report to you today once we get payment. RDB 07-22-14 gary looking for closure, I am looking for closure report.sent email requesting RDB"
Remarks:	"cleanup in progress"

Material:

Site ID:	491212
Operable Unit ID:	1240767
Operable Unit:	01
Material ID:	2240992
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 9210118
Facility Type: ER
DER Facility ID: 309856
Site ID: 130488
DEC Region: 3
Spill Date: 1992-12-01
Spill Number/Closed Date: 9210118 / 1997-11-07
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-12-01
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1992-12-15
Spill Record Last Update: 2006-02-17
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "GASOLINE ODOR IN BASEMENT OF APARTMENT BUILDING NEXT DOOR TO GAS STATION GAS STATION RECEIVED A DELIVERY AT 8:00 A.M. T. GHIOSAY RESPONDED"

Material:
Site ID: 130488
Operable Unit ID: 976578
Operable Unit: 01
Material ID: 407123
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Pounds
Recovered: .00

DAVENPORT AUTO / WEST PLAINS SERVICE (Continued) **S110309404**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

328
SSW
1/4-1/2
0.409 mi.
2158 ft.

SPILL NUMBER 0012427 **NY LTANKS** **S104950616**
22 LAUREL PL **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	104510
Spill Number/Closed Date:	0012427 / 2001-05-10
Spill Date:	2001-02-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-02-20
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-20
Spill Record Last Update:	2001-06-05
Spiller Name:	LOUIS MEAD
Spiller Company:	Not reported
Spiller Address:	22 LAUREL PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LOUIS MEAD
Spiller Phone:	(914) 662-3557
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92327
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/20/2001 TANK OUT OF USE FOR 20 YEARS. PIN HOLES & MINOR SOIL CONTAMINATION FOUND. 05/10/2001 ELITE ENVIRONMENTAL AND NES PULLED TANK AND COMPLETED CLEANUP; NO FURTHER ACTION."
Remarks:	"small amount of contamination found while pulling a 1000 gal tank. "

Material:

Site ID:	104510
Operable Unit ID:	833963
Operable Unit:	01
Material ID:	542696
Material Code:	0001A

SPILL NUMBER 0012427 (Continued) **S104950616**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH329 **200 CENTRA CORP** **NY LTANKS** **S108059537**
SSE **200 CENTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.412 mi.
2175 ft. **Site 2 of 4 in cluster BH**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Site ID:	367663
Spill Number/Closed Date:	0604650 / 2007-12-12
Spill Date:	2006-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-07-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-25
Spill Record Last Update:	2007-12-12
Spiller Name:	SHARON ROURKE
Spiller Company:	200 CENTRA CORP
Spiller Address:	200 CENTRE AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	SHARON ROURKE
Spiller Phone:	(203) 557-3600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317637
DEC Memo:	"12/04/06 Tank removed and samples ok according to D Jackson - WCHD. TG"
Remarks:	"PBS No: 3-800237 -PBS No. not found in UIS, may be invalid. UNCOVER REPAIR AND TEST"

200 CENTRA CORP (Continued) **S108059537**

Material:

Site ID:	367663
Operable Unit ID:	1125568
Operable Unit:	01
Material ID:	2115091
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	367663
Spill Tank Test:	1550151
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BK330 **CONSOLIDATED EDISON - ECHO AVE. SITE** **NY SHWS** **S101008407**
ENE **ECHO AVENUE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.412 mi.
2178 ft. **Site 3 of 3 in cluster BK**

Relative:
Lower

Actual:
30 ft.

SHWS:

Program:	HW
Site Code:	56077
Classification:	P
Region:	3
Acres:	3
HW Code:	360016
Record Add:	11/18/1999
Record Upd:	04/07/2015
Updated By:	GWHEITZM

Site Description: LocationThe Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. This 3 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal).Site FeaturesAll the former structures and underground utility services have been removed, and the whole site has been levelled, top-soiled and grassed.Current UseThe site is currently vacantPast Use of the SiteCon Edison used the site as an electrical distribution substation until 1981. PCBs transformers were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. The soil on site and the sediment in the Bay were

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

	contaminated with PCBs.
Env Problem:	Prior to remediation the contaminant of concern was PCBs.Remediation of the site is complete. The cleanup of PCBs and other incidentally detected contaminants has mitigated the threat to the environment, and in particular to the natural habitat in the bay.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BJ331 **FIRST ASSEMBLY OF GOD** **NY LTANKS** **S110490783**
West **177 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.414 mi.
2186 ft. **Site 2 of 4 in cluster BJ**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	435290
Spill Number/Closed Date:	1002183 / 2010-08-30
Spill Date:	2010-05-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-26
Spill Record Last Update:	2010-08-30
Spiller Name:	Not reported
Spiller Company:	BARNABY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	BARNABY
Spiller Phone:	(914) 632-0031
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	390193
DEC Memo:	"7/1/10: No call backs made by dispatch desk. No indication of contamination at the time of the report. Unknown action at this time. jod 08/19/10 Northeast Environmental reported that they excavated and removed the LUST along with 40.92 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA. TG"

FIRST ASSEMBLY OF GOD (Continued) **S110490783**

Remarks: "550gal ust"

Material:
Site ID: 435290
Operable Unit ID: 1186074
Operable Unit: 01
Material ID: 2180843
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

332
WSW
1/4-1/2
0.415 mi.
2193 ft.

48 1ST STREET **NY LTANKS** **S104279084**
48 1ST STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:
Site ID: 116893
Spill Number/Closed Date: 9911183 / 1999-12-22
Spill Date: 1999-12-22
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: PJDECICC
Referred To: Not reported
Reported to Dept: 1999-12-22
CID: 389
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-12-22
Spill Record Last Update: 1999-12-30
Spiller Name: CALLER
Spiller Company: CASTLE OIL CORPORTATION
Spiller Address: 290 LOCUST AVENUE
Spiller City,St,Zip: BRONX, NY
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported

48 1ST STREET (Continued) **S104279084**

DEC Region: 3
DER Facility ID: 101696
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO "
Remarks: "caller reporting a spill of material from a tank overfill clean up was done no callback is necessary"

Material:
Site ID: 116893
Operable Unit ID: 1089889
Operable Unit: 01
Material ID: 296651
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: Gallons
Recovered: 5.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BI333 **GONCALVES RESIDENCE** **NY LTANKS** **S108298870**
East **1 LAFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2196 ft. **Site 2 of 3 in cluster BI**

Relative:
Lower

Actual:
35 ft.

LTANKS:
Site ID: 373629
Spill Number/Closed Date: 0609401 / 2007-01-10
Spill Date: 2006-11-15
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-11-15
CID: 410
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-11-15
Spill Record Last Update: 2007-01-10
Spiller Name: ED ALLEN
Spiller Company: ROBINSON OIL
Spiller Address: 500 EXECUTIVE BLVD

GONCALVES RESIDENCE (Continued) **S108298870**

Spiller City,St,Zip:	ELMSFORD, NY
Spiller County:	001
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323367
DEC Memo:	""
Remarks:	"CLEANUP IN PROGRESS:"

Material:

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	Gallons
Recovered:	2.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BI334 **GONCALVES RESIDENCE** **NY LTANKS** **S102674341**
East **1 LAFFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2196 ft. **Site 3 of 3 in cluster BI**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	156301
Spill Number/Closed Date:	9410991 / 1994-11-29
Spill Date:	1994-11-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-11-29
Cleanup Meets Standard:	False

GONCALVES RESIDENCE (Continued) **S102674341**

SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132292
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED 100 GAL. COULDN'T FIT BEING CLEANED NOW SPEEDI-DRI AND PADS COMPLETED"

Material:

Site ID:	156301
Operable Unit ID:	1008868
Operable Unit:	01
Material ID:	376855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BG335 **RESIDENCE** **NY LTANKS** **S107410404**
NW **7 PRINCE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2198 ft. **Site 5 of 6 in cluster BG**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Site ID:	351640
Spill Number/Closed Date:	0506424 / 2005-10-29
Spill Date:	2005-08-24
Spill Cause:	Tank Failure

RESIDENCE (Continued) **S107410404**

Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-24
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-24
Spill Record Last Update:	2005-10-29
Spiller Name:	JOHN BROWN
Spiller Company:	RESIDENCE
Spiller Address:	7 PRINCE ST
Spiller City,St,Zip:	NEW ROCHELLE, NY 10803
Spiller County:	001
Spiller Contact:	JOHN BROWN
Spiller Phone:	(914) 879-7900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	298912
DEC Memo:	"Report to John O'Dee -RA October 29, 2005: CASTLTON DISPOSED OF LUST AND 57.27 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

Material:

Site ID:	351640
Operable Unit ID:	1109140
Operable Unit:	01
Material ID:	2099127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BJ336 **SPILL NUMBER 0210119** **NY LTANKS** **S105997830**
WSW **68 FIRST STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.419 mi.
2212 ft. **Site 3 of 4 in cluster BJ**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	267616
Spill Number/Closed Date:	0210119 / 2003-03-03
Spill Date:	2002-12-03
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-07
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-07
Spill Record Last Update:	2003-03-03
Spiller Name:	OWNER
Spiller Company:	NEW ROCHELLE HOUSING
Spiller Address:	68 FIRST STREET
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	218016
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/07/03: Also see spill #02-10080. Dec 2003 - 1000 gallon UST removed along with 150 tons of impacted soil. Tank removal report submitted by American Envionmental Assessment Corp. NFA. TG"
Remarks:	"CALLER PULLED TANK AND FOUND CONTAMINATION. "

Material:

Site ID:	267616
Operable Unit ID:	861369
Operable Unit:	01
Material ID:	513520
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILL NUMBER 0210119 (Continued) **S105997830**

Tank Test:

BG337 **RENTAL HOUSE** **NY LTANKS** **S100153568**
NW **119 SICKLES AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.421 mi.
2221 ft. **Site 6 of 6 in cluster BG**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Site ID:	119461
Spill Number/Closed Date:	9107320 / 1991-11-25
Spill Date:	1991-10-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	HOULIHAN & LAWRENCE RLTY.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103766
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DISCOVERED SEEPAGE FROM TANK ON BASEMENT CONCRETE FLOOR APPLIED SPEEDI-DRY SPILLER WILL CONTACT LUZON OIL FOR CLEAN UP"

Material:

Site ID:	119461
Operable Unit ID:	961556
Operable Unit:	01
Material ID:	419532
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

RENTAL HOUSE (Continued) **S100153568**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BL338 **SPILL NUMBER 0104402** **NY LTANKS** **S105135031**
NE **30 LINCOLN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.426 mi.
2247 ft. **Site 1 of 2 in cluster BL**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Site ID:	328750
Spill Number/Closed Date:	0104402 / 2001-11-14
Spill Date:	2001-07-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-07-25
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-25
Spill Record Last Update:	2002-02-07
Spiller Name:	OWNER
Spiller Company:	AVALLONE
Spiller Address:	30 LINCOLN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	264577
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/14/2001 G.C. RELIABLE PULLED TANK. NO LEAK OR DISCHARGE EVIDENT. NO FURTHER ACTION."
Remarks:	"failed test"

Material:

Site ID:	328750
Operable Unit ID:	841036
Operable Unit:	01
Material ID:	532897

SPILL NUMBER 0104402 (Continued) **S105135031**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	328750
Spill Tank Test:	1526481
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

BJ339 **SPILL NUMBER 0210366** **NY LTANKS** **S105997907**
West **182 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.427 mi.
2253 ft. **Site 4 of 4 in cluster BJ**

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	282696
Spill Number/Closed Date:	0210366 / 2003-03-03
Spill Date:	2003-01-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-14
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001

SPILL NUMBER 0210366 (Continued) **S105997907**

Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229505
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Jan 2003 - 1000 gallon tank was removed from the property. 100 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environemtal Assessement. NFA. TG"
Remarks:	"SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL AT ABOVE LOCATION. PROPTERY IS OWNED BY THE CITY OF NEW ROCHELLE AND CALLER IS A CONTRACTOR FOR THE CITY. TANK APPEARS TO HAVE BEEN ABANDONED YEARDS AGO. "

Material:

Site ID:	282696
Operable Unit ID:	861605
Operable Unit:	01
Material ID:	513753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BM340 **PLASTIC WORKS** **NY LTANKS** **S103824027**
NNE **115 CEDAR ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.430 mi.
2268 ft. **Site 1 of 2 in cluster BM**

Relative:
Lower

Actual:
50 ft.

LTANKS:

Site ID:	163894
Spill Number/Closed Date:	9812998 / 1999-02-22
Spill Date:	1999-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

PLASTIC WORKS (Continued) **S103824027**

Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	1999-03-01
Spiller Name:	GARY STRUTTEN
Spiller Company:	PLASTIC WORKS
Spiller Address:	115 CEDAR ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	GARY STRUTTEN
Spiller Phone:	(914) 576-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	138224
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER'S COMPANY WAS PULLING A 550GAL UST - TANK WAS FULL OF HOLES"

Material:

Site ID:	163894
Operable Unit ID:	1073438
Operable Unit:	01
Material ID:	313271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH341 **SPILL NUMBER 0202241** **NY LTANKS S102674170**
SSE **208 CENTER AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2277 ft. **Site 3 of 4 in cluster BH**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	215702
Spill Number/Closed Date:	9314003 / 1994-03-11
Spill Date:	1994-02-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-03-11
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-28

SPILL NUMBER 0202241 (Continued) **S102674170**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-11
Spill Record Last Update:	1995-01-05
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller City,St,Zip:	BRONX, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK WAS OVERFILLED CASTLE CREW TO CLEAN UP"

Material:

Site ID:	215702
Operable Unit ID:	996014
Operable Unit:	01
Material ID:	389350
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	215703
Spill Number/Closed Date:	9315255 / 1994-04-11
Spill Date:	1994-03-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-04-11
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-26
CID:	Not reported
Water Affected:	Not reported

SPILL NUMBER 0202241 (Continued) **S102674170**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-11
Spill Record Last Update:	1995-01-04
Spiller Name:	Not reported
Spiller Company:	WRG
Spiller Address:	420 WESTCHESTER AVE.
Spiller City,St,Zip:	PORTCHESTER, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY GUAGE RESULTED IN OVERFILL WCHD NOTIFIED CASTLE OIL WILL CLEAN UP"

Material:

Site ID:	215703
Operable Unit ID:	997178
Operable Unit:	01
Material ID:	387016
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0202241
Facility Type:	ER
DER Facility ID:	177797
Site ID:	214599
DEC Region:	3
Spill Date:	2002-06-01
Spill Number/Closed Date:	0202241 / 2002-08-12
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-06-01
CID:	257

SPILL NUMBER 0202241 (Continued) **S102674170**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-01
Spill Record Last Update:	2002-09-26
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	208 CENTER AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	""
Remarks:	"bad gauge - contained - cleanup to be done by castleton enviromental"
	Not reported

Material:

Site ID:	214599
Operable Unit ID:	855230
Operable Unit:	01
Material ID:	520107
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BL342 **SPILL NUMBER 0300463** **NY LTANKS S105998684**
NE **52 LINCOLN ST** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.432 mi.
2279 ft. **Site 2 of 2 in cluster BL**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Site ID:	202585
Spill Number/Closed Date:	0300463 / 2003-04-14
Spill Date:	2003-04-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jghardy

SPILL NUMBER 0300463 (Continued) **S105998684**

Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-22
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller City,St,Zip:	ELMSFORD, NY 10523-
Spiller County:	001
Spiller Contact:	ED ALLAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	168519
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"Above material reported spilled at above location due to tank overfill. Crew is on site and cleanup is in progress at time of call. All material is expected to be recovered."

Material:

Site ID:	202585
Operable Unit ID:	868761
Operable Unit:	01
Material ID:	508540
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	0806544
Facility Type:	ER
DER Facility ID:	168519
Site ID:	403827
DEC Region:	3
Spill Date:	2008-09-10
Spill Number/Closed Date:	0806544 / 2008-12-26
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SPILL NUMBER 0300463 (Continued) **S105998684**

SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-09-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-11
Spill Record Last Update:	2008-12-26
Spiller Name:	LOUIS VACCARO
Spiller Company:	LOIS VACCARO
Spiller Address:	52 LINCOLN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	LOUIS VACCARO
Contact Phone:	(914) 235-8284
DEC Memo:	"11/16/08 New England Tank Services reported that they removed one 550 gallon tank along with 7.09 tons of petroleum contaminated soil. NFA TG"
Remarks:	"Callers company was removing a 550 gallon tank and found it had holes in it. Unknown how much fuel had been leaking or for how long. Clean up will start within the next few days."

Material:

Site ID:	403827
Operable Unit ID:	1160514
Operable Unit:	01
Material ID:	2151689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BM343 **I-95 EXIT 16** **NY LTANKS** **S102673537**
NNE **OPP. 111 CEDAR ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.436 mi.
2300 ft. **Site 2 of 2 in cluster BM**

Relative:
Lower

Actual:
62 ft.

LTANKS:

Site ID:	244221
Spill Number/Closed Date:	9001240 / 1990-08-01
Spill Date:	1990-05-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1990-08-01
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	MIGOYA CONST. CO. ?
Spiller Address:	3520 DELAVAL AVE.
Spiller City,St,Zip:	BRONX, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	200593
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : N.F.A. 09/27/95: This is additional information about material spilled from the translation of the old spill file: POSS. WASTE OIL."
Remarks:	"DIESEL SPILLED WHILE FILLING HEAVY CONSTRUCTION EQUIPMENT ALSO APPEARSTHAT THEY HAVE CHANGED THEIR CRANKCASE OIL BY DRAINING ONTO GROUND A USED OIL FILTER WAS FOUND THERE ALSO"

Material:

Site ID:	244221
Operable Unit ID:	941067
Operable Unit:	01
Material ID:	439592
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

I-95 EXIT 16 (Continued) **S102673537**

Oxygenate: Not reported

Tank Test:

BN344 **SPILL NUMBER 0009195** **NY LTANKS** **S104877181**
SSE **17 POPLAR PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.439 mi.
2316 ft. **Site 1 of 3 in cluster BN**

Relative:
Lower

Actual:
74 ft.

LTANKS:

Site ID:	63217
Spill Number/Closed Date:	0009195 / 2001-01-08
Spill Date:	2000-11-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-09
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-09
Spill Record Last Update:	2001-02-02
Spiller Name:	DESIGN BUILDERS GROUP
Spiller Company:	Not reported
Spiller Address:	17 POPLAR PL
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	DESIGN BUILDERS GROUP
Spiller Phone:	(914) 948-9785
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	61128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/17/2000 TANK TEST FAILURE LETTER SENT. TANK SCHEDULED FOR RETEST ON 11/20/00. 01/08/2001 ENVIROSTAR PULLED TANK. TANK WAS SOUND, NO RELEASE. EVIROSTAR REPORTS TANK FAILED DUE TO FAULTY OIL LINES. NO CONTAMINATION FOUND. NO FURTHER ACTION REQUIRED."
Remarks:	"uncover repair retest"

Material:

Site ID:	63217
Operable Unit ID:	831505
Operable Unit:	01
Material ID:	543152

SPILL NUMBER 0009195 (Continued) **S104877181**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BH345 **RESIDENCE** **NY LTANKS** **S106124419**
SSE **6 POPLAR ROAD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.440 mi.
2321 ft. **Site 4 of 4 in cluster BH**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	82997
Spill Number/Closed Date:	0310014 / 2012-08-13
Spill Date:	2003-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-11-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	RUDY TAYLOR
Spiller Phone:	(914) 833-0287
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76439
DEC Memo:	"7/29/10 Homeowner TTF JO'M 7/25/12: There is no such address as 6 Poplar Road in New Rochelle. This should either be 6 Poplar Road in Larchmont, or 6 Poplar Place in New Rochelle. jod 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"

RESIDENCE (Continued) **S106124419**

Remarks: ""

Material:
Site ID: 82997
Operable Unit ID: 875149
Operable Unit: 01
Material ID: 498967
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Pounds
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:
Site ID: 82997
Spill Tank Test: 1528823
Tank Number: 1
Tank Size: 500
Test Method: 03
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified: Not reported
Test Method: Horner EZ Check I or II

346
South
1/4-1/2
0.442 mi.
2334 ft.

LIPMAN RESIDENCE **NY LTANKS** **S106971579**
54 LIBERTY AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
48 ft.

LTANKS:
Site ID: 333699
Spill Number/Closed Date: 0409061 / 2005-04-02
Spill Date: 2004-11-16
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2004-11-16
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0

LIPMAN RESIDENCE (Continued) **S106971579**

Date Entered In Computer:	2004-11-16
Spill Record Last Update:	2005-04-02
Spiller Name:	JOSH LITSMAN
Spiller Company:	LISTMAN RESIDENCE
Spiller Address:	54 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELE, NY
Spiller County:	001
Spiller Contact:	JOSH LITSMAN
Spiller Phone:	(914) 813-5024
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268950
DEC Memo:	"02/18/04 ZURICH CLAIM BEING HANDLED BY LEWIS ENVIRONMENTAL. SMALL AMOUNT OF CONTAMINATION UNDER PUBLIC SIDEWALK/ROADWAY CANNOT BE REMOVED SAFELY. DEC SPOKE WITH LEWIS (BOB KRAUSE) ABOUT SAMPLING REQUIREMENTS. REPORT TO FOLLOW. jod 04/02/05 LEWIS ENVIRONMENTAL DISPOSED OF LUST AND 82.08 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SOILTEST CAME BACK OVER THE LIMIT:"

Material:

Tank Test:

BO347 **TELEDYNE HYDRA-POWER** **NY SWF/LF** **1000201735**
ENE **310 MAIN ST** **NY Spills** **NYD001650209**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.442 mi. **FINDS**
2335 ft. **Site 1 of 2 in cluster BO** **NY MANIFEST**
ECHO

Relative:
Lower

Actual:
21 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling
Activity Number:	[60J11]
Active:	No
East Coordinate:	603184
North Coordinate:	4529831
Accuracy Code:	Not reported
Regulatory Status:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

SPILLS:

Facility ID:	1408123
Facility Type:	ER
DER Facility ID:	456652
Site ID:	501675
DEC Region:	3
Spill Date:	2014-11-06
Spill Number/Closed Date:	1408123 / 2014-11-06
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	6010
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2014-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2014-11-06
Spiller Name:	MIKE TASHENT
Spiller Company:	M TECH MOTORS
Spiller Address:	310 MAIN ST REAR
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller Company:	999
Contact Name:	MIKE TASHENT
Contact Phone:	(914) 355-2500
DEC Memo:	"11/6/14- Spoke to caller. He was on site and noted where auto shop flushed some waste oil to roadside curb. Cleanup completed by spiller with speedidry. Caller states cleanup is complete. NFA DT"
Remarks:	"loss to sewer and roadway. C/u in progress"

Material:

Site ID:	501675
Operable Unit ID:	1251062
Operable Unit:	01
Material ID:	2252898
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	Gallons
Recovered:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

Facility ID: 0713299
Facility Type: ER
DER Facility ID: 344570
Site ID: 395027
DEC Region: 3
Spill Date: 2008-03-17
Spill Number/Closed Date: 0713299 / 2010-11-30
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: jkomara
Referred To: WCDOH - PBS
Reported to Dept: 2008-03-17
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-03-17
Spill Record Last Update: 2010-11-30
Spiller Name: MIMI
Spiller Company: CAR DEALER
Spiller Address: 310 MAIN STREET
Spiller City,St,Zip: NEW ROCHELLE, NY
Spiller Company: 001
Contact Name: MIMI
Contact Phone: (212) 962-4301
DEC Memo: "11/30/10 No Info 3 years old spills will nbot be following up NFA JO'M "
Remarks: "DURING SOIL BORINGS FOUND CONTAMINTAED SOIL"

Material:
Site ID: 395027
Operable Unit ID: 1151973
Operable Unit: 01
Material ID: 2142744
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Tank Test:

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	TELEDYNE HYDRA-POWER
Facility address:	310 MAIN ST NEW ROCHELLE, NY 108015716
EPA ID:	NYD001650209
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	(914) 632-2200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TELEDYNE HYDRA-POWER
Owner/operator address:	310 MAIN ST OPERCITY, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(914) 632-2200
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 08/18/1980
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 03/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004335808

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:
EPA ID: NYD001650209
Country: USA
Location Address 1: 310 MAIN ST
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: 5716

Mailing Info:
Name: TELEDYNE HYDRA POWER INC
Contact: RICHARD C. SNYDER
Address: 10-12 PINE COURT
City/State/Zip: NEW ROCHELLE, NY 10801
Country: USA

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Phone: 914-632-2200

Manifest:

Document ID: PAC6193121
Manifest Status: Completed copy
Trans1 State ID: PAAH0421
Trans2 State ID: Not reported
Generator Ship Date: 01/21/1993
Trans1 Recv Date: 01/21/1993
Trans2 Recv Date: 01/22/1993
TSD Site Recv Date: 01/22/1993
Part A Recv Date: 02/02/1993
Part B Recv Date: 02/04/1993
Generator EPA ID: NYD001650209
Trans1 EPA ID: CTD983883745
Trans2 EPA ID: Not reported
TSDF ID: PAD067098822
Waste Code: F001 - UNKNOWN
Quantity: 00300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1993

Document ID: NYA1235367
Manifest Status: Completed copy
Trans1 State ID: PLATE#
Trans2 State ID: Not reported
Generator Ship Date: 10/08/1984
Trans1 Recv Date: 10/08/1984
Trans2 Recv Date: / /
TSD Site Recv Date: 10/08/1984
Part A Recv Date: 10/16/1984
Part B Recv Date: 10/19/1984
Generator EPA ID: NYD001650209
Trans1 EPA ID: NYD000824334
Trans2 EPA ID: Not reported
TSDF ID: NYD000824334
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1984

Document ID: NJA1241335
Manifest Status: Completed copy
Trans1 State ID: NJDEPS581
Trans2 State ID: Not reported
Generator Ship Date: 10/24/1991

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Trans1 Recv Date:	10/24/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/24/1991
Part A Recv Date:	/ /
Part B Recv Date:	11/08/1991
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1991

Document ID:	NJA1053512
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	11/28/1990
Trans1 Recv Date:	11/28/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/28/1990
Part A Recv Date:	12/28/1990
Part B Recv Date:	01/07/1991
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0798146
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	05/01/1990
Trans1 Recv Date:	05/01/1990
Trans2 Recv Date:	/ /

TELEDYNE HYDRA-POWER (Continued) **1000201735**

TSD Site Recv Date:	05/02/1990
Part A Recv Date:	06/14/1990
Part B Recv Date:	06/20/1990
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0846650
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS581
Trans2 State ID:	Not reported
Generator Ship Date:	01/25/1990
Trans1 Recv Date:	01/25/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/26/1990
Part A Recv Date:	03/28/1990
Part B Recv Date:	03/30/1990
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1990

Document ID:	NJA0632991
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S58112066
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/1989
Trans1 Recv Date:	10/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/06/1989
Part A Recv Date:	10/12/1989

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Part B Recv Date: 11/14/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1989

Document ID: NJA0632447
Manifest Status: Completed copy
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 06/26/1989
Trans1 Recv Date: 06/26/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 06/27/1989
Part A Recv Date: 07/19/1989
Part B Recv Date: 07/07/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1989

Document ID: NJA0632704
Manifest Status: Completed copy
Trans1 State ID: S58112066
Trans2 State ID: Not reported
Generator Ship Date: 08/22/1989
Trans1 Recv Date: 08/22/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 08/23/1989
Part A Recv Date: 09/07/1989
Part B Recv Date: 09/05/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 1989

Document ID: CTC0168881
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: CTE43069
Trans2 State ID: Not reported
Generator Ship Date: 12/26/1990
Trans1 Recv Date: 12/26/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 12/26/1990
Part A Recv Date: 04/03/1991
Part B Recv Date: 01/23/1991
Generator EPA ID: NYD001650209
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: Not reported
TSDF ID: CTD021816889
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

Document ID: NJA0560838
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 02/01/1989
Trans1 Recv Date: 02/01/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 02/06/1989
Part A Recv Date: 03/15/1989
Part B Recv Date: 02/13/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Waste Code: X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Specific Gravity: 100
Year: 1989

Document ID: NJA0798464
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS581
Trans2 State ID: Not reported
Generator Ship Date: 06/22/1990
Trans1 Recv Date: 06/22/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 06/25/1990
Part A Recv Date: 08/07/1990
Part B Recv Date: 08/06/1990
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1990

Document ID: NJA0632201
Manifest Status: Completed copy
Trans1 State ID: S58112603
Trans2 State ID: Not reported
Generator Ship Date: 04/25/1989
Trans1 Recv Date: 04/25/1989
Trans2 Recv Date: / /
TSD Site Recv Date: 05/01/1989
Part A Recv Date: 05/10/1989
Part B Recv Date: 05/09/1989
Generator EPA ID: NYD001650209
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1989

Document ID:	NYA6456618
Manifest Status:	Completed copy
Trans1 State ID:	PLATE#
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/1988
Trans1 Recv Date:	03/30/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/30/1988
Part A Recv Date:	04/05/1988
Part B Recv Date:	04/12/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1988

Document ID:	NYA5744286
Manifest Status:	Completed copy
Trans1 State ID:	PLATE#
Trans2 State ID:	57745GB
Generator Ship Date:	04/14/1987
Trans1 Recv Date:	04/14/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/14/1987
Part A Recv Date:	04/22/1987
Part B Recv Date:	05/05/1987
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1987

Document ID:	NYA6402132
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	57745GB
Generator Ship Date:	12/30/1987
Trans1 Recv Date:	12/30/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1987
Part A Recv Date:	01/15/1988
Part B Recv Date:	01/12/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1987

Document ID:	CTA0042088
Manifest Status:	Completed copy
Trans1 State ID:	CT4163A
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/1987
Trans1 Recv Date:	03/31/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/31/1987
Part A Recv Date:	04/07/1987
Part B Recv Date:	04/14/1987
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	CTD980521280
Trans2 EPA ID:	Not reported
TSDF ID:	CTD021816889
Waste Code:	CR02 - AUTHORIZED WASTE OIL
Quantity:	00500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1987

Document ID:	NYA6458922
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Trans1 State ID:	PLATE#
Trans2 State ID:	IC1244
Generator Ship Date:	06/24/1988
Trans1 Recv Date:	06/24/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/24/1988
Part A Recv Date:	07/01/1988
Part B Recv Date:	07/19/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1988

Document ID:	NJA0533423
Manifest Status:	Completed copy
Trans1 State ID:	S58112603
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/1988
Trans1 Recv Date:	11/21/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/22/1988
Part A Recv Date:	11/25/1988
Part B Recv Date:	11/30/1988
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	X726 - MISC OIL/GAS PRODUCTS (NJ ONLY)
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Year: 1988

Document ID: NYA3825472
Manifest Status: Completed copy
Trans1 State ID: PLATE#
Trans2 State ID: 577-45GB
Generator Ship Date: 10/29/1986
Trans1 Recv Date: 10/29/1986
Trans2 Recv Date: / /
TSD Site Recv Date: 10/29/1986
Part A Recv Date: 11/07/1986
Part B Recv Date: 11/10/1986
Generator EPA ID: NYD001650209
Trans1 EPA ID: NYD000824334
Trans2 EPA ID: Not reported
TSDF ID: NYD000824334
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1986

ECHO:
Envid: 1000201735
Registry ID: 110004335808
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110004335808

348
NW
1/4-1/2
0.442 mi.
2336 ft.

WALTON RESIDENCE **NY LTANKS** **S108639866**
129 SICKLES AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
67 ft.

LTANKS:
Site ID: 383296
Spill Number/Closed Date: 0703375 / 2007-08-28
Spill Date: 2007-06-22
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2007-06-22
CID: 408
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 2007-06-28
Recommended Penalty: False
UST Involvement: False

WALTON RESIDENCE (Continued) **S108639866**

Remediation Phase:	0
Date Entered In Computer:	2007-06-22
Spill Record Last Update:	2007-08-28
Spiller Name:	MARGRET WALTON
Spiller Company:	PRIVATE HOME
Spiller Address:	129 SICKLES AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY 10801
Spiller County:	001
Spiller Contact:	MARGRET WALTON
Spiller Phone:	(914) 235-5241
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	332760
DEC Memo:	"6/29/07: Envirotrac is consultant for insurance company. Report to follow. jod 08/08/07 Northeast Environmental reported that the tank was excavated and removed along with 19.85 tons of impacted soil. NFA TG"
Remarks:	"soil contamination found during tank removal; NOT YET CONTAINED OR CLEANED;"

Material:

Site ID:	383296
Operable Unit ID:	1140659
Operable Unit:	01
Material ID:	2130748
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

349
East
1/4-1/2
0.444 mi.
2344 ft.

Relative:
Lower

Actual:
47 ft.

FIUMFREDO RESIDENCE **NY LTANKS** **S111012239**
12 BAYVIEW AVE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	447470
Spill Number/Closed Date:	1100096 / 2011-09-22
Spill Date:	2011-04-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported

FIUMFREDO RESIDENCE (Continued) **S111012239**

Reported to Dept:	2011-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2011-08-08
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-04
Spill Record Last Update:	2011-09-22
Spiller Name:	ROSE FIUMFREDO
Spiller Company:	ROSE FIUMFREDO
Spiller Address:	12 DAYVIEW AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	ROSE FIUMFREDO
Spiller Phone:	(914) 632-0496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402070
DEC Memo:	"4/4/11 - To retest tank. KAB 4/28/11 Morris called in for follow up. Tank failed again. He said tank top was exposed for most of length and one side and some samples taken. Morris said whoever did repairs, sounds like they only put a new vent riser on. Did not check piping, which is heavily crusted. jc 5-6-11 Failed 2nd retest today. Owner giving Kathy a hard time. Morris will retest again next week. Kathy said road name should be Bayview not Dayview, made change. jc 5/13/11 Tank failed for a 3rd time. Plan to pull, according to Tank Tech. dw 8-4-11 Homeowner called dispatch desk. He wants to remove the tank himself and do ALL of the work. He says he would cut open the tank and clean with speedi dri, dispose of tank at scrap yard, etc. I recommended that he hire an environmental consultant to AT LEAST oversee project because the DEC will need a TCR which would include soil samples, manifests, disposal receipts, etc. I told him that this spill will not be closed out until a proper and acceptable Tank Closure Report has been submitted to this office for review. I told him to contact J O'Dee in White Plains for further info. This guy seems bent on doing everything himself even though it was recommended that he hire a consultant to oversee the project. jm 8/4/11: Recieved call from Sandy Perratta 914-557-0142. He is the same individual who called the dispatch desk earlier today. He is not the property owner but a friend of the owner. States he is in the construction business and he can remove the tank himself. He states he has the OSHA 30-hour training and also states he knows that he doesn't need confined space entry training if the tank is less than 4 feet below ground . I again stated he should have a professional contractor do the work for safety reasons. jod 8/8/11: Received voice-mail message from Mr Perratta stating he had removed the tank and it was on the lawn awaiting a DEC drive-by inspection. I met New Rochelle Fire Captain Henry Senno on site. The tank was cut and cleaned and is on plastic. The excavation is open and is not fenced or secured. There is no evidence of any holes in the tank, and no evidence of any leak or contamination. Captain Senno states he will follow up with the owner, as no permits were filed for the removal as required in New Rochelle. DEC Spills requires no further action at this time. jod 9/8/11: I left this spill open after discussing the situation with Capt Senno on either August 9th or 10th. There was still a 55-gallon drum of

FIUMFREDO RESIDENCE (Continued) **S111012239**

heating oil and heating oil sludge that was removed from the tank remaining on the site. On either Aug 11th or 12th I spoke with Mr Perrotta and stated the spill would be left open until he submitted a disposal receipt to DEC for proper disposal of that waste drum. To date, Mr Perrotta has submitted a disposal recipt for the tank (entered in eDocs) but has not submitted a disposal receipt for the drum. jod 9/22/11: Letter from Linda Enes forwarded to DEC. She states she is in posesseion of the 55-gallon drum, and is using it to fuel a space heater. I called her this morning and she states her husband transported the drum in his pick-up truck from New Rochelle to their home in Dover Plains NY. Letter has been entered into eDocs. DEC requires no further action. jod"

Remarks: "repair/retest pending"

Material:

Site ID:	447470
Operable Unit ID:	1197626
Operable Unit:	01
Material ID:	2193927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

350 WSW 1/4-1/2 0.447 mi. 2360 ft. **CONTAMINATRED SOIL** **NY LTANKS** **S104276929**
23 FIRST ST **N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 57 ft.

LTANKS:

Site ID:	102476
Spill Number/Closed Date:	9702187 / 1999-06-10
Spill Date:	1997-05-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-20
CID:	369
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False

CONTAMINATRED SOIL (Continued) **S104276929**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-20
Spill Record Last Update:	1999-06-11
Spiller Name:	Not reported
Spiller Company:	MR WILLIAMS
Spiller Address:	23 FIRST ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	BRIAN SCHUG
Spiller Phone:	(914) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90745
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING SITE EVALUATION-CALLER WILL REMOVE SOIL-CLEANUP IN PROGRESS"

Material:

Site ID:	102476
Operable Unit ID:	1048062
Operable Unit:	01
Material ID:	335128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

---

351 **RESIDENCE** **NY LTANKS** **S102660166**
SW **38 BEECHWOOD AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.448 mi.
2367 ft.

Relative:
Lower

Actual:
37 ft.

LTANKS:

Site ID:	105369
Spill Number/Closed Date:	9705244 / 1997-11-10
Spill Date:	1997-07-31
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-31

RESIDENCE (Continued) **S102660166**

CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-31
Spill Record Last Update:	1998-02-05
Spiller Name:	MARVIN KAPUS
Spiller Company:	Not reported
Spiller Address:	38 BEECHWOOD AVE
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	MARVIN KAPUS
Spiller Phone:	(914) 738-1351
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92963
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/31/97 CONTAMINATED SOIL BEING REMOVED & STOCKPILED; 08/01/97 TANK FOUND DURING DEMOLITION OF HOUSE; TANK AND CONTAMINATION REMOVED; "
Remarks:	"demolition of building - ust 550 gal tank - tank had holes in it contaminated soil found "

Material:

Site ID:	105369
Operable Unit ID:	1048510
Operable Unit:	01
Material ID:	334464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BO352 **DEFENDER MARINE SUPPLY** **NY LTANKS** **S103479285**
ENE **309 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.448 mi.
2367 ft. **Site 2 of 2 in cluster BO**

Relative:
Lower

Actual:
25 ft.

LTANKS:

Site ID:	93459
Spill Number/Closed Date:	9806235 / 2002-09-19
Spill Date:	1998-08-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

DEFENDER MARINE SUPPLY (Continued) **S103479285**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-08-19
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-19
Spill Record Last Update:	2002-09-19
Spiller Name:	WILLIAM GOING
Spiller Company:	DEFENDER MARINE SUPPLY
Spiller Address:	309 MAIN ST
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	WILLIAM GOING
Spiller Phone:	(914) 744-3705
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83786
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/19/98 WCHD NOTIFIED. 09/14/02 - 8 TO 10 YARDS OF SOIL STOCKPILED. CLOSURE REPORT TO FOLLOW ONCE SAMPLE RESULTS RECEIVED. 09/19/02 CLOSURE REPORT RECEIVED FROM WILLIAM GOING. DISPOSAL OF TANK AND 10.45 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"during a tank removal caller found contamined soil"

Material:

Site ID:	93459
Operable Unit ID:	1067422
Operable Unit:	01
Material ID:	317407
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BN353 **FUNICELOLO HOME** **NY LTANKS** **S107489124**
SSE **24 POPLAR PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.450 mi.
2375 ft. **Site 2 of 3 in cluster BN**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Site ID:	355533
Spill Number/Closed Date:	0509719 / 2006-11-19
Spill Date:	2005-11-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-11-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-14
Spill Record Last Update:	2006-11-19
Spiller Name:	FUNICEOLO HOME
Spiller Company:	FUNICELOLO HOME
Spiller Address:	24 POPULAR PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FUNICEOLO HOME
Spiller Phone:	(914) 636-5043
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305561
DEC Memo:	"PLAN WAS TO ABANDON BUT FOUND HOLES SO NOWTHEY WILL REMOVE NO KNOWN EXPERTS AT THIS TIME November 19, 2006: ONE HOLE FOUND ON TOP OF TANK. TANK CANNOT BE REMOVED DUE TO SAFETY AND STRUCTURAL CONSIDERATIONS. MUNICIPAL WATER AND SEWER. ROYAL ENVIRONMENTAL TOOK A GROUND WATER SAMPLE BENATH TANK, ALL ANALYTES NON-DETECT. TANK ABANDONED IN PLACE WITH SLURRY. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES FOUND IN A 1000 GALLON TANK;"

Material:

Site ID:	355533
Operable Unit ID:	1112888
Operable Unit:	01
Material ID:	2102930
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

FUNICELOLO HOME (Continued) **S107489124**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BN354 **LABELLA RESIDENCE** **NY LTANKS** **S107789449**
SSE **219 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.454 mi.
2397 ft. **Site 3 of 3 in cluster BN**

Relative:
Lower

Actual:
72 ft.

LTANKS:

Site ID:	364328
Spill Number/Closed Date:	0601959 / 2009-09-01
Spill Date:	2006-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2009-09-01
Spiller Name:	LARRY LABELLA
Spiller Company:	LABELLA RESIDENCE
Spiller Address:	219 CENTRAL AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	LARRY LABELLA
Spiller Phone:	(914) 654-0719
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	314554
DEC Memo:	"05/24/06: Soil samples clean. US Tank Tech will be repairing and retesting. 9/1/09: Tank passed a retest in isolation on 6-13-06. At that time, new fuel lines had been run from the tank to the boiler room but were not hooked up at the time of the test. A full system test was performed 7-24-09 with the lines connected. The tank system passed this retest. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"UNCOVER REPAIR AND RETEST."

LABELLA RESIDENCE (Continued) **S107789449**

Material:

Site ID:	364328
Operable Unit ID:	1122357
Operable Unit:	01
Material ID:	2111830
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	364328
Spill Tank Test:	1550008
Tank Number:	1
Tank Size:	1000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

355 **SPILL NUMBER 0210080** **NY LTANKS** **S105997807**
West **196 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2423 ft.

Relative:
Lower

Actual:
71 ft.

LTANKS:

Site ID:	155360
Spill Number/Closed Date:	0210080 / 2003-03-03
Spill Date:	2003-01-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-06
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-06
Spill Record Last Update:	2003-03-04

SPILL NUMBER 0210080 (Continued) **S105997807**

Spiller Name:	Not reported
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131601
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Dec. 2002 - One 1200 gallon tank was removed from the property. 300 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environmetnal Assessment. NFA. TG"
Remarks:	"1200 GAL UNDERGROUND STORAGE TANK - 4 OTHER SPILL #'S ON THIS SAME SITE - DELORES FROM DEC SAYS THEY NEED ANOTHER NEW SPILL #"

Material:

Site ID:	155360
Operable Unit ID:	861323
Operable Unit:	01
Material ID:	513483
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BP356 **RESIDENCE** **NY LTANKS** **S105230245**
South **98 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2426 ft. **Site 1 of 4 in cluster BP**

Relative:
Lower

Actual:
46 ft.

LTANKS:

Site ID:	204562
Spill Number/Closed Date:	0107187 / 2002-01-11
Spill Date:	2001-10-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-10-11
CID:	252

RESIDENCE (Continued) **S105230245**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-11
Spill Record Last Update:	2002-03-22
Spiller Name:	REALTOR
Spiller Company:	MR GAMIANO
Spiller Address:	98 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	CAROL MASCOLINO-REALTOR
Spiller Phone:	(914) 576-1112
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170048
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/11/2002 ADVANCED PULLED TANK AND 99.6 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"PETROLEUM ODOR AND STAINING IN THE SOIL-RECOMMEND TANK REMOVAL"

Material:

Site ID:	204562
Operable Unit ID:	844253
Operable Unit:	01
Material ID:	532018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	204562
Spill Tank Test:	1526660
Tank Number:	Not reported
Tank Size:	1000
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

357
WNW
1/4-1/2
0.463 mi.
2443 ft.

MANONE PLACE
15 COLONIAL PLACE
NEW ROCHELLE, NY

NY LTANKS **S107523607**
N/A

Relative:
Higher

Actual:
84 ft.

LTANKS:

Site ID:	359413
Spill Number/Closed Date:	0513004 / 2006-05-08
Spill Date:	2006-02-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-09
Spill Record Last Update:	2006-05-08
Spiller Name:	FLORENCE MANONE
Spiller Company:	MANONE PLACE
Spiller Address:	15 COLONIAL PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FLORENCE MANONE
Spiller Phone:	(914) 633-7791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309466
DEC Memo:	"John O'Dee is lead and will/has contacted. May 8, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND FIVE DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 GALLON TANK, HOLES AND CONTAMINATION, WOULD LIKE A CALL BACK PERTAINING TO THIS PROPERTY"

Material:

Site ID:	359413
Operable Unit ID:	1116622
Operable Unit:	01
Material ID:	2107064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

MANONE PLACE (Continued) **S107523607**

Oxygenate: Not reported

Tank Test:

358
SSE
1/4-1/2
0.466 mi.
2463 ft.

TRINITY ARMS APARTMENTS **NY LTANKS** **S109416298**
25 TRINITY PLACE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
70 ft.

LTANKS:

Site ID:	409448
Spill Number/Closed Date:	0811859 / 2009-04-22
Spill Date:	2009-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-30
Spill Record Last Update:	2009-04-22
Spiller Name:	WILLY SILSDORF
Spiller Company:	TRINITY ARMS LTD
Spiller Address:	25 TRINITY PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	LARRY BOYD
Spiller Phone:	(914) 682-5676
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Spoke to W. Silsdorf. Think it may be leak in piping or fitting. Will probably Uncover, repair and retest. dvw 04/21/09 Wayne Schnieder reported ttf 1/3/09. passing retest after line replacement. No contamination. NFA TG "
Remarks:	"Caller states he performed a EZ-3 test and had a failure. Caller does not believe a spill or resources are affected."

Material:

Site ID:	409448
Operable Unit ID:	1165955
Operable Unit:	01
Material ID:	2157389
Material Code:	0001A

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	283512
Spill Number/Closed Date:	8905211 / 1992-07-30
Spill Date:	1989-08-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1992-07-30
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ANN JASLOCKI
Spiller Address:	REAL ESTATE
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"4K PETRO TITE, -.234 GPH"

Material:

Site ID:	283512
Operable Unit ID:	932936
Operable Unit:	01
Material ID:	445651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	283512
Spill Tank Test:	1535913
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Unknown

BQ359 **SPILL NUMBER 9814027** **NY LTANKS** **S104619985**
NW **48 REMINGTON PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.471 mi.
2488 ft. **Site 1 of 2 in cluster BQ**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Site ID:	80830
Spill Number/Closed Date:	9814027 / 1999-02-19
Spill Date:	1999-02-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-19
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-19
Spill Record Last Update:	1999-03-01
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AV
Spiller City,St,Zip:	BRONX, NY 10454-
Spiller County:	001
Spiller Contact:	MAMMY JONES
Spiller Phone:	(914) 636-5128
Spiller Extention:	Not reported

SPILL NUMBER 9814027 (Continued) **S104619985**

DEC Region: 3
DER Facility ID: 74863
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks: "STORAGE TANK OVERFILL - TANK IS OUTSIDE UNDERGROUND - CONTAMINATED SOIL WAS REMOVED & REPLACED WITH FRESH SOIL"

Material:
Site ID: 80830
Operable Unit ID: 1071478
Operable Unit: 01
Material ID: 310733
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: Gallons
Recovered: 3.00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

360
ENE
1/4-1/2
0.472 mi.
2490 ft.

RITACCO HOME **NY LTANKS** **S107789088**
24 JACKSON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
24 ft.

LTANKS:
Site ID: 362141
Spill Number/Closed Date: 0600187 / 2006-07-28
Spill Date: 2006-04-06
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-04-06
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-04-06
Spill Record Last Update: 2006-07-28
Spiller Name: RITACCO HOME
Spiller Company: RITACCO HOME
Spiller Address: 24 JACKSON STREET

RITACCO HOME (Continued) **S107789088**

Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	RITACCO HOME
Spiller Phone:	(914) 576-1430
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	312378
DEC Memo:	"04/10/06: Northeast to continue remediation. No GW involved as of now. July 28, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.00 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES IN A 550 GALLON AND CONTAMINATED SOIL;"

Material:

Site ID:	362141
Operable Unit ID:	1120244
Operable Unit:	01
Material ID:	2109739
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

361
SSW
1/4-1/2
0.474 mi.
2502 ft.

COMMERICAL BUILIDING **NY LTANKS** **S106472134**
719 MAIN ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
59 ft.

LTANKS:

Site ID:	301693
Spill Number/Closed Date:	0404182 / 2004-10-28
Spill Date:	2004-07-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-07-19
CID:	405
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False

COMMERICAL BUILIDING (Continued) **S106472134**

Remediation Phase:	0
Date Entered In Computer:	2004-07-19
Spill Record Last Update:	2004-10-28
Spiller Name:	JOHN DEURANTE
Spiller Company:	COMMERICAL BUILIDING
Spiller Address:	719 MAIN ST.
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	JOHN DEURANTE
Spiller Phone:	(914) 632-4222
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	243806
DEC Memo:	"10/28/04 TANK PASSED RETEST AFTER PIPING WAS REPLACED. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"RECOMMEND, UNCOVER, REPAIR, RETEST"

Material:

Tank Test:

Site ID:	301693
Spill Tank Test:	1529456
Tank Number:	1
Tank Size:	1080
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

362
East
1/4-1/2
0.474 mi.
2505 ft.

CONSOLIDATED EDISON-ECHO AVE. SITE
ECHO AVE
NEW ROCHELLE, NY 10801

SEMS-ARCHIVE **1000111631**
RCRA-CESQG **NYD981141252**
NY Spills
NY MANIFEST

Relative:
Lower

Actual:
17 ft.

SEMS-ARCHIVE:

Site ID:	202659
EPA ID:	NYD981141252
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0202659
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Alias Name(s):

Alias Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
Alias Address:	Not reported WESTCHESTER, NY

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

CERCLIS-NFRAP Assessment History:

Action:	DISCOVERY
Date Started:	/ /
Date Completed:	04/19/88
Priority Level:	Not reported

Action:	ARCHIVE SITE
Date Started:	/ /
Date Completed:	09/30/92
Priority Level:	Not reported

Action:	PRELIMINARY ASSESSMENT
Date Started:	/ /
Date Completed:	09/30/92
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	CON EDISON - ECHO AVENUE SUBSTATION
Facility address:	ECHO AVENUE NEW ROCHELLE, NY 10801
EPA ID:	NYD981141252
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1951

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1951
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 01/01/2001
Site name: ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Small Quantity Generator

Date form received by agency: 03/29/1996
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 11/19/1985
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Large Quantity Generator

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

SPILLS:
Facility ID: 9711031
Facility Type: ER
DER Facility ID: 101608
Site ID: 116789
DEC Region: 3
Spill Date: 1998-01-01
Spill Number/Closed Date: 9711031 / 1998-01-06
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-01-01
CID: 204
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-01
Spill Record Last Update: 1998-01-29
Spiller Name: STEVE ROMERO
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: STEVE ROMERO
Contact Phone: (212) 580-6763
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/01/98 OIL/WATER SEPARATOR OVERFLOWED; SUSPECTS OUTLET PIPE BECAME CLOGGED OR FROZEN CAUSING OVERFLOW; 01/02/98 3,300 GAL CONTAINED IN DIKED AREA; 100 GAL OVERFLOWED DIKE ONTO SOIL AND INTO DRAIN; 01/06/98 SPILL CLEANED UP BY CON ED; H2O HAS LESS THAN 1 PPM PCB "
Remarks: "OIL / WATER SEPARATOR MALFUNCTIONED 3300 IN CONTAINMENT AREA"

Material:
Site ID: 116789
Operable Unit ID: 1053908
Operable Unit: 01
Material ID: 329298
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 3400.00
Units: Gallons

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

NY MANIFEST:
EPA ID: NYD981141252
Country: USA
Location Address 1: ECHO AVE
Location Address 2: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip Code: 10801
Location Zip Code 4: Not reported

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Manifest:

Document ID: NYB9791883
Manifest Status: Not reported
Trans1 State ID: AE50394PA
Trans2 State ID: Not reported
Generator Ship Date: 01/20/2003
Trans1 Recv Date: 01/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: B004 - PCB ARTICLES WITH 50 PPM BUT < 500 PPM
Quantity: 08210
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2003

Document ID: NYA5717304
Manifest Status: Completed copy
Trans1 State ID: JA-113
Trans2 State ID: 558-TSM
Generator Ship Date: 01/28/1988

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans1 Recv Date:	01/28/1988
Trans2 Recv Date:	02/04/1988
TSD Site Recv Date:	02/05/1988
Part A Recv Date:	02/08/1988
Part B Recv Date:	02/11/1988
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	NJD054126164
TSDF ID:	NYD049836679
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	21460
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	125
Year:	1988

Document ID:	NYG1699497
Manifest Status:	Not reported
Trans1 State ID:	XF31635PA
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2000
Trans1 Recv Date:	01/18/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/20/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	10100
Units:	P - Pounds
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB9245052
Manifest Status:	Not reported
Trans1 State ID:	AD06661PA
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2000
Trans1 Recv Date:	01/27/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00499
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851671
Manifest Status:	Not reported
Trans1 State ID:	XH47240PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2000
Trans1 Recv Date:	03/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	45320
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851689
Manifest Status:	Not reported
Trans1 State ID:	TZ47345PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2000
Trans1 Recv Date:	03/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	50440
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Document ID: NYB8851698
Manifest Status: Not reported
Trans1 State ID: XB51788PA
Trans2 State ID: Not reported
Generator Ship Date: 03/14/2000
Trans1 Recv Date: 03/14/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/15/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 44140
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851707
Manifest Status: Not reported
Trans1 State ID: XG32072PA
Trans2 State ID: Not reported
Generator Ship Date: 03/14/2000
Trans1 Recv Date: 03/14/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/15/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 44160
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851716
Manifest Status: Not reported
Trans1 State ID: TV30802PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46640
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851725
Manifest Status: Not reported
Trans1 State ID: TY15443PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 57300
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851734
Manifest Status: Not reported
Trans1 State ID: XE53087PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50640
Units: P - Pounds
Number of Containers: 001

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851752
Manifest Status: Not reported
Trans1 State ID: XB51788PA
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49720
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851761
Manifest Status: Not reported
Trans1 State ID: XH447244P
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 46700
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851779
Manifest Status: Not reported
Trans1 State ID: XA49178PA

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	47240
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851788
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	48460
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYB8851797
Manifest Status:	Not reported
Trans1 State ID:	XG70657PA
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2000
Trans1 Recv Date:	03/09/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 59640
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851806
Manifest Status: Not reported
Trans1 State ID: TS31639PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 52920
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851815
Manifest Status: Not reported
Trans1 State ID: XC58821PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD196714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 51220
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

CONSOLIDATED EDISON-ECHO AVE. SITE (Continued) **1000111631**

Year: 2000

Document ID: NYB8851824
Manifest Status: Not reported
Trans1 State ID: XD54730PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 62880
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYB8851833
Manifest Status: Not reported
Trans1 State ID: XG70656PA
Trans2 State ID: Not reported
Generator Ship Date: 03/09/2000
Trans1 Recv Date: 03/09/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981141252
Trans1 EPA ID: PAD146714878
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49100
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

BP363
South
1/4-1/2
0.482 mi.
2547 ft.

SPILL NUMBER 9803423
106 LIBERTY AV
NEW ROCHELLE, NY

Site 2 of 4 in cluster BP

NY LTANKS **S104619561**
N/A

Relative:
Lower

Actual:
45 ft.

LTANKS:

Site ID:	140786
Spill Number/Closed Date:	9803423 / 1998-08-18
Spill Date:	1998-06-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-17
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-17
Spill Record Last Update:	1998-10-02
Spiller Name:	MARGURITE FINCH
Spiller Company:	Not reported
Spiller Address:	106 LIBERTY AV
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	MARGURITE FINCH
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	120231
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PULLED THE TANK TODAY & FOUND IT TO BE LEAKING - CONTAMINATED SOIL IS BEING DUG UP & STOCK PILED"

Material:

Site ID:	140786
Operable Unit ID:	1064251
Operable Unit:	01
Material ID:	566529
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILL NUMBER 9803423 (Continued) **S104619561**

Tank Test:

364
NE
1/4-1/2
0.484 mi.
2558 ft.

TTF AT RESIDENCE
68 JACKSON ST
NEW ROCHELLE, NY

NY LTANKS **S108957764**
N/A

Relative:
Lower

Actual:
25 ft.

LTANKS:

Site ID:	388761
Spill Number/Closed Date:	0707955 / 2008-03-26
Spill Date:	2007-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-10-20
CID:	79
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-22
Spill Record Last Update:	2008-03-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller County:	001
Spiller Contact:	MR JOHNSON
Spiller Phone:	(914) 235-1496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	338305
DEC Memo:	"March 26, 2008: ENVIROSTAR REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"TEST FAILED DUE TO BUBBLING. HORNER EASY 3 TEST,"

Material:

Site ID:	388761
Operable Unit ID:	1145917
Operable Unit:	01
Material ID:	2136260
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

TTF AT RESIDENCE (Continued) **S108957764**

Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

BP365 **COLLEGE OF NEW ROCHELLE** **NY LTANKS** **S104619776**
South **103 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.486 mi.
2565 ft. **Site 3 of 4 in cluster BP**

Relative:
Lower

Actual:
44 ft.

LTANKS:

Site ID:	118985
Spill Number/Closed Date:	9809357 / 2005-04-17
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODee
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-10-26
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	2005-04-17
Spiller Name:	UNKNOWN
Spiller Company:	COLLEGE OF NEW ROCHELLE
Spiller Address:	103 LIBERTY AVE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	COLLEGE OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103367
DEC Memo:	"02/23/99 Letter sent to tank owner requesting information 04/17/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF RESULTS. NO CALL BACK REQUESTED AT TIME OF CALL."

Material:

Site ID:	118985

COLLEGE OF NEW ROCHELLE (Continued) **S104619776**

Operable Unit ID:	1066630
Operable Unit:	01
Material ID:	316813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	118985
Spill Tank Test:	1546454
Tank Number:	1
Tank Size:	1080
Test Method:	03
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

366
SE
1/4-1/2
0.486 mi.
2567 ft.

Relative:
Lower

Actual:
40 ft.

CIUSSETELLI RESIDENCE **NY LTANKS** **S105996325**
4 FAIRVIEW PLACE **N/A**
NEW ROCHELLE, NY

LTANKS:

Site ID:	161898
Spill Number/Closed Date:	0204230 / 2010-07-13
Spill Date:	2002-07-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-07-23
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2010-07-13
Spiller Name:	Not reported

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	RON CIUSSETELLI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136674
DEC Memo:	"7/13/10: Report of a residential tank test failure. No indication of contamination noted on initial report. Report indicates all exterior piping loose, multiple vents and fills. Probable air leak. No further information received. jod"
Remarks:	"all exterior piping loose...multiple vents and fille..and questions contact caller."

Material:

Site ID:	161898
Operable Unit ID:	857023
Operable Unit:	01
Material ID:	518487
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	161898
Spill Tank Test:	1527307
Tank Number:	1
Tank Size:	550
Test Method:	03
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	Not reported
Test Method:	Horner EZ Check I or II

---

367 **NELSTAD MATERIAL CORP** **NY LTANKS** **S102154943**
ENE **40 HUNTINGTON PL** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY SPDES**
0.487 mi.
2573 ft.

Relative:
Lower

Actual:
13 ft.

LTANKS:

Site ID:	200280
Spill Number/Closed Date:	0208898 / 2004-05-03
Spill Date:	2002-11-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response.

NELSTAD MATERIAL CORP (Continued) **S102154943**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-27
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-11-27
Spill Record Last Update:	2004-05-19
Spiller Name:	JOHN CAPOSELLA
Spiller Company:	NELSTAD CONCRETE
Spiller Address:	40 HUNTINGTON PL
Spiller City,St,Zip:	NEW ROCHELLE, ZZ
Spiller County:	001
Spiller Contact:	JOHN CAPOSELLA
Spiller Phone:	(914) 636-8090
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	166657
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MANCINI 5/11/04: Letter to Nelstadt Materials Corp from Joe Mancini, WCDOH dated 3May2004. Closure report by Ira D Conklin has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"1000 UST LEAKING - CALLER DOING ABANDONMENT ON TANK AND DISCOVERED WATER IN IT"

Material:

Site ID:	200280
Operable Unit ID:	862078
Operable Unit:	01
Material ID:	515890
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPILLS:

Facility ID:	9400648
Facility Type:	ER
DER Facility ID:	126495
Site ID:	148664

NELSTAD MATERIAL CORP (Continued) **S102154943**

DEC Region:	3
Spill Date:	1994-04-14
Spill Number/Closed Date:	9400648 / 1994-04-20
Spill Cause:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-14
CID:	Not reported
Water Affected:	L.I. SOUND
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-20
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE LEAKING OIL INTO SOUND COAST GUARD WILL RESPOND PO NOWACK STORM DRAIN OUTFALL SHEEN PRESENTED BUT NOT RECOVERABLE RECURRING PROBLEM"

Material:

Site ID:	148664
Operable Unit ID:	994366
Operable Unit:	01
Material ID:	558757
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

SPDES:

Permit Number:	NYR00D345
State-Region:	03

NELSTAD MATERIAL CORP (Continued) **S102154943**

Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	3273
State Water Body Name:	ECHO BAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.912861 / -73.772611
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP
Non-Gov Permit Street Address:	NELSTAD MATERIAL CORP
Non-Gov Permit Supplemental Location:	40 HUNTINGTON PL
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Permit Street Address:	40 HUNTINGTON PL
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported

BP368 **BLANCO RESIDENCE** **NY LTANKS** **S103238839**
South **30 LINDEN PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.488 mi.
2575 ft. **Site 4 of 4 in cluster BP**

Relative:
Lower

Actual:
50 ft.

LTANKS:

Site ID:	227988
Spill Number/Closed Date:	9802704 / 1998-07-30
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-01
Spill Record Last Update:	1998-08-04
Spiller Name:	FRANK BLANCO
Spiller Company:	BLANCO RESIDENCE
Spiller Address:	30 LINDEN PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	001
Spiller Contact:	FRANK BLANCO
Spiller Phone:	(914) 633-7605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 LETTER REC'D FROM NES,INC. INDICATING TANK AND APPROX. 21.86 TONS CONTAMINATED SOIL WAS REMOVED. NFA."
Remarks:	"CALLERS AGENCY CALLED FOR NO HOT WATER - SERVICE MAN FOUND TANK EMPTY - POSSIBLY A TANK LEAK OR LINE FAILURE"

BLANCO RESIDENCE (Continued) **S103238839**

Material:
Site ID: 227988
Operable Unit ID: 1063369
Operable Unit: 01
Material ID: 321024
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Gallons
Recovered: .00
Resource Affected: Not reported
Oxygenate: Not reported

Tank Test:

---

369 SW 1/4-1/2 0.489 mi. 2583 ft. **NEW ROCHELLE LEAF TS** **NY SWF/LF** **S103592520**
85 BEECHWOOD AVE **N/A**
NEW ROCHELLE, NY 10801

Relative: Lower

Actual: 57 ft.

SWF/LF:
Flag: ACTIVE
Region Code: 3
Phone Number: 9146542129
Owner Name: Westchester County
Owner Type: Municipal
Owner Address: 270 North Avenue
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Email: Not reported
Owner Phone: 9146373031
Contact Name: Alexander Tergis
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: atergis@newrochelleny.com
Contact Phone: 9146542136
Activity Desc: Transfer station - registration
Activity Number: [60R19]
Active: Yes
East Coordinate: 603779
North Coordinate: 4529858
Accuracy Code: Not reported
Regulatory Status: Registration
Waste Type: Yard Waste;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #: 60R19
Authorization Date: Not reported
Expiration Date: Not reported

370
NNE
1/4-1/2
0.490 mi.
2587 ft.

7-UP BOTTLING CO
PALMER AVE & CEDAR ST
NEW ROCHELLE, NY

NY LTANKS **S100560336**
N/A

Relative:
Lower

Actual:
28 ft.

LTANKS:

Site ID:	60684
Spill Number/Closed Date:	9302874 / 1999-08-02
Spill Date:	1993-06-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	1994-12-08
Cleanup Meets Standard:	True
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1993-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-08
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59196
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/08/94: CONTRACTOR WAS FENLEY AND NICOL. TANK PULLED AND CONTA. SOIL REMOVEDFROM PIT. TANK REMOVAL REPORT WAS REQUESTED BUT NOT RECIEVED. 08/02/99: FINAL CLOSURE REPORT RECEIVED FROM GIBSON, DUNN & CRUTCHER ON 7/27/99; SENT TO TARRYTOWN OFFICE. "
Remarks:	"TANK PULL DEC (TODD) IS AWARE OF AND HANDLING SPILL"

Material:

Site ID:	60684
Operable Unit ID:	981198
Operable Unit:	01
Material ID:	399984
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported

7-UP BOTTLING CO (Continued) **S100560336**

Oxygenate: Not reported

Tank Test:

371
SE
1/4-1/2
0.490 mi.
2588 ft.

NORTH EVARTS **NY LTANKS** **S104620864**
44 NORTH EVARTS AVE **N/A**
ELSMFORD, NY

Relative:
Lower

Actual:
40 ft.

LTANKS:

Site ID:	74554
Spill Number/Closed Date:	9913333 / 2005-02-26
Spill Date:	2000-02-24
Spill Cause:	Tank Failure
Spill Source:	Vessel
Spill Class:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6000
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2005-02-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	44 NORTH EVARTS AVE
Spiller City,St,Zip:	ELSMFORD, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	69944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 2/26/05 surface spill from bilge tank on boat--j omara handled-close "
Remarks:	"bilge tank on boat ruptured - spill to soil and some contained in a catch basin - ny boat reg ny4947ju - fire dept and haz mat on scene- " Not reported

Material:

Site ID:	74554
Operable Unit ID:	1087874
Operable Unit:	01
Material ID:	295189
Material Code:	0009
Material Name:	gasoline

NORTH EVARTS (Continued) **S104620864**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	Gallons
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

BQ372 **HERNANDEZ - TTF** **NY LTANKS** **S117853761**
NW **70 REMINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.490 mi.
2588 ft. **Site 2 of 2 in cluster BQ**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	505764
Spill Number/Closed Date:	1411959 / 2015-06-16
Spill Date:	2015-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-23
Spill Record Last Update:	2015-06-17
Spiller Name:	DAISE Hernandez
Spiller Company:	Hernandez
Spiller Address:	70 REMINGTON PLACE
Spiller City,St,Zip:	NEW ROCHELLE, NY
Spiller County:	999
Spiller Contact:	DAISE FENANDEZ
Spiller Phone:	(914) 563-3381
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	460572
DEC Memo:	"3-23-15: V.Mc call to Ms.Fenandez: Parents house, will speak w/Mom and try to find out age of house/UST and callbk w/update. Noted: gen. life time of UST 20 to 25 years, re-test Vs. remove. 6/16/15: UST removed by Envirostar. No evidence of leak or contamination was found. Tank Closure report entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
	Not reported

HERNANDEZ - TTF (Continued) **S117853761**

Remarks: "caller reporting a failed tank test, tank is a 550 gallon tank. repair and retest tank"

Material:

Site ID:	505764
Operable Unit ID:	1255071
Operable Unit:	01
Material ID:	2257761
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Count: 7 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NEW ROCHELLE	1007740476	NEW ROCHELLE CREEK CABLES	ADJACENT TO GLEN ISLAND BRIDGE	10804	FINDS, ECHO
NEW ROCHELLE	S108467789	SIDEWALK / IN FRONT OF NE	HARRISON STREET		NY LTANKS
NEW ROCHELLE	S100153602	N.SHORE LONG ISLAND SOUND	NEW ROCHELLE TO DANBURY		NY LTANKS
NEW ROCHELLE	S110248231	VALU CLEAN CLEANERS	1335 A NORTH AVE.	10804	NY DRYCLEANERS
NEW ROCHELLE	S105684699	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY VCP
NEW ROCHELLE	S113916612	MEARL CORP.	PALMER AVE	10801	NY SHWS
NEW ROCHELLE	S117975694	MM 5.4 LEFT LANE	I-95 SOUTHBOUND		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 04/18/2016
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/13/2015
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 135

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/05/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 13

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/16/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/29/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/29/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 03/30/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 51

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 08/01/2015
Date Data Arrived at EDR: 11/19/2015
Date Made Active in Reports: 12/10/2015
Number of Days to Update: 21

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/04/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 52

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/08/2015
Date Data Arrived at EDR: 01/08/2015
Date Made Active in Reports: 02/09/2015
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/13/2015
Date Data Arrived at EDR: 10/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 118

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/28/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 08/20/2015
Date Data Arrived at EDR: 10/30/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 111

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/24/2015
Date Data Arrived at EDR: 12/01/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 34

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/27/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/11/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/24/2015
Date Data Arrived at EDR: 12/01/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 34

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 12/14/2014
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 28

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/13/2015
Date Data Arrived at EDR: 10/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 118

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Date Data Arrived at EDR: 11/25/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 65

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 08/20/2015
Date Data Arrived at EDR: 10/30/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 111

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 52

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/29/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 03/31/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/31/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 02/04/2016
Date Data Arrived at EDR: 03/24/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 04/01/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/22/2015
Date Data Arrived at EDR: 12/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 57
Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36
Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15
Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 01/15/2016
Next Scheduled EDR Contact: 05/02/2016
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/21/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/17/2015
Date Data Arrived at EDR: 12/04/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/01/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Annually

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/17/2015
Date Data Arrived at EDR: 12/04/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/01/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 02/08/2016
Date Data Arrived at EDR: 02/10/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 41

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/26/2015
Date Made Active in Reports: 09/02/2015
Number of Days to Update: 68

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 02/18/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/19/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/30/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 03/11/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/01/2015
Date Data Arrived at EDR: 09/03/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/18/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 133

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/08/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2015
Date Data Arrived at EDR: 08/26/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 10/15/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 33

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/12/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/18/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 28

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/11/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/26/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/07/2015
Date Data Arrived at EDR: 07/09/2015
Date Made Active in Reports: 09/16/2015
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/08/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 46

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/24/2015
Date Made Active in Reports: 09/30/2015
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/26/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/15/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 11/23/2015
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 86

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Date Data Arrived at EDR: 11/26/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/07/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/24/2016
Next Scheduled EDR Contact: 07/11/2016
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/09/2016
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 44

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 03/02/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/04/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/04/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 07/20/2015
Date Data Arrived at EDR: 09/09/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 55

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 03/08/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 10/25/2015
Date Data Arrived at EDR: 01/29/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 67

Source: Department of Defense
Telephone: 571-373-0407
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 03/01/2016
Date Data Arrived at EDR: 03/03/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/25/2016
Date Data Arrived at EDR: 02/16/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 01/05/2016
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 10/16/2015
Date Data Arrived at EDR: 01/12/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/14/2016
Next Scheduled EDR Contact: 06/27/2016
Data Release Frequency: Varies

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/24/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/22/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 01/11/2016
Date Data Arrived at EDR: 01/12/2016
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/01/2015
Date Data Arrived at EDR: 12/29/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/16/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 02/01/2016
Date Data Arrived at EDR: 02/03/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Annually

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 02/04/2016
Date Data Arrived at EDR: 02/05/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 46

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/25/2016
Next Scheduled EDR Contact: 08/08/2016
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/09/2016
Date Made Active in Reports: 04/20/2016
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/20/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/22/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 86

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/24/2016
Next Scheduled EDR Contact: 06/06/2016
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/20/2015
Date Data Arrived at EDR: 09/23/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 103

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/23/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2016
Date Data Arrived at EDR: 02/25/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 26

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2016
Date Data Arrived at EDR: 02/25/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 26

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

Registered Tank Database in Nassau County

A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 01/22/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 60
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/04/2016
Next Scheduled EDR Contact: 07/18/2016
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 12/16/2015
Date Data Arrived at EDR: 12/21/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 52
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/07/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 12/16/2015
Date Data Arrived at EDR: 12/21/2015
Date Made Active in Reports: 02/11/2016
Number of Days to Update: 52
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/07/2016
Next Scheduled EDR Contact: 06/20/2016
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/19/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/19/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/02/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/13/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/17/2015
Date Made Active in Reports: 08/12/2015
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/12/2016
Next Scheduled EDR Contact: 07/25/2016
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/24/2015
Date Made Active in Reports: 08/18/2015
Number of Days to Update: 25

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 03/16/2016
Date Data Arrived at EDR: 03/29/2016
Date Made Active in Reports: 04/19/2016
Number of Days to Update: 21

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 03/19/2015
Date Made Active in Reports: 04/07/2015
Number of Days to Update: 19

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/14/2016
Next Scheduled EDR Contact: 06/27/2016
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

LA ROCHELLE
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

TARGET PROPERTY COORDINATES

Latitude (North):	40.910808 - 40° 54' 38.91''
Longitude (West):	73.783536 - 73° 47' 0.73''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602448.1
UTM Y (Meters):	4529356.5
Elevation:	84 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 84 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
WESTCHESTER, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 36119C - FEMA DFIRM Flood data

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MOUNT VERNON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Ordovician
Series:	Middle Ordovician (Mohawkian)
Code:	O2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 4628045.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
		INQUIRY #:	4628045.2s
LAT/LONG:	40.910808 / 73.783536	DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: gravelly loam

Hydrologic Group: Not reported

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 127 inches

Depth to Watertable Min: > 38 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 141 Min: 4	Max: 7.3 Min: 4.5
2	3 inches	72 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000835790	0 - 1/8 Mile ESE
2	USGS40000835842	1/8 - 1/4 Mile NNE
3	USGS40000835908	1/2 - 1 Mile NNE
4	USGS40000835896	1/2 - 1 Mile NE
5	USGS40000835943	1/2 - 1 Mile NNW
6	USGS40000835557	1/2 - 1 Mile SSW
7	USGS40000835919	1/2 - 1 Mile ENE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG80000040052	1/4 - 1/2 Mile WSW
A2	NYOG80000040051	1/4 - 1/2 Mile WSW
A3	NYOG80000040050	1/2 - 1 Mile WSW
A4	NYOG80000040049	1/2 - 1 Mile WSW
A5	NYOG80000040053	1/2 - 1 Mile WSW

PHYSICAL SETTING SOURCE MAP - 4628045.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	La Rochelle	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Amy Stanton
LAT/LONG:	40.910808 / 73.783536	INQUIRY #:	4628045.2s
		DATE:	May 24, 2016 1:07 pm

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ESE **FED USGS** **USGS40000835790**
0 - 1/8 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405436073465501		
Monloc name:	WE 105		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9100993
Longitude:	-73.7815215	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	98.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	268
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	8.00	

2
NNE **FED USGS** **USGS40000835842**
1/8 - 1/4 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405445073470001		
Monloc name:	WE 100		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9125993
Longitude:	-73.7829104	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	85.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	300
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	8.00	

3
NNE **FED USGS** **USGS40000835908**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405502073464401		
Monloc name:	WE 283		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9173214
Longitude:	-73.7784658	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

4
NE **FED USGS** **USGS40000835896**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405459073463801		
Monloc name:	WE 104		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9164881
Longitude:	-73.7767991	Sourcemap scale:	Not Reported

Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	750
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	15.00	

5
NNW **FED USGS** **USGS40000835943**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405510073471501		
Monloc name:	WE 98		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.9195436
Longitude:	-73.7870772	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	55.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	401
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	4.00	

6
SSW **FED USGS** **USGS40000835557**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405354073472801		
Monloc name:	WE 103		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.8984329
Longitude:	-73.7906885	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	50.00
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	220
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	12.00	

7
ENE **FED USGS** **USGS40000835919**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-405504073460301		
Monloc name:	WE1055		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02030102	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.917877
Longitude:	-73.7670766	Sourcemap scale:	Not Reported
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	1
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Till		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	17
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1955	3.00	

Map ID
Direction
Distance

Database EDR ID Number

A1
WSW **OIL_GAS** **NYOG80000040052**
1/4 - 1/2 Mile

Api wellno:	31119237750000	Cnty:	0
Hole:	23775	Sidetrck:	0
Completion:	0	Well name:	SCW 4
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-02 00:00:00	Date total:	2008-09-19 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792499		
Surface la:	40.909323		
Bottom hol:	BH		
Bottom h00:	-73.792499		
Bottom h01:	40.909323		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	75	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:15.897000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237750000		
Site id:	NYOG80000040052		

A2
WSW **OIL_GAS** **NYOG80000040051**
1/4 - 1/2 Mile

Api wellno:	31119237740000	Cnty:	0
Hole:	23774	Sidetrck:	0
Completion:	0	Well name:	SCW 3
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-08-21 00:00:00	Date total:	2008-09-16 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792772		
Surface la:	40.909283		
Bottom hol:	BH		
Bottom h00:	-73.792772		

Bottom h01:	40.909283		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	73	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:30.367000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237740000		
Site id:	NYOG80000040051		

A3
WSW **OIL_GAS** **NYOG80000040050**
1/2 - 1 Mile

Api wellno:	31119237730000	Cnty:	0
Hole:	23773	Sidetrck:	0
Completion:	0	Well name:	SCW 2
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	NL	Map symbol:	OP
Well statu:	PA	Date statu:	2008-11-06 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-07-10 00:00:00	Date total:	2008-07-19 00:00:00
Date well :	Not Reported	Date wel00:	2008-10-10 00:00:00
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.792953		
Surface la:	40.909185		
Bottom hol:	BH		
Bottom h00:	-73.792953		
Bottom h01:	40.909185		
True verti:	1500	Measured d:	1500
Kickoff:	0	Drilleddep:	1500
Elevation:	71	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-02 08:26:56.020000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237730000		
Site id:	NYOG80000040050		

A4
WSW **OIL_GAS** **NYOG80000040049**
1/2 - 1 Mile

Api wellno:	31119237720000	Cnty:	0
Hole:	23772	Sidetrck:	0
Completion:	0	Well name:	SCW 1
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-08 00:00:00	Date total:	2008-09-23 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.793051		
Surface la:	40.909223		
Bottom hol:	BH		
Bottom h00:	-73.793051		
Bottom h01:	40.909223		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	72	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-10 07:49:59.300000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237720000		
Site id:	NYOG80000040049		

A5
WSW **OIL_GAS** **NYOG80000040053**
1/2 - 1 Mile

Api wellno:	31119237760000	Cnty:	0
Hole:	23776	Sidetrck:	0
Completion:	0	Well name:	SCW 5
Company na:	180 Union Avenue Owner LP	Operator n:	2438
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-11-13 00:00:00
Date permi:	2008-04-04 00:00:00	Permit iss:	2008-05-13 00:00:00
Date spudd:	2008-09-08 00:00:00	Date total:	2008-09-23 00:00:00
Date well :	2008-10-09 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	New Rochelle	Quad:	Mount Vernon
Quadsec:	H	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	Westcheste
Region:	3	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.793036		
Surface la:	40.909069		
Bottom hol:	BH		
Bottom h00:	-73.793036		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Bottom h01:	40.909069		
True verti:	500	Measured d:	500
Kickoff:	0	Drilleddep:	500
Elevation:	69	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-03-10 07:50:13.420000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31119237760000		
Site id:	NYOG80000040053		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

BLACKSTONE CONSULTING LLC

JOHN O'CONNOR

Senior Project Manager

PROFESSIONAL SUMMARY:

Mr. O'Connor has extensive experience in environmental programs compliance and management. He has performed and managed environmental projects related to hazardous materials building inspections; hazardous materials abatement site monitoring and emergency response planning; indoor air quality investigations (IAQ); Phase I and II environmental site assessments (ESA); underground/aboveground storage tank (UST/AST) removal and replacement and systems management; and quality control audits. He has written a variety of environmental assessment reports and proposals. Mr. O'Connor has performed these services at a variety of private, commercial, industrial and governmental facilities.

PROJECT EXPERIENCE:

- Over eighteen years of experience in conducting environmental assessments in commercial facilities, industrial properties, single and multi-family housing developments, and schools.
- Extensive experience in conducting Phase I Environmental Site Assessments in accordance with ASTM, HUD MAP, Fannie Mae and Freddie Mac Guidelines, as well as numerous private lender guidelines.
- Extensive experience in project management of asbestos and lead abatement projects, soil remediation projects and UST removals.
- Experience in conducting Phase II Environmental Site Assessments including materials sampling and soil and ground-water borings.
- Experience in environmental personnel management, project cost estimating, and effective staff scheduling.
- Experience in conducting quality control audits of field personnel for a multi-million dollar federal lead hazard risk assessment project.
- Experience as a Project Manager for a $500,000.00 mold abatement project.
- Knowledgeable in regulatory requirements for, and identification of, environmental hazards associated with commercial and residential buildings. Advises clients in effective management and resolution of the identified concerns.
- Trained in the health effects of lead and asbestos, federal and state regulations, techniques of assessment and abatement, use of protective equipment, assessment record keeping and reporting.

- A highly trained lead inspector, qualified in the use of Niton XL Spectrum Analyzer. Performs lead-based paint surveys in support of public and private multifamily developments and private residences.
- Experienced in conducting Energy Audits for single family residences, multi-family and commercial properties.
- Extensive training in environmental regulations, hazard identification, risk assessment and abatement methods.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

B.S., Millersville University, Major: Occupational Safety and Hygiene Management

Manufacturer's Training Course for Niton XL Spectrum Analyzer

EPA/AHERA Annual Asbestos Refresher Course

EPA Model Lead Paint Risk Assessor

Radon Measurement Operators Training Course

Home Energy Rating System Training

CERTIFICATIONS/ACCREDITATIONS/CONTINUING EDUCATION:

HUD Sponsored Multifamily Accelerated Processing (MAP) Training, Baltimore, Maryland

Maryland Accredited Lead Paint Risk Assessor

Pennsylvania Accredited Lead Paint Risk Assessor

Virginia Accredited Lead Paint Risk Assessor

District of Columbia Accredited Lead Paint Risk Assessor

EPA/AHERA Certified Asbestos Building Inspector

EPA/AHERA Certified Asbestos Management Planner

EPA Radon Measurement Proficiency Program Listed Inspector

Florida Licensed Radon Measurement Technician

Certified to Collect Drinking Water: Maryland

BLACKSTONE CONSULTING LLC

ALLAN S. COFFEE

Associate

PROFESSIONAL SUMMARY:

Mr. Coffee has over 25 years of experience assisting clients in their relationship with the built environment. He has expertise in all aspects of environmental oversight, regulation, and liability associated with property acquisition, management, and disposition. He also specializes in team leadership and oversight of Due Diligence activities, Phase I ESAs, Building Surveys, Subsurface Soil and Groundwater Sampling, Soil and Groundwater Remediation and Monitoring, as well as Regulatory Closure.

SELECTED PROJECT EXPERIENCE:

- Managed and directed technical and financial aspects of all operations in the Western United States Division for a national full-service environmental consulting company, including environmental services (Phase I ESAs, soil and groundwater, etc.), construction services (asbestos, lead, and other regulated building materials), industrial hygiene services (occupational monitoring, negative exposure assessments), and indoor air quality (moisture, microbial growth).
- Directed all aspects of environmental geology services for an environmental consulting company, including the oversight and management of technical approach, project budgeting and accounting for Due Diligence, Phase I ESAs, and soil and groundwater remediation.
- Performed Phase I ESAs, Soil and Groundwater Assessments, and regulatory communication for a variety of property owners, environmental consulting companies, and government projects.

EDUCATION AND PROFESSIONAL AFFILIATIONS

University of California at Los Angeles, CA, Bachelor of Science

OSHA 40-Hour HAZWOPER (Hazardous Waste Operator and Emergency Response)

NIOSH 582 Analyst Equivalent Certification

Indoor Air Quality Specialist/Inspector

California Registered Environmental Assessor I (REA I)

BLACKSTONE CONSULTING LLC

STEPHEN E. MANELIS

Principal and Co-Founder

PROFESSIONAL SUMMARY:

Mr. Manelis is co-founder of Blackstone and has over 18 years of experience with Environmental Site Assessments (ESAs) and other Due Diligence consulting during Real Estate Transactions and Mergers/Acquisitions. Specific experience includes Phase I and II ESAs, Environmental Compliance/Audit, and Asbestos, Lead-based paint, Radon gas, and Mold/IAQ consulting, and Property Condition Assessments. Additional experience includes soil/groundwater contamination assessments and regulatory agency coordination, remedial-action planning and management, pre-construction soil and groundwater characterization for urban redevelopment site/Brownfields, NPDES permitting and storm water management; wetland delineation and permitting; and threatened and endangered species studies.

In addition to leading Blackstone's Real Estate and Due Diligence business unit, Mr. Manelis is responsible for developing and maintaining Blackstone's national client accounts program.

SELECTED PROJECT EXPERIENCE:

Managed over 3300 Phase I Environmental Site Assessments (ESAs) for corporate real estate departments, real estate investment trusts (REITs), Fannie Mae/Freddie Mac underwriters, large national and regional banks, private/public investment groups and equity sponsors, and industrial/commercial facilities throughout the United States. In addition to site visit experience on numerous types of real estate, experiences include organization of project staff for single projects and/or portfolios, management of field activities and accurate interpretation of data, and final report QA/QC.

Third party review coordinator and project manager during industrial facility mergers/acquisitions throughout the continental U.S. As consultant to equity partners, provided capital expenditure and annual operating budgets associated with environmental compliance, waste management and disposal, and permitting.

Provided technical support and project management for wetland delineation and habitat assessment studies in the Southeast. Work involved reviewed of wetland field survey activities, surveying and map preparation, and the research of Federal and State databases concerning known occurrences of threatened and endangered species followed by field verification.

Program Manager for due diligence team associated industrial park acquisition by a publicly-traded REIT. Environmental issues included past manufacturing operations,

underground storage tanks usage, various hazardous materials storage, and adjoining property with known groundwater contamination migrating onto the site. Past on-site use and contamination triggered New Jersey ISRA reporting and coordination with the NJDEP. Phase I ESA and Phase II subsurface investigation work completed within 21-days and evaluation of risk and potential remediation cost defined. Quick response and resolution allowed transaction to occur and assigned liability to the appropriate parties protecting the buyer.

Program Manager for redevelopment of industrial property formerly consisting of vehicle repair facility, furniture stripper, machine shop, and light manufacturer. Client was publicly-traded REIT and project included mid-rise 200-unit multi-family housing development with subterranean parking. Contamination identified during due diligence required notification to state regulatory agency with potential to stall acquisition and development approvals. Remediation risk and cost defined during due diligence allowing transaction to occur before regulatory closure achieved. Remediation activities of soil and groundwater performed in conjunction with construction providing savings and fast-tracking regulatory closure with state agency. Project was completed and remains in client portfolio.

Program Manager for environmental due diligence and redevelopment consulting services for privately-held nationwide student housing developer. Project included acquisition and redevelopment of a high profile student housing project in Philadelphia, PA. Work included initial environmental due diligence, identification and resolution of asbestos and underground storage tank risk via sampling, and proper permitting prior to demolition of over 200,000 square feet of building space. Project construction proceeded as planned.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

University of Rhode Island - Bachelor of Science, Natural Resource Development

ASTM E-50 Committee for Environmental Assessment

National Registry of Environmental Professionals (NREP)

AHERA/EPA Asbestos in Buildings Inspector

Liability Design for Environmental Professionals (DPIC Companies)

40-Hour OSHA Training

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 6193173.2s
September 16, 2020

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	791
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

COORDINATES

Latitude (North):	40.9105970 - 40° 54' 38.14''
Longitude (West):	73.7837670 - 73° 47' 1.56''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602429.0
UTM Y (Meters):	4529333.0
Elevation:	88 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	SOUND CLEANER	63 MEMORIAL HWY	NY DRYCLEANERS	Lower	2, 0.000,
A2	SOUND CLEANERS	63 MEMORIAL HWY	EDR Hist Cleaner	Lower	2, 0.000,
A3	OFFICE BUILDING	8-10 RAILROAD PLACE	NY Spills	Lower	4, 0.001,
B4	RESIDENCE	129 DIVISON ST	NY Spills	Higher	34, 0.006, SSW
A5	AVALON ON THE SOUND	HUGUENOT STREET AND	NY UST	Higher	36, 0.007, SSE
A6	UST	MEMORIAL HIGHWAY AND	NY Spills	Higher	36, 0.007, SSE
A7	CONSOLIDATED EDISON	MEMORIAL HIGHWAY & H	NY MANIFEST	Higher	36, 0.007, SSE
B8	CON EDISON	DIVISION & HUGUENOT	NY MANIFEST	Higher	47, 0.009, South
B9	CON EDISON MANHOLE:	HUGENOT AVE & DIVISI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	47, 0.009, South
B10	CON ED	DIVISION ST & HUGENO	NY MANIFEST	Higher	47, 0.009, South
B11	CON EDISON	HUGENOT ST & DIVISIO	NY MANIFEST	Higher	47, 0.009, South
B12	CON EDISON	HUGENOT & DIVISION S	NY MANIFEST	Higher	47, 0.009, South
B13	CON EDISON - TRANSFO	DIVISION ST AND HUGE	RCRA-LQG	Higher	47, 0.009, South
B14	CON EDISON TRANSFORM	DIVISION ST & HUGUEN	RCRA NonGen / NLR	Higher	47, 0.009, South
A15	METRO NORTH TRACKS	EAST OF NEW ROCHELLE	NY Spills	Lower	48, 0.009, WSW
A16	METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	NY Spills	Lower	48, 0.009, WSW
B17	NYSDOT BIN 1049890	DIVISION ST OVER MET	RCRA NonGen / NLR	Higher	49, 0.009, South
C18	MH1204	HUGUENOT AVE/LAWTON	NY Spills	Higher	97, 0.018, East
B19	ROAD	HUGUENOT ST/DIVISION	NY Spills	Higher	163, 0.031, South
B20	VACANT LOT	HUGUENOT ST/DIVISION	NY LTANKS	Higher	163, 0.031, South
B21	SHORELINE OIL	296 HUGENOT ST,REAR	NY LTANKS	Higher	174, 0.033, SSW
B22	LILLIAN VERNON CO.	WESTCHESTER PLACE	NY LTANKS	Higher	179, 0.034, South
A23	NYSDOT BIN 1091390	DIVISION ST OVER I 9	RCRA NonGen / NLR	Lower	185, 0.035, West
B24	NEW ROCHELLE IRISH B	38 DIVISION STREET	NY UST	Higher	206, 0.039, South
D25	CON EDISON	260 NORTH AVE	NJ MANIFEST	Lower	217, 0.041, NE
D26	CON EDISON	260 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	217, 0.041, NE
B27	HAYES KATHRYN INC	36-38 DIVISION ST	EDR Hist Cleaner	Higher	230, 0.044, South
B28	JONES RESIDENCE	311 HUGUENOT STREET	NY LTANKS	Higher	238, 0.045, SSW
C29	MAIN LIBRARY	LAWTON ST	NY LTANKS	Higher	239, 0.045, East
D30	CON EDISON TRANSFORM	NORTH AVE & HUGUENOT	RCRA NonGen / NLR, NY MANIFEST	Lower	240, 0.045, NE
D31	CON EDISON MANHOLE:	HUGUENOT AVE & NORTH	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	240, 0.045, NE
D32	CON EDISON	NORTH AVE & HUGENOT	NY MANIFEST	Lower	240, 0.045, NE
D33	HUGUENOT AND NORTH A	HUGUENOT AND NORTH A	NY Spills	Lower	240, 0.045, NE
D34	CON EDISON MANHOLE:	HUGENUOT ST & NORTH	RCRA NonGen / NLR	Lower	240, 0.045, NE
C35	ACCESSOCRAFT PRODUCT	48 LAWTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	242, 0.046, ESE
E36	SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	NY Spills	Lower	255, 0.048, West
D37	US POSTAL SERVICE	255 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	258, 0.049, ENE
B38	306 HUGUENOT STREET	306 HUGUENOT STREET	NY AST	Higher	270, 0.051, SSW
B39	CERUSSI AND VERE	306 HUGUENOT ST	NY UST	Higher	270, 0.051, SSW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D40	COMMERCIAL BUILDING	271 NORTH AVE	NY Spills	Lower	287, 0.054, NE
D41	KAUFMAN HUGUENOT COM	271 NORTH AVENUE	NY UST, NY AST	Lower	287, 0.054, NE
D42	A PLUS INC	271 NORTH AVE STE 11	EDR Hist Auto	Lower	287, 0.054, NE
C43	LAWTON STREET REALTY	41-43 LAWTON ST	NY LTANKS	Higher	291, 0.055, ESE
C44	LAWTON STREET REALTY	41-43 LAWTON STREET	NY UST	Higher	291, 0.055, ESE
C45	PAVEMENT	41 LAWTON STREET	NY Spills	Higher	291, 0.055, ESE
C46	LAWTON STREET REALTY	41-43 LAWTON ST	NY Spills	Higher	291, 0.055, ESE
D47	FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	RCRA NonGen / NLR	Higher	292, 0.055, ENE
F48	STATION CLEANERS	24 STATION PLZ	EDR Hist Cleaner	Lower	299, 0.057, NNW
F49	NEW ROCHELLE CITY OF	24 STATION PLZ N	RCRA-SQG	Lower	299, 0.057, NNW
G50	CABLE	29 DIVISION STREET	NY Spills	Higher	301, 0.057, South
H51	NORTH BROOK REALTY A	270 NORTH AVENUE, SU	NY UST	Lower	325, 0.062, NNE
I52	VINEK / KRACKO - UST	316 HUGUENOT ST	NY Spills	Higher	367, 0.070, SSW
H53	EAST RIVER SAVINGS B	277 NORTH AVE.	NY LTANKS	Lower	378, 0.072, NNE
H54	CON EDISON MANHOLE:	277 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	378, 0.072, NNE
H55	277 NR PRINCIPAL, LL	277 NORTH AVENUE	NY UST	Lower	378, 0.072, NNE
H56	BUSINESS	277 NORTH AVENUE	NY LTANKS	Lower	378, 0.072, NNE
H57	277 NORTH LLC	277 NORTH AVENUE	NY LTANKS	Lower	378, 0.072, NNE
H58	CONSOLIDATED EDISON	F/O 277 NORTH AVE	NY MANIFEST	Lower	378, 0.072, NNE
G59	CON EDISON	19 DIVISION ST & WAS	NY Spills, NY MANIFEST	Higher	420, 0.080, SSE
J60	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	425, 0.080, East
J61	CON EDISON	ANDERSON ST & NORTH	NY MANIFEST	Higher	425, 0.080, East
J62	CON EDISON	NORTH AVE & ANDERSON	RCRA NonGen / NLR, FINDS, ECHO	Higher	425, 0.080, East
J63	CON EDISON	NORTH AVE & ANDERSON	NJ MANIFEST	Higher	425, 0.080, East
J64	CON EDISON TRANSFORM	NORTH AVE & ANDERSON	RCRA NonGen / NLR, NY MANIFEST	Higher	425, 0.080, East
J65	CON ED STREET EXCAVA	NORTH AVE AND ANDERS	NY Spills	Higher	425, 0.080, East
J66	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	425, 0.080, East
J67	CONCRETE FLOORING WI	230 NORTH AVENUE	NY Spills	Higher	444, 0.084, East
J68	CON EDISON	230 NORTH AVE	NJ MANIFEST	Higher	444, 0.084, East
J69	MKM EQUITY, LLC	230 NORTH AVENUE	NY AST	Higher	444, 0.084, East
J70	CON EDISON	230 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	444, 0.084, East
J71	CON ED	230 NORTH AVE	NY MANIFEST	Higher	444, 0.084, East
J72	NORTH AVE REALITY	5 ANDERSON ST	NY LTANKS, NY AST	Higher	444, 0.084, East
J73	ANDERSON DEVELOPMENT	5 ANDERSON STREET	NY UST	Higher	444, 0.084, East
E74	ST GABRIEL'S CHURCH	120 DIVISION ST	NY Spills	Higher	459, 0.087, West
G75	COMM/RESIDENT. PROPE	15 DIVISION STREET	NY LTANKS	Higher	466, 0.088, SSE
J76	NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	NY LTANKS	Higher	484, 0.092, ESE
J77	CVS PHARMACY #8447	222 NORTH AVE	RCRA-VSQG, NY MANIFEST	Higher	519, 0.098, East
I78	CON EDISON	HUGENOT & CENTRE ST	NY MANIFEST	Higher	521, 0.099, SSW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I79	CON EDISON	HUGUENOT ST & CENTRE	RCRA NonGen / NLR	Higher	521, 0.099, SSW
I80	CON EDISON	CENTER & HUGUENOT	NY MANIFEST	Higher	521, 0.099, SSW
I81	CON EDISON	CENTRE AVE & HUGUENO	NY MANIFEST	Higher	521, 0.099, SSW
K82	ROCHELLE DELUXE TAXI	10 STATION PLAZA SOU	NY UST	Lower	525, 0.099, North
I83	SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	NY UST	Higher	535, 0.101, SSW
I84	APARTMENT BLDG	54 CENTRE AVE	NY LTANKS	Higher	535, 0.101, SSW
I85	CEMENT COURT YARD	54 CENTER AVE	NY Spills	Higher	535, 0.101, SSW
G86	RPM REALTY INC	9-15 DIVISION STREET	NY UST	Higher	541, 0.102, SSE
G87	RPM REALTY INC	9-15 DIVISION STREET	NY AST	Higher	541, 0.102, SSE
L88	STATION CLEANERS	1 DEPOT PLAZA #1	NY DRYCLEANERS	Lower	557, 0.105, NNW
L89	DEPOT PLACE LLC	1 DEPOT PLACE	NY UST	Lower	557, 0.105, NNW
I90	ERIC S TURNER & CO I	33-35 CENTRE AVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	560, 0.106, SSW
I91	CENTRE AVENUE DEVELO	33 CENTRE AVENUE	NY BROWNFIELDS	Higher	560, 0.106, SSW
M92	P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	NY Spills	Lower	560, 0.106, SW
M93	I-95	I-95EB MP54	NY Spills	Lower	560, 0.106, SW
I94	GREEN HEAVEN CLEANER	62 CENTRE AVE	NY DRYCLEANERS	Higher	573, 0.109, SSW
I95	SIMONETTI CLEANERS	62 CENTRE ST	RCRA-VSQG, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	573, 0.109, SSW
I96	SIMONETTI CLEANERS &	62 CENTRE AVE	EDR Hist Cleaner	Higher	573, 0.109, SSW
I97	HACKER MORRIS J & SO	64 CENTRE AVE	EDR Hist Auto	Higher	584, 0.111, South
I98	COMMERCIAL PROPERTY	64 CENTRE AVE	NY LTANKS	Higher	584, 0.111, South
I99	M.J. HACKER & SONS I	64 CENTRE AVE	NY UST	Higher	584, 0.111, South
N100	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	591, 0.112, NE
N101	CON EDISON	HUGUENOT ST & LE COU	NJ MANIFEST	Higher	591, 0.112, NE
N102	CON EDISON	HUGUENOT ST & LE COU	RCRA NonGen / NLR	Higher	591, 0.112, NE
N103	CON EDISON	HUGUENOT ST & LE COU	NY MANIFEST	Higher	591, 0.112, NE
N104	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	591, 0.112, NE
O105	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	593, 0.112, SW
O106	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Higher	593, 0.112, SW
J107	SPEEDY CLEANERS	217 NORTH AVENUE	US AIRS, FINDS, ECHO, NY DRYCLEANERS	Higher	595, 0.113, East
K108	SPOKEN ARTS BUILDING	310 NORTH AVENUE	NY UST	Lower	600, 0.114, North
N109	TRUMP PLAZA	175 HUGUENOT STREET	NY LTANKS, NY Spills	Higher	605, 0.115, NE
I110	NYNEX LOCATION	342 HUEGNOT ST	NY LTANKS	Higher	608, 0.115, SSW
I111	VERIZON	342 HUGUENOT ST	NY Spills	Higher	608, 0.115, SSW
I112	NEW YORK TELEPHONE C	342 HUGUENOT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	608, 0.115, SSW
K113	NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	NY UST	Lower	614, 0.116, North
O114	APPAREL PLUS	27 CENTRE AVE	NY Spills	Higher	624, 0.118, SW
P115	SPILL NUMBER 9900400	535 MAIN ST	NY Spills	Higher	630, 0.119, SSE
P116	SIDNEY FURNITURE	535 MAIN ST	NY Spills	Higher	630, 0.119, SSE
K117	CONSOLIDATED EDISON	F/O 311 NORTH AVE	NY MANIFEST	Lower	634, 0.120, North

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J118	CATHOLIC NEWS PUBLIS	210 NORTH AVE	NY LTANKS	Higher	635, 0.120, ESE
L119	COMMERCIAL - UST	35 GRAND STREET	NY Spills	Lower	636, 0.120, NNW
P120	NOVA REALTY - UST	523 MAIN ST	NY Spills	Higher	638, 0.121, SSE
Q121	CON EDISON	LECOUNT PL & ANDERSO	NJ MANIFEST	Higher	645, 0.122, ENE
Q122	CON EDISON	LECOUNT PL & ANDERSO	RCRA NonGen / NLR, FINDS, ECHO	Higher	645, 0.122, ENE
Q123	CON EDISON	LECOUNT PL & ANDERSO	NY MANIFEST	Higher	645, 0.122, ENE
P124	LILLIAN VERNON CORPO	543-549 MAIN STREET	NY UST	Higher	647, 0.123, SSE
P125	BLUE GILL REALTY	543 MAIN ST	NY LTANKS, NY Spills	Higher	647, 0.123, SSE
P126	543 MAIN STREET	543 MAIN STREET	NY UST	Higher	647, 0.123, SSE
P127	CONSOLIDATED EDISON	DIVISION & MAIN	NY MANIFEST	Higher	651, 0.123, SSE
P128	CON EDISON - TRANSFO	DIVISION ST & MAIN S	RCRA-LQG	Higher	651, 0.123, SSE
P129	CON EDISON	DIVISION ST & MAIN S	NY MANIFEST	Higher	651, 0.123, SSE
P130	CON EDISON - TRANSFO	DIVISION ST & MAIN S	NJ MANIFEST	Higher	651, 0.123, SSE
K131	CON EDISON MANHOLE:	313 NORTH AVE FRONT	RCRA NonGen / NLR	Lower	654, 0.124, North
R132	75 CENTRE AVENUE LLC	75 CENTRE AVENUE	NY UST, NY AST	Higher	661, 0.125, South
R133	CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	NY LTANKS	Higher	661, 0.125, South
O134	MR CHIMNEY CLEAN	32 RELYEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	661, 0.125, SSW
Q135	MACYS	33 LE COUNT PLACE	NY MANIFEST	Higher	670, 0.127, ENE
K136	4 STORY APARTMENT BU	320 NORTH AVENUE	NY UST	Lower	670, 0.127, North
P137	COMMERCIAL PROPERTY	522 MAIN STREET	NY LTANKS	Higher	678, 0.128, SSE
P138	NEW ROCHELLE SUPERMA	538 MAIN STREET	NY AST	Higher	679, 0.129, SSE
R139	MAISON 347 LLC	347 HUGUENOT STREET	NY UST	Higher	683, 0.129, SSW
P140	542 MAIN STREET LLC	542 MAIN STREET	NY UST	Higher	686, 0.130, SSE
P141	OFFICE BLDG	542 MAIN STREET	NY LTANKS	Higher	686, 0.130, SSE
S142	COMMERCIAL BUILDING	507 MAIN STREET	NY LTANKS	Higher	687, 0.130, SE
143	CON EDISON	19 DIVISION ST & WAS	RCRA NonGen / NLR, FINDS, ECHO	Higher	687, 0.130, NW
P144	CON EDISON TRANSFORM	CHURCH ST & MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	688, 0.130, SE
P145	CON EDISON TRANSFORM	MAIN ST & CHRUCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	688, 0.130, SE
P146	CON EDISON MANHOLE:	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	688, 0.130, SE
P147	CON EDISON	MAIN ST & CHURCH ST	NY MANIFEST	Higher	688, 0.130, SE
R148	COCO RESIDENCE	81 CENTRE AVE	NY LTANKS	Higher	700, 0.133, South
T149	CON EDISON	205 NORTH AVE	RCRA NonGen / NLR	Higher	711, 0.135, ESE
T150	CON EDISON	205 NORTH AVE	NJ MANIFEST	Higher	711, 0.135, ESE
T151	CON EDISON	205 NORTH AVE	NY MANIFEST	Higher	711, 0.135, ESE
R152	587 MAIN STREET	348 HUGUENOT STREET	NY AST	Higher	721, 0.137, SSW
P153	CON EDISON	552 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	722, 0.137, South
P154	CON EDISON	552 MAIN ST	NJ MANIFEST	Higher	722, 0.137, South
K155	CON EDISON - MANHOLE	GARDEN ST AND NORTH	RCRA-LQG, NY MANIFEST	Lower	728, 0.138, North
K156	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	728, 0.138, North

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K157	CON EDISON MANHOLE 4	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	728, 0.138, North
K158	CON EDISON MANHOLE:	NORTH ST & GARDEN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	728, 0.138, North
K159	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, FINDS, ECHO	Lower	728, 0.138, North
K160	CON EDISON SERVICE B	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	728, 0.138, North
161	BLOOMINGDALE PARKING	554 MAIN ST	NY UST	Higher	732, 0.139, South
T162	BARON MANAGEMENT	200 NORTH AVENUE	NY UST	Higher	733, 0.139, ESE
S163	FORMER CHASE BANK BU	491 MAIN STREET	NY UST, NY AST	Higher	747, 0.141, SE
S164	BARCLAYS BANK OF NY/	491 MAIN ST.	NY LTANKS	Higher	747, 0.141, SE
L165	RESIDENCE	60 GRAND STREET	NY LTANKS, NY Spills	Lower	749, 0.142, NNW
S166	NEW ROCHELLE PUBLIC	1 LAWTON	NY LTANKS	Higher	749, 0.142, SE
R167	CON EDISON	565 MAIN ST	RCRA NonGen / NLR	Higher	755, 0.143, South
R168	CON EDISON	565 MAIN ST	NJ MANIFEST	Higher	755, 0.143, South
S169	ADREAN PRINTING CO	490 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	776, 0.147, SE
R170	HANGERS CLEANERS	562-564 MAIN STREET	NY DRYCLEANERS	Higher	776, 0.147, South
O171	PRO AUTO PARTS	41 REYLEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	780, 0.148, SSW
U172	NYS THRUWAY AUTHORIT	I-95 AT MP 605.76 NO	RCRA-LQG, NY MANIFEST	Lower	780, 0.148, North
L173	GUIDANCE CENTER INC	70 GRAND ST	NY LTANKS	Lower	785, 0.149, NNW
R174	FIRST METRO SERVICES	357 HUGONOT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	790, 0.150, SSW
T175	RETTNER MANAGEMENT C	481 MAIN ST	NY UST	Higher	795, 0.151, ESE
T176	14 LE COUNT STANDARD	14 LE COUNT PL, 455	NY BROWNFIELDS	Higher	805, 0.152, East
R177	MISR REALTY, LLC	573-579 MAIN STREET	NY AST	Higher	809, 0.153, South
R178	MISR REALTY, LLC	573-579 MAIN STREET	NY UST	Higher	809, 0.153, South
O179	INDUST OVERALL SERVI	10 BARTELS PLACE	NY LTANKS	Lower	816, 0.155, SW
R180	CON EDISON TRANSFORM	CENTRE AVE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	820, 0.155, South
R181	CON EDISON	CENTRE & MAIN ST	NJ MANIFEST	Higher	820, 0.155, South
R182	CON EDISON	CENTRE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	820, 0.155, South
R183	CON ED	CENTRE & MAIN ST	NY MANIFEST	Higher	820, 0.155, South
R184	CON EDISON	MAIN ST & CENTRE ST	NY MANIFEST	Higher	820, 0.155, South
O185	NYSDEC-SITE 360109 I	10 BARTELS PL	NJ MANIFEST	Lower	820, 0.155, SW
O186	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY SHWS, NY CBS	Lower	820, 0.155, SW
O187	INDUSTRIAL OVERALL S	10 BARTELLS PLACE	NY UST	Lower	820, 0.155, SW
O188	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY CBS AST	Lower	820, 0.155, SW
O189	NYSDEC-SITE 360109 I	10 BARTELS PL	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Lower	820, 0.155, SW
190	RITZCOVAN - TTF	22 BURLING LANE	NY LTANKS	Lower	823, 0.156, NNW
U191	CON EDISON MANHOLE:	NORTH AVE & BURLING	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	826, 0.156, North
V192	CASARRA RESIDENCE	9 BADEAU PL	NY LTANKS	Higher	865, 0.164, West
W193	STORAGE USA	363 HUGUENOT STREET	NY UST	Higher	877, 0.166, SSW
X194	DRIVE IT YOURSELF	20 GARDEN STREET	NY UST	Lower	919, 0.174, NNE
Y195	NYNEX	40 WASHINGTON AVE	NY LTANKS	Higher	919, 0.174, WNW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z196	ROTH CLEANERS	1 LEROY PL	RCRA NonGen / NLR, FINDS, ECHO, NY DRYCLEANERS, NY...	Higher	935, 0.177, SSE
Z197	CONSOLIDATED EDISON	DIVISION ST & LEROY	NY MANIFEST	Higher	954, 0.181, SSE
AA198	CON ED-V14	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	956, 0.181, East
AA199	CON ED-V37	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	956, 0.181, East
V200	RESIDENCE	18 BADEAU PLACE	NY LTANKS	Higher	960, 0.182, West
AB201	J B & FRANKS	27 BARTELS PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	963, 0.182, SW
Y202	ST GABRIEL HIGH SCHO	50 WASHINGTON AVE	NY LTANKS, NY Spills	Higher	979, 0.185, WNW
Y203	ST GABRIEL SCHOOL	50 WASHINGTON AVE	NY LTANKS	Higher	979, 0.185, WNW
Z204	CHURCH-DIVISION STRE	26 SOUTH DIVISION ST	NY BROWNFIELDS	Higher	986, 0.187, SSE
X205	FURNITURE RESTORNATI	26 GARDEN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	989, 0.187, NNE
W206	CON EDISON	HUGENOT ST & COLUMBU	NY MANIFEST	Higher	990, 0.188, SSW
W207	CON EDISON	HUGENOT AVE & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
W208	CON EDISON	HUGUENOT ST & COLUMB	NY MANIFEST	Higher	990, 0.188, SSW
V209	DIIORGI HOME	47 WARREN STREET	NY LTANKS	Higher	997, 0.189, WSW
U210	CON EDISON MANHOLE:	350 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1014, 0.192, North
AB211	CON EDISON	35 BARTELS PL	NY MANIFEST	Lower	1020, 0.193, SW
AB212	CON EDISON	35 BARTELS PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1020, 0.193, SW
AC213	APT BUILDING	40 WARREN STREET	NY LTANKS, NY Spills	Higher	1021, 0.193, WSW
AD214	CON EDISON TRANSFORM	595 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1035, 0.196, SSW
X215	COTTAGE - GARDEN AUT	30 GARDEN STREET	NY UST	Lower	1038, 0.197, NNE
AD216	CON EDISON TRANSFORM	592 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1040, 0.197, South
AE217	RUSH MFG CORP	18 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1054, 0.200, SSW
V218	NYNEX	UNION AVENUE AND WAR	NY MANIFEST	Higher	1060, 0.201, West
219	CITIZEN	33 GROVE ST	NY LTANKS	Higher	1067, 0.202, WSW
AF220	THE MALL	MAIN STREET	NY LTANKS	Lower	1076, 0.204, East
AG221	CON EDISON SERVICE B	CENTRE AVE & LEROY	RCRA NonGen / NLR, FINDS	Higher	1083, 0.205, South
AG222	CON EDISON	CENTRE AVE & LEROY	NY MANIFEST	Higher	1083, 0.205, South
AG223	CON EDISON SERVICE B	LEROY PL & CENTER AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1083, 0.205, South
AH224	CON EDISON SERVICE B	174 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1091, 0.207, ESE
W225	381-383 HUGUENOT LLC	381 HUGUENOT STREET	NY UST	Higher	1092, 0.207, SSW
W226	THE HUGUENOT	381-393 HUGUENOT STR	NY BROWNFIELDS	Higher	1092, 0.207, SSW
AI227	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1094, 0.207, North
AI228	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1094, 0.207, North
AI229	HNJ REALTY	358-364 N AVENUE	PA MANIFEST	Lower	1094, 0.207, North
AI230	HNJ REALTY	358-364 N AVE	PA MANIFEST	Lower	1094, 0.207, North
AI231	SCHMUKLER'S CLEANERS	360 NORTH AVE.	NY DRYCLEANERS	Lower	1113, 0.211, North
AI232	SCHMUCKLERS CLEANERS	360 NORTH AVE	RCRA-VSQG, NY MANIFEST	Lower	1113, 0.211, North
AJ233	NEW ROCHELLE HOSPITA	COVION PLACE	NY LTANKS	Higher	1114, 0.211, NW
AJ234	SOUND SHORE MEDICAL	16 GUION PL	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	1140, 0.216, NW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AJ235	MONTEFIORE - NEW ROC	16 GUION PLACE	NY UST, NY AST	Higher	1140, 0.216, NW
AJ236	SOUTH SHORE MED CENT	16 GUION PLACE	NY LTANKS	Higher	1140, 0.216, NW
AJ237	SOUND SHORE MEDICAL	16 GUION PL	PA MANIFEST	Higher	1140, 0.216, NW
238	RESIDENCE	79 WARREN ST	NY LTANKS	Higher	1141, 0.216, West
AJ239	66 MEMORIAL BLVD	66 MEMORIAL BLVD	NY LTANKS	Higher	1142, 0.216, NW
AK240	LEXINGTON CENTER FOR	3 COTTAGE PL	NJ MANIFEST	Lower	1144, 0.217, NNE
AK241	LEXINGTON CENTER FOR	3 COTTAGE PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1144, 0.217, NNE
242	CON EDISON	46 CLINTON PL	RCRA NonGen / NLR, NY MANIFEST	Higher	1152, 0.218, SE
AH243	35 CLINTON PLACE LLC	35 CLINTON PLACE	NY AST	Higher	1153, 0.218, SE
AI244	MAYCO, LLC	18-20 MAY ST	NY AST	Lower	1153, 0.218, NNW
AF245	MONROE COLLEGE	420 MAIN STREET	NY AST	Lower	1176, 0.223, East
AL246	CON EDISON MANHOLE 1	HUGEONOT ST & HARRIS	RCRA NonGen / NLR, NJ MANIFEST	Lower	1189, 0.225, NE
AL247	CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NY MANIFEST	Lower	1189, 0.225, NE
AD248	CON EDISON	MAIN ST & MAPLE AVE	NY MANIFEST	Higher	1190, 0.225, SSW
AD249	CON EDISON	MAPLE AVE & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST	Higher	1190, 0.225, SSW
AD250	CON EDISON MANHOLE:	MAIN ST & MAPLE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1190, 0.225, SSW
AC251	PREFERRED CLEANERS	95 UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1190, 0.225, West
AE252	ALL AMERICAN SPORTS	44 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1204, 0.228, SW
AH253	CO-OP	30 CLINTON PLACE	NY LTANKS	Higher	1206, 0.228, SE
AH254	30 CLINTON PLACE OWN	30 CLINTON PLACE	NY UST, NY AST	Higher	1206, 0.228, SE
AH255	CON EDISON	150 NORTH AV	NY MANIFEST	Higher	1209, 0.229, SE
AM256	CON EDISON	45 HARRISON ST	NY MANIFEST	Lower	1220, 0.231, ENE
AM257	CON EDISON	45 HARRISON ST	NJ MANIFEST	Lower	1220, 0.231, ENE
AM258	CON EDISON	45 HARRISON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1220, 0.231, ENE
AM259	CITY OF NEW ROCHELLE	45 HARRISON STREET	NY LTANKS	Lower	1220, 0.231, ENE
AH260	CON EDISON MANHOLE:	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1221, 0.231, ESE
AH261	CON EDISON SERVICE B	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Higher	1221, 0.231, ESE
AN262	CON EDISON	OPP 20 LOCKWOOD AV	NY MANIFEST	Lower	1224, 0.232, NNW
AI263	CON EDISON TRANSFORM	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR, NY MANIFEST	Lower	1226, 0.232, North
AI264	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1226, 0.232, North
AI265	CON EDISON	LOCKWOOD AVE & NORTH	NY MANIFEST	Lower	1226, 0.232, North
AI266	CON EDISON	LOCKWOOD AVE & NORTH	NJ MANIFEST	Lower	1226, 0.232, North
AI267	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1226, 0.232, North
AI268	CON EDISON	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR	Lower	1226, 0.232, North
AC269	LJNJ ASSOCIATES	100-102 UNION AVE	NY UST	Higher	1227, 0.232, West
AC270	100-102 UNION AVENUE	100-102 UNION AVENUE	NY LTANKS	Higher	1227, 0.232, West
AM271	CON ED	HARRISON ST & CEDER	NY MANIFEST	Lower	1228, 0.233, ENE
AM272	CON EDISON	HARRISON ST & CEDER	NJ MANIFEST	Lower	1228, 0.233, ENE
AM273	CON EDISON	HARRISON ST & CEDER	RCRA NonGen / NLR, FINDS, ECHO	Lower	1228, 0.233, ENE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AM274	CON EDISON SERVICE B	HARRISON AVE & CEDAR	RCRA NonGen / NLR, NY MANIFEST	Lower	1228, 0.233, ENE
AI275	368 NORTH AVE MGMT C	368 NORTH AVENUE	NY UST	Lower	1230, 0.233, North
AC276	KAGEL HOME	99 UNION AVE	NY LTANKS	Higher	1230, 0.233, West
AG277	125	CENTRE AVE	NY LTANKS	Higher	1232, 0.233, South
AL278	HEALTH DEPT OFFICE	145 HUGUENOT ST	NY LTANKS, NY Spills	Lower	1245, 0.236, NE
AL279	LONGINES WITTNAUER W	145 HUGUENOT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1245, 0.236, NE
AL280	GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NY UST	Lower	1245, 0.236, NE
AM281	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1247, 0.236, ENE
AM282	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR, FINDS, ECHO	Lower	1247, 0.236, ENE
AM283	CON ED	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1247, 0.236, ENE
AM284	CON EDISON	HARRISON ST & FOUNTA	NJ MANIFEST	Lower	1247, 0.236, ENE
AM285	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1247, 0.236, ENE
AM286	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1247, 0.236, ENE
AM287	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1247, 0.236, ENE
AM288	CON EDISON	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1247, 0.236, ENE
AM289	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1247, 0.236, ENE
AM290	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1247, 0.236, ENE
AF291	MONROE COLLEGE	5 FRANKLIN AVE	NY LTANKS	Lower	1249, 0.237, East
AI292	CASANOVA BROS. REALT	370 NORTH AVENUE	NY UST	Lower	1253, 0.237, North
AC293	TANK TEST FAILURE	50 WALNUT ST	NY LTANKS	Higher	1264, 0.239, WSW
AO294	DOMENICO PROCOPIO	618 MAIN STREET	NY UST, NY AST	Lower	1279, 0.242, SSW
AO295	DOMENICO PROCOPIO PR	618 MAIN ST	NY LTANKS, NY Spills	Lower	1279, 0.242, SSW
AC296	ROBERTS HOME	58 WALNUT STREET	NY LTANKS	Higher	1281, 0.243, WSW
AP297	@	60 WALNUT STREET	NY LTANKS	Higher	1287, 0.244, West
AO298	VACANT	399 HUGUENOT STREET	NY UST, NY AST	Lower	1294, 0.245, SSW
AH299	FLAMINGO CLEANERS	149 NORTH AVE	RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Higher	1297, 0.246, SE
AH300	FLAMINGO/TYK CLEANER	149 NORTH AV.	NY DRYCLEANERS	Higher	1297, 0.246, SE
AH301	COLONIAL CLEANERS CO	149 NORTH AVE	RCRA NonGen / NLR	Higher	1297, 0.246, SE
AH302	OFF-SITE FLAMINGO CL	149 NORTH AVENUE	NY BROWNFIELDS	Higher	1297, 0.246, SE
AN303	MAY PARTNERS, LLC	35-45 MAY STREET	NY AST	Lower	1302, 0.247, NNW
AM304	FIREHOUSE	HARRISON ST	NY LTANKS	Lower	1329, 0.252, ENE
AL305	BERGMAN REALTY SERVI	140 HUGUENOT STREET	NY LTANKS	Lower	1351, 0.256, NE
AQ306	BLESSED SACREMENT CH	15 SHEA PL	NY LTANKS	Higher	1392, 0.264, South
AP307	APARTMENT BLDG.	114 UNION AVE.	NY LTANKS, NY Spills	Higher	1393, 0.264, West
AN308	DIMATTOE TTF	55 MAY STREET	NY LTANKS	Lower	1405, 0.266, NNW
309	CITY OF NEW ROCHELLE	1 HARRISON STREET	NY LTANKS	Lower	1411, 0.267, East
AO310	EXXON S/S	635 MAIN STREET	NY LTANKS, NY Spills	Lower	1419, 0.269, SSW
AR311	BLESSED SACREMENT SC	24 MAPLE AVE.	NY LTANKS, NY Spills	Higher	1424, 0.270, South
AS312	COMMERCIAL PROPERTY	38 LOCUST AVE	NY LTANKS	Higher	1439, 0.273, ESE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AS313	COMMERCIAL SITE	38 LOCUST AVE	NY LTANKS	Higher	1439, 0.273, ESE
AT314	SPILL NUMBER 0208792	386 NORTH AV	NY LTANKS	Lower	1448, 0.274, North
AU315	DEMELIA - TTF	95 WASHINGTON AVE	NY LTANKS	Higher	1449, 0.274, West
316	10 COMMERCE DRIVE RA	10 COMMERCE DRIVE	NY BROWNFIELDS	Lower	1461, 0.277, NNE
317	RESIDENCE	64 CHURCH ST	NY LTANKS	Lower	1483, 0.281, SE
AV318	CANDREA/GALLETTA RES	35 CHARLES ST	NY LTANKS	Higher	1516, 0.287, WSW
AP319	SPILL NUMBER 0007965	45 CHARLES ST	NY LTANKS	Higher	1531, 0.290, WSW
AW320	RUSH MANUFACTURING C	10-12 PINE CT	CORRACTS, RCRA-VSQG, NY Spills, FINDS, ECHO, NJ...	Lower	1535, 0.291, SW
AW321	GKIDS REALTY	10/12 PINE COURT	NY LTANKS	Lower	1535, 0.291, SW
AU322	BRAM REALTY	105 WASHINGTON AVE	NY LTANKS	Lower	1549, 0.293, West
AV323	MERLUCCI RESIDENCE	30 CHARLES STREET	NY LTANKS	Higher	1552, 0.294, WSW
AT324	KGM PROPERTY ASSOC.	394 N. AVE.	NY LTANKS	Lower	1553, 0.294, North
AT325	GETTY# 677	381 NORTH AVE	NY LTANKS, NY Spills	Lower	1573, 0.298, North
AS326	APT. BUILDING	55-59 LOCUST AVE.	NY LTANKS	Higher	1584, 0.300, ESE
AT327	KGM REALTY CO.	396 NORTH AVE.	NY LTANKS	Lower	1584, 0.300, North
AQ328	BLESSED SACRAMENT HS	24 SHEA PLACE	NY LTANKS	Higher	1612, 0.305, South
AQ329	BLESSED SACRAMENT HI	24 SHEA PLACE	NY LTANKS	Higher	1614, 0.306, South
AX330	BLESSED SACRAMENT CH	SHEA PLACE	NY LTANKS	Higher	1628, 0.308, SSE
331	FRANKA INC.	132-143 UNION AVE.	NY LTANKS	Higher	1642, 0.311, West
AY332	PROFESSIONAL BUILDIN	421 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	1642, 0.311, SSW
AX333	FAILED TANK TEST	156 CENTRE AVE	NY LTANKS	Higher	1650, 0.312, SSE
AX334	APARTMENT HOUSE	156 CENTRE AVE	NY LTANKS	Higher	1650, 0.312, SSE
AR335	A D VANDROFF	47 MAPLE AVENUE	NY LTANKS, NY Spills	Higher	1655, 0.313, South
AT336	DIPASQUALE PROPERTY	400 NORTH AVE	NY LTANKS	Lower	1673, 0.317, North
AS337	60-70 OWNERS CORP	60-70 LOCUST AVE	NY LTANKS, NY Spills	Higher	1681, 0.318, ESE
AS338	APARTMENT BUILDING	60-70 LOCUST AVE	NY LTANKS	Higher	1681, 0.318, ESE
AS339	COMMERCIAL USTS	60-70 LOCUST AVE	NY LTANKS	Higher	1681, 0.318, ESE
AW340	BAKERS PRIDE OVEN CO	30 PINE ST.	RCRA-LQG, NY SHWS, NY Spills, FINDS, ECHO, NY...	Lower	1691, 0.320, SW
341	SPILL 0106072 / PBS	370 MAIN ST	NY LTANKS	Lower	1719, 0.326, ENE
342	APARTMENT BUILDING	67-70 LOCUST AVE	NY LTANKS	Higher	1720, 0.326, ESE
AZ343	BUSINESS	88 GROVE AVE.	NY LTANKS	Higher	1750, 0.331, WSW
AZ344	COMMERCIAL BUILDING	88-90 GROVE AVE.	NY LTANKS	Higher	1750, 0.331, WSW
345	KLING	108 VAN GUILDER AVE	NY LTANKS, NY Spills	Lower	1764, 0.334, WNW
BA346	COMMERICAL BUILDING	405 NORTH AVE	NY LTANKS	Lower	1765, 0.334, North
AW347	PONSERELLA HOME	20 PINE STREET	NY LTANKS	Lower	1779, 0.337, SW
348	CON EDISON-CEDAR ST	ONE RAMADA PLAZA	EDR MGP	Lower	1791, 0.339, NE
349	CHURCH OF LATTER DAY	111 NORTH AVE	NY LTANKS	Lower	1796, 0.340, SE
AY350	SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	NY LTANKS	Lower	1836, 0.348, SSW
BA351	APARTMENT BLDG	1 THE BOULEVARD	NY LTANKS	Lower	1894, 0.359, North

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BA352	PRIVATE DWELLING	19 ROCHELLE PLACE	NY LTANKS	Lower	1913, 0.362, NNW
353	BUSINESS COMPLEX	55 WEBSTER AVE	NY LTANKS	Lower	1921, 0.364, SW
BB354	I-95 EXIT 16	OPP. 111 CEDAR ST.	NY LTANKS	Lower	1933, 0.366, NNE
BB355	PLASTIC WORKS	115 CEDAR ST	NY LTANKS	Lower	1934, 0.366, NNE
356	NICK MAZZA RESIDENCE	20 DAVIS AVE	NY LTANKS	Lower	1940, 0.367, SSE
BC357	SHERIDEN PLAZA	1 SHERIDEN PLAZA	NY LTANKS	Lower	1953, 0.370, NE
BD358	JASON PARTNERS LTD	675 MAIN ST	NY LTANKS	Lower	1968, 0.373, SSW
BE359	ABANDONED GAS STATIO	197 WEBSTER AV	NY LTANKS	Lower	1986, 0.376, West
BC360	MUTUAL BISCUIT COMPA	65 RIVER ST.	NY LTANKS, NY Spills	Lower	1999, 0.379, NE
BF361	GETTY 58114	340 MAIN STREET	NY LTANKS, NY Spills	Lower	2004, 0.380, ENE
362	SUNOCO	71 HUGUENOT ST	NY LTANKS, NY Spills	Lower	2015, 0.382, ENE
BD363	6 WEBSTER	6 WEBSTER AVE	NY LTANKS	Lower	2025, 0.384, SSW
BG364	SPILL NUMBER 0314082	136 VANGUILDER AVE	NY LTANKS	Lower	2035, 0.385, WNW
BH365	STEWART DWELLING	100 SICKLES AVE	NY LTANKS, NY Spills	Lower	2043, 0.387, NW
BE366	MAR-LAP SVC CNTR	210 WEBSTER AVE	NY LTANKS, NY Spills	Lower	2087, 0.395, West
367	SPILL NUMBER 0302495	85 NORTH AVE	NY LTANKS, NY Spills	Lower	2094, 0.397, SE
BH368	BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NY LTANKS	Lower	2094, 0.397, NW
BF369	JEROME RESIDENCE	33 ECHO AVE	NY LTANKS	Lower	2095, 0.397, ENE
BI370	MICELI HOME	194 CENTRE AVE	NY LTANKS	Lower	2096, 0.397, SSE
BF371	POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	NY LTANKS	Lower	2108, 0.399, ENE
BH372	POINVIL RESIDENCE	107 SICKLES AVE	NY LTANKS	Lower	2110, 0.400, NW
BD373	AMOCO SERVICE STATIO	690 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	2128, 0.403, SSW
BJ374	RESIDENCE	10 LAFAYETTE ST	NY LTANKS	Lower	2129, 0.403, East
BG375	YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	NY LTANKS	Lower	2129, 0.403, WNW
BK376	COMMERCIAL-TTF	172 UNION AVE	NY LTANKS	Lower	2131, 0.404, West
BH377	TAHIR RESIDENCE	112 SICKLES AVE	NY LTANKS, NY Spills	Lower	2144, 0.406, NW
BF378	SCOT S/S	44 ECHO AVENUE	NY LTANKS, NY Spills	Lower	2148, 0.407, ENE
BF379	GAS STATION	44 ECHO AVE	NY LTANKS	Lower	2148, 0.407, ENE
BJ380	GONCALVES RESIDENCE	1 LAFFAYETTE STREET	NY LTANKS	Lower	2152, 0.408, East
BI381	200 CENTRA CORP	200 CENTER AVE	NY LTANKS	Lower	2173, 0.412, SSE
BF382	CONSOLIDATED EDISON	ECHO AVENUE	NY SHWS	Lower	2175, 0.412, ENE
BK383	FIRST ASSEMBLY OF GO	177 UNION AVE	NY LTANKS	Lower	2184, 0.414, West
384	48 1ST STREET	48 1ST STREET	NY LTANKS	Lower	2192, 0.415, WSW
BJ385	GONCALVES RESIDENCE	1 LAFAYETTE STREET	NY LTANKS	Lower	2193, 0.415, East
BH386	RESIDENCE	7 PRINCE ST	NY LTANKS	Lower	2195, 0.416, NW
BL387	TROY RESIDENCE	150 LOCKWOOD AV	NY LTANKS, NY Spills	Lower	2202, 0.417, WNW
BH388	RENTAL HOUSE	119 SICKLES AVE.	NY LTANKS	Lower	2218, 0.420, NW
BM389	SPILL NUMBER 0104402	30 LINCOLN ST	NY LTANKS	Lower	2245, 0.425, NE
BK390	SPILL NUMBER 0210366	182 UNION AV	NY LTANKS	Lower	2251, 0.426, West

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BI391	APT. BUILDING	208 CENTER AVE.	NY LTANKS, NY Spills	Lower	2275, 0.431, SSE
BM392	SPILL NUMBER 0300463	52 LINCOLN ST	NY LTANKS, NY Spills	Lower	2277, 0.431, NE
BN393	DEFENDER MARINE SUPP	309 MAIN ST	NY LTANKS	Lower	2310, 0.438, ENE
BO394	SPILL NUMBER 0009195	17 POPLAR PL	NY LTANKS	Lower	2315, 0.438, SSE
BI395	RESIDENCE	6 POPLAR ROAD	NY LTANKS	Lower	2319, 0.439, SSE
396	WALTON RESIDENCE	129 SICKLES AVE	NY LTANKS	Lower	2333, 0.442, NW
397	LIPMAN RESIDENCE	54 LIBERTY AVE	NY LTANKS	Lower	2333, 0.442, South
398	FIUMFREDO RESIDENCE	12 BAYVIEW AVE	NY LTANKS	Lower	2341, 0.443, East
BN399	TELEDYNE HYDRA-POWER	310 MAIN ST	NY SWF/LF, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	2342, 0.444, ENE
400	WILLIAMS TTF	23 1ST ST	NY LTANKS	Lower	2360, 0.447, WSW
401	RESIDENCE	38 BEECHWOOD AVE	NY LTANKS	Lower	2367, 0.448, SW
BO402	FUNICELOLO HOME	24 POPLAR PLACE	NY LTANKS	Lower	2374, 0.450, SSE
BO403	LABELLA RESIDENCE	219 CENTRE AVE	NY LTANKS	Lower	2395, 0.454, SSE
404	SPILL NUMBER 0210080	196 UNION AV	NY LTANKS	Lower	2421, 0.459, West
BP405	RESIDENCE	98 LIBERTY AVE	NY LTANKS	Lower	2425, 0.459, South
BL406	MANONE PLACE	15 COLONIAL PLACE	NY LTANKS	Lower	2437, 0.462, WNW
407	TRINITY ARMS APARTME	25 TRINITY PLACE	NY LTANKS	Lower	2461, 0.466, SSE
BQ408	SPILL NUMBER 9814027	48 REMINGTON PL	NY LTANKS	Lower	2484, 0.470, NW
409	RITACCO HOME	24 JACKSON STREET	NY LTANKS	Lower	2487, 0.471, ENE
410	CON EDISON - ECHO AV	ECHO AVENUE	SEMS-ARCHIVE, RCRA-VSQG, NY Spills, NY MANIFEST	Lower	2502, 0.474, East
411	COMMERICAL BUILIDING	719 MAIN ST	NY LTANKS	Lower	2524, 0.478, SSW
BP412	SPILL NUMBER 9803423	106 LIBERTY AV	NY LTANKS	Lower	2546, 0.482, South
413	TTF AT RESIDENCE	68 JACKSON ST	NY LTANKS	Lower	2555, 0.484, NE
BP414	COLLEGE OF NEW ROCHE	103 LIBERTY AVE	NY LTANKS	Lower	2564, 0.486, South
415	CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	NY LTANKS	Lower	2564, 0.486, SE
BR416	FORMER MANCUSO MARIN	HUNTINGTON PLACE	US BROWNFIELDS	Lower	2567, 0.486, ENE
BR417	NELSTAD MATERIAL COR	40 HUNTINGTON PL	NY LTANKS, NY Spills, NY SPDES	Lower	2570, 0.487, ENE
BP418	BLANCO RESIDENCE	30 LINDEN PLACE	NY LTANKS	Lower	2574, 0.488, South
419	NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	NY SWF/LF	Lower	2584, 0.489, SW
420	7-UP BOTTLING CO	PALMER AVE & CEDAR S	NY LTANKS	Lower	2584, 0.489, NNE
BS421	NORTH EVARTS	44 NORTH EVARTS AVE	NY LTANKS	Lower	2584, 0.489, SE
BQ422	HERNANDEZ - TTF	70 REMINGTON PLACE	NY LTANKS	Higher	2585, 0.490, NW
BS423	RESIDENCE APT BLD	45 NORTH AVE	NY LTANKS	Lower	2587, 0.490, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF UST ---- Major Oil Storage Facilities Database
NY MOSF ---- Major Oil Storage Facility Site Listing
NY MOSF AST ---- Major Oil Storage Facilities Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing
NY ENG CONTROLS ---- Registry of Engineering Controls
NY INST CONTROL ---- Registry of Institutional Controls

State and tribal voluntary cleanup sites

NY VCP ---- Voluntary Cleanup Agreements
INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---- Registered Waste Tire Storage & Facility List
NY SWRCY ---- Registered Recycling Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register
NY PFAS ---- PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database

NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
NY LEAD ---- Lead-based Paint Testing Results
MINES MRDS ---- Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 07/29/2020 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - ECHO AV Site ID: 0202659 EPA Id: NYD981141252	***ECHO AVENUE***	***E 1/4 - 1/2 (0.474 mi.)***	***410***	***766***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/23/2020 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSH MANUFACTURING C	***10-12 PINE CT***	***SW 1/4 - 1/2 (0.291 mi.)***	***AW320***	***567***

EPA ID:: NYD075436394

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/23/2020 has revealed that there are 6 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO EPA ID:: NYP004353199	DIVISION ST AND HUGE	S 0 - 1/8 (0.009 mi.)	B13	22
CON EDISON - TRANSFO EPA ID:: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P128	208
FLAMINGO CLEANERS EPA ID:: NYD012946885	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH299***	***525***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.138 mi.)***	***K155***	***245***
NYS THRUWAY AUTHORIT EPA ID:: NYD986963445	***I-95 AT MP 605.76 NO***	***N 1/8 - 1/4 (0.148 mi.)***	***U172***	***277***
NYSDEC-SITE 360109 I EPA ID:: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.155 mi.)***	***O189***	***309***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/23/2020 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL EPA ID:: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ234***	***404***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW ROCHELLE CITY OF EPA ID:: NYR000244764	24 STATION PLZ N	NNW 0 - 1/8 (0.057 mi.)	F49	69

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 03/23/2020 has revealed that there are 3 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #8447 EPA ID:: NYR000194654	***222 NORTH AVE***	***E 0 - 1/8 (0.098 mi.)***	***J77***	***112***
SIMONETTI CLEANERS EPA ID:: NYD982531634	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***I95***	***154***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLERS CLEANERS EPA ID:: NYD012950770	***360 NORTH AVE***	***N 1/8 - 1/4 (0.211 mi.)***	***AI232***	***397***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/12/2020 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL Site Code: 413917	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.155 mi.)***	***O186***	***303***
BAKERS PRIDE OVEN CO Site Code: 355304	***30 PINE ST.***	***SW 1/4 - 1/2 (0.320 mi.)***	***AW340***	***620***
CONSOLIDATED EDISON Site Code: 56077	ECHO AVENUE	ENE 1/4 - 1/2 (0.412 mi.)	BF382	722

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 04/03/2020 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELEDYNE HYDRA-POWER	***310 MAIN ST***	***ENE 1/4 - 1/2 (0.444 mi.)***	***BN399***	***747***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW ROCHELLE LEAF TS	85 BEECHWOOD AVE	SW 1/4 - 1/2 (0.489 mi.)	419	785

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/12/2020 has revealed that there are 164 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VACANT LOT Spill Number/Closed Date: 0510542 / 2006-03-15 Site ID: 356539 Spill Date: 2005-12-08	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B20	30
SHORELINE OIL Spill Number/Closed Date: 8709425 / 1988-04-06 Site ID: 83347 Spill Date: 1988-02-03	296 HUGENOT ST,REAR	SSW 0 - 1/8 (0.033 mi.)	B21	32
LILLIAN VERNON CO. Spill Number/Closed Date: 9213055 / 1995-03-16 Site ID: 201286 Spill Date: 1993-02-22	WESTCHESTER PLACE	S 0 - 1/8 (0.034 mi.)	B22	33
JONES RESIDENCE Spill Number/Closed Date: 0410335 / 2005-09-11 Site ID: 335236 Spill Date: 2004-12-17	311 HUGUENOT STREET	SSW 0 - 1/8 (0.045 mi.)	B28	39
MAIN LIBRARY Spill Number/Closed Date: 9713843 / 1998-03-27 Site ID: 273025 Spill Date: 1998-03-13	LAWTON ST	E 0 - 1/8 (0.045 mi.)	C29	41
LAWTON STREET REALTY Spill Number/Closed Date: 1706064 / 2019-02-15 Spill Number/Closed Date: 1605726 / 2019-02-15 Site ID: 560365 Site ID: 532284 Spill Date: 2017-09-21 Spill Date: 2016-09-07	41-43 LAWTON ST	ESE 0 - 1/8 (0.055 mi.)	C43	63
NORTH AVE REALITY Spill Number/Closed Date: 8803214 / 1989-11-30 Spill Number/Closed Date: 9812584 / 1999-07-12 Spill Number/Closed Date: 9812585 / 1999-07-12 Site ID: 68769 Site ID: 68770 Site ID: 68771 Spill Date: 1988-07-14	***5 ANDERSON ST***	***E 0 - 1/8 (0.084 mi.)***	***J72***	***102***

Spill Date: 1999-01-12				
COMM/RESIDENT. PROPE	15 DIVISION STREET	SSE 0 - 1/8 (0.088 mi.)	G75	109
Spill Number/Closed Date: 9405558 / 2005-02-10				
Site ID: 119901				
Spill Date: 1994-07-25				
NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	ESE 0 - 1/8 (0.092 mi.)	J76	111
Spill Number/Closed Date: 9111450 / 1992-02-06				
Site ID: 306853				
Spill Date: 1992-02-06				
APARTMENT BLDG	54 CENTRE AVE	SSW 0 - 1/8 (0.101 mi.)	I84	125
Spill Number/Closed Date: 0206558 / 2005-02-27				
Spill Number/Closed Date: 0403405 / 2004-12-10				
Site ID: 254563				
Site ID: 84302				
Spill Date: 2002-09-06				
Spill Date: 2004-06-29				
COMMERCIAL PROPERTY	64 CENTRE AVE	S 0 - 1/8 (0.111 mi.)	I98	160
Spill Number/Closed Date: 1308480 / 2015-04-28				
Site ID: 489220				
Spill Date: 2013-11-20				
TRUMP PLAZA	***175 HUGUENOT STREET***	***NE 0 - 1/8 (0.115 mi.)***	***N109***	***180***
Spill Number/Closed Date: 0512575 / 2006-03-08				
Site ID: 358910				
Spill Date: 2006-01-29				
NYNEX LOCATION	342 HUEGNOT ST	SSW 0 - 1/8 (0.115 mi.)	I110	183
Spill Number/Closed Date: 9708146 / 1997-10-10				
Site ID: 270876				
Spill Date: 1997-10-10				
CATHOLIC NEWS PUBLIS	210 NORTH AVE	ESE 0 - 1/8 (0.120 mi.)	J118	195
Spill Number/Closed Date: 0503023 / 2005-08-28				
Site ID: 347516				
Spill Date: 2005-06-13				
BLUE GILL REALTY	***543 MAIN ST***	***SSE 0 - 1/8 (0.123 mi.)***	***P125***	***203***
Spill Number/Closed Date: 0308082 / 2004-05-12				
Site ID: 94435				
Spill Date: 2003-07-14				
CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	S 1/8 - 1/4 (0.125 mi.)	R133	214
Spill Number/Closed Date: 0311823 / 2004-12-30				
Site ID: 149369				
Spill Date: 2004-01-21				
COMMERCIAL PROPERTY	522 MAIN STREET	SSE 1/8 - 1/4 (0.128 mi.)	P137	222
Spill Number/Closed Date: 1100723 / 2011-06-06				
Site ID: 448142				
Spill Date: 2011-04-20				
OFFICE BLDG	542 MAIN STREET	SSE 1/8 - 1/4 (0.130 mi.)	P141	225
Spill Number/Closed Date: 0509995 / 2006-03-22				
Site ID: 355877				
Spill Date: 2005-11-21				
COMMERCIAL BUILDING	507 MAIN STREET	SE 1/8 - 1/4 (0.130 mi.)	S142	226
Spill Number/Closed Date: 9110835 / 1992-03-10				
Site ID: 286303				

Spill Date: 1992-01-17				
COCO RESIDENCE Spill Number/Closed Date: 0311339 / 2005-01-10 Site ID: 313391 Spill Date: 2004-01-07	81 CENTRE AVE	S 1/8 - 1/4 (0.133 mi.)	R148	237
BARCLAYS BANK OF NY/ Spill Number/Closed Date: 8905129 / 1991-03-25 Site ID: 299548 Spill Date: 1989-08-23	491 MAIN ST.	SE 1/8 - 1/4 (0.141 mi.)	S164	261
NEW ROCHELLE PUBLIC Spill Number/Closed Date: 1311408 / Not Reported Spill Number/Closed Date: 0201697 / 2002-09-18 Site ID: 492304 Site ID: 306611 Spill Date: 2014-03-06 Spill Date: 2002-05-15	1 LAWTON	SE 1/8 - 1/4 (0.142 mi.)	S166	265
CASARRA RESIDENCE Spill Number/Closed Date: 0209171 / 2003-02-05 Site ID: 157707 Spill Date: 2002-12-06	9 BADEAU PL	W 1/8 - 1/4 (0.164 mi.)	V192	319
NYNEX Spill Number/Closed Date: 8803234 / 1988-07-22 Site ID: 60528 Spill Date: 1988-07-14	40 WASHINGTON AVE	WNW 1/8 - 1/4 (0.174 mi.)	Y195	322
RESIDENCE Spill Number/Closed Date: 9609269 / 1996-10-24 Site ID: 177416 Spill Date: 1996-10-24	18 BADEAU PLACE	W 1/8 - 1/4 (0.182 mi.)	V200	330
ST GABRIEL HIGH SCHO Spill Number/Closed Date: 1903323 / 2019-09-18 Site ID: 591279 Spill Date: 2019-07-01	***50 WASHINGTON AVE***	***WNW 1/8 - 1/4 (0.185 mi.)***	***Y202***	***334***
ST GABRIEL SCHOOL Spill Number/Closed Date: 0302359 / 2003-12-12 Site ID: 314440 Spill Date: 2003-06-05	50 WASHINGTON AVE	WNW 1/8 - 1/4 (0.185 mi.)	Y203	336
DIIORGI HOME Spill Number/Closed Date: 0500295 / 2005-08-28 Site ID: 343230 Spill Date: 2005-04-07	47 WARREN STREET	WSW 1/8 - 1/4 (0.189 mi.)	V209	350
APT BUILDING Spill Number/Closed Date: 0812107 / 2009-03-03 Spill Number/Closed Date: 0109254 / 2001-12-19 Site ID: 409713 Site ID: 150939 Spill Date: 2009-02-06 Spill Date: 2001-12-19	***40 WARREN STREET***	***WSW 1/8 - 1/4 (0.193 mi.)***	***AC213***	***357***
CITIZEN Spill Number/Closed Date: 8708588 / 1989-11-28 Site ID: 135309 Spill Date: 1988-01-07	33 GROVE ST	WSW 1/8 - 1/4 (0.202 mi.)	219	370
NEW ROCHELLE HOSPITA	COVION PLACE	NW 1/8 - 1/4 (0.211 mi.)	AJ233	402

Spill Number/Closed Date: 9003911 / 1991-03-15 Site ID: 136814 Spill Date: 1990-07-09				
SOUTH SHORE MED CENT Spill Number/Closed Date: 0512440 / 2006-12-19 Site ID: 358758 Spill Date: 2006-01-26	16 GUION PLACE	NW 1/8 - 1/4 (0.216 mi.)	AJ236	416
RESIDENCE Spill Number/Closed Date: 0510555 / 2006-03-28 Site ID: 356553 Spill Date: 2005-12-08	79 WARREN ST	W 1/8 - 1/4 (0.216 mi.)	238	420
66 MEMORIAL BLVD Spill Number/Closed Date: 0002907 / 2000-10-24 Site ID: 59397 Spill Date: 2000-06-08	66 MEMORIAL BLVD	NW 1/8 - 1/4 (0.216 mi.)	AJ239	421
CO-OP Spill Number/Closed Date: 9504589 / 1997-04-15 Site ID: 189169 Spill Date: 1995-07-17	30 CLINTON PLACE	SE 1/8 - 1/4 (0.228 mi.)	AH253	449
100-102 UNION AVENUE Spill Number/Closed Date: 9608199 / 1996-11-08 Site ID: 166425 Spill Date: 1996-10-01	100-102 UNION AVENUE	W 1/8 - 1/4 (0.232 mi.)	AC270	480
KAGEL HOME Spill Number/Closed Date: 0513684 / 2006-03-09 Site ID: 360201 Spill Date: 2006-02-27	99 UNION AVE	W 1/8 - 1/4 (0.233 mi.)	AC276	488
125 Spill Number/Closed Date: 0001835 / 2000-05-15 Site ID: 205498 Spill Date: 2000-05-12	CENTRE AVE	S 1/8 - 1/4 (0.233 mi.)	AG277	489
TANK TEST FAILURE Spill Number/Closed Date: 1107925 / 2013-02-05 Site ID: 455637 Spill Date: 2011-09-21	50 WALNUT ST	WSW 1/8 - 1/4 (0.239 mi.)	AC293	514
ROBERTS HOME Spill Number/Closed Date: 0608623 / 2012-08-17 Site ID: 372634 Spill Date: 2006-10-23	58 WALNUT STREET	WSW 1/8 - 1/4 (0.243 mi.)	AC296	520
@ Spill Number/Closed Date: 0502010 / 2005-07-17 Site ID: 346287 Spill Date: 2005-05-19	60 WALNUT STREET	W 1/8 - 1/4 (0.244 mi.)	AP297	521
BLESSED SACREMENT CH Spill Number/Closed Date: 0204856 / 2003-10-03 Site ID: 167332 Spill Date: 2002-08-07	15 SHEA PL	S 1/4 - 1/2 (0.264 mi.)	AQ306	542
APARTMENT BLDG. Spill Number/Closed Date: 9414493 / 1995-02-14 Spill Number/Closed Date: 0011198 / 2001-04-06 Site ID: 238808	***114 UNION AVE.***	***W 1/4 - 1/2 (0.264 mi.)***	***AP307***	***543***

Site ID: 151446 Spill Date: 1995-02-02 Spill Date: 2001-01-14				
BLESSED SACREMENT SC	***24 MAPLE AVE.***	***S 1/4 - 1/2 (0.270 mi.)***	***AR311***	***552***
Spill Number/Closed Date: 0204857 / 2003-10-03 Site ID: 80066 Spill Date: 2002-08-07				
COMMERCIAL PROPERTY	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AS312	555
Spill Number/Closed Date: 1213228 / 2013-02-04 Site ID: 476407 Spill Date: 2012-12-10				
COMMERCIAL SITE	38 LOCUST AVE	ESE 1/4 - 1/2 (0.273 mi.)	AS313	556
Spill Number/Closed Date: 0206043 / 2002-09-26 Spill Number/Closed Date: 0408593 / 2005-02-13 Site ID: 239569 Site ID: 333366 Spill Date: 2002-09-11 Spill Date: 2004-11-04				
DEMELIA - TTF	95 WASHINGTON AVE	W 1/4 - 1/2 (0.274 mi.)	AU315	559
Spill Number/Closed Date: 1406916 / 2015-04-14 Site ID: 500408 Spill Date: 2014-10-01				
CANDREA/GALLETTA RES	35 CHARLES ST	WSW 1/4 - 1/2 (0.287 mi.)	AV318	565
Spill Number/Closed Date: 1202322 / 2012-09-13 Site ID: 465083 Spill Date: 2012-06-07				
SPILL NUMBER 0007965	45 CHARLES ST	WSW 1/4 - 1/2 (0.290 mi.)	AP319	566
Spill Number/Closed Date: 0007965 / 2000-10-26 Site ID: 61314 Spill Date: 2000-10-06				
MERLUCCI RESIDENCE	30 CHARLES STREET	WSW 1/4 - 1/2 (0.294 mi.)	AV323	587
Spill Number/Closed Date: 1103221 / 2011-11-14 Site ID: 450778 Spill Date: 2011-06-22				
APT. BUILDING	55-59 LOCUST AVE.	ESE 1/4 - 1/2 (0.300 mi.)	AS326	597
Spill Number/Closed Date: 9200639 / 1992-06-26 Site ID: 168647 Spill Date: 1992-04-01				
BLESSED SACRAMENT HS	24 SHEA PLACE	S 1/4 - 1/2 (0.305 mi.)	AQ328	599
Spill Number/Closed Date: 1300960 / Not Reported Site ID: 481320 Spill Date: 2013-04-29				
BLESSED SACRAMENT HI	24 SHEA PLACE	S 1/4 - 1/2 (0.306 mi.)	AQ329	601
Spill Number/Closed Date: 0400709 / 2004-07-06 Site ID: 249284 Spill Date: 2004-04-21				
BLESSED SACRAMENT CH	SHEA PLACE	SSE 1/4 - 1/2 (0.308 mi.)	AX330	602
Spill Number/Closed Date: 8704259 / 1987-11-20 Site ID: 324974 Spill Date: 1987-08-02				
FRANKA INC.	132-143 UNION AVE.	W 1/4 - 1/2 (0.311 mi.)	331	604

Spill Number/Closed Date: 9312205 / 1995-11-09
Site ID: 176106
Spill Date: 1994-01-17

FAILED TANK TEST — 156 CENTRE AVE — SSE 1/4 - 1/2 (0.312 mi.) — AX333 — 607
Spill Number/Closed Date: 1308221 / 2019-08-14
Site ID: 488939
Spill Date: 2013-11-12

APARTMENT HOUSE — 156 CENTRE AVE — SSE 1/4 - 1/2 (0.312 mi.) — AX334 — 609
Spill Number/Closed Date: 0312650 / 2004-04-22
Site ID: 267104
Spill Date: 2004-02-13

A D VANDROFF — ***47 MAPLE AVENUE*** — ***S 1/4 - 1/2 (0.313 mi.)*** — ***AR335*** — ***610***
Spill Number/Closed Date: 9603128 / 1996-06-14
Site ID: 178537
Spill Date: 1996-06-05

60-70 OWNERS CORP — ***60-70 LOCUST AVE*** — ***ESE 1/4 - 1/2 (0.318 mi.)*** — ***AS337*** — ***614***
Spill Number/Closed Date: 1802312 / 2018-10-17
Site ID: 570894
Spill Date: 2018-05-29

APARTMENT BUILDING — 60-70 LOCUST AVE — ESE 1/4 - 1/2 (0.318 mi.) — AS338 — 617
Spill Number/Closed Date: 1602555 / 2018-06-26
Site ID: 528964
Spill Date: 2016-06-13

COMMERCIAL USTS — 60-70 LOCUST AVE — ESE 1/4 - 1/2 (0.318 mi.) — AS339 — 618
Spill Number/Closed Date: 1803271 / 2018-12-06
Site ID: 571898
Spill Date: 2018-06-25

APARTMENT BUILDING — 67-70 LOCUST AVE — ESE 1/4 - 1/2 (0.326 mi.) — 342 — 632
Spill Number/Closed Date: 1008207 / 2011-03-10
Site ID: 441682
Spill Date: 2010-11-04

BUSINESS — 88 GROVE AVE. — WSW 1/4 - 1/2 (0.331 mi.) — AZ343 — 633
Spill Number/Closed Date: 9411669 / 2010-04-28
Site ID: 172950
Spill Date: 1994-12-01

COMMERCIAL BUILDING — 88-90 GROVE AVE. — WSW 1/4 - 1/2 (0.331 mi.) — AZ344 — 635
Spill Number/Closed Date: 9411598 / 2010-04-28
Site ID: 113133
Spill Date: 1994-11-29

HERNANDEZ - TTF — 70 REMINGTON PLACE — NW 1/4 - 1/2 (0.490 mi.) — BQ422 — 788
Spill Number/Closed Date: 1411959 / 2015-06-16
Site ID: 505764
Spill Date: 2015-03-23

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST RIVER SAVINGS B Spill Number/Closed Date: 8912285 / 1991-01-16 Site ID: 271129 Spill Date: 1990-03-26	277 NORTH AVE.	NNE 0 - 1/8 (0.072 mi.)	H53	74
BUSINESS	277 NORTH AVENUE	NNE 0 - 1/8 (0.072 mi.)	H56	79

Spill Number/Closed Date: 0611580 / 2008-12-04
Site ID: 376243
Spill Date: 2007-01-18

277 NORTH LLC — 277 NORTH AVENUE — NNE 0 - 1/8 (0.072 mi.) — H57 — 80
Spill Number/Closed Date: 0611648 / 2008-12-04
Site ID: 376329
Spill Date: 2007-01-19

RESIDENCE — ***60 GRAND STREET*** — ***NNW 1/8 - 1/4 (0.142 mi.)*** — ***L165*** — ***262***
Spill Number/Closed Date: 0407555 / 2004-10-07
Site ID: 332054
Spill Date: 2004-10-07

GUIDANCE CENTER INC — 70 GRAND ST — NNW 1/8 - 1/4 (0.149 mi.) — L173 — 280
Spill Number/Closed Date: 9613894 / 1997-10-03
Site ID: 77017
Spill Date: 1997-02-26

INDUST OVERALL SERVI — 10 BARTELS PLACE — SW 1/8 - 1/4 (0.155 mi.) — O179 — 290
Spill Number/Closed Date: 1400928 / 2017-03-30
Site ID: 494186
Spill Date: 2014-04-28

RITZCOVAN - TTF — 22 BURLING LANE — NNW 1/8 - 1/4 (0.156 mi.) — 190 — 315
Spill Number/Closed Date: 1506693 / 2016-03-22
Site ID: 514123
Spill Date: 2015-09-22

THE MALL — MAIN STREET — E 1/8 - 1/4 (0.204 mi.) — AF220 — 372
Spill Number/Closed Date: 9010648 / 1991-01-04
Site ID: 326514
Spill Date: 1991-01-04

CITY OF NEW ROCHELLE — 45 HARRISON STREET — ENE 1/8 - 1/4 (0.231 mi.) — AM259 — 458
Spill Number/Closed Date: 0513733 / 2006-06-21
Site ID: 360263
Spill Date: 2006-02-28

HEALTH DEPT OFFICE — ***145 HUGUENOT ST*** — ***NE 1/8 - 1/4 (0.236 mi.)*** — ***AL278*** — ***490***
Spill Number/Closed Date: 8901038 / 1989-06-01
Site ID: 259815
Spill Date: 1989-05-02

MONROE COLLEGE — 5 FRANKLIN AVE — E 1/8 - 1/4 (0.237 mi.) — AF291 — 512
Spill Number/Closed Date: 0307536 / 2005-03-27
Site ID: 165556
Spill Date: 2003-10-16

DOMENICO PROCOPIO PR — ***618 MAIN ST*** — ***SSW 1/8 - 1/4 (0.242 mi.)*** — ***AO295*** — ***517***
Spill Number/Closed Date: 9809866 / 2004-03-30
Site ID: 278454
Spill Date: 1998-11-05

FIREHOUSE — HARRISON ST — ENE 1/4 - 1/2 (0.252 mi.) — AM304 — 539
Spill Number/Closed Date: 9713840 / 1998-03-27
Site ID: 252028
Spill Date: 1998-03-13

BERGMAN REALTY SERVI — 140 HUGUENOT STREET — NE 1/4 - 1/2 (0.256 mi.) — AL305 — 540
Spill Number/Closed Date: 0505137 / 2007-11-07
Site ID: 350100
Spill Date: 2005-07-28

DIMATTOE TTF — 55 MAY STREET — NNW 1/4 - 1/2 (0.266 mi.) — AN308 — 546

Spill Number/Closed Date: 1301890 / 2013-08-08
Site ID: 482303
Spill Date: 2013-05-23

CITY OF NEW ROCHELLE Spill Number/Closed Date: 0201696 / 2002-09-18 Site ID: 75380 Spill Date: 2002-05-15	1 HARRISON STREET	E 1/4 - 1/2 (0.267 mi.)	309	548
EXXON S/S Spill Number/Closed Date: 9206930 / 2005-03-11 Site ID: 140421 Spill Date: 1992-09-16	***635 MAIN STREET***	***SSW 1/4 - 1/2 (0.269 mi.)***	***AO310***	***549***
SPILL NUMBER 0208792 Spill Number/Closed Date: 0208792 / 2002-11-26 Site ID: 71430 Spill Date: 2002-11-25	386 NORTH AV	N 1/4 - 1/2 (0.274 mi.)	AT314	558
RESIDENCE Spill Number/Closed Date: 0408510 / 2008-05-01 Site ID: 333255 Spill Date: 2004-11-02	64 CHURCH ST	SE 1/4 - 1/2 (0.281 mi.)	317	563
GKIDS REALTY Spill Number/Closed Date: 0200337 / 2003-12-09 Site ID: 235436 Spill Date: 2002-04-10	10/12 PINE COURT	SW 1/4 - 1/2 (0.291 mi.)	AW321	584
BRAM REALTY Spill Number/Closed Date: 0902464 / 2010-02-01 Site ID: 414506 Spill Date: 2009-06-01	105 WASHINGTON AVE	W 1/4 - 1/2 (0.293 mi.)	AU322	586
KGM PROPERTY ASSOC. Spill Number/Closed Date: 9202033 / 1993-01-27 Site ID: 69270 Spill Date: 1992-05-12	394 N. AVE.	N 1/4 - 1/2 (0.294 mi.)	AT324	588
GETTY# 677 Spill Number/Closed Date: 0400912 / 2005-01-18 Site ID: 242546 Spill Date: 2004-04-27	***381 NORTH AVE***	***N 1/4 - 1/2 (0.298 mi.)***	***AT325***	***589***
KGM REALTY CO. Spill Number/Closed Date: 9201744 / 1993-01-27 Site ID: 89642 Spill Date: 1992-05-12	396 NORTH AVE.	N 1/4 - 1/2 (0.300 mi.)	AT327	598
PROFESSIONAL BUILDIN Spill Number/Closed Date: 0606014 / 2007-01-29 Site ID: 369299 Spill Date: 2006-08-23	***421 HUGUENOT STREET***	***SSW 1/4 - 1/2 (0.311 mi.)***	***AY332***	***605***
DIPASQUALE PROPERTY Spill Number/Closed Date: 1103122 / 2012-04-26 Site ID: 450672 Spill Date: 2011-06-20	400 NORTH AVE	N 1/4 - 1/2 (0.317 mi.)	AT336	612
SPILL 0106072 / PBS Spill Number/Closed Date: 0106072 / 2001-11-13 Site ID: 133647 Spill Date: 2001-09-07	370 MAIN ST	ENE 1/4 - 1/2 (0.326 mi.)	341	630
KLING	***108 VAN GUILDER AVE***	***WNW 1/4 - 1/2 (0.334 mi.)***	***345***	***636***

Spill Number/Closed Date: 0308565 / 2005-02-12 Site ID: 214235 Spill Date: 2003-11-13				
COMMERICAL BUILDING Spill Number/Closed Date: 1805047 / 2018-11-13 Site ID: 574752 Spill Date: 2018-08-08	405 NORTH AVE	N 1/4 - 1/2 (0.334 mi.)	BA346	639
PONSERELLA HOME Spill Number/Closed Date: 0500819 / 2005-05-22 Spill Number/Closed Date: 0413182 / 2005-05-22 Site ID: 343902 Site ID: 339043 Spill Date: 2005-04-20 Spill Date: 2005-03-18	20 PINE STREET	SW 1/4 - 1/2 (0.337 mi.)	AW347	641
CHURCH OF LATTER DAY Spill Number/Closed Date: 0403126 / 2004-09-21 Site ID: 266466 Spill Date: 2004-06-22	111 NORTH AVE	SE 1/4 - 1/2 (0.340 mi.)	349	643
SPILL NUMBER 9908602 Spill Number/Closed Date: 9908602 / 2000-09-14 Site ID: 283271 Spill Date: 1999-10-15	HUGUENOT ST & SOUTH	SSW 1/4 - 1/2 (0.348 mi.)	AY350	644
APARTMENT BLDG Spill Number/Closed Date: 9809315 / 1999-10-14 Site ID: 303319 Spill Date: 1998-10-26	1 THE BOULEVARD	N 1/4 - 1/2 (0.359 mi.)	BA351	646
PRIVATE DWELLING Spill Number/Closed Date: 0706958 / 2008-02-01 Site ID: 387568 Spill Date: 2007-09-24	19 ROCHELLE PLACE	NNW 1/4 - 1/2 (0.362 mi.)	BA352	647
BUSINESS COMPLEX Spill Number/Closed Date: 9912136 / 2000-05-11 Site ID: 86196 Spill Date: 2000-01-19	55 WEBSTER AVE	SW 1/4 - 1/2 (0.364 mi.)	353	648
I-95 EXIT 16 Spill Number/Closed Date: 9001240 / 1990-08-01 Site ID: 244221 Spill Date: 1990-05-02	OPP. 111 CEDAR ST.	NNE 1/4 - 1/2 (0.366 mi.)	BB354	650
PLASTIC WORKS Spill Number/Closed Date: 9812998 / 1999-02-22 Site ID: 163894 Spill Date: 1999-01-22	115 CEDAR ST	NNE 1/4 - 1/2 (0.366 mi.)	BB355	651
NICK MAZZA RESIDENCE Spill Number/Closed Date: 0000532 / 2000-04-20 Site ID: 211468 Spill Date: 2000-04-13	20 DAVIS AVE	SSE 1/4 - 1/2 (0.367 mi.)	356	652
SHERIDEN PLAZA Spill Number/Closed Date: 8909204 / 1990-03-07 Site ID: 80178 Spill Date: 1989-12-19	1 SHERIDEN PLAZA	NE 1/4 - 1/2 (0.370 mi.)	BC357	653
JASON PARTNERS LTD	675 MAIN ST	SSW 1/4 - 1/2 (0.373 mi.)	BD358	654

Spill Number/Closed Date: 0211105 / 2003-03-26
Site ID: 86967
Spill Date: 2003-02-05

ABANDONED GAS STATIO — 197 WEBSTER AV — W 1/4 - 1/2 (0.376 mi.) — BE359 — 655
Spill Number/Closed Date: 9707099 / 2001-07-19
Site ID: 231589
Spill Date: 1997-09-15

MUTUAL BISCUIT COMPA — 65 RIVER ST. — NE 1/4 - 1/2 (0.379 mi.) — BC360 — 657
Spill Number/Closed Date: 8707334 / 1988-02-18
Spill Number/Closed Date: 8708530 / 1988-02-18
Site ID: 286036
Site ID: 286037
Spill Date: 1987-11-25
Spill Date: 1988-01-05

GETTY 58114 — 340 MAIN STREET — ENE 1/4 - 1/2 (0.380 mi.) — BF361 — 661
Spill Number/Closed Date: 0913713 / 2010-04-29
Site ID: 426673
Spill Date: 2010-03-26

SUNOCO — 71 HUGUENOT ST — ENE 1/4 - 1/2 (0.382 mi.) — 362 — 671
Spill Number/Closed Date: 9514850 / 1996-07-26
Site ID: 255332
Spill Date: 1996-02-20

6 WEBSTER — 6 WEBSTER AVE — SSW 1/4 - 1/2 (0.384 mi.) — BD363 — 673
Spill Number/Closed Date: 0403816 / 2004-10-08
Site ID: 81655
Spill Date: 2004-07-09

SPILL NUMBER 0314082 — 136 VANGUILDER AVE — WNW 1/4 - 1/2 (0.385 mi.) — BG364 — 675
Spill Number/Closed Date: 0314082 / 2004-06-08
Site ID: 80232
Spill Date: 2004-03-25

STEWART DWELLING — 100 SICKLES AVE — NW 1/4 - 1/2 (0.387 mi.) — BH365 — 676
Spill Number/Closed Date: 1200264 / 2012-08-13
Site ID: 462885
Spill Date: 2012-04-10

MAR-LAP SVC CNTR — 210 WEBSTER AVE — W 1/4 - 1/2 (0.395 mi.) — BE366 — 679
Spill Number/Closed Date: 1311416 / 2017-04-06
Site ID: 492314
Spill Date: 2014-03-06

SPILL NUMBER 0302495 — 85 NORTH AVE — SE 1/4 - 1/2 (0.397 mi.) — 367 — 686
Spill Number/Closed Date: 0507677 / 2009-10-09
Spill Number/Closed Date: 0302495 / 2003-08-12
Site ID: 353132
Site ID: 114935
Spill Date: 2005-09-26
Spill Date: 2003-06-09

BRIEN-AMIE RESIDENCE — 105 SICKLES AVE — NW 1/4 - 1/2 (0.397 mi.) — BH368 — 689
Spill Number/Closed Date: 0304963 / 2004-02-02
Site ID: 219644
Spill Date: 2003-08-08

JEROME RESIDENCE — 33 ECHO AVE — ENE 1/4 - 1/2 (0.397 mi.) — BF369 — 690
Spill Number/Closed Date: 0405389 / 2005-02-13

Site ID: 235222
Spill Date: 2004-08-17

MICELI HOME — 194 CENTRE AVE — SSE 1/4 - 1/2 (0.397 mi.) — BI370 — 691
Spill Number/Closed Date: 0604103 / 2006-10-22
Site ID: 366997
Spill Date: 2006-07-13

POWERTEST,ECHO & MAI — 36 ECHO AVE @ MAIN S — ENE 1/4 - 1/2 (0.399 mi.) — BF371 — 692
Spill Number/Closed Date: 8709260 / 1988-02-11
Site ID: 283199
Spill Date: 1988-01-30

POINVIL RESIDENCE — 107 SICKLES AVE — NW 1/4 - 1/2 (0.400 mi.) — BH372 — 694
Spill Number/Closed Date: 1104844 / 2014-11-05
Site ID: 452458
Spill Date: 2011-07-28

AMOCO SERVICE STATIO — 690 MAIN ST — SSW 1/4 - 1/2 (0.403 mi.) — BD373 — 695
Spill Number/Closed Date: 0209490 / 2002-12-16
Spill Number/Closed Date: 0212950 / 2003-04-01
Spill Number/Closed Date: 8604411 / 1987-01-14
Site ID: 274754
Site ID: 274755
Site ID: 274757
Spill Date: 2002-12-16
Spill Date: 2003-03-31
Spill Date: 1986-10-08

RESIDENCE — 10 LAFAYETTE ST — E 1/4 - 1/2 (0.403 mi.) — BJ374 — 707
Spill Number/Closed Date: 0512638 / 2006-03-15
Site ID: 358990
Spill Date: 2006-02-01

YOUNG ADULT INSTITUT — 150 VAN GUILDER AVE — WNW 1/4 - 1/2 (0.403 mi.) — BG375 — 708
Spill Number/Closed Date: 0507808 / 2005-12-18
Site ID: 353295
Spill Date: 2005-09-29

COMMERCIAL-TTF — 172 UNION AVE — W 1/4 - 1/2 (0.404 mi.) — BK376 — 709
Spill Number/Closed Date: 1502358 / Not Reported
Site ID: 508618
Spill Date: 2015-06-02

TAHIR RESIDENCE — 112 SICKLES AVE — NW 1/4 - 1/2 (0.406 mi.) — BH377 — 710
Spill Number/Closed Date: 0610140 / 2007-10-24
Site ID: 374522
Spill Date: 2006-12-06

SCOT S/S — 44 ECHO AVENUE — ENE 1/4 - 1/2 (0.407 mi.) — BF378 — 713
Spill Number/Closed Date: 9201557 / 2006-02-17
Spill Number/Closed Date: 9210810 / 1995-02-09
Spill Number/Closed Date: 1001469 / 2010-11-01
Site ID: 130487
Site ID: 130489
Site ID: 434525
Spill Date: 1992-05-08
Spill Date: 1992-12-17
Spill Date: 2010-05-07

GAS STATION — 44 ECHO AVE — ENE 1/4 - 1/2 (0.407 mi.) — BF379 — 719

Spill Number/Closed Date: 1309599 / 2014-02-13
Site ID: 490405
Spill Date: 2014-01-02

GONCALVES RESIDENCE Spill Number/Closed Date: 9410991 / 1994-11-29 Site ID: 156301 Spill Date: 1994-11-17	1 LAFFAYETTE STREET	E 1/4 - 1/2 (0.408 mi.)	BJ380	720
200 CENTRA CORP Spill Number/Closed Date: 0604650 / 2007-12-12 Site ID: 367663 Spill Date: 2006-07-25	200 CENTER AVE	SSE 1/4 - 1/2 (0.412 mi.)	BI381	721
FIRST ASSEMBLY OF GO Spill Number/Closed Date: 1002183 / 2010-08-30 Site ID: 435290 Spill Date: 2010-05-26	177 UNION AVE	W 1/4 - 1/2 (0.414 mi.)	BK383	724
48 1ST STREET Spill Number/Closed Date: 9911183 / 1999-12-22 Site ID: 116893 Spill Date: 1999-12-22	48 1ST STREET	WSW 1/4 - 1/2 (0.415 mi.)	384	725
GONCALVES RESIDENCE Spill Number/Closed Date: 0609401 / 2007-01-10 Site ID: 373629 Spill Date: 2006-11-15	1 LAFAYETTE STREET	E 1/4 - 1/2 (0.415 mi.)	BJ385	726
RESIDENCE Spill Number/Closed Date: 0506424 / 2005-10-29 Site ID: 351640 Spill Date: 2005-08-24	7 PRINCE ST	NW 1/4 - 1/2 (0.416 mi.)	BH386	728
TROY RESIDENCE Spill Number/Closed Date: 0209497 / 2005-03-18 Site ID: 221207 Spill Date: 2002-12-16	***150 LOCKWOOD AV***	***WNW 1/4 - 1/2 (0.417 mi.)***	***BL387***	***729***
RENTAL HOUSE Spill Number/Closed Date: 9107320 / 1991-11-25 Site ID: 119461 Spill Date: 1991-10-08	119 SICKLES AVE.	NW 1/4 - 1/2 (0.420 mi.)	BH388	731
SPILL NUMBER 0104402 Spill Number/Closed Date: 0104402 / 2001-11-14 Site ID: 328750 Spill Date: 2001-07-24	30 LINCOLN ST	NE 1/4 - 1/2 (0.425 mi.)	BM389	732
SPILL NUMBER 0210366 Spill Number/Closed Date: 0210366 / 2003-03-03 Site ID: 282696 Spill Date: 2003-01-14	182 UNION AV	W 1/4 - 1/2 (0.426 mi.)	BK390	733
APT. BUILDING Spill Number/Closed Date: 9314003 / 1994-03-11 Spill Number/Closed Date: 9315255 / 1994-04-11 Site ID: 215702 Site ID: 215703 Spill Date: 1994-02-28 Spill Date: 1994-03-26	***208 CENTER AVE.***	***SSE 1/4 - 1/2 (0.431 mi.)***	***BI391***	***735***
SPILL NUMBER 0300463	***52 LINCOLN ST***	***NE 1/4 - 1/2 (0.431 mi.)***	***BM392***	***738***

Spill Number/Closed Date: 0300463 / 2003-04-14
Site ID: 202585
Spill Date: 2003-04-14

DEFENDER MARINE SUPP — 309 MAIN ST — ENE 1/4 - 1/2 (0.438 mi.) — BN393 — 740
Spill Number/Closed Date: 9806235 / 2002-09-19
Site ID: 93459
Spill Date: 1998-08-19

SPILL NUMBER 0009195 — 17 POPLAR PL — SSE 1/4 - 1/2 (0.438 mi.) — BO394 — 741
Spill Number/Closed Date: 0009195 / 2001-01-08
Site ID: 63217
Spill Date: 2000-11-09

RESIDENCE — 6 POPLAR ROAD — SSE 1/4 - 1/2 (0.439 mi.) — BI395 — 742
Spill Number/Closed Date: 0310014 / 2012-08-13
Site ID: 82997
Spill Date: 2003-11-25

WALTON RESIDENCE — 129 SICKLES AVE — NW 1/4 - 1/2 (0.442 mi.) — 396 — 743
Spill Number/Closed Date: 0703375 / 2007-08-28
Site ID: 383296
Spill Date: 2007-06-22

LIPMAN RESIDENCE — 54 LIBERTY AVE — S 1/4 - 1/2 (0.442 mi.) — 397 — 744
Spill Number/Closed Date: 0409061 / 2005-04-02
Site ID: 333699
Spill Date: 2004-11-16

FIUMFREDO RESIDENCE — 12 BAYVIEW AVE — E 1/4 - 1/2 (0.443 mi.) — 398 — 745
Spill Number/Closed Date: 1100096 / 2011-09-22
Site ID: 447470
Spill Date: 2011-04-04

WILLIAMS TTF — 23 1ST ST — WSW 1/4 - 1/2 (0.447 mi.) — 400 — 753
Spill Number/Closed Date: 9702187 / 1999-06-10
Site ID: 102476
Spill Date: 1997-05-20

RESIDENCE — 38 BEECHWOOD AVE — SW 1/4 - 1/2 (0.448 mi.) — 401 — 755
Spill Number/Closed Date: 9705244 / 1997-11-10
Site ID: 105369
Spill Date: 1997-07-31

FUNICELOLO HOME — 24 POPLAR PLACE — SSE 1/4 - 1/2 (0.450 mi.) — BO402 — 756
Spill Number/Closed Date: 0509719 / 2006-11-19
Site ID: 355533
Spill Date: 2005-11-14

LABELLA RESIDENCE — 219 CENTRE AVE — SSE 1/4 - 1/2 (0.454 mi.) — BO403 — 757
Spill Number/Closed Date: 0601959 / 2009-09-01
Site ID: 364328
Spill Date: 2006-05-23

SPILL NUMBER 0210080 — 196 UNION AV — W 1/4 - 1/2 (0.459 mi.) — 404 — 758
Spill Number/Closed Date: 0210080 / 2003-03-03
Site ID: 155360
Spill Date: 2003-01-06

RESIDENCE — 98 LIBERTY AVE — S 1/4 - 1/2 (0.459 mi.) — BP405 — 759
Spill Number/Closed Date: 0107187 / 2002-01-11
Site ID: 204562
Spill Date: 2001-10-11

MANONE PLACE — 15 COLONIAL PLACE — WNW 1/4 - 1/2 (0.462 mi.) — BL406 — 761

Spill Number/Closed Date: 0513004 / 2006-05-08 Site ID: 359413 Spill Date: 2006-02-09				
TRINITY ARMS APARTME Spill Number/Closed Date: 0811859 / 2009-04-22 Spill Number/Closed Date: 8905211 / 1992-07-30 Site ID: 409448 Site ID: 283512 Spill Date: 2009-01-30 Spill Date: 1989-08-12	25 TRINITY PLACE	SSE 1/4 - 1/2 (0.466 mi.)	407	762
SPILL NUMBER 9814027 Spill Number/Closed Date: 9814027 / 1999-02-19 Site ID: 80830 Spill Date: 1999-02-19	48 REMINGTON PL	NW 1/4 - 1/2 (0.470 mi.)	BQ408	764
RITACCO HOME Spill Number/Closed Date: 0600187 / 2006-07-28 Site ID: 362141 Spill Date: 2006-04-06	24 JACKSON STREET	ENE 1/4 - 1/2 (0.471 mi.)	409	765
COMMERICAL BUILIDING Spill Number/Closed Date: 0404182 / 2004-10-28 Site ID: 301693 Spill Date: 2004-07-19	719 MAIN ST	SSW 1/4 - 1/2 (0.478 mi.)	411	772
SPILL NUMBER 9803423 Spill Number/Closed Date: 9803423 / 1998-08-18 Site ID: 140786 Spill Date: 1998-06-17	106 LIBERTY AV	S 1/4 - 1/2 (0.482 mi.)	BP412	773
TTF AT RESIDENCE Spill Number/Closed Date: 0707955 / 2008-03-26 Site ID: 388761 Spill Date: 2007-10-20	68 JACKSON ST	NE 1/4 - 1/2 (0.484 mi.)	413	774
COLLEGE OF NEW ROCHE Spill Number/Closed Date: 9809357 / 2005-04-17 Site ID: 118985 Spill Date: 1998-10-26	103 LIBERTY AVE	S 1/4 - 1/2 (0.486 mi.)	BP414	775
CIUSSETELLI RESIDENC Spill Number/Closed Date: 0204230 / 2010-07-13 Site ID: 161898 Spill Date: 2002-07-22	4 FAIRVIEW PLACE	SE 1/4 - 1/2 (0.486 mi.)	415	776
NELSTAD MATERIAL COR Spill Number/Closed Date: 0208898 / 2004-05-03 Site ID: 200280 Spill Date: 2002-11-27	***40 HUNTINGTON PL***	***ENE 1/4 - 1/2 (0.487 mi.)***	***BR417***	***780***
BLANCO RESIDENCE Spill Number/Closed Date: 9802704 / 1998-07-30 Site ID: 227988 Spill Date: 1998-06-01	30 LINDEN PLACE	S 1/4 - 1/2 (0.488 mi.)	BP418	784
7-UP BOTTLING CO Spill Number/Closed Date: 9302874 / 1999-08-02 Site ID: 60684 Spill Date: 1993-06-02	PALMER AVE & CEDAR S	NNE 1/4 - 1/2 (0.489 mi.)	420	786
NORTH EVARTS	44 NORTH EVARTS AVE	SE 1/4 - 1/2 (0.489 mi.)	BS421	787

Spill Number/Closed Date: 9913333 / 2005-02-26
Site ID: 74554
Spill Date: 2000-02-24

RESIDENCE APT BLD — 45 NORTH AVE — SE 1/4 - 1/2 (0.490 mi.) — BS423 — 789
Spill Number/Closed Date: 1905688 / Not Reported
Site ID: 593733
Spill Date: 2019-08-30

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 39 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AVALON ON THE SOUND	HUGUENOT STREET AND	SSE 0 - 1/8 (0.007 mi.)	A5	10
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 3. Closed - Removed Id/Status:: 3-800626 Site Status: Unregulated: <1101 gal. PBS				
NEW ROCHELLE IRISH B	38 DIVISION STREET	S 0 - 1/8 (0.039 mi.)	B24	36
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 3. Closed - Removed Id/Status:: 3-600097 Site Status: Unregulated				
CERUSSI AND VERE	306 HUGUENOT ST	SSW 0 - 1/8 (0.051 mi.)	B39	59
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 0. Administratively closed Id/Status:: 3-078360 Site Status: Administratively Closed				
LAWTON STREET REALTY	41-43 LAWTON STREET	ESE 0 - 1/8 (0.055 mi.)	C44	65
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 3. Closed - Removed Id/Status:: 3-801435 Site Status: Unregulated				
ANDERSON DEVELOPMENT	5 ANDERSON STREET	E 0 - 1/8 (0.084 mi.)	J73	107
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 3. Closed - Removed Id/Status:: 3-185515 Site Status: Unregulated				
SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	SSW 0 - 1/8 (0.101 mi.)	I83	124
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020 Status: 1. In-Service Id/Status:: 3-169773 Site Status: Active				
RPM REALTY INC	9-15 DIVISION STREET	SSE 0 - 1/8 (0.102 mi.)	G86	129
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020				

Status: 3. Closed - Removed
Id/Status:: 3-166189
Site Status: Active

M.J. HACKER & SONS I | 64 CENTRE AVE | S 0 - 1/8 (0.111 mi.) | I99 | 161
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 8. Unregistered
Status: 3a. Closed - Prior to 04/1991
Id/Status:: 3-137979
Site Status: Unregulated

LILLIAN VERNON CORPO | 543-549 MAIN STREET | SSE 0 - 1/8 (0.123 mi.) | P124 | 203
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-600279
Site Status: Unregulated: <1101 gal. PBS

543 MAIN STREET | 543 MAIN STREET | SSE 0 - 1/8 (0.123 mi.) | P126 | 206
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-801106
Site Status: Unregulated: <1101 gal. PBS

75 CENTRE AVENUE LLC | 75 CENTRE AVENUE | S 1/8 - 1/4 (0.125 mi.) | R132 | 213
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-800240
Site Status: Active

MAISON 347 LLC | 347 HUGUENOT STREET | SSW 1/8 - 1/4 (0.129 mi.) | R139 | 224
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-502626
Site Status: Active

542 MAIN STREET LLC | 542 MAIN STREET | SSE 1/8 - 1/4 (0.130 mi.) | P140 | 224
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-800617
Site Status: Active

BLOOMINGDALE PARKING | 554 MAIN ST | S 1/8 - 1/4 (0.139 mi.) | 161 | 258
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-600330
Site Status: Unregulated: <1101 gal. PBS

BARON MANAGEMENT | 200 NORTH AVENUE | ESE 1/8 - 1/4 (0.139 mi.) | T162 | 259
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 0. Administratively closed
Id/Status:: 3-167843
Site Status: Administratively Closed

FORMER CHASE BANK BU | 491 MAIN STREET | SE 1/8 - 1/4 (0.141 mi.) | S163 | 260
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-164372
Site Status: Active

RETTNER MANAGEMENT C | 481 MAIN ST | ESE 1/8 - 1/4 (0.151 mi.) | T175 | 284
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020

Status: 0. Administratively closed
Status: 3. Closed - Removed
Id/Status:: 3-255033
Site Status: Unregulated

MISR REALTY, LLC | 573-579 MAIN STREET | S 1/8 - 1/4 (0.153 mi.) | R178 | 290
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-800238
Site Status: Active

STORAGE USA | 363 HUGUENOT STREET | SSW 1/8 - 1/4 (0.166 mi.) | W193 | 320
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-801137
Site Status: Administratively Closed

381-383 HUGUENOT LLC | 381 HUGUENOT STREET | SSW 1/8 - 1/4 (0.207 mi.) | W225 | 380
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 2. Temporarily out of service
Id/Status:: 3-802286
Site Status: Active

MONTEFIORE - NEW ROC | 16 GUION PLACE | NW 1/8 - 1/4 (0.216 mi.) | AJ235 | 409
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Status: 3. Closed - Removed
Status: 4. Closed - in place
Id/Status:: 3-123269
Site Status: Active

30 CLINTON PLACE OWN | 30 CLINTON PLACE | SE 1/8 - 1/4 (0.228 mi.) | AH254 | 450
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-078727
Site Status: Active

LJNJ ASSOCIATES | 100-102 UNION AVE | W 1/8 - 1/4 (0.232 mi.) | AC269 | 477
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 0. Administratively closed
Status: 3. Closed - Removed
Id/Status:: 3-601056
Site Status: Unregulated: <1101 gal. PBS

Lower Elevation	Address	Direction / Distance	Map ID	Page

KAUFMAN HUGUENOT COM | 271 NORTH AVENUE | NE 0 - 1/8 (0.054 mi.) | D41 | 61
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-183776
Site Status: Active

NORTH BROOK REALTY A | 270 NORTH AVENUE, SU | NNE 0 - 1/8 (0.062 mi.) | H51 | 72
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-600117
Site Status: Active

277 NR PRINCIPAL, LL | 277 NORTH AVENUE | NNE 0 - 1/8 (0.072 mi.) | H55 | 77
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020

Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-502049
Site Status: Active

ROCHELLE DELUXE TAXI | 10 STATION PLAZA SOU | N 0 - 1/8 (0.099 mi.) | K82 | 121
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Database: UST, Date of Government Version: 06/22/2020
Status: 3. Closed - Removed
Id/Status:: 3-600004
Site Status: Unregulated: <1101 gal. PBS

DEPOT PLACE LLC | 1 DEPOT PLACE | NNW 0 - 1/8 (0.105 mi.) | L89 | 131
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-801085
Site Status: Unregulated: <1101 gal. PBS

SPOKEN ARTS BUILDING | 310 NORTH AVENUE | N 0 - 1/8 (0.114 mi.) | K108 | 180
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-600705
Site Status: Unregulated: <1101 gal. PBS

NORTH GARDEN ASSOCIA | 309-311 NORTH AVENUE | N 0 - 1/8 (0.116 mi.) | K113 | 189
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-496928
Site Status: Active

4 STORY APARTMENT BU | 320 NORTH AVENUE | N 1/8 - 1/4 (0.127 mi.) | K136 | 221
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-600732
Site Status: Unregulated: <1101 gal. PBS

INDUSTRIAL OVERALL S | 10 BARTELLS PLACE | SW 1/8 - 1/4 (0.155 mi.) | O187 | 307
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 0. Administratively closed
Status: 3. Closed - Removed
Id/Status:: 3-025453
Site Status: Unregulated

DRIVE IT YOURSELF | 20 GARDEN STREET | NNE 1/8 - 1/4 (0.174 mi.) | X194 | 321
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-494380
Site Status: Unregulated

COTTAGE - GARDEN AUT | 30 GARDEN STREET | NNE 1/8 - 1/4 (0.197 mi.) | X215 | 362
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-802310
Site Status: Active

368 NORTH AVE MGMT C | 368 NORTH AVENUE | N 1/8 - 1/4 (0.233 mi.) | AI275 | 487
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-600272
Site Status: Unregulated: <1101 gal. PBS

GHP 145 HUGUENOT DEL | 145 HUGUENOT STREET | NE 1/8 - 1/4 (0.236 mi.) | AL280 | 499
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020

Status: 1. In-Service
Id/Status:: 3-497436
Site Status: Active

CASANOVA BROS. REALT | 370 NORTH AVENUE | N 1/8 - 1/4 (0.237 mi.) | AI292 | 514
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-800088
Site Status: Unregulated: <1101 gal. PBS

DOMENICO PROCOPIO | ***618 MAIN STREET*** | ***SSW 1/8 - 1/4 (0.242 mi.)*** | ***AO294*** | ***515***
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-800233
Site Status: Unregulated: <1101 gal. PBS

VACANT | ***399 HUGUENOT STREET*** | ***SSW 1/8 - 1/4 (0.245 mi.)*** | ***AO298*** | ***522***
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 4. Closed - in place
Id/Status:: 3-801616
Site Status: Unregulated

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 06/22/2020 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.155 mi.)***	***O186***	***303***

Facility Status: Unregulated/Closed
CBS Number: 3-000235

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 18 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
306 HUGUENOT STREET	306 HUGUENOT STREET	SSW 0 - 1/8 (0.051 mi.)	B38	58

Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-800236

MKM EQUITY, LLC | 230 NORTH AVENUE | E 0 - 1/8 (0.084 mi.) | J69 | 99
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
PBS Number: 3-600105

NORTH AVE REALITY | ***5 ANDERSON ST*** | ***E 0 - 1/8 (0.084 mi.)*** | ***J72*** | ***102***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 6. Closed - Work Permit Open

PBS Number: 3-185515

RPM REALTY INC | 9-15 DIVISION STREET | SSE 0 - 1/8 (0.102 mi.) | G87 | 130
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-166189

75 CENTRE AVENUE LLC | 75 CENTRE AVENUE | S 1/8 - 1/4 (0.125 mi.) | R132 | 213
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-800240

NEW ROCHELLE SUPERMA | 538 MAIN STREET | SSE 1/8 - 1/4 (0.129 mi.) | P138 | 223
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
PBS Number: 3-166995

587 MAIN STREET | 348 HUGUENOT STREET | SSW 1/8 - 1/4 (0.137 mi.) | R152 | 242
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
PBS Number: 3-802131

FORMER CHASE BANK BU | 491 MAIN STREET | SE 1/8 - 1/4 (0.141 mi.) | S163 | 260
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-164372

MISR REALTY, LLC | 573-579 MAIN STREET | S 1/8 - 1/4 (0.153 mi.) | R177 | 289
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-800238

MONTEFIORE - NEW ROC | 16 GUION PLACE | NW 1/8 - 1/4 (0.216 mi.) | AJ235 | 409
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Status: 3. Closed - Removed
PBS Number: 3-123269

35 CLINTON PLACE LLC | 35 CLINTON PLACE | SE 1/8 - 1/4 (0.218 mi.) | AH243 | 429
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-078646

30 CLINTON PLACE OWN | 30 CLINTON PLACE | SE 1/8 - 1/4 (0.228 mi.) | AH254 | 450
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Status: 1. In-Service
PBS Number: 3-078727

Lower Elevation	Address	Direction / Distance	Map ID	Page

KAUFMAN HUGUENOT COM | 271 NORTH AVENUE | NE 0 - 1/8 (0.054 mi.) | D41 | 61
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-183776

MAYCO, LLC | 18-20 MAY ST | NNW 1/8 - 1/4 (0.218 mi.) | AI244 | 429
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 1. In-Service
PBS Number: 3-175447

MONROE COLLEGE | 420 MAIN STREET | E 1/8 - 1/4 (0.223 mi.) | AF245 | 430
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020

Status: 0. Administratively closed
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-800251

DOMENICO PROCOPIO ***618 MAIN STREET*** ***SSW 1/8 - 1/4 (0.242 mi.)*** ***AO294*** ***515***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 0. Administratively closed
PBS Number: 3-800233

VACANT ***399 HUGUENOT STREET*** ***SSW 1/8 - 1/4 (0.245 mi.)*** ***AO298*** ***522***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
PBS Number: 3-801616

MAY PARTNERS, LLC 35-45 MAY STREET NNW 1/8 - 1/4 (0.247 mi.) AN303 538
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-600544

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	10 BARTELS PLACE	SW 1/8 - 1/4 (0.155 mi.)	O188	309

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/12/2020 has revealed that there are 9 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRE AVENUE DEVELO Site Code: 580085	33 CENTRE AVENUE	SSW 0 - 1/8 (0.106 mi.)	I91	135
14 LE COUNT STANDARD Site Code: 568962	14 LE COUNT PL, 455	E 1/8 - 1/4 (0.152 mi.)	T176	285
CHURCH-DIVISION STRE Site Code: 582599	26 SOUTH DIVISION ST	SSE 1/8 - 1/4 (0.187 mi.)	Z204	338
THE HUGUENOT Site Code: 544502	381-393 HUGUENOT STR	SSW 1/8 - 1/4 (0.207 mi.)	W226	382
FLAMINGO CLEANERS Site Code: 335220	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH299***	***525***
OFF-SITE FLAMINGO CL	149 NORTH AVENUE	SE 1/8 - 1/4 (0.246 mi.)	AH302	536

Site Code: 414661

Lower Elevation	Address	Direction / Distance	Map ID	Page
SCHMUCKLER'S DRY CLE Site Code: 551607	358-364 NORTH AVENUE	N 1/8 - 1/4 (0.207 mi.)	AI227	388
SCHMUCKLER'S DRY CLE Site Code: 357446	358-364 NORTH AVENUE	N 1/8 - 1/4 (0.207 mi.)	AI228	389
10 COMMERCE DRIVE RA Site Code: 591030	10 COMMERCE DRIVE	NNE 1/4 - 1/2 (0.277 mi.)	316	561

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 06/01/2020 has revealed that there is 1 US BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER MANCUSO MARIN ACRES property ID: 10127 Cleanup Completion Date: -	HUNTINGTON PLACE	ENE 1/4 - 1/2 (0.486 mi.)	BR416	778

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/12/2020 has revealed that there are 29 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Spill Date: 2008-12-09 Spill Number/Closed Date: 0810056 / 2010-05-04 Site ID: 407567	129 DIVISON ST	SSW 0 - 1/8 (0.006 mi.)	B4	9
UST Spill Date: 2000-02-04 Spill Number/Closed Date: 9912617 / 2000-04-04 Site ID: 254637	MEMORIAL HIGHWAY AND	SSE 0 - 1/8 (0.007 mi.)	A6	11
MH1204	HUGUENOT AVE/LAWTON	E 0 - 1/8 (0.018 mi.)	C18	28

Spill Date: 2000-02-09
Spill Number/Closed Date: 9912755 / 2000-02-14
Site ID: 262084

ROAD	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.031 mi.)	B19	29
Spill Date: 2006-08-29				
Spill Number/Closed Date: 0606187 / 2006-09-03				
Site ID: 369495				
PAVEMENT	41 LAWTON STREET	ESE 0 - 1/8 (0.055 mi.)	C45	66
Spill Date: 2012-07-23				
Spill Number/Closed Date: 1203965 / 2012-07-23				
Site ID: 466814				
LAWTON STREET REALTY	41-43 LAWTON ST	ESE 0 - 1/8 (0.055 mi.)	C46	67
Spill Date: 2018-10-29				
Spill Number/Closed Date: 1808090 / 2019-02-15				
Site ID: 578882				
CABLE	29 DIVISION STREET	S 0 - 1/8 (0.057 mi.)	G50	71
Spill Date: 2008-07-30				
Spill Number/Closed Date: 0804961 / 2008-07-30				
Site ID: 401965				
VINEK / KRACKO - UST	316 HUGUENOT ST	SSW 0 - 1/8 (0.070 mi.)	I52	73
Spill Date: 2018-06-12				
Spill Number/Closed Date: 1802819 / 2018-07-23				
Site ID: 571425				
CON EDISON	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.080 mi.)***	***G59***	***83***
Spill Date: 2008-07-30				
Spill Number/Closed Date: 0804960 / 2008-08-16				
Site ID: 401964				
CON ED STREET EXCAVA	NORTH AVE AND ANDERS	E 0 - 1/8 (0.080 mi.)	J65	93
Spill Date: 2019-09-05				
Spill Number/Closed Date: 1905834 / 2019-10-22				
Site ID: 593884				
CONCRETE FLOORING WI	230 NORTH AVENUE	E 0 - 1/8 (0.084 mi.)	J67	96
Spill Date: 2014-04-08				
Spill Number/Closed Date: 1400277 / 2018-07-10				
Site ID: 493512				
ST GABRIEL'S CHURCH	120 DIVISION ST	W 0 - 1/8 (0.087 mi.)	E74	108
Spill Date: 2019-09-17				
Spill Number/Closed Date: 1906243 / 2020-04-01				
Site ID: 594314				
CEMENT COURT YARD	54 CENTER AVE	SSW 0 - 1/8 (0.101 mi.)	I85	127
Spill Date: 1998-07-18				
Spill Date: 1999-10-04				
Spill Number/Closed Date: 9804849 / 2002-07-15				
Spill Number/Closed Date: 9908117 / 1999-10-04				
Site ID: 114515				
Site ID: 114516				
TRUMP PLAZA	***175 HUGUENOT STREET***	***NE 0 - 1/8 (0.115 mi.)***	***N109***	***180***
Spill Date: 2005-07-20				
Spill Date: 2005-12-19				
Spill Number/Closed Date: 0504821 / 2006-03-08				
Spill Number/Closed Date: 0510932 / 2005-12-19				

Site ID: 349739
Site ID: 356986

VERIZON | 342 HUGUENOT ST | SSW 0 - 1/8 (0.115 mi.) | I111 | 184
Spill Date: 2005-03-22
Spill Number/Closed Date: 0413326 / 2005-09-11
Site ID: 342403

APPAREL PLUS | 27 CENTRE AVE | SW 0 - 1/8 (0.118 mi.) | O114 | 189
Spill Date: 2014-01-14
Spill Number/Closed Date: 1309988 / 2014-01-14
Site ID: 490810

SPILL NUMBER 9900400 | 535 MAIN ST | SSE 0 - 1/8 (0.119 mi.) | P115 | 190
Spill Date: 1995-02-17
Spill Date: 1999-04-08
Spill Number/Closed Date: 9415294 / 1995-03-03
Spill Number/Closed Date: 9900400 / 1999-07-09
Site ID: 251083
Site ID: 81102

SIDNEY FURNITURE | 535 MAIN ST | SSE 0 - 1/8 (0.119 mi.) | P116 | 192
Spill Date: 2015-12-03
Spill Number/Closed Date: 1509029 / 2015-12-04
Site ID: 517634

NOVA REALTY - UST | 523 MAIN ST | SSE 0 - 1/8 (0.121 mi.) | P120 | 197
Spill Date: 2019-02-11
Spill Number/Closed Date: 1811358 / Not Reported
Site ID: 582291

BLUE GILL REALTY | 543 MAIN ST | SSE 0 - 1/8 (0.123 mi.) | P125 | 203
Spill Date: 1993-02-03
Spill Number/Closed Date: 9212475 / 2004-05-12
Site ID: 125220

Lower Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING Spill Date: 1990-11-28 Spill Number/Closed Date: 9009493 / 1991-05-07 Site ID: 220275	8-10 RAILROAD PLACE	0 - 1/8 (0.001 mi.)	A3	8
METRO NORTH TRACKS Spill Date: 2003-10-31 Spill Number/Closed Date: 0308130 / 2004-07-16 Site ID: 279322	EAST OF NEW ROCHELLE	WSW 0 - 1/8 (0.009 mi.)	A15	25
METRO NORTH TRAIN ST Spill Date: 1989-07-10 Spill Number/Closed Date: 8903573 / 1989-07-19 Site ID: 104107	NEW HAVEN LINE &R/R	WSW 0 - 1/8 (0.009 mi.)	A16	26
HUGUENOT AND NORTH A Spill Date: 2003-12-03 Spill Number/Closed Date: 0310260 / 2005-03-05 Site ID: 313618	HUGUENOT AND NORTH A	NE 0 - 1/8 (0.045 mi.)	D33	48
SPILL NUMBER 9803949 Spill Date: 1998-06-29 Spill Number/Closed Date: 9803949 / 1998-06-29	MILEPOST 5.5 SB I95	W 0 - 1/8 (0.048 mi.)	E36	55

Site ID: 166821				
COMMERCIAL BUILDING Spill Date: 2018-04-06 Spill Number/Closed Date: 1800222 / Not Reported Site ID: 568710	271 NORTH AVE	NE 0 - 1/8 (0.054 mi.)	D40	60
P&D TRANSPORT - HOT Spill Date: 2003-11-18 Spill Number/Closed Date: 0308809 / 2003-11-26 Site ID: 329742	I-95 NB @ MM 5.4	SW 0 - 1/8 (0.106 mi.)	M92	139
I-95 Spill Date: 1987-04-07 Spill Number/Closed Date: 8700158 / 1987-04-07 Site ID: 121121	I-95EB MP54	SW 0 - 1/8 (0.106 mi.)	M93	140
COMMERCIAL - UST Spill Date: 2017-10-06 Spill Number/Closed Date: 1706607 / 2018-04-05 Site ID: 560927	35 GRAND STREET	NNW 0 - 1/8 (0.120 mi.)	L119	196

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/23/2020 has revealed that there are 76 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004317285	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.009 mi.)***	***B9***	***15***
CON EDISON TRANSFORM EPA ID:: NYP004349395	DIVISION ST & HUGUEN	S 0 - 1/8 (0.009 mi.)	B14	24
NYSDOT BIN 1049890 EPA ID:: NYD987011897	DIVISION ST OVER MET	S 0 - 1/8 (0.009 mi.)	B17	27
ACCESSOCRAFT PRODUCT EPA ID:: NYR000014753	***48 LAWTON ST***	***ESE 0 - 1/8 (0.046 mi.)***	***C35***	***50***
FEDERAL PROPERTY MAI EPA ID:: NYR000163337	244 NORTH AVE SUITE	ENE 0 - 1/8 (0.055 mi.)	D47	68
CON EDISON EPA ID:: NYP004759452	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J62***	***89***
CON EDISON TRANSFORM EPA ID:: NYP004367611	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J64***	***91***
CON EDISON EPA ID:: NYP004760179	***230 NORTH AVE***	***E 0 - 1/8 (0.084 mi.)***	***J70***	***100***
CON EDISON	HUGUENOT ST & CENTRE	SSW 0 - 1/8 (0.099 mi.)	I79	118

EPA ID:: NYP004211728				
ERIC S TURNER & CO I EPA ID:: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I90***	***132***
CON EDISON MANHOLE 1 EPA ID:: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N100***	***164***
CON EDISON EPA ID:: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	N102	168
CON EDISON MANHOLE 1 EPA ID:: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N104***	***171***
CON EDISON TRANSFORM EPA ID:: NYP004365318	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O105***	***174***
CON EDISON TRANSFORM EPA ID:: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O106***	***176***
NEW YORK TELEPHONE C EPA ID:: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.115 mi.)***	***I112***	***186***
CON EDISON EPA ID:: NYP004788378	***LECOUNT PL & ANDERSO***	***ENE 0 - 1/8 (0.122 mi.)***	***Q122***	***200***
MR CHIMNEY CLEAN EPA ID:: NYD987011855	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.125 mi.)***	***O134***	***216***
CON EDISON EPA ID:: NYP004800058	***19 DIVISION ST & WAS***	***NW 1/8 - 1/4 (0.130 mi.)***	***143***	***227***
CON EDISON TRANSFORM EPA ID:: NYP004478517	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P144***	***229***
CON EDISON TRANSFORM EPA ID:: NYP004364576	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P145***	***231***
CON EDISON MANHOLE: EPA ID:: NYP004478624	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P146***	***233***
CON EDISON EPA ID:: NYP004772265	205 NORTH AVE	ESE 1/8 - 1/4 (0.135 mi.)	T149	238
CON EDISON EPA ID:: NYP004828044	***552 MAIN ST***	***S 1/8 - 1/4 (0.137 mi.)***	***P153***	***242***
CON EDISON EPA ID:: NYP004880023	565 MAIN ST	S 1/8 - 1/4 (0.143 mi.)	R167	268
ADREAN PRINTING CO EPA ID:: NY0000233981	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S169***	***270***
FIRST METRO SERVICES EPA ID:: NYR000022053	***357 HUGONOT ST***	***SSW 1/8 - 1/4 (0.150 mi.)***	***R174***	***282***
CON EDISON TRANSFORM EPA ID:: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R180***	***292***
CON EDISON EPA ID:: NYP004760815	***CENTRE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R182***	***296***
ROTH CLEANERS EPA ID:: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Z196***	***323***
CON EDISON TRANSFORM EPA ID:: NYP004464459	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD214***	***360***
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.197 mi.)***	***AD216***	***364***

EPA ID:: NYP004357059				
CON EDISON SERVICE B EPA ID:: NYP004517694	***CENTRE AVE & LEROY***	***S 1/8 - 1/4 (0.205 mi.)***	***AG221***	***373***
CON EDISON SERVICE B EPA ID:: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG223***	***376***
CON EDISON SERVICE B EPA ID:: NYP004442943	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AH224***	***378***
CON EDISON EPA ID:: NYP004157665	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.218 mi.)***	***242***	***426***
CON EDISON EPA ID:: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AD249***	***437***
CON EDISON MANHOLE: EPA ID:: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AD250***	***439***
PREFERRED CLEANERS EPA ID:: NYD050275254	***95 UNION AVE***	***W 1/8 - 1/4 (0.225 mi.)***	***AC251***	***442***
CON EDISON MANHOLE: EPA ID:: NYP004443198	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH260***	***459***
CON EDISON SERVICE B EPA ID:: NYP004452439	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH261***	***461***
COLONIAL CLEANERS CO EPA ID:: NYD982718058	149 NORTH AVE	SE 1/8 - 1/4 (0.246 mi.)	AH301	534

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYSDOT BIN 1091390 EPA ID:: NYD987019197	DIVISION ST OVER I 9	W 0 - 1/8 (0.035 mi.)	A23	34
CON EDISON EPA ID:: NYP004880056	***260 NORTH AVE***	***NE 0 - 1/8 (0.041 mi.)***	***D26***	***38***
CON EDISON TRANSFORM EPA ID:: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.045 mi.)***	***D30***	***42***
CON EDISON MANHOLE: EPA ID:: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.045 mi.)***	***D31***	***44***
CON EDISON MANHOLE: EPA ID:: NYP004419065	HUGENUOT ST & NORTH	NE 0 - 1/8 (0.045 mi.)	D34	49
US POSTAL SERVICE EPA ID:: NYR000106369	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D37***	***56***
CON EDISON MANHOLE: EPA ID:: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***H54***	***75***
CON EDISON MANHOLE: EPA ID:: NYP004364030	313 NORTH AVE FRONT	N 0 - 1/8 (0.124 mi.)	K131	212
CON EDISON MANHOLE: EPA ID:: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K156***	***248***
CON EDISON MANHOLE 4 EPA ID:: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K157***	***250***
CON EDISON MANHOLE: EPA ID:: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.138 mi.)***	***K158***	***252***
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K159***	***255***

EPA ID:: NYP004313615				
CON EDISON SERVICE B	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K160***	***256***
EPA ID:: NYP004463667				
PRO AUTO PARTS	***41 REYLEA PL***	***SSW 1/8 - 1/4 (0.148 mi.)***	***O171***	***274***
EPA ID:: NYR000016535				
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.156 mi.)***	***U191***	***317***
EPA ID:: NYP004307492				
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.182 mi.)***	***AB201***	***331***
EPA ID:: NYD986884732				
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***X205***	***341***
EPA ID:: NYD987034998				
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***U210***	***351***
EPA ID:: NYP004432886				
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB212***	***354***
EPA ID:: NYP004205654				
RUSH MFG CORP	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AE217***	***366***
EPA ID:: NYD981185051				
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK241***	***423***
EPA ID:: NYR000193854				
CON EDISON MANHOLE 1	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.225 mi.)***	***AL246***	***432***
EPA ID:: NYP004219570				
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AE252***	***445***
EPA ID:: NYR000040113				
CON EDISON	***45 HARRISON ST***	***ENE 1/8 - 1/4 (0.231 mi.)***	***AM258***	***456***
EPA ID:: NYP004758215				
CON EDISON TRANSFORM	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.232 mi.)***	***AI263***	***465***
EPA ID:: NYP004372751				
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI264***	***467***
EPA ID:: NYP004218356				
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI267***	***473***
EPA ID:: NYP004222626				
CON EDISON	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AI268	477
EPA ID:: NYP004838332				
CON EDISON	***HARRISON ST & CEDER***	***ENE 1/8 - 1/4 (0.233 mi.)***	***AM273***	***483***
EPA ID:: NYP004759924				
CON EDISON SERVICE B	***HARRISON AVE & CEDAR***	***ENE 1/8 - 1/4 (0.233 mi.)***	***AM274***	***485***
EPA ID:: NYP004347621				
LONGINES WITTNAUER W	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL279***	***495***
EPA ID:: NYD001317221				
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM281	500
EPA ID:: NYP004769477				
CON EDISON	***FOUNTAIN PL & HARRIS***	***ENE 1/8 - 1/4 (0.236 mi.)***	***AM282***	***501***
EPA ID:: NYP004758272				
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM285	505
EPA ID:: NYP004769345				

EXECUTIVE SUMMARY

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 06/08/2020 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREEN HEAVEN CLEANER Facility Id: 3-5510-00298	62 CENTRE AVE	SSW 0 - 1/8 (0.109 mi.)	I94	141
SPEEDY CLEANERS Facility Id: 3-5510-00344	***217 NORTH AVENUE***	***E 0 - 1/8 (0.113 mi.)***	***J107***	***178***
HANGERS CLEANERS Facility Id: 3-5510-00358	562-564 MAIN STREET	S 1/8 - 1/4 (0.147 mi.)	R170	273
ROTH CLEANERS Facility Id: 3-5510-00292	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Z196***	***323***
FLAMINGO/TYK CLEANER Facility Id: 3-5510-00335	149 NORTH AV.	SE 1/8 - 1/4 (0.246 mi.)	AH300	534

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANER	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	A1	8
STATION CLEANERS Facility Id: ---	1 DEPOT PLAZA #1	NNW 0 - 1/8 (0.105 mi.)	L88	130
SCHMUKLER'S CLEANERS Facility Id: 3-5510-00327	360 NORTH AVE.	N 1/8 - 1/4 (0.211 mi.)	AI231	397

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 100 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004151221	MEMORIAL HIGHWAY & H	SSE 0 - 1/8 (0.007 mi.)	A7	12
CON EDISON EPA ID: NYP004676847	DIVISION & HUGUENOT	S 0 - 1/8 (0.009 mi.)	B8	14
CON EDISON MANHOLE: EPA ID: NYP004317285	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.009 mi.)***	***B9***	***15***
CON ED EPA ID: NYP004353199	DIVISION ST & HUGENO	S 0 - 1/8 (0.009 mi.)	B10	18
CON EDISON EPA ID: NYP004677894	HUGENOT ST & DIVISIO	S 0 - 1/8 (0.009 mi.)	B11	19
CON EDISON EPA ID: NYP004677548	HUGENOT & DIVISION S	S 0 - 1/8 (0.009 mi.)	B12	21
ACCESSOCRAFT PRODUCT EPA ID: NYR000014753	***48 LAWTON ST***	***ESE 0 - 1/8 (0.046 mi.)***	***C35***	***50***
CON EDISON EPA ID: NYP004800058	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.080 mi.)***	***G59***	***83***
CON EDISON	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J60	86

EPA ID: NYP004683272				
CON EDISON EPA ID: NYP004709622	ANDERSON ST & NORTH	E 0 - 1/8 (0.080 mi.)	J61	87
CON EDISON TRANSFORM EPA ID: NYP004367611	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J64***	***91***
CON EDISON EPA ID: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J66	94
CON ED EPA ID: NYP004760179	230 NORTH AVE	E 0 - 1/8 (0.084 mi.)	J71	101
CVS PHARMACY #8447 EPA ID: NYR000194654	***222 NORTH AVE***	***E 0 - 1/8 (0.098 mi.)***	***J77***	***112***
CON EDISON EPA ID: NYP004677530	HUGENOT & CENTRE ST	SSW 0 - 1/8 (0.099 mi.)	I78	116
CON EDISON EPA ID: NYP004676839	CENTER & HUGUENOT	SSW 0 - 1/8 (0.099 mi.)	I80	118
CON EDISON EPA ID: NYP004332961	CENTRE AVE & HUGUENO	SSW 0 - 1/8 (0.099 mi.)	I81	120
ERIC S TURNER & CO I EPA ID: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I90***	***132***
SIMONETTI CLEANERS EPA ID: NYD982531634	***62 CENTRE ST***	***SSW 0 - 1/8 (0.109 mi.)***	***I95***	***154***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N100***	***164***
CON EDISON EPA ID: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	N103	169
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N104***	***171***
CON EDISON TRANSFORM EPA ID: NYP004365318	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O105***	***174***
CON EDISON TRANSFORM EPA ID: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.112 mi.)***	***O106***	***176***
NEW YORK TELEPHONE C EPA ID: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.115 mi.)***	***I112***	***186***
CON EDISON EPA ID: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.122 mi.)	Q123	201
CONSOLIDATED EDISON EPA ID: NYP004123873	DIVISION & MAIN	SSE 0 - 1/8 (0.123 mi.)	P127	207
CON EDISON EPA ID: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P129	210
MR CHIMNEY CLEAN EPA ID: NYD987011855	***32 RELYEA PL***	***SSW 1/8 - 1/4 (0.125 mi.)***	***O134***	***216***
MACYS EPA ID: NYP000890137	33 LE COUNT PLACE	ENE 1/8 - 1/4 (0.127 mi.)	Q135	219
CON EDISON TRANSFORM EPA ID: NYP004478517	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P144***	***229***
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P145***	***231***

EPA ID: NYP004364576				
CON EDISON MANHOLE: EPA ID: NYP004478624	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P146***	***233***
CON EDISON EPA ID: NYP004680070	MAIN ST & CHURCH ST	SE 1/8 - 1/4 (0.130 mi.)	P147	235
CON EDISON EPA ID: NYP004772265	205 NORTH AVE	ESE 1/8 - 1/4 (0.135 mi.)	T151	240
ADREAN PRINTING CO EPA ID: NY0000233981	***490 MAIN ST***	***SE 1/8 - 1/4 (0.147 mi.)***	***S169***	***270***
CON EDISON TRANSFORM EPA ID: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.155 mi.)***	***R180***	***292***
CON ED EPA ID: NYP004760815	CENTRE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	R183	297
CON EDISON EPA ID: NYP004658019	MAIN ST & CENTRE ST	S 1/8 - 1/4 (0.155 mi.)	R184	299
ROTH CLEANERS EPA ID: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Z196***	***323***
CONSOLIDATED EDISON EPA ID: NYP004124210	DIVISION ST & LEROY	SSE 1/8 - 1/4 (0.181 mi.)	Z197	327
CON EDISON EPA ID: NYP004677837	HUGENOT ST & COLUMBU	SSW 1/8 - 1/4 (0.188 mi.)	W206	345
CON EDISON EPA ID: NYP004677621	HUGENOT AVE & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	W207	347
CON EDISON EPA ID: NYP004687802	HUGUENOT ST & COLUMB	SSW 1/8 - 1/4 (0.188 mi.)	W208	348
CON EDISON TRANSFORM EPA ID: NYP004464459	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.196 mi.)***	***AD214***	***360***
CON EDISON TRANSFORM EPA ID: NYP004357059	***592 MAIN ST***	***S 1/8 - 1/4 (0.197 mi.)***	***AD216***	***364***
NYNEX EPA ID: NYP000932509	UNION AVENUE AND WAR	W 1/8 - 1/4 (0.201 mi.)	V218	369
CON EDISON EPA ID: NYP004517694	CENTRE AVE & LEROY	S 1/8 - 1/4 (0.205 mi.)	AG222	374
CON EDISON SERVICE B EPA ID: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.205 mi.)***	***AG223***	***376***
CON EDISON SERVICE B EPA ID: NYP004442943	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AH224***	***378***
SOUND SHORE MEDICAL EPA ID: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AJ234***	***404***
CON EDISON EPA ID: NYP004157665	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.218 mi.)***	***242***	***426***
CON EDISON EPA ID: NYP004674354	MAIN ST & MAPLE AVE	SSW 1/8 - 1/4 (0.225 mi.)	AD248	435
CON EDISON MANHOLE: EPA ID: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AD250***	***439***
PREFERRED CLEANERS	***95 UNION AVE***	***W 1/8 - 1/4 (0.225 mi.)***	***AC251***	***442***

EPA ID: NYD050275254				
CON EDISON EPA ID: NYP004710497	150 NORTH AV	SE 1/8 - 1/4 (0.229 mi.)	AH255	452
CON EDISON MANHOLE: EPA ID: NYP004443198	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH260***	***459***
CON EDISON SERVICE B EPA ID: NYP004452439	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH261***	***461***
FLAMINGO CLEANERS EPA ID: NYD012946885	***149 NORTH AVE***	***SE 1/8 - 1/4 (0.246 mi.)***	***AH299***	***525***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TRANSFORM EPA ID: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.045 mi.)***	***D30***	***42***
CON EDISON MANHOLE: EPA ID: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.045 mi.)***	***D31***	***44***
CON EDISON EPA ID: NYP004343786	NORTH AVE & HUGENOT	NE 0 - 1/8 (0.045 mi.)	D32	47
US POSTAL SERVICE EPA ID: NYR000106369	***255 NORTH AVE***	***ENE 0 - 1/8 (0.049 mi.)***	***D37***	***56***
CON EDISON MANHOLE: EPA ID: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.072 mi.)***	***H54***	***75***
CONSOLIDATED EDISON EPA ID: NYP004230322	F/O 277 NORTH AVE	NNE 0 - 1/8 (0.072 mi.)	H58	82
CONSOLIDATED EDISON EPA ID: NYP004230306	F/O 311 NORTH AVE	N 0 - 1/8 (0.120 mi.)	K117	193
CON EDISON - MANHOLE EPA ID: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.138 mi.)***	***K155***	***245***
CON EDISON MANHOLE: EPA ID: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K156***	***248***
CON EDISON MANHOLE 4 EPA ID: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K157***	***250***
CON EDISON MANHOLE: EPA ID: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.138 mi.)***	***K158***	***252***
CON EDISON SERVICE B EPA ID: NYP004463667	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K160***	***256***
PRO AUTO PARTS EPA ID: NYR000016535	***41 REYLEA PL***	***SSW 1/8 - 1/4 (0.148 mi.)***	***O171***	***274***
NYS THRUWAY AUTHORIT EPA ID: NYD986963445	***I-95 AT MP 605.76 NO***	***N 1/8 - 1/4 (0.148 mi.)***	***U172***	***277***
NYSDEC-SITE 360109 I EPA ID: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.155 mi.)***	***O189***	***309***
CON EDISON MANHOLE: EPA ID: NYP004307492	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.156 mi.)***	***U191***	***317***
CON ED-V14 EPA ID: NYP004028122	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.181 mi.)	AA198	329
CON ED-V37	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.181 mi.)	AA199	329

EPA ID: NYP004027967				
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.182 mi.)***	***AB201***	***331***
EPA ID: NYD986884732				
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***X205***	***341***
EPA ID: NYD987034998				
CON EDISON MANHOLE:	***350 NORTH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***U210***	***351***
EPA ID: NYP004432886				
CON EDISON	35 BARTELS PL	SW 1/8 - 1/4 (0.193 mi.)	AB211	353
EPA ID: NYP004744074				
CON EDISON	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.193 mi.)***	***AB212***	***354***
EPA ID: NYP004205654				
RUSH MFG CORP	***18 COLUMBUS AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***AE217***	***366***
EPA ID: NYD981185051				
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***N 1/8 - 1/4 (0.211 mi.)***	***AI232***	***397***
EPA ID: NYD012950770				
LEXINGTON CENTER FOR	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.217 mi.)***	***AK241***	***423***
EPA ID: NYR000193854				
CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NE 1/8 - 1/4 (0.225 mi.)	AL247	434
EPA ID: NYP004219572				
ALL AMERICAN SPORTS	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AE252***	***445***
EPA ID: NYD002182897				
EPA ID: NYR000040113				
CON EDISON	45 HARRISON ST	ENE 1/8 - 1/4 (0.231 mi.)	AM256	454
EPA ID: NYP004758215				
CON EDISON	OPP 20 LOCKWOOD AV	NNW 1/8 - 1/4 (0.232 mi.)	AN262	463
EPA ID: NYP004679965				
CON EDISON TRANSFORM	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.232 mi.)***	***AI263***	***465***
EPA ID: NYP004372751				
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI264***	***467***
EPA ID: NYP004218356				
CON EDISON	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AI265	470
EPA ID: NYP004838332				
CON EDISON MANHOLE 1	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI267***	***473***
EPA ID: NYP004222626				
CON ED	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.233 mi.)	AM271	481
EPA ID: NYP004759924				
CON EDISON SERVICE B	***HARRISON AVE & CEDAR***	***ENE 1/8 - 1/4 (0.233 mi.)***	***AM274***	***485***
EPA ID: NYP004347621				
LONGINES WITTNAUER W	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.236 mi.)***	***AL279***	***495***
EPA ID: NYD001317221				
CON ED	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AM283	502
EPA ID: NYP004759510				
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM287	507
EPA ID: NYP004769477				
CON EDISON	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AM288	508
EPA ID: NYP004758272				
CON EDISON	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM290	511

EPA ID: NYP004769345

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 3 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL Generator EPA Id: NYD075431502	16 GUION PL	NW 1/8 - 1/4 (0.216 mi.)	AJ237	417

Lower Elevation	Address	Direction / Distance	Map ID	Page
HNJ REALTY	358-364 N AVENUE	N 1/8 - 1/4 (0.207 mi.)	AI229	396
HNJ REALTY Generator EPA Id: NYD012950779	358-364 N AVE	N 1/8 - 1/4 (0.207 mi.)	AI230	396

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 25 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J63	90
CON EDISON EPA Id: NYP004760179	230 NORTH AVE	E 0 - 1/8 (0.084 mi.)	J68	98
ERIC S TURNER & CO I EPA Id: NYD002015402	***33-35 CENTRE AVE***	***SSW 0 - 1/8 (0.106 mi.)***	***I90***	***132***
CON EDISON MANHOLE 1 EPA Id: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N100***	***164***
CON EDISON EPA Id: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	N101	167
CON EDISON MANHOLE 1 EPA Id: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***N104***	***171***
CON EDISON EPA Id: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.122 mi.)	Q121	199
CON EDISON - TRANSFO EPA Id: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P130	211
CON EDISON EPA Id: NYP004772265	205 NORTH AVE	ESE 1/8 - 1/4 (0.135 mi.)	T150	239
CON EDISON EPA Id: NYP004828044	552 MAIN ST	S 1/8 - 1/4 (0.137 mi.)	P154	244
CON EDISON EPA Id: NYP004880023	565 MAIN ST	S 1/8 - 1/4 (0.143 mi.)	R168	269
CON EDISON	CENTRE & MAIN ST	S 1/8 - 1/4 (0.155 mi.)	R181	295

EPA Id: NYP004760815				
CON EDISON EPA Id: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.225 mi.)***	***AD249***	***437***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004880056	260 NORTH AVE	NE 0 - 1/8 (0.041 mi.)	D25	36
NYSDEC-SITE 360109 I EPA Id: NYR000208967	10 BARTELS PL	SW 1/8 - 1/4 (0.155 mi.)	O185	300
LEXINGTON CENTER FOR EPA Id: NYR000193854	3 COTTAGE PL	NNE 1/8 - 1/4 (0.217 mi.)	AK240	422
CON EDISON MANHOLE 1 EPA Id: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.225 mi.)***	***AL246***	***432***
CON EDISON EPA Id: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.231 mi.)	AM257	455
CON EDISON MANHOLE 1 EPA Id: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI264***	***467***
CON EDISON EPA Id: NYP004838332	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AI266	472
CON EDISON MANHOLE 1 EPA Id: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AI267***	***473***
CON EDISON EPA Id: NYP004759924	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.233 mi.)	AM272	482
CON EDISON EPA Id: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AM284	503
CON EDISON EPA Id: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM286	505
CON EDISON EPA Id: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AM289	510

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON-CEDAR ST	ONE RAMADA PLAZA	NE 1/4 - 1/2 (0.339 mi.)	348	643

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HACKER MORRIS J & SO	64 CENTRE AVE	S 0 - 1/8 (0.111 mi.)	I97	159

Lower Elevation	Address	Direction / Distance	Map ID	Page
A PLUS INC	271 NORTH AVE STE 11	NE 0 - 1/8 (0.054 mi.)	D42	62

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HAYES KATHRYN INC	36-38 DIVISION ST	S 0 - 1/8 (0.044 mi.)	B27	39
SIMONETTI CLEANERS &	62 CENTRE AVE	SSW 0 - 1/8 (0.109 mi.)	I96	158


Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANERS	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	A2	8
STATION CLEANERS	24 STATION PLZ	NNW 0 - 1/8 (0.057 mi.)	F48	69

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 6 records.

Site Name	Database(s)
CE-CEDAR ST MGP NEW ROCHELLE	NY SHWS
MEARL CORP.	NY SHWS
SIDEWALK / IN FRONT OF NE	NY LTANKS
N.SHORE LONG ISLAND SOUND	NY LTANKS
MM 5.4 LEFT LANE	NY LTANKS
CE-CEDAR ST MGP NEW ROCHELLE	NY VCP

OVERVIEW MAP - 6193173.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands


N

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Michelle Thomas
LAT/LONG:	40.910597 / 73.783767	INQUIRY #:	6193173.2s
		DATE:	September 16, 2020 10:31 am

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6193173.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Michelle Thomas
LAT/LONG:	40.910597 / 73.783767	INQUIRY #:	6193173.2s
		DATE:	September 16, 2020 10:32 am

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	1	0	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	4	NR	NR	NR	6
RCRA-SQG	0.250		1	1	NR	NR	NR	2
RCRA-VSQG	0.250		2	1	NR	NR	NR	3
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	1	2	0	NR	3
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		18	35	111	NR	NR	164
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		17	22	NR	NR	NR	39
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		5	13	NR	NR	NR	18
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		1	7	1	NR	NR	9
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	1	NR	NR	1
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		29	NR	NR	NR	NR	29
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		25	51	NR	NR	NR	76
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		4	4	NR	NR	NR	8
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		35	65	NR	NR	NR	100
RI MANIFEST	0.250		0	0	NR	NR	NR	0
PA MANIFEST	0.250		0	3	NR	NR	NR	3
NJ MANIFEST	0.250		9	16	NR	NR	NR	25
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		4	NR	NR	NR	NR	4
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		0	154	225	120	0	0	499

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **SOUND CLEANER** **NY DRYCLEANERS** **S110247943**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.000 mi.
2 ft. **Site 1 of 9 in cluster A**

Relative: DRYCLEANERS:
Lower

Name:	SOUND CLEANER
Address:	63 MEMORIAL HWY
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	Not reported
Phone Number:	Not reported
Region:	3
Registration Effective Date:	Not reported
Inspection Date:	Not reported
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
83 ft.

A2 **SOUND CLEANERS** **EDR Hist Cleaner** **1020090702**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.000 mi.
2 ft. **Site 2 of 9 in cluster A**

Relative: EDR Hist Cleaner
Lower

Actual:
83 ft.

Year:	Name:	Type:
2007	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2010	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2011	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2012	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2013	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2014	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC

A3 **OFFICE BUILDING** **NY Spills** **S102154161**
8-10 RAILROAD PLACE **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.001 mi.
4 ft. **Site 3 of 9 in cluster A**

Relative: SPILLS:
Lower

Name:	OFFICE BUILDING
Address:	8-10 RAILROAD PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9009493 / 1991-05-07
Facility ID:	9009493
Facility Type:	ER
DER Facility ID:	182194
Site ID:	220275
DEC Region:	3
Spill Cause:	Unknown

Actual:
80 ft.

OFFICE BUILDING (Continued) **S102154161**

Spill Class:	C3
SWIS:	6010
Spill Date:	1990-11-28
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1990-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-03-18
Cleanup Meets Std:	True
Last Inspection:	1991-03-18
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-12-06
Spill Record Last Update:	1991-05-08
Spiller Name:	Not reported
Spiller Company:	8 RAILROAD PLACE CORP.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"UNDERGROUND TANK SYSTEM APPEARS TO BE LEAKING ACCORDING TO READINGS MAPLE MAINTENANCE LAGRANGEVILLE NO ODORS NO PRODUCT IN VIEW CALLED JOHN TENORE MAPLE MAINT. WILL BE DOING A TANK TEST MAYBE ONLY 100"

All Materials:

Site ID:	220275
Operable Unit ID:	946581
Operable Unit:	01
Material ID:	429706
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	800.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B4 **RESIDENCE** **NY Spills** **S109413260**
SSW **129 DIVISON ST** **N/A**
< 1/8 **TARRYTOWN, NY**
0.006 mi.
34 ft. **Site 1 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Name:	RESIDENCE
Address:	129 DIVISON ST
City,State,Zip:	TARRYTOWN, NY
Spill Number/Closed Date:	0810056 / 2010-05-04
Facility ID:	0810056
Facility Type:	ER
DER Facility ID:	356816
Site ID:	407567

RESIDENCE (Continued) **S109413260**

DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6026
Spill Date:	2008-12-09
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-09
Spill Record Last Update:	2010-08-27
Spiller Name:	Not reported
Spiller Company:	3RD PARTY SPILL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"12/09/2008: Con Ed reports that this location is the former GM site that was/is a Brownsfield site. Con Ed was laying a gas line when stained soils was found in the trench...ra 08/27/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	"CALLER STATES THAT THEY RECIEVED A 3RD PARTY CALLL STATING THAT THEY FOUND AN UNK PETROLEUM PRODUCT DURING AN EXCAVATION. CLEAN UP IS PENDING."

All Materials:

Site ID:	407567
Operable Unit ID:	1164107
Operable Unit:	01
Material ID:	2155468
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A5 **AVALON ON THE SOUND** **NY UST** **U003994344**
SSE **HUGUENOT STREET AND MEMORAL HWY** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.007 mi.
36 ft. **Site 4 of 9 in cluster A**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Name:	AVALON ON THE SOUND
Address:	HUGUENOT STREET AND MEMORAL HWY
City,State,Zip:	NEW ROCHELLE, NY 10801

AVALON ON THE SOUND (Continued) **U003994344**

Id/Status:	3-800626 / Unregulated: <1101 gal. PBS
Operator Name:	Avalonbay
Owner Name:	Avalonbay Redevelopment LLC
Owner Street:	535 Fifth Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10017
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/01/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

A6 **UST** **NY Spills** **S104509646**
SSE **MEMORIAL HIGHWAY AND HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.007 mi.
36 ft. **Site 5 of 9 in cluster A**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	UST
Address:	MEMORIAL HIGHWAY AND HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9912617 / 2000-04-04
Facility ID:	9912617
Facility Type:	ER
DER Facility ID:	208558
Site ID:	254637
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2000-02-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-02-04
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons

UST (Continued) **S104509646**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-04
Spill Record Last Update:	2017-10-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	AVALONBAY COMMUNITIES
DEC Memo:	" 02/04/2000 STEVE AT AKRF. NEW ROCHELLE F.D. HAS BEEN ON SITE AS WELL AS T. GHIOSAY 04/04/2000 LETTER SENT TO AKRF BY T. GHIOSAY; CLEANUP SATISFACTORY - SPILL FILE CLOSED."
Remarks:	"CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL"

All Materials:

Site ID:	254637
Operable Unit ID:	1091315
Operable Unit:	01
Material ID:	294499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A7 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650791**
SSE **MEMORIAL HIGHWAY & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.007 mi.
36 ft. **Site 6 of 9 in cluster A**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MEMORIAL HIGHWAY & HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004151221
Facility Status:	Not reported
Location Address 1:	MEMORIAL HIGHWAY & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004151221
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY

CONSOLIDATED EDISON (Continued) **S108650791**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	06/21/2007
Trans1 Recv Date:	06/21/2007
Trans2 Recv Date:	06/22/2007
TSD Site Recv Date:	06/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004151221
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000174983GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H129
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1820
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B8
South
< 1/8
0.009 mi.
47 ft.

CON EDISON
DIVISION & HUGUENOT
NEW ROCHELLE, NY

Site 2 of 18 in cluster B

NY MANIFEST **S117319604**
N/A

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DIVISION & HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004676847
Facility Status:	Not reported
Location Address 1:	DIVISION & HUGUENOT
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676847
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770952JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117319604**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B9 **CON EDISON MANHOLE: 1215** **RCRA NonGen / NLR** **1016678044**
South **HUGENOT AVE & DIVISION ST NE** **FINDS** **NYP004317285**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.009 mi. **NY MANIFEST**
47 ft. **Site 3 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-06-30 00:00:00.0
Facility name:	CON EDISON MANHOLE: 1215
Facility address:	HUGENOT AVE & DIVISION ST NE COR NEW ROCHELLE, NY 10801
EPA ID:	NYP004317285
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-05-30 00:00:00.0
Site name: CON EDISON MANHOLE: 1215
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:
Registry ID: 110058874865

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678044
Registry ID: 110058874865
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058874865
Name: CON EDISON MANHOLE: 1215
Address: HUGENOT AVE & DIVISION ST NE
City,State,Zip: NEW ROCHELLE, NY 10801

NY MANIFEST:
Name: CON EDISON
Address: HUGENOT AVE & DIVISION ST NE
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004317285
Facility Status: Not reported
Location Address 1: DIVISION ST & HUGUENOT ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

NY MANIFEST:

EPAID:	NYP004317285
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2013
Trans1 Recv Date:	05/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/30/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004317285
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842831JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B10 **CON ED** **NY MANIFEST** **S119073734**
South **DIVISION ST & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
47 ft. **Site 4 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON ED
Address:	DIVISION ST & HUGENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004353199
Facility Status:	Not reported
Location Address 1:	DIVISION ST AND HUGENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004353199
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2013
Trans1 Recv Date:	08/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004353199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON ED (Continued) **S119073734**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694814JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B11 **CON EDISON** **NY MANIFEST** **S117535602**
South **HUGENOT ST & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.009 mi.
47 ft. **Site 5 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT ST & DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004677894
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & DIVISION ST
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677894

CON EDISON (Continued) **S117535602**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677894
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774861JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117535602**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

B12 **CON EDISON** **NY MANIFEST** **S117535593**
South **HUGENOT & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.009 mi.
47 ft. **Site 6 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:
Name: CON EDISON
Address: HUGENOT & DIVISION ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004677548
Facility Status: Not reported
Location Address 1: HUGENOT & DIVISION ST
Code: BP
Location Address 2: MH 1218
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004677548
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/14/2014
Trans1 Recv Date: 10/14/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677548
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012774875JJK

CON EDISON (Continued) **S117535593**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B13 **CON EDISON - TRANSFORMER MANHOLE 1154** **RCRA-LQG** **1016962308**
South **DIVISION ST AND HUGENOT ST** **NYP004353199**
< 1/8 **NEW ROCHELLE, NY 10805**
0.009 mi.
47 ft. **Site 7 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA-LQG:

Date form received by agency:	2014-03-27 00:00:00.0
Facility name:	CON EDISON - TRANSFORMER MANHOLE 1154
Facility address:	DIVISION ST AND HUGENOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004353199
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	2013-08-29 00:00:00.
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	2013-08-29 00:00:00.
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-09-29 00:00:00.0
Site name:	CON EDISON TRANSFORMER MANHOLE: 1154
Classification:	Not a generator, verified

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Date form received by agency: 2013-08-29 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

B14
South
< 1/8
0.009 mi.
47 ft.

Relative: Higher

Actual: 101 ft.

CON EDISON TRANSFORMER MANHOLE: 1154 **RCRA NonGen / NLR** **1016961985**
DIVISION ST & HUGUENOT ST **NYP004349395**
NEW ROCHELLE, NY 10801

Site 8 of 18 in cluster B

RCRA NonGen / NLR:
Date form received by agency: 2013-09-21 00:00:00.0
Facility name: CON EDISON TRANSFORMER MANHOLE: 1154
Facility address: DIVISION ST & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004349395
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-08-21 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 1154
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON TRANSFORMER MANHOLE: 1154 (Continued) **1016961985**

Violation Status: No violations found

A15
WSW
< 1/8
0.009 mi.
48 ft.

METRO NORTH TRACKS **NY Spills** **S106126232**
EAST OF NEW ROCHELLE STAT **N/A**
NEW ROCHELLE, NY

Site 7 of 9 in cluster A

Relative:
Lower

Actual:
81 ft.

SPILLS:

Name:	METRO NORTH TRACKS
Address:	EAST OF NEW ROCHELLE STAT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308130 / 2004-07-16
Facility ID:	0308130
Facility Type:	ER
DER Facility ID:	226808
Site ID:	279322
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2003-10-31
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-10-31
CID:	418
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-31
Spill Record Last Update:	2004-07-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOANNE REILLEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/5/03 Joanne Reilly stated that the area is inaccessible to work in because of hi speed train taffic. Requested permission to cleanup during a planned closure for a capital project scheduled in 2004. Will submit request in writing to TG. TG 07-15-04 Letter rec'd from Metro North claiming cleanup has been completed. NFA. TG."
Remarks:	"caller states that spill is between 2 tracks and currently have a company rep enroute to the scene"

All Materials:

Site ID:	279322
Operable Unit ID:	874415
Operable Unit:	01
Material ID:	501652
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported

METRO NORTH TRACKS (Continued) **S106126232**

Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A16
WSW
< 1/8
0.009 mi.
48 ft.

METRO NORTH TRAIN STATION **NY Spills** **S102153509**
NEW HAVEN LINE &R/R PLAZA **N/A**
NEW ROCHELLE, NY

Site 8 of 9 in cluster A

Relative:
Lower

Actual:
81 ft.

SPILLS:

Name:	METRO NORTH TRAIN STATION
Address:	NEW HAVEN LINE &R/R PLAZA
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8903573 / 1989-07-19
Facility ID:	8903573
Facility Type:	ER
DER Facility ID:	92033
Site ID:	104107
DEC Region:	3
Spill Cause:	Vandalism
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1989-07-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-07-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-07-10
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-19
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	METRO NORTH TRAIN STATION
Spiller Address:	NEW HAVEN LINE &R/R PLAZA
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"SOMEONE PUT STEEL BAR ON TRACK. TRAIN HIT BAR, PUNCTURED SMALL HOLE IN TRANFORMER. CAR #8669, EMPLOYEE WALKED TRACK. CLEAN UP IN PROGRESS. WCHD WILL INVESTIGATE, AMER. ENV. TECH, RCIHFIELD CT, NFA"

All Materials:

Site ID:	104107
Operable Unit ID:	928993
Operable Unit:	01
Material ID:	447657

METRO NORTH TRAIN STATION (Continued) **S102153509**

Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B17 **NYSDOT BIN 1049890** **RCRA NonGen / NLR** **1000789726**
South **DIVISION ST OVER METRO NORTH** **NYD987011897**
< 1/8 **NEW ROCHELLE, NY 10803**
0.009 mi.
49 ft. **Site 9 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	NYSDOT BIN 1049890
Facility address:	DIVISION ST OVER METRO NORTH NEW ROCHELLE, NY 10803
EPA ID:	NYD987011897
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	914-431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYSDOT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State

NYSDOT BIN 1049890 (Continued) **1000789726**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

Date form received by agency: 1992-08-12 00:00:00.0
Site name: NYSDOT BIN 1049890
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

C18 **MH1204** **NY Spills** **S104509750**
East **HUGUENOT AVE/LAWTON AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.018 mi.
97 ft. **Site 1 of 7 in cluster C**

Relative:
Higher

Actual:
91 ft.

SPILLS:
Name: MH1204
Address: HUGUENOT AVE/LAWTON AV
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9912755 / 2000-02-14
Facility ID: 9912755
Facility Type: ER
DER Facility ID: 214030
Site ID: 262084
DEC Region: 3
Spill Cause: Unknown

MH1204 (Continued) **S104509750**

Spill Class:	C4
SWIS:	6010
Spill Date:	2000-02-09
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-02-09
CID:	270
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2000-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/09/2000 SOURCE UNKNOWN-NO OIL FILLED CONED EQUIPMENT NEARBY. VAC TRUCK BEING SENT TO SITE. WILL CALL WITH RESULTS OF PRODUCT I.D. SPILL VOLUME DOWNGRADED TO 3 GALLONS. 02/14/2000 CLEANUP REPORT SENT TO TARRYTOWN OFFICE. AMOUNT SPILLED WAS ACTUALLY 3 GALLONS. NFA"
Remarks:	"OIL STAGNANT SAMPLES WILL BE TAKEN CLEAN UP PENDING"

All Materials:

Site ID:	262084
Operable Unit ID:	1091472
Operable Unit:	01
Material ID:	294626
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B19 **ROAD** **NY Spills** **S108130430**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
163 ft. **Site 10 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Name:	ROAD
Address:	HUGUENOT ST/DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606187 / 2006-09-03
Facility ID:	0606187
Facility Type:	ER

ROAD (Continued) **S108130430**

DER Facility ID:	306600
Site ID:	369495
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-08-29
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-29
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-29
Spill Record Last Update:	2006-09-03
Spiller Name:	JEFF CULLEN
Spiller Company:	GC RELIABLE SERVICE COMPA
Spiller Address:	80 GROVE ST
Spiller Company:	001
Contact Name:	WESTCHESTER FIRE CONTROL
DEC Memo:	"DPW sanded road. No product to recover. jod"
Remarks:	"SPILL SPANS FOR FIVE BLOCKS BETWEEN THE TWO STREETS GIVEN IN LOCATION: CLEANUP IN PROGRESS: DPW ON SCENE:"

All Materials:

Site ID:	369495
Operable Unit ID:	1127329
Operable Unit:	01
Material ID:	2116923
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B20 **VACANT LOT** **NY LTANKS** **S107489335**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.031 mi.
163 ft. **Site 11 of 18 in cluster B**

Relative: **Higher**

Actual: **101 ft.**

LTANKS:

Name:	VACANT LOT
Address:	HUGUENOT ST/DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510542 / 2006-03-15
Facility ID:	0510542

VACANT LOT (Continued) **S107489335**

Site ID:	356539
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-15
Spiller Name:	STEVE GRENS
Spiller Company:	VACANT LOT
Spiller Address:	HUGUENOT ST/DIVISION ST
Spiller County:	001
Spiller Contact:	STEVE GRENS
Spiller Phone:	(914) 806-5650
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306600
DEC Memo:	"March 15, 2006: BROOKSIDE ENVIRONMENTAL DISPOSED OF LUST AND 5.62 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM AKRF. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallons."

All Materials:

Site ID:	356539
Operable Unit ID:	1113840
Operable Unit:	01
Material ID:	2103900
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B21
SSW
< 1/8
0.033 mi.
174 ft.

SHORELINE OIL
296 HUGENOT ST,REAR OF
NEW ROCHELLE, NY

Site 12 of 18 in cluster B

NY LTANKS **S102674768**
N/A

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	SHORELINE OIL
Address:	296 HUGENOT ST,REAR OF
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8709425 / 1988-04-06
Facility ID:	8709425
Site ID:	83347
Spill Date:	1988-02-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-04-06
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1988-05-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	1988-05-05
Spiller Name:	Not reported
Spiller Company:	SHORELINE OIL
Spiller Address:	34 EVANS ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76706
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : SITE INSPECT:NO EVIDENCE OF CONTAMINATION FROM OUTSIDE LOCKED GATE. N.F.A. T.D. 05/03/88: NO EVIDENCE OF CONTAMINATION OBSERVED DURING INSPECTION. NFA. "
Remarks:	"OIL INTO PRIVATE DRAIN, TO SUMP,TO SEWER,FROM CAPT.O'CONNOR NRFD(914-654-2215). COMPANY CLEANING UP. DEC TO INVESIGATE & VERIFY CLEAN UP. N.F.A. SEE UPDATE."

All Materials:

Site ID:	83347
Operable Unit ID:	914524
Operable Unit:	01
Material ID:	464747
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

SHORELINE OIL (Continued) **S102674768**

Recovered: .00
Oxygenate: Not reported

B22 **LILLIAN VERNON CO.** **NY LTANKS** **S100494788**
South **WESTCHESTER PLACE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.034 mi.
179 ft. **Site 13 of 18 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	LILLIAN VERNON CO.
Address:	WESTCHESTER PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9213055 / 1995-03-16
Facility ID:	9213055
Site ID:	201286
Spill Date:	1993-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-16
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-23
Spill Record Last Update:	1995-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	167465
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO HAVE MEETING TO DISCUSS FURTHER ACTION TANK IS BEING PUMPED DOWN TEMP TANK BEING SET UP AES SYSTEM II"

All TTF:

Facility ID:	9213055
Spill Number:	9213055
Spill Tank Test:	1541204
Site ID:	201286
Tank Number:	Not reported
Tank Size:	0

LILLIAN VERNON CO. (Continued) **S100494788**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	201286
Operable Unit ID:	977443
Operable Unit:	01
Material ID:	570289
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

A23 **NYSDOT BIN 1091390** **RCRA NonGen / NLR** **1000790435**
West **DIVISION ST OVER I 95** **NYD987019197**
< 1/8 **NEW ROCHELLE, NY 10803**
0.035 mi.
185 ft. **Site 9 of 9 in cluster A**

Relative:
Lower

Actual:
79 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	NYSDOT BIN 1091390
Facility address:	DIVISION ST OVER I 95 NEW ROCHELLE, NY 10803
EPA ID:	NYD987019197
Mailing address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact:	RICHARD MANNS
Contact address:	BURNETT BLVD POUGHKEEPSIE, NY 12603
Contact country:	US
Contact telephone:	914-431-5743
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYSDOT
Owner/operator address:	4 BURNETT BLVD POUGHKEEPSIE, NY 12603
Owner/operator country:	US
Owner/operator telephone:	914-431-5743

NYSDOT BIN 1091390 (Continued) **1000790435**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYSDOT
Owner/operator address: 4 BURNETT BLVD
POUGHKEEPSIE, NY 12603
Owner/operator country: US
Owner/operator telephone: 914-431-5743
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

Date form received by agency: 1992-09-25 00:00:00.0
Site name: NYSDOT BIN 1091390
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

B24 **NEW ROCHELLE IRISH BENEVOLENT SOCIETY** **NY UST** **U003884840**
South **38 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.039 mi.
206 ft. **Site 14 of 18 in cluster B**

Relative: **Higher**
Actual: **101 ft.**

WESTCHESTER CO. UST:

Name:	NEW ROCHELLE IRISH BENEVOLENT SOCIETY
Address:	38 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600097 / Unregulated
Operator Name:	New Rochelle Irish Benevolent Society
Owner Name:	New Rochelle Irish Benevolent Society
Owner Street:	38 Division Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	26051652
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1940
Date Perm Closure:	01/09/2015
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	6. Wrapped (Piping)
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

D25 **CON EDISON** **NJ MANIFEST** **S120678197**
NE **260 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.041 mi.
217 ft. **Site 1 of 12 in cluster D**

Relative: **Lower**
Actual: **86 ft.**

NJ MANIFEST:

EPA Id:	NYP004880056
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported

CON EDISON (Continued) **S120678197**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319282JJK
EPA ID:	NYP004880056
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D26 **CON EDISON** **RCRA NonGen / NLR** **1019909014**
NE **260 NORTH AVE** **FINDS** **NYP004880056**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.041 mi.
217 ft. **Site 2 of 12 in cluster D**

Relative:
Lower

Actual:
86 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-12-16 00:00:00.0
Facility name:	CON EDISON
Facility address:	260 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004880056
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-12-16 00:00:00.0
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069645085

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON (Continued) **1019909014**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019909014
Registry ID:	110069645085
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069645085
Name:	CON EDISON
Address:	260 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

B27 **HAYES KATHRYN INC** **EDR Hist Cleaner** **1020002440**
South **36-38 DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.044 mi.
230 ft. **Site 15 of 18 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual: **101 ft.**

Year:	Name:	Type:
1969	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1970	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1971	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1972	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1973	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1974	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1975	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1976	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1977	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs

B28 **JONES RESIDENCE** **NY LTANKS** **S106737602**
SSW **311 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
238 ft. **Site 16 of 18 in cluster B**

Relative: LTANKS:
Higher

Actual: **101 ft.**

Name:	JONES RESIDENCE
Address:	311 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0410335 / 2005-09-11
Facility ID:	0410335
Site ID:	335236
Spill Date:	2004-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-12-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester

JONES RESIDENCE (Continued) **S106737602**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-17
Spill Record Last Update:	2005-09-11
Spiller Name:	DARRYL JONES
Spiller Company:	JONES RESIDENCE
Spiller Address:	311 HUGENOT STREET
Spiller County:	001
Spiller Contact:	DARRYL JONES
Spiller Phone:	(914) 632-5368
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	270458
DEC Memo:	"12/21/04 PBS FACILITY: 3-801006. jbo September 11, 2005: TANK CLOSED IN PLACE. FIVE SAMPLES TAKEN, NO CONTAMINATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-801006 "

All TTF:

Facility ID:	0410335
Spill Number:	0410335
Spill Tank Test:	1548406
Site ID:	335236
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	335236
Operable Unit ID:	1097307
Operable Unit:	01
Material ID:	577292
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C29 **MAIN LIBRARY** **NY LTANKS** **S103037429**
East **LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
239 ft. **Site 2 of 7 in cluster C**

Relative: **Higher**

Actual: **91 ft.**

LTANKS:

Name:	MAIN LIBRARY
Address:	LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9713843 / 1998-03-27
Facility ID:	9713843
Site ID:	273025
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALLELLO
Spiller Phone:	(914) 654-2315
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222185
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED - SYSTEM PASSED. NFA."
Remarks:	""

All TTF:

Facility ID:	9713843
Spill Number:	9713843
Spill Tank Test:	1545675
Site ID:	273025
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

MAIN LIBRARY (Continued) **S103037429**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 273025
Operable Unit ID: 1056692
Operable Unit: 01
Material ID: 324833
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

D30 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963620**
NE **NORTH AVE & HUGUENOT ST** **NY MANIFEST** **NYP004366100**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
240 ft. **Site 3 of 12 in cluster D**

Relative:
Lower

Actual:
85 ft.

RCRA NonGen / NLR:
Date form received by agency: 2013-10-25 00:00:00.0
Facility name: CON EDISON TRANSFORMER MANHOLE: 5042
Facility address: NORTH AVE & HUGUENOT ST
NEW ROCHELLE, NY 10801
EPA ID: NYP004366100
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-09-25 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004366100
Facility Status: Not reported
Location Address 1: NOAR/HUGUNOT ST
Code: BP
Location Address 2: MH5042
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004366100
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/25/2013
Trans1 Recv Date: 09/25/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004366100
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

TSDF ID 2:	Not reported
Manifest Tracking Number:	011694648JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D31 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016677599**
NE **HUGUENOT AVE & NORTH AVE** **FINDS** **NYP004312476**
< 1/8 **NEW ROCHELLE, NY 10805** **ECHO**
0.045 mi. **NY MANIFEST**
240 ft. **Site 4 of 12 in cluster D**

Relative: **Lower**

Actual: **85 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2013-06-14 00:00:00.0
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGUENOT AVE & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004312476
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 2013-05-14 00:00:00.0
- Site name: CON EDISON MANHOLE: 5071
- Classification: Conditionally Exempt Small Quantity Generator

- Violation Status: No violations found

FINDS:
- Registry ID: 110058876550

- Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1016677599
- Registry ID: 110058876550
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058876550
- Name: CON EDISON MANHOLE: 5071
- Address: HUGUENOT AVE & NORTH AVE
- City,State,Zip: NEW ROCHELLE, NY 10805

NY MANIFEST:
- Name: CON EDISON
- Address: HUGUENOT AVE & NORTH AVE
- City,State,Zip: NEW ROCHELLE, NY 10805
- Country: USA
- EPA ID: NYP004312476
- Facility Status: Not reported
- Location Address 1: HUGUENOT & NORTH AVE
- Code: BP

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004312476
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658348JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D32 **CON EDISON** **NY MANIFEST** **1016961580**
NE **NORTH AVE & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
240 ft. **Site 5 of 12 in cluster D**

Relative:
Lower

Actual:
85 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & HUGENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004343786
Facility Status:	Not reported
Location Address 1:	NORTH AVENUE & HUGENOT STR
Code:	BP
Location Address 2:	EET
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004343786
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2013
Trans1 Recv Date:	08/08/2013
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **1016961580**

TSD Site Recv Date:	08/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004343786
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D33 **HUGUENOT AND NORTH AVE** **NY Spills** **S106126832**
NE **HUGUENOT AND NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
240 ft. **Site 6 of 12 in cluster D**

Relative: SPILLS:
Lower

Name:	HUGUENOT AND NORTH AVE
Address:	HUGUENOT AND NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0310260 / 2005-03-05
Facility ID:	0310260
Facility Type:	ER
DER Facility ID:	252866
Site ID:	313618
DEC Region:	3
Spill Cause:	Traffic Accident
Spill Class:	C3

Actual:
85 ft.

HUGUENOT AND NORTH AVE (Continued) **S106126832**

SWIS:	6010
Spill Date:	2003-12-03
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-03
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-09
Spill Record Last Update:	2005-03-05
Spiller Name:	CARLOS TORRES
Spiller Company:	HUGUENOT AND NORTH AVE
Spiller Address:	HUGUENOT AND NORTH AVE
Spiller Company:	001
Contact Name:	CARLOS TORRES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 3/5/05 5gallon surface spill--close "
Remarks:	"a tow truck carrying a dump truck . the dump truck ruptured and spilled about 5 to 6 gallons of fuel"

D34 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016968295**
NE **HUGENUOT ST & NORTH AVE** **NYP004419065**
< 1/8 **NEW ROCHELLE, NY 10805**
0.045 mi.
240 ft. **Site 7 of 12 in cluster D**

Relative: **Lower**

Actual: **85 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2014-02-15 00:00:00.0
Facility name:	CON EDISON MANHOLE: 5071
Facility address:	HUGENUOT ST & NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004419065
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON MANHOLE: 5071 (Continued) **1016968295**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2014-01-15 00:00:00.0
Site name: CON EDISON MANHOLE: 5071
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

C35 **ACCESSOCRAFT PRODUCTS INC** **RCRA NonGen / NLR** **1001079768**
ESE **48 LAWTON ST** **FINDS** **NYR000014753**
< 1/8 **NEW ROCHELLE, NY 10802** **ECHO**
0.046 mi. **NY MANIFEST**
242 ft. **Site 3 of 7 in cluster C**

Relative: Higher
Actual: 94 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: ACCESSOCRAFT PRODUCTS INC
Facility address: 48 LAWTON ST
NEW ROCHELLE, NY 10802
EPA ID: NYR000014753
Mailing address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact: Not reported
Contact address: LAWTON ST
NEW ROCHELLE, NY 10802
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-654-2163
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVE - CITY HALL

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-654-2163
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

Date form received by agency: 1996-05-10 00:00:00.0
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Not a generator, verified

Date form received by agency: 1996-03-06 00:00:00.0
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

Date form received by agency: 1995-10-11 00:00:00.0
Site name: ACCESSOCRAFT PRODUCTS INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

. Waste code: NONE
. Waste name: None

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Violation Status: No violations found

FINDS:
Registry ID: 110000849672

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001079768
Registry ID:	110000849672
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000849672
Name:	ACCESSOCRAFT PRODUCTS INC
Address:	48 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY 10802

NY MANIFEST:

Name:	ACCESSOCRAFT INC
Address:	48 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYR000014753
Facility Status:	Not reported
Location Address 1:	48 LAWTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000014753
Mailing Name:	ACCESSOCRAFT INC
Mailing Contact:	PAUL STEINMAN
Mailing Address 1:	48 LAWTON STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146322411

NY MANIFEST:

Document ID:	RIC0034295
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	RI49238
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1996
Trans1 Recv Date:	01/22/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/23/1996
Part A Recv Date:	02/01/1996
Part B Recv Date:	02/05/1996
Generator EPA ID:	NYR000014753
Trans1 EPA ID:	RID059735761
Trans2 EPA ID:	Not reported

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

TSDF ID 1:	RID059735761
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F009 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00148
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D003 - NON-LISTED REACTIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00160
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00152
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

E36 **SPILL NUMBER 9803949** **NY Spills** **S104647160**
West **MILEPOST 5.5 SB I95** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.048 mi.
255 ft. **Site 1 of 2 in cluster E**

Relative: **Lower**

Actual: **79 ft.**

SPILLS:

Name:	SPILL NUMBER 9803949
Address:	MILEPOST 5.5 SB I95
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9803949 / 1998-06-29
Facility ID:	9803949
Facility Type:	ER
DER Facility ID:	140562
Site ID:	166821
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-06-29
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-29
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-29
Spill Record Last Update:	1998-07-02
Spiller Name:	MR STEPHEN WELDON
Spiller Company:	STEPHENS TRANSP INC
Spiller Address:	60 JOFFRE
Spiller Company:	001
Contact Name:	SGT POWELL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"drive shaft broke on trk rupturing the saddle tank - cleanup in progress"

All Materials:

Site ID:	166821
Operable Unit ID:	1064663
Operable Unit:	01
Material ID:	322269
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D37 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1005444315**
ENE **255 NORTH AVE** **NY MANIFEST** **NYR000106369**
< 1/8 **NEW ROCHELLE, NY 10801**
0.049 mi.
258 ft. **Site 8 of 12 in cluster D**

Relative:
Lower

Actual:
87 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	US POSTAL SERVICE
Facility address:	255 NORTH AVE NEW ROCHELLE, NY 10801-9998
EPA ID:	NYR000106369
Mailing address:	WESTCHESTER AVE WHITE PLAINS, NY 10610-9111
Contact:	JOANNE KUNNY
Contact address:	WESTCHESTER AVE WHITE PLAINS, NY 10610-9111
Contact country:	US
Contact telephone:	914-697-7074
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	255 NORTH AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-5906
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	2001-01-01 00:00:00.
Owner/Op end date:	Not reported

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	255 NORTH AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-5906
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	2001-01-01 00:00:00.
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

US POSTAL SERVICE (Continued) **1005444315**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: US POSTAL SERVICE
Classification: Not a generator, verified

Date form received by agency: 2002-05-17 00:00:00.0
Site name: US POSTAL SERVICE
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

NY MANIFEST:
Name: US POSTAL SERVICE
Address: 255 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10801-9998
Country: USA
EPA ID: NYR000106369
Facility Status: Not reported
Location Address 1: 255 NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000106369
Mailing Name: US POSTAL SERVICE
Mailing Contact: RICHARD FERRARI
Mailing Address 1: 255 NORTH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10802
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146977074

NY MANIFEST:
Document ID: NYG2937357

US POSTAL SERVICE (Continued) **1005444315**

Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	27571PANY
Trans2 State ID:	PW8913
Generator Ship Date:	05/29/2002
Trans1 Recv Date:	05/29/2002
Trans2 Recv Date:	05/30/2002
TSD Site Recv Date:	05/31/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106369
Trans1 EPA ID:	NYD986908085
Trans2 EPA ID:	NYD082785429
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00060
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

B38 **306 HUGUENOT STREET CORP.** **NY AST** **U004187406**
SSW **306 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 17 of 18 in cluster B**

Relative: WESTCHESTER CO. AST:
Higher

Actual: Name: 306 HUGUENOT STREET CORP.
101 ft. Address: 306 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
PBS Number: 3-800236
Site Status: Active
GDS Number: Not reported
Operator Name: Gary Garafolo
Owner Name: 306 Huguenot Street Corp.
Owner Street: P.O. Box 196

306 HUGUENOT STREET CORP. (Continued) **U004187406**

Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	001
Status:	1. In-Service
Date Installation:	12/01/1986
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	Not reported
Dispenser:	3. Gravity

B39 **CERUSSI AND VERE** **NY UST** **U004187246**
SSW **306 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.051 mi.
270 ft. **Site 18 of 18 in cluster B**

Relative: **Higher**
Actual: **101 ft.**

WESTCHESTER CO. UST:

Name:	CERUSSI AND VERE
Address:	306 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-078360 / Administratively Closed
Operator Name:	Not reported
Owner Name:	Michael A Cerussi & F G Vere
Owner Street:	88 Woodlands Rd
Owner Address2:	Not reported
Owner City:	Harrison
Owner State:	NY
Owner Zipcode:	10528
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1986
Date Perm Closure:	12/01/2001
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported

CERUSSI AND VERE (Continued) **U004187246**

Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

D40 **COMMERCIAL BUILDING** **NY Spills** **S121984763**
NE **271 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.054 mi.
287 ft. **Site 9 of 12 in cluster D**

Relative: SPILLS:
Lower

Actual:
84 ft.

Name:	COMMERCIAL BUILDING
Address:	271 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1800222 / Not Reported
Facility ID:	1800222
Facility Type:	ER
DER Facility ID:	522007
Site ID:	568710
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2018-04-06
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2018-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2018-04-06
Spill Record Last Update:	2018-04-06
Spiller Name:	GEORGE PRELA
Spiller Company:	GEORGE PRELA (KAUFMANN HUEGENAUGHT CO)
Spiller Address:	271 NORTH AVENUE
Spiller Company:	999
Contact Name:	GEORGE PRELA
DEC Memo:	"04/06/18 WCDH called in a spill at this apartment complex. A line leaked in a boiler room causing approximately 20 gallon spill. No drains or waterways were impacted. #6 Fuel oil is congealed indicating it has been leaking for awhile. The superintendent is doing the clean up. WCDH gave them until Monday to finish the clean up and do the repairs. Kaufman Hugenout Company 450 7th Ave, New York, NY (212) 471-4300; creid@kaufmanorganization.com PBS No. 3-183776 BTR"
Remarks:	"in basement - cleanup pending"

COMMERCIAL BUILDING (Continued) **S121984763**

All Materials:

Site ID:	568710
Operable Unit ID:	1316583
Operable Unit:	01
Material ID:	2324343
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

D41 **KAUFMAN HUGUENOT COMPANY** **NY UST U003994672**
NE **271 NORTH AVENUE** **NY AST N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.054 mi.
287 ft. **Site 10 of 12 in cluster D**

Relative: **Lower**
Actual: **84 ft.**

WESTCHESTER CO. UST:

Name:	KAUFMAN HUGUENOT COMPANY
Address:	271 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-183776 / Active
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10123
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1900
Date Perm Closure:	01/01/2011
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

KAUFMAN HUGUENOT COMPANY (Continued) **U003994672**

WESTCHESTER CO. AST:

Name:	KAUFMAN HUGUENOT COMPANY
Address:	271 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-183776
Site Status:	Active
GDS Number:	Not reported
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10123
Tank Number:	002
Status:	1. In-Service
Date Installation:	08/01/2007
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	4. Groundwater Well
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	2. Transfer Station Containment
Dispenser:	2. Suction

D42 **A PLUS INC** **EDR Hist Auto** **1020468102**
NE **271 NORTH AVE STE 117** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.054 mi.
287 ft. **Site 11 of 12 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: **84 ft.**

Year:	Name:	Type:
2014	A PLUS INC	Gasoline Service Stations, NEC

C43 **LAWTON STREET REALTY CORP** **NY LTANKS** **S118953553**
ESE **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
291 ft. **Site 4 of 7 in cluster C**

Relative: **Higher**

Actual: **94 ft.**

LTANKS:

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1706064 / 2019-02-15
Facility ID:	1706064
Site ID:	560365
Spill Date:	2017-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2017-09-21
Spill Record Last Update:	2019-02-15
Spiller Name:	Not reported
Spiller Company:	MIKE LAGE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MIKE LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/21/17 3000 gallon UST failed TT with hissing. Same tank failed test last year. Owner is waiting on Con Ed to convert over to natural gas. Conversion should be finished in 3-4 months. Tank will be pulled in approx. 6 months. WC PBS# 3-801435. ga 9-27-17 From Wchd, TTF at a PBS site. 41-43 Lawton St, New Rochelle 3k UST heating oil Old open TTF on site 1605726 RDB 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG "
Remarks:	"3000 gal ust"

All Materials:

Site ID:	560365
Operable Unit ID:	1308365
Operable Unit:	01
Material ID:	2315311
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

LAWTON STREET REALTY CORP (Continued) **S118953553**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1605726 / 2019-02-15
Facility ID:	1605726
Site ID:	532284
Spill Date:	2016-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2016-09-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-09-07
Spill Record Last Update:	2019-02-15
Spiller Name:	MICHAEL LAGE
Spiller Company:	LAWTON STREET REALTY CORP
Spiller Address:	41-43 LAWTON ST
Spiller County:	999
Spiller Contact:	MICHAEL LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/7/16 Called Tank Tech - 3000 gal tank failed with popping sound indicative of piping & fitting failure. Owner notified on site. Spoke to owner. Tank to be removed & replaced, contract pending. Property is 13 residential & 2 commercial. Building is on municipal water. Sent owner draft guidelines and contractor list. ga 5-4-17 Meeting with WCDOH. WC to follow up. GHP 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG"
Remarks:	"pbs tank failure"

All Materials:

Site ID:	532284
Operable Unit ID:	1281058
Operable Unit:	01
Material ID:	2286307
Material Code:	0001A

LAWTON STREET REALTY CORP (Continued) **S118953553**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

C44 **LAWTON STREET REALTY CORP.** **NY UST** **U004176798**
ESE **41-43 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
291 ft. **Site 5 of 7 in cluster C**

Relative: **Higher**
Actual: **94 ft.**

WESTCHESTER CO. UST:

Name:	LAWTON STREET REALTY CORP.
Address:	41-43 LAWTON STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-801435 / Unregulated
Operator Name:	Lawton Street Realty Corp.
Owner Name:	Lawton Street Realty Corp.
Owner Street:	4391 Boston Post Road
Owner Address2:	Not reported
Owner City:	Pelham Manor
Owner State:	NY
Owner Zipcode:	10803
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	06/01/1927
Date Perm Closure:	10/29/2018
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

C45 **PAVEMENT** **NY Spills** **S112147960**
ESE **41 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
291 ft. **Site 6 of 7 in cluster C**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Name:	PAVEMENT
Address:	41 LAWTON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1203965 / 2012-07-23
Facility ID:	1203965
Facility Type:	ER
DER Facility ID:	421153
Site ID:	466814
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2012-07-23
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2012-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-23
Spill Record Last Update:	2012-07-23
Spiller Name:	BADGE 620
Spiller Company:	UNKNOWN
Spiller Address:	41 LAWTON STREET
Spiller Company:	999
Contact Name:	BADGE 620
DEC Memo:	"7-23-12 FD cleaned up. jc"
Remarks:	"Possibly from garbage truck. Fire Dept. Clean up."

All Materials:

Site ID:	466814
Operable Unit ID:	1216796
Operable Unit:	01
Material ID:	2215011
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C46 **LAWTON STREET REALTY CORP** **NY Spills** **S123160020**
ESE **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
291 ft. **Site 7 of 7 in cluster C**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1808090 / 2019-02-15
Facility ID:	1808090
Facility Type:	ER
DER Facility ID:	486301
Site ID:	578882
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2018-10-29
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2018-10-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-10-29
Spill Record Last Update:	2019-02-15
Spiller Name:	Not reported
Spiller Company:	MICHAEL LAGE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MICHAEL LAGE
DEC Memo:	"10/29/18 North East Env. pulled 3,000 gallon UST from under a parking lot, found holes in tank. No waterways on property, no drains, property on municipal water. No ground water impacts noted at this time. Cleanup to start in 3 weeks. Left message for property owner to call duty desk. ga 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG"
Remarks:	"it was 3000 gallon tank pbs 3-801435. The cleanup is pending"

All Materials:

Site ID:	578882
Operable Unit ID:	1326616
Operable Unit:	01
Material ID:	2335419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

LAWTON STREET REALTY CORP (Continued) **S123160020**

Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

D47 **FEDERAL PROPERTY MAINTENANCE CORP** **RCRA NonGen / NLR** **1012186472**
ENE **244 NORTH AVE SUITE 153** **NYR000163337**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
292 ft. **Site 12 of 12 in cluster D**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:
Date form received by agency: 2017-05-25 00:00:00.0
Facility name: FEDERAL PROPERTY MAINTENANCE CORP
Facility address: 244 NORTH AVE SUITE 153
NEW ROCHELLE, NY 10801
EPA ID: NYR000163337
Mailing address: NORTH AVE SUITE 153
NEW ROCHELLE, NY 10801
Contact: KRISTIE EFFEREN
Contact address: NORTH AVE SUITE 153
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: 914-355-2226
Contact email: FEDERALPMC@AOL.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: KRISTIE EFFEREN
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2005-06-24 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: ANTHONY VALENTINO
Owner/operator address: GRANT AVE
HARRISON, NY 10528
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1978-05-20 00:00:00.
Owner/Op end date: Not reported

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2009-02-23 00:00:00.0
Site name: FEDERAL PROPERTY MAINTENANCE CORP
Classification: Not a generator, verified

Violation Status: No violations found

F48 **STATION CLEANERS** **EDR Hist Cleaner** **1020094775**
NNW **24 STATION PLZ** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
299 ft. **Site 1 of 2 in cluster F**

Relative: EDR Hist Cleaner
Lower

Actual: **71 ft.**

Year:	Name:	Type:
2005	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2006	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC

F49 **NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION** **RCRA-SQG** **1026059561**
NNW **24 STATION PLZ N** **NYR000244764**
< 1/8 **NEW ROCHELLE, NY 10801**
0.057 mi.
299 ft. **Site 2 of 2 in cluster F**

Relative: RCRA-SQG:
Lower
Date form received by agency: 2020-01-16 00:00:00.0

Actual: **71 ft.**
Facility name: NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT
Facility address: 24 STATION PLZ N
NEW ROCHELLE, NY 10801
EPA ID: NYR000244764
Mailing address: NORTH AVENUE
NEW ROCHELLE, NY 10801
Contact: TODD CASTALDO
Contact address: NORTH AVENUE
NEW ROCHELLE, NY 10801

NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT (Continued) **1026059561**

Contact country: US
Contact telephone: 914-654-2185
Contact email: TCASTALD@NEWROCHELLENY.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CITY OF NEW ROCHELLE DEPARTMENT OF FINANCE
Owner/operator address: NORTH AVENUE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-200-9404
Owner/operator email: RBONACCI@NEWROCHELLENY.COM
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 1991-03-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW ROCHELLE
Owner/operator address: NORTH AVENUE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-654-2185
Owner/operator email: TCASTALD@NEWROCHELLENY.COM
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 1991-03-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): Not reported
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT (Continued) **1026059561**

Hazardous Waste Summary:

- Waste code: D008
- Waste name: LEAD

Violation Status: No violations found

G50 **CABLE** **NY Spills** **S109206706**
South **29 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.057 mi.
301 ft. **Site 1 of 5 in cluster G**

Relative: **Higher**
Actual: **101 ft.**

SPILLS:

Name:	CABLE
Address:	29 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0804961 / 2008-07-30
Facility ID:	0804961
Facility Type:	ER
DER Facility ID:	351170
Site ID:	401965
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jpcummin
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-07-31
Spiller Name:	ERTSDESK
Spiller Company:	CABLE
Spiller Address:	29 DIVISION STREET
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"SEE SP: 0804960. -- NFA"
Remarks:	"8 OUNCES AND ON GOING AND WONT MAKE 2 HOUR CLEAN UP"

All Materials:

Site ID:	401965
Operable Unit ID:	1158737
Operable Unit:	01
Material ID:	2149827
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum

CABLE (Continued) **S109206706**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

H51 **NORTH BROOK REALTY ASSOCIATES** **NY UST** **U004259521**
NNE **270 NORTH AVENUE, SUITE 200** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.062 mi.
325 ft. **Site 1 of 7 in cluster H**

Relative: **Lower**

Actual: **80 ft.**

WESTCHESTER CO. UST:

Name:	NORTH BROOK REALTY ASSOCIATES
Address:	270 NORTH AVENUE, SUITE 200
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600117 / Active
Operator Name:	North Brook Realty Associates
Owner Name:	North Brook Realty Associates
Owner Street:	270 North Avenue, Suite 200
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	15000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

I52 **VINEK / KRACKO - USTS** **NY Spills** **S122479707**
SSW **316 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.070 mi.
367 ft. **Site 1 of 19 in cluster I**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	VINEK / KRACKO - USTS
Address:	316 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1802819 / 2018-07-23
Facility ID:	1802819
Facility Type:	ER
DER Facility ID:	524548
Site ID:	571425
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	6010
Spill Date:	2018-06-12
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2018-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-06-12
Spill Record Last Update:	2018-07-23
Spiller Name:	Elliot Kracko
Spiller Company:	Vinek Corp
Spiller Address:	316 HUGUEKNOT ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"6/12/18 North East Env. pulled 3 USTs - 550, 1000 previously abandoned, and 300 newly discovered tank. Tanks had holes, contaminated soil underneath 1000 and 300, and above the 550. No waterways on property. Property on municipal water. North East has started cleanup. ga 7-19-18 D. Monaco submitted closure report to DEC. Report is on D2. BTR 7-23-18 Closure report documents tank removal and remediation. 17.91 tons of petroleum impacted soil was removed from the rear of the structure (550 gallon tank). A total of 549.82 tons of petroleum impacted soil was removed from the front of the structure (1000 and 300 gallon tanks). Sample results are below CP-51. NFA. BTR"
Remarks:	"holes in tank 550 tank 1000 tank 300 tank removed clean up has started"

All Materials:

Site ID:	571425
Operable Unit ID:	1319254
Operable Unit:	01
Material ID:	2327236
Material Code:	0022

VINEK / KRACKO - USTS (Continued) **S122479707**

Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

H53 **EAST RIVER SAVINGS BANK** **NY LTANKS** **U003647446**
NNE **277 NORTH AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
378 ft. **Site 2 of 7 in cluster H**

Relative:
Lower

Actual:
81 ft.

LTANKS:

Name:	EAST RIVER SAVINGS BANK
Address:	277 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8912285 / 1991-01-16
Facility ID:	8912285
Site ID:	271129
Spill Date:	1990-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-03-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-29
Spill Record Last Update:	1991-03-19
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220684
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/19/91: TANK WAS REKINED AND PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK WAS ISOLATED AND THEY WILL RETEST PETRO-TITE -.3385 GPH"

All TTF:

Facility ID:	8912285

EAST RIVER SAVINGS BANK (Continued) **U003647446**

Spill Number:	8912285
Spill Tank Test:	1536885
Site ID:	271129
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271129
Operable Unit ID:	937979
Operable Unit:	01
Material ID:	441756
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

H54 **CON EDISON MANHOLE: 11295** **RCRA NonGen / NLR** **1016960384**
NNE **277 NORTH AVE** **NY MANIFEST** **NYP004323457**
< 1/8 **NEW ROCHELLE, NY 10802**
0.072 mi.
378 ft. **Site 3 of 7 in cluster H**

Relative:
Lower

Actual:
81 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-07-28 00:00:00.0
Facility name:	CON EDISON MANHOLE: 11295
Facility address:	277 NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004323457
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 2013-06-28 00:00:00.0
- Site name: CON EDISON MANHOLE: 11295
- Classification: Conditionally Exempt Small Quantity Generator

- Violation Status: No violations found

NY MANIFEST:
- Name: CON EDISON
- Address: 277 NORTH AVE
- City,State,Zip: NEW ROCHELLE, NY 10802
- Country: USA
- EPA ID: NYP004323457
- Facility Status: Not reported
- Location Address 1: FO 277 NORTH AVE
- Code: BP
- Location Address 2: MH #11295
- Total Tanks: Not reported
- Location City: NEW ROCHELLE
- Location State: NY
- Location Zip: 10805
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004323457
- Mailing Name: CON EDISON
- Mailing Contact: CON EDISON
- Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2013
Trans1 Recv Date:	06/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004323457
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693229JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H55 **277 NR PRINCIPAL, LLC** **NY UST** **U003994270**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.072 mi.
378 ft. **Site 4 of 7 in cluster H**

Relative: WESTCHESTER CO. UST:
Lower

Name:	277 NR PRINCIPAL, LLC
Address:	277 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-502049 / Active
Operator Name:	277 NR Principal, LLC

Actual:
81 ft.

277 NR PRINCIPAL, LLC (Continued) **U003994270**

Owner Name:	277 NR Principal, LLC
Owner Street:	277 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	01/01/1900
Date Perm Closure:	10/10/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	10/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	5. Jacketed,9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	6. Wrapped (Piping),9. Urethane
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

H56 **BUSINESS** **NY LTANKS** **S108467526**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
378 ft. **Site 5 of 7 in cluster H**

Relative: **Lower**

Actual: **81 ft.**

LTANKS:

Name:	BUSINESS
Address:	277 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0611580 / 2008-12-04
Facility ID:	0611580
Site ID:	376243
Spill Date:	2007-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-18
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE
Spiller Company:	BUSINESS
Spiller Address:	277 NORTH AVE
Spiller County:	001
Spiller Contact:	BRUCE
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11648 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"PIN HOLE IN TANK"

All TTF:

Facility ID:	0611580
Spill Number:	0611580
Spill Tank Test:	1550567
Site ID:	376243
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

BUSINESS (Continued) **S108467526**

Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	376243
Operable Unit ID:	1133835
Operable Unit:	01
Material ID:	2123664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H57 **277 NORTH LLC** **NY LTANKS** **S108467546**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.072 mi.
378 ft. **Site 6 of 7 in cluster H**

Relative: **Lower**

Actual: **81 ft.**

LTANKS:

Name:	277 NORTH LLC
Address:	277 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0611648 / 2008-12-04
Facility ID:	0611648
Site ID:	376329
Spill Date:	2007-01-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-19
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE MOSES
Spiller Company:	277 NORTH LLC
Spiller Address:	277 NORTH AVE

277 NORTH LLC (Continued) **S108467546**

Spiller County:	001
Spiller Contact:	BRUCE MOSES
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11580 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"EZ 3 LP WAS TEST USED: TANK IS BEING VACCED OUT AND TEMP TANK PUT IN PLACE: ARRANGEMENTS FOR FURTHER TESTING ARE BEING MADE:"

All TTF:

Facility ID:	0611648
Spill Number:	0611648
Spill Tank Test:	1550579
Site ID:	376329
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	376329
Operable Unit ID:	1133914
Operable Unit:	01
Material ID:	2123743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H58 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157675**
NNE **F/O 277 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.072 mi.
378 ft. **Site 7 of 7 in cluster H**

Relative:
Lower

Actual:
81 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	F/O 277 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004230322
Facility Status:	Not reported
Location Address 1:	F/O 277 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230322
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2011
Trans1 Recv Date:	03/10/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230322
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655972JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N

CONSOLIDATED EDISON (Continued) **S111157675**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G59 **CON EDISON** **NY Spills** **S109206705**
SSE **19 DIVISION ST & WASHINGTON AV** **NY MANIFEST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
420 ft. **Site 2 of 5 in cluster G**

Relative: **Higher**
Actual: **100 ft.**

SPILLS:

Name:	ARIEL CABLE
Address:	19 DIVISION STREET/WASHIN
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0804960 / 2008-08-16
Facility ID:	0804960
Facility Type:	ER
DER Facility ID:	351169
Site ID:	401964
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported

CON EDISON (Continued) **S109206705**

Remediation Phase: 0
Date Entered In Computer: 2008-07-30
Spill Record Last Update: 2008-08-16
Spiller Name: ERTSDESK
Spiller Company: ARIEL CABLE
Spiller Address: 19 DIVISION STREET/WASHIN
Spiller Company: 001
Contact Name: ERTSDESK
DEC Memo: "CONTRACTOR ENROUTE"
Remarks: "6 OUNCES AND ONGOING AND CRW WILL BE ENROUTE"

All Materials:
Site ID: 401964
Operable Unit ID: 1158736
Operable Unit: 01
Material ID: 2149826
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Name: CON EDISON
Address: 19 DIVISION ST & WASHINGTON AV
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004800058
Facility Status: Not reported
Location Address 1: WASHINGTON ST & HUEGONOT AVE
Code: BP
Location Address 2: MH 7241
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004800058
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported

CON EDISON (Continued) **S109206705**

Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2015
Trans1 Recv Date:	06/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004800058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469241JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	819
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J60 **CON EDISON** **NY MANIFEST** **S113920666**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
425 ft. **Site 1 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004683272
Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004683272
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2014
Trans1 Recv Date:	10/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773173JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S113920666**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J61 **CON EDISON** **NY MANIFEST** **S117538298**
East **ANDERSON ST & NORTH AV** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
425 ft. **Site 2 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	ANDERSON ST & NORTH AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004709622
Facility Status:	Not reported
Location Address 1:	ANDERSON ST & NORTH AV
Code:	BP
Location Address 2:	SB2063
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004709622
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117538298**

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 12/23/2014
Trans1 Recv Date: 12/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004709622
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012773453JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 25
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

J62 **CON EDISON** **RCRA NonGen / NLR** **1018281020**
East **NORTH AVE & ANDERSON** **FINDS** **NYP004759452**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.080 mi.
425 ft. **Site 3 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-03-28 00:00:00.0
Facility name:	CON EDISON
Facility address:	NORTH AVE & ANDERSON NEW ROCHELLE, NY 10801
EPA ID:	NYP004759452
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-03-28 00:00:00.0
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067686427

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON (Continued) **1018281020**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281020
Registry ID:	110067686427
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686427
Name:	CON EDISON
Address:	NORTH AVE & ANDERSON
City,State,Zip:	NEW ROCHELLE, NY 10801

J63 **CON EDISON** **NJ MANIFEST** **S120669728**
East **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
425 ft. **Site 4 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004759452
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091137JJK
EPA ID:	NYP004759452
Date Shipped:	3/28/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

CON EDISON (Continued) **S120669728**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J64 **CON EDISON TRANSFORMER MANHOLE: 3585** **RCRA NonGen / NLR** **1016963788**
East **NORTH AVE & ANDERSON ST** **NY MANIFEST** **NYP004367611**
< 1/8 **NEW ROCHELLE, NY 10802**
0.080 mi.
425 ft. **Site 5 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-10-29 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3585
Facility address:	NORTH AVE & ANDERSON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004367611
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-09-29 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 3585
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & ANDERSON ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004367611
Facility Status: Not reported
Location Address 1: NORTH AVE & ANDERSON ST
Code: BP
Location Address 2: TM3585
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004367611
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2013
Trans1 Recv Date: 09/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004367611
Trans1 EPA ID: Not reported

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694650JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J65 **CON ED STREET EXCAVATION** **NY Spills** **S125359722**
East **NORTH AVE AND ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.080 mi.
425 ft. **Site 6 of 18 in cluster J**

Relative: SPILLS:
Higher

Actual: Name:	CON ED STREET EXCAVATION
90 ft. Address:	NORTH AVE AND ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1905834 / 2019-10-22
Facility ID:	1905834
Facility Type:	ER
DER Facility ID:	543845
Site ID:	593884
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2019-09-05
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2019-09-05

CON ED STREET EXCAVATION (Continued) **S125359722**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-05
Spill Record Last Update:	2019-10-22
Spiller Name:	ERT
Spiller Company:	UNKNOWN
Spiller Address:	NORTH AVE AND ANDERSON ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"9/5/19 Con Ed found 1/2 gallon oil in soil when excavating. They stopped work, covered site, and will take soil samples for analysis. Cleanup pending results. No waterways or drains impacted. ga 09/05/19 Excerpt from EMIS, Senior Specialist, Sean Egan (04430) with EHS Street Construction, reported .5 gallon of an unknown oil within an excavation. Work immediately stopped and crews will be covering the excavation with a road plate. Samples for PCB, Oil ID and Flashpoint will be taken, however, the CoC was not available at the time of the call. TG 10/22/19 Excerpt from EMIS 275035/3; 10/8/2019 1:00 PM Allstate Clean venture removed 35 cubic yards of soil to permit work to continue. Sent to Clean Earth on 9/12/2019. Reinhart, Kenneth NFA. TG"
Remarks:	"LOSS DISCOVERED IN EXCAVATION"

All Materials:

Site ID:	593884
Operable Unit ID:	1341458
Operable Unit:	01
Material ID:	2351367
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J66 **CON EDISON** **NY MANIFEST** **S118088384**
East **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
425 ft. **Site 7 of 18 in cluster J**

Relative: **Higher**

Actual: **90 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & ANDERSON
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004759452

CON EDISON (Continued) **S118088384**

Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759452
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091137JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S118088384**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J67 **CONCRETE FLOORING WITH CRACKS** **NY Spills** **S116554293**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.084 mi.
444 ft. **Site 8 of 18 in cluster J**

Relative: **Higher**

Actual: **90 ft.**

SPILLS:

Name:	CONCRETE FLOORING WITH CRACKS
Address:	230 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1400277 / 2018-07-10
Facility ID:	1400277
Facility Type:	ER
DER Facility ID:	448397
Site ID:	493512
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2014-04-08
Investigator:	JBODEE
Referred To:	WCDOH PBS
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2014-04-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2018-07-10
Spiller Name:	Not reported
Spiller Company:	STERLING SOLUTIONS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK LANZELLI
DEC Memo:	"4-9-14 Last night I traded voicemails with Jerry. He said that he didn't know anymore than provided to the Hotline and I should talk to

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Frank in the morning. This morning I spoke to Frank. Location has a 1500 gallon vaulted tank with a remote fill at curb. There is currently some oil in the basement sump. Sump is unplugged and it doesn't appear any was pumped out. Frank doesn't know where oil came from, but vault sounds inaccessible. Frank is trying to contact management company to let them know tank needs to be tested. Management Company: Sterling Solutions, 914/437-6245, Aurora is Almeada contact Owner: Milka Iwanow, 914/409-6513 jc 4/09/14: Email received this morning from Chris Lalak: Sebastian went to this one and will follow up. It is a block away from my office. The tank in a vaulted AST (1500 gallon from 1931). There is a spill across the floor and in cracks in the floor getting to a sump pump. The sump goes to the sanitary. The spill may have been going on for so time, the super was very vague. The AST is visible except for a small area that sticks into the floor of the vault. The tank is not visibly leaking. Almeida replaced the underground lines with above ground lines recently. The between the tank, the former underground lines, and the sump is some distance and they will need to excavate the floor. The building has hired Dutchess. Pumping out the tank is not simple. The building has natural gas and oil. jod 04-09-14 followup email, After a second look at this one with a plumber,It looks like the old lines might be leaking. The plumber will uncover the old lines. The tank is not being pumped out at this time. The bottom of the tank is visible for the most part. (the plumber went in the vault, before we were there).Possibly, the remote fill is also an issue. They will replace the tank with an unregulated tank. Sebastian will continue to handle the spill. The floor will be opened up tomorrow to investigate. RDB 7/10/18: Email message received from Sebastian Bimonte of WCDoH: Can you NFA this one. The call from what I can remember was possible sheen in the sump pump located in the basement of an apartment building. As a precaution a section of the floor was excavated and a soil sample was retrieved. Soils below CP-51. *The sample results dated April 24 of 2014 show contamination levels below CP-51 except for the Xylenes which are slightly over the guidance. Municipal water and sewer in this area, WCDoH recommending NFA at this time. Sample results entered into D2 DecDocs. jod"

Remarks: "Caller advised unknown amount of oil spilled onto concrete floor with cracks. Clean up is pending."

All Materials:

Site ID:	493512
Operable Unit ID:	1243015
Operable Unit:	01
Material ID:	2243651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

J68 **CON EDISON** **NJ MANIFEST** **S120669791**
East **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
444 ft. **Site 9 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004760179
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091109JJK
EPA ID:	NYP004760179
Date Shipped:	3/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669791**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J69 **MKM EQUITY, LLC** **NY AST** **A100365275**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
444 ft. **Site 10 of 18 in cluster J**

Relative: WESTCHESTER CO. AST:
Higher

Actual:
90 ft.

Name:	MKM EQUITY, LLC
Address:	230 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-600105
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MKM Equity, LLC c/o Cornell Pace Inc.
Owner Street:	542 Main Street, Ste. 2
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	08/01/1931
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2014
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	0. None

J70 **CON EDISON** **RCRA NonGen / NLR** **1018281086**
East **230 NORTH AVE** **FINDS** **NYP004760179**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.084 mi.
444 ft. **Site 11 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-03-30 00:00:00.0
Facility name:	CON EDISON
Facility address:	230 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004760179
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-03-30 00:00:00.0
Site name:	CON EDISON
Classification:	Large Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067687015

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON (Continued) **1018281086**

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281086
Registry ID:	110067687015
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067687015
Name:	CON EDISON
Address:	230 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

J71 **CON ED** **NY MANIFEST** **S118088454**
East **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
444 ft. **Site 12 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON ED
Address:	230 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004760179
Facility Status:	Not reported
Location Address 1:	OPP 230 NORTH AVE
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760179
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2015
Trans1 Recv Date:	03/30/2015
Trans2 Recv Date:	Not reported

CON ED (Continued) **S118088454**

TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760179
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091109JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J72 **NORTH AVE REALITY** **NY LTANKS** **S103559119**
East **5 ANDERSON ST** **NY AST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.084 mi.
444 ft. **Site 13 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	NORTH AVE REALITY
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8803214 / 1989-11-30
Facility ID:	8803214
Site ID:	68769
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30

NORTH AVE REALITY (Continued) **S103559119**

SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-28
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	YOSHIAKI KOWANISHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	281826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K FAILED 4-GAL. PER HOUR"

All TTF:

Facility ID:	8803214
Spill Number:	8803214
Spill Tank Test:	1534286
Site ID:	68769
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68769
Operable Unit ID:	918394
Operable Unit:	01
Material ID:	458777
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

NORTH AVE REALITY (Continued) **S103559119**

Recovered:	.00
Oxygenate:	Not reported
Name:	5 ANDERSON ST
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812584 / 1999-07-12
Facility ID:	9812584
Site ID:	68770
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	2003-07-01
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

All TTF:

Facility ID:	9812584
Spill Number:	9812584
Spill Tank Test:	1546738
Site ID:	68770
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

NORTH AVE REALITY (Continued) **S103559119**

Last Modified Date: Not reported

All Materials:

Site ID:	68770
Operable Unit ID:	1069836
Operable Unit:	01
Material ID:	557973
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	5 ANDERSON ST
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812585 / 1999-07-12
Facility ID:	9812585
Site ID:	68771
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	1999-09-07
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

All TTF:

Facility ID:	9812585
Spill Number:	9812585

NORTH AVE REALITY (Continued) **S103559119**

Spill Tank Test:	1546739
Site ID:	68771
Tank Number:	2
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68771
Operable Unit ID:	1069838
Operable Unit:	01
Material ID:	312860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

WESTCHESTER CO. AST:

Name:	ANDERSON DEVELOPMENT GROUP
Address:	5 ANDERSON STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-185515
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Yonkers, NY 10701
Tank Number:	01
Status:	6. Closed - Work Permit Open
Date Installation:	04/01/1999
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	02/10/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)

NORTH AVE REALITY (Continued) **S103559119**

Tank Secondary Containment:	2. Vault (w/ access),5. Synthetic Liner
Piping Location:	1. Aboveground
Piping Type:	2. Galvanized Steel
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

J73 **ANDERSON DEVELOPMENT GROUP** **NY UST** **U004320191**
East **5 ANDERSON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
444 ft. **Site 14 of 18 in cluster J**

Relative:
Higher

Actual:
90 ft.

WESTCHESTER CO. UST:

Name:	ANDERSON DEVELOPMENT GROUP
Address:	5 ANDERSON STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-185515 / Unregulated
Operator Name:	Anderson Development Group
Owner Name:	Anderson Development Group
Owner Street:	1955 Central Park Avenue
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	7. Excavation/trench Liner system
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None

ANDERSON DEVELOPMENT GROUP (Continued) **U004320191**

Date Installation:	Not reported
Date Perm Closure:	04/01/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

E74 **ST GABRIEL'S CHURCH** **NY Spills** **S125360094**
West **120 DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.087 mi.
459 ft. **Site 2 of 2 in cluster E**

Relative: **Higher**

Actual: **93 ft.**

SPILLS:

Name:	ST GABRIEL'S CHURCH
Address:	120 DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1906243 / 2020-04-01
Facility ID:	1906243
Facility Type:	ER
DER Facility ID:	544249
Site ID:	594314
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2019-09-17
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2019-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-17
Spill Record Last Update:	2020-04-01
Spiller Name:	TIM ROFF
Spiller Company:	ST GABRIEL'S CHURCH
Spiller Address:	120 DIVISION ST
Spiller Company:	999
Contact Name:	TIM ROFF
DEC Memo:	"9/17/19 Church had tank removed last week (PBS site), temp tank installed. Temp tank expanded from heat, spilling 7 gallons oil to secondary containment (metal dike with metal floor around tank) and 3

ST GABRIEL'S CHURCH (Continued) **S125360094**

gallons to asphalt. No waterways, drains, soil, or grass impacted. New Rochelle Fire Dept. put down speedy dry, Metro Env. drummed used absorbents & debris for disposal, reports to follow. ga 1/28/20: Tank removal was reported as Spill 1903323. Report submitted under that case number. This was a 10 gallons spill from a temp AST. Cleanup was completed the same day. jod"

Remarks: "Over explansion of above ground storage tank caused spill into containment and some on blacktop outside of containment. Cleanup is underway."

All Materials:

Site ID:	594314
Operable Unit ID:	1341883
Operable Unit:	01
Material ID:	2351864
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

G75 **COMM/RESIDENT. PROPERTY** **NY LTANKS** **S101341321**
SSE **15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.088 mi.
466 ft. **Site 3 of 5 in cluster G**

Relative: **Higher**

Actual: **100 ft.**

LTANKS:

Name:	COMM/RESIDENT. PROPERTY
Address:	15 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9405558 / 2005-02-10
Facility ID:	9405558
Site ID:	119901
Spill Date:	1994-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-10
Spiller Name:	Not reported

COMM/RESIDENT. PROPERTY (Continued) **S101341321**

Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104134
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. Tank taken out of service by Royal Environmental. "
Remarks:	"TANK TEST ON 7/21/94"

All TTF:

Facility ID:	9405558
Spill Number:	9405558
Spill Tank Test:	1542973
Site ID:	119901
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	119901
Operable Unit ID:	1002771
Operable Unit:	01
Material ID:	382138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

J76 **NEW ROCHELLE PUBLIC LIBR.** **NY LTANKS** **S100177858**
ESE **MEMORIAL HIGHWAY** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.092 mi.
484 ft. **Site 15 of 18 in cluster J**

Relative:
Higher

Actual:
93 ft.

LTANKS:

Name:	NEW ROCHELLE PUBLIC LIBR.
Address:	MEMORIAL HIGHWAY
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9111450 / 1992-02-06
Facility ID:	9111450
Site ID:	306853
Spill Date:	1992-02-06
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247822
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SOME ON PAVEMENT,SOME IN STORM DRAIN F.D.HAZMAT USED SORBENT TO CONTAIN AND VENTED BUILING SPOKE WITH DEP. CHIEF STONE"

All Materials:

Site ID:	306853
Operable Unit ID:	965176
Operable Unit:	01
Material ID:	416486
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J77 **CVS PHARMACY #8447** **RCRA-VSQG** **1014958220**
East **222 NORTH AVE** **NY MANIFEST** **NYR000194654**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
519 ft. **Site 16 of 18 in cluster J**

Relative:
Higher

Actual:
91 ft.

RCRA-VSQG:

Date form received by agency:	2019-04-08 00:00:00.0
Facility name:	CVS PHARMACY #8447
Facility address:	222 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYR000194654
Mailing address:	CVS DR MAIL DROP 23062A WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	401-770-7132
Contact email:	NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CVS ALBANY LLC
Owner/operator address:	CVS DR WOONSOCKET, RI 02895
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	2011-07-30 00:00:00.
Owner/Op end date:	Not reported
Owner/operator name:	45 SOUTH MAIN STREET CORP
Owner/operator address:	NOT APPLICABLE RYE, NY 10580
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2011-01-20 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2016-03-17 00:00:00.0
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

Date form received by agency: 2014-03-17 00:00:00.0
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

Date form received by agency: 2013-07-01 00:00:00.0
Site name: CVS PHARMACY #8447
Classification: Large Quantity Generator

Date form received by agency: 2012-03-05 00:00:00.0
Site name: CVS PHARMACY #8447
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

CVS PHARMACY #8447 (Continued) **1014958220**

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 47

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 33

Waste code: D010
Waste name: SELENIUM
Amount (Lbs): 33

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs): 9

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 8

CVS PHARMACY #8447 (Continued) **1014958220**

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 30

Violation Status: No violations found

NY MANIFEST:
Name: CVS PHARMACY #8447
Address: 222 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYR000194654
Facility Status: Not reported
Location Address 1: 222 NORTH AVE.
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000194654
Mailing Name: CVS PHARMACY #8447
Mailing Contact: CVS PHARMACY #8447
Mailing Address 1: 222 NORTH AVE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146377591

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 12/30/2013
Trans1 Recv Date: 12/30/2013
Trans2 Recv Date: 01/13/2014
TSD Site Recv Date: 01/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000194654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: INR000110197
TSDF ID 2: Not reported
Manifest Tracking Number: 005855377FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

CVS PHARMACY #8447 (Continued) **1014958220**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	P001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I78 **CON EDISON** **NY MANIFEST** **S117535592**
SSW **HUGENOT & CENTRE ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 2 of 19 in cluster I**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT & CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004677530
Facility Status:	Not reported
Location Address 1:	HUGENOT & CENTRE ST
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677530
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S117535592**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677530
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774876JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I79 **CON EDISON** **RCRA NonGen / NLR** **1014398803**
SSW **HUGUENOT ST & CENTRE ST** **NYP004211728**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 3 of 19 in cluster I**

Relative: **Higher**

Actual: **96 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2010-07-19 00:00:00.0
Facility name:	CON EDISON
Facility address:	HUGUENOT ST & CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004211728
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

I80 **CON EDISON** **NY MANIFEST** **S117319603**
SSW **CENTER & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.099 mi.
521 ft. **Site 4 of 19 in cluster I**

Relative: **Higher**

Actual: **96 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	CENTER & HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004676839
Facility Status:	Not reported
Location Address 1:	CENTER & HUGUENOT
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported

CON EDISON (Continued) **S117319603**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676839
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770954JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S117319603**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I81 **CON EDISON** **NY MANIFEST** **S113917500**
SSW **CENTRE AVE & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
521 ft. **Site 5 of 19 in cluster I**

Relative: **Higher**
Actual: **96 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	CENTRE AVE & HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004332961
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004332961
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2013
Trans1 Recv Date:	07/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/26/2013
Part A Recv Date:	Not reported

CON EDISON (Continued) **S113917500**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004332961
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695949JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K82 **ROCHELLE DELUXE TAXI, INC.** **NY UST** **U001736524**
North **10 STATION PLAZA SOUTH** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.099 mi.
525 ft. **Site 1 of 12 in cluster K**

Relative: WESTCHESTER CO. UST:
Lower

Actual:
77 ft.

Name:	ROCHELLE DELUXE TAXI, INC.
Address:	10 STATION PLAZA SOUTH
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600004 / Unregulated: <1101 gal. PBS
Operator Name:	Rochell Deluxe Taxi, Inc.
Owner Name:	8 Railroad Place Corporation
Owner Street:	8 Station Plaza South
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

ROCHELLE DELUXE TAXI, INC. (Continued) **U001736524**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	11/03/1993
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

UST:

Name:	DELUXE TAXI
Address:	10 STATION PLAZA
City,State,Zip:	NEW ROCHELLE - WESCHESTER, NY 10801
Id/Status:	2-601600 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	566353.87500
UTM Y:	4486105.00000
Site Type:	Unknown

Affiliation Records:

Site Id:	23562
Affiliation Type:	Facility Owner
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Mail Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported

ROCHELLE DELUXE TAXI, INC. (Continued) **U001736524**

Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Facility Operator
Company Name:	DELUXE TAXI
Contact Type:	Not reported
Contact Name:	ROCHELLE DELUXE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23562
Affiliation Type:	Emergency Contact
Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	JOHN TENORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 632-2108
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47103
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	05/01/1999
Registered:	True
Tank Location:	Underground

ROCHELLE DELUXE TAXI, INC. (Continued) **U001736524**

Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

I83 **SEASONWEIN MANAGEMENT LLC** **NY UST** **U003994353**
SSW **54 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.101 mi.
535 ft. **Site 6 of 19 in cluster I**

Relative:
Higher

Actual:
98 ft.

WESTCHESTER CO. UST:

Name:	SEASONWEIN MANAGEMENT LLC
Address:	54 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-169773 / Active
Operator Name:	Matt Seasonwein
Owner Name:	Seasonwein Management LLC
Owner Street:	300 Gramatan Avenue
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10552
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1928
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None

SEASONWEIN MANAGEMENT LLC (Continued) **U003994353**

Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

I84 **APARTMENT BLDG** **NY LTANKS** **S105996855**
SSW **54 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.101 mi.
535 ft. **Site 7 of 19 in cluster I**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	54 CENTRE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0206558 / 2005-02-27
Facility ID:	0206558
Site ID:	254563
Spill Date:	2002-09-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-09-24
CID:	390
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2005-02-27
Spiller Name:	ENERITO GONZALEZ
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AV
Spiller County:	001
Spiller Contact:	ENERITO GONZALEZ
Spiller Phone:	(914) 309-2775
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208499
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 2/27/05 #4 overfill to surface--close "
Remarks:	"spill was noticed on 9/6 - unk when it occurred"

All Materials:

Site ID:	254563
Operable Unit ID:	858169
Operable Unit:	01
Material ID:	517160
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported

APARTMENT BLDG (Continued) **S105996855**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APARTMENT BLDG
Address:	54 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403405 / 2004-12-10
Facility ID:	0403405
Site ID:	84302
Spill Date:	2004-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-06-29
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-29
Spill Record Last Update:	2004-12-10
Spiller Name:	BASSAM MABER
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AVE
Spiller County:	001
Spiller Contact:	BASSAM MABER
Spiller Phone:	(914) 645-6420
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77542
DEC Memo:	"12/10/04 PBS facility. Tank passed a retest after piping was repaired. Spill file closed by Danielle Jackson of the Westchester County Health Dept. No further action is required at this time. jbo"
Remarks:	"Tank Test Failure. Reccommend Retest."

All TTF:

Facility ID:	0403405
Spill Number:	0403405
Spill Tank Test:	1529391
Site ID:	84302
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

APARTMENT BLDG (Continued) **S105996855**

Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 84302
Operable Unit ID: 886824
Operable Unit: 01
Material ID: 490990
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

I85 **CEMENT COURT YARD** **NY Spills** **S104282704**
SSW **54 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.101 mi.
535 ft. **Site 8 of 19 in cluster I**

Relative:
Higher

Actual:
98 ft.

SPILLS:
Name: SPILL NUMBER 9804849
Address: 54 CENTER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9804849 / 2002-07-15
Facility ID: 9804849
Facility Type: ER
DER Facility ID: 99871
Site ID: 114515
DEC Region: 3
Spill Cause: Deliberate
Spill Class: C4
SWIS: 6010
Spill Date: 1998-07-18
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-07-18
CID: 207
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-07-18
Spill Record Last Update: 2002-07-15

CEMENT COURT YARD (Continued) **S104282704**

Spiller Name:	Not reported
Spiller Company:	NABER REALTY INC
Spiller Address:	BOX 156H
Spiller Company:	001
Contact Name:	CAPT DIMEGLIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"fd called to an odor of fuel oil in a residence- upon arrival in basement it appeared were working on the oil boiler and were pumping product into sewer thru sump pumps"

All Materials:

Site ID:	114515
Operable Unit ID:	1065894
Operable Unit:	01
Material ID:	319611
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CEMENT COURT YARD
Address:	54 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908117 / 1999-10-04
Facility ID:	9908117
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114516
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-10-04
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1999-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-04
Spill Record Last Update:	1999-10-06
Spiller Name:	Not reported
Spiller Company:	CEMENT COURT YARD
Spiller Address:	54 CENTER AVE
Spiller Company:	001

CEMENT COURT YARD (Continued) **S104282704**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 10/4/99 SPILLER CLEANED UP. NFA"
Remarks: "BLDG SUPER OVERORDERED - CLEANED UP"

All Materials:
Site ID: 114516
Operable Unit ID: 1082403
Operable Unit: 01
Material ID: 555958
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6.00
Units: G
Recovered: 6.00
Oxygenate: Not reported

G86 **RPM REALTY INC** **NY UST** **U004240676**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
541 ft. **Site 4 of 5 in cluster G**

Relative: **Higher**
Actual: **99 ft.**

WESTCHESTER CO. UST:
Name: RPM REALTY INC
Address: 9-15 DIVISION STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-166189 / Active
Operator Name: Gary Garafolo
Owner Name: RPM Realty Inc.
Owner Street: PO Box 817
Owner Address2: Not reported
Owner City: Katonah
Owner State: NY
Owner Zipcode: 10536
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 2000
Product Stored: 0009. Gasoline
Product Stored Percent: Not reported
Tank Leak Detection: 4. Groundwater Well
Date Installation: Not reported
Date Perm Closure: 06/17/1997
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 0. No Pippping
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported

RPM REALTY INC (Continued) **U004240676**

Spill Prevention: 0. None
Dispenser: 2. Suction

G87 **RPM REALTY INC** **NY AST** **A100412045**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
541 ft. **Site 5 of 5 in cluster G**

Relative: **Higher**
Actual: **99 ft.**

WESTCHESTER CO. AST:

Name:	RPM REALTY INC
Address:	9-15 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-166189
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	2
Status:	1. In-Service
Date Installation:	06/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

L88 **STATION CLEANERS** **NY DRYCLEANERS** **S110247994**
NNW **1 DEPOT PLAZA #1** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
557 ft. **Site 1 of 5 in cluster L**

Relative: **Lower**
Actual: **72 ft.**

DRYCLEANERS:

Name:	STATION CLEANERS
Address:	1 DEPOT PLAZA #1
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	---
Phone Number:	Not reported

STATION CLEANERS (Continued) **S110247994**

Region:	3
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	???

L89 **DEPOT PLACE LLC** **NY UST** **U003994482**
NNW **1 DEPOT PLACE** **N/A**
< 1/8 **MAMARONECK (T), NY**
0.105 mi.
557 ft. **Site 2 of 5 in cluster L**

Relative: **Lower**
Actual: **72 ft.**

WESTCHESTER CO. UST:

Name:	DEPOT PLACE LLC
Address:	1 DEPOT PLACE
City,State,Zip:	MAMARONECK (T), NY
Id/Status:	3-801085 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Depot LLC
Owner Street:	1 Depot Place
Owner Address2:	Not reported
Owner City:	Mamaroneck
Owner State:	NY
Owner Zipcode:	Not reported
GDS Number:	Not reported
Tank Number:	001
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/21/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

I90 **ERIC S TURNER & CO INC.** **RCRA NonGen / NLR** **1007204937**
SSW **33-35 CENTRE AVE** **NJ MANIFEST** **NYD002015402**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.106 mi.
560 ft. **Site 9 of 19 in cluster I**

Relative:
Higher

Actual:
92 ft.

RCRA NonGen / NLR:

Date form received by agency:	2019-07-29 00:00:00.0
Facility name:	ERIC S TURNER & CO INC.
Facility address:	33-35 CENTRE AVE NEW ROCHELLE, NY 10801-0000
EPA ID:	NYD002015402
Mailing address:	PO BOX #816 NEW ROCHELLE, NY 10801-0000
Contact:	WILLIAM TURNER
Contact address:	PO BOX #816 NEW ROCHELLE, NY 10801-0000
Contact country:	US
Contact telephone:	914-235-7114
Telephone ext.:	9999
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2007-01-01 00:00:00.0
Site name:	ERIC S TURNER & CO INC.
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	2006-01-01 00:00:00.0
Site name:	ERIC S TURNER & CO INC.
Classification:	Small Quantity Generator

Date form received by agency:	2005-03-18 00:00:00.0
Site name:	ERIC S TURNER & CO INC.
Classification:	Large Quantity Generator

Date form received by agency:	1994-03-21 00:00:00.0
Site name:	ERIC S TURNER & CO INC.
Classification:	Large Quantity Generator

ERIC S TURNER & CO INC. (Continued) **1007204937**

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYD002015402
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	9142357114
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5224399
EPA ID:	NYD002015402
Date Shipped:	12/06/2004
TSDF EPA ID:	NJR000022442
Transporter EPA ID:	NJR000023325
Transporter 2 EPA ID:	OHD009865825
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/06/2004
Date Trans2 Transported Waste:	12/07/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

Data Entry Number: 01250521
Was Load Rejected: No
Reason Load Was Rejected: Not reported

NY MANIFEST:
Name: ERIC S TURNER & CO INC.
Address: 33-35 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801-0000
Country: USA
EPA ID: NYD002015402
Facility Status: Not reported
Location Address 1: 33-35 CENTRE AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD002015402
Mailing Name: ERIC S TURNER & CO INC.
Mailing Contact: W V TURNER PRESIDENT
Mailing Address 1: P. O. BOX 816
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142357114

NY MANIFEST:
Document ID: NJA5224399
Manifest Status: Not reported
seq: Not reported
Year: 2004
Trans1 State ID: NJAF906B
Trans2 State ID: 58746
Generator Ship Date: 12/06/2004
Trans1 Recv Date: 12/06/2004
Trans2 Recv Date: 12/07/2004
TSD Site Recv Date: 12/08/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002015402
Trans1 EPA ID: NJR000023325
Trans2 EPA ID: Not reported
TSDF ID 1: NJR000022
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported

ERIC S TURNER & CO INC. (Continued) **1007204937**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

I91 **CENTRE AVENUE DEVELOPMENT - SOUTH** **NY BROWNFIELDS** **S123658091**
SSW **33 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.106 mi.
560 ft. **Site 10 of 19 in cluster I**

Relative: **Higher**

Actual: **92 ft.**

BROWNFIELDS:

Name:	CENTRE AVENUE DEVELOPMENT - SOUTH
Address:	33 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	580085
Acres:	0.46
HW Code:	C360182
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/03/2018
Record Updated Date:	06/12/2019
Update By:	RDBENDEL
Site Description:	Location The 0.46-acre rectangular-shaped site is located in an urban area in the Downtown District of the City of New Rochelle, New York and is identified as Section 2, Block 437, Lots 1, 3 and 42 on the Westchester County Tax Map. Lots 1 and 3 are identified by address 339 Huguenot Street and Lot 42 is identified by 33-35 Centre Avenue. The property is undergoing a lot merger in conjunction with

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S123658091**

development. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. Site Features The site encompasses an area of about 20,000 square feet (0.46 acres). Sidewalk elevations (el) generally increase from southwest to northeast and range from about el 87.3 to 97.2 feet referenced to the North American Vertical Datum of 1988 (NAVD88). The site is occupied by a one-story industrial building with a partial cellar occupied by an electroplating and metal-finishing business, and an open-air parking lot. Current Zoning and Land Use The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above only. Permitted principal uses of LI districts include manufacturers, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. The surrounding area includes commercial, industrial, residential and institutional buildings. Past Use of the Site Based on review of Sanborn fire insurance maps, Lots 1 and 3 were developed with dwellings between 1887 and 1951 and with a parking lot between 1990 and 2003. Lot 42 is shown as undeveloped land prior to 1931, as a garage in 1931, and subsequently developed with residential, commercial and industrial buildings. Lot 42 has been occupied by an electroplating and metal-finishing business since 1971. The site is registered as a Conditionally Exempt Small Quantity Generator (CESQG) (Facility ID No.NYD002015402 [Eric S. Turner & Company, Inc.]). The site was historically listed as a Large Quantity Generator (LQG) and as a Small Quantity Generator (SGQ) for the generation of characteristic hazardous waste D001 (ignitable waste), D002 (corrosive waste), D005 (barium), D007 (chromium), D008 (lead), D039 (tetrachloroethene [PCE]), and U226 (1,1,1-trichloroethane [1,1,1-TCA]) between 1984 and 2004. The site is also identified as a New York State Department of Environmental Conservation (NYSDEC) Air Discharge Facility (Facility ID No. 3611900260 [Eric S. Turner & Company, Inc.]) for potential uncontrolled emissions less than 100 tons of total hazardous air pollutants per year. Site Geology and Hydrogeology According to the 1970 Geologic Map of New York Lower Hudson Sheet published by the University of the State of New York, the bedrock underlying the site is of the Hartland Formation, and is comprised primarily of basal amphibolite overlain by politic schists. Soil borings were advanced to explore the subsurface conditions during the 24 January 2018 Phase II Environmental Site Assessment by WCD Ground, LLC (WCD) and the 25 January 2018 Summary Report of Environmental Investigation by WCD. During the previous subsurface investigations at the site, historic fill was identified across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay. Sand with varying amounts of silt, clay and gravel was observed beneath the historic fill. Regional groundwater flow direction for the area is estimated to the south-southwest. Groundwater underlying the site is reported to range from about 5 to 15 feet bgs across the site footprint.

Env Problem: The primary contaminants of concern include volatile organic

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S123658091**

	compounds (VOC), semivolatile organic compounds (SVOC) and metals in soil, and chlorinated VOCs (CVOC) in groundwater and soil vapor. Contaminant concentrations detected above applicable regulatory standards for each media (soil, groundwater, soil vapor) are summarized below. Soil - A total of 20 soil samples were collected during previous investigations. Soil sample analytical results were compared to UU and RURR SCOs. Analytes detected with concentrations above the restricted residential soil cleanup objectives are listed below. SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and ideno(1,2,3-cd)pyrene *Metals barium, chromium, and nickel. Groundwater - A total of 15 groundwater samples were collected during previous investigations. Groundwater sample analytical results were compared to the NYSDEC SGVs. Analytes detected with concentrations above NYSDEC SGVs are listed below. VOCs 1,1,1-TCA, 1,1-dichoethane, 1,1-DCE, PCE, and TCE Soil Vapor - A total of four soil vapor samples and one outdoor ambient air sample were collected during previous investigations. Soil vapor sample analytical results were compared to the minimum soil vapor concentrations recommending mitigation as set forth in the NYSDOH October 2006 Guidance for Evaluating Soil Vapor Intrusion in New York State Decision Matrices for Sub-slab Vapor and Indoor Air and subsequent updates (2017). Relevant findings are listed below. Total VOC concentrations ranged from 6,279 to 278,781 ?g/m3
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	3/12/2019 8:16:00 AM
Record Upd:	5/28/2019 10:34:00 AM
Updated By:	SMQUANDT
Own Op:	6
Sub Type:	P03
Owner Name:	Daniel Hollander
Owner Company:	Huguenot Partners LLC
Owner Address:	c/o DHA Capital LLC
Owner Addr2:	154 Grand Street, Suite 4S03
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S123658091**

Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Development Partners LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	Huguenot Centre Holdings LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S123658091**

Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

M92 **P&D TRANSPORT - HOT TAR** **NY Spills** **S106126552**
SW **I-95 NB @ MM 5.4** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 1 of 2 in cluster M**

Relative: **Lower**

Actual: **79 ft.**

SPILLS:

Name:	P&D TRANSPORT - HOT TAR
Address:	I-95 NB @ MM 5.4
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308809 / 2003-11-26
Facility ID:	0308809
Facility Type:	ER
DER Facility ID:	265298
Site ID:	329742
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B2
SWIS:	6010
Spill Date:	2003-11-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-11-18
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-18
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	P&D TRANSPORT
Spiller Address:	171 BROWNSTONE AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11-18-03 P&D Transport trailer carrying 5000 gallons of a hot tar product developed several leaks from seams and holes beneath the trailer. The driver, John Culbreath, pulled the vehicle to the shoulder of I-95 NB at mm 5.4 in New Rochelle. The trailer drained hot tar to the road shoulder where it flowed downhill until it cooled

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

	and solidified. Approximatley 200 feet of shoulder where affected before the trailer could be offloaded. DEC called out Castlton Environmental contractors when a company Rep stated that he/she would not sent a second truck to offload the damaged trailer. Castlton contacted Mystic Bulk Carriers and requested their assistance. Mystic provided a heated truck, suitable to offload the cargo and return it to Ownes Corning in Kearny where the load was originally picked up. The P&D damaged trailer was towed off the road to a spot near the I-95 toll plaza. Castlton performed the removal of the solidified tar several days later as they were delayed by heavy rain which created hazardous working conditions on busily traveled I-95. As of 11-18-03, Portland Asphalt indicated that they would pay Caslton directly for the cost of the cleanup. "
Remarks:	"material goes into a manhole which leads to a water way. poss hutchinson river. spill not controlled yet. caller req call back from rep"

All Materials:

Site ID:	329742
Operable Unit ID:	877435
Operable Unit:	01
Material ID:	498725
Material Code:	0018A
Material Name:	tar
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M93 **I-95** **NY Spills** **S102152708**
SW **I-95EB MP54** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.106 mi.
560 ft. **Site 2 of 2 in cluster M**

Relative: **Lower**
Actual: **79 ft.**

SPILLS:

Name:	I-95
Address:	I-95EB MP54
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8700158 / 1987-04-07
Facility ID:	8700158
Facility Type:	ER
DER Facility ID:	105126
Site ID:	121121
DEC Region:	3
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1987-04-07
Investigator:	WEED
Referred To:	Not reported
Reported to Dept:	1987-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle

I-95 (Continued) **S102152708**

Spill Notifier:	Police Department
Cleanup Ceased:	1987-04-07
Cleanup Meets Std:	True
Last Inspection:	1987-04-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-04-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	121121
Operable Unit ID:	904779
Operable Unit:	01
Material ID:	473726
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I94 **GREEN HEAVEN CLEANERS** **NY DRYCLEANERS** **S106437149**
SSW **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
573 ft. **Site 11 of 19 in cluster I**

Relative:
Higher

Actual:
98 ft.

DRYCLEANERS:

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	3/29/1999 12:14:00 PM
Inspection Date:	2000-09-29 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	3/29/1999 12:14:00 PM
Inspection Date:	2001-10-05 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	3/29/1999 12:14:00 PM
Inspection Date:	2002-10-01 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	3/29/1999 12:14:00 PM
Inspection Date:	2003-10-02 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	3/29/1999 12:14:00 PM
Inspection Date:	2004-10-07 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2005-10-13 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2006-10-13 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2007-10-12 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2008-10-16 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2009-10-15 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 3/29/1999 12:14:00 PM
Inspection Date: 2010-11-11 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 4/29/2010 10:15:16 AM
Inspection Date: 2000-09-29 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 4/29/2010 10:15:16 AM
Inspection Date: 2001-10-05 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 4/29/2010 10:15:16 AM
Inspection Date: 2002-10-01 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 4/29/2010 10:15:16 AM
Inspection Date: 2003-10-02 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 4/29/2010 10:15:16 AM

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Inspection Date:	2004-10-07 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2005-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2006-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2007-10-12 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2008-10-16 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2009-10-15 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	4/29/2010 10:15:16 AM
Inspection Date:	2010-11-11 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2/28/2012 4:30:08 PM
Inspection Date:	2000-09-29 08:00:00
Install Date:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2001-10-05 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2002-10-01 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2003-10-02 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE

GREEN HEAVEN CLEANERS (Continued) **S106437149**

City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2004-10-07 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2005-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2006-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2007-10-12 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2008-10-16 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2009-10-15 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2/28/2012 4:30:08 PM
Inspection Date: 2010-11-11 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2000-09-29 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2001-10-05 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2002-10-01 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2003-10-02 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2004-10-07 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2005-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2006-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2007-10-12 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2008-10-16 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2009-10-15 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 5/10/2018 10:08:40 AM
Inspection Date: 2010-11-11 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000
Current Business: Not reported

I95
SSW
< 1/8
0.109 mi.
573 ft.

SIMONETTI CLEANERS
62 CENTRE ST
NEW ROCHELLE, NY 10801

Site 12 of 19 in cluster I

RCRA-VSQG **1000338662**
US AIRS **NYD982531634**
FINDS
ECHO
NY MANIFEST

Relative:
Higher

Actual:
98 ft.

RCRA-VSQG:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	SIMONETTI CLEANERS
Facility address:	62 CENTRE ST NEW ROCHELLE, NY 10801
EPA ID:	NYD982531634
Mailing address:	CENTRE ST NEW ROCHELLE, NY 10801
Contact:	KWANG YUN
Contact address:	CENTRE ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-5350
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KWANG YUN
Owner/operator address:	24 SUMMIT AVE MOUNT VERNON, NY 10550
Owner/operator country:	US
Owner/operator telephone:	914-665-0274
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KWANG YUN
Owner/operator address:	24 SUMMIT AVE MOUNT VERNON, NY 10550
Owner/operator country:	US
Owner/operator telephone:	914-665-0274
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

SIMONETTI CLEANERS (Continued) **1000338662**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: SIMONETTI CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1996-03-21 00:00:00.0
Site name: SIMONETTI CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

SIMONETTI CLEANERS (Continued) **1000338662**

Violation Status: No violations found

US AIRS MINOR:

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR 020000003606156000
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

Envid:	1000338662
Region Code:	02
Programmatic ID:	AIR NY0000003551000298
Facility Registry ID:	110012174805
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012174805

Click Here:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

SIMONETTI CLEANERS (Continued) **1000338662**

ECHO:

Envid:	1000338662
Registry ID:	110012174805
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012174805
Name:	CENTRE CLEANERS
Address:	62 CENTRE STREET
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	SIMONETTI CLEANERS
Address:	62 CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD982531634
Facility Status:	Not reported
Location Address 1:	62 CENTRE AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982531634
Mailing Name:	SIMONETTI CLEANERS
Mailing Contact:	SIMONETTI CLEANERS
Mailing Address 1:	62 CENTRE AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146365350

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/12/2007
Trans1 Recv Date:	05/12/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	000497613SKS

SIMONETTI CLEANERS (Continued) **1000338662**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I96 **SIMONETTI CLEANERS & TAYLORING** **EDR Hist Cleaner** **1020088094**
SSW **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.109 mi.
573 ft. **Site 13 of 19 in cluster I**

Relative: EDR Hist Cleaner
Higher

Actual:
98 ft.

Year:	Name:	Type:
1980	GEM CLEANERS	Drycleaning Plants, Except Rugs
1982	GEM CLEANERS	Drycleaning Plants, Except Rugs
1983	GEM CLEANERS	Drycleaning Plants, Except Rugs
1985	GEM CLEANERS	Drycleaning Plants, Except Rugs
1986	GEM CLEANERS	Drycleaning Plants, Except Rugs
1987	GEM CLEANERS	Drycleaning Plants, Except Rugs
1988	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1989	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1990	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1991	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1992	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1993	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1994	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1995	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1996	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1997	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1998	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1999	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC

SIMONETTI CLEANERS & TAYLORING (Continued) **1020088094**

2000	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2001	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2002	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2003	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2004	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2005	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2006	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2007	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2008	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2009	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2010	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2011	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2012	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2013	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2014	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC

I97 **HACKER MORRIS J & SONS INC** **EDR Hist Auto** **1020903179**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.111 mi.
584 ft. **Site 14 of 19 in cluster I**

Relative: EDR Hist Auto
Higher

Actual:
98 ft.

Year:	Name:	Type:
1969	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1970	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1971	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1972	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1973	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1974	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1975	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1976	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1977	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1978	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1979	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1980	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1982	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1983	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1985	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1986	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1987	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1988	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1989	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1990	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1991	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1992	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1993	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1994	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1995	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1996	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1997	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1998	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1999	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2000	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2001	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2002	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2003	MORRIS J HACKER & SONS INC	General Automotive Repair Shops

HACKER MORRIS J & SONS INC (Continued) **1020903179**

2004	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2005	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2006	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2007	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2008	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2009	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2010	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2011	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2012	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2013	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2014	MORRIS J HACKER & SONS INC	General Automotive Repair Shops

---

I98 **COMMERCIAL PROPERTY** **NY LTANKS** **S116156733**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.111 mi.
584 ft. **Site 15 of 19 in cluster I**

Relative: **Higher**

Actual: **98 ft.**

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	64 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1308480 / 2015-04-28
Facility ID:	1308480
Site ID:	489220
Spill Date:	2013-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-20
Spill Record Last Update:	2015-05-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	64 CENTRE AVE
Spiller County:	999
Spiller Contact:	STEVE MANGELS
Spiller Phone:	(914) 632-2610
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444316
DEC Memo:	"11-20-13: Chris/WCHD call to V.Mc./Dispt.: Closed Unreg. PBS faciliy. Wayne/WCHD to handle. 11/20/2013 1:48:33 PM:: From Chris Lalak to Wayne Schneider via email:: Wayne, Former PBS site 3-137979 Expired in 1992 (removed gasoline tanks) TTF for Underground waste oil tank estimated as a 550 (Ullage leak and they plan to remove the

COMMERCIAL PROPERTY (Continued) **S116156733**

tank.) The Facility is: M. Hacker and Sons. Please get them to register and deal with the TTF jod 04/23/15 HydroEnvironmental Solutions submitted a report documenting the installation of a temporary monitoring well in the location were the LUST was removed. (See report in DecDocs) Trace levels of VOCs & SVOCs in the sample. TG 4-28-15 closed NFA -RDB"

Remarks: ""

All Materials:

Site ID:	489220
Operable Unit ID:	1238809
Operable Unit:	01
Material ID:	2238759
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

I99 **M.J. HACKER & SONS INC.** **NY UST** **U004176847**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.111 mi.
584 ft. **Site 16 of 19 in cluster I**

Relative: **Higher**

Actual: **98 ft.**

WESTCHESTER CO. UST:

Name:	M.J. HACKER & SONS INC.
Address:	64 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-137979 / Unregulated
Operator Name:	Steve Mangels
Owner Name:	Steve Mangels
Owner Street:	64 Centre Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	3a. Closed - Prior to 04/1991
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1973
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel

M.J. HACKER & SONS INC. (Continued) **U004176847**

Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	002
Status:	3a. Closed - Prior to 04/1991
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1980
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	003
Status:	8. Unregistered
Capacity:	500
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	004
Status:	3. Closed - Removed
Capacity:	750
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported

M.J. HACKER & SONS INC. (Continued) **U004176847**

Date Installation:	01/01/1900
Date Perm Closure:	05/12/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	005
Status:	3. Closed - Removed
Capacity:	Not reported
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	05/14/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1979
Date Perm Closure:	03/06/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None

M.J. HACKER & SONS INC. (Continued) **U004176847**

Dispenser: 2. Suction

N100 **CON EDISON MANHOLE 1178** **RCRA NonGen / NLR** **1014918331**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219455**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
591 ft. **Site 1 of 6 in cluster N**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	2010-12-03 00:00:00.0
Facility name:	CON EDISON MANHOLE 1178
Facility address:	HUGUENOT ST & LECOUNT PL MH 1178 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219455
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2010-11-03 00:00:00.0
Site name:	CON EDISON MANHOLE 1178
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004219455
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874912JJK
EPA ID:	NYP004219455
Date Shipped:	11/03/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Quantity: 100 P

NY MANIFEST:
Name: CONSOLIDATED EDISON - MH 1178
Address: HUGUENOT ST & LECOUNT PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004219455
Facility Status: Not reported
Location Address 1: HUGUENOT ST & LE COURT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004219455
Mailing Name: CONSOLIDATED EDISON - MH 1178
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/03/2010
Trans1 Recv Date: 11/03/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004219455
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 006874912JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N101 **CON EDISON** **NJ MANIFEST** **S120676596**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
591 ft. **Site 2 of 6 in cluster N**

Relative: **Higher**
Actual: **88 ft.**

NJ MANIFEST:

EPA Id:	NYP004837407
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472144JJK
EPA ID:	NYP004837407
Date Shipped:	9/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported

CON EDISON (Continued) **S120676596**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N102 **CON EDISON** **RCRA NonGen / NLR** **1019907724**
NE **HUGUENOT ST & LE COUNT PL** **NYP004837407**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
591 ft. **Site 3 of 6 in cluster N**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date form received by agency: 2015-09-11 00:00:00.0
88 ft. Facility name: CON EDISON
Facility address: HUGUENOT ST & LE COUNT PL
NEW ROCHELLE, NY 10801
EPA ID: NYP004837407
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02

CON EDISON (Continued) **1019907724**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-09-11 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

N103 **CON EDISON** **NY MANIFEST** **S119077729**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
591 ft. **Site 4 of 6 in cluster N**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:
Name: CON EDISON
Address: HUGUENOT ST & LE COUNT PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004837407
Facility Status: Not reported
Location Address 1: HUGENOT ST & LECOUNT PL
Code: BP
Location Address 2: V 7723
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004837407
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON (Continued) **S119077729**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/2015
Trans1 Recv Date:	09/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837407
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472144JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N104 **CON EDISON MANHOLE 1181** **RCRA NonGen / NLR** **1014918324**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219380**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
591 ft. **Site 5 of 6 in cluster N**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	2010-12-02 00:00:00.0
Facility name:	CON EDISON MANHOLE 1181
Facility address:	HUGUENOT ST & LECOUNT PL MH 1181 NEW ROCHELLE, NY 10801
EPA ID:	NYP004219380
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2010-11-02 00:00:00.0
Site name:	CON EDISON MANHOLE 1181
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004219380
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874911JJK
EPA ID:	NYP004219380
Date Shipped:	11/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

CON EDISON MANHOLE 1181 (Continued) **1014918324**

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 1181
Address:	HUGUENOT ST & LECOUNT PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004219380
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & LE COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219380
Mailing Name:	CONSOLIDATED EDISON - MH 1181
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/02/2010
Trans1 Recv Date:	11/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219380
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874911JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O105 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016963532**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004365318**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
593 ft. **Site 1 of 11 in cluster O**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-10-24 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004365318
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-09-24 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 4319
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: CENTRE AVE & RELYEA PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004365318
Facility Status: Not reported
Location Address 1: CENTRE AVE & RELYEA PL
Code: BP
Location Address 2: TM 4319
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004365318
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/24/2013
Trans1 Recv Date: 09/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004365318
Trans1 EPA ID: Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694707JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O106 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016965006**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004379020**
< 1/8 **NEW ROCHELLE, NY 10802**
0.112 mi.
593 ft. **Site 2 of 11 in cluster O**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	2013-11-23 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 4319
Facility address:	CENTRE AVE & RELYEA PL NEW ROCHELLE, NY 10802
EPA ID:	NYP004379020
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
88 ft.

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 2013-10-23 00:00:00.0
- Site name: CON EDISON TRANSFORMER MANHOLE: 4319
- Classification: Conditionally Exempt Small Quantity Generator

- Violation Status: No violations found

NY MANIFEST:
- Name: CON EDISON
- Address: CENTRE AVE & RELYEA PL
- City,State,Zip: NEW ROCHELLE, NY 10802
- Country: USA
- EPA ID: NYP004379020
- Facility Status: Not reported
- Location Address 1: CENTRE AVE & RELYEA PL
- Code: BP
- Location Address 2: SB4314
- Total Tanks: Not reported
- Location City: NEW ROCHELLE
- Location State: NY
- Location Zip: 10801
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004379020
- Mailing Name: CON EDISON
- Mailing Contact: CON EDISON
- Mailing Address 1: 4 IRVING PLACE
- Mailing Address 2: 15TH FL
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: Not reported

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693664JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J107 **SPEEDY CLEANERS** **US AIRS** **1006295756**
East **217 NORTH AVENUE** **FINDS** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.113 mi. **NY DRYCLEANERS**
595 ft. **Site 17 of 18 in cluster J**

Relative: **Higher**
Actual: **91 ft.**

US AIRS MINOR:

Envid:	1006295756
Region Code:	02
Programmatic ID:	AIR NY0000003551000344
Facility Registry ID:	110012166921
D and B Number:	Not reported

SPEEDY CLEANERS (Continued) **1006295756**

Primary SIC Code: 7212
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:
Registry ID: 110012166921

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1006295756
Registry ID: 110012166921
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012166921
Name: SPEEDY CLEANERS
Address: 217 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801

DRYCLEANERS:
Name: SPEEDY CLEANERS
Address: 217 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY
Facility ID: 3-5510-00344
Phone Number: 914-654-9082
Region: Not reported
Registration Effective Date: 9/24/2003 13:22:51:203
Inspection Date: 1931-12-03 00:00:00
Install Date: 00/03
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

K108 **SPOKEN ARTS BUILDING (FORMER)** **NY UST** **U003885171**
North **310 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.114 mi.
600 ft. **Site 2 of 12 in cluster K**

Relative: WESTCHESTER CO. UST:
Lower

Name:	SPOKEN ARTS BUILDING (FORMER)
Address:	310 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600705 / Unregulated: <1101 gal. PBS
Operator Name:	Mr. Anthony Blaise
Owner Name:	City Of New Rochelle
Owner Street:	515 North Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1994
Date Perm Closure:	09/01/1994
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Actual:
75 ft.

N109 **TRUMP PLAZA** **NY LTANKS** **S107522540**
NE **175 HUGUENOT STREET** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.115 mi.
605 ft. **Site 6 of 6 in cluster N**

Relative: LTANKS:
Higher

Name:	TRUMP PLAZA
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512575 / 2006-03-08
Facility ID:	0512575
Site ID:	358910
Spill Date:	2006-01-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010

Actual:
88 ft.

TRUMP PLAZA (Continued) **S107522540**

Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-01-30
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-30
Spill Record Last Update:	2006-03-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN MANFREDI
Spiller Phone:	(914) 241-3795
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	307023
DEC Memo:	"3/08/06 See JM associates spill closure report for 05-04821. TG"
Remarks:	""

All Materials:

Site ID:	358910
Operable Unit ID:	1116137
Operable Unit:	01
Material ID:	2106280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	DEVELOPMENT SITE
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0504821 / 2006-03-08
Facility ID:	0504821
Facility Type:	ER
DER Facility ID:	307023
Site ID:	349739
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6010
Spill Date:	2005-07-20
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-07-21

TRUMP PLAZA (Continued) **S107522540**

CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2006-03-08
Spiller Name:	JOHN MANFREDIE
Spiller Company:	NEW ROCHELLE #1A
Spiller Address:	HUGIGNOT /LAACONTA
Spiller Company:	001
Contact Name:	JOHN MANFREDIE
DEC Memo:	"3/02/06 UST removal report submitted by JM Associates including information about two other spill reports listed for the same parcel, 05-10932 and 05-12575. A total of 5 UST's were removed along with 3,351.05 tons of petroleum impacted soil. Based on the information contained in the report, no further action is required. TG"
Remarks:	"DURING EXCAVATION FOUND AN ABANDON TANK: AND FOUND CONTAMINATED SOIL"
	Not reported

All Materials:

Site ID:	349739
Operable Unit ID:	1107327
Operable Unit:	01
Material ID:	2097217
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	TRUMP PLAZA
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510932 / 2005-12-19
Facility ID:	0510932
Facility Type:	ER
DER Facility ID:	307023
Site ID:	356986
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-12-19
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported

TRUMP PLAZA (Continued) **S107522540**

Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2006-03-08
Spiller Name:	SEAN MCKAY
Spiller Company:	TRUMP PLAZA
Spiller Address:	175 HUEGOTNOT STREET
Spiller Company:	001
Contact Name:	SEAN MCKAY
DEC Memo:	"CONFIRMED CLEANUP WITH WCDOH 3/8/06 See spill JM Associates closure report for 05-04821"
Remarks:	"SPILL AROUND GENERATOR AND IN PROCESS OF BEING CLEANED UP;"

All Materials:

Site ID:	356986
Operable Unit ID:	1114275
Operable Unit:	01
Material ID:	2104355
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I110 **NYNEX LOCATION** **NY LTANKS** **S102660218**
SSW **342 HUEGNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.115 mi.
608 ft. **Site 17 of 19 in cluster I**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	NYNEX LOCATION
Address:	342 HUEGNOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9708146 / 1997-10-10
Facility ID:	9708146
Site ID:	270876
Spill Date:	1997-10-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	365
Water Affected:	Not reported

NYNEX LOCATION (Continued) **S102660218**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1997-11-12
Spiller Name:	RICH KALISTA
Spiller Company:	BELL ATLANTIC
Spiller Address:	2203 MCCONNELL ST
Spiller County:	001
Spiller Contact:	TOM MUFF
Spiller Phone:	(914) 449-5321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220510
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DOING AN UPGRADE FOR A NYNEX LOCATION AND REMOVING 2 UNDERGROUND TANKS FROM A BASEMENT - TANKS WERE ENCASED BY SAND & WHEN REMOVED THE SAND WAS CONTAMINATED - THEY HAVE REMOVED SAND."

All Materials:

Site ID:	270876
Operable Unit ID:	1051372
Operable Unit:	01
Material ID:	330133
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I111 **VERIZON** **NY Spills** **S106867403**
SSW **342 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.115 mi.
608 ft. **Site 18 of 19 in cluster I**

Relative: **Higher**

Actual: **95 ft.**

SPILLS:

Name:	VERIZON
Address:	342 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413326 / 2005-09-11
Facility ID:	0413326
Facility Type:	ER
DER Facility ID:	288752
Site ID:	342403
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-03-22

VERIZON (Continued) **S106867403**

Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-22
Spill Record Last Update:	2005-09-11
Spiller Name:	CLAUDIA
Spiller Company:	VERIZON
Spiller Address:	342 HUGUENOT ST.
Spiller Company:	001
Contact Name:	CLAUDIA
DEC Memo:	"September 11, 2005: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank is tight has a bad vent line. Will be replacing the vent line."

All TTF:

Facility ID:	0413326
Spill Number:	0413326
Spill Tank Test:	1548716
Site ID:	342403
Tank Number:	6
Tank Size:	6000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	342403
Operable Unit ID:	1101130
Operable Unit:	01
Material ID:	581261
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I112 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000553730**
SSW **342 HUGUENOT ST** **NY MANIFEST** **NYD986961605**
< 1/8 **NEW ROCHELLE, NY 10801**
0.115 mi.
608 ft. **Site 19 of 19 in cluster I**

Relative:
Higher

Actual:
95 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	NEW YORK TELEPHONE CO
Facility address:	342 HUGUENOT ST NEW ROCHELLE, NY 10801
EPA ID:	NYD986961605
Mailing address:	NINTH AVE NEW YORK, NY 10001
Contact:	CATHERINE ROM
Contact address:	NINTH AVE NEW YORK, NY 10001
Contact country:	US
Contact telephone:	212-502-7694
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK TELEPHONE CO
Owner/operator address:	342 HUGUENOT ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-9964
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK TELEPHONE CO
Owner/operator address:	342 HUGUENOT ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-9964
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

NEW YORK TELEPHONE CO (Continued) **1000553730**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

Date form received by agency: 1991-07-02 00:00:00.0
Site name: NEW YORK TELEPHONE CO
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

NY MANIFEST:
Name: TELESECTOR RESOURCES GROUP
Address: 342 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYD986961605
Facility Status: Not reported
Location Address 1: 342 HUGANAUGHT STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WESTCHESTER
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986961605
Mailing Name: TELESECTOR RESOURCES GROUP
Mailing Contact: WAYNE SEBRO
Mailing Address 1: 441 9TH AVENUE 5TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10001
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2125027694

NEW YORK TELEPHONE CO (Continued) **1000553730**

NY MANIFEST:

Document ID:	ILA7651009
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	1478
Trans2 State ID:	2075
Generator Ship Date:	10/23/1997
Trans1 Recv Date:	10/23/1997
Trans2 Recv Date:	10/23/1997
TSD Site Recv Date:	10/29/1997
Part A Recv Date:	11/26/1997
Part B Recv Date:	11/20/1997
Generator EPA ID:	NYD986961605
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	NJD000813477
TSDF ID 1:	ILD000608471
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

K113 **NORTH GARDEN ASSOCIATES LLC** **NY UST** **U004177039**
North **309-311 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.116 mi.
614 ft. **Site 3 of 12 in cluster K**

Relative: **Lower**
Actual: **74 ft.**

WESTCHESTER CO. UST:

Name:	NORTH GARDEN ASSOCIATES LLC
Address:	309-311 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-496928 / Active
Operator Name:	Harrin Platzner
Owner Name:	North Garden Associates LLC
Owner Street:	P.O Box 111
Owner Address2:	309-311 North Avenue
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/15/1947
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	2. Suction

O114 **APPAREL PLUS** **NY Spills** **S116156116**
SW **27 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.118 mi.
624 ft. **Site 3 of 11 in cluster O**

Relative: **Higher**
Actual: **88 ft.**

SPILLS:

Name:	APPAREL PLUS
Address:	27 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1309988 / 2014-01-14
Facility ID:	1309988
Facility Type:	ER
DER Facility ID:	445839
Site ID:	490810
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010

APPAREL PLUS (Continued) **S116156116**

Spill Date:	2014-01-14
Investigator:	DXWEITZ
Referred To:	Not reported
Reported to Dept:	2014-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-14
Spill Record Last Update:	2014-01-14
Spiller Name:	CHRIS LALAK
Spiller Company:	APPAREL PLUS LAUNDRY
Spiller Address:	27 CENTRE AVE
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"1/14/14 Chris Lalak from WCHD called and said that this was motor oil from a truck in the parking lot. People at the laundry did the cleanup. According to Chris Lalak, the spill can be closed. They were there for other reasons. NFA dw"
Remarks:	"loss to sewer. c/u in progress"

All Materials:

Site ID:	490810
Operable Unit ID:	1240364
Operable Unit:	01
Material ID:	2240510
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

P115 **SPILL NUMBER 9900400** **NY Spills** **S104648843**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.119 mi.
630 ft. **Site 1 of 20 in cluster P**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	535 MAIN ST ASSOCIATION
Address:	535 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9415294 / 1995-03-03
Facility ID:	9415294
Facility Type:	ER
DER Facility ID:	205781
Site ID:	251083
DEC Region:	3

SPILL NUMBER 9900400 (Continued) **S104648843**

Spill Cause:	Human Error
Spill Class:	D4
SWIS:	6010
Spill Date:	1995-02-17
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER DID NOT HEAR VENT ALARM AND OVERFILLED TANK REGENT OIL CLEANED UP"

All Materials:

Site ID:	251083
Operable Unit ID:	1012611
Operable Unit:	01
Material ID:	370473
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 9900400
Address:	535 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9900400 / 1999-07-09
Facility ID:	9900400
Facility Type:	ER
DER Facility ID:	75076
Site ID:	81102
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-04-08
Investigator:	jbodee

SPILL NUMBER 9900400 (Continued) **S104648843**

Referred To:	Not reported
Reported to Dept:	1999-04-12
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-12
Spill Record Last Update:	2004-02-24
Spiller Name:	MR GOLDBERG
Spiller Company:	MR GOLDBERG
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MR GOLDBERG
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/9/99 SPILL CLEANED BY TOWN & COUNTRYF OIL. NFA"
Remarks:	"FAULTY VENT ALARM - SPILLED LESS THAN 1 GAL - CLEANED UP - TENANTS STILL COMPLAINING OF ODORS"

All Materials:

Site ID:	81102
Operable Unit ID:	1075164
Operable Unit:	01
Material ID:	307538
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P116 **SIDNEY FURNITURE** **NY Spills** **S118460140**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.119 mi.
630 ft. **Site 2 of 20 in cluster P**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	SIDNEY FURNITURE
Address:	535 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1509029 / 2015-12-04
Facility ID:	1509029
Facility Type:	ER
DER Facility ID:	75076
Site ID:	517634
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010

SIDNEY FURNITURE (Continued) **S118460140**

Spill Date:	2015-12-03
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-04
Spill Record Last Update:	2015-12-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHELLE GUERRERO
DEC Memo:	"12/04/15: Caller states she is at work, states she is pregnant, and states that they were working on the furnace and there was a small oil spill. She wanted to know if oil spills are hazardous. I was in the process of answering her questions and she hung up. Westchester County Dept of Health notified. No further DEC action. jod"
Remarks:	"Caller advised aprx 1/2 gal of oil spilled onto carpet. Clean up is pending. Caller is requesting a call back"

All Materials:

Site ID:	517634
Operable Unit ID:	1266703
Operable Unit:	01
Material ID:	2270652
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

K117 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157674**
North **F/O 311 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.120 mi.
634 ft. **Site 4 of 12 in cluster K**

Relative: **Lower**

Actual: **74 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	F/O 311 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004230306
Facility Status:	Not reported
Location Address 1:	F/O 311 NORTH AVE

CONSOLIDATED EDISON (Continued) **S111157674**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230306
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2011
Trans1 Recv Date:	03/10/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230306
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655968JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CONSOLIDATED EDISON (Continued) **S111157674**

Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J118 **CATHOLIC NEWS PUBLISHING** **NY LTANKS** **S106972587**
ESE **210 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
635 ft. **Site 18 of 18 in cluster J**

Relative: LTANKS:
Higher

Name:	CATHOLIC NEWS PUBLISHING
Address:	210 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0503023 / 2005-08-28
Facility ID:	0503023
Site ID:	347516
Spill Date:	2005-06-13
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-13
CID:	44
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-13
Spill Record Last Update:	2005-08-28
Spiller Name:	MYLES RIDDER
Spiller Company:	CATHOLIC NEWS PUBLISHING
Spiller Address:	210 NORTH AVE
Spiller County:	001
Spiller Contact:	MYLES RIDDER
Spiller Phone:	(914) 632-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293840
DEC Memo:	"August 28, 2005: NORTHEAT DISPOSED OF LUST AND 48.90 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"

Actual:
91 ft.

CATHOLIC NEWS PUBLISHING (Continued) **S106972587**

Remarks: "1000 GALLON TANK AND HOLES IN TANK"

All Materials:

Site ID:	347516
Operable Unit ID:	1105241
Operable Unit:	01
Material ID:	1502620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L119 **COMMERCIAL - UST** **NY Spills** **S121119478**
NNW **35 GRAND STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
636 ft. **Site 3 of 5 in cluster L**

Relative: **Lower**

Actual: **76 ft.**

SPILLS:

Name:	COMMERCIAL - UST
Address:	35 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1706607 / 2018-04-05
Facility ID:	1706607
Facility Type:	ER
DER Facility ID:	514557
Site ID:	560927
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B4
SWIS:	6010
Spill Date:	2017-10-06
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2017-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-10-06
Spill Record Last Update:	2018-04-05
Spiller Name:	Not reported
Spiller Company:	The Luxuria
Spiller Address:	35 GRAND STREET
Spiller Company:	999
Contact Name:	GARY GIGLIO
DEC Memo:	"10/6/17 - A 1k gal. UST was removed. Laboratory soil post excavation

COMMERCIAL - UST (Continued) **S121119478**

samples were collected. TCR will be submitted to the DEC. KAB 4/5/18: VMT Environmental removed the leaking UST and disposed of a total of 269 tons of petroleum contaminated soil. Report from Performer Compliance submitted to DEC has been reviewed and entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"

Remarks: "underground 1,000 gallon oil tank. clean up is on going."

All TTF:

Facility ID:	1706607
Spill Number:	1706607
Spill Tank Test:	2504339
Site ID:	560927
Tank Number:	UST
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	560927
Operable Unit ID:	1308916
Operable Unit:	01
Material ID:	2315940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

P120 **NOVA REALTY - UST** **NY Spills** **S123660999**
SSE **523 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.121 mi.
638 ft. **Site 3 of 20 in cluster P**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Name:	NOVA REALTY - UST
Address:	523 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1811358 / Not Reported
Facility ID:	1811358
Facility Type:	ER
DER Facility ID:	534783
Site ID:	582291
DEC Region:	3

NOVA REALTY - UST (Continued) **S123660999**

Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2019-02-11
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2019-02-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2019-02-11
Spill Record Last Update:	2020-05-04
Spiller Name:	BRIAN HEAPS
Spiller Company:	Nova Realty
Spiller Address:	523 MAIN ST
Spiller Company:	001
Contact Name:	BRAIN HEAPS
DEC Memo:	"2/11/19 Northeastern Env. was hired to do vac out of UST under basement floor - owners thought there was water in the tank. Northeastern found oil in the sump. That has been vacuumed out. Tank is under concrete floor of basement. No waterways on property, no drains other than sump. Tank to be removed to do further investigation and cleanup. Site is hair salon. Left message for property contact to call duty desk. ga 2/11/19 Owner to hire Northeastern to remove tank and do any cleanup. Property on municipal water. ga 5/04/2020: Message sent to Northeast requesting an update. jod"
Remarks:	"oil found in sump. investigation and c/u ongoing"

All Materials:

Site ID:	582291
Operable Unit ID:	1329976
Operable Unit:	01
Material ID:	2339121
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Q121
ENE
< 1/8
0.122 mi.
645 ft.

CON EDISON
LECOUNT PL & ANDERSON ST
NEW ROCHELLE, NY 10801

Site 1 of 4 in cluster Q

NJ MANIFEST **S120672272**
N/A

Relative:
Higher

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004788378
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014467901JJK
EPA ID:	NYP004788378
Date Shipped:	5/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120672272**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q122 **CON EDISON** **RCRA NonGen / NLR** **1019903661**
ENE **LECOUNT PL & ANDERSON ST** **FINDS** **NYP004788378**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.122 mi.
645 ft. **Site 2 of 4 in cluster Q**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-05-30 00:00:00.0
Facility name:	CON EDISON
Facility address:	LECOUNT PL & ANDERSON ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004788378
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-05-30 00:00:00.0
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019903661**

Registry ID: 110069670270

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903661
Registry ID:	110069670270
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069670270
Name:	CON EDISON
Address:	LECOUNT PL & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801

Q123 **CON EDISON** **NY MANIFEST** **S119075589**
ENE **LECOUNT PL & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.122 mi.
645 ft. **Site 3 of 4 in cluster Q**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	LECOUNT PL & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004788378
Facility Status:	Not reported
Location Address 1:	LECOUTN PL & MAIN ST
Code:	BP
Location Address 2:	SB 1996
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004788378
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S119075589**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2015
Trans1 Recv Date:	05/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004788378
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467901JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P124 **LILLIAN VERNON CORPORATION** **NY UST** **U003994695**
SSE **543-549 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
647 ft. **Site 4 of 20 in cluster P**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. UST:

Name:	LILLIAN VERNON CORPORATION
Address:	543-549 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600279 / Unregulated: <1101 gal. PBS
Operator Name:	Joseph F. Dimicco
Owner Name:	Lillian Vernon Corp.
Owner Street:	510 South Fulton Ave
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10550
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

P125 **BLUE GILL REALTY** **NY LTANKS** **S102152290**
SSE **543 MAIN ST** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
647 ft. **Site 5 of 20 in cluster P**

Relative: **Higher**
Actual: **100 ft.**

LTANKS:

Name:	BLUE GILL REALTY
Address:	543 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308082 / 2004-05-12
Facility ID:	0308082
Site ID:	94435
Spill Date:	2003-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010

BLUE GILL REALTY (Continued) **S102152290**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-10-30
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-05-19
Spiller Name:	JEFF WEIR
Spiller Company:	BLUE GILL REALTY
Spiller Address:	543 MAIN ST
Spiller County:	001
Spiller Contact:	JEFF WEIR
Spiller Phone:	(646) 435-8110
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	84546
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MAGNUSON 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #9212475. Letter has PBS #3-801106."
Remarks:	"TANK HAS BEEN REMOVED."

All TTF:

Facility ID:	0308082
Spill Number:	0308082
Spill Tank Test:	1528780
Site ID:	94435
Tank Number:	1
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	94435
Operable Unit ID:	876585
Operable Unit:	01
Material ID:	501599
Material Code:	0001A
Material Name:	#2 fuel oil

BLUE GILL REALTY (Continued) **S102152290**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	LILLIAN VERNON CORP.
Address:	543 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9212475 / 2004-05-12
Facility ID:	9212475
Facility Type:	ER
DER Facility ID:	108333
Site ID:	125220
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	1993-02-03
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2004-05-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #0308082."
Remarks:	"FUEL OIL LINE HAS PIN HOLE LEAK DISCOVERED IN EXCAVATION BY EMER.ENVIRO. SERVICE TODAY REMOTE FILL LINE 2 VERY BADLY PITTED AND CORRODED WILL DRILL WELL 2/4/93"

All Materials:

Site ID:	125220
Operable Unit ID:	976940
Operable Unit:	01
Material ID:	402326

BLUE GILL REALTY (Continued) **S102152290**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

P126 **543 MAIN STREET** **NY UST** **U003994286**
SSE **543 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
647 ft. **Site 6 of 20 in cluster P**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. UST:

Name:	543 MAIN STREET
Address:	543 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-801106 / Unregulated: <1101 gal. PBS
Operator Name:	Paul Risse
Owner Name:	Bluegill Realty, LLC
Owner Street:	250 West 30th Street
Owner Address2:	Not reported
Owner City:	NY
Owner State:	NY
Owner Zipcode:	10001
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	2500
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/07/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

P127 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243060**
SSE **DIVISION & MAIN** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.123 mi.
651 ft. **Site 7 of 20 in cluster P**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	DIVISION & MAIN
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004123873
Facility Status:	Not reported
Location Address 1:	DIVISION & MAIN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004123873
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1309977
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	47651JM
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2004
Trans1 Recv Date:	08/28/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004123873
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

CONSOLIDATED EDISON (Continued) **1009243060**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

P128 **CON EDISON - TRANSFORMER MANHOLE 3307** **RCRA-LQG** **1019325947**
SSE **DIVISION ST & MAIN ST** **NYP004872319**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
651 ft. **Site 8 of 20 in cluster P**

Relative: **Higher**

Actual: **99 ft.**

RCRA-LQG:

Date form received by agency:	2016-02-26 00:00:00.0
Facility name:	CON EDISON - TRANSFORMER MANHOLE 3307
Facility address:	DIVISION ST & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004872319
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2015-11-23 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2015-11-23 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 9020

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Violation Status: No violations found

P129 **CON EDISON** **NY MANIFEST** **S118464238**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
651 ft. **Site 9 of 20 in cluster P**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DIVISION ST & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004872319
Facility Status:	Not reported
Location Address 1:	DIVISION ST & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004872319
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/23/2015
Trans1 Recv Date:	11/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004872319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245368JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S118464238**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9020
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P130 **CON EDISON - TRANSFORMER MANHOLE 3307** **NJ MANIFEST** **S120677907**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
651 ft. **Site 10 of 20 in cluster P**

Relative: **Higher**

Actual: **99 ft.**

NJ MANIFEST:

EPA Id:	NYP004872319
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	013245368JJK
EPA ID:	NYP004872319
Date Shipped:	11/23/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **S120677907**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K131 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016963395**
North **313 NORTH AVE FRONT OF** **NYP004364030**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
654 ft. **Site 5 of 12 in cluster K**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	2013-10-20 00:00:00.0
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	313 NORTH AVE FRONT OF NEW ROCHELLE, NY 10801
EPA ID:	NYP004364030
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

Actual:
74 ft.

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-09-20 00:00:00.0
Site name: CON EDISON MANHOLE: 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

R132 **75 CENTRE AVENUE LLC** **NY UST U004175967**
South **75 CENTRE AVENUE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.125 mi.
661 ft. **Site 1 of 16 in cluster R**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:
Name: 75 CENTRE AVENUE LLC
Address: 75 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-800240 / Active
Operator Name: Dino Rentoulis
Owner Name: John & Dino Rentoulis
Owner Street: P.O. Box 330
Owner Address2: Not reported
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10605
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron

75 CENTRE AVENUE LLC (Continued) **U004175967**

Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

Name:	75 CENTRE AVENUE LLC
Address:	75 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800240
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	P.O. Box 330
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605

Tank Number:	002
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

R133 **CENTRE-MAIN ASSOCIATES** **NY LTANKS** **S106123770**
South **75 - 77 CENTER AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.125 mi.
661 ft. **Site 2 of 16 in cluster R**

Relative: **Higher**

Actual: **99 ft.**

LTANKS:

Name:	CENTRE-MAIN ASSOCIATES
Address:	75 - 77 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0311823 / 2004-12-30

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

Facility ID:	0311823
Site ID:	149369
Spill Date:	2004-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-21
CID:	44
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2005-01-10
Spiller Name:	ED
Spiller Company:	Not reported
Spiller Address:	75 - 77 CENTER AVE
Spiller County:	001
Spiller Contact:	ED
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127066
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 1/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson, WCDOH dated 30Dec2004. WCDOH requires NFA at this time."
Remarks:	"recommend, uncover repair and retest. Tank is bolted in basement."

All TTF:

Facility ID:	0311823
Spill Number:	0311823
Spill Tank Test:	1528926
Site ID:	149369
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	149369

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

Operable Unit ID:	877137
Operable Unit:	01
Material ID:	497066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O134 **MR CHIMNEY CLEAN** **RCRA NonGen / NLR** **1004758604**
SSW **32 RELYEA PL** **FINDS** **NYD987011855**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.125 mi. **NY MANIFEST**
661 ft. **Site 4 of 11 in cluster O**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	MR CHIMNEY CLEAN
Facility address:	32 RELYEA PL NEW ROCHELLE, NY 10801
EPA ID:	NYD987011855
Mailing address:	RELYEA PL NEW ROCHELLE, NY 10801
Contact:	MAURICE MCKENNA
Contact address:	RELYEA PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-632-6660
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NAUAL MOTION PICTURES
Owner/operator address:	270 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-2406
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NAUAL MOTION PICTURES
Owner/operator address:	270 MAIN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-632-2406
Owner/operator email:	Not reported

MR CHIMNEY CLEAN (Continued) **1004758604**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: MR CHIMNEY CLEAN
Classification: Not a generator, verified

Date form received by agency: 1994-06-01 00:00:00.0
Site name: MR CHIMNEY CLEAN
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

FINDS:
Registry ID: 110004493922

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MR CHIMNEY CLEAN (Continued) **1004758604**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758604
Registry ID:	110004493922
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004493922
Name:	MR CHIMNEY CLEAN
Address:	32 RELYEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	NAVAL MOTION PICTURE SERVICE
Address:	32 RELYEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD987011855
Facility Status:	Not reported
Location Address 1:	270 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987011855
Mailing Name:	NAVAL MOTION PICTURE SERVICE
Mailing Contact:	PAUL RAMOS
Mailing Address 1:	270 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	CTF0276746
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/1994
Trans1 Recv Date:	06/23/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/27/1994
Part A Recv Date:	/ /
Part B Recv Date:	07/11/1994
Generator EPA ID:	NYD987011855
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported

MR CHIMNEY CLEAN (Continued) **1004758604**

TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Q135 **MACYS** **NY MANIFEST** **1009232715**
ENE **33 LE COUNT PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.127 mi.
670 ft. **Site 4 of 4 in cluster Q**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	MACYS
Address:	33 LE COUNT PLACE
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP000890137
Facility Status:	Not reported
Location Address 1:	33 LE COUNT PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000890137
Mailing Name:	MACYS
Mailing Contact:	MACYS
Mailing Address 1:	33 LE COUNT PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY

MACYS (Continued) **1009232715**

Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337700

NY MANIFEST:

Document ID:	NYA7026894
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	06/22/1989
Trans1 Recv Date:	06/22/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/22/1989
Part A Recv Date:	08/03/1989
Part B Recv Date:	06/29/1989
Generator EPA ID:	NYP000890137
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

K136 **4 STORY APARTMENT BUILDING** **NY UST** **U003883840**
North **320 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.127 mi.
670 ft. **Site 6 of 12 in cluster K**

Relative: WESTCHESTER CO. UST:
Lower

Actual: Name: 4 STORY APARTMENT BUILDING
72 ft. Address: 320 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-600732 / Unregulated: <1101 gal. PBS
Operator Name: City Of New Rochelle
Owner Name: City Of New Rochelle
Owner Street: 515 North Avenue
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 1500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 09/01/1961
Date Perm Closure: 02/28/1995
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 12. Double-Walled (AST only)
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 1. Float Vent Valve
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 0. None

Tank Number: 2
Status: 3. Closed - Removed
Capacity: 550
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1949
Date Perm Closure: 02/28/1995
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/underground combination
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 1. Float Vent Valve

4 STORY APARTMENT BUILDING (Continued) **U003883840**

Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 0. None

P137 **COMMERCIAL PROPERTY** **NY LTANKS** **S111012266**
SSE **522 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.128 mi.
678 ft. **Site 11 of 20 in cluster P**

Relative: **Higher**
Actual: **98 ft.**

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	522 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1100723 / 2011-06-06
Facility ID:	1100723
Site ID:	448142
Spill Date:	2011-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-20
Spill Record Last Update:	2011-06-06
Spiller Name:	PETER OH
Spiller Company:	ADELPHI
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JEFF
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402739
DEC Memo:	"Spoke to Georgia at Advanced. Soil boring had field evidence of petroleum impact. DT 4/20/11 6/6/11: Report from Preferred Environmental entered into eDocs. NFA jod"
Remarks:	"1721 THE CALLER ADVISED DISPATCH THEY ARE AWAITING TANK TEST RESULTS."

All Materials:

Site ID:	448142
Operable Unit ID:	1198388
Operable Unit:	01
Material ID:	2194662
Material Code:	0001A
Material Name:	#2 fuel oil

COMMERCIAL PROPERTY (Continued) **S111012266**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

P138 **NEW ROCHELLE SUPERMARKET CORP.** **NY AST** **A100204374**
SSE **538 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.129 mi.
679 ft. **Site 12 of 20 in cluster P**

Relative:
Higher

Actual:
100 ft.

WESTCHESTER CO. AST:

Name:	NEW ROCHELLE SUPERMARKET CORP.
Address:	538 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-166995
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Andrew Taveras
Owner Name:	New Rochelle Supermarket Corp.
Owner Street:	538 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/09/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

R139 **MAISON 347 LLC** **NY UST** **U004274867**
SSW **347 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.129 mi.
683 ft. **Site 3 of 16 in cluster R**

Relative: **Higher**
Actual: **94 ft.**

WESTCHESTER CO. UST:

Name:	MAISON 347 LLC
Address:	347 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-502626 / Active
Operator Name:	Maison 347 LLC
Owner Name:	Maison 347 LLC
Owner Street:	347 Huguenot St
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1995
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

P140 **542 MAIN STREET LLC** **NY UST** **U003917838**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.130 mi.
686 ft. **Site 13 of 20 in cluster P**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. UST:

Name:	542 MAIN STREET LLC
Address:	542 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-800617 / Active
Operator Name:	Cornell Pace Inc.
Owner Name:	542 Main Street LLC
Owner Street:	542 Main Street, 2nd Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

542 MAIN STREET LLC (Continued) **U003917838**

Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1904
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	2. Rubber liner
Tank External Protection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

P141 **OFFICE BLDG** **NY LTANKS** **S107489194**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
686 ft. **Site 14 of 20 in cluster P**

Relative: **Higher**

Actual: **100 ft.**

LTANKS:

Name:	OFFICE BLDG
Address:	542 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0509995 / 2006-03-22
Facility ID:	0509995
Site ID:	355877
Spill Date:	2005-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2005-11-21
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-03-22
Spiller Name:	UNKNOWN
Spiller Company:	OFFICE BLDG
Spiller Address:	542 MAIN STREET
Spiller County:	001
Spiller Contact:	UNKNOWN

OFFICE BLDG (Continued) **S107489194**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305921
DEC Memo:	"March 22, 2006 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	""

All TTF:

Facility ID:	0509995
Spill Number:	0509995
Spill Tank Test:	1549528
Site ID:	355877
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	355877
Operable Unit ID:	1113209
Operable Unit:	01
Material ID:	2103275
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S142 **COMMERCIAL BUILDING** **NY LTANKS** **S100177795**
SE **507 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
687 ft. **Site 1 of 5 in cluster S**

Relative:
Higher

Actual:
96 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	507 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9110835 / 1992-03-10
Facility ID:	9110835
Site ID:	286303
Spill Date:	1992-01-17
Spill Cause:	Tank Failure

COMMERCIAL BUILDING (Continued) **S100177795**

Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-02-06
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	1992-02-06
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-23
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	EPHRAIM ASSOC.
Spiller Address:	300 EAST 74TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	232045
DEC Memo:	""
Remarks:	"BANK AGREEMENT ASSESMENT REVEALED 1K #2 FUEL TANK 12 IN CONCRETE REMAINDER A/G IN BRICK VAULT TANK PULLED TODAY WITH ONE HOLE IN BOTTOM CONCRETE SLAB NOT CRACKED WILL PULL AND INSPECT ON MONDAY"

All Materials:

Site ID:	286303
Operable Unit ID:	960971
Operable Unit:	01
Material ID:	415913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

143
NW
1/8-1/4
0.130 mi.
687 ft.

CON EDISON
19 DIVISION ST & WASHINGTON AVE
NEW ROCHELLE, NY 10801

RCRA NonGen / NLR **1019904602**
FINDS **NYP004800058**
ECHO

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-06-28 00:00:00.0
Facility name:	CON EDISON
Facility address:	19 DIVISION ST & WASHINGTON AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004800058

CON EDISON (Continued) **1019904602**

Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-06-28 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:
Registry ID: 110069642630

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019904602
Registry ID: 110069642630
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069642630
Name: CON EDISON
Address: 19 DIVISION ST & WASHINGTON AVE

CON EDISON (Continued) **1019904602**

City,State,Zip: NEW ROCHELLE, NY 10801

P144 **CON EDISON TRANSFORMER MANHOLE: 3586** **RCRA NonGen / NLR** **1016974043**
SE **CHURCH ST & MAIN ST** **NY MANIFEST** **NYP004478517**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.130 mi.
688 ft. **Site 15 of 20 in cluster P**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:
Date form received by agency: 2014-04-25 00:00:00.0
Facility name: CON EDISON TRANSFORMER MANHOLE: 3586
Facility address: CHURCH ST & MAIN ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004478517
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2014-03-25 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 3586
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: CHURCH ST & MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004478517
Facility Status: Not reported

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Location Address 1:	CHURCH MAIN ST
Code:	BP
Location Address 2:	SB3586
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004478517
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/2014
Trans1 Recv Date:	03/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478517
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770521JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P145 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963458**
SE **MAIN ST & CHRUCH ST** **NY MANIFEST** **NYP004364576**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.130 mi.
688 ft. **Site 16 of 20 in cluster P**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-10-23 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5042
Facility address:	MAIN ST & CHRUCH ST
	NEW ROCHELLE, NY 10801
EPA ID:	NYP004364576
Mailing address:	IRVING PL, 15TH FL NE
	NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Historical Generators:
Date form received by agency: 2013-09-23 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 5042
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: MAIN ST & CHRUCH ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004364576
Facility Status: Not reported
Location Address 1: MAINS T & CHURCH ST
Code: BP
Location Address 2: TM 5042
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004364576
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/23/2013
Trans1 Recv Date: 09/23/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004364576
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694706JJK
Import Indicator: N
Export Indicator: N

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P146 **CON EDISON MANHOLE: 12758** **RCRA NonGen / NLR** **1016974052**
SE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004478624**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.130 mi.
688 ft. **Site 17 of 20 in cluster P**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-04-25 00:00:00.0
Facility name:	CON EDISON MANHOLE: 12758
Facility address:	MAIN ST & CHURCH ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004478624
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-03-25 00:00:00.0
Site name:	CON EDISON MANHOLE: 12758
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	MAIN ST & CHURCH ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004478624
Facility Status:	Not reported
Location Address 1:	MAIN & CHURCH ST
Code:	BP
Location Address 2:	SB12758
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004478624
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/2014

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Trans1 Recv Date:	03/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478624
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770524JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P147 **CON EDISON** **NY MANIFEST** **S117535683**
SE **MAIN ST & CHURCH ST** **N/A**
1/8-1/4 **OSSINING, NY 10801**
0.130 mi.
688 ft. **Site 18 of 20 in cluster P**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	MAIN ST & CHURCH ST
City,State,Zip:	OSSINING, NY 10801
Country:	USA
EPA ID:	NYP004680070
Facility Status:	Not reported
Location Address 1:	MAIN ST & CHURCH ST
Code:	BP
Location Address 2:	MH2419

Actual:
97 ft.

CON EDISON (Continued) **S117535683**

Total Tanks:	Not reported
Location City:	OSSINING
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004680070
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2014
Trans1 Recv Date:	10/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680070
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774891JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds

CON EDISON (Continued) **S117535683**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R148 **COCO RESIDENCE** **NY LTANKS** **S106123934**
South **81 CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.133 mi.
700 ft. **Site 4 of 16 in cluster R**

Relative: LTANKS:
Higher

Actual:
100 ft.

Name:	COCO RESIDENCE
Address:	81 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0311339 / 2005-01-10
Facility ID:	0311339
Site ID:	313391
Spill Date:	2004-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-07
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-07
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ED COCO
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 01/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson dated 9Feb2004(?). WCDOH requires NFA at this time."
Remarks:	"Failed test. Unknown if the tank is leaking"

COCO RESIDENCE (Continued) **S106123934**

All TTF:

Facility ID:	0311339
Spill Number:	0311339
Spill Tank Test:	1528899
Site ID:	313391
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313391
Operable Unit ID:	878986
Operable Unit:	01
Material ID:	500153
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T149 **CON EDISON** **RCRA NonGen / NLR** **1019902313**
ESE **205 NORTH AVE** **NYP004772265**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
711 ft. **Site 1 of 6 in cluster T**

Relative: **Higher**

Actual: **91 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-04-22 00:00:00.0
Facility name:	CON EDISON
Facility address:	205 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004772265
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON (Continued) **1019902313**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 2015-04-22 00:00:00.0
- Site name: CON EDISON
- Classification: Small Quantity Generator

Violation Status: No violations found

T150 **CON EDISON** **NJ MANIFEST** **S120670860**
ESE **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
711 ft. **Site 2 of 6 in cluster T**

Relative: **Higher**

Actual: **91 ft.**

NJ MANIFEST:
- EPA Id: NYP004772265
- Mail Address: IRVING PL 15TH FL NE
- Mail City/State/Zip: NEW YORK, NY 10003
- Facility Phone: Not reported
- Emergency Phone: Not reported
- Contact: THOMAS TEELING
- Comments: Not reported
- SIC Code: Not reported
- County: NY119
- Municipal: Not reported
- Previous EPA Id: Not reported
- Gen Flag: Not reported
- Trans Flag: Not reported
- TSDF Flag: Not reported
- Name Change: Not reported
- Date Change: Not reported

Manifest:
- Manifest Number: 014454078JJK
- EPA ID: NYP004772265
- Date Shipped: 4/22/2015
- TSDF EPA ID: NJD002200046
- Transporter EPA ID: NYD006982359
- Transporter 2 EPA ID: Not reported
- Transporter 3 EPA ID: Not reported
- Transporter 4 EPA ID: Not reported
- Transporter 5 EPA ID: Not reported

CON EDISON (Continued) **S120670860**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

T151 **CON EDISON** **NY MANIFEST** **S119074690**
ESE **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.135 mi.
711 ft. **Site 3 of 6 in cluster T**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	205 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004772265
Facility Status:	Not reported
Location Address 1:	208 NORTH AVE
Code:	BP
Location Address 2:	SB 2029
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772265

CON EDISON (Continued) **S119074690**

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454078JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S119074690**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

R152 **587 MAIN STREET** **NY AST** **A100433537**
SSW **348 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.137 mi.
721 ft. **Site 5 of 16 in cluster R**

Relative: **Higher**
Actual: **95 ft.**

WESTCHESTER CO. AST:

Name:	587 MAIN STREET
Address:	348 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-802131
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	Not reported
Owner Name:	RXR 587 Main Owner LLC
Owner Street:	625 RXR Plaza
Owner Address2:	Not reported
Owner City/State/Zip:	Uniondale, NY 11556
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	8000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/23/2017
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

P153 **CON EDISON** **RCRA NonGen / NLR** **1019906923**
South **552 MAIN ST** **FINDS** **NYP004828044**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.137 mi.
722 ft. **Site 19 of 20 in cluster P**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-08-21 00:00:00.0
Facility name:	CON EDISON
Facility address:	552 MAIN ST NEW ROCHELLE, NY 10801

CON EDISON (Continued) **1019906923**

EPA ID: NYP004828044
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-08-21 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:
Registry ID: 110069679360

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906923
Registry ID: 110069679360
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069679360
Name: CON EDISON

CON EDISON (Continued) **1019906923**

Address: 552 MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801

P154 **CON EDISON** **NJ MANIFEST** **S120675741**
South **552 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.137 mi.
722 ft. **Site 20 of 20 in cluster P**

Relative:
Higher

Actual:
101 ft.

NJ MANIFEST:

EPA Id:	NYP004828044
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473164JJK
EPA ID:	NYP004828044
Date Shipped:	8/21/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120675741**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K155 **CON EDISON - MANHOLE 1535** **RCRA-LQG** **1016451189**
North **GARDEN ST AND NORTH AVE** **NY MANIFEST** **NYP004302303**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.138 mi.
728 ft. **Site 7 of 12 in cluster K**

Relative:
Lower

Actual:
71 ft.

RCRA-LQG:

Date form received by agency:	2014-03-27 00:00:00.0
Facility name:	CON EDISON - MANHOLE 1535
Facility address:	GARDEN ST AND NORTH AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004302303
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2013-04-17 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2013-04-17 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-05-17 00:00:00.0
Site name: CON EDISON MANHOLE: 1535
Classification: Not a generator, verified

Date form received by agency: 2013-04-17 00:00:00.0
Site name: CON EDISON MANHOLE: 1535
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: GARDEN ST & NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

EPA ID: NYP004302303
Facility Status: Not reported
Location Address 1: GARDEN ST AND NORTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004302303
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/17/2013
Trans1 Recv Date: 04/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004302303
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010456840JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K156 **CON EDISON MANHOLE: 4177** **RCRA NonGen / NLR** **1016451046**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004300836**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.138 mi.
728 ft. **Site 8 of 12 in cluster K**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2013-05-11 00:00:00.0
Facility name:	CON EDISON MANHOLE: 4177
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004300836
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Historical Generators:
Date form received by agency: 2013-04-11 00:00:00.0
Site name: CON EDISON MANHOLE: 4177
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004300836
Facility Status: Not reported
Location Address 1: NORTH AVE C/O GARDEN ST
Code: BP
Location Address 2: MH 4177
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004300836
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2013
Trans1 Recv Date: 04/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004300836
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010707795JJK
Import Indicator: N
Export Indicator: N

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K157 **CON EDISON MANHOLE 4175** **RCRA NonGen / NLR** **1014918789**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004224085**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
728 ft. **Site 9 of 12 in cluster K**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2011-02-14 00:00:00.0
Facility name:	CON EDISON MANHOLE 4175
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004224085
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2011-01-15 00:00:00.0
Site name: CON EDISON MANHOLE 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: NORTH AVE & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004224085
Facility Status: Not reported
Location Address 1: NORTH AV & GARDEN ST
Code: BP
Location Address 2: MH 4175
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004224085
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/15/2011

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Trans1 Recv Date:	01/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224085
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655781JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K158 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016677331**
North **NORTH ST & GARDEN ST** **NY MANIFEST** **NYP004309076**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
728 ft. **Site 10 of 12 in cluster K**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	2013-06-08 00:00:00.0
Facility name:	CON EDISON MANHOLE: 4175
Facility address:	NORTH ST & GARDEN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004309076
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported

Actual:
71 ft.

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-05-08 00:00:00.0
Site name: CON EDISON MANHOLE: 4175
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH ST & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004309076
Facility Status: Not reported
Location Address 1: NORTH AVE & GARDEN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004309076
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2013
Trans1 Recv Date:	05/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004309076
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655511JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K159 **CON EDISON MANHOLE: 20274** **RCRA NonGen / NLR** **1016677685**
North **NORTH AVE & GARDEN ST** **FINDS** **NYP004313615**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.138 mi.
728 ft. **Site 11 of 12 in cluster K**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-06-15 00:00:00.0
Facility name:	CON EDISON MANHOLE: 20274
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004313615
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-05-15 00:00:00.0
Site name:	CON EDISON MANHOLE: 20274
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110058877390

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677685
Registry ID:	110058877390
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877390
Name:	CON EDISON MANHOLE: 20274
Address:	NORTH AVE & GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10802

K160 **CON EDISON SERVICE BOX: 1539** **RCRA NonGen / NLR** **1016972589**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004463667**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.138 mi.
728 ft. **Site 12 of 12 in cluster K**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-04-11 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 1539
Facility address:	NORTH AVE & GARDEN ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004463667
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-03-11 00:00:00.0
Site name:	CON EDISON SERVICE BOX: 1539

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON ED
Address: NORTH AVE & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004463667
Facility Status: Not reported
Location Address 1: NO AVE 48 AND 48 GARDEN ST
Code: BP
Location Address 2: SB 1539
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004463667
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/11/2014
Trans1 Recv Date: 03/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004463667
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772800JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

161 **BLOOMINGDALE PARKING LOT** **NY UST** **U003884000**
South **554 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.139 mi.
732 ft.

Relative: **Higher**

Actual: **102 ft.**

WESTCHESTER CO. UST:

Name:	BLOOMINGDALE PARKING LOT
Address:	554 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Id/Status:	3-600330 / Unregulated: <1101 gal. PBS
Operator Name:	Mel Watson
Owner Name:	Fraydun Enterprises
Owner Street:	3 New York Plaza
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10004
GDS Number:	Not reported
Tank Number:	2
Status:	4. Closed - in place
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	08/01/1992
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None

BLOOMINGDALE PARKING LOT (Continued) **U003884000**

Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

T162 **BARON MANAGEMENT** **NY UST** **U004187277**
ESE **200 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.139 mi.
733 ft. **Site 4 of 6 in cluster T**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Name:	BARON MANAGEMENT
Address:	200 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-167843 / Administratively Closed
Operator Name:	Segundo Tirado
Owner Name:	Ronald Rettner
Owner Street:	481 Main Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	03/05/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

S163 **FORMER CHASE BANK BUIDING** **NY UST** **U003885235**
SE **491 MAIN STREET** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.141 mi.
747 ft. **Site 2 of 5 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Name:	FORMER CHASE BANK BUIDING
Address:	491 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-164372 / Active
Operator Name:	Not reported
Owner Name:	DBCHASE LLC c/o Sansome Pacific Properties, Inc
Owner Street:	303 Sacramento Street, 4th Floor
Owner Address2:	Not reported
Owner City:	San Francisco
Owner State:	CA
Owner Zipcode:	94111
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/05/1990
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	FORMER CHASE BANK BUIDING
Address:	491 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-164372
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Not reported
Owner Name:	DBCHASE LLC c/o Sansome Pacific Properties, Inc
Owner Street:	303 Sacramento Street, 4th Floor
Owner Address2:	Not reported
Owner City/State/Zip:	San Francisco, CA 94111
Tank Number:	02
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil

FORMER CHASE BANK BUIDING (Continued) **U003885235**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

S164 **BARCLAYS BANK OF NY/NA** **NY LTANKS** **S100140601**
SE **491 MAIN ST.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.141 mi.
747 ft. **Site 3 of 5 in cluster S**

Relative: LTANKS:
Higher

Name:	BARCLAYS BANK OF NY/NA
Address:	491 MAIN ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8905129 / 1991-03-25
Facility ID:	8905129
Site ID:	299548
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	1997-02-12
Spiller Name:	Not reported
Spiller Company:	BARCLAYS BANK OF NY/NA
Spiller Address:	604 BROAD HOLLOW RD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	242324

Actual:
94 ft.

BARCLAYS BANK OF NY/NA (Continued) **S100140601**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 10/06/89: GND INC. (516) 933-1085 NAT MOSER: 1500 GAL #2 FAILED RETEST -.132GPH. TANK TO BE RELINED OR REPLACED. 03/25/91: TANK REMOVED. "
Remarks: "NAT MOSER (TELECOM 8-23, 1615) WILL CALL BACK AFTER CONTACTING BARCLAYS AND REVIEWING OPTIONS. PETRO TITE 2K 4 GPH"

All TTF:

Facility ID:	8905129
Spill Number:	8905129
Spill Tank Test:	1535898
Site ID:	299548
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	299548
Operable Unit ID:	930451
Operable Unit:	01
Material ID:	445568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L165 **RESIDENCE** **NY LTANKS** **S107788125**
NNW **60 GRAND STREET** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
749 ft. **Site 4 of 5 in cluster L**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Name:	RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0407555 / 2004-10-07
Facility ID:	0407555
Site ID:	332054
Spill Date:	2004-10-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4

RESIDENCE (Continued) **S107788125**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2004-10-07
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-07
Spill Record Last Update:	2004-11-01
Spiller Name:	ROB HILL
Spiller Company:	RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller County:	001
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 579-3414
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	267201
DEC Memo:	""
Remarks:	"TRUCK DIRVER OVERFILLED AND BLEW A LINE. CREWS ARE IN ROUTE."

All Materials:

Site ID:	332054
Operable Unit ID:	1094311
Operable Unit:	01
Material ID:	574419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	IFO CIOTTI RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601618 / 2006-11-07
Facility ID:	0601618
Facility Type:	ER
DER Facility ID:	267201
Site ID:	363896
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	6010
Spill Date:	2006-05-12
Investigator:	TDGHIOSA

RESIDENCE (Continued) **S107788125**

Referred To:	Not reported
Reported to Dept:	2006-05-12
CID:	408
Water Affected:	STORM DRAINS ON GRAN
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-12
Spill Record Last Update:	2006-11-07
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WAYNE SCHNEIDER
DEC Memo:	"05/12/06 Friday Stefan Goreau reported from the field that the spilled oil resembled motor oil rather than fuel oil, so he doesn't believe that the spill came from the residence. Northeast Environmental was called by the homeowner to do the cleanup but now the homeowner is not considered the RP. Since rain is imminent and Northeast has a vac truck on site, NE was advised to pump the oil out of the drains. DEC to pick up the expense. TG 11/07/06 IRS completed. TG"
Remarks:	"CAUSE IS EITHER TANK OVERFILL OR CHECK VALVE FAILURE."

All Materials:

Site ID:	363896
Operable Unit ID:	1121950
Operable Unit:	01
Material ID:	2111430
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CIOTTI RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0602271 / 2007-02-16
Facility ID:	0602271
Facility Type:	ER
DER Facility ID:	267201
Site ID:	364705
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2006-05-31
Investigator:	TDGHIOSA

RESIDENCE (Continued) **S107788125**

Referred To:	Not reported
Reported to Dept:	2006-05-31
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-31
Spill Record Last Update:	2007-02-16
Spiller Name:	ROBERT CIOTTI
Spiller Company:	CIOTTI RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller Company:	001
Contact Name:	ROBERT CIOTTI
DEC Memo:	""
Remarks:	"TESTED THE REMOTE FILL PIPE AND FOUND IT NOT WORKING: 02/15/07 Northeast Envoronmental reported that they excavated 12.31 tons of petroleum impacted soil. NFA TG"

All Materials:

Site ID:	364705
Operable Unit ID:	1122726
Operable Unit:	01
Material ID:	2112202
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S166 **NEW ROCHELLE PUBLIC LIBRARY** **NY LTANKS** **S105995872**
SE **1 LAWTON** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.142 mi.
749 ft. **Site 4 of 5 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	NEW ROCHELLE PUBLIC LIBRARY
Address:	1 LAWTON
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1311408 / Not Reported
Facility ID:	1311408
Site ID:	492304
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2015-10-16
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE PUBLIC LIBRARY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROB
Spiller Phone:	(914) 473-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	447251
DEC Memo:	"Tank failed with a dry leak. Will most likely be uncovering, repairing and retesting. WCDOH has been notified...mm 10-15-15 email update request sent to WCHD RDB 10-16-15 Wayne is handling and will forward an update"
Remarks:	""

All TTF:

Facility ID:	1311408
Spill Number:	1311408
Spill Tank Test:	2495159
Site ID:	492304
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MBMASTRO
Last Modified Date:	Not reported

All Materials:

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242331
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported
Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242328
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported
Name:	CITY NEW ROCHELLE LIBRARY
Address:	1 LAWTON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0201697 / 2002-09-18
Facility ID:	0201697
Site ID:	306611
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE LIBRARY
Spiller Address:	1 LAWTON STREET
Spiller County:	001
Spiller Contact:	FRANK GALLELO
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	274126
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST "

All TTF:

Facility ID:	0201697
Spill Number:	0201697

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Spill Tank Test:	1527134
Site ID:	306611
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306611
Operable Unit ID:	852656
Operable Unit:	01
Material ID:	523107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R167 **CON EDISON** **RCRA NonGen / NLR** **1019909012**
South **565 MAIN ST** **NYP004880023**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
755 ft. **Site 6 of 16 in cluster R**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-12-16 00:00:00.0
Facility name:	CON EDISON
Facility address:	565 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004880023
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No

CON EDISON (Continued) **1019909012**

Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-12-16 00:00:00.0
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

R168 **CON EDISON** **NJ MANIFEST** **S120678194**
South **565 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
755 ft. **Site 7 of 16 in cluster R**

Relative: **Higher**
Actual: **101 ft.**

NJ MANIFEST:

EPA Id:	NYP004880023
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319281JJK
EPA ID:	NYP004880023
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CON EDISON (Continued) **S120678194**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

S169 **ADREAN PRINTING CO** **RCRA NonGen / NLR** **1004755683**
SE **490 MAIN ST** **FINDS** **NY0000233981**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.147 mi. **NY MANIFEST**
776 ft. **Site 5 of 5 in cluster S**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	ADREAN PRINTING CO
Facility address:	490 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NY0000233981
Mailing address:	MAIN ST NEW ROCHELLE, NY 10801
Contact:	MICHAEL GOLDBERGER
Contact address:	MAIN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-0200
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAEL GOLDBERGER

ADREAN PRINTING CO (Continued) **1004755683**

Owner/operator address: 490 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-636-0200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MICHAEL GOLDBERGER
Owner/operator address: 490 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-636-0200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: ADREAN PRINTING CO
Classification: Not a generator, verified

Date form received by agency: 1994-04-21 00:00:00.0
Site name: ADREAN PRINTING CO
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

ADREAN PRINTING CO (Continued) **1004755683**

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:
Registry ID: 110004314297

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755683
Registry ID:	110004314297
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004314297
Name:	ADREAN PRINTING CO
Address:	490 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	ADREAN PRINTING
Address:	490 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NY0000233981
Facility Status:	Not reported
Location Address 1:	490 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000233981
Mailing Name:	ADREAN PRINTING
Mailing Contact:	WILLIAM C WHITE
Mailing Address 1:	490 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146360200

ADREAN PRINTING CO (Continued) **1004755683**

NY MANIFEST:

Document ID:	NYG0919566
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	PW2414
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/28/1997
Part A Recv Date:	/ /
Part B Recv Date:	09/19/1997
Generator EPA ID:	NY0000233981
Trans1 EPA ID:	NYR000025767
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981182769
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

R170 **HANGERS CLEANERS** **NY DRYCLEANERS** **S110246761**
South **562-564 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.147 mi.
776 ft. **Site 8 of 16 in cluster R**

Relative:
Higher

Actual:
102 ft.

DRYCLEANERS:

Name:	HANGERS CLEANERS
Address:	562-564 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00358
Phone Number:	914-235-0300
Region:	Not reported

HANGERS CLEANERS (Continued) **S110246761**

Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	04MAR23
Install Date:	02
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	CO2
Current Business:	Not reported

O171 **PRO AUTO PARTS** **RCRA NonGen / NLR** **1001079946**
SSW **41 REYLEA PL** **FINDS** **NYR000016535**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.148 mi. **NY MANIFEST**
780 ft. **Site 5 of 11 in cluster O**

Relative:
Lower

Actual:
87 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	PRO AUTO PARTS
Facility address:	41 REYLEA PL NEW ROCHELLE, NY 10801-6918
EPA ID:	NYR000016535
Mailing address:	SUMMERFIELD ST SCARSDALE, NY 10853
Contact:	Not reported
Contact address:	SUMMERFIELD ST SCARSDALE, NY 10853
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PRO AUTO PARTS CORP
Owner/operator address:	135 SUMMER FIELD ST SCARSDALE, NY 10853
Owner/operator country:	US
Owner/operator telephone:	914-772-4871
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	PRO AUTO PARTS CORP
Owner/operator address:	135 SUMMER FIELD ST SCARSDALE, NY 10853
Owner/operator country:	US
Owner/operator telephone:	914-772-4871
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

PRO AUTO PARTS (Continued) **1001079946**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: PRO AUTO PARTS
Classification: Not a generator, verified

Date form received by agency: 1995-11-16 00:00:00.0
Site name: PRO AUTO PARTS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D010
. Waste name: SELENIUM

Violation Status: No violations found

FINDS:
Registry ID: 110004520377

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

PRO AUTO PARTS (Continued) **1001079946**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001079946
Registry ID:	110004520377
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004520377
Name:	PRO AUTO PARTS
Address:	41 REYLEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	PRO AUTO PARTS
Address:	41 REYLEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801-6918
Country:	USA
EPA ID:	NYR000016535
Facility Status:	Not reported
Location Address 1:	41 REYLEA PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000016535
Mailing Name:	PRO AUTO PARTS
Mailing Contact:	PHILIP A MORRIS JR
Mailing Address 1:	135 SUMMERFIELD ROAD
Mailing Address 2:	Not reported
Mailing City:	SCARSDALE
Mailing State:	NY
Mailing Zip:	10583
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9147933336

NY MANIFEST:

Document ID:	NYB7350417
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1995
Trans1 Recv Date:	12/21/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/21/1995
Part A Recv Date:	01/05/1996
Part B Recv Date:	01/03/1996
Generator EPA ID:	NYR000016535

PRO AUTO PARTS (Continued) **1001079946**

Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00130
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	089

U172 **NYS THRUWAY AUTHORITY BRIDGE BIN 5514550** **RCRA-LQG** **1000553909**
North **I-95 AT MP 605.76 NORTH AVE OVER NYS THRUWAY I-95** **NY MANIFEST** **NYD986963445**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.148 mi.
780 ft. **Site 1 of 3 in cluster U**

Relative: **Lower**
Actual: **71 ft.**

RCRA-LQG:

Date form received by agency:	2017-12-05 00:00:00.0
Facility name:	NYS THRUWAY AUTHORITY BRIDGE BIN 5514550
Facility address:	I-95 AT MP 605.76 NORTH AVE OVER NYS THRUWAY I-95 NEW ROCHELLE, NY 10801
EPA ID:	NYD986963445
Mailing address:	EXECUTIVE BLVD SUITE 400 SUFFERN, NY 10901
Contact:	MOUSSA KALISSA
Contact address:	EXECUTIVE BLVD SUITE 400 SUFFERN, NY 10901
Contact country:	US
Contact telephone:	845-918-2526
Contact email:	MOUSSA.KALISSA@THRUWAY.NY.GOV
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NYS THRUWAY AUTHORITY
Owner/operator address:	SOUTHERN BLVD ALBANY, NY 12209
Owner/operator country:	US
Owner/operator telephone:	518-436-3190
Owner/operator email:	Not reported
Owner/operator fax:	518-436-3060
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	1955-12-15 00:00:00.
Owner/Op end date:	Not reported

Owner/operator name:	NYS THRUWAY AUTHORITY
Owner/operator address:	SOUTHERN BLVD ALBANY, NY 12209
Owner/operator country:	US
Owner/operator telephone:	518-436-3190
Owner/operator email:	Not reported
Owner/operator fax:	518-436-3060
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	1955-12-15 00:00:00.
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2007-01-01 00:00:00.0
Site name:	NYS THRUWAY AUTH
Classification:	Not a generator, verified

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Date form received by agency: 2006-01-01 00:00:00.0
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: NYS THRUWAY AUTH
Classification: Not a generator, verified

Date form received by agency: 1992-02-19 00:00:00.0
Site name: NYS THRUWAY
Classification: Large Quantity Generator

Date form received by agency: 1991-07-12 00:00:00.0
Site name: NYS THRUWAY AUTH
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: NEW YORK STATE THRUWAY AUTHORITY
Address: I-95 AT MP 605.76 NORTH AVE OV
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYD986963445
Facility Status: Not reported
Location Address 1: I-95 NORTH & NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986963445
Mailing Name: NEW YORK STATE THRUWAY AUTHORITY
Mailing Contact: NEW YORK STATE THRUWAY AUTHORITY
Mailing Address 1: 333 SOUTH BROADWAY
Mailing Address 2: Not reported
Mailing City: TARRYTOWN
Mailing State: NY
Mailing Zip: 10591
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

NY MANIFEST:

Document ID:	MIA2540754
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	5825
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/1992
Trans1 Recv Date:	05/26/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/27/1992
Part A Recv Date:	/ /
Part B Recv Date:	06/16/1992
Generator EPA ID:	NYD986963445
Trans1 EPA ID:	PAD064375470
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID000724831
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

L173 **GUIDANCE CENTER INC** **NY LTANKS** **S102556009**
NNW **70 GRAND ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.149 mi.
785 ft. **Site 5 of 5 in cluster L**

Relative: **Lower**

Actual: **80 ft.**

LTANKS:

Name:	GUIDANCE CENTER INC
Address:	70 GRAND ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9613894 / 1997-10-03
Facility ID:	9613894
Site ID:	77017

GUIDANCE CENTER INC (Continued) **S102556009**

Spill Date:	1997-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-26
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-02-26
Spill Record Last Update:	1997-10-22
Spiller Name:	STEVEN SMITH
Spiller Company:	GUIDANCE CENTER INC
Spiller Address:	70 GRAND ST
Spiller County:	001
Spiller Contact:	STEVEN SMITH
Spiller Phone:	(914) 636-4440
Spiller Extention:	250
DEC Region:	3
DER Facility ID:	71920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/03/97 LETTER SENT; BASED ON TANK REMOVAL REPORT, NFA; "
Remarks:	"OLD GASOLINE TANK FOUND UNDER THE GROUND - FOUND CONTAMINATED SOIL PHASE 2 COMPLETED - NO REMEDATION STARTED OWNER OF PROPERTY WILL AWAIT DIRECTION FROM DEC ABOUT TANK REMOVAL"

All Materials:

Site ID:	77017
Operable Unit ID:	1041477
Operable Unit:	01
Material ID:	339001
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R174 **FIRST METRO SERVICES** **RCRA NonGen / NLR** **1004759815**
SSW **357 HUGONOT ST** **FINDS** **NYR000022053**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.150 mi.
790 ft. **Site 9 of 16 in cluster R**

Relative:
Higher

Actual:
93 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	FIRST METRO SERVICES
Facility address:	357 HUGONOT ST NEW ROCHELLE, NY 10805
EPA ID:	NYR000022053
Mailing address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact:	BILL LIVANOS
Contact address:	S DIVISION ST NEW ROCHELLE, NY 10805
Contact country:	US
Contact telephone:	914-576-7210
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LEO SATALICH
Owner/operator address:	19 LYON PL NEW ROCHELLE, NY 10805
Owner/operator country:	US
Owner/operator telephone:	914-632-9692
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	LEO SATALICH
Owner/operator address:	19 LYON PL NEW ROCHELLE, NY 10805
Owner/operator country:	US
Owner/operator telephone:	914-632-9692
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

FIRST METRO SERVICES (Continued) **1004759815**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: FIRST METRO SERVICES
Classification: Not a generator, verified

Date form received by agency: 1996-04-09 00:00:00.0
Site name: FIRST METRO SERVICES
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D006
. Waste name: CADMIUM

Violation Status: No violations found

FINDS:
Registry ID: 110004523882

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759815
Registry ID: 110004523882
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004523882
Name: FIRST METRO SERVICES
Address: 357 HUGONOT ST
City,State,Zip: NEW ROCHELLE, NY 10805

T175 **RETTNER MANAGEMENT CORP** **NY UST** **U004177201**
ESE **481 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.151 mi.
795 ft. **Site 5 of 6 in cluster T**

Relative: **Higher**

Actual: **92 ft.**

WESTCHESTER CO. UST:

Name:	RETTNER MANAGEMENT CORP
Address:	481 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-255033 / Unregulated
Operator Name:	Rettner Main St, LLC
Owner Name:	Rettner Main Street, LLC
Owner Street:	30 Church Street
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	09/01/2002
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/01/1970
Date Perm Closure:	06/18/2019
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None

RETTNER MANAGEMENT CORP (Continued) **U004177201**

Piping Secondary Containment: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

T176 **14 LE COUNT STANDARD PRINTING** **NY BROWNFIELDS** **S122449231**
East **14 LE COUNT PL, 455 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.152 mi.
805 ft. **Site 6 of 6 in cluster T**

Relative: **Higher**
Actual: **89 ft.**

BROWNFIELDS:

Name:	14 LE COUNT STANDARD PRINTING
Address:	14 LE COUNT PL, 455 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	568962
Acres:	0.927
HW Code:	C360176
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	04/13/2018
Record Updated Date:	12/31/2019
Update By:	JEBROWN
Site Description:	Location: The site is located mixed-use area of New Rochelle, southwest of Le Count Place, northwest of Main Street, and northeast of North Avenue. Land uses within a quarter-mile of the site are predominantly commercial/residential. Site Features: The site used to contain seven buildings, three of which were vacant. Of the non-vacant buildings, one (455 Main Street) was occupied by a beauty salon and a sportswear store on the first floor and professional offices on the second and third floors; another (459 Main Street) was occupied by a travel agency, hair salon, and medical offices on the first floor and offices on the second floor; and the parking lot on 14 Le Count Place was being utilized by Monroe College for parking, pursuant to a Parking Space License Agreement. There were parking lots on site associated with the existing uses. All buildings on-site have since been demolished, and a new building is under construction. Current Uses and Zoning: As noted above, the site is used for a mixture of retail, residential, and commercial uses. It is zoned for Downtown Business Overlay Zone (DB), which allows for a mix of uses including residential, office, retail, commercial, cultural/entertainment, civic/religious, light industrial, and parking/utilities. Past Use of the Site: Historically, the site has been dedicated to commercial/residential uses. Notable commercial uses include a former printing shop operated by the Evening Standard Newspaper (209 North Avenue), a photo-engraving shop (207 North Avenue) and an undertaker/funeral home (14 Le Count Place). The existing on-site buildings were reportedly constructed between 1903 and 1931. Several Recognized Environmental Concerns (RECs) were identified during Phase I site assessments. The RECs are identified as out of service or previously abandoned USTs and soil contamination as a result of the historic printing operations. Site Geology and Hydrogeology: Beneath an asphalt/concrete surface, surficial historic fill of up to 5 feet deep, consisting of soils similar to the underlying natural residuals, blanket the site. The site is underlain by soils formed by the decomposition of the underlying gneiss bedrock. These soils generally consist of silty/clayey sand containing varying percentages of gravel. Weathered gneissic bedrock

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

	is typically present at depths on the order of 20 to 25 feet below grade. The regional groundwater flow direction around the site was confirmed during the Remedial Investigation to follow the general topography of the region, which slopes gently downwards towards Echo Bay to the east and southeast of the site. The groundwater depth was measured during the 2017 water sampling event and found to be approximately 18 feet below ground surface. There are two operable units for this site. Operable Unit(OU) 01 is the brownfield-related remedial work and is the subject of this document. OU 02 encompasses the response to a petroleum spill reported on this property. Work on OU 02 is governed by a separate Order on Consent (Index no: CO 3-20190404-74) and is not part of the BCP cleanup.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals and PAHs in soil, benzene and cis-1,2-DCE in groundwater and trichloroethene in sub-slab soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Groundwater has not met standards for cis-1,2-dichloroethene and benzene. Residual contamination in the groundwater is being managed with monitored natural attenuation under a Site Management Plan.
Health Problem:	The site has been remediated; therefore, the potential for exposure to contaminated soil or groundwater has been eliminated. In addition, the area is served by a public water supply that is not affected by this contamination. Because the site is vacant, inhalation of site contaminants due to soil vapor intrusion does not represent a current concern. However, a soil vapor intrusion evaluation will be completed and appropriate actions to address exposures will be implemented for any new buildings constructed on the site. Additional investigations are recommended to determine if soil vapor intrusion is a potential concern for offsite buildings.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	7/31/2018 3:59:00 PM
Record Upd:	12/19/2019 4:32:00 PM
Updated By:	JEBROWN
Own Op:	1
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	14 Le Count Place LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	14 Le Count Place LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Bill balter
Owner Company:	WBLM 14 le Count owner llc
Owner Address:	480 bedford road
Owner Addr2:	Not reported
Owner City,St,Zip:	chappaqua, ny, NY 10514
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	WBLM 14 Le Count Owner LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

HW Code:	Not reported
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	1/14/2019 11:26:00 AM
Record Updated:	1/14/2019 11:26:00 AM

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

Updated By:	MAKING
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	5/22/2019 2:53:00 PM
Record Updated:	5/22/2019 2:53:00 PM
Updated By:	GAAHLERS
Crossref ID:	C360176-0818
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	12/13/2019 3:05:00 PM
Record Updated:	12/13/2019 3:05:00 PM
Updated By:	MAKING
Crossref ID:	Not reported
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	12/18/2019 12:28:00 PM
Record Updated:	12/18/2019 12:28:00 PM
Updated By:	MAKING

R177 **MISR REALTY, LLC** **NY AST** **U004176186**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
809 ft. **Site 10 of 16 in cluster R**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. AST:

Name:	MISR REALTY, LLC
Address:	573-579 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800238
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MISR Realty LLC
Owner Street:	542 Main Street, 4th Floor
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle

MISR REALTY, LLC (Continued) **U004176186**

Spill Prevention: 0. None
Dispenser: 2. Suction

R178 **MISR REALTY, LLC** **NY UST** **U004259541**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.153 mi.
809 ft. **Site 11 of 16 in cluster R**

Relative: WESTCHESTER CO. UST:
Higher
Actual: Name: MISR REALTY, LLC
100 ft. Address: 573-579 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-800238 / Active
Operator Name: Pedro Benoit
Owner Name: MISR Realty LLC
Owner Street: 542 Main Street, 4th Floor
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: Not reported
Date Installation: Not reported
Date Perm Closure: 11/01/2004
Tank Location: 6. Underground, vaulted, with access
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

O179 **INDUST OVERALL SERVICE CORP** **NY LTANKS** **S116555778**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.155 mi.
816 ft. **Site 6 of 11 in cluster O**

Relative: LTANKS:
Lower
Actual: Name: INDUST OVERALL SERVICE CORP
81 ft. Address: 10 BARTELS PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1400928 / 2017-03-30
Facility ID: 1400928

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Site ID:	494186
Spill Date:	2014-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	ELMOORE
Referred To:	Not reported
Reported to Dept:	2014-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-28
Spill Record Last Update:	2017-03-30
Spiller Name:	BOB OBRIEN
Spiller Company:	INDUSTRIAL OVERALL SERV CORP
Spiller Address:	10 BARTELL PL
Spiller County:	999
Spiller Contact:	BOB OBRIEN
Spiller Phone:	(914) 235-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449117
DEC Memo:	"4-28-14: Chris/WCHD call to Dispt./V.Mc.: Heating oil tank, out of service, failed test. 3/30/2017 -- Carlos drove by this week and the soil pile has been removed. This spill can be closed, with the entire site clean-up being accomplished under Haz Waste. 360109 ELM"
Remarks:	"tank 2 5000 gallon"

All TTF:

Facility ID:	1400928
Spill Number:	1400928
Spill Tank Test:	2495577
Site ID:	494186
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	True
UST:	True
Cause:	03
Source:	00
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

Facility ID:	1400928
Spill Number:	1400928
Spill Tank Test:	2495578
Site ID:	494186

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Tank Number:	2
Tank Size:	5000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	494186
Operable Unit ID:	1243715
Operable Unit:	01
Material ID:	2244419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

R180 **CON EDISON TRANSFORMER MANHOLE: 2750** **RCRA NonGen / NLR** **1016677840**
South **CENTRE AVE & MAIN ST** **FINDS** **NYP004315198**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.155 mi. **NY MANIFEST**
820 ft. **Site 12 of 16 in cluster R**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-06-21 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2750
Facility address:	CENTRE AVE & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004315198
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-05-21 00:00:00.0
Site name:	CON EDISON TRANSFORMER MANHOLE: 2750
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110058871369

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677840
Registry ID:	110058871369
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058871369
Name:	CON EDISON TRANSFORMER MANHOLE: 2750
Address:	CENTRE AVE & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	CON EDISON
Address:	CENTRE AVE & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004315198
Facility Status:	Not reported
Location Address 1:	CENTRE ST & MAIN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004315198
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/21/2013
Trans1 Recv Date: 05/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/28/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004315198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007019053JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R181 **CON EDISON** **NJ MANIFEST** **S120669849**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 13 of 16 in cluster R**

Relative:
Higher

Actual:
100 ft.

NJ MANIFEST:

EPA Id:	NYP004760815
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091694JJK
EPA ID:	NYP004760815
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON (Continued) **S120669849**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R182 **CON EDISON** **RCRA NonGen / NLR** **1019901339**
South **CENTRE & MAIN ST** **FINDS** **NYP004760815**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.155 mi.
820 ft. **Site 14 of 16 in cluster R**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-03-31 00:00:00.0
Facility name:	CON EDISON
Facility address:	CENTRE & MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004760815
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

CON EDISON (Continued) **1019901339**

Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-03-31 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:
Registry ID: 110069701530

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901339
Registry ID: 110069701530
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069701530
Name: CON EDISON
Address: CENTRE & MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801

R183 **CON ED** **NY MANIFEST** **S119074042**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 15 of 16 in cluster R**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:
Name: CON ED
Address: CENTRE & MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004760815
Facility Status: Not reported
Location Address 1: CENTRE AVE & MAIN ST
Code: BP
Location Address 2: TM 2750
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004760815
Mailing Name: CON ED
Mailing Contact: TOM TEELING

CON ED (Continued) **S119074042**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760815
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091694JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R184 **CON EDISON** **NY MANIFEST** **S117318285**
South **MAIN ST & CENTRE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 16 of 16 in cluster R**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MAIN ST & CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004658019
Facility Status:	Not reported
Location Address 1:	MAIN ST & CENTRE ST
Code:	BP
Location Address 2:	MH734
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004658019
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2014
Trans1 Recv Date:	09/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004658019
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771786JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117318285**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O185 **NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP** **NJ MANIFEST** **S120679001**
SW **10 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 7 of 11 in cluster O**

Relative: **Lower**

Actual: **81 ft.**

NJ MANIFEST:

EPA Id:	NYR000208967
Mail Address:	BARTELS PL
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ROBERT R OBRIEN
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010914098JJK
EPA ID:	NYR000208967
Date Shipped:	1/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Manifest Number:	000959895GBF
EPA ID:	NYR000208967
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Manifest Number:	014168256JJK
EPA ID:	NYR000208967
Date Shipped:	10/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Reason Load Was Rejected: Not reported

O186 **INDUSTRIAL OVERALL** **NY SHWS** **S110043643**
SW **10 BARTELS PLACE** **NY CBS** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 8 of 11 in cluster O**

Relative: **Lower**

Actual: **81 ft.**

SHWS:
Name: INDUSTRIAL OVERALL SERVICE CORP.
Address: 10 BARTELS PLACE
City,State,Zip: NEW ROCHELLE, NY
Program: HW
Site Code: 413917
Classification: 2
Region: 3
Acres: 0.41999999999999998
HW Code: 360109
Record Add: 05/15/2009
Record Upd: 04/04/2018
Updated By: DACROSBY
Site Description: Location: The Industrial Overall Service Corporation site is located at 10 Bartels Place in the City of New Rochelle, Westchester County. The site is located east of I-95 and west of US-1 (Huguenot Street) and it is bounded by Relyea Place, Bartels Place, Centre Avenue and the Metro North railroad property and tracks. Site Features: The site is 0.42 acres in size and resides on a slightly sloping irregularly shaped parcel consisting of two tax parcels. The main site feature includes a six-sided building which occupies the majority of the property and a small parking area located to the south and southwest of the building. Current Zoning/ Uses: This property is zoned for commercial use. The building is currently vacant and for sale. The surrounding area is a mix of commercial and residential establishments situated in an urban setting. Past Uses of the Site: Industrial Overall Service Corporation operated at the current location as a uniform and industrial clothing dry cleaning/laundering facility, historically cleaning heavily soiled clothing from industrial, auto body and gasoline dispensing businesses from 1956 until 2010. Dry cleaning equipment was reportedly decommissioned in 1978, but water washing continued. From 1980-1998 Workingman s Closet, an embroidery and uniform retail outfit, operated on the second floor of the building. From 2010 until 2016, Apparel Plus Textile Rental LLC ran a rental linen service company on both floors of the building, which involved water laundering. Historically, a precision scale company also operated out of the second floor of the building from sometime between 1932 and 1956 until sometime before 1973 when Industrial Overall purchased the building to occupy it entirely. Based on a Sanborn Fire Insurance Map from 1931, the site previously operated an automobile sales and service business. This site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site and adjacent Metro-north property. OU1 consists of the entire site property with the addition of an off-site source area

INDUSTRIAL OVERALL (Continued) **S110043643**

which lies to the northeast of the site on the adjacent Metro-north property. Operable unit 2 (OU2) is the off-site groundwater plume. Site Geology and Hydrology: Groundwater is found in the overburden and in the bedrock. Groundwater is generally found 10 to 15 feet below ground surface and flows in a southwesterly direction. Overburden in the vicinity ranges in thickness from 2.2 feet to 32 feet, and consists of fill material (1-5 feet in thickness) and varied amounts of fine to coarse sand with varying amounts of silt. Below the sandy silt is a till like material. Depth to bedrock is variable across the site from a depth of a few feet to over 35 feet below grade. Bedrock in the vicinity is a highly weathered rock which is undulating in nature and is generally more transmissive than the till-like overburden material directly above.

Env Problem: This section summarizes the assessment of existing and potential future environmental impacts presented by the site. Environmental impacts may include existing and potential future exposure pathways to fish and wildlife receptors, wetlands, groundwater resources, and surface water. Based upon the resources and pathways identified and the toxicity of the contaminants of ecological concern at this site, a Fish and Wildlife Resources Impact Analysis (FWRIA) was deemed not necessary for OU 01. Nature and Extent of Contamination: The primary contaminants of concern at the site include the dry cleaning chemicals tetrachloroethene (PCE), trichloroethene (TCE) and their associated breakdown products. PCE and TCE are found in on-site and off-site soil and groundwater. Two primary source areas remain at and adjacent to the site. These include a lint trap within on-site building and an off-site debris and waste disposal area located to the northwest outside the building on the adjacent Metro North Railroad property. Soil: Maximum concentrations of PCE and TCE in on-site soils/wastes located in the remaining lint trap source area exceed 21,000 parts per million (ppm) and 1,200 ppm, respectively. In addition to volatile organic compounds (VOCs), soils on- and off-site were also sampled for semi-volatile organic compounds (SVOCs) and metals. No SVOCs exceeded SCOs, but several metals (barium, cadmium, chromium, lead, and silver) exceeded their respective unrestricted use SCOs directly underneath the lint trap. Also under the lint trap, barium, cadmium, and lead exceeded commercial SCOs, while only barium out of these metals did not exceed protection of groundwater SCOs. Also chromium exceeds the protection of groundwater SCO in one off-site location. On-site and off-site soil contains VOCs mainly in the two source areas, but some soil located under the site parking lot also contained VOCs above protection of groundwater SCOs of 0.47 ppm for TCE and 1.3 ppm for PCE. Generally, however, concentrations of PCE and TCE in on-site soils decrease to below the soil cleanup objectives (SCOs) for the protection of groundwater not far from the actual lint trap. The debris and waste disposal source area on the off-site Metro North property contains a maximum PCE concentration of 500 ppm and a maximum TCE concentration of 11 ppm. Groundwater: Contamination migrating from the two source areas has impacted groundwater in the bedrock and overburden, and created a plume extending downgradient (southwest) more than 1,900 feet from the site. The highest level of PCE in on-site groundwater was 140,000 parts per billion (ppb) near the lint trap, compared to the groundwater standard of 5 ppb. On the adjacent off-site Metro North Railroad property, PCE concentrations in groundwater reached 3,600 ppb. The maximum level of TCE in on-site groundwater was 13,000 ppb near the lint trap, and 1,800 ppb beneath the adjacent off-site Metro

INDUSTRIAL OVERALL (Continued) **S110043643**

North Railroad property, compared to the groundwater standard of 5 ppb. TCE was also detected upgradient of the site at 5300 ppb indicating a second potential off-site upgradient source. Several breakdown products of PCE and TCE were also noted in the groundwater. The maximum on-site cis-1,2 dichloroethene (cis-1,2 DCE) concentration was 27,000 ppb near the lint trap, and 130 ppb beneath the off-site adjacent Metro North Railroad property. The maximum on-site vinyl chloride (VC) concentration was 1,600 ppb near the lint trap compared to the groundwater standard of 2 ppb.1-1-1 trichloroethane (1,1,1-TCA) was detected on-site at a maximum concentration of 730 ppb beneath the on-site building, compared to the groundwater standard of 5 ppb. However, 1,1,1-TCA was also detected upgradient of the site at 910 ppb indicating an off-site, upgradient source. Soil Vapor, Sub-slab Vapor and Indoor Air: Samples were not collected on-site because the site is vacant. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. No significant environmental resources have been identified near the site.

Health Problem: Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Most of the site is covered with pavement and buildings; however, trespassers or employees walking, digging, or otherwise disturbing the soil on the adjacent Metro North property could come in contact with site-related contaminants. Volatile organic compounds in the soil or groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site redevelopment. Sub-slab depressurization systems have been installed in two off-site residential buildings to prevent the inhalation of site-related contamination. In addition, air monitoring is on-going at five additional off-site residential buildings to verify further actions are not needed. Sampling indicates soil vapor intrusion may be a concern for additional off-site buildings and sampling is recommended.
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 6/11/2009 3:11:00 PM
Record Upd: 3/16/2017 1:50:00 PM
Updated By: KATHOMPS
Own Op: 4
Sub Type: Not reported
Owner Name: Robert R. O'Brien
Owner Company: Apparel + Plus Textile Rental, LLC

INDUSTRIAL OVERALL (Continued) **S110043643**

Owner Address:	27 Centre Avenue/10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	ROBERT O'BRIEN
Owner Company:	WORKING MAN'S CLOSET, INC
Owner Address:	3 KOLBERT DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	SCARSDALE, NY 10583
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	Not reported
Owner Name:	Mr Burton Dorfman, Esq.
Owner Company:	Industrial Overall Service Corporation
Owner Address:	10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Region 3 Headquarters
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	21 South Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
HW Code:	360109
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109

INDUSTRIAL OVERALL (Continued) **S110043643**

Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: 1
Cross Ref Type: Spill No.
Record Added Date: 4/14/2014 11:03:00 AM
Record Updated: 4/14/2014 11:03:00 AM
Updated By: RDBENDEL
Crossref ID: Not reported
Cross Ref Type Code: 1
Cross Ref Type: Spill No.
Record Added Date: 2/14/2014 8:19:00 AM
Record Updated: 2/14/2014 8:19:00 AM
Updated By: ELMOORE
Crossref ID: Not reported
Cross Ref Type Code: 2
Cross Ref Type: HW Site ID
Record Added Date: 5/21/2009 3:07:00 PM
Record Updated: 5/21/2009 3:07:00 PM
Updated By: RXKEATIN

CBS:
Name: INDUSTRIAL OVERALL
Address: 10 BARTELS PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
CBS Number: 3-000235
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 3
UTMX: 602235.01207
UTMY: 4529263.44535

O187 **INDUSTRIAL OVERALL SERVICE CORP.** **NY UST** **U004176640**
SW **10 BARTELLS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.155 mi.
820 ft. **Site 9 of 11 in cluster O**

Relative: WESTCHESTER CO. UST:
Lower
Actual: Name: INDUSTRIAL OVERALL SERVICE CORP.
81 ft. Address: 10 BARTELLS PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-025453 / Unregulated
Operator Name: Robert O'Brien
Owner Name: Industrial Overall Service Corp.
Owner Street: 10 Bartels Place
Owner Address2: Not reported

INDUSTRIAL OVERALL SERVICE CORP. (Continued) **U004176640**

Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	03/11/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1980
Date Perm Closure:	08/26/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	0. None

O188
SW
1/8-1/4
0.155 mi.
820 ft.

INDUSTRIAL OVERALL
10 BARTELS PLACE
NEW ROCHELLE, NY 10801

Site 10 of 11 in cluster O

Relative: Lower

Actual: 81 ft.

NY CBS AST | **S105455801** | **N/A**

NY CBS AST:
No Details: No Details

O189
SW
1/8-1/4
0.155 mi.
820 ft.

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
10 BARTELS PL
NEW ROCHELLE, NY 10801

Site 11 of 11 in cluster O

Relative: Lower

Actual: 81 ft.

RCRA-LQG | **1016678149**
FINDS | **NYR000208967**
ECHO
NY MANIFEST

RCRA-LQG:

Date form received by agency:	2016-04-19 00:00:00.0
Facility name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Facility address:	10 BARTELS PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000208967
Mailing address:	CENTRE AVE NEW ROCHELLE, NY 10801
Contact:	DAVID CROSBY
Contact address:	BROADWAY ALBANY, NY 12233
Contact country:	US
Contact telephone:	518-402-9662
Contact email:	DAVID.CROSBY@DEC.NY.GOV
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	BARTELS PL NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-235-1220
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	2010-08-23 00:00:00.

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Owner/Op end date: Not reported

Owner/operator name: ROBERT OBRIEN
Owner/operator address: CENTRE AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 1900-01-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: ROBERT OBRIEN
Owner/operator address: CENTRE AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1900-01-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 1950-06-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Historical Generators:
Date form received by agency: 2014-12-09 00:00:00.0
Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Not a generator, verified

Date form received by agency: 2014-03-31 00:00:00.0
Site name: INDUSTRIAL OVERALL SERVICE CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 10230

Waste code: D008
Waste name: LEAD
Amount (Lbs): 10230

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 10230

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 10230

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 10230

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 2014-03-18 00:00:00.0
Date achieved compliance: 2014-07-08 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 2014-03-31 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 2014-03-18 00:00:00.0
Date achieved compliance: 2014-07-08 00:00:00.0
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 2014-07-14 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 12000
Paid penalty amount: 12000

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 2014-03-18 00:00:00.0
Date achieved compliance: 2014-07-08 00:00:00.0
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 2014-04-15 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 10000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 2014-07-08 00:00:00.0
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 2014-04-01 00:00:00.0
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Listing - General
Date achieved compliance: 2014-07-08 00:00:00.0
Evaluation lead agency: State

Evaluation date: 2014-03-18 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 2014-07-08 00:00:00.0
Evaluation lead agency: State

FINDS:
Registry ID: 110058881152

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678149
Registry ID: 110058881152
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058881152
Name: NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address: 10 BARTELS PL
City,State,Zip: NEW ROCHELLE, NY 10801

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

NY MANIFEST:

Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address:	10 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000208967
Facility Status:	Not reported
Location Address 1:	10 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000208967
Mailing Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Contact:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Address 1:	10 BARTELS PL
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014168256JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

190
NNW
1/8-1/4
0.156 mi.
823 ft.

RITZCOVAN - TTF
22 BURLING LANE
NEW ROCHELLE, NY

NY LTANKS **S118263505**
N/A

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	RITZCOVAN - TTF
Address:	22 BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1506693 / 2016-03-22
Facility ID:	1506693
Site ID:	514123
Spill Date:	2015-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2016-03-22
Spiller Name:	Not given
Spiller Company:	Ritzcovan (Owner)
Spiller Address:	22 BURLING LANE
Spiller County:	999

RITZCOVAN - TTF (Continued) **S118263505**

Spiller Contact:	BRUCE
Spiller Phone:	9147120600
Spiller Extention:	1
DEC Region:	3
DER Facility ID:	468599
DEC Memo:	"9/24/15 Spoke to Bruce, the contact, who is trying to arrange tank removal, as he is tentatively purchasing the property from Ritzcovan. I gave him a list of contractors in Westchester. dw 3/22/16: Grazi-1 Environmental disposed of the leaking UST and approximately 10.15 tons of petroleum contaminated soil. Soil sample results submitted for review. Tank Closure Report entered into DecDocs system. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"unknown whether contaminated. option recover & repair, or remove; unknown at this time"

All TTF:

Facility ID:	1506693
Spill Number:	1506693
Spill Tank Test:	2498471
Site ID:	514123
Tank Number:	Not reported
Tank Size:	275
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	DXWEITZ
Last Modified Date:	Not reported

All Materials:

Site ID:	514123
Operable Unit ID:	1263331
Operable Unit:	01
Material ID:	2267021
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

U191 **CON EDISON MANHOLE: 12245** **RCRA NonGen / NLR** **1016677186**
North **NORTH AVE & BURLING LANE** **FINDS** **NYP004307492**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.156 mi. **NY MANIFEST**
826 ft. **Site 2 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-06-06 00:00:00.0
Facility name:	CON EDISON MANHOLE: 12245
Facility address:	NORTH AVE & BURLING LANE NEW ROCHELLE, NY 10801
EPA ID:	NYP004307492
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-05-06 00:00:00.0
Site name:	CON EDISON MANHOLE: 12245
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110058877531

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677186
Registry ID:	110058877531
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877531
Name:	CON EDISON MANHOLE: 12245
Address:	NORTH AVE & BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004307492
Facility Status:	Not reported
Location Address 1:	NORTH AVE & BURLING LANE
Code:	BP
Location Address 2:	MH 12245
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10580
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004307492
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	05/07/2013
TSD Site Recv Date:	05/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307492
Trans1 EPA ID:	Not reported

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	004816866FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V192 **CASARRA RESIDENCE** **NY LTANKS** **S105997517**
West **9 BADEAU PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.164 mi.
865 ft. **Site 1 of 4 in cluster V**

Relative: LTANKS:
Higher

Actual: Name:	CASARRA RESIDENCE
104 ft. Address:	9 BADEAU PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209171 / 2003-02-05
Facility ID:	0209171
Site ID:	157707
Spill Date:	2002-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-12-06
CID:	257

CASARRA RESIDENCE (Continued) **S105997517**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-06
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	9 BADEAU PL
Spiller County:	001
Spiller Contact:	SAL CASARRA
Spiller Phone:	(914) 235-0620
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/05/2003 Northeast Environmental removed the tank and reported that no contamination was present. NFA TG"
Remarks:	"uncover repair and retest"

All Materials:

Site ID:	157707
Operable Unit ID:	860605
Operable Unit:	01
Material ID:	516149
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

W193 **STORAGE USA** **NY UST** **U003949850**
SSW **363 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.166 mi.
877 ft. **Site 1 of 6 in cluster W**

Relative:
Higher

Actual:
92 ft.

WESTCHESTER CO. UST:

Name:	STORAGE USA
Address:	363 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-801137 / Administratively Closed
Operator Name:	Narine Nathu
Owner Name:	SUSA Partnership, L.P.
Owner Street:	175 Toyota Plaza
Owner Address2:	Not reported
Owner City:	Memphis
Owner State:	TN
Owner Zipcode:	38103
GDS Number:	Not reported

STORAGE USA (Continued) **U003949850**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1934
Date Perm Closure:	03/15/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

X194 **DRIVE IT YOURSELF** **NY UST** **U004176354**
NNE **20 GARDEN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.174 mi.
919 ft. **Site 1 of 3 in cluster X**

Relative: **Lower**
Actual: **71 ft.**

WESTCHESTER CO. UST:

Name:	DRIVE IT YOURSELF
Address:	20 GARDEN STREET
City,State,Zip:	NEW ROCHELLE, NY 10805
Id/Status:	3-494380 / Unregulated
Operator Name:	Drive It Yourself
Owner Name:	Ed;edward Jr;tim Tostanowski
Owner Street:	128 Saw Mill River Rd.
Owner Address2:	Not reported
Owner City:	Yonkers
Owner State:	NY
Owner Zipcode:	10701
GDS Number:	Not reported

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1974
Date Perm Closure:	02/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None

DRIVE IT YOURSELF (Continued) **U004176354**

Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 2. Suction

Y195 **NYNEX** **NY LTANKS** **S100164268**
WNW **40 WASHINGTON AVE** **N/A**
1/8-1/4 **GREENBUSH, NY**
0.174 mi.
919 ft. **Site 1 of 3 in cluster Y**

Relative:
Higher

Actual:
112 ft.

LTANKS:
Name: NYNEX
Address: 40 WASHINGTON AVE
City,State,Zip: GREENBUSH, NY
Spill Number/Closed Date: 8803234 / 1988-07-22
Facility ID: 8803234
Site ID: 60528
Spill Date: 1988-07-14
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-07-22
SWIS: 6000
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-07-14
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 1988-07-22
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-03-28
Spill Record Last Update: 1988-09-07
Spiller Name: Not reported
Spiller Company: JOHN ALBARANO
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 59075
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK PUMED OUT.TO BE REMOVED. "
Remarks: "#2FUEL 5K 1.842 / 4K .170 DIESEL"

All TTF:
Facility ID: 8803234
Spill Number: 8803234
Spill Tank Test: 1534290
Site ID: 60528
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported

NYNEX (Continued) **S100164268**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	60528
Operable Unit ID:	918404
Operable Unit:	01
Material ID:	458797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z196 **ROTH CLEANERS** **RCRA NonGen / NLR** **1000237840**
SSE **1 LEROY PL** **FINDS** **NYD078706686**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.177 mi. **NY DRYCLEANERS**
935 ft. **Site 1 of 3 in cluster Z** **NY MANIFEST**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	ROTH CLEANERS
Facility address:	1 LEROY PL NEW ROCHELLE, NY 10805
EPA ID:	NYD078706686
Mailing address:	LEROY PL NEW ROCHELLE, NY 10805
Contact:	BEN ROTH
Contact address:	LEROY PL NEW ROCHELLE, NY 10805
Contact country:	US
Contact telephone:	914-633-7114
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BEN ROTH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported

ROTH CLEANERS (Continued) **1000237840**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BEN ROTH
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: ROTH CLEANERS
Classification: Not a generator, verified

Date form received by agency: 1986-08-27 00:00:00.0
Site name: ROTH CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

ROTH CLEANERS (Continued) **1000237840**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - Manifest
- Date violation determined: 1987-04-24 00:00:00.0
- Date achieved compliance: 1987-04-26 00:00:00.0
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 1987-04-24 00:00:00.0
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 1987-04-24 00:00:00.0
- Evaluation: NON-FINANCIAL RECORD REVIEW
- Area of violation: Generators - Manifest
- Date achieved compliance: 1987-04-26 00:00:00.0
- Evaluation lead agency: State

FINDS:
- Registry ID: 110004370369

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1000237840
- Registry ID: 110004370369
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004370369
- Name: ROTH CLEANERS
- Address: 1 LEROY PL
- City,State,Zip: NEW ROCHELLE, NY 10805

DRYCLEANERS:
- Name: ROTH CLEANERS
- Address: 1 LEROY PLACE
- City,State,Zip: NEW ROCHELLE, NY 10805
- Facility ID: 3-5510-00292

ROTH CLEANERS (Continued) **1000237840**

Phone Number:	914-633-7114
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	2016-07-09 00:00:00
Install Date:	98
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

NY MANIFEST:

Name:	ROTH CLEANERS
Address:	1 LEROY PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD078706686
Facility Status:	Not reported
Location Address 1:	1 LEROY PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD078706686
Mailing Name:	ROTH CLEANERS
Mailing Contact:	ROTH CLEANERS
Mailing Address 1:	1 LEROY PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337114

NY MANIFEST:

Document ID:	NYC6190896
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	NYCR2436
Trans2 State ID:	TNT218034
Generator Ship Date:	06/23/2000
Trans1 Recv Date:	06/23/2000
Trans2 Recv Date:	06/28/2000
TSD Site Recv Date:	06/30/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD078706686
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591

ROTH CLEANERS (Continued) **1000237840**

TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	P - Pounds
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Z197 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243086**
SSE **DIVISION ST & LEROY PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.181 mi.
954 ft. **Site 2 of 3 in cluster Z**

Relative: **Higher**

Actual: **100 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	DIVISION ST & LEROY PL
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004124210
Facility Status:	Not reported
Location Address 1:	DIVISION ST & LEROY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY

CONSOLIDATED EDISON (Continued) **1009243086**

Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004124210
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE1309986
Manifest Status: Not reported
seq: Not reported
Year: 2004
Trans1 State ID: 46614JM
Trans2 State ID: Not reported
Generator Ship Date: 08/30/2004
Trans1 Recv Date: 08/30/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/30/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004124210
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00014
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

CONSOLIDATED EDISON (Continued) **1009243086**

Specific Gravity: 01.00

AA198 **CON ED-V14** **NY MANIFEST** **S109064677**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.181 mi.
956 ft. **Site 1 of 2 in cluster AA**

Relative: **Lower**
Actual: **87 ft.**

NY MANIFEST:

Name:	CON ED-V14
Address:	LECOUNT PL & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004028122
Facility Status:	Not reported
Location Address 1:	LECOUNT PL & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	0000

NY MANIFEST:

EPAID:	NYP004028122
Mailing Name:	CON ED-V14
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

AA199 **CON ED-V37** **NY MANIFEST** **S109064681**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.181 mi.
956 ft. **Site 2 of 2 in cluster AA**

Relative: **Lower**
Actual: **87 ft.**

NY MANIFEST:

Name:	CON ED-V37
Address:	LECOUNT PL & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004027967
Facility Status:	Not reported
Location Address 1:	LECOUNT PL & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE

CON ED-V37 (Continued) **S109064681**

Location State: NY
Location Zip: 10801
Location Zip 4: 0000

NY MANIFEST:
EPAID: NYP004027967
Mailing Name: CON ED-V37
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

V200 **RESIDENCE** **NY LTANKS** **S102663947**
West **18 BADEAU PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.182 mi.
960 ft. **Site 2 of 4 in cluster V**

Relative:
Higher

Actual:
104 ft.

LTANKS:
Name: RESIDENCE
Address: 18 BADEAU PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9609269 / 1996-10-24
Facility ID: 9609269
Site ID: 177416
Spill Date: 1996-10-24
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1996-10-24
CID: 266
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1996-10-24
Spill Record Last Update: 1996-12-05
Spiller Name: Not reported
Spiller Company: JULIO VALER
Spiller Address: 18 BADEAU PLACE
Spiller County: 001
Spiller Contact: JULIO VALER
Spiller Phone: (914) 636-8917
Spiller Extention: Not reported
DEC Region: 3

RESIDENCE (Continued) **S102663947**

DER Facility ID: 149078
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "CUSTOMER ORDERED TOO MUCH OIL. SPILLED ONTO BLACKTOP DRIVEWAY. CLEANED UP."

All Materials:
Site ID: 177416
Operable Unit ID: 1037374
Operable Unit: 01
Material ID: 345000
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Oxygenate: Not reported

AB201 **J B & FRANKS** **RCRA NonGen / NLR** **1000100357**
SW **27 BARTELS PL** **FINDS** **NYD986884732**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.182 mi. **NY MANIFEST**
963 ft. **Site 1 of 3 in cluster AB**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:
Date form received by agency: 2007-01-01 00:00:00.0
Facility name: J B & FRANKS
Facility address: 27 BARTELS PL
NEW ROCHELLE, NY 10801-6901
EPA ID: NYD986884732
Mailing address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact: Not reported
Contact address: BARTELS PL
NEW ROCHELLE, NY 10804
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

J B & FRANKS (Continued) **1000100357**

Owner/operator name: ANTHONY LANTZ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: J B & FRANKS
Classification: Not a generator, verified

Date form received by agency: 1989-12-01 00:00:00.0
Site name: J B & FRANKS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:
Registry ID: 110004439705

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

J B & FRANKS (Continued) **1000100357**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000100357
Registry ID:	110004439705
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004439705
Name:	J B & FRANKS
Address:	27 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	J B FRANKS
Address:	27 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801-6901
Country:	USA
EPA ID:	NYD986884732
Facility Status:	Not reported
Location Address 1:	27 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10804
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986884732
Mailing Name:	J B FRANKS
Mailing Contact:	J B FRANKS
Mailing Address 1:	27 BARTELS PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10804
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146360570

NY MANIFEST:

Document ID:	NYA7038792
Manifest Status:	K
seq:	Not reported
Year:	1989
Trans1 State ID:	N23008
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/1989
Trans1 Recv Date:	12/06/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/07/1989

J B & FRANKS (Continued) **1000100357**

Part A Recv Date:	01/24/1990
Part B Recv Date:	12/18/1989
Generator EPA ID:	NYD986884732
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Y202 **ST GABRIEL HIGH SCHOOL** **NY LTANKS** **S117851738**
WNW **50 WASHINGTON AVE** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.185 mi.
979 ft. **Site 2 of 3 in cluster Y**

Relative: **Higher**

Actual: **110 ft.**

LTANKS:

Name:	INTERSTITIAL FAILURE
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1903323 / 2019-09-18
Facility ID:	1903323
Site ID:	591279
Spill Date:	2019-07-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2019-07-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

ST GABRIEL HIGH SCHOOL (Continued) **S117851738**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2019-07-01
Spill Record Last Update:	2019-09-18
Spiller Name:	Not reported
Spiller Company:	St Gabriel Church
Spiller Address:	50 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	JIM ROFF
Spiller Phone:	(518) 527-3384
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	"7/1/19 Leak in interstitial WCDOH requiring Church to replace tank. Temp tank to be used in interim. Church tank to be completely emptied Tues and new tank to be installed once funding approved. mt. 09/17/19 Metro Environmental Serices reported that they removed the tank. Post excavation soil sample results were below DEC Soil Guidance values. NFA. TG"
Remarks:	"no spill tank test failure"

All Materials:

Site ID:	591279
Operable Unit ID:	1338903
Operable Unit:	01
Material ID:	2348426
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	ST GABRIEL HIGH SCHOOL
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1500015 / 2019-03-01
Facility ID:	1500015
Facility Type:	ER
DER Facility ID:	253527
Site ID:	506147
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2015-04-01
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-04-01
CID:	Not reported

ST GABRIEL HIGH SCHOOL (Continued) **S117851738**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-01
Spill Record Last Update:	2019-03-01
Spiller Name:	Not reported
Spiller Company:	CHURCH OF ST GABRIELLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SHARIMA RYAN
DEC Memo:	"4-1-15 Spoke with Sharima. They have excavated 1 drum of soil and will probably excavate a couple more to complete the cleanup. WCDOH - Denise is handling. 3k tank. jm Denise, Please handle this one. PBS 3-058122 Contamination found around leaking spill catch basin. 1 drum removed but more work to do. Contractor stopped and is submitting proposal to school. Contractor wrapping up for the day no need to inspect today. 3k UST from 2003 Thank You Chris Christopher J. Lalak MS Radiological and Chemical Analyst Westchester County Department of Health 145 Huguenot Street - 7th Floor New Rochelle, NY 10801 3/01/19: I spoke with Denise Heinzinger at WCDoH. She states she cannot check the file at this time because it was moved their Mount Kisco office. But she states there is a note on her Spill log which reads: Leaking spill box, WCD Group hired, soil remediated, tank removed on 4/29/15. Cleanup was completed and a report was filed with WCDOH PBS. jod"
Remarks:	"leaking spill box - cleanup in progress"

All Materials:

Site ID:	506147
Operable Unit ID:	1255466
Operable Unit:	01
Material ID:	2258224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Y203 **ST GABRIEL SCHOOL** **NY LTANKS** **S105999147**
WNW **50 WASHINGTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.185 mi.
979 ft. **Site 3 of 3 in cluster Y**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Name:	ST GABRIEL SCHOOL
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY

ST GABRIEL SCHOOL (Continued) **S105999147**

Spill Number/Closed Date:	0302359 / 2003-12-12
Facility ID:	0302359
Site ID:	314440
Spill Date:	2003-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2003-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2019-03-01
Spiller Name:	LARRY
Spiller Company:	ST GABRIEL SCHOOL
Spiller Address:	50 WASHINGTON AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	" 12/12/03 ALSO REPORTED AS 03-05820. SEE THAT FILE FOR UPDATES. NFA THIS NUMBER."
Remarks:	""

All TTF:

Facility ID:	0302359
Spill Number:	0302359
Spill Tank Test:	1528429
Site ID:	314440
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314440
Operable Unit ID:	869188

ST GABRIEL SCHOOL (Continued) **S105999147**

Operable Unit:	01
Material ID:	506840
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z204 **CHURCH-DIVISION STREET, TOWER A** **NY BROWNFIELDS** **S123658107**
SSE **26 SOUTH DIVISION STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.187 mi.
986 ft. **Site 3 of 3 in cluster Z**

Relative: **Higher**
Actual: **99 ft.**

BROWNFIELDS:

Name:	CHURCH-DIVISION STREET, TOWER A
Address:	26 SOUTH DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10805
Program:	BCP
Site Code:	582599
Acres:	0.992
HW Code:	C360187
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	02/22/2019
Record Updated Date:	03/05/2020
Update By:	RDBENDEL
Site Description:	Site Location: The site is located in the City of New Rochelle, Westchester County, New York, at 26 South Division Street on a 0.992-acre lot. The property is located in a mixed use commercial and residential neighborhood and is bounded on the west by South Division Street and on the east by Church Street. The site is a portion of block 414, lot 8. Site Features: The site is currently vacant and formerly housed part of a 62,500 square foot municipal parking garage. The parking garage was demolished in 2018. Current Zoning and Land Use: The Site is zoned DO-2 (Downtown Overlay Zone District) which allows for mixed-use residential and commercial applications. Past Use of the Site: The site was historically occupied from 1891 until 1952 by an auto garage which included a tire repair center as well as several upholsterers. The site was developed as a municipal parking garage from 1972 until 2018. Site Geology and Hydrogeology: Site soils consist of a fill layer which ranges from 6 to 10 feet in depth underlain by a sandy silt layer which extends to weathered bedrock. Fill material consists of sand and silt with varying amounts of gravel, concrete, brick and asphalt. Bedrock was encountered at depths ranging between 8 and 14 feet below grade. Groundwater flows in a southeasterly direction towards the New Rochelle Harbor, approximately 2,000 feet away. Groundwater depth ranges from 9.6 to 12.2 feet below grade.
Env Problem:	Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), metals, Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

for VOCs. Based on investigations conducted to date, the primary contaminants of concern include metals and polycyclic aromatic hydrocarbons (PAHs) in soil. Soil: The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2.3 parts per million (ppm) vs USCO of 1 ppm), benzo[a]pyrene (2.2 ppm vs USCO of 1 ppm), benzo[b]fluoranthene (2.7 parts per million (ppm) vs USCO of 1 ppm), benzo[k]fluoranthene (0.93 ppm vs USCO of 0.8 ppm), Chrysene (2.2 ppm vs USCO of 1 ppm), and indeno(1,2,3-c,d)pyrene (1.4 ppm vs USCO of 0.5 ppm). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): barium (2,590 vs USCO of 350 ppm), cadmium (7.0 ppm vs USCO of 2.5 ppm), copper (52 ppm - 1,300 ppm vs USCO of 50 ppm), lead (89 - 7,550 ppm vs USCO of 63 ppm), mercury (0.245 - 22.7 ppm vs USCO of 0.18 ppm), nickel (30.8 - 41.5 ppm vs USCO of 30 ppm), and zinc (118 - 4,230 ppm vs USCO of 109 ppm) The following pesticides were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): P,P'-DDD (0.00353 - 0.0038 ppm vs USCO of 0.0033 ppm), P,P'-DDE (0.00626 - 0.0109 ppm vs USCO of 0.0033 ppm), and P,P'-DDT (0.00388 - 0.114 ppm vs USCO of 0.0033 ppm). PCBs were also identified in one sample exceeding the Unrestricted Soil Cleanup Objectives of 0.1 ppm at 0.13 ppm. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - No contaminants of concern were identified from the remedial investigation that exceeded the Ambient Water Quality Standards for groundwater (AWQS) including the contaminant classes VOCs, SVOCs, metals, pesticides, and PCBs. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 41.6 and 51.2 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. Based on the on-site groundwater investigation, there is a potential for contamination to migrate off-site towards residential and commercial areas, but the down-gradient area is served by municipal water. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) were detected in on-site soil vapor samples for tetrachloroethylene (PCE) and trichloroethene (TCE) at 437 and 80.6 micrograms per cubic meter (ug/m3) respectively near the center of the site. Soil vapor sampling of the perimeter of the site found PCE detections ranging from 3.53 to 27 ug/m3 and no detections for TCE. These compounds were used in dry cleaners and one was historically located across South Division Street from the site with recorded waste disposal manifests of chlorinated solvents. No detections of CVOCs were found in on-site soils or groundwater, thus the source of the vapors is likely not on-site. The complete excavation of soils across the site, as part of the IRM, may result in the dissipation of vapors remaining on-site.

Health Problem: People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by site related contamination. Access to the site is restricted by a fence. However, people who enter the site may come into contact with soil and groundwater contamination if they dig below the ground surface. Volatile organic compounds in the groundwater and soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

	related contaminants due to soil vapor intrusion does not represent a current concern. Additional evaluations are needed to determine if there is a potential soil vapor intrusion concern for off site buildings.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	5/31/2019 9:47:00 AM
Record Upd:	5/31/2019 9:47:00 AM
Updated By:	JEBROWN
Own Op:	6
Sub Type:	P03
Owner Name:	Jared Dworken
Owner Company:	RXR Church-Division Tower A Holdings LLC
Owner Address:	75 Rockefeller Plaza, Suite 1300
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10019
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	N/A
Owner Company:	City of New Rochelle
Owner Address:	515 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	tom geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	one library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	2/21/2020 10:08:00 AM
Record Updated:	2/21/2020 10:08:00 AM
Updated By:	MDKILMER

X205 **FURNITURE RESTORNATION CENTER** **RCRA NonGen / NLR** **1000872286**
NNE **26 GARDEN ST** **FINDS** **NYD987034998**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.187 mi. **NY MANIFEST**
989 ft. **Site 2 of 3 in cluster X**

Relative: **Lower**
Actual: **72 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	FURNITURE RESTORNATION CENTER
Facility address:	26 GARDEN ST NEW ROCHELLE, NY 10801-4204
EPA ID:	NYD987034998

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Mailing address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	GARDEN ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-633-9292
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KENT ZOOK
Owner/operator address:	26 GARDEN ST NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	914-633-9292
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: FURNITURE RESTORNATION CENTER
Classification: Not a generator, verified

Date form received by agency: 1993-06-02 00:00:00.0
Site name: FURNITURE RESTORNATION CENTER
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 1998-09-02 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:
Registry ID: 110004505287

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000872286
Registry ID:	110004505287
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004505287
Name:	FURNITURE RESTORNATION CENTER
Address:	26 GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	FURNITURE RESTORATION OF NEW ROCHELLE
Address:	26 GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10801-4204
Country:	USA
EPA ID:	NYD987034998
Facility Status:	Not reported
Location Address 1:	26 GARDEN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987034998
Mailing Name:	FURNITURE RESTORATION OF NEW ROCHELLE
Mailing Contact:	HENRY FLAVIC
Mailing Address 1:	166 WEBSTER AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	6111
Mailing Country:	USA
Mailing Phone:	9145923132

NY MANIFEST:

Document ID:	NYG1592532
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	AE53110PA
Trans2 State ID:	Not reported
Generator Ship Date:	07/06/2000
Trans1 Recv Date:	07/06/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987034998
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00935
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	017
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

W206 **CON EDISON** **NY MANIFEST** **S117535600**
SSW **HUGENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.188 mi.
990 ft. **Site 2 of 6 in cluster W**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT ST & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004677837
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677837
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S117535600**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677837
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774864JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W207
SSW
1/8-1/4
0.188 mi.
990 ft.

CON EDISON
HUGENOT AVE & COLUMBUS AVE
NEW ROCHELLE, NY 10802

Site 3 of 6 in cluster W

NY MANIFEST **S117535594**
N/A

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT AVE & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004677621
Facility Status:	Not reported
Location Address 1:	HUGENOT AVE & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677621
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774907JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117535594**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W208 **CON EDISON** **NY MANIFEST** **S117536317**
SSW **HUGUENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.188 mi.
990 ft. **Site 4 of 6 in cluster W**

Relative: **Higher**
Actual: **91 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	HUGUENOT ST & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004687802
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004687802
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117536317**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2014
Trans1 Recv Date:	10/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004687802
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773160JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V209 **DIIORGI HOME** **NY LTANKS** **S106869098**
WSW **47 WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.189 mi.
997 ft. **Site 3 of 4 in cluster V**

Relative: **Higher**

Actual: **98 ft.**

LTANKS:

Name:	DIIORGI HOME
Address:	47 WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0500295 / 2005-08-28
Facility ID:	0500295
Site ID:	343230
Spill Date:	2005-04-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2005-08-28
Spiller Name:	ANTHONY DIIORGI
Spiller Company:	DIIORGI HOME
Spiller Address:	47 WARREN STREET
Spiller County:	001
Spiller Contact:	ANTHONY DIIORGI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	289715
DEC Memo:	"August 28, 2005: GC RELIABLE REMOVED LUST AND CONTAMINATED SOIL. NORTHEST ENVIRONMENTAL DISPOSED OF 18 DRUMS OF SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SHE WILL CALLL BACK WITH MORE INFO:"

All Materials:

Site ID:	343230
Operable Unit ID:	1101915
Operable Unit:	01
Material ID:	582154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U210 **CON EDISON MANHOLE: 4179** **RCRA NonGen / NLR** **1016969613**
North **350 NORTH AVE** **NY MANIFEST** **NYP004432886**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.192 mi.
1014 ft. **Site 3 of 3 in cluster U**

Relative:
Lower

Actual:
71 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-03-04 00:00:00.0
Facility name:	CON EDISON MANHOLE: 4179
Facility address:	350 NORTH AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004432886
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-02-04 00:00:00.0
Site name:	CON EDISON MANHOLE: 4179
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	350 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004432886
Facility Status:	Not reported
Location Address 1:	OPP 350 NORTH AVE
Code:	BP
Location Address 2:	MH4179
Total Tanks:	Not reported

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004432886
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004432886
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692716JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB211 **CON EDISON** **NY MANIFEST** **S117741191**
SW **35 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 2 of 3 in cluster AB**

Relative: **Lower**
Actual: **67 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	35 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004744074
Facility Status:	Not reported
Location Address 1:	35 BARTELS PL
Code:	BP
Location Address 2:	DRIP WATER
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004744074
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117741191**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	008683680FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB212 **CON EDISON** **RCRA NonGen / NLR** **1014398214**
SW **35 BARTELS PL** **NY MANIFEST** **NYP004205654**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.193 mi.
1020 ft. **Site 3 of 3 in cluster AB**

Relative: **Lower**

Actual: **67 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-03-05 00:00:00.0
Facility name:	CON EDISON
Facility address:	35 BARTELS PL NEW ROCHELLE, NY 10805
EPA ID:	NYP004205654
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON (Continued) **1014398214**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-03-05 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 35 BARTELS PL
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004205654
Facility Status: Not reported
Location Address 1: 35 BARTELS PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004205654
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON (Continued) **1014398214**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2010
Trans1 Recv Date:	04/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004205654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	002012659FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC213 **APT BUILDING** **NY LTANKS** **S105230135**
WSW **40 WARREN STREET** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.193 mi.
1021 ft. **Site 1 of 7 in cluster AC**

Relative: **Higher**

Actual: **92 ft.**

LTANKS:

Name:	APT BUILDING
Address:	40 WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0812107 / 2009-03-03
Facility ID:	0812107
Site ID:	409713
Spill Date:	2009-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-06
Spill Record Last Update:	2009-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	359905
DEC Memo:	"Piping failure, need to repair and retest - mm 02/20/2009 Passed retest results that came into PBS to J. O'Dee---BHY 3/3/09: Review of report submitted by WCC Tank Technology. Tank was tested by WCC on 1-9-09 for the property owner. The tank passed the test and documentation was submitted to the owner and the New Rochelle FD. Elite Environmental tested the tank for a prospective buyer on 2-6-09 and failed the tank, resulting in this spill report to the DEC. On 2-12-09 WCC again tested the tank with reps from New Rochelle FD and Royal Environmental. The tank passed this test. All three tests were preformed with the Horner Locator Plus system. Based upon the information received as of this date, DEC is requiring No Further Action at this time. jod"
Remarks:	"550 gal tank failed test/ failure due to bad fitting"

All Materials:

Site ID:	409713
Operable Unit ID:	1166213
Operable Unit:	01
Material ID:	2157665

APT BUILDING (Continued) **S105230135**

Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: SPILL NUMBER 0109254
Address: 40 WARREN ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0109254 / 2001-12-19
Facility ID: 0109254
Site ID: 150939
Spill Date: 2001-12-19
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jghardy
Referred To: Not reported
Reported to Dept: 2001-12-19
CID: 211
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-12-19
Spill Record Last Update: 2002-01-03
Spiller Name: Not reported
Spiller Company: ROBISON OIL
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: MALLARDI RES
Spiller Phone: (914) 636-7448
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 128278
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks: "DRIVER OVERFILLED TANK - SPILL CONTAINED WITH PADS - CLEAN UP CREW ENROUTE"

All Materials:
Site ID: 150939
Operable Unit ID: 846633
Operable Unit: 01
Material ID: 530463
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

APT BUILDING (Continued) **S105230135**

Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: BARRAGAN RESIDENCE
Address: 40 WARREN ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0908848 / 2010-04-08
Facility ID: 0908848
Facility Type: ER
DER Facility ID: 128278
Site ID: 421508
DEC Region: 3
Spill Cause: Other
Spill Class: C3
SWIS: 6010
Spill Date: 2009-11-06
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2009-11-06
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-11-06
Spill Record Last Update: 2010-04-08
Spiller Name: GABREILLE BARRAGAN
Spiller Company: GABREILLE BARRAGAN
Spiller Address: 40 WARREN ST
Spiller Company: 999
Contact Name: NIKKI RICKETTS
DEC Memo: "11/06/09: Property was purchased by a new owner within the past year. New owner passed away, his wife was having the tank replaced for sale of the property. Northeast installed a new AST in the basement and pulled this 1K tank. Contamination evident. New Rochelle FD inspected. Northeast will be completing clean up. jod 02/09/10 Northeast Environmental reported that they excavated and removed one tank along with 35.64 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG"
Remarks: "REMOVAL OF A 1000 GALLON UST SOIL CONTAMINATION FOUND CLEAN UP PENDING."

All Materials:
Site ID: 421508
Operable Unit ID: 1177396
Operable Unit: 01
Material ID: 2170184

APT BUILDING (Continued) **S105230135**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AD214 **CON EDISON TRANSFORMER MANHOLE: 5365** **RCRA NonGen / NLR 1016972665**
SSW **595 MAIN ST** **NY MANIFEST NYP004464459**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.196 mi.
1035 ft. **Site 1 of 5 in cluster AD**

Relative:
Higher

Actual:
93 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-04-12 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5365
Facility address:	595 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004464459
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-03-12 00:00:00.0
Site name:	CON EDISON TRANSFORMER MANHOLE: 5365
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

NY MANIFEST:

Name:	CON EDISON
Address:	595 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10804
Country:	USA
EPA ID:	NYP004464459
Facility Status:	Not reported
Location Address 1:	595 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10804
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004464459
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/12/2014
Trans1 Recv Date:	03/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004464459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771156JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X215 **COTTAGE - GARDEN AUTO REPAIR** **NY UST** **U004315585**
NNE **30 GARDEN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.197 mi.
1038 ft. **Site 3 of 3 in cluster X**

Relative: **Lower**

Actual: **71 ft.**

WESTCHESTER CO. UST:

Name:	COTTAGE - GARDEN AUTO REPAIR
Address:	30 GARDEN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-802310 / Active
Operator Name:	The Mark 95 LLC, Mark II LLC, MJ Garden LLC
Owner Name:	Mark Stagg-The Mark 95 LLC, Mark II LLC, MJ Garden
Owner Street:	1763 Pitman Avenue
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10710
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/14/2001
Date Perm Closure:	02/10/2020
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None

COTTAGE - GARDEN AUTO REPAIR (Continued) **U004315585**

Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/14/2001
Date Perm Closure:	02/10/2020
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	3
Status:	3. Closed - Removed
Capacity:	500
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	02/24/2020
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

AD216 **CON EDISON TRANSFORMER MANHOLE: 2806** **RCRA NonGen / NLR** **1016962648**
South **592 MAIN ST** **NY MANIFEST** **NYP004357059**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.197 mi.
1040 ft. **Site 2 of 5 in cluster AD**

Relative:
Higher

Actual:
95 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-10-09 00:00:00.0
Facility name:	CON EDISON TRANSFORMER MANHOLE: 2806
Facility address:	592 MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004357059
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-09-09 00:00:00.0
Site name:	CON EDISON TRANSFORMER MANHOLE: 2806
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	592 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10804
Country:	USA
EPA ID:	NYP004357059
Facility Status:	Not reported
Location Address 1:	592 MAIN ST.
Code:	BP
Location Address 2:	MH # 2806
Total Tanks:	Not reported

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004357059
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2013
Trans1 Recv Date:	09/09/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004357059
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707806JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE217 **RUSH MFG CORP** **RCRA NonGen / NLR** **1000238316**
SSW **18 COLUMBUS AVE** **FINDS** **NYD981185051**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.200 mi. **NY MANIFEST**
1054 ft. **Site 1 of 2 in cluster AE**

Relative: **Lower**
Actual: **79 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	RUSH MFG CORP
Facility address:	18 COLUMBUS AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD981185051
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact:	DENNIS MCNAMARA
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-636-2700
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MATTHEW RUSH
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

RUSH MFG CORP (Continued) **1000238316**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: RUSH MFG CORP
Classification: Not a generator, verified

Date form received by agency: 1986-03-03 00:00:00.0
Site name: RUSH MFG CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Violation Status: No violations found

FINDS:
Registry ID: 110002092967

Click Here:

Environmental Interest/Information System:
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

RUSH MFG CORP (Continued) **1000238316**

ECHO:

Envid:	1000238316
Registry ID:	110002092967
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002092967
Name:	RUSH MFG CORP
Address:	18 COLUMBUS AVE.
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	RUSH MANUFACTURING CORPORATION
Address:	18 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD981185051
Facility Status:	Not reported
Location Address 1:	381 HUGUENOT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981185051
Mailing Name:	RUSH MANUFACTURING CORPORATION
Mailing Contact:	RUSH MANUFACTURING CORPORATION
Mailing Address 1:	381 HUGUENOT STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142362700

NY MANIFEST:

Document ID:	NJA2751945
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	2809
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1997
Trans1 Recv Date:	12/30/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	12/30/1997
Part A Recv Date:	01/15/1998
Part B Recv Date:	01/20/1998
Generator EPA ID:	NYD981185051
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

RUSH MFG CORP (Continued) **1000238316**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

V218 **NYNEX** **NY MANIFEST** **1009234555**
West **UNION AVENUE AND WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.201 mi.
1060 ft. **Site 4 of 4 in cluster V**

Relative: **Higher**
Actual: **97 ft.**

NY MANIFEST:

Name:	NYNEX
Address:	UNION AVENUE AND WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP000932509
Facility Status:	Not reported
Location Address 1:	UNION AVENUE AND WARREN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000932509
Mailing Name:	NYNEX
Mailing Contact:	V ORCHIER
Mailing Address 1:	221 EAST 37TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA

NYNEX (Continued) **1009234555**

Mailing Phone: 2123387126

NY MANIFEST:

Document ID:	MIA4512835
Manifest Status:	K
seq:	Not reported
Year:	1996
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/1996
Trans1 Recv Date:	12/17/1996
Trans2 Recv Date:	12/20/1996
TSD Site Recv Date:	01/03/1997
Part A Recv Date:	/ /
Part B Recv Date:	01/23/1997
Generator EPA ID:	NYP000932509
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574
TSDF ID 1:	MID096963194
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

219
WSW
1/8-1/4
0.202 mi.
1067 ft.

CITIZEN **NY LTANKS** **S100165790**
33 GROVE ST **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	CITIZEN
Address:	33 GROVE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8708588 / 1989-11-28

CITIZEN (Continued) **S100165790**

Facility ID:	8708588
Site ID:	135309
Spill Date:	1988-01-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-11-28
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-27
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	CAPT. FERGESON
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK RUPTURE IN CITIZEN'S BASEMENT. TANK TO BE EMPTIED."

All Materials:

Site ID:	135309
Operable Unit ID:	913258
Operable Unit:	01
Material ID:	463968
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	550.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AF220 **THE MALL** **NY LTANKS** **S100141913**
East **MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.204 mi.
1076 ft. **Site 1 of 3 in cluster AF**

Relative: **Lower**

Actual: **80 ft.**

LTANKS:

Name:	THE MALL
Address:	MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9010648 / 1991-01-04
Facility ID:	9010648
Site ID:	326514
Spill Date:	1991-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-10
Spill Record Last Update:	1992-07-31
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	263025
DEC Memo:	"Administratively closed due to file review and/or information received. If new information arises to contradict this determination DEC reserves the right to reopen this spill without prejudice. Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WATER FOUND IN TANK TO BE PUMPED OUT HONER EASY -.087"

All TTF:

Facility ID:	9010648
Spill Number:	9010648
Spill Tank Test:	1538129
Site ID:	326514
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

THE MALL (Continued) **S100141913**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	326514
Operable Unit ID:	947782
Operable Unit:	01
Material ID:	430787
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AG221 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1017773973**
South **CENTRE AVE & LEROY** **FINDS** **NYP004517694**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1083 ft. **Site 1 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-05-30 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	CENTRE AVE & LEROY NEW ROCHELLE, NY 10801
EPA ID:	NYP004517694
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2014-04-30 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 2014-04-30 00:00:00.0
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:
Registry ID: 110063800506

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AG222 **CON EDISON** **NY MANIFEST** **S117059593**
South **CENTRE AVE & LEROY** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.205 mi.
1083 ft. **Site 2 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:
Name: CON EDISON
Address: CENTRE AVE & LEROY
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004517694
Facility Status: Not reported
Location Address 1: C/O CENTRE AVE & LEROY PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004517694
Mailing Name: CON EDISON
Mailing Contact: CON EDISON

CON EDISON (Continued) **S117059593**

Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2014
Trans1 Recv Date:	04/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004517694
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772797JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG223 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1016973761**
South **LEROY PL & CENTER AVE** **NY MANIFEST** **NYP004475687**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.205 mi.
1083 ft. **Site 3 of 4 in cluster AG**

Relative:
Higher

Actual:
101 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-04-22 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 3313
Facility address:	LEROY PL & CENTER AVE NEW ROCHELLE, NY 10802
EPA ID:	NYP004475687
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-03-22 00:00:00.0
Site name:	CON EDISON SERVICE BOX: 3313
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	LEROY PL & CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004475687
Facility Status:	Not reported
Location Address 1:	SEC LEROY & CENTRE AVE
Code:	BP
Location Address 2:	SB3313
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004475687
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2014
Trans1 Recv Date:	03/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004475687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772784JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH224 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016970578**
ESE **174 NORTH AVE** **NY MANIFEST** **NYP004442943**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1091 ft. **Site 1 of 11 in cluster AH**

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-03-16 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	174 NORTH AVE NEW ROCHELLE, NY 10804
EPA ID:	NYP004442943
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-02-16 00:00:00.0
Site name:	CON EDISON SERVICE BOX: 2040
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 174 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10804
Country: USA
EPA ID: NYP004442943
Facility Status: Not reported
Location Address 1: FO 174 NORTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004442943
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004442943
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692698JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W225 **381-383 HUGUENOT LLC** **NY UST** **U004315578**
SSW **381 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1092 ft. **Site 5 of 6 in cluster W**

Relative: **Higher**
Actual: **90 ft.**

WESTCHESTER CO. UST:

Name:	381-383 HUGUENOT LLC
Address:	381 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-802286 / Active
Operator Name:	Not reported
Owner Name:	381-383 Huguenot LLC
Owner Street:	20 Amelia Earhart Lane
Owner Address2:	Not reported
Owner City:	Rye
Owner State:	NY
Owner Zipcode:	10580
GDS Number:	Not reported
Tank Number:	UST-1
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron

381-383 HUGUENOT LLC (Continued) **U004315578**

Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	UST-2
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	UST-3
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

W226 **THE HUGUENOT** **NY BROWNFIELDS** **S120706214**
SSW **381-393 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1092 ft. **Site 6 of 6 in cluster W**

Relative:
Higher

Actual:
90 ft.

BROWNFIELDS:

Name:	THE HUGUENOT
Address:	381-393 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	544502
Acres:	0.39
HW Code:	C360157
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	03/29/2017
Record Updated Date:	03/02/2020
Update By:	AMOMOROG
Site Description:	Location: The 0.39-acre site is located in an urban area at 381-393 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site consists of four irregular-shaped parcels and currently maintains two structures. A 3,400-square foot one-story building with a partial basement sits on the south end of the site which, until August of 2018, was used for office and storage space associated with a U-Haul business, a real-estate firm, and a janitorial supply business. The second structure is a two-story building located on the north end of the site that until June of 2018 housed a church ministry on the first floor, two apartments on the second floor, and a hydraulic repair business in the basement. Both buildings are now vacant pending demolition. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The site and surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site has been utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. The potential source of contamination in this area includes the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site has maintained a residential dwelling since 1931, and has been used for truck and trailer parking since the 1990s. The potential source of contamination in this area includes a former fuel oil UST, which was removed prior to 1997. The southern portion of the site has maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then a warehouse from the 1970s to 2010s. The potential source of contamination in this area includes former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation

THE HUGUENOT (Continued) **S120706214**

(NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction.

Env Problem:

Nature and Extent of Contamination: Based upon investigations conducted to date, the primary contaminants of concern found in site soils include semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals. Soil - Numerous soil borings were completed between 2016 and 2018 to delineate the nature and extent of contamination on the site. Soil samples were analyzed for VOCs, SVOCs, metals, pesticides and PCBs. The investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted residential use soil cleanup objectives (RRSCOs). SVOCs identified in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - On-site groundwater was investigated through the installation of monitoring wells located on and around the site. Groundwater investigations were conducted between 2016 and 2018 and included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and per- and polyfluoroalkyl substances (PFAS). VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum

THE HUGUENOT (Continued) **S120706214**

concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected in 2018. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in all the groundwater samples collected both on and off-site in 2018. Total PFOA+PFOS levels ranged from 25.8 to 184 parts per trillion (ppt) in the five on-site monitoring wells, and 16.7 to 32 ppt in the three off-site monitoring wells. Three of the five on-site monitoring wells were found with total PFOA+PFOS levels exceeding the Environmental Protection Agency s (EPA's) health advisory level of 70 ppt, with the highest levels found in the two monitoring wells located on the south side of the site adjacent to the former car wash and gas station. The third on-site monitoring well with total PFOA+PFOS levels exceeding the EPA health advisory level of 70 ppt is located on the west side of the site downgradient of the former dry-cleaning operation. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during the Phase II Environmental Site Assessment in 2016 and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site and only one of the six owners agreed to the sampling. Soil vapor intrusion sampling was conducted during the Remedial Investigation in March 2018 at this adjacent building located north of the site that houses a church ministry on the first floor with apartments located above. Air samples collected were analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air,

THE HUGUENOT (Continued) **S120706214**

maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings.

Health Problem: People will not come into contact with contaminated soil or groundwater unless they dig below ground surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. However, an evaluation of the potential for soil vapor intrusion to occur is recommended for any site redevelopment. Soil vapor intrusion sampling was conducted at one off-site building and no soil vapor intrusion concerns were identified. Further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/22/2018 12:50:00 PM
Record Upd: 6/6/2019 1:24:00 PM
Updated By: GWHEITZM
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 11604 Luvie Ct.
Owner Addr2: Not reported
Owner City,St,Zip: Potomac, MD 20854
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: Not reported
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN

THE HUGUENOT (Continued) **S120706214**

Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,3-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	selenium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

THE HUGUENOT (Continued) **S120706214**

HW Code:	Not reported
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	fluorene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	sec-butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported

THE HUGUENOT (Continued) **S120706214**

Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	10/19/2018 11:54:00 AM
Record Updated:	10/19/2018 11:54:00 AM
Updated By:	JBODEE

AI227 **SCHMUCKLER'S DRY CLEANERS - OFF SITE** **NY BROWNFIELDS** **S121933772**
North **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1094 ft. **Site 1 of 15 in cluster AI**

Relative: **Lower**
Actual: **74 ft.**

BROWNFIELDS:

Name:	SCHMUCKLER'S DRY CLEANERS - OFF SITE
Address:	358-364 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10804
Program:	BCP
Site Code:	551607
Acres:	Not reported
HW Code:	C360088A
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/13/2017
Record Updated Date:	06/03/2019
Update By:	KJCARPEN
Site Description:	Location: This is the off-site component to Schmuckler s Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. Site Features: This off-site investigation covers an approximately one city block area encompassing surrounding buildings and downgradient direction of groundwater flow. Current Zoning/Use(s): Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commerical uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site is provided from a municipal source. Past Uses of the Site: The area of the off-site includes multiple commercial and residential current and historical uses. Site Geology and Hydrogeology: The site is underlain by fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater flows to the southeast. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater.
Env Problem:	The on-site BCP site, a former dry cleaner, has CVOCs and petroleum contaminants associated with it. Information will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported

SCHMUCKLER'S DRY CLEANERS - OFF SITE (Continued) **S121933772**

Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AI228 **SCHMUCKLER'S DRY CLEANERS** **NY BROWNFIELDS** **S107787044**
North **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1094 ft. **Site 2 of 15 in cluster AI**

Relative: BROWNFIELDS:
Lower

Actual: Name:	SCHMUCKLER'S DRY CLEANERS
74 ft. Address:	358-364 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10804
Program:	BCP
Site Code:	357446
Acres:	0.21
HW Code:	C360088
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/29/2005
Record Updated Date:	06/03/2019
Update By:	KJCARPEN
Site Description:	Location: The Schmuckler s Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. The site is 0.21 acres, most of which is covered by a two-story row building with a full basement. Site Features: Site Features: In addition to the former dry cleaners, historically located on the first floor, the site also includes an enclosed backyard area to the immediate west of the building. The backyard consists of lawn, elevated planting beds, concrete pad, and a paved walkway. Current Zoning/Use(s): The site is commercially zoned, and

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

currently has five commercial tenants occupying both the first and second floors. Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commercial uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site is provided from a municipal source. Past Uses of the Site: The building on-site was built in 1891, and operated by Schmuckler s Cleaners from 1914 to 2006 on the first floor and basement of the building. Additions were added to the building in 1937, and two in 1987. The site was acquired by the Volunteer, HNJ Realty, LLC, in August 2005, and entered into the Brownfield Cleanup Program in June 2006. Site Geology and Hydrogeology: The site is underlain by fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater flows to the southeast. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater.

Env Problem:

Based on the investigations conducted to date, the which included the analysis for volatile organic and semi-volatile organic compounds (VOCs and SVOCs), inorganics, polychlorinated bi-phenols (PCBs) and pesticides in soil and groundwater and VOCs in soil vapor, the primary contaminants of concern at the site are chlorinated volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE) and its breakdown compounds, in soils, groundwater, sub-slab vapor, and soil gas; petroleum-related VOCs in soils, groundwater, sub-slab vapor, and soil gas; and semi-volatile organic compounds (SVOCs) in groundwater. In August 2015 an in situ pilot test was performed to assess potential remedial effectiveness of an enhanced biological product. Prior to the pilot injection, the test well contained 27,000 parts per billion (ppb) of PCE, 960 ppb of trichloroethylene (TCE), 2,100 ppb of cis-1,2-dichloroethylene (DCE) and 49 ppb of vinyl chloride (VC). Post injection levels after two months were 8,100 ppb of PCE, 11,000 ppb of TCE, 1,500 ppb of cis-1,2-DCE, and 53 ppb of VC. The decrease in PCE concentrations, coupled with the increase in degradation products, indicate that the breakdown of contaminants (dechlorination) is occurring. SVOC concentrations also decreased in the test well after the pilot. For example phenanthrene levels dropped from 78 ppb to 3.7 ppb two months after the pilot injection. An expansion of the pilot test using the same enhanced biological product was performed in October 2017. This time, the injections occurred in five wells in the basement and outside the building, while monitoring occurred in six wells located around the site. In July 2017, prior to the expansion of the expanded test, the highest concentration of PCE was 17,000 ppb, TCE was 2,100 ppb, cis-1,2-DCE was 1,600 ppb, and VC was 73. Two months after the injections, in December 2017, the concentrations of contaminants in the same well were: 1,300 ppb PCE, 17,000 ppb TCE, 1,900 ppb cis-1,2-DCE, and 61 ppb VC. The highest concentration of SVOCs during the pilot expansion was phenanthrene which dropped from 2,000 ppb to 540 ppb two months after the injection event. In addition, approximately 40-gallons of LNAPL have been collected to date just off-site in the southeast, downgradient direction using both bailers and a sorbent recovery socks left in the well in between monitoring/bailing events. Soils:

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Tetrachloroethylene (PCE), trichloroethene (TCE), and multiple petroleum related VOCs were detected in onsite soils underneath the building slab. The highest concentration of PCE at 210 parts per million (ppm), exceeding restricted commercial soil cleanup objectives (SCOs), was located underneath the former dry cleaning equipment room. Other contaminants detected in soils only exceeded the Protection of Groundwater SCOs. These exceedences were largely in soils located downgradient of the dry cleaning equipment room and consisted of: TCE at 1.3 ppm, cis-1,2 dichloroethene (cis-1,2-DCE) at 3 ppm, n-propylbenzene at 16 ppm, m+p xylenes at 15 ppm, ethylbenzene at 6.6 ppm, 1,3,5-trimethylbenzene at 63 ppm, and 1,2,4-trimethylbenzene at 99 ppm. There is no indication of off-site soil contamination. Groundwater: Petroleum-based floating product (light non-aqueous phase liquid or LNAPL) was observed in groundwater under much of the on-site building slab, a maximum of 6 inches thick under the former dry cleaning equipment room. Also observed were very high concentrations of select VOCs also under the former drycleaning equipment room. The maximum detected PCE was 830,000 parts per billion (ppb), and TCE at 58,000 ppb. 25 individual VOCs were also detected in site groundwater samples exceeding NYS Class GA groundwater standards. These include the above-mentioned PCE, TCE, as well as other maximum detected concentrations of PCE breakdown products: cis-1,2-DCE at 8,700 ppb, and vinyl chloride at 28 ppb. BTEX was detected, with benzene at 62 ppb, toluene at 130 ppb, ethylbenzene at 150 ppb, m+p xylene at 520 ppb, and o-xylene at 290 ppb. Other significant concentrations of VOCs detected in groundwater include 1,3,5-trimethylbenzene at 890 ppb, and 1,2,4-trimethylbenzene at 840 ppb. Eight SVOCs were detected over groundwater standards in groundwater under the building slab, including napthalene at a concentration of 1300 ppb, phenanthrene at 2400 ppb, acenapthene at 710 ppb, and antracene at 280 ppb. Bedrock wells were installed off-site in the downgradient, sidegradient, and upgradient directions. Petroleum-based VOCs and SVOCs were detected in the bedrock aquifer at concentrations above groundwater standards. For VOCs, total maximum BTEX concentration of 722 ppb was detected in a downgradient bedrock well. 11 individual SVOC contaminants were detected over groundwater standards in the same downgradient off-site bedrock well, including naphthalene at 4100 ppb, phenanthrene at 2800 ppb, acenapthene at 710 ppb, and antracene at 300 ppb. The extent of groundwater contamination is concentrated underneath the on-site building slab, with petroleum-based VOC and SVOC contaminants and LNAPL extending off-site in the bedrock downgradient or southeast direction. Soil Gas/Soil Vapor: The high concentrations of PCE (787,000 ug/m3), TCE (15,200 ug/m3), cis-1,2-DCE (46,000 ug/m3), and Vinyl Chloride (34 ug/m3) in soil vapor under the slab of the on-site building required the installation and continuing operation of a combined soil vapor extraction and sub-slab mitigation system during a 2008-2013 Interim Remedial Measure (IRM) action. PCE (at 91 ug/m3) and TCE (13.4 ug/m3) were also detected in soil gas outside of the building near the location of a former drywell. Benzene (37 ug/m3), toluene (126 ug/m3), ethylbenzene (85 ug/m3), xylene (555 ug/m3), 1,3,5-trimethylbenzene (3 ug/m3), and 1,2,4-trimethylbenzene (14 ug/m3) were also detected in subslab vapor and soil gas. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.

Health Problem: People may contact contaminants in soil or groundwater if they dig

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

below the surface or contact contaminated groundwater. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of the buildings, is referred to as soil vapor intrusion. A combination soil vapor extraction and sub-slab depressurization system was installed in the on-site building to prevent vapors beneath the slab from entering the building. There is a potential for inhalation of site contaminants due to soil vapor intrusion at this building when the sub-slab depressurization system is turned off for a period of time during groundwater bioremediation injection treatments. Soil vapor intrusion sampling at one off-site building did not identify any soil vapor intrusion concerns for that building. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for other off-site buildings.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:54'51 / 73:47'03
Dell:	False
Record Add:	12/29/2005 2:46:00 PM
Record Upd:	11/10/2015 3:54:00 PM
Updated By:	KATHOMPS
Own Op:	1
Sub Type:	P03
Owner Name:	Hal Shapiro
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave #107
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Comfort Homes & Property Management LLC
Owner Address:	358 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	HAL SHAPIRO
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave
Owner Addr2:	#107
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Owner Company:	New Rochelle Public Library
Owner Address:	1 Liberty Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	United Community Center of Westchester, Inc.
Owner Address:	360 - 362 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Stephanie Mossey
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Neighborhood Taxi
Owner Address:	364 North Ave; Suite 108
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Swan Beauty Spa, Inc
Owner Address:	364 North Ave., Room 101
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	cymene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

HW Code:	Not reported
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,4-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	acenaphthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,2-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	diethyl phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1,2,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	fluorine
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	9/7/2017 1:27:00 PM
Record Updated:	9/7/2017 1:27:00 PM
Updated By:	KATHOMPS

AI229 **HNJ REALTY** **PA MANIFEST** **S123092729**
North **358-364 N AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1094 ft. **Site 3 of 15 in cluster AI**

Relative: PA MANIFEST:
Lower No Details: No Details

Actual:
74 ft.

AI230 **HNJ REALTY** **PA MANIFEST** **S123092728**
North **358-364 N AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1094 ft. **Site 4 of 15 in cluster AI**

Relative: Manifest Details:
Lower

Actual:
74 ft.

Year:	2017
Manifest Number:	006197432FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD012950779
Generator Date:	01/31/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Evoqua Water Technologies LLC
TSD Facility Address:	118 Park Rd
TSD Facility City:	Darlington
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D040
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	600
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD987270725
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	006197432FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD012950779
Generator Date:	01/31/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Evoqua Water Technologies LLC
TSD Facility Address:	118 Park Rd
TSD Facility City:	Darlington
TSD Facility State:	PA

HNJ REALTY (Continued) **S123092728**

Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	600
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD987270725
Date TSP Sig:	Not reported

AI231 **SCHMUKLER'S CLEANERS** **NY DRYCLEANERS** **S110247878**
North **360 NORTH AVE.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.211 mi.
1113 ft. **Site 5 of 15 in cluster AI**

Relative: **Lower**
Actual: **75 ft.**

DRYCLEANERS:

Name:	SCHMUKLER'S CLEANERS
Address:	360 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00327
Phone Number:	914-632-2705
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	2013-11-07 00:00:00
Install Date:	98/06
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AI232 **SCHMUCKLERS CLEANERS** **RCRA-VSQG** **1000303485**
North **360 NORTH AVE** **NY MANIFEST** **NYD012950770**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.211 mi.
1113 ft. **Site 6 of 15 in cluster AI**

Relative: **Lower**
Actual: **75 ft.**

RCRA-VSQG:

Date form received by agency:	2008-03-31 00:00:00.0
Facility name:	SCHMUCKLERS CLEANERS
Facility address:	360 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD012950770
Mailing address:	BLACK BIRCH LANE SCARSDALE, NY 10583
Contact:	HAL I SHAPIRO
Contact address:	BLACK BIRCH LANE SCARSDALE, NY 10583
Contact country:	US
Contact telephone:	917-693-9019
Contact email:	HALSHAP@GMAIL.COM
EPA Region:	02

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: HNJ REALTY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2007-08-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: HNJ REALTY LLC
Owner/operator address: BLACK BIRCH LANE
SCARSDALE, NY 10583
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2005-08-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2008-03-30 00:00:00.0
Site name: SCHMUCKLERS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2006-01-01 00:00:00.0
Site name: SCHMUKLERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1998-03-09 00:00:00.0
Site name: SCHMUKLERS
Classification: Small Quantity Generator

Date form received by agency: 1993-10-29 00:00:00.0
Site name: SCHMUKLERS
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(3)
Area of violation: Generators - General
Date violation determined: 2003-09-08 00:00:00.0
Date achieved compliance: 2003-09-18 00:00:00.0
Violation lead agency: State

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 2003-09-18 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1999-05-20 00:00:00.0
Date achieved compliance: 2003-09-08 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1999-07-06 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 1999-05-20 00:00:00.0
Date achieved compliance: 2003-09-08 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1999-07-06 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 1999-05-20 00:00:00.0
Date achieved compliance: 2003-09-08 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1999-07-06 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 2003-09-08 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 2003-09-18 00:00:00.0
Evaluation lead agency: State

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Evaluation date: 1999-05-20 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 2003-09-08 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1999-05-20 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 2003-09-08 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1999-05-20 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 2003-09-08 00:00:00.0
Evaluation lead agency: State

NY MANIFEST:
Name: SHMUCKLERS DRY CLEANERS
Address: 360 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYD012950770
Facility Status: Not reported
Location Address 1: 360 NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD012950770
Mailing Name: SHMUCKLERS DRY CLEANERS
Mailing Contact: SHMUCKLERS DRY CLEANERS
Mailing Address 1: 360 NORTH AVENUE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146322705

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 09/18/2006
Trans1 Recv Date: 09/18/2006
Trans2 Recv Date: 09/25/2006
TSD Site Recv Date: 09/26/2006

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	000814271JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ233 **NEW ROCHELLE HOSPITAL** **NY LTANKS** **S100141273**
NW **COVION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.211 mi.
1114 ft. **Site 1 of 6 in cluster AJ**

Relative:
Higher

Actual:
102 ft.

LTANKS:

Name:	NEW ROCHELLE HOSPITAL
Address:	COVION PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9003911 / 1991-03-15
Facility ID:	9003911
Site ID:	136814
Spill Date:	1990-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	1991-04-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	117069
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/15/91: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WILL EIR PBS TO FOLLOW AINLEY +.094"

All TTF:

Facility ID:	9003911
Spill Number:	9003911
Spill Tank Test:	1537277
Site ID:	136814
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	136814
Operable Unit ID:	941734
Operable Unit:	01
Material ID:	435036
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

Units: Not reported
Recovered: .00
Oxygenate: Not reported

AJ234 **SOUND SHORE MEDICAL CENTER** **RCRA-SQG** **1000130172**
NW **16 GUION PL** **FINDS** **NYD075431502**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.216 mi. **NY MANIFEST**
1140 ft. **Site 2 of 6 in cluster AJ**

Relative: Higher
Actual: 100 ft.

RCRA-SQG:
Date form received by agency: 2013-10-31 00:00:00.0
Facility name: SOUND SHORE MEDICAL CENTER
Facility address: 16 GUION PL
NEW ROCHELLE, NY 10802
EPA ID: NYD075431502
Mailing address: GUION PL
NEW ROCHELLE, NY 10802
Contact: GARRETT T DOERING
Contact address: E 210TH ST
BRONX, NY 10467
Contact country: US
Contact telephone: 717-920-7600
Contact email: GDOREING@MONTEFIORE.ORG
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-632-5000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175
YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: 914-378-6300
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Owner/Operator Type: Owner
Owner/Op start date: 2013-11-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner/operator address: CORPORATE BLVD SOUTH SUITE 175
YONKERS, NY 10701
Owner/operator country: US
Owner/operator telephone: 914-378-6300
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2013-11-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: SOUND SHORE MEDICAL CENTER
Owner/operator address: 16 GUION PL
NEW ROCHELLE, NY 10802
Owner/operator country: US
Owner/operator telephone: 914-632-5000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2007-01-01 00:00:00.0
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2006-01-01 00:00:00.0
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Date form received by agency: 1997-09-08 00:00:00.0
Site name: SOUNDSHORE MEDICAL CENTER
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U170
. Waste name: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 2012-09-11 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:
Registry ID: 110004368620

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

Click Here:

Environmental Interest/Information System:
COMPLIANCE AND EMISSIONS REPORTING
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000130172
Registry ID:	110004368620
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004368620
Name:	MONTEFIORE - NEW ROCHELLE HOSPITAL
Address:	16 GUION PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	MONTEFIORE NEW ROCHELLE HOSPITAL
Address:	16 GUION PL
City,State,Zip:	NEW ROCHELLE, NY 10802-9982
Country:	USA
EPA ID:	NYD075431502
Facility Status:	Not reported
Location Address 1:	16 GUION PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD075431502
Mailing Name:	MONTEFIORE NEW ROCHELLE HOSPITAL
Mailing Contact:	JARED SHAPIRO
Mailing Address 1:	111 EAST 210TH STREET
Mailing Address 2:	ENVIRONMENTAL HEALTH & SAFETY
Mailing City:	BRONX
Mailing State:	NY
Mailing Zip:	10467
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189207600

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **1000130172**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2013
Trans1 Recv Date:	12/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	006926469FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	51
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	U010
Waste Code 1_2:	U035
Waste Code 1_3:	U058
Waste Code 1_4:	U059
Waste Code 1_5:	U150
Waste Code 1_6:	Not reported

AJ235 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **NY UST U003857945**
NW **16 GUION PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1140 ft. **Site 3 of 6 in cluster AJ**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. UST:

Name:	MONTEFIORE - NEW ROCHELLE HOSPITAL
Address:	16 GUION PLACE
City,State,Zip:	NEW ROCHELLE, NY 10802
Id/Status:	3-123269 / Active

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Operator Name:	Montefiore Medical Center
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10467
GDS Number:	Not reported

Tank Number:	2 day
Status:	4. Closed - in place
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1978
Date Perm Closure:	Not reported
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0008. Diesel

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1981
Date Perm Closure:	07/19/2006
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5B
Status:	1. In-Service
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	07/01/2006
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	8
Status:	1. In-Service
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	0
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	10/22/2010
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	plastic sleeve
Overfill Prevention:	2. High Level Alarm

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Secondary Containment: 4. Double-Walled (underground only)
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

WESTCHESTER CO. AST:
Name: MONTEFIORE - NEW ROCHELLE HOSPITAL
Address: 16 GUION PLACE
City,State,Zip: NEW ROCHELLE, NY 10802
PBS Number: 3-123269
Site Status: Active
GDS Number: Not reported
Operator Name: Montefiore Medical Center
Owner Name: Montefiore Medical Center
Owner Street: 111 East 210th Street
Owner Address2: Not reported
Owner City/State/Zip: Bronx, NY 10467

Tank Number: # 8 Day
Status: 1. In-Service
Date Installation: 10/22/2010
Capacity: 25
Product Stored: 0008. Diesel
Product Stored Percent: 0
Date Perm Closure: 01/01/1900
Tank Location: 2. Aboveground (contact w/ impervious barrier)
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 1. Diking (aboveground only),6. Remote impounding area
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 04
Status: 3. Closed - Removed
Date Installation: 01/01/1997
Capacity: 2000
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Date Perm Closure: 12/19/2018
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: other
Tank Leak Detection: 0. None
Tank Secondary Containment: 9. Modified double-walled (aboveground only)
Piping Location: 1. Aboveground
Piping Type: 10. Copper
Piping External Protection: 99. Other
Piping Leak Detection: 0. None

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 day
Status:	1. In-Service
Date Installation:	06/01/1976
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1971
Capacity:	30000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3 day
Status:	1. In-Service
Date Installation:	07/01/1980
Capacity:	50
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	12/01/1981
Capacity:	500
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	12/01/2005
Capacity:	700
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/2016
Capacity:	10000

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AJ236 **SOUTH SHORE MED CENTER** **NY LTANKS** **S107523501**
NW **16 GUION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1140 ft. **Site 4 of 6 in cluster AJ**

Relative: **Higher**

Actual: **100 ft.**

LTANKS:

Name:	SOUTH SHORE MED CENTER
Address:	16 GUION PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512440 / 2006-12-19
Facility ID:	0512440
Site ID:	358758
Spill Date:	2006-01-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-01-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2006-12-22
Spiller Name:	VERONICA
Spiller Company:	SOUND SHORE MED CENTER
Spiller Address:	16 GUION PLACE
Spiller County:	001
Spiller Contact:	VERONICA
Spiller Phone:	(201) 489-8700
Spiller Extention:	Not reported
DEC Region:	3

SOUTH SHORE MED CENTER (Continued) **S107523501**

DER Facility ID: 308757
DEC Memo: "Tank removed, no contamination found. NFA jod 12/22/06 - Letter from Wayne Schneider of WCDOD dated 8/29/06 addressed to Dir. of Engr., Sound Shore Medical Center, has requested NYSDEC to colose this spill #."
Remarks: "Tank test failure. Ullage leak was detected."

All TTF:
Facility ID: 0512440
Spill Number: 0512440
Spill Tank Test: 1549678
Site ID: 358758
Tank Number: 5
Tank Size: 2000
Material: 0008
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 358758
Operable Unit ID: 1115985
Operable Unit: 01
Material ID: 2106096
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AJ237 **SOUND SHORE MEDICAL CENTER** **PA MANIFEST** **S111771577**
NW **16 GUION PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1140 ft. **Site 5 of 6 in cluster AJ**

Relative:
Higher

Actual:
100 ft.

Manifest Details:
Year: 2010
Manifest Number: 006962317JJK
Manifest Type: TSD Copy
Generator EPA Id: NYD075431502
Generator Date: 10/19/2010
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: NULL
TSD EPA Id: PAD067098822

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U188
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

---

238 **RESIDENCE** **NY LTANKS** **S107489339**
West **79 WARREN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1141 ft.

Relative: **Higher**

Actual: **98 ft.**

LTANKS:

Name:	RESIDENCE
Address:	79 WARREN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510555 / 2006-03-28
Facility ID:	0510555
Site ID:	356553
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-28
Spiller Name:	ISHMAL GALVIN
Spiller Company:	RESIDENCE
Spiller Address:	79 WARREN ST
Spiller County:	001
Spiller Contact:	ISHMAL GALVIN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306611
DEC Memo:	"March 28, 2006: GRAZI-1 CORP DISPOSED OF LUST AND 67.95 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons"

All Materials:

RESIDENCE (Continued) **S107489339**

Site ID:	356553
Operable Unit ID:	1113853
Operable Unit:	01
Material ID:	2103913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ239 **66 MEMORIAL BLVD** **NY LTANKS** **S104621761**
NW **66 MEMORIAL BLVD** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1142 ft. **Site 6 of 6 in cluster AJ**

Relative: **Higher**
Actual: **90 ft.**

LTANKS:

Name:	66 MEMORIAL BLVD
Address:	66 MEMORIAL BLVD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0002907 / 2000-10-24
Facility ID:	0002907
Site ID:	59397
Spill Date:	2000-06-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-06-08
CID:	389
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-08
Spill Record Last Update:	2000-11-21
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	58153
DEC Memo:	""
Remarks:	"caller reporting a spill of material from a tank being hit while escavating land for a basement. no callback is necessary caller is

66 MEMORIAL BLVD (Continued) **S104621761**

anaymous. clena up is being done at this time."

All Materials:

Site ID:	59397
Operable Unit ID:	824416
Operable Unit:	01
Material ID:	551247
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AK240 **LEXINGTON CENTER FOR RECOVERY INC** **NJ MANIFEST** **S117987423**
NNE **3 COTTAGE PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1144 ft. **Site 1 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYR000193854
Mail Address:	COTTAGE PL
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LISA OBRIEN
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008900746JJK
EPA ID:	NYR000193854
Date Shipped:	5/25/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NY0001031814
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	30.00 Pounds

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	300.00 Pounds

AK241 **LEXINGTON CENTER FOR RECOVERY INC** **RCRA NonGen / NLR** **1014958140**
NNE **3 COTTAGE PL** **NY MANIFEST** **NYR000193854**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.217 mi.
1144 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	2012-09-27 00:00:00.0
Facility name:	LEXINGTON CENTER FOR RECOVERY INC
Facility address:	3 COTTAGE PL NEW ROCHELLE, NY 10801
EPA ID:	NYR000193854
Mailing address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact:	LISA OBRIEN
Contact address:	COTTAGE PL NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	914-235-6633
Telephone ext.:	1503

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Contact email: LOBRIEN@LEXINGTONCTR.ORG
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BARRY J JACOBSON
Owner/operator address: E 40TH ST 8TH FL
NEW YORK, NY 10016
Owner/operator country: US
Owner/operator telephone: 212-889-7460
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1983-02-02 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: LEXINGTON CENTER FOR RECOVERY INC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2008-07-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2012-05-18 00:00:00.0
Site name: LEXINGTON CENTER FOR RECOVERY INC
Classification: Large Quantity Generator

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Hazardous Waste Summary:

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 2014-02-19 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
Name: LEXINGTON CENTER FOR RECOVERY INC
Address: 3 COTTAGE PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYR000193854
Facility Status: Not reported
Location Address 1: 3 COTTAGE PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000193854
Mailing Name: LEXINGTON CENTER FOR RECOVERY INC
Mailing Contact: LEXINGTON CENTER FOR RECOVERY INC
Mailing Address 1: 3 COTTAGE PL
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142356633

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NY0001031814
Trans2 State ID: NJ0000027193
Generator Ship Date: 05/25/2012
Trans1 Recv Date: 05/25/2012
Trans2 Recv Date: 06/01/2012
TSD Site Recv Date: 06/06/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193854

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008900746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D009
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

242 **CON EDISON** **RCRA NonGen / NLR** **1012184999**
SE **46 CLINTON PL** **NY MANIFEST** **NYP004157665**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1152 ft.

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date form received by agency:	2016-06-01 00:00:00.0
Facility name:	CON EDISON
Facility address:	46 CLINTON PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004157665
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON (Continued) **1012184999**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2008-04-01 00:00:00.0
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 46 CLINTON PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004157665
Facility Status: Not reported
Location Address 1: 46 CLINTON PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10805
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004157665
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRAMKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported

CON EDISON (Continued) **1012184999**

Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2008
Trans1 Recv Date:	04/01/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004157665
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	002013408FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	180
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	6
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH243 **35 CLINTON PLACE LLC** **NY AST** **A100359845**
SE **35 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1153 ft. **Site 2 of 11 in cluster AH**

Relative: **Higher**
Actual: **90 ft.**

WESTCHESTER CO. AST:

Name:	35 CLINTON PLACE LLC
Address:	35 CLINTON PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-078646
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Norman Avelenda
Owner Name:	35 Clinton Place LLC
Owner Street:	35 Clinton Place, #1B
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1939
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

AI244 **MAYCO, LLC** **NY AST** **A100252337**
NNW **18-20 MAY ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1153 ft. **Site 7 of 15 in cluster AI**

Relative: **Lower**
Actual: **79 ft.**

WESTCHESTER CO. AST:

Name:	MAYCO, LLC
Address:	18-20 MAY ST
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-175447
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Alex Hay
Owner Name:	Mayco, LLC
Owner Street:	P.O. Box 1755
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10156

MAYCO, LLC (Continued) **A100252337**

Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1980
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

AF245 **MONROE COLLEGE** **NY AST** **A100252339**
East **420 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.223 mi.
1176 ft. **Site 2 of 3 in cluster AF**

Relative: **Lower**

Actual: **77 ft.**

WESTCHESTER CO. AST:

Name:	MONROE COLLEGE
Address:	420 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800251
Site Status:	Active
GDS Number:	Not reported
Operator Name:	James Moore
Owner Name:	Monroe College
Owner Street:	434 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	001
Status:	1. In-Service
Date Installation:	07/01/2004
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Date Perm Closure:	04/13/2004
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	2. Manual Interstitial Monitoring

MONROE COLLEGE (Continued) **A100252339**

Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

Tank Number:	001old
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	04/13/2004
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	99. Other
Tank External Protection:	99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	99. Other
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	99. Other
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	1
Status:	0. Administratively closed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	11/06/2003
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AL246 **CON EDISON MANHOLE 1174** **RCRA NonGen / NLR** **1014918343**
NE **HUGEONOT ST & HARRISON ST** **NJ MANIFEST** **NYP004219570**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.225 mi.
1189 ft. **Site 1 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

RCRA NonGen / NLR:

Date form received by agency:	2010-12-04 00:00:00.0
Facility name:	CON EDISON MANHOLE 1174
Facility address:	HUGEONOT ST & HARRISON ST NEW ROCHELLE, NY 10802
EPA ID:	NYP004219570
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2010-11-04 00:00:00.0
Site name:	CON EDISON MANHOLE 1174
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004219570
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874917JJK
EPA ID:	NYP004219570
Date Shipped:	11/04/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/04/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

AL247 **CONSOLIDATED EDISON - MH 1174** **NY MANIFEST** **S110709396**
NE **HUGUENOT ST & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.225 mi.
1189 ft. **Site 2 of 6 in cluster AL**

Relative:
Lower

Actual:
72 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 1174
Address:	HUGUENOT ST & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004219572
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & HARRISON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219572
Mailing Name:	CONSOLIDATED EDISON - MH 1174
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2010
Trans1 Recv Date:	11/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874917JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N

CONSOLIDATED EDISON - MH 1174 (Continued) **S110709396**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD248 **CON EDISON** **NY MANIFEST** **S117535572**
SSW **MAIN ST & MAPLE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.225 mi.
1190 ft. **Site 3 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MAIN ST & MAPLE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004674354
Facility Status:	Not reported
Location Address 1:	MAIN ST & MAPLE AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004674354
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117535572**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2014
Trans1 Recv Date:	10/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004674354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	007747843FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	559
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	D005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD249 **CON EDISON** **RCRA NonGen / NLR** **1014399091**
SSW **MAPLE AVE & MAIN ST** **NJ MANIFEST** **NYP004214680**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.225 mi.
1190 ft. **Site 4 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	2010-09-01 00:00:00.0
Facility name:	CON EDISON
Facility address:	MAPLE AVE & MAIN ST NEW ROCHELLE, NY 10804
EPA ID:	NYP004214680
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004214680
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **1014399091**

Date Change: Not reported

Manifest:
Manifest Number: 004086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/01/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 09/02/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 120 P

Manifest Number: 001086092GBF
EPA ID: NYP004214680
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

CON EDISON (Continued) **1014399091**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	120 P

AD250 **CON EDISON MANHOLE: 734** **RCRA NonGen / NLR** **1016969502**
SSW **MAIN ST & MAPLE ST** **NY MANIFEST** **NYP004431706**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.225 mi.
1190 ft. **Site 5 of 5 in cluster AD**

Relative:
Higher

Actual:
88 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-03-01 00:00:00.0
Facility name:	CON EDISON MANHOLE: 734
Facility address:	MAIN ST & MAPLE ST NEW ROCHELLE, NY 10805
EPA ID:	NYP004431706
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2014-02-01 00:00:00.0
Site name: CON EDISON MANHOLE: 734
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON ED
Address: MAIN ST & MAPLE ST
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004431706
Facility Status: Not reported
Location Address 1: 591 MAIN ST
Code: BP
Location Address 2: MH 734
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004431706
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/01/2014
Trans1 Recv Date:	02/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004431706
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011696225JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC251 **PREFERRED CLEANERS** **RCRA NonGen / NLR** **1000353766**
West **95 UNION AVE** **FINDS** **NYD050275254**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.225 mi. **NY MANIFEST**
1190 ft. **Site 2 of 7 in cluster AC**

Relative:
Higher

Actual:
96 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	PREFERRED CLEANERS
Facility address:	95 UNION AVE NEW ROCHELLE, NY 10801-6238
EPA ID:	NYD050275254
Mailing address:	UNION AVE NEW ROCHELLE, NY 10801
Contact:	Not reported
Contact address:	UNION AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	914-472-6038
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	RICHARD MEYERING
Owner/operator address:	141 WILMOT RD SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	914-472-6038
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

PREFERRED CLEANERS (Continued) **1000353766**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: PREFERRED CLEANERS
Classification: Not a generator, verified

Date form received by agency: 1995-06-19 00:00:00.0
Site name: PREFERRED CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

FINDS:
Registry ID: 110004357918

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

PREFERRED CLEANERS (Continued) **1000353766**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000353766
Registry ID:	110004357918
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004357918
Name:	PREFERRED CLEANERS
Address:	95 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	NEBRASKA CLEANERS
Address:	95 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY 10801-6238
Country:	USA
EPA ID:	NYD050275254
Facility Status:	Not reported
Location Address 1:	95 UNION AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD050275254
Mailing Name:	NEBRASKA CLEANERS
Mailing Contact:	NEBRASKA CLEANERS
Mailing Address 1:	95 UNION AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146364937

NY MANIFEST:

Document ID:	CTF0452797
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	NYLH7543
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/1995
Trans1 Recv Date:	11/20/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/27/1995

PREFERRED CLEANERS (Continued) **1000353766**

Part A Recv Date:	/ /
Part B Recv Date:	12/13/1995
Generator EPA ID:	NYD050275254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD001156009
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

AE252 **ALL AMERICAN SPORTS CORP** **RCRA NonGen / NLR** **1004760316**
SW **44 COLUMBUS AVE** **FINDS** **NYR000040113**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.228 mi. **NY MANIFEST**
1204 ft. **Site 2 of 2 in cluster AE**

Relative: **Lower**

Actual: **66 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	ALL AMERICAN SPORTS CORP
Facility address:	44 COLUMBUS AVE NEW ROCHELLE, NY 10802
EPA ID:	NYR000040113
Mailing address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact:	LAMELLE WILLIAMS
Contact address:	COLUMBUS AVE NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	914-636-7070
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Owner/Operator Summary:

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE
	NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	914-636-7070
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ALL AMERICAN SPORTS CORP
Owner/operator address:	44 COLUMBUS AVE
	NEW ROCHELLE, NY 10802
Owner/operator country:	US
Owner/operator telephone:	914-636-7070
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2006-01-01 00:00:00.0
Site name:	ALL AMERICAN SPORTS CORP
Classification:	Not a generator, verified

Date form received by agency:	1997-05-30 00:00:00.0
Site name:	ALL AMERICAN SPORTS CORP
Classification:	Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:
Registry ID: 110004534709

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004760316
Registry ID:	110004534709
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004534709
Name:	ALL AMERICAN SPORTS CORP
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802

NY MANIFEST:

Name:	RIDDELL ALL AMERICAN
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD002182897
Facility Status:	Not reported
Location Address 1:	44 COLUMBUS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD002182897
Mailing Name:	RIDDELL ALL AMERICAN
Mailing Contact:	PERSING MEJIA
Mailing Address 1:	44 COLUMBUS AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146367070

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Name:	ALL AMERICAN SPORTS CORP
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYR000040113
Facility Status:	Not reported
Location Address 1:	44 COLUMBUS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000040113
Mailing Name:	ALL AMERICAN SPORTS CORP
Mailing Contact:	LAMELLE WILLIAMS
Mailing Address 1:	44 COLUMBUS AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146367070

NY MANIFEST:

Document ID:	NJA2706453
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/1997
Trans1 Recv Date:	10/13/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/20/1997
Part A Recv Date:	10/29/1997
Part B Recv Date:	11/12/1997
Generator EPA ID:	NYR000040113
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00426
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH253 **CO-OP** **NY LTANKS** **S101658613**
SE **30 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.228 mi.
1206 ft. **Site 3 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	CO-OP
Address:	30 CLINTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9504589 / 1997-04-15
Facility ID:	9504589
Site ID:	189169
Spill Date:	1995-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-20
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	MERILITH MNGT.
Spiller Address:	1101 MIDLAND AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

CO-OP (Continued) **S101658613**

DER Facility ID: 157941
DEC Memo: ""
Remarks: "OIL SEEPING INTO BASEMENT POSSIBLE TANK FAILURE SOME OIL GOT INTO SUMP PIT AND DISCHARGED OUT SUMP PUMP TAKEN OFF LINE"

All TTF:
Facility ID: 9504589
Spill Number: 9504589
Spill Tank Test: 1544004
Site ID: 189169
Tank Number: Not reported
Tank Size: 0
Material: 0003
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 189169
Operable Unit ID: 1019355
Operable Unit: 01
Material ID: 366101
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

AH254 **30 CLINTON PLACE OWNERS INC.** **NY UST U003855209**
SE **30 CLINTON PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.228 mi.
1206 ft. **Site 4 of 11 in cluster AH**

Relative: Higher
Actual: 89 ft.

WESTCHESTER CO. UST:
Name: 30 CLINTON PLACE OWNERS INC.
Address: 30 CLINTON PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-078727 / Active
Operator Name: David Kuilon
Owner Name: 30 Clinton Place Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Tank Number:	1old
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	07/01/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

WESTCHESTER CO. AST:

Name:	30 CLINTON PLACE OWNERS INC.
Address:	30 CLINTON PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-078727
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Kuilon
Owner Name:	30 Clinton Place Owners Inc.
Owner Street:	30 Clinton Place
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801

Tank Number:	001
Status:	1. In-Service
Date Installation:	10/01/1996
Capacity:	3500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Tank Number:	1
Status:	4. Closed - in place
Date Installation:	01/01/1996
Capacity:	4200
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	07/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AH255 **CON EDISON** **NY MANIFEST** **S117538379**
SE **150 NORTH AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1209 ft. **Site 5 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	150 NORTH AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004710497
Facility Status:	Not reported
Location Address 1:	150 NORTH AV
Code:	BP
Location Address 2:	SB2044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004710497
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117538379**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004710497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774700JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM256 **CON EDISON** **NY MANIFEST** **S118088270**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1220 ft. **Site 1 of 19 in cluster AM**

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	45 HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004758215
Facility Status:	Not reported
Location Address 1:	45 HARRISON ST
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758215
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758215
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091127JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118088270**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM257 **CON EDISON** **NJ MANIFEST** **S120669623**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1220 ft. **Site 2 of 19 in cluster AM**

Relative: **Lower**
Actual: **74 ft.**

NJ MANIFEST:

EPA Id:	NYP004758215
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091127JJK
EPA ID:	NYP004758215
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120669623**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM258 **CON EDISON** **RCRA NonGen / NLR** **1018280911**
ENE **45 HARRISON ST** **FINDS** **NYP004758215**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.231 mi.
1220 ft. **Site 3 of 19 in cluster AM**

Relative: **Lower**

Actual: **74 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-03-26 00:00:00.0
Facility name:	CON EDISON
Facility address:	45 HARRISON ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004758215
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON (Continued) **1018280911**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-03-26 00:00:00.0
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067684303

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280911
Registry ID:	110067684303
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067684303
Name:	CON EDISON
Address:	45 HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801

AM259 **CITY OF NEW ROCHELLE** **NY LTANKS** **S107658678**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.231 mi.
1220 ft. **Site 4 of 19 in cluster AM**

Relative:
Lower

Actual:
74 ft.

LTANKS:

Name:	CITY OF NEW ROCHELLE
Address:	45 HARRISON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513733 / 2006-06-21
Facility ID:	0513733
Site ID:	360263
Spill Date:	2006-02-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-02-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-28
Spill Record Last Update:	2006-06-21
Spiller Name:	DEE LESTER
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	45 HARRISON STREET
Spiller County:	001
Spiller Contact:	DEE LESTER
Spiller Phone:	(914) 654-2072
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310380
DEC Memo:	"Tank passed retest after piping was replaced. NFA"
Remarks:	"TANK SIZE IS 5000 GALLON, TEST METHOD WAS EZ3 LOCATOR PLUS,"

All Materials:

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107948
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	360263
Operable Unit ID:	1117439

CITY OF NEW ROCHELLE (Continued) **S107658678**

Operable Unit:	01
Material ID:	2107952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH260 **CON EDISON MANHOLE: 2042** **RCRA NonGen / NLR** **1016970603**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004443198**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.231 mi.
1221 ft. **Site 6 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-03-16 00:00:00.0
Facility name:	CON EDISON MANHOLE: 2042
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10804
EPA ID:	NYP004443198
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2014-02-16 00:00:00.0
Site name:	CON EDISON MANHOLE: 2042
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & CLINTON PL
City,State,Zip: NEW ROCHELLE, NY 10804
Country: USA
EPA ID: NYP004443198
Facility Status: Not reported
Location Address 1: NORTH AVE & CLINTON PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004443198
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/16/2014
Trans1 Recv Date: 02/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004443198
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772860JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH261 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016971500**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004452439**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.231 mi.
1221 ft. **Site 7 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	2014-03-26 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 2040
Facility address:	NORTH AVE & CLINTON PL NEW ROCHELLE, NY 10805
EPA ID:	NYP004452439
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2014-02-26 00:00:00.0
Site name: CON EDISON SERVICE BOX: 2040
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & CLINTON PL
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004452439
Facility Status: Not reported
Location Address 1: NORTH AVE & CLINTON PLS
Code: BP
Location Address 2: SB2040
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004452439
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/26/2014
Trans1 Recv Date: 02/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004452439

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772758JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN262 **CON EDISON** **NY MANIFEST** **S117535673**
NNW **OPP 20 LOCKWOOD AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1224 ft. **Site 1 of 3 in cluster AN**

Relative: **Lower**

Actual: **80 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 20 LOCKWOOD AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004679965
Facility Status:	Not reported
Location Address 1:	OPP 20 LOCKWOOD AV
Code:	BP
Location Address 2:	MH11199
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

CON EDISON (Continued) **S117535673**

NY MANIFEST:

EPAID:	NYP004679965
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/18/2014
Trans1 Recv Date:	10/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004679965
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774833JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117535673**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AI263 **CON EDISON TRANSFORMER MANHOLE: 1552** **RCRA NonGen / NLR** **1016964344**
North **LOCKWOOD AVE & NORTH ST** **NY MANIFEST** **NYP004372751**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.232 mi.
1226 ft. **Site 8 of 15 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:
Date form received by agency: 2013-11-10 00:00:00.0
Facility name: CON EDISON TRANSFORMER MANHOLE: 1552
Facility address: LOCKWOOD AVE & NORTH ST
NEW ROCHELLE, NY 10802
EPA ID: NYP004372751
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2013-10-10 00:00:00.0
Site name: CON EDISON TRANSFORMER MANHOLE: 1552
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Address:	LOCKWOOD AVE & NORTH ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004372751
Facility Status:	Not reported
Location Address 1:	LOCKWOOD AVE & NORTH ST
Code:	BP
Location Address 2:	TM 1552
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004372751
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2013
Trans1 Recv Date:	10/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004372751
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693714JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI264 **CON EDISON MANHOLE 1545** **RCRA NonGen / NLR** **1014918224**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004218356**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.232 mi.
1226 ft. **Site 9 of 15 in cluster AI**

Relative:
Lower

Actual:
78 ft.

RCRA NonGen / NLR:

Date form received by agency:	2010-11-18 00:00:00.0
Facility name:	CON EDISON MANHOLE 1545
Facility address:	NORTH AVE & LOCKWOOD AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004218356
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2010-10-19 00:00:00.0
Site name: CON EDISON MANHOLE 1545
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004218356
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CHRISTOPHER BLAICH
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874846JJK
EPA ID: NYP004218356
Date Shipped: 10/19/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/19/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/20/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	NORTH AVE & LOCKWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004218356
Facility Status:	Not reported
Location Address 1:	NORTH AV OPP LOCKWOOD
Code:	BP
Location Address 2:	MH 1545
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004218356
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2010
Trans1 Recv Date:	10/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004218356
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874846JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI265 **CON EDISON** **NY MANIFEST** **S118259837**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1226 ft. **Site 10 of 15 in cluster AI**

Relative: **Lower**
Actual: **78 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	LOCKWOOD AVE & NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004838332
Facility Status:	Not reported
Location Address 1:	LOCKWOOD AVE & NORTH AVE

CON EDISON (Continued) **S118259837**

Code:	BP
Location Address 2:	TM 1552
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004838332
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004838332
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472178JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S118259837**

Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI266 **CON EDISON** **NJ MANIFEST** **S120676674**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1226 ft. **Site 11 of 15 in cluster AI**

Relative: **Lower**
Actual: **78 ft.**

NJ MANIFEST:

EPA Id:	NYP004838332
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472178JJK
EPA ID:	NYP004838332
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

CON EDISON (Continued) **S120676674**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AI267 **CON EDISON MANHOLE 1562** **RCRA NonGen / NLR** **1014918646**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004222626**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.232 mi.
1226 ft. **Site 12 of 15 in cluster AI**

Relative: **Lower**

Actual: **78 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2011-01-30 00:00:00.0
Facility name:	CON EDISON MANHOLE 1562
Facility address:	NORTH AVE & LOCKWOOD AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004222626
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2010-12-31 00:00:00.0
Site name: CON EDISON MANHOLE 1562
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004222626
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DONALD SENNO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655578JJK
EPA ID: NYP004222626
Date Shipped: 12/31/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 12/31/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Date TSDF Received Waste:	01/04/2011
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	150 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	NORTH AVE & LOCKWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004222626
Facility Status:	Not reported
Location Address 1:	NORTH AVE & LOCKHEED
Code:	BP
Location Address 2:	MH 1962
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004222626
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/2010
Trans1 Recv Date:	12/31/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/04/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004222626
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655578JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI268 **CON EDISON** **RCRA NonGen / NLR** **1019907792**
North **LOCKWOOD AVE & NORTH AVE** **NYP004838332**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1226 ft. **Site 13 of 15 in cluster AI**

Relative: **Lower**
Actual: **78 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-09-14 00:00:00.0
Facility name:	CON EDISON
Facility address:	LOCKWOOD AVE & NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYP004838332
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-09-14 00:00:00.0
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

AC269 **LJNJ ASSOCIATES** **NY UST** **U003884659**
West **100-102 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1227 ft. **Site 3 of 7 in cluster AC**

Relative: **Higher**
Actual: **95 ft.**

WESTCHESTER CO. UST:

Name:	LJNJ ASSOCIATES
Address:	100-102 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-601056 / Unregulated: <1101 gal. PBS
Operator Name:	Bob Rossi

LJNJ ASSOCIATES (Continued) **U003884659**

Owner Name:	Ljnj Associates
Owner Street:	133 Meadow Lane
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	1080
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1959
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None
Tank Number:	2
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None
Tank Number:	3
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported

LJNJ ASSOCIATES (Continued) **U003884659**

Tank Leak Detection:	0. None
Date Installation:	03/01/1988
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/01/1996
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	5
Status:	0. Administratively closed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported

LJNJ ASSOCIATES (Continued) **U003884659**

Spill Prevention: 0. None
Dispenser: 0. None

AC270 **100-102 UNION AVENUE** **NY LTANKS** **S104514442**
West **100-102 UNION AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1227 ft. **Site 4 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	100-102 UNION AVENUE
Address:	100-102 UNION AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9608199 / 1996-11-08
Facility ID:	9608199
Site ID:	166425
Spill Date:	1996-10-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-01
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-01
Spill Record Last Update:	1996-12-10
Spiller Name:	LJ NJ ASSOC
Spiller Company:	100-102 UNION AVENUE
Spiller Address:	100-102 UNION AVENUE
Spiller County:	001
Spiller Contact:	LJ NJ ASSOC
Spiller Phone:	(914) 636-7297
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140217
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/96 LETTER SENT BASED ON CLOSURE REPORT NFA"
Remarks:	"caller pulled tank and found contaminated soil."

All Materials:

Site ID:	166425
Operable Unit ID:	1036474
Operable Unit:	01
Material ID:	343940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

100-102 UNION AVENUE (Continued) **S104514442**

Units: G
Recovered: Not reported
Oxygenate: Not reported

AM271 **CON ED** **NY MANIFEST** **S118088428**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1228 ft. **Site 5 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:
Name: CON ED
Address: HARRISON ST & CEDER ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004759924
Facility Status: Not reported
Location Address 1: HARRISON ST & CEDAR ST
Code: BP
Location Address 2: MH 8003
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004759924
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/29/2015
Trans1 Recv Date: 03/29/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004759924
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported

CON ED (Continued) **S118088428**

Manifest Tracking Number:	014091107JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM272 **CON EDISON** **NJ MANIFEST** **S120669767**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1228 ft. **Site 6 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYP004759924
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091107JJK

CON EDISON (Continued) **S120669767**

EPA ID:	NYP004759924
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM273 **CON EDISON** **RCRA NonGen / NLR** **1018281062**
ENE **HARRISON ST & CEDER ST** **FINDS** **NYP004759924**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.233 mi.
1228 ft. **Site 7 of 19 in cluster AM**

Relative: **Lower**

Actual: **75 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-03-29 00:00:00.0
Facility name:	CON EDISON
Facility address:	HARRISON ST & CEDER ST NEW ROCHELLE, NY 10801
EPA ID:	NYP004759924
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON (Continued) **1018281062**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-03-29 00:00:00.0
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:
Registry ID: 110067686793

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281062
Registry ID: 110067686793
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067686793
Name: CON EDISON
Address: HARRISON ST & CEDER ST
City,State,Zip: NEW ROCHELLE, NY 10801

AM274 **CON EDISON SERVICE BOX: 8001** **RCRA NonGen / NLR** **1016961840**
ENE **HARRISON AVE & CEDAR AVE** **NY MANIFEST** **NYP004347621**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.233 mi.
1228 ft. **Site 8 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	2013-09-19 00:00:00.0
Facility name:	CON EDISON SERVICE BOX: 8001
Facility address:	HARRISON AVE & CEDAR AVE NEW ROCHELLE, NY 10805
EPA ID:	NYP004347621
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2013-08-19 00:00:00.0
Site name:	CON EDISON SERVICE BOX: 8001
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	HARRISON AVE & CEDAR AVE
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004347621
Facility Status:	Not reported
Location Address 1:	HARRISO AVE & CEDAR
Code:	BP
Location Address 2:	SB 8001
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 8001 (Continued) **1016961840**

Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004347621
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2013
Trans1 Recv Date:	08/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004347621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694672JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 8001 (Continued) **1016961840**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI275 **368 NORTH AVE MGMT CO. INC.** **NY UST** **U003994274**
North **368 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.233 mi.
1230 ft. **Site 14 of 15 in cluster AI**

Relative: WESTCHESTER CO. UST:
Lower

Actual: **79 ft.**

Name:	368 NORTH AVE MGMT CO. INC.
Address:	368 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600272 / Unregulated: <1101 gal. PBS
Operator Name:	Barry Shapiro
Owner Name:	368 North Ave Mgmt Co. Inc.
Owner Street:	27 Country Ridge Road
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/24/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AC276 **KAGEL HOME** **NY LTANKS** **S107658662**
West **99 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1230 ft. **Site 5 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	KAGEL HOME
Address:	99 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513684 / 2006-03-09
Facility ID:	0513684
Site ID:	360201
Spill Date:	2006-02-27
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	2006-03-06
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-27
Spill Record Last Update:	2006-03-09
Spiller Name:	ANDREW KAGEL
Spiller Company:	KAGEL HOME
Spiller Address:	99 UNION AVE
Spiller County:	001
Spiller Contact:	ANDREW KAGEL
Spiller Phone:	(914) 403-2881
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310321
DEC Memo:	"Homeowner waiting on proposal from N.E. to finish job. 3/6/06 Northeast Environmental reported that the tank was removed along with eight drums of petroleum impacted soil. NFA. TG"
Remarks:	"55o gallon tank had holes and found contaminated soil;"

All Materials:

Site ID:	360201
Operable Unit ID:	1117385
Operable Unit:	01
Material ID:	2107892
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG277 **125** **NY LTANKS** **S104621592**
South **CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.233 mi.
1232 ft. **Site 4 of 4 in cluster AG**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Name:	125
Address:	CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0001835 / 2000-05-15
Facility ID:	0001835
Site ID:	205498
Spill Date:	2000-05-12
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-12
CID:	196
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-12
Spill Record Last Update:	2000-06-21
Spiller Name:	UNKNOWN
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	OPERATOR 631
Spiller Phone:	(914) 595-5901
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170636
DEC Memo:	""
Remarks:	"TANK OVER FILL AT THIS LOCATION. 10 GALLONS SPILLED AND THE SPILL WAS CLEANED UP BY THE FIRE DEPT. THE SPILL IS AT THE CHURCH BLESSED SACRMENT CHURCH. BABR MCDONALD FROM COUNTY HEATH DEPT. 637-4890 WAS CALLED TO THE SCENE ALSO."

All Materials:

Site ID:	205498
Operable Unit ID:	823753
Operable Unit:	01
Material ID:	290047
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AL278 **HEALTH DEPT OFFICE** **NY LTANKS** **S105236833**
NE **145 HUGUENOT ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.236 mi.
1245 ft. **Site 3 of 6 in cluster AL**

Relative: **Lower**

Actual: **70 ft.**

LTANKS:

Name:	GALESI ENTERPRICES
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8901038 / 1989-06-01
Facility ID:	8901038
Site ID:	259815
Spill Date:	1989-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1989-06-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212473
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. "
Remarks:	"8K, -.116"

All TTF:

Facility ID:	8901038
Spill Number:	8901038
Spill Tank Test:	1535410
Site ID:	259815
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

HEALTH DEPT OFFICE (Continued) **S105236833**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	259815
Operable Unit ID:	927170
Operable Unit:	01
Material ID:	452349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	HEALTH DEPT OFFICE
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0109500 / 2001-12-28
Facility ID:	0109500
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259813
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2001-12-28
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-12-28
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-28
Spill Record Last Update:	2002-01-03
Spiller Name:	CHRIS LALAK
Spiller Company:	HEALTH DEPT OFFICE
Spiller Address:	145 HUGUENOT ST
Spiller Company:	001
Contact Name:	CHRIS LALAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 12/28/2001 C. LALAK @ WCDOH HANDLED. SPILL CLEANED UP. NO

HEALTH DEPT OFFICE (Continued) **S105236833**

FURTHER ACTION."
Remarks: "all cleaned up less than 1 oz"

All Materials:
Site ID: 259813
Operable Unit ID: 846776
Operable Unit: 01
Material ID: 527159
Material Code: 0031A
Material Name: mercury
Case No.: 07439976
Material FA: Hazardous Material
Quantity: 1.00
Units: G
Recovered: 1.00
Oxygenate: Not reported

Name: SPILL NUMBER 0308837
Address: 145 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0308837 / 2003-11-19
Facility ID: 0308837
Facility Type: ER
DER Facility ID: 212473
Site ID: 259814
DEC Region: 3
Spill Cause: Unknown
Spill Class: C4
SWIS: 6010
Spill Date: 2003-11-19
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2003-11-19
CID: 322
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-11-19
Spill Record Last Update: 2003-12-02
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: CHRIS LALAK
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 11/19/03: Spill is unrecoverable per C. Lalak, WCDOH. Recommends NFA at this time."
Remarks: "approx 10 gal unk oil on roadway - highway dept placing sand "

All Materials:
Site ID: 259814

HEALTH DEPT OFFICE (Continued) **S105236833**

Operable Unit ID:	875003
Operable Unit:	01
Material ID:	571327
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERICAL PROPERTY
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0909155 / 2009-11-16
Facility ID:	0909155
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421828
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-16
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

All Materials:

Site ID:	421828
Operable Unit ID:	1177706
Operable Unit:	01
Material ID:	2170525
Material Code:	0001A
Material Name:	#2 fuel oil

HEALTH DEPT OFFICE (Continued) **S105236833**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Name:	COMMERICAL PROPERTY
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0909156 / 2009-11-16
Facility ID:	0909156
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421829
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-16
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

All Materials:

Site ID:	421829
Operable Unit ID:	1177707
Operable Unit:	01
Material ID:	2170526
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00

HEALTH DEPT OFFICE (Continued) **S105236833**

Oxygenate: Not reported

AL279 **LONGINES WITTNAUER WATCH CO** **RCRA NonGen / NLR** **1000235411**
NE **145 HUGUENOT ST** **FINDS** **NYD001317221**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.236 mi. **NY MANIFEST**
1245 ft. **Site 4 of 6 in cluster AL**

Relative:
Lower

Actual:
70 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	LONGINES WITTNAUER WATCH CO
Facility address:	145 HUGUENOT ST NEW ROCHELLE, NY 10802
EPA ID:	NYD001317221
Mailing address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact:	Not reported
Contact address:	HUGUENOT ST NEW ROCHELLE, NY 10802
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: LONGINES WITTNAUER WATCH CO
Classification: Not a generator, verified

Date form received by agency: 1985-03-11 00:00:00.0
Site name: LONGINES WITTNAUER WATCH CO
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P013
. Waste name: BARIUM CYANIDE

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P097
. Waste name: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 1994-09-17 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Evaluation lead agency: State

Evaluation date: 1985-08-19 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

FINDS:
Registry ID: 110004333720

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000235411
Registry ID: 110004333720
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004333720
Name: LONGINES WITTNAUER WATCH CO
Address: 145 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY 10802

NY MANIFEST:
Name: LONGINES WITTHAVER WATCH COMPANY
Address: 145 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYD001317221
Facility Status: Not reported
Location Address 1: 145 HUGUENOT STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001317221
Mailing Name: LONGINES WITTHAVER WATCH COMPANY
Mailing Contact: LONGINES WITTHAVER WATCH COMPANY
Mailing Address 1: 145 HUGUENOT STREET
Mailing Address 2: Not reported
Mailing City: NEW RTOCHELLE
Mailing State: NY
Mailing Zip: 10802
Mailing Zip 4: Not reported
Mailing Country: USA

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Mailing Phone: 9145761000

NY MANIFEST:

Document ID:	NJA0309928
Manifest Status:	C
seq:	Not reported
Year:	1987
Trans1 State ID:	NJDEP#S10
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/1987
Trans1 Recv Date:	08/19/1987
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/20/1987
Part A Recv Date:	08/28/1987
Part B Recv Date:	08/27/1987
Generator EPA ID:	NYD001317221
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD089216790
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00224
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	021
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00450
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	P106 - SODIUM CYANIDE
Waste Code:	Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00064
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00036
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

AL280 **GHP 145 HUGUENOT DELAWARE, LLC** **NY UST** **U004315552**
NE **145 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 5 of 6 in cluster AL**

Relative: **Lower**
Actual: **70 ft.**

WESTCHESTER CO. UST:

Name:	GHP 145 HUGUENOT DELAWARE, LLC
Address:	145 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-497436 / Active
Operator Name:	David Clemente
Owner Name:	GHP 145 Huguenot Delaware, LLC
Owner Street:	4 West Red Oak Lane, Suite 200
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	3-497436
Status:	1. In-Service
Capacity:	6000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	07/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None

GHP 145 HUGUENOT DELAWARE, LLC (Continued) **U004315552**

Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: 4. Double-Walled (underground only)
Spill Prevention: 1. Catch Basin
Dispenser: 0. None

AM281 **CON EDISON** **RCRA NonGen / NLR** **1019902084**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769477**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 9 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:
Date form received by agency: 2015-04-16 00:00:00.0
Facility name: CON EDISON
Facility address: FOUNTAIN PL & HARRISON ST
SB8007
NEW ROCHELLE, NY 10801
EPA ID: NYP004769477
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2015-04-16 00:00:00.0
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

AM282 **CON EDISON** **RCRA NonGen / NLR** **1018280916**
ENE **FOUNTAIN PL & HARRISON ST** **FINDS** **NYP004758272**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.236 mi.
1247 ft. **Site 10 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

RCRA NonGen / NLR:

Date form received by agency:	2015-03-26 00:00:00.0
Facility name:	CON EDISON
Facility address:	HARRISON ST & FOUNTAIN PL NEW ROCHELLE, NY 10801
EPA ID:	NYP004758272
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-03-26 00:00:00.0
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067684358

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON (Continued) **1018280916**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280916
Registry ID:	110067684358
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067684358
Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801

AM283 **CON ED** **NY MANIFEST** **S118088390**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 11 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Name:	CON ED
Address:	HARRISON ST & FOUNTAIN PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004759510
Facility Status:	Not reported
Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759510
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported

CON ED (Continued) **S118088390**

TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091122JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM284 **CON EDISON** **NJ MANIFEST** **S120669628**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 12 of 19 in cluster AM**

Relative: NJ MANIFEST:
Lower

Actual:
75 ft.

EPA Id:	NYP004758272
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON (Continued) **S120669628**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091128JJK
EPA ID:	NYP004758272
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM285 **CON EDISON** **RCRA NonGen / NLR** **1019902074**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769345**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 13 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date form received by agency:	2015-04-16 00:00:00.0
Facility name:	CON EDISON
Facility address:	FOUNTAIN PL & HARRISON ST MH8008 NEW ROCHELLE, NY 10801
EPA ID:	NYP004769345
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	2015-04-16 00:00:00.0
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

AM286 **CON EDISON** **NJ MANIFEST** **S120670602**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 14 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYP004769345
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON (Continued) **S120670602**

Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660843GBF
EPA ID:	NYP004769345
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM287 **CON EDISON** **NY MANIFEST** **S118089345**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 15 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004769477
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP
Location Address 2:	SB 8007
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769477
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660844GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118089345**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM288 **CON EDISON** **NY MANIFEST** **S118088276**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 16 of 19 in cluster AM**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	HARRISON ST & FOUNTAIN PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004758272
Facility Status:	Not reported
Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	SB 8044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758272
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S118088276**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091128JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM289 **CON EDISON** **NJ MANIFEST** **S120670610**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 17 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYP004769477
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660844GBF
EPA ID:	NYP004769477
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120670610**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM290 **CON EDISON** **NY MANIFEST** **S118089335**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1247 ft. **Site 18 of 19 in cluster AM**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004769345
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP
Location Address 2:	MH 8008
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769345
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769345
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118089335**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660843GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF291 **MONROE COLLEGE** **NY LTANKS** **S106124169**
East **5 FRANKLIN AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.237 mi.
1249 ft. **Site 3 of 3 in cluster AF**

Relative: LTANKS:
Lower

Name:	MONROE COLLEGE
Address:	5 FRANKLIN AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0307536 / 2005-03-27
Facility ID:	0307536
Site ID:	165556
Spill Date:	2003-10-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-10-16
CID:	270

Actual:
75 ft.

MONROE COLLEGE (Continued) **S106124169**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-16
Spill Record Last Update:	2005-03-27
Spiller Name:	JIM MOORE
Spiller Company:	MONROE COLLEGE
Spiller Address:	5 FRANKLIN AVE
Spiller County:	001
Spiller Contact:	JIM MOORE
Spiller Phone:	(914) 403-3458
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	278527
DEC Memo:	"03/27/05 CLEAN UP COMPLETED. SPILL FILE CLOSED BY OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod As per email from WCHD: 03-07536 5 Franklin Ave, NEw Rochelle, NY (also known as 420 Main St, New Rochelle) Tank removed from basement, soil disposed of. NFA"
Remarks:	"recomend repair retest"

All TTF:

Facility ID:	0307536
Spill Number:	0307536
Spill Tank Test:	1528740
Site ID:	165556
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	165556
Operable Unit ID:	873930
Operable Unit:	01
Material ID:	501063
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI292 **CASANOVA BROS. REALTY** **NY UST** **U003884076**
North **370 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.237 mi.
1253 ft. **Site 15 of 15 in cluster AI**

Relative: **Lower**
Actual: **79 ft.**

WESTCHESTER CO. UST:

Name:	CASANOVA BROS. REALTY
Address:	370 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-800088 / Unregulated: <1101 gal. PBS
Operator Name:	Israel Estrada
Owner Name:	Casanova Bros. Realty
Owner Street:	370 North Ave
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/14/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AC293 **TANK TEST FAILURE** **NY LTANKS** **S111239332**
WSW **50 WALNUT ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.239 mi.
1264 ft. **Site 6 of 7 in cluster AC**

Relative: **Higher**
Actual: **94 ft.**

LTANKS:

Name:	TANK TEST FAILURE
Address:	50 WALNUT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1107925 / 2013-02-05
Facility ID:	1107925
Site ID:	455637
Spill Date:	2011-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010

TANK TEST FAILURE (Continued) **S111239332**

Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-21
Spill Record Last Update:	2013-02-06
Spiller Name:	Not reported
Spiller Company:	SAL VIGNA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KEN RONK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	410212
DEC Memo:	"9-21-11 Owner is Pietro Vigna and doesn't speak english. Sal is his son. Sal cell: (914)424-2239. Sal has Eastern Env coming out Wed to investigate further. jc 2/6/13: Northeast Environmental disposed of LUST and a total of 21.05 tons of petroleum contaminated soil. Exit sample results showed residual contamination over CP-51 Guidance values. Additional excavation of contaminted soil is not possible with causing possible structural damage to the building foundations. Based upon the information provided, this Department requires no further action at this time. Closed - doesn not meet standarsds. jod"
Remarks:	"tank test failure"

All Materials:

Site ID:	455637
Operable Unit ID:	1205789
Operable Unit:	01
Material ID:	2202749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AO294 **DOMENICO PROCOPIO** **NY UST U003988536**
SSW **618 MAIN STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.242 mi.
1279 ft. **Site 1 of 4 in cluster AO**

Relative: **Lower**
Actual: **87 ft.**

WESTCHESTER CO. UST:

Name:	DOMENICO PROCOPIO
Address:	618 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801

DOMENICO PROCOPIO (Continued) **U003988536**

Id/Status:	3-800233 / Unregulated: <1101 gal. PBS
Operator Name:	Domenico Procopio
Owner Name:	Domenico Procopio
Owner Street:	126 Liberty Avenue
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10805
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/24/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

WESTCHESTER CO. AST:

Name:	DOMENICO PROCOPIO
Address:	618 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800233
Site Status:	Unregulated: <1101 gal. PBS
GDS Number:	Not reported
Operator Name:	Domenico Procopio
Owner Name:	Domenico Procopio
Owner Street:	126 Liberty Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10805
Tank Number:	2
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported

DOMENICO PROCOPIO (Continued) **U003988536**

Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

AO295 **DOMENICO PROCOPIO PROPERTY** **NY LTANKS** **S103558292**
SSW **618 MAIN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.242 mi.
1279 ft. **Site 2 of 4 in cluster AO**

Relative: **Lower**
Actual: **87 ft.**

LTANKS:

Name:	DOMINIC PROCOPIO
Address:	618 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9809866 / 2004-03-30
Facility ID:	9809866
Site ID:	278454
Spill Date:	1998-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-05
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-05
Spill Record Last Update:	2004-03-30
Spiller Name:	DOMINIC PROCOPIO
Spiller Company:	DOMINIC PROCOPIO
Spiller Address:	10 MAPLE AVE
Spiller County:	001
Spiller Contact:	DOMINIC PROCOPIO
Spiller Phone:	(914) 576-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	226099
DEC Memo:	""
Remarks:	"CHECK PIPING AND RETEST"

All TTF:

Facility ID:	9809866
Spill Number:	9809866
Spill Tank Test:	1546499
Site ID:	278454
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	278454
Operable Unit ID:	1067125
Operable Unit:	01
Material ID:	313759
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	DOMENICO PROCOPIO PROPERTY
Address:	618 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0408557 / 2005-03-17

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

Facility ID:	0408557
Facility Type:	ER
DER Facility ID:	226099
Site ID:	333327
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2004-11-03
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2004-11-03
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-03
Spill Record Last Update:	2005-04-05
Spiller Name:	DOMINICKO PROCOPIO
Spiller Company:	Not reported
Spiller Address:	618 MAIN ST
Spiller Company:	001
Contact Name:	DOMINICKO PROCOPIO
DEC Memo:	"PBS #3-800233 11/16/2004 Stephan Goreau of WCDOH spill update -- several inches in basement of sewer/oil mix---BHY 4/4/05: Letter to Vincent Rippa, Domenico Procopio Property from Stefan Goreau, WCDOH dated 17Mar2005. WCDOH requires NFA at this time."
Remarks:	"Imporperly Abondoned tank."

All Materials:

Site ID:	333327
Operable Unit ID:	1095482
Operable Unit:	01
Material ID:	575615
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC296 **ROBERTS HOME** **NY LTANKS** **S108298719**
WSW **58 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.243 mi.
1281 ft. **Site 7 of 7 in cluster AC**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	ROBERTS HOME
Address:	58 WALNUT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0608623 / 2012-08-17
Facility ID:	0608623
Site ID:	372634
Spill Date:	2006-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2012-08-17
Spiller Name:	TOM ROBERTS
Spiller Company:	ROBERTS HOME
Spiller Address:	58 WALNUT STREET
Spiller County:	001
Spiller Contact:	TOM ROBERTS
Spiller Phone:	(914) 755-9816
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	322369
DEC Memo:	"8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M"
Remarks:	""

All TTF:

Facility ID:	0608623
Spill Number:	0608623
Spill Tank Test:	1550391
Site ID:	372634
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

ROBERTS HOME (Continued) **S108298719**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 372634
Operable Unit ID: 1130371
Operable Unit: 01
Material ID: 2120048
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

AP297 @ **NY LTANKS** **S106971852**
West **60 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.244 mi.
1287 ft. **Site 1 of 3 in cluster AP**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Name: @
Address: 60 WALNUT STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0502010 / 2005-07-17
Facility ID: 0502010
Site ID: 346287
Spill Date: 2005-05-19
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-05-19
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-05-19
Spill Record Last Update: 2005-07-17
Spiller Name: MR. GALLERO
Spiller Company: Not reported
Spiller Address: 60 WALNUT STREET
Spiller County: 001
Spiller Contact: MR. GALLERO

@ (Continued) **S106971852**

Spiller Phone:	(914) 469-7160
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	292543
DEC Memo:	"July 17, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 33.65 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK HAD HOLES IN IT:"

All Materials:

Site ID:	346287
Operable Unit ID:	1104017
Operable Unit:	01
Material ID:	584224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO298 **VACANT** **NY UST U004177556**
SSW **399 HUGUENOT STREET** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1294 ft. **Site 3 of 4 in cluster AO**

Relative: **Lower**

Actual: **83 ft.**

WESTCHESTER CO. UST:

Name:	VACANT
Address:	399 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-801616 / Unregulated
Operator Name:	Atco Properties
Owner Name:	399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street:	555 Fifth Avenue, 16th Floor
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10017
GDS Number:	Not reported
Tank Number:	5
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	12/01/1956
Date Perm Closure:	02/01/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground

VACANT (Continued) **U004177556**

Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	4. Closed - in place
Capacity:	1000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	12/01/1956
Date Perm Closure:	02/01/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	7
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	0009. Gasoline
Product Stored Percent:	0
Tank Leak Detection:	0. None
Date Installation:	12/01/1956
Date Perm Closure:	02/01/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	VACANT
Address:	399 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-801616
Site Status:	Unregulated

VACANT (Continued) **U004177556**

GDS Number: Not reported
Operator Name: Atco Properties
Owner Name: 399 Huguenot Corp. c/o Atco Properties Mgmt Inc
Owner Street: 555 Fifth Avenue, 16th Floor
Owner Address2: Not reported
Owner City/State/Zip: New York, NY 10017

Tank Number: 1
Status: 3. Closed - Removed
Date Installation: 01/01/1900
Capacity: 275
Product Stored: 0022. Waste/Used Oil
Product Stored Percent: 0
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: Not reported
Tank Internal Protection: Not reported
Tank External Protection: Not reported
Tank Leak Detection: Not reported
Tank Secondary Containment: Not reported
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: Not reported
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 2
Status: 3. Closed - Removed
Date Installation: 01/01/1900
Capacity: 750
Product Stored: 0015. Motor Oil
Product Stored Percent: 0
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: Not reported
Tank Internal Protection: Not reported
Tank External Protection: Not reported
Tank Leak Detection: Not reported
Tank Secondary Containment: Not reported
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: Not reported
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: Not reported
Spill Prevention: Not reported
Dispenser: Not reported

Tank Number: 3
Status: 3. Closed - Removed
Date Installation: 01/01/1900
Capacity: 275

VACANT (Continued) **U004177556**

Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	4
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Leak Detection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

AH299 **FLAMINGO CLEANERS** **RCRA-LQG** **1000299848**
SE **149 NORTH AVE** **NY BROWNFIELDS** **NYD012946885**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.246 mi.
1297 ft. **Site 8 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA-LQG:

Date form received by agency:	2012-07-10 00:00:00.0
Facility name:	FLAMINGO CLEANERS
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801
EPA ID:	NYD012946885
Mailing address:	NORTH AVE NEW ROCHELLE, NY 10801
Contact:	RICHARD H DORAN
Contact address:	DORSON ENVIRONMENTAL MGMT INC 45 KNOLLWOOD RD SUITE 300 ELMSFORD, NY 10523

FLAMINGO CLEANERS (Continued) **1000299848**

Contact country: US
Contact telephone: 914-592-3117
Contact email: RDORAN@DORSON.COM
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: V & V CAPITAL LLC
Owner/operator address: PHILLIPS HILL RD
NEW CITY, NY 10956
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2011-07-14 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: TAEYOON KIM
Owner/operator address: 149 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-235-1591
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TAEYOON KIM
Owner/operator address: 149 NORTH AVE
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-235-1591
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Owner/Op end date: Not reported

Owner/operator name: LUIGI LLESHAJ
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 2011-07-14 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2007-01-01 00:00:00.0
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2006-01-01 00:00:00.0
Site name: FLAMINGO CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1991-11-21 00:00:00.0
Site name: FLAMINGO CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE,

FLAMINGO CLEANERS (Continued) **1000299848**

1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 2006-07-10 00:00:00.0
Date achieved compliance: 2006-08-18 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 2006-08-03 00:00:00.0
Enf. disposition status: Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 2006-07-10 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 2006-08-18 00:00:00.0
Evaluation lead agency: State

BROWNFIELDS:
Name: FLAMINGO CLEANERS
Address: 149 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Program: BCP
Site Code: 335220
Acres: 0.122
HW Code: C360078
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 12/16/2004
Record Updated Date: 01/28/2020
Update By: KJCARPEN
Site Description: Location: The Flamingo Cleaners site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site is a one-story commercial building with a full basement. The building is divided into four commercial tenant spaces which have been occupied at various times by a bar/lounge, beauty salon, delicatessen, a travel agency and a dry-cleaner. Current Zoning/use(s): The site consists of four retail spaces. The site is zoned for commercial use. The surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a medical center, and a church. Past Uses of the Site: The existing building was constructed in 1941 and used for retail. Flamingo Cleaners began dry cleaning operations in 1958, and ran until 2005 when all dry-cleaning equipment was removed. Site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). Prior completed investigations include a Phase I Investigation in October of 2003 and a Phase II Investigation completed in March of 2004. The Volunteer entered into a Brownfield Cleanup Agreement in April 2005. A Decision Document was issued in March 2012 for a remedy involving source soil removal and in situ chemical oxidation treatment of groundwater. Based on the extent of the site contamination, a referral to State Superfund for an off-site investigation was completed in December 2007. The groundwater plume was found to be isolated to immediately behind the building and little to no off-site impacts were noted in groundwater, soils, nor in soil vapor. Site Geology/hydrogeology: The site is underlain by glacial till which sits atop highly weathered bedrock. Bedrock ranges from 5 - 22 feet below ground surface. The water table is between 5 - 11 feet below ground surface. Groundwater flow direction is predominantly to the south-southeast toward Long Island Sound, however, site specific groundwater flow direction is

FLAMINGO CLEANERS (Continued) **1000299848**

	radial, and seasonally affected.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE or perc) which was present in soils, groundwater, and indoor air. PCE breakdown products Trichloroethene (TCE) and 1,2-dichloroethene (1,2-DCE), vinyl chloride, as well as 1,1,1 trichloroethane (1,1,1 TCA), were also present at the site. Remedial actions have removed source soils, treated groundwater, and have prevented contaminants from entering the indoor air. Residual contamination in the soil, groundwater, and indoor air is being managed under a Site Management Plan.
Health Problem:	Measures are in place to control the potential for coming in contact with subsurface soil and ground water contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater and/or soil may move into the soil vapor (air space within the soil), which in turn may move into overlying building and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilate/remove the air beneath the building) has been installed in the on-site building to prevent the indoor air quality from being affected by the contamination in the soil vapor beneath the building. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:90'830 / 73:77'928
Dell:	False
Record Add:	12/16/2004 12:46:00 PM
Record Upd:	10/25/2013 4:35:00 PM
Updated By:	BXANDERS
Own Op:	6
Sub Type:	P03
Owner Name:	JO-ANNE LATINO
Owner Company:	JAMM North Avenue Realty, LLC.
Owner Address:	31 Green St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Charlestown, MA 2129
Owner Country:	United States of America
Own Op:	4
Sub Type:	Not reported
Owner Name:	Abbas A. Alsaidi
Owner Company:	New Rock Mini Mart & Deli Inc.
Owner Address:	149 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Owner Name:	Luigi Tush Lleshaj
Owner Company:	V & V Capital LLC
Owner Address:	369 Phillips Hill Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michael Knipfing
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	149-155 North Corp.
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Luigi Lleshaj
Owner Company:	V&V Capital LLC
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	new City, NY 10956
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Not reported
Owner Company:	Luigi Lleshaj
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	The Estate of Dorothy Kettner
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN

FLAMINGO CLEANERS (Continued) **1000299848**

Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	7/12/2016 12:27:00 PM
Record Updated:	7/12/2016 12:27:00 PM
Updated By:	JBODEE
Crossref ID:	W3-1058-05-03
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	12/5/2016 12:19:00 PM
Record Updated:	12/5/2016 12:19:00 PM
Updated By:	KATHOMPS
Crossref ID:	Not reported
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	11/4/2016 10:40:00 AM
Record Updated:	11/4/2016 10:40:00 AM
Updated By:	KATHOMPS
Crossref ID:	Not reported
Cross Ref Type Code:	1
Cross Ref Type:	Spill No.
Record Added Date:	7/23/2012 4:23:00 PM
Record Updated:	7/23/2012 4:23:00 PM
Updated By:	JPCUMMIN

FLAMINGO CLEANERS (Continued) **1000299848**

NY MANIFEST:

Name:	V & V CAPITAL LLC
Address:	149 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD012946885
Facility Status:	Not reported
Location Address 1:	149 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012946885
Mailing Name:	V & V CAPITAL LLC
Mailing Contact:	V&V CAPITAL LLC - FORMER FLAMINGO CLEANERS
Mailing Address 1:	149 NORTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3615865900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2013
Trans1 Recv Date:	01/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX168000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	008835161JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	6160
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	F002
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH300 **FLAMINGO/TYK CLEANERS** **NY DRYCLEANERS** **S110246604**
SE **149 NORTH AV.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1297 ft. **Site 9 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

DRYCLEANERS:

Name:	FLAMINGO/TYK CLEANERS
Address:	149 NORTH AV.
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00335
Phone Number:	914-235-1591
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	2019-09-08 00:00:00
Install Date:	94/08
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

AH301 **COLONIAL CLEANERS CORP** **RCRA NonGen / NLR** **1000338874**
SE **149 NORTH AVE** **NYD982718058**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1297 ft. **Site 10 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	COLONIAL CLEANERS CORP
Facility address:	149 NORTH AVE NEW ROCHELLE, NY 10801-7405

COLONIAL CLEANERS CORP (Continued) **1000338874**

EPA ID: NYD982718058
Mailing address: NORTH AVE
NEW ROCHELLE, NY 10801
Contact: Not reported
Contact address: NORTH AVE
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: COLONIAL CLEANERS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COLONIAL CLEANERS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

COLONIAL CLEANERS CORP (Continued) **1000338874**

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: COLONIAL CLEANERS CORP
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: COLONIAL CLEANERS CORP
Classification: Not a generator, verified

Date form received by agency: 1988-11-30 00:00:00.0
Site name: COLONIAL CLEANERS CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

AH302 **OFF-SITE FLAMINGO CLEANERS** **NY BROWNFIELDS** **S110043637**
SE **149 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.246 mi.
1297 ft. **Site 11 of 11 in cluster AH**

Relative:
Higher

Actual:
89 ft.

BROWNFIELDS:
Name: OFF-SITE FLAMINGO CLEANERS
Address: 149 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Program: BCP
Site Code: 414661
Acres: Not reported
HW Code: C360078A
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 06/03/2009
Record Updated Date: 08/23/2019
Update By: KJCARPEN
Site Description: Location: This site is the off-site component of the former Flamingo Dry Cleaners site (C360078). The site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site itself is a one-story commercial building which includes four commercial spaces including the former dry cleaner space. This off-site component is comprised of immediately-surrounding areas. Current Zoning/Uses: Surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a college, a medical facility, and a church. Historical Uses: The on-site building was constructed in 1941 and used for retail.

OFF-SITE FLAMINGO CLEANERS (Continued) **S110043637**

Flamingo Cleaners began operations in 1958 and ran until 2005 when all dry-cleaning equipment was removed. On-site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). A referral for off-site work was completed in December 2007 and a SSF RI/FS Work assignment was approved in March 2009. The RI field work was conducted in the summer of 2009 and fall of 2009. Additional round of gw analyses occurred in spring 2010. The on-going off-site investigation thus far indicates that PCE is not present in environmental media above standards in the area surrounding the site. Site Geology/Hydrogeology: The area surrounding the site is underlain by glacial till which sit atop highly weathered bedrock. Area bedrock ranges from 5-25 feet below ground surface. The water table ranges from 5-11 feet below ground surface. Groundwater flow direction is predominantly to the south-southwest toward Long Island Sound, but site specific groundwater flow direction is radial and seasonally affected.

Env Problem:	Nature and Extent of Contamination: Based on investigations to date, the primary contaminant of concern at the site is tetracholoroethylene (PCE), a dry cleaning solvent. On-site, PCE has been detected in soils, soil vapor, indoor air, and groundwater. The off-site investigation to date indicates that there are no off-site impacts. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site.
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2/27/2010 1:25:00 PM
Record Upd:	10/18/2012 2:41:00 PM
Updated By:	ldennist
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AN303 **MAY PARTNERS, LLC** **NY AST** **A100355569**
NNW **35-45 MAY STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.247 mi.
1302 ft. **Site 2 of 3 in cluster AN**

Relative: **Lower**
Actual: **79 ft.**

WESTCHESTER CO. AST:

Name:	MAY PARTNERS, LLC
Address:	35-45 MAY STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-600544
Site Status:	Active
GDS Number:	Not reported
Operator Name:	May Partners, LLC
Owner Name:	May Partners, LLC c/o Andover Properties
Owner Street:	25 East Spring Valley Avenue, Suite 280
Owner Address2:	Not reported
Owner City/State/Zip:	Maywood, NJ 07607
Tank Number:	001
Status:	3. Closed - Removed
Date Installation:	Not reported
Capacity:	4800
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	Not reported
Tank Location:	4. Aboveground: w/ 10% or more below ground
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	3. Gravity
Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None

MAY PARTNERS, LLC (Continued) **A100355569**

Piping Secondary Containment: 0. None
Overfill Prevention: 5. Vent Whistle
Spill Prevention: 0. None
Dispenser: 0. None

AM304 **FIREHOUSE** **NY LTANKS** **S103037428**
ENE **HARRISON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.252 mi.
1329 ft. **Site 19 of 19 in cluster AM**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:

Name:	FIREHOUSE
Address:	HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9713840 / 1998-03-27
Facility ID:	9713840
Site ID:	252028
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALELLO
Spiller Phone:	(914) 654-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED. SYSTEM PASSED. NFA"
Remarks:	""

All TTF:

Facility ID:	9713840
Spill Number:	9713840
Spill Tank Test:	1545673
Site ID:	252028
Tank Number:	2
Tank Size:	5000

FIREHOUSE (Continued) **S103037428**

Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	252028
Operable Unit ID:	1059801
Operable Unit:	01
Material ID:	324831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL305 **BERGMAN REALTY SERVICES** **NY LTANKS** **S106972591**
NE **140 HUGUENOT STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.256 mi.
1351 ft. **Site 6 of 6 in cluster AL**

Relative:
Lower

Actual:
66 ft.

LTANKS:

Name:	BERGMAN REALTY SERVICES
Address:	140 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0505137 / 2007-11-07
Facility ID:	0505137
Site ID:	350100
Spill Date:	2005-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	WCDOH
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

BERGMAN REALTY SERVICES (Continued) **S106972591**

Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2007-11-07
Spiller Name:	STEVE RING
Spiller Company:	RING HOME
Spiller Address:	140 HUGINOT STREET
Spiller County:	001
Spiller Contact:	STEVE RING
Spiller Phone:	(732) 855-8600
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	296544
DEC Memo:	"10/13/05 Closure letter sent to the RP from Danielle Jackson of the WCHD based on information submitted in a tank closure report. NFA TG"
Remarks:	""

All TTF:

Facility ID:	0505137
Spill Number:	0505137
Spill Tank Test:	1549133
Site ID:	350100
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	350100
Operable Unit ID:	1107682
Operable Unit:	01
Material ID:	2097572
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AQ306 **BLESSED SACREMENT CHURCH** **NY LTANKS** **S105996474**
South **15 SHEA PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1392 ft. **Site 1 of 3 in cluster AQ**

Relative:
Higher

Actual:
97 ft.

LTANKS:

Name:	BLESSED SACREMENT CHURCH
Address:	15 SHEA PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0204856 / 2003-10-03
Facility ID:	0204856
Site ID:	167332
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	BLESSED SACREMENT CHURCH
Spiller Address:	15 SHEA PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140984
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"DRY LEAK"

All TTF:

Facility ID:	0204856
Spill Number:	0204856
Spill Tank Test:	1527358
Site ID:	167332
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

BLESSED SACREMENT CHURCH (Continued) **S105996474**

Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	167332
Operable Unit ID:	856138
Operable Unit:	01
Material ID:	519078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP307 **APARTMENT BLDG.** **NY LTANKS** **S104950549**
West **114 UNION AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.264 mi.
1393 ft. **Site 2 of 3 in cluster AP**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Name:	APARTMENT BLDG.
Address:	114 UNION AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9414493 / 1995-02-14
Facility ID:	9414493
Site ID:	238808
Spill Date:	1995-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-02-06
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-03-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001

APARTMENT BLDG. (Continued) **S104950549**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"ESTIMATED WRONG TANK SIZE SPILL CONTAINED NATL.ENVIR.CO. SPILL CREW ON WAY ENV PROD. AND SERVICES HIRED TO CLEAN UP. WILL EXCAVATE DRYWELL."

All Materials:

Site ID:	238808
Operable Unit ID:	1012066
Operable Unit:	01
Material ID:	373228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	175.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0011198
Address:	114 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0011198 / 2001-04-06
Facility ID:	0011198
Site ID:	151446
Spill Date:	2001-01-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-14
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-14
Spill Record Last Update:	2001-04-24
Spiller Name:	Not reported
Spiller Company:	ALBINO FUELS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

APARTMENT BLDG. (Continued) **S104950549**

DEC Region: 3
DER Facility ID: 128711
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE SEE ONE PAGE UDATE BY V. MCCABE 04/06/2001 NORTHEAST COMPLETED CLEANUP. DISPOSED OF 4 DRUMS OF CONTAMINATION. SPILL INFORMATION FORWARDED TO LAW ENFORCEMENT FOR FURTHER ACTION. SPILLS - NO FURTHER ACTION."
Remarks: "tank overfilled caused spill - spill is contained in a parking lot spiller is - albano fuel - 667-0900 (914)-clean up crew on site at this time"

All Materials:
Site ID: 151446
Operable Unit ID: 832582
Operable Unit: 01
Material ID: 541520
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 40.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: RESIDENCE
Address: 114 UNION AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9414511 / 1995-02-13
Facility ID: 9414511
Facility Type: ER
DER Facility ID: 196552
Site ID: 238809
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6010
Spill Date: 1995-02-02
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1995-02-02
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Fire Department
Cleanup Ceased: 1995-02-13
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-02-07
Spill Record Last Update: 1995-02-13
Spiller Name: Not reported
Spiller Company: REGENT OIL

APARTMENT BLDG. (Continued) **S104950549**

Spiller Address: 53 CHARLES STREET
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "SPILLER MAKING DELIVERY FILLED WRONG HOLE FD & CLEAN UP CREW ON SCENE TANK OVERFILL EP & S HIRED BY SPILLER AND ON SCENE CONTACTED WCHD WILL RESPOND SEE SPILL #94-14493"

All Materials:
Site ID: 238809
Operable Unit ID: 1008085
Operable Unit: 01
Material ID: 373246
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: .00
Oxygenate: Not reported

AN308 **DIMATTOE TTF** **NY LTANKS** **S113820294**
NNW **55 MAY STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.266 mi.
1405 ft. **Site 3 of 3 in cluster AN**

Relative: **Lower**
Actual: **79 ft.**

LTANKS:
Name: DIMATTOE TTF
Address: 55 MAY STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1301890 / 2013-08-08
Facility ID: 1301890
Site ID: 482303
Spill Date: 2013-05-23
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2013-05-23
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2013-05-23
Spill Record Last Update: 2013-08-08
Spiller Name: Not reported
Spiller Company: DIMATTOE

DIMATTOE TTF (Continued) **S113820294**

Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	AMELIO DIMATTOE
Spiller Phone:	(914) 403-1942
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	437556
DEC Memo:	"5/23/13 left message on homeowner's phone. Spoke to Kathy, at US Tank Tech Tank is 1000 gal. Real estate transaction, and plans are to retest. dw 07/31/13 Northeast Environmental reported that they cut & cleaned the tank and obtained a soil sample from beneath the tank. The soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"repair/retest pending"

All TTF:

Facility ID:	1301890
Spill Number:	1301890
Spill Tank Test:	2493480
Site ID:	482303
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.70
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	482303
Operable Unit ID:	1232041
Operable Unit:	01
Material ID:	2230831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

309
East
1/4-1/2
0.267 mi.
1411 ft.

CITY OF NEW ROCHELLE FIRE
1 HARRISON STREET
NEW ROCHELLE, NY

NY LTANKS **S105995871**
N/A

Relative:
Lower

Actual:
72 ft.

LTANKS:

Name:	CITY OF NEW ROCHELLE FIRE
Address:	1 HARRISON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0201696 / 2002-09-18
Facility ID:	0201696
Site ID:	75380
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE FIRE DEPT
Spiller Address:	1 HARRISON STREET
Spiller County:	001
Spiller Contact:	FRANK GALLELLO-FIRE DEPT
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70557
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST.PBS 3-600407 "

All TTF:

Facility ID:	0201696
Spill Number:	0201696
Spill Tank Test:	1527133
Site ID:	75380
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

CITY OF NEW ROCHELLE FIRE (Continued) **S105995871**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 75380
Operable Unit ID: 854864
Operable Unit: 01
Material ID: 523106
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AO310 **EXXON S/S** **NY LTANKS** **1000553075**
SSW **635 MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.269 mi.
1419 ft. **Site 4 of 4 in cluster AO**

Relative: **Lower**
Actual: **85 ft.**

LTANKS:
Name: EXXON S/S
Address: 635 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9206930 / 2005-03-11
Facility ID: 9206930
Site ID: 140421
Spill Date: 1992-09-16
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1992-09-16
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2005-03-12
Spiller Name: Not reported
Spiller Company: EXXON
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

EXXON S/S (Continued) **1000553075**

DEC Region: 3
DER Facility ID: 119925
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/11/05 per contractors report 7 tanks removes all in good condition (no evidence of holes or cracks; no detect in post excavation samples--close "
Remarks: "DURING TANK REMOVAL CONTAMINATED SOIL DISCOVERED WILL TEST"

All Materials:
Site ID: 140421
Operable Unit ID: 970699
Operable Unit: 01
Material ID: 407611
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: CUMBERLAND FARMS 70288
Address: 635 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1405322 / Not Reported
Facility ID: 1405322
Facility Type: ER
DER Facility ID: 119925
Site ID: 498745
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 2014-08-15
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2014-08-15
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 2014-08-15
Spill Record Last Update: 2019-12-03
Spiller Name: Not reported
Spiller Company: CUMBERLAND FARMS 70288
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOHN

EXXON S/S (Continued) **1000553075**

DEC Memo: "8-15-14 Spoke with Angela Pimento at CF. She will have John return call to dispatch desk. jm Recv'd callback from Chris Lalak - WCDOH. He has spoken with John. Double wall fiberglass piping from dispensers to tanks. Leak is contained in tanktop sump. System has has been shut down at this time until they figure out what they are going to do. They believe they will probably replace lines. Chris says no leak to environment and he will be taking lead. jm 5-15 new spill 15-01325; Phase 2report 10-15-15 email status request sent to WCHD & Cumby RDB 10-22-15, from Cumby In response to the line failure, CFI engaged Island Pump & Tank (IPT) to perform the repairs. In lieu of replacing the product piping, IPT installed a siphon bar on the regular tanks and removed the submersible pump from the regular tank that had the failed product piping. IPT then removed and capped the regular product piping that had failed. The secondary line was tested and the dispenser pans and STP sumps were hydrostatically tested and passed. RDB 2-16 new SPills 15-10746 3-8-16 during meeting with WCHD, Singh, his att, his consultant, Cumby, their consultant and att, taking place in New Rochelle. Closure was denied on spills 14-05322 & 15-01325and RPs agreed to a scope of work by March 16. RDB 5-4-17 Work completed, waiting for closure report. GHP 12-3-19 Call from HighPoint Engineering. Felix and Sons Contractor installed new tanks in September 2016 and tightness tested October 2016. What do we have to do to close the spill . Sunny Singh for 635 Main Street Realty LLC (516-777-4320) is the client. BTR"

Remarks: "spill to containment/clean up complete"

All Materials:

Site ID:	498745
Operable Unit ID:	1248186
Operable Unit:	01
Material ID:	2249583
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	CUMBERLAND FARM
Address:	635 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0514511 / 2006-03-20
Facility ID:	0514511
Facility Type:	ER
DER Facility ID:	119925
Site ID:	361248
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-20
Investigator:	RXAMATO
Referred To:	WCDOH
Reported to Dept:	2006-03-20
CID:	444

EXXON S/S (Continued) **1000553075**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-31
Spiller Name:	MELISSA GLIDEN
Spiller Company:	CUMBERLAND FARM
Spiller Address:	635 MAIN STREET
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
DEC Memo:	"03/21/06: Closed - NFA R. Amato"
Remarks:	"water in the dispenser pan and tyree enroute to clean up"

AR311 **BLESSED SACREMENT SCHOOL** **NY LTANKS** **S102154123**
South **24 MAPLE AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.270 mi.
1424 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	NEW ROCHELLE CATH MIDDLE
Address:	24 MAPLE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0204857 / 2003-10-03
Facility ID:	0204857
Site ID:	80066
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE CATH MIDDLE
Spiller Address:	24 MAPLE AV
Spiller County:	001
Spiller Contact:	MARV
Spiller Phone:	(914) 637-7505
Spiller Extention:	Not reported

BLESSED SACREMENT SCHOOL (Continued) **S102154123**

DEC Region: 3
DER Facility ID: 74246
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks: ""

All TTF:
Facility ID: 0204857
Spill Number: 0204857
Spill Tank Test: 1527359
Site ID: 80066
Tank Number: 1
Tank Size: 2000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 80066
Operable Unit ID: 856140
Operable Unit: 01
Material ID: 519079
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: BLESSED SACREMENT SCHOOL
Address: 24 MAPLE AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9008354 / 1990-11-26
Facility ID: 9008354
Facility Type: ER
DER Facility ID: 107755
Site ID: 124420
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6010
Spill Date: 1990-10-30
Investigator: tdghiosa

BLESSED SACREMENT SCHOOL (Continued) **S102154123**

Referred To:	Not reported
Reported to Dept:	1990-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-10-31
Cleanup Meets Std:	True
Last Inspection:	1990-10-31
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-06
Spill Record Last Update:	1990-11-26
Spiller Name:	Not reported
Spiller Company:	CASTLE FUEL
Spiller Address:	290 LOCUST AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE BURST DURING DELIVERY WC FIRE CONTROL ON SCENE ABSORBANT PADS HAVE BEEN PUT DOWN CHIEF MCCAFFREY CONTACTED BUT HE WASN'T ON SCENE HAS NO INFO."

All Materials:

Site ID:	124420
Operable Unit ID:	945552
Operable Unit:	01
Material ID:	432188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BLESSED SACRAMENT SCHOOL
Address:	24 MAPLE AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9111148 / 1992-03-17
Facility ID:	9111148
Facility Type:	ER
DER Facility ID:	107755
Site ID:	124421
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1992-01-29
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1992-01-29
CID:	Not reported
Water Affected:	Not reported

BLESSED SACREMENT SCHOOL (Continued) **S102154123**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1992-02-05
Cleanup Meets Std:	True
Last Inspection:	1992-02-05
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-30
Spill Record Last Update:	1992-03-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL DISCOVERED SEEPING OUT OF GROUND/BLACKTOP WALKWAY (BETWEEN SCHOOL AND BEAUTY SALON) SUSPECT BROKEN RETURN LINE APPROX 30' FROM TANK TO BURNER - 2K TANK AL EASTMAN TO EIR CASTLE OIL CREW ENROUTE"

All Materials:

Site ID:	124421
Operable Unit ID:	964875
Operable Unit:	01
Material ID:	416206
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AS312 **COMMERCIAL PROPERTY** **NY LTANKS** **S112810152**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1439 ft. **Site 1 of 6 in cluster AS**

Relative: **Higher**

Actual: **89 ft.**

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1213228 / 2013-02-04
Facility ID:	1213228
Site ID:	476407
Spill Date:	2012-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-12-10
CID:	Not reported

COMMERCIAL PROPERTY (Continued) **S112810152**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-10
Spill Record Last Update:	2013-02-04
Spiller Name:	Not reported
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	HAL SHAPIRO
Spiller Phone:	(914) 355-5350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"12-10-12 PBS site. Tank failed with popping. US Tank Tech has been testing since '98. Super was at site during test and Shapiro notified by phone. jc 12/19/12: Update from WCDoH PBS: >>> Lalak, Chris >>cjl1@westchestergov.com> 12/11/2012 4:23 PM >>> 1213228 38 Locust, new Rochelle PBS 3-800080 TTF 3K tank from 84 Tyra/Carlos Lead jod 2/4/2013: Tank passed a retest after piping was repaired. Report entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"1211 THE CALLER IS REPORTING A FAILED TANK TEST."

All Materials:

Site ID:	476407
Operable Unit ID:	1226235
Operable Unit:	01
Material ID:	2223616
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AS313 **COMMERCIAL SITE** **NY LTANKS** **U003857828**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.273 mi.
1439 ft. **Site 2 of 6 in cluster AS**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	SBJ ASSOCIATES
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0206043 / 2002-09-26
Facility ID:	0206043
Site ID:	239569
Spill Date:	2002-09-11
Spill Cause:	Tank Test Failure

COMMERCIAL SITE (Continued) **U003857828**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-10-29
Spiller Name:	BARRY SHAPIRO
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	38 LOCUST AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	""
Remarks:	"RECOMMENDATION IS TO UNCOVER - REPAIR - AND RE-TEST."

All TTF:

Facility ID:	0206043
Spill Number:	0206043
Spill Tank Test:	1527440
Site ID:	239569
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239569
Operable Unit ID:	857630
Operable Unit:	01
Material ID:	571516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

COMMERCIAL SITE (Continued) **U003857828**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL SITE
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0408593 / 2005-02-13
Facility ID:	0408593
Site ID:	333366
Spill Date:	2004-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-11-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-05
Spill Record Last Update:	2005-02-13
Spiller Name:	BARRY SHAPIRO
Spiller Company:	COMMERCIAL SITE
Spiller Address:	38 LOCUS AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"02/13/05 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-800080 "

AT314 **SPILL NUMBER 0208792** **NY LTANKS** **S105997404**
North **386 NORTH AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.274 mi.
1448 ft. **Site 1 of 5 in cluster AT**

Relative: LTANKS:
Lower

Name:	SPILL NUMBER 0208792
Address:	386 NORTH AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0208792 / 2002-11-26
Facility ID:	0208792
Site ID:	71430

Actual:
75 ft.

SPILL NUMBER 0208792 (Continued) **S105997404**

Spill Date:	2002-11-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-11-26
Spiller Name:	ROBERT CRIILLO
Spiller Company:	WILCO
Spiller Address:	95 PLAIN AV
Spiller County:	001
Spiller Contact:	CARTER RESIDENCE
Spiller Phone:	(914) 632-6577
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67588
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 SPILL CLEANUP TO BE COMPLETED TOMORROW."
Remarks:	"take pride environmental enroute to clean up the soil"

All Materials:

Site ID:	71430
Operable Unit ID:	861979
Operable Unit:	01
Material ID:	515786
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU315 **DEMELIA - TTF** **NY LTANKS** **S117364514**
West **95 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.274 mi.
1449 ft. **Site 1 of 2 in cluster AU**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	DEMELIA - TTF
Address:	95 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1406916 / 2015-04-14

DEMELIA - TTF (Continued) **S117364514**

Facility ID:	1406916
Site ID:	500408
Spill Date:	2014-10-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-01
Spill Record Last Update:	2015-04-14
Spiller Name:	ROSEMARIE DEMELIA
Spiller Company:	Estate of DeMelia
Spiller Address:	95 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455413
DEC Memo:	"This house is the estate of R Demellia's late mother. Tank failed with only hissing, maybe a line leak but cant be sure. House is being prep'ed for sale....mm 12/08/14: From Envirostar: We pulled a 550 UST at 95 Washington Ave New Rochelle that had previously failed a tank test (spill # 1406916). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Chuck LiVecchi 95 Washington Ave New Rochelle NY jod 3/20/15: Update from Envirostar via email: We removed 6 containers of contaminated soil Between march 12th and yesterday we took samples and back filled the hole. We will Submit for closure. jod 4/13/15: Report with request for closure entered into DecDocs. Post-Ex soil samples show contamination in excess of CP-51 Guidance. Additional information being requested from Envirostar. jod 4/14/2015: Envirostar removed and disposed of the leaking UST and a total of 108.96 tons of petroleum contaminated soil. Some residual contamination over CP-51 Guidance could not be excavated from along the foundation and due to safety concerns with buried utility lines. No evidence of ground water impact noted. Based upon information provided, no further action required at this time. jod"
Remarks:	"550 test failure"

All TTF:

Facility ID:	1406916
Spill Number:	1406916
Spill Tank Test:	2496432
Site ID:	500408
Tank Number:	1
Tank Size:	550

DEMELIA - TTF (Continued) **S117364514**

Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	500408
Operable Unit ID:	1249816
Operable Unit:	01
Material ID:	2251444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

316
NNE
1/4-1/2
0.277 mi.
1461 ft.

10 COMMERCE DRIVE RAIL YARD **NY BROWNFIELDS** **S125465243**
10 COMMERCE DRIVE **N/A**
NEW ROCHELLE, NY 14614

Relative:
Lower

Actual:
66 ft.

BROWNFIELDS:

Name:	10 COMMERCE DRIVE RAIL YARD
Address:	10 COMMERCE DRIVE
City,State,Zip:	NEW ROCHELLE, NY 14614
Program:	BCP
Site Code:	591030
Acres:	1
HW Code:	C360192
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/25/2019
Record Updated Date:	08/29/2019
Update By:	KJCARPEN
Site Description:	Site Location: The Site is located at 10 Commerce Drive in downtown New Rochelle near the Metro North train station. The Site is located in a predominantly commercial, former industrial downtown urban area, which is recently transitioning into more of a residential transit-oriented neighborhood. Site Features: The existing on-site building is vacant. The subject property is currently vacant. The Site is bound by Commerce Drive (Renewal Place) to the northwest with a parking lot across the street that borders the Metro North commuter rail line, a 9-story office building (20 Cedar Street) to the northeast, a 10-story office building (145 Huguenot Street) to the southeast, and a commercial building occupied by a pool supplier (20

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Commerce Drive) to the southwest. The area is still predominantly commercial but new mixed use residential/commercial projects are being encouraged by the City in the DO Zone area. Current Zoning and Land Use: The Site is currently located in the Central Parking Area Downtown Overlay Zone District (a/k/a the DO Zone). Past Use of the Site: The site housed a former railroad freight yard, complete with sidings and freight houses as well as coal piles. The Westchester Coal & Oil Company also occupied the southeastern portion of the Site and off-Site property as observed on historical Sanborn maps dated 1931 and 1951. Based on a review of Sanborn Maps, it appears the railyard structures and buildings were demolished in the mid-1960 s and the Site was vacant until the current building on the Site was constructed in or about 1981-1982. From at least 1992 to 2003, an electronics manufacturer and generator of hazardous waste, known as MF Electronics Corporation, was present at the Site. This manufacturer is described as both a circuit board manufacturer and manufacturer of quartz chips used in electronic timing devices. Site Geology and Hydrogeology: The elevation of the Subject Property is approximately 71 feet above mean sea level (amsl). The Subject Property slopes to the northeast toward Long Island Sound, located about 3,000 feet to the east-southeast. The Site is not in a flood zone and is not proximate to any water bodies. Bedrock is located approximately 18 ft below the ground ssurface. The site is underlain by the Hartland Formation, which consists of interbedded units of granite, schist, and amphibolite. Groundwater flow is toward the south east toward Long Island Sound. Groundwater in New Rochelle is not used as a potable water source. Potable water is provided to the Subject Property by the SUEZ Water Company and is derived from surface impoundments in the Croton, Catskill, and Delaware watersheds.
Not reported

Env Problem: Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available. Preliminary information indicates that fill soils contain coal particles, ash, and demolition debris, which may be related to the railyard operations, and which may have resulted in semi-volatile organic compounds (SVOC) and metals contamination on the Site. The most recent subsurface Phase II investigation revealed soils with some black staining and old railroad ties which exhibited a coal tar odor, and associated SVOC contamination. Obstructions were hit at 3 feet in two of the four geotechnical borings suggesting on site landfilling of prior structures, including possible rail lines and railroad ties or timbers from the prior buildings.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	767 Third Avenue, 33rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	767 Third Avenue, 33rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

---

317 SE 1/4-1/2 0.281 mi. 1483 ft. **RESIDENCE 64 CHURCH ST NEW ROCHELLE, NY** **NY LTANKS** **S106971497 N/A**

Relative: Lower

Actual: 86 ft.

LTANKS:

Name:	RESIDENCE
Address:	64 CHURCH ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0408510 / 2008-05-01
Facility ID:	0408510
Site ID:	333255
Spill Date:	2004-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-02

RESIDENCE (Continued) **S106971497**

CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-02-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2008-05-01
Spiller Name:	RAMONE OCEGUERA
Spiller Company:	Not reported
Spiller Address:	64 CHURCH ST
Spiller County:	001
Spiller Contact:	RAMONE OCEGUERA
Spiller Phone:	(914) 396-7293
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268502
DEC Memo:	"11/22/04 AST ON GROUND UNDER DECK. TANK LOST APPROX 150 GALLONS AFTER TEST. FREE PRODUCT IN SUMP PIT IN BASEMENT. FURTHER INVESTIGATION TO BE DONE BY ADVANCED ENVIRONMENTAL. jod 5/1/2008: Advanced Environmental disposed of LUST and 26.15 tons of contaminated soil. Ground water was impacted and sampled. Spill closure report from ECC submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"tank test failed."

All TTF:

Facility ID:	0408510
Spill Number:	0408510
Spill Tank Test:	1548304
Site ID:	333255
Tank Number:	1
Tank Size:	275
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	333255
Operable Unit ID:	1095424
Operable Unit:	01
Material ID:	575563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

RESIDENCE (Continued) **S106971497**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AV318 **CANDREA/GALLETTA RESIDENCE** **NY LTANKS** **S112148789**
WSW **35 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.287 mi.
1516 ft. **Site 1 of 2 in cluster AV**

Relative: **Higher**
Actual: **92 ft.**

LTANKS:

Name:	CANDREA/GALLETTA RESIDENCE
Address:	35 CHARLES ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1202322 / 2012-09-13
Facility ID:	1202322
Site ID:	465083
Spill Date:	2012-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-07
Spill Record Last Update:	2012-09-13
Spiller Name:	Not reported
Spiller Company:	GALETTA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	GALETTA
Spiller Phone:	914-497-9141
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	419452
DEC Memo:	"6-7-12 Kathy already notified owner. Spoke with Anthony, owners son-in-law. Told him to forward passing retest to office for spill to be closed. He asked for email to that affect. I sent. jc 6/18/12- US Tank reports that retest failed. Unknown further action. DT 09/13/12 Castlton Environmental reported that they excavated and removed the tank along with 21.04 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"550 gal ust"

All Materials:

Site ID:	465083

CANDREA/GALLETTA RESIDENCE (Continued) **S112148789**

Operable Unit ID:	1215116
Operable Unit:	01
Material ID:	2213205
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AP319 **SPILL NUMBER 0007965** **NY LTANKS** **S104782459**
WSW **45 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.290 mi.
1531 ft. **Site 3 of 3 in cluster AP**

Relative: **Higher**
Actual: **92 ft.**

LTANKS:

Name:	SPILL NUMBER 0007965
Address:	45 CHARLES ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0007965 / 2000-10-26
Facility ID:	0007965
Site ID:	61314
Spill Date:	2000-10-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-06
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-06
Spill Record Last Update:	2000-11-07
Spiller Name:	Not reported
Spiller Company:	ALBANO FUEL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ALBANO FUEL
Spiller Phone:	(914) 667-0900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/26/2000 TRI-STATE COMPLETED CLEANUP AFTER DEC INSPECTION. INITIAL SPILL BY ALBANO FUEL WAS NEVER REPORTED. NFA"
Remarks:	"SPILL OCCURRED DURING FILL. TRI STATE WAS CONTRACTED FOR CLEAN UP."

SPILL NUMBER 0007965 (Continued) **S104782459**

All Materials:

Site ID:	61314
Operable Unit ID:	830442
Operable Unit:	01
Material ID:	545482
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW320 **RUSH MANUFACTURING CORP** **CORRACTS** **1000201737**
SW **10-12 PINE CT** **RCRA-VSQG** **NYD075436394**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY Spills**
0.291 mi. **FINDS**
1535 ft. **Site 1 of 4 in cluster AW** **ECHO**
NJ MANIFEST
Relative: **RI MANIFEST**
Lower

Actual: **56 ft.**

CORRACTS:

Region:	02
Name:	RUSH MANUFACTURING CORP
Address:	10-12 PINE CT
Address 2:	Not reported
City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYD075436394
Area Name:	SITEWIDE
Corrective Action:	CA050
Actual Date:	1992-09-22 00:00:00.0
NAICS Code 1:	336413
NAICS Code 2:	Not reported
NAICS Code 3:	332999
NAICS Code 4:	336413

Region:	02
Name:	RUSH MANUFACTURING CORP
Address:	10-12 PINE CT
Address 2:	Not reported
City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYD075436394
Area Name:	SITEWIDE
Corrective Action:	CA075LO
Actual Date:	1994-05-03 00:00:00.0
NAICS Code 1:	336413
NAICS Code 2:	Not reported
NAICS Code 3:	332999
NAICS Code 4:	336413

RCRA-VSQG:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	RUSH MANUFACTURING CORP
Facility address:	10-12 PINE CT NEW ROCHELLE, NY 10801

RUSH MANUFACTURING CORP (Continued) **1000201737**

EPA ID: NYD075436394
Mailing address: PINE CT
NEW ROCHELLE, NY 10801
Contact: DENNIS MCNAMARA
Contact address: PINE CT
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: 914-636-2700
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: RUSH MANUFACTURING CORP
Owner/operator address: 10-12 PINE CT
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-636-2700
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TELEDYNE HYDRA-POWER
Owner/operator address: 10-12 PINE COURT
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: 914-632-2200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

RUSH MANUFACTURING CORP (Continued) **1000201737**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1997-06-09 00:00:00.0
Site name: RUSH MANUFACTURING CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1992-02-25 00:00:00.0
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

Date form received by agency: 1980-11-19 00:00:00.0
Site name: RUSH MANUFACTURING CORP
Classification: Not a generator, verified

Date form received by agency: 1979-12-31 00:00:00.0
Site name: RUSH MANUFACTURING CORP
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

RUSH MANUFACTURING CORP (Continued) **1000201737**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Corrective Action Summary:
Event date: 1992-09-22 00:00:00.0
Event: RFA COMPLETED

Event date: 1994-05-03 00:00:00.0
Event: CA PRIORITIZATION-LOW CA PRIORITY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1990-01-26 00:00:00.0
Date achieved compliance: 1990-05-02 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1990-03-12 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Area of violation: Generators - General
Date violation determined: 1989-02-23 00:00:00.0
Date achieved compliance: 1989-05-12 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1989-03-27 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1988-03-16 00:00:00.0
Date achieved compliance: 1988-11-17 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1988-05-09 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1987-08-27 00:00:00.0
Date achieved compliance: 1988-11-17 00:00:00.0
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 1986-03-19 00:00:00.0
Date achieved compliance: 1986-05-27 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1986-04-15 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date violation determined: 1984-02-23 00:00:00.0
Date achieved compliance: 1985-10-07 00:00:00.0
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 1985-03-27 00:00:00.0
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 1990-01-26 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1990-05-02 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1989-02-23 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1989-05-12 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1988-03-16 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1988-11-17 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1988-03-11 00:00:00.0
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 1987-08-27 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1988-11-17 00:00:00.0
Evaluation lead agency: EPA

Evaluation date: 1986-03-19 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1986-05-27 00:00:00.0
Evaluation lead agency: State

Evaluation date: 1984-02-23 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 1985-10-07 00:00:00.0
Evaluation lead agency: State

SPILLS:
Name: COMMERCIAL MACHINE SHOP

RUSH MANUFACTURING CORP (Continued) **1000201737**

Address:	10-12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0804532 / 2008-09-26
Facility ID:	0804532
Facility Type:	ER
DER Facility ID:	350696
Site ID:	401456
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-07-21
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-21
Spill Record Last Update:	2008-09-26
Spiller Name:	MICHEAL
Spiller Company:	COMMERCIAL MACHINE SHOP
Spiller Address:	10-12 PINE COURT
Spiller Company:	001
Contact Name:	MICHEAL
DEC Memo:	"08/01/08 Conklin Services & Construction submitted a Limited Subsurface Investigation Report. Four geoprobe borings were placed around an abandoned tank. Slight soil contamination exists in borings 1 and 2, however the levels are below DEC TAGM guidance values. NFA TG"
Remarks:	"SOIL BORINGS SHOWED CONTAMINATED SHOP"

All Materials:

Site ID:	401456
Operable Unit ID:	1158245
Operable Unit:	01
Material ID:	2149301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ALPHA MEDICAL EQUIPMENT OF NY
Address:	10-12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0901536 / 2009-06-22

RUSH MANUFACTURING CORP (Continued) **1000201737**

Facility ID:	0901536
Facility Type:	ER
DER Facility ID:	350696
Site ID:	413531
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2009-05-07
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-06-22
Spiller Name:	Not reported
Spiller Company:	ALPHA MEDICAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NIKI
DEC Memo:	"5/7/09 At a construction site, contaminated soils were encountered, which was confirmed by soil tests done by Northeast. They will be doing the site remediation and will submit a cleanup report. dw 06/12/09 Northeast Environmental provided oversight activity when petroleum impacted soil was discovered and need to be removed. Remediation consisted of the removal of 425.66 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were all below DEC guidance values. NFA required. TG"
Remarks:	"1231 The caller advised dispatch North East Environmental will conduct the clean up. The caller requested a call back. No water ways affected."

All Materials:

Site ID:	413531
Operable Unit ID:	1169955
Operable Unit:	01
Material ID:	2161660
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

FINDS:

RUSH MANUFACTURING CORP (Continued) **1000201737**

Registry ID: 110009468343

Click Here:

Environmental Interest/Information System:

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000201737
Registry ID:	110009468343
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009468343
Name:	RUSH MFG CORP
Address:	10-12 PINE CT
City,State,Zip:	NEW ROCHELLE, NY 10801

NJ MANIFEST:

EPA Id:	NYD075436394
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001619722SKS
EPA ID:	NYD075436394
Date Shipped:	02/23/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/26/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001803673SKS
EPA ID:	NYD075436394
Date Shipped:	05/08/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	002115978SKS
EPA ID:	NYD075436394
Date Shipped:	10/01/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	5 G

Manifest Number:	001811141SKS
EPA ID:	NYD075436394
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 8 G

Manifest Number: 002486638SKS
EPA ID: NYD075436394
Date Shipped: 01/29/2010
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/01/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H020
Quantity: 7 G

RUSH MANUFACTURING CORP (Continued) **1000201737**

Manifest Number:	000266181CEX
EPA ID:	NYD075436394
Date Shipped:	10/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	9 G

Manifest Number:	001819324SKS
EPA ID:	NYD075436394
Date Shipped:	07/16/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

Manifest Number:	001632477SKS
EPA ID:	NYD075436394
Date Shipped:	01/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

RI MANIFEST:

EPA Id:	NYD075436394
GEN Cert Date:	10/7/1991
Manifest Document Number:	CTC0168898
Waste Description:	OIL
TSDF Id:	CTD021816889
TSDF Name:	UNITED
Qty:	575
WT/Vol Units:	G
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Item Number:	1
Transporter 2 Name:	Not reported
Transporter Name 2:	SEALAND
Transporter EPAID:	CTD983872748
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Quarter:	Not reported
Waste Description:	OIL
Transporter Contact Name:	Not reported
Quantity:	575
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SEALAND
Billing Name:	Not reported
Transporter EPA ID:	CTD983872748
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/7/1991
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Quarter:	Not reported
Waste Description:	OIL
Transporter Contact Name:	Not reported
Quantity:	575
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SEALAND
Billing Name:	Not reported
Transporter EPA ID:	CTD983872748
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/7/1991
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

AW321 **GKIDS REALTY** **NY LTANKS** **S105995601**
SW **10/12 PINE COURT** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.291 mi.
1535 ft. **Site 2 of 4 in cluster AW**

Relative: LTANKS:
Lower

Name:	GKIDS REALTY
Address:	10/12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0200337 / 2003-12-09
Facility ID:	0200337
Site ID:	235436
Spill Date:	2002-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3

Actual:
56 ft.

GKIDS REALTY (Continued) **S105995601**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-04-10
CID:	204
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-10
Spill Record Last Update:	2003-12-10
Spiller Name:	GKIDS REALTY
Spiller Company:	GKIDS REALTY
Spiller Address:	10/12 PINE COURT
Spiller County:	001
Spiller Contact:	MICHAEL GOLD
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193919
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER #2 PBS 3-504998 handled by WCHD 12/09/03 TANK CLOSED IN PLACE, SAMPLE RESULTS BELOW TAGM. SPILL CLOSED BY WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE - RECOMMEND TO ISOLATE PIPING AND RETEST "

All TTF:

Facility ID:	0200337
Spill Number:	0200337
Spill Tank Test:	1527023
Site ID:	235436
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235436
Operable Unit ID:	851333
Operable Unit:	01
Material ID:	525339
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

GKIDS REALTY (Continued) **S105995601**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU322 **BRAM REALTY** **NY LTANKS** **S109583709**
West **105 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.293 mi.
1549 ft. **Site 2 of 2 in cluster AU**

Relative: LTANKS:
Lower

Actual:
85 ft.

Name:	BRAM REALTY
Address:	105 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0902464 / 2010-02-01
Facility ID:	0902464
Site ID:	414506
Spill Date:	2009-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-01
Spill Record Last Update:	2010-02-01
Spiller Name:	HAL SHAPIRO
Spiller Company:	BRAM REALTY
Spiller Address:	105 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	363644
DEC Memo:	"6-1-09: V.Mc.^ Hal/BRAM REALTY: Left Mess: Req.Callbk. to dispt &/or J.O'Dee. 6-3-09: HAL SHAPIRO CALLED AND STATED IS WAS AWARE OF PROPER PROCEDURES TO FOLLOW. HE WILL CONTACT HIS OIL CO. FOR DIRECTION AND NOTIFY DEC OF OUTCOME. 01/25/10 Enviroshield reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was obseved in the tank excavation. NFA TG "
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST UNK IF ANY PRODUCT WAS SPILLED."

All Materials:

BRAM REALTY (Continued) **S109583709**

Site ID:	414506
Operable Unit ID:	1170891
Operable Unit:	01
Material ID:	2162674
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AV323 **MERLUCCI RESIDENCE** **NY LTANKS** **S111063886**
WSW **30 CHARLES STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1552 ft. **Site 2 of 2 in cluster AV**

Relative: LTANKS:
Higher

Actual: Name:	MERLUCCI RESIDENCE
92 ft. Address:	30 CHARLES STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1103221 / 2011-11-14
Facility ID:	1103221
Site ID:	450778
Spill Date:	2011-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-22
Spill Record Last Update:	2011-11-14
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MR MERLUCCI
Spiller Phone:	(914) 632-2099
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	405335
DEC Memo:	"6/22/11 UST is 62 years old, according to Ms. Merlucci. House is for sale. US Tank Tech has notified Town & Country Oil not evacuate tank prior to further action (repair, retest, tank pull) of owner. dw

MERLUCCI RESIDENCE (Continued) **S111063886**

11/14/11: UST removed by JM Associates. Report states tank was inspected and no corrosion holes were found. Soil samples taken from tank grave showed minor amounts of contamination, most below CP-51 with a few slight exceedences of SVOCs. Excavation was backfilled. Report will be entered into eDocs. jod"

Remarks: "repair retest pending or removal"

All Materials:

Site ID:	450778
Operable Unit ID:	1200979
Operable Unit:	01
Material ID:	2197455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AT324 **KGM PROPERTY ASSOC.** **NY LTANKS** **U003647638**
North **394 N. AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1553 ft. **Site 2 of 5 in cluster AT**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Name:	KGM PROPERTY ASSOC.
Address:	394 N. AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9202033 / 1993-01-27
Facility ID:	9202033
Site ID:	69270
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-20
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001

KGM PROPERTY ASSOC. (Continued) **U003647638**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65872
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK IS 38 YEARS OLD THIS TANK WAS ORIGINAL REPORTED UNDER #9201744 BUT IS LOCATED AT DIFFERENT ADDRESS PETRO-TITE -.422 GPH"

All TTF:

Facility ID:	9202033
Spill Number:	9202033
Spill Tank Test:	1540014
Site ID:	69270
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	69270
Operable Unit ID:	966124
Operable Unit:	01
Material ID:	557154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AT325 **GETTY# 677** **NY LTANKS** **S103482965**
North **381 NORTH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.298 mi.
1573 ft. **Site 3 of 5 in cluster AT**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	GETTY# 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0400912 / 2005-01-18
Facility ID:	0400912
Site ID:	242546

GETTY# 677 (Continued) **S103482965**

Spill Date:	2004-04-27
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-04-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-27
Spill Record Last Update:	2005-01-18
Spiller Name:	STEVEN PHELTS
Spiller Company:	GETTY# 677
Spiller Address:	381 NORTH AVE
Spiller County:	001
Spiller Contact:	STEVEN PHELTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 1/18/2005 close and handle under existing spill 9003146 "
Remarks:	"FOUND CONTAMINATED SOIL WHILE REMOVING TANK: "

All Materials:

Site ID:	242546
Operable Unit ID:	882894
Operable Unit:	01
Material ID:	555170
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GETTY # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0900607 / 2009-04-16
Facility ID:	0900607
Facility Type:	ER
DER Facility ID:	199318
Site ID:	412555

GETTY# 677 (Continued) **S103482965**

DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-04-16
Investigator:	RXAMATO
Referred To:	Not reported
Reported to Dept:	2009-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-16
Spill Record Last Update:	2009-04-16
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/17/09: Vac truck pumped out dispenser sump...close/nfa..ra"
Remarks:	"DUE TO POOR HOUSEKEEPING A HALF GALLON OF PRODUCT WAS SPILLED TO CONRETE BAY FLOORS. CLEAN UP WAS DONE."

All Materials:

Site ID:	412555
Operable Unit ID:	1169019
Operable Unit:	01
Material ID:	2160665
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	.50
Oxygenate:	Not reported

Name:	GETTY STATION#677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0503897 / 2006-12-19
Facility ID:	0503897
Facility Type:	ER
DER Facility ID:	199318
Site ID:	348603
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	2005-07-01
Investigator:	JBODee

GETTY# 677 (Continued) **S103482965**

Referred To:	Not reported
Reported to Dept:	2005-07-01
CID:	409
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-01
Spill Record Last Update:	2006-12-19
Spiller Name:	UNKNOWN
Spiller Company:	CUSTOMER TANK OVERFILL
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	""
Remarks:	"1 cup and has been cleaned up."

All Materials:

Site ID:	348603
Operable Unit ID:	1106254
Operable Unit:	01
Material ID:	1971181
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0912229 / 2010-02-23
Facility ID:	0912229
Facility Type:	ER
DER Facility ID:	199318
Site ID:	425106
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-02-23
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

GETTY# 677 (Continued) **S103482965**

Cleanup Meets Std:	True
Last Inspection:	2010-02-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-23
Spill Record Last Update:	2010-03-30
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"2/23/10 confirmed clean up, nfa...mm"
Remarks:	"HALF GALLON OF WASTE OIL TO CONCRETE CLEAN UP WAS DONE."

All Materials:

Site ID:	425106
Operable Unit ID:	1180837
Operable Unit:	01
Material ID:	2174836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	REAR OF GETTY STATION
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9805150 / 1998-07-27
Facility ID:	9805150
Facility Type:	ER
DER Facility ID:	199318
Site ID:	242548
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1998-07-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-24
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-24
Spill Record Last Update:	1998-08-04

GETTY# 677 (Continued) **S103482965**

Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ORLANDO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 SITE INSPECTED BY J. O'DEE. TYREE IN PROCESS OF INSTALLING A MONITORING WELL AT 381 NORTH AVE., NEW ROCHELLE. IT APPEARS A RESIDENT PARKED CAR OVER STORM DRAIN WHILE CHANGING OIL. THE S/S EMPLOYEES WILL OBSERVE THE AREA AND CONTACT DEC IF ANY ADDITIONAL DUMPING OCCURS. NFA."
Remarks:	"FOUND OIL SPILLED INTO SEWER IN REAR OF GAS STATION"

All Materials:

Site ID:	242548
Operable Unit ID:	1063026
Operable Unit:	01
Material ID:	319903
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	90.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1001015 / 2010-04-27
Facility ID:	1001015
Facility Type:	ER
DER Facility ID:	199318
Site ID:	433723
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-04-27
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2010-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-04-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-05-10
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY 677

GETTY# 677 (Continued) **S103482965**

Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/27/10 - Spill cleaned up. NFA. KAB 5/10/10: Update from Denise Heinzinger of WCDOH who inspected: #1001015 small spill onto concrete at 381 North Ave, New Rochelle, clean up performed jod"
Remarks:	"1 pint onto concrete. Clean up complete"

All Materials:

Site ID:	433723
Operable Unit ID:	1184583
Operable Unit:	01
Material ID:	2178854
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GETTY STATION # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1005811 / 2010-08-25
Facility ID:	1005811
Facility Type:	ER
DER Facility ID:	199318
Site ID:	439142
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	D4
SWIS:	6010
Spill Date:	2010-08-25
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-08-25
Spill Record Last Update:	2010-08-25
Spiller Name:	MIKE CARR
Spiller Company:	GETTY
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"8/25/10 Confirmed clean up with caller, nfa...mm"
Remarks:	"Caller stated they had spilt waste oil on concrete, Are has been

GETTY# 677 (Continued) **S103482965**

cleaned up."

All Materials:

Site ID:	439142
Operable Unit ID:	1189791
Operable Unit:	01
Material ID:	2184749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GETTY 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1012947 / 2011-03-31
Facility ID:	1012947
Facility Type:	ER
DER Facility ID:	401849
Site ID:	447247
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6038
Spill Date:	2011-03-29
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2011-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-29
Spill Record Last Update:	2011-03-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"3-29-11 Called and left message for Mike to return call to dispatch desk. jm 3-31-11 Spoke with Mike. Spill was as stated and cleanup completed. jm"
Remarks:	"contained to bay floor, clean up"

All Materials:

Site ID:	447247
Operable Unit ID:	1197384

GETTY# 677 (Continued) **S103482965**

Operable Unit:	01
Material ID:	2193703
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AS326 **APT. BUILDING** **NY LTANKS** **S102660713**
ESE **55-59 LOCUST AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.300 mi.
1584 ft. **Site 3 of 6 in cluster AS**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	APT. BUILDING
Address:	55-59 LOCUST AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9200639 / 1992-06-26
Facility ID:	9200639
Site ID:	168647
Spill Date:	1992-04-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-05-12
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1992-05-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	1998-01-14
Spiller Name:	Not reported
Spiller Company:	N.Y. PROPERTIES CO.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142042
DEC Memo:	""
Remarks:	"TWO UC TANKS WERE BURIED RAIN FORCES OIL UP THROUGH BLACKTOP MGNT. CO.APPLIES SPEEDI-DRY BUT DOES NOT REPORT OR REPAIR"

All Materials:

APT. BUILDING (Continued) **S102660713**

Site ID:	168647
Operable Unit ID:	964508
Operable Unit:	01
Material ID:	415419
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AT327 **KGM REALTY CO.** **NY LTANKS** **S100493525**
North **396 NORTH AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.300 mi.
1584 ft. **Site 4 of 5 in cluster AT**

Relative: LTANKS:
Lower

Name:	KGM REALTY CO.
Address:	396 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9201744 / 1993-01-27
Facility ID:	9201744
Site ID:	89642
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-13
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."

Actual:
72 ft.

KGM REALTY CO. (Continued) **S100493525**

Remarks: "TANK #1 IS 64 YEARS OLD AND TANK #2 IS 38 YEARS OLD WILL EIR TANK #2 NEXT WEEK"

All TTF:

Facility ID:	9201744
Spill Number:	9201744
Spill Tank Test:	1539987
Site ID:	89642
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	89642
Operable Unit ID:	969160
Operable Unit:	01
Material ID:	413039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AQ328 **BLESSED SACRAMENT HS** **NY LTANKS** **S113494296**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.305 mi.
1612 ft. **Site 2 of 3 in cluster AQ**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Name:	BLESSED SACRAMENT HS
Address:	24 SHEA PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1300960 / Not Reported
Facility ID:	1300960
Site ID:	481320
Spill Date:	2013-04-29
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported

BLESSED SACRAMENT HS (Continued) **S113494296**

Reported to Dept:	2013-04-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-04-29
Spill Record Last Update:	2017-11-16
Spiller Name:	ED SULLIVAN
Spiller Company:	HIGH SCHOOL
Spiller Address:	24 SHEA PLACE
Spiller County:	999
Spiller Contact:	ED SULLIVAN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"This is a 1K ust. Testing done every year. Appears to be a piping problem, will uncover, repair and retest. WCDOH has been notified....mm 8/5/13 Failed retest. Spoke to Kathy Morgan at US Tank Test. dw 11-16-2017 A consultant called-in to say they will submit a closure report today. BTR"
Remarks:	"tank test failure"

All TTF:

Facility ID:	1300960
Spill Number:	1300960
Spill Tank Test:	2493383
Site ID:	481320
Tank Number:	0
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2229789
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported

BLESSED SACRAMENT HS (Continued) **S113494296**

Recovered:	Not reported
Oxygenate:	Not reported
Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2230143
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ329 **BLESSED SACRAMENT HIGH SC** **NY LTANKS** **S106385926**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.306 mi.
1614 ft. **Site 3 of 3 in cluster AQ**

Relative: **Higher**
Actual: **91 ft.**

LTANKS:

Name:	BLESSED SACRAMENT HIGH SC
Address:	24 SHEA PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0400709 / 2004-07-06
Facility ID:	0400709
Site ID:	249284
Spill Date:	2004-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-04-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-21
Spill Record Last Update:	2004-07-06
Spiller Name:	LARRY HANSEN
Spiller Company:	BLESSED SACRAMENT HIGH SC
Spiller Address:	24 SHEA PLACE
Spiller County:	001
Spiller Contact:	LARRY HANSEN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 07/06/04 TANK PASSED RETEST."
Remarks: "FAILED SUBLINGS RECOMMEND UNCOVER REPAIR & RETEST OR REMOVE: "

All TTF:
Facility ID: 0400709
Spill Number: 0400709
Spill Tank Test: 1529181
Site ID: 249284
Tank Number: 1
Tank Size: 5000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 249284
Operable Unit ID: 884909
Operable Unit: 01
Material ID: 491955
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AX330 **BLESSED SACRAMENT CHURCH** **NY LTANKS** **S100165619**
SSE **SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.308 mi.
1628 ft. **Site 1 of 3 in cluster AX**

Relative:
Higher

Actual:
91 ft.

LTANKS:
Name: BLESSED SACRAMENT CHURCH
Address: SHEA PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 8704259 / 1987-11-20
Facility ID: 8704259
Site ID: 324974
Spill Date: 1987-08-02
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 1987-11-20
SWIS: 6010
Investigator: UNASSIGNED

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

Referred To:	Not reported
Reported to Dept:	1987-08-02
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-30
Spill Record Last Update:	1987-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261780
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST. / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST RETEST PASSED.NFA. "
Remarks:	"TTTF-TWO TANKS FAILED"

All TTF:

Facility ID:	8704259
Spill Number:	8704259
Spill Tank Test:	1531452
Site ID:	324974
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	324974
Operable Unit ID:	908133
Operable Unit:	01
Material ID:	466902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

Oxygenate: Not reported

---

331 West 1/4-1/2 0.311 mi. 1642 ft. **FRANKA INC.** **132-143 UNION AVE.** **NEW ROCHELLE, NY** **NY LTANKS** **S104276153** **N/A**

Relative: Higher

Actual: 90 ft.

LTANKS:

Name:	FRANKA INC.
Address:	132-143 UNION AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9312205 / 1995-11-09
Facility ID:	9312205
Site ID:	176106
Spill Date:	1994-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-11-09
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1995-11-08
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-24
Spill Record Last Update:	1995-11-27
Spiller Name:	Not reported
Spiller Company:	REGENT OIL CO.
Spiller Address:	53 CHARLES STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148008
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/95 FINAL INSPECTION PERFORMED TRENCH IS OIL FREE SUMP PIT IS OIL FREE BASEMENT IS FREE OF PETROLEUM NO OIL STAIN ON SIDEWALK"
Remarks:	"1K TANK UNDERGROUND POSSIBLE LEAK CLEAN UP CREW ENROUTE"

All Materials:

Site ID:	176106
Operable Unit ID:	994225
Operable Unit:	01
Material ID:	391197
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

FRANKA INC. (Continued) **S104276153**

Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY332 **PROFESSIONAL BUILDING COP** **NY LTANKS** **S108982494**
SSW **421 HUGUENOT STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.311 mi.
1642 ft. **Site 1 of 2 in cluster AY**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	PROFESSIONAL OFFICE CORP
Address:	421 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606014 / 2007-01-29
Facility ID:	0606014
Site ID:	369299
Spill Date:	2006-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-08-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-24
Spill Record Last Update:	2007-01-29
Spiller Name:	GERRI SEENY
Spiller Company:	PROFESSIONAL OFFICE CORP
Spiller Address:	421 HUGUENOT STREET
Spiller County:	001
Spiller Contact:	GERRI SEENY
Spiller Phone:	(914) 632-3400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	319185
DEC Memo:	"RECOMMENDING ISOLATION. 0606014 - 421 Huguenot St, New Rochelle - removed petrometer and remote fill from system and retested, passed. NFA. 10/23/06 test date"
Remarks:	""

All TTF:

Facility ID:	0606014
Spill Number:	0606014
Spill Tank Test:	1550220
Site ID:	369299

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	369299
Operable Unit ID:	1127138
Operable Unit:	01
Material ID:	2116724
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	PROFESSIONAL BUILDING COP
Address:	421 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0711337 / 2008-06-24
Facility ID:	0711337
Facility Type:	ER
DER Facility ID:	319185
Site ID:	392804
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-01-28
Investigator:	WCHD
Referred To:	SCHNEIDER
Reported to Dept:	2008-01-28
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0

PROFESSIONAL BUILDING COP (Continued) **S108982494**

Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2008-06-24
Spiller Name:	GERRY
Spiller Company:	PROFESSIONAL BUILDING COP
Spiller Address:	421 HUGUENOT STREET
Spiller Company:	001
Contact Name:	GERRY
DEC Memo:	"Spoke to Gerry. Danielle Jackson of WCHD may be handling. WCHD to inspect today. 06/24/08 Wayne Schneider WCHD reported 421 Huguenot St, New Rochelle - leaking tank. Contaminated soil remediated. See attached NFA TG "
Remarks:	"HOLES AND CONTAMINATED SOIL"

All TTF:

Facility ID:	0711337
Spill Number:	0711337
Spill Tank Test:	2384563
Site ID:	392804
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	392804
Operable Unit ID:	1149789
Operable Unit:	01
Material ID:	2140347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX333 **FAILED TANK TEST** **NY LTANKS** **S114561821**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.312 mi.
1650 ft. **Site 2 of 3 in cluster AX**

Relative: **Higher**
Actual: **89 ft.**

LTANKS:

Name:	FAILED TANK TEST
Address:	156 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1308221 / 2019-08-14

FAILED TANK TEST (Continued) **S114561821**

Facility ID:	1308221
Site ID:	488939
Spill Date:	2013-11-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2013-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-12
Spill Record Last Update:	2019-08-14
Spiller Name:	WILLIE
Spiller Company:	FAILED TANK TEST
Spiller Address:	156 CENTRE AVE
Spiller County:	999
Spiller Contact:	WILLIE
Spiller Phone:	(914) 774-2508
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	"11/12/13: Residential tank test failure. No indication of a release at this time. Message sent to Elite requesting additional information on the owner, or their realtor. jod 11/12/13: Update received from Chris Lalak. This is not a residential tank. This is a 10K #4 Oil tank, PBS 3-600412. Wayne Schneider will follow up on retest. jod 11-13-18 new management co looking for closure; submitted test from 2013- RDB 11-13-18 I asked WCHD for information. RDB 11-15-18 I requested annual tightness tests, they are not able to provide; RDB 11-19-18 I asked when tank will be removed. RDB 11-19-18 email from WCHD- No work permit application has come in. RDB 1/23/19: I spoke to Ray Hilyer at Elite Environmental. Timeline of events: *Nov 2013 tank fails tightness test performed by Elite, Spill 1308221 reported. *2016 Elite is called back to the site to retest. The parking lot or the tank had been patched, another company had excavated and repiped the UST. Tank is retested and passes. Test results sent to WCDOH. *2017 Tank is retested and passes. *Nov 2018 a new owner (management company) Librett Real Estate Group becomes involved with refinancing the property. In order to refinance the open Spill 1308221 needs to be addressed. Elite Environmental is contacted to remove the 10k gallon UST. *Dec2018 the UST is removed, soil contamination is extensive. Spill 180 Elite reports the contamination appears to be older and weathered #4 oil. To date they have excavated approximately 300 tons. jod 8/14/19: The cleanup has been completed by Elite. Closure report for the site was submitted to the Westchester Health Dept. See Spill 1809754 for further information and a scanned copy of the TCR. NFA this spill case number. jod"
Remarks:	"Tank test failure"

FAILED TANK TEST (Continued) **S114561821**

All TTF:

Facility ID:	1308221
Spill Number:	1308221
Spill Tank Test:	2494704
Site ID:	488939
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	488939
Operable Unit ID:	1238546
Operable Unit:	01
Material ID:	2238468
Material Code:	9999
Material Name:	other - failed tank test
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AX334 **APARTMENT HOUSE** **NY LTANKS** **S106385339**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.312 mi.
1650 ft. **Site 3 of 3 in cluster AX**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	APARTMENT HOUSE
Address:	156 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0312650 / 2004-04-22
Facility ID:	0312650
Site ID:	267104
Spill Date:	2004-02-13
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	2004-02-13
CID:	406

APARTMENT HOUSE (Continued) **S106385339**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-13
Spill Record Last Update:	2019-01-02
Spiller Name:	JIM DONELAN
Spiller Company:	PROTEST
Spiller Address:	PO BOX 1937
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 698-4100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	" 04/22/04 TANK PASSED A RETEST ON 3-22-04. NFA jod"
Remarks:	"Failed tank test"

All TTF:

Facility ID:	0312650
Spill Number:	0312650
Spill Tank Test:	1528979
Site ID:	267104
Tank Number:	1
Tank Size:	10000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AR335 **A D VANDROFF** **NY LTANKS S102241692**
South **47 MAPLE AVENUE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.313 mi.
1655 ft. **Site 2 of 2 in cluster AR**

Relative:
Higher

Actual:
88 ft.

LTANKS:

Name:	A D VANDROFF
Address:	47 MAPLE AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9603128 / 1996-06-14
Facility ID:	9603128
Site ID:	178537
Spill Date:	1996-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3

A D VANDROFF (Continued) **S102241692**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-05
Spill Record Last Update:	1996-09-04
Spiller Name:	A D VANDROFF
Spiller Company:	A D VANDROFF
Spiller Address:	47 MAPLE AVENUE
Spiller County:	001
Spiller Contact:	A D VANDROFF
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/14/96 SEE SPILL # 9603064"
Remarks:	"gross failure of tank."

SPILLS:

Name:	APT. BUILDING
Address:	47 MAPLE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9603064 / 1996-08-12
Facility ID:	9603064
Facility Type:	ER
DER Facility ID:	248269
Site ID:	307417
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1996-06-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-04
CID:	349
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-06-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-04
Spill Record Last Update:	1996-10-21

A D VANDROFF (Continued) **S102241692**

Spiller Name:	OWNER - ARTHUR DANDROFF
Spiller Company:	Not reported
Spiller Address:	47 MAPLE AV
Spiller Company:	001
Contact Name:	OWNER - ARTHUR DANDROFF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/04/96 WCHD TO INSPECT 06/14/96 SEE SPILL # 9603128 08/12/96 CONTENTS GONE IN FOUR DAYS AFTER FILL UP TANK REMOVED LINES TESTED NO LEAKS FOUND FROM TESTS SMALL HOLES FOUND IN TANKS VERY MINIMAL CONTAMINATION "
Remarks:	"APARTMENT BLDG - SUPERINTENDENT MRS CHURCHILL 914-636-4142 - RECIEVED 900 GALLONS ON THURSDAY - NOW ITS IS EMPTY - CHECK OF AREA INCLUDING SEWERS NO ODOR - FD ON SCENE - WILL BE TESTING W/WATER - TEMP. TANK TO BE PUT IN"

All Materials:

Site ID:	307417
Operable Unit ID:	1030609
Operable Unit:	01
Material ID:	349302
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT336 **DIPASQUALE PROPERTY** **NY LTANKS** **S111063882**
North **400 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.317 mi.
1673 ft. **Site 5 of 5 in cluster AT**

Relative:
Lower

Actual:
70 ft.

LTANKS:

Name:	DIPASQUALE PROPERTY
Address:	400 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1103122 / 2012-04-26
Facility ID:	1103122
Site ID:	450672
Spill Date:	2011-06-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

DIPASQUALE PROPERTY (Continued) **S111063882**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-20
Spill Record Last Update:	2012-04-26
Spiller Name:	MR CHARLIE DIPASQUALE
Spiller Company:	NDR GROUP
Spiller Address:	400 NORTH AVE
Spiller County:	999
Spiller Contact:	MR DIPASQUALE
Spiller Phone:	(914) 633-7092
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	404310
DEC Memo:	"6/20/11: This spill initially reported as a residential TTF. Property is actually a commercial office building with apartments on the second floor. Previous Spill number for this site is 1102214 which was reported on May 27th. Owner informed US Tank Tech of the prior Phase I site investigation, but apparently did not inform them of the Phase II which found high levels of contamination. US Tank Tech reports they were hired to test the in-service 550 gallon heating oil tank, and perform a site investigation to locate a second, out-of-service tank. The 550 failed the vaccuum test, petroleum odors evident in the well point. US Tank Tech also reports they believe the second out-of-service tank may be located under the office building. Owner states the second tank is a 275 gallon heating oil, but that can not be confirmed at this time. US Tank Tech also reports there are at least two additional sets of fill and vent pipes, for other out-of-service or abandoned USTs. Tester also noted petroleum odors from the basement sump pit. jod 6/21/11: US Tank Tech reported that the owner says he hired Northeast Environmental to address these two spills issues. Message sent to Northeast asking for confirmation. jod 9/29/11: Northeast reports the owner has hired them to begin investigation and remediation. jod 10/21/11: The UST has been removed by Northeast and contaminated soil is evident. Remediation work is being scheduled. jod 4/26/2012: Closure report from Northeast Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"
Remarks:	"repair/retest pending"

All Materials:

Site ID:	450672
Operable Unit ID:	1200876
Operable Unit:	01
Material ID:	2197327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AS337 **60-70 OWNERS CORP** **NY LTANKS** **S105140483**
ESE **60-70 LOCUST AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1681 ft. **Site 4 of 6 in cluster AS**

Relative: **Higher**
Actual: **89 ft.**

LTANKS:

Name:	60-70 OWNERS CORP
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1802312 / 2018-10-17
Facility ID:	1802312
Site ID:	570894
Spill Date:	2018-05-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2018-05-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-05-29
Spill Record Last Update:	2018-11-08
Spiller Name:	NANETTE GIORDANO
Spiller Company:	60-70 OWNERS CORP
Spiller Address:	ARCHER PROPERTY MANAGEMENT
Spiller County:	001
Spiller Contact:	NANETTE GIORDANO
Spiller Phone:	914-315-6105
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"5/29/18 Property has 2 8000 gallon UST, not in use. Both tanks had been for #6 fuel oil, were cleaned out, Tank 1 (in building #70) was filled with #2 oil, Tank 2 was left empty (in building #60). Tank 2 now has 28 inches of water in it. Northeast Environmental has been called and will be on site tomorrow. Property has converted to gas. It's an apartment building. ga 6/12/18 received call from Nanette, indicating that she was waiting for board approval to remove one of the tanks. Tank #1 is being repaired and retested, Tank #2 is being removed. BW 7/17/18 - G C Engineering will be submitted tank removal notification to the WCDOH and DEC. A TCR will be submitted to both the WCDOH and DEC. KAB 7-23-18 G C sent email to Carlos and cc'd me. It talks about their plans with remediation. Forwarded to KB. jc 08-09-18 Site visit during soil remediation. Approx. 120 cu. yards removed from the site. There is fuel oil contamination about 12 feet down. G.C. Environmental claimed they excavated to bed rock but the recent heavy rain washed soil back in. They were dewatering at the time to continue excavating. BTR 10/17/18 - G.C. Environmental, Inc. conduct conducted removal liquid and sludge, two 8K USTs,

60-70 OWNERS CORP (Continued) **S105140483**

contaminated soils and collected soil samples. A vac truck used to remove 8,772 gal. liquid waste and sludge from the tanks and was disposed at Clean Water Of New York, Inc., NY. 884.7 tons of contaminated soils was removed and disposed at Clean Earth of Carteret, NJ. One excavation was generated to remove the two 8K USTs. 23 sidewalls and bottom soil samples were collected and laboratory analyzed. 13 soil sample results showed VOCs and SVOCs in the low ppb range, well below the NYS soil guidelines. There are no significant impacts from the tank. NFA. KAB"

Remarks: "tank test failure"

All Materials:

Site ID:	570894
Operable Unit ID:	1318738
Operable Unit:	01
Material ID:	2326671
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	60-70 OWNERS CORP
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0900729 / 2009-07-24
Facility ID:	0900729
Facility Type:	ER
DER Facility ID:	142314
Site ID:	412683
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-04-20
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-20
Spill Record Last Update:	2009-07-24
Spiller Name:	AILEEN DEMARIA
Spiller Company:	ARCHER PROPERTY MANAGEMENT

60-70 OWNERS CORP (Continued) **S105140483**

Spiller Address:	60-70 LOCUST AVE
Spiller Company:	999
Contact Name:	NIKKI RICKETTES
DEC Memo:	"NE ENV. CLEANING UP. REPORT TO BE SUBMITTED. DT 07/22/09 Northeast Environmental reported that they excavated and removed and replaced the removed fill lines. a total of 35.80 tons of petroleum impacted soil was excavated and disposed. NFA TG"
Remarks:	"WHILE REPLACING THE REMOTE FILL LINES, PRODUCT WAS FOUND IN SOIL. CLEAN UP IS IN PROGRESS."

All Materials:

Site ID:	412683
Operable Unit ID:	1169142
Operable Unit:	01
Material ID:	2160789
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	412683
Operable Unit ID:	1169142
Operable Unit:	01
Material ID:	2160788
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	SPILL NUMBER 0105779
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0105779 / 2002-11-08
Facility ID:	0105779
Facility Type:	ER
DER Facility ID:	142314
Site ID:	168987
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C6
SWIS:	6010
Spill Date:	2001-08-27
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-08-29
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department

60-70 OWNERS CORP (Continued) **S105140483**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-29
Spill Record Last Update:	2003-02-25
Spiller Name:	FREDERICK BECK
Spiller Company:	Not reported
Spiller Address:	60-70 LOCUST AVE
Spiller Company:	001
Contact Name:	FREDERICK BECK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 08/29/2001 WCDOH ON SITE."
Remarks:	"info to caller that there is a pit at the location filled w/oil and w/heavy rain it overflows onto street"

All Materials:

Site ID:	168987
Operable Unit ID:	844138
Operable Unit:	01
Material ID:	530670
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AS338 **APARTMENT BUILDING** **NY LTANKS** **S118707739**
ESE **60-70 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1681 ft. **Site 5 of 6 in cluster AS**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1602555 / 2018-06-26
Facility ID:	1602555
Site ID:	528964
Spill Date:	2016-06-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2016-06-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

APARTMENT BUILDING (Continued) **S118707739**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-06-13
Spill Record Last Update:	2018-06-26
Spiller Name:	ROB HILL
Spiller Company:	Apartment
Spiller Address:	60-70 LOCUST AVE
Spiller County:	999
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 855-7272
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"6/13/16 - To be handle by the Westchester County DOH under PBS. KAB Email from Chris Lalak: Keith, TTF at a PBS SITE. 60-70 Locust 3-413925 8k #6 oil tank UST from 1954 Chris 6/26/18: As per Chris Lalak, of WCDoH: I see notes in our log. It was a Wayne Schneider and Carlos Torres spill case. And it was sent to close in 2016 . This UST currently being removed by Northeast Environmental. See Spill 1803271 for further info. NFA this spill number. jod"
Remarks:	"8,000 gallon tank failed tank test."

All Materials:

Site ID:	528964
Operable Unit ID:	1277806
Operable Unit:	01
Material ID:	2282672
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AS339 **COMMERCIAL USTS** **NY LTANKS** **S122481715**
ESE **60-70 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1681 ft. **Site 6 of 6 in cluster AS**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	COMMERCIAL USTS
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1803271 / 2018-12-06
Facility ID:	1803271
Site ID:	571898
Spill Date:	2018-06-25
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported

COMMERCIAL USTS (Continued) **S122481715**

SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2018-06-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-06-25
Spill Record Last Update:	2018-12-06
Spiller Name:	Not reported
Spiller Company:	NANETTE DIORDANO
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NANETTE DIORDANO
Spiller Phone:	(914) 315-6105
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"6/25/18 spoke with Cathy Morgan of US Tank. At the end of May they tested Tank #170 and Tank #260, both 8K #2 fuel oil USTs, and both failed. Tank #260 was planned on being removed and Tank #170 was being retested. Tank #170 failed the retest today. Northeast Environmental is completing the repairs and removal of the tanks, BW 6/26/18: Update from Chris Lalak at WCDoH: Isolation test failed. Facility asked to empty the tank immediately. NEE is already on the job. 8000 UST with about 2000 gallon in it. The facility is currently using Natural gas for Heat/hotwater. Second 8k (out of service) on site to be removed by NEE. Property mgmt Nanette Giordano Archer Mgmt 914-315-6105 jod 12/06/18: Closure report for this site was submitted under Spill 1802312. Remediation has been completed, no further action is required at this time. jod"
Remarks:	"8000 gallons pbs #3-413925 tank test failure"

All Materials:

Site ID:	571898
Operable Unit ID:	1319717
Operable Unit:	01
Material ID:	2327762
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AW340
SW
1/4-1/2
0.320 mi.
1691 ft.

Relative:
Lower

Actual:
49 ft.

BAKERS PRIDE OVEN CO INC
30 PINE ST.
NEW ROCHELLE, NY 10801

Site 3 of 4 in cluster AW

Database(s): RCRA-LQG, NY SHWS, NY Spills, FINDS, ECHO, NY MANIFEST, NJ MANIFEST

EDR ID Number: 1004571492
EPA ID Number: NYD986925808

RCRA-LQG:

Date form received by agency:	2012-06-27 00:00:00.0
Facility name:	INDUSTRIAL OVERALL SERVICES FORMER
Facility address:	30 PINE ST NEW ROCHELLE, NY 10805
EPA ID:	NYD986925808
Mailing address:	PINE ST NEW ROCHELLE, NY 10805
Contact:	BURT DORFMAN
Contact address:	BARTELS AVE NEW ROCHELLE, NY 10801
Contact country:	US
Contact telephone:	845-353-3500
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NYS DEPT ENVIRONMENTAL CONSERVATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	2011-12-13 00:00:00.
Owner/Op end date:	Not reported

Owner/operator name:	INDUSTRIAL OVERALL SERVICE CORP
Owner/operator address:	BARTELS AVE NEW ROCHELLE, NY 10801
Owner/operator country:	US
Owner/operator telephone:	845-353-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 2010-08-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2008-12-16 00:00:00.0
Site name: BAKERS PRIDE OVEN
Classification: Small Quantity Generator

Date form received by agency: 2007-01-01 00:00:00.0
Site name: BAKERS PRIDE OVEN CO INC
Classification: Small Quantity Generator

Date form received by agency: 2006-01-01 00:00:00.0
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 1994-05-12 00:00:00.0
Site name: BAKERS PRIDE OVEN CO INC
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 2012-06-14 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SHWS:
Name: BAKER'S PRIDE OVEN
Address: 30 PINE STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Program: HW
Site Code: 355304
Classification: Not reported
Region: 3
Acres: 3.75
HW Code: 360087
Record Add: 11/08/2005
Record Upd: 07/21/2009
Updated By: RXKEATIN
Site Description: The Baker?s Pride site is located at 30 Pine Street in the City of New Rochelle, Westchester County, NY. The surrounding area is urban with commercial and residential establishments mixed in between the commercial businesses. The Baker?s Pride site is an approximately 3.75 acre flat to severely sloping irregularly shaped parcel. The Baker?s Pride building occupies approximately 111,450 sf of building space and occupies the majority of the property. Baker?s Pride owns the Bakers Pride Oven Company Inc and is engaged in the production of restaurant/commercial grade ovens and broilers. The site is bordered by Metro North railroad tracks to the west and northwest, a mix of commercial and residential properties to the northeast, east, and south. Interstate (I-95) is located to the west of the Metro North railroad tracks. In 2005, a Phase II Environmental Assessment report was completed by Enercon as part of closure proceedings for a 3,000 gallon fuel oil UST that was closed in place and a 10,000 gallon fuel oil UST that was removed. Monitoring wells installed as part of this assessment revealed the presence of PCE in groundwater at levels up to 1,430 ppb. (The State groundwater standard for PCE is 5 ppb.) Also, this report noted chemical storage for cutting oils, lubricants, solvents and paints. No products were indicated that contained PCE. In 2007 a follow up report was conducted which revealed PCE in groundwater at levels up to 1,700 ppb. The site was added as a potential inactive hazardous waste disposal site ("P site") in 2007. A State funded site characterization was initiated in 2008 to determine the source of the PCE groundwater

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

plume. A total of 9 monitoring wells were installed in the fall of 2008. Groundwater contaminated with PCE showed higher levels of PCE in wells upgradient from the Baker?s Pride facility. The PCE concentrations were as high as 3,700 ppb in MW-13 which is located about 300 feet upgradient from the Baker?s Pride facility. This prompted the State to do a second round of groundwater sampling further upgradient of MW-13. Two additional wells (MW-24 and MW-25) were installed about 150 feet upgradient of MW-13 in the winter of 2009. MW-24 revealed PCE at 5,300 ppb. The second round of sampling further defined a groundwater plume with a source area upgradient from the Bakers Pride site. Since the site information for Baker?s Pride indicates that the plume of PCE is coming from an off-site source, the Baker?s Pride site (360087) will not be listed in the Registry of Inactive Hazardous Waste Disposal sites. A separate site was added to the Registry to address the source of the PCE plume (See site #360109.)

Env Problem: Based upon investigations to date, the primary contaminants of concern at the site include tetrachloroetylene (PCE) and its associated breakdown products. PCE was detected in upgradient groundwater as well as on-site and also in indoor air in residences upgradient of the site. PCE was detected on-site in groundwater from non-detect up to 3,200 parts per billion (ppb) at MW-1) above the respective groundwater standard of 5 ppb. Upgradient off-site levels of PCE were as high as 5,300 ppb. Indoor air was impacted in two residences with the highest level being 530 micrograms per cubic meter (ug/m3) at a property on Bartels Place. Since the highest levels of PCE were identified in the groundwater upgradient of the site this suggests an off-site source that is impacting the Baker?s Pride site. The source of this contamination is the Industrial Overall Service Corp. Class 2 site (#360109)

Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

SPILLS:

Name:	BAKERS PRIDE OVEN CO
Address:	30 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9404759 / 2003-10-08
Facility ID:	9404759
Facility Type:	ER
DER Facility ID:	122872
Site ID:	144128
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	1994-07-07
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1994-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-11
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 10/17/03: Letter to Mark Fogarty, Baker's Pride from Danielle Jackson, dated 10/8/2003. Closure report by Env. Products & Services and sample results have been reviewed. While there is some contamination remaining, WCDOH does not see the contamination as a risk to human health. WCDOH recommends NFA at this time."
Remarks:	"SOIL STOCKPILED BOB SPERONI WAS ON SITE FAXED TO TARRYTOWN & WCHD"

All Materials:

Site ID:	144128
Operable Unit ID:	1001834
Operable Unit:	01
Material ID:	381361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:
Registry ID: 110002092949

Click Here:

Environmental Interest/Information System:
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004571492
Registry ID:	110002092949
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002092949
Name:	BAKERS PRIDE OVEN CO INC
Address:	30 PINE ST.
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	INDUSTIRAL OVERALL UNIFORM
Address:	30 PINE ST
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD986925808
Facility Status:	Not reported
Location Address 1:	30 PINE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:
EPAID: NYD986925808

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Mailing Name:	INDUSTIRAL OVERALL UNIFORM
Mailing Contact:	IRA NEVIN
Mailing Address 1:	30 PINE ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5184029564

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/28/2012
Trans1 Recv Date:	12/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008923493JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1800
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD986925808
Mail Address:	30 PINE ST
Mail City/State/Zip:	NEW ROCHELLE 10801
Facility Phone:	9145760200
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008921150JJK
EPA ID:	NYD986925808
Date Shipped:	7/2/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,815.00 gallons
Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,200.00 Pounds
Manifest Number:	008923493JJK
EPA ID:	NYD986925808
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F001 F002
Hand Code: Not reported
Quantity: 1,800.00 Pounds

Manifest Number: 008923039JJK
EPA ID: NYD986925808
Date Shipped: 7/31/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW ROCHELLE 10801
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F001 F002
Hand Code: Not reported
Quantity: 150.00 Pounds

Manifest Number: NJA4033255

BAKERS PRIDE OVEN CO INC (Continued) **1004571492**

EPA ID:	NYD986925808
Date Shipped:	04/02/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/02/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030425
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

---

341 **SPILL 0106072 / PBS 3-800919** **NY LTANKS** **S105135128**
ENE **370 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.326 mi.
1719 ft.

Relative: LTANKS:
Lower

Name:	SPILL 0106072 / PBS 3-800919
Address:	370 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0106072 / 2001-11-13
Facility ID:	0106072
Site ID:	133647
Spill Date:	2001-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

Actual:
57 ft.

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2014-08-15
Spiller Name:	STEVEN WOODS
Spiller Company:	Monroe College
Spiller Address:	370 MAIN ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114844
DEC Memo:	"09/07/2001 PROPERTY FOR SALE. TANK TESTED BY POTENTIAL BUYER. SELLER TO REMOVE OR RETEST. 11/13/2001 TANK PASSED A RETEST AFTER REFIT. NO FURTHER ACTION. 8/15/14: Hard copy file pulled for FOIL. File scanned to PDF, will wiil entered into DecDocs. Paper file discarded. NOTE: WCDoH PBS records indicate this UST was Closed - in place and the site listed as Unregulated 7/30/2002. jod"
Remarks:	"will fill tank with sand and abandoned it"

All TTF:

Facility ID:	0106072
Spill Number:	0106072
Spill Tank Test:	2495803
Site ID:	133647
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	04
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	133647
Operable Unit ID:	844476
Operable Unit:	01
Material ID:	530955

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

342
ESE
1/4-1/2
0.326 mi.
1720 ft.

APARTMENT BUILDING
67-70 LOCUST AVE
NEW ROCHELLE, NY

NY LTANKS **S110611357**
N/A

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	67-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1008207 / 2011-03-10
Facility ID:	1008207
Site ID:	441682
Spill Date:	2010-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-04
Spill Record Last Update:	2011-03-10
Spiller Name:	ABRAHAM WATHCELL
Spiller Company:	UNKNOWN
Spiller Address:	67- 70 LOCUST AVE
Spiller County:	999
Spiller Contact:	ABRAHAM WATHCELL
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396710
DEC Memo:	"Left message for callback. DT 11/4/10 11/5/10: Call back from Abraham Wathcell of NY Tank Testing to dispatch desk. This was a test failure of an 8K heating oil tank at a co-op. PBS #3-413925 will handled by WCDOH. Mr Wathcell stated he had discussed the results with the management compny and was recommending removal of the tank rather than retest. jod 3/10/11 As per WCDOH eplaced fill pipe, manway gasket and repaired gauge. Passed retest on 2/14/11. NFA JO'M "

APARTMENT BUILDING (Continued) **S110611357**

Not reported
Remarks: ""

All TTF:
Facility ID: 1008207
Spill Number: 1008207
Spill Tank Test: 2489743
Site ID: 441682
Tank Number: 1
Tank Size: 8000
Material: 0003
EPA UST: False
UST: True
Cause: 00
Source: 99
Test Method: 21
Test Method 2: Horner EZY3/EZY3 Locator Plus
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: jbodee
Last Modified Date: Not reported

All Materials:
Site ID: 441682
Operable Unit ID: 1192229
Operable Unit: 01
Material ID: 2187465
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AZ343 **BUSINESS** **NY LTANKS** **S101341432**
WSW **88 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.331 mi.
1750 ft. **Site 1 of 2 in cluster AZ**

Relative:
Higher

Actual:
89 ft.

LTANKS:
Name: BUSINESS
Address: 88 GROVE AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9411669 / 2010-04-28
Facility ID: 9411669
Site ID: 172950
Spill Date: 1994-12-01
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: tdghiosa
Referred To: Not reported

BUSINESS (Continued) **S101341432**

Reported to Dept:	1994-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	MR. OGMAN
Spiller Address:	88 GROVE AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	145542
DEC Memo:	"4/28/10 16 year old TTF No further info NFA JO'M "
Remarks:	"WILL EXPLORE IT NEXT"

All TTF:

Facility ID:	9411669
Spill Number:	9411669
Spill Tank Test:	1543408
Site ID:	172950
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	172950
Operable Unit ID:	1005375
Operable Unit:	01
Material ID:	374006
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AZ344 **COMMERCIAL BUILDING** **NY LTANKS** **S104276178**
WSW **88-90 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.331 mi.
1750 ft. **Site 2 of 2 in cluster AZ**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	88-90 GROVE AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9411598 / 2010-04-28
Facility ID:	9411598
Site ID:	113133
Spill Date:	1994-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	98741
DEC Memo:	"4/28/10 16 year old TTF NFA JO'M"
Remarks:	"TANK TEST FAILURE PETRO-TITE II VISUAL"

All TTF:

Facility ID:	9411598
Spill Number:	9411598
Spill Tank Test:	1543402
Site ID:	113133
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

COMMERCIAL BUILDING (Continued) **S104276178**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 113133
Operable Unit ID: 1005335
Operable Unit: 01
Material ID: 373942
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

---

345 WNW 1/4-1/2 0.334 mi. 1764 ft. **KLING** **NY LTANKS S106124350**
108 VAN GUILDER AVE **NY Spills N/A**
NEW ROCHELLE, NY

Relative: Lower
Actual: 77 ft.

LTANKS:
Name: KLING
Address: 108 VAN GUILDER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0308565 / 2005-02-12
Facility ID: 0308565
Site ID: 214235
Spill Date: 2003-11-13
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-11-13
CID: 199
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-11-13
Spill Record Last Update: 2005-02-12
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: RICHARD KLING
Spiller Phone: (914) 636-0076
Spiller Extention: Not reported

KLING (Continued) **S106124350**

DEC Region: 3
DER Facility ID: 177496
DEC Memo: "03/24/04 TANK IS IN A CRAWL SPACE UNDER THE FOUNDATION AND CANNOT BE REMOVED. ROYAL ENVIRONMENTAL INSPECTED TANK AND FOUND NO EVIDENCE OF CONTAMINATION. ROYAL INSTALLED A NEW 275 AST BUT HAS NOT YET PUT THAT TANK IN SERVICE, AWAITING INSPECTION FROM NEW ROCHELLE FIRE DEPT. ONCE AST IS IN SERVICE, ROYAL IS TO CUT AND CLEAN 550 UST AND OBTAIN A SOIL SAMPLE FROM BENEATH TANK. SAMPLE RESULTS TO BE FORWARDED TO DEC. ADDITIONAL SPILL NUMBERS CALLED IN: 03-13745 AND 03-14031. jbo"
Remarks: "uncover / repair / retest"

All TTF:
Facility ID: 0308565
Spill Number: 0308565
Spill Tank Test: 1528806
Site ID: 214235
Tank Number: 1
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 214235
Operable Unit ID: 874811
Operable Unit: 01
Material ID: 502049
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: ANON
Address: 108 VAN GUILDER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0313745 / 2004-03-24
Facility ID: 0313745
Facility Type: ER
DER Facility ID: 177496
Site ID: 214236
DEC Region: 3
Spill Cause: Unknown
Spill Class: E5

KLING (Continued) **S106124350**

SWIS:	6010
Spill Date:	2004-03-16
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2005-02-12
Spiller Name:	DR RICHARD KLEIN
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	DR RICHARD KLEIN
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo"
Remarks:	"CALLER STATES THAT THERE IS A VERY STRONG ODOR AT THE DOCTOR'S OFFICE AND SHE CAN SMELL IT AT HER HOME. SOMETIMES ODOR IS VERY OVERWELMING: A LARGE CONTAINER IS IN THE BACK YARD OF DOCTOR'S OFFICE: SHE JUST WANTED SOMEONE TO CHECK OUT: *****UPDATE***** SHE CALLED BACK AND SAID THAT SOMEONE TOLD HER THAT A COMPANY CAME IN A CHECKED IT OUT- ROYAL IN PELHAM NY*"

All Materials:

Site ID:	214236
Operable Unit ID:	879034
Operable Unit:	01
Material ID:	495337
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0314031
Address:	108 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0314031 / 2004-03-24
Facility ID:	0314031
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214237
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	6010
Spill Date:	2004-03-24

KLING (Continued) **S106124350**

Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-24
CID:	407
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-24
Spill Record Last Update:	2005-02-12
Spiller Name:	RICHARD KLING MD
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	RICHARD KLING MD
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo 03/30/04 SITE INSPECTED BY STEFAN GOREAU OF WCHD. jbo"
Remarks:	"unknown if spill, caller refused to give name, detected odor of gas/oil from neighbors building, renovation ongoing at building, caller believed odor was related to work."

All Materials:

Site ID:	214237
Operable Unit ID:	880985
Operable Unit:	01
Material ID:	495617
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA346 **COMMERICAL BUILDING** **NY LTANKS** **S122878510**
North **405 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.334 mi.
1765 ft. **Site 1 of 3 in cluster BA**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	COMMERICAL BUILDING
Address:	405 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1805047 / 2018-11-13
Facility ID:	1805047
Site ID:	574752
Spill Date:	2018-08-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4

COMMERICAL BUILDING (Continued) **S122878510**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2018-08-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-08-09
Spill Record Last Update:	2018-11-13
Spiller Name:	Not reported
Spiller Company:	HAYCO MANAGEMENT COMPANY
Spiller Address:	405 NORTH AVE
Spiller County:	001
Spiller Contact:	ABE WHSLER
Spiller Phone:	(646) 321-2876
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	527718
DEC Memo:	"8/9/18 tank test failure for 3000 gallon tank at an apartment building. Building is managed by Hayco Mgmt Co. Left message for Hayco to call duty desk. ga 11/13/18 - Westchester County DOH has informed the DEC the tank has passed the tank testing. NFA. KAB"
Remarks:	"caller extremely hard to understand"

All TTF:

Facility ID:	1805047
Spill Number:	1805047
Spill Tank Test:	2506324
Site ID:	574752
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	04
Test Method:	33
Test Method 2:	EZY 3
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	KABROWNE
Last Modified Date:	Not reported

All Materials:

Site ID:	574752
Operable Unit ID:	1322545
Operable Unit:	01
Material ID:	2330882
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

COMMERICAL BUILDING (Continued) **S122878510**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AW347 **PONSERELLA HOME** **NY LTANKS** **S106869214**
SW **20 PINE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.337 mi.
1779 ft. **Site 4 of 4 in cluster AW**

Relative:
Lower

Actual:
47 ft.

LTANKS:

Name:	BELIVE HOME
Address:	20 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0500819 / 2005-05-22
Facility ID:	0500819
Site ID:	343902
Spill Date:	2005-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2005-05-22
Spiller Name:	JOHN BELIVE
Spiller Company:	BELIVE HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOHN BELIVE
Spiller Phone:	(914) 253-8449
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"05/22/05 PREVIOUSLY REPORTED TTF IS 04-13182. NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 34.56 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 gallon , found holes and contaminated soil:"

All Materials:

Site ID:	343902
Operable Unit ID:	1102568
Operable Unit:	01

PONSERELLA HOME (Continued) **S106869214**

Material ID:	582785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PONSERELLA HOME
Address:	20 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413182 / 2005-05-22
Facility ID:	0413182
Site ID:	339043
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-22
Spiller Name:	JOE PONSERELLA
Spiller Company:	PONSERELLA HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOE PONSERELLA
Spiller Phone:	(914) 760-6684
Spiller Extention:	CELL
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"5/22/05 See spill 05-00819. NFA this number. jod"
Remarks:	""

All TTF:

Facility ID:	0413182
Spill Number:	0413182
Spill Tank Test:	1548700
Site ID:	339043
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported

PONSERELLA HOME (Continued) **S106869214**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	339043
Operable Unit ID:	1100961
Operable Unit:	01
Material ID:	581111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

348
NE
1/4-1/2
0.339 mi.
1791 ft.

CON EDISON-CEDAR ST WORKS-NEWROCH'LE MGP **EDR MGP** **1008407973**
ONE RAMADA PLAZA **N/A**
NEW ROCHELLE, NY 10801

Relative:
Lower

Actual:
50 ft.

Manufactured Gas Plants:
No additional information available

349
SE
1/4-1/2
0.340 mi.
1796 ft.

CHURCH OF LATTER DAY SAIN **NY LTANKS** **S106471932**
111 NORTH AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Name:	CHURCH OF LATTER DAY SAIN
Address:	111 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403126 / 2004-09-21
Facility ID:	0403126
Site ID:	266466
Spill Date:	2004-06-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported

CHURCH OF LATTER DAY SAIN (Continued) **S106471932**

Reported to Dept:	2004-06-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22
Spill Record Last Update:	2004-09-21
Spiller Name:	MATT SCHIEFERSTEIN
Spiller Company:	CHURCH OF LATTER DAY SAIN
Spiller Address:	111 NORTH AVE
Spiller County:	001
Spiller Contact:	MATT SCHIEFERSTEIN
Spiller Phone:	(631) 351-3555
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217081
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/23/04 APPROXIMATELY 200 TONS OF CONTAMINATED SOIL REMOVED. CLOSURE REPORT TO FOLLOW. jbo 09/21/04 ANSON ENVIRONMENTAL DISPOSED OF LUST AND 168.02 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"WHILE DIGGING A FOUNDATION FOUND A TANK: CONTAMINATED SOIL ALSO: "

All Materials:

Site ID:	266466
Operable Unit ID:	885085
Operable Unit:	01
Material ID:	490726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY350 **SPILL NUMBER 9908602** **NY LTANKS** **S104620556**
SSW **HUGUENOT ST & SOUTH PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.348 mi.
1836 ft. **Site 2 of 2 in cluster AY**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	SPILL NUMBER 9908602
Address:	HUGUENOT ST & SOUTH PLAZA
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908602 / 2000-09-14
Facility ID:	9908602
Site ID:	283271
Spill Date:	1999-10-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other

SPILL NUMBER 9908602 (Continued) **S104620556**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1999-10-15
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-10-15
Spill Record Last Update:	2000-09-26
Spiller Name:	CITY OF NEW ROCHELLE
Spiller Company:	Not reported
Spiller Address:	HUGUENOT ST
Spiller County:	001
Spiller Contact:	CITY OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229755
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 10/15/99 DELUXE TAXICAB SITE; TANKS HAD BEEN REMOVED BUT CONTAMINATED SOIL; SOIL BEING REMOVED--WILL SUBMIT REPORT. 12/09/99 LETTER SENT TO N. RECCHIA; MUST BETTER DEFINE THE EXTENT OF CONTAMINATION IN THE OVERBURDEN SOIL & GROUNDWATER 05/18/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; ADDITIONAL INVESTIGATION IS REQUIRED AT THIS SITE 09/14/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; BASED ON RESULTS REPORTED BY THE ENERGY & ENVIRONMENTAL ANLAYSISTS, INC. IN AUGUST 2000, THIS SPILL IS CLOSED. "
Remarks:	"VACANT LOT AND DURING EXCAVATION - CONTAMINATED SOIL FOUND"

All Materials:

Site ID:	283271
Operable Unit ID:	1087287
Operable Unit:	01
Material ID:	297711
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA351 **APARTMENT BLDG** **NY LTANKS** **S104515070**
North **1 THE BOULEVARD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.359 mi.
1894 ft. **Site 2 of 3 in cluster BA**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	1 THE BOULEVARD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9809315 / 1999-10-14
Facility ID:	9809315
Site ID:	303319
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-10-26
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	1999-11-22
Spiller Name:	ELJAK REALTY
Spiller Company:	APT BLDG
Spiller Address:	1 THE BLVD
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	245085
DEC Memo:	""
Remarks:	"EXCAVATE PIPING AND RETEST"

All TTF:

Facility ID:	9809315
Spill Number:	9809315
Spill Tank Test:	1546451
Site ID:	303319
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F

APARTMENT BLDG (Continued) **S104515070**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 303319
Operable Unit ID: 1070412
Operable Unit: 01
Material ID: 316775
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BA352 **PRIVATE DWELLING** **NY LTANKS** **S108765819**
NNW **19 ROCHELLE PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.362 mi.
1913 ft. **Site 3 of 3 in cluster BA**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:
Name: PRIVATE DWELLING
Address: 19 ROCHELLE PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0706958 / 2008-02-01
Facility ID: 0706958
Site ID: 387568
Spill Date: 2007-09-24
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2007-09-24
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-09-24
Spill Record Last Update: 2008-02-01
Spiller Name: ROLAND ANDRALOISKI
Spiller Company: Not reported
Spiller Address: 19 ROCHELLE PLACE
Spiller County: 001
Spiller Contact: ROLAND ANDRALOISKI
Spiller Phone: (914) 774-7362
Spiller Extention: Not reported

PRIVATE DWELLING (Continued) **S108765819**

DEC Region: 3
DER Facility ID: 336995
DEC Memo: "To uncover and retest. 12/05/08 Northeast Environmental reported that the tank was excavated and removed. Noe cotaminated soil was observed in the tank grave. TAGM soil sample results were below DEC guidance values. NFA. TG "
Remarks: ""

All TTF:
Facility ID: 0706958
Spill Number: 0706958
Spill Tank Test: 1764128
Site ID: 387568
Tank Number: 1
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 387568
Operable Unit ID: 1144768
Operable Unit: 01
Material ID: 2135078
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

---

353 **BUSINESS COMPLEX** **NY LTANKS** **S104516367**
SW **55 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.364 mi.
1921 ft.

Relative:
Lower

Actual:
53 ft.

LTANKS:
Name: BUSINESS COMPLEX
Address: 55 WEBSTER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9912136 / 2000-05-11
Facility ID: 9912136
Site ID: 86196
Spill Date: 2000-01-19
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial

BUSINESS COMPLEX (Continued) **S104516367**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2000-01-20
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2004-11-23
Spiller Name:	MR LIBERETT
Spiller Company:	BUSINESS COMPLEX
Spiller Address:	55 WEBSTER AVE
Spiller County:	001
Spiller Contact:	MR LIBERETT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79113
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/09/2000 ACCORDING TO MR. BOB ALERES PHASE 11 REPORT COMPLETED. WILL SUBMIT COPY TO T. GHIOSAY. 05/11/00 - Spill closure letter sent by J. O'Mara to: DL Rothberg & Associates PC 1350 Broadway Suite 1711 NY NY 10018 Attention Debra Rothberg, Esq"
Remarks:	"THEY REMOVED A 3,000 GALLON TANK AND PUT IN A NEW 1,000 GALLON TANK THEY SUSPECT THE 3,000 GALLON HAD LEAKED UNKNOWN MATERIAL INTO THE GROUND.THEY GOT THE LAB RESULTS BACK YESTERDAY.THEY SUSPECT IT MAY BE HEATING OIL BUT ARE NOT SURE."

All Materials:

Site ID:	86196
Operable Unit ID:	1086666
Operable Unit:	01
Material ID:	294030
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BB354 **I-95 EXIT 16** **NY LTANKS** **S102673537**
NNE **OPP. 111 CEDAR ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.366 mi.
1933 ft. **Site 1 of 2 in cluster BB**

Relative: **Lower**

Actual: **51 ft.**

LTANKS:

Name:	I-95 EXIT 16
Address:	OPP. 111 CEDAR ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9001240 / 1990-08-01
Facility ID:	9001240
Site ID:	244221
Spill Date:	1990-05-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1990-08-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	MIGOYA CONST. CO. ?
Spiller Address:	3520 DELAVAL AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	200593
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : N.F.A. 09/27/95: This is additional information about material spilled from the translation of the old spill file: POSS. WASTE OIL."
Remarks:	"DIESEL SPILLED WHILE FILLING HEAVY CONSTRUCTION EQUIPMENT ALSO APPEARSTHAT THEY HAVE CHANGED THEIR CRANKCASE OIL BY DRAINING ONTO GROUND A USED OIL FILTER WAS FOUND THERE ALSO"

All Materials:

Site ID:	244221
Operable Unit ID:	941067
Operable Unit:	01
Material ID:	439592
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G

I-95 EXIT 16 (Continued) **S102673537**

Recovered: .00
Oxygenate: Not reported

BB355 **PLASTIC WORKS** **NY LTANKS** **S103824027**
NNE **115 CEDAR ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.366 mi.
1934 ft. **Site 2 of 2 in cluster BB**

Relative: **Lower**
Actual: **51 ft.**

LTANKS:

Name:	PLASTIC WORKS
Address:	115 CEDAR ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812998 / 1999-02-22
Facility ID:	9812998
Site ID:	163894
Spill Date:	1999-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	1999-03-01
Spiller Name:	GARY STRUTTEN
Spiller Company:	PLASTIC WORKS
Spiller Address:	115 CEDAR ST
Spiller County:	001
Spiller Contact:	GARY STRUTTEN
Spiller Phone:	(914) 576-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	138224
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER'S COMPANY WAS PULLING A 550GAL UST - TANK WAS FULL OF HOLES"

All Materials:

Site ID:	163894
Operable Unit ID:	1073438
Operable Unit:	01
Material ID:	313271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

PLASTIC WORKS (Continued) **S103824027**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

356
SSE
1/4-1/2
0.367 mi.
1940 ft.

NICK MAZZA RESIDENCE
20 DAVIS AVE
NEW ROCHELLE, NY

NY LTANKS **S104621408**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Name:	NICK MAZZA RESIDENCE
Address:	20 DAVIS AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0000532 / 2000-04-20
Facility ID:	0000532
Site ID:	211468
Spill Date:	2000-04-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-13
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-13
Spill Record Last Update:	2000-05-03
Spiller Name:	N/A
Spiller Company:	NICK MAZZA
Spiller Address:	20 DAVIS AVE
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/14/2000 ENVIROSTAR REPAIRED; U.S. TANK TO RETEST ON 4/17/2000. 04/20/2000 U.S. TANK TECH RETESTED TANK AFTER ENVIROSTAR REPLACED PIPING. TANK PASSED RETEST. NFA"
Remarks:	"tank failed the test. he did not have the homeowners name or phone number "

All TTF:

Facility ID:	0000532
Spill Number:	0000532
Spill Tank Test:	1525485

NICK MAZZA RESIDENCE (Continued) **S104621408**

Site ID:	211468
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	18
Test Method 2:	Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	211468
Operable Unit ID:	822249
Operable Unit:	01
Material ID:	288777
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC357 **SHERIDEN PLAZA** **NY LTANKS** **S100138278**
NE **1 SHERIDEN PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.370 mi.
1953 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
36 ft.

LTANKS:

Name:	SHERIDEN PLAZA
Address:	1 SHERIDEN PLAZA
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8909204 / 1990-03-07
Facility ID:	8909204
Site ID:	80178
Spill Date:	1989-12-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-12-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

SHERIDEN PLAZA (Continued) **S100138278**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-12-21
Spill Record Last Update:	1992-02-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74339
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATION FOUND DURING TANK REMOVAL SOIL TO BE STOCKPILED ON PLASTIC DEC TO INSPECT TANK HOLE TYREE VACING OUT HOLE"

All Materials:

Site ID:	80178
Operable Unit ID:	934143
Operable Unit:	01
Material ID:	442378
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BD358 **JASON PARTNERS LTD** **NY LTANKS** **S105998096**
SSW **675 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.373 mi.
1968 ft. **Site 1 of 3 in cluster BD**

Relative: **Lower**
Actual: **65 ft.**

LTANKS:

Name:	JASON PARTNERS LTD
Address:	675 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0211105 / 2003-03-26
Facility ID:	0211105
Site ID:	86967
Spill Date:	2003-02-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-02-05
CID:	297
Water Affected:	Not reported

JASON PARTNERS LTD (Continued) **S105998096**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-05
Spill Record Last Update:	2003-04-09
Spiller Name:	JAMIE MIZRAHI
Spiller Company:	JASON PARTNERS LTD
Spiller Address:	675 MAIN ST
Spiller County:	001
Spiller Contact:	JAMIE MIZRAHI
Spiller Phone:	(914) 682-6664
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79721
DEC Memo:	""
Remarks:	"CALLERS COMPANY HIRED TO REMOVE A 3000 GAL INGROUND TANK AT THE ABOVE LOCATION, AFTER TANK WAS REMOVED, HOLE WERE FOUND IN TANK AND CONTAMINATED SOIL WAS DISCOVERED - DIRT IS BEING REMOVED AND STORED ON PLASTIC"

All Materials:

Site ID:	86967
Operable Unit ID:	862143
Operable Unit:	01
Material ID:	514466
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE359 **ABANDONED GAS STATION** **NY LTANKS** **S102660200**
West **197 WEBSTER AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.376 mi.
1986 ft. **Site 1 of 2 in cluster BE**

Relative: **Lower**

Actual: **79 ft.**

LTANKS:

Name:	ABANDONED GAS STATION
Address:	197 WEBSTER AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9707099 / 2001-07-19
Facility ID:	9707099
Site ID:	231589
Spill Date:	1997-09-15
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa

ABANDONED GAS STATION (Continued) **S102660200**

Referred To:	Not reported
Reported to Dept:	1997-09-15
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-09-15
Spill Record Last Update:	2001-08-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	EDWARD SELLIAN
Spiller Phone:	(561) 221-1754
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	190875
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/19/2001 LETTER SENT TO IRA CONKLIN & SONS BY T. GHIOSAY; BASED ON SUBSURFACE INVESTIGATION REPORT, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL LISTED AS CLOSED."
Remarks:	"CALLER REMOVING TANKS AND FOUND SOIL CONTAMINATION"

All Materials:

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC360 **MUTUAL BISCUIT COMPANY** **NY LTANKS** **S104193116**
NE **65 RIVER ST.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.379 mi.
1999 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Name:	MUTUAL BISCUIT COMPANY
Address:	65 RIVER ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8707334 / 1988-02-18
Facility ID:	8707334
Site ID:	286036
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-25
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-01
Spill Record Last Update:	1988-03-11
Spiller Name:	HUGH GEORGE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : WILL RETEST. / / : TANKS REMOVED. LR 02-18-88 N F A. "
Remarks:	"TTTF-4K TANK;-0.7584 GPH,4K TANK;-0.3312 GPH"

All TTF:

Facility ID:	8707334
Spill Number:	8707334
Spill Tank Test:	1532438
Site ID:	286036
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286036
Operable Unit ID:	911503
Operable Unit:	01
Material ID:	466293
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MUTUAL BISCUIT
Address:	65 RIVER ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8708530 / 1988-02-18
Facility ID:	8708530
Site ID:	286037
Spill Date:	1988-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	HUGH GEORGE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANKS REMOVED 02-18-88 LR N F A. "
Remarks:	"5K (RETEST) 1.34GPH TO PUMP & PULL TANK"

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

All TTF:

Facility ID:	8708530
Spill Number:	8708530
Spill Tank Test:	1532919
Site ID:	286037
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286037
Operable Unit ID:	913194
Operable Unit:	01
Material ID:	570954
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	POST MARINE SUPPLY
Address:	65 RIVER ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9904805 / 1999-07-22
Facility ID:	9904805
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139056
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-07-22
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1999-07-22
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-22
Spill Record Last Update:	1999-09-10
Spiller Name:	NASER JABER
Spiller Company:	POST MARINE SUPPLY
Spiller Address:	65 RIVER ST
Spiller Company:	001
Contact Name:	NASER JABER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA "
Remarks:	"CALLER STATES THAT HE WITTNESSED SUBJ DUMPING GAS INTO A STORM DRAIN. JOHN O'MARA (REGION 3 SPILLS) NOTIFIED AND ALSO ENCON POLICE"

All Materials:

Site ID:	139056
Operable Unit ID:	1079250
Operable Unit:	01
Material ID:	301132
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	POST MARINE SUPPLY
Address:	65 RIVER ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908179 / 1999-10-18
Facility ID:	9908179
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139057
DEC Region:	3
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1999-10-05
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Date Entered In Computer:	1999-10-05
Spill Record Last Update:	1999-11-04
Spiller Name:	MICHAEL GRAVANESE
Spiller Company:	POST MARINE SUPLLY
Spiller Address:	65 RIVER SR
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/18/99 DEC INSPECTED SITE. ONE LEAKY BATTERY FOUND NEXT TO DIESEL TANKS. BATTERIES TO BE REMOVED LATER TODAY. NFA"
Remarks:	"CALLER IS AN EX EMPLOYEE REPORTING BATTERIES BEING STORED NEXT TO GASOLINE TANKS AND BELIEVES THEY MIGHT BE LEAKING BATTERY ACID."

All Materials:

Site ID:	139057
Operable Unit ID:	1082477
Operable Unit:	01
Material ID:	300856
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF361 **GETTY 58114** **NY LTANKS S107657288**
ENE **340 MAIN STREET** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.380 mi.
2004 ft. **Site 1 of 6 in cluster BF**

Relative: **Lower**
Actual: **38 ft.**

LTANKS:

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0913713 / 2010-04-29
Facility ID:	0913713
Site ID:	426673
Spill Date:	2010-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2010-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

GETTY 58114 (Continued) **S107657288**

Date Entered In Computer:	2010-03-26
Spill Record Last Update:	2018-04-09
Spiller Name:	ROBERT O'KEEFE
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TOM ANDERSON
Spiller Phone:	(845) 216-8064
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310476
DEC Memo:	"3/26/10 Tyree to go there on Mon. 3/29 to do repairs. dw 4/29/10 Getty 340 Main St New Rochelle line test failed do to faulty check valve. Tyree replaced check valve. Passed retest on 4/12/10 NFA JO'M 10-23-17 SEND OUT 30 day tank letter- RDB 10-25-17 call from Raul Naube @ 5168027171; retuned call; explained the current situation. offered to remove tanks for him. he is waiting for a court case, I advised him that he is in violation of the NYS CRRR pertaining to tanks, he has other sites on Long Island. Never in Westchester, I welcomed him to region; he will move forward with the permits and intends to remove the tanks- RDB 12-12-17 Rahul@lotusmgmt.com 340 Main Street Realty Inc. 25 Newbridge Road, Suite 312, Hicksville, NY 11801 _RDB 12-12-17 called and left another message RDB 12-18-17 email sent, I called your office last week and left a message. The tanks at your facility need to be removed. Please contact me today and discuss the schedule for the tank s removal or this case will be referred to Region 3, Regional Attorney for enforcement. RDB 1-3-18 email from Cider, The owner of the above referenced property has received the permit for removal of the USTs (NR BD/NR FM).We are only waiting on the contractors schedule.In the meantime, we wanted to confirm that there is nothing else required by your department?As soon as the schedule is confirmed, we will let you know. RDB 1-4-18 response, Thanks for the email and call. Who is the contractor for the tank removal? Do you have a guesstimate for the removal date? As I have explained to Rahul, this site is progressing towards enforcement and penalties. RDB 1-4-18, The contractor for the tank removals will be Felik s and Sons. Rahul is pushing them to get out there as soon as possible. My guestimate would be about two/three weeks to begin. As soon as we get the schedule from the contractor/Rahul, I will let you know. RDB Tank removal began. New Spill called in 17-09698 This spill closed- RDB 02-12-18 Spoke with Tim Fisher of Antea Group. Excavation under the northern dispenser island to commence on Thursday. Endpoint samples from both the registered tank removal and ghost tank removal show no exceedances. Sand from inside the ghost tanks is stock piled on site. All soil to be removed upon completion of excavation activities. BTR 4/9/18 pre-work notification from 12/27/17 in D2. BW "
Remarks:	"in line problem - Tyree notified - cleanup and repair pending"

All Materials:

Site ID:	426673
Operable Unit ID:	1182349
Operable Unit:	01
Material ID:	2176532
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

GETTY 58114 (Continued) **S107657288**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600016 / 2006-04-01
Facility ID:	0600016
Facility Type:	ER
DER Facility ID:	310476
Site ID:	361935
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-01
CID:	41
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-01
Spill Record Last Update:	2006-04-04
Spiller Name:	Not reported
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"04/04/06: closed NFA"
Remarks:	"LESS THAN ONE GALLON OF EACH - ON ALPHALT - CLEANED UP"

All Materials:

Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01
Material ID:	2109530
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

GETTY 58114 (Continued) **S107657288**

Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01
Material ID:	2109529
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513793 / 2006-03-02
Facility ID:	0513793
Facility Type:	ER
DER Facility ID:	310476
Site ID:	360340
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-01
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2006-03-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-01
Spill Record Last Update:	2006-03-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"Some staining - Cleaned up NFA"
Remarks:	"LESS THAN A GAL OF BOTH HAS BEEN CLEANED UP."

All Materials:

Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108025
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported

GETTY 58114 (Continued) **S107657288**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported
Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108026
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported
Name:	GETTY #58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601041 / 2006-04-27
Facility ID:	0601041
Facility Type:	ER
DER Facility ID:	310476
Site ID:	363188
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-27
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2006-04-27
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-27
Spill Record Last Update:	2006-05-02
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"5/2/06: Staining - cleaned up NFA"
Remarks:	"speedi dri applied and cleaned up"

All Materials:

Site ID:	363188

GETTY 58114 (Continued) **S107657288**

Operable Unit ID: 1121255
Operable Unit: 01
Material ID: 2110750
Material Code: 0043A
Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 363188
Operable Unit ID: 1121255
Operable Unit: 01
Material ID: 2110748
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 363188
Operable Unit ID: 1121255
Operable Unit: 01
Material ID: 2110749
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GETTY 58114
Address: 340 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0603586 / 2006-07-03
Facility ID: 0603586
Facility Type: ER
DER Facility ID: 310476
Site ID: 366335
DEC Region: 3
Spill Cause: Housekeeping
Spill Class: C4
SWIS: 6010
Spill Date: 2006-06-30
Investigator: JPCUMMIN
Referred To: Not reported
Reported to Dept: 2006-06-30
CID: 409
Water Affected: Not reported

GETTY 58114 (Continued) **S107657288**

Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-30
Spill Record Last Update:	2006-07-11
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"COMBINED TOTAL OF LESS THAN A GAL. HAS BEEN CLEANED UP."

All Materials:

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113775
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113776
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606306 / 2006-09-03
Facility ID:	0606306
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369636
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010

GETTY 58114 (Continued) **S107657288**

Spill Date:	2006-09-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-01
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"LESS THAN A GAL OF BOTH ABND THEY HAVE BEEN CLEANED UP."

All Materials:

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117068
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117069
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606253 / 2006-09-03
Facility ID:	0606253
Facility Type:	ER

GETTY 58114 (Continued) **S107657288**

DER Facility ID:	310476
Site ID:	369567
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-08-30
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-30
CID:	77
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-31
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"1 qt of waste oil spilled onto asphalt, speedy dry applied."

All Materials:

Site ID:	369567
Operable Unit ID:	1127402
Operable Unit:	01
Material ID:	2117000
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY #58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0602340 / 2006-06-07
Facility ID:	0602340
Facility Type:	ER
DER Facility ID:	310476
Site ID:	364789
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-06-01

GETTY 58114 (Continued) **S107657288**

Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-06-01
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-01
Spill Record Last Update:	2006-06-07
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"SPEEDI DRI DOWN STAINING ONLY"

All Materials:

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112286
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

362
ENE
1/4-1/2
0.382 mi.
2015 ft.

SUNOCO
71 HUGUENOT ST
NEW ROCHELLE, NY

NY LTANKS **S102233475**
NY Spills **N/A**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Name:	SUNOCO / A-PLUS
Address:	71 HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9514850 / 1996-07-26
Facility ID:	9514850
Site ID:	255332
Spill Date:	1996-02-20
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-20
Spill Record Last Update:	1996-09-05
Spiller Name:	RUSSELL HAMMOND
Spiller Company:	SUNOCO / A-PLUS
Spiller Address:	71 HUGUENOT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209140
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/26/96 EPS SUBMITTED G.W. INVESTIAGATION WHICH INDICATES THAT SUNOCO IS THE SOURCE OF G.W. CONTAM. ON 15 RIVER ST. "
Remarks:	"soil boring for assessment for station upgrade - head space reading indicates potential of petroleum release"

All Materials:

Site ID:	255332
Operable Unit ID:	1025945
Operable Unit:	01
Material ID:	354972
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUNOCO (Continued) **S102233475**

SPILLS:

Name:	SUNOCO
Address:	71 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9610201 / 2005-01-20
Facility ID:	9610201
Facility Type:	ER
DER Facility ID:	201279
Site ID:	245037
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1996-02-28
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-11-15
CID:	366
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-15
Spill Record Last Update:	2005-01-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RUSSELL HAMMOND
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 11/15/96 PETROLEUM FOUND DURING WELL SAMPLING; 09/22/97 LETTER SENT; REMEDIATION IS REQUIRED AT THIS SITE; 01/02/98 LETTER SENT; REMEDIATION PROPOSAL IS APPROVED; WORK MUST START WITHIN THIRTY DAYS; 12/30/99 LETTER SENT TO SUN COMPANY; PROPOSAL TO INSTALL HI-VAC SYSTEM AT THIS SITE IS APPROVED & REQUIRED 1/20/05 nfa letter has been sent do to low and declining groundwater contamination--close 05/18/00 LETTER SENT TO MATRIX ENV. BY J. HARDY; REMEDIAL ACTION PLAN OF 1/12/00 IS APPROVED AND REQUIRED 04/19/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; YOU ARE AUTHOR IZED TO OPERATE REMEDIAL SYSTEMS FOR 90 DAYS WHILE DISCHARGE PERMIT APPLICATIONS ARE BEING PROCESSED 06/22/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; AUTHORIZED BY WCDOH TO OPERATE SYSTEM FOR 90 DAYS WHILE PERMITTING IS IN PROGRESS 05/09/03: Letter sent to Matrix Env. Tech. by J. Hardy; Report submitted dated March 20, 2003. Next report due after completion of one year monitoring period. 2/12/04: Letter sent to Matrix Env. Tech. by J. Hardy. No further action is required at this time. Spill cannot be closed due to BTEX levels in monitoring wells 2 & 4."
Remarks:	"while removing old tanks discovered contaminated soil. caller's company is cleaning. "

All Materials:

Site ID:	245037

SUNOCO (Continued) **S102233475**

Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	342418
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	245037
Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	2096838
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BD363 **6 WEBSTER** **NY LTANKS** **S106472061**
SSW **6 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.384 mi.
2025 ft. **Site 2 of 3 in cluster BD**

Relative: **Lower**
Actual: **60 ft.**

LTANKS:

Name:	6 WEBSTER
Address:	6 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403816 / 2004-10-08
Facility ID:	0403816
Site ID:	81655
Spill Date:	2004-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-07-09
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-09
Spill Record Last Update:	2004-10-08

6 WEBSTER (Continued) **S106472061**

Spiller Name:	SANDRA
Spiller Company:	Not reported
Spiller Address:	6 WEBSTER AVE
Spiller County:	001
Spiller Contact:	SANDRA
Spiller Phone:	(914) 738-4106
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75517
DEC Memo:	"10/08/04 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. SPILL CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NFA REQUIRED AT THIS TIME. jbo "
Remarks:	"tank test failed.uncover the tank isolate,and retest"

All TTF:

Facility ID:	0403816
Spill Number:	0403816
Spill Tank Test:	1529427
Site ID:	81655
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	81655
Operable Unit ID:	886220
Operable Unit:	01
Material ID:	491374
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BG364 **SPILL NUMBER 0314082** **NY LTANKS** **S106385679**
WNW **136 VANGUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.385 mi.
2035 ft. **Site 1 of 2 in cluster BG**

Relative: **Lower**

Actual: **76 ft.**

LTANKS:

Name:	SPILL NUMBER 0314082
Address:	136 VANGUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0314082 / 2004-06-08
Facility ID:	0314082
Site ID:	80232
Spill Date:	2004-03-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-25
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-25
Spill Record Last Update:	2004-06-08
Spiller Name:	SILVANA CARRUSA
Spiller Company:	Not reported
Spiller Address:	136 VANGUILDER AVE
Spiller County:	001
Spiller Contact:	SILVANA CARRUSA
Spiller Phone:	(914) 654-1101
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74387
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/08/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 43.55 TONS OF CONTAMINATED SOIL. NFA REQUIRED. jbo"
Remarks:	"tank test failed. repair and retest and remove"

All TTF:

Facility ID:	0314082
Spill Number:	0314082
Spill Tank Test:	1529072
Site ID:	80232
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

SPILL NUMBER 0314082 (Continued) **S106385679**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 80232
Operable Unit ID: 881015
Operable Unit: 01
Material ID: 495664
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BH365 **STEWART DWELLING** **NY LTANKS S109414263**
NW **100 SICKLES AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.387 mi.
2043 ft. **Site 1 of 6 in cluster BH**

Relative:
Lower

Actual:
69 ft.

LTANKS:
Name: STEWART DWELLING
Address: 100 SICKLES AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1200264 / 2012-08-13
Facility ID: 1200264
Site ID: 462885
Spill Date: 2012-04-10
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2012-04-10
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2012-04-10
Spill Record Last Update: 2012-08-13
Spiller Name: Not reported
Spiller Company: STEWART
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: STEWART

STEWART DWELLING (Continued) **S109414263**

Spiller Phone:	914-235-6390
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	326980
DEC Memo:	"4-10-12 Spoke with Kathy. Failed with a popping sound. They have recommended a retest because this sound usually means piping or fitting leak. Homeowner is elderly so they are dealing with her daughter, Eunice at 914-715-1040. jm 8/13/2012: Envirostar removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"550gal ust"

All Materials:

Site ID:	462885
Operable Unit ID:	1212990
Operable Unit:	01
Material ID:	2210869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	STEWART RESIDENCE
Address:	100 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0612561 / 2007-03-12
Facility ID:	0612561
Facility Type:	ER
DER Facility ID:	326980
Site ID:	377421
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2007-02-19
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-02-19
CID:	410
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-20
Spill Record Last Update:	2007-03-12

STEWART DWELLING (Continued) **S109414263**

Spiller Name:	SUZANNE LUGO
Spiller Company:	TOWN AND COUNTRY OIL
Spiller Address:	275 EAST 7TH STREET
Spiller Company:	001
Contact Name:	NECOLA STEWART
DEC Memo:	""
Remarks:	"SPILL WAS LESS THAN ONE GALLON ON ICE OUTSIDE OF RESIDENCE: CLEANUP IN PROGRESS: MATERIAL CAME OUT OF VENT PIPE:"

All Materials:

Site ID:	377421
Operable Unit ID:	1134955
Operable Unit:	01
Material ID:	2124838
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	RESIDENCE
Address:	100 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0811178 / 2009-01-09
Facility ID:	0811178
Facility Type:	ER
DER Facility ID:	326980
Site ID:	408736
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-01-09
Investigator:	dxweitz
Referred To:	Not reported
Reported to Dept:	2009-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-09
Spill Record Last Update:	2009-01-09
Spiller Name:	SUE LUGO
Spiller Company:	TOWN & COUNTRY OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NECOLA STEWART
DEC Memo:	"1/9/09 Problem with the vent whistle. Town and Country is there

STEWART DWELLING (Continued) **S109414263**

fixing the vent, and cleaning up the 1 gal spill. NFA dw"
Remarks: "Caller states during a fill some oil sprayed out of the vent pipe onto soil. Spill was cleaned."

All Materials:
Site ID: 408736
Operable Unit ID: 1165255
Operable Unit: 01
Material ID: 2156662
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

BE366 **MAR-LAP SVC CNTR** **NY LTANKS S103568792**
West **210 WEBSTER AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.395 mi.
2087 ft. **Site 2 of 2 in cluster BE**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:
Name: CITGO WEBSTER FOOD MART
Address: 210 WEBSTER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1311416 / 2017-04-06
Facility ID: 1311416
Site ID: 492314
Spill Date: 2014-03-06
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2014-03-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2014-03-06
Spill Record Last Update: 2017-04-06
Spiller Name: Not reported
Spiller Company: LINE TEST FAILURE
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: VISHAL KUMAR
Spiller Phone: (914) 632-2364
Spiller Extention: Not reported

MAR-LAP SVC CNTR (Continued) **S103568792**

DEC Region: 3
DER Facility ID: 216842
DEC Memo: "Wanye Schneider, WCDOH, is handling...mm 4-5-17 ask American for update"
Remarks: "regular and super product line test failure - repair/retest pending"

All Materials:
Site ID: 492314
Operable Unit ID: 1241846
Operable Unit: 01
Material ID: 2242337
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: SSN REALTY
Address: 210 WEBSTER AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1200103 / 2013-11-06
Facility ID: 1200103
Facility Type: ER
DER Facility ID: 216842
Site ID: 462718
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 6010
Spill Date: 2012-04-04
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2012-04-04
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-04-04
Spill Record Last Update: 2013-11-06
Spiller Name: MR KUMAR
Spiller Company: SSN REALTY
Spiller Address: 210 WEBSTER AVE
Spiller Company: 999
Contact Name: MR KUMAR
DEC Memo: "4-4-12: V.Mc. call to Mr.Kumar: Phone # no longer is service.
4-4-12: V.Mc. call to SEBASTIAN/WCHD: Left Mess.: Req. callbk. to

MAR-LAP SVC CNTR (Continued) **S103568792**

Dispt. Update from WCDOH: greater than greater than greater than Bimonte, Sebastian greater than spb4@westchestergov.com greater than 4/5/2012 9:46 AM greater than greater than greater than John, SSN Realty 210 Webster Ave New Rochelle NY Super Tank product in interstitial space. Manual check during PBS inspection yesterday. Product clear no water or dirt. Diesel Tank product in interstitial space. Manual check during PBS Inspection yesterday. Product clear no water of dirt. Tanks One was hired to test inner and outer tanks. Super, inner wall passed, outer wall failed. Diesel inner wall failed, outer wall passed. Both tanks should be pumped out by today. Sebastian Bimonte jod 5/23/2012 -- After a meeting in NPO among owner, tank maintenance contractor, Mr. Nesci (attorney), WC DOH, and CK last Friday (5/18), Ispoke to Rachel at Hydro Environmental about a site assessment. Work plan to be submitted shortly. ELM 6/05/12: Update received from Sebastian Bimonte of WCDOH PBS: 1200103: SNN Realty in Mount Vernon. This was product in the interstitial during PBS inspection. No release to environment. Tank repaired NOH issued and can be closed. jod 6/5/2012 -- Site assessment being conducted at my request: field work on 210 Webster Ave in New Rochelle on Tuesday, June 12, 2012 per email from Hydro Enviro. ELM 7/31/2012 -- RI report clearly shows groundwater contamination (BETX/MTBE) around the tank field and dispensers. Need further delineation and RAP. Nothing in unsaturated soils. ELM 8/22/2012 -- Contractor working on a Phase II RI work plan. ELM 9/19/2012 -- Approved an RI work plan. Except that they did include the schedule and failed to mention RAP possibilities. ELM 1/22/2013 -- HydroTech informed me that they have the permit needed from the muny to perform the remediation. ELM 2/21/2013 -- Still no word on mobilizing for remediation. ELM 11-6-13 email from county, There is a whole history here.The 1200103 was for product in the interstitial. Sebastian and Carlos worked with Ed Moore on it.Basically double walled tanks leaked into the interstitial. It appear to be the striker plate were missing and from sticking the tanks they wore out. Eastmond lined the tanks and had trouble removing the product from the IS (completely). We requested spill closure and Ed Moore kept the spill open and continued to work on the PBS issues. They are replacing all tanks now. American Petroleum (Ed- Thank You for making this happen)Wayne Schneider is inspected the site this afternoon and will handle the spill. I suggest we close out spill 1200103 and keep 1307998.(Wayne please provide a brief update to all after your inspection today.) 11-6-13 tanks yanked, new spill 13-07998, close this one RDB "

Remarks: "12 oz per product found during investigation on inter.cont., on the super tank and diesel tank."

All Materials:

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

MAR-LAP SVC CNTR (Continued) **S103568792**

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210675
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WESTERN AVE CITGO
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413599 / 2005-03-30
Facility ID:	0413599
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342744
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"IT WAS SOME RESIDEU IN A SPILL BUCKET ALL CLEANED UP:"

All Materials:

Site ID:	342744
Operable Unit ID:	1101460
Operable Unit:	01
Material ID:	581627
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

MAR-LAP SVC CNTR (Continued) **S103568792**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WESTERN AVE CITGO
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413600 / 2005-03-30
Facility ID:	0413600
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342745
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"WHILE CHANGING OIL THEY KICKED A BUCKET OVER AND IN PROCESS OF CLEANING UP AT THIS TIME;"

All Materials:

Site ID:	342745
Operable Unit ID:	1101461
Operable Unit:	01
Material ID:	581628
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

MAR-LAP SVC CNTR (Continued) **S103568792**

Name:	CITGO STATION
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600746 / 2006-08-15
Facility ID:	0600746
Facility Type:	ER
DER Facility ID:	216842
Site ID:	362821
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2006-04-19
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2006-04-19
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-04-19
Spill Record Last Update:	2020-01-21
Spiller Name:	SEBASTIAN BELLAFONTE
Spiller Company:	CITGO STATION.
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN BELLAFONTE
DEC Memo:	"04/25/06: refer to WC PBS. 12/21/06 - Letter from Barbara McDonald from WCDOH to Sebastian Bulfamonte, SSN Realty 94 1st Street, New Rochelle, NY 10801, states that documentation is acceptable to the Westchester County Department of Health and the work permits issued 5/11/06 and 6/6/06 are closed. NFA."
Remarks:	"FOUND THE MATERIAL BETWEEN THE INTERSTIAL SPACE OF THE TWO TANKS. 4000 GAL TANKS. PBS 3-180092"

All Materials:

Site ID:	362821
Operable Unit ID:	1120900
Operable Unit:	01
Material ID:	2110381
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MAR-LAP SVC CNTR
Address:	210 WEBSTER AVE

MAR-LAP SVC CNTR (Continued) **S103568792**

City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8906053 / 1989-09-21
Facility ID:	8906053
Facility Type:	ER
DER Facility ID:	216842
Site ID:	266088
DEC Region:	3
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1989-07-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-09-19
Cleanup Meets Std:	True
Last Inspection:	1989-09-19
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	MAR-LAP SVC CNTR
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL."
Remarks:	"HAVE EXCAVATED AND REMOVED GAS CONTAMINATED SOIL FROM AROUND 3 5ANKS. SOIL BEING REMOVED TODAY BY E.E.S. NFA"

All Materials:

Site ID:	266088
Operable Unit ID:	931218
Operable Unit:	01
Material ID:	446446
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

367
SE
1/4-1/2
0.397 mi.
2094 ft.

SPILL NUMBER 0302495
85 NORTH AVE
NEW ROCHELLE, NY

NY LTANKS
NY Spills

S105999167
N/A

Relative:
Lower

Actual:
69 ft.

LTANKS:

Name:	GAS STATION
Address:	85 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0507677 / 2009-10-09
Facility ID:	0507677
Site ID:	353132
Spill Date:	2005-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jkomara
Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2009-10-09
Spiller Name:	FRANK
Spiller Company:	GAS STATION
Spiller Address:	85 NORTH AVE.
Spiller County:	001
Spiller Contact:	FRANK
Spiller Phone:	(914) 632-2109
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	"9/28/05 Also see spills 03-04446, 05-11827 and 05-07653. jod Closure report received and site visit with WCHD performed. NFA if no money State money spent on Spill # 0304446 pin # 03236. 4/5/07 JO'M 10/9/09 Closed this spill refer to 0304446 JO'M"
Remarks:	"LINE FAILURE."

All Materials:

Site ID:	353132
Operable Unit ID:	1110599
Operable Unit:	01
Material ID:	2100636
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILL NUMBER 0302495 (Continued) **S105999167**

Name:	SPILL NUMBER 0302495
Address:	85 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0302495 / 2003-08-12
Facility ID:	0302495
Site ID:	114935
Spill Date:	2003-06-09
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-09
CID:	405
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-08-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	85 NORTH AVE
Spiller County:	001
Spiller Contact:	DISPATCHER 629
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	""
Remarks:	"caller states that there is an overspill at the above address - some has gone into the sewer - cell # 914-760-1305 is for the fire chief on scene - unknown if the spill is stopped or not"

All Materials:

Site ID:	114935
Operable Unit ID:	869316
Operable Unit:	01
Material ID:	506969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	FRANKIES AUTO
Address:	85 NORTH AVE

SPILL NUMBER 0302495 (Continued) **S105999167**

City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0507653 / 2005-10-07
Facility ID:	0507653
Facility Type:	ER
DER Facility ID:	100200
Site ID:	353098
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2005-09-26
Investigator:	JKOMARA
Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2005-10-07
Spiller Name:	FRANK
Spiller Company:	FRANKIES AUTO
Spiller Address:	85 NORTH AVE.
Spiller Company:	001
Contact Name:	FRANK
DEC Memo:	"9/28/05 Also see spills 03-04446, 03-11827 and 05-07677. jod 10/07/05 Refer to spill 05-07677 for all updates. This spill number closed. jod"
Remarks:	"GASOLINE IN SANITARY SEWER NEXT TO STATION AND ODORS: PLEASE CALL DOH ON THIS ISSUE"

All Materials:

Site ID:	353098
Operable Unit ID:	1110568
Operable Unit:	01
Material ID:	2100602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH368 **BRIEN-AMIE RESIDENCE** **NY LTANKS** **S105999591**
NW **105 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2094 ft. **Site 2 of 6 in cluster BH**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	BRIEN-AMIE RESIDENCE
Address:	105 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0304963 / 2004-02-02
Facility ID:	0304963
Site ID:	219644
Spill Date:	2003-08-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-08-11
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-11
Spill Record Last Update:	2004-02-02
Spiller Name:	BRIEN-AMIE RESIDENCE
Spiller Company:	Not reported
Spiller Address:	105 SICKLES AVE
Spiller County:	001
Spiller Contact:	BRIEN-AMIE RESIDENCE
Spiller Phone:	(914) 576-6823
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181652
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/11/03: 1000 gal. underground tank. 02/02/04 DUTCHESS DISPOSED OF LUST AND 75.35 TONS OF CONTAMINATED SOIL. SAMPLE RESULTS BELOW TAGM LIMITS. NFA jbo"
Remarks:	"they were doing an inplace closure tank abandonment & encountered contaminated soil from the 550 gal underground tank - unk about soil removal at this point"

All Materials:

Site ID:	219644
Operable Unit ID:	873280
Operable Unit:	01
Material ID:	502238
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

BRIEN-AMIE RESIDENCE (Continued) **S105999591**

Recovered: .00
Oxygenate: Not reported

BF369 **JEROME RESIDENCE** **NY LTANKS** **S106702572**
ENE **33 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2095 ft. **Site 2 of 6 in cluster BF**

Relative: **Lower**
Actual: **35 ft.**

LTANKS:

Name:	JEROME RESIDENCE
Address:	33 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0405389 / 2005-02-13
Facility ID:	0405389
Site ID:	235222
Spill Date:	2004-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-08-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-17
Spill Record Last Update:	2005-02-13
Spiller Name:	MARK JEROME
Spiller Company:	JEROME RESIDENCE
Spiller Address:	33 ECHO AVE
Spiller County:	001
Spiller Contact:	MARK JEROME
Spiller Phone:	(914) 632-5400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193747
DEC Memo:	"02/13/05 MILLER ENVIRONMENTAL REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- ISOLATION & RETEST"

All TTF:

Facility ID:	0405389
Spill Number:	0405389
Spill Tank Test:	1529557
Site ID:	235222
Tank Number:	Not reported
Tank Size:	1000
Material:	0001

JEROME RESIDENCE (Continued) **S106702572**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489552
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BI370 **MICELI HOME** **NY LTANKS** **S108059468**
SSE **194 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.397 mi.
2096 ft. **Site 1 of 4 in cluster BI**

Relative: **Lower**
Actual: **78 ft.**

LTANKS:

Name:	MICELI HOME
Address:	194 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0604103 / 2006-10-22
Facility ID:	0604103
Site ID:	366997
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported

MICELI HOME (Continued) **S108059468**

SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-10-22
Spiller Name:	MARIO MICELI
Spiller Company:	MICELI HOME
Spiller Address:	194 CENTRE AVE
Spiller County:	001
Spiller Contact:	MARIO MICELI
Spiller Phone:	(914) 235-2198
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317018
DEC Memo:	"CLOSING REPORT TO JOHN O'DEE. October 22, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 23.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 gallon tank had holes"

All Materials:

Site ID:	366997
Operable Unit ID:	1124924
Operable Unit:	01
Material ID:	2114431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF371 **POWERTEST,ECHO & MAIN** **NY LTANKS** **S100139866**
ENE **36 ECHO AVE @ MAIN ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.399 mi.
2108 ft. **Site 3 of 6 in cluster BF**

Relative: **Lower**

Actual: **33 ft.**

LTANKS:

Name:	POWERTEST,ECHO & MAIN
Address:	36 ECHO AVE @ MAIN ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8709260 / 1988-02-11
Facility ID:	8709260
Site ID:	283199
Spill Date:	1988-01-30

POWERTEST,ECHO & MAIN (Continued) **S100139866**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-11
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-02-01
Spill Record Last Update:	1988-06-13
Spiller Name:	Not reported
Spiller Company:	HACKER,JOSHUA;POWERTEST
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229700
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 02-01-88 TANK REPLACED 5 YRS.AGO. AS PER DEPUTY CHIEF WILLIAM COMVERY,BASEMENT ODORS GREATLY DISSAPATED, ONCE VENTED. 02/11/88: CHECKED STATION; SEEMS TO BE ODOR PROBLEM DURING DELIVERIES. 11/29/95: This is additional information about material spilled from the translation of the old spill file: FUMES."
Remarks:	"DELIVERY THIS MORNING, ONGOING PROBLEM, EXPLOSIVE READING IN BASEMENT. NEW ROCHELLE F.D. HAS VENTED BASEMENT AND WILL MONITOR."

All Materials:

Site ID:	283199
Operable Unit ID:	914517
Operable Unit:	01
Material ID:	464589
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH372 **POINVIL RESIDENCE** **NY LTANKS** **S111160012**
NW **107 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.400 mi.
2110 ft. **Site 3 of 6 in cluster BH**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	POINVIL RESIDENCE
Address:	107 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1104844 / 2014-11-05
Facility ID:	1104844
Site ID:	452458
Spill Date:	2011-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-28
Spill Record Last Update:	2017-08-10
Spiller Name:	HENRY POINVILE
Spiller Company:	POINVILE
Spiller Address:	107 SICKLES AVE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	407046
DEC Memo:	"7-28-11 Spoke with Kathy Morgan, This a is a real estate transaction. The plan at this time is to uncover, isolate and retest. The tank is 1080 gallon UST that is probably the original tank - age unknown. jm 2/17/12: Residential TTF, DEC Lead changed to unassigned. jod 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M 08/10/17 Spoke to the present homeowner who stated that she is attempting to sell the house and that this TTF came up during the transaction. She stated that she not informed by the previous owner that the tank failed a tank test. She is planning to have the tank removed. She was advised to speak to her attorney about the previous owners statement that nothing was wrong with the tank. TG"
Remarks:	"repair/retest pending -"

All Materials:

Site ID:	452458
Operable Unit ID:	1202639
Operable Unit:	01
Material ID:	2199228

POINVIL RESIDENCE (Continued) **S111160012**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BD373 **AMOCO SERVICE STATION #736** **NY LTANKS** **1001128018**
SSW **690 MAIN ST** **NY Spills** **NYR000036855**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.403 mi. **NY MANIFEST**
2128 ft. **Site 3 of 3 in cluster BD**

Relative:
Lower

Actual:
64 ft.

LTANKS:

Name:	RACE TANK INC
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209490 / 2002-12-16
Facility ID:	0209490
Site ID:	274754
Spill Date:	2002-12-16
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-16
CID:	246
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2002-12-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	DAVE BERRY
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"Tanker overfilled tank and material spilled at location. Approx 10 gal went into storm drain and sewer. Fire dept on scene now speedy dry applied"

All Materials:

Site ID:	274754

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Operable Unit ID:	862563
Operable Unit:	01
Material ID:	512914
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

Name:	RACE TANK INC
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0212950 / 2003-04-01
Facility ID:	0212950
Site ID:	274755
Spill Date:	2003-03-31
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-03-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-31
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	WESTCHESTER CO 911
Spiller Phone:	(914) 231-1904
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"PRODUCT DID ENTER CONTAINMENT AREA - NO CLEAN UP"

All Materials:

Site ID:	274755
Operable Unit ID:	863771
Operable Unit:	01
Material ID:	512669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8604411 / 1987-01-14
Facility ID:	8604411
Site ID:	274757
Spill Date:	1986-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1987-01-14
SWIS:	6010
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-01-14
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-10-16
Spill Record Last Update:	1998-03-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"TTTF"

All TTF:

Facility ID:	8604411
Spill Number:	8604411
Spill Tank Test:	1530280
Site ID:	274757
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	274757
Operable Unit ID:	901332
Operable Unit:	01
Material ID:	477220
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	AMOCO GAS STATION
Address:	690 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9111342 / 1997-12-10
Facility ID:	9111342
Facility Type:	ER
DER Facility ID:	101511
Site ID:	116684
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1992-02-03
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1992-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-02-04
Spill Record Last Update:	2004-08-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 09/26/97 LETTER SENT; VES SYSTEM MUST BE OPERATING WITHIN ONE

AMOCO SERVICE STATION #736 (Continued) **1001128018**

WEEK OR EXPLAIN WHY IT ISN'T GOING TO BE 12/10/97 LETTER & SIGNED STIPULATION SENT; NFA. SEE SPILL 96-13029 FOR UPDATES. jod"

Remarks: "BALTEC ASSOC. ON SITE PERFORMING SOIL SURVEY TOOK SAMPLE BELOW GRADE AND FOUND FREE PRODUCT NO CALL BACK NEEDED"

All Materials:

Site ID:	116684
Operable Unit ID:	961469
Operable Unit:	01
Material ID:	416381
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	SUNOCO S/S
Address:	690 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9313209 / 1994-02-28
Facility ID:	9313209
Facility Type:	ER
DER Facility ID:	101511
Site ID:	116685
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	1994-02-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	1994-06-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/03/94: NO DEC RESPONSE. "
Remarks:	"ICE IN FILL BOX SORBENTS USED TO CLEAN UP"

All Materials:

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Site ID:	116685
Operable Unit ID:	995095
Operable Unit:	01
Material ID:	388600
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AM0CO STATION 736
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0002007 / 2000-05-17
Facility ID:	0002007
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274753
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2000-05-17
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-17
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-05-17
Spill Record Last Update:	2000-07-17
Spiller Name:	ALFRED
Spiller Company:	AM0CO STATION 736
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ALFRED
DEC Memo:	""
Remarks:	"maintance crew on the way for cleanup and repairs"

All Materials:

Site ID:	274753
Operable Unit ID:	823636
Operable Unit:	01
Material ID:	550387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	USA PETRO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0305414 / 2003-10-29
Facility ID:	0305414
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274756
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2003-08-21
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-08-21
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2003-10-29
Spiller Name:	Not reported
Spiller Company:	USA PETRO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	CINDY BADOLATO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BADOLATO 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED AS OF 9/12/03"
Remarks:	"leaking valve on a pump - pbs #3-183660 - pump taken out of service"

All Materials:

Site ID:	274756
Operable Unit ID:	873709
Operable Unit:	01
Material ID:	502669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9613029 / 2013-04-26
Facility ID:	9613029
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274758
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1997-01-29
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1997-02-04
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-04
Spill Record Last Update:	2013-04-26
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY ALSO SEE SPILL 91-11342. 02/07/97 AS PART OF AN ONGOING REMEDIATION THEY FOUND NEWER PRODUCT INFLUENCING THEIR CLEAN UP. 04/24/97 LETTER & STIPULATION AGREEMENT SENT TO BE SIGNED. 12/10/97 COPY OF SIGNED STIPULATION SENT BACK 08/11/98 LETTER SENT; IMMEDIATE ACTION TOWARD AUTOMATED PRODUCT REMOVAL AND GROUNDWATER CONTROL AT SITE IS REQUIRED. 12/07/00 LETTER SENT TO DELTA ENVIRONMENTAL BY J. HARDY; PROPOSE A REMEDIAL ACTION PLAN WHICH IS SUBSTANTIALLY MORE AGRESSIVE THAN THE ONE EXISTING AT THIS TIME. 01/11/01 LETTER SENT TO DELTA ENV. BY J. HARDY; CONCEPTUAL REMEDIAL ACTION PLAN OF 12/13/00 IS APPROVED & REQUIRED. 4/23/04: Letter to Aaron Lapine, Delta Env. Consultants by J. Hardy. Submit one report per year. Include operating data and GW monitoring data in same report. 8/9/04: Letter to A. Lapine, Delta Env. from J Hardy. Reduce monitor well sampling to semi-annual. Report annually. 6/15/09 annual submitted 6/9/09 shows relatively stable groundwater levels but no info as to system operation--sent email to envirotrac to submit operation info jh 4/20/10 site in remediation as system has been operating for many years. Original impacts to adjoining restaurant have also been resolved for years so it seems spill is contained; spill cannot be closed however as there is still significant contamination jh 07/02/12 Contaminated soils on the station have been excavated down to bedrock. 4 gw wells remain, 1 on-site upgradient, 2 off-site downgradient , 1 in the tank field. After review of the documentation

AMOCO SERVICE STATION #736 (Continued) **1001128018**

and a phone conversation, consultant will submit a quarterly groundwater monitoring plan for the next year, after which time the monitoring frequency may be adjusted based on results. It appears the source has been removed. mt 4/26/13 Spill Closed, asymptptic conditions approaching gw standards in final well. no further action required. mt "

Remarks: "THEY HAVE A 1991 SPILL NUMBER, BUT THIS APPEARS TO BE A FRESH SPILL UNK IF SAME"

All Materials:

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	2096843
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	341679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9806161 / 2005-02-14
Facility ID:	9806161
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274759
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-08-18
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-08-18
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-18
Spill Record Last Update:	2005-02-14
Spiller Name:	ERIC LISMANIS
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ERIC LISMANIS
DEC Memo:	"2/14/05 HANDLE AS PART OF 9613029--CLSOE"
Remarks:	"PUMP MALFUNCTION FOR UNDERGROUND STORAGE TANK / NO CLEAN UP"

All Materials:

Site ID:	274759
Operable Unit ID:	1067358
Operable Unit:	01
Material ID:	317336
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	AMOCO SERVICE STATION #736
Facility address:	690 MAIN ST NEW ROCHELLE, NY 10801
EPA ID:	NYR000036855
Mailing address:	OLD POST RD BALTEZ ASSOCIATES INC BEDFORD, NY 10506
Contact:	Not reported
Contact address:	OLD POST RD BEDFORD, NY 10506
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	AMOCO CORP
Owner/operator address:	300 INTERPACE PKWY MORRIS CORP PARSIPPANY, NJ 07054
Owner/operator country:	US
Owner/operator telephone:	201-331-7000
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AMOCO CORP
Owner/operator address: 300 INTERPACE PKWY MORRIS CORP
PARSIPPANY, NJ 07054
Owner/operator country: US
Owner/operator telephone: 201-331-7000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: AMOCO SERVICE STATION #736
Classification: Not a generator, verified

Date form received by agency: 1999-07-14 00:00:00.0
Site name: AMOCO SERVICE STATION #736
Classification: Small Quantity Generator

Date form received by agency: 1997-03-21 00:00:00.0
Site name: AMOCO SERVICE STATION #736
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

AMOCO SERVICE STATION #736 (Continued) **1001128018**

NY MANIFEST:

Name:	AMOCO SERVICE STATION #736
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000036855
Facility Status:	Not reported
Location Address 1:	690 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000036855
Mailing Name:	AMOCO SERVICE STATION #736
Mailing Contact:	JONATHAN LANDAU
Mailing Address 1:	130 BUSINESS PARK DR
Mailing Address 2:	Not reported
Mailing City:	ARMONK
Mailing State:	NY
Mailing Zip:	10504
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142349580

NY MANIFEST:

Document ID:	NYG0063774
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	04/27/1998
Trans1 Recv Date:	04/27/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000036855
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	GAD093380814
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

BJ374 **RESIDENCE** **NY LTANKS** **S107523528**
East **10 LAFAYETTE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.403 mi.
2129 ft. **Site 1 of 3 in cluster BJ**

Relative: **Lower**
Actual: **47 ft.**

LTANKS:

Name:	RESIDENCE
Address:	10 LAFAYETTE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512638 / 2006-03-15
Facility ID:	0512638
Site ID:	358990
Spill Date:	2006-02-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-01
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-01

RESIDENCE (Continued) **S107523528**

Spill Record Last Update:	2006-03-15
Spiller Name:	MARIO KOTLAR
Spiller Company:	RESIDENCE
Spiller Address:	10 LAFFEYTE ST
Spiller County:	001
Spiller Contact:	MARIO KOTLAR
Spiller Phone:	(914) 235-8882
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308993
DEC Memo:	"Northeast to return 2/3/06 for soil excavation & sampling. March 15, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 42.57 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallon."

All Materials:

Site ID:	358990
Operable Unit ID:	1116216
Operable Unit:	01
Material ID:	2106363
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG375 **YOUNG ADULT INSTITUTE** **NY LTANKS** **S107410752**
WNW **150 VAN GUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.403 mi.
2129 ft. **Site 2 of 2 in cluster BG**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Name:	YOUNG ADULT INSTITUTE
Address:	150 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0507808 / 2005-12-18
Facility ID:	0507808
Site ID:	353295
Spill Date:	2005-09-29
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-29
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

YOUNG ADULT INSTITUTE (Continued) **S107410752**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-29
Spill Record Last Update:	2005-12-18
Spiller Name:	MARGARET FORC
Spiller Company:	YOUNG ADULT INSTITUTE
Spiller Address:	150 VAN GUILDER AVE
Spiller County:	001
Spiller Contact:	MARGARET FORC
Spiller Phone:	(212) 273-6172
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300615
DEC Memo:	"Left message with contact. Robison returning to clean up fuel in street. New England was removing UST and some product leaked out of tank on ground. Area roped off by Fire Marshal. December 18, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 13.63 TONS OF CONTAMINATED SOIL. CLEAN UP COMPLETED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. DISPOSAL RECEIPT FORWARDED TO BECI. jod"
Remarks:	"550 GALLON TANK AND FOUND HOLES: FIRE MARSHALL ON SCENE"

All Materials:

Site ID:	353295
Operable Unit ID:	1110757
Operable Unit:	01
Material ID:	2100797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BK376 **COMMERCIAL-TTF** **NY LTANKS** **S117975659**
West **172 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.404 mi.
2131 ft. **Site 1 of 3 in cluster BK**

Relative: LTANKS:
Lower

Actual: **77 ft.**

Name:	COMMERCIAL-TTF
Address:	172 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1502358 / Not Reported
Facility ID:	1502358
Site ID:	508618
Spill Date:	2015-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	Unassigned

COMMERCIAL-TTF (Continued) **S117975659**

Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2015-08-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	463301
DEC Memo:	"6/3/15 Spoke to Mr. Scorzelli, who did not have contact info for owner at that time, and does not know what owner will be doing. dw "
Remarks:	"TEST FAILURE"

All Materials:

Site ID:	508618
Operable Unit ID:	1257927
Operable Unit:	01
Material ID:	2260991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BH377 **TAHIR RESIDENCE** **NY LTANKS** **S108299038**
NW **112 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.406 mi.
2144 ft. **Site 4 of 6 in cluster BH**

Relative: **Lower**
Actual: **69 ft.**

LTANKS:

Name:	GONZALO RESIDENCE
Address:	112 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0610140 / 2007-10-24
Facility ID:	0610140
Site ID:	374522
Spill Date:	2006-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported

TAHIR RESIDENCE (Continued) **S108299038**

SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-12-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-06
Spill Record Last Update:	2007-10-24
Spiller Name:	ISMAIL GALVAN
Spiller Company:	Not reported
Spiller Address:	112 SICKLES AVE
Spiller County:	001
Spiller Contact:	ISMAIL GALVAN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	324199
DEC Memo:	"09/18/07 Dutchess Environmental reported that the 550 gallon tank was removed and that no sign of oil contamination was observed in the tank grave. NFA TG"
Remarks:	"UNCOVER REPAIR AND TEST OR REMOVE"

All TTF:

Facility ID:	0610140
Spill Number:	0610140
Spill Tank Test:	1550484
Site ID:	374522
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	374522
Operable Unit ID:	1132196
Operable Unit:	01
Material ID:	2121918
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

TAHIR RESIDENCE (Continued) **S108299038**

Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: TAHIR RESIDENCE
Address: 112 SICKLES AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0911724 / 2010-03-22
Facility ID: 0911724
Facility Type: ER
DER Facility ID: 324199
Site ID: 424559
DEC Region: 3
Spill Cause: Human Error
Spill Class: B3
SWIS: 6010
Spill Date: 2010-02-02
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2010-02-03
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 2010-02-12
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-02-03
Spill Record Last Update: 2010-03-22
Spiller Name: CHRIS
Spiller Company: PARADISE OIL
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ISHMAEL TAHIR
DEC Memo: "2/3/10 homeowner, Mr. Tahir, is satisfied with cleanup done by Paradise Oil Co., both inside and outside the house. NFA dw 2/12/10: Spill re-opened. WCDOH reported this spill, after complaints by home owner that the oil company had taken no action. Marc Grazioli re-inspected the site today and reports the spill has still not been remediated. jod 2/17/10: Update from Marc Grazioli: The outside portion of the spill was handled before the big snow that came last week. I was only able to look into the basement through an open window since no one was home when I was there. There was absorbent on the ground and I would guess it was the second round of cleanup because it appeared dry. jod 3/22/10: DEC requires no further action at this time. jod"
Remarks: "5gals oil to basement area/10 gals to out side,driveway. Clean up complete"

All Materials:
Site ID: 424559
Operable Unit ID: 1180325

TAHIR RESIDENCE (Continued) **S108299038**

Operable Unit:	01
Material ID:	2174200
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BF378 **SCOT S/S** **NY LTANKS S110309404**
ENE **44 ECHO AVENUE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2148 ft. **Site 4 of 6 in cluster BF**

Relative: **Lower**

Actual: **32 ft.**

LTANKS:

Name:	MARIO'S S/S
Address:	44 ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9201557 / 2006-02-17
Facility ID:	9201557
Site ID:	130487
Spill Date:	1992-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	1992-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/17/06 SEE SPILLS 92-10118 AND 92-10810. jod"
Remarks:	"FOUND LINE LEAKING AT DISPENSER GASOLINE TANK IS OK MAIN & ELMSFORD TO POSS. REPAIR MONDAY WILLIAMS SUGGESTED TO MAIN & ELMSFORD CO. THAT THEUY SHUT THIS PUMP DOWN UNTIL REPAIRS ARE MADE SPOKE W/ WILL"

SCOT S/S (Continued) **S110309404**

All TTF:

Facility ID:	9201557
Spill Number:	9201557
Spill Tank Test:	1539973
Site ID:	130487
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130487
Operable Unit ID:	968828
Operable Unit:	01
Material ID:	412859
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	SCOTT S/S
Address:	44 ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9210810 / 1995-02-09
Facility ID:	9210810
Site ID:	130489
Spill Date:	1992-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1995-02-09
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True

SCOT S/S (Continued) **S110309404**

Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E.I.R. PETRO-TITE"

All TTF:

Facility ID:	9210810
Spill Number:	9210810
Spill Tank Test:	1540972
Site ID:	130489
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130489
Operable Unit ID:	975022
Operable Unit:	01
Material ID:	404252
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	DAVENPORT AUTO / WEST PLAINS SERVICE
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1001469 / 2010-11-01
Facility ID:	1001469
Site ID:	434525

SCOT S/S (Continued) **S110309404**

Spill Date:	2010-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-07
Spill Record Last Update:	2010-11-01
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	INA -
Spiller Phone:	(914) 235-8073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"5/7/10 Metro Env. tested UST, and it failed a TT. Davenport Auto thinks it may be fuel lines, and got list of contractors to examine problem more closely, and to determine remedial actions. Site is a WCHD-PBS site# 3-137480 Tank was tank #6- 550 gal. dw 11/1/10 As per WCDOH Two tanks pulled, reviewed TCR, recommend NFA. NFA JOM "
Remarks:	"tank test - cleanup pending"

All Materials:

Site ID:	434525
Operable Unit ID:	1185347
Operable Unit:	01
Material ID:	2179667
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	SCOT S/S
Address:	44 ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9210118 / 1997-11-07
Facility ID:	9210118
Facility Type:	ER

SCOT S/S (Continued) **S110309404**

DER Facility ID:	309856
Site ID:	130488
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1992-12-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-15
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"GASOLINE ODOR IN BASEMENT OF APARTMENT BUILDING NEXT DOOR TO GAS STATION GAS STATION RECEIVED A DELIVERY AT 8:00 A.M. T. GHIOSAY RESPONDED"

All Materials:

Site ID:	130488
Operable Unit ID:	976578
Operable Unit:	01
Material ID:	407123
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	ECHO SERVICE STATION
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1310365 / 2016-07-26
Facility ID:	1310365
Facility Type:	ER
DER Facility ID:	389397
Site ID:	491212
DEC Region:	3
Spill Cause:	Equipment Failure

SCOT S/S (Continued) **S110309404**

Spill Class:	C4
SWIS:	6010
Spill Date:	2014-01-29
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-29
Spill Record Last Update:	2016-07-26
Spiller Name:	Not reported
Spiller Company:	WEST PLAINS SERVICE INC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHAEL BURNSTEIN
DEC Memo:	"Chris Lalak called duty desk. American Petro is pulling tanks today. WCDOH is handling this and will do follow up...mm 1/29/2014 -- Called Pat Dunn @ APECCO to get some details. Dispensers had no sumps; discovered soil contamination under a dispenser. Trench along side dispenser is clean to 2 1/2 feet below grade; they expect limited dig and haul. ELM 2-11-14 Iyt was not a tank pull as originally noted by WCHD only line and dispenser replacement. RDB 2-13-14, spill #13-09599 was closed and referred to this one, the line test failure led to thic contamination RDB 03-14 contamination deep in excavation under former dispenser. crews worried about garage and building under neath, met on site with Gary and owner, advised them additional soil needed removal. 03-10-14 Using a Hydro Vac to get the remaining contaminated soils from excavation. 03-18-14 status report in edocs 05-13-14 email from Gary, Work done, report done,plan on forwarding report to you today once we get payment. RDB 07-22-14 gary looking for closure, I am looking for closure report.sent email requesting RDB 7-25-16 TCR submitted- Spill closed RDB"
Remarks:	"cleanup in progress"

All Materials:

Site ID:	491212
Operable Unit ID:	1240767
Operable Unit:	01
Material ID:	2240992
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BF379 **GAS STATION** **NY LTANKS** **S116156793**
ENE **44 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2148 ft. **Site 5 of 6 in cluster BF**

Relative: **Lower**
Actual: **32 ft.**

LTANKS:

Name:	GAS STATION
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1309599 / 2014-02-13
Facility ID:	1309599
Site ID:	490405
Spill Date:	2014-01-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-02
Spill Record Last Update:	2014-02-13
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CARLOS TORREZ
Spiller Phone:	(914) 424-5927
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"1/2/14 - WCDOH is oversight the ongoing tank tests. KAB 1/2/2014 -- APECCO hired by new operator (lease signed within past 6 weeks). Piping and dispensers and electronic leak monitoring equipment to be replaced. Based on lack of leak detection records for past 10 to 12 years, DEC requested TT and IS tests and system check of electronics. Tanks are probably suitable for service, but testing required for confirmation. It appears to be loose fittings. Electronics recently rewired at the computer console within past couple of weeks, but wiring ended near the top of the tanks. No probes in the interstitial space, just loose wiring near top of tank. Owner's representative took electronic system wire ends from the site despite WCDOH's request to take custody. ELM 2-13-14 closed and referred to spill 13-10365 which revealed contaminated soils when the failed lines were removed. RDB"
Remarks:	"repair/retest pending - to Ed Moore (waiting for results)"

All Materials:

Site ID:	490405
Operable Unit ID:	1239966

GAS STATION (Continued) **S116156793**

Operable Unit:	01
Material ID:	2240056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BJ380 **GONCALVES RESIDENCE** **NY LTANKS** **S102674341**
East **1 LAFFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.408 mi.
2152 ft. **Site 2 of 3 in cluster BJ**

Relative: **Lower**

Actual: **37 ft.**

LTANKS:

Name:	GONCALVES RESIDENCE
Address:	1 LAFFAYETTE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9410991 / 1994-11-29
Facility ID:	9410991
Site ID:	156301
Spill Date:	1994-11-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-11-29
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132292
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED 100 GAL. COULDN'T FIT BEING CLEANED NOW SPEEDI-DRI AND PADS COMPLETED"

GONCALVES RESIDENCE (Continued) **S102674341**

All Materials:

Site ID:	156301
Operable Unit ID:	1008868
Operable Unit:	01
Material ID:	376855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI381 **200 CENTRA CORP** **NY LTANKS** **S108059537**
SSE **200 CENTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.412 mi.
2173 ft. **Site 2 of 4 in cluster BI**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	200 CENTRA CORP
Address:	200 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0604650 / 2007-12-12
Facility ID:	0604650
Site ID:	367663
Spill Date:	2006-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-07-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-25
Spill Record Last Update:	2007-12-12
Spiller Name:	SHARON ROURKE
Spiller Company:	200 CENTRA CORP
Spiller Address:	200 CENTRE AVE
Spiller County:	001
Spiller Contact:	SHARON ROURKE
Spiller Phone:	(203) 557-3600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317637
DEC Memo:	"12/04/06 Tank removed and samples ok according to D Jackson - WCHD.

200 CENTRA CORP (Continued) **S108059537**

TG"
Remarks: "PBS No: 3-800237 -PBS No. not found in UIS, may be invalid. UNCOVER REPAIR AND TEST"

All TTF:
Facility ID: 0604650
Spill Number: 0604650
Spill Tank Test: 1550151
Site ID: 367663
Tank Number: 1
Tank Size: 5000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 367663
Operable Unit ID: 1125568
Operable Unit: 01
Material ID: 2115091
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

BF382 **CONSOLIDATED EDISON - ECHO AVE. SITE** **NY SHWS** **S101008407**
ENE **ECHO AVENUE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.412 mi.
2175 ft. **Site 6 of 6 in cluster BF**

Relative: **Lower**
Actual: **30 ft.**

SHWS:
Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Program: HW
Site Code: 56077
Classification: Not reported
Region: 3
Acres: 3
HW Code: 360016
Record Add: 11/18/1999
Record Upd: 05/01/2019
Updated By: AMOMOROG
Site Description: Location The Site is located at 78 Echo Avenue in New Rochelle,

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Westchester County, New York. This 3 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed, and the whole site has been levelled, top-soiled and grassed. Current Use The site is currently vacant Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. PCBs transformers were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. The soil on site and the sediment in the Bay were contaminated with PCBs.

Env Problem:	Prior to remediation the contaminant of concern was PCBs. Remediation of the site is complete. The cleanup of PCBs and other incidentally detected contaminants has mitigated the threat to the environment, and in particular to the natural habitat in the bay.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	4

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Sub Type:	E
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BK383 **FIRST ASSEMBLY OF GOD** **NY LTANKS** **S110490783**
West **177 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.414 mi.
2184 ft. **Site 2 of 3 in cluster BK**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:

Name:	FIRST ASSEMBLY OF GOD
Address:	177 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1002183 / 2010-08-30
Facility ID:	1002183
Site ID:	435290
Spill Date:	2010-05-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-26
Spill Record Last Update:	2010-08-30

FIRST ASSEMBLY OF GOD (Continued) **S110490783**

Spiller Name:	Not reported
Spiller Company:	BARNABY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BARNABY
Spiller Phone:	(914) 632-0031
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	390193
DEC Memo:	"7/1/10: No call backs made by dispatch desk. No indication of contamination at the time of the report. Unknown action at this time. jod 08/19/10 Northeast Environmental reported that they excavated and removed the LUST along with 40.92 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA. TG"
Remarks:	"550gal ust"

All Materials:

Site ID:	435290
Operable Unit ID:	1186074
Operable Unit:	01
Material ID:	2180843
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

384
WSW
1/4-1/2
0.415 mi.
2192 ft.

48 1ST STREET
48 1ST STREET
NEW ROCHELLE, NY

NY LTANKS **S104279084**
N/A

Relative:
Lower

Actual:
75 ft.

LTANKS:

Name:	48 1ST STREET
Address:	48 1ST STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9911183 / 1999-12-22
Facility ID:	9911183
Site ID:	116893
Spill Date:	1999-12-22
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	PJDECICC
Referred To:	Not reported
Reported to Dept:	1999-12-22
CID:	389
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

48 1ST STREET (Continued) **S104279084**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-22
Spill Record Last Update:	1999-12-30
Spiller Name:	CALLER
Spiller Company:	CASTLE OIL CORPORTATION
Spiller Address:	290 LOCUST AVENUE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	101696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO "
Remarks:	"caller reporting a spill of material from a tank overfill clean up was done no callback is necessary"

All Materials:

Site ID:	116893
Operable Unit ID:	1089889
Operable Unit:	01
Material ID:	296651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BJ385 **GONCALVES RESIDENCE** **NY LTANKS** **S108298870**
East **1 LAFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.415 mi.
2193 ft. **Site 3 of 3 in cluster BJ**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Name:	GONCALVES RESIDENCE
Address:	1 LAFAYETTE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0609401 / 2007-01-10
Facility ID:	0609401
Site ID:	373629
Spill Date:	2006-11-15
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-11-15
CID:	410

GONCALVES RESIDENCE (Continued) **S108298870**

Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-15
Spill Record Last Update:	2007-01-10
Spiller Name:	ED ALLEN
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323367
DEC Memo:	""
Remarks:	"CLEANUP IN PROGRESS:"

All Materials:

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

BH386 **RESIDENCE** **NY LTANKS** **S107410404**
NW **7 PRINCE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.416 mi.
2195 ft. **Site 5 of 6 in cluster BH**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Name:	RESIDENCE
Address:	7 PRINCE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0506424 / 2005-10-29
Facility ID:	0506424
Site ID:	351640
Spill Date:	2005-08-24
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-24
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-24
Spill Record Last Update:	2005-10-29
Spiller Name:	JOHN BROWN
Spiller Company:	RESIDENCE
Spiller Address:	7 PRINCE ST
Spiller County:	001
Spiller Contact:	JOHN BROWN
Spiller Phone:	(914) 879-7900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	298912
DEC Memo:	"Report to John O'Dee -RA October 29, 2005: CASTLTON DISPOSED OF LUST AND 57.27 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

All Materials:

Site ID:	351640
Operable Unit ID:	1109140
Operable Unit:	01
Material ID:	2099127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL387 **TROY RESIDENCE** **NY LTANKS** **S105997625**
WNW **150 LOCKWOOD AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.417 mi.
2202 ft. **Site 1 of 2 in cluster BL**

Relative: **Lower**

Actual: **83 ft.**

LTANKS:

Name:	TROY RESIDENCE
Address:	150 LOCKWOOD AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209497 / 2005-03-18
Facility ID:	0209497
Site ID:	221207
Spill Date:	2002-12-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-12-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2005-04-05
Spiller Name:	RICK TROY
Spiller Company:	RICK TROY
Spiller Address:	150 LOCKWOOD AV
Spiller County:	001
Spiller Contact:	RICK TROY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	182943
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 12/16/02: WCDOH ON SITE. 140 TONS SOIL REMOVED. CLOSURE REPORT PENDING. 04/08/03: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 3/26/2003. Closure report from GFE has been reviewed. Groundwater samples must be collected. Result submitted to WCHD by May 12, 2003. PBS #3-601067 & 3-601068. 08/13/02: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 7/21/03. Further remediation and quarterly sampling is required. Results of sampling are to be submitted to WCDOH quarterly. First report due by 9/01/2003. 5/25/04: Letter to Lockwood Realty, LLC, from Christopher Lalak, WCDOH, dated 25May2004. Two rounds of sampling have been received, third is overdue. Third round must be received by 25Jun2004. 11/22/04: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 17Nov2004. Based on groundwater sampling results, closure report and inspections, sampling must continue for the next year on a quarterly basis. After sampling, site will be reviewed. Next results due 28Feb2005. 4/4/05: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 18Mar2005. Spill has been

TROY RESIDENCE (Continued) **S105997625**

satisfactorily remediated. WCDOH requires NFA."
Remarks: "CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL"

All Materials:
Site ID: 221207
Operable Unit ID: 860802
Operable Unit: 01
Material ID: 512920
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: NEW ROCHELLE RADIOLOGY
Address: 150 LOCKWOOD AV
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0209877 / 2003-03-28
Facility ID: 0209877
Facility Type: ER
DER Facility ID: 182943
Site ID: 221208
DEC Region: 3
Spill Cause: Unknown
Spill Class: C3
SWIS: 6010
Spill Date: 2002-12-27
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-12-30
CID: 365
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-12-30
Spill Record Last Update: 2003-05-21
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "CALLER WENT TO HAVE A MAMMOGRAM DONE & SHE STAATED THE ENTIRE BLDG SMELLED LIKE FUEL OIL - UNK IF IT HAD TO DO WITH THE CONSTRUCTION THAT WAS GOING ON IN THE PARKING LOT OR NOT"

TROY RESIDENCE (Continued) **S105997625**

All Materials:

Site ID:	221208
Operable Unit ID:	861114
Operable Unit:	01
Material ID:	513296
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH388 **RENTAL HOUSE** **NY LTANKS** **S100153568**
NW **119 SICKLES AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.420 mi.
2218 ft. **Site 6 of 6 in cluster BH**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	RENTAL HOUSE
Address:	119 SICKLES AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9107320 / 1991-11-25
Facility ID:	9107320
Site ID:	119461
Spill Date:	1991-10-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	HOULIHAN & LAWRENCE RLTY.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	103766
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

RENTAL HOUSE (Continued) **S100153568**

GHIOSAY "
Remarks: "DISCOVERED SEEPAGE FROM TANK ON BASEMENT CONCRETE FLOOR APPLIED SPEEDI-DRY SPILLER WILL CONTACT LUZON OIL FOR CLEAN UP"

All Materials:
Site ID: 119461
Operable Unit ID: 961556
Operable Unit: 01
Material ID: 419532
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

BM389 **SPILL NUMBER 0104402** **NY LTANKS** **S105135031**
NE **30 LINCOLN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.425 mi.
2245 ft. **Site 1 of 2 in cluster BM**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:
Name: SPILL NUMBER 0104402
Address: 30 LINCOLN ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0104402 / 2001-11-14
Facility ID: 0104402
Site ID: 328750
Spill Date: 2001-07-24
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-07-25
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-25
Spill Record Last Update: 2002-02-07
Spiller Name: OWNER
Spiller Company: AVALLONE
Spiller Address: 30 LINCOLN ST
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported

SPILL NUMBER 0104402 (Continued) **S105135031**

DEC Region: 3
DER Facility ID: 264577
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/14/2001 G.C. RELIABLE PULLED TANK. NO LEAK OR DISCHARGE EVIDENT. NO FURTHER ACTION."
Remarks: "failed test"

All TTF:
Facility ID: 0104402
Spill Number: 0104402
Spill Tank Test: 1526481
Site ID: 328750
Tank Number: 1
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 328750
Operable Unit ID: 841036
Operable Unit: 01
Material ID: 532897
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BK390 **SPILL NUMBER 0210366** **NY LTANKS** **S105997907**
West **182 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.426 mi.
2251 ft. **Site 3 of 3 in cluster BK**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:
Name: SPILL NUMBER 0210366
Address: 182 UNION AV
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0210366 / 2003-03-03
Facility ID: 0210366
Site ID: 282696
Spill Date: 2003-01-14
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3

SPILL NUMBER 0210366 (Continued) **S105997907**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-14
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229505
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Jan 2003 - 1000 gallon tank was removed from the property. 100 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environemtal Assessement. NFA. TG"
Remarks:	"SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL AT ABOVE LOCATION. PROPTERY IS OWNED BY THE CITY OF NEW ROCHELLE AND CALLER IS A CONTRACTOR FOR THE CITY. TANK APPEARS TO HAVE BEEN ABANDONED YEARDS AGO. "

All Materials:

Site ID:	282696
Operable Unit ID:	861605
Operable Unit:	01
Material ID:	513753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI391 **APT. BUILDING** **NY LTANKS** **S102674170**
SSE **208 CENTER AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2275 ft. **Site 3 of 4 in cluster BI**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Name:	APT. BUILDING
Address:	208 CENTER AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9314003 / 1994-03-11
Facility ID:	9314003
Site ID:	215702
Spill Date:	1994-02-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1994-03-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-11
Spill Record Last Update:	1995-01-05
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK WAS OVERFILLED CASTLE CREW TO CLEAN UP"

All Materials:

Site ID:	215702
Operable Unit ID:	996014
Operable Unit:	01
Material ID:	389350
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APT. BUILDING (Continued) **S102674170**

Name:	APT. BUILDING
Address:	208 CENTER AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9315255 / 1994-04-11
Facility ID:	9315255
Site ID:	215703
Spill Date:	1994-03-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-04-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-11
Spill Record Last Update:	1995-01-04
Spiller Name:	Not reported
Spiller Company:	WRG
Spiller Address:	420 WESTCHESTER AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY GUAGE RESULTED IN OVERFILL WCHD NOTIFIED CASTLE OIL WILL CLEAN UP"

All Materials:

Site ID:	215703
Operable Unit ID:	997178
Operable Unit:	01
Material ID:	387016
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 0202241
Address:	208 CENTER AVE

APT. BUILDING (Continued) **S102674170**

City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0202241 / 2002-08-12
Facility ID:	0202241
Facility Type:	ER
DER Facility ID:	177797
Site ID:	214599
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2002-06-01
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-06-01
CID:	257
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-01
Spill Record Last Update:	2002-09-26
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	208 CENTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"bad gauge - contained - cleanup to be done by castleton enviromental"
	Not reported

All Materials:

Site ID:	214599
Operable Unit ID:	855230
Operable Unit:	01
Material ID:	520107
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM392 **SPILL NUMBER 0300463** **NY LTANKS** **S105998684**
NE **52 LINCOLN ST** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2277 ft. **Site 2 of 2 in cluster BM**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:

Name:	SPILL NUMBER 0300463
Address:	52 LINCOLN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0300463 / 2003-04-14
Facility ID:	0300463
Site ID:	202585
Spill Date:	2003-04-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-22
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	168519
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"Above material reported spilled at above location due to tank overfill. Crew is on site and cleanup is in progress at time of call. All material is expected to be recovered."

All Materials:

Site ID:	202585
Operable Unit ID:	868761
Operable Unit:	01
Material ID:	508540
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILL NUMBER 0300463 (Continued) **S105998684**

SPILLS:

Name:	VACCARO RESIDENCE
Address:	52 LINCOLN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0806544 / 2008-12-26
Facility ID:	0806544
Facility Type:	ER
DER Facility ID:	168519
Site ID:	403827
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2008-09-10
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-09-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-11
Spill Record Last Update:	2008-12-26
Spiller Name:	LOUIS VACCARO
Spiller Company:	LOIS VACCARO
Spiller Address:	52 LINCOLN ST
Spiller Company:	999
Contact Name:	LOUIS VACCARO
DEC Memo:	"11/16/08 New England Tank Services reported that they removed one 550 gallon tank along with 7.09 tons of petroleum contaminated soil. NFA TG"
Remarks:	"Callers company was removing a 550 gallon tank and found it had holes in it. Unknown how much fuel had been leaking or for how long. Clean up will start within the next few days."

All Materials:

Site ID:	403827
Operable Unit ID:	1160514
Operable Unit:	01
Material ID:	2151689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BN393 **DEFENDER MARINE SUPPLY** **NY LTANKS** **S103479285**
ENE **309 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.438 mi.
2310 ft. **Site 1 of 2 in cluster BN**

Relative: **Lower**
Actual: **26 ft.**

LTANKS:

Name:	DEFENDER MARINE SUPPLY
Address:	309 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9806235 / 2002-09-19
Facility ID:	9806235
Site ID:	93459
Spill Date:	1998-08-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-08-19
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-19
Spill Record Last Update:	2002-09-19
Spiller Name:	WILLIAM GOING
Spiller Company:	DEFENDER MARINE SUPPLY
Spiller Address:	309 MAIN ST
Spiller County:	001
Spiller Contact:	WILLIAM GOING
Spiller Phone:	(914) 744-3705
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83786
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/19/98 WCHD NOTIFIED. 09/14/02 - 8 TO 10 YARDS OF SOIL STOCKPILED. CLOSURE REPORT TO FOLLOW ONCE SAMPLE RESULTS RECEIVED. 09/19/02 CLOSURE REPORT RECEIVED FROM WILLIAM GOING. DISPOSAL OF TANK AND 10.45 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"during a tank removal caller found contamined soil"

All Materials:

Site ID:	93459
Operable Unit ID:	1067422
Operable Unit:	01
Material ID:	317407
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

DEFENDER MARINE SUPPLY (Continued) **S103479285**

Oxygenate: Not reported

BO394 **SPILL NUMBER 0009195** **NY LTANKS** **S104877181**
SSE **17 POPLAR PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.438 mi.
2315 ft. **Site 1 of 3 in cluster BO**

Relative: **Lower**
Actual: **74 ft.**

LTANKS:

Name:	SPILL NUMBER 0009195
Address:	17 POPLAR PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0009195 / 2001-01-08
Facility ID:	0009195
Site ID:	63217
Spill Date:	2000-11-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-09
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-09
Spill Record Last Update:	2001-02-02
Spiller Name:	DESIGN BUILDERS GROUP
Spiller Company:	Not reported
Spiller Address:	17 POPLAR PL
Spiller County:	001
Spiller Contact:	DESIGN BUILDERS GROUP
Spiller Phone:	(914) 948-9785
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	61128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/17/2000 TANK TEST FAILURE LETTER SENT. TANK SCHEDULED FOR RETEST ON 11/20/00. 01/08/2001 ENVIROSTAR PULLED TANK. TANK WAS SOUND, NO RELEASE. EVIROSTAR REPORTS TANK FAILED DUE TO FAULTY OIL LINES. NO CONTAMINATION FOUND. NO FURTHER ACTION REQUIRED."
Remarks:	"uncover repair retest"

All Materials:

Site ID:	63217
Operable Unit ID:	831505
Operable Unit:	01
Material ID:	543152
Material Code:	0001A
Material Name:	#2 fuel oil

SPILL NUMBER 0009195 (Continued) **S104877181**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI395 **RESIDENCE** **NY LTANKS** **S106124419**
SSE **6 POPLAR ROAD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.439 mi.
2319 ft. **Site 4 of 4 in cluster BI**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Name:	RESIDENCE
Address:	6 POPLAR ROAD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0310014 / 2012-08-13
Facility ID:	0310014
Site ID:	82997
Spill Date:	2003-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-11-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RUDY TAYLOR
Spiller Phone:	(914) 833-0287
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76439
DEC Memo:	"7/29/10 Homeowner TTF JO'M 7/25/12: There is no such address as 6 Poplar Road in New Rochelle. This should either be 6 Poplar Road in Larchmont, or 6 Poplar Place in New Rochelle. jod 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"
Remarks:	""

All TTF:

Facility ID:	0310014

RESIDENCE (Continued) **S106124419**

Spill Number:	0310014
Spill Tank Test:	1528823
Site ID:	82997
Tank Number:	1
Tank Size:	500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	82997
Operable Unit ID:	875149
Operable Unit:	01
Material ID:	498967
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

---

396 **WALTON RESIDENCE** **NY LTANKS** **S108639866**
NW **129 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.442 mi.
2333 ft.

Relative:
Lower

Actual:
67 ft.

LTANKS:

Name:	WALTON RESIDENCE
Address:	129 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0703375 / 2007-08-28
Facility ID:	0703375
Site ID:	383296
Spill Date:	2007-06-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-06-22
CID:	408
Water Affected:	Not reported
Spill Notifier:	Other

WALTON RESIDENCE (Continued) **S108639866**

Last Inspection:	2007-06-28
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-22
Spill Record Last Update:	2007-08-28
Spiller Name:	MARGRET WALTON
Spiller Company:	PRIVATE HOME
Spiller Address:	129 SICKLES AVE
Spiller County:	001
Spiller Contact:	MARGRET WALTON
Spiller Phone:	(914) 235-5241
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	332760
DEC Memo:	"6/29/07: Envirotrac is consultant for insurance company. Report to follow. jod 08/08/07 Northeast Environmental reported that the tank was excavated and removed along with 19.85 tons of impacted soil. NFA TG"
Remarks:	"soil contamination found during tank removal; NOT YET CONTAINED OR CLEANED;"

All Materials:

Site ID:	383296
Operable Unit ID:	1140659
Operable Unit:	01
Material ID:	2130748
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

397
South
1/4-1/2
0.442 mi.
2333 ft.

LIPMAN RESIDENCE
54 LIBERTY AVE
NEW ROCHELLE, NY

NY LTANKS **S106971579**
N/A

Relative:
Lower

Actual:
48 ft.

LTANKS:

Name:	LIPMAN RESIDENCE
Address:	54 LIBERTY AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0409061 / 2005-04-02
Facility ID:	0409061
Site ID:	333699
Spill Date:	2004-11-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee

LIPMAN RESIDENCE (Continued) **S106971579**

Referred To:	Not reported
Reported to Dept:	2004-11-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-16
Spill Record Last Update:	2005-04-02
Spiller Name:	JOSH LITSMAN
Spiller Company:	LISTMAN RESIDENCE
Spiller Address:	54 LIBERTY AVE
Spiller County:	001
Spiller Contact:	JOSH LITSMAN
Spiller Phone:	(914) 813-5024
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268950
DEC Memo:	"02/18/04 ZURICH CLAIM BEING HANDLED BY LEWIS ENVIRONMENTAL. SMALL AMOUNT OF CONTAMINATION UNDER PUBLIC SIDEWALK/ROADWAY CANNOT BE REMOVED SAFELY. DEC SPOKE WITH LEWIS (BOB KRAUSE) ABOUT SAMPLING REQUIREMENTS. REPORT TO FOLLOW. jod 04/02/05 LEWIS ENVIRONMENTAL DISPOSED OF LUST AND 82.08 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SOILTEST CAME BACK OVER THE LIMIT:"

398
East
1/4-1/2
0.443 mi.
2341 ft.

FIUMFREDO RESIDENCE **NY LTANKS** **S111012239**
12 BAYVIEW AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
47 ft.

LTANKS:

Name:	FIUMFREDO RESIDENCE
Address:	12 BAYVIEW AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1100096 / 2011-09-22
Facility ID:	1100096
Site ID:	447470
Spill Date:	2011-04-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D2
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2011-08-08
Recommended Penalty:	False
Meets Standard:	False

FIUMFREDO RESIDENCE (Continued) **S111012239**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-04
Spill Record Last Update:	2011-09-22
Spiller Name:	ROSE FIUMFREDO
Spiller Company:	ROSE FIUMFREDO
Spiller Address:	12 DAYVIEW AVE
Spiller County:	999
Spiller Contact:	ROSE FIUMFREDO
Spiller Phone:	(914) 632-0496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402070
DEC Memo:	"4/4/11 - To retest tank. KAB 4/28/11 Morris called in for follow up. Tank failed again. He said tank top was exposed for most of length and one side and some samples taken. Morris said whoever did repairs, sounds like they only put a new vent riser on. Did not check piping, which is heavily crusted. jc 5-6-11 Failed 2nd retest today. Owner giving Kathy a hard time. Morris will retest again next week. Kathy said road name should be Bayview not Dayview, made change. jc 5/13/11 Tank failed for a 3rd time. Plan to pull, according to Tank Tech. dw 8-4-11 Homeowner called dispatch desk. He wants to remove the tank himself and do ALL of the work. He says he would cut open the tank and clean with speedi dri, dispose of tank at scrap yard, etc. I recommended that he hire an environmental consultant to AT LEAST oversee project because the DEC will need a TCR which would include soil samples, manifests, disposal receipts, etc. I told him that this spill will not be closed out until a proper and acceptable Tank Closure Report has been submitted to this office for review. I told him to contact J O'Dee in White Plains for further info. This guy seems bent on doing everything himself even though it was recommended that he hire a consultant to oversee the project. jm 8/4/11: Recieved call from Sandy Perratta 914-557-0142. He is the same individual who called the dispatch desk earlier today. He is not the property owner but a friend of the owner. States he is in the construction business and he can remove the tank himself. He states he has the OSHA 30-hour training and also states he knows that he doesn't need confined space entry training if the tank is less than 4 feet below ground . I again stated he should have a professional contractor do the work for safety reasons. jod 8/8/11: Received voice-mail message from Mr Perratta stating he had removed the tank and it was on the lawn awaiting a DEC drive-by inspection. I met New Rochelle Fire Captain Henry Senno on site. The tank was cut and cleaned and is on plastic. The excavation is open and is not fenced or secured. There is no evidence of any holes in the tank, and no evidence of any leak or contamination. Captain Senno states he will follow up with the owner, as no permits were filed for the removal as required in New Rochelle. DEC Spills requires no further action at this time. jod 9/8/11: I left this spill open after discussing the situation with Capt Senno on either August 9th or 10th. There was still a 55-gallon drum of heating oil and heating oil sludge that was removed from the tank remaining on the site. On either Aug 11th or 12th I spoke with Mr Perrotta and stated the spill would be left open until he submitted a disposal receipt to DEC for proper disposal of that waste drum. To date, Mr Perrotta has submitted a disposal recipt for the tank (entered in eDocs) but has not submitted a disposal receipt for the drum. jod 9/22/11: Letter from Linda Enes forwarded to DEC. She

FIUMFREDO RESIDENCE (Continued) **S111012239**

states she is in posesseion of the 55-gallon drum, and is using it to fuel a space heater. I called her this morning and she states her husband transported the drum in his pick-up truck from New Rochelle to their home in Dover Plains NY. Letter has been entered into eDocs. DEC requires no further action. jod"

Remarks: "repair/retest pending"

All Materials:

Site ID:	447470
Operable Unit ID:	1197626
Operable Unit:	01
Material ID:	2193927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BN399 **TELEDYNE HYDRA-POWER** **NY SWF/LF** **1000201735**
ENE **310 MAIN ST** **NY Spills** **NYD001650209**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.444 mi. **FINDS**
2342 ft. **Site 2 of 2 in cluster BN** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
24 ft.

SWF/LF:

Name:	PAR TRADING INC
Address:	310 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[60J11]
Active:	No
East Coordinate:	603184
North Coordinate:	4529831
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

SPILLS:

Name:	CAR DEALER
Address:	310 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0713299 / 2010-11-30
Facility ID:	0713299
Facility Type:	ER
DER Facility ID:	344570
Site ID:	395027
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-03-17
Investigator:	jkomara
Referred To:	WCDOH - PBS
Reported to Dept:	2008-03-17
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-17
Spill Record Last Update:	2010-11-30
Spiller Name:	MIMI
Spiller Company:	CAR DEALER
Spiller Address:	310 MAIN STREET
Spiller Company:	001
Contact Name:	MIMI
DEC Memo:	"11/30/10 No Info 3 years old spills will nbot be following up NFA JO'M "
Remarks:	"DURING SOIL BORINGS FOUND CONTAMINTAED SOIL"

All Materials:

Site ID:	395027
Operable Unit ID:	1151973
Operable Unit:	01
Material ID:	2142744
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Name:	M TECH MOTORS
Address:	310 MAIN ST REAR
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1408123 / 2014-11-06
Facility ID:	1408123
Facility Type:	ER
DER Facility ID:	456652
Site ID:	501675
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2014-11-06
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2014-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2014-11-06
Spiller Name:	MIKE TASHENT
Spiller Company:	M TECH MOTORS
Spiller Address:	310 MAIN ST REAR
Spiller Company:	999
Contact Name:	MIKE TASHENT
DEC Memo:	"11/6/14- Spoke to caller. He was on site and noted where auto shop flushed some waste oil to roadside curb. Cleanup completed by spiller with speedidry. Caller states cleanup is complete. NFA DT"
Remarks:	"loss to sewer and roadway. C/u in progress"

All Materials:

Site ID:	501675
Operable Unit ID:	1251062
Operable Unit:	01
Material ID:	2252898
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	TELEDYNE HYDRA-POWER
Facility address:	310 MAIN ST

TELEDYNE HYDRA-POWER (Continued) **1000201735**

NEW ROCHELLE, NY 10801-5716
EPA ID: NYD001650209
Mailing address: MAIN ST
NEW ROCHELLE, NY 10801
Contact: Not reported
Contact address: MAIN ST
NEW ROCHELLE, NY 10801
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: TELEDYNE HYDRA-POWER
Owner/operator address: 310 MAIN ST
NEW ROCHELLE, NY 10801
Owner/operator country: US
Owner/operator telephone: 914-632-2200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TELEDYNE HYDRA-POWER
Owner/operator address: 310 MAIN ST
OPERCITY, NY 99999
Owner/operator country: US
Owner/operator telephone: 914-632-2200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 1980-11-19 00:00:00.0
Site name: TELEDYNE HYDRA-POWER
Classification: Not a generator, verified

Date form received by agency: 1980-08-18 00:00:00.0
Site name: TELEDYNE HYDRA-POWER
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U238
. Waste name: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 1987-08-27 00:00:00.0
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 1986-03-19 00:00:00.0

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:
Registry ID: 110004335808

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000201735
Registry ID: 110004335808
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004335808
Name: TELEDYNE HYDRA-POWER
Address: 310 MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801

NY MANIFEST:
Name: TELEDYNE HYDRA POWER INC
Address: 310 MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801-5716
Country: USA
EPA ID: NYD001650209
Facility Status: Not reported
Location Address 1: 310 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: 5716

NY MANIFEST:
EPAID: NYD001650209
Mailing Name: TELEDYNE HYDRA POWER INC
Mailing Contact: RICHARD C. SNYDER
Mailing Address 1: 10-12 PINE COURT
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10801
Mailing Zip 4: Not reported
Mailing Country: USA

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Mailing Phone: 9146322200

NY MANIFEST:

Document ID:	PAC6193121
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	PAAH0421
Trans2 State ID:	Not reported
Generator Ship Date:	01/21/1993
Trans1 Recv Date:	01/21/1993
Trans2 Recv Date:	01/22/1993
TSD Site Recv Date:	01/22/1993
Part A Recv Date:	02/02/1993
Part B Recv Date:	02/04/1993
Generator EPA ID:	NYD001650209
Trans1 EPA ID:	CTD983883745
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

400
WSW
1/4-1/2
0.447 mi.
2360 ft.

WILLIAMS TTF **NY LTANKS** **S104276929**
23 1ST ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
57 ft.

LTANKS:

Name:	WILLIAMS TTF
Address:	23 1ST ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9702187 / 1999-06-10

WILLIAMS TTF (Continued) **S104276929**

Facility ID:	9702187
Site ID:	102476
Spill Date:	1997-05-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-20
CID:	369
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-20
Spill Record Last Update:	2018-01-24
Spiller Name:	Not reported
Spiller Company:	MR WILLIAMS
Spiller Address:	23 FIRST ST
Spiller County:	001
Spiller Contact:	BRIAN SCHUG
Spiller Phone:	(914) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90745
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING SITE EVALUATION-CALLER WILL REMOVE SOIL-CLEANUP IN PROGRESS"

All Materials:

Site ID:	102476
Operable Unit ID:	1048062
Operable Unit:	01
Material ID:	335128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

401
SW
1/4-1/2
0.448 mi.
2367 ft.

RESIDENCE
38 BEECHWOOD AVE
NEW ROCHELLE, NY

NY LTANKS **S102660166**
N/A

Relative:
Lower

Actual:
37 ft.

LTANKS:

Name:	RESIDENCE
Address:	38 BEECHWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9705244 / 1997-11-10
Facility ID:	9705244
Site ID:	105369
Spill Date:	1997-07-31
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-31
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-31
Spill Record Last Update:	1998-02-05
Spiller Name:	MARVIN KAPUS
Spiller Company:	Not reported
Spiller Address:	38 BEECHWOOD AVE
Spiller County:	001
Spiller Contact:	MARVIN KAPUS
Spiller Phone:	(914) 738-1351
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92963
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/31/97 CONTAMINATED SOIL BEING REMOVED & STOCKPILED; 08/01/97 TANK FOUND DURING DEMOLITION OF HOUSE; TANK AND CONTAMINATION REMOVED; "
Remarks:	"demolition of building - ust 550 gal tank - tank had holes in it contaminated soil found "

All Materials:

Site ID:	105369
Operable Unit ID:	1048510
Operable Unit:	01
Material ID:	334464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

RESIDENCE (Continued) **S102660166**

Oxygenate: Not reported

BO402 **FUNICELOLO HOME** **NY LTANKS** **S107489124**
SSE **24 POPLAR PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.450 mi.
2374 ft. **Site 2 of 3 in cluster BO**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Name:	FUNICELOLO HOME
Address:	24 POPLAR PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0509719 / 2006-11-19
Facility ID:	0509719
Site ID:	355533
Spill Date:	2005-11-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-11-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-14
Spill Record Last Update:	2006-11-19
Spiller Name:	FUNICEOLO HOME
Spiller Company:	FUNICELOLO HOME
Spiller Address:	24 POPULAR PLACE
Spiller County:	001
Spiller Contact:	FUNICEOLO HOME
Spiller Phone:	(914) 636-5043
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305561
DEC Memo:	"PLAN WAS TO ABANDON BUT FOUND HOLES SO NOWTHEY WILL REMOVE NO KNOWN EXPERTS AT THIS TIME November 19, 2006: ONE HOLE FOUND ON TOP OF TANK. TANK CANNOT BE REMOVED DUE TO SAFETY AND STRUCTURAL CONSIDERATIONS. MUNICIPAL WATER AND SEWER. ROYAL ENVIRONMENTAL TOOK A GROUND WATER SAMPLE BENATH TANK, ALL ANALYTES NON-DETECT. TANK ABANDONED IN PLACE WITH SLURRY. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES FOUND IN A 1000 GALLON TANK;"

All Materials:

Site ID:	355533
Operable Unit ID:	1112888
Operable Unit:	01
Material ID:	2102930

FUNICELOLO HOME (Continued) **S107489124**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO403 **LABELLA RESIDENCE** **NY LTANKS** **S107789449**
SSE **219 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.454 mi.
2395 ft. **Site 3 of 3 in cluster BO**

Relative: **Lower**

Actual: **72 ft.**

LTANKS:

Name:	LABELLA RESIDENCE
Address:	219 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601959 / 2009-09-01
Facility ID:	0601959
Site ID:	364328
Spill Date:	2006-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2009-09-01
Spiller Name:	LARRY LABELLA
Spiller Company:	LABELLA RESIDENCE
Spiller Address:	219 CENTRAL AVE
Spiller County:	001
Spiller Contact:	LARRY LABELLA
Spiller Phone:	(914) 654-0719
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	314554
DEC Memo:	"05/24/06: Soil samples clean. US Tank Tech will be repairing and retesting. 9/1/09: Tank passed a retest in isolation on 6-13-06. At that time, new fuel lines had been run from the tank to the boiler room but were not hooked up at the time of the test. A full system test was performed 7-24-09 with the lines connected. The tank system passed this retest. Based upon the information provided, no further action is required at this time. jod"

LABELLA RESIDENCE (Continued) **S107789449**

Remarks: "UNCOVER REPAIR AND RETEST."

All TTF:

Facility ID:	0601959
Spill Number:	0601959
Spill Tank Test:	1550008
Site ID:	364328
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	364328
Operable Unit ID:	1122357
Operable Unit:	01
Material ID:	2111830
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

404 West 1/4-1/2 0.459 mi. 2421 ft.

SPILL NUMBER 0210080
196 UNION AV
NEW ROCHELLE, NY

NY LTANKS **S105997807** **N/A**

Relative: Lower

Actual: 71 ft.

LTANKS:

Name:	SPILL NUMBER 0210080
Address:	196 UNION AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0210080 / 2003-03-03
Facility ID:	0210080
Site ID:	155360
Spill Date:	2003-01-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-06

SPILL NUMBER 0210080 (Continued) **S105997807**

CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-06
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131601
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Dec. 2002 - One 1200 gallon tank was removed from the property. 300 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environmetnal Assessment. NFA. TG"
Remarks:	"1200 GAL UNDERGROUND STORAGE TANK - 4 OTHER SPILL #'S ON THIS SAME SITE - DELORES FROM DEC SAYS THEY NEED ANOTHER NEW SPILL #"

All Materials:

Site ID:	155360
Operable Unit ID:	861323
Operable Unit:	01
Material ID:	513483
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BP405 **RESIDENCE** **NY LTANKS** **S105230245**
South **98 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.459 mi.
2425 ft. **Site 1 of 4 in cluster BP**

Relative:
Lower

Actual:
46 ft.

LTANKS:

Name:	RESIDENCE
Address:	98 LIBERTY AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0107187 / 2002-01-11
Facility ID:	0107187
Site ID:	204562
Spill Date:	2001-10-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

RESIDENCE (Continued) **S105230245**

Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-10-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-11
Spill Record Last Update:	2002-03-22
Spiller Name:	REALTOR
Spiller Company:	MR GAMIANO
Spiller Address:	98 LIBERTY AVE
Spiller County:	001
Spiller Contact:	CAROL MASCOLINO-REALTOR
Spiller Phone:	(914) 576-1112
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170048
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/11/2002 ADVANCED PULLED TANK AND 99.6 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"PETROLEUM ODOR AND STAINING IN THE SOIL-RECOMMEND TANK REMOVAL"

All TTF:

Facility ID:	0107187
Spill Number:	0107187
Spill Tank Test:	1526660
Site ID:	204562
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	204562
Operable Unit ID:	844253
Operable Unit:	01
Material ID:	532018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RESIDENCE (Continued) **S105230245**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL406 **MANONE PLACE** **NY LTANKS** **S107523607**
WNW **15 COLONIAL PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.462 mi.
2437 ft. **Site 2 of 2 in cluster BL**

Relative: **Lower**

Actual: **84 ft.**

LTANKS:

Name:	MANONE PLACE
Address:	15 COLONIAL PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513004 / 2006-05-08
Facility ID:	0513004
Site ID:	359413
Spill Date:	2006-02-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-09
Spill Record Last Update:	2006-05-08
Spiller Name:	FLORENCE MANONE
Spiller Company:	MANONE PLACE
Spiller Address:	15 COLONIAL PLACE
Spiller County:	001
Spiller Contact:	FLORENCE MANONE
Spiller Phone:	(914) 633-7791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309466
DEC Memo:	"John O'Dee is lead and will/has contacted. May 8, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND FIVE DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 GALLON TANK, HOLES AND CONTAMINATION, WOULD LIKE A CALL BACK PERTAINING TO THIS PROPERTY"

All Materials:

Site ID:	359413
Operable Unit ID:	1116622

MANONE PLACE (Continued) **S107523607**

Operable Unit:	01
Material ID:	2107064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

407 **TRINITY ARMS APARTMENTS** **NY LTANKS** **S109416298**
SSE **25 TRINITY PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.466 mi.
2461 ft.

Relative: **Lower**

Actual: **70 ft.**

LTANKS:

Name:	TRINITY ARMS APARTMENTS
Address:	25 TRINITY PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0811859 / 2009-04-22
Facility ID:	0811859
Site ID:	409448
Spill Date:	2009-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-30
Spill Record Last Update:	2009-04-22
Spiller Name:	WILLY SILSDORF
Spiller Company:	TRINITY ARMS LTD
Spiller Address:	25 TRINITY PLACE
Spiller County:	999
Spiller Contact:	LARRY BOYD
Spiller Phone:	(914) 682-5676
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Spoke to W. Silsdorf. Think it may be leak in piping or fitting. Will probably Uncover, repair and retest. dvw 04/21/09 Wayne Schnieder reported ttf 1/3/09. passing retest after line replacement. No contamination. NFA TG "
Remarks:	"Caller states he performed a EZ-3 test and had a failure. Caller

TRINITY ARMS APARTMENTS (Continued) **S109416298**

does not believe a spill or resources are affected."

All Materials:

Site ID:	409448
Operable Unit ID:	1165955
Operable Unit:	01
Material ID:	2157389
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	APT BLDG
Address:	25 TRINITY PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8905211 / 1992-07-30
Facility ID:	8905211
Site ID:	283512
Spill Date:	1989-08-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ANN JASLOCKI
Spiller Address:	REAL ESTATE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"4K PETRO TITE, -.234 GPH"

All TTF:

Facility ID:	8905211
Spill Number:	8905211

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Spill Tank Test:	1535913
Site ID:	283512
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	283512
Operable Unit ID:	932936
Operable Unit:	01
Material ID:	445651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BQ408 **SPILL NUMBER 9814027** **NY LTANKS** **S104619985**
NW **48 REMINGTON PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.470 mi.
2484 ft. **Site 1 of 2 in cluster BQ**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Name:	SPILL NUMBER 9814027
Address:	48 REMINGTON PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9814027 / 1999-02-19
Facility ID:	9814027
Site ID:	80830
Spill Date:	1999-02-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-19
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

SPILL NUMBER 9814027 (Continued) **S104619985**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-19
Spill Record Last Update:	1999-03-01
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AV
Spiller County:	001
Spiller Contact:	MAMMY JONES
Spiller Phone:	(914) 636-5128
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74863
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"STORAGE TANK OVERFILL - TANK IS OUTSIDE UNDERGROUND - CONTAMINATED SOIL WAS REMOVED & REPLACED WITH FRESH SOIL"

All Materials:

Site ID:	80830
Operable Unit ID:	1071478
Operable Unit:	01
Material ID:	310733
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

---

409 **RITACCO HOME** **NY LTANKS** **S107789088**
ENE **24 JACKSON STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.471 mi.
2487 ft.

Relative: **Lower**

Actual: **24 ft.**

LTANKS:

Name:	RITACCO HOME
Address:	24 JACKSON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600187 / 2006-07-28
Facility ID:	0600187
Site ID:	362141
Spill Date:	2006-04-06
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-06
CID:	444

RITACCO HOME (Continued) **S107789088**

Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-06
Spill Record Last Update:	2006-07-28
Spiller Name:	RITACCO HOME
Spiller Company:	RITACCO HOME
Spiller Address:	24 JACKSON STREET
Spiller County:	001
Spiller Contact:	RITACCO HOME
Spiller Phone:	(914) 576-1430
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	312378
DEC Memo:	"04/10/06: Northeast to continue remediation. No GW involved as of now. July 28, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.00 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES IN A 550 GALLON AND CONTAMINATED SOIL;"

All Materials:

Site ID:	362141
Operable Unit ID:	1120244
Operable Unit:	01
Material ID:	2109739
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

410
East
1/4-1/2
0.474 mi.
2502 ft.

CON EDISON - ECHO AVENUE SUBSTATION **SEMS-ARCHIVE** **1000111631**
ECHO AVENUE **RCRA-VSQG** **NYD981141252**
NEW ROCHELLE, NY 10801 **NY Spills**
NY MANIFEST

Relative:
Lower

Actual:
17 ft.

SEMS Archive:

Site ID:	0202659
EPA ID:	NYD981141252
Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
Address:	ECHO AVE
Address 2:	Not reported
City,State,Zip:	NEW ROCHELLE, NY 10801
Cong District:	20
FIPS Code:	36119
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

SEMS Archive Detail:

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1992-09-30 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1988-04-19 04:00:00
Finish Date:	1988-04-19 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1992-09-30 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

RCRA-VSQG:

Date form received by agency:	2007-01-01 00:00:00.0
Facility name:	CON EDISON - ECHO AVENUE SUBSTATION
Facility address:	ECHO AVENUE NEW ROCHELLE, NY 10801
EPA ID:	NYD981141252
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Contact address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 1951-01-01 00:00:00.
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 1951-01-01 00:00:00.
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 2006-01-01 00:00:00.0
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 2004-02-25 00:00:00.0
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 2001-01-01 00:00:00.0
Site name: ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 1999-07-14 00:00:00.0
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Small Quantity Generator

Date form received by agency: 1996-03-29 00:00:00.0
Site name: CON EDISON - ECHO AVENUE SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 1985-11-19 00:00:00.0
Site name: CON EDISON - ECHO AVENUE SUB
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

SPILLS:
Name: CON EDISON
Address: ECHO AVENUE SUBSTATION
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9711031 / 1998-01-06
Facility ID: 9711031
Facility Type: ER
DER Facility ID: 101608
Site ID: 116789
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

SWIS:	6010
Spill Date:	1998-01-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-01-01
CID:	204
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-01
Spill Record Last Update:	1998-01-29
Spiller Name:	STEVE ROMERO
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	STEVE ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/01/98 OIL/WATER SEPARATOR OVERFLOWED; SUSPECTS OUTLET PIPE BECAME CLOGGED OR FROZEN CAUSING OVERFLOW; 01/02/98 3,300 GAL CONTAINED IN DIKED AREA; 100 GAL OVERFLOWED DIKE ONTO SOIL AND INTO DRAIN; 01/06/98 SPILL CLEANED UP BY CON ED; H2O HAS LESS THAN 1 PPM PCB "
Remarks:	"OIL / WATER SEPARATOR MALFUNCTIONED 3300 IN CONTAINMENT AREA"

All Materials:

Site ID:	116789
Operable Unit ID:	1053908
Operable Unit:	01
Material ID:	329298
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	3400.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD981141252
Facility Status:	Not reported
Location Address 1:	ECHO AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981141252
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYB9791883
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	AE50394PA
Trans2 State ID:	Not reported
Generator Ship Date:	01/20/2003
Trans1 Recv Date:	01/20/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/21/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981141252
Trans1 EPA ID:	PAD146714878
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B004 - PCB ARTICLES WITH 50 PPM BUT < 500 PPM
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	08210
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Handling Method: L Landfill.
Specific Gravity: 01.00

411
SSW
1/4-1/2
0.478 mi.
2524 ft.

COMMERICAL BUILIDING
719 MAIN ST
NEW ROCHELLE, NY

NY LTANKS **S106472134**
N/A

Relative:
Lower

Actual:
59 ft.

LTANKS:

Name:	COMMERICAL BUILIDING
Address:	719 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0404182 / 2004-10-28
Facility ID:	0404182
Site ID:	301693
Spill Date:	2004-07-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-07-19
CID:	405
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-19
Spill Record Last Update:	2004-10-28
Spiller Name:	JOHN DEURANTE
Spiller Company:	COMMERICAL BUILIDING
Spiller Address:	719 MAIN ST.
Spiller County:	001
Spiller Contact:	JOHN DEURANTE
Spiller Phone:	(914) 632-4222
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	243806
DEC Memo:	"10/28/04 TANK PASSED RETEST AFTER PIPING WAS REPLACED. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"RECOMMEND, UNCOVER, REPAIR, RETEST"

All TTF:

Facility ID:	0404182
Spill Number:	0404182
Spill Tank Test:	1529456
Site ID:	301693
Tank Number:	1
Tank Size:	1080
Material:	Not reported

COMMERICAL BUILIDING (Continued) **S106472134**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BP412 **SPILL NUMBER 9803423** **NY LTANKS** **S104619561**
South **106 LIBERTY AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.482 mi.
2546 ft. **Site 2 of 4 in cluster BP**

Relative: LTANKS:
Lower

Actual: | | |
|---|---|
45 ft. | Name: SPILL NUMBER 9803423 |
| Address: 106 LIBERTY AV |
| City,State,Zip: NEW ROCHELLE, NY |
| Spill Number/Closed Date: 9803423 / 1998-08-18 |
| Facility ID: 9803423 |
| Site ID: 140786 |
| Spill Date: 1998-06-17 |
| Spill Cause: Tank Failure |
| Spill Source: Private Dwelling |
| Spill Class: C4 |
| Cleanup Ceased: Not reported |
| SWIS: 6010 |
| Investigator: tdghiosa |
| Referred To: Not reported |
| Reported to Dept: 1998-06-17 |
| CID: 365 |
| Water Affected: Not reported |
| Spill Notifier: Other |
| Last Inspection: Not reported |
| Recommended Penalty: False |
| Meets Standard: True |
| UST Involvement: False |
| Remediation Phase: 0 |
| Date Entered In Computer: 1998-06-17 |
| Spill Record Last Update: 1998-10-02 |
| Spiller Name: MARGURITE FINCH |
| Spiller Company: Not reported |
| Spiller Address: 106 LIBERTY AV |
| Spiller County: 001 |
| Spiller Contact: MARGURITE FINCH |
| Spiller Phone: Not reported |
| Spiller Extention: Not reported |
| DEC Region: 3 |
| DER Facility ID: 120231 |
| DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: "PULLED THE TANK TODAY & FOUND IT TO BE LEAKING - CONTAMINATED SOIL IS BEING DUG UP & STOCK PILED" |

SPILL NUMBER 9803423 (Continued) **S104619561**

All Materials:

Site ID:	140786
Operable Unit ID:	1064251
Operable Unit:	01
Material ID:	566529
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

413
NE
1/4-1/2
0.484 mi.
2555 ft.

TTF AT RESIDENCE
68 JACKSON ST
NEW ROCHELLE, NY

NY LTANKS **S108957764**
N/A

Relative:
Lower

Actual:
25 ft.

LTANKS:

Name:	TTF AT RESIDENCE
Address:	68 JACKSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0707955 / 2008-03-26
Facility ID:	0707955
Site ID:	388761
Spill Date:	2007-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-10-20
CID:	79
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-22
Spill Record Last Update:	2008-03-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MR JOHNSON
Spiller Phone:	(914) 235-1496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	338305
DEC Memo:	"March 26, 2008: ENVIROSTAR REMOVED AND DISPOSED OF TANK. NO EVIDENCE

TTF AT RESIDENCE (Continued) **S108957764**

OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "TEST FAILED DUE TO BUBBLING. HORNER EASY 3 TEST,"

All Materials:
Site ID: 388761
Operable Unit ID: 1145917
Operable Unit: 01
Material ID: 2136260
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BP414 **COLLEGE OF NEW ROCHELLE** **NY LTANKS** **S104619776**
South **103 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.486 mi.
2564 ft. **Site 3 of 4 in cluster BP**

Relative: **Lower**
Actual: **44 ft.**

LTANKS:
Name: COLLEGE OF NEW ROCHELLE
Address: 103 LIBERTY AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9809357 / 2005-04-17
Facility ID: 9809357
Site ID: 118985
Spill Date: 1998-10-26
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JBODee
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 1998-10-26
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-26
Spill Record Last Update: 2005-04-17
Spiller Name: UNKNOWN
Spiller Company: COLLEGE OF NEW ROCHELLE
Spiller Address: 103 LIBERTY AVE
Spiller County: 001
Spiller Contact: COLLEGE OF NEW ROCHELLE
Spiller Phone: Not reported
Spiller Extention: Not reported

COLLEGE OF NEW ROCHELLE (Continued) **S104619776**

DEC Region: 3
DER Facility ID: 103367
DEC Memo: "02/23/99 Letter sent to tank owner requesting information 04/17/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod"
Remarks: "TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF RESULTS. NO CALL BACK REQUESTED AT TIME OF CALL."

All TTF:
Facility ID: 9809357
Spill Number: 9809357
Spill Tank Test: 1546454
Site ID: 118985
Tank Number: 1
Tank Size: 1080
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 118985
Operable Unit ID: 1066630
Operable Unit: 01
Material ID: 316813
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

415
SE
1/4-1/2
0.486 mi.
2564 ft.

CIUSSETELLI RESIDENCE **NY LTANKS** **S105996325**
4 FAIRVIEW PLACE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
40 ft.

LTANKS:
Name: CIUSSETELLI RESIDENCE
Address: 4 FAIRVIEW PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0204230 / 2010-07-13
Facility ID: 0204230
Site ID: 161898
Spill Date: 2002-07-22
Spill Cause: Tank Test Failure

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-07-23
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2010-07-13
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	RON CIUSSETELLI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136674
DEC Memo:	"7/13/10: Report of a residential tank test failure. No indication of contamination noted on initial report. Report indicates all exterior piping loose, multiple vents and fills. Probable air leak. No further information received. jod"
Remarks:	"all exterior piping loose...multiple vents and fille..and questions contact caller."

All TTF:

Facility ID:	0204230
Spill Number:	0204230
Spill Tank Test:	1527307
Site ID:	161898
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	161898
Operable Unit ID:	857023
Operable Unit:	01
Material ID:	518487

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR416 **FORMER MANCUSO MARINA** **US BROWNFIELDS** **1006975972**
ENE **HUNTINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.486 mi.
2567 ft. **Site 1 of 2 in cluster BR**

Relative:
Lower

Actual:
14 ft.

US BROWNFIELDS:

Name:	FORMER MANCUSO MARINA
Address:	HUNTINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Recipient Name:	R2 Brownfields TBA (Pre-law Superfund TBA)
Grant Type:	TBA
Property Number:	-
Parcel size:	1.23
Latitude:	40.912585
Longitude:	-73.773854
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	10127
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	11217
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	3/1/2003
Ownership Entity:	-
Completion Date:	3/1/2003
Current Owner:	City of New Rochelle, NY
Did Owner Change:	N
Cleanup Required:	-
Video Available:	N

FORMER MANCUSO MARINA (Continued) **1006975972**

Photo Available:	N
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-

FORMER MANCUSO MARINA (Continued) **1006975972**

Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	marina and boat storage facility
Below Poverty Number:	1670
Below Poverty Percent:	18.43
Meidan Income:	9092
Meidan Income Number:	3667
Meidan Income Percent:	40.47
Vacant Housing Number:	349
Vacant Housing Percent:	8.63
Unemployed Number:	334
Unemployed Percent:	3.69

BR417 **NELSTAD MATERIAL CORP** **NY LTANKS** **S102154943**
ENE **40 HUNTINGTON PL** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY SPDES**
0.487 mi.
2570 ft. **Site 2 of 2 in cluster BR**

Relative: **Lower**
Actual: **13 ft.**

LTANKS:

Name:	NELSTAD CONCRETE
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0208898 / 2004-05-03
Facility ID:	0208898
Site ID:	200280
Spill Date:	2002-11-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010

NELSTAD MATERIAL CORP (Continued) **S102154943**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-27
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-11-27
Spill Record Last Update:	2004-05-19
Spiller Name:	JOHN CAPOSELLA
Spiller Company:	NELSTAD CONCRETE
Spiller Address:	40 HUNTINGTON PL
Spiller County:	001
Spiller Contact:	JOHN CAPOSELLA
Spiller Phone:	(914) 636-8090
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	166657
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MANCINI 5/11/04: Letter to Nelstadt Materials Corp from Joe Mancini, WCDOH dated 3May2004. Closure report by Ira D Conklin has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"1000 UST LEAKING - CALLER DOING ABANDONMENT ON TANK AND DISCOVERED WATER IN IT"

All Materials:

Site ID:	200280
Operable Unit ID:	862078
Operable Unit:	01
Material ID:	515890
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CEMENT PLANT
Address:	40 HUNTINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9400648 / 1994-04-20
Facility ID:	9400648
Facility Type:	ER
DER Facility ID:	126495
Site ID:	148664
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010

NELSTAD MATERIAL CORP (Continued) **S102154943**

Spill Date:	1994-04-14
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-14
CID:	Not reported
Water Affected:	L.I. SOUND
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-20
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE LEAKING OIL INTO SOUND COAST GUARD WILL RESPOND PO NOWACK STORM DRAIN OUTFALL SHEEN PRESENTED BUT NOT RECOVERABLE RECURRING PROBLEM"

All Materials:

Site ID:	148664
Operable Unit ID:	994366
Operable Unit:	01
Material ID:	558757
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Permit Number:	NYR00D345
State-Region:	03
Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	3273
State Water Body Name:	ECHO BAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.912861 / -73.772611

NELSTAD MATERIAL CORP (Continued) **S102154943**

DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP
Non-Gov Permit Street Address:	NELSTAD MATERIAL CORP
Non-Gov Permit Supplemental Location:	40 HUNTINGTON PL
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Permit Street Address:	40 HUNTINGTON PL
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

BP418 **BLANCO RESIDENCE** **NY LTANKS** **S103238839**
South **30 LINDEN PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.488 mi.
2574 ft. **Site 4 of 4 in cluster BP**

Relative: LTANKS:
Lower

Actual:
50 ft.

Name:	BLANCO RESIDENCE
Address:	30 LINDEN PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9802704 / 1998-07-30
Facility ID:	9802704
Site ID:	227988
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other

BLANCO RESIDENCE (Continued) **S103238839**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-01
Spill Record Last Update:	1998-08-04
Spiller Name:	FRANK BLANCO
Spiller Company:	BLANCO RESIDENCE
Spiller Address:	30 LINDEN PLACE
Spiller County:	001
Spiller Contact:	FRANK BLANCO
Spiller Phone:	(914) 633-7605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 LETTER REC'D FROM NES,INC. INDICATING TANK AND APPROX. 21.86 TONS CONTAMINATED SOIL WAS REMOVED. NFA."
Remarks:	"CALLERS AGENCY CALLED FOR NO HOT WATER - SERVICE MAN FOUND TANK EMPTY - POSSIBLY A TANK LEAK OR LINE FAILURE"

All Materials:

Site ID:	227988
Operable Unit ID:	1063369
Operable Unit:	01
Material ID:	321024
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

419 **NEW ROCHELLE LEAF TS** **NY SWF/LF** **S103592520**
SW **85 BEECHWOOD AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.489 mi.
2584 ft.

Relative: **Lower**

Actual: **57 ft.**

SWF/LF:

Name:	NEW ROCHELLE LEAF TS
Address:	85 BEECHWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Flag:	ACTIVE
Region Code:	3
Phone Number:	9146542129
Owner Name:	City of New Rochelle
Owner Type:	Municipal
Owner Address:	525 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Email:	Not reported
Owner Phone:	9142353536
Contact Name:	John O'Keefe

NEW ROCHELLE LEAF TS (Continued) **S103592520**

Contact Address:	224 E. Main St.
Contact Addr2:	Not reported
Contact City,St,Zip:	New Rochelle, NY 10801
Contact Email:	jokeefe@newrochelleny.com
Contact Phone:	9142353536
Activity Desc:	Transfer station - registration
Activity Number:	[60R19]
Active:	Yes
East Coordinate:	603779
North Coordinate:	4529858
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Yard Waste;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #:	60R19
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	City of New Rochelle
Operator Type:	Not reported
Laste Date:	10/30/2019

---

420 **7-UP BOTTLING CO** **NY LTANKS** **S100560336**
NNE **PALMER AVE & CEDAR ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.489 mi.
2584 ft.

Relative: **Lower**

Actual: **28 ft.**

LTANKS:

Name:	7-UP BOTTLING CO
Address:	PALMER AVE & CEDAR ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9302874 / 1999-08-02
Facility ID:	9302874
Site ID:	60684
Spill Date:	1993-06-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-12-08
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1993-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-08
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

7-UP BOTTLING CO (Continued) **S100560336**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 59196
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/08/94: CONTRACTOR WAS FENLEY AND NICOL. TANK PULLED AND CONTA. SOIL REMOVEDFROM PIT. TANK REMOVAL REPORT WAS REQUESTED BUT NOT RECIEVED. 08/02/99: FINAL CLOSURE REPORT RECEIVED FROM GIBSON, DUNN & CRUTCHER ON 7/27/99; SENT TO TARRYTOWN OFFICE. "
Remarks: "TANK PULL DEC (TODD) IS AWARE OF AND HANDLING SPILL"

All Materials:
Site ID: 60684
Operable Unit ID: 981198
Operable Unit: 01
Material ID: 399984
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BS421 **NORTH EVARTS** **NY LTANKS** **S104620864**
SE **44 NORTH EVARTS AVE** **N/A**
1/4-1/2 **ELSMFORD, NY**
0.489 mi.
2584 ft. **Site 1 of 2 in cluster BS**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:
Name: NORTH EVARTS
Address: 44 NORTH EVARTS AVE
City,State,Zip: ELSMFORD, NY
Spill Number/Closed Date: 9913333 / 2005-02-26
Facility ID: 9913333
Site ID: 74554
Spill Date: 2000-02-24
Spill Cause: Tank Failure
Spill Source: Vessel
Spill Class: Not reported
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jkomara
Referred To: Not reported
Reported to Dept: 2000-02-24
CID: 322
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: True
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-02-24
Spill Record Last Update: 2005-02-26
Spiller Name: Not reported

NORTH EVARTS (Continued) **S104620864**

Spiller Company:	Not reported
Spiller Address:	44 NORTH EVARTS AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	69944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 2/26/05 surface spill from bilge tank on boat--j omara handled-close "
Remarks:	"bilge tank on boat ruptured - spill to soil and some contained in a catch basin - ny boat reg ny4947ju - fire dept and haz mat on scene- "
	Not reported

All Materials:

Site ID:	74554
Operable Unit ID:	1087874
Operable Unit:	01
Material ID:	295189
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BQ422 **HERNANDEZ - TTF** **NY LTANKS** **S117853761**
NW **70 REMINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.490 mi.
2585 ft. **Site 2 of 2 in cluster BQ**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	HERNANDEZ - TTF
Address:	70 REMINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1411959 / 2015-06-16
Facility ID:	1411959
Site ID:	505764
Spill Date:	2015-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

HERNANDEZ - TTF (Continued) **S117853761**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-23
Spill Record Last Update:	2015-06-17
Spiller Name:	DAISE Hernandez
Spiller Company:	Hernandez
Spiller Address:	70 REMINGTON PLACE
Spiller County:	999
Spiller Contact:	DAISE FENANDEZ
Spiller Phone:	(914) 563-3381
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	460572
DEC Memo:	"3-23-15: V.Mc call to Ms.Fenandez: Parents house, will speak w/Mom and try to find out age of house/UST and callbk w/update. Noted: gen. life time of UST 20 to 25 years, re-test Vs. remove. 6/16/15: UST removed by Envirostar. No evidence of leak or contamination was found. Tank Closure report entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
	Not reported
Remarks:	"caller reporting a failed tank test, tank is a 550 gallon tank. repair and retest tank"

All Materials:

Site ID:	505764
Operable Unit ID:	1255071
Operable Unit:	01
Material ID:	2257761
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BS423 **RESIDENCE APT BLD** **NY LTANKS** **S125358698**
SE **45 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.490 mi.
2587 ft. **Site 2 of 2 in cluster BS**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:

Name:	RESIDENCE APT BLD
Address:	45 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1905688 / Not Reported
Facility ID:	1905688
Site ID:	593733
Spill Date:	2019-08-30
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JPCUMMIN

RESIDENCE APT BLD (Continued) **S125358698**

Referred To:	Not reported
Reported to Dept:	2019-08-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2019-08-30
Spill Record Last Update:	2019-08-30
Spiller Name:	Not reported
Spiller Company:	RESIDENCE APT BLD
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ABRAHAM
Spiller Phone:	(646) 321-2876
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	543707
DEC Memo:	"8/30/19 Tank tast failure. Caller has not been able to contact the owner as his office closed early today and he isn't sure of the size but believes it is a 3k tank. Caller was not able to provide any additional information. BW"
Remarks:	"tank test"

All Materials:

Site ID:	593733
Operable Unit ID:	1341311
Operable Unit:	01
Material ID:	2351184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Count: 6 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NEW ROCHELLE	S108467789	SIDEWALK / IN FRONT OF NE	HARRISON STREET		NY LTANKS
NEW ROCHELLE	S100153602	N.SHORE LONG ISLAND SOUND	NEW ROCHELLE TO DANBURY		NY LTANKS
NEW ROCHELLE	S121933897	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY SHWS
NEW ROCHELLE	S105684699	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY VCP
NEW ROCHELLE	S113916612	MEARL CORP.	PALMER AVE	10801	NY SHWS
NEW ROCHELLE	S117975694	MM 5.4 LEFT LANE	I-95 SOUTHBOUND		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/02/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/15/2020
Date Data Arrived at EDR: 05/19/2020
Date Made Active in Reports: 06/18/2020
Number of Days to Update: 30

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/04/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/13/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 05/15/2020
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/24/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/13/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 05/15/2020
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/24/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/22/2020
Date Data Arrived at EDR: 03/24/2020
Date Made Active in Reports: 06/18/2020
Number of Days to Update: 86

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/28/2020
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 04/08/2020
Date Made Active in Reports: 06/25/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/24/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/15/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 08/03/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 02/01/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/06/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/23/2020
Next Scheduled EDR Contact: 11/01/2020
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/24/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 04/22/2020
Date Data Arrived at EDR: 06/18/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 78
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/15/2020
Next Scheduled EDR Contact: 09/28/2020
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/16/2019
Date Data Arrived at EDR: 12/16/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 77
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/17/2020
Next Scheduled EDR Contact: 09/28/2020
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/29/2020
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/29/2020
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/17/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/29/2020
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Semi-Annually

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 03/17/2020
Date Data Arrived at EDR: 03/18/2020
Date Made Active in Reports: 05/29/2020
Number of Days to Update: 72

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/11/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/29/2020
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/29/2020
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/01/2020
Date Data Arrived at EDR: 06/02/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/15/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 04/08/2020
Date Made Active in Reports: 06/25/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/24/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/21/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/14/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/31/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/19/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 07/28/2020
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/19/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 08/06/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 05/20/2020
Date Data Arrived at EDR: 05/22/2020
Date Made Active in Reports: 08/06/2020
Number of Days to Update: 76
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 08/06/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 02/27/2020
Date Data Arrived at EDR: 03/24/2020
Date Made Active in Reports: 06/18/2020
Number of Days to Update: 86
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/23/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 08/03/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/23/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 05/21/2020
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/13/2020
Date Data Arrived at EDR: 05/18/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 86
Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/13/2020
Next Scheduled EDR Contact: 11/30/2020
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62
Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574
Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/06/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63
Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/05/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 80
Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/31/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/06/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/17/2020
Next Scheduled EDR Contact: 09/28/2020
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 02/05/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 79

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/14/2020
Next Scheduled EDR Contact: 11/30/2020
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 03/01/2020
Date Data Arrived at EDR: 04/21/2020
Date Made Active in Reports: 07/15/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/21/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 01/31/2020
Date Data Arrived at EDR: 05/13/2020
Date Made Active in Reports: 08/03/2020
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/15/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/27/2020
Date Data Arrived at EDR: 05/06/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 34

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/09/2019
Date Data Arrived at EDR: 10/11/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 70

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/13/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/30/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/25/2019
Date Data Arrived at EDR: 10/25/2019
Date Made Active in Reports: 01/15/2020
Number of Days to Update: 82
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/20/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 01/15/2020
Number of Days to Update: 42
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 09/04/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/31/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/06/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/24/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/27/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2020
Date Data Arrived at EDR: 07/15/2020
Date Made Active in Reports: 07/21/2020
Number of Days to Update: 6

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/06/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/22/2020
Next Scheduled EDR Contact: 10/05/2020
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/07/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/28/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/21/2020
Next Scheduled EDR Contact: 11/30/2020
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 08/25/2020
Number of Days to Update: 22

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/03/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2020
Date Data Arrived at EDR: 05/21/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/25/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 05/28/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 77

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 09/10/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/28/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/28/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 80

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/01/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/03/2020
Date Data Arrived at EDR: 03/03/2020
Date Made Active in Reports: 05/28/2020
Number of Days to Update: 86

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 09/15/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 04/04/2020
Date Data Arrived at EDR: 04/07/2020
Date Made Active in Reports: 06/26/2020
Number of Days to Update: 80

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 07/02/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/19/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/17/2019
Date Made Active in Reports: 04/01/2019
Number of Days to Update: 74

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/18/2020
Date Data Arrived at EDR: 05/19/2020
Date Made Active in Reports: 08/03/2020
Number of Days to Update: 76

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/17/2020
Next Scheduled EDR Contact: 11/30/2020
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 08/14/2019
Date Data Arrived at EDR: 08/14/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/07/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 12/24/2019
Date Data Arrived at EDR: 03/03/2020
Date Made Active in Reports: 05/15/2020
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/24/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 06/08/2020
Date Data Arrived at EDR: 06/12/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 08/31/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/27/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 06/10/2020
Number of Days to Update: 77

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 06/25/2020
Date Data Arrived at EDR: 06/25/2020
Date Made Active in Reports: 07/22/2020
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/24/2020
Next Scheduled EDR Contact: 10/12/2020
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/31/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/14/2020
Date Made Active in Reports: 07/31/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/15/2020
Next Scheduled EDR Contact: 11/02/2020
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/14/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 05/31/2020
Date Data Arrived at EDR: 06/03/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 09/01/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 04/15/2020
Date Made Active in Reports: 07/06/2020
Number of Days to Update: 82

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/14/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 07/01/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/28/2020
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/11/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Semi-Annually

NYC LEAD 2: Recent Lead Paint Violations
Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 06/02/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 30

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 08/04/2020
Next Scheduled EDR Contact: 11/06/2019
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results
The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 05/29/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 34

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 08/04/2020
Next Scheduled EDR Contact: 11/16/2020
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/26/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/26/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 06/09/2020
Date Data Arrived at EDR: 06/09/2020
Date Made Active in Reports: 08/18/2020
Number of Days to Update: 70

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 06/09/2020
Date Data Arrived at EDR: 06/09/2020
Date Made Active in Reports: 08/18/2020
Number of Days to Update: 70

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/22/2020
Next Scheduled EDR Contact: 11/09/2020
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/12/2020
Date Data Arrived at EDR: 05/12/2020
Date Made Active in Reports: 07/27/2020
Number of Days to Update: 76

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/10/2020
Next Scheduled EDR Contact: 11/23/2020
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/19/2020
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 10/02/2019
Date Made Active in Reports: 12/10/2019
Number of Days to Update: 69

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/11/2020
Next Scheduled EDR Contact: 11/30/2020
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/09/2020
Next Scheduled EDR Contact: 10/26/2020
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

HALSTEAD STATION
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

TARGET PROPERTY COORDINATES

Latitude (North):	40.910597 - 40° 54' 38.15''
Longitude (West):	73.783767 - 73° 47' 1.56''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602429.0
UTM Y (Meters):	4529333.0
Elevation:	88 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940557 MOUNT VERNON, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 88 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36119C0341F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
36119C0342F	FEMA FIRM Flood data
36119C0343F	FEMA FIRM Flood data
36119C0344F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MOUNT VERNON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Ordovician
Series:	Middle Ordovician (Mohawkian)
Code:	O2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 6193173.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Michelle Thomas
		INQUIRY #:	6193173.2s
LAT/LONG:	40.910597 / 73.783767	DATE:	September 16, 2020 10:32 am

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: gravelly loam

Hydrologic Group: Not reported

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 127 inches

Depth to Watertable Min: > 38 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5
2	3 inches	72 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
2	USGS40000835790	0 - 1/8 Mile ESE
3	USGS40000835842	1/8 - 1/4 Mile NNE
4	USGS40000835908	1/2 - 1 Mile NNE
5	USGS40000835896	1/2 - 1 Mile NE
6	USGS40000835943	1/2 - 1 Mile NNW
7	USGS40000835557	1/2 - 1 Mile SSW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NY0002662	0 - 1/8 Mile NE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG90000040391	1/4 - 1/2 Mile West
A2	NYOG90000040390	1/4 - 1/2 Mile West
A3	NYOG90000040389	1/4 - 1/2 Mile WSW
A4	NYOG90000040388	1/4 - 1/2 Mile West
A5	NYOG90000040392	1/4 - 1/2 Mile WSW

PHYSICAL SETTING SOURCE MAP - 6193173.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Michelle Thomas
		INQUIRY #:	6193173.2s
LAT/LONG:	40.910597 / 73.783767	DATE:	September 16, 2020 10:32 am

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
NE
0 - 1/8 Mile
Lower

FRDS PWS **NY0002662**

PWS ID:	NY0002662	PWS type:	System Owner/Responsible Party
PWS name:	ROTONDE ANTHONY	PWS address:	C/O ANTHONY ROTONDE
PWS address:	RT 6	PWS city:	BREWSTER
PWS state:	NY	PWS zip:	10509
PWS ID:	NY0002662	PWS type:	System Owner/Responsible Party
PWS name:	ROTONDE ANTHONY	PWS address:	C/O ANTHONY ROTONDE
PWS address:	RT 6	PWS city:	BREWSTER
PWS state:	NY	PWS zip:	10509
PWS ID:	NY0002662	Activity status:	Active
Date system activated:	Not Reported	Date system deactivated:	Not Reported
Retail population:	00000200	System name:	POLO'S
System address:	Not Reported	System address:	RT 6
System city:	BREWSTER	System state:	NY
System zip:	10509		
County FIPS:	039	City served:	SOUTHEAST (T)
Latitude:	405441	Longitude:	0734658

2
ESE
0 - 1/8 Mile
Higher

FED USGS **USGS40000835790**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 105	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	268	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported
Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	8.00	Feet to sea level:	Not Reported
Note:	Not Reported		

3
NNE
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000835842**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 100	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	300	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	8.00	Feet to sea level:	Not Reported
Note:	Not Reported		

4
NNE **FED USGS** **USGS40000835908**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 283	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

5
NE **FED USGS** **USGS40000835896**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 104	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	750	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	15.00	Feet to sea level:	Not Reported
Note:	Not Reported		

6
NNW **FED USGS** **USGS40000835943**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 98	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	401	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	4.00	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
FED USGS	**USGS40000835557**

7
SSW
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 103	Type:	Well
Description:	Not Reported	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	220	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	12.00	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

A1
West
1/4 - 1/2 Mile

OIL_GAS **NYOG90000040391**

API Well #:	31119237750000	Well Name:	SCW 4
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Type:	Geothermal	Well Status:	Active
Permit Date:	0	Drill Date:	0
Completion Date:	200810 9	Plug Date:	0
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A2
West
1/4 - 1/2 Mile

OIL_GAS **NYOG90000040390**

API Well #:	31119237740000	Well Name:	SCW 3
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Type:	Geothermal	Well Status:	Active
Permit Date:	0	Drill Date:	0
Completion Date:	200810 9	Plug Date:	0
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A3
WSW
1/4 - 1/2 Mile

OIL_GAS **NYOG90000040389**

API Well #:	31119237730000	Well Name:	SCW 2
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Type:	Not Listed	Well Status:	Plugged and Abandoned
Permit Date:	0	Drill Date:	0
Completion Date:	0	Plug Date:	0
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

A4
West
1/4 - 1/2 Mile

OIL_GAS **NYOG90000040388**

API Well #:	31119237720000	Well Name:	SCW 1
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Type:	Geothermal	Well Status:	Active
Permit Date:	0	Drill Date:	0
Completion Date:	200810 9	Plug Date:	0

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A5
WSW
1/4 - 1/2 Mile

OIL_GAS **NYOG90000040392**

API Well #:	31119237760000	Well Name:	SCW 5
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Type:	Geothermal	Well Status:	Active
Permit Date:	0	Drill Date:	0
Completion Date:	200810 9	Plug Date:	0
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

BLACKSTONE CONSULTING LLC

JOHN O'CONNOR

Senior Project Manager

PROFESSIONAL SUMMARY:

Mr. O'Connor has over 22 years of experience performing environmental site assessments, asbestos and lead-based paint surveys, and other due diligence efforts throughout the United States, and over five years of experience performing property condition assessments on multifamily buildings for various financial institutions. He has successfully managed single and multi-site projects encompassing a broad range of property types including multifamily, retail, office, industrial, hospitality, assisted living and special use, and has performed over 500 dual-scope projects specifically for Freddie Mac and/or Fannie Mae.

PROJECT EXPERIENCE:

- Over twenty-two years of experience in conducting environmental assessments in commercial facilities, industrial properties, single and multi-family housing developments, and schools, and over five years of experience performing property condition assessments.
- Extensive experience in conducting Phase I Environmental Site Assessments and Property Condition Assessments in accordance with ASTM, Fannie Mae and Freddie Mac Guidelines, as well as numerous private lender guidelines.
- Extensive experience in project management of asbestos and lead abatement projects, soil remediation projects and UST removals.
- Experience in conducting Phase II Environmental Site Assessments including materials sampling and soil and ground-water borings.
- Experience in environmental personnel management, project cost estimating, and effective staff scheduling.
- Experience in conducting quality control audits of field personnel for a multi-million dollar federal lead hazard risk assessment project.
- Experience as a Project Manager for a $500,000.00 mold abatement project.
- Knowledgeable in regulatory requirements for, and identification of, environmental hazards associated with commercial and residential buildings. Advises clients in effective management and resolution of the identified concerns.
- Trained in the health effects of lead and asbestos, federal and state regulations, techniques of assessment and abatement, use of protective equipment, assessment record keeping and reporting.

- A highly trained lead inspector, qualified in the use of Niton XL Spectrum Analyzer. Performs lead-based paint surveys in support of public and private multifamily developments and private residences.
- Experienced in conducting Energy Audits for single family residences, multi-family and commercial properties.
- Extensive training in environmental regulations, hazard identification, risk assessment and abatement methods.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

B.S., Millersville University, Major: Occupational Safety and Hygiene Management Manufacturer's Training Course for Niton XL Spectrum Analyzer

EPA/AHERA Annual Asbestos Refresher Course EPA Model

Lead Paint Risk Assessor

Radon Measurement Operators Training Course Home

Energy Rating System Training

CERTIFICATIONS/ACCREDITATIONS/CONTINUING EDUCATION:

HUD Sponsored Multifamily Accelerated Processing (MAP) Training, Baltimore, Maryland EPA/AHERA Certified Asbestos Building Inspector

EPA/AHERA Certified Asbestos Management Planner

EPA Radon Measurement Proficiency Program Listed Inspector

National Radon Proficiency Program (NRPP) Certified Residential Measurement Provider Florida Licensed Radon Measurement Technician

Certified to Collect Drinking Water: Maryland

BLACKSTONE CONSULTING LLC

LAUREN BEYRENT

Project Manager

PROFESSIONAL SUMMARY:

Ms. Beyrent has over 7 years of experience in the environmental due diligence sector with an emphasis on completing Phase I Environmental Site Assessments (ESAs) and Property Condition Assessments (PCAs) at commercial, industrial, manufacturing/warehouse, and multi-family residential properties. Other responsibilities include project staffing and management of large portfolio budgets, communicating findings with clients, and ensuring timely completion of her projects.

SELECTED PROJECT EXPERIENCE:

- Project manager for various environmental and property condition assessments throughout the U.S., Canada, and Mexico. Specific job functions include: communication with clients and property contacts, historic and local/state/federal research, government records/environmental regulatory database reviews, and technical report writing. PCA assessments also include the evaluation of typical building systems such as the building site and envelope, interior systems, roofing systems, mechanical equipment, plumbing, electrical/lighting systems, building structure, life safety/fire protection systems, and ADA compliance. Technical writing skills are utilized to prepare PCA reports, which include cost estimations, capital reserve planning, and engineering data analysis.
- Assessments were conducted for real estate owners, investors, and lending institutions in accordance with applicable American Society for Testing and Materials (ASTM) Standards and Guidelines, U.S. EPA All Appropriate Inquiry rules, and additional project-specific guidelines. Routinely conducts radon and asbestos sampling and mold evaluations during the diligence assessments.
- Performed an ADA accessibility survey and evaluation for an existing facility using the ADA Standards for Accessible Design to determine the property's compliance with applicable federal, state, and local accessibility regulations. The ADA survey included an evaluation of the paths of travel throughout the exterior and interior portions of a property, and the accessible design of parking spaces, ramps, stairs, signage, public spaces, restrooms, signage, and other uses.
- Assisted in several remediation projects for various contaminated properties, which included soil and groundwater sampling, surveying, well-monitoring, and soil removal activities.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

Clemson University – Clemson, South Carolina B.S.- Environmental and Natural Resources, Minor in Biological Sciences
OSHA 10 Hour Occupational Safety & Health Training for Construction
OSHA 40 Hour HAZWOPER
Standard First Aid CPR/AED Level C
Working at Heights, Man-Lift/Aerial Lift Operation Training

BLACKSTONE CONSULTING LLC

AKISHA STAGGERS

Senior Project Manager

PROFESSIONAL SUMMARY:

Ms. Staggers has over 15 years of experience in environmental consulting, with a strong background in HUD related projects. Ms. Staggers has proven expertise in all facets of environmental assessment projects including Phase I and Phase II environmental site assessments, vapor intrusion assessments, environmental compliance investigations, and lead and asbestos investigations. She manages environmental projects for industry and government clients that effectively address due diligence requirements for property transfer.

SELECTED PROJECT EXPERIENCE:

- Managed the preparation and QA/QC of HUD Environmental Review Records and associated NEPA compliance reporting/correspondence, Phase I Environmental Site Assessments (ESA), Limited Phase II Environmental Site Assessments, Asbestos Building Surveys, and Lead-based Paint Inspection Reports.
- Developed reporting protocols to meet NEPA requirements for USDA and HUD
- Managed environmental staff, which included overall coordination of day to day operations and providing technical guidance.
- Developed several training programs for completing Tier 1 Vapor Encroachment Screenings, environmental review compliance reporting, and floodplain management for the project management team.
- Trained environmental staff to complete and coordinate Phase I Environmental Site Assessments, HUD Environmental Assessments, Tier 1 Vapor Encroachment Screenings, Asbestos Inspections and Lead-based paint inspections.

EDUCATION AND PROFESSIONAL AFFILIATIONS

Virginia Polytechnic Institute and State University, VA, Bachelor of Science in Environmental Science

LPA-1 XRF Lead Paint Detection Device Operator Training/ Radiation Safety Training

Advisory Council on Historic Preservation: The Section 106 Essentials -2008 Training Course

Screening for Potential Vapor Intrusion Problems under the ASTM E 2600 Standard – Presented by Anthony J. Buonicore, P.E., BCEE, QEP – November 2009

HUD Multifamily Accelerated Processing (MAP) Training - 2009 Washington, D.C.

BLACKSTONE CONSULTING LLC

REBECCA L. RENICK
Principal, Director of Lending Services
Baltimore, MD
(443) 977-7671
brenick@blackstoneconsulting.com

PROFESSIONAL SUMMARY:

Ms. Renick has over 19 years of management experience in environmental and physical due diligence consulting. She opened Blackstone's Mid-Atlantic Regional Office in Baltimore in 2007, and as Blackstone's Director of Lending Services, she is responsible for directing Blackstone's nationwide lender Fannie and Freddie lending work. Ms. Renick has significant experience in the due diligence industry on a variety of property types, but specializes in the multifamily arena.

As Principal and Director of Lending Services, Ms. Renick is responsible for the management, development, and direction of a specialized group of environmental, property condition, and energy professionals serving the lending community.

Ms. Renick originates new business and services numerous Fannie Mae Delegated Underwriting and Servicing (DUS), Freddie Mac Seller/Servicers, traditional lenders, and equity clients.

SELECTED PROJECT EXPERIENCE:

- Responsible for cultivating, establishing, and maintaining client relationships.
- Develop and execute solutions for Blackstone Fannie and Freddie projects, having worked on thousands of GSE multifamily reports in recent years. Responsible for a range of client and internal presentations.
- Effectively managed client relationships and portfolios with the country's largest multifamily lenders, including CBRE Capital Markets, Inc., Walker & Dunlop, KeyBank Real Estate Capital, Jones Lang LaSalle, Capital One, and Wells Fargo Multifamily Capital, and numerous private equity organizations.
- Successfully executed numerous multifamily portfolio lending transactions nationwide for both the debt and equity interest.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

B.A., Rutgers University, English.

Halstead Station
255 Huguenot Street
New Rochelle, NY 10801

Inquiry Number: 6986656.2s
May 19, 2022

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1147
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

COORDINATES

Latitude (North):	40.9105400 - 40ˆ 54' 37.94''
Longitude (West):	73.7838360 - 73ˆ 47' 1.80''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602423.3
UTM Y (Meters):	4529326.5
Elevation:	90 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14105990 MOUNT VERNON, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	LA ROCHELLE & SHEARW	255 HUGUENOT STREET	NY SPDES		TP
A2	SOUND CLEANER	63 MEMORIAL HWY	NY DRYCLEANERS	Lower	1 ft.
A3	SOUND CLEANERS	63 MEMORIAL HWY	EDR Hist Cleaner	Lower	1 ft.
A4	OFFICE BUILDING	8-10 RAILROAD PLACE	NY Spills	Lower	3, 0.001,
B5	RESIDENCE	129 DIVISON ST	NY Spills	Higher	28, 0.005, South
A6	CONSOLIDATED EDISON	MEMORIAL HIGHWAY & H	NY MANIFEST	Higher	42, 0.008, SSE
A7	UST	MEMORIAL HIGHWAY AND	NY Spills	Higher	42, 0.008, SSE
B8	CON EDISON	HUGENOT ST & DIVISIO	NY MANIFEST	Higher	43, 0.008, South
B9	CON EDISON	HUGENOT & DIVISION S	NY MANIFEST	Higher	43, 0.008, South
B10	CON EDISON	DIVISION & HUGUENOT	NY MANIFEST	Higher	43, 0.008, South
B11	CON EDISON TRANSFORM	DIVISION ST & HUGUEN	RCRA NonGen / NLR	Higher	43, 0.008, South
B12	CON ED	DIVISION ST & HUGENO	NY MANIFEST	Higher	43, 0.008, South
B13	CON EDISON MANHOLE:	HUGENOT AVE & DIVISI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	43, 0.008, South
B14	CON EDISON - TRANSFO	DIVISION ST AND HUGE	RCRA-LQG	Higher	43, 0.008, South
A15	METRO NORTH TRAIN ST	NEW HAVEN LINE &R/R	NY Spills	Lower	48, 0.009, West
A16	METRO NORTH TRACKS	EAST OF NEW ROCHELLE	NY Spills	Lower	48, 0.009, West
B17	NYSDOT BIN 1049890	DIVISION ST OVER MET	RCRA NonGen / NLR	Higher	48, 0.009, South
C18	MH1204	HUGUENOT AVE/LAWTON	NY Spills	Higher	95, 0.018, East
B19	VACANT LOT	HUGUENOT ST/DIVISION	NY LTANKS	Higher	160, 0.030, South
B20	ROAD	HUGUENOT ST/DIVISION	NY Spills	Higher	160, 0.030, South
B21	SHORELINE OIL	296 HUGENOT ST,REAR	NY LTANKS	Higher	168, 0.032, SSW
B22	LILLIAN VERNON CO.	WESTCHESTER PLACE	NY LTANKS	Higher	175, 0.033, South
D23	NYSDOT BIN 1091390	DIVISION ST OVER I 9	RCRA NonGen / NLR	Lower	186, 0.035, West
E24	CON EDISON	260 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	215, 0.041, NE
E25	CON EDISON	260 NORTH AVE	NJ MANIFEST	Lower	215, 0.041, NE
B26	HAYES KATHRYN INC	36-38 DIVISION ST	EDR Hist Cleaner	Higher	226, 0.043, South
B27	JONES RESIDENCE	311 HUGUENOT STREET	NY LTANKS	Higher	233, 0.044, SSW
E28	HUGUENOT AND NORTH A	HUGUENOT AND NORTH A	NY Spills	Lower	238, 0.045, NE
E29	CON EDISON MANHOLE:	HUGUENOT AVE & NORTH	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	238, 0.045, NE
E30	CON EDISON MANHOLE:	HUGENUOT ST & NORTH	RCRA NonGen / NLR	Lower	238, 0.045, NE
E31	CON EDISON TRANSFORM	NORTH AVE & HUGUENOT	RCRA NonGen / NLR, NY MANIFEST	Lower	238, 0.045, NE
E32	CON EDISON	NORTH AVE & HUGENOT	NY MANIFEST	Lower	238, 0.045, NE
C33	MAIN LIBRARY	LAWTON ST	NY LTANKS	Higher	238, 0.045, East
C34	ACCESSOCRAFT PRODUCT	48 LAWTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	240, 0.045, ESE
E35	US POSTAL SERVICE	255 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	256, 0.048, NE
D36	SPILL NUMBER 9803949	MILEPOST 5.5 SB I95	NY Spills	Lower	256, 0.048, West
B37	306 HUGUENOT STREET	306 HUGUENOT STREET	NY AST	Higher	264, 0.050, SSW
E38	A PLUS INC	271 NORTH AVE STE 11	EDR Hist Auto	Lower	285, 0.054, NE
E39	COMMERCIAL BUILDING	271 NORTH AVE	NY Spills	Lower	285, 0.054, NE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	KAUFMAN HUGUENOT COM	271 NORTH AVENUE	NY UST, NY AST	Lower	285, 0.054, NE
C41	LAWTON STREET REALTY	41-43 LAWTON ST	NY Spills	Higher	289, 0.055, ESE
C42	LAWTON STREET REALTY	41-43 LAWTON ST	NY LTANKS	Higher	289, 0.055, ESE
C43	PAVEMENT	41 LAWTON STREET	NY Spills	Higher	289, 0.055, ESE
E44	FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	RCRA NonGen / NLR	Lower	290, 0.055, ENE
F45	NEW ROCHELLE CITY OF	24 STATION PLZ N	RCRA NonGen / NLR	Lower	298, 0.056, NNW
F46	STATION CLEANERS	24 STATION PLZ	EDR Hist Cleaner	Lower	298, 0.056, NNW
G47	CABLE	29 DIVISION STREET	NY Spills	Higher	298, 0.056, SSE
E48	247 NORTH AVENUE SIT	247 NORTH AVENUE	NY BROWNFIELDS	Lower	315, 0.060, ENE
H49	NORTH BROOK REALTY A	270 NORTH AVENUE, SU	NY UST	Lower	323, 0.061, NNE
I50	SOIL	316 HUGUENOT ST	NY Spills	Higher	361, 0.068, SSW
I51	FIRESTONE TIRE AND A	316 HUGUENOT STREET	NY BROWNFIELDS	Higher	361, 0.068, SSW
H52	EAST RIVER SAVINGS B	277 NORTH AVE.	NY LTANKS	Lower	376, 0.071, NNE
H53	CON EDISON MANHOLE:	277 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	376, 0.071, NNE
H54	CONSOLIDATED EDISON	F/O 277 NORTH AVE	NY MANIFEST	Lower	376, 0.071, NNE
H55	BUSINESS	277 NORTH AVENUE	NY LTANKS	Lower	376, 0.071, NNE
H56	277 NR PRINCIPAL, LL	277 NORTH AVENUE	NY UST	Lower	376, 0.071, NNE
H57	277 NORTH LLC	277 NORTH AVENUE	NY LTANKS	Lower	376, 0.071, NNE
G58	CON EDISON	19 DIVISION ST & WAS	NY Spills, NY MANIFEST	Higher	417, 0.079, SSE
J59	CON EDISON	NORTH AVE & ANDERSON	RCRA NonGen / NLR, FINDS, ECHO	Higher	423, 0.080, East
J60	CON ED STREET EXCAVA	NORTH AVE AND ANDERS	NY Spills	Higher	423, 0.080, East
J61	CON EDISON	NORTH AVE & ANDERSON	NJ MANIFEST	Higher	423, 0.080, East
J62	CON EDISON TRANSFORM	NORTH AVE & ANDERSON	RCRA NonGen / NLR, NY MANIFEST	Higher	423, 0.080, East
J63	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	423, 0.080, East
J64	CON EDISON	NORTH AVE & ANDERSON	NY MANIFEST	Higher	423, 0.080, East
J65	CON EDISON	ANDERSON ST & NORTH	NY MANIFEST	Higher	423, 0.080, East
I66	BLOCK 417 NEW ROCHEL	327-329 HUGUENOT ST	RCRA NonGen / NLR	Higher	429, 0.081, SSW
I67	BLOCK 417 NEW ROCHEL	327-329 HUGUENOT STR	NY BROWNFIELDS	Higher	429, 0.081, SSW
J68	NORTH AVE REALITY	5 ANDERSON ST	NY LTANKS	Higher	442, 0.084, East
J69	CON EDISON	230 NORTH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	442, 0.084, East
J70	CONCRETE FLOORING WI	230 NORTH AVENUE	NY Spills	Higher	442, 0.084, East
J71	CON EDISON	230 NORTH AVE	NJ MANIFEST	Higher	442, 0.084, East
J72	CON ED	230 NORTH AVE	NY MANIFEST	Higher	442, 0.084, East
H73	GOODRICH RUBBER 285	285 NORTH AVENUE	NY BROWNFIELDS	Lower	459, 0.087, NNE
74	ST GABRIEL'S CHURCH	120 DIVISION ST	NY Spills	Higher	460, 0.087, WNW
G75	COMM/RESIDENT. PROPE	15 DIVISION STREET	NY LTANKS	Higher	463, 0.088, SSE
J76	NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	NY LTANKS	Higher	482, 0.091, ESE
I77	CON EDISON	HUGUENOT ST & CENTRE	RCRA NonGen / NLR	Higher	515, 0.098, SSW
I78	CON EDISON	CENTER & HUGUENOT	NY MANIFEST	Higher	515, 0.098, SSW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I79	CON EDISON	CENTRE AVE & HUGUENO	NY MANIFEST	Higher	515, 0.098, SSW
I80	CON EDISON	HUGENOT & CENTRE ST	NY MANIFEST	Higher	515, 0.098, SSW
J81	CVS PHARMACY #8447	222 NORTH AVE	RCRA-VSQG, NY MANIFEST	Higher	518, 0.098, East
K82	DELUXE TAXI	10 STATION PLAZA	NY UST	Lower	523, 0.099, North
I83	CEMENT COURT YARD	54 CENTER AVE	NY Spills	Higher	530, 0.100, SSW
I84	APARTMENT BLDG	54 CENTRE AV	NY LTANKS	Higher	530, 0.100, SSW
I85	SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	NY UST	Higher	530, 0.100, SSW
G86	RPM REALTY INC	9-15 DIVISION STREET	NY AST	Higher	538, 0.102, SSE
G87	RPM REALTY INC	9-15 DIVISION STREET	NY UST	Higher	538, 0.102, SSE
I88	CENTRE AVENUE DEVELO	33-35 CENTRE AVENUE	NY BROWNFIELDS	Higher	555, 0.105, SSW
I89	CENTRE AVENUE DEVELO	33-35 CENTRE AVENUE	NY INST CONTROL	Higher	555, 0.105, SSW
I90	CENTRE AVENUE DEVELO	33 CENTRE AVENUE	NY BROWNFIELDS	Higher	555, 0.105, SSW
I91	CENTRE AVENUE DEVELO	33-35 CENTRE AVENUE	NY ENG CONTROLS	Higher	555, 0.105, SSW
L92	STATION CLEANERS	1 DEPOT PLAZA #1	NY DRYCLEANERS	Lower	555, 0.105, NNW
M93	P&D TRANSPORT - HOT	I-95 NB @ MM 5.4	NY Spills	Lower	555, 0.105, SW
M94	I-95	I-95EB MP54	NY Spills	Lower	555, 0.105, SW
I95	GREEN HEAVEN CLEANER	62 CENTRE AVE	NY DRYCLEANERS	Higher	568, 0.108, South
I96	SIMONETTI CLEANERS &	62 CENTRE AVE	EDR Hist Cleaner	Higher	568, 0.108, South
I97	CENTRE CLEANERS	62 CENTRE STREET	RCRA-VSQG, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	568, 0.108, South
I98	HACKER MORRIS J & SO	64 CENTRE AVE	EDR Hist Auto	Higher	579, 0.110, South
I99	COMMERCIAL	64 CENTER AVE	NY Spills	Higher	579, 0.110, South
I100	COMMERCIAL PROPERTY	64 CENTRE AVE	NY LTANKS	Higher	579, 0.110, South
N101	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Lower	588, 0.111, SW
N102	CON EDISON TRANSFORM	CENTRE AVE & RELYEA	RCRA NonGen / NLR, NY MANIFEST	Lower	588, 0.111, SW
O103	CON EDISON	HUGUENOT ST & LE COU	NY MANIFEST	Lower	589, 0.112, NE
O104	CON EDISON	HUGUENOT ST & LE COU	NJ MANIFEST	Lower	589, 0.112, NE
O105	CON EDISON	HUGUENOT ST & LE COU	RCRA NonGen / NLR	Lower	589, 0.112, NE
O106	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	589, 0.112, NE
O107	CON EDISON MANHOLE 1	HUGUENOT ST & LECOUN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	589, 0.112, NE
J108	SPEEDY CLEANERS	217 NORTH AVENUE	US AIRS, FINDS, ECHO, NY DRYCLEANERS	Higher	593, 0.112, East
I109	NYNEX LOCATION	342 HUEGNOT ST	NY LTANKS	Higher	602, 0.114, SSW
I110	NEW YORK TELEPHONE C	342 HUGUENOT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	602, 0.114, SSW
I111	VERIZON	342 HUGUENOT ST	NY Spills	Higher	602, 0.114, SSW
O112	DEVELOPMENT SITE	175 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	603, 0.114, NE
K113	NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	NY UST	Lower	612, 0.116, North
N114	APPAREL PLUS	27 CENTRE AVE	NY Spills	Lower	619, 0.117, SW
P115	535 MAIN ST ASSOCIAT	535 MAIN STREET	NY Spills	Higher	627, 0.119, SSE
P116	SIDNEY FURNITURE	535 MAIN ST	NY Spills	Higher	627, 0.119, SSE
K117	CONSOLIDATED EDISON	F/O 311 NORTH AVE	NY MANIFEST	Lower	631, 0.120, North

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L118	COMMERCIAL - UST	35 GRAND STREET	NY Spills	Lower	634, 0.120, NNW
J119	CATHOLIC NEWS PUBLIS	210 NORTH AVE	NY LTANKS	Higher	634, 0.120, ESE
P120	NOVA REALTY - UST	523 MAIN ST	NY Spills	Higher	636, 0.120, SSE
Q121	CON EDISON	LECOUNT PL & ANDERSO	NY MANIFEST	Higher	643, 0.122, ENE
Q122	CON EDISON	LECOUNT PL & ANDERSO	NJ MANIFEST	Higher	643, 0.122, ENE
Q123	CON EDISON	LECOUNT PL & ANDERSO	RCRA NonGen / NLR, FINDS, ECHO	Higher	643, 0.122, ENE
P124	LILLIAN VERNON CORP.	543 MAIN STREET	NY LTANKS, NY Spills	Higher	643, 0.122, SSE
R125	VERIZON NEW YORK INC	342 HUGUENOT STREET	NY UST	Higher	644, 0.122, SSW
P126	CON EDISON - TRANSFO	DIVISION ST & MAIN S	RCRA-LQG	Higher	648, 0.123, SSE
P127	CONSOLIDATED EDISON	DIVISION & MAIN	NY MANIFEST	Higher	648, 0.123, SSE
P128	CON EDISON - TRANSFO	DIVISION ST & MAIN S	NJ MANIFEST	Higher	648, 0.123, SSE
P129	CON EDISON	DIVISION ST & MAIN S	NY MANIFEST	Higher	648, 0.123, SSE
J130	PART OF STANDARD PRI	211 NORTH AVE	NY Spills	Higher	651, 0.123, East
K131	CON EDISON MANHOLE:	313 NORTH AVE FRONT	RCRA NonGen / NLR	Lower	652, 0.123, North
R132	75 CENTRE AVENUE LLC	75 CENTRE AVENUE	NY UST, NY AST	Higher	656, 0.124, South
R133	CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	NY LTANKS	Higher	656, 0.124, South
N134	MR CHIMNEY CLEAN	32 RELYEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	656, 0.124, SSW
Q135	MACYS	33 LE COUNT PLACE	NY MANIFEST	Higher	667, 0.126, ENE
P136	COMMERCIAL PROPERTY	522 MAIN STREET	NY LTANKS	Higher	676, 0.128, SSE
R137	MAISON 347 LLC	347 HUGUENOT STREET	NY UST	Higher	678, 0.128, SSW
P138	542 MAIN STREET LLC	542 MAIN STREET	NY UST	Higher	682, 0.129, SSE
P139	OFFICE BLDG	542 MAIN STREET	NY LTANKS	Higher	682, 0.129, SSE
S140	COMMERCIAL BUILDING	507 MAIN STREET	NY LTANKS	Higher	685, 0.130, SE
141	CON EDISON	19 DIVISION ST & WAS	RCRA NonGen / NLR, FINDS, ECHO	Higher	685, 0.130, NW
P142	CON EDISON TRANSFORM	MAIN ST & CHRUCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	687, 0.130, SE
P143	CON EDISON	MAIN ST & CHURCH ST	NY MANIFEST	Higher	687, 0.130, SE
P144	CON EDISON MANHOLE:	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	687, 0.130, SE
P145	CON EDISON TRANSFORM	CHURCH ST & MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	687, 0.130, SE
R146	COCO RESIDENCE	81 CENTRE AVE	NY LTANKS	Higher	694, 0.131, South
T147	CON EDISON	205 NORTH AVE	RCRA NonGen / NLR	Higher	710, 0.134, ESE
T148	CON EDISON	205 NORTH AVE	NY MANIFEST	Higher	710, 0.134, ESE
T149	CON EDISON	205 NORTH AVE	NJ MANIFEST	Higher	710, 0.134, ESE
P150	CON EDISON	552 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	718, 0.136, South
P151	CON EDISON	552 MAIN ST	NJ MANIFEST	Higher	718, 0.136, South
K152	CON EDISON MANHOLE:	NORTH ST & GARDEN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	726, 0.138, North
K153	CON EDISON MANHOLE 4	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	726, 0.138, North
K154	CON EDISON SERVICE B	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	726, 0.138, North
K155	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, NY MANIFEST	Lower	726, 0.138, North
K156	CON EDISON MANHOLE:	NORTH AVE & GARDEN S	RCRA NonGen / NLR, FINDS, ECHO	Lower	726, 0.138, North

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K157	CON EDISON - MANHOLE	GARDEN ST AND NORTH	RCRA-LQG, NY MANIFEST	Lower	726, 0.138, North
S158	500 MAIN STREET LAUN	500, 506 AND 510 MAI	NY BROWNFIELDS	Higher	744, 0.141, SE
S159	FORMER CHASE BANK BU	491 MAIN STREET	NY UST, NY AST	Higher	744, 0.141, SE
S160	BARCLAYS BANK OF NY/	491 MAIN ST.	NY LTANKS	Higher	744, 0.141, SE
S161	NEW ROCHELLE PUBLIC	1 LAWTON	NY LTANKS	Higher	746, 0.141, SE
L162	CIOTTI RESIDENCE	60 GRAND STREET	NY LTANKS, NY Spills	Lower	747, 0.141, NNW
U163	CON EDISON	565 MAIN ST	RCRA NonGen / NLR	Higher	750, 0.142, South
U164	CON EDISON	565 MAIN ST	NJ MANIFEST	Higher	750, 0.142, South
V165	PROPOSED RESIDENTIAL	11 GARDEN STREET	NY BROWNFIELDS, NY SPDES	Lower	757, 0.143, North
V166	GARDEN STREET RESIDE	11 GARDEN ST	RCRA NonGen / NLR	Lower	757, 0.143, North
U167	HANGERS CLEANERS	562-564 MAIN STREET	NY DRYCLEANERS	Higher	771, 0.146, South
S168	ADREAN PRINTING CO	490 MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	773, 0.146, SE
N169	PRO AUTO PARTS	41 REYLEA PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	774, 0.147, SSW
V170	NYS THRUWAY AUTHORIT	I-95 NORTH AVE OVER	RCRA-LQG, NY MANIFEST	Lower	778, 0.147, North
L171	GUIDANCE CENTER INC	70 GRAND ST	NY LTANKS	Lower	784, 0.148, NNW
R172	FIRST METRO SERVICES	357 HUGONOT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	784, 0.148, SSW
N173	MP CENTRE LLC	10 BARTELS PLACE	NY UST	Lower	800, 0.152, SW
T174	14 LE COUNT STANDARD	14 LE COUNT PL, 455	NY BROWNFIELDS	Lower	803, 0.152, East
U175	MISR REALTY, LLC	573-579 MAIN STREET	NY UST	Higher	804, 0.152, South
U176	MISR REALTY, LLC	573-579 MAIN STREET	NY AST	Higher	804, 0.152, South
N177	INDUST OVERALL SERVI	10 BARTELS PLACE	NY LTANKS	Lower	811, 0.154, SW
U178	CON EDISON TRANSFORM	CENTRE AVE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	814, 0.154, South
U179	CON EDISON	CENTRE & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	814, 0.154, South
U180	CON EDISON	CENTRE & MAIN ST	NJ MANIFEST	Higher	814, 0.154, South
U181	CON EDISON	MAIN ST & CENTRE ST	NY MANIFEST	Higher	814, 0.154, South
U182	CON ED	CENTRE & MAIN ST	NY MANIFEST	Higher	814, 0.154, South
N183	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY SHWS, NY CBS	Lower	815, 0.154, SW
N184	NYSDEC-SITE 360109 I	10 BARTELS PL	NJ MANIFEST	Lower	815, 0.154, SW
N185	NYSDEC-SITE 360109 I	10 BARTELS PL	RCRA-LQG, NY Spills, FINDS, ECHO, NY MANIFEST	Lower	815, 0.154, SW
N186	INDUSTRIAL OVERALL	10 BARTELS PLACE	NY AST, NY CBS AST	Lower	815, 0.154, SW
187	RITZCOVAN - TTF	22 BURLING LANE	NY LTANKS	Lower	821, 0.155, NNW
V188	CON EDISON MANHOLE:	NORTH AVE & BURLING	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	824, 0.156, North
W189	CASARRA RESIDENCE	9 BADEAU PL	NY LTANKS	Higher	864, 0.164, West
V190	COTTAGE-GARDEN AUTO	20 GARDEN ST., 26 GA	NY INST CONTROL, NY BROWNFIELDS	Lower	916, 0.173, NNE
X191	NYNEX	40 WASHINGTON AVE	NY LTANKS	Higher	919, 0.174, WNW
Y192	ROTH CLEANERS	1 LEROY PL	RCRA NonGen / NLR, FINDS, ECHO, NY DRYCLEANERS, NY...	Higher	932, 0.177, SSE
Y193	CONSOLIDATED EDISON	DIVISION ST & LEROY	NY MANIFEST	Higher	951, 0.180, SSE
Z194	CON ED-V37	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	955, 0.181, East
Z195	CON ED-V14	LECOUNT PL & MAIN ST	NY MANIFEST	Lower	955, 0.181, East

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AA196	J B & FRANKS	27 BARTELS PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	958, 0.181, SW
W197	RESIDENCE	18 BADEAU PLACE	NY LTANKS	Higher	959, 0.182, West
X198	ST GABRIEL SCHOOL	50 WASHINGTON AVE	NY LTANKS	Higher	980, 0.186, WNW
X199	SAINT GABRIEL HIGH S	50 WASHINGTON AVENUE	NY UST	Higher	980, 0.186, WNW
X200	INTERSTITIAL FAILURE	50 WASHINGTON AVE	NY LTANKS, NY Spills	Higher	980, 0.186, WNW
Y201	CHURCH-DIVISION STRE	26 SOUTH DIVISION ST	NY BROWNFIELDS	Higher	983, 0.186, SSE
AB202	CON EDISON	HUGUENOT ST & COLUMB	NY MANIFEST	Higher	985, 0.187, SSW
AB203	CON EDISON	HUGENOT AVE & COLUMB	NY MANIFEST	Higher	985, 0.187, SSW
AB204	CON EDISON	HUGENOT ST & COLUMBU	NY MANIFEST	Higher	985, 0.187, SSW
AC205	FURNITURE RESTORNATI	26 GARDEN ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	987, 0.187, NNE
W206	DIIORGI HOME	47 WARREN STREET	NY LTANKS	Higher	994, 0.188, West
AD207	CON EDISON MANHOLE:	350 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1012, 0.192, North
AA208	CON EDISON	35 BARTELS PL	RCRA-VSQG, RCRA NonGen / NLR, NY MANIFEST	Lower	1015, 0.192, SW
AA209	CON EDISON	35 BARTELS PL	NY MANIFEST	Lower	1015, 0.192, SW
AE210	SPILL NUMBER 0109254	40 WARREN ST	NY LTANKS, NY Spills	Higher	1018, 0.193, WSW
AB211	CON EDISON TRANSFORM	595 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1029, 0.195, SSW
212	CON EDISON TRANSFORM	592 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1034, 0.196, South
AB213	RUSH MFG CORP	18 COLUMBUS AVE.	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1048, 0.198, SSW
W214	NYNEX	UNION AVENUE AND WAR	NY MANIFEST	Higher	1058, 0.200, West
215	CITIZEN	33 GROVE ST	NY LTANKS	Lower	1062, 0.201, WSW
AF216	THE MALL	MAIN STREET	NY LTANKS	Lower	1074, 0.203, East
AG217	CON EDISON SERVICE B	CENTRE AVE & LEROY	RCRA NonGen / NLR, FINDS	Higher	1079, 0.204, South
AG218	CON EDISON	CENTRE AVE & LEROY	NY MANIFEST	Higher	1079, 0.204, South
AG219	CON EDISON SERVICE B	LEROY PL & CENTER AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1079, 0.204, South
AB220	381-383 HUGUENOT LLC	381 HUGUENOT STREET	NY UST	Higher	1086, 0.206, SSW
AH221	CON EDISON SERVICE B	174 NORTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1089, 0.206, ESE
AD222	HNJ REALTY	358-364 N AVENUE	PA MANIFEST	Lower	1092, 0.207, North
AD223	HNJ REALTY	358-364 N AVE	PA MANIFEST	Lower	1092, 0.207, North
AD224	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1092, 0.207, North
AD225	SCHMUCKLER'S DRY CLE	358-364 NORTH AVENUE	NY BROWNFIELDS	Lower	1092, 0.207, North
AD226	SCHMUKLER'S CLEANERS	360 NORTH AVE.	NY DRYCLEANERS	Lower	1111, 0.210, North
AD227	SCHMUCKLERS CLEANERS	360 NORTH AVE	RCRA-VSQG, NY MANIFEST	Lower	1111, 0.210, North
AI228	NEW ROCHELLE HOSPITA	COVION PLACE	NY LTANKS	Higher	1112, 0.211, NW
AI229	SOUND SHORE MED CENT	16 GUION PLACE	NY LTANKS	Higher	1138, 0.216, NW
AI230	SOUND SHORE MEDICAL	16 GUION PL	PA MANIFEST	Higher	1138, 0.216, NW
AI231	MONTEFIORE - NEW ROC	16 GUION PL	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	1138, 0.216, NW
AI232	MONTEFIORE - NEW ROC	16 GUION PLACE	NY UST, NY AST	Higher	1138, 0.216, NW
233	RESIDENCE	79 WARREN ST	NY LTANKS	Higher	1140, 0.216, West
AI234	66 MEMORIAL BLVD	66 MEMORIAL BLVD	NY LTANKS	Higher	1140, 0.216, NW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC235	LEXINGTON CENTER FOR	3 COTTAGE PL	NJ MANIFEST	Lower	1141, 0.216, NNE
AC236	LEXINGTON CENTER FOR	3 COTTAGE PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1141, 0.216, NNE
AH237	35 CLINTON PLACE LLC	35 CLINTON PLACE	NY AST	Higher	1150, 0.218, SE
AJ238	MAYCO, LLC	18-20 MAY ST	NY AST	Lower	1151, 0.218, NNW
239	CON EDISON	46 CLINTON PL	RCRA NonGen / NLR, NY MANIFEST	Higher	1151, 0.218, SE
AB240	THE HUGUENOT	387 HUGUENOT STREET	NY BROWNFIELDS	Lower	1154, 0.219, SSW
AB241	THE HUGUENOT	387 HUGUENOT STREET	NY ENG CONTROLS	Lower	1154, 0.219, SSW
AB242	THE HUGUENOT	387 HUGUENOT STREET	NY INST CONTROL	Lower	1154, 0.219, SSW
AF243	MONROE COLLEGE	420 MAIN STREET	NY UST	Lower	1174, 0.222, East
AB244	CON EDISON	MAIN ST & MAPLE AVE	NY MANIFEST	Lower	1185, 0.224, SSW
AB245	CON EDISON	MAPLE AVE & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST	Lower	1185, 0.224, SSW
AB246	CON EDISON MANHOLE:	MAIN ST & MAPLE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1185, 0.224, SSW
AK247	CON EDISON MANHOLE 1	HUGEONOT ST & HARRIS	RCRA NonGen / NLR, NJ MANIFEST	Lower	1187, 0.225, NE
AK248	CONSOLIDATED EDISON	HUGUENOT ST & HARRIS	NY MANIFEST	Lower	1187, 0.225, NE
AE249	PREFERRED CLEANERS	95 UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1188, 0.225, West
250	ALL AMERICAN SPORTS	44 COLUMBUS AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1199, 0.227, SW
AH251	30 CLINTON PLACE OWN	30 CLINTON PLACE	NY UST, NY AST	Lower	1203, 0.228, SE
AH252	CO-OP	30 CLINTON PLACE	NY LTANKS	Lower	1203, 0.228, SE
AH253	CON EDISON	150 NORTH AV	NY MANIFEST	Lower	1207, 0.229, ESE
AL254	CON EDISON	45 HARRISON ST	NY MANIFEST	Lower	1218, 0.231, ENE
AL255	CON EDISON	45 HARRISON ST	NJ MANIFEST	Lower	1218, 0.231, ENE
AL256	CITY OF NEW ROCHELLE	45 HARRISON STREET	NY LTANKS	Lower	1218, 0.231, ENE
AL257	NEW ROCHELLE FIRE ST	45 HARRISON STREET	NY UST	Lower	1218, 0.231, ENE
AL258	CON EDISON	45 HARRISON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1218, 0.231, ENE
AH259	CON EDISON MANHOLE:	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Lower	1219, 0.231, ESE
AH260	CON EDISON SERVICE B	NORTH AVE & CLINTON	RCRA NonGen / NLR, NY MANIFEST	Lower	1219, 0.231, ESE
AJ261	CON EDISON	OPP 20 LOCKWOOD AV	NY MANIFEST	Lower	1222, 0.231, NNW
AD262	CON EDISON	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR	Lower	1224, 0.232, North
AD263	CON EDISON	LOCKWOOD AVE & NORTH	NY MANIFEST	Lower	1224, 0.232, North
AD264	CON EDISON TRANSFORM	LOCKWOOD AVE & NORTH	RCRA NonGen / NLR, NY MANIFEST	Lower	1224, 0.232, North
AD265	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1224, 0.232, North
AD266	CON EDISON	LOCKWOOD AVE & NORTH	NJ MANIFEST	Lower	1224, 0.232, North
AD267	CON EDISON MANHOLE 1	NORTH AVE & LOCKWOOD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1224, 0.232, North
AE268	100-102 UNION AVENUE	100-102 UNION AVENUE	NY LTANKS	Higher	1225, 0.232, West
AL269	CON EDISON	HARRISON ST & CEDER	NJ MANIFEST	Lower	1226, 0.232, ENE
AL270	CON EDISON SERVICE B	HARRISON AVE & CEDAR	RCRA NonGen / NLR, NY MANIFEST	Lower	1226, 0.232, ENE
AL271	CON EDISON	HARRISON ST & CEDER	RCRA NonGen / NLR, FINDS, ECHO	Lower	1226, 0.232, ENE
AL272	CON ED	HARRISON ST & CEDER	NY MANIFEST	Lower	1226, 0.232, ENE
AG273	125	CENTRE AVE	NY LTANKS	Higher	1227, 0.232, South

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AE274	KAGEL HOME	99 UNION AVE	NY LTANKS	Higher	1227, 0.232, West
AK275	GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NY UST	Lower	1243, 0.235, NE
AK276	LONGINES WITTNAUER W	145 HUGUENOT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1243, 0.235, NE
AK277	GALESI ENTERPRICES	145 HUGUENOT ST	NY LTANKS, NY Spills	Lower	1243, 0.235, NE
AL278	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1245, 0.236, ENE
AL279	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1245, 0.236, ENE
AL280	CON EDISON	HARRISON ST & FOUNTA	RCRA NonGen / NLR, FINDS, ECHO	Lower	1245, 0.236, ENE
AL281	CON EDISON	FOUNTAIN PL & HARRIS	NJ MANIFEST	Lower	1245, 0.236, ENE
AL282	CON EDISON	HARRISON ST & FOUNTA	NJ MANIFEST	Lower	1245, 0.236, ENE
AL283	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1245, 0.236, ENE
AL284	CON EDISON	FOUNTAIN PL & HARRIS	RCRA NonGen / NLR	Lower	1245, 0.236, ENE
AL285	CON EDISON	FOUNTAIN PL & HARRIS	NY MANIFEST	Lower	1245, 0.236, ENE
AL286	CON ED	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1245, 0.236, ENE
AL287	CON EDISON	HARRISON ST & FOUNTA	NY MANIFEST	Lower	1245, 0.236, ENE
AF288	MONROE COLLEGE	5 FRANKLIN AVE	NY LTANKS	Lower	1247, 0.236, East
AE289	TANK TEST FAILURE	50 WALNUT ST	NY LTANKS	Higher	1260, 0.239, WSW
AM290	DOMENICO PROCOPIO PR	618 MAIN ST	NY LTANKS, NY Spills	Lower	1273, 0.241, SSW
AE291	ROBERTS HOME	58 WALNUT STREET	NY LTANKS	Higher	1278, 0.242, WSW
AN292	@	60 WALNUT STREET	NY LTANKS	Higher	1284, 0.243, West
AH293	OFF-SITE FLAMINGO CL	149 NORTH AVENUE	NY BROWNFIELDS	Lower	1295, 0.245, ESE
AH294	FLAMINGO CLEANERS	149 NORTH AVE	RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Lower	1295, 0.245, ESE
AH295	FLAMINGO/TYK CLEANER	149 NORTH AV.	NY DRYCLEANERS	Lower	1295, 0.245, ESE
AH296	COLONIAL CLEANERS CO	149 NORTH AVE	RCRA NonGen / NLR	Lower	1295, 0.245, ESE
AG297	130 CENTRE AVENUE CO	130 CENTRE AVENUE	NY AST	Higher	1319, 0.250, South
AL298	FIREHOUSE	HARRISON ST	NY LTANKS	Lower	1327, 0.251, ENE
AK299	BERGMAN REALTY SERVI	140 HUGUENOT STREET	NY LTANKS	Lower	1349, 0.255, NE
AO300	BLESSED SACREMENT CH	15 SHEA PL	NY LTANKS	Higher	1387, 0.263, South
AN301	SPILL NUMBER 0011198	114 UNION AVE	NY LTANKS, NY Spills	Higher	1390, 0.263, West
AJ302	DIMATTOE TTF	55 MAY STREET	NY LTANKS	Lower	1403, 0.266, NNW
303	CITY OF NEW ROCHELLE	1 HARRISON STREET	NY LTANKS	Lower	1409, 0.267, East
AM304	EXXON S/S	635 MAIN STREET	NY LTANKS, NY Spills	Lower	1413, 0.268, SSW
AP305	NEW ROCHELLE CATH MI	24 MAPLE AV	NY LTANKS, NY Spills	Higher	1419, 0.269, South
AQ306	COMMERCIAL PROPERTY	38 LOCUST AVE	NY LTANKS	Lower	1437, 0.272, ESE
AQ307	COMMERCIAL SITE	38 LOCUST AVE	NY LTANKS	Lower	1437, 0.272, ESE
AR308	SPILL NUMBER 0208792	386 NORTH AV	NY LTANKS	Lower	1446, 0.274, North
AS309	DEMELIA - TTF	95 WASHINGTON AVE	NY LTANKS	Higher	1448, 0.274, West
310	10 COMMERCE DRIVE RA	10 COMMERCE DRIVE	NY INST CONTROL, NY BROWNFIELDS, NY Spills	Lower	1459, 0.276, NE
311	RESIDENCE	64 CHURCH ST	NY LTANKS	Lower	1481, 0.280, SE
AT312	CANDREA/GALLETTA RES	35 CHARLES ST	NY LTANKS	Higher	1512, 0.286, WSW

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AN313	SPILL NUMBER 0007965	45 CHARLES ST	NY LTANKS	Higher	1528, 0.289, WSW
AU314	GKIDS REALTY	10/12 PINE COURT	NY LTANKS	Lower	1530, 0.290, SW
AU315	RUSH MANUFACTURING C	10-12 PINE CT	CORRACTS, RCRA-VSQG, NY Spills, FINDS, ECHO, RI...	Lower	1530, 0.290, SW
AS316	BRAM REALTY	105 WASHINGTON AVE	NY LTANKS	Lower	1548, 0.293, West
AT317	MERLUCCI RESIDENCE	30 CHARLES STREET	NY LTANKS	Higher	1548, 0.293, WSW
AR318	KGM PROPERTY ASSOC.	394 N. AVE.	NY LTANKS	Lower	1551, 0.294, North
AR319	GETTY# 677	381 NORTH AVE	NY LTANKS, NY Spills	Lower	1570, 0.297, North
AR320	KGM REALTY CO.	396 NORTH AVE.	NY LTANKS	Lower	1582, 0.300, North
AQ321	APT. BUILDING	55-59 LOCUST AVE.	NY LTANKS	Higher	1582, 0.300, ESE
AO322	BLESSED SACRAMENT HS	24 SHEA PLACE	NY LTANKS	Higher	1607, 0.304, South
AO323	BLESSED SACRAMENT HI	24 SHEA PLACE	NY LTANKS	Higher	1609, 0.305, South
AV324	BLESSED SACRAMENT CH	SHEA PLACE	NY LTANKS	Higher	1623, 0.307, SSE
AW325	PROFESSIONAL OFFICE	421 HUGUENOT STREET	NY LTANKS, NY Spills	Lower	1637, 0.310, SSW
326	FRANKA INC.	132-143 UNION AVE.	NY LTANKS	Higher	1639, 0.310, West
AV327	FAILED TANK TEST	156 CENTRE AVE	NY LTANKS	Lower	1646, 0.312, SSE
AV328	APARTMENT HOUSE	156 CENTRE AVE	NY LTANKS	Lower	1646, 0.312, SSE
AP329	APT. BUILDING	47 MAPLE AV	NY LTANKS, NY Spills	Lower	1650, 0.312, South
AR330	DIPASQUALE PROPERTY	400 NORTH AVE	NY LTANKS	Lower	1671, 0.316, North
AQ331	SPILL NUMBER 0105779	60-70 LOCUST AVE	NY LTANKS, NY Spills	Lower	1679, 0.318, ESE
AQ332	APARTMENT BUILDING	60-70 LOCUST AVE	NY LTANKS	Lower	1679, 0.318, ESE
AQ333	COMMERCIAL USTS	60-70 LOCUST AVE	NY LTANKS	Lower	1679, 0.318, ESE
AU334	INDUSTRIAL OVERALL S	30 PINE ST	RCRA-LQG, NY SHWS, NY Spills, FINDS, ECHO, NY...	Lower	1686, 0.319, SW
335	SPILL 0106072 / PBS	370 MAIN ST	NY LTANKS	Lower	1717, 0.325, ENE
336	APARTMENT BUILDING	67-70 LOCUST AVE	NY LTANKS	Lower	1719, 0.326, ESE
AX337	BUSINESS	88 GROVE AVE.	NY LTANKS	Lower	1746, 0.331, WSW
AX338	COMMERCIAL BUILDING	88-90 GROVE AVE.	NY LTANKS	Lower	1746, 0.331, WSW
AY339	COMMERICAL BUILDING	405 NORTH AVE	NY LTANKS	Lower	1763, 0.334, North
AY340	RESIDENCE	405 NORTH AVE	NY LTANKS	Lower	1763, 0.334, North
341	KLING	108 VAN GUILDER AVE	NY LTANKS, NY Spills	Lower	1764, 0.334, WNW
AU342	BELIVE HOME	20 PINE STREET	NY LTANKS	Lower	1774, 0.336, SW
343	CON EDISON-CEDAR ST	ONE RAMADA PLAZA	EDR MGP	Lower	1789, 0.339, NE
344	CHURCH OF LATTER DAY	111 NORTH AVE	NY LTANKS	Lower	1794, 0.340, SE
AW345	SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	NY LTANKS	Lower	1830, 0.347, SSW
AY346	APARTMENT BLDG	1 THE BOULEVARD	NY LTANKS	Lower	1892, 0.358, North
AY347	PRIVATE DWELLING	19 ROCHELLE PLACE	NY LTANKS	Lower	1911, 0.362, NNW
348	BUSINESS COMPLEX	55 WEBSTER AVE	NY LTANKS	Lower	1916, 0.363, SW
AZ349	I-95 EXIT 16	OPP. 111 CEDAR ST.	NY LTANKS	Lower	1931, 0.366, NNE
AZ350	CON ED DOWNED O/H TR	115 CEDAR ST	NY LTANKS, NY Spills	Lower	1932, 0.366, NNE
351	NICK MAZZA RESIDENCE	20 DAVIS AVE	NY LTANKS	Lower	1937, 0.367, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BA352	SHERIDEN PLAZA	1 SHERIDEN PLAZA	NY LTANKS	Lower	1951, 0.370, NE
BB353	JASON PARTNERS LTD	675 MAIN ST	NY LTANKS	Lower	1962, 0.372, SSW
BC354	ABANDONED GAS STATIO	197 WEBSTER AV	NY LTANKS	Lower	1984, 0.376, West
BA355	MUTUAL BISCUIT COMPA	65 RIVER ST.	NY LTANKS, NY Spills	Lower	1997, 0.378, NE
BD356	GETTY 58114	340 MAIN STREET	NY LTANKS, NY Spills	Lower	2002, 0.379, ENE
357	SUNOCO	71 HUGUENOT ST	NY LTANKS, NY Spills	Lower	2012, 0.381, ENE
BB358	6 WEBSTER	6 WEBSTER AVE	NY LTANKS	Lower	2020, 0.383, SSW
BE359	SPILL NUMBER 0314082	136 VANGUILDER AVE	NY LTANKS	Lower	2035, 0.385, WNW
BF360	RESIDENCE	100 SICKLES AVE	NY LTANKS, NY Spills	Lower	2042, 0.387, NW
BC361	MAR-LAP SVC CNTR	210 WEBSTER AVE	NY LTANKS, NY Spills	Lower	2086, 0.395, West
BD362	JEROME RESIDENCE	33 ECHO AVE	NY LTANKS	Lower	2092, 0.396, ENE
BG363	MICELI HOME	194 CENTRE AVE	NY LTANKS	Lower	2092, 0.396, SSE
BF364	BRIEN-AMIE RESIDENCE	105 SICKLES AVE	NY LTANKS	Lower	2093, 0.396, NW
365	SPILL NUMBER 0302495	85 NORTH AVE	NY LTANKS, NY Spills	Lower	2093, 0.396, SE
BD366	POWERTEST,ECHO & MAI	36 ECHO AVE @ MAIN S	NY LTANKS	Lower	2106, 0.399, ENE
BF367	POINVIL RESIDENCE	107 SICKLES AVE	NY LTANKS	Lower	2108, 0.399, NW
BB368	AMOCO SERVICE STATIO	690 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	2122, 0.402, SSW
BH369	RESIDENCE	10 LAFAYETTE ST	NY LTANKS	Lower	2126, 0.403, East
BE370	YOUNG ADULT INSTITUT	150 VAN GUILDER AVE	NY LTANKS	Lower	2128, 0.403, WNW
BI371	COMMERCIAL-TTF	172 UNION AVE	NY LTANKS	Lower	2129, 0.403, West
BF372	GONZALO RESIDENCE	112 SICKLES AVE	NY LTANKS, NY Spills	Lower	2142, 0.406, NW
BD373	GAS STATION	44 ECHO AVE	NY LTANKS	Lower	2145, 0.406, ENE
BD374	MARIO'S S/S	44 ECHO AVENUE	NY LTANKS, NY Spills	Lower	2145, 0.406, ENE
BH375	GONCALVES RESIDENCE	1 LAFFAYETTE STREET	NY LTANKS	Lower	2150, 0.407, East
BG376	200 CENTRA CORP	200 CENTER AVE	NY LTANKS	Lower	2169, 0.411, SSE
BD377	CONSOLIDATED EDISON	ECHO AVENUE	NY SHWS, NY ENG CONTROLS, NY INST CONTROL	Lower	2173, 0.412, ENE
BI378	FIRST ASSEMBLY OF GO	177 UNION AVE	NY LTANKS	Lower	2181, 0.413, West
379	48 1ST STREET	48 1ST STREET	NY LTANKS	Lower	2188, 0.414, WSW
BH380	GONCALVES RESIDENCE	1 LAFAYETTE STREET	NY LTANKS	Lower	2191, 0.415, East
BF381	RESIDENCE	7 PRINCE ST	NY LTANKS	Lower	2193, 0.415, NW
BJ382	TROY RESIDENCE	150 LOCKWOOD AV	NY LTANKS, NY Spills	Lower	2202, 0.417, WNW
BF383	RENTAL HOUSE	119 SICKLES AVE.	NY LTANKS	Lower	2216, 0.420, NW
BK384	SPILL NUMBER 0104402	30 LINCOLN ST	NY LTANKS	Lower	2243, 0.425, NE
BI385	SPILL NUMBER 0210366	182 UNION AV	NY LTANKS	Lower	2248, 0.426, West
BG386	APT. BUILDING	208 CENTER AVE.	NY LTANKS, NY Spills	Lower	2272, 0.430, SSE
BK387	VACCARO RESIDENCE	52 LINCOLN ST	NY LTANKS, NY Spills	Lower	2275, 0.431, NE
BL388	DEFENDER MARINE SUPP	309 MAIN ST	NY LTANKS	Lower	2307, 0.437, ENE
BM389	SPILL NUMBER 0009195	17 POPLAR PL	NY LTANKS	Lower	2311, 0.438, SSE
BG390	RESIDENCE	6 POPLAR ROAD	NY LTANKS	Lower	2315, 0.438, SSE

MAPPED SITES SUMMARY

Target Property Address:
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
391	LIPMAN RESIDENCE	54 LIBERTY AVE	NY LTANKS	Lower	2328, 0.441, South
392	WALTON RESIDENCE	129 SICKLES AVE	NY LTANKS	Lower	2331, 0.441, NW
393	FIUMFREDO RESIDENCE	12 BAYVIEW AVE	NY LTANKS	Lower	2339, 0.443, East
BL394	TELEDYNE HYDRA-POWER	310 MAIN ST	NY SWF/LF, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	2339, 0.443, ENE
395	WILLIAMS TTF	23 1ST ST	NY LTANKS	Lower	2355, 0.446, WSW
396	RESIDENCE	38 BEECHWOOD AVE	NY LTANKS	Lower	2362, 0.447, SW
BM397	FUNICELOLO HOME	24 POPLAR PLACE	NY LTANKS	Lower	2369, 0.449, SSE
BM398	LABELLA RESIDENCE	219 CENTRE AVE	NY LTANKS	Lower	2392, 0.453, SSE
399	SPILL NUMBER 0210080	196 UNION AV	NY LTANKS	Lower	2418, 0.458, West
BN400	RESIDENCE	98 LIBERTY AVE	NY LTANKS	Lower	2420, 0.458, South
BJ401	MANONE PLACE	15 COLONIAL PLACE	NY LTANKS	Lower	2438, 0.462, WNW
402	TRINITY ARMS APARTME	25 TRINITY PLACE	NY LTANKS	Lower	2458, 0.466, SSE
BO403	SPILL NUMBER 9814027	48 REMINGTON PL	NY LTANKS	Lower	2482, 0.470, NW
404	RITACCO HOME	24 JACKSON STREET	NY LTANKS	Lower	2485, 0.471, ENE
405	CON EDISON - ECHO AV	ECHO AVENUE	SEMS-ARCHIVE, RCRA-VSQG, NY Spills, NY MANIFEST	Lower	2500, 0.473, East
BP406	COMMERICAL BUILIDING	719 MAIN ST	NY LTANKS	Lower	2518, 0.477, SSW
BN407	SPILL NUMBER 9803423	106 LIBERTY AV	NY LTANKS	Lower	2541, 0.481, South
408	TTF AT RESIDENCE	68 JACKSON ST	NY LTANKS	Lower	2553, 0.484, NE
BN409	COLLEGE OF NEW ROCHE	103 LIBERTY AVE	NY LTANKS	Lower	2558, 0.484, South
410	CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	NY LTANKS	Lower	2562, 0.485, SE
BQ411	FORMER MANCUSO MARIN	HUNTINGTON PLACE	US BROWNFIELDS	Lower	2564, 0.486, ENE
BQ412	NELSTAD MATERIAL COR	40 HUNTINGTON PL	NY LTANKS, NY Spills, NY SPDES	Lower	2568, 0.486, ENE
BN413	BLANCO RESIDENCE	30 LINDEN PLACE	NY LTANKS	Lower	2569, 0.487, South
414	BEECHWOOD AVENUE ORG	85 BEECHWOOD AVENUE	NY SWF/LF, NY SPDES	Lower	2578, 0.488, SW
415	7-UP BOTTLING CO	PALMER AVE & CEDAR S	NY LTANKS	Lower	2583, 0.489, NE
BR416	NORTH EVARTS	44 NORTH EVARTS AVE	NY LTANKS	Lower	2583, 0.489, SE
BO417	HERNANDEZ - TTF	70 REMINGTON PLACE	NY LTANKS	Higher	2583, 0.489, NW
BR418	RESIDENCE APT BLD	45 NORTH AVE	NY LTANKS	Lower	2586, 0.490, SE
BP419	10 FAMILY HOUSE + CO	727-729 MAIN ST	NY LTANKS	Lower	2640, 0.500, SSW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
LA ROCHELLE & SHEARW 255 HUGUENOT STREET CITY OF NEW ROCHELLE, NY 10801	NY SPDES Permit Number: NYR11E141	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
NY TANKS ---------- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

NY VCP ---------- Voluntary Cleanup Agreements
INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
NY SWRCY ---------- Registered Recycling Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---------- Delisted Registry Sites
US CDL ---------- National Clandestine Laboratory Register
NY PFAS ---------- PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST ---------- Historical Petroleum Bulk Storage Database
NY HIST AST ---------- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---------- Spill Liens Information
LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System

NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
NY LEAD ---- Lead-based Paint Testing Results
MINES MRDS ---- Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 01/25/2022 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - ECHO AV Site ID: 0202659 EPA Id: NYD981141252	***ECHO AVENUE***	***E 1/4 - 1/2 (0.473 mi.)***	***405***	***1118***

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 02/28/2022 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSH MANUFACTURING C	***10-12 PINE CT***	***SW 1/4 - 1/2 (0.290 mi.)***	***AU315***	***885***

EPA ID:: NYD075436394

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 02/28/2022 has revealed that there are 6 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - TRANSFO EPA ID:: NYP004353199	DIVISION ST AND HUGE	S 0 - 1/8 (0.008 mi.)	B14	26
CON EDISON - TRANSFO EPA ID:: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P126	309

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.138 mi.)***	***K157***	***374***
NYS THRUWAY AUTHORIT EPA ID:: NYD986963445	***I-95 NORTH AVE OVER***	***N 1/8 - 1/4 (0.147 mi.)***	***V170***	***414***
NYSDEC-SITE 360109 I EPA ID:: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.154 mi.)***	***N185***	***452***
FLAMINGO CLEANERS EPA ID:: NYD012946885	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AH294***	***810***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/28/2022 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MONTEFIORE - NEW ROC EPA ID:: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AI231***	***605***

EXECUTIVE SUMMARY

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 02/28/2022 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #8447 EPA ID:: NYR000194654	***222 NORTH AVE***	***E 0 - 1/8 (0.098 mi.)***	***J81***	***152***
CENTRE CLEANERS EPA ID:: NYD982531634	***62 CENTRE STREET***	***S 0 - 1/8 (0.108 mi.)***	***I97***	***248***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004205654	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.192 mi.)***	***AA208***	***539***
SCHMUCKLERS CLEANERS EPA ID:: NYD012950770	***360 NORTH AVE***	***N 1/8 - 1/4 (0.210 mi.)***	***AD227***	***590***

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/08/2022 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL Site Code: 413917 Class Code: Significant threat to the public health or environment - action required.	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.154 mi.)***	***N183***	***445***
INDUSTRIAL OVERALL S Site Code: 355304	***30 PINE ST***	***SW 1/4 - 1/2 (0.319 mi.)***	***AU334***	***943***
CONSOLIDATED EDISON Site Code: 56077	***ECHO AVENUE***	***ENE 1/4 - 1/2 (0.412 mi.)***	***BD377***	***1053***

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/21/2021 has revealed that there are

2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELEDYNE HYDRA-POWER	***310 MAIN ST***	***ENE 1/4 - 1/2 (0.443 mi.)***	***BL394***	***1096***
BEECHWOOD AVENUE ORG	***85 BEECHWOOD AVENUE***	***SW 1/4 - 1/2 (0.488 mi.)***	***414***	***1139***

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 03/15/2022 has revealed that there are 166 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VACANT LOT	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.030 mi.)	B19	36
Spill Number/Closed Date: 0510542 / 2006-03-15				
Site ID: 356539				
Spill Date: 2005-12-08				
SHORELINE OIL	296 HUGENOT ST,REAR	SSW 0 - 1/8 (0.032 mi.)	B21	38
Spill Number/Closed Date: 8709425 / 1988-04-06				
Site ID: 83347				
Spill Date: 1988-02-03				
LILLIAN VERNON CO.	WESTCHESTER PLACE	S 0 - 1/8 (0.033 mi.)	B22	39
Spill Number/Closed Date: 9213055 / 1995-03-16				
Site ID: 201286				
Spill Date: 1993-02-22				
JONES RESIDENCE	311 HUGUENOT STREET	SSW 0 - 1/8 (0.044 mi.)	B27	48
Spill Number/Closed Date: 0410335 / 2005-09-11				
Site ID: 335236				
Spill Date: 2004-12-17				
MAIN LIBRARY	LAWTON ST	E 0 - 1/8 (0.045 mi.)	C33	61
Spill Number/Closed Date: 9713843 / 1998-03-27				
Site ID: 273025				
Spill Date: 1998-03-13				
LAWTON STREET REALTY	41-43 LAWTON ST	ESE 0 - 1/8 (0.055 mi.)	C42	77
Spill Number/Closed Date: 1706064 / 2019-02-15				
Spill Number/Closed Date: 1605726 / 2019-02-15				
Site ID: 560365				
Site ID: 532284				
Spill Date: 2017-09-21				
Spill Date: 2016-09-07				
NORTH AVE REALITY	5 ANDERSON ST	E 0 - 1/8 (0.084 mi.)	J68	128
Spill Number/Closed Date: 8803214 / 1989-11-30				
Spill Number/Closed Date: 9812584 / 1999-07-12				
Spill Number/Closed Date: 9812585 / 1999-07-12				
Site ID: 68769				
Site ID: 68770				

Site ID: 68771
Spill Date: 1988-07-14
Spill Date: 1999-01-12

COMM/RESIDENT. PROPE	15 DIVISION STREET	SSE 0 - 1/8 (0.088 mi.)	G75	143
Spill Number/Closed Date: 9405558 / 2005-02-10				
Site ID: 119901				
Spill Date: 1994-07-25				
NEW ROCHELLE PUBLIC	MEMORIAL HIGHWAY	ESE 0 - 1/8 (0.091 mi.)	J76	144
Spill Number/Closed Date: 9111450 / 1992-02-06				
Site ID: 306853				
Spill Date: 1992-02-06				
APARTMENT BLDG	54 CENTRE AV	SSW 0 - 1/8 (0.100 mi.)	I84	165
Spill Number/Closed Date: 0403405 / 2004-12-10				
Spill Number/Closed Date: 0206558 / 2005-02-27				
Site ID: 84302				
Site ID: 254563				
Spill Date: 2004-06-29				
Spill Date: 2002-09-06				
COMMERCIAL PROPERTY	64 CENTRE AVE	S 0 - 1/8 (0.110 mi.)	I100	257
Spill Number/Closed Date: 1308480 / 2015-04-28				
Site ID: 489220				
Spill Date: 2013-11-20				
NYNEX LOCATION	342 HUEGNOT ST	SSW 0 - 1/8 (0.114 mi.)	I109	282
Spill Number/Closed Date: 9708146 / 1997-10-10				
Site ID: 270876				
Spill Date: 1997-10-10				
CATHOLIC NEWS PUBLIS	210 NORTH AVE	ESE 0 - 1/8 (0.120 mi.)	J119	299
Spill Number/Closed Date: 0503023 / 2005-08-28				
Site ID: 347516				
Spill Date: 2005-06-13				
LILLIAN VERNON CORP.	***543 MAIN STREET***	***SSE 0 - 1/8 (0.122 mi.)***	***P124***	***306***
Spill Number/Closed Date: 0308082 / 2004-05-12				
Site ID: 94435				
Spill Date: 2003-07-14				
CENTRE-MAIN ASSOCIAT	75 - 77 CENTER AVE	S 0 - 1/8 (0.124 mi.)	R133	320
Spill Number/Closed Date: 0311823 / 2004-12-30				
Site ID: 149369				
Spill Date: 2004-01-21				
COMMERCIAL PROPERTY	522 MAIN STREET	SSE 1/8 - 1/4 (0.128 mi.)	P136	326
Spill Number/Closed Date: 1100723 / 2011-06-06				
Site ID: 448142				
Spill Date: 2011-04-20				
OFFICE BLDG	542 MAIN STREET	SSE 1/8 - 1/4 (0.129 mi.)	P139	329
Spill Number/Closed Date: 0509995 / 2006-03-22				
Site ID: 355877				
Spill Date: 2005-11-21				
COMMERCIAL BUILDING	507 MAIN STREET	SE 1/8 - 1/4 (0.130 mi.)	S140	330
Spill Number/Closed Date: 9110835 / 1992-03-10				
Site ID: 286303				
Spill Date: 1992-01-17				
COCO RESIDENCE	81 CENTRE AVE	S 1/8 - 1/4 (0.131 mi.)	R146	346

Spill Number/Closed Date: 0311339 / 2005-01-10
Site ID: 313391
Spill Date: 2004-01-07

BARCLAYS BANK OF NY/ 491 MAIN ST. SE 1/8 - 1/4 (0.141 mi.) S160 386
Spill Number/Closed Date: 8905129 / 1991-03-25
Site ID: 299548
Spill Date: 1989-08-23

NEW ROCHELLE PUBLIC 1 LAWTON SE 1/8 - 1/4 (0.141 mi.) S161 387
Spill Number/Closed Date: 0201697 / 2002-09-18
Spill Number/Closed Date: 1311408 / Not Reported
Site ID: 306611
Site ID: 492304
Spill Date: 2002-05-15
Spill Date: 2014-03-06

CASARRA RESIDENCE 9 BADEAU PL W 1/8 - 1/4 (0.164 mi.) W189 472
Spill Number/Closed Date: 0209171 / 2003-02-05
Site ID: 157707
Spill Date: 2002-12-06

NYNEX 40 WASHINGTON AVE WNW 1/8 - 1/4 (0.174 mi.) X191 502
Spill Number/Closed Date: 8803234 / 1988-07-22
Site ID: 60528
Spill Date: 1988-07-14

RESIDENCE 18 BADEAU PLACE W 1/8 - 1/4 (0.182 mi.) W197 515
Spill Number/Closed Date: 9609269 / 1996-10-24
Site ID: 177416
Spill Date: 1996-10-24

ST GABRIEL SCHOOL 50 WASHINGTON AVE WNW 1/8 - 1/4 (0.186 mi.) X198 516
Spill Number/Closed Date: 0302359 / 2003-12-12
Site ID: 314440
Spill Date: 2003-06-05

INTERSTITIAL FAILURE ***50 WASHINGTON AVE*** ***WNW 1/8 - 1/4 (0.186 mi.)*** ***X200*** ***517***
Spill Number/Closed Date: 1903323 / 2019-09-18
Site ID: 591279
Spill Date: 2019-07-01

DIIORGI HOME 47 WARREN STREET W 1/8 - 1/4 (0.188 mi.) W206 534
Spill Number/Closed Date: 0500295 / 2005-08-28
Site ID: 343230
Spill Date: 2005-04-07

SPILL NUMBER 0109254 ***40 WARREN ST*** ***WSW 1/8 - 1/4 (0.193 mi.)*** ***AE210*** ***550***
Spill Number/Closed Date: 0812107 / 2009-03-03
Spill Number/Closed Date: 0109254 / 2001-12-19
Site ID: 409713
Site ID: 150939
Spill Date: 2009-02-06
Spill Date: 2001-12-19

NEW ROCHELLE HOSPITA COVION PLACE NW 1/8 - 1/4 (0.211 mi.) AI228 599
Spill Number/Closed Date: 9003911 / 1991-03-15
Site ID: 136814
Spill Date: 1990-07-09

SOUND SHORE MED CENT 16 GUION PLACE NW 1/8 - 1/4 (0.216 mi.) AI229 601
Spill Number/Closed Date: 0512440 / 2006-12-19

Site ID: 358758
Spill Date: 2006-01-26

RESIDENCE Spill Number/Closed Date: 0510555 / 2006-03-28 Site ID: 356553 Spill Date: 2005-12-08	79 WARREN ST	W 1/8 - 1/4 (0.216 mi.)	233	619
66 MEMORIAL BLVD Spill Number/Closed Date: 0002907 / 2000-10-24 Site ID: 59397 Spill Date: 2000-06-08	66 MEMORIAL BLVD	NW 1/8 - 1/4 (0.216 mi.)	AI234	620
100-102 UNION AVENUE Spill Number/Closed Date: 9608199 / 1996-11-08 Site ID: 166425 Spill Date: 1996-10-01	100-102 UNION AVENUE	W 1/8 - 1/4 (0.232 mi.)	AE268	761
125 Spill Number/Closed Date: 0001835 / 2000-05-15 Site ID: 205498 Spill Date: 2000-05-12	CENTRE AVE	S 1/8 - 1/4 (0.232 mi.)	AG273	771
KAGEL HOME Spill Number/Closed Date: 0513684 / 2006-03-09 Site ID: 360201 Spill Date: 2006-02-27	99 UNION AVE	W 1/8 - 1/4 (0.232 mi.)	AE274	772
TANK TEST FAILURE Spill Number/Closed Date: 1107925 / 2013-02-05 Site ID: 455637 Spill Date: 2011-09-21	50 WALNUT ST	WSW 1/8 - 1/4 (0.239 mi.)	AE289	803
ROBERTS HOME Spill Number/Closed Date: 0608623 / 2012-08-17 Site ID: 372634 Spill Date: 2006-10-23	58 WALNUT STREET	WSW 1/8 - 1/4 (0.242 mi.)	AE291	806
@ Spill Number/Closed Date: 0502010 / 2005-07-17 Site ID: 346287 Spill Date: 2005-05-19	60 WALNUT STREET	W 1/8 - 1/4 (0.243 mi.)	AN292	808
BLESSED SACREMENT CH Spill Number/Closed Date: 0204856 / 2003-10-03 Site ID: 167332 Spill Date: 2002-08-07	15 SHEA PL	S 1/4 - 1/2 (0.263 mi.)	AO300	830
SPILL NUMBER 0011198 Spill Number/Closed Date: 0011198 / 2001-04-06 Spill Number/Closed Date: 9414493 / 1995-02-14 Site ID: 151446 Site ID: 238808 Spill Date: 2001-01-14 Spill Date: 1995-02-02	***114 UNION AVE***	***W 1/4 - 1/2 (0.263 mi.)***	***AN301***	***832***
NEW ROCHELLE CATH MI Spill Number/Closed Date: 0204857 / 2003-10-03 Site ID: 80066 Spill Date: 2002-08-07	***24 MAPLE AV***	***S 1/4 - 1/2 (0.269 mi.)***	***AP305***	***841***
DEMELIA - TTF Spill Number/Closed Date: 1406916 / 2015-04-14	95 WASHINGTON AVE	W 1/4 - 1/2 (0.274 mi.)	AS309	848

Site ID: 500408
Spill Date: 2014-10-01

CANDREA/GALLETTA RES Spill Number/Closed Date: 1202322 / 2012-09-13 Site ID: 465083 Spill Date: 2012-06-07	35 CHARLES ST	WSW 1/4 - 1/2 (0.286 mi.)	AT312	882
SPILL NUMBER 0007965 Spill Number/Closed Date: 0007965 / 2000-10-26 Site ID: 61314 Spill Date: 2000-10-06	45 CHARLES ST	WSW 1/4 - 1/2 (0.289 mi.)	AN313	883
MERLUCCI RESIDENCE Spill Number/Closed Date: 1103221 / 2011-11-14 Site ID: 450778 Spill Date: 2011-06-22	30 CHARLES STREET	WSW 1/4 - 1/2 (0.293 mi.)	AT317	910
APT. BUILDING Spill Number/Closed Date: 9200639 / 1992-06-26 Site ID: 168647 Spill Date: 1992-04-01	55-59 LOCUST AVE.	ESE 1/4 - 1/2 (0.300 mi.)	AQ321	922
BLESSED SACRAMENT HS Spill Number/Closed Date: 1300960 / Not Reported Site ID: 481320 Spill Date: 2013-04-29	24 SHEA PLACE	S 1/4 - 1/2 (0.304 mi.)	AO322	923
BLESSED SACRAMENT HI Spill Number/Closed Date: 0400709 / 2004-07-06 Site ID: 249284 Spill Date: 2004-04-21	24 SHEA PLACE	S 1/4 - 1/2 (0.305 mi.)	AO323	924
BLESSED SACRAMENT CH Spill Number/Closed Date: 8704259 / 1987-11-20 Site ID: 324974 Spill Date: 1987-08-02	SHEA PLACE	SSE 1/4 - 1/2 (0.307 mi.)	AV324	926
FRANKA INC. Spill Number/Closed Date: 9312205 / 1995-11-09 Site ID: 176106 Spill Date: 1994-01-17	132-143 UNION AVE.	W 1/4 - 1/2 (0.310 mi.)	326	930
HERNANDEZ - TTF Spill Number/Closed Date: 1411959 / 2015-06-16 Site ID: 505764 Spill Date: 2015-03-23	70 REMINGTON PLACE	NW 1/4 - 1/2 (0.489 mi.)	BO417	1143

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST RIVER SAVINGS B Spill Number/Closed Date: 8912285 / 1991-01-16 Site ID: 271129 Spill Date: 1990-03-26	277 NORTH AVE.	NNE 0 - 1/8 (0.071 mi.)	H52	96
BUSINESS Spill Number/Closed Date: 0611580 / 2008-12-04 Site ID: 376243 Spill Date: 2007-01-18	277 NORTH AVENUE	NNE 0 - 1/8 (0.071 mi.)	H55	103
277 NORTH LLC Spill Number/Closed Date: 0611648 / 2008-12-04	277 NORTH AVENUE	NNE 0 - 1/8 (0.071 mi.)	H57	105

Site ID: 376329
Spill Date: 2007-01-19

DEVELOPMENT SITE	***175 HUGUENOT STREET***	***NE 0 - 1/8 (0.114 mi.)***	***O112***	***288***
Spill Number/Closed Date: 0512575 / 2006-03-08				
Site ID: 358910				
Spill Date: 2006-01-29				
CIOTTI RESIDENCE	***60 GRAND STREET***	***NNW 1/8 - 1/4 (0.141 mi.)***	***L162***	***390***
Spill Number/Closed Date: 0407555 / 2004-10-07				
Site ID: 332054				
Spill Date: 2004-10-07				
GUIDANCE CENTER INC	70 GRAND ST	NNW 1/8 - 1/4 (0.148 mi.)	L171	419
Spill Number/Closed Date: 9613894 / 1997-10-03				
Site ID: 77017				
Spill Date: 1997-02-26				
INDUST OVERALL SERVI	10 BARTELS PLACE	SW 1/8 - 1/4 (0.154 mi.)	N177	432
Spill Number/Closed Date: 1400928 / 2017-03-30				
Site ID: 494186				
Spill Date: 2014-04-28				
RITZCOVAN - TTF	22 BURLING LANE	NNW 1/8 - 1/4 (0.155 mi.)	187	467
Spill Number/Closed Date: 1506693 / 2016-03-22				
Site ID: 514123				
Spill Date: 2015-09-22				
CITIZEN	33 GROVE ST	WSW 1/8 - 1/4 (0.201 mi.)	215	565
Spill Number/Closed Date: 8708588 / 1989-11-28				
Site ID: 135309				
Spill Date: 1988-01-07				
THE MALL	MAIN STREET	E 1/8 - 1/4 (0.203 mi.)	AF216	566
Spill Number/Closed Date: 9010648 / 1991-01-04				
Site ID: 326514				
Spill Date: 1991-01-04				
CO-OP	30 CLINTON PLACE	SE 1/8 - 1/4 (0.228 mi.)	AH252	724
Spill Number/Closed Date: 9504589 / 1997-04-15				
Site ID: 189169				
Spill Date: 1995-07-17				
CITY OF NEW ROCHELLE	45 HARRISON STREET	ENE 1/8 - 1/4 (0.231 mi.)	AL256	729
Spill Number/Closed Date: 0513733 / 2006-06-21				
Site ID: 360263				
Spill Date: 2006-02-28				
GALESI ENTERPRICES	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.235 mi.)***	***AK277***	***780***
Spill Number/Closed Date: 8901038 / 1989-06-01				
Site ID: 259815				
Spill Date: 1989-05-02				
MONROE COLLEGE	5 FRANKLIN AVE	E 1/8 - 1/4 (0.236 mi.)	AF288	801
Spill Number/Closed Date: 0307536 / 2005-03-27				
Site ID: 165556				
Spill Date: 2003-10-16				
DOMENICO PROCOPIO PR	***618 MAIN ST***	***SSW 1/8 - 1/4 (0.241 mi.)***	***AM290***	***804***
Spill Number/Closed Date: 9809866 / 2004-03-30				
Site ID: 278454				
Spill Date: 1998-11-05				
FIREHOUSE	HARRISON ST	ENE 1/4 - 1/2 (0.251 mi.)	AL298	828

Spill Number/Closed Date: 9713840 / 1998-03-27
Site ID: 252028
Spill Date: 1998-03-13

BERGMAN REALTY SERVI Spill Number/Closed Date: 0505137 / 2007-11-07 Site ID: 350100 Spill Date: 2005-07-28	140 HUGUENOT STREET	NE 1/4 - 1/2 (0.255 mi.)	AK299	829
DIMATTOE TTF Spill Number/Closed Date: 1301890 / 2013-08-08 Site ID: 482303 Spill Date: 2013-05-23	55 MAY STREET	NNW 1/4 - 1/2 (0.266 mi.)	AJ302	835
CITY OF NEW ROCHELLE Spill Number/Closed Date: 0201696 / 2002-09-18 Site ID: 75380 Spill Date: 2002-05-15	1 HARRISON STREET	E 1/4 - 1/2 (0.267 mi.)	303	836
EXXON S/S Spill Number/Closed Date: 9206930 / 2005-03-11 Site ID: 140421 Spill Date: 1992-09-16	***635 MAIN STREET***	***SSW 1/4 - 1/2 (0.268 mi.)***	***AM304***	***838***
COMMERCIAL PROPERTY Spill Number/Closed Date: 1213228 / 2013-02-04 Site ID: 476407 Spill Date: 2012-12-10	38 LOCUST AVE	ESE 1/4 - 1/2 (0.272 mi.)	AQ306	844
COMMERCIAL SITE Spill Number/Closed Date: 0408593 / 2005-02-13 Spill Number/Closed Date: 0206043 / 2002-09-26 Site ID: 333366 Site ID: 239569 Spill Date: 2004-11-04 Spill Date: 2002-09-11	38 LOCUST AVE	ESE 1/4 - 1/2 (0.272 mi.)	AQ307	845
SPILL NUMBER 0208792 Spill Number/Closed Date: 0208792 / 2002-11-26 Site ID: 71430 Spill Date: 2002-11-25	386 NORTH AV	N 1/4 - 1/2 (0.274 mi.)	AR308	847
RESIDENCE Spill Number/Closed Date: 0408510 / 2008-05-01 Site ID: 333255 Spill Date: 2004-11-02	64 CHURCH ST	SE 1/4 - 1/2 (0.280 mi.)	311	880
GKIDS REALTY Spill Number/Closed Date: 0200337 / 2003-12-09 Site ID: 235436 Spill Date: 2002-04-10	10/12 PINE COURT	SW 1/4 - 1/2 (0.290 mi.)	AU314	884
BRAM REALTY Spill Number/Closed Date: 0902464 / 2010-02-01 Site ID: 414506 Spill Date: 2009-06-01	105 WASHINGTON AVE	W 1/4 - 1/2 (0.293 mi.)	AS316	909
KGM PROPERTY ASSOC. Spill Number/Closed Date: 9202033 / 1993-01-27 Site ID: 69270 Spill Date: 1992-05-12	394 N. AVE.	N 1/4 - 1/2 (0.294 mi.)	AR318	911
GETTY# 677	***381 NORTH AVE***	***N 1/4 - 1/2 (0.297 mi.)***	***AR319***	***913***

Spill Number/Closed Date: 0400912 / 2005-01-18 Site ID: 242546 Spill Date: 2004-04-27				
KGM REALTY CO. Spill Number/Closed Date: 9201744 / 1993-01-27 Site ID: 89642 Spill Date: 1992-05-12	396 NORTH AVE.	N 1/4 - 1/2 (0.300 mi.)	AR320	920
PROFESSIONAL OFFICE Spill Number/Closed Date: 0606014 / 2007-01-29 Site ID: 369299 Spill Date: 2006-08-23	***421 HUGUENOT STREET***	***SSW 1/4 - 1/2 (0.310 mi.)***	***AW325***	***927***
FAILED TANK TEST Spill Number/Closed Date: 1308221 / 2019-08-14 Site ID: 488939 Spill Date: 2013-11-12	156 CENTRE AVE	SSE 1/4 - 1/2 (0.312 mi.)	AV327	931
APARTMENT HOUSE Spill Number/Closed Date: 0312650 / 2004-04-22 Site ID: 267104 Spill Date: 2004-02-13	156 CENTRE AVE	SSE 1/4 - 1/2 (0.312 mi.)	AV328	933
APT. BUILDING Spill Number/Closed Date: 9603128 / 1996-06-14 Site ID: 178537 Spill Date: 1996-06-05	***47 MAPLE AV***	***S 1/4 - 1/2 (0.312 mi.)***	***AP329***	***934***
DIPASQUALE PROPERTY Spill Number/Closed Date: 1103122 / 2012-04-26 Site ID: 450672 Spill Date: 2011-06-20	400 NORTH AVE	N 1/4 - 1/2 (0.316 mi.)	AR330	936
SPILL NUMBER 0105779 Spill Number/Closed Date: 1802312 / 2018-10-17 Site ID: 570894 Spill Date: 2018-05-29	***60-70 LOCUST AVE***	***ESE 1/4 - 1/2 (0.318 mi.)***	***AQ331***	***937***
APARTMENT BUILDING Spill Number/Closed Date: 1602555 / 2018-06-26 Site ID: 528964 Spill Date: 2016-06-13	60-70 LOCUST AVE	ESE 1/4 - 1/2 (0.318 mi.)	AQ332	941
COMMERCIAL USTS Spill Number/Closed Date: 1803271 / 2018-12-06 Site ID: 571898 Spill Date: 2018-06-25	60-70 LOCUST AVE	ESE 1/4 - 1/2 (0.318 mi.)	AQ333	942
SPILL 0106072 / PBS Spill Number/Closed Date: 0106072 / 2001-11-13 Site ID: 133647 Spill Date: 2001-09-07	370 MAIN ST	ENE 1/4 - 1/2 (0.325 mi.)	335	958
APARTMENT BUILDING Spill Number/Closed Date: 1008207 / 2011-03-10 Site ID: 441682 Spill Date: 2010-11-04	67-70 LOCUST AVE	ESE 1/4 - 1/2 (0.326 mi.)	336	959
BUSINESS Spill Number/Closed Date: 9411669 / 2010-04-28 Site ID: 172950 Spill Date: 1994-12-01	88 GROVE AVE.	WSW 1/4 - 1/2 (0.331 mi.)	AX337	961
COMMERCIAL BUILDING	88-90 GROVE AVE.	WSW 1/4 - 1/2 (0.331 mi.)	AX338	962

Spill Number/Closed Date: 9411598 / 2010-04-28
Site ID: 113133
Spill Date: 1994-11-29

COMMERICAL BUILDING	405 NORTH AVE	N 1/4 - 1/2 (0.334 mi.)	AY339	964
Spill Number/Closed Date: 1805047 / 2018-11-13 Site ID: 574752 Spill Date: 2018-08-08				
RESIDENCE	405 NORTH AVE	N 1/4 - 1/2 (0.334 mi.)	AY340	965
Spill Number/Closed Date: 2003161 / Not Reported Site ID: 608877 Spill Date: 2020-07-17				
KLING	***108 VAN GUILDER AVE***	***WNW 1/4 - 1/2 (0.334 mi.)***	***341***	***966***
Spill Number/Closed Date: 0308565 / 2005-02-12 Site ID: 214235 Spill Date: 2003-11-13				
BELIVE HOME	20 PINE STREET	SW 1/4 - 1/2 (0.336 mi.)	AU342	970
Spill Number/Closed Date: 0500819 / 2005-05-22 Spill Number/Closed Date: 0413182 / 2005-05-22 Site ID: 343902 Site ID: 339043 Spill Date: 2005-04-20 Spill Date: 2005-03-18				
CHURCH OF LATTER DAY	111 NORTH AVE	SE 1/4 - 1/2 (0.340 mi.)	344	972
Spill Number/Closed Date: 0403126 / 2004-09-21 Site ID: 266466 Spill Date: 2004-06-22				
SPILL NUMBER 9908602	HUGUENOT ST & SOUTH	SSW 1/4 - 1/2 (0.347 mi.)	AW345	973
Spill Number/Closed Date: 9908602 / 2000-09-14 Site ID: 283271 Spill Date: 1999-10-15				
APARTMENT BLDG	1 THE BOULEVARD	N 1/4 - 1/2 (0.358 mi.)	AY346	974
Spill Number/Closed Date: 9809315 / 1999-10-14 Site ID: 303319 Spill Date: 1998-10-26				
PRIVATE DWELLING	19 ROCHELLE PLACE	NNW 1/4 - 1/2 (0.362 mi.)	AY347	976
Spill Number/Closed Date: 0706958 / 2008-02-01 Site ID: 387568 Spill Date: 2007-09-24				
BUSINESS COMPLEX	55 WEBSTER AVE	SW 1/4 - 1/2 (0.363 mi.)	348	977
Spill Number/Closed Date: 9912136 / 2000-05-11 Site ID: 86196 Spill Date: 2000-01-19				
I-95 EXIT 16	OPP. 111 CEDAR ST.	NNE 1/4 - 1/2 (0.366 mi.)	AZ349	978
Spill Number/Closed Date: 9001240 / 1990-08-01 Site ID: 244221 Spill Date: 1990-05-02				
CON ED DOWNED O/H TR	***115 CEDAR ST***	***NNE 1/4 - 1/2 (0.366 mi.)***	***AZ350***	***979***
Spill Number/Closed Date: 9812998 / 1999-02-22 Site ID: 163894 Spill Date: 1999-01-22				
NICK MAZZA RESIDENCE	20 DAVIS AVE	SSE 1/4 - 1/2 (0.367 mi.)	351	982

Spill Number/Closed Date: 0000532 / 2000-04-20 Site ID: 211468 Spill Date: 2000-04-13				
SHERIDEN PLAZA Spill Number/Closed Date: 8909204 / 1990-03-07 Site ID: 80178 Spill Date: 1989-12-19	1 SHERIDEN PLAZA	NE 1/4 - 1/2 (0.370 mi.)	BA352	983
JASON PARTNERS LTD Spill Number/Closed Date: 0211105 / 2003-03-26 Site ID: 86967 Spill Date: 2003-02-05	675 MAIN ST	SSW 1/4 - 1/2 (0.372 mi.)	BB353	984
ABANDONED GAS STATIO Spill Number/Closed Date: 9707099 / 2001-07-19 Site ID: 231589 Spill Date: 1997-09-15	197 WEBSTER AV	W 1/4 - 1/2 (0.376 mi.)	BC354	985
MUTUAL BISCUIT COMPA Spill Number/Closed Date: 8707334 / 1988-02-18 Spill Number/Closed Date: 8708530 / 1988-02-18 Site ID: 286036 Site ID: 286037 Spill Date: 1987-11-25 Spill Date: 1988-01-05	***65 RIVER ST.***	***NE 1/4 - 1/2 (0.378 mi.)***	***BA355***	***986***
GETTY 58114 Spill Number/Closed Date: 0913713 / 2010-04-29 Site ID: 426673 Spill Date: 2010-03-26	***340 MAIN STREET***	***ENE 1/4 - 1/2 (0.379 mi.)***	***BD356***	***991***
SUNOCO Spill Number/Closed Date: 9514850 / 1996-07-26 Site ID: 255332 Spill Date: 1996-02-20	***71 HUGUENOT ST***	***ENE 1/4 - 1/2 (0.381 mi.)***	***357***	***1000***
6 WEBSTER Spill Number/Closed Date: 0403816 / 2004-10-08 Site ID: 81655 Spill Date: 2004-07-09	6 WEBSTER AVE	SSW 1/4 - 1/2 (0.383 mi.)	BB358	1003
SPILL NUMBER 0314082 Spill Number/Closed Date: 0314082 / 2004-06-08 Site ID: 80232 Spill Date: 2004-03-25	136 VANGUILDER AVE	WNW 1/4 - 1/2 (0.385 mi.)	BE359	1004
RESIDENCE Spill Number/Closed Date: 1200264 / 2012-08-13 Site ID: 462885 Spill Date: 2012-04-10	***100 SICKLES AVE***	***NW 1/4 - 1/2 (0.387 mi.)***	***BF360***	***1006***
MAR-LAP SVC CNTR Spill Number/Closed Date: 1311416 / 2017-04-06 Site ID: 492314 Spill Date: 2014-03-06	***210 WEBSTER AVE***	***W 1/4 - 1/2 (0.395 mi.)***	***BC361***	***1009***
JEROME RESIDENCE Spill Number/Closed Date: 0405389 / 2005-02-13 Site ID: 235222 Spill Date: 2004-08-17	33 ECHO AVE	ENE 1/4 - 1/2 (0.396 mi.)	BD362	1015
MICELI HOME	194 CENTRE AVE	SSE 1/4 - 1/2 (0.396 mi.)	BG363	1017

Spill Number/Closed Date: 0604103 / 2006-10-22
Site ID: 366997
Spill Date: 2006-07-13

BRIEN-AMIE RESIDENCE | 105 SICKLES AVE | NW 1/4 - 1/2 (0.396 mi.) | BF364 | 1018
Spill Number/Closed Date: 0304963 / 2004-02-02
Site ID: 219644
Spill Date: 2003-08-08

SPILL NUMBER 0302495 | ***85 NORTH AVE*** | ***SE 1/4 - 1/2 (0.396 mi.)*** | ***365*** | ***1019***
Spill Number/Closed Date: 0302495 / 2003-08-12
Spill Number/Closed Date: 0507677 / 2009-10-09
Site ID: 114935
Site ID: 353132
Spill Date: 2003-06-09
Spill Date: 2005-09-26

POWERTEST,ECHO & MAI | 36 ECHO AVE @ MAIN S | ENE 1/4 - 1/2 (0.399 mi.) | BD366 | 1022
Spill Number/Closed Date: 8709260 / 1988-02-11
Site ID: 283199
Spill Date: 1988-01-30

POINVIL RESIDENCE | 107 SICKLES AVE | NW 1/4 - 1/2 (0.399 mi.) | BF367 | 1023
Spill Number/Closed Date: 1104844 / 2014-11-05
Site ID: 452458
Spill Date: 2011-07-28

AMOCO SERVICE STATIO | ***690 MAIN ST*** | ***SSW 1/4 - 1/2 (0.402 mi.)*** | ***BB368*** | ***1024***
Spill Number/Closed Date: 0209490 / 2002-12-16
Spill Number/Closed Date: 0212950 / 2003-04-01
Spill Number/Closed Date: 8604411 / 1987-01-14
Site ID: 274754
Site ID: 274755
Site ID: 274757
Spill Date: 2002-12-16
Spill Date: 2003-03-31
Spill Date: 1986-10-08

RESIDENCE | 10 LAFAYETTE ST | E 1/4 - 1/2 (0.403 mi.) | BH369 | 1038
Spill Number/Closed Date: 0512638 / 2006-03-15
Site ID: 358990
Spill Date: 2006-02-01

YOUNG ADULT INSTITUT | 150 VAN GUILDER AVE | WNW 1/4 - 1/2 (0.403 mi.) | BE370 | 1039
Spill Number/Closed Date: 0507808 / 2005-12-18
Site ID: 353295
Spill Date: 2005-09-29

COMMERCIAL-TTF | 172 UNION AVE | W 1/4 - 1/2 (0.403 mi.) | BI371 | 1040
Spill Number/Closed Date: 1502358 / 2020-09-01
Site ID: 508618
Spill Date: 2015-06-02

GONZALO RESIDENCE | ***112 SICKLES AVE*** | ***NW 1/4 - 1/2 (0.406 mi.)*** | ***BF372*** | ***1041***
Spill Number/Closed Date: 0610140 / 2007-10-24
Site ID: 374522
Spill Date: 2006-12-06

GAS STATION | 44 ECHO AVE | ENE 1/4 - 1/2 (0.406 mi.) | BD373 | 1043
Spill Number/Closed Date: 1309599 / 2014-02-13
Site ID: 490405

Spill Date: 2014-01-02

MARIO'S S/S	***44 ECHO AVENUE***	***ENE 1/4 - 1/2 (0.406 mi.)***	***BD374***	***1045***
Spill Number/Closed Date: 1001469 / 2010-11-01				
Spill Number/Closed Date: 9201557 / 2006-02-17				
Spill Number/Closed Date: 9210810 / 1995-02-09				
Site ID: 434525				
Site ID: 130487				
Site ID: 130489				
Spill Date: 2010-05-07				
Spill Date: 1992-05-08				
Spill Date: 1992-12-17				
GONCALVES RESIDENCE	1 LAFFAYETTE STREET	E 1/4 - 1/2 (0.407 mi.)	BH375	1050
Spill Number/Closed Date: 9410991 / 1994-11-29				
Site ID: 156301				
Spill Date: 1994-11-17				
200 CENTRA CORP	200 CENTER AVE	SSE 1/4 - 1/2 (0.411 mi.)	BG376	1051
Spill Number/Closed Date: 0604650 / 2007-12-12				
Site ID: 367663				
Spill Date: 2006-07-25				
FIRST ASSEMBLY OF GO	177 UNION AVE	W 1/4 - 1/2 (0.413 mi.)	BI378	1072
Spill Number/Closed Date: 1002183 / 2010-08-30				
Site ID: 435290				
Spill Date: 2010-05-26				
48 1ST STREET	48 1ST STREET	WSW 1/4 - 1/2 (0.414 mi.)	379	1073
Spill Number/Closed Date: 9911183 / 1999-12-22				
Site ID: 116893				
Spill Date: 1999-12-22				
GONCALVES RESIDENCE	1 LAFAYETTE STREET	E 1/4 - 1/2 (0.415 mi.)	BH380	1074
Spill Number/Closed Date: 0609401 / 2007-01-10				
Site ID: 373629				
Spill Date: 2006-11-15				
RESIDENCE	7 PRINCE ST	NW 1/4 - 1/2 (0.415 mi.)	BF381	1075
Spill Number/Closed Date: 0506424 / 2005-10-29				
Site ID: 351640				
Spill Date: 2005-08-24				
TROY RESIDENCE	***150 LOCKWOOD AV***	***WNW 1/4 - 1/2 (0.417 mi.)***	***BJ382***	***1076***
Spill Number/Closed Date: 0209497 / 2005-03-18				
Site ID: 221207				
Spill Date: 2002-12-16				
RENTAL HOUSE	119 SICKLES AVE.	NW 1/4 - 1/2 (0.420 mi.)	BF383	1080
Spill Number/Closed Date: 9107320 / 1991-11-25				
Site ID: 119461				
Spill Date: 1991-10-08				
SPILL NUMBER 0104402	30 LINCOLN ST	NE 1/4 - 1/2 (0.425 mi.)	BK384	1081
Spill Number/Closed Date: 0104402 / 2001-11-14				
Site ID: 328750				
Spill Date: 2001-07-24				
SPILL NUMBER 0210366	182 UNION AV	W 1/4 - 1/2 (0.426 mi.)	BI385	1082
Spill Number/Closed Date: 0210366 / 2003-03-03				
Site ID: 282696				
Spill Date: 2003-01-14				
APT. BUILDING	***208 CENTER AVE.***	***SSE 1/4 - 1/2 (0.430 mi.)***	***BG386***	***1084***

Spill Number/Closed Date: 9314003 / 1994-03-11
Spill Number/Closed Date: 9315255 / 1994-04-11
Site ID: 215702
Site ID: 215703
Spill Date: 1994-02-28
Spill Date: 1994-03-26

VACCARO RESIDENCE	***52 LINCOLN ST***	***NE 1/4 - 1/2 (0.431 mi.)***	***BK387***	***1087***
Spill Number/Closed Date: 0300463 / 2003-04-14 Site ID: 202585 Spill Date: 2003-04-14				
DEFENDER MARINE SUPP	309 MAIN ST	ENE 1/4 - 1/2 (0.437 mi.)	BL388	1089
Spill Number/Closed Date: 9806235 / 2002-09-19 Site ID: 93459 Spill Date: 1998-08-19				
SPILL NUMBER 0009195	17 POPLAR PL	SSE 1/4 - 1/2 (0.438 mi.)	BM389	1090
Spill Number/Closed Date: 0009195 / 2001-01-08 Site ID: 63217 Spill Date: 2000-11-09				
RESIDENCE	6 POPLAR ROAD	SSE 1/4 - 1/2 (0.438 mi.)	BG390	1091
Spill Number/Closed Date: 0310014 / 2012-08-13 Site ID: 82997 Spill Date: 2003-11-25				
LIPMAN RESIDENCE	54 LIBERTY AVE	S 1/4 - 1/2 (0.441 mi.)	391	1092
Spill Number/Closed Date: 0409061 / 2005-04-02 Site ID: 333699 Spill Date: 2004-11-16				
WALTON RESIDENCE	129 SICKLES AVE	NW 1/4 - 1/2 (0.441 mi.)	392	1093
Spill Number/Closed Date: 0703375 / 2007-08-28 Site ID: 383296 Spill Date: 2007-06-22				
FIUMFREDO RESIDENCE	12 BAYVIEW AVE	E 1/4 - 1/2 (0.443 mi.)	393	1094
Spill Number/Closed Date: 1100096 / 2011-09-22 Site ID: 447470 Spill Date: 2011-04-04				
WILLIAMS TTF	23 1ST ST	WSW 1/4 - 1/2 (0.446 mi.)	395	1106
Spill Number/Closed Date: 9702187 / 1999-06-10 Site ID: 102476 Spill Date: 1997-05-20				
RESIDENCE	38 BEECHWOOD AVE	SW 1/4 - 1/2 (0.447 mi.)	396	1107
Spill Number/Closed Date: 9705244 / 1997-11-10 Site ID: 105369 Spill Date: 1997-07-31				
FUNICELOLO HOME	24 POPLAR PLACE	SSE 1/4 - 1/2 (0.449 mi.)	BM397	1108
Spill Number/Closed Date: 0509719 / 2006-11-19 Site ID: 355533 Spill Date: 2005-11-14				
LABELLA RESIDENCE	219 CENTRE AVE	SSE 1/4 - 1/2 (0.453 mi.)	BM398	1109
Spill Number/Closed Date: 0601959 / 2009-09-01 Site ID: 364328 Spill Date: 2006-05-23				
SPILL NUMBER 0210080	196 UNION AV	W 1/4 - 1/2 (0.458 mi.)	399	1110

Spill Number/Closed Date: 0210080 / 2003-03-03
Site ID: 155360
Spill Date: 2003-01-06

RESIDENCE	98 LIBERTY AVE	S 1/4 - 1/2 (0.458 mi.)	BN400	1111
Spill Number/Closed Date: 0107187 / 2002-01-11 Site ID: 204562 Spill Date: 2001-10-11				
MANONE PLACE	15 COLONIAL PLACE	WNW 1/4 - 1/2 (0.462 mi.)	BJ401	1113
Spill Number/Closed Date: 0513004 / 2006-05-08 Site ID: 359413 Spill Date: 2006-02-09				
TRINITY ARMS APARTME	25 TRINITY PLACE	SSE 1/4 - 1/2 (0.466 mi.)	402	1114
Spill Number/Closed Date: 0811859 / 2009-04-22 Spill Number/Closed Date: 8905211 / 1992-07-30 Site ID: 409448 Site ID: 283512 Spill Date: 2009-01-30 Spill Date: 1989-08-12				
SPILL NUMBER 9814027	48 REMINGTON PL	NW 1/4 - 1/2 (0.470 mi.)	BO403	1116
Spill Number/Closed Date: 9814027 / 1999-02-19 Site ID: 80830 Spill Date: 1999-02-19				
RITACCO HOME	24 JACKSON STREET	ENE 1/4 - 1/2 (0.471 mi.)	404	1117
Spill Number/Closed Date: 0600187 / 2006-07-28 Site ID: 362141 Spill Date: 2006-04-06				
COMMERICAL BUILIDING	719 MAIN ST	SSW 1/4 - 1/2 (0.477 mi.)	BP406	1126
Spill Number/Closed Date: 0404182 / 2004-10-28 Site ID: 301693 Spill Date: 2004-07-19				
SPILL NUMBER 9803423	106 LIBERTY AV	S 1/4 - 1/2 (0.481 mi.)	BN407	1127
Spill Number/Closed Date: 9803423 / 1998-08-18 Site ID: 140786 Spill Date: 1998-06-17				
TTF AT RESIDENCE	68 JACKSON ST	NE 1/4 - 1/2 (0.484 mi.)	408	1128
Spill Number/Closed Date: 0707955 / 2008-03-26 Site ID: 388761 Spill Date: 2007-10-20				
COLLEGE OF NEW ROCHE	103 LIBERTY AVE	S 1/4 - 1/2 (0.484 mi.)	BN409	1129
Spill Number/Closed Date: 9809357 / 2005-04-17 Site ID: 118985 Spill Date: 1998-10-26				
CIUSSETELLI RESIDENC	4 FAIRVIEW PLACE	SE 1/4 - 1/2 (0.485 mi.)	410	1130
Spill Number/Closed Date: 0204230 / 2010-07-13 Site ID: 161898 Spill Date: 2002-07-22				
NELSTAD MATERIAL COR	***40 HUNTINGTON PL***	***ENE 1/4 - 1/2 (0.486 mi.)***	***BQ412***	***1134***
Spill Number/Closed Date: 0208898 / 2004-05-03 Site ID: 200280 Spill Date: 2002-11-27				
BLANCO RESIDENCE	30 LINDEN PLACE	S 1/4 - 1/2 (0.487 mi.)	BN413	1138

Spill Number/Closed Date: 9802704 / 1998-07-30
Site ID: 227988
Spill Date: 1998-06-01

7-UP BOTTLING CO — PALMER AVE & CEDAR S — NE 1/4 - 1/2 (0.489 mi.) — 415 — 1141
Spill Number/Closed Date: 9302874 / 1999-08-02
Site ID: 60684
Spill Date: 1993-06-02

NORTH EVARTS — 44 NORTH EVARTS AVE — SE 1/4 - 1/2 (0.489 mi.) — BR416 — 1142
Spill Number/Closed Date: 9913333 / 2005-02-26
Site ID: 74554
Spill Date: 2000-02-24

RESIDENCE APT BLD — 45 NORTH AVE — SE 1/4 - 1/2 (0.490 mi.) — BR418 — 1144
Spill Number/Closed Date: 1905688 / Not Reported
Site ID: 593733
Spill Date: 2019-08-30

10 FAMILY HOUSE + CO — 727-729 MAIN ST — SSW 1/4 - 1/2 (0.500 mi.) — BP419 — 1145
Spill Number/Closed Date: 1610526 / Not Reported
Site ID: 541362
Spill Date: 2017-02-22

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 21 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SEASONWEIN MANAGEMEN	54 CENTRE AVENUE	SSW 0 - 1/8 (0.100 mi.)	I85	167
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 1. In-Service Id/Status:: 3-169773 Site Status: Active				
RPM REALTY INC	9-15 DIVISION STREET	SSE 0 - 1/8 (0.102 mi.)	G87	168
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 3. Closed - Removed Id/Status:: 3-166189 Site Status: Active				
VERIZON NEW YORK INC	342 HUGUENOT STREET	SSW 0 - 1/8 (0.122 mi.)	R125	309
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022				
75 CENTRE AVENUE LLC	***75 CENTRE AVENUE***	***S 0 - 1/8 (0.124 mi.)***	***R132***	***319***
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 3. Closed - Removed Id/Status:: 3-800240 Site Status: Active				
MAISON 347 LLC	347 HUGUENOT STREET	SSW 1/8 - 1/4 (0.128 mi.)	R137	327
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022				

Status: 1. In-Service
Id/Status:: 3-502626
Site Status: Active

542 MAIN STREET LLC | 542 MAIN STREET | SSE 1/8 - 1/4 (0.129 mi.) | P138 | 328
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 1. In-Service
Id/Status:: 3-800617
Site Status: Active

FORMER CHASE BANK BU | 491 MAIN STREET | SE 1/8 - 1/4 (0.141 mi.) | S159 | 385
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 4. Closed - in place
Id/Status:: 3-164372
Site Status: Active

MISR REALTY, LLC | 573-579 MAIN STREET | S 1/8 - 1/4 (0.152 mi.) | U175 | 431
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 3. Closed - Removed
Id/Status:: 3-800238
Site Status: Active

SAINT GABRIEL HIGH S | 50 WASHINGTON AVENUE | WNW 1/8 - 1/4 (0.186 mi.) | X199 | 517
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022

381-383 HUGUENOT LLC | 381 HUGUENOT STREET | SSW 1/8 - 1/4 (0.206 mi.) | AB220 | 576
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 2. Temporarily out of service
Id/Status:: 3-802286
Site Status: Active

MONTEFIORE - NEW ROC | 16 GUION PLACE | NW 1/8 - 1/4 (0.216 mi.) | AI232 | 613
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 4. Closed - in place
Status: 3. Closed - Removed
Status: 1. In-Service
Id/Status:: 3-123269
Site Status: Active

Lower Elevation	Address	Direction / Distance	Map ID	Page

KAUFMAN HUGUENOT COM | 271 NORTH AVENUE | NE 0 - 1/8 (0.054 mi.) | E40 | 75
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 4. Closed - in place
Id/Status:: 3-183776
Site Status: Active

NORTH BROOK REALTY A | 270 NORTH AVENUE, SU | NNE 0 - 1/8 (0.061 mi.) | H49 | 91
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 1. In-Service
Id/Status:: 3-600117
Site Status: Active

277 NR PRINCIPAL, LL | 277 NORTH AVENUE | NNE 0 - 1/8 (0.071 mi.) | H56 | 104
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022
Status: 3. Closed - Removed
Status: 1. In-Service
Id/Status:: 3-502049
Site Status: Active

DELUXE TAXI | 10 STATION PLAZA | N 0 - 1/8 (0.099 mi.) | K82 | 160
Database: UST, Date of Government Version: 12/16/2021

Lower Elevation	Address	Direction / Distance	Map ID	Page
NORTH GARDEN ASSOCIA	309-311 NORTH AVENUE	N 0 - 1/8 (0.116 mi.)	K113	291
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 1. In-Service Id/Status:: 3-496928 Site Status: Active				
MP CENTRE LLC	10 BARTELS PLACE	SW 1/8 - 1/4 (0.152 mi.)	N173	424
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 0. Administratively closed Status: 3. Closed - Removed Status: 8. Unregistered Id/Status:: 3-025453 Site Status: Active				
MONROE COLLEGE	420 MAIN STREET	E 1/8 - 1/4 (0.222 mi.)	AF243	698
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022				
30 CLINTON PLACE OWN	***30 CLINTON PLACE***	***SE 1/8 - 1/4 (0.228 mi.)***	***AH251***	***722***
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 3. Closed - Removed Id/Status:: 3-078727 Site Status: Active				
NEW ROCHELLE FIRE ST	45 HARRISON STREET	ENE 1/8 - 1/4 (0.231 mi.)	AL257	731
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022				
GHP 145 HUGUENOT DEL	145 HUGUENOT STREET	NE 1/8 - 1/4 (0.235 mi.)	AK275	773
Database: WESTCHESTER CO. UST, Date of Government Version: 02/04/2022 Status: 1. In-Service Id/Status:: 3-497436 Site Status: Active				

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 12/16/2021 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.154 mi.)***	***N183***	***445***
Facility Status: Unregulated/Closed CBS Number: 3-000235				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 12 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
306 HUGUENOT STREET	306 HUGUENOT STREET	SSW 0 - 1/8 (0.050 mi.)	B37	73
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022				

Status: 1. In-Service
PBS Number: 3-800236

RPM REALTY INC | 9-15 DIVISION STREET | SSE 0 - 1/8 (0.102 mi.) | G86 | 168
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-166189

75 CENTRE AVENUE LLC | 75 CENTRE AVENUE | S 0 - 1/8 (0.124 mi.) | R132 | 319
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-800240

FORMER CHASE BANK BU | 491 MAIN STREET | SE 1/8 - 1/4 (0.141 mi.) | S159 | 385
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-164372

MISR REALTY, LLC | 573-579 MAIN STREET | S 1/8 - 1/4 (0.152 mi.) | U176 | 431
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-800238

MONTEFIORE - NEW ROC | 16 GUION PLACE | NW 1/8 - 1/4 (0.216 mi.) | AI232 | 613
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
Status: 3. Closed - Removed
PBS Number: 3-123269

35 CLINTON PLACE LLC | 35 CLINTON PLACE | SE 1/8 - 1/4 (0.218 mi.) | AH237 | 628
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-078646

130 CENTRE AVENUE CO | 130 CENTRE AVENUE | S 1/8 - 1/4 (0.250 mi.) | AG297 | 827
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-165735

Lower Elevation	Address	Direction / Distance	Map ID	Page

KAUFMAN HUGUENOT COM | 271 NORTH AVENUE | NE 0 - 1/8 (0.054 mi.) | E40 | 75
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-183776

INDUSTRIAL OVERALL | 10 BARTELS PLACE | SW 1/8 - 1/4 (0.154 mi.) | N186 | 466
Database: AST, Date of Government Version: 12/16/2021
Facility Id: 3-000235

MAYCO, LLC | 18-20 MAY ST | NNW 1/8 - 1/4 (0.218 mi.) | AJ238 | 629
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
PBS Number: 3-175447

30 CLINTON PLACE OWN | 30 CLINTON PLACE | SE 1/8 - 1/4 (0.228 mi.) | AH251 | 722
Database: WESTCHESTER CO. AST, Date of Government Version: 02/04/2022
Status: 1. In-Service
Status: 4. Closed - in place
PBS Number: 3-078727

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL OVERALL	***10 BARTELS PLACE***	***SW 1/8 - 1/4 (0.154 mi.)***	***N186***	***466***

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 02/08/2022 has revealed that there are 3 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRE AVENUE DEVELO Site Code: 580085	33-35 CENTRE AVENUE	SSW 0 - 1/8 (0.105 mi.)	I91	217

Lower Elevation	Address	Direction / Distance	Map ID	Page
THE HUGUENOT Site Code: 544502	387 HUGUENOT STREET	SSW 1/8 - 1/4 (0.219 mi.)	AB241	640
CONSOLIDATED EDISON Site Code: 56077	***ECHO AVENUE***	***ENE 1/4 - 1/2 (0.412 mi.)***	***BD377***	***1053***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 02/08/2022 has revealed that there are 5 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRE AVENUE DEVELO Site Code: 580085	33-35 CENTRE AVENUE	SSW 0 - 1/8 (0.105 mi.)	I89	177

Lower Elevation	Address	Direction / Distance	Map ID	Page
COTTAGE-GARDEN AUTO Site Code: 574524	***20 GARDEN ST., 26 GA***	***NNE 1/8 - 1/4 (0.173 mi.)***	***V190***	***473***
THE HUGUENOT Site Code: 544502	387 HUGUENOT STREET	SSW 1/8 - 1/4 (0.219 mi.)	AB242	653
10 COMMERCE DRIVE RA Site Code: 591030	***10 COMMERCE DRIVE***	***NE 1/4 - 1/2 (0.276 mi.)***	***310***	***850***
CONSOLIDATED EDISON Site Code: 56077	***ECHO AVENUE***	***ENE 1/4 - 1/2 (0.412 mi.)***	***BD377***	***1053***

EXECUTIVE SUMMARY

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/08/2022 has revealed that there are 17 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FIRESTONE TIRE AND A Site Code: 616446	316 HUGUENOT STREET	SSW 0 - 1/8 (0.068 mi.)	I51	94
BLOCK 417 NEW ROCHEL Site Code: 616464	327-329 HUGUENOT STR	SSW 0 - 1/8 (0.081 mi.)	I67	125
CENTRE AVENUE DEVELO Site Code: 580085	33-35 CENTRE AVENUE	SSW 0 - 1/8 (0.105 mi.)	I88	169
CENTRE AVENUE DEVELO Site Code: 603948	33 CENTRE AVENUE	SSW 0 - 1/8 (0.105 mi.)	I90	215
500 MAIN STREET LAUN Site Code: 601437	500, 506 AND 510 MAI	SE 1/8 - 1/4 (0.141 mi.)	S158	378
CHURCH-DIVISION STRE Site Code: 582599	26 SOUTH DIVISION ST	SSE 1/8 - 1/4 (0.186 mi.)	Y201	520

Lower Elevation	Address	Direction / Distance	Map ID	Page
247 NORTH AVENUE SIT Site Code: 602511	247 NORTH AVENUE	ENE 0 - 1/8 (0.060 mi.)	E48	88
GOODRICH RUBBER 285 Site Code: 615508	285 NORTH AVENUE	NNE 0 - 1/8 (0.087 mi.)	H73	139
PROPOSED RESIDENTIAL Site Code: 588043	***11 GARDEN STREET***	***N 1/8 - 1/4 (0.143 mi.)***	***V165***	***398***
14 LE COUNT STANDARD Site Code: 568962	14 LE COUNT PL, 455	E 1/8 - 1/4 (0.152 mi.)	T174	426
COTTAGE-GARDEN AUTO Site Code: 574524	***20 GARDEN ST., 26 GA***	***NNE 1/8 - 1/4 (0.173 mi.)***	***V190***	***473***
SCHMUCKLER'S DRY CLE Site Code: 357446	358-364 NORTH AVENUE	N 1/8 - 1/4 (0.207 mi.)	AD224	582
SCHMUCKLER'S DRY CLE Site Code: 551607	358-364 NORTH AVENUE	N 1/8 - 1/4 (0.207 mi.)	AD225	588
THE HUGUENOT Site Code: 544502	387 HUGUENOT STREET	SSW 1/8 - 1/4 (0.219 mi.)	AB240	633
OFF-SITE FLAMINGO CL Site Code: 414661	149 NORTH AVENUE	ESE 1/8 - 1/4 (0.245 mi.)	AH293	809
FLAMINGO CLEANERS Site Code: 335220	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AH294***	***810***
10 COMMERCE DRIVE RA Site Code: 591030	***10 COMMERCE DRIVE***	***NE 1/4 - 1/2 (0.276 mi.)***	***310***	***850***

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 02/23/2022 has revealed that there is 1 US BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER MANCUSO MARIN ACRES property ID: 10127 Cleanup Completion Date: -	HUNTINGTON PLACE	ENE 1/4 - 1/2 (0.486 mi.)	BQ411	1132

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 03/15/2022 has revealed that there are 31 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENCE Spill Number/Closed Date: 0810056 / 2010-05-04 Site ID: 407567 Spill Date: 2008-12-09	129 DIVISON ST	S 0 - 1/8 (0.005 mi.)	B5	10
UST Spill Number/Closed Date: 9912617 / 2000-04-04 Site ID: 254637 Spill Date: 2000-02-04	MEMORIAL HIGHWAY AND	SSE 0 - 1/8 (0.008 mi.)	A7	13
MH1204 Spill Number/Closed Date: 9912755 / 2000-02-14 Site ID: 262084 Spill Date: 2000-02-09	HUGUENOT AVE/LAWTON	E 0 - 1/8 (0.018 mi.)	C18	35
ROAD Spill Number/Closed Date: 0606187 / 2006-09-03 Site ID: 369495 Spill Date: 2006-08-29	HUGUENOT ST/DIVISION	S 0 - 1/8 (0.030 mi.)	B20	37
LAWTON STREET REALTY Spill Number/Closed Date: 1808090 / 2019-02-15 Site ID: 578882 Spill Date: 2018-10-29	41-43 LAWTON ST	ESE 0 - 1/8 (0.055 mi.)	C41	76
PAVEMENT Spill Number/Closed Date: 1203965 / 2012-07-23	41 LAWTON STREET	ESE 0 - 1/8 (0.055 mi.)	C43	80

Site ID: 466814
Spill Date: 2012-07-23

CABLE	29 DIVISION STREET	SSE 0 - 1/8 (0.056 mi.)	G47	87
Spill Number/Closed Date: 0804961 / 2008-07-30				
Site ID: 401965				
Spill Date: 2008-07-30				
SOIL	316 HUGUENOT ST	SSW 0 - 1/8 (0.068 mi.)	I50	92
Spill Number/Closed Date: 1802819 / 2018-07-23				
Spill Number/Closed Date: 2003772 / Not Reported				
Site ID: 571425				
Site ID: 609507				
Spill Date: 2018-06-12				
Spill Date: 2020-08-03				
CON EDISON	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.079 mi.)***	***G58***	***107***
Spill Number/Closed Date: 0804960 / 2008-08-16				
Site ID: 401964				
Spill Date: 2008-07-30				
CON ED STREET EXCAVA	NORTH AVE AND ANDERS	E 0 - 1/8 (0.080 mi.)	J60	112
Spill Number/Closed Date: 1905834 / 2019-10-22				
Site ID: 593884				
Spill Date: 2019-09-05				
CONCRETE FLOORING WI	230 NORTH AVENUE	E 0 - 1/8 (0.084 mi.)	J70	135
Spill Number/Closed Date: 1400277 / 2018-07-10				
Site ID: 493512				
Spill Date: 2014-04-08				
ST GABRIEL'S CHURCH	120 DIVISION ST	WNW 0 - 1/8 (0.087 mi.)	74	142
Spill Number/Closed Date: 1906243 / 2020-04-01				
Site ID: 594314				
Spill Date: 2019-09-17				
CEMENT COURT YARD	54 CENTER AVE	SSW 0 - 1/8 (0.100 mi.)	I83	163
Spill Number/Closed Date: 9804849 / 2002-07-15				
Spill Number/Closed Date: 9908117 / 1999-10-04				
Site ID: 114515				
Site ID: 114516				
Spill Date: 1998-07-18				
Spill Date: 1999-10-04				
COMMERCIAL	64 CENTER AVE	S 0 - 1/8 (0.110 mi.)	I99	255
Spill Number/Closed Date: 2102839 / Not Reported				
Spill Number/Closed Date: 2104935 / Not Reported				
Site ID: 621593				
Site ID: 623763				
Spill Date: 2021-06-25				
Spill Date: 2021-08-24				
VERIZON	342 HUGUENOT ST	SSW 0 - 1/8 (0.114 mi.)	I111	287
Spill Number/Closed Date: 0413326 / 2005-09-11				
Site ID: 342403				
Spill Date: 2005-03-22				
535 MAIN ST ASSOCIAT	535 MAIN STREET	SSE 0 - 1/8 (0.119 mi.)	P115	293
Spill Number/Closed Date: 9415294 / 1995-03-03				
Spill Number/Closed Date: 9900400 / 1999-07-09				
Site ID: 251083				

Site ID: 81102
Spill Date: 1995-02-17
Spill Date: 1999-04-08

SIDNEY FURNITURE — 535 MAIN ST — SSE 0 - 1/8 (0.119 mi.) — P116 — 295
Spill Number/Closed Date: 1509029 / 2015-12-04
Site ID: 517634
Spill Date: 2015-12-03

NOVA REALTY - UST — 523 MAIN ST — SSE 0 - 1/8 (0.120 mi.) — P120 — 300
Spill Number/Closed Date: 1811358 / Not Reported
Site ID: 582291
Spill Date: 2019-02-11

LILLIAN VERNON CORP. — ***543 MAIN STREET*** — ***SSE 0 - 1/8 (0.122 mi.)*** — ***P124*** — ***306***
Spill Number/Closed Date: 9212475 / 2004-05-12
Site ID: 125220
Spill Date: 1993-02-03

PART OF STANDARD PRI — 211 NORTH AVE — E 0 - 1/8 (0.123 mi.) — J130 — 315
Spill Number/Closed Date: 2106341 / Not Reported
Site ID: 625227
Spill Date: 2021-10-05

Lower Elevation	Address	Direction / Distance	Map ID	Page
OFFICE BUILDING Spill Number/Closed Date: 9009493 / 1991-05-07 Site ID: 220275 Spill Date: 1990-11-28	8-10 RAILROAD PLACE	0 - 1/8 (0.001 mi.)	A4	9
METRO NORTH TRAIN ST Spill Number/Closed Date: 8903573 / 1989-07-19 Site ID: 104107 Spill Date: 1989-07-10	NEW HAVEN LINE &R/R	W 0 - 1/8 (0.009 mi.)	A15	29
METRO NORTH TRACKS Spill Number/Closed Date: 0308130 / 2004-07-16 Site ID: 279322 Spill Date: 2003-10-31	EAST OF NEW ROCHELLE	W 0 - 1/8 (0.009 mi.)	A16	30
HUGUENOT AND NORTH A Spill Number/Closed Date: 0310260 / 2005-03-05 Site ID: 313618 Spill Date: 2003-12-03	HUGUENOT AND NORTH A	NE 0 - 1/8 (0.045 mi.)	E28	49
SPILL NUMBER 9803949 Spill Number/Closed Date: 9803949 / 1998-06-29 Site ID: 166821 Spill Date: 1998-06-29	MILEPOST 5.5 SB I95	W 0 - 1/8 (0.048 mi.)	D36	72
COMMERCIAL BUILDING Spill Number/Closed Date: 1800222 / Not Reported Site ID: 568710 Spill Date: 2018-04-06	271 NORTH AVE	NE 0 - 1/8 (0.054 mi.)	E39	74
P&D TRANSPORT - HOT Spill Number/Closed Date: 0308809 / 2003-11-26 Site ID: 329742 Spill Date: 2003-11-18	I-95 NB @ MM 5.4	SW 0 - 1/8 (0.105 mi.)	M93	233
I-95	I-95EB MP54	SW 0 - 1/8 (0.105 mi.)	M94	234

Spill Number/Closed Date: 8700158 / 1987-04-07
Site ID: 121121
Spill Date: 1987-04-07

DEVELOPMENT SITE ***175 HUGUENOT STREET*** ***NE 0 - 1/8 (0.114 mi.)*** ***O112*** ***288***
Spill Number/Closed Date: 0510932 / 2005-12-19
Spill Number/Closed Date: 0504821 / 2006-03-08
Site ID: 356986
Site ID: 349739
Spill Date: 2005-12-19
Spill Date: 2005-07-20

APPAREL PLUS 27 CENTRE AVE SW 0 - 1/8 (0.117 mi.) N114 292
Spill Number/Closed Date: 1309988 / 2014-01-14
Site ID: 490810
Spill Date: 2014-01-14

COMMERCIAL - UST 35 GRAND STREET NNW 0 - 1/8 (0.120 mi.) L118 297
Spill Number/Closed Date: 1706607 / 2018-04-05
Site ID: 560927
Spill Date: 2017-10-06

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/28/2022 has revealed that there are 78 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TRANSFORM EPA ID:: NYP004349395	DIVISION ST & HUGUEN	S 0 - 1/8 (0.008 mi.)	B11	18
CON EDISON MANHOLE: EPA ID:: NYP004317285	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.008 mi.)***	***B13***	***22***
NYSDOT BIN 1049890 EPA ID:: NYD987011897	DIVISION ST OVER MET	S 0 - 1/8 (0.009 mi.)	B17	31
ACCESSOCRAFT PRODUCT EPA ID:: NYR000014753	***48 LAWTON ST***	***ESE 0 - 1/8 (0.045 mi.)***	***C34***	***63***
CON EDISON EPA ID:: NYP004759452	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J59***	***109***
CON EDISON TRANSFORM EPA ID:: NYP004367611	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J62***	***114***
BLOCK 417 NEW ROCHEL	327-329 HUGUENOT ST	SSW 0 - 1/8 (0.081 mi.)	I66	122
CON EDISON EPA ID:: NYP004760179	***230 NORTH AVE***	***E 0 - 1/8 (0.084 mi.)***	***J69***	***132***
CON EDISON EPA ID:: NYP004211728	HUGUENOT ST & CENTRE	SSW 0 - 1/8 (0.098 mi.)	I77	145
NEW YORK TELEPHONE C	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.114 mi.)***	***I110***	***283***

EPA ID:: NYD986961605				
CON EDISON	***LECOUNT PL & ANDERSO***	***ENE 0 - 1/8 (0.122 mi.)***	***Q123***	***304***
EPA ID:: NYP004788378				
MR CHIMNEY CLEAN	***32 RELYEA PL***	***SSW 0 - 1/8 (0.124 mi.)***	***N134***	***321***
EPA ID:: NYD987011855				
CON EDISON	***19 DIVISION ST & WAS***	***NW 1/8 - 1/4 (0.130 mi.)***	***141***	***331***
EPA ID:: NYP004800058				
CON EDISON TRANSFORM	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P142***	***334***
EPA ID:: NYP004364576				
CON EDISON MANHOLE:	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P144***	***339***
EPA ID:: NYP004478624				
CON EDISON TRANSFORM	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P145***	***343***
EPA ID:: NYP004478517				
CON EDISON	205 NORTH AVE	ESE 1/8 - 1/4 (0.134 mi.)	T147	348
EPA ID:: NYP004772265				
CON EDISON	***552 MAIN ST***	***S 1/8 - 1/4 (0.136 mi.)***	***P150***	***353***
EPA ID:: NYP004828044				
CON EDISON	565 MAIN ST	S 1/8 - 1/4 (0.142 mi.)	U163	394
EPA ID:: NYP004880023				
ADREAN PRINTING CO	***490 MAIN ST***	***SE 1/8 - 1/4 (0.146 mi.)***	***S168***	***405***
EPA ID:: NY0000233981				
FIRST METRO SERVICES	***357 HUGONOT ST***	***SSW 1/8 - 1/4 (0.148 mi.)***	***R172***	***420***
EPA ID:: NYR000022053				
CON EDISON TRANSFORM	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.154 mi.)***	***U178***	***434***
EPA ID:: NYP004315198				
CON EDISON	***CENTRE & MAIN ST***	***S 1/8 - 1/4 (0.154 mi.)***	***U179***	***438***
EPA ID:: NYP004760815				
ROTH CLEANERS	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Y192***	***503***
EPA ID:: NYD078706686				
CON EDISON TRANSFORM	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.195 mi.)***	***AB211***	***553***
EPA ID:: NYP004464459				
CON EDISON TRANSFORM	***592 MAIN ST***	***S 1/8 - 1/4 (0.196 mi.)***	***212***	***557***
EPA ID:: NYP004357059				
CON EDISON SERVICE B	***CENTRE AVE & LEROY***	***S 1/8 - 1/4 (0.204 mi.)***	***AG217***	***568***
EPA ID:: NYP004517694				
CON EDISON SERVICE B	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.204 mi.)***	***AG219***	***572***
EPA ID:: NYP004475687				
CON EDISON SERVICE B	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.206 mi.)***	***AH221***	***577***
EPA ID:: NYP004442943				
CON EDISON	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.218 mi.)***	***239***	***630***
EPA ID:: NYP004157665				
PREFERRED CLEANERS	***95 UNION AVE***	***W 1/8 - 1/4 (0.225 mi.)***	***AE249***	***713***
EPA ID:: NYD050275254				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
NYSDOT BIN 1091390	DIVISION ST OVER I 9	W 0 - 1/8 (0.035 mi.)	D23	40

EPA ID:: NYD987019197				
CON EDISON	***260 NORTH AVE***	***NE 0 - 1/8 (0.041 mi.)***	***E24***	***43***
EPA ID:: NYP004880056				
CON EDISON MANHOLE:	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.045 mi.)***	***E29***	***50***
EPA ID:: NYP004312476				
CON EDISON MANHOLE:	HUGENUOT ST & NORTH	NE 0 - 1/8 (0.045 mi.)	E30	54
EPA ID:: NYP004419065				
CON EDISON TRANSFORM	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.045 mi.)***	***E31***	***56***
EPA ID:: NYP004366100				
US POSTAL SERVICE	***255 NORTH AVE***	***NE 0 - 1/8 (0.048 mi.)***	***E35***	***68***
EPA ID:: NYR000106369				
FEDERAL PROPERTY MAI	244 NORTH AVE SUITE	ENE 0 - 1/8 (0.055 mi.)	E44	81
EPA ID:: NYR000163337				
NEW ROCHELLE CITY OF	24 STATION PLZ N	NNW 0 - 1/8 (0.056 mi.)	F45	84
EPA ID:: NYR000244764				
CON EDISON MANHOLE:	***277 NORTH AVE***	***NNE 0 - 1/8 (0.071 mi.)***	***H53***	***98***
EPA ID:: NYP004323457				
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.111 mi.)***	***N101***	***259***
EPA ID:: NYP004365318				
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.111 mi.)***	***N102***	***262***
EPA ID:: NYP004379020				
CON EDISON	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	O105	269
EPA ID:: NYP004837407				
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O106***	***271***
EPA ID:: NYP004219380				
CON EDISON MANHOLE 1	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O107***	***276***
EPA ID:: NYP004219455				
CON EDISON MANHOLE:	313 NORTH AVE FRONT	N 0 - 1/8 (0.123 mi.)	K131	316
EPA ID:: NYP004364030				
CON EDISON MANHOLE:	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.138 mi.)***	***K152***	***357***
EPA ID:: NYP004309076				
CON EDISON MANHOLE 4	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K153***	***360***
EPA ID:: NYP004224085				
CON EDISON SERVICE B	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K154***	***364***
EPA ID:: NYP004463667				
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K155***	***368***
EPA ID:: NYP004300836				
CON EDISON MANHOLE:	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K156***	***371***
EPA ID:: NYP004313615				
GARDEN STREET RESIDE	11 GARDEN ST	N 1/8 - 1/4 (0.143 mi.)	V166	402
PRO AUTO PARTS	***41 REYLEA PL***	***SSW 1/8 - 1/4 (0.147 mi.)***	***N169***	***410***
EPA ID:: NYR000016535				
CON EDISON MANHOLE:	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.156 mi.)***	***V188***	***468***
EPA ID:: NYP004307492				
J B & FRANKS	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.181 mi.)***	***AA196***	***510***
EPA ID:: NYD986884732				
FURNITURE RESTORNATI	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***AC205***	***528***

EPA ID:: NYD987034998				
CON EDISON MANHOLE: EPA ID:: NYP004432886	***350 NORTH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***AD207***	***535***
CON EDISON EPA ID:: NYP004205654	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.192 mi.)***	***AA208***	***539***
RUSH MFG CORP EPA ID:: NYD981185051	***18 COLUMBUS AVE.***	***SSW 1/8 - 1/4 (0.198 mi.)***	***AB213***	***560***
LEXINGTON CENTER FOR EPA ID:: NYR000193854	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.216 mi.)***	***AC236***	***623***
CON EDISON EPA ID:: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.224 mi.)***	***AB245***	***700***
CON EDISON MANHOLE: EPA ID:: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.224 mi.)***	***AB246***	***704***
CON EDISON MANHOLE 1 EPA ID:: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.225 mi.)***	***AK247***	***708***
ALL AMERICAN SPORTS EPA ID:: NYR000040113	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.227 mi.)***	***250***	***717***
CON EDISON EPA ID:: NYP004758215	***45 HARRISON ST***	***ENE 1/8 - 1/4 (0.231 mi.)***	***AL258***	***731***
CON EDISON MANHOLE: EPA ID:: NYP004443198	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH259***	***733***
CON EDISON SERVICE B EPA ID:: NYP004452439	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH260***	***737***
CON EDISON EPA ID:: NYP004838332	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AD262	742
CON EDISON TRANSFORM EPA ID:: NYP004372751	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.232 mi.)***	***AD264***	***746***
CON EDISON MANHOLE 1 EPA ID:: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD265***	***750***
CON EDISON MANHOLE 1 EPA ID:: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD267***	***756***
CON EDISON SERVICE B EPA ID:: NYP004347621	***HARRISON AVE & CEDAR***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AL270***	***763***
CON EDISON EPA ID:: NYP004759924	***HARRISON ST & CEDER***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AL271***	***766***
LONGINES WITTNAUER W EPA ID:: NYD001317221	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.235 mi.)***	***AK276***	***773***
CON EDISON EPA ID:: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL278	785
CON EDISON EPA ID:: NYP004758272	***HARRISON ST & FOUNTA***	***ENE 1/8 - 1/4 (0.236 mi.)***	***AL280***	***788***
CON EDISON EPA ID:: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL284	795
COLONIAL CLEANERS CO EPA ID:: NYD982718058	149 NORTH AVE	ESE 1/8 - 1/4 (0.245 mi.)	AH296	823

EXECUTIVE SUMMARY

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 12/10/2021 has revealed that there are 8 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREEN HEAVEN CLEANER Facility Id: 3-5510-00298	62 CENTRE AVE	S 0 - 1/8 (0.108 mi.)	I95	235
SPEEDY CLEANERS Facility Id: 3-5510-00344	***217 NORTH AVENUE***	***E 0 - 1/8 (0.112 mi.)***	***J108***	***281***
HANGERS CLEANERS Facility Id: 3-5510-00358	562-564 MAIN STREET	S 1/8 - 1/4 (0.146 mi.)	U167	405
ROTH CLEANERS Facility Id: 3-5510-00292	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Y192***	***503***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANER	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	A2	9
STATION CLEANERS Facility Id: ---	1 DEPOT PLAZA #1	NNW 0 - 1/8 (0.105 mi.)	L92	232
SCHMUKLER'S CLEANERS Facility Id: 3-5510-00327	360 NORTH AVE.	N 1/8 - 1/4 (0.210 mi.)	AD226	590
FLAMINGO/TYK CLEANER Facility Id: 3-5510-00335	149 NORTH AV.	ESE 1/8 - 1/4 (0.245 mi.)	AH295	823

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 99 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004151221	MEMORIAL HIGHWAY & H	SSE 0 - 1/8 (0.008 mi.)	A6	11
CON EDISON EPA ID: NYP004677894	HUGENOT ST & DIVISIO	S 0 - 1/8 (0.008 mi.)	B8	14
CON EDISON EPA ID: NYP004677548	HUGENOT & DIVISION S	S 0 - 1/8 (0.008 mi.)	B9	15
CON EDISON EPA ID: NYP004676847	DIVISION & HUGUENOT	S 0 - 1/8 (0.008 mi.)	B10	17
CON ED EPA ID: NYP004353199	DIVISION ST & HUGENO	S 0 - 1/8 (0.008 mi.)	B12	21
CON EDISON MANHOLE: EPA ID: NYP004317285	***HUGENOT AVE & DIVISI***	***S 0 - 1/8 (0.008 mi.)***	***B13***	***22***
ACCESSOCRAFT PRODUCT EPA ID: NYR000014753	***48 LAWTON ST***	***ESE 0 - 1/8 (0.045 mi.)***	***C34***	***63***
CON EDISON EPA ID: NYP004800058	***19 DIVISION ST & WAS***	***SSE 0 - 1/8 (0.079 mi.)***	***G58***	***107***
CON EDISON TRANSFORM	***NORTH AVE & ANDERSON***	***E 0 - 1/8 (0.080 mi.)***	***J62***	***114***

EPA ID: NYP004367611				
CON EDISON EPA ID: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J63	118
CON EDISON EPA ID: NYP004683272	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J64	119
CON EDISON EPA ID: NYP004709622	ANDERSON ST & NORTH	E 0 - 1/8 (0.080 mi.)	J65	121
CON ED EPA ID: NYP004760179	230 NORTH AVE	E 0 - 1/8 (0.084 mi.)	J72	138
CON EDISON EPA ID: NYP004676839	CENTER & HUGUENOT	SSW 0 - 1/8 (0.098 mi.)	I78	148
CON EDISON EPA ID: NYP004332961	CENTRE AVE & HUGUENO	SSW 0 - 1/8 (0.098 mi.)	I79	149
CON EDISON EPA ID: NYP004677530	HUGENOT & CENTRE ST	SSW 0 - 1/8 (0.098 mi.)	I80	151
CVS PHARMACY #8447 EPA ID: NYR000194654	***222 NORTH AVE***	***E 0 - 1/8 (0.098 mi.)***	***J81***	***152***
CENTRE CLEANERS EPA ID: NYD982531634	***62 CENTRE STREET***	***S 0 - 1/8 (0.108 mi.)***	***I97***	***248***
NEW YORK TELEPHONE C EPA ID: NYD986961605	***342 HUGUENOT ST***	***SSW 0 - 1/8 (0.114 mi.)***	***I110***	***283***
CON EDISON EPA ID: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.122 mi.)	Q121	301
CONSOLIDATED EDISON EPA ID: NYP004123873	DIVISION & MAIN	SSE 0 - 1/8 (0.123 mi.)	P127	312
CON EDISON EPA ID: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P129	314
MR CHIMNEY CLEAN EPA ID: NYD987011855	***32 RELYEA PL***	***SSW 0 - 1/8 (0.124 mi.)***	***N134***	***321***
MACYS EPA ID: NYP000890137	33 LE COUNT PLACE	ENE 1/8 - 1/4 (0.126 mi.)	Q135	326
CON EDISON TRANSFORM EPA ID: NYP004364576	***MAIN ST & CHRUCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P142***	***334***
CON EDISON EPA ID: NYP004680070	MAIN ST & CHURCH ST	SE 1/8 - 1/4 (0.130 mi.)	P143	338
CON EDISON MANHOLE: EPA ID: NYP004478624	***MAIN ST & CHURCH ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P144***	***339***
CON EDISON TRANSFORM EPA ID: NYP004478517	***CHURCH ST & MAIN ST***	***SE 1/8 - 1/4 (0.130 mi.)***	***P145***	***343***
CON EDISON EPA ID: NYP004772265	205 NORTH AVE	ESE 1/8 - 1/4 (0.134 mi.)	T148	350
ADREAN PRINTING CO EPA ID: NY0000233981	***490 MAIN ST***	***SE 1/8 - 1/4 (0.146 mi.)***	***S168***	***405***
CON EDISON TRANSFORM EPA ID: NYP004315198	***CENTRE AVE & MAIN ST***	***S 1/8 - 1/4 (0.154 mi.)***	***U178***	***434***
CON EDISON	MAIN ST & CENTRE ST	S 1/8 - 1/4 (0.154 mi.)	U181	442

EPA ID: NYP004658019				
CON ED EPA ID: NYP004760815	CENTRE & MAIN ST	S 1/8 - 1/4 (0.154 mi.)	U182	443
ROTH CLEANERS EPA ID: NYD078706686	***1 LEROY PL***	***SSE 1/8 - 1/4 (0.177 mi.)***	***Y192***	***503***
CONSOLIDATED EDISON EPA ID: NYP004124210	DIVISION ST & LEROY	SSE 1/8 - 1/4 (0.180 mi.)	Y193	508
CON EDISON EPA ID: NYP004687802	HUGUENOT ST & COLUMB	SSW 1/8 - 1/4 (0.187 mi.)	AB202	524
CON EDISON EPA ID: NYP004677621	HUGENOT AVE & COLUMB	SSW 1/8 - 1/4 (0.187 mi.)	AB203	525
CON EDISON EPA ID: NYP004677837	HUGENOT ST & COLUMBU	SSW 1/8 - 1/4 (0.187 mi.)	AB204	527
CON EDISON TRANSFORM EPA ID: NYP004464459	***595 MAIN ST***	***SSW 1/8 - 1/4 (0.195 mi.)***	***AB211***	***553***
CON EDISON TRANSFORM EPA ID: NYP004357059	***592 MAIN ST***	***S 1/8 - 1/4 (0.196 mi.)***	***212***	***557***
NYNEX EPA ID: NYP000932509	UNION AVENUE AND WAR	W 1/8 - 1/4 (0.200 mi.)	W214	565
CON EDISON EPA ID: NYP004517694	CENTRE AVE & LEROY	S 1/8 - 1/4 (0.204 mi.)	AG218	570
CON EDISON SERVICE B EPA ID: NYP004475687	***LEROY PL & CENTER AV***	***S 1/8 - 1/4 (0.204 mi.)***	***AG219***	***572***
CON EDISON SERVICE B EPA ID: NYP004442943	***174 NORTH AVE***	***ESE 1/8 - 1/4 (0.206 mi.)***	***AH221***	***577***
MONTEFIORE - NEW ROC EPA ID: NYD075431502	***16 GUION PL***	***NW 1/8 - 1/4 (0.216 mi.)***	***AI231***	***605***
CON EDISON EPA ID: NYP004157665	***46 CLINTON PL***	***SE 1/8 - 1/4 (0.218 mi.)***	***239***	***630***
PREFERRED CLEANERS EPA ID: NYD050275254	***95 UNION AVE***	***W 1/8 - 1/4 (0.225 mi.)***	***AE249***	***713***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID: NYP004312476	***HUGUENOT AVE & NORTH***	***NE 0 - 1/8 (0.045 mi.)***	***E29***	***50***
CON EDISON TRANSFORM EPA ID: NYP004366100	***NORTH AVE & HUGUENOT***	***NE 0 - 1/8 (0.045 mi.)***	***E31***	***56***
CON EDISON EPA ID: NYP004343786	NORTH AVE & HUGENOT	NE 0 - 1/8 (0.045 mi.)	E32	60
US POSTAL SERVICE EPA ID: NYR000106369	***255 NORTH AVE***	***NE 0 - 1/8 (0.048 mi.)***	***E35***	***68***
CON EDISON MANHOLE: EPA ID: NYP004323457	***277 NORTH AVE***	***NNE 0 - 1/8 (0.071 mi.)***	***H53***	***98***
CONSOLIDATED EDISON EPA ID: NYP004230322	F/O 277 NORTH AVE	NNE 0 - 1/8 (0.071 mi.)	H54	101
CON EDISON TRANSFORM	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.111 mi.)***	***N101***	***259***

EPA ID: NYP004365318				
CON EDISON TRANSFORM EPA ID: NYP004379020	***CENTRE AVE & RELYEA***	***SW 0 - 1/8 (0.111 mi.)***	***N102***	***262***
CON EDISON EPA ID: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	O103	266
CON EDISON MANHOLE 1 EPA ID: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O106***	***271***
CON EDISON MANHOLE 1 EPA ID: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O107***	***276***
CONSOLIDATED EDISON EPA ID: NYP004230306	F/O 311 NORTH AVE	N 0 - 1/8 (0.120 mi.)	K117	296
CON EDISON MANHOLE: EPA ID: NYP004309076	***NORTH ST & GARDEN ST***	***N 1/8 - 1/4 (0.138 mi.)***	***K152***	***357***
CON EDISON MANHOLE 4 EPA ID: NYP004224085	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K153***	***360***
CON EDISON SERVICE B EPA ID: NYP004463667	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K154***	***364***
CON EDISON MANHOLE: EPA ID: NYP004300836	***NORTH AVE & GARDEN S***	***N 1/8 - 1/4 (0.138 mi.)***	***K155***	***368***
CON EDISON - MANHOLE EPA ID: NYP004302303	***GARDEN ST AND NORTH***	***N 1/8 - 1/4 (0.138 mi.)***	***K157***	***374***
PRO AUTO PARTS EPA ID: NYR000016535	***41 REYLEA PL***	***SSW 1/8 - 1/4 (0.147 mi.)***	***N169***	***410***
NYS THRUWAY AUTHORIT EPA ID: NYD986963445	***I-95 NORTH AVE OVER***	***N 1/8 - 1/4 (0.147 mi.)***	***V170***	***414***
NYSDEC-SITE 360109 I EPA ID: NYR000208967	***10 BARTELS PL***	***SW 1/8 - 1/4 (0.154 mi.)***	***N185***	***452***
CON EDISON MANHOLE: EPA ID: NYP004307492	***NORTH AVE & BURLING***	***N 1/8 - 1/4 (0.156 mi.)***	***V188***	***468***
CON ED-V37 EPA ID: NYP004027967	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.181 mi.)	Z194	509
CON ED-V14 EPA ID: NYP004028122	LECOUNT PL & MAIN ST	E 1/8 - 1/4 (0.181 mi.)	Z195	510
J B & FRANKS EPA ID: NYD986884732	***27 BARTELS PL***	***SW 1/8 - 1/4 (0.181 mi.)***	***AA196***	***510***
FURNITURE RESTORNATI EPA ID: NYD987034998	***26 GARDEN ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***AC205***	***528***
CON EDISON MANHOLE: EPA ID: NYP004432886	***350 NORTH AVE***	***N 1/8 - 1/4 (0.192 mi.)***	***AD207***	***535***
CON EDISON EPA ID: NYP004205654	***35 BARTELS PL***	***SW 1/8 - 1/4 (0.192 mi.)***	***AA208***	***539***
CON EDISON EPA ID: NYP004744074	35 BARTELS PL	SW 1/8 - 1/4 (0.192 mi.)	AA209	548
RUSH MFG CORP EPA ID: NYD981185051	***18 COLUMBUS AVE.***	***SSW 1/8 - 1/4 (0.198 mi.)***	***AB213***	***560***
SCHMUCKLERS CLEANERS	***360 NORTH AVE***	***N 1/8 - 1/4 (0.210 mi.)***	***AD227***	***590***

EPA ID: NYD012950770				
LEXINGTON CENTER FOR EPA ID: NYR000193854	***3 COTTAGE PL***	***NNE 1/8 - 1/4 (0.216 mi.)***	***AC236***	***623***
CON EDISON EPA ID: NYP004674354	MAIN ST & MAPLE AVE	SSW 1/8 - 1/4 (0.224 mi.)	AB244	698
CON EDISON MANHOLE: EPA ID: NYP004431706	***MAIN ST & MAPLE ST***	***SSW 1/8 - 1/4 (0.224 mi.)***	***AB246***	***704***
CONSOLIDATED EDISON EPA ID: NYP004219572	HUGUENOT ST & HARRIS	NE 1/8 - 1/4 (0.225 mi.)	AK248	711
ALL AMERICAN SPORTS EPA ID: NYD002182897 EPA ID: NYR000040113	***44 COLUMBUS AVE***	***SW 1/8 - 1/4 (0.227 mi.)***	***250***	***717***
CON EDISON EPA ID: NYP004710497	150 NORTH AV	ESE 1/8 - 1/4 (0.229 mi.)	AH253	725
CON EDISON EPA ID: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.231 mi.)	AL254	727
CON EDISON MANHOLE: EPA ID: NYP004443198	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH259***	***733***
CON EDISON SERVICE B EPA ID: NYP004452439	***NORTH AVE & CLINTON***	***ESE 1/8 - 1/4 (0.231 mi.)***	***AH260***	***737***
CON EDISON EPA ID: NYP004679965	OPP 20 LOCKWOOD AV	NNW 1/8 - 1/4 (0.231 mi.)	AJ261	741
CON EDISON EPA ID: NYP004838332	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AD263	745
CON EDISON TRANSFORM EPA ID: NYP004372751	***LOCKWOOD AVE & NORTH***	***N 1/8 - 1/4 (0.232 mi.)***	***AD264***	***746***
CON EDISON MANHOLE 1 EPA ID: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD265***	***750***
CON EDISON MANHOLE 1 EPA ID: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD267***	***756***
CON EDISON SERVICE B EPA ID: NYP004347621	***HARRISON AVE & CEDAR***	***ENE 1/8 - 1/4 (0.232 mi.)***	***AL270***	***763***
CON ED EPA ID: NYP004759924	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.232 mi.)	AL272	769
LONGINES WITTNAUER W EPA ID: NYD001317221	***145 HUGUENOT ST***	***NE 1/8 - 1/4 (0.235 mi.)***	***AK276***	***773***
CON EDISON EPA ID: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL283	793
CON EDISON EPA ID: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL285	797
CON ED EPA ID: NYP004759510	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AL286	798
CON EDISON EPA ID: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AL287	800
FLAMINGO CLEANERS EPA ID: NYD012946885	***149 NORTH AVE***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AH294***	***810***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 3 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUND SHORE MEDICAL Generator EPA Id: NYD075431502	16 GUION PL	NW 1/8 - 1/4 (0.216 mi.)	AI230	602

Lower Elevation	Address	Direction / Distance	Map ID	Page
HNJ REALTY	358-364 N AVENUE	N 1/8 - 1/4 (0.207 mi.)	AD222	581
HNJ REALTY Generator EPA Id: NYD012950779	358-364 N AVE	N 1/8 - 1/4 (0.207 mi.)	AD223	581

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 24 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004759452	NORTH AVE & ANDERSON	E 0 - 1/8 (0.080 mi.)	J61	113
CON EDISON EPA Id: NYP004760179	230 NORTH AVE	E 0 - 1/8 (0.084 mi.)	J71	136
CON EDISON EPA Id: NYP004788378	LECOUNT PL & ANDERSO	ENE 0 - 1/8 (0.122 mi.)	Q122	303
CON EDISON - TRANSFO EPA Id: NYP004872319	DIVISION ST & MAIN S	SSE 0 - 1/8 (0.123 mi.)	P128	312
CON EDISON EPA Id: NYP004772265	205 NORTH AVE	ESE 1/8 - 1/4 (0.134 mi.)	T149	352
CON EDISON EPA Id: NYP004828044	552 MAIN ST	S 1/8 - 1/4 (0.136 mi.)	P151	355
CON EDISON EPA Id: NYP004880023	565 MAIN ST	S 1/8 - 1/4 (0.142 mi.)	U164	397
CON EDISON EPA Id: NYP004760815	CENTRE & MAIN ST	S 1/8 - 1/4 (0.154 mi.)	U180	440

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004880056	260 NORTH AVE	NE 0 - 1/8 (0.041 mi.)	E25	46
CON EDISON EPA Id: NYP004837407	HUGUENOT ST & LE COU	NE 0 - 1/8 (0.112 mi.)	O104	267
CON EDISON MANHOLE 1 EPA Id: NYP004219380	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O106***	***271***
CON EDISON MANHOLE 1 EPA Id: NYP004219455	***HUGUENOT ST & LECOUN***	***NE 0 - 1/8 (0.112 mi.)***	***O107***	***276***
NYSDEC-SITE 360109 I	10 BARTELS PL	SW 1/8 - 1/4 (0.154 mi.)	N184	450

EPA Id: NYR000208967				
LEXINGTON CENTER FOR EPA Id: NYR000193854	3 COTTAGE PL	NNE 1/8 - 1/4 (0.216 mi.)	AC235	621
CON EDISON EPA Id: NYP004214680	***MAPLE AVE & MAIN ST***	***SSW 1/8 - 1/4 (0.224 mi.)***	***AB245***	***700***
CON EDISON MANHOLE 1 EPA Id: NYP004219570	***HUGEONOT ST & HARRIS***	***NE 1/8 - 1/4 (0.225 mi.)***	***AK247***	***708***
CON EDISON EPA Id: NYP004758215	45 HARRISON ST	ENE 1/8 - 1/4 (0.231 mi.)	AL255	728
CON EDISON MANHOLE 1 EPA Id: NYP004222626	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD265***	***750***
CON EDISON EPA Id: NYP004838332	LOCKWOOD AVE & NORTH	N 1/8 - 1/4 (0.232 mi.)	AD266	755
CON EDISON MANHOLE 1 EPA Id: NYP004218356	***NORTH AVE & LOCKWOOD***	***N 1/8 - 1/4 (0.232 mi.)***	***AD267***	***756***
CON EDISON EPA Id: NYP004759924	HARRISON ST & CEDER	ENE 1/8 - 1/4 (0.232 mi.)	AL269	762
CON EDISON EPA Id: NYP004769345	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL279	787
CON EDISON EPA Id: NYP004769477	FOUNTAIN PL & HARRIS	ENE 1/8 - 1/4 (0.236 mi.)	AL281	791
CON EDISON EPA Id: NYP004758272	HARRISON ST & FOUNTA	ENE 1/8 - 1/4 (0.236 mi.)	AL282	792

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON-CEDAR ST	ONE RAMADA PLAZA	NE 1/4 - 1/2 (0.339 mi.)	343	972

EXECUTIVE SUMMARY

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HACKER MORRIS J & SO	64 CENTRE AVE	S 0 - 1/8 (0.110 mi.)	I98	254

Lower Elevation	Address	Direction / Distance	Map ID	Page
A PLUS INC	271 NORTH AVE STE 11	NE 0 - 1/8 (0.054 mi.)	E38	74

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HAYES KATHRYN INC	36-38 DIVISION ST	S 0 - 1/8 (0.043 mi.)	B26	47
SIMONETTI CLEANERS &	62 CENTRE AVE	S 0 - 1/8 (0.108 mi.)	I96	248


Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUND CLEANERS	63 MEMORIAL HWY	0 - 1/8 (0.000 mi.)	A3	9
STATION CLEANERS	24 STATION PLZ	NNW 0 - 1/8 (0.056 mi.)	F46	87

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 6 records.

Site Name	Database(s)
CE-CEDAR ST MGP NEW ROCHELLE	NY SHWS
MEARL CORP.	NY SHWS
SIDEWALK / IN FRONT OF NE	NY LTANKS
N.SHORE LONG ISLAND SOUND	NY LTANKS
MM 5.4 LEFT LANE	NY LTANKS
CE-CEDAR ST MGP NEW ROCHELLE	NY VCP

OVERVIEW MAP - 6986656.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory


State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Julie Brunner
		INQUIRY #:	6986656.2s
LAT/LONG:	40.91054 / 73.783836	DATE:	May 19, 2022 9:52 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6986656.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Julie Brunner
		INQUIRY #:	6986656.2s
LAT/LONG:	40.91054 / 73.783836	DATE:	May 19, 2022 9:53 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	1	0	NR	1
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		2	4	NR	NR	NR	6
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-VSQG	0.250		2	2	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	1	2	0	NR	3
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	0	2	NR	NR	2
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		19	34	113	NR	NR	166
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		9	12	NR	NR	NR	21
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		4	8	NR	NR	NR	12
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		1	1	1	NR	NR	3
NY INST CONTROL	0.500		1	2	2	NR	NR	5
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		6	10	1	NR	NR	17
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	1	NR	NR	1
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		31	NR	NR	NR	NR	31
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		27	51	NR	NR	NR	78
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		4	4	NR	NR	NR	8
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		35	64	NR	NR	NR	99
RI MANIFEST	0.250		0	0	NR	NR	NR	0
PA MANIFEST	0.250		0	3	NR	NR	NR	3
NJ MANIFEST	0.250		8	16	NR	NR	NR	24
NY SPDES	TP	1	NR	NR	NR	NR	NR	1
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		4	NR	NR	NR	NR	4
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		1	155	215	125	0	0	496

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **LA ROCHELLE & SHEARWOOD PLACE** **NY SPDES** **S123190515**
Target **255 HUGUENOT STREET** **N/A**
Property **CITY OF NEW ROCHELLE, NY 10801**

Site 1 of 8 in cluster A

Actual: SPDES:
90 ft.

Name:	LA ROCHELLE & SHEARWOOD PLACE
Address:	255 HUGUENOT STREET
City,State,Zip:	CITY OF NEW ROCHELLE, NY 10801
Permit Number:	NYR11E141
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.910671 / -73.783950
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

A2 **SOUND CLEANER** **NY DRYCLEANERS** **S110247943**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
1 ft.

Site 2 of 8 in cluster A

Relative: DRYCLEANERS:
Lower

Name:	SOUND CLEANER
Address:	63 MEMORIAL HWY
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	Not reported
Phone Number:	Not reported
Region:	3
Registration Effective Date:	Not reported
Inspection Date:	Not reported
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
83 ft.

A3 **SOUND CLEANERS** **EDR Hist Cleaner** **1020090702**
63 MEMORIAL HWY **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
1 ft.

Site 3 of 8 in cluster A

Relative: EDR Hist Cleaner
Lower

Actual:
83 ft.

Year:	Name:	Type:
2007	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2010	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2011	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2012	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2013	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC
2014	SOUND CLEANERS	Drycleaning Plants, Except Rugs, NEC

A4 **OFFICE BUILDING** **NY Spills** **S102154161**
8-10 RAILROAD PLACE **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.001 mi.
3 ft. **Site 4 of 8 in cluster A**

Relative: SPILLS:
Lower

Name:	OFFICE BUILDING
Address:	8-10 RAILROAD PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9009493 / 1991-05-07
Facility ID:	9009493
Facility Type:	ER
DER Facility ID:	182194
Site ID:	220275
DEC Region:	3
Spill Cause:	Unknown

Actual:
80 ft.

OFFICE BUILDING (Continued) **S102154161**

Spill Class:	C3
SWIS:	6010
Spill Date:	1990-11-28
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1990-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-03-18
Cleanup Meets Std:	True
Last Inspection:	1991-03-18
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-12-06
Spill Record Last Update:	1991-05-08
Spiller Name:	Not reported
Spiller Company:	8 RAILROAD PLACE CORP.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"UNDERGROUND TANK SYSTEM APPEARS TO BE LEAKING ACCORDING TO READINGS MAPLE MAINTENANCE LAGRANGEVILLE NO ODORS NO PRODUCT IN VIEW CALLED JOHN TENORE MAPLE MAINT. WILL BE DOING A TANK TEST MAYBE ONLY 100"

All Materials:

Site ID:	220275
Operable Unit ID:	946581
Operable Unit:	01
Material ID:	429706
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	800.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B5 **RESIDENCE** **NY Spills** **S109413260**
South **129 DIVISON ST** **N/A**
< 1/8 **TARRYTOWN, NY**
0.005 mi.
28 ft. **Site 1 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Name:	RESIDENCE
Address:	129 DIVISON ST
City,State,Zip:	TARRYTOWN, NY
Spill Number/Closed Date:	0810056 / 2010-05-04
Facility ID:	0810056
Facility Type:	ER
DER Facility ID:	356816
Site ID:	407567

RESIDENCE (Continued) **S109413260**

DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6026
Spill Date:	2008-12-09
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-09
Spill Record Last Update:	2010-08-27
Spiller Name:	Not reported
Spiller Company:	3RD PARTY SPILL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"12/09/2008: Con Ed reports that this location is the former GM site that was/is a Brownsfield site. Con Ed was laying a gas line when stained soils was found in the trench...ra 08/27/2010 See eDocs for Con Ed report detailing cleanup and closure DMP"
Remarks:	"CALLER STATES THAT THEY RECIEVED A 3RD PARTY CALLL STATING THAT THEY FOUND AN UNK PETROLEUM PRODUCT DURING AN EXCAVATION. CLEAN UP IS PENDING."

All Materials:

Site ID:	407567
Operable Unit ID:	1164107
Operable Unit:	01
Material ID:	2155468
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A6 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650791**
SSE **MEMORIAL HIGHWAY & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.008 mi.
42 ft. **Site 5 of 8 in cluster A**

Relative: **Higher**

Actual: **99 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MEMORIAL HIGHWAY & HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10802

CONSOLIDATED EDISON (Continued) **S108650791**

Country:	USA
EPA ID:	NYP004151221
Facility Status:	Not reported
Location Address 1:	MEMORIAL HIGHWAY & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004151221
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	06/21/2007
Trans1 Recv Date:	06/21/2007
Trans2 Recv Date:	06/22/2007
TSD Site Recv Date:	06/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004151221
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000174983GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H129
Waste Code:	Not reported
Waste Code:	Not reported

CONSOLIDATED EDISON (Continued) **S108650791**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1820
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A7 **UST** **NY Spills** **S104509646**
SSE **MEMORIAL HIGHWAY AND HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.008 mi.
42 ft. **Site 6 of 8 in cluster A**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	UST
Address:	MEMORIAL HIGHWAY AND HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9912617 / 2000-04-04
Facility ID:	9912617
Facility Type:	ER
DER Facility ID:	208558
Site ID:	254637
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2000-02-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-02-04
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-04
Spill Record Last Update:	2017-10-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	AVALONBAY COMMUNITIES

UST (Continued) **S104509646**

DEC Memo: " 02/04/2000 STEVE AT AKRF. NEW ROCHELLE F.D. HAS BEEN ON SITE AS WELL AS T. GHIOSAY 04/04/2000 LETTER SENT TO AKRF BY T. GHIOSAY; CLEANUP SATISFACTORY - SPILL FILE CLOSED."
Remarks: "CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL"

All Materials:
Site ID: 254637
Operable Unit ID: 1091315
Operable Unit: 01
Material ID: 294499
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

B8 **CON EDISON** **NY MANIFEST** **S117535602**
South **HUGENOT ST & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.008 mi.
43 ft. **Site 2 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:
Name: CON EDISON
Address: HUGENOT ST & DIVISION ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004677894
Facility Status: Not reported
Location Address 1: HUGENOT ST & DIVISION ST
Code: BP
Location Address 2: MH 1218
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004677894
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON (Continued) **S117535602**

seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677894
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774861JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B9 **CON EDISON** **NY MANIFEST** **S117535593**
South **HUGEPOT & DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.008 mi.
43 ft. **Site 3 of 16 in cluster B**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	HUGENOT & DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA

Actual:
101 ft.

CON EDISON (Continued) **S117535593**

EPA ID: NYP004677548
Facility Status: Not reported
Location Address 1: HUGENOT & DIVISION ST
Code: BP
Location Address 2: MH 1218
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004677548
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/14/2014
Trans1 Recv Date: 10/14/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677548
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012774875JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117535593**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B10 **CON EDISON** **NY MANIFEST** **S117319604**
South **DIVISION & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.008 mi.
43 ft. **Site 4 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DIVISION & HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004676847
Facility Status:	Not reported
Location Address 1:	DIVISION & HUGUENOT
Code:	BP
Location Address 2:	MH 1218
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676847
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359

CON EDISON (Continued) **S117319604**

Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770952JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B11 **CON EDISON TRANSFORMER MANHOLE: 1154** **RCRA NonGen / NLR** **1016961985**
South **DIVISION ST & HUGUENOT ST** **NYP004349395**
< 1/8 **NEW ROCHELLE, NY 10801**
0.008 mi.
43 ft. **Site 5 of 16 in cluster B**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130921
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 1154
Handler Address:	DIVISION ST & HUGUENOT ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004349395
Contact Name:	DENNIS ROHRER
Contact Address:	Not reported

CON EDISON TRANSFORMER MANHOLE: 1154 (Continued) **1016961985**

Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON TRANSFORMER MANHOLE: 1154 (Continued) **1016961985**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130821
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 1154
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130921
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 1154
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

B12 **CON ED** **NY MANIFEST** **S119073734**
South **DIVISION ST & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10805**
0.008 mi.
43 ft. **Site 6 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON ED
Address:	DIVISION ST & HUGENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004353199
Facility Status:	Not reported
Location Address 1:	DIVISION ST AND HUGENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004353199
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2013
Trans1 Recv Date:	08/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004353199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694814JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S119073734**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B13 **CON EDISON MANHOLE: 1215** **RCRA NonGen / NLR** **1016678044**
South **HUGENOT AVE & DIVISION ST NE** **FINDS** **NYP004317285**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.008 mi. **NY MANIFEST**
43 ft. **Site 7 of 16 in cluster B**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130630
Handler Name:	CON EDISON MANHOLE: 1215
Handler Address:	HUGENOT AVE & DIVISION ST NE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004317285
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Historic Generators:

Receive Date:		20130530
Handler Name:	CON EDISON MANHOLE: 1215	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130630
Handler Name:	CON EDISON MANHOLE: 1215	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058874865

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678044
Registry ID: 110058874865

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058874865
Name:	CON EDISON MANHOLE: 1215
Address:	HUGENOT AVE & DIVISION ST NE
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT AVE & DIVISION ST NE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004317285
Facility Status:	Not reported
Location Address 1:	DIVISION ST & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004317285
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2013
Trans1 Recv Date:	05/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/30/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004317285
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842831JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON MANHOLE: 1215 (Continued) **1016678044**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B14 **CON EDISON - TRANSFORMER MANHOLE 1154** **RCRA-LQG** **1016962308**
South **DIVISION ST AND HUGENOT ST** **NYP004353199**
< 1/8 **NEW ROCHELLE, NY 10805**
0.008 mi.
43 ft. **Site 8 of 16 in cluster B**

Relative: **Higher**

Actual: **101 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 1154
Handler Address:	DIVISION ST AND HUGENOT ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10805
EPA ID:	NYP004353199
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130829
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130829
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - TRANSFORMER MANHOLE 1154
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130829
Handler Name: CON EDISON TRANSFORMER MANHOLE: 1154
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

CON EDISON - TRANSFORMER MANHOLE 1154 (Continued) **1016962308**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130929
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 1154
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

A15 **METRO NORTH TRAIN STATION** **NY Spills** **S102153509**
West **NEW HAVEN LINE &R/R PLAZA** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.009 mi.
48 ft. **Site 7 of 8 in cluster A**

Relative:
Lower

Actual:
81 ft.

SPILLS:

Name:	METRO NORTH TRAIN STATION
Address:	NEW HAVEN LINE &R/R PLAZA
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8903573 / 1989-07-19
Facility ID:	8903573
Facility Type:	ER
DER Facility ID:	92033
Site ID:	104107
DEC Region:	3
Spill Cause:	Vandalism
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1989-07-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-07-10
CID:	Not reported

METRO NORTH TRAIN STATION (Continued) **S102153509**

Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-07-10
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-19
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	METRO NORTH TRAIN STATION
Spiller Address:	NEW HAVEN LINE &R/R PLAZA
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"SOMEONE PUT STEEL BAR ON TRACK. TRAIN HIT BAR, PUNCTURED SMALL HOLE IN TRANFORMER. CAR #8669, EMPLOYEE WALKED TRACK. CLEAN UP IN PROGRESS. WCHD WILL INVESTIGATE, AMER. ENV. TECH, RCIHFIELD CT, NFA"

All Materials:

Site ID:	104107
Operable Unit ID:	928993
Operable Unit:	01
Material ID:	447657
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A16 **METRO NORTH TRACKS** **NY Spills** **S106126232**
West **EAST OF NEW ROCHELLE STAT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.009 mi.
48 ft. **Site 8 of 8 in cluster A**

Relative: **Lower**
Actual: **81 ft.**

SPILLS:

Name:	METRO NORTH TRACKS
Address:	EAST OF NEW ROCHELLE STAT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308130 / 2004-07-16
Facility ID:	0308130
Facility Type:	ER
DER Facility ID:	226808
Site ID:	279322
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2003-10-31
Investigator:	tdghiosa

METRO NORTH TRACKS (Continued) **S106126232**

Referred To:	Not reported
Reported to Dept:	2003-10-31
CID:	418
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-31
Spill Record Last Update:	2004-07-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOANNE REILLEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/5/03 Joanne Reilly stated that the area is inaccessible to work in because of hi speed train taffic. Requested permission to cleanup during a planned closure for a capital project scheduled in 2004. Will submit request in writing to TG. TG 07-15-04 Letter rec'd from Metro North claiming cleanup has been completed. NFA. TG."
Remarks:	"caller states that spill is between 2 tracks and currently have a company rep enroute to the scene"

All Materials:

Site ID:	279322
Operable Unit ID:	874415
Operable Unit:	01
Material ID:	501652
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B17 **NYSDOT BIN 1049890** **RCRA NonGen / NLR** **1000789726**
South **DIVISION ST OVER METRO NORTH** **NYD987011897**
< 1/8 **NEW ROCHELLE, NY 10803**
0.009 mi.
48 ft. **Site 9 of 16 in cluster B**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NYSDOT BIN 1049890	
Handler Address:		DIVISION ST OVER METRO NORTH
Handler City,State,Zip:		NEW ROCHELLE, NY 10803
EPA ID:		NYD987011897
Contact Name:		RICHARD MANNS
Contact Address:		BURNETT BLVD
Contact City,State,Zip:		POUGHKEEPSIE, NY 12603

NYSDOT BIN 1049890 (Continued) **1000789726**

Contact Telephone:	914-431-5743
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	BURNETT BLVD
Mailing City,State,Zip:	POUGHKEEPSIE, NY 12603
Owner Name:	NYSDOT
Owner Type:	State
Operator Name:	NYSDOT
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYSDOT BIN 1049890 (Continued) **1000789726**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYSDOT
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYSDOT
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYSDOT
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported

NYSDOT BIN 1049890 (Continued) **1000789726**

Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYSDOT BIN 1049890
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYSDOT BIN 1049890
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920812
Handler Name: NYSDOT BIN 1049890
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C18 **MH1204** **NY Spills** **S104509750**
East **HUGUENOT AVE/LAWTON AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.018 mi.
95 ft. **Site 1 of 6 in cluster C**

Relative: **Higher**

Actual: **91 ft.**

SPILLS:

Name:	MH1204
Address:	HUGUENOT AVE/LAWTON AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9912755 / 2000-02-14
Facility ID:	9912755
Facility Type:	ER
DER Facility ID:	214030
Site ID:	262084
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2000-02-09
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-02-09
CID:	270
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-09
Spill Record Last Update:	2000-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/09/2000 SOURCE UNKNOWN-NO OIL FILLED CONED EQUIPMENT NEARBY. VAC TRUCK BEING SENT TO SITE. WILL CALL WITH RESULTS OF PRODUCT I.D. SPILL VOLUME DOWNGRADED TO 3 GALLONS. 02/14/2000 CLEANUP REPORT SENT TO TARRYTOWN OFFICE. AMOUNT SPILLED WAS ACTUALLY 3 GALLONS. NFA"
Remarks:	"OIL STAGNANT SAMPLES WILL BE TAKEN CLEAN UP PENDING"

All Materials:

Site ID:	262084
Operable Unit ID:	1091472
Operable Unit:	01
Material ID:	294626
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B19 **VACANT LOT** **NY LTANKS** **S107489335**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.030 mi.
160 ft. **Site 10 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	VACANT LOT
Address:	HUGUENOT ST/DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510542 / 2006-03-15
Facility ID:	0510542
Site ID:	356539
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-15
Spiller Name:	STEVE GRENS
Spiller Company:	VACANT LOT
Spiller Address:	HUGUENOT ST/DIVISION ST
Spiller County:	001
Spiller Contact:	STEVE GRENS
Spiller Phone:	(914) 806-5650
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306600
DEC Memo:	"March 15, 2006: BROOKSIDE ENVIRONMENTAL DISPOSED OF LUST AND 5.62 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM AKRF. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallons."

All Materials:

Site ID:	356539
Operable Unit ID:	1113840
Operable Unit:	01
Material ID:	2103900
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B20 **ROAD** **NY Spills** **S108130430**
South **HUGUENOT ST/DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.030 mi.
160 ft. **Site 11 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

SPILLS:

Name:	ROAD
Address:	HUGUENOT ST/DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606187 / 2006-09-03
Facility ID:	0606187
Facility Type:	ER
DER Facility ID:	306600
Site ID:	369495
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-08-29
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-08-29
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-29
Spill Record Last Update:	2006-09-03
Spiller Name:	JEFF CULLEN
Spiller Company:	GC RELIABLE SERVICE COMPA
Spiller Address:	80 GROVE ST
Spiller Company:	001
Contact Name:	WESTCHESTER FIRE CONTROL
DEC Memo:	"DPW sanded road. No product to recover. jod"
Remarks:	"SPILL SPANS FOR FIVE BLOCKS BETWEEN THE TWO STREETS GIVEN IN LOCATION: CLEANUP IN PROGRESS: DPW ON SCENE:"

All Materials:

Site ID:	369495
Operable Unit ID:	1127329
Operable Unit:	01
Material ID:	2116923
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B21
SSW
< 1/8
0.032 mi.
168 ft.

SHORELINE OIL
296 HUGENOT ST,REAR OF
NEW ROCHELLE, NY

Site 12 of 16 in cluster B

NY LTANKS **S102674768**
N/A

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	SHORELINE OIL
Address:	296 HUGENOT ST,REAR OF
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8709425 / 1988-04-06
Facility ID:	8709425
Site ID:	83347
Spill Date:	1988-02-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-04-06
SWIS:	6010
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1988-05-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	1988-05-05
Spiller Name:	Not reported
Spiller Company:	SHORELINE OIL
Spiller Address:	34 EVANS ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76706
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : SITE INSPECT:NO EVIDENCE OF CONTAMINATION FROM OUTSIDE LOCKED GATE. N.F.A. T.D. 05/03/88: NO EVIDENCE OF CONTAMINATION OBSERVED DURING INSPECTION. NFA. "
Remarks:	"OIL INTO PRIVATE DRAIN, TO SUMP,TO SEWER,FROM CAPT.O'CONNOR NRFD(914-654-2215). COMPANY CLEANING UP. DEC TO INVESIGATE & VERIFY CLEAN UP. N.F.A. SEE UPDATE."

All Materials:

Site ID:	83347
Operable Unit ID:	914524
Operable Unit:	01
Material ID:	464747
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

SHORELINE OIL (Continued) **S102674768**

Recovered: .00
Oxygenate: Not reported

B22 **LILLIAN VERNON CO.** **NY LTANKS** **S100494788**
South **WESTCHESTER PLACE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.033 mi.
175 ft. **Site 13 of 16 in cluster B**

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	LILLIAN VERNON CO.
Address:	WESTCHESTER PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9213055 / 1995-03-16
Facility ID:	9213055
Site ID:	201286
Spill Date:	1993-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-16
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-23
Spill Record Last Update:	1995-08-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	167465
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO HAVE MEETING TO DISCUSS FURTHER ACTION TANK IS BEING PUMPED DOWN TEMP TANK BEING SET UP AES SYSTEM II"

All TTF:

Facility ID:	9213055
Spill Number:	9213055
Spill Tank Test:	1541204
Site ID:	201286
Tank Number:	Not reported
Tank Size:	0

LILLIAN VERNON CO. (Continued) **S100494788**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	201286
Operable Unit ID:	977443
Operable Unit:	01
Material ID:	570289
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

D23 **NYSDOT BIN 1091390** **RCRA NonGen / NLR** **1000790435**
West **DIVISION ST OVER I 95** **NYD987019197**
< 1/8 **NEW ROCHELLE, NY 10803**
0.035 mi.
186 ft. **Site 1 of 2 in cluster D**

Relative: **Lower**
Actual: **79 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NYSDOT BIN 1091390	
Handler Address:		DIVISION ST OVER I 95
Handler City,State,Zip:		NEW ROCHELLE, NY 10803
EPA ID:		NYD987019197
Contact Name:		RICHARD MANNS
Contact Address:		BURNETT BLVD
Contact City,State,Zip:		POUGHKEEPSIE, NY 12603
Contact Telephone:		914-431-5743
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		BURNETT BLVD
Mailing City,State,Zip:		POUGHKEEPSIE, NY 12603

NYSDOT BIN 1091390 (Continued) **1000790435**

Owner Name:	NYSDOT
Owner Type:	State
Operator Name:	NYSDOT
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

NYSDOT BIN 1091390 (Continued) **1000790435**

Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 BURNETT BLVD
Owner/Operator City,State,Zip: POUGHKEEPSIE, NY 12603
Owner/Operator Telephone: 914-431-5743
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 BURNETT BLVD
Owner/Operator City,State,Zip: POUGHKEEPSIE, NY 12603
Owner/Operator Telephone: 914-431-5743
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 BURNETT BLVD
Owner/Operator City,State,Zip: POUGHKEEPSIE, NY 12603
Owner/Operator Telephone: 914-431-5743
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYSDOT BIN 1091390
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

NYSDOT BIN 1091390 (Continued) **1000790435**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: NYSDOT BIN 1091390	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19920925
Handler Name: NYSDOT BIN 1091390	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E24 **CON EDISON** **RCRA NonGen / NLR** **1019909014**
NE **260 NORTH AVE** **FINDS** **NYP004880056**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.041 mi.
215 ft. **Site 1 of 13 in cluster E**

Relative: **Lower**
Actual: **86 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20151216
Handler Name: CON EDISON	
Handler Address:	260 NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004880056
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON (Continued) **1019909014**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON (Continued) **1019909014**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151216
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151216
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019909014**

FINDS:
Registry ID: 110069645085

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019909014
Registry ID:	110069645085
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069645085
Name:	CON EDISON
Address:	260 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

E25 **CON EDISON** **NJ MANIFEST** **S120678197**
NE **260 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.041 mi.
215 ft. **Site 2 of 13 in cluster E**

Relative: **Lower**

Actual: **86 ft.**

NJ MANIFEST:

EPA Id:	NYP004880056
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319282JJK
EPA ID:	NYP004880056
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120678197**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B26 **HAYES KATHRYN INC** **EDR Hist Cleaner** **1020002440**
South **36-38 DIVISION ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.043 mi.
226 ft. **Site 14 of 16 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual:
101 ft.

Year:	Name:	Type:
1969	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1970	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1971	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1972	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1973	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1974	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1975	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1976	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs
1977	HAYES KATHRYN INC	Drycleaning Plants, Except Rugs

B27
SSW
< 1/8
0.044 mi.
233 ft.

JONES RESIDENCE
311 HUGUENOT STREET
NEW ROCHELLE, NY

Site 15 of 16 in cluster B

NY LTANKS **S106737602**
N/A

Relative:
Higher

Actual:
101 ft.

LTANKS:

Name:	JONES RESIDENCE
Address:	311 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0410335 / 2005-09-11
Facility ID:	0410335
Site ID:	335236
Spill Date:	2004-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-12-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-17
Spill Record Last Update:	2005-09-11
Spiller Name:	DARRYL JONES
Spiller Company:	JONES RESIDENCE
Spiller Address:	311 HUGENOT STREET
Spiller County:	001
Spiller Contact:	DARRYL JONES
Spiller Phone:	(914) 632-5368
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	270458
DEC Memo:	"12/21/04 PBS FACILITY: 3-801006. jbo September 11, 2005: TANK CLOSED IN PLACE. FIVE SAMPLES TAKEN, NO CONTAMINATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-801006 "

All TTF:

Facility ID:	0410335
Spill Number:	0410335
Spill Tank Test:	1548406
Site ID:	335236
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

JONES RESIDENCE (Continued) **S106737602**

Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 335236
Operable Unit ID: 1097307
Operable Unit: 01
Material ID: 577292
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

E28 **HUGUENOT AND NORTH AVE** **NY Spills** **S106126832**
NE **HUGUENOT AND NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
238 ft. **Site 3 of 13 in cluster E**

Relative: **Lower**
Actual: **85 ft.**

SPILLS:
Name: HUGUENOT AND NORTH AVE
Address: HUGUENOT AND NORTH AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0310260 / 2005-03-05
Facility ID: 0310260
Facility Type: ER
DER Facility ID: 252866
Site ID: 313618
DEC Region: 3
Spill Cause: Traffic Accident
Spill Class: C3
SWIS: 6010
Spill Date: 2003-12-03
Investigator: WCHD
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 2003-12-03
CID: 403
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-12-09
Spill Record Last Update: 2005-03-05
Spiller Name: CARLOS TORRES

HUGUENOT AND NORTH AVE (Continued) **S106126832**

Spiller Company:	HUGUENOT AND NORTH AVE
Spiller Address:	HUGUENOT AND NORTH AVE
Spiller Company:	001
Contact Name:	CARLOS TORRES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 3/5/05 5gallon surface spill--close "
Remarks:	"a tow truck carrying a dump truck . the dump truck ruptured and spilled about 5 to 6 gallons of fuel"

E29 **CON EDISON MANHOLE: 5071** **RCRA NonGen / NLR** **1016677599**
NE **HUGUENOT AVE & NORTH AVE** **FINDS** **NYP004312476**
< 1/8 **NEW ROCHELLE, NY 10805** **ECHO**
0.045 mi. **NY MANIFEST**
238 ft. **Site 4 of 13 in cluster E**

Relative: **Lower**
Actual: **85 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130614
Handler Name:	CON EDISON MANHOLE: 5071
Handler Address:	HUGUENOT AVE & NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10805
EPA ID:	NYP004312476
Contact Name:	DOMINIC BIZZARO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130514
Handler Name: CON EDISON MANHOLE: 5071	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130614

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Handler Name: CON EDISON MANHOLE: 5071
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058876550

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677599
Registry ID: 110058876550
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058876550
Name: CON EDISON MANHOLE: 5071
Address: HUGUENOT AVE & NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10805

NY MANIFEST:
Name: CON EDISON
Address: HUGUENOT AVE & NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004312476
Facility Status: Not reported
Location Address 1: HUGUENOT & NORTH AVE
Code: BP
Location Address 2: Not reported

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004312476
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658348JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds

CON EDISON MANHOLE: 5071 (Continued) **1016677599**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E30
NE
< 1/8
0.045 mi.
238 ft.

CON EDISON MANHOLE: 5071 **RCRA NonGen / NLR** **1016968295**
HUGENUOT ST & NORTH AVE **NYP004419065**
NEW ROCHELLE, NY 10805

Site 5 of 13 in cluster E

Relative:
Lower

Actual:
85 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20140215
Handler Name:	CON EDISON MANHOLE: 5071
Handler Address:	HUGENUOT ST & NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10805
EPA ID:	NYP004419065
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON MANHOLE: 5071 (Continued) **1016968295**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140115
Handler Name: CON EDISON MANHOLE: 5071	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 5071 (Continued) **1016968295**

Electronic Manifest Broker: Not reported

Receive Date: 20140215
Handler Name: CON EDISON MANHOLE: 5071
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E31 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963620**
NE **NORTH AVE & HUGUENOT ST** **NY MANIFEST** **NYP004366100**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
238 ft. **Site 6 of 13 in cluster E**

Relative: **Lower**
Actual: **85 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20131025
Handler Name: CON EDISON TRANSFORMER MANHOLE: 5042
Handler Address: NORTH AVE & HUGUENOT ST
Handler City,State,Zip: NEW ROCHELLE, NY 10801
EPA ID: NYP004366100
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20130925
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5042
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131025
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5042
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004366100
Facility Status:	Not reported
Location Address 1:	NOAR/HUGUNOT ST
Code:	BP
Location Address 2:	MH5042
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

NY MANIFEST:

EPAID:	NYP004366100
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/25/2013
Trans1 Recv Date:	09/25/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004366100
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694648JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963620**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E32 **CON EDISON** **NY MANIFEST** **1016961580**
NE **NORTH AVE & HUGENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.045 mi.
238 ft. **Site 7 of 13 in cluster E**

Relative:
Lower

Actual:
85 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & HUGENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004343786
Facility Status:	Not reported
Location Address 1:	NORTH AVENUE & HUGENOT STR
Code:	BP
Location Address 2:	EET
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004343786
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2013
Trans1 Recv Date:	08/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004343786
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **1016961580**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C33 **MAIN LIBRARY** **NY LTANKS** **S103037429**
East **LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.045 mi.
238 ft. **Site 2 of 6 in cluster C**

Relative: **Higher**

Actual: **91 ft.**

LTANKS:

Name:	MAIN LIBRARY
Address:	LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9713843 / 1998-03-27
Facility ID:	9713843
Site ID:	273025
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported

MAIN LIBRARY (Continued) **S103037429**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALLELLO
Spiller Phone:	(914) 654-2315
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222185
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED - SYSTEM PASSED. NFA."
Remarks:	""

All TTF:

Facility ID:	9713843
Spill Number:	9713843
Spill Tank Test:	1545675
Site ID:	273025
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	273025
Operable Unit ID:	1056692
Operable Unit:	01
Material ID:	324833
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C34 **ACCESSOCRAFT PRODUCTS INC** **RCRA NonGen / NLR** **1001079768**
ESE **48 LAWTON ST** **FINDS** **NYR000014753**
< 1/8 **NEW ROCHELLE, NY 10802** **ECHO**
0.045 mi. **NY MANIFEST**
240 ft. **Site 3 of 6 in cluster C**

Relative: **Higher**
Actual: **94 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	ACCESSOCRAFT PRODUCTS INC
Handler Address:	48 LAWTON ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYR000014753
Contact Name:	Not reported
Contact Address:	LAWTON ST
Contact City,State,Zip:	NEW ROCHELLE, NY 10802
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	LAWTON ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10802
Owner Name:	CITY OF NEW ROCHELLE
Owner Type:	Municipal
Operator Name:	CITY OF NEW ROCHELLE
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste Code: NONE
Waste Description: Not Defined

Waste Code: P030
Waste Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste Code: P098
Waste Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Waste Code: P106
Waste Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF NEW ROCHELLE
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NORTH AVE - CITY HALL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802
Owner/Operator Telephone: 914-654-2163
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW ROCHELLE
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NORTH AVE - CITY HALL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802
Owner/Operator Telephone: 914-654-2163
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW ROCHELLE
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Owner/Operator Address: NORTH AVE - CITY HALL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802
Owner/Operator Telephone: 914-654-2163
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19960510
Handler Name: ACCESSOCRAFT PRODUCTS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ACCESSOCRAFT PRODUCTS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ACCESSOCRAFT PRODUCTS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19951011
Handler Name: ACCESSOCRAFT PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960306
Handler Name: ACCESSOCRAFT PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 339914
NAICS Description: COSTUME JEWELRY AND NOVELTY MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110000849672

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079768
Registry ID: 110000849672
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000849672
Name: ACCESSOCRAFT PRODUCTS INC
Address: 48 LAWTON ST
City,State,Zip: NEW ROCHELLE, NY 10802

NY MANIFEST:
Name: ACCESSOCRAFT INC
Address: 48 LAWTON ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA

ACCESSOCRAFT PRODUCTS INC (Continued) **1001079768**

EPA ID:	NYR000014753
Facility Status:	Not reported
Location Address 1:	48 LAWTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000014753
Mailing Name:	ACCESSOCRAFT INC
Mailing Contact:	PAUL STEINMAN
Mailing Address 1:	48 LAWTON STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146322411

E35 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1005444315**
NE **255 NORTH AVE** **NY MANIFEST** **NYR000106369**
< 1/8 **NEW ROCHELLE, NY 10801**
0.048 mi.
256 ft. **Site 8 of 13 in cluster E**

Relative: **Lower**

Actual: **87 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	US POSTAL SERVICE	
Handler Address:		255 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801-9998
EPA ID:		NYR000106369
Contact Name:		JOANNE KUNNY
Contact Address:		WESTCHESTER AVE
Contact City,State,Zip:		WHITE PLAINS, NY 10610-9111
Contact Telephone:		914-697-7074
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Federal
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		WESTCHESTER AVE
Mailing City,State,Zip:		WHITE PLAINS, NY 10610-9111
Owner Name:		US POSTAL SERVICE
Owner Type:		Federal
Operator Name:		US POSTAL SERVICE

US POSTAL SERVICE (Continued) **1005444315**

Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned, The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

US POSTAL SERVICE (Continued) **1005444315**

Hazardous Waste Summary:
Waste Code: D002
Waste Description: CORROSIVE WASTE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: US POSTAL SERVICE
Legal Status: Federal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 255 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801-9998
Owner/Operator Telephone: 914-632-5906
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: US POSTAL SERVICE
Legal Status: Federal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 255 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801-9998
Owner/Operator Telephone: 914-632-5906
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: US POSTAL SERVICE
Legal Status: Federal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 255 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801-9998
Owner/Operator Telephone: 914-632-5906
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: US POSTAL SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

US POSTAL SERVICE (Continued) **1005444315**

Handler Name: US POSTAL SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020517
Handler Name: US POSTAL SERVICE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: US POSTAL SERVICE
Address: 255 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10801-9998
Country: USA
EPA ID: NYR000106369
Facility Status: Not reported
Location Address 1: 255 NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000106369
Mailing Name: US POSTAL SERVICE
Mailing Contact: RICHARD FERRARI
Mailing Address 1: 255 NORTH AVENUE

US POSTAL SERVICE (Continued) **1005444315**

Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146977074

D36 **SPILL NUMBER 9803949** **NY Spills** **S104647160**
West **MILEPOST 5.5 SB I95** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.048 mi.
256 ft. **Site 2 of 2 in cluster D**

Relative:
Lower

Actual:
79 ft.

SPILLS:

Name:	SPILL NUMBER 9803949
Address:	MILEPOST 5.5 SB I95
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9803949 / 1998-06-29
Facility ID:	9803949
Facility Type:	ER
DER Facility ID:	140562
Site ID:	166821
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-06-29
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-29
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-29
Spill Record Last Update:	1998-07-02
Spiller Name:	MR STEPHEN WELDON
Spiller Company:	STEPHENS TRANSP INC
Spiller Address:	60 JOFFRE
Spiller Company:	001
Contact Name:	SGT POWELL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"drive shaft broke on trk rupturing the saddle tank - cleanup in progress"

All Materials:

Site ID:	166821
Operable Unit ID:	1064663
Operable Unit:	01

SPILL NUMBER 9803949 (Continued) **S104647160**

Material ID:	322269
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B37 **306 HUGUENOT STREET CORP.** **NY AST** **U004187406**
SSW **306 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.050 mi.
264 ft. **Site 16 of 16 in cluster B**

Relative: WESTCHESTER CO. AST:
Higher

Actual:
101 ft.

Name:	306 HUGUENOT STREET CORP.
Address:	306 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800236
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	306 Huguenot Street Corp.
Owner Street:	P.O. Box 196
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	001
Status:	1. In-Service
Date Installation:	12/01/1986
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	Not reported
Dispenser:	3. Gravity

E38 **A PLUS INC** **EDR Hist Auto** **1020468102**
NE **271 NORTH AVE STE 117** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.054 mi.
285 ft. **Site 9 of 13 in cluster E**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
84 ft. 2014 A PLUS INC Gasoline Service Stations, NEC

E39 **COMMERCIAL BUILDING** **NY Spills** **S121984763**
NE **271 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.054 mi.
285 ft. **Site 10 of 13 in cluster E**

Relative: SPILLS:
Lower

Actual:
84 ft.

Name:	COMMERCIAL BUILDING
Address:	271 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1800222 / Not Reported
Facility ID:	1800222
Facility Type:	ER
DER Facility ID:	522007
Site ID:	568710
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2018-04-06
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2018-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2018-04-06
Spill Record Last Update:	2018-04-06
Spiller Name:	GEORGE PRELA
Spiller Company:	GEORGE PRELA (KAUFMANN HUEGENAUGHT CO)
Spiller Address:	271 NORTH AVENUE
Spiller Company:	999
Contact Name:	GEORGE PRELA
DEC Memo:	"04/06/18 WCDH called in a spill at this apartment complex. A line leaked in a boiler room causing approximately 20 gallon spill. No drains or waterways were impacted. #6 Fuel oil is congealed indicating it has been leaking for awhile. The superintendent is doing the clean up. WCDH gave them until Monday to finish the clean up and do the repairs. Kaufman Hugenout Company 450 7th Ave, New York, NY (212) 471-4300; creid@kaufmanorganization.com PBS No. 3-183776 BTR"
Remarks:	"in basement - cleanup pending"

COMMERCIAL BUILDING (Continued) **S121984763**

All Materials:

Site ID:	568710
Operable Unit ID:	1316583
Operable Unit:	01
Material ID:	2324343
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

E40 **KAUFMAN HUGUENOT COMPANY** **NY UST U003994672**
NE **271 NORTH AVENUE** **NY AST N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.054 mi.
285 ft. **Site 11 of 13 in cluster E**

Relative: **Lower**
Actual: **84 ft.**

WESTCHESTER CO. UST:

Name:	KAUFMAN HUGUENOT COMPANY
Address:	271 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-183776 / Active
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10123
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1900
Date Perm Closure:	01/01/2011
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

KAUFMAN HUGUENOT COMPANY (Continued) **U003994672**

WESTCHESTER CO. AST:

Name:	KAUFMAN HUGUENOT COMPANY
Address:	271 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-183776
Site Status:	Active
GDS Number:	Not reported
Operator Name:	George Prela
Owner Name:	Kaufman Huguenot Co.
Owner Street:	450 Seventh Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10123
Tank Number:	002
Status:	1. In-Service
Date Installation:	08/01/2007
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	4. Groundwater Well
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	2. Transfer Station Containment
Dispenser:	2. Suction

C41 **LAWTON STREET REALTY CORP** **NY Spills** **S123160020**
ESE **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
289 ft. **Site 4 of 6 in cluster C**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1808090 / 2019-02-15
Facility ID:	1808090
Facility Type:	ER
DER Facility ID:	486301
Site ID:	578882
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2018-10-29
Investigator:	TDGHIOSA
Referred To:	Not reported

LAWTON STREET REALTY CORP (Continued) **S123160020**

Reported to Dept:	2018-10-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-10-29
Spill Record Last Update:	2019-02-15
Spiller Name:	Not reported
Spiller Company:	MICHAEL LAGE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MICHAEL LAGE
DEC Memo:	"10/29/18 North East Env. pulled 3,000 gallon UST from under a parking lot, found holes in tank. No waterways on property, no drains, property on municipal water. No ground water impacts noted at this time. Cleanup to start in 3 weeks. Left message for property owner to call duty desk. ga 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG"
Remarks:	"it was 3000 gallon tank pbs 3-801435. The cleanup is pending"

All Materials:

Site ID:	578882
Operable Unit ID:	1326616
Operable Unit:	01
Material ID:	2335419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

C42 **LAWTON STREET REALTY CORP** **NY LTANKS** **S118953553**
ESE **41-43 LAWTON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
289 ft. **Site 5 of 6 in cluster C**

Relative: **Higher**
Actual: **94 ft.**

LTANKS:

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1706064 / 2019-02-15
Facility ID:	1706064
Site ID:	560365
Spill Date:	2017-09-21
Spill Cause:	Tank Test Failure

LAWTON STREET REALTY CORP (Continued) **S118953553**

Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2017-09-21
Spill Record Last Update:	2019-02-15
Spiller Name:	Not reported
Spiller Company:	MIKE LAGE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MIKE LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/21/17 3000 gallon UST failed TT with hissing. Same tank failed test last year. Owner is waiting on Con Ed to convert over to natural gas. Conversion should be finished in 3-4 months. Tank will be pulled in approx. 6 months. WC PBS# 3-801435. ga 9-27-17 From Wchd, TTF at a PBS site. 41-43 Lawton St, New Rochelle 3k UST heating oil Old open TTF on site 1605726 RDB 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG "
Remarks:	"3000 gal ust"

All Materials:

Site ID:	560365
Operable Unit ID:	1308365
Operable Unit:	01
Material ID:	2315311
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	LAWTON STREET REALTY CORP
Address:	41-43 LAWTON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1605726 / 2019-02-15
Facility ID:	1605726
Site ID:	532284

LAWTON STREET REALTY CORP (Continued) **S118953553**

Spill Date:	2016-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2016-09-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-09-07
Spill Record Last Update:	2019-02-15
Spiller Name:	MICHAEL LAGE
Spiller Company:	LAWTON STREET REALTY CORP
Spiller Address:	41-43 LAWTON ST
Spiller County:	999
Spiller Contact:	MICHAEL LAGE
Spiller Phone:	(914) 804-6934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	486301
DEC Memo:	"9/7/16 Called Tank Tech - 3000 gal tank failed with popping sound indicative of piping & fitting failure. Owner notified on site. Spoke to owner. Tank to be removed & replaced, contract pending. Property is 13 residential & 2 commercial. Building is on municipal water. Sent owner draft guidelines and contractor list. ga 5-4-17 Meeting with WCDOH. WC to follow up. GHP 02/14/19 Northeast Environmental reported that they excavated and removed the tank along with 33.96 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG"
Remarks:	"pbs tank failure"

All Materials:

Site ID:	532284
Operable Unit ID:	1281058
Operable Unit:	01
Material ID:	2286307
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

C43 **PAVEMENT** **NY Spills** **S112147960**
ESE **41 LAWTON STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.055 mi.
289 ft. **Site 6 of 6 in cluster C**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Name:	PAVEMENT
Address:	41 LAWTON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1203965 / 2012-07-23
Facility ID:	1203965
Facility Type:	ER
DER Facility ID:	421153
Site ID:	466814
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2012-07-23
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2012-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-23
Spill Record Last Update:	2012-07-23
Spiller Name:	BADGE 620
Spiller Company:	UNKNOWN
Spiller Address:	41 LAWTON STREET
Spiller Company:	999
Contact Name:	BADGE 620
DEC Memo:	"7-23-12 FD cleaned up. jc"
Remarks:	"Possibly from garbage truck. Fire Dept. Clean up."

All Materials:

Site ID:	466814
Operable Unit ID:	1216796
Operable Unit:	01
Material ID:	2215011
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

E44 **FEDERAL PROPERTY MAINTENANCE CORP** **RCRA NonGen / NLR** **1012186472**
ENE **244 NORTH AVE SUITE 153** **NYR000163337**
< 1/8 **NEW ROCHELLE, NY 10801**
0.055 mi.
290 ft. **Site 12 of 13 in cluster E**

Relative: **Lower**
Actual: **89 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20170525
Handler Name:	FEDERAL PROPERTY MAINTENANCE CORP
Handler Address:	244 NORTH AVE SUITE 153
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000163337
Contact Name:	KRISTIE EFFEREN
Contact Address:	NORTH AVE SUITE 153
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	914-355-2226
Contact Fax:	Not reported
Contact Email:	FEDERALPMC@AOL.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	NORTH AVE SUITE 153
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	ANTHONY VALENTINO
Owner Type:	Private
Operator Name:	KRISTIE EFFEREN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171128
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KRISTIE EFFEREN
Legal Status:	Private
Date Became Current:	20050624
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ANTHONY VALENTINO
Legal Status:	Private
Date Became Current:	19780520
Date Ended Current:	Not reported
Owner/Operator Address:	59 GRANT AVE
Owner/Operator City,State,Zip:	HARRISON, NY 10528
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

Owner/Operator Indicator: Operator
Owner/Operator Name: KRISTIE EFFEREN
Legal Status: Private
Date Became Current: 20050624
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANTHONY VALENTINO
Legal Status: Private
Date Became Current: 19780520
Date Ended Current: Not reported
Owner/Operator Address: 59 GRANT AVE
Owner/Operator City,State,Zip: HARRISON, NY 10528
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20170525
Handler Name: FEDERAL PROPERTY MAINTENANCE CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20090223
Handler Name: FEDERAL PROPERTY MAINTENANCE CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 562111
NAICS Description: SOLID WASTE COLLECTION

NAICS Code: 562112

FEDERAL PROPERTY MAINTENANCE CORP (Continued) **1012186472**

NAICS Description: HAZARDOUS WASTE COLLECTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F45 **NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION** **RCRA NonGen / NLR** **1026059561**
NNW **24 STATION PLZ N** **NYR000244764**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
298 ft. **Site 1 of 2 in cluster F**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20200909
Handler Name:	NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT
Handler Address:	24 STATION PLZ N
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000244764
Contact Name:	TODD CASTALDO
Contact Address:	NORTH AVENUE
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	914-654-2185
Contact Fax:	Not reported
Contact Email:	TCASTALD@NEWROCHELLENY.COM
Contact Title:	OPERATIONS MANAGER
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	NORTH AVENUE
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	CITY OF NEW ROCHELLE DEPARTMENT OF FINANCE
Owner Type:	Municipal
Operator Name:	CITY OF NEW ROCHELLE
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT (Continued) **1026059561**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CITY OF NEW ROCHELLE
Legal Status:	Municipal
Date Became Current:	19910301
Date Ended Current:	Not reported
Owner/Operator Address:	515 NORTH AVENUE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-654-2185

NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT (Continued) 1026059561

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: TCASTALD@NEWROCHELLENY.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW ROCHELLE DEPARTMENT OF FINANCE
Legal Status: Municipal
Date Became Current: 19910301
Date Ended Current: Not reported
Owner/Operator Address: 515 NORTH AVENUE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-200-9404
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: RBONACCI@NEWROCHELLENY.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF NEW ROCHELLE
Legal Status: Municipal
Date Became Current: 19910301
Date Ended Current: Not reported
Owner/Operator Address: 515 NORTH AVENUE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-654-2185
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: TCASTALD@NEWROCHELLENY.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW ROCHELLE DEPARTMENT OF FINANCE
Legal Status: Municipal
Date Became Current: 19910301
Date Ended Current: Not reported
Owner/Operator Address: 515 NORTH AVENUE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-200-9404
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: RBONACCI@NEWROCHELLENY.COM

Historic Generators:
Receive Date: 20200909
Handler Name: NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200116
Handler Name: NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT
Federal Waste Generator Description: Small Quantity Generator

NEW ROCHELLE CITY OF TRAIN STATION REHABILITATION PROJECT (Continued) **1026059561**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485112
NAICS Description: COMMUTER RAIL SYSTEMS

NAICS Code: 488210
NAICS Description: SUPPORT ACTIVITIES FOR RAIL TRANSPORTATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F46 **STATION CLEANERS** **EDR Hist Cleaner** **1020094775**
NNW **24 STATION PLZ** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.056 mi.
298 ft. **Site 2 of 2 in cluster F**

Relative: EDR Hist Cleaner
Lower

Actual: **71 ft.**

Year:	Name:	Type:
2005	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2006	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	STATION CLEANERS	Drycleaning Plants, Except Rugs, NEC

G47 **CABLE** **NY Spills** **S109206706**
SSE **29 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.056 mi.
298 ft. **Site 1 of 5 in cluster G**

Relative: SPILLS:
Higher

Actual: **101 ft.**

Name: CABLE
Address: 29 DIVISION STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0804961 / 2008-07-30
Facility ID: 0804961
Facility Type: ER
DER Facility ID: 351170
Site ID: 401965
DEC Region: 3

CABLE (Continued) **S109206706**

Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jpcummin
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-07-31
Spiller Name:	ERTSDESK
Spiller Company:	CABLE
Spiller Address:	29 DIVISION STREET
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"SEE SP: 0804960. -- NFA"
Remarks:	"8 OUNCES AND ON GOING AND WONT MAKE 2 HOUR CLEAN UP"

All Materials:

Site ID:	401965
Operable Unit ID:	1158737
Operable Unit:	01
Material ID:	2149827
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E48 **247 NORTH AVENUE SITE** **NY BROWNFIELDS** **S127478116**
ENE **247 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.060 mi.
315 ft. **Site 13 of 13 in cluster E**

Relative:
Lower

Actual:
89 ft.

BROWNFIELDS:

Name:	247 NORTH AVENUE SITE
Address:	247 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	602511
Acres:	0.570
HW Code:	C360200
SWIS:	6010
Town:	New Rochelle (c)

247 NORTH AVENUE SITE (Continued) **S127478116**

Record Added Date:	03/27/2020
Record Updated Date:	07/26/2021
Update By:	DJEATON
Site Description:	"Site Location: The 0.57 acre property is found at 247 North Avenue, New Rochelle, NY 10801 (tax map number; Section 1, Block 231, Lot 19). The site is located in a commercial and residential urban area in downtown New Rochelle. The site is bound by North Avenue to the west and LeCount Place to the east. While not adjacent to the site, Huguenot Street is to the north and Main Street is to the south. Site Features: The Subject Property is currently improved with a 1-story commercial building temporarily occupied by a medical clinic (Planned Parenthood) and an employment assistance organization, and also contains an associated asphalt parking lot. The current onsite building was constructed in 1941. The closest surface water body is an inlet of the Long Island Sound, located approximately 0.4 miles east of the site. The New Rochelle Metro-North train station is within walking distance to the west. Current Zoning and Land Use: The site is located in the Downtown Business (DB) District, which contains a Downtown Overlay (DO-2) zone. The surrounding properties to the North include a multi-storied residential building and a one-story commercial building. Properties to the South include a residential building with ground-floor retail and a preschool. The property to the East across Le Count Place is occupied by a Marriott Residence Inn Hotel. Properties to the West include two-story commercial buildings across North Avenue, which are occupied by a bank and retail stores. The closest residential area is the property immediately adjacent on the south side of the site. Past Use of the Site: By 1887, the site was developed with a structure appearing to be a coal and wood yard. By 1896, two more structures appeared on the property, one of them labeled Laundry , from 1903-1931. Various other commercial businesses operated until 1942, when the site appears to be vacant. A 120-gallon gasoline storage tank was noted on the 1911 Sanborn map. By 1951, a commercial building, resembling the current site building was present on the Southwest portion of the site. From 1951 and up until the present, no significant changes were observed. A Phase II ESA conducted in October 2019, indicated the presence of SVOCs (Semi-Volatile Organic Compounds) and metals in soil exceeding applicable soil standards, and the presence of VOCs (Volatile Organic Compounds) in soil vapor outside of the building footprint at levels exceeding applicable screening levels. Site Geology and Hydrogeology: There are no predominant geological surface features such as rock outcroppings on the site. Surface soil at the site predominantly consists of gravelly to very gravelly loam. The general topographic gradient is towards the north east. Under natural, undisturbed conditions, shallow groundwater flow generally follows the topography of the land surface and on this basis, the topography suggests that groundwater flow across the site is in an easterly direction. However, localized conditions can alter flow direction and thus the presumed flow may not coincide with the actual flow in the site area. The site is not located within a floodplain. "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and this entry will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

247 NORTH AVENUE SITE (Continued) **S127478116**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-06-23 09:24:00
Record Upd:	2020-06-23 09:24:00
Updated By:	JEBROWN
Own Op:	1
Sub Type:	E
Owner Name:	bruce Berg
Owner Company:	247 North Avenue Associates LLC
Owner Address:	c/o Cappelli Organization
Owner Addr2:	7 Renaissance Square, 4th Floor
Owner City,St,Zip:	white Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	bruce Berg
Owner Company:	247 North Avenue Associates LLC
Owner Address:	c/o Cappelli Organization
Owner Addr2:	7 Renaissance Square, 4th Floor
Owner City,St,Zip:	white Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	ONE LIBRARY PLAZA
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Vincent Russell
Owner Company:	Planned Parenthood Hudson Peconic, Inc.
Owner Address:	570 Taxter Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Elmford, NY 10523
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Joanne Dunn
Owner Company:	First Source Referral Center
Owner Address:	247 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported

247 NORTH AVENUE SITE (Continued) **S127478116**

Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

H49 **NORTH BROOK REALTY ASSOCIATES** **NY UST** **U004259521**
NNE **270 NORTH AVENUE, SUITE 200** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.061 mi.
323 ft. **Site 1 of 8 in cluster H**

Relative: **Lower**

Actual: **80 ft.**

WESTCHESTER CO. UST:

Name:	NORTH BROOK REALTY ASSOCIATES
Address:	270 NORTH AVENUE, SUITE 200
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-600117 / Active
Operator Name:	North Brook Realty Associates
Owner Name:	North Brook Realty Associates
Owner Street:	270 North Avenue, Suite 200
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	15000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

I50 **SOIL** **NY Spills** **S122479707**
SSW **316 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.068 mi.
361 ft. **Site 1 of 24 in cluster I**

Relative:
Higher

Actual:
99 ft.

SPILLS:

Name:	VINEK / KRACKO - USTS
Address:	316 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1802819 / 2018-07-23
Facility ID:	1802819
Facility Type:	ER
DER Facility ID:	524548
Site ID:	571425
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	6010
Spill Date:	2018-06-12
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2018-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-06-12
Spill Record Last Update:	2018-07-23
Spiller Name:	Elliot Kracko
Spiller Company:	Vinek Corp
Spiller Address:	316 HUGUEKNOT ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"6/12/18 North East Env. pulled 3 USTs - 550, 1000 previously abandoned, and 300 newly discovered tank. Tanks had holes, contaminated soil underneath 1000 and 300, and above the 550. No waterways on property. Property on municipal water. North East has started cleanup. ga 7-19-18 D. Monaco submitted closure report to DEC. Report is on D2. BTR 7-23-18 Closure report documents tank removal and remediation. 17.91 tons of petroleum impacted soil was removed from the rear of the structure (550 gallon tank). A total of 549.82 tons of petroleum impacted soil was removed from the front of the structure (1000 and 300 gallon tanks). Sample results are below CP-51. NFA. BTR"
Remarks:	"holes in tank 550 tank 1000 tank 300 tank removed clean up has started"

All Materials:

Site ID:	571425
Operable Unit ID:	1319254
Operable Unit:	01
Material ID:	2327236
Material Code:	0022

SOIL (Continued) **S122479707**

Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: SOIL
Address: 316 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 2003772 / Not Reported
Facility ID: 2003772
Facility Type: ER
DER Facility ID: 524548
Site ID: 609507
DEC Region: 3
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 6010
Spill Date: 2020-08-03
Investigator: MDKILMER
Referred To: Not reported
Reported to Dept: 2020-08-05
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2020-08-05
Spill Record Last Update: 2021-02-23
Spiller Name: KEVIN B
Spiller Company: ALL STATE
Spiller Address: 316 HUGUENOT ST
Spiller Company: 999
Contact Name: KEVIN B
DEC Memo: "8-5/20 spoke to Kevin B from abc both spill numbers are same owner both are phase 2 site assessment with contamination Kevin to give property owner information DEC folloup required . LR 2/23/21: Reassigning to Michael Kilmer as related to BCP site Firestone Tire and Auto Repair (C360215). MDK"
Remarks: "phase two no clean up"

All Materials:
Site ID: 609507
Operable Unit ID: 1356659
Operable Unit: 01
Material ID: 2367978
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum

SOIL (Continued) **S122479707**

Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

I51 **FIRESTONE TIRE AND AUTO REPAIR SITE** **NY BROWNFIELDS** **S127478137**
SSW **316 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.068 mi.
361 ft. **Site 2 of 24 in cluster I**

Relative:
Higher

Actual:
99 ft.

BROWNFIELDS:
Name: FIRESTONE TIRE AND AUTO REPAIR SITE
Address: 316 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Program: BCP
Site Code: 616446
Acres: 0.281
HW Code: C360215
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 02/17/2021
Record Updated Date: 04/12/2021
Update By: RDBENDEL
Site Description: "Site Location The 0.281-acre site is located at 316 Huguenot Street, New Rochelle, New York 10801 on Tax Parcel 2-415-13. The site is located in an urban mixed-use area in downtown New Rochelle. The surrounding properties include retail businesses, retail/commercial store fronts, a multi-story apartment structure, commercial businesses, and mixed-use properties. The site is located north of Centre Avenue and east of Huguenot Street. The site is walking distance from the New Rochelle Metro-North train station. Site Features The 316 Huguenot Street Parcel is currently improved with a one-story wood/steel frame commercial structure, which still houses a retail plumbing home improvement business. The building is slab on grade with a partial mezzanine level storage area. The building was constructed around 1957 to house a Firestone Tire & Auto Repair Business. Paved parking areas are located on both the Huguenot Street and Westchester Place sides of the building. The closest surface water body is an inlet of the Long Island Sound located approximately 0.8 miles east of the site. The Metro North Train Station is located within walking distance of the site. Current Zoning and Land Use The 316 Huguenot Street Parcel is currently located in the Downtown Business (DB) District. The parcel is currently or was previously considered commercial / retail space uses. The surrounding properties include retail businesses, retail/commercial store fronts, a multi-story apartment structure, commercial businesses, and mixed-use properties. The closest residential area is a condominium building that is located about 50 feet away from the subject property. The site is also approximately 0.07 miles from the Metro-North rail line, which is northwest of the site. The site is not located in a flood zone. Past Uses of the Site Based on aerial photographs, historical Sanborn maps, and information obtained from the City of New Rochelle Tax Assessor s Office, the historical uses of the site include the following uses. Historical Sanborn maps identified the property as undeveloped from 1887-1911. Between 1911 and 1951, the site was improved with a retail filling station and an automotive repair

FIRESTONE TIRE AND AUTO REPAIR SITE (Continued) **S127478137**

garage. Maps of the subject property from 1931 and 1951 show the filling station and three gasoline tanks within the northern most section of the parcel. In 1957, a Building Permit was issue for the existing commercial structure for Firestone Tire & Auto Repair Shop. The T-shaped building contained a vehicle service area and storage/sales rooms. A 1990 fire insurance map noted that the building was vacant. The building was operated as a retail home improvement business prior to being used by Kent Supply Company, which now temporarily operates a plumbing supply company at the site but is a month-to-month tenant. Prior to 2002, the City of New Rochelle is listed as the owner of the site. McCosker Equities Ltd. purchased the site in 2002. Vinek Holding Corp. purchased the property from McCosker Equities Ltd. in 2009. Allstate Ventures LLC purchased the property in July 2018 from Vinek Holding Corp. and then finally the Requestor purchased the site in October 2019. Site Geology and Hydrogeology A historic fill layer is present under the current asphalt parking lot from 3.5 to 7 ft-bgs. The site s subsurface soils are composed of dark brown and gray coarse to fine grained sand, gravel and clay to depths of 6 to 15 ft-bgs. At 15 ft-bgs, weathered bedrock is present. According to the 1970 Geologic Map of New York - Lower Hudson Sheet - published by the University of the State of New York, the underlying bedrock of the site is of the Hartland Formation and is comprised of primarily basal amphibolite gneiss overlain by politic schists. According to the United State Geological Survey (USGS), the site s average topographic elevation is approximately 107-feet above mean sea level. The site is a relatively flat with regional topography slopping to the west. Groundwater was encountered at depths ranging from 4 ft-bgs to 8 ft-bgs and groundwater flow direction is anticipated to flow with the surface elevation profile to the west. The site is not located in a flood zone."

Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	new rochelle public library
Owner Address:	1 library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America

FIRESTONE TIRE AND AUTO REPAIR SITE (Continued) **S127478137**

Own Op:	6
Sub Type:	P03
Owner Name:	Mikel Jeremias
Owner Company:	Allstate Acquisitions LLC
Owner Address:	13 Hayes Court, Unit 101
Owner Addr2:	Not reported
Owner City,St,Zip:	Monroe, NY 10950
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Mikel Jeremias
Owner Company:	Allstate Acquisitions LLC
Owner Address:	13 Hayes Court, Unit 101
Owner Addr2:	Not reported
Owner City,St,Zip:	Monroe, NY 10950
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Frank Nicosia
Owner Company:	Kent Supply
Owner Address:	316 huguenot Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	1802819
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-02-23 10:28:00
Record Updated:	2021-02-23 10:28:00
Updated By:	MDKILMER
Crossref ID:	2003772
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-02-23 10:27:00
Record Updated:	2021-02-23 10:27:00
Updated By:	MDKILMER

H52 **EAST RIVER SAVINGS BANK** **NY LTANKS** **U003647446**
NNE **277 NORTH AVE.** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.071 mi.
376 ft. **Site 2 of 8 in cluster H**

Relative: LTANKS:
Lower

Name:	EAST RIVER SAVINGS BANK
Address:	277 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8912285 / 1991-01-16
Facility ID:	8912285
Site ID:	271129
Spill Date:	1990-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported

Actual:
81 ft.

EAST RIVER SAVINGS BANK (Continued) **U003647446**

Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-03-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-29
Spill Record Last Update:	1991-03-19
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220684
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/19/91: TANK WAS REKINED AND PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK WAS ISOLATED AND THEY WILL RETEST PETRO-TITE -.3385 GPH"

All TTF:

Facility ID:	8912285
Spill Number:	8912285
Spill Tank Test:	1536885
Site ID:	271129
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271129
Operable Unit ID:	937979
Operable Unit:	01
Material ID:	441756
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

EAST RIVER SAVINGS BANK (Continued) **U003647446**

Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

H53 **CON EDISON MANHOLE: 11295** **RCRA NonGen / NLR** **1016960384**
NNE **277 NORTH AVE** **NY MANIFEST** **NYP004323457**
< 1/8 **NEW ROCHELLE, NY 10802**
0.071 mi.
376 ft. **Site 3 of 8 in cluster H**

Relative: **Lower**
Actual: **81 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130728
Handler Name:	CON EDISON MANHOLE: 11295
Handler Address:	277 NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004323457
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130628
Handler Name:	CON EDISON MANHOLE: 11295
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130728
Handler Name:	CON EDISON MANHOLE: 11295
Federal Waste Generator Description:	Not a generator, verified

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	277 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004323457
Facility Status:	Not reported
Location Address 1:	FO 277 NORTH AVE
Code:	BP
Location Address 2:	MH #11295
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004323457
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359

CON EDISON MANHOLE: 11295 (Continued) **1016960384**

Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2013
Trans1 Recv Date:	06/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004323457
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693229JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H54 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157675**
NNE **F/O 277 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.071 mi.
376 ft. **Site 4 of 8 in cluster H**

Relative: NY MANIFEST:
Lower

Name:	CONSOLIDATED EDISON
Address:	F/O 277 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004230322
Facility Status:	Not reported
Location Address 1:	F/O 277 NORTH AVE

Actual:
81 ft.

CONSOLIDATED EDISON (Continued) **S111157675**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230322
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2011
Trans1 Recv Date:	03/10/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230322
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655972JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CONSOLIDATED EDISON (Continued) **S111157675**

Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H55 **BUSINESS** **NY LTANKS** **S108467526**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.071 mi.
376 ft. **Site 5 of 8 in cluster H**

Relative: LTANKS:
Lower

Actual: Name:	BUSINESS
81 ft. Address:	277 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0611580 / 2008-12-04
Facility ID:	0611580
Site ID:	376243
Spill Date:	2007-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-18
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE
Spiller Company:	BUSINESS
Spiller Address:	277 NORTH AVE
Spiller County:	001
Spiller Contact:	BRUCE
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11648 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM

BUSINESS (Continued) **S108467526**

levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks: "PIN HOLE IN TANK"

All TTF:
Facility ID: 0611580
Spill Number: 0611580
Spill Tank Test: 1550567
Site ID: 376243
Tank Number: 1
Tank Size: 10000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 376243
Operable Unit ID: 1133835
Operable Unit: 01
Material ID: 2123664
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

H56 **277 NR PRINCIPAL, LLC** **NY UST** **U003994270**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.071 mi.
376 ft. **Site 6 of 8 in cluster H**

Relative: WESTCHESTER CO. UST:
Lower
Actual: Name: 277 NR PRINCIPAL, LLC
81 ft. Address: 277 NORTH AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-502049 / Active
Operator Name: 277 NR Principal, LLC
Owner Name: 277 NR Principal, LLC
Owner Street: 277 North Avenue
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

277 NR PRINCIPAL, LLC (Continued) **U003994270**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	01/01/1900
Date Perm Closure:	10/10/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	10/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	5. Jacketed,9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	6. Wrapped (Piping),9. Urethane
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

H57 **277 NORTH LLC** **NY LTANKS** **S108467546**
NNE **277 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.071 mi.
376 ft. **Site 7 of 8 in cluster H**

Relative: LTANKS:
Lower

Name:	277 NORTH LLC
Address:	277 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0611648 / 2008-12-04
Facility ID:	0611648
Site ID:	376329
Spill Date:	2007-01-19
Spill Cause:	Tank Test Failure

Actual:
81 ft.

277 NORTH LLC (Continued) **S108467546**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-01-19
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2008-12-04
Spiller Name:	BRUCE MOSES
Spiller Company:	277 NORTH LLC
Spiller Address:	277 NORTH AVE
Spiller County:	001
Spiller Contact:	BRUCE MOSES
Spiller Phone:	(914) 712-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	327408
DEC Memo:	"Two LUSTs removed. Also see spill 06-11580 12/4/08: Northeast Environmental disposed of LUST and 356.79 tons of petroleum contaminated soil. Exit sample results were near or below TAGM levels. Based upon the information provided, this Department requires No Further Action at this time. jod"
Remarks:	"EZ 3 LP WAS TEST USED: TANK IS BEING VACCED OUT AND TEMP TANK PUT IN PLACE: ARRANGEMENTS FOR FURTHER TESTING ARE BEING MADE:"

All TTF:

Facility ID:	0611648
Spill Number:	0611648
Spill Tank Test:	1550579
Site ID:	376329
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	376329
Operable Unit ID:	1133914
Operable Unit:	01

277 NORTH LLC (Continued) **S108467546**

Material ID:	2123743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G58 **CON EDISON** **NY Spills** **S109206705**
SSE **19 DIVISION ST & WASHINGTON AV** **NY MANIFEST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.079 mi.
417 ft. **Site 2 of 5 in cluster G**

Relative: **Higher**
Actual: **100 ft.**

SPILLS:

Name:	ARIEL CABLE
Address:	19 DIVISION STREET/WASHIN
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0804960 / 2008-08-16
Facility ID:	0804960
Facility Type:	ER
DER Facility ID:	351169
Site ID:	401964
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2008-07-30
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-07-30
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-30
Spill Record Last Update:	2008-08-16
Spiller Name:	ERTSDESK
Spiller Company:	ARIEL CABLE
Spiller Address:	19 DIVISION STREET/WASHIN
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"CONTRACTOR ENROUTE"
Remarks:	"6 OUNCES AND ONGOING AND CRW WILL BE ENROUTE"

All Materials:

Site ID:	401964
Operable Unit ID:	1158736
Operable Unit:	01

CON EDISON (Continued) **S109206705**

Material ID:	2149826
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	19 DIVISION ST & WASHINGTON AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004800058
Facility Status:	Not reported
Location Address 1:	WASHINGTON ST & HUEGONOT AVE
Code:	BP
Location Address 2:	MH 7241
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004800058
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2015
Trans1 Recv Date:	06/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004800058
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046

CON EDISON (Continued) **S109206705**

TSDF ID 2:	Not reported
Manifest Tracking Number:	014469241JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	819
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J59 **CON EDISON** **RCRA NonGen / NLR** **1018281020**
East **NORTH AVE & ANDERSON** **FINDS** **NYP004759452**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.080 mi.
423 ft. **Site 1 of 17 in cluster J**

Relative: **Higher**
Actual: **90 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150328
Handler Name:	CON EDISON	
Handler Address:		NORTH AVE & ANDERSON
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004759452
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported

CON EDISON (Continued) **1018281020**

Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502

CON EDISON (Continued) **1018281020**

Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150328
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150328
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067686427

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON EDISON (Continued) **1018281020**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281020
Registry ID:	110067686427
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686427
Name:	CON EDISON
Address:	NORTH AVE & ANDERSON
City,State,Zip:	NEW ROCHELLE, NY 10801

J60 **CON ED STREET EXCAVATION** **NY Spills** **S125359722**
East **NORTH AVE AND ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.080 mi.
423 ft. **Site 2 of 17 in cluster J**

Relative: **Higher**
Actual: **90 ft.**

SPILLS:

Name:	CON ED STREET EXCAVATION
Address:	NORTH AVE AND ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1905834 / 2019-10-22
Facility ID:	1905834
Facility Type:	ER
DER Facility ID:	543845
Site ID:	593884
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2019-09-05
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2019-09-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-05
Spill Record Last Update:	2019-10-22
Spiller Name:	ERT
Spiller Company:	UNKNOWN
Spiller Address:	NORTH AVE AND ANDERSON ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"9/5/19 Con Ed found 1/2 gallon oil in soil when excavating. They stopped work, covered site, and will take soil samples for analysis. Cleanup pending results. No waterways or drains impacted. ga 09/05/19

CON ED STREET EXCAVATION (Continued) **S125359722**

Excerpt from EMIS, Senior Specialist, Sean Egan (04430) with EHS Street Construction, reported .5 gallon of an unknown oil within an excavation. Work immediately stopped and crews will be covering the excavation with a road plate. Samples for PCB, Oil ID and Flashpoint will be taken, however, the CoC was not available at the time of the call. TG 10/22/19 Excerpt from EMIS 275035/3; 10/8/2019 1:00 PM Allstate Clean venture removed 35 cubic yards of soil to permit work to continue. Sent to Clean Earth on 9/12/2019. Reinhart, Kenneth NFA. TG"

Remarks: "LOSS DISCOVERED IN EXCAVATION"

All Materials:

Site ID:	593884
Operable Unit ID:	1341458
Operable Unit:	01
Material ID:	2351367
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J61 **CON EDISON** **NJ MANIFEST** **S120669728**
East **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
423 ft. **Site 3 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004759452
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091137JJK
EPA ID:	NYP004759452
Date Shipped:	3/28/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON (Continued) **S120669728**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J62 **CON EDISON TRANSFORMER MANHOLE: 3585** **RCRA NonGen / NLR** **1016963788**
East **NORTH AVE & ANDERSON ST** **NY MANIFEST** **NYP004367611**
< 1/8 **NEW ROCHELLE, NY 10802**
0.080 mi.
423 ft. **Site 4 of 17 in cluster J**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:	20131029
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3585
Handler Address:	NORTH AVE & ANDERSON ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004367611
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

Actual:
90 ft.

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130929
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3585
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131029
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3585
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004367611
Facility Status:	Not reported

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004367611
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/29/2013
Trans1 Recv Date:	09/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/02/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004367611
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694650JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON TRANSFORMER MANHOLE: 3585 (Continued) **1016963788**

Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J63 **CON EDISON** **NY MANIFEST** **S118088384**
East **NORTH AVE & ANDERSON** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
423 ft. **Site 5 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & ANDERSON
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004759452
Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759452
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015

CON EDISON (Continued) **S118088384**

Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091137JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J64 **CON EDISON** **NY MANIFEST** **S113920666**
East **NORTH AVE & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
423 ft. **Site 6 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004683272
Facility Status:	Not reported
Location Address 1:	NORTH AVE & ANDERSON ST
Code:	BP
Location Address 2:	TM3585

CON EDISON (Continued) **S113920666**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004683272
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2014
Trans1 Recv Date:	10/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773173JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S113920666**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J65 **CON EDISON** **NY MANIFEST** **S117538298**
East **ANDERSON ST & NORTH AV** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.080 mi.
423 ft. **Site 7 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	ANDERSON ST & NORTH AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004709622
Facility Status:	Not reported
Location Address 1:	ANDERSON ST & NORTH AV
Code:	BP
Location Address 2:	SB2063
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004709622
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2014

CON EDISON (Continued) **S117538298**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709622
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773453JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I66 **BLOCK 417 NEW ROCHELLE** **RCRA NonGen / NLR** **1027099637**
SSW **327-329 HUGUENOT ST** **NYR000253161**
< 1/8 **NEW ROCHELLE, NY 10801**
0.081 mi.
429 ft. **Site 3 of 24 in cluster I**

Relative: **Higher**

Actual: **97 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20211104
Handler Name:	BLOCK 417 NEW ROCHELLE	
Handler Address:		327-329 HUGUENOT ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYR000253161
Contact Name:		KEVIN MCMANUS
Contact Address:		RENAISSSANCE SQ, 4TH FLR
Contact City,State,Zip:		WHITE PLAINS, NY 10805
Contact Telephone:		914-769-6500
Contact Fax:		Not reported
Contact Email:		KMCMANUS@ICAPPELLI.COM
Contact Title:		ENVIRONMENTAL PROJECTS MANAGER

BLOCK 417 NEW ROCHELLE (Continued) **1027099637**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	RENAISSSANCE SQ, 4TH FLR
Mailing City,State,Zip:	WHITE PLAINS, NY 10805
Owner Name:	RFMCH HUGUENOT PROPERTY OWER II LLC
Owner Type:	Private
Operator Name:	RFMCH HUGUENOT PROPERTY OWER II LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

BLOCK 417 NEW ROCHELLE (Continued) **1027099637**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211104
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RFMCH HUGUENOT PROPERTY OWER II LLC
Legal Status:	Private
Date Became Current:	20210128
Date Ended Current:	Not reported
Owner/Operator Address:	7 RENAISSSANCE SQ, 4TH FLR
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10805
Owner/Operator Telephone:	914-769-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	KMCMANUS@ICAPPELLI.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RFMCH HUGUENOT PROPERTY OWER II LLC
Legal Status:	Private
Date Became Current:	20210128
Date Ended Current:	Not reported
Owner/Operator Address:	7 RENAISSSANCE SQ, 4TH FLR
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10805
Owner/Operator Telephone:	914-769-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	KMCMANUS@ICAPPELLI.COM

Historic Generators:

Receive Date:	20211104
Handler Name: BLOCK 417 NEW ROCHELLE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

BLOCK 417 NEW ROCHELLE (Continued) **1027099637**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 531390
NAICS Description: OTHER ACTIVITIES RELATED TO REAL ESTATE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I67 BLOCK 417 NEW ROCHELLE **NY BROWNFIELDS S127478138**
SSW 327-329 HUGUENOT STREET **N/A**
< 1/8 NEW ROCHELLE, NY 10801
0.081 mi.
429 ft. **Site 4 of 24 in cluster I**

Relative: Higher
Actual: 97 ft.

BROWNFIELDS:
Name: BLOCK 417 NEW ROCHELLE
Address: 327-329 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Program: BCP
Site Code: 616464
Acres: 0.344
HW Code: C360216
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 02/18/2021
Record Updated Date: 01/25/2022
Update By: RDBENDEL
Site Description: "Site Location: The 0.344-acre site is located at 327-329 Huguenot Street, New Rochelle, New York, 10801. The site is located in a mixed-use downtown commercial and residential neighborhood undergoing significant revitalization as the result of the Brownfield Cleanup Program. The surrounding properties are used as stores, restaurants, parking lots, residential buildings, and a church. Site Features: The 0.344-acre site is currently improved as a rectangular parking lot. Two circular asphalt patched areas are located within the site. The patched areas are suspected to be filled potholes. The site is currently used for storage of construction materials, parking, and also contains two temporary office trailers by the site owner. A bus stop shelter location is located adjacent to the site along Huguenot Street. The closest waterbody to the site is Ferris Creek, which is located approximately 0.68 miles from the site. The closest open surface water body to the site is the Long Island Sound, which is approximately 0.95 miles from the site. The site is not located in a flood zone. Current Zoning and Land Use: The site is currently located in the Downtown Business (DB) and Downtown Overlay (DO-2) Gateway Transition Districts. Allowed uses in these districts include stores, retail, offices, and residential units on the second floor and above in buildings. The subject property is currently used as a parking lot. A church is located north of the site. Huguenot Street is located east of the site. Centre Avenue and a parking lot are located south of the site. This is a BCP site being redeveloped.

BLOCK 417 NEW ROCHELLE (Continued) **S127478138**

Commercial properties are present to the west of the site. The surrounding properties also include stores, restaurants, commercial buildings, and residential buildings. The closest residential area is an apartment building located approximately 0.083 miles away. The closest rail line is located approximately 0.034 miles away from the site. Past Use of the Site: Based on aerial photographs, deeds, and historical Sanborn maps, the historical uses of the site include the following uses: Maps from 1887 - 1903 depict the site as a vacant lot. D. and L. Building Company recorded a mortgage for the site in May 1910. This may be when the contaminated historic fill soils were placed on the site. In maps from 1911-1951, the site is occupied by apartments and street level stores. The complex is identified as D&L Apartments. In July 1915, Bonniecrest, Inc. purchased the property from Robertson T. Barrett, Referee, at a public auction. Jacob Malakoff became the owner of the site in 1921. The site was purchased by Irene Hendrick in July 1925. Ms. Hendrick sold the site to The Emigrant Industrial Savings Bank in 1938. In June 1939, The Emigrant Industrial Savings Bank transferred ownership of the site to Thelma Portugh, who then transferred the property to Herald Management Corp. Samron Realty Corporation purchased the site in December 1939. In June 1945, 1320-1328 Grant Avenue Corporation purchased the site. Huguenot-Center Corporation purchased the site in June 1946. Maps between 1951 and 1992 show D&L Apartments are on the site, but the buildings were noted to be vacant. In January 1952, Leon Steinman and Sylvia Rubin purchased the site. Harry Crown purchased the site in May 1956, and he sold the property to Ruth Crown in 1960. Salco Holding Corporation purchased the property in February 1962. Residential lists were associated with the site in 1972. In 1986, Huguenot Arms Associates (c/o Danray Development Organization) purchased the site. Residential lists were associated with the site in 1987. The City of New Rochelle acquired the site through a condemnation proceeding in 1990. In the 1993 map, the apartments are no longer present. Therefore, the current parking lot, which is present on the site now, is likely to have been constructed by the City after building demolition. Maps from 1994 to 2003 depict the site as a parking lot. The City of New Rochelle Corporation for Local Development acquired ownership of the site in May 2019. Later in the same month, Huguenot Partners LLC purchased the property. The current owner, RFMCH Huguenot Property Owner LLC purchased the site from Huguenot Partners LLC in August 2019. Site Geology and Hydrogeology: According to the United States Geological survey (USGS) Mount Vernon, 2013, 7.5-minute series topographic map, the site is approximately 96 feet above mean sea level. The site s topography slopes gently to the north. According to the Department of the Interior United States Geologic survey, the site soils are mapped as Quanternary till overlaying bedrock further classified as a geologic ground moraine. The subject property is composed of Uf Urban Land soil. This indicates that over sixty percent of the land surface is covered. surface materials on the site consist of 3 to 5 inches of asphalt. The subsurface geology of the site generally consists of uncontrolled fill from grade to depths ranging from 5 to 11 feet below grade surface (ft-bgs). The uncontrolled fill consisted of red-brown/brown coarse to fine sand and/or coarse to fine gravel with varying amounts of silt, brick, concrete and asphalt millings. some portions of fill were composed off brick fragments or concrete. A concrete slab is present in some parts of the site between 3 and 8 ft-bgs. A decomposed rock stratum begins between 5 to 11 ft-bgs. The natural

BLOCK 417 NEW ROCHELLE (Continued) **S127478138**

	decomposed rock extends to depths between 10 and 22 ft-bgs. Bedrock is present under the natural decomposed rock. The bedrock is part of the Hartland formation defined as mica schist and mica gneiss, medium to coarsely crystalline. The bedrock consists of dark gray, weathered, hard, slightly to intensely fractured Gneiss; overlying dark gray, slightly weathered, hard, slightly fractured to moderately fractured schist, with high angle foliations/banding. Groundwater on the site is primarily derived from precipitation. NP&V estimated that groundwater flowed to the east towards Ferris Creek. However, SESI s Phase I report noted that groundwater flow was expected to be to the south-southwest based on its investigation of the neighboring property to the south (339 Huguenot Street) and on reports for a nearby facility. Overburden groundwater is present at the site ranging between 0.2 to 10 ft-bgs. Groundwater was also found between 16 and 27 ft-bgs throughout the site. The depth of the groundwater indicates that some shallow water-bearing fractures are present in the bedrock. "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-05-03 12:53:00
Record Upd:	2021-05-03 12:53:00
Updated By:	JEBROWN
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Bruce Berg
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Bruce Berg
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported

BLOCK 417 NEW ROCHELLE (Continued) **S127478138**

Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bruce Berg
Owner Company:	RFMCH Huguenot Property Owner II LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bruce Berg
Owner Company:	RFMCH Huguenot Development Partners II LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

J68 **NORTH AVE REALITY** **NY LTANKS** **S103559119**
East **5 ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.084 mi.
442 ft. **Site 8 of 17 in cluster J**

Relative: LTANKS:
Higher

Name:	NORTH AVE REALITY
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8803214 / 1989-11-30
Facility ID:	8803214
Site ID:	68769
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

Actual:
90 ft.

NORTH AVE REALITY (Continued) **S103559119**

Remediation Phase:	0
Date Entered In Computer:	1988-07-28
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	YOSHIAKI KOWANISHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	281826
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K FAILED 4-GAL. PER HOUR"

All TTF:

Facility ID:	8803214
Spill Number:	8803214
Spill Tank Test:	1534286
Site ID:	68769
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68769
Operable Unit ID:	918394
Operable Unit:	01
Material ID:	458777
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	5 ANDERSON ST
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812584 / 1999-07-12
Facility ID:	9812584
Site ID:	68770
Spill Date:	1999-01-12

NORTH AVE REALITY (Continued) **S103559119**

Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	2003-07-01
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

All TTF:

Facility ID:	9812584
Spill Number:	9812584
Spill Tank Test:	1546738
Site ID:	68770
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68770
Operable Unit ID:	1069836
Operable Unit:	01
Material ID:	557973
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported

NORTH AVE REALITY (Continued) **S103559119**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	5 ANDERSON ST
Address:	5 ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812585 / 1999-07-12
Facility ID:	9812585
Site ID:	68771
Spill Date:	1999-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-01-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-12
Spill Record Last Update:	1999-09-07
Spiller Name:	YOSHIAKI KAWANISHA
Spiller Company:	5 ANDERSON ST
Spiller Address:	5 ANDERSON ST
Spiller County:	001
Spiller Contact:	YOSHIAKI KAWANISHA
Spiller Phone:	(914) 633-3708
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65455
DEC Memo:	""
Remarks:	"TESTED TANK, TANK FAILED."

All TTF:

Facility ID:	9812585
Spill Number:	9812585
Spill Tank Test:	1546739
Site ID:	68771
Tank Number:	2
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

NORTH AVE REALITY (Continued) **S103559119**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	68771
Operable Unit ID:	1069838
Operable Unit:	01
Material ID:	312860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J69 **CON EDISON** **RCRA NonGen / NLR** **1018281086**
East **230 NORTH AVE** **FINDS** **NYP004760179**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.084 mi.
442 ft. **Site 9 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150330
Handler Name:	CON EDISON	
Handler Address:		230 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004760179
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

CON EDISON (Continued) **1018281086**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150330
Handler Name:	CON EDISON

CON EDISON (Continued) **1018281086**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150330
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067687015

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281086
Registry ID:	110067687015
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067687015
Name:	CON EDISON
Address:	230 NORTH AVE

CON EDISON (Continued) **1018281086**

City,State,Zip: NEW ROCHELLE, NY 10801

J70 **CONCRETE FLOORING WITH CRACKS** **NY Spills** **S116554293**
East **230 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.084 mi.
442 ft. **Site 10 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

SPILLS:

Name:	CONCRETE FLOORING WITH CRACKS
Address:	230 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1400277 / 2018-07-10
Facility ID:	1400277
Facility Type:	ER
DER Facility ID:	448397
Site ID:	493512
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2014-04-08
Investigator:	JBODEE
Referred To:	WCDOH PBS
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2014-04-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2018-07-10
Spiller Name:	Not reported
Spiller Company:	STERLING SOLUTIONS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK LANZELLI
DEC Memo:	"4-9-14 Last night I traded voicemails with Jerry. He said that he didn't know anymore than provided to the Hotline and I should talk to Frank in the morning. This morning I spoke to Frank. Location has a 1500 gallon vaulted tank with a remote fill at curb. There is currently some oil in the basement sump. Sump is unplugged and it doesn't appear any was pumped out. Frank doesn't know where oil came from, but vault sounds inaccessible. Frank is trying to contact management company to let them know tank needs to be tested. Management Company: Sterling Solutions, 914/437-6245, Aurora is Almeada contact Owner: Milka Iwanow, 914/409-6513 jc 4/09/14: Email received this morning from Chris Lalak: Sebastian went to this one and will follow up. It is a block away from my office. The tank in a vaulted AST (1500 gallon from 1931). There is a spill across the floor and in cracks in the floor getting to a sump pump. The sump goes to the sanitary. The spill may have been going on for so time, the super was very vague. The AST is visible except for a small area

CONCRETE FLOORING WITH CRACKS (Continued) **S116554293**

Remarks: that sticks into the floor of the vault. The tank is not visibly leaking. Almeida replaced the underground lines with above ground lines recently. The between the tank, the former underground lines, and the sump is some distance and they will need to excavate the floor. The building has hired Dutchess. Pumping out the tank is not simple. The building has natural gas and oil. jod 04-09-14 followup email, After a second look at this one with a plumber,It looks like the old lines might be leaking. The plumber will uncover the old lines. The tank is not being pumped out at this time. The bottom of the tank is visible for the most part. (the plumber went in the vault, before we were there).Possibly, the remote fill is also an issue. They will replace the tank with an unregulated tank. Sebastian will continue to handle the spill. The floor will be opened up tomorrow to investigate. RDB 7/10/18: Email message received from Sebastian Bimonte of WCDoH: Can you NFA this one. The call from what I can remember was possible sheen in the sump pump located in the basement of an apartment building. As a precaution a section of the floor was excavated and a soil sample was retrieved. Soils below CP-51. *The sample results dated April 24 of 2014 show contamination levels below CP-51 except for the Xylenes which are slightly over the guidance. Municipal water and sewer in this area, WCDoH recommending NFA at this time. Sample results entered into D2 DecDocs. jod" "Caller advised unknown amount of oil spilled onto concrete floor with cracks. Clean up is pending."

All Materials:

Site ID:	493512
Operable Unit ID:	1243015
Operable Unit:	01
Material ID:	2243651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

J71 **CON EDISON** **NJ MANIFEST** **S120669791**
East **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
442 ft. **Site 11 of 17 in cluster J**

Relative: **Higher**
Actual: **90 ft.**

NJ MANIFEST:

EPA Id:	NYP004760179
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON (Continued) **S120669791**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091109JJK
EPA ID:	NYP004760179
Date Shipped:	3/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J72 **CON ED** **NY MANIFEST** **S118088454**
East **230 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.084 mi.
442 ft. **Site 12 of 17 in cluster J**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON ED
Address:	230 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004760179
Facility Status:	Not reported
Location Address 1:	OPP 230 NORTH AVE
Code:	BP
Location Address 2:	TM 3585
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760179
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2015
Trans1 Recv Date:	03/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760179
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091109JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118088454**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H73 **GOODRICH RUBBER 285 NORTH AVENUE SITE** **NY BROWNFIELDS** **S127282809**
NNE **285 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.087 mi.
459 ft. **Site 8 of 8 in cluster H**

Relative: **Lower**
Actual: **74 ft.**

BROWNFIELDS:

Name:	GOODRICH RUBBER 285 NORTH AVENUE SITE
Address:	285 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	615508
Acres:	0.930
HW Code:	C360212
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	01/06/2021
Record Updated Date:	02/25/2021
Update By:	AMOMOROG
Site Description:	"Site Location: The site is located at 285 North Avenue (formerly known at 277 North Avenue and 273 North Avenue), New Rochelle, New York 10801, Tax Parcel Identification No. 1-239-0033 (formerly known as Tax Parcel Identification Nos. 1-239-0029 and 1-239-0033). The site is located in a primarily commercial use neighborhood. Site Features: The site is currently contains a vacant three-story steel frame masonry block commercial office building on the northern portion of the site and a vacant one-story building with a two-story addition present on the southern portion of the site. Paved parking areas are found within the southeastern section of the property and off the northeastern and southeastern sides of the buildings. Current Zoning and Land Use: The site is currently located in the Downtown Mixed Use District. The on-site building was most recently used as

GOODRICH RUBBER 285 NORTH AVENUE SITE (Continued) **S127282809**

commercial office building. The last tenant was a bank in one portion of the building. The bank vacated the site in approximately March-April 2019 and the site is now vacant. The surrounding properties are primarily commercial with some residential uses. The site is located along the northeastern side of North Avenue in the City of New Rochelle, Westchester County, New York. A multi-story mixed use commercial and residential structure are located northeast of the property. To the southeast of the site, there is a restaurant, multi-tenanted retail and commercial office structure, and a United states Post Office. A Chase Bank office building is located to the southwest. Active below grade railway lines are located approximately 109 feet from the site to the north. The site is located approximately 500 feet from the New England Thruway (Interstate Route 95). Past Use of the Site: Historical usages of the site beginning in 1887 includes: a hotel, pavilion, stable(s), beer storage, saloon, restaurant(s), jewelers, tailors, upholsters, plumbing supply shop, machining company, filling station, auto repair garage, rubber vulcanization facility, a materials facility, dental practice, roofing and siding business, locksmith, and law firms. Several of these historical entities were located within two multi-tenanted commercial structures. The first building existed from the 1930s to 1975. The second was constructed in 1975 and presently exists on-site. Of particular relevance to the environmental investigation, from 1911 to the early 1930s, a rubber vulcanization (hardening) facility was present in the southern portion of the site. The facility was run by Westchester Rubber Works. The map noted that the facility has one small gas vulcanizer. In addition, in 1911, a W.F. Vernon Masons Materials facility was located on-site with newspaper articles stating that B.F. Goodrich took over the facility and operated it until the 1950s. It was noted to supply brick, cement, and lime. In 1951, a filling station and auto repair garage were also identified as present on-site. In 1972, Cornwall Automatic and Mawaco Machine Co. were noted as present on-site. Three underground storage tanks (UST) are associated with the site. A 3,000 gallon underground storage tank (UST) was registered on-site in 1930. The status of this UST is unknown. From 1975 to 2007, a 10,000 gallon UST existed on-site. This tank had failed several tightness tests which spurred the opening of NYSDEC Spill Nos. 8912285 in 1990, and 0611580, and 0611648 in 2007. The tank was eventually removed from the site in 2007 along with 356 tons of contaminated soil. The third tank is a 5,000 gallon UST which is currently present on-site. Site Geology and Hydrogeology: The site is approximately 80 feet above sea level. The topography of the area is level. Subsurface materials on the site consist of contaminated historic fill composed of sand with brick, gravel, asphalt, silt and concrete. The historic fill is present to a maximum depth of approximately 20 feet below ground surface (ft bgs). Along the perimeter of the site boundary, native sand with silt and gravel was present under the fill. Presumed weathered bedrock was encountered at depths ranging from 9 to 19 ft bgs. Groundwater was encountered during the subsurface investigation at depths ranging from approximately 13 to 17 ft bgs. Groundwater is assumed to flow in an easterly direction towards Echo Bay approximately 2,500 feet away. "

Env Problem: "Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."

Health Problem: "Information submitted with the BCP application regarding the

GOODRICH RUBBER 285 NORTH AVENUE SITE (Continued) **S127282809**

	conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Casey Fisher
Owner Company:	277 NR Principal LLC
Owner Address:	c/o Fisher Development Associates, LLC
Owner Addr2:	7 penn Plaza, Suite 1400
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Casey Fisher
Owner Company:	277 NR Principal LLC
Owner Address:	c/o Fisher Development Associates, LLC
Owner Addr2:	7 penn Plaza, Suite 1400
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

74
WNW
< 1/8
0.087 mi.
460 ft.

ST GABRIEL'S CHURCH
120 DIVISION ST
NEW ROCHELLE, NY

NY Spills **S125360094**
N/A

Relative:
Higher

Actual:
93 ft.

SPILLS:

Name:	ST GABRIEL'S CHURCH
Address:	120 DIVISION ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1906243 / 2020-04-01
Facility ID:	1906243
Facility Type:	ER
DER Facility ID:	544249
Site ID:	594314
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2019-09-17
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2019-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-17
Spill Record Last Update:	2020-04-01
Spiller Name:	TIM ROFF
Spiller Company:	ST GABRIEL'S CHURCH
Spiller Address:	120 DIVISION ST
Spiller Company:	999
Contact Name:	TIM ROFF
DEC Memo:	"9/17/19 Church had tank removed last week (PBS site), temp tank installed. Temp tank expanded from heat, spilling 7 gallons oil to secondary containment (metal dike with metal floor around tank) and 3 gallons to asphalt. No waterways, drains, soil, or grass impacted. New Rochelle Fire Dept. put down speedy dry, Metro Env. drummed used absorbents & debris for disposal, reports to follow. ga 1/28/20: Tank removal was reported as Spill 1903323. Report submitted under that case number. This was a 10 gallons spill from a temp AST. Cleanup was completed the same day. jod"
Remarks:	"Over explansion of above ground storage tank caused spill into containment and some on blacktop outside of containment. Cleanup is underway."

All Materials:

Site ID:	594314
Operable Unit ID:	1341883
Operable Unit:	01
Material ID:	2351864
Material Code:	0001A
Material Name:	#2 fuel oil

ST GABRIEL'S CHURCH (Continued) **S125360094**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

G75 **COMM/RESIDENT. PROPERTY** **NY LTANKS** **S101341321**
SSE **15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.088 mi.
463 ft. **Site 3 of 5 in cluster G**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Name:	COMM/RESIDENT. PROPERTY
Address:	15 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9405558 / 2005-02-10
Facility ID:	9405558
Site ID:	119901
Spill Date:	1994-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104134
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. Tank taken out of service by Royal Environmental. "
Remarks:	"TANK TEST ON 7/21/94"

All TTF:

Facility ID:	9405558
Spill Number:	9405558

COMM/RESIDENT. PROPERTY (Continued) **S101341321**

Spill Tank Test:	1542973
Site ID:	119901
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	119901
Operable Unit ID:	1002771
Operable Unit:	01
Material ID:	382138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

J76 **NEW ROCHELLE PUBLIC LIBR.** **NY LTANKS** **S100177858**
ESE **MEMORIAL HIGHWAY** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.091 mi.
482 ft. **Site 13 of 17 in cluster J**

Relative:
Higher

Actual:
93 ft.

LTANKS:

Name:	NEW ROCHELLE PUBLIC LIBR.
Address:	MEMORIAL HIGHWAY
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9111450 / 1992-02-06
Facility ID:	9111450
Site ID:	306853
Spill Date:	1992-02-06
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported

NEW ROCHELLE PUBLIC LIBR. (Continued) **S100177858**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247822
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SOME ON PAVEMENT,SOME IN STORM DRAIN F.D.HAZMAT USED SORBENT TO CONTAIN AND VENTED BUILING SPOKE WITH DEP. CHIEF STONE"

All Materials:

Site ID:	306853
Operable Unit ID:	965176
Operable Unit:	01
Material ID:	416486
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I77 **CON EDISON** **RCRA NonGen / NLR** **1014398803**
SSW **HUGUENOT ST & CENTRE ST** **NYP004211728**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
515 ft. **Site 5 of 24 in cluster I**

Relative: **Higher**
Actual: **96 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON	
Handler Address:		HUGUENOT ST & CENTRE ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004211728
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

CON EDISON (Continued) **1014398803**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON (Continued) **1014398803**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20100719
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

I78 **CON EDISON** **NY MANIFEST** **S117319603**
SSW **CENTER & HUGUENOT** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.098 mi.
515 ft. **Site 6 of 24 in cluster I**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	CENTER & HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004676839
Facility Status:	Not reported
Location Address 1:	CENTER & HUGUENOT
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004676839
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2014
Trans1 Recv Date:	10/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004676839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770954JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117319603**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I79 **CON EDISON** **NY MANIFEST** **S113917500**
SSW **CENTRE AVE & HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
515 ft. **Site 7 of 24 in cluster I**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	CENTRE AVE & HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004332961
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & HUGUENOT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004332961
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S113917500**

Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2013
Trans1 Recv Date: 07/22/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004332961
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011695949JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

I80 **CON EDISON** **NY MANIFEST** **S117535592**
SSW **HUGENOT & CENTRE ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
515 ft. **Site 8 of 24 in cluster I**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT & CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004677530
Facility Status:	Not reported
Location Address 1:	HUGENOT & CENTRE ST
Code:	BP
Location Address 2:	MH 1230
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677530
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677530
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774876JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117535592**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J81 **CVS PHARMACY #8447** **RCRA-VSQG 1014958220**
East **222 NORTH AVE** **NY MANIFEST NYR000194654**
< 1/8 **NEW ROCHELLE, NY 10801**
0.098 mi.
518 ft. **Site 14 of 17 in cluster J**

Relative: **Higher**
Actual: **91 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20210222
Handler Name:	CVS PHARMACY #8447	
Handler Address:		222 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYR000194654
Contact Name:		NICOLE WILKINSON
Contact Address:		CVS DR MC2340
Contact City,State,Zip:		WOONSOCKET, RI 02895
Contact Telephone:		401-770-7132
Contact Fax:		401-652-1901
Contact Email:		NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:		DIRECTOR, CORPORATE ENVIRONMENTAL
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2020
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		CVS DR MC2340
Mailing City,State,Zip:		WOONSOCKET, RI 02895
Owner Name:		45 SOUTH MAIN STREET CORP
Owner Type:		Private

CVS PHARMACY #8447 (Continued) **1014958220**

Operator Name:	CVS ALBANY, LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210222
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CVS PHARMACY #8447 (Continued) **1014958220**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D003
Waste Description: REACTIVE WASTE

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

CVS PHARMACY #8447 (Continued) **1014958220**

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110730
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	11 GLEN OAKS DR
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	917-757-4922
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	NOT APPLICABLE
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110730
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	NOT APPLICABLE
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110730
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY LLC
Legal Status:	Private
Date Became Current:	20110730
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	11 GLEN OAKS DR
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	917-757-4922
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY, L.L.C.
Legal Status:	Private
Date Became Current:	20110730

CVS PHARMACY #8447 (Continued) **1014958220**

Date Ended Current:	Not reported
Owner/Operator Address:	11 GLEN OAKS DRIVE
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	NOT APPLICABLE
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CVS ALBANY, LLC
Legal Status:	Private
Date Became Current:	20110730
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR MC2340
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	45 SOUTH MAIN STREET CORP
Legal Status:	Private
Date Became Current:	20110120
Date Ended Current:	Not reported
Owner/Operator Address:	11 GLEN OAKS DRIVE
Owner/Operator City,State,Zip:	RYE, NY 10580
Owner/Operator Telephone:	917-757-4922
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140317
Handler Name: CVS PHARMACY #8447	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CVS PHARMACY #8447 (Continued) **1014958220**

Receive Date: 20160317
Handler Name: CVS PHARMACY #8447
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210222
Handler Name: CVS PHARMACY #8447
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20120305
Handler Name: CVS PHARMACY #8447
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130701
Handler Name: CVS PHARMACY #8447
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190408
Handler Name: CVS PHARMACY #8447
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

CVS PHARMACY #8447 (Continued) **1014958220**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CVS PHARMACY #8447
Address:	222 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000194654
Facility Status:	Not reported
Location Address 1:	222 NORTH AVE.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000194654
Mailing Name:	CVS PHARMACY #8447
Mailing Contact:	CVS PHARMACY #8447
Mailing Address 1:	222 NORTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146377591

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MNS000110924
Trans2 State ID:	NJD054126164

CVS PHARMACY #8447 (Continued) **1014958220**

Generator Ship Date:	12/30/2013
Trans1 Recv Date:	12/30/2013
Trans2 Recv Date:	01/13/2014
TSD Site Recv Date:	01/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	005855377FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	P001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K82 **DELUXE TAXI** **NY UST** **U001736524**
North **10 STATION PLAZA** **N/A**
< 1/8 **NEW ROCHELLE - WESCHESTER, NY 10801**
0.099 mi.
523 ft. **Site 1 of 10 in cluster K**

Relative: UST:
Lower

Actual:
77 ft.

Name:	DELUXE TAXI
Address:	10 STATION PLAZA
City,State,Zip:	NEW ROCHELLE - WESCHESTER, NY 10801
Id/Status:	2-601600 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

DELUXE TAXI (Continued) **U001736524**

UTM X: 566353.87500
UTM Y: 4486105.00000
Site Type: Unknown

Affiliation Records:

Site Id: 23562
Affiliation Type: Emergency Contact
Company Name: 8 RAILROAD PLACE CORP.
Contact Type: Not reported
Contact Name: JOHN TENORE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 632-2108
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23562
Affiliation Type: Facility Operator
Company Name: DELUXE TAXI
Contact Type: Not reported
Contact Name: ROCHELLE DELUXE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 636-7777
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23562
Affiliation Type: Mail Contact
Company Name: 8 RAILROAD PLACE CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 8 STATION PLAZA SOUTH
Address2: Not reported
City: NEW ROCHELLE
State: NY
Zip Code: 10801
Country Code: 001
Phone: (914) 636-7777
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23562
Affiliation Type: Facility Owner

DELUXE TAXI (Continued) **U001736524**

Company Name:	8 RAILROAD PLACE CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	8 STATION PLAZA SOUTH
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10801
Country Code:	001
Phone:	(914) 636-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47103
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	05/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

I83 **CEMENT COURT YARD** **NY Spills** **S104282704**
SSW **54 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.100 mi.
530 ft. **Site 9 of 24 in cluster I**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Name:	SPILL NUMBER 9804849
Address:	54 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9804849 / 2002-07-15
Facility ID:	9804849
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114515
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-07-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-18
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-18
Spill Record Last Update:	2002-07-15
Spiller Name:	Not reported
Spiller Company:	NABER REALTY INC
Spiller Address:	BOX 156H
Spiller Company:	001
Contact Name:	CAPT DIMEGLIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"fd called to an odor of fuel oil in a residence- upon arrival in basement it appeared were working on the oil boiler and were pumping product into sewer thru sump pumps"

All Materials:

Site ID:	114515
Operable Unit ID:	1065894
Operable Unit:	01
Material ID:	319611
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CEMENT COURT YARD (Continued) **S104282704**

Name:	CEMENT COURT YARD
Address:	54 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908117 / 1999-10-04
Facility ID:	9908117
Facility Type:	ER
DER Facility ID:	99871
Site ID:	114516
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-10-04
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1999-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-04
Spill Record Last Update:	1999-10-06
Spiller Name:	Not reported
Spiller Company:	CEMENT COURT YARD
Spiller Address:	54 CENTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 10/4/99 SPILLER CLEANED UP. NFA"
Remarks:	"BLDG SUPER OVERORDERED - CLEANED UP"

All Materials:

Site ID:	114516
Operable Unit ID:	1082403
Operable Unit:	01
Material ID:	555958
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	6.00
Oxygenate:	Not reported

I84 **APARTMENT BLDG** **NY LTANKS** **S105996855**
SSW **54 CENTRE AV** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.100 mi.
530 ft. **Site 10 of 24 in cluster I**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	54 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403405 / 2004-12-10
Facility ID:	0403405
Site ID:	84302
Spill Date:	2004-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-06-29
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-29
Spill Record Last Update:	2004-12-10
Spiller Name:	BASSAM MABER
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AVE
Spiller County:	001
Spiller Contact:	BASSAM MABER
Spiller Phone:	(914) 645-6420
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77542
DEC Memo:	"12/10/04 PBS facility. Tank passed a retest after piping was repaired. Spill file closed by Danielle Jackson of the Westchester County Health Dept. No further action is required at this time. jbo"
Remarks:	"Tank Test Failure. Reccommend Retest."

All TTF:

Facility ID:	0403405
Spill Number:	0403405
Spill Tank Test:	1529391
Site ID:	84302
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

APARTMENT BLDG (Continued) **S105996855**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84302
Operable Unit ID:	886824
Operable Unit:	01
Material ID:	490990
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APARTMENT BLDG
Address:	54 CENTRE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0206558 / 2005-02-27
Facility ID:	0206558
Site ID:	254563
Spill Date:	2002-09-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-09-24
CID:	390
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2005-02-27
Spiller Name:	ENERITO GONZALEZ
Spiller Company:	APARTMENT BLDG
Spiller Address:	54 CENTRE AV
Spiller County:	001
Spiller Contact:	ENERITO GONZALEZ
Spiller Phone:	(914) 309-2775
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208499
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 2/27/05 #4 overfill to surface--close "
Remarks:	"spill was noticed on 9/6 - unk when it occurred"

APARTMENT BLDG (Continued) **S105996855**

All Materials:

Site ID:	254563
Operable Unit ID:	858169
Operable Unit:	01
Material ID:	517160
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I85 **SEASONWEIN MANAGEMENT LLC** **NY UST** **U003994353**
SSW **54 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.100 mi.
530 ft. **Site 11 of 24 in cluster I**

Relative: **Higher**
Actual: **98 ft.**

WESTCHESTER CO. UST:

Name:	SEASONWEIN MANAGEMENT LLC
Address:	54 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-169773 / Active
Operator Name:	Matt Seasonwein
Owner Name:	Seasonwein Management LLC
Owner Street:	300 Gramatan Avenue
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10552
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1928
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

G86 **RPM REALTY INC** **NY AST** **A100412045**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
538 ft. **Site 4 of 5 in cluster G**

Relative: **Higher**
Actual: **99 ft.**

WESTCHESTER CO. AST:

Name:	RPM REALTY INC
Address:	9-15 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-166189
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City/State/Zip:	Katonah, NY 10536
Tank Number:	2
Status:	1. In-Service
Date Installation:	06/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

G87 **RPM REALTY INC** **NY UST** **U004240676**
SSE **9-15 DIVISION STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.102 mi.
538 ft. **Site 5 of 5 in cluster G**

Relative: **Higher**
Actual: **99 ft.**

WESTCHESTER CO. UST:

Name:	RPM REALTY INC
Address:	9-15 DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-166189 / Active
Operator Name:	Gary Garafolo
Owner Name:	RPM Realty Inc.
Owner Street:	PO Box 817
Owner Address2:	Not reported
Owner City:	Katonah
Owner State:	NY
Owner Zipcode:	10536
GDS Number:	Not reported

RPM REALTY INC (Continued) **U004240676**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	Not reported
Date Perm Closure:	06/17/1997
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

I88 **CENTRE AVENUE DEVELOPMENT - SOUTH** **NY BROWNFIELDS** **S127990256**
SSW **33-35 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
555 ft. **Site 12 of 24 in cluster I**

Relative: **Higher**

Actual: **92 ft.**

BROWNFIELDS:

Name:	CENTRE AVENUE DEVELOPMENT - SOUTH
Address:	33-35 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	580085
Acres:	0.459
HW Code:	C360182
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/03/2018
Record Updated Date:	12/27/2021
Update By:	AMSERVIS
Site Description:	"Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above.

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

Env Problem:

"Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

	1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "
Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-03-12 08:16:00
Record Upd:	2021-09-02 12:50:00
Updated By:	MDKILMER
Own Op:	1
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Daniel Hollander
Owner Company:	Huguenot Partners LLC
Owner Address:	c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Development Partners LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	Huguenot Centre Holdings, LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
HW Code:	C360182
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

Waste Code:	Not reported
HW Code:	C360182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,4-dioxane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,2-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

HW Code:	C360182
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cyanides(soluble cyanide salts)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	PCB aroclor 1262
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	601703563
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-07-06 11:28:00
Record Updated:	2021-07-06 11:28:00
Updated By:	MDKILMER
Crossref ID:	C360182-06-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-02 17:00:00
Record Updated:	2020-10-02 17:00:00
Updated By:	MDKILMER
Crossref ID:	06/28/2019

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990256**

Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-02 16:59:00
Record Updated:	2020-10-02 16:59:00
Updated By:	MDKILMER

I89 **CENTRE AVENUE DEVELOPMENT - SOUTH** **NY INST CONTROL** **S127990308**
SSW **33-35 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
555 ft. **Site 13 of 24 in cluster I**

Relative:
Higher

Actual:
92 ft.

INST CONTROL:

Name:	CENTRE AVENUE DEVELOPMENT - SOUTH
Address:	33-35 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	580085
Control Name:	IC/EC Plan
HW Code:	C360182
Control Code:	34
Control Type:	INST
Dt record added:	09/02/2021
Dt rec updated:	12/27/2021
Updated By:	JEBROWN
Site Code:	580085
Site Description:	"Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "

Health Problem: "Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Dell: Not reported
Record Add: 2019-03-12 08:16:00
Record Upd: 2021-09-02 12:50:00
Updated By: MDKILMER
Own Op: 1
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Daniel Hollander
Owner Company: Huguenot Partners LLC
Owner Address: c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10013
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Development Partners LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: Huguenot Centre Holdings, LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
HW Code: C360182
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	mercury

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,4-dioxane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,2-dichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cyanides(soluble cyanide salts)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: toluene
Waste Quantity: UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Code: Not reported
HW Code: C360182
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: PCB aroclor 1262
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 601703563
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-07-06 11:28:00
Record Updated: 2021-07-06 11:28:00
Updated By: MDKILMER
Crossref ID: C360182-06-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:00:00
Record Updated: 2020-10-02 17:00:00
Updated By: MDKILMER
Crossref ID: 06/28/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 16:59:00
Record Updated: 2020-10-02 16:59:00
Updated By: MDKILMER

Name: CENTRE AVENUE DEVELOPMENT - SOUTH
Address: 33-35 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 580085
Control Name: Site Management Plan
HW Code: C360182
Control Code: 32
Control Type: INST
Dt record added: 09/02/2021

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Dt rec updated: 12/27/2021
Updated By: JEBROWN
Site Code: 580085
Site Description: "Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "
Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4’-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4’-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4’-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application.
Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "

Health Problem: "Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-03-12 08:16:00
Record Upd: 2021-09-02 12:50:00
Updated By: MDKILMER
Own Op: 1
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Sub Type: P03
Owner Name: Daniel Hollander
Owner Company: Huguenot Partners LLC
Owner Address: c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10013
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Development Partners LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: Huguenot Centre Holdings, LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
HW Code: C360182
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: perfluorooctanoic acid

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: Perfluorooctane Sulfonate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,4-dioxane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,2-dichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Code: Not reported
HW Code: C360182
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cyanides(soluble cyanide salts)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: PCB aroclor 1262
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

HW Code: C360182
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 601703563
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-07-06 11:28:00
Record Updated: 2021-07-06 11:28:00
Updated By: MDKILMER
Crossref ID: C360182-06-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:00:00
Record Updated: 2020-10-02 17:00:00
Updated By: MDKILMER
Crossref ID: 06/28/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 16:59:00
Record Updated: 2020-10-02 16:59:00
Updated By: MDKILMER

Name: CENTRE AVENUE DEVELOPMENT - SOUTH
Address: 33-35 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 580085
Control Name: Monitoring Plan
HW Code: C360182
Control Code: 31
Control Type: INST
Dt record added: 09/02/2021
Dt rec updated: 12/27/2021
Updated By: JEBROWN
Site Code: 580085
Site Description: "Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above.

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

	1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "
Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-03-12 08:16:00
Record Upd:	2021-09-02 12:50:00
Updated By:	MDKILMER
Own Op:	1
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Daniel Hollander
Owner Company:	Huguenot Partners LLC
Owner Address:	c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Development Partners LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	Huguenot Centre Holdings, LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
HW Code: C360182
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Code: Not reported
HW Code: C360182
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: Perfluorooctane Sulfonate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,4-dioxane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,2-dichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

HW Code: C360182
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cyanides(soluble cyanide salts)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: PCB aroclor 1262
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 601703563
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-07-06 11:28:00
Record Updated: 2021-07-06 11:28:00
Updated By: MDKILMER
Crossref ID: C360182-06-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:00:00
Record Updated: 2020-10-02 17:00:00
Updated By: MDKILMER
Crossref ID: 06/28/2019

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 16:59:00
Record Updated: 2020-10-02 16:59:00
Updated By: MDKILMER

Name: CENTRE AVENUE DEVELOPMENT - SOUTH
Address: 33-35 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 580085
Control Name: Ground Water Use Restriction
HW Code: C360182
Control Code: 08
Control Type: INST
Dt record added: 09/02/2021
Dt rec updated: 12/27/2021
Updated By: JEBROWN
Site Code: 580085
Site Description: "Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

and flows to the south-southwest. "

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "

Health Problem: "Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-03-12 08:16:00
Record Upd: 2021-09-02 12:50:00
Updated By: MDKILMER
Own Op: 1
Sub Type: P03

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Daniel Hollander
Owner Company: Huguenot Partners LLC
Owner Address: c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10013
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Development Partners LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: Huguenot Centre Holdings, LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
HW Code: C360182
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Code: Not reported
HW Code: C360182
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: Perfluorooctane Sulfonate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

HW Code: C360182
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,4-dioxane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,2-dichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cyanides(soluble cyanide salts)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: PCB aroclor 1262
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 601703563
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-07-06 11:28:00
Record Updated: 2021-07-06 11:28:00
Updated By: MDKILMER
Crossref ID: C360182-06-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:00:00
Record Updated: 2020-10-02 17:00:00
Updated By: MDKILMER
Crossref ID: 06/28/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 16:59:00
Record Updated: 2020-10-02 16:59:00
Updated By: MDKILMER

Name: CENTRE AVENUE DEVELOPMENT - SOUTH
Address: 33-35 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 580085
Control Name: Environmental Easement
HW Code: C360182
Control Code: J
Control Type: INST
Dt record added: 09/02/2021
Dt rec updated: 12/27/2021
Updated By: JEBROWN
Site Code: 580085
Site Description: "Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4’-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4’-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4’-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "

Health Problem: "Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-03-12 08:16:00
Record Upd: 2021-09-02 12:50:00
Updated By: MDKILMER
Own Op: 1
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Daniel Hollander
Owner Company: Huguenot Partners LLC
Owner Address: c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10013

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Development Partners LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: Huguenot Centre Holdings, LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Louis Cappelli
Owner Company: RFMCH Huguenot Property Owner LLC
Owner Address: 7 Renaissance Square, 4th Floor
Owner Addr2: Not reported
Owner City,St,Zip: White Plains, NY 10601
Owner Country: United States of America
HW Code: C360182
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

HW Code:	C360182
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,4-dioxane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,2-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: DDD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: cyanides(soluble cyanide salts)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: PCB aroclor 1262
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360182
Waste Type: 1,1-dichloroethene

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990308**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 601703563
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-07-06 11:28:00
Record Updated: 2021-07-06 11:28:00
Updated By: MDKILMER
Crossref ID: C360182-06-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:00:00
Record Updated: 2020-10-02 17:00:00
Updated By: MDKILMER
Crossref ID: 06/28/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 16:59:00
Record Updated: 2020-10-02 16:59:00
Updated By: MDKILMER

I90 **CENTRE AVENUE DEVELOPMENT - SOUTH - OFF-SITE** **NY BROWNFIELDS** **S123658091**
SSW **33 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
555 ft. **Site 14 of 24 in cluster I**

Relative: **Higher**

Actual: **92 ft.**

BROWNFIELDS:
Name: CENTRE AVENUE DEVELOPMENT - SOUTH - OFF-SITE
Address: 33 CENTRE AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Program: BCP
Site Code: 603948
Acres: Not reported
HW Code: C360182A
SWIS: 6010
Town: New Rochelle (c)
Record Added Date: 04/15/2020
Record Updated Date: 07/28/2021
Update By: KABROWNE
Site Description: "Location: The site is located in the area surrounding the Brownfield Cleanup Site Centre Ave Development South (C360182) at 33 Centre Avenue in the City of New Rochelle, Westchester County. Site Features: The area includes multi story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The State Superfund Site Industrial Overall Services Corp (Site No. 360109) state Superfund site is located adjacent to and west of the off site area. Current Zoning and Land Use: The off site area includes the Downtown Business (DB) and Light Industry (LI) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above only. Permitted principal uses of LI districts include manufacturers, offices, medical facilities and parking garages. Past Use of the Site: The off site area has documented impacts in the groundwater from plumes originating from the BCP site Centre Ave Development South (C360182) with the historic use of 1,1,1 TCA in electroplating operations. PCE and its breakdown products are also found in off site groundwater emanating from the SSF site Industrial

CENTRE AVENUE DEVELOPMENT - SOUTH - OFF-SITE (Continued) **S123658091**

	Overall Services Corp (360109). Site Geology and Hydrogeology: Site soil at the Centre Avenue Development South site consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material is underlain by fine to silty sand followed by a 6 12 inch layer of weathered (decomposed) rock overlying the bedrock. Groundwater underlying the site is present only in bedrock and flows to the south southwest. Groundwater is present at depth between 5 to 15 feet bgs across the site. "
Env Problem:	"Off-site results will be made available once the investigation is complete."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	C360182A
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	1,4-dioxane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH - OFF-SITE (Continued) **S123658091**

Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	1,1,2-trichlorethylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182A
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

I91 **CENTRE AVENUE DEVELOPMENT - SOUTH** **NY ENG CONTROLS** **S127990292**
SSW **33-35 CENTRE AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
555 ft. **Site 15 of 24 in cluster I**

Relative:
Higher

Actual:
92 ft.

ENG CONTROLS:

Name:	CENTRE AVENUE DEVELOPMENT - SOUTH
Address:	33-35 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	580085
HW Code:	C360182
Control Code:	12
Control Type:	ENG
Date Record Added:	09/02/2021
Date Rec Updated:	12/27/2021
Updated By:	JEBROWN
Site Description:	"Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail,

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

	groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "
Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-03-12 08:16:00
Record Upd:	2021-09-02 12:50:00
Updated By:	MDKILMER
Own Op:	1
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Daniel Hollander
Owner Company:	Huguenot Partners LLC
Owner Address:	c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Development Partners LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	Huguenot Centre Holdings, LLC
Owner Address:	7 Renaissance Square, 4th Floor

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
HW Code:	C360182
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dibenz[a,h]anthracene

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,4-dioxane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,2-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	copper
Waste Quantity:	UNKNOWN

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cyanides(soluble cyanide salts)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	PCB aroclor 1262
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	601703563
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-07-06 11:28:00
Record Updated:	2021-07-06 11:28:00
Updated By:	MDKILMER
Crossref ID:	C360182-06-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-02 17:00:00
Record Updated:	2020-10-02 17:00:00
Updated By:	MDKILMER

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Crossref ID:	06/28/2019
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-02 16:59:00
Record Updated:	2020-10-02 16:59:00
Updated By:	MDKILMER
Name:	CENTRE AVENUE DEVELOPMENT - SOUTH
Address:	33-35 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	580085
HW Code:	C360182
Control Code:	36
Control Type:	ENG
Date Record Added:	09/02/2021
Date Rec Updated:	12/27/2021
Updated By:	JEBROWN
Site Description:	"Location: The site is located in the City of New Rochelle, Westchester County, New York at 33-35 Centre Avenue on a 0.46-acre lot. The site is located on the northern part of the city block bordered by Centre Avenue to the north, Huguenot Street to the east, Columbus Avenue to the south, and Relyea Place to the west. The site is bordered to the south by multi-story residential and commercial buildings. The site is approximately 1 mile west of Echo Bay. The Industrial Overall Services Corp. (Site No. 360109) State Superfund site is located just to the west of the site (downgradient), on the other side of Reylea Place. Site Features: The site is currently being developed into a multi-story residential building and construction of the building began in July 2020, after all soil above bedrock was removed from the site as part of an Interim Remedial Measure (IRM) completed under the BCP. Current Zoning and Land Use: The site is located within the Downtown Business (DB) (eastern portion) and Light Industry (LI) (western portion) zoning districts. Permitted principal uses of DB districts include stores, retail, offices, and residential units located on the second floor and above. Permitted principal uses of LI districts include manufacturing, offices, medical facilities and parking garages. The current zoning designation is consistent with the proposed development. Past Use of the Site: The site has been used for various residential, commercial and industrial purposes since the 1930s. Starting in 1971, the western half of the site was used as an electroplating and metal-finishing business and the eastern half of the site was used as a parking lot. Industrial operations ceased in December 2018. Site Geology and Hydrogeology: Site soils consisted of historic fill across the site from grade surface to depths ranging from 1 to 7.5 feet below grade surface (ft bgs). Historic fill was generally deeper on the eastern portion of the site. Historic fill predominately consisted of brown and black sand with varying amounts of gravel, brick, organic material, asphalt, metal and clay with an average fill depth of approximately 5 ft bgs across the Site. The fill material was underlain by fine to silty sand followed by a 6 to 12-inch layer of weathered (decomposed) rock overlying the bedrock. All soil was removed from the site as part of an IRM. Bedrock beneath the site consists of metamorphic rock containing high angle features capable of transporting groundwater to depths of at least 70 feet below the top of bedrock. Groundwater underlying the site is present in bedrock and flows to the south-southwest. "

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Env Problem: "Remediation at the site is partially complete. Remedial actions thus far have successfully achieved soil cleanup objectives for unrestricted use. Implementation of In-Situ Chemical Oxidation and In-Situ Treatment using Activated Carbon have resulted in a decrease in contaminant concentrations in groundwater. Groundwater will be monitored during the Site Management phase of the project. Groundwater will be monitored until residual concentrations of groundwater contaminants are below groundwater standards, or there is a bulk reduction to asymptotic levels acceptable to the Department. If concentrations of groundwater contaminants do not decrease to levels that are acceptable to the Department, contingent remedial actions may be required which could include in-situ chemical reduction or groundwater extraction and treatment. Prior to remediation, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in groundwater, and VOCs in soil vapor. Prior to Completion of partial Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, cyanide, and the emerging contaminants per-and poly fluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, PCBs, pesticides, metals, and cyanide in soil, VOCs, metals and the emerging contaminants PFAS and 1,4-dioxane in the groundwater, and VOCs in soil vapor. Soil - A total of 36 soil samples were collected during the remedial investigation from 19 borings extending to bedrock across the site. Several constituents were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs). The following is a list of those compounds and the maximum exceedance: trichloroethene (TCE) 0.92 parts per million (ppm) vs USCO of 0.47 ppm, benzo(a)anthracene 64 ppm vs USCO of 1 ppm, benzo(a)pyrene 56 ppm vs USCO of 1 ppm, benzo(k)fluoranthene 25 ppm vs USCO of 0.8 ppm, benzo(b)fluoranthene 69 ppm vs USCO of 1 ppm, chrysene 61 ppm vs USCO of 1 ppm, dibenzo(a,h)anthracene 8.6 ppm vs USCO of 0.33 ppm, fluoranthene 120 ppm vs USCO of 100 ppm, indeno(1,2,3-cd)pyrene 36 ppm vs USCO of 0.5 ppm, pyrene 120 ppm vs USCO of 100 ppm, barium 416 ppm vs USCO of 350 ppm, copper 396 ppm vs USCO of 50 ppm, lead 357 ppm vs USCO of 63 ppm, mercury 2.54 ppm vs USCO of 0.18 ppm, nickel 1600 ppm vs USCO of 30 ppm, zinc 254 ppm vs USCO of 109 ppm, 4,4'-DDE 0.134 ppm vs USCO of 0.0033 ppm, 4,4'-DDD 0.156 ppm vs USCO of 0.0033 ppm, 4,4'-DDT 0.521 ppm vs USCO of 0.0033 ppm, chlordane 0.186 ppm vs USCO of 0.094 ppm, dieldrin 0.0234 ppm vs USCO of 0.005 ppm, PCBs 0.11 ppm vs USCO of 0.1 ppm, and cyanide 74 ppm vs USCO of 27 ppm. Emerging contaminants were detected in soil samples collected from the site. The emerging contaminant 1,4-dioxane was detected in one sample at a concentration of 16 parts per billion (ppb). Perfluorooctanesulfonic acid (PFOS) was detected in 22 out of 30 samples collected throughout the site with a maximum concentration of 21.8 ppb. Perfluorooctanoic acid (PFOA) was detected in 6 out of 30 samples collected throughout the site with a maximum concentration of 1.52 ppb. Concentrations of PFAS in soil were generally higher on the western half of the site compared to the eastern half of the site. All on-site soils were excavated down to the bedrock surface and transported off-site for disposal as part of a soil removal IRM. Therefore, following the IRM, there are no soils remaining that exceed the USCOs. There is no

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

indication that soil contamination extends off-site. Groundwater - A total of nine groundwater wells were installed in bedrock throughout the site prior to the IRM. A non-aqueous phase liquid (NAPL) was encountered in one well on the east half of the site. This NAPL was again encountered during the IRM at the weathered bedrock interface and sampled. Fingerprinting results indicated that the NAPL was characteristic of a highly degraded petroleum. No further evidence of the NAPL was observed on the eastern half of the site after the removal of the affected bedrock and liquids encountered. Prior to the IRM, groundwater samples were collected from monitoring wells and analyzed for VOCs, SVOCs, PCBs, pesticides, metals and cyanide as well as the emerging contaminants PFAS and 1,4-dioxane. No PCBs or cyanide were detected in any groundwater samples. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, benzo(b)fluoranthene, chrysene, and phenol; the metals chromium, iron, manganese, magnesium, and nickel; and the pesticide dieldrin were detected in at least one groundwater sample in exceedance of groundwater standards. The locations where elevated SVOCs were noted in groundwater do not coincide with locations where elevated SVOCs were noted in soil, which suggests that the PAHs may be present in the dissolved phase. The concentrations of sodium, iron, manganese, magnesium appear to be background levels with no distinction between upgradient and downgradient monitoring wells. These compounds are typically naturally occurring or related to road salt application. Nickel and chromium, which may have been used during the electroplating process, were detected at maximum concentrations of 12,970 ppb versus a groundwater standard of 100 ppb, and 7,937 ppb versus a groundwater standard of 50 ppb, respectively. The pesticide dieldrin was only detected in one well at 0.005 ppb, marginally exceeding the groundwater standard of 0.004 ppb. The chlorinated VOCs PCE, TCE and 1,1,1-TCA, and their respective degradation byproducts, were detected in groundwater samples collected from the western half of the site in exceedance of groundwater standards and at levels suggesting the presence of separate phase material. The VOC toluene was also detected in exceedance of groundwater standards in the western half of the site and xylene (22 ppb) on the eastern half of the site in one sample. The highest concentrations of VOCs encountered at the site were for TCE (3,400 ppb), 1,1,1-TCA (1,000,000 ppb), 1,1-dichloroethene (28,000 ppb), and toluene (7,200 ppb) compared to a groundwater standard of 5 ppb for each of these constituents. Chlorinated VOCs were not detected in groundwater samples collected from the eastern half of the site. 1,4-dioxane, a contaminant (stabilizer) typically associated with 1,1,1-TCA, was detected at concentrations up to 320 ppb in groundwater samples, where elevated levels of chlorinated VOCs were also encountered on the western half of the site. For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 796 and 3,140 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. PFAS concentrations in groundwater were approximately an order of magnitude higher on the western half of the site compared to the eastern half of the site. VOC, PFAS, and 1,4-dioxane groundwater contamination is migrating off-site in the direction of groundwater flow to the southwest. The off-site groundwater plumes from this site are comingled with groundwater plumes emanating from the Industrial Overall Services Corp. (Site No. 360109) State Superfund site. The Industrial Overall Services Corp. site is located just to the west of

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

the site on the other side of Relyea Place. No private or municipal drinking water wells are within 0.5 miles of the site, and Chapter 873, article VII of the Laws of Westchester County, prohibits potable use of groundwater without prior approval. A supplemental remedial investigation (SRI-1) was conducted following the IRM to determine the nature and extent of contamination in bedrock groundwater. The SRI-1 consisted of the geophysical logging at ten locations and the installation of sixteen monitoring wells screened at depths ranging from 75 to 27 feet above mean sea level (ft, amsl) following the IRM. The data collected during the SRI revealed that source level contamination consisting primarily of chlorinated VOCs (max concentration 140,000 ppb 1,1,1-TCA compared to the groundwater standard of 5 ppb) persists in bedrock groundwater following the IRM. Total CVOC concentrations are greatest in the southwest corner of the site and have migrated both horizontally and vertically through high angle features towards the southwest site boundary. PFAS (SRI-1 max concentration 904 ppt PFOS) and 1,4-dioxane (SRI-1 max concentration 294 ppb) concentrations in bedrock groundwater are lower than pre-IRM concentrations, but still well above groundwater standards. A second supplemental remedial investigation (SRI-2) was conducted following SRI-1 to further determine the extent of contamination in bedrock groundwater off-site in high angle fracture features. SRI-2 consisted of the installation of six monitoring wells screened at depths ranging from 55 to 45 ft, amsl and 0 to 20 ft, amsl. The data collected during SRI-2 revealed that elevated levels of contamination consisting primarily of chlorinated VOCs are migrating horizontally and vertically off-site in groundwater through high angle fracture features. PFAS, 1,4-dioxane and CVOCs are present in bedrock groundwater at depths down to 0 ft, amsl. Soil Vapor - A total of nine soil vapor samples were collected from locations throughout the site prior to the implementation of the IRM. Elevated levels of chlorinated volatile organic compounds were detected in soil vapor samples collected from the western half of the site, nearer to where elevated levels of PCE, TCE and 1,1,1-TCA were encountered in groundwater contamination. The maximum concentrations of TCE, 1,1-dichloroethene, and 1,1,1-TCA detected were 184 micrograms per cubic meter (ug/m3), 1,110 ug/m3, 15,100 ug/m3 respectively. Soil vapor impacts may extend off-site and may be comingled with soil vapor impacts from the Industrial Overall Services Corp. site. "

Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with residual contamination at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-03-12 08:16:00
Record Upd:	2021-09-02 12:50:00
Updated By:	MDKILMER
Own Op:	1
Sub Type:	P03
Owner Name:	Louis Cappelli

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Daniel Hollander
Owner Company:	Huguenot Partners LLC
Owner Address:	c/o DHA Capital LLC, 154 Grand Street, Suite 4503
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Development Partners LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	Huguenot Centre Holdings, LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Louis Cappelli
Owner Company:	RFMCH Huguenot Property Owner LLC
Owner Address:	7 Renaissance Square, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
HW Code:	C360182
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

HW Code:	C360182
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	Perfluorooctane Sulfonate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,4-dioxane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,2-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	cyanides(soluble cyanide salts)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	xylene (mixed)

CENTRE AVENUE DEVELOPMENT - SOUTH (Continued) **S127990292**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	PCB aroclor 1262
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360182
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	601703563
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-07-06 11:28:00
Record Updated:	2021-07-06 11:28:00
Updated By:	MDKILMER
Crossref ID:	C360182-06-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-02 17:00:00
Record Updated:	2020-10-02 17:00:00
Updated By:	MDKILMER
Crossref ID:	06/28/2019
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-02 16:59:00
Record Updated:	2020-10-02 16:59:00
Updated By:	MDKILMER

L92 **STATION CLEANERS** **NY DRYCLEANERS** **S110247994**
NNW **1 DEPOT PLAZA #1** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.105 mi.
555 ft. **Site 1 of 4 in cluster L**

Relative: DRYCLEANERS:
Lower

Name:	STATION CLEANERS
Address:	1 DEPOT PLAZA #1
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	---
Phone Number:	Not reported
Region:	3
Registration Effective Date:	???
Inspection Date:	Not reported
Install Date:	Not reported
Expiration Date:	Not reported

Actual:
72 ft.

STATION CLEANERS (Continued) **S110247994**

Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	???

M93 **P&D TRANSPORT - HOT TAR** **NY Spills** **S106126552**
SW **I-95 NB @ MM 5.4** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.105 mi.
555 ft. **Site 1 of 2 in cluster M**

Relative: **Lower**
Actual: **79 ft.**

SPILLS:

Name:	P&D TRANSPORT - HOT TAR
Address:	I-95 NB @ MM 5.4
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308809 / 2003-11-26
Facility ID:	0308809
Facility Type:	ER
DER Facility ID:	265298
Site ID:	329742
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B2
SWIS:	6010
Spill Date:	2003-11-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-11-18
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-18
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	P&D TRANSPORT
Spiller Address:	171 BROWNSTONE AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11-18-03 P&D Transport trailer carrying 5000 gallons of a hot tar product developed several leaks from seams and holes beneath the trailer. The driver, John Culbreath, pulled the vehicle to the shoulder of I-95 NB at mm 5.4 in New Rochelle. The trailer drained hot tar to the road shoulder where it flowed downhill until it cooled and solidified. Approximatley 200 feet of shoulder where affected before the trailer could be offloaded. DEC called out Castlton Environmental contractors when a company Rep stated that he/she would not sent a second truck to offload the damaged trailer. Castlton contacted Mystic Bulk Carriers and requested their assistance. Mystic provided a heated truck, suitable to offload the cargo and return it

P&D TRANSPORT - HOT TAR (Continued) **S106126552**

to Ownes Corning in Kearny where the load was originally picked up. The P&D damaged trailer was towed off the road to a spot near the I-95 toll plaza. Castlton performed the removal of the solidified tar several days later as they were delayed by heavy rain which created hazardous working conditions on busily traveled I-95. As of 11-18-03, Portland Asphalt indicated that they would pay Caslton directly for the cost of the cleanup. "

Remarks: "material goes into a manhole which leads to a water way. poss hutchinson river. spill not controlled yet. caller req call back from rep"

All Materials:

Site ID:	329742
Operable Unit ID:	877435
Operable Unit:	01
Material ID:	498725
Material Code:	0018A
Material Name:	tar
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M94 **I-95** **NY Spills** **S102152708**
SW **I-95EB MP54** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.105 mi.
555 ft. **Site 2 of 2 in cluster M**

Relative: **Lower**

Actual: **79 ft.**

SPILLS:

Name:	I-95
Address:	I-95EB MP54
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8700158 / 1987-04-07
Facility ID:	8700158
Facility Type:	ER
DER Facility ID:	105126
Site ID:	121121
DEC Region:	3
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	6010
Spill Date:	1987-04-07
Investigator:	WEED
Referred To:	Not reported
Reported to Dept:	1987-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	1987-04-07
Cleanup Meets Std:	True
Last Inspection:	1987-04-07
Recommended Penalty:	False
UST Trust:	False

I-95 (Continued) **S102152708**

Remediation Phase:	0
Date Entered In Computer:	1987-04-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	121121
Operable Unit ID:	904779
Operable Unit:	01
Material ID:	473726
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I95 **GREEN HEAVEN CLEANERS** **NY DRYCLEANERS** **S106437149**
South **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.108 mi.
568 ft. **Site 16 of 24 in cluster I**

Relative:
Higher

Actual:
98 ft.

DRYCLEANERS:

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2000-09-29 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2001-10-05 08:00:00
Install Date:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 1999-03-29 12:14:00
Inspection Date: 2002-10-01 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 1999-03-29 12:14:00
Inspection Date: 2003-10-02 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 1999-03-29 12:14:00
Inspection Date: 2004-10-07 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE

GREEN HEAVEN CLEANERS (Continued) **S106437149**

City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2005-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2006-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2007-10-12 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	1999-03-29 12:14:00
Inspection Date:	2008-10-16 08:00:00
Install Date:	Not reported
Expiration Date:	04/29/2010
Removal Date:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 1999-03-29 12:14:00
Inspection Date: 2009-10-15 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 1999-03-29 12:14:00
Inspection Date: 2010-11-11 08:00:00
Install Date: Not reported
Expiration Date: 04/29/2010
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2010-04-29 10:15:16
Inspection Date: 2000-09-29 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2001-10-05 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2002-10-01 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2003-10-02 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2004-10-07 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2010-04-29 10:15:16
Inspection Date: 2005-10-13 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2010-04-29 10:15:16
Inspection Date: 2006-10-13 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2010-04-29 10:15:16
Inspection Date: 2007-10-12 08:00:00
Install Date: Not reported
Expiration Date: 02/28/2012
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2008-10-16 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2009-10-15 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2010-04-29 10:15:16
Inspection Date:	2010-11-11 08:00:00
Install Date:	Not reported
Expiration Date:	02/28/2012
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2012-02-28 16:30:08
Inspection Date:	2000-09-29 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2018
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2012-02-28 16:30:08
Inspection Date:	2001-10-05 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2018
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2012-02-28 16:30:08
Inspection Date:	2002-10-01 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2018
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2012-02-28 16:30:08
Inspection Date:	2003-10-02 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2018
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2012-02-28 16:30:08
Inspection Date:	2004-10-07 08:00:00
Install Date:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2005-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2006-10-13 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2007-10-12 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE

GREEN HEAVEN CLEANERS (Continued) **S106437149**

City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2008-10-16 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2009-10-15 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2012-02-28 16:30:08
Inspection Date: 2010-11-11 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business: Not reported

Name: GREEN HEAVEN CLEANERS
Address: 62 CENTRE AVE
City,State,Zip: NEW ROCHELLE, NY 10801 7213
Facility ID: 3-5510-00298
Phone Number: 9146365350
Region: Not reported
Registration Effective Date: 2018-05-10 10:08:40
Inspection Date: 2000-09-29 08:00:00
Install Date: Not reported
Expiration Date: 05/10/2028
Removal Date: Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2001-10-05 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2002-10-01 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2003-10-02 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2004-10-07 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2005-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2006-10-13 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2007-10-12 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

GREEN HEAVEN CLEANERS (Continued) **S106437149**

Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2008-10-16 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2009-10-15 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

Name:	GREEN HEAVEN CLEANERS
Address:	62 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801 7213
Facility ID:	3-5510-00298
Phone Number:	9146365350
Region:	Not reported
Registration Effective Date:	2018-05-10 10:08:40
Inspection Date:	2010-11-11 08:00:00
Install Date:	Not reported
Expiration Date:	05/10/2028
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF-2000; CAS 64742-48-9, synthetic hydrocarbon, ExxonMobil
Current Business:	Not reported

I96 **SIMONETTI CLEANERS & TAYLORING** **EDR Hist Cleaner** **1020088094**
South **62 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.108 mi.
568 ft. **Site 17 of 24 in cluster I**

Relative: EDR Hist Cleaner
Higher

Actual: Year: Name: Type:
98 ft.

Year:	Name:	Type:
1980	GEM CLEANERS	Drycleaning Plants, Except Rugs
1982	GEM CLEANERS	Drycleaning Plants, Except Rugs
1983	GEM CLEANERS	Drycleaning Plants, Except Rugs
1985	GEM CLEANERS	Drycleaning Plants, Except Rugs
1986	GEM CLEANERS	Drycleaning Plants, Except Rugs
1987	GEM CLEANERS	Drycleaning Plants, Except Rugs
1988	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1989	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1990	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs
1991	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1992	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1993	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1994	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1995	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1996	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1997	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1998	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
1999	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2000	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2001	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2002	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2003	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2004	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2005	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2006	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2007	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2008	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2009	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2010	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2011	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2012	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2013	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC
2014	SIMONETTI CLEANERS & TAYLORING	Drycleaning Plants, Except Rugs, NEC

I97 **CENTRE CLEANERS** **RCRA-VSQG** **1000338662**
South **62 CENTRE STREET** **US AIRS** **NYD982531634**
< 1/8 **NEW ROCHELLE, NY 10801** **FINDS**
0.108 mi. **ECHO**
568 ft. **Site 18 of 24 in cluster I** **NY MANIFEST**

Relative: RCRA-VSQG:
Higher

Actual:
98 ft.

Date Form Received by Agency:		20070101
Handler Name:	SIMONETTI CLEANERS	
Handler Address:		62 CENTRE ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD982531634
Contact Name:		KWANG YUN
Contact Address:		CENTRE ST
Contact City,State,Zip:		NEW ROCHELLE, NY 10801
Contact Telephone:		914-636-5350
Contact Fax:		Not reported

CENTRE CLEANERS (Continued) **1000338662**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	CENTRE ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	KWANG YUN
Owner Type:	Private
Operator Name:	KWANG YUN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

CENTRE CLEANERS (Continued) **1000338662**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KWANG YUN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	24 SUMMIT AVE
Owner/Operator City,State,Zip:	MOUNT VERNON, NY 10550
Owner/Operator Telephone:	914-665-0274
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	KWANG YUN

CENTRE CLEANERS (Continued) **1000338662**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	24 SUMMIT AVE
Owner/Operator City,State,Zip:	MOUNT VERNON, NY 10550
Owner/Operator Telephone:	914-665-0274
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KWANG YUN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	24 SUMMIT AVE
Owner/Operator City,State,Zip:	MOUNT VERNON, NY 10550
Owner/Operator Telephone:	914-665-0274
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: SIMONETTI CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: SIMONETTI CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960321
Handler Name: SIMONETTI CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CENTRE CLEANERS (Continued) **1000338662**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000338662
Region Code: 02
Programmatic ID: AIR 020000003606156000
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

Envid: 1000338662
Region Code: 02
Programmatic ID: AIR NY0000003551000298
Facility Registry ID: 110012174805
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:
Registry ID: 110012174805

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major

CENTRE CLEANERS (Continued) **1000338662**

redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000338662
Registry ID:	110012174805
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012174805
Name:	CENTRE CLEANERS
Address:	62 CENTRE STREET
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	SIMONETTI CLEANERS
Address:	62 CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD982531634
Facility Status:	Not reported
Location Address 1:	62 CENTRE AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982531634
Mailing Name:	SIMONETTI CLEANERS
Mailing Contact:	SIMONETTI CLEANERS
Mailing Address 1:	62 CENTRE AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146365350

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CENTRE CLEANERS (Continued) **1000338662**

Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/12/2007
Trans1 Recv Date:	05/12/2007
Trans2 Recv Date:	05/17/2007
TSD Site Recv Date:	05/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982531634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	000497613SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I98 **HACKER MORRIS J & SONS INC** **EDR Hist Auto** **1020903179**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.110 mi.
579 ft. **Site 19 of 24 in cluster I**

Relative: EDR Hist Auto
Higher

Actual:
98 ft.

Year:	Name:	Type:
1969	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1970	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1971	HACKER MORRIS J & SONS INC	Gasoline Service Stations

HACKER MORRIS J & SONS INC (Continued) **1020903179**

1972	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1973	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1974	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1975	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1976	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1977	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1978	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1979	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1980	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1982	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1983	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1985	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1986	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1987	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1988	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1989	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1990	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1991	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1992	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1993	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1994	HACKER MORRIS J & SONS INC	Gasoline Service Stations
1995	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1996	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1997	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1998	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
1999	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2000	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2001	HACKER MORRIS J & SONS INC	General Automotive Repair Shops
2002	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2003	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2004	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2005	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2006	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2007	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2008	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2009	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2010	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2011	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2012	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2013	MORRIS J HACKER & SONS INC	General Automotive Repair Shops
2014	MORRIS J HACKER & SONS INC	General Automotive Repair Shops

---

I99 **COMMERCIAL** **NY Spills** **S127585823**
South **64 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.110 mi.
579 ft. **Site 20 of 24 in cluster I**

Relative:
Higher

Actual:
98 ft.

SPILLS:

Name:	COMMERCIAL
Address:	64 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2102839 / Not Reported
Facility ID:	2102839
Facility Type:	ER
DER Facility ID:	569082
Site ID:	621593
DEC Region:	3

COMMERCIAL (Continued) **S127585823**

Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Spill Date:	2021-06-25
Investigator:	MDKILMER
Referred To:	Not reported
Reported to Dept:	2021-06-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2021-06-25
Spill Record Last Update:	2021-06-25
Spiller Name:	ANDREW ALLEN
Spiller Company:	CENTER POINT DEVELOPERS LLC
Spiller Address:	64 CENTER AVE
Spiller Company:	999
Contact Name:	ANDREW ALLEN
DEC Memo:	"6/25/21: Discovery of two 30-gallon tanks during support of excavation work. Contingency plan in place for sampling and removal. Spill linked with BCP site Swan Garage Kent Supply (C360210). PM changed to Michael Kilmer. MDK"
Remarks:	"cleanup pending."

All Materials:

Site ID:	621593
Operable Unit ID:	1368772
Operable Unit:	01
Material ID:	2381633
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	64 CENTER AVE & 8 WESTCHESTER ST
Address:	64 CENTER AVE & 8 WESTCHESTER ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2104935 / Not Reported
Facility ID:	2104935
Facility Type:	ER
DER Facility ID:	571072
Site ID:	623763
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6010
Spill Date:	2021-08-24

COMMERCIAL (Continued) **S127585823**

Investigator:	MDKILMER
Referred To:	Not reported
Reported to Dept:	2021-08-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2021-08-24
Spill Record Last Update:	2021-08-25
Spiller Name:	JOHN STEWART
Spiller Company:	ALLSTATE CAPITAL LLC & CENTERPOINT DEVELOPERS LLC
Spiller Address:	64 CENTER AVE & 8 WESTCHESTER ST
Spiller Company:	999
Contact Name:	JOHN STEWART
DEC Memo:	"8/25/21: Spill called in for UST removal at BCP site Swan Garage Kent Suply (C360210). Cross referencing and closing upon BCP FER approval. MDK"
Remarks:	"appx 2 gals of product released to soil. clean up in progress."

All Materials:

Site ID:	623763
Operable Unit ID:	1370911
Operable Unit:	01
Material ID:	2384008
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

I100 **COMMERCIAL PROPERTY** **NY LTANKS** **S116156733**
South **64 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.110 mi.
579 ft. **Site 21 of 24 in cluster I**

Relative: **Higher**
Actual: **98 ft.**

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	64 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1308480 / 2015-04-28
Facility ID:	1308480
Site ID:	489220
Spill Date:	2013-11-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported

COMMERCIAL PROPERTY (Continued) **S116156733**

SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-20
Spill Record Last Update:	2015-05-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	64 CENTRE AVE
Spiller County:	999
Spiller Contact:	STEVE MANGELS
Spiller Phone:	(914) 632-2610
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444316
DEC Memo:	"11-20-13: Chris/WCHD call to V.Mc./Dispt.: Closed Unreg. PBS faciliy. Wayne/WCHD to handle. 11/20/2013 1:48:33 PM:: From Chris Lalak to Wayne Schneider via email:: Wayne, Former PBS site 3-137979 Expired in 1992 (removed gasoline tanks) TTF for Underground waste oil tank estimated as a 550 (Ullage leak and they plan to remove the tank.) The Facility is: M. Hacker and Sons. Please get them to register and deal with the TTF jod 04/23/15 HydroEnvironmental Solutions submitted a report documenting the installation of a temporary monitoring well in the location were the LUST was removed. (See report in DecDocs) Trace levels of VOCs & SVOCs in the sample. TG 4-28-15 closed NFA -RDB"
Remarks:	""

All Materials:

Site ID:	489220
Operable Unit ID:	1238809
Operable Unit:	01
Material ID:	2238759
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

N101 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016963532**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004365318**
< 1/8 **NEW ROCHELLE, NY 10801**
0.111 mi.
588 ft. **Site 1 of 11 in cluster N**

Relative: **Lower**

Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20131024
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 4319
Handler Address:	CENTRE AVE & RELYEA PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004365318
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130924
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 4319
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131024
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 4319
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: CENTRE AVE & RELYEA PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004365318
Facility Status: Not reported
Location Address 1: CENTRE AVE & RELYEA PL
Code: BP
Location Address 2: TM 4319
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004365318
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/24/2013
Trans1 Recv Date: 09/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004365318

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016963532**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694707JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N102 **CON EDISON TRANSFORMER MANHOLE: 4319** **RCRA NonGen / NLR** **1016965006**
SW **CENTRE AVE & RELYEA PL** **NY MANIFEST** **NYP004379020**
< 1/8 **NEW ROCHELLE, NY 10802**
0.111 mi.
588 ft. **Site 2 of 11 in cluster N**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20131123
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 4319
Handler Address:	CENTRE AVE & RELYEA PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004379020
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20140701
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20131023
Handler Name: CON EDISON TRANSFORMER MANHOLE: 4319
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131123
Handler Name: CON EDISON TRANSFORMER MANHOLE: 4319
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: CENTRE AVE & RELYEA PL
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004379020

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Facility Status:	Not reported
Location Address 1:	CENTRE AVE & RELYEA PL
Code:	BP
Location Address 2:	SB4314
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004379020
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693664JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON TRANSFORMER MANHOLE: 4319 (Continued) **1016965006**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O103 **CON EDISON** **NY MANIFEST** **S119077729**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
589 ft. **Site 1 of 6 in cluster O**

Relative:
Lower

Actual:
88 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGUENOT ST & LE COUNT PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004837407
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & LECOUNT PL
Code:	BP
Location Address 2:	V 7723
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004837407
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported

CON EDISON (Continued) **S119077729**

Generator Ship Date:	09/11/2015
Trans1 Recv Date:	09/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837407
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472144JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O104 **CON EDISON** **NJ MANIFEST** **S120676596**
NE **HUGUENOT ST & LE COUNT PL** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
589 ft. **Site 2 of 6 in cluster O**

Relative: **Lower**

Actual: **88 ft.**

NJ MANIFEST:

EPA Id:	NYP004837407
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported

CON EDISON (Continued) **S120676596**

County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472144JJK
EPA ID:	NYP004837407
Date Shipped:	9/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

O105 **CON EDISON** **RCRA NonGen / NLR** **1019907724**
NE **HUGUENOT ST & LE COUNT PL** **NYP004837407**
< 1/8 **NEW ROCHELLE, NY 10801**
0.112 mi.
589 ft. **Site 3 of 6 in cluster O**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150911
Handler Name:	CON EDISON	
Handler Address:		HUGUENOT ST & LE COUNT PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004837407
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019907724**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150911
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150911
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019907724**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

O106 **CON EDISON MANHOLE 1181** **RCRA NonGen / NLR** **1014918324**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219380**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
589 ft. **Site 4 of 6 in cluster O**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20101202
Handler Name:	CON EDISON MANHOLE 1181
Handler Address:	HUGUENOT ST & LECOUNT PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004219380
Contact Name:	DONALD SENNO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20101102
Handler Name:	CON EDISON MANHOLE 1181
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20101202
Handler Name: CON EDISON MANHOLE 1181
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004219380
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DONALD SENNO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874911JJK
EPA ID: NYP004219380
Date Shipped: 11/02/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 1181
Address:	HUGUENOT ST & LECOUNT PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004219380
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & LE COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219380

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Mailing Name:	CONSOLIDATED EDISON - MH 1181
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/02/2010
Trans1 Recv Date:	11/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219380
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874911JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON MANHOLE 1181 (Continued) **1014918324**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

O107 **CON EDISON MANHOLE 1178** **RCRA NonGen / NLR** **1014918331**
NE **HUGUENOT ST & LECOUNT PL** **NJ MANIFEST** **NYP004219455**
< 1/8 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.112 mi.
589 ft. **Site 5 of 6 in cluster O**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20101203
Handler Name:	CON EDISON MANHOLE 1178
Handler Address:	HUGUENOT ST & LECOUNT PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004219455
Contact Name:	DOMINIC BIZZARO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20101103
Handler Name:	CON EDISON MANHOLE 1178
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20101203
Handler Name:	CON EDISON MANHOLE 1178
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004219455
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874912JJK
EPA ID:	NYP004219455
Date Shipped:	11/03/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON MANHOLE 1178 (Continued) **1014918331**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 1178
Address:	HUGUENOT ST & LECOUNT PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004219455
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & LE COURT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219455
Mailing Name:	CONSOLIDATED EDISON - MH 1178
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON MANHOLE 1178 (Continued) **1014918331**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2010
Trans1 Recv Date:	11/03/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219455
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874912JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J108 **SPEEDY CLEANERS** **US AIRS** **1006295756**
East **217 NORTH AVENUE** **FINDS** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.112 mi. **NY DRYCLEANERS**
593 ft. **Site 15 of 17 in cluster J**

Relative:
Higher

Actual:
91 ft.

US AIRS MINOR:

Envid:	1006295756
Region Code:	02
Programmatic ID:	AIR NY0000003551000344
Facility Registry ID:	110012166921
D and B Number:	Not reported
Primary SIC Code:	7212
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110012166921

Click Here:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1006295756
Registry ID:	110012166921
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012166921
Name:	SPEEDY CLEANERS
Address:	217 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801

DRYCLEANERS:

Name:	SPEEDY CLEANERS
Address:	217 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Facility ID:	3-5510-00344
Phone Number:	914-654-9082
Region:	Not reported

SPEEDY CLEANERS (Continued) **1006295756**

Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	1931-12-03 00:00:00
Install Date:	00/03
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

I109 **NYNEX LOCATION** **NY LTANKS** **S102660218**
SSW **342 HUEGNOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.114 mi.
602 ft. **Site 22 of 24 in cluster I**

Relative: **Higher**
Actual: **95 ft.**

LTANKS:

Name:	NYNEX LOCATION
Address:	342 HUEGNOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9708146 / 1997-10-10
Facility ID:	9708146
Site ID:	270876
Spill Date:	1997-10-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1997-11-12
Spiller Name:	RICH KALISTA
Spiller Company:	BELL ATLANTIC
Spiller Address:	2203 MCCONNELL ST
Spiller County:	001
Spiller Contact:	TOM MUFF
Spiller Phone:	(914) 449-5321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220510
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DOING AN UPGRADE FOR A NYNEX LOCATION AND REMOVING 2 UNDERGROUND TANKS FROM A BASEMENT - TANKS WERE ENCASED BY SAND & WHEN REMOVED THE SAND WAS CONTAMINATED - THEY HAVE REMOVED SAND."

All Materials:

NYNEX LOCATION (Continued) **S102660218**

Site ID:	270876
Operable Unit ID:	1051372
Operable Unit:	01
Material ID:	330133
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I110 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000553730**
SSW **342 HUGUENOT ST** **NY MANIFEST** **NYD986961605**
< 1/8 **NEW ROCHELLE, NY 10801**
0.114 mi.
602 ft. **Site 23 of 24 in cluster I**

Relative: **Higher**
Actual: **95 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NEW YORK TELEPHONE CO	
Handler Address:		342 HUGUENOT ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD986961605
Contact Name:		CATHERINE ROM
Contact Address:		NINTH AVE
Contact City,State,Zip:		NEW YORK, NY 10001
Contact Telephone:		212-502-7694
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		NINTH AVE
Mailing City,State,Zip:		NEW YORK, NY 10001
Owner Name:		NEW YORK TELEPHONE CO
Owner Type:		Private
Operator Name:		NEW YORK TELEPHONE CO
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

NEW YORK TELEPHONE CO (Continued) **1000553730**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported

NEW YORK TELEPHONE CO (Continued) **1000553730**

Date Ended Current:	Not reported
Owner/Operator Address:	342 HUGUENOT ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-9964
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	342 HUGUENOT ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-9964
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	342 HUGUENOT ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-9964
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	342 HUGUENOT ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-9964
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: NEW YORK TELEPHONE CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

NEW YORK TELEPHONE CO (Continued) **1000553730**

Receive Date: 20070101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910702
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: TELESECTOR RESOURCES GROUP
Address: 342 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYD986961605
Facility Status: Not reported
Location Address 1: 342 HUGANAUGHT STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WESTCHESTER
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986961605
Mailing Name: TELESECTOR RESOURCES GROUP
Mailing Contact: WAYNE SEBRO

NEW YORK TELEPHONE CO (Continued) **1000553730**

Mailing Address 1:	441 9TH AVENUE 5TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125027694

I111 **VERIZON** **NY Spills** **S106867403**
SSW **342 HUGUENOT ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.114 mi.
602 ft. **Site 24 of 24 in cluster I**

Relative:
Higher

Actual:
95 ft.

SPILLS:

Name:	VERIZON
Address:	342 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413326 / 2005-09-11
Facility ID:	0413326
Facility Type:	ER
DER Facility ID:	288752
Site ID:	342403
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-03-22
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-22
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-22
Spill Record Last Update:	2005-09-11
Spiller Name:	CLAUDIA
Spiller Company:	VERIZON
Spiller Address:	342 HUGUENOT ST.
Spiller Company:	001
Contact Name:	CLAUDIA
DEC Memo:	"September 11, 2005: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank is tight has a bad vent line. Will be replacing the vent line."

All TTF:

Facility ID:	0413326
Spill Number:	0413326

VERIZON (Continued) **S106867403**

Spill Tank Test:	1548716
Site ID:	342403
Tank Number:	6
Tank Size:	6000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	342403
Operable Unit ID:	1101130
Operable Unit:	01
Material ID:	581261
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O112 **DEVELOPMENT SITE** **NY LTANKS** **S107522540**
NE **175 HUGUENOT STREET** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.114 mi.
603 ft. **Site 6 of 6 in cluster O**

Relative:
Lower

Actual:
88 ft.

LTANKS:

Name:	TRUMP PLAZA
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512575 / 2006-03-08
Facility ID:	0512575
Site ID:	358910
Spill Date:	2006-01-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-01-30
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

DEVELOPMENT SITE (Continued) **S107522540**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-30
Spill Record Last Update:	2006-03-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN MANFREDI
Spiller Phone:	(914) 241-3795
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	307023
DEC Memo:	"3/08/06 See JM associates spill closure report for 05-04821. TG"
Remarks:	""

All Materials:

Site ID:	358910
Operable Unit ID:	1116137
Operable Unit:	01
Material ID:	2106280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	TRUMP PLAZA
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510932 / 2005-12-19
Facility ID:	0510932
Facility Type:	ER
DER Facility ID:	307023
Site ID:	356986
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2005-12-19
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

DEVELOPMENT SITE (Continued) **S107522540**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2006-03-08
Spiller Name:	SEAN MCKAY
Spiller Company:	TRUMP PLAZA
Spiller Address:	175 HUEGOTNOT STREET
Spiller Company:	001
Contact Name:	SEAN MCKAY
DEC Memo:	"CONFIRMED CLEANUP WITH WCDOH 3/8/06 See spill JM Associates closure report for 05-04821"
Remarks:	"SPILL AROUND GENERATOR AND IN PROCESS OF BEING CLEANED UP;"

All Materials:

Site ID:	356986
Operable Unit ID:	1114275
Operable Unit:	01
Material ID:	2104355
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	DEVELOPMENT SITE
Address:	175 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0504821 / 2006-03-08
Facility ID:	0504821
Facility Type:	ER
DER Facility ID:	307023
Site ID:	349739
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6010
Spill Date:	2005-07-20
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2006-03-08
Spiller Name:	JOHN MANFREDIE

DEVELOPMENT SITE (Continued) **S107522540**

Spiller Company: NEW ROCHELLE #1A
Spiller Address: HUGIGNOT /LAACONTA
Spiller Company: 001
Contact Name: JOHN MANFREDIE
DEC Memo: "3/02/06 UST removal report submitted by JM Associates including information about two other spill reports listed for the same parcel, 05-10932 and 05-12575. A total of 5 UST's were removed along with 3,351.05 tons of petroleum impacted soil. Based on the information contained in the report, no further action is required. TG"
Remarks: "DURING EXCAVATION FOUND AN ABANDON TANK: AND FOUND CONTAMINATED SOIL"
Not reported

All Materials:
Site ID: 349739
Operable Unit ID: 1107327
Operable Unit: 01
Material ID: 2097217
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

K113 **NORTH GARDEN ASSOCIATES LLC** **NY UST** **U004177039**
North **309-311 NORTH AVENUE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.116 mi.
612 ft. **Site 2 of 10 in cluster K**

Relative: WESTCHESTER CO. UST:
Lower
Name: NORTH GARDEN ASSOCIATES LLC
Actual: Address: 309-311 NORTH AVENUE
74 ft. City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-496928 / Active
Operator Name: Harrin Platzner
Owner Name: North Garden Associates LLC
Owner Street: P.O Box 111
Owner Address2: 309-311 North Avenue
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1
Status: 1. In-Service
Capacity: 3000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 10/15/1947
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None

NORTH GARDEN ASSOCIATES LLC (Continued) **U004177039**

Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	2. Suction

N114 **APPAREL PLUS** **NY Spills** **S116156116**
SW **27 CENTRE AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.117 mi.
619 ft. **Site 3 of 11 in cluster N**

Relative: **Lower**

Actual: **88 ft.**

SPILLS:

Name:	APPAREL PLUS
Address:	27 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1309988 / 2014-01-14
Facility ID:	1309988
Facility Type:	ER
DER Facility ID:	445839
Site ID:	490810
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2014-01-14
Investigator:	DXWEITZ
Referred To:	Not reported
Reported to Dept:	2014-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-14
Spill Record Last Update:	2014-01-14
Spiller Name:	CHRIS LALAK
Spiller Company:	APPAREL PLUS LAUNDRY
Spiller Address:	27 CENTRE AVE
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"1/14/14 Chris Lalak from WCHD called and said that this was motor oil from a truck in the parking lot. People at the laundry did the cleanup. According to Chris Lalak, the spill can be closed. They were there for other reasons. NFA dw"
Remarks:	"loss to sewer. c/u in progress"

All Materials:

Site ID:	490810

APPAREL PLUS (Continued) **S116156116**

Operable Unit ID:	1240364
Operable Unit:	01
Material ID:	2240510
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

P115 **535 MAIN ST ASSOCIATION** **NY Spills** **S104648843**
SSE **535 MAIN STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.119 mi.
627 ft. **Site 1 of 17 in cluster P**

Relative: **Higher**

Actual: **99 ft.**

SPILLS:

Name:	535 MAIN ST ASSOCIATION
Address:	535 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9415294 / 1995-03-03
Facility ID:	9415294
Facility Type:	ER
DER Facility ID:	205781
Site ID:	251083
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	6010
Spill Date:	1995-02-17
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER DID NOT HEAR VENT ALARM AND OVERFILLED TANK REGENT OIL CLEANED UP"

535 MAIN ST ASSOCIATION (Continued) **S104648843**

All Materials:

Site ID:	251083
Operable Unit ID:	1012611
Operable Unit:	01
Material ID:	370473
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 9900400
Address:	535 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9900400 / 1999-07-09
Facility ID:	9900400
Facility Type:	ER
DER Facility ID:	75076
Site ID:	81102
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-04-08
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-04-12
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-12
Spill Record Last Update:	2004-02-24
Spiller Name:	MR GOLDBERG
Spiller Company:	MR GOLDBERG
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MR GOLDBERG
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/9/99 SPILL CLEANED BY TOWN & COUNTRYF OIL. NFA"
Remarks:	"FAULTY VENT ALARM - SPILLED LESS THAN 1 GAL - CLEANED UP - TENANTS STILL COMPLAINING OF ODORS"

All Materials:

Site ID:	81102
Operable Unit ID:	1075164
Operable Unit:	01

535 MAIN ST ASSOCIATION (Continued) **S104648843**

Material ID:	307538
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P116 **SIDNEY FURNITURE** **NY Spills** **S118460140**
SSE **535 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.119 mi.
627 ft. **Site 2 of 17 in cluster P**

Relative: **Higher**
Actual: **99 ft.**

SPILLS:

Name:	SIDNEY FURNITURE
Address:	535 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1509029 / 2015-12-04
Facility ID:	1509029
Facility Type:	ER
DER Facility ID:	75076
Site ID:	517634
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010
Spill Date:	2015-12-03
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-04
Spill Record Last Update:	2015-12-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHELLE GUERRERO
DEC Memo:	"12/04/15: Caller states she is at work, states she is pregnant, and states that they were working on the furnace and there was a small oil spill. She wanted to know if oil spills are hazardous. I was in the process of answering her questions and she hung up. Westchester County Dept of Health notified. No further DEC action. jod"
Remarks:	"Caller advised aprx 1/2 gal of oil spilled onto carpet. Clean up is pending. Caller is requesting a call back"

SIDNEY FURNITURE (Continued) **S118460140**

All Materials:

Site ID:	517634
Operable Unit ID:	1266703
Operable Unit:	01
Material ID:	2270652
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

K117 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157674**
North **F/O 311 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.120 mi.
631 ft. **Site 3 of 10 in cluster K**

Relative: **Lower**
Actual: **74 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	F/O 311 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004230306
Facility Status:	Not reported
Location Address 1:	F/O 311 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230306
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported

CONSOLIDATED EDISON (Continued) **S111157674**

Generator Ship Date:	03/10/2011
Trans1 Recv Date:	03/10/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230306
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655968JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L118 **COMMERCIAL - UST** **NY Spills** **S121119478**
NNW **35 GRAND STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
634 ft. **Site 2 of 4 in cluster L**

Relative: **Lower**

Actual: **76 ft.**

SPILLS:

Name:	COMMERCIAL - UST
Address:	35 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1706607 / 2018-04-05
Facility ID:	1706607
Facility Type:	ER
DER Facility ID:	514557
Site ID:	560927

COMMERCIAL - UST (Continued) **S121119478**

DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B4
SWIS:	6010
Spill Date:	2017-10-06
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2017-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-10-06
Spill Record Last Update:	2018-04-05
Spiller Name:	Not reported
Spiller Company:	The Luxuria
Spiller Address:	35 GRAND STREET
Spiller Company:	999
Contact Name:	GARY GIGLIO
DEC Memo:	"10/6/17 - A 1k gal. UST was removed. Laboratory soil post excavation samples were collected. TCR will be submitted to the DEC. KAB 4/5/18: VMT Environmental removed the leaking UST and disposed of a total of 269 tons of petroleum contaminated soil. Report from Performer Compliance submitted to DEC has been reviewed and entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"underground 1,000 gallon oil tank. clean up is on going."

All TTF:

Facility ID:	1706607
Spill Number:	1706607
Spill Tank Test:	2504339
Site ID:	560927
Tank Number:	UST
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	560927
Operable Unit ID:	1308916
Operable Unit:	01

COMMERCIAL - UST (Continued) **S121119478**

Material ID:	2315940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

J119 **CATHOLIC NEWS PUBLISHING** **NY LTANKS** **S106972587**
ESE **210 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
634 ft. **Site 16 of 17 in cluster J**

Relative: **Higher**

Actual: **91 ft.**

LTANKS:

Name:	CATHOLIC NEWS PUBLISHING
Address:	210 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0503023 / 2005-08-28
Facility ID:	0503023
Site ID:	347516
Spill Date:	2005-06-13
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-13
CID:	44
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-13
Spill Record Last Update:	2005-08-28
Spiller Name:	MYLES RIDDER
Spiller Company:	CATHOLIC NEWS PUBLISHING
Spiller Address:	210 NORTH AVE
Spiller County:	001
Spiller Contact:	MYLES RIDDER
Spiller Phone:	(914) 632-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293840
DEC Memo:	"August 28, 2005: NORTHEAT DISPOSED OF LUST AND 48.90 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK AND HOLES IN TANK"

All Materials:

CATHOLIC NEWS PUBLISHING (Continued) **S106972587**

Site ID:	347516
Operable Unit ID:	1105241
Operable Unit:	01
Material ID:	1502620
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P120 **NOVA REALTY - UST** **NY Spills** **S123660999**
SSE **523 MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.120 mi.
636 ft. **Site 3 of 17 in cluster P**

Relative: **Higher**
Actual: **98 ft.**

SPILLS:

Name:	NOVA REALTY - UST
Address:	523 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1811358 / Not Reported
Facility ID:	1811358
Facility Type:	ER
DER Facility ID:	534783
Site ID:	582291
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B2
SWIS:	6010
Spill Date:	2019-02-11
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2019-02-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2019-02-11
Spill Record Last Update:	2020-12-09
Spiller Name:	BRIAN HEAPS
Spiller Company:	Nova Realty
Spiller Address:	523 MAIN ST
Spiller Company:	001
Contact Name:	BRAIN HEAPS
DEC Memo:	"2/11/19 Northeast Environmental was hired to do vac out of UST under basement floor - owners thought there was water in the tank. Northeast found oil in the sump. Sump and tank have been vacuumed out. Tank is under concrete floor of basement. No waterways on

NOVA REALTY - UST (Continued) **S123660999**

property, no drains other than sump. Tank to be removed to do further investigation and cleanup. Site is hair salon. Left message for property contact to call duty desk. ga 2/11/19: Owner to hire Northeast to remove tank and any cleanup. Property on municipal water. ga 5/04/2020: Message sent to Northeast requesting an update. jod 11/18/20: I spoke with Dwayne Monaco at Northeast. They were never hired to remove or replace the UST. He states Northeast vacced out the UST and the sump pit and installed a temp tank. The temp tank has since been removed but Northeast has not performed any additional work. jod"

Remarks: "oil found in sump. investigation and c/u ongoing"

All Materials:

Site ID:	582291
Operable Unit ID:	1329976
Operable Unit:	01
Material ID:	2339121
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Q121 **CON EDISON** **NY MANIFEST** **S119075589**
ENE **LECOUNT PL & ANDERSON ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.122 mi.
643 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	LECOUNT PL & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004788378
Facility Status:	Not reported
Location Address 1:	LECOUTN PL & MAIN ST
Code:	BP
Location Address 2:	SB 1996
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004788378
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S119075589**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2015
Trans1 Recv Date:	05/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004788378
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467901JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q122
ENE
< 1/8
0.122 mi.
643 ft.

CON EDISON
LECOUNT PL & ANDERSON ST
NEW ROCHELLE, NY 10801

Site 2 of 4 in cluster Q

NJ MANIFEST **S120672272**
N/A

Relative:
Higher

Actual:
90 ft.

NJ MANIFEST:

EPA Id:	NYP004788378
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014467901JJK
EPA ID:	NYP004788378
Date Shipped:	5/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120672272**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q123 **CON EDISON** **RCRA NonGen / NLR** **1019903661**
ENE **LECOUNT PL & ANDERSON ST** **FINDS** **NYP004788378**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.122 mi.
643 ft. **Site 3 of 4 in cluster Q**

Relative: **Higher**
Actual: **90 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150530
Handler Name:	CON EDISON	
Handler Address:		LECOUNT PL & ANDERSON ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004788378
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019903661**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150530
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150530
Handler Name: CON EDISON	

CON EDISON (Continued) **1019903661**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069670270

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903661
Registry ID:	110069670270
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069670270
Name:	CON EDISON
Address:	LECOUNT PL & ANDERSON ST
City,State,Zip:	NEW ROCHELLE, NY 10801

P124 **LILLIAN VERNON CORP.** **NY LTANKS** **S102152290**
SSE **543 MAIN STREET** **NY Spills** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.122 mi.
643 ft. **Site 4 of 17 in cluster P**

Relative: **Higher**
Actual: **100 ft.**

LTANKS:

Name:	BLUE GILL REALTY
Address:	543 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308082 / 2004-05-12
Facility ID:	0308082

LILLIAN VERNON CORP. (Continued) **S102152290**

Site ID:	94435
Spill Date:	2003-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-10-30
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-05-19
Spiller Name:	JEFF WEIR
Spiller Company:	BLUE GILL REALTY
Spiller Address:	543 MAIN ST
Spiller County:	001
Spiller Contact:	JEFF WEIR
Spiller Phone:	(646) 435-8110
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	84546
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MAGNUSON 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #9212475. Letter has PBS #3-801106."
Remarks:	"TANK HAS BEEN REMOVED."

All TTF:

Facility ID:	0308082
Spill Number:	0308082
Spill Tank Test:	1528780
Site ID:	94435
Tank Number:	1
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

LILLIAN VERNON CORP. (Continued) **S102152290**

All Materials:

Site ID:	94435
Operable Unit ID:	876585
Operable Unit:	01
Material ID:	501599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	LILLIAN VERNON CORP.
Address:	543 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9212475 / 2004-05-12
Facility ID:	9212475
Facility Type:	ER
DER Facility ID:	108333
Site ID:	125220
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	1993-02-03
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2004-05-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 5/18/04: Letter to Geoffrey J. Weir, Bluegill Realty, LLC, 250 West 30th Street, NY,NY 10001 from Karen Magnuson, WCDOH dated 12May2004. Closure report by Ambient Group has been reviewed. Results of soil and groundwater samples were satisfactory. WCDOH recommends NFA at this time. See also spill #0308082."
Remarks:	"FUEL OIL LINE HAS PIN HOLE LEAK DISCOVERED IN EXCAVATION BY

LILLIAN VERNON CORP. (Continued) **S102152290**

EMER.ENVIRO. SERVICE TODAY REMOTE FILL LINE 2 VERY BADLY PITTED AND CORRODED WILL DRILL WELL 2/4/93"

All Materials:

Site ID:	125220
Operable Unit ID:	976940
Operable Unit:	01
Material ID:	402326
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

R125 **VERIZON NEW YORK INC. (NY96332)** **NY UST** **U004334181**
SSW **342 HUGUENOT STREET** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.122 mi.
644 ft. **Site 1 of 6 in cluster R**

Relative: **Higher**

Actual: **95 ft.**

NY UST:

No Details:	No Details

P126 **CON EDISON - TRANSFORMER MANHOLE 3307** **RCRA-LQG** **1019325947**
SSE **DIVISION ST & MAIN ST** **NYP004872319**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
648 ft. **Site 5 of 17 in cluster P**

Relative: **Higher**

Actual: **99 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160226
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 3307
Handler Address:	DIVISION ST & MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004872319
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151123
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151123
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160226
Handler Name: CON EDISON - TRANSFORMER MANHOLE 3307
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **1019325947**

NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P127 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243060**
SSE **DIVISION & MAIN** **N/A**
< 1/8 **NEW ROCHELLE, NY 10802**
0.123 mi.
648 ft. **Site 6 of 17 in cluster P**

Relative: **Higher**
Actual: **99 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	DIVISION & MAIN
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004123873
Facility Status:	Not reported
Location Address 1:	DIVISION & MAIN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004123873
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

P128 **CON EDISON - TRANSFORMER MANHOLE 3307** **NJ MANIFEST** **S120677907**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
648 ft. **Site 7 of 17 in cluster P**

Relative: **Higher**
Actual: **99 ft.**

NJ MANIFEST:

EPA Id:	NYP004872319
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON - TRANSFORMER MANHOLE 3307 (Continued) **S120677907**

Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	013245368JJK
EPA ID:	NYP004872319
Date Shipped:	11/23/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P129 **CON EDISON** **NY MANIFEST** **S118464238**
SSE **DIVISION ST & MAIN ST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
648 ft. **Site 8 of 17 in cluster P**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DIVISION ST & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004872319
Facility Status:	Not reported
Location Address 1:	DIVISION ST & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004872319
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/23/2015
Trans1 Recv Date:	11/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004872319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245368JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118464238**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9020
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J130 **PART OF STANDARD PRINTING BROWNFIELDS** **NY Spills** **S128042580**
East **211 NORTH AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.123 mi.
651 ft. **Site 17 of 17 in cluster J**

Relative: **Higher**
Actual: **91 ft.**

SPILLS:

Name:	PART OF STANDARD PRINTING BROWNFIELDS
Address:	211 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2106341 / Not Reported
Facility ID:	2106341
Facility Type:	ER
DER Facility ID:	572429
Site ID:	625227
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6010
Spill Date:	2021-10-05
Investigator:	GHPRATT
Referred To:	Not reported
Reported to Dept:	2021-10-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

PART OF STANDARD PRINTING BROWNFIELDS (Continued) **S128042580**

Remediation Phase:	1
Date Entered In Computer:	2021-10-05
Spill Record Last Update:	2021-10-06
Spiller Name:	Not reported
Spiller Company:	STANDARD PRINTING
Spiller Address:	14 Lecount Place
Spiller Company:	999
Contact Name:	STEVEN GUSTEMS
DEC Memo:	"10/5/21 assigned to GHP. BW 10/5/21 Partially uncovered tank. Size unknown. Soil impacts observed, odor. Liquid was observed in tank through hole. Investigation to continue tomorrow. Steve Gustems SESI coordinating with shoring contractor L&M, Northeast remedial contractor. City FD said 1000gal tank was closed in place, this to be confirmed. No GW anticipated. Verbally asked for soil samples.GHP 10/6/21: Call with Steve Gustems SESI, tank uncovered estimated 1100 gal tank. Three ft of product in tank. Stained and order contaminated soil on top of tank removed. Requested pictures. Sides of tank to be excavated, requested excavation extent to clean all sides as practicable. Soil between tank and property most accessible. Off site Monitoring well 2 ft from end of tank.GHP"
Remarks:	"historic tank - site manager gerald pratt - cleanup pending"

All Materials:

Site ID:	625227
Operable Unit ID:	1372375
Operable Unit:	01
Material ID:	2385703
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K131 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016963395**
North **313 NORTH AVE FRONT OF** **NYP004364030**
< 1/8 **NEW ROCHELLE, NY 10801**
0.123 mi.
652 ft. **Site 4 of 10 in cluster K**

Relative: **Lower**
Actual: **74 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20131020
Handler Name:	CON EDISON MANHOLE: 4175
Handler Address:	313 NORTH AVE FRONT OF
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004364030
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

CON EDISON MANHOLE: 4175 (Continued) **1016963395**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130920
Handler Name:	CON EDISON MANHOLE: 4175
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131020
Handler Name:	CON EDISON MANHOLE: 4175
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

R132 **75 CENTRE AVENUE LLC** **NY UST** **U004175967**
South **75 CENTRE AVENUE** **NY AST** **N/A**
< 1/8 **NEW ROCHELLE, NY 10801**
0.124 mi.
656 ft. **Site 2 of 6 in cluster R**

Relative:
Higher

Actual:
99 ft.

WESTCHESTER CO. UST:

Name:	75 CENTRE AVENUE LLC
Address:	75 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-800240 / Active
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	P.O. Box 330
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	Not reported
Date Perm Closure:	11/01/2004
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

Name:	75 CENTRE AVENUE LLC
Address:	75 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800240
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Dino Rentoulis
Owner Name:	John & Dino Rentoulis
Owner Street:	P.O. Box 330
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605
Tank Number:	002
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil

75 CENTRE AVENUE LLC (Continued) **U004175967**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

R133 **CENTRE-MAIN ASSOCIATES** **NY LTANKS** **S106123770**
South **75 - 77 CENTER AVE** **N/A**
< 1/8 **NEW ROCHELLE, NY**
0.124 mi.
656 ft. **Site 3 of 6 in cluster R**

Relative: **Higher**
Actual: **99 ft.**

LTANKS:

Name:	CENTRE-MAIN ASSOCIATES
Address:	75 - 77 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0311823 / 2004-12-30
Facility ID:	0311823
Site ID:	149369
Spill Date:	2004-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-21
CID:	44
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2005-01-10
Spiller Name:	ED
Spiller Company:	Not reported
Spiller Address:	75 - 77 CENTER AVE
Spiller County:	001
Spiller Contact:	ED
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127066

CENTRE-MAIN ASSOCIATES (Continued) **S106123770**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 1/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson, WCDOH dated 30Dec2004. WCDOH requires NFA at this time."
Remarks: "recommend, uncover repair and retest. Tank is bolted in basement."

All TTF:

Facility ID:	0311823
Spill Number:	0311823
Spill Tank Test:	1528926
Site ID:	149369
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	149369
Operable Unit ID:	877137
Operable Unit:	01
Material ID:	497066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N134 **MR CHIMNEY CLEAN** **RCRA NonGen / NLR** **1004758604**
SSW **32 RELYEA PL** **FINDS** **NYD987011855**
< 1/8 **NEW ROCHELLE, NY 10801** **ECHO**
0.124 mi. **NY MANIFEST**
656 ft. **Site 4 of 11 in cluster N**

Relative: **Higher**
Actual: **90 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MR CHIMNEY CLEAN	
Handler Address:		32 RELYEA PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD987011855
Contact Name:		MAURICE MCKENNA
Contact Address:		RELYEA PL
Contact City,State,Zip:		NEW ROCHELLE, NY 10801
Contact Telephone:		914-632-6660
Contact Fax:		Not reported
Contact Email:		Not reported

MR CHIMNEY CLEAN (Continued) **1004758604**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	RELYEA PL
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	NAUAL MOTION PICTURES
Owner Type:	Private
Operator Name:	NAUAL MOTION PICTURES
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

MR CHIMNEY CLEAN (Continued) **1004758604**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	X002
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NAUAL MOTION PICTURES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	270 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-2406
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NAUAL MOTION PICTURES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	270 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-2406
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NAUAL MOTION PICTURES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	270 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-2406

MR CHIMNEY CLEAN (Continued) **1004758604**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: MR CHIMNEY CLEAN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MR CHIMNEY CLEAN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940601
Handler Name: MR CHIMNEY CLEAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

MR CHIMNEY CLEAN (Continued) **1004758604**

FINDS:
Registry ID: 110004493922

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758604
Registry ID:	110004493922
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004493922
Name:	MR CHIMNEY CLEAN
Address:	32 RELYEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	NAVAL MOTION PICTURE SERVICE
Address:	32 RELYEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD987011855
Facility Status:	Not reported
Location Address 1:	270 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987011855
Mailing Name:	NAVAL MOTION PICTURE SERVICE
Mailing Contact:	PAUL RAMOS
Mailing Address 1:	270 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

Q135
ENE
1/8-1/4
0.126 mi.
667 ft.

MACYS
33 LE COUNT PLACE
NEW ROCHELLE, NY

Site 4 of 4 in cluster Q

NY MANIFEST **1009232715**
N/A

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

Name:	MACYS
Address:	33 LE COUNT PLACE
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP000890137
Facility Status:	Not reported
Location Address 1:	33 LE COUNT PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000890137
Mailing Name:	MACYS
Mailing Contact:	MACYS
Mailing Address 1:	33 LE COUNT PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337700

P136
SSE
1/8-1/4
0.128 mi.
676 ft.

COMMERCIAL PROPERTY
522 MAIN STREET
NEW ROCHELLE, NY

Site 9 of 17 in cluster P

NY LTANKS **S111012266**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	522 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1100723 / 2011-06-06
Facility ID:	1100723
Site ID:	448142
Spill Date:	2011-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-20
CID:	Not reported
Water Affected:	Not reported

COMMERCIAL PROPERTY (Continued) **S111012266**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-20
Spill Record Last Update:	2011-06-06
Spiller Name:	PETER OH
Spiller Company:	ADELPHI
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JEFF
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402739
DEC Memo:	"Spoke to Georgia at Advanced. Soil boring had field evidence of petroleum impact. DT 4/20/11 6/6/11: Report from Preferred Environmental entered into eDocs. NFA jod"
Remarks:	"1721 THE CALLER ADVISED DISPATCH THEY ARE AWAITING TANK TEST RESULTS."

All Materials:

Site ID:	448142
Operable Unit ID:	1198388
Operable Unit:	01
Material ID:	2194662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

R137 **MAISON 347 LLC** **NY UST** **U004274867**
SSW **347 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.128 mi.
678 ft. **Site 4 of 6 in cluster R**

Relative: **Higher**

Actual: **94 ft.**

WESTCHESTER CO. UST:

Name:	MAISON 347 LLC
Address:	347 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-502626 / Active
Operator Name:	Maison 347 LLC
Owner Name:	Maison 347 LLC
Owner Street:	347 Huguenot St
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported

MAISON 347 LLC (Continued) **U004274867**

Tank Number:	1
Status:	1. In-Service
Capacity:	2500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1995
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

P138 **542 MAIN STREET LLC** **NY UST** **U003917838**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.129 mi.
682 ft. **Site 10 of 17 in cluster P**

Relative: **Higher**

Actual: **100 ft.**

WESTCHESTER CO. UST:

Name:	542 MAIN STREET LLC
Address:	542 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-800617 / Active
Operator Name:	Cornell Pace Inc.
Owner Name:	542 Main Street LLC
Owner Street:	542 Main Street, 2nd Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	ANNUAL TIGHTNESS TEST
Date Installation:	01/01/1904
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	2. Rubber liner
Tank External Protection:	ANNUAL TIGHTNESS TEST
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle

542 MAIN STREET LLC (Continued) **U003917838**

Piping Secondary Containment: Not reported
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

P139 **OFFICE BLDG** **NY LTANKS** **S107489194**
SSE **542 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.129 mi.
682 ft. **Site 11 of 17 in cluster P**

Relative: **Higher**
Actual: **100 ft.**

LTANKS:
Name: OFFICE BLDG
Address: 542 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0509995 / 2006-03-22
Facility ID: 0509995
Site ID: 355877
Spill Date: 2005-11-21
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2005-11-21
CID: 407
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-11-21
Spill Record Last Update: 2006-03-22
Spiller Name: UNKNOWN
Spiller Company: OFFICE BLDG
Spiller Address: 542 MAIN STREET
Spiller County: 001
Spiller Contact: UNKNOWN
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 305921
DEC Memo: "March 22, 2006 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: ""

All TTF:
Facility ID: 0509995
Spill Number: 0509995
Spill Tank Test: 1549528
Site ID: 355877
Tank Number: 1
Tank Size: 3000
Material: 0001

OFFICE BLDG (Continued) **S107489194**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	355877
Operable Unit ID:	1113209
Operable Unit:	01
Material ID:	2103275
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S140 **COMMERCIAL BUILDING** **NY LTANKS** **S100177795**
SE **507 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.130 mi.
685 ft. **Site 1 of 6 in cluster S**

Relative:
Higher

Actual:
96 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	507 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9110835 / 1992-03-10
Facility ID:	9110835
Site ID:	286303
Spill Date:	1992-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1992-02-06
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	1992-02-06
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-23

COMMERCIAL BUILDING (Continued) **S100177795**

Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	EPHRAIM ASSOC.
Spiller Address:	300 EAST 74TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	232045
DEC Memo:	""
Remarks:	"BANK AGREEMENT ASSESMENT REVEALED 1K #2 FUEL TANK 12 IN CONCRETE REMAINDER A/G IN BRICK VAULT TANK PULLED TODAY WITH ONE HOLE IN BOTTOM CONCRETE SLAB NOT CRACKED WILL PULL AND INSPECT ON MONDAY"

All Materials:

Site ID:	286303
Operable Unit ID:	960971
Operable Unit:	01
Material ID:	415913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

141
NW
1/8-1/4
0.130 mi.
685 ft.

CON EDISON **RCRA NonGen / NLR** **1019904602**
19 DIVISION ST & WASHINGTON AVE **FINDS** **NYP004800058**
NEW ROCHELLE, NY 10801 **ECHO**

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150628
Handler Name:	CON EDISON	
Handler Address:		19 DIVISION ST & WASHINGTON AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004800058
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2

CON EDISON (Continued) **1019904602**

Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1019904602**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150628
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150628
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069642630

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019904602**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904602
Registry ID:	110069642630
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069642630
Name:	CON EDISON
Address:	19 DIVISION ST & WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

P142 **CON EDISON TRANSFORMER MANHOLE: 5042** **RCRA NonGen / NLR** **1016963458**
SE **MAIN ST & CHRUCH ST** **NY MANIFEST** **NYP004364576**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.130 mi.
687 ft. **Site 12 of 17 in cluster P**

Relative:
Higher

Actual:
97 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20131023
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5042
Handler Address:	MAIN ST & CHRUCH ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004364576
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130923
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5042
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Electronic Manifest Broker: Not reported

Receive Date: 20131023
Handler Name: CON EDISON TRANSFORMER MANHOLE: 5042
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: MAIN ST & CHRUCH ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004364576
Facility Status: Not reported
Location Address 1: MAINS T & CHURCH ST
Code: BP
Location Address 2: TM 5042
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004364576
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

CON EDISON TRANSFORMER MANHOLE: 5042 (Continued) **1016963458**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2013
Trans1 Recv Date:	09/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004364576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694706JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P143 **CON EDISON** **NY MANIFEST** **S117535683**
SE **MAIN ST & CHURCH ST** **N/A**
1/8-1/4 **OSSINING, NY 10801**
0.130 mi.
687 ft. **Site 13 of 17 in cluster P**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MAIN ST & CHURCH ST
City,State,Zip:	OSSINING, NY 10801
Country:	USA
EPA ID:	NYP004680070
Facility Status:	Not reported
Location Address 1:	MAIN ST & CHURCH ST
Code:	BP
Location Address 2:	MH2419
Total Tanks:	Not reported
Location City:	OSSINING
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004680070
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2014
Trans1 Recv Date:	10/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680070
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774891JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117535683**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P144 **CON EDISON MANHOLE: 12758** **RCRA NonGen / NLR** **1016974052**
SE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004478624**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.130 mi.
687 ft. **Site 14 of 17 in cluster P**

Relative: **Higher**
Actual: **97 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140425
Handler Name:	CON EDISON MANHOLE: 12758
Handler Address:	MAIN ST & CHURCH ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004478624
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Historic Generators:
Receive Date: 20140325
Handler Name: CON EDISON MANHOLE: 12758
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140425
Handler Name: CON EDISON MANHOLE: 12758
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: MAIN ST & CHURCH ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004478624
Facility Status: Not reported
Location Address 1: MAIN & CHURCH ST
Code: BP
Location Address 2: SB12758
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004478624

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/2014
Trans1 Recv Date:	03/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478624
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770524JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON MANHOLE: 12758 (Continued) **1016974052**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

P145 **CON EDISON TRANSFORMER MANHOLE: 3586** **RCRA NonGen / NLR** **1016974043**
SE **CHURCH ST & MAIN ST** **NY MANIFEST** **NYP004478517**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.130 mi.
687 ft. **Site 15 of 17 in cluster P**

Relative: **Higher**
Actual: **97 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140425
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3586
Handler Address:	CHURCH ST & MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004478517
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140325
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3586
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140425
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 3586
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	CHURCH ST & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004478517
Facility Status:	Not reported
Location Address 1:	CHURCH MAIN ST
Code:	BP
Location Address 2:	SB3586
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004478517
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/2014
Trans1 Recv Date:	03/25/2014

CON EDISON TRANSFORMER MANHOLE: 3586 (Continued) **1016974043**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478517
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770521JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R146 **COCO RESIDENCE** **NY LTANKS** **S106123934**
South **81 CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.131 mi.
694 ft. **Site 5 of 6 in cluster R**

Relative: LTANKS:
Higher

Actual: Name:	COCO RESIDENCE
100 ft. Address:	81 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0311339 / 2005-01-10
Facility ID:	0311339
Site ID:	313391
Spill Date:	2004-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3

COCO RESIDENCE (Continued) **S106123934**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-01-07
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-07
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ED COCO
Spiller Phone:	(914) 961-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 01/10/05: Letter to Edward D. Coco, Centre-Main Associates from Danielle Jackson dated 9Feb2004(?). WCDOH requires NFA at this time."
Remarks:	"Failed test. Unknown if the tank is leaking"

All TTF:

Facility ID:	0311339
Spill Number:	0311339
Spill Tank Test:	1528899
Site ID:	313391
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313391
Operable Unit ID:	878986
Operable Unit:	01
Material ID:	500153
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

COCO RESIDENCE (Continued) **S106123934**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T147 **CON EDISON** **RCRA NonGen / NLR** **1019902313**
ESE **205 NORTH AVE** **NYP004772265**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.134 mi.
710 ft. **Site 1 of 4 in cluster T**

Relative: **Higher**
Actual: **91 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150422
Handler Name:	CON EDISON	
Handler Address:		205 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004772265
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON (Continued) **1019902313**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019902313**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T148 **CON EDISON** **NY MANIFEST** **S119074690**
ESE **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.134 mi.
710 ft. **Site 2 of 4 in cluster T**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	205 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004772265
Facility Status:	Not reported
Location Address 1:	208 NORTH AVE
Code:	BP
Location Address 2:	SB 2029
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772265
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

CON EDISON (Continued) **S119074690**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454078JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T149 **CON EDISON** **NJ MANIFEST** **S120670860**
ESE **205 NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.134 mi.
710 ft. **Site 3 of 4 in cluster T**

Relative:
Higher

Actual:
91 ft.

NJ MANIFEST:

EPA Id:	NYP004772265
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454078JJK
EPA ID:	NYP004772265
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120670860**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P150 **CON EDISON** **RCRA NonGen / NLR** **1019906923**
South **552 MAIN ST** **FINDS** **NYP004828044**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.136 mi.
718 ft. **Site 16 of 17 in cluster P**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150821
Handler Name:	CON EDISON	
Handler Address:		552 MAIN ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004828044
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019906923**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150821
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150821
Handler Name: CON EDISON	

CON EDISON (Continued) **1019906923**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069679360

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906923
Registry ID:	110069679360
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069679360
Name:	CON EDISON
Address:	552 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

P151 **CON EDISON** **NJ MANIFEST** **S120675741**
South **552 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.136 mi.
718 ft. **Site 17 of 17 in cluster P**

Relative: **Higher**
Actual: **101 ft.**

NJ MANIFEST:

EPA Id:	NYP004828044
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON (Continued) **S120675741**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473164JJK
EPA ID:	NYP004828044
Date Shipped:	8/21/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K152 **CON EDISON MANHOLE: 4175** **RCRA NonGen / NLR** **1016677331**
North **NORTH ST & GARDEN ST** **NY MANIFEST** **NYP004309076**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
726 ft. **Site 5 of 10 in cluster K**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130608
Handler Name:	CON EDISON MANHOLE: 4175
Handler Address:	NORTH ST & GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004309076
Contact Name:	DENNIS ROHRER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130508
Handler Name:	CON EDISON MANHOLE: 4175
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130608
Handler Name:	CON EDISON MANHOLE: 4175
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: NORTH ST & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004309076
Facility Status: Not reported
Location Address 1: NORTH AVE & GARDEN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004309076
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/08/2013
Trans1 Recv Date: 05/08/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/14/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004309076

CON EDISON MANHOLE: 4175 (Continued) **1016677331**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655511JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K153 **CON EDISON MANHOLE 4175** **RCRA NonGen / NLR** **1014918789**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004224085**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.138 mi.
726 ft. **Site 6 of 10 in cluster K**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:	20110214
Handler Name:	CON EDISON MANHOLE 4175
Handler Address:	NORTH AVE & GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004224085
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

Actual:
71 ft.

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110115
Handler Name:	CON EDISON MANHOLE 4175
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110214
Handler Name:	CON EDISON MANHOLE 4175
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	NORTH AVE & GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004224085

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Facility Status: Not reported
Location Address 1: NORTH AV & GARDEN ST
Code: BP
Location Address 2: MH 4175
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004224085
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/15/2011
Trans1 Recv Date: 01/15/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/17/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004224085
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007655781JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON MANHOLE 4175 (Continued) **1014918789**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K154 **CON EDISON SERVICE BOX: 1539** **RCRA NonGen / NLR** **1016972589**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004463667**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.138 mi.
726 ft. **Site 7 of 10 in cluster K**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140411
Handler Name:	CON EDISON SERVICE BOX:	1539
Handler Address:		NORTH AVE & GARDEN ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004463667
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140311
Handler Name:	CON EDISON SERVICE BOX: 1539
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140411
Handler Name: CON EDISON SERVICE BOX:	1539
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	NORTH AVE & GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004463667
Facility Status:	Not reported
Location Address 1:	NO AVE 48 AND 48 GARDEN ST
Code:	BP
Location Address 2:	SB 1539
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004463667
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON SERVICE BOX: 1539 (Continued) **1016972589**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2014
Trans1 Recv Date:	03/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004463667
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772800JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K155 **CON EDISON MANHOLE: 4177** **RCRA NonGen / NLR** **1016451046**
North **NORTH AVE & GARDEN ST** **NY MANIFEST** **NYP004300836**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.138 mi.
726 ft. **Site 8 of 10 in cluster K**

Relative: **Lower**

Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130511
Handler Name:	CON EDISON MANHOLE: 4177
Handler Address:	NORTH AVE & GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004300836
Contact Name:	CHRISTOPHER BLAICH
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130411
Handler Name:	CON EDISON MANHOLE: 4177
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130511
Handler Name:	CON EDISON MANHOLE: 4177
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: NORTH AVE & GARDEN ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004300836
Facility Status: Not reported
Location Address 1: NORTH AVE C/O GARDEN ST
Code: BP
Location Address 2: MH 4177
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004300836
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2013
Trans1 Recv Date: 04/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004300836

CON EDISON MANHOLE: 4177 (Continued) **1016451046**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707795JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K156 **CON EDISON MANHOLE: 20274** **RCRA NonGen / NLR** **1016677685**
North **NORTH AVE & GARDEN ST** **FINDS** **NYP004313615**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.138 mi.
726 ft. **Site 9 of 10 in cluster K**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130615
Handler Name:	CON EDISON MANHOLE: 20274
Handler Address:	NORTH AVE & GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004313615
Contact Name:	CHRISTOPHER BLAICH
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130515
Handler Name:	CON EDISON MANHOLE: 20274
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130615
Handler Name:	CON EDISON MANHOLE: 20274
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058877390

Click Here:

Environmental Interest/Information System:

CON EDISON MANHOLE: 20274 (Continued) **1016677685**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677685
Registry ID:	110058877390
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877390
Name:	CON EDISON MANHOLE: 20274
Address:	NORTH AVE & GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10802

K157 **CON EDISON - MANHOLE 1535** **RCRA-LQG** **1016451189**
North **GARDEN ST AND NORTH AVE** **NY MANIFEST** **NYP004302303**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.138 mi.
726 ft. **Site 10 of 10 in cluster K**

Relative: **Lower**

Actual: **71 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 1535
Handler Address:	GARDEN ST AND NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004302303
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130417
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130417
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 1535
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130417
Handler Name: CON EDISON MANHOLE: 1535
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130517

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

Handler Name: CON EDISON MANHOLE: 1535
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: GARDEN ST & NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004302303
Facility Status: Not reported
Location Address 1: GARDEN ST AND NORTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004302303
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON - MANHOLE 1535 (Continued) **1016451189**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2013
Trans1 Recv Date:	04/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004302303
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456840JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S158 **500 MAIN STREET LAUNDRY SITE** **NY BROWNFIELDS** **S126218333**
SE **500, 506 AND 510 MAIN STREET AND 12 CHURCH STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.141 mi.
744 ft. **Site 2 of 6 in cluster S**

Relative: BROWNFIELDS:
Higher

Name:	500 MAIN STREET LAUNDRY SITE
Address:	500, 506 AND 510 MAIN STREET AND 12 CHURCH STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP

Actual:
96 ft.

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

Site Code:	601437
Acres:	0.790
HW Code:	C360199
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	02/20/2020
Record Updated Date:	02/12/2021
Update By:	RDBENDEL
Site Description:	"Location: The Main Street Laundry Site (site) comprises four tax parcels, totaling approximately 0.79 acres in size, located in an urban area of the City of New Rochelle, Westchester County, New York. The site is located at 500, 506, and 510 Main street and 12 Church Street. The site is bounded to the northwest by Main Street, to the southwest by Church Street, to the southeast by an access driveway and a three- story brick building, and to the northeast by a two-story brick building and an existing private parking lot. The site is approximately 0.25 miles south of the New Rochelle Metro North train station and approximately 0.75 miles west of Echo Bay. Site Features: The site is currently improved with four buildings located on four contiguous tax parcels. 500 Main Street contains a three- story building (including a basement level) currently occupied by the New York Covenant Church. 506 Main Street contains a two- story building that is currently vacant. 510 Main Street contains a three- story brick building occupied by the Liebman s Children's Uniform Clothing store. 12 Church Street contains a multi-story building occupied by the French Speaking Baptist Church of New Rochelle. The portions of the site outside of the building footprints are paved driveways and parking areas. No surface soils are present on the site. Current Zoning and Land Use: The site is located in the Downtown Business District (a/k/a the DB Zone) and is currently used as commercial property. The surrounding properties are mainly commercial with some residential uses. The site redevelopment plan is a mixed-use commercial and residential housing building. Past Use of the Site: The site was originally developed in 1887 as a meat market and laundry that existed until at least 1896. Additional historical uses included lodging, commercial retail, Fire Department Headquarters, auto storage, fur storage, ice rink, and church spaces. The Fire Department was present from 1903 until the 1990s. Several underground storage tanks (USTs) and aboveground storage tanks (ASTs) were noted on-site associated with past site use. Site Geology and Hydrogeology: Site soil consists of fill material over a layer of varied coarse to fine sand with silt to an approximate depth of 2 to 16 feet below ground surface (bgs). Weathered rock was encountered at depths ranging from about 14 to 38 feet bgs. Area bedrock ranges from 20 to 38 feet bgs based on a geotechnical investigation. Groundwater is found in the overburden. Groundwater flow direction is dominantly to the south-southeast towards Long Island Sound, but is influenced by the tides. Groundwater depth ranges from 7.5 to 12 feet bgs. "
Env Problem:	"Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semivolatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), metals, cyanide, pesticides, and the emerging contaminants per- and polyfluorinated substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include SVOCs, metals, and pesticides, in soils, SVOCs in groundwater, and VOCs in soil vapor. Soil: The site is mostly occupied by buildings and the portions of the site outside of

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

building footprints are paved driveways and parking areas. No surface soils are present on the site. Samples of subsurface soil (deeper than 2 inches) were collected throughout the site during the RI to document soil conditions. A total of 36 subsurface soil samples were collected from 24 locations to depths extending to 22 feet below ground surface (bgs). No VOCs, PCBs, or cyanide were detected in subsurface soils above Unrestricted Soil Cleanup Objectives (USCOs). Several SVOCs and metals as well as one pesticide were identified in subsurface soil at concentrations exceeding their USCOs. Exceedances of USCOs were encountered beneath the 500 Main Street and 12 Church Street buildings and access driveways. Exceedances of USCOs were not present beneath the 506 Main Street and 510 Main Street buildings. SVOC concentrations above USCOs were found in subsurface soil samples collected from the southeastern portion of the site. The highest SVOC concentrations were found in soil boring 14 (SB-14) at a depth of 6 feet bgs. SB-14 is located in an access driveway and the vertical extent of the SVOC contamination reaches to 6 feet bgs. The highest concentrations of any SVOCs detected were for benzo(b)fluoranthene and benzo(a)anthracene, both at 18 parts per million (ppm) (USCO: 1 ppm). The next highest concentrations were for benzo(a)pyrene and chrysene, both at 16 ppm (USCO: 1 ppm), benzo(k)fluoranthene at 7 ppm (USCO: 0.8 ppm), indeno(1,2,3-cd)pyrene at 6.7 ppm (USCO: 0.5 ppm), and dibenz(a,h)anthracene at 1.8 ppm (USCO: 0.33 ppm). Metals concentrations above USCOs were found in subsurface soil samples collected from the southern half of the site. The highest concentrations for metals encountered were arsenic at 39.7 ppm (USCO: 13 ppm), lead at 194 ppm (USCO: 63 ppm), mercury at 1.9 ppm (USCO: 0.18 ppm), copper at 59.5 ppm (USCO: 50 ppm), and zinc at 686 ppm (USCO: 109 ppm). The deepest exceedance for metals was found at 20 feet bgs. Pesticide concentrations above USCOs were found in subsurface soil samples collected from the southeastern portion of the site. The highest concentration of a pesticide encountered was for 4,4 -DDT at 0.34 ppm (USCO: 0.0033 ppm) found at a depth of 13 feet bgs. No per- and polyfluoroalkyl substances (PFAS) were detected above the screening level of 1 part per billion (ppb). 1,4-dioxane was not detected in any subsurface soil samples. The presence of SVOCs, metals, and pesticides in subsurface soils is related to the historical use of the site and/or was present in fill material added to the site in the past. There is no indication soil contamination is migrating off-site. Groundwater: Groundwater samples were collected from eight monitoring wells throughout the site. Groundwater samples were analyzed for VOCs, SVOCs, metals, cyanide, pesticides, and PCBs as well as the emerging contaminants PFAS and 1,4-dioxane. No pesticides, PCBs, or cyanide were detected above groundwater standards. The VOCs cis-1,2- dichloroethene and hexachlorobenzene were detected in one well each, respectively at 6.4 parts per billion (ppb) exceeding the groundwater standard of 5 ppb, and 0.044 ppb exceeding the groundwater standard of 0.04 ppb. The SVOCs benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, indeno(1,2,3-cd)pyrene, and phenol were detected above groundwater standards in several wells. The greatest SVOC concentration in groundwater was for benzo(b)fluoranthene at 0.075 ppb (standard: 0.002 ppb). The metals aluminum, iron, magnesium, manganese, and sodium were detected in groundwater samples collected from the site in exceedance of groundwater standards. These metals are common, naturally occurring and/or associated with road salt application, and were present across the site. The metals

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

detected in groundwater are not likely attributed to the site contamination. The metal exceedances found in groundwater were different than the metals that exceeded the SCOs. The SVOCs and VOCs present are attributed to historic site use. 1,4-dioxane was not detected in any wells. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 66.3 and 601 parts per trillion (ppt), respectively, exceeding the 10 ppt screening level for each. PFOA and PFOS were detected in every well above the 10 ppt screening level. The presence of PFAS may be attributed to the historical use of the site as a fire department, the highest concentrations of PFAS in groundwater were near the building (12 Church Street) which was used for fire department headquarters. However, no source of PFOA or PFOS was encountered in subsurface soil. There is a possibility that VOC and SVOC groundwater contamination is migrating off-site. Elevated levels of PFOA and PFOS in groundwater are consistent with concentrations encountered at other nearby Brownfield Cleanup Program (BCP) sites. Soil Vapor: Soil vapor samples were collected at four locations throughout the western half of the site. Two soil vapor samples were collected in the access driveways in the western and southwestern portion of the site at a depth of 5-6 feet bgs, which is approximately 2-3 feet above the groundwater table. The other two soil vapor samples were taken one foot beneath the building slab due to the presence of shallow groundwater. One soil vapor point was located in the basement of 510 Main Street and the other was collected in the basement of 500 Main Street. Soil vapor samples were analyzed for VOCs. There were two VOC detections for one of the constituents listed on the New York State Department of Health (NYS DOH) soil vapor/ indoor air matrices. The VOC trichloroethene (TCE) was detected at 20.8 micrograms per cubic meter (ug/m^3) in a sample collected one foot beneath the 506 Main Street building slab at a location along the northern boundary of the site and at 3.56 ug/m^3 in a sample collected one foot beneath the 510 Main Street building slab along the western boundary of the site. Petroleum related VOCs were detected in several soil vapor points,including, but not limited to, benzene up to 51.5 ug/m^3, methyl ethyl ketone up to 124 ug/m^3,ethanol up to 347 ug/m^3, toluene up to 244 ug/m^3, and m,p-xylene up to 307 ug/m^3. Acetone and chloroform were also detected. Acetone is a common laboratory contaminant, and chloroform is a common byproduct of drinking water chlorination. There are no NYS DOH matrices for these constituents and no action is needed based on the detections. The results of on-site soil vapor sampling indicate further evaluation of soil vapor intrusion for any future buildings on the site is warranted. There are possible off-site sources of soil vapor contamination. Soil vapor intrusion is not expected to be a concern for off-site buildings."

Health Problem: "The site is currently covered with buildings and pavement. People are not expected to come into contact with contaminated soil and groundwater unless they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil vapor (air spaces within the soil), may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. An evaluation of the potential for soil vapor intrusion to occur is recommended for any new buildings built on-site

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

	as part of the expected remediation and site redevelopment. Soil vapor intrusion is not expected to be a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-05-21 10:30:00
Record Upd:	2020-12-10 13:25:00
Updated By:	KAJUNKIN
Own Op:	1
Sub Type:	E
Owner Name:	n/a
Owner Company:	French Speaking Baptist Church of New Rochelle
Owner Address:	12 Church Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	One Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	n/a
Owner Company:	French Speaking Baptist Church of New Rochelle
Owner Address:	12 Church Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Rashid A. Walker
Owner Company:	BRP 500 Main LLC
Owner Address:	c/o BRP Development Corp.
Owner Addr2:	100 Park Avenue, 36th Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Steve Smith
Owner Company:	New Rochelle Tower Owner LLC
Owner Address:	100 Park Avenue, 36th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Jonathan Newman

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

Owner Company:	Leibman's Children's Clothing
Owner Address:	510 Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Steve Smith
Owner Company:	New Rochelle Tower Owner LLC
Owner Address:	100 Park Avenue, 36th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	n/a
Owner Company:	New York Covenant Church
Owner Address:	500 Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Steve Smith
Owner Company:	BRP Main TC Owner LLC
Owner Address:	c/o Corporation System
Owner Addr2:	28 Liberty St.
Owner City,St,Zip:	New York, NY 10005
Owner Country:	United States of America
HW Code:	C360199
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	hexachlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

500 MAIN STREET LAUNDRY SITE (Continued) **S126218333**

HW Code:	C360199
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360199
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

S159 **FORMER CHASE BANK BUIDING** **NY UST** **U003885235**
SE **491 MAIN STREET** **NY AST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.141 mi.
744 ft. **Site 3 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

WESTCHESTER CO. UST:

Name:	FORMER CHASE BANK BUIDING
Address:	491 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-164372 / Active
Operator Name:	Not reported
Owner Name:	DBCHASE LLC c/o Sansome Pacific Properties, Inc
Owner Street:	303 Sacramento Street, 4th Floor
Owner Address2:	Not reported
Owner City:	San Francisco
Owner State:	CA
Owner Zipcode:	94111
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/05/1990
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	FORMER CHASE BANK BUIDING
Address:	491 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-164372
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Not reported
Owner Name:	DBCHASE LLC c/o Sansome Pacific Properties, Inc
Owner Street:	303 Sacramento Street, 4th Floor
Owner Address2:	Not reported
Owner City/State/Zip:	San Francisco, CA 94111
Tank Number:	02
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil

FORMER CHASE BANK BUIDING (Continued) **U003885235**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

S160 **BARCLAYS BANK OF NY/NA** **NY LTANKS** **S100140601**
SE **491 MAIN ST.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.141 mi.
744 ft. **Site 4 of 6 in cluster S**

Relative: LTANKS:
Higher

Name:	BARCLAYS BANK OF NY/NA
Address:	491 MAIN ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8905129 / 1991-03-25
Facility ID:	8905129
Site ID:	299548
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	1997-02-12
Spiller Name:	Not reported
Spiller Company:	BARCLAYS BANK OF NY/NA
Spiller Address:	604 BROAD HOLLOW RD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	242324

Actual:
94 ft.

BARCLAYS BANK OF NY/NA (Continued) **S100140601**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 10/06/89: GND INC. (516) 933-1085 NAT MOSER: 1500 GAL #2 FAILED RETEST -.132GPH. TANK TO BE RELINED OR REPLACED. 03/25/91: TANK REMOVED. "

Remarks: "NAT MOSER (TELECOM 8-23, 1615) WILL CALL BACK AFTER CONTACTING BARCLAYS AND REVIEWING OPTIONS. PETRO TITE 2K 4 GPH"

All TTF:

Facility ID:	8905129
Spill Number:	8905129
Spill Tank Test:	1535898
Site ID:	299548
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	299548
Operable Unit ID:	930451
Operable Unit:	01
Material ID:	445568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S161 **NEW ROCHELLE PUBLIC LIBRARY** **NY LTANKS** **S105995872**
SE **1 LAWTON** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.141 mi.
746 ft. **Site 5 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	CITY NEW ROCHELLE LIBRARY
Address:	1 LAWTON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0201697 / 2002-09-18
Facility ID:	0201697
Site ID:	306611
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE LIBRARY
Spiller Address:	1 LAWTON STREET
Spiller County:	001
Spiller Contact:	FRANK GALLELO
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	274126
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST "

All TTF:

Facility ID:	0201697
Spill Number:	0201697
Spill Tank Test:	1527134
Site ID:	306611
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306611
Operable Unit ID:	852656
Operable Unit:	01
Material ID:	523107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Recovered:	.00
Oxygenate:	Not reported
Name:	NEW ROCHELLE PUBLIC LIBRARY
Address:	1 LAWTON
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1311408 / Not Reported
Facility ID:	1311408
Site ID:	492304
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2015-10-16
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE PUBLIC LIBRARY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROB
Spiller Phone:	(914) 473-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	447251
DEC Memo:	"Tank failed with a dry leak. Will most likely be uncovering, repairing and retesting. WCDOH has been notified...mm 10-15-15 email update request sent to WCHD RDB 10-16-15 Wayne is handling and will forward an update"
Remarks:	""

All TTF:

Facility ID:	1311408
Spill Number:	1311408
Spill Tank Test:	2495159
Site ID:	492304
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus

NEW ROCHELLE PUBLIC LIBRARY (Continued) **S105995872**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MBMASTRO
Last Modified Date:	Not reported

All Materials:

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242331
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	492304
Operable Unit ID:	1241838
Operable Unit:	01
Material ID:	2242328
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

L162 **CIOTTI RESIDENCE** **NY LTANKS S107788125**
NNW **60 GRAND STREET** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.141 mi.
747 ft. **Site 3 of 4 in cluster L**

Relative: **Lower**
Actual: **80 ft.**

LTANKS:

Name:	RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0407555 / 2004-10-07
Facility ID:	0407555
Site ID:	332054
Spill Date:	2004-10-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2004-10-07
CID:	408
Water Affected:	Not reported

CIOTTI RESIDENCE (Continued) **S107788125**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-07
Spill Record Last Update:	2004-11-01
Spiller Name:	ROB HILL
Spiller Company:	RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller County:	001
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 579-3414
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	267201
DEC Memo:	""
Remarks:	"TRUCK DIRVER OVERFILLED AND BLEW A LINE. CREWS ARE IN ROUTE."

All Materials:

Site ID:	332054
Operable Unit ID:	1094311
Operable Unit:	01
Material ID:	574419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SUEZ HYDRANT 17
Address:	60 GRAND ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2005098 / 2021-12-28
Facility ID:	2005098
Facility Type:	ER
DER Facility ID:	559083
Site ID:	610873
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2020-09-03
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2020-09-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported

CIOTTI RESIDENCE (Continued) **S107788125**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-09-03
Spill Record Last Update:	2021-12-28
Spiller Name:	MARK SUMNER
Spiller Company:	UNK
Spiller Address:	57 GRAND ST
Spiller Company:	999
Contact Name:	MARK SUMNER
DEC Memo:	"9/3/2020 just called back and spoke with Mark from Suez, they were replacing a fire hydrant and came across contaminated soil. Mark stated that it appeared to start as a sheen, but was then building on top of itself leading him to believe there may be sludge / free product. He will be sending me over picture shortly that I will forward to you. I also did some research and found that the address listed is in close proximity to a large apartment building. TJP spoke with Beynan, he is going to take a look at this site this afternoon. also spoke with Chris Lalak from WCDOH, he did a search in the PBS database and was unable to find any registered facilities on grand st or Burling Lane where the apartment building is TJP 9/3/2020 Update from Beynan - De minimis sheen on the water surface. No product. There may have been a remote fill pipe at 60 Grand Street but they are on natural gas now. I will follow up with the homeowner regarding the spill and ask if they have a UST. Suez is going to dispose of the water they vac d out and the asphalt, then go ahead with the valve replacement. TJP 09-04-20 No UST was present. Absorbent pads didn't pick anything up on the water surface. Waiting for sample results from Suez to close the spill. BTR"
Remarks:	"caller states crews excavating and unk type petroleum product filling in excavation site. clean up pending."

All Materials:

Site ID:	610873
Operable Unit ID:	1358019
Operable Unit:	01
Material ID:	2369446
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	CIOTTI RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0602271 / 2007-02-16
Facility ID:	0602271
Facility Type:	ER
DER Facility ID:	267201
Site ID:	364705
DEC Region:	3

CIOTTI RESIDENCE (Continued) **S107788125**

Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2006-05-31
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-05-31
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-31
Spill Record Last Update:	2007-02-16
Spiller Name:	ROBERT CIOTTI
Spiller Company:	CIOTTI RESIDENCE
Spiller Address:	60 GRAND STREET
Spiller Company:	001
Contact Name:	ROBERT CIOTTI
DEC Memo:	""
Remarks:	"TESTED THE REMOTE FILL PIPE AND FOUND IT NOT WORKING: 02/15/07 Northeast Envoronmental reported that they excavated 12.31 tons of petroleum impacted soil. NFA TG"

All Materials:

Site ID:	364705
Operable Unit ID:	1122726
Operable Unit:	01
Material ID:	2112202
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	IFO CIOTTI RESIDENCE
Address:	60 GRAND STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601618 / 2006-11-07
Facility ID:	0601618
Facility Type:	ER
DER Facility ID:	267201
Site ID:	363896
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	6010
Spill Date:	2006-05-12
Investigator:	TDGHIOSA

CIOTTI RESIDENCE (Continued) **S107788125**

Referred To:	Not reported
Reported to Dept:	2006-05-12
CID:	408
Water Affected:	STORM DRAINS ON GRAN
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-12
Spill Record Last Update:	2006-11-07
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WAYNE SCHNEIDER
DEC Memo:	"05/12/06 Friday Stefan Goreau reported from the field that the spilled oil resembled motor oil rather than fuel oil, so he doesn't believe that the spill came from the residence. Northeast Environmental was called by the homeowner to do the cleanup but now the homeowner is not considered the RP. Since rain is imminent and Northeast has a vac truck on site, NE was advised to pump the oil out of the drains. DEC to pick up the expense. TG 11/07/06 IRS completed. TG"
Remarks:	"CAUSE IS EITHER TANK OVERFILL OR CHECK VALVE FAILURE."

All Materials:

Site ID:	363896
Operable Unit ID:	1121950
Operable Unit:	01
Material ID:	2111430
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U163 **CON EDISON** **RCRA NonGen / NLR** **1019909012**
South **565 MAIN ST** **NYP004880023**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.142 mi.
750 ft. **Site 1 of 10 in cluster U**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20151216
Handler Name:	CON EDISON	
Handler Address:		565 MAIN ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004880023
Contact Name:		THOMAS TEELING
Contact Address:		Not reported

CON EDISON (Continued) **1019909012**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON (Continued) **1019909012**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151216
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151216
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

U164 **CON EDISON** **NJ MANIFEST** **S120678194**
South **565 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.142 mi.
750 ft. **Site 2 of 10 in cluster U**

Relative:
Higher

Actual:
101 ft.

NJ MANIFEST:

EPA Id:	NYP004880023
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319281JJK
EPA ID:	NYP004880023
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120678194**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

V165 **PROPOSED RESIDENTIAL DEVELOPMENT** **NY BROWNFIELDS S127063304**
North **11 GARDEN STREET** **NY SPDES N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
757 ft. **Site 1 of 5 in cluster V**

Relative: **Lower**
Actual: **71 ft.**

BROWNFIELDS:

Name:	GARDEN ST APARTMENTS
Address:	11 GARDEN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	588043
Acres:	0.902
HW Code:	C360188
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	05/03/2019
Record Updated Date:	12/30/2021
Update By:	AMSERVIS
Site Description:	"Site Location: The site is located at 11 Garden Street in a commercial and residential area of the City of New Rochelle. The site is a triangular shaped parcel approximately 0.9-acres in size. The site is bounded to the north by Garden Street, to the west by mixed commercial/residential structures and to the south and east by the Hartford Railroad. Site Features: The site is currently being developed into a multi-story residential building and construction is nearly finished. Current Zoning and Land Use: The site is currently located in a Downtown Mixed-Use Urban Renewal District. The surrounding properties include various vendors and retailers (mixed commercial/residential use) and the Amtrak and Metro-North train routes. Past Use of the Site: The first known business on the site was a marble works in 1887. By 1896, a dwelling and barn were constructed on the central portions of the site. Between 1896 and 1903, the marble works was replaced with a three-story commercial building that included a saloon. Between 1903 and 1911, a brick oven baking company was constructed on the south-central portion of the site. Between 1911 and 1931, the site was substantially reconfigured with the addition of a cabinet shop, automotive shop and garages as well as repurposing a dwelling to a blacksmith shop and the bakery to a wood working facility. In addition, a structure labelled oils and another circular unspecified structure were located near the woodworking facility on a 1931 Sanborn map depiction of the site. By 1951, the site was cleared of all but two structures; the former saloon and blacksmith shop had each been extended east and repurposed as a paint store and automotive facility, respectively. Between 1996 and 2003, all remaining site structures were demolished. The City of New Rochelle acquired the site in 1998 and has operated a municipal parking lot at the site since the time of acquisition. Site Geology and Hydrogeology: On-site soils consist of medium to coarse-grained sand and gravel fill ranging from 7-18 feet below grade surface (bgs)

PROPOSED RESIDENTIAL DEVELOPMENT (Continued) **S127063304**

underlain by native soils consisting of silty sand extending to depths of 26-40 feet bgs. Weathered bedrock is present beneath native soils. Groundwater is present within native soils at depths ranging from 18.5 to 24.5 feet bgs. Groundwater flow direction beneath the site is to the north toward the Cottage-Garden Auto Repair BCP (C360180) site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included metals and polycyclic aromatic hydrocarbons (PAHs) in soil; and VOCs in soil vapor. Remedial actions have achieved soil cleanup objectives for unrestricted use. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), metals, total petroleum hydrocarbons (TPH), hexavalent chromium, and the emerging contaminants per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, the primary contaminants of concern include SVOCs, metals and pesticides in soil, and VOCs in soil vapor. Soil: Surface soil samples to assess direct human exposure were not collected during the RI due to the lack of exposed surface soil (presence of an asphalt parking lot) within the site boundary. A total of 47 subsurface soil samples were collected from 11 locations across the site to document soil conditions. Soil samples were collected at depths ranging from 1 to 20 feet below grade. Two SVOCs, six metals, and one pesticide (4,4'-DDT) were detected in soil samples collected during the RI at concentrations that exceeded unrestricted soil cleanup objectives (USCOs). Compounds were detected at the following maximum concentrations: benzo(b)fluoranthene (1.2 parts per million (ppm) vs a USCO of 1 ppm), indeno(1,2,3-cd)pyrene (0.56 ppm vs a USCO of 0.5 ppm), copper (61 ppm vs a USCO of 50 ppm), lead (878 ppm vs a USCO of 63 ppm), mercury (0.36 ppm vs a USCO of 0.18 ppm), nickel (60 ppm vs a USCO of 30 ppm), zinc (1,370 ppm vs a USCO of 109 ppm), hexavalent chromium (1.24 ppm vs a USCO of 1 ppm), and 4,4'-DDT (0.00409 ppm vs a USCO of 0.0033 ppm). PFAS compounds including Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were detected below their soil guidance values of 0.66 parts per billion (ppb) and 0.88 ppb respectively. Soil contamination is not expected to migrate off-site. Groundwater: Groundwater samples were collected from four monitoring wells installed at the site as part of the RI. The metals iron, magnesium, manganese, and sodium were detected in groundwater samples in exceedance of groundwater standards. These metals are naturally occurringa component of road salt, and are likely not associated with contamination from the site. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were detected in groundwater samples collected from the site at concentrations up to 55 and 23 parts per trillion (ppt) respectively, exceeding the 10 ppt maximum contaminant level (MCL) for each. Detectable levels of PFAS below their soil guidance values in on-site soils indicate the site is not contributing PFAS to groundwater. The levels observed in the on-site groundwater are consistent with the general conditions for PFAS in groundwater in the New Rochelle area. Additionally, the area is served by municipal water. Soil Vapor: Soil vapor samples were collected at seven locations throughout the site. Soil vapor samples were collected from a depth of 5 ft at three locations and from a depth of 15 ft at four locations. The chlorinated VOC (CVOC) tetrachloroethene (PCE) was detected in four soil vapor samples and

PROPOSED RESIDENTIAL DEVELOPMENT (Continued) **S127063304**

	the CVOC trichloroethene (TCE) was detected in one soil vapor sample. The maximum concentration of PCE detected was 17.6 micrograms per meter cubed (ug/m^3). TCE was detected in one soil vapor sample at a concentration of 12.7 ug/m^3. No on-site source was identified for these soil vapor constituents in the soil or groundwater. Across Garden Street to the north of this site is the BCP site Cottage-Garden Auto Repair (C360180). The RI for the Cottage-Garden Auto Repair site documented impacts from CVOCs to groundwater and soil vapor; however, the Cottage-Garden Auto Repair site is hydraulically down gradient of this site. CVOC concentrations in the soil vapor at the Cottage-Garden Auto Repair site border with Garden Street were in the range of hundreds of ug/m3 as compared to the Garden St. Apartments site border with Garden Street had concentrations in the range of 12-17 ug/m^3. Detection of CVOCs at this site may be a result of migration from the off-site BCP site to the north. "
Health Problem:	"Contact with contaminated soil is no longer a potential concern since all contaminated soil has been removed from the site and replaced with clean fill material. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. A soil vapor intrusion evaluation indicates that soil vapor intrusion is no longer a potential concern for on-site buildings. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-05-25 11:53:00
Record Upd:	2021-11-19 11:18:00
Updated By:	WBBENNET
Own Op:	1
Sub Type:	P03
Owner Name:	David Gallo and Matt Ardito
Owner Company:	Highgarden Tower LLC
Owner Address:	G&G Garden Street LLC, 50 Jericho Quad, Suite 109
Owner Addr2:	Not reported
Owner City,St,Zip:	Jericho, NY 11753
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	David Gallo and Allison Giosa
Owner Company:	G&G Garden Street LLC
Owner Address:	50 Jericho Quadrangle, Suite 109
Owner Addr2:	Not reported
Owner City,St,Zip:	Jericho, NY 11753
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	new rochelle public library
Owner Address:	1 library plaza
Owner Addr2:	Not reported

PROPOSED RESIDENTIAL DEVELOPMENT (Continued) **S127063304**

Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	David Gallo and Matt Ardito
Owner Company:	Highgarden Tower LLC
Owner Address:	G&G Garden Street LLC, 50 Jericho Quad, Suite 109
Owner Addr2:	Not reported
Owner City,St,Zip:	Jericho, NY 11753
Owner Country:	United States of America
HW Code:	C360188
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360188
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360188-08-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-08-31 14:59:00
Record Updated:	2021-08-31 14:59:00
Updated By:	MDKILMER
Crossref ID:	09/05/2019
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2021-08-31 14:59:00
Record Updated:	2021-09-23 13:25:00
Updated By:	WBBENNET

SPDES:

Name:	PROPOSED RESIDENTIAL DEVELOPMENT
Address:	11 GARDEN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Permit Number:	NYR11H658

PROPOSED RESIDENTIAL DEVELOPMENT (Continued) **S127063304**

State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.913435 / -73.783092
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

V166 **GARDEN STREET RESIDENCES** **RCRA NonGen / NLR** **1026834012**
North **11 GARDEN ST** **NYR000249706**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.143 mi.
757 ft. **Site 2 of 5 in cluster V**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:	20210322
Handler Name:	GARDEN STREET RESIDENCES
Handler Address:	11 GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000249706
Contact Name:	MARK J FONTE
Contact Address:	CHURCH ST
Contact City,State,Zip:	TARRYTOWN, NY 10591
Contact Telephone:	914-490-3366
Contact Fax:	Not reported
Contact Email:	MARK@TRIFONT.COM
Contact Title:	CONSTRUCTION MANAGER
EPA Region:	02

Actual:
71 ft.

GARDEN STREET RESIDENCES (Continued) **1026834012**

Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	GARDEN ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	HIGHGARDEN TOWER LLC
Owner Type:	Private
Operator Name:	HIGHGARDEN TOWER LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

GARDEN STREET RESIDENCES (Continued) **1026834012**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	HIGHGARDEN TOWER LLC
Legal Status:	Private
Date Became Current:	20201217
Date Ended Current:	Not reported
Owner/Operator Address:	50 JERICHO QUADRANGLE
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	HIGHGARDEN TOWER LLC
Legal Status:	Private
Date Became Current:	20201217
Date Ended Current:	Not reported
Owner/Operator Address:	50 JERICHO QUADRANGLE
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20210322
Handler Name:	GARDEN STREET RESIDENCES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

GARDEN STREET RESIDENCES (Continued) **1026834012**

List of NAICS Codes and Descriptions:
NAICS Code: 531390
NAICS Description: OTHER ACTIVITIES RELATED TO REAL ESTATE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

U167 **HANGERS CLEANERS** **NY DRYCLEANERS** **S110246761**
South **562-564 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.146 mi.
771 ft. **Site 3 of 10 in cluster U**

Relative:
Higher

Actual:
102 ft.

DRYCLEANERS:
Name: HANGERS CLEANERS
Address: 562-564 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Facility ID: 3-5510-00358
Phone Number: 914-235-0300
Region: Not reported
Registration Effective Date: 9/24/2003 13:22:51:203
Inspection Date: 04MAR23
Install Date: 02
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: CO2
Current Business: Not reported

S168 **ADREAN PRINTING CO** **RCRA NonGen / NLR** **1004755683**
SE **490 MAIN ST** **FINDS** **NY0000233981**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.146 mi. **NY MANIFEST**
773 ft. **Site 6 of 6 in cluster S**

Relative:
Higher

Actual:
94 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: ADREAN PRINTING CO
Handler Address: 490 MAIN ST
Handler City,State,Zip: NEW ROCHELLE, NY 10801
EPA ID: NY0000233981
Contact Name: MICHAEL GOLDBERGER
Contact Address: MAIN ST
Contact City,State,Zip: NEW ROCHELLE, NY 10801
Contact Telephone: 914-636-0200
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported

ADREAN PRINTING CO (Continued) **1004755683**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	MAIN ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	MICHAEL GOLDBERGER
Owner Type:	Private
Operator Name:	MICHAEL GOLDBERGER
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

ADREAN PRINTING CO (Continued) **1004755683**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D011
Waste Description:	SILVER

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MICHAEL GOLDBERGER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	490 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-636-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	MICHAEL GOLDBERGER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	490 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-636-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	MICHAEL GOLDBERGER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	490 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-636-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ADREAN PRINTING CO (Continued) **1004755683**

Historic Generators:

Receive Date:		20060101
Handler Name:	ADREAN PRINTING CO	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20070101
Handler Name:	ADREAN PRINTING CO	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		19940421
Handler Name:	ADREAN PRINTING CO	
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004314297

Click Here:

ADREAN PRINTING CO (Continued) **1004755683**

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755683
Registry ID:	110004314297
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004314297
Name:	ADREAN PRINTING CO
Address:	490 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	ADREAN PRINTING
Address:	490 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NY0000233981
Facility Status:	Not reported
Location Address 1:	490 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000233981
Mailing Name:	ADREAN PRINTING
Mailing Contact:	WILLIAM C WHITE
Mailing Address 1:	490 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146360200

N169 **PRO AUTO PARTS** **RCRA NonGen / NLR** **1001079946**
SSW **41 REYLEA PL** **FINDS** **NYR000016535**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.147 mi. **NY MANIFEST**
774 ft. **Site 5 of 11 in cluster N**

Relative: **Lower**
Actual: **87 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	PRO AUTO PARTS	
Handler Address:		41 REYLEA PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801-6918
EPA ID:		NYR000016535
Contact Name:		Not reported
Contact Address:		SUMMERFIELD ST
Contact City,State,Zip:		SCARSDALE, NY 10853
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		SUMMERFIELD ST
Mailing City,State,Zip:		SCARSDALE, NY 10853
Owner Name:		PRO AUTO PARTS CORP
Owner Type:		Private
Operator Name:		PRO AUTO PARTS CORP
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

PRO AUTO PARTS (Continued) **1001079946**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D010
Waste Description:	SELENIUM

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PRO AUTO PARTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	135 SUMMER FIELD ST
Owner/Operator City,State,Zip:	SCARSDALE, NY 10853
Owner/Operator Telephone:	914-772-4871
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

PRO AUTO PARTS (Continued) **1001079946**

Owner/Operator Name:	PRO AUTO PARTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	135 SUMMER FIELD ST
Owner/Operator City,State,Zip:	SCARSDALE, NY 10853
Owner/Operator Telephone:	914-772-4871
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PRO AUTO PARTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	135 SUMMER FIELD ST
Owner/Operator City,State,Zip:	SCARSDALE, NY 10853
Owner/Operator Telephone:	914-772-4871
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: PRO AUTO PARTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: PRO AUTO PARTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: PRO AUTO PARTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

PRO AUTO PARTS (Continued) **1001079946**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19951116
Handler Name: PRO AUTO PARTS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004520377

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001079946
Registry ID:	110004520377
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004520377
Name:	PRO AUTO PARTS
Address:	41 REYLEA PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	PRO AUTO PARTS
Address:	41 REYLEA PL

PRO AUTO PARTS (Continued) **1001079946**

City,State,Zip: NEW ROCHELLE, NY 10801-6918
Country: USA
EPA ID: NYR000016535
Facility Status: Not reported
Location Address 1: 41 REYLEA PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000016535
Mailing Name: PRO AUTO PARTS
Mailing Contact: PHILIP A MORRIS JR
Mailing Address 1: 135 SUMMERFIELD ROAD
Mailing Address 2: Not reported
Mailing City: SCARSDALE
Mailing State: NY
Mailing Zip: 10583
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9147933336

V170 **NYS THRUWAY AUTHORITY BRIDGE BIN 5514550** **RCRA-LQG** **1000553909**
North **I-95 NORTH AVE OVER NYS THRUWAY I-95** **NY MANIFEST** **NYD986963445**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.147 mi.
778 ft. **Site 3 of 5 in cluster V**

Relative: **Lower**
Actual: **71 ft.**

RCRA-LQG:
Date Form Received by Agency: 20171205
Handler Name: NYS THRUWAY AUTHORITY BRIDGE BIN 5514550
Handler Address: I-95 NORTH AVE OVER NYS THRUWAY I-95
Handler City,State,Zip: NEW ROCHELLE, NY 10801
EPA ID: NYD986963445
Contact Name: MOUSSA KALISSA
Contact Address: EXECUTIVE BLVD STE 400
Contact City,State,Zip: SUFFERN, NY 10901
Contact Telephone: 845-918-2526
Contact Fax: 845-918-2597
Contact Email: MOUSSA.KALISSA@THRUWAY.NY.GOV
Contact Title: ENVIRONMENTAL SPECIALIST
EPA Region: 02
Land Type: State
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R3
Mailing Address: EXECUTIVE BLVD STE 400
Mailing City,State,Zip: SUFFERN, NY 10901
Owner Name: NYS THRUWAY AUTHORITY

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Owner Type:	State
Operator Name:	NYS THRUWAY AUTHORITY
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211125
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NYS THRUWAY AUTHORITY
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12209
Owner/Operator Telephone: 518-436-3190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 518-436-3060
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 189
Owner/Operator City,State,Zip: ALBANY, NY 12201-0189
Owner/Operator Telephone: 518-436-2811
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 189
Owner/Operator City,State,Zip: ALBANY, NY 12201-0189
Owner/Operator Telephone: 518-436-2811
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 189

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Owner/Operator City,State,Zip: ALBANY, NY 12201-0189
Owner/Operator Telephone: 518-436-2811
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTHORITY
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12209
Owner/Operator Telephone: 518-436-3190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 518-436-3060
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NYS THRUWAY AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYS THRUWAY AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYS THRUWAY AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Receive Date: 19910712
Handler Name: NYS THRUWAY AUTH
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20171205
Handler Name: NYS THRUWAY AUTHORITY BRIDGE BIN 5514550
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19920219
Handler Name: NYS THRUWAY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23731
NAICS Description: HIGHWAY, STREET, AND BRIDGE CONSTRUCTION

NAICS Code: 92119
NAICS Description: OTHER GENERAL GOVERNMENT SUPPORT

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: NEW YORK STATE THRUWAY AUTHORITY

NYS THRUWAY AUTHORITY BRIDGE BIN 5514550 (Continued) **1000553909**

Address:	I-95 AT MP 605.76 NORTH AVE OV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD986963445
Facility Status:	Not reported
Location Address 1:	I-95 NORTH & NORTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986963445
Mailing Name:	NEW YORK STATE THRUWAY AUTHORITY
Mailing Contact:	NEW YORK STATE THRUWAY AUTHORITY
Mailing Address 1:	333 SOUTH BROADWAY
Mailing Address 2:	Not reported
Mailing City:	TARRYTOWN
Mailing State:	NY
Mailing Zip:	10591
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

L171 **GUIDANCE CENTER INC** **NY LTANKS** **S102556009**
NNW **70 GRAND ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.148 mi.
784 ft. **Site 4 of 4 in cluster L**

Relative:
Lower

Actual:
80 ft.

LTANKS:

Name:	GUIDANCE CENTER INC
Address:	70 GRAND ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9613894 / 1997-10-03
Facility ID:	9613894
Site ID:	77017
Spill Date:	1997-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-26
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0

GUIDANCE CENTER INC (Continued) **S102556009**

Date Entered In Computer:	1997-02-26
Spill Record Last Update:	1997-10-22
Spiller Name:	STEVEN SMITH
Spiller Company:	GUIDANCE CENTER INC
Spiller Address:	70 GRAND ST
Spiller County:	001
Spiller Contact:	STEVEN SMITH
Spiller Phone:	(914) 636-4440
Spiller Extention:	250
DEC Region:	3
DER Facility ID:	71920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/03/97 LETTER SENT; BASED ON TANK REMOVAL REPORT, NFA; "
Remarks:	"OLD GASOLINE TANK FOUND UNDER THE GROUND - FOUND CONTAMINATED SOIL PHASE 2 COMPLETED - NO REMEDATION STARTED OWNER OF PROPERTY WILL AWAIT DIRECTION FROM DEC ABOUT TANK REMOVAL"

All Materials:

Site ID:	77017
Operable Unit ID:	1041477
Operable Unit:	01
Material ID:	339001
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R172 **FIRST METRO SERVICES** **RCRA NonGen / NLR** **1004759815**
SSW **357 HUGONOT ST** **FINDS** **NYR000022053**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.148 mi.
784 ft. **Site 6 of 6 in cluster R**

Relative: **Higher**
Actual: **93 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	FIRST METRO SERVICES	
Handler Address:		357 HUGONOT ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYR000022053
Contact Name:		BILL LIVANOS
Contact Address:		S DIVISION ST
Contact City,State,Zip:		NEW ROCHELLE, NY 10805
Contact Telephone:		914-576-7210
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported

FIRST METRO SERVICES (Continued) **1004759815**

State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	S DIVISION ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10805
Owner Name:	LEO SATALICH
Owner Type:	Private
Operator Name:	LEO SATALICH
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No

FIRST METRO SERVICES (Continued) **1004759815**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D006
Waste Description:	CADMIUM

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LEO SATALICH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	19 LYON PL
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10805
Owner/Operator Telephone:	914-632-9692
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LEO SATALICH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	19 LYON PL
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10805
Owner/Operator Telephone:	914-632-9692
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LEO SATALICH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	19 LYON PL
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10805
Owner/Operator Telephone:	914-632-9692
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: FIRST METRO SERVICES	
Federal Waste Generator Description:	Not a generator, verified

FIRST METRO SERVICES (Continued) **1004759815**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: FIRST METRO SERVICES
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960409
Handler Name: FIRST METRO SERVICES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004523882

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

FIRST METRO SERVICES (Continued) **1004759815**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004759815
Registry ID:	110004523882
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004523882
Name:	FIRST METRO SERVICES
Address:	357 HUGONOT ST
City,State,Zip:	NEW ROCHELLE, NY 10805

N173 **MP CENTRE LLC** **NY UST** **U004359605**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.152 mi.
800 ft. **Site 6 of 11 in cluster N**

Relative: **Lower**

Actual: **84 ft.**

WESTCHESTER CO. UST:

Name:	MP CENTRE LLC
Address:	10 BARTELS PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-025453 / Active
Operator Name:	MP Centre LLC
Owner Name:	MP Centre LLC
Owner Street:	10 Bartels Place
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	03/11/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed

MP CENTRE LLC (Continued) **U004359605**

Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1980
Date Perm Closure:	08/26/2014
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	unreg 1
Status:	8. Unregistered
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	unreg 2
Status:	8. Unregistered
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported

MP CENTRE LLC (Continued) **U004359605**

Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	unreg 3
Status:	8. Unregistered
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

T174 **14 LE COUNT STANDARD PRINTING** **NY BROWNFIELDS** **S122449231**
East **14 LE COUNT PL, 455 MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.152 mi.
803 ft. **Site 4 of 4 in cluster T**

Relative: **Lower**
Actual: **89 ft.**

BROWNFIELDS:

Name:	14 LE COUNT STANDARD PRINTING
Address:	14 LE COUNT PL, 455 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	568962
Acres:	0.927
HW Code:	C360176
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	04/13/2018
Record Updated Date:	06/09/2021
Update By:	DJEATON
Site Description:	"Location: The site is located mixed-use area of New Rochelle, southwest of Le Count Place, northwest of Main Street, and northeast of North Avenue. Land uses within a quarter-mile of the site are predominantly commercial/residential. Site Features: The site used to contain seven buildings, three of which were vacant. Of the non-vacant buildings, one (455 Main Street) was occupied by a beauty salon and a sportswear store on the first floor and professional offices on the second and third floors; another (459 Main Street) was occupied by a travel agency, hair salon, and medical offices on the first floor and offices on the second floor; and the parking lot on 14 Le Count Place was being utilized by Monroe College for parking,

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

pursuant to a Parking Space License Agreement. There were parking lots on site associated with the existing uses. All buildings on-site have since been demolished, and a new building is under construction. Current Uses and Zoning: As noted above, the site is used for a mixture of retail, residential, and commercial uses. It is zoned for Downtown Business Overlay Zone (DB), which allows for a mix of uses including residential, office, retail, commercial, cultural/entertainment, civic/religious, light industrial, and parking/utilities. Past Use of the Site: Historically, the site has been dedicated to commercial/residential uses. Notable commercial uses include a former printing shop operated by the Evening Standard Newspaper (209 North Avenue), a photo-engraving shop (207 North Avenue) and an undertaker/funeral home (14 Le Count Place). The existing on-site buildings were reportedly constructed between 1903 and 1931. Several Recognized Environmental Concerns (RECs) were identified during Phase I site assessments. The RECs are identified as out of service or previously abandoned USTs and soil contamination as a result of the historic printing operations. Site Geology and Hydrogeology: Beneath an asphalt/concrete surface, surficial historic fill of up to 5 feet deep, consisting of soils similar to the underlying natural residuals, blanket the site. Beneath the fill, the site is underlain by soils formed by the decomposition of the underlying gneiss bedrock. These soils generally consist of silty/clayey sand containing varying percentages of gravel. Weathered gneissic bedrock is typically present at depths on the order of 20 to 25 feet below grade. The regional groundwater flow direction around the site was confirmed during the Remedial Investigation to follow the general topography of the region, which slopes gently downwards towards Echo Bay to the east and southeast of the site. The groundwater depth was measured during the 2017 water sampling event and found to be approximately 18 feet below ground surface. There are two operable units for this site. Operable Unit(OU) 01 is the brownfield-related remedial work and is the subject of this document. OU 02 encompasses the response to a petroleum spill reported on this property. Work on OU 02 is governed by a separate Order on Consent (Index no: CO 3-20190404-74) and is not part of the BCP cleanup. "

Env Problem: "Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Groundwater has not met standards for cis-1,2-dichloroethene and benzene. Residual contamination in the groundwater is being managed with monitored natural attenuation under a Site Management Plan. Prior to remediation, the primary contaminants of concern were metals and PAHs in soil, benzene and cis-1,2-DCE in groundwater and trichloroethene in sub-slab soil vapor. "

Health Problem: "The site has been remediated; therefore, the potential for exposure to contaminated soil or groundwater has been eliminated. In addition, the area is served by a public water supply that is not affected by this contamination. Because the site is vacant, inhalation of site contaminants due to soil vapor intrusion does not represent a current concern. However, a soil vapor intrusion evaluation will be completed and appropriate actions to address exposures will be implemented for any new buildings constructed on the site. Additional investigations are recommended to determine if soil vapor intrusion is a potential concern for offsite buildings."

Dump: False
Structure: False
Lagoon: False

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-07-31 15:59:00
Record Upd:	2019-12-19 16:32:00
Updated By:	JEBROWN
Own Op:	1
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	14 Le Count Place LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	14 Le Count Place LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Bill balter
Owner Company:	WBLM 14 le Count owner llc
Owner Address:	480 bedford road
Owner Addr2:	Not reported
Owner City,St,Zip:	chappaqua, ny, NY 10514
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bill Balter
Owner Company:	WBLM 14 Le Count Owner LLC
Owner Address:	480 Bedford Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Chappaqua, NY 10514
Owner Country:	United States of America
HW Code:	C360176
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

HW Code:	C360176
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176

14 LE COUNT STANDARD PRINTING (Continued) **S122449231**

Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360176
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1808873
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-01-14 11:26:00
Record Updated:	2019-01-14 11:26:00
Updated By:	MAKING
Crossref ID:	1901867
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-05-22 14:53:00
Record Updated:	2019-05-22 14:53:00
Updated By:	GAAHLERS
Crossref ID:	C360176-0818
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2019-12-13 15:05:00
Record Updated:	2019-12-13 15:05:00
Updated By:	MAKING
Crossref ID:	593393378
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-12-18 12:28:00
Record Updated:	2019-12-18 12:28:00
Updated By:	MAKING
Crossref ID:	2009330
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-02-11 08:55:00
Record Updated:	2021-02-11 08:55:00
Updated By:	JBODEE

U175 **MISR REALTY, LLC** **NY UST** **U004259541**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.152 mi.
804 ft. **Site 4 of 10 in cluster U**

Relative: WESTCHESTER CO. UST:
Higher

Actual:
100 ft.

Name:	MISR REALTY, LLC
Address:	573-579 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-800238 / Active
Operator Name:	Pedro Benoit
Owner Name:	MISR Realty LLC
Owner Street:	542 Main Street, 3rd Floor
Owner Address2:	Not reported
Owner City:	New Rochelle
Owner State:	NY
Owner Zipcode:	10801
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	Not reported
Date Perm Closure:	11/01/2004
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

U176 **MISR REALTY, LLC** **NY AST** **U004176186**
South **573-579 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.152 mi.
804 ft. **Site 5 of 10 in cluster U**

Relative: WESTCHESTER CO. AST:
Higher

Actual:
100 ft.

Name:	MISR REALTY, LLC
Address:	573-579 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-800238
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Pedro Benoit
Owner Name:	MISR Realty LLC
Owner Street:	542 Main Street, 3rd Floor
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801

MISR REALTY, LLC (Continued) **U004176186**

Tank Number:	001
Status:	1. In-Service
Date Installation:	09/01/2004
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,99. Other
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

N177 **INDUST OVERALL SERVICE CORP** **NY LTANKS** **S116555778**
SW **10 BARTELS PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.154 mi.
811 ft. **Site 7 of 11 in cluster N**

Relative: LTANKS:
Lower

Name:	INDUST OVERALL SERVICE CORP
Address:	10 BARTELS PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1400928 / 2017-03-30
Facility ID:	1400928
Site ID:	494186
Spill Date:	2014-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	ELMOORE
Referred To:	Not reported
Reported to Dept:	2014-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-28
Spill Record Last Update:	2022-02-25
Spiller Name:	BOB OBRIEN
Spiller Company:	INDUSTRIAL OVERALL SERV CORP
Spiller Address:	10 BARTELL PL
Spiller County:	999

Actual:
81 ft.

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Spiller Contact:	BOB OBRIEN
Spiller Phone:	(914) 235-1220
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449117
DEC Memo:	"4-28-14: Chris/WCHD call to Dispt./V.Mc.: Heating oil tank, out of service, failed test. 3/30/2017 -- Carlos drove by this week and the soil pile has been removed. This spill can be closed, with the entire site clean-up being accomplished under Haz Waste. 360109 ELM"
Remarks:	"tank 2 5000 gallon"

All TTF:

Facility ID:	1400928
Spill Number:	1400928
Spill Tank Test:	2495577
Site ID:	494186
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	True
UST:	True
Cause:	03
Source:	00
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

Facility ID:	1400928
Spill Number:	1400928
Spill Tank Test:	2495578
Site ID:	494186
Tank Number:	2
Tank Size:	5000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	494186
Operable Unit ID:	1243715
Operable Unit:	01
Material ID:	2244419
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

INDUST OVERALL SERVICE CORP (Continued) **S116555778**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

U178 **CON EDISON TRANSFORMER MANHOLE: 2750** **RCRA NonGen / NLR** **1016677840**
South **CENTRE AVE & MAIN ST** **FINDS** **NYP004315198**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.154 mi. **NY MANIFEST**
814 ft. **Site 6 of 10 in cluster U**

Relative: **Higher**

Actual: **100 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130621
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2750
Handler Address:	CENTRE AVE & MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004315198
Contact Name:	DENNIS ROHRER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130521
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2750
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130621
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2750
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058871369

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677840
Registry ID:	110058871369
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058871369
Name:	CON EDISON TRANSFORMER MANHOLE: 2750
Address:	CENTRE AVE & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	CON EDISON
Address:	CENTRE AVE & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004315198
Facility Status:	Not reported
Location Address 1:	CENTRE ST & MAIN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004315198
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/2013
Trans1 Recv Date:	05/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004315198
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007019053JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON TRANSFORMER MANHOLE: 2750 (Continued) **1016677840**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U179 **CON EDISON** **RCRA NonGen / NLR** **1019901339**
South **CENTRE & MAIN ST** **FINDS** **NYP004760815**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.154 mi.
814 ft. **Site 7 of 10 in cluster U**

Relative: **Higher**
Actual: **100 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150331
Handler Name:	CON EDISON	
Handler Address:		CENTRE & MAIN ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004760815
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019901339**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150331

CON EDISON (Continued) **1019901339**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069701530

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901339
Registry ID: 110069701530
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069701530
Name: CON EDISON
Address: CENTRE & MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10801

U180 **CON EDISON** **NJ MANIFEST** **S120669849**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
814 ft. **Site 8 of 10 in cluster U**

Relative: **Higher**
Actual: **100 ft.**

NJ MANIFEST:
EPA Id: NYP004760815
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported

CON EDISON (Continued) **S120669849**

Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091694JJK
EPA ID:	NYP004760815
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U181 **CON EDISON** **NY MANIFEST** **S117318285**
South **MAIN ST & CENTRE ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
814 ft. **Site 9 of 10 in cluster U**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MAIN ST & CENTRE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004658019
Facility Status:	Not reported
Location Address 1:	MAIN ST & CENTRE ST
Code:	BP
Location Address 2:	MH734
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004658019
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2014
Trans1 Recv Date:	09/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004658019
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771786JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117318285**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U182 **CON ED** **NY MANIFEST** **S119074042**
South **CENTRE & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
814 ft. **Site 10 of 10 in cluster U**

Relative: **Higher**

Actual: **100 ft.**

NY MANIFEST:

Name:	CON ED
Address:	CENTRE & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004760815
Facility Status:	Not reported
Location Address 1:	CENTRE AVE & MAIN ST
Code:	BP
Location Address 2:	TM 2750
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760815
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON ED (Continued) **S119074042**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760815
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091694JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N183 **INDUSTRIAL OVERALL** **NY SHWS** **S110043643**
SW **10 BARTELS PLACE** **NY CBS** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
815 ft. **Site 8 of 11 in cluster N**

Relative:
Lower

Actual:
81 ft.

SHWS:
Name: INDUSTRIAL OVERALL SERVICE CORP.
Address: 10 BARTELS PLACE
City,State,Zip: NEW ROCHELLE, NY 10801-7241
Program: HW
Site Code: 413917
Classification: Significant threat to the public health or environment - action required.
Region: 3
Acres: 0.420
HW Code: 360109
Record Add: 05/15/2009
Record Upd: 07/10/2020
Updated By: KJCARPEN
Site Description: "Location: The Industrial Overall Service Corporation site is located at 10 Bartels Place in the City of New Rochelle, Westchester County. The site is located east of I-95 and west of US-1 (Huguenot Street) and it is bounded by Relyea Place, Bartels Place, Centre Avenue and the Metro North railroad property and tracks. Site Features: The site is 0.53 acres in size and resides on a slightly sloping irregularly shaped property consisting of two tax parcels. The main site feature includes a six-sided building which occupies the majority of the property and a small parking area located to the south and southwest of the building. Current Zoning/ Uses: This property is zoned for commercial use. The building was sold in 2019 and site use remains commercial in nature. The surrounding area is a mix of commercial and residential establishments situated in an urban setting. Past Uses of the Site: Industrial Overall Service Corporation operated at this location as a uniform and industrial clothing dry cleaning/laundering facility, historically cleaning heavily soiled clothing from industrial, auto body and gasoline dispensing businesses from 1956 until 2010. Dry cleaning equipment was reportedly decommissioned in 1980, but water washing continued. From 1980-1998 Workingman s Closet, an embroidery and uniform retail outfit, operated on the second floor of the building. From 2010 until 2016, Apparel Plus Textile Rental LLC ran a rental linen service company on both floors of the building, which involved water laundering. Historically, a precision scale company also operated out of the second floor of the building from sometime between 1932 and 1956 until sometime before 1973 when Industrial Overall purchased the building to occupy it entirely. Based on a Sanborn Fire Insurance Map from 1931, the site previously operated an automobile sales and service business. This site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site and adjacent Metro-north property. OU1 consists of the entire site property with the addition of an off-site source area which lies to the northeast of the site on the adjacent Metro-north property. Operable unit 2 (OU2) is the off-site groundwater plume. Site Geology and Hydrology: Groundwater is found in the overburden and in the bedrock. Groundwater is generally found 10 to 15 feet

INDUSTRIAL OVERALL (Continued) **S110043643**

below ground surface and flows in a southwesterly direction. Overburden in the vicinity ranges in thickness from 2.2 feet to 32 feet, and consists of fill material (1-5 feet in thickness) and varied amounts of fine to coarse sand with varying amounts of silt. Below the sandy silt is a till like material. Depth to bedrock is variable across the site from a depth of a few feet to over 35 feet below grade. Bedrock in the vicinity is a highly weathered rock which is undulating in nature and is generally more transmissive than the till-like overburden material directly above. "

Env Problem: "OU1: On-Site and Adjacent Metro North Property Nature and Extent of Contamination: The primary contaminants of concern at the site include the dry cleaning chemicals tetrachloroethene (PCE), trichloroethene (TCE) and their associated breakdown products. PCE and TCE are found in on-site and off-site soil and groundwater. Two primary source areas remain at and adjacent to the site. These include a lint trap within on-site building and an off-site debris and waste disposal area located to the northwest outside the building on the adjacent Metro North Railroad property. Soil: Maximum concentrations of PCE and TCE in on-site soils/wastes located in the remaining lint trap source area exceed 21,000 parts per million (ppm) and 1,200 ppm, respectively. In addition to volatile organic compounds (VOCs), soils on- and off-site were also sampled for semi-volatile organic compounds (SVOCs) and metals. No SVOCs exceeded SCOs, but several metals (barium, cadmium, chromium, lead, and silver) exceeded their respective unrestricted use SCOs directly underneath the lint trap. Also under the lint trap, barium, cadmium, and lead exceeded commercial SCOs, while only barium out of these metals did not exceed protection of groundwater SCOs. Also chromium exceeds the protection of groundwater SCO in one off-site location. On-site and off-site soil contains VOCs mainly in the two source areas, but some soil located under the site parking lot also contained VOCs above protection of groundwater SCOs of 0.47 ppm for TCE and 1.3 ppm for PCE. Generally, however, concentrations of PCE and TCE in on-site soils decrease to below the soil cleanup objectives (SCOs) for the protection of groundwater not far from the actual lint trap. The debris and waste disposal source area on the off-site Metro North property contains a maximum PCE concentration of 500 ppm and a maximum TCE concentration of 11 ppm. Groundwater: Contamination migrating from the two source areas has impacted groundwater in the bedrock and overburden, and created a plume extending downgradient (southwest) more than 1,900 feet from the site. The highest level of PCE in on-site groundwater was 140,000 parts per billion (ppb) near the lint trap, compared to the groundwater standard of 5 ppb. On the adjacent off-site Metro North Railroad property, PCE concentrations in groundwater reached 3,600 ppb. The maximum level of TCE in on-site groundwater was 13,000 ppb near the lint trap, and 1,800 ppb beneath the adjacent off-site Metro North Railroad property, compared to the groundwater standard of 5 ppb. TCE was also detected upgradient of the site at 5,300 ppb indicating a second potential off-site upgradient source. Several breakdown products of PCE and TCE were also noted in the groundwater. The maximum on-site cis-1,2 dichloroethene (cis-1,2 DCE) concentration was 27,000 ppb near the lint trap, and 130 ppb beneath the off-site adjacent Metro North Railroad property. The maximum on-site vinyl chloride (VC) concentration was 1,600 ppb near the lint trap compared to the groundwater standard of 2 ppb.1-1-1 trichloroethane (1,1,1-TCA) was detected on-site at a maximum

INDUSTRIAL OVERALL (Continued) **S110043643**

concentration of 730 ppb beneath the on-site building, compared to the groundwater standard of 5 ppb. However, 1,1,1-TCA was also detected upgradient of the site at 910 ppb indicating an off-site, upgradient source. Soil Vapor, Sub-slab Vapor and Indoor Air: Mitigation of Soil Vapor Intrusion within the on-site building was completed in March 2019. In January 2019, the sale of and plans for occupancy of the on-site building required a soil vapor intrusion (SVI) evaluation to occur. Prior to remediation, the sub-slab soil vapor Samples had maximum concentrations of 19,000 ug/m3 of 1,1,1-TCA, 8,800 ug/m3 of 1,1-dichloroethene, 650 ug/m3 of cis-1,2-DCE, 28,000 ug/m3 of PCE, and 37,000 ug/m3 of TCE. Indoor air contained a maximum concentration of 2.1 ug/m3 of TCE. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. No significant environmental resources have been identified near the site. Based upon the resources and pathways identified and the toxicity of the contaminants of ecological concern at this site, a Fish and Wildlife Resources Impact Analysis (FWRIA) was deemed not necessary for OU 01. OU2: Off-site Groundwater and Associated Soil Vapor Intrusion Impacts Soil: Soil contamination was not yet identified in OU2. Groundwater: Determination of the extent of OU2 groundwater contamination is ongoing. However, contamination migrating from the two source areas in OU1 has impacted groundwater in the bedrock and overburden, and created a plume of PCE and degredation compounds extending downgradient (southwest) more than 1,900 feet from the site. Soil Vapor, Sub-slab Vapor and Indoor Air: Determination of the nature and extent of OU2 soil vapor intrusion impacts is ongoing. However, fourteen residential or commercial structures were sampled during the investigation for OU1. Vapor control measures were taken in two structures, and five structures continue to be monitored for soil vapor intrusion. "

Health Problem: "Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Most of the site is covered with pavement and buildings; however, trespassers or employees walking, digging, or otherwise disturbing the soil on the adjacent Metro North property could come in contact with site-related contaminants. Volatile organic compounds in the soil or groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site redevelopment. Sub-slab depressurization systems have been installed in two off-site residential buildings to prevent the inhalation of site-related contamination. In addition, air monitoring is on-going at five additional off-site residential buildings to verify further actions are not needed. Sampling indicates soil vapor intrusion may be a concern for additional off-site buildings and sampling is recommended."

Dump: False
Structure: False
Lagoon: False

INDUSTRIAL OVERALL (Continued) **S110043643**

Landfill:	False
Pond:	False
Disp Start:	UNKNOWN
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-06-11 15:11:00
Record Upd:	2017-03-16 13:50:00
Updated By:	KATHOMPS
Own Op:	1
Sub Type:	NNN
Owner Name:	ROBERT O'BRIEN
Owner Company:	WORKING MAN'S CLOSET, INC
Owner Address:	3 KOLBERT DRIVE
Owner Addr2:	Not reported
Owner City,St,Zip:	SCARSDALE, NY 10583
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	08
Owner Name:	Robert R. O'Brien
Owner Company:	Apparel + Plus Textile Rental, LLC
Owner Address:	27 Centre Avenue/10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Region 3 Headquarters
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	21 South Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	Mr Burton Dorfman, Esq.
Owner Company:	Industrial Overall Service Corporation
Owner Address:	10 Bartells Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	360109
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	360109
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

INDUSTRIAL OVERALL (Continued) **S110043643**

HW Code: 360109
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: 1,1-dichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 360109
Waste Type: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1309988
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-04-14 11:03:00
Record Updated: 2014-04-14 11:03:00
Updated By: RDBENDEL
Crossref ID: 1310684
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-02-14 08:19:00
Record Updated: 2014-02-14 08:19:00
Updated By: ELMOORE
Crossref ID: 592743106
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-10-02 14:25:00
Record Updated: 2019-10-02 14:25:00
Updated By: KATHOMPS
Crossref ID: 360087
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-05-21 15:07:00
Record Updated: 2009-05-21 15:07:00
Updated By: RXKEATIN

CBS:
Name: INDUSTRIAL OVERALL
Address: 10 BARTELS PLACE
City,State,Zip: NEW ROCHELLE, NY 10801

INDUSTRIAL OVERALL (Continued) **S110043643**

CBS Number:	3-000235
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	3
UTMX:	602235.01207
UTMY:	4529263.44535

N184 **NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP** **NJ MANIFEST** **S120679001**
SW **10 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
815 ft. **Site 9 of 11 in cluster N**

Relative: **Lower**
Actual: **81 ft.**

NJ MANIFEST:

EPA Id:	NYR000208967
Mail Address:	BARTELS PL
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ROBERT R OBRIEN
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010914098JJK
EPA ID:	NYR000208967
Date Shipped:	1/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Manifest Number:	000959895GBF
EPA ID:	NYR000208967
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **S120679001**

Manifest Number:	014168256JJK
EPA ID:	NYR000208967
Date Shipped:	10/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

N185 **NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP** **RCRA-LQG** **1016678149**
SW **10 BARTELS PL** **NY Spills** **NYR000208967**
1/8-1/4 **NEW ROCHELLE, NY 10801** **FINDS**
0.154 mi. **ECHO**
815 ft. **Site 10 of 11 in cluster N** **NY MANIFEST**

Relative: **Lower**
Actual: **81 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160419
Handler Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Handler Address:	10 BARTELS PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000208967
Contact Name:	DAVID CROSBY
Contact Address:	BROADWAY
Contact City,State,Zip:	ALBANY, NY 12233

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Contact Telephone:	518-402-9662
Contact Fax:	Not reported
Contact Email:	DAVID.CROSBY@DEC.NY.GOV
Contact Title:	NYSDEC REMEDIATION
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	CENTRE AVE
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	ROBERT OBRIEN
Owner Type:	Private
Operator Name:	ROBERT OBRIEN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	INDUSTRIAL OVERALL SERVICE CORP
Legal Status:	Private
Date Became Current:	19500601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROBERT OBRIEN
Legal Status:	Private
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	27 CENTRE AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	INDUSTRIAL OVERALL SERVICE CORP
Legal Status:	Private
Date Became Current:	20100823
Date Ended Current:	Not reported
Owner/Operator Address:	10 BARTELS PL
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-235-1220
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROBERT OBRIEN
Legal Status:	Private
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	27 CENTRE AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	INDUSTRIAL OVERALL SERVICE CORP
Legal Status:	Private
Date Became Current:	20100823
Date Ended Current:	Not reported
Owner/Operator Address:	10 BARTELS PL
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-235-1220

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: INDUSTRIAL OVERALL SERVICE CORP
Legal Status: Private
Date Became Current: 19500601
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20160419
Handler Name: NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141209
Handler Name: INDUSTRIAL OVERALL SERVICE CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140331
Handler Name: INDUSTRIAL OVERALL SERVICE CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

List of NAICS Codes and Descriptions:
NAICS Code: 812331
NAICS Description: LINEN SUPPLY

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20140318
Actual Return to Compliance Date: 20140708
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20140331
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Yes
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYMOC
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20140318
Actual Return to Compliance Date: 20140708
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20140331
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Corrective Action Component: Yes
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYMOC
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20140318
Actual Return to Compliance Date: 20140708
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20140714
Enforcement Responsible Agency: State
Enforcement Docket Number: R3-20140301-51
Enforcement Attorney: ZK
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYMOC
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Proposed Amount:	Not reported
Final Monetary Amount:	12000
Paid Amount:	12000
Final Count:	1
Final Amount:	12000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20140318
Actual Return to Compliance Date:	20140708
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20140415
Enforcement Responsible Agency:	State
Enforcement Docket Number:	R3-20140301-51
Enforcement Attorney:	ZK
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYMOC
Enforcement Responsible Sub-Organization:	R3
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	10000
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20140318
Actual Return to Compliance Date:	20140708
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20140415
Enforcement Responsible Agency:	State
Enforcement Docket Number:	R3-20140301-51
Enforcement Attorney:	ZK

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYMOC
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 10000
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20140318
Actual Return to Compliance Date: 20140708
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20140714
Enforcement Responsible Agency: State
Enforcement Docket Number: R3-20140301-51
Enforcement Attorney: ZK
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYMOC
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Proposed Amount:	Not reported
Final Monetary Amount:	12000
Paid Amount:	12000
Final Count:	1
Final Amount:	12000
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20140401
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Evaluation Date:	20140318
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20140401
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20140318
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20140401
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20140318
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYMOC

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20140708
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20140708
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NOT A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYMOC
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SPILLS:

Name:	DRY CLEANER MP CENTER LLC
Address:	10 BARTELS PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2109982 / Not Reported
Facility ID:	2109982
Facility Type:	ER
DER Facility ID:	449117
Site ID:	634013
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2022-02-23
Investigator:	MRDOMARA
Referred To:	Not reported
Reported to Dept:	2022-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2022-02-24
Spill Record Last Update:	2022-02-25
Spiller Name:	GARY GIOGLO
Spiller Company:	MP CENTER LLC
Spiller Address:	10 BARTLES PLACE
Spiller Company:	999
Contact Name:	GARY GIOGLO
DEC Memo:	"2/24/22 two #2 fuel oil USTs were removed as part of remedial

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

activities currently occurring at the spill site. Location is a commercial site (dry cleaners). Tanks are registered with Westchester County DOH PBS #3-025543. Following removal of the tanks, holes were identified and impacted soils were encountered. Excavation is expected but discussions with the site owner are currently ongoing. BW 2/25/22: This is State Superfund Site HW360109. jod"

Remarks: "clean up in progress"

All Materials:

Site ID:	634013
Operable Unit ID:	1381089
Operable Unit:	01
Material ID:	2395039
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

FINDS:

Registry ID: 110058881152

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016678149
Registry ID:	110058881152
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058881152
Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address:	10 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Address:	10 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000208967
Facility Status:	Not reported
Location Address 1:	10 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000208967
Mailing Name:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Contact:	NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP
Mailing Address 1:	10 BARTELS PL
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000208967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014168256JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds

NYSDEC-SITE 360109 INDUSTRIAL OVERALL SERVICE CORP (Continued) **1016678149**

Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N186 **INDUSTRIAL OVERALL** **NY AST S105455801**
SW **10 BARTELS PLACE** **NY CBS AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.154 mi.
815 ft. **Site 11 of 11 in cluster N**

Relative: **Lower**

Actual: **81 ft.**

AST:

Name:	INDUSTRIAL OVERALL
Address:	10 BARTELS PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Region:	STATE
DEC Region:	3
Site Status:	Unregulated/Closed
Facility Id:	3-000235
Program Type:	CBS
UTM X:	602235.01207
UTM Y:	4529263.44535
Expiration Date:	N/A
Site Type:	Unknown

Tank Info:

Tank Number:	001
Tank Id:	188570
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/1990
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/1990
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

NY CBS AST:

No Details:	No Details

187
NNW
1/8-1/4
0.155 mi.
821 ft.

RITZCOVAN - TTF
22 BURLING LANE
NEW ROCHELLE, NY

NY LTANKS

S118263505
N/A

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	RITZCOVAN - TTF
Address:	22 BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1506693 / 2016-03-22
Facility ID:	1506693
Site ID:	514123
Spill Date:	2015-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2016-03-22
Spiller Name:	Not given
Spiller Company:	Ritzcovan (Owner)
Spiller Address:	22 BURLING LANE
Spiller County:	999
Spiller Contact:	BRUCE
Spiller Phone:	9147120600
Spiller Extention:	1
DEC Region:	3
DER Facility ID:	468599
DEC Memo:	"9/24/15 Spoke to Bruce, the contact, who is trying to arrange tank removal, as he is tentatively purchasing the property from Ritzcovan. I gave him a list of contractors in Westchester. dw 3/22/16: Grazi-1 Environmental disposed of the leaking UST and approximately 10.15 tons of petroleum contaminated soil. Soil sample results submitted for review. Tank Closure Report entered into DecDocs system. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"unknown whether contaminated. option recover & repair, or remove; unknown at this time"

All TTF:

Facility ID:	1506693
Spill Number:	1506693
Spill Tank Test:	2498471
Site ID:	514123
Tank Number:	Not reported
Tank Size:	275
Material:	0001

RITZCOVAN - TTF (Continued) **S118263505**

EPA UST:	False
UST:	True
Cause:	00
Source:	00
Test Method:	NN
Test Method 2:	Testing Not Required
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	DXWEITZ
Last Modified Date:	Not reported

All Materials:

Site ID:	514123
Operable Unit ID:	1263331
Operable Unit:	01
Material ID:	2267021
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

V188 **CON EDISON MANHOLE: 12245** **RCRA NonGen / NLR** **1016677186**
North **NORTH AVE & BURLING LANE** **FINDS** **NYP004307492**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.156 mi. **NY MANIFEST**
824 ft. **Site 4 of 5 in cluster V**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130606
Handler Name:	CON EDISON MANHOLE: 12245
Handler Address:	NORTH AVE & BURLING LANE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004307492
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20130506
Handler Name: CON EDISON MANHOLE: 12245
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130606
Handler Name: CON EDISON MANHOLE: 12245
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058877531

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

ECHO:

Envid:	1016677186
Registry ID:	110058877531
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877531
Name:	CON EDISON MANHOLE: 12245
Address:	NORTH AVE & BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & BURLING LANE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004307492
Facility Status:	Not reported
Location Address 1:	NORTH AVE & BURLING LANE
Code:	BP
Location Address 2:	MH 12245
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10580
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004307492
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	05/07/2013
TSD Site Recv Date:	05/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307492
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	004816866FLE

CON EDISON MANHOLE: 12245 (Continued) **1016677186**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W189 **CASARRA RESIDENCE** **NY LTANKS** **S105997517**
West **9 BADEAU PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.164 mi.
864 ft. **Site 1 of 4 in cluster W**

Relative:
Higher

Actual:
104 ft.

LTANKS:

Name:	CASARRA RESIDENCE
Address:	9 BADEAU PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209171 / 2003-02-05
Facility ID:	0209171
Site ID:	157707
Spill Date:	2002-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-12-06
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

CASARRA RESIDENCE (Continued) **S105997517**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-06
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	9 BADEAU PL
Spiller County:	001
Spiller Contact:	SAL CASARRA
Spiller Phone:	(914) 235-0620
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/05/2003 Northeast Environmental removed the tank and reported that no contamination was present. NFA TG"
Remarks:	"uncover repair and retest"

All Materials:

Site ID:	157707
Operable Unit ID:	860605
Operable Unit:	01
Material ID:	516149
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

V190 **COTTAGE-GARDEN AUTO REPAIR SITE** **NY INST CONTROL** **S127282799**
NNE **20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE** **NY BROWNFIELDS** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.173 mi.
916 ft. **Site 5 of 5 in cluster V**

Relative: **Lower**
Actual: **71 ft.**

INST CONTROL:

Name:	COTTAGE-GARDEN AUTO REPAIR SITE
Address:	20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	574524
Control Name:	IC/EC Plan
HW Code:	C360180
Control Code:	34
Control Type:	INST
Dt record added:	12/18/2020
Dt rec updated:	12/31/2020
Updated By:	JEBROWN
Site Code:	574524
Site Description:	"Site Location: The site is located at 20 and 26 Garden Street and 10 Cottage Place in a commercial and residential area of New Rochelle, New York. Residential development is present along Cottage Place, which borders the northeast side of the site; commercial development is present along Garden Street, which borders the southeast side of

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

the site. Interstate I-95 runs along the west side of the site. Site Features: The site consists of five tax parcels and one partial parcel totaling approximately 0.988 acre. The site was historically occupied by four commercial buildings and one residential building. All on-site buildings were demolished between late 2017 and mid-2018. The site is currently under redevelopment. Current Zoning and Land Use: The site is currently located in the Neighborhood Business District (NB District). Allowable uses in NB Districts include business, professional, or governmental offices, retail stores, dry cleaners, banks, restaurants, houses of worship, animal hospitals, and dwelling units located on or above the second floor only. The site has been most recently used for a variety of commercial and residential uses, including appliance retail, vehicle and tire repair, parking, and an apartment building. The site is currently vacant. All prior buildings were demolished by the BCP applicant upon acquisition in 2017. Past Use of the Site: The lots were historically comprised of four commercial buildings, one residential building, and asphalt parking lots. The residential parcel was constructed in the early 1990s, with conversion to multiple apartments over the years. The remaining commercial buildings have been used as a kitchen and bath dealer, warehouses, retail tire and auto repair facility, a gasoline station with tanks that were closed in place in 2001, and various other commercial, retail, and light manufacturing uses. The auto repair facility, former plastic works manufacturing and/or metal stripping company on the site were likely responsible for the volatile organic compounds (VOCs) and metals contamination. Site Geology and Hydrogeology: The subsurface conditions consist of brown to gray fine to coarse sand, mixed with traces of silt and gravel to depths 20 to 24 ft below ground surface (bgs). Fractured bedrock was encountered on the eastern side of the site at approximately 21 ft bgs. The subsurface conditions of the region do not exhibit unusual geologic conditions to the subject property or to adjoining site properties. The subject parcels are connected to the public water supply system and the property uses the public sewage treatment system for the sanitary waste disposal. Groundwater was encountered at depths of approximately 15 ft to 18 ft bgs in soil borings. Groundwater flows to the west across the site."

Env Problem: "Remediation at the site is complete. Prior to remediation,the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for Target Compound List (TCL) and Target Analyte List (TAL) plus 30 tentatively identified compounds (TICs), Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed for volatile organic compounds (VOCs). Based on investigations conducted to date, the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Soil The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2 parts per million (ppm) vs. USCO of 1 ppm), benzo[b]fluoranthene (1.2 3.2 ppm vs. USCO of 1 ppm), benzo(k)fluoranthene (1.3 ppm vs. USCO of 0.8 ppm), benzo(a)pyrene

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

(1.2 2 ppm vs. USCO of 1 ppm), chrysene (1.2 2.3 ppm vs. USCO of 1 ppm), dibenzo(a,h)anthracene (0.4 ppm vs. USCO of 0.33 ppm) and indeno(1,2,3-cd)pyrene (0.56 1.6 ppm vs. USCO of 0.5 ppm). The depth of PAH impacts is within the top 3 ft below ground surface (bgs). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCO): barium (396 ppm vs. USCO of 350 ppm), cadmium (7.6 22.9 ppm vs. USCO of 2.5 ppm), copper (95.8 227 ppm), lead (68.9 1900 ppm vs. USCO of 63 ppm), mercury (0.23 5 ppm vs. USCO of 0.18 ppm), nickel (39 252 ppm vs. USCO of 30 ppm), and zinc (115 706 ppm vs. USCO of 109 ppm). The depth of metals exceeding their respective USCOs ranged from 1.5 feet to 24 feet bgs. Perfluorooctanesulfonic acid (PFOS), an emerging contaminant, was detected in site soils at concentrations ranging from 0.72-4.18 parts per billion (ppb). No exceedances of the VOCs or PCB SCOs were identified in any of the soil samples collected. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - The following VOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): trichloroethene (TCE) (8.8 9.8 parts per billion (ppb) vs. 5 ppb groundwater standard) and benzene (1.1 ppb vs. 1 ppb groundwater standard) 1,1,2-trichloroethane (1,1,2-TCA) (1.3 ppb vs. 1 ppb groundwater standard), methyl-tertiary-butyl-ether (MTBE) (29 ppb vs. 10 ppb groundwater standard), and methylene chloride (5.4 ppb vs. 5 ppb groundwater standard). The following SVOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): benzo(a)anthracene (0.017 ppb) at a concentration exceeding its AWQS of 0.002 ppb; this may be an artifact of suspended solids in the sample. PFOS was detected at concentrations ranging from 7.68 72.3 parts per trillion (ppt); one sample exceeded the Environmental Protection Agency s (EPA) lifetime health advisory level (HAL) of 70 ppt., and several samples exceeded the New York Drinking Water Quality Council s proposed maximum contaminant level (MCL) of 10 ppt. Perfluorooctanoic acid (PFOA), another emerging contaminant, was detected in site groundwater at concentrations ranging from 7.27-35.7 ppt; these concentrations are below the EPA HAL of 70 ppt, but above the NYS proposed MCL of 10 ppt. No pesticides or PCBs were detected in any of the groundwater samples. None of the metal contaminants of concern were above the AWQS in any of the groundwater samples. Based on the on-site groundwater investigation, there is a potential for contamination to migrate off-site. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) including, tetrachloroethene (PCE) (45 200 micrograms per cubic meter (ug/m3)), carbon tetrachloride (41 630 ug/m3), trichloroethylene (TCE) (31 810 ug/m3), cis-1,2-dichloroethene (13 - 110 ug/m3), were identified in soil vapor samples collected from the site. Recent soil vapor data was available for an adjacent property on Garden Street with lower detections of CVOCs than the site soil vapor results, indicating that the vapor contamination has likely migrated off-site. "

Health Problem: "Removal of contaminated soil and treatment of groundwater is complete, but low levels of contaminants remain in groundwater. Groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for inhalation of site contaminants due to soil vapor intrusion will be evaluated for any buildings on the site with actions taken to address exposures. An evaluation has determined that soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-11-05 09:46:00
Record Upd: 2020-12-29 11:10:00
Updated By: JEBROWN
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden II LLC
Owner Address: 1250 Waters Place, Ph1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden IV LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Stagg
Owner Company: The Mark 95 LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Not reported
Owner Company: The Mark 95 II LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
HW Code: C360180
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: 1,1,2-trichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

HW Code: C360180
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methyl-tert-butyl ether (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1910786
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-07-29 15:16:00
Record Updated: 2020-07-29 15:16:00

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Updated By: MDKILMER
Crossref ID: C360180-11-18
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:29:00
Record Updated: 2020-10-02 17:29:00
Updated By: MDKILMER
Crossref ID: 603233342
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-30 11:04:00
Record Updated: 2020-11-30 11:04:00
Updated By: GWHEITZM
Crossref ID: 01/16/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 17:28:00
Record Updated: 2020-10-02 17:28:00
Updated By: MDKILMER

Name: COTTAGE-GARDEN AUTO REPAIR SITE
Address: 20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 574524
Control Name: Monitoring Plan
HW Code: C360180
Control Code: 31
Control Type: INST
Dt record added: 12/18/2020
Dt rec updated: 12/31/2020
Updated By: JEBROWN
Site Code: 574524
Site Description: "Site Location: The site is located at 20 and 26 Garden Street and 10 Cottage Place in a commercial and residential area of New Rochelle, New York. Residential development is present along Cottage Place, which borders the northeast side of the site; commercial development is present along Garden Street, which borders the southeast side of the site. Interstate I-95 runs along the west side of the site. Site Features: The site consists of five tax parcels and one partial parcel totaling approximately 0.988 acre. The site was historically occupied by four commercial buildings and one residential building. All on-site buildings were demolished between late 2017 and mid-2018. The site is currently under redevelopment. Current Zoning and Land Use: The site is currently located in the Neighborhood Business District (NB District). Allowable uses in NB Districts include business, professional, or governmental offices, retail stores, dry cleaners, banks, restaurants, houses of worship, animal hospitals, and dwelling units located on or above the second floor only. The site has been most recently used for a variety of commercial and residential uses, including appliance retail, vehicle and tire repair, parking, and an apartment building. The site is currently vacant. All prior buildings were demolished by the BCP applicant upon acquisition in 2017. Past Use of the Site: The lots were historically comprised of four commercial buildings, one residential building, and asphalt parking lots. The residential parcel was constructed in the early 1990s, with conversion to multiple apartments over the years. The remaining commercial buildings have been used as a kitchen and

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

bath dealer, warehouses, retail tire and auto repair facility, a gasoline station with tanks that were closed in place in 2001, and various other commercial, retail, and light manufacturing uses. The auto repair facility, former plastic works manufacturing and/or metal stripping company on the site were likely responsible for the volatile organic compounds (VOCs) and metals contamination. Site Geology and Hydrogeology: The subsurface conditions consist of brown to gray fine to coarse sand, mixed with traces of silt and gravel to depths 20 to 24 ft below ground surface (bgs). Fractured bedrock was encountered on the eastern side of the site at approximately 21 ft bgs. The subsurface conditions of the region do not exhibit unusual geologic conditions to the subject property or to adjoining site properties. The subject parcels are connected to the public water supply system and the property uses the public sewage treatment system for the sanitary waste disposal. Groundwater was encountered at depths of approximately 15 ft to 18 ft bgs in soil borings. Groundwater flows to the west across the site."

Env Problem: "Remediation at the site is complete. Prior to remediation,the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for Target Compound List (TCL) and Target Analyte List (TAL) plus 30 tentatively identified compounds (TICs), Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed for volatile organic compounds (VOCs). Based on investigations conducted to date, the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Soil The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2 parts per million (ppm) vs. USCO of 1 ppm), benzo[b]fluoranthene (1.2 3.2 ppm vs. USCO of 1 ppm), benzo(k)fluoranthene (1.3 ppm vs. USCO of 0.8 ppm), benzo(a)pyrene (1.2 2 ppm vs. USCO of 1 ppm), chrysene (1.2 2.3 ppm vs. USCO of 1 ppm), dibenzo(a,h)anthracene (0.4 ppm vs. USCO of 0.33 ppm) and indeno(1,2,3-cd)pyrene (0.56 1.6 ppm vs. USCO of 0.5 ppm). The depth of PAH impacts is within the top 3 ft below ground surface (bgs). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCO): barium (396 ppm vs. USCO of 350 ppm), cadmium (7.6 22.9 ppm vs. USCO of 2.5 ppm), copper (95.8 227 ppm), lead (68.9 1900 ppm vs. USCO of 63 ppm), mercury (0.23 5 ppm vs. USCO of 0.18 ppm), nickel (39 252 ppm vs. USCO of 30 ppm), and zinc (115 706 ppm vs. USCO of 109 ppm). The depth of metals exceeding their respective USCOs ranged from 1.5 feet to 24 feet bgs. Perfluorooctanesulfonic acid (PFOS), an emerging contaminant, was detected in site soils at concentrations ranging from 0.72-4.18 parts per billion (ppb). No exceedances of the VOCs or PCB SCOs were identified in any of the soil samples collected. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - The following VOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): trichloroethene (TCE) (8.8 9.8 parts per billion (ppb) vs. 5 ppb groundwater standard) and benzene (1.1 ppb vs. 1 ppb

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

groundwater standard) 1,1,2-trichloroethane (1,1,2-TCA) (1.3 ppb vs. 1 ppb groundwater standard), methyl-tertiary-butyl-ether (MTBE) (29 ppb vs. 10 ppb groundwater standard), and methylene chloride (5.4 ppb vs. 5 ppb groundwater standard). The following SVOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): benzo(a)anthracene (0.017 ppb) at a concentration exceeding its AWQS of 0.002 ppb; this may be an artifact of suspended solids in the sample. PFOS was detected at concentrations ranging from 7.68 72.3 parts per trillion (ppt); one sample exceeded the Environmental Protection Agency s (EPA) lifetime health advisory level (HAL) of 70 ppt., and several samples exceeded the New York Drinking Water Quality Council s proposed maximum contaminant level (MCL) of 10 ppt. Perfluorooctanoic acid (PFOA), another emerging contaminant, was detected in site groundwater at concentrations ranging from 7.27-35.7 ppt; these concentrations are below the EPA HAL of 70 ppt, but above the NYS proposed MCL of 10 ppt. No pesticides or PCBs were detected in any of the groundwater samples. None of the metal contaminants of concern were above the AWQS in any of the groundwater samples. Based on the on-site groundwater investigation, there is a potential for contamination to migrate off-site. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) including, tetrachloroethene (PCE) (45 200 micrograms per cubic meter (ug/m3)), carbon tetrachloride (41 630 ug/m3), trichloroethylene (TCE) (31 810 ug/m3), cis-1,2-dichloroethene (13 - 110 ug/m3), were identified in soil vapor samples collected from the site. Recent soil vapor data was available for an adjacent property on Garden Street with lower detections of CVOCs than the site soil vapor results, indicating that the vapor contamination has likely migrated off-site. "

Health Problem: "Removal of contaminated soil and treatment of groundwater is complete, but low levels of contaminants remain in groundwater. Groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for inhalation of site contaminants due to soil vapor intrusion will be evaluated for any buildings on the site with actions taken to address exposures. An evaluation has determined that soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-11-05 09:46:00
Record Upd: 2020-12-29 11:10:00
Updated By: JEBROWN
Own Op: 6
Sub Type: P03

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Name: Joseph Simone
Owner Company: MJ Garden II LLC
Owner Address: 1250 Waters Place, Ph1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden IV LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Stagg

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Company: The Mark 95 LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Not reported
Owner Company: The Mark 95 II LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
HW Code: C360180
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: 1,1,2-trichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

HW Code: C360180
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methyl-tert-butyl ether (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1910786
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-07-29 15:16:00
Record Updated: 2020-07-29 15:16:00
Updated By: MDKILMER
Crossref ID: C360180-11-18
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:29:00
Record Updated: 2020-10-02 17:29:00
Updated By: MDKILMER
Crossref ID: 603233342
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-30 11:04:00
Record Updated: 2020-11-30 11:04:00
Updated By: GWHEITZM
Crossref ID: 01/16/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 17:28:00
Record Updated: 2020-10-02 17:28:00
Updated By: MDKILMER

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Name: COTTAGE-GARDEN AUTO REPAIR SITE
Address: 20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 574524
Control Name: Site Management Plan
HW Code: C360180
Control Code: 32
Control Type: INST
Dt record added: 12/18/2020
Dt rec updated: 12/31/2020
Updated By: JEBROWN
Site Code: 574524
Site Description: "Site Location: The site is located at 20 and 26 Garden Street and 10 Cottage Place in a commercial and residential area of New Rochelle, New York. Residential development is present along Cottage Place, which borders the northeast side of the site; commercial development is present along Garden Street, which borders the southeast side of the site. Interstate I-95 runs along the west side of the site. Site Features: The site consists of five tax parcels and one partial parcel totaling approximately 0.988 acre. The site was historically occupied by four commercial buildings and one residential building. All on-site buildings were demolished between late 2017 and mid-2018. The site is currently under redevelopment. Current Zoning and Land Use: The site is currently located in the Neighborhood Business District (NB District). Allowable uses in NB Districts include business, professional, or governmental offices, retail stores, dry cleaners, banks, restaurants, houses of worship, animal hospitals, and dwelling units located on or above the second floor only. The site has been most recently used for a variety of commercial and residential uses, including appliance retail, vehicle and tire repair, parking, and an apartment building. The site is currently vacant. All prior buildings were demolished by the BCP applicant upon acquisition in 2017. Past Use of the Site: The lots were historically comprised of four commercial buildings, one residential building, and asphalt parking lots. The residential parcel was constructed in the early 1990s, with conversion to multiple apartments over the years. The remaining commercial buildings have been used as a kitchen and bath dealer, warehouses, retail tire and auto repair facility, a gasoline station with tanks that were closed in place in 2001, and various other commercial, retail, and light manufacturing uses. The auto repair facility, former plastic works manufacturing and/or metal stripping company on the site were likely responsible for the volatile organic compounds (VOCs) and metals contamination. Site Geology and Hydrogeology: The subsurface conditions consist of brown to gray fine to coarse sand, mixed with traces of silt and gravel to depths 20 to 24 ft below ground surface (bgs). Fractured bedrock was encountered on the eastern side of the site at approximately 21 ft bgs. The subsurface conditions of the region do not exhibit unusual geologic conditions to the subject property or to adjoining site properties. The subject parcels are connected to the public water supply system and the property uses the public sewage treatment system for the sanitary waste disposal. Groundwater was encountered at depths of approximately 15 ft to 18 ft bgs in soil borings. Groundwater flows to the west across the site."
Env Problem: "Remediation at the site is complete. Prior to remediation,the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater;

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for Target Compound List (TCL) and Target Analyte List (TAL) plus 30 tentatively identified compounds (TICs), Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed for volatile organic compounds (VOCs). Based on investigations conducted to date, the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Soil The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2 parts per million (ppm) vs. USCO of 1 ppm), benzo[b]fluoranthene (1.2 3.2 ppm vs. USCO of 1 ppm), benzo(k)fluoranthene (1.3 ppm vs. USCO of 0.8 ppm), benzo(a)pyrene (1.2 2 ppm vs. USCO of 1 ppm), chrysene (1.2 2.3 ppm vs. USCO of 1 ppm), dibenzo(a,h)anthracene (0.4 ppm vs. USCO of 0.33 ppm) and indeno(1,2,3-cd)pyrene (0.56 1.6 ppm vs. USCO of 0.5 ppm). The depth of PAH impacts is within the top 3 ft below ground surface (bgs). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCO): barium (396 ppm vs. USCO of 350 ppm), cadmium (7.6 22.9 ppm vs. USCO of 2.5 ppm), copper (95.8 227 ppm), lead (68.9 1900 ppm vs. USCO of 63 ppm), mercury (0.23 5 ppm vs. USCO of 0.18 ppm), nickel (39 252 ppm vs. USCO of 30 ppm), and zinc (115 706 ppm vs. USCO of 109 ppm). The depth of metals exceeding their respective USCOs ranged from 1.5 feet to 24 feet bgs. Perfluorooctanesulfonic acid (PFOS), an emerging contaminant, was detected in site soils at concentrations ranging from 0.72-4.18 parts per billion (ppb). No exceedances of the VOCs or PCB SCOs were identified in any of the soil samples collected. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - The following VOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): trichloroethene (TCE) (8.8 9.8 parts per billion (ppb) vs. 5 ppb groundwater standard) and benzene (1.1 ppb vs. 1 ppb groundwater standard) 1,1,2-trichloroethane (1,1,2-TCA) (1.3 ppb vs. 1 ppb groundwater standard), methyl-tertiary-butyl-ether (MTBE) (29 ppb vs. 10 ppb groundwater standard), and methylene chloride (5.4 ppb vs. 5 ppb groundwater standard). The following SVOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): benzo(a)anthracene (0.017 ppb) at a concentration exceeding its AWQS of 0.002 ppb; this may be an artifact of suspended solids in the sample. PFOS was detected at concentrations ranging from 7.68 72.3 parts per trillion (ppt); one sample exceeded the Environmental Protection Agency s (EPA) lifetime health advisory level (HAL) of 70 ppt., and several samples exceeded the New York Drinking Water Quality Council s proposed maximum contaminant level (MCL) of 10 ppt. Perfluorooctanoic acid (PFOA), another emerging contaminant, was detected in site groundwater at concentrations ranging from 7.27-35.7 ppt; these concentrations are below the EPA HAL of 70 ppt, but above the NYS proposed MCL of 10 ppt. No pesticides or PCBs were detected in any of the groundwater samples. None of the metal contaminants of concern were above the AWQS in any of the groundwater samples. Based on the on-site groundwater investigation, there is a potential for contamination to migrate

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

off-site. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) including, tetrachloroethene (PCE) (45 200 micrograms per cubic meter (ug/m3)), carbon tetrachloride (41 630 ug/m3), trichloroethylene (TCE) (31 810 ug/m3), cis-1,2-dichloroethene (13 - 110 ug/m3), were identified in soil vapor samples collected from the site. Recent soil vapor data was available for an adjacent property on Garden Street with lower detections of CVOCs than the site soil vapor results, indicating that the vapor contamination has likely migrated off-site. "

Health Problem: "Removal of contaminated soil and treatment of groundwater is complete, but low levels of contaminants remain in groundwater. Groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for inhalation of site contaminants due to soil vapor intrusion will be evaluated for any buildings on the site with actions taken to address exposures. An evaluation has determined that soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-11-05 09:46:00
Record Upd: 2020-12-29 11:10:00
Updated By: JEBROWN
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden II LLC
Owner Address: 1250 Waters Place, Ph1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden IV LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Stagg
Owner Company: The Mark 95 LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Not reported
Owner Company: The Mark 95 II LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
HW Code: C360180
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methylene chloride
Waste Quantity: UNKNOWN

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Waste Code: Not reported
HW Code: C360180
Waste Type: 1,1,2-trichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

HW Code: C360180
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methyl-tert-butyl ether (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1910786
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-07-29 15:16:00
Record Updated: 2020-07-29 15:16:00
Updated By: MDKILMER
Crossref ID: C360180-11-18
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:29:00
Record Updated: 2020-10-02 17:29:00
Updated By: MDKILMER
Crossref ID: 603233342
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-30 11:04:00
Record Updated: 2020-11-30 11:04:00
Updated By: GWHEITZM
Crossref ID: 01/16/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 17:28:00
Record Updated: 2020-10-02 17:28:00
Updated By: MDKILMER

Name: COTTAGE-GARDEN AUTO REPAIR SITE
Address: 20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 574524
Control Name: Environmental Easement
HW Code: C360180
Control Code: J
Control Type: INST
Dt record added: 12/18/2020
Dt rec updated: 12/31/2020
Updated By: JEBROWN
Site Code: 574524
Site Description: "Site Location: The site is located at 20 and 26 Garden Street and 10 Cottage Place in a commercial and residential area of New Rochelle, New York. Residential development is present along Cottage Place, which borders the northeast side of the site; commercial development is present along Garden Street, which borders the southeast side of the site. Interstate I-95 runs along the west side of the site. Site Features: The site consists of five tax parcels and one partial parcel totaling approximately 0.988 acre. The site was historically

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

occupied by four commercial buildings and one residential building. All on-site buildings were demolished between late 2017 and mid-2018. The site is currently under redevelopment. Current Zoning and Land Use: The site is currently located in the Neighborhood Business District (NB District). Allowable uses in NB Districts include business, professional, or governmental offices, retail stores, dry cleaners, banks, restaurants, houses of worship, animal hospitals, and dwelling units located on or above the second floor only. The site has been most recently used for a variety of commercial and residential uses, including appliance retail, vehicle and tire repair, parking, and an apartment building. The site is currently vacant. All prior buildings were demolished by the BCP applicant upon acquisition in 2017. Past Use of the Site: The lots were historically comprised of four commercial buildings, one residential building, and asphalt parking lots. The residential parcel was constructed in the early 1990s, with conversion to multiple apartments over the years. The remaining commercial buildings have been used as a kitchen and bath dealer, warehouses, retail tire and auto repair facility, a gasoline station with tanks that were closed in place in 2001, and various other commercial, retail, and light manufacturing uses. The auto repair facility, former plastic works manufacturing and/or metal stripping company on the site were likely responsible for the volatile organic compounds (VOCs) and metals contamination. Site Geology and Hydrogeology: The subsurface conditions consist of brown to gray fine to coarse sand, mixed with traces of silt and gravel to depths 20 to 24 ft below ground surface (bgs). Fractured bedrock was encountered on the eastern side of the site at approximately 21 ft bgs. The subsurface conditions of the region do not exhibit unusual geologic conditions to the subject property or to adjoining site properties. The subject parcels are connected to the public water supply system and the property uses the public sewage treatment system for the sanitary waste disposal. Groundwater was encountered at depths of approximately 15 ft to 18 ft bgs in soil borings. Groundwater flows to the west across the site."

Env Problem: "Remediation at the site is complete. Prior to remediation,the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for Target Compound List (TCL) and Target Analyte List (TAL) plus 30 tentatively identified compounds (TICs), Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed for volatile organic compounds (VOCs). Based on investigations conducted to date, the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Soil The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2 parts per million (ppm) vs. USCO of 1 ppm), benzo[b]fluoranthene (1.2 3.2 ppm vs. USCO of 1 ppm), benzo(k)fluoranthene (1.3 ppm vs. USCO of 0.8 ppm), benzo(a)pyrene (1.2 2 ppm vs. USCO of 1 ppm), chrysene (1.2 2.3 ppm vs. USCO of 1 ppm), dibenzo(a,h)anthracene (0.4 ppm vs. USCO of 0.33 ppm) and indeno(1,2,3-cd)pyrene (0.56 1.6 ppm vs. USCO of 0.5 ppm). The depth

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

of PAH impacts is within the top 3 ft below ground surface (bgs). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCO): barium (396 ppm vs. USCO of 350 ppm), cadmium (7.6 22.9 ppm vs. USCO of 2.5 ppm), copper (95.8 227 ppm), lead (68.9 1900 ppm vs. USCO of 63 ppm), mercury (0.23 5 ppm vs. USCO of 0.18 ppm), nickel (39 252 ppm vs. USCO of 30 ppm), and zinc (115 706 ppm vs. USCO of 109 ppm). The depth of metals exceeding their respective USCOs ranged from 1.5 feet to 24 feet bgs. Perfluorooctanesulfonic acid (PFOS), an emerging contaminant, was detected in site soils at concentrations ranging from 0.72-4.18 parts per billion (ppb). No exceedances of the VOCs or PCB SCOs were identified in any of the soil samples collected. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - The following VOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): trichloroethene (TCE) (8.8 9.8 parts per billion (ppb) vs. 5 ppb groundwater standard) and benzene (1.1 ppb vs. 1 ppb groundwater standard) 1,1,2-trichloroethane (1,1,2-TCA) (1.3 ppb vs. 1 ppb groundwater standard), methyl-tertiary-butyl-ether (MTBE) (29 ppb vs. 10 ppb groundwater standard), and methylene chloride (5.4 ppb vs. 5 ppb groundwater standard). The following SVOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): benzo(a)anthracene (0.017 ppb) at a concentration exceeding its AWQS of 0.002 ppb; this may be an artifact of suspended solids in the sample. PFOS was detected at concentrations ranging from 7.68 72.3 parts per trillion (ppt); one sample exceeded the Environmental Protection Agency s (EPA) lifetime health advisory level (HAL) of 70 ppt., and several samples exceeded the New York Drinking Water Quality Council s proposed maximum contaminant level (MCL) of 10 ppt. Perfluorooctanoic acid (PFOA), another emerging contaminant, was detected in site groundwater at concentrations ranging from 7.27-35.7 ppt; these concentrations are below the EPA HAL of 70 ppt, but above the NYS proposed MCL of 10 ppt. No pesticides or PCBs were detected in any of the groundwater samples. None of the metal contaminants of concern were above the AWQS in any of the groundwater samples. Based on the on-site groundwater investigation, there is a potential for contamination to migrate off-site. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) including, tetrachloroethene (PCE) (45 200 micrograms per cubic meter (ug/m3)), carbon tetrachloride (41 630 ug/m3), trichloroethylene (TCE) (31 810 ug/m3), cis-1,2-dichloroethene (13 - 110 ug/m3), were identified in soil vapor samples collected from the site. Recent soil vapor data was available for an adjacent property on Garden Street with lower detections of CVOCs than the site soil vapor results, indicating that the vapor contamination has likely migrated off-site. "

Health Problem: "Removal of contaminated soil and treatment of groundwater is complete, but low levels of contaminants remain in groundwater. Groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for inhalation of site contaminants due to soil vapor

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

intrusion will be evaluated for any buildings on the site with actions taken to address exposures. An evaluation has determined that soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-11-05 09:46:00
Record Upd: 2020-12-29 11:10:00
Updated By: JEBROWN
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden II LLC
Owner Address: 1250 Waters Place, Ph1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden IV LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 1
Sub Type: P03

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Name: Joseph Simone
Owner Company: MJ Garden III LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Joseph Simone
Owner Company: MJ Garden LLC
Owner Address: 1250 Waters Place, PH1
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10461
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Stagg
Owner Company: The Mark 95 LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Not reported
Owner Company: The Mark 95 II LLC
Owner Address: 5959 Broadway, Suite 3
Owner Addr2: Not reported
Owner City,St,Zip: Bronx, NY 10463
Owner Country: United States of America
HW Code: C360180
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: 1,1,2-trichloroethane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Waste Code: Not reported
HW Code: C360180
Waste Type: zinc
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: methyl-tert-butyl ether (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360180
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1910786
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-07-29 15:16:00
Record Updated: 2020-07-29 15:16:00
Updated By: MDKILMER
Crossref ID: C360180-11-18
Cross Ref Type Code: 23

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-02 17:29:00
Record Updated: 2020-10-02 17:29:00
Updated By: MDKILMER
Crossref ID: 603233342
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-30 11:04:00
Record Updated: 2020-11-30 11:04:00
Updated By: GWHEITZM
Crossref ID: 01/16/2019
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-02 17:28:00
Record Updated: 2020-10-02 17:28:00
Updated By: MDKILMER

BROWNFIELDS:

Name:	COTTAGE-GARDEN AUTO REPAIR SITE
Address:	20 GARDEN ST., 26 GARDEN ST. AND 10 COTTAGE PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	574524
Acres:	0.988
HW Code:	C360180
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	08/03/2018
Record Updated Date:	01/25/2022
Update By:	RDBENDEL
Site Description:	"Site Location: The site is located at 20 and 26 Garden Street and 10 Cottage Place in a commercial and residential area of New Rochelle, New York. Residential development is present along Cottage Place, which borders the northeast side of the site; commercial development is present along Garden Street, which borders the southeast side of the site. Interstate I-95 runs along the west side of the site. Site Features: The site consists of five tax parcels and one partial parcel totaling approximately 0.988 acre. The site was historically occupied by four commercial buildings and one residential building. All on-site buildings were demolished between late 2017 and mid-2018. The site is currently under redevelopment. Current Zoning and Land Use: The site is currently located in the Neighborhood Business District (NB District). Allowable uses in NB Districts include business, professional, or governmental offices, retail stores, dry cleaners, banks, restaurants, houses of worship, animal hospitals, and dwelling units located on or above the second floor only. The site has been most recently used for a variety of commercial and residential uses, including appliance retail, vehicle and tire repair, parking, and an apartment building. The site is currently vacant. All prior buildings were demolished by the BCP applicant upon acquisition in 2017. Past Use of the Site: The lots were historically comprised of four commercial buildings, one residential building, and asphalt parking lots. The residential parcel was constructed in the early 1990s, with conversion to multiple apartments over the years. The remaining commercial buildings have been used as a kitchen and bath dealer, warehouses, retail tire and auto repair facility, a gasoline station with tanks that were closed in place in 2001, and

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

various other commercial, retail, and light manufacturing uses. The auto repair facility, former plastic works manufacturing and/or metal stripping company on the site were likely responsible for the volatile organic compounds (VOCs) and metals contamination. Site Geology and Hydrogeology: The subsurface conditions consist of brown to gray fine to coarse sand, mixed with traces of silt and gravel to depths 20 to 24 ft below ground surface (bgs). Fractured bedrock was encountered on the eastern side of the site at approximately 21 ft bgs. The subsurface conditions of the region do not exhibit unusual geologic conditions to the subject property or to adjoining site properties. The subject parcels are connected to the public water supply system and the property uses the public sewage treatment system for the sanitary waste disposal. Groundwater was encountered at depths of approximately 15 ft to 18 ft bgs in soil borings. Groundwater flows to the west across the site."

Env Problem:

"Remediation at the site is complete. Prior to remediation,the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for Target Compound List (TCL) and Target Analyte List (TAL) plus 30 tentatively identified compounds (TICs), Total Petroleum Hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants PFAS and 1,4-dioxane. Soil vapor samples were analyzed for volatile organic compounds (VOCs). Based on investigations conducted to date, the primary contaminants of concern include VOCs, metals, and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs and PFAS in groundwater; and VOCs in soil vapor. Soil The following PAHs were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCOs): benzo[a]anthracene (2 parts per million (ppm) vs. USCO of 1 ppm), benzo[b]fluoranthene (1.2 3.2 ppm vs. USCO of 1 ppm), benzo(k)fluoranthene (1.3 ppm vs. USCO of 0.8 ppm), benzo(a)pyrene (1.2 2 ppm vs. USCO of 1 ppm), chrysene (1.2 2.3 ppm vs. USCO of 1 ppm), dibenzo(a,h)anthracene (0.4 ppm vs. USCO of 0.33 ppm) and indeno(1,2,3-cd)pyrene (0.56 1.6 ppm vs. USCO of 0.5 ppm). The depth of PAH impacts is within the top 3 ft below ground surface (bgs). The following metals were identified at concentrations that exceed their Unrestricted Soil Cleanup Objectives (USCO): barium (396 ppm vs. USCO of 350 ppm), cadmium (7.6 22.9 ppm vs. USCO of 2.5 ppm), copper (95.8 227 ppm), lead (68.9 1900 ppm vs. USCO of 63 ppm), mercury (0.23 5 ppm vs. USCO of 0.18 ppm), nickel (39 252 ppm vs. USCO of 30 ppm), and zinc (115 706 ppm vs. USCO of 109 ppm). The depth of metals exceeding their respective USCOs ranged from 1.5 feet to 24 feet bgs. Perfluorooctanesulfonic acid (PFOS), an emerging contaminant, was detected in site soils at concentrations ranging from 0.72-4.18 parts per billion (ppb). No exceedances of the VOCs or PCB SCOs were identified in any of the soil samples collected. Based on the on-site soil investigation, it does not appear that soil contamination is migrating off-site. Groundwater - The following VOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): trichloroethene (TCE) (8.8 9.8 parts per billion (ppb) vs. 5 ppb groundwater standard) and benzene (1.1 ppb vs. 1 ppb groundwater standard) 1,1,2-trichloroethane (1,1,2-TCA) (1.3 ppb vs. 1 ppb groundwater standard), methyl-tertiary-butyl-ether (MTBE) (29

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

ppb vs. 10 ppb groundwater standard), and methylene chloride (5.4 ppb vs. 5 ppb groundwater standard). The following SVOCs were identified at concentrations that exceed the Ambient Water Quality Standards for groundwater (AWQS): benzo(a)anthracene (0.017 ppb) at a concentration exceeding its AWQS of 0.002 ppb; this may be an artifact of suspended solids in the sample. PFOS was detected at concentrations ranging from 7.68 72.3 parts per trillion (ppt); one sample exceeded the Environmental Protection Agency s (EPA) lifetime health advisory level (HAL) of 70 ppt., and several samples exceeded the New York Drinking Water Quality Council s proposed maximum contaminant level (MCL) of 10 ppt. Perfluorooctanoic acid (PFOA), another emerging contaminant, was detected in site groundwater at concentrations ranging from 7.27-35.7 ppt; these concentrations are below the EPA HAL of 70 ppt, but above the NYS proposed MCL of 10 ppt. No pesticides or PCBs were detected in any of the groundwater samples. None of the metal contaminants of concern were above the AWQS in any of the groundwater samples. Based on the on-site groundwater investigation, there is a potential for contamination to migrate off-site. Soil Vapor - Elevated levels of chlorinated volatile organic compounds (CVOCs) including, tetrachloroethene (PCE) (45 200 micrograms per cubic meter (ug/m3)), carbon tetrachloride (41 630 ug/m3), trichloroethylene (TCE) (31 810 ug/m3), cis-1,2-dichloroethene (13 - 110 ug/m3), were identified in soil vapor samples collected from the site. Recent soil vapor data was available for an adjacent property on Garden Street with lower detections of CVOCs than the site soil vapor results, indicating that the vapor contamination has likely migrated off-site. "

Health Problem:	"Removal of contaminated soil and treatment of groundwater is complete, but low levels of contaminants remain in groundwater. Groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for inhalation of site contaminants due to soil vapor intrusion will be evaluated for any buildings on the site with actions taken to address exposures. An evaluation has determined that soil vapor intrusion is not a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-11-05 09:46:00
Record Upd:	2020-12-29 11:10:00
Updated By:	JEBROWN
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden II LLC

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Address:	1250 Waters Place, Ph1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden III LLC
Owner Address:	1250 Waters Place, PH1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden LLC
Owner Address:	1250 Waters Place, PH1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden IV LLC
Owner Address:	1250 Waters Place, PH1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden III LLC
Owner Address:	1250 Waters Place, PH1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph Simone
Owner Company:	MJ Garden LLC
Owner Address:	1250 Waters Place, PH1
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10461
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mark Stagg
Owner Company:	The Mark 95 LLC
Owner Address:	5959 Broadway, Suite 3

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10463
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Not reported
Owner Company:	The Mark 95 II LLC
Owner Address:	5959 Broadway, Suite 3
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10463
Owner Country:	United States of America
HW Code:	C360180
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	1,1,2-trichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	carbon tetrachloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	cis-1,2-dichloroethene

COTTAGE-GARDEN AUTO REPAIR SITE (Continued) **S127282799**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	methyl-tert-butyl ether (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360180
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1910786
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-07-29 15:16:00
Record Updated:	2020-07-29 15:16:00
Updated By:	MDKILMER
Crossref ID:	C360180-11-18
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-02 17:29:00
Record Updated:	2020-10-02 17:29:00
Updated By:	MDKILMER
Crossref ID:	603233342
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-11-30 11:04:00
Record Updated:	2020-11-30 11:04:00
Updated By:	GWHEITZM
Crossref ID:	01/16/2019
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-02 17:28:00
Record Updated:	2020-10-02 17:28:00
Updated By:	MDKILMER

X191 **NYNEX** **NY LTANKS** **S100164268**
WNW **40 WASHINGTON AVE** **N/A**
1/8-1/4 **GREENBUSH, NY**
0.174 mi.
919 ft. **Site 1 of 4 in cluster X**

Relative:
Higher

Actual:
112 ft.

LTANKS:

Name:	NYNEX
Address:	40 WASHINGTON AVE
City,State,Zip:	GREENBUSH, NY
Spill Number/Closed Date:	8803234 / 1988-07-22
Facility ID:	8803234
Site ID:	60528
Spill Date:	1988-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-07-22
SWIS:	6000
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-07-22
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-28
Spill Record Last Update:	1988-09-07
Spiller Name:	Not reported
Spiller Company:	JOHN ALBARANO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59075
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK PUMED OUT.TO BE REMOVED. "
Remarks:	"#2FUEL 5K 1.842 / 4K .170 DIESEL"

All TTF:

Facility ID:	8803234
Spill Number:	8803234
Spill Tank Test:	1534290
Site ID:	60528
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

NYNEX (Continued) **S100164268**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 60528
Operable Unit ID: 918404
Operable Unit: 01
Material ID: 458797
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Y192 **ROTH CLEANERS** **RCRA NonGen / NLR** **1000237840**
SSE **1 LEROY PL** **FINDS** **NYD078706686**
1/8-1/4 **NEW ROCHELLE, NY 10805** **ECHO**
0.177 mi. **NY DRYCLEANERS**
932 ft. **Site 1 of 3 in cluster Y** **NY MANIFEST**

Relative:
Higher

Actual:
100 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	ROTH CLEANERS	
Handler Address:		1 LEROY PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYD078706686
Contact Name:		BEN ROTH
Contact Address:		LEROY PL
Contact City,State,Zip:		NEW ROCHELLE, NY 10805
Contact Telephone:		914-633-7114
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		LEROY PL
Mailing City,State,Zip:		NEW ROCHELLE, NY 10805
Owner Name:		BEN ROTH
Owner Type:		Private
Operator Name:		BEN ROTH
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

ROTH CLEANERS (Continued) **1000237840**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

ROTH CLEANERS (Continued) **1000237840**

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BEN ROTH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BEN ROTH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BEN ROTH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: ROTH CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

ROTH CLEANERS (Continued) **1000237840**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ROTH CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860827
Handler Name: ROTH CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 19870424
Actual Return to Compliance Date: 19870426
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19870426
Enforcement Identifier: 001
Date of Enforcement Action: 19870424
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL

ROTH CLEANERS (Continued) **1000237840**

Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19870424
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870426
Scheduled Compliance Date:	19870426
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004370369

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000237840
Registry ID:	110004370369
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004370369
Name:	ROTH CLEANERS
Address:	1 LEROY PL
City,State,Zip:	NEW ROCHELLE, NY 10805

ROTH CLEANERS (Continued) **1000237840**

DRYCLEANERS:

Name:	ROTH CLEANERS
Address:	1 LEROY PLACE
City,State,Zip:	NEW ROCHELLE, NY 10805
Facility ID:	3-5510-00292
Phone Number:	914-633-7114
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	2016-07-09 00:00:00
Install Date:	98
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

NY MANIFEST:

Name:	ROTH CLEANERS
Address:	1 LEROY PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD078706686
Facility Status:	Not reported
Location Address 1:	1 LEROY PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD078706686
Mailing Name:	ROTH CLEANERS
Mailing Contact:	ROTH CLEANERS
Mailing Address 1:	1 LEROY PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146337114

Y193 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243086**
SSE **DIVISION ST & LEROY PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.180 mi.
951 ft. **Site 2 of 3 in cluster Y**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	DIVISION ST & LEROY PL
City,State,Zip:	NEW ROCHELLE, NY

CONSOLIDATED EDISON (Continued) **1009243086**

Country:	USA
EPA ID:	NYP004124210
Facility Status:	Not reported
Location Address 1:	DIVISION ST & LEROY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004124210
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Z194 **CON ED-V37** **NY MANIFEST** **S109064681**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.181 mi.
955 ft. **Site 1 of 2 in cluster Z**

Relative:
Lower

Actual:
87 ft.

NY MANIFEST:

Name:	CON ED-V37
Address:	LECOUNT PL & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004027967
Facility Status:	Not reported
Location Address 1:	LECOUNT PL & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	0000

NY MANIFEST:

EPAID:	NYP004027967
Mailing Name:	CON ED-V37
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported

CON ED-V37 (Continued) **S109064681**

Mailing Phone: Not reported

Z195 **CON ED-V14** **NY MANIFEST** **S109064677**
East **LECOUNT PL & MAIN ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.181 mi.
955 ft. **Site 2 of 2 in cluster Z**

Relative: **Lower**
Actual: **87 ft.**

NY MANIFEST:

Name:	CON ED-V14
Address:	LECOUNT PL & MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004028122
Facility Status:	Not reported
Location Address 1:	LECOUNT PL & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	0000

NY MANIFEST:

EPAID:	NYP004028122
Mailing Name:	CON ED-V14
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

AA196 **J B & FRANKS** **RCRA NonGen / NLR** **1000100357**
SW **27 BARTELS PL** **FINDS** **NYD986884732**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.181 mi. **NY MANIFEST**
958 ft. **Site 1 of 3 in cluster AA**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	J B & FRANKS	
Handler Address:		27 BARTELS PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801-6901
EPA ID:		NYD986884732
Contact Name:		Not reported
Contact Address:		BARTELS PL
Contact City,State,Zip:		NEW ROCHELLE, NY 10804
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported

J B & FRANKS (Continued) **1000100357**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	BARTELS PL
Mailing City,State,Zip:	NEW ROCHELLE, NY 10804
Owner Name:	ANTHONY LANTZ
Owner Type:	Private
Operator Name:	ANTHONY LANTZ
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

J B & FRANKS (Continued) **1000100357**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ANTHONY LANTZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ANTHONY LANTZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ANTHONY LANTZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

J B & FRANKS (Continued) **1000100357**

Historic Generators:

Receive Date:	19990708
Handler Name: J B & FRANKS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: J B & FRANKS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: J B & FRANKS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19891201
Handler Name: J B & FRANKS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

J B & FRANKS (Continued) **1000100357**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004439705

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000100357
Registry ID:	110004439705
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004439705
Name:	J B & FRANKS
Address:	27 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	J B FRANKS
Address:	27 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10801-6901
Country:	USA
EPA ID:	NYD986884732
Facility Status:	Not reported
Location Address 1:	27 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10804
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986884732
Mailing Name:	J B FRANKS
Mailing Contact:	J B FRANKS
Mailing Address 1:	27 BARTELS PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10804
Mailing Zip 4:	Not reported

J B & FRANKS (Continued) **1000100357**

Mailing Country: USA
Mailing Phone: 9146360570

W197 **RESIDENCE** **NY LTANKS** **S102663947**
West **18 BADEAU PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.182 mi.
959 ft. **Site 2 of 4 in cluster W**

Relative: **Higher**
Actual: **104 ft.**

LTANKS:

Name:	RESIDENCE
Address:	18 BADEAU PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9609269 / 1996-10-24
Facility ID:	9609269
Site ID:	177416
Spill Date:	1996-10-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-24
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-24
Spill Record Last Update:	1996-12-05
Spiller Name:	Not reported
Spiller Company:	JULIO VALER
Spiller Address:	18 BADEAU PLACE
Spiller County:	001
Spiller Contact:	JULIO VALER
Spiller Phone:	(914) 636-8917
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149078
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED TOO MUCH OIL. SPILLED ONTO BLACKTOP DRIVEWAY. CLEANED UP."

All Materials:

Site ID:	177416
Operable Unit ID:	1037374
Operable Unit:	01
Material ID:	345000
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RESIDENCE (Continued) **S102663947**

Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

X198 **ST GABRIEL SCHOOL** **NY LTANKS** **S105999147**
WNW **50 WASHINGTON AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.186 mi.
980 ft. **Site 2 of 4 in cluster X**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Name:	ST GABRIEL SCHOOL
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0302359 / 2003-12-12
Facility ID:	0302359
Site ID:	314440
Spill Date:	2003-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2003-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-05
Spill Record Last Update:	2019-03-01
Spiller Name:	LARRY
Spiller Company:	ST GABRIEL SCHOOL
Spiller Address:	50 WASHINGTON AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	" 12/12/03 ALSO REPORTED AS 03-05820. SEE THAT FILE FOR UPDATES. NFA THIS NUMBER."
Remarks:	""

All TTF:

Facility ID:	0302359
Spill Number:	0302359
Spill Tank Test:	1528429
Site ID:	314440
Tank Number:	1

ST GABRIEL SCHOOL (Continued) **S105999147**

Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314440
Operable Unit ID:	869188
Operable Unit:	01
Material ID:	506840
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

X199 **SAINT GABRIEL HIGH SCHOOL** **NY UST** **U004334081**
WNW **50 WASHINGTON AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.186 mi.
980 ft. **Site 3 of 4 in cluster X**

Relative:
Higher

Actual:
110 ft.

NY UST:
No Details: No Details

X200 **INTERSTITIAL FAILURE** **NY LTANKS** **S117851738**
WNW **50 WASHINGTON AVE** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.186 mi.
980 ft. **Site 4 of 4 in cluster X**

Relative:
Higher

Actual:
110 ft.

LTANKS:

Name:	INTERSTITIAL FAILURE
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1903323 / 2019-09-18
Facility ID:	1903323
Site ID:	591279
Spill Date:	2019-07-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3

INTERSTITIAL FAILURE (Continued) **S117851738**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2019-07-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2019-07-01
Spill Record Last Update:	2019-09-18
Spiller Name:	Not reported
Spiller Company:	St Gabriel Church
Spiller Address:	50 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	JIM ROFF
Spiller Phone:	(518) 527-3384
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	253527
DEC Memo:	"7/1/19 Leak in interstitial WCDOH requiring Church to replace tank. Temp tank to be used in interim. Church tank to be completely emptied Tues and new tank to be installed once funding approved. mt. 09/17/19 Metro Environmental Serices reported that they removed the tank. Post excavation soil sample results were below DEC Soil Guidance values. NFA. TG"
Remarks:	"no spill tank test failure"

All Materials:

Site ID:	591279
Operable Unit ID:	1338903
Operable Unit:	01
Material ID:	2348426
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	ST GABRIEL HIGH SCHOOL
Address:	50 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1500015 / 2019-03-01
Facility ID:	1500015
Facility Type:	ER
DER Facility ID:	253527
Site ID:	506147
DEC Region:	3

INTERSTITIAL FAILURE (Continued) **S117851738**

Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2015-04-01
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-04-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-01
Spill Record Last Update:	2019-03-01
Spiller Name:	Not reported
Spiller Company:	CHURCH OF ST GABRIELLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SHARIMA RYAN
DEC Memo:	"4-1-15 Spoke with Sharima. They have excavated 1 drum of soil and will probably excavate a couple more to complete the cleanup. WCDOH - Denise is handling. 3k tank. jm Denise, Please handle this one. PBS 3-058122 Contamination found around leaking spill catch basin. 1 drum removed but more work to do. Contractor stopped and is submitting proposal to school. Contractor wrapping up for the day no need to inspect today. 3k UST from 2003 Thank You Chris Christopher J. Lalak MS Radiological and Chemical Analyst Westchester County Department of Health 145 Huguenot Street - 7th Floor New Rochelle, NY 10801 3/01/19: I spoke with Denise Heinzinger at WCDoH. She states she cannot check the file at this time because it was moved their Mount Kisco office. But she states there is a note on her Spill log which reads: Leaking spill box, WCD Group hired, soil remediated, tank removed on 4/29/15. Cleanup was completed and a report was filed with WCDOH PBS. jod"
Remarks:	"leaking spill box - cleanup in progress"

All Materials:

Site ID:	506147
Operable Unit ID:	1255466
Operable Unit:	01
Material ID:	2258224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Y201 **CHURCH-DIVISION STREET, TOWER A** **NY BROWNFIELDS** **S123658107**
SSE **26 SOUTH DIVISION STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.186 mi.
983 ft. **Site 3 of 3 in cluster Y**

Relative: **Higher**
Actual: **99 ft.**

BROWNFIELDS:

Name:	CHURCH-DIVISION STREET, TOWER A
Address:	26 SOUTH DIVISION STREET
City,State,Zip:	NEW ROCHELLE, NY 10805
Program:	BCP
Site Code:	582599
Acres:	0.992
HW Code:	C360187
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	02/22/2019
Record Updated Date:	12/30/2020
Update By:	AMSERVIS
Site Description:	"Site Location: The site is located at 26 South Division Street in the City of New Rochelle, Westchester County, New York, on a 0.992-acre lot that is bounded on the west by South Division Street and on the east by Church Street. The site is parcel 2-414-0008. Site Features: The site is currently vacant and formerly housed part of a 62,500 square foot municipal parking garage. The parking garage was demolished in 2018. The site is currently undergoing redevelopment construction. Current Zoning and Land Use: The site is zoned DO-2 (Downtown Overlay Zone District) which allows for mixed-use apartment style residential and commercial applications. The property is located between a mixed-use commercial area to the north and single-family residential neighborhood the south. Past Use of the Site: The site was historically occupied from 1891 until 1952 by an auto garage which included a tire repair center as well as several upholsterers. The remaining structures on-site included an apartment building, fur vault, and a Salvation Army store, until the site was developed as a municipal parking garage from 1972 until 2018. Prior to remediation, the primary contaminants of concern included metals and polycyclic aromatic hydrocarbons (PAHs) in soil. Site Geology and Hydrogeology: Prior to the completion of the IRM, site soils consisted of a fill layer which ranges from 6 to 10 feet in depth underlain by a sandy silt layer which extends to weathered bedrock. Fill material consists of sand and silt with varying amounts of gravel, concrete, brick and asphalt. Bedrock was encountered at depths ranging between 8 and 14 feet below grade original grade. Groundwater flows in a southeasterly direction towards the New Rochelle Harbor, approximately 2,000 feet away. Groundwater depth ranges from 9.6 to 12.2 feet below grade original grade. All site soils were removed under the Interim Remedial Action (IRM) for the site. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern include metals and polycyclic aromatic hydrocarbons (PAHs) in soil, and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Prior to Completion of Remediation: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), metals, total petroleum hydrocarbons (TPH), cyanide, hexavalent chromium, and the emerging contaminants perfluorooctanesulfonic acid (PFOS), perfluorooctanoic acid (PFOA)

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based on investigations conducted to date, prior to the IRM, the primary contaminants of concern include metals and polycyclic aromatic hydrocarbons (PAHs) in soil, and VOCs in soil vapor. Soil: Prior to the completion of the IRM, 48 subsurface samples were taken at 10 locations down to bedrock from depths up to 13 feet. Several PAHs, metals, pesticides, PCBs, and one VOC (acetone) were identified at concentrations that exceeded their unrestricted soil cleanup objectives (USCOs). The following compounds were found to have USCO exceedances: benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, indeno(1,2,3-c,d)pyrene, barium, cadmium, copper, lead, mercury, nickel, zinc, DDD, DDE, DDT, PCBs, and acetone. PFOS was reported in one sample at 1.41 parts per billion (ppb). Remedial actions as part of the IRM have successfully achieved soil cleanup objectives for unrestricted use. There is no indication that site-related soil contamination extends off-site. Groundwater: Prior to the completion of the IRM, three temporary monitoring wells, located across the site, were sampled. The metals iron, magnesium, manganese, and sodium exceeded groundwater standards in all wells, and one well also exhibited total and dissolved nickel concentrations of 128.9 parts per billion (ppb) and 120.1 ppb, respectively, compared to a groundwater standard of 100 ppb. Another well exhibited a dissolved antimony concentration of 4.06 ppb compared to the standard of 3 ppb. One well contained low-level estimated concentrations of SVOCs at the method detection limit (MDL) and as such their concentration could not be accurately quantified. The SVOC and metals concentrations found in site groundwater are representative of typical urban background conditions associated with the presence of historic fill, are naturally occurring and/or are due to road salt application. The IRM is complete and has removed all soils above bedrock and thus any possible source material for continued groundwater contamination. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 41.6 and 51.2 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for each. Since all soil above bedrock has been removed, the sample containing a low level of PFOS has been excavated, there are no potential on-site sources of PFOA and PFOS remaining, and no potential for PFOA/PFOS contamination to migrate off-site remains. Additionally, the area is served by municipal water. Soil Vapor During a 2018 site assessment, elevated levels of chlorinated volatile organic compounds (CVOCs) were detected in on-site soil vapor samples. Tetrachloroethylene (PCE) and trichloroethene (TCE) were found at 437 and 80.6 micrograms per cubic meter (ug/m3) respectively at the center of the site. During the 2019 remedial investigation, soil vapor sampling along the perimeter of the site found PCE ranging from 3.53 to 27 ug/m3, with no detections of TCE. No detections of CVOCs were identified in on-site soils or groundwater. Since the PCE soil vapor concentration at the center of the site was one to two orders of magnitude higher than near the perimeter, there was likely an unidentified source of CVOCs in unsaturated soils near the center of the site. However, the complete excavation of soils down to bedrock across the entire site as part of the IRM, removed any potentially impacted soils in the unsaturated zone, and has addressed potential soil vapor intrusion concerns for any future buildings constructed on-site, as well as the potential migration of soil vapor off-site. "

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

Health Problem:	"People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by site related contamination. Since all soil at the site was removed to bedrock and replaced with clean fill, people are not expected to come in contact with contaminated soil. In addition, soil vapor intrusion is no longer expected to be a potential concern for on-site or offsite buildings. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-05-31 09:47:00
Record Upd:	2020-08-05 13:34:00
Updated By:	JEBROWN
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	tom geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	one library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Jared Dworken
Owner Company:	RXR Church-Division Tower A Holdings LLC
Owner Address:	75 Rockefeller Plaza, Suite 1300
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10019
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Jared Dworken
Owner Company:	RXR Church-Division Tower A Holdings LLC
Owner Address:	75 Rockefeller Plaza, Suite 1300
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10019
Owner Country:	United States of America
HW Code:	C360187
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	cadmium

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360187
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360187-06-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-08-05 13:59:00
Record Updated:	2020-08-05 13:59:00
Updated By:	MDKILMER
Crossref ID:	1910786

CHURCH-DIVISION STREET, TOWER A (Continued) **S123658107**

Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-02-21 10:08:00
Record Updated:	2020-02-21 10:08:00
Updated By:	MDKILMER
Crossref ID:	06/26/20
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-08-05 14:02:00
Record Updated:	2020-08-05 14:02:00
Updated By:	MDKILMER

AB202 **CON EDISON** **NY MANIFEST** **S117536317**
SSW **HUGUENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.187 mi.
985 ft. **Site 1 of 12 in cluster AB**

Relative: **Higher**

Actual: **91 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	HUGUENOT ST & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP004687802
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004687802
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2014
Trans1 Recv Date:	10/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014

CON EDISON (Continued) **S117536317**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004687802
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773160JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB203 **CON EDISON** **NY MANIFEST** **S117535594**
SSW **HUGENOT AVE & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.187 mi.
985 ft. **Site 2 of 12 in cluster AB**

Relative: **Higher**

Actual: **91 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT AVE & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004677621
Facility Status:	Not reported
Location Address 1:	HUGENOT AVE & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY

CON EDISON (Continued) **S117535594**

Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004677621
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/15/2014
Trans1 Recv Date: 10/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004677621
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012774907JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117535594**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB204 **CON EDISON** **NY MANIFEST** **S117535600**
SSW **HUGENOT ST & COLUMBUS AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.187 mi.
985 ft. **Site 3 of 12 in cluster AB**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HUGENOT ST & COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004677837
Facility Status:	Not reported
Location Address 1:	HUGENOT ST & COLUMBUS AVE
Code:	BP
Location Address 2:	MH 3424
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677837
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2014
Trans1 Recv Date:	10/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677837

CON EDISON (Continued) **S117535600**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774864JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC205 **FURNITURE RESTORNATION CENTER** **RCRA NonGen / NLR** **1000872286**
NNE **26 GARDEN ST** **FINDS** **NYD987034998**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.187 mi. **NY MANIFEST**
987 ft. **Site 1 of 3 in cluster AC**

Relative: **Lower**
Actual: **72 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	FURNITURE RESTORNATION CENTER
Handler Address:	26 GARDEN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801-4204
EPA ID:	NYD987034998
Contact Name:	Not reported
Contact Address:	GARDEN ST
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	GARDEN ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	KENT ZOOK
Owner Type:	Private
Operator Name:	KENT ZOOK
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KENT ZOOK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	26 GARDEN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-633-9292
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KENT ZOOK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	26 GARDEN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-633-9292
Owner/Operator Telephone Ext:	Not reported

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KENT ZOOK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 26 GARDEN ST
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-633-9292
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: FURNITURE RESTORNATION CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: FURNITURE RESTORNATION CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: FURNITURE RESTORNATION CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930602
Handler Name: FURNITURE RESTORNATION CENTER

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19980902
Evaluation Responsible Agency:	State

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYWME
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004505287

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000872286
Registry ID:	110004505287
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004505287
Name:	FURNITURE RESTORNATION CENTER
Address:	26 GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	FURNITURE RESTORATION OF NEW ROCHELLE
Address:	26 GARDEN ST
City,State,Zip:	NEW ROCHELLE, NY 10801-4204
Country:	USA
EPA ID:	NYD987034998
Facility Status:	Not reported
Location Address 1:	26 GARDEN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987034998
Mailing Name:	FURNITURE RESTORATION OF NEW ROCHELLE
Mailing Contact:	HENRY FLAVIC
Mailing Address 1:	166 WEBSTER AVE
Mailing Address 2:	Not reported

FURNITURE RESTORNATION CENTER (Continued) **1000872286**

Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	6111
Mailing Country:	USA
Mailing Phone:	9145923132

W206 **DIIORGI HOME** **NY LTANKS** **S106869098**
West **47 WARREN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.188 mi.
994 ft. **Site 3 of 4 in cluster W**

Relative: **Higher**
Actual: **98 ft.**

LTANKS:

Name:	DIIORGI HOME
Address:	47 WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0500295 / 2005-08-28
Facility ID:	0500295
Site ID:	343230
Spill Date:	2005-04-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2005-08-28
Spiller Name:	ANTHONY DIIORGI
Spiller Company:	DIIORGI HOME
Spiller Address:	47 WARREN STREET
Spiller County:	001
Spiller Contact:	ANTHONY DIIORGI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	289715
DEC Memo:	"August 28, 2005: GC RELIABLE REMOVED LUST AND CONTAMINATED SOIL. NORTHEST ENVIRONMENTAL DISPOSED OF 18 DRUMS OF SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SHE WILL CALLL BACK WITH MORE INFO:"

All Materials:

Site ID:	343230
Operable Unit ID:	1101915

DIIORGI HOME (Continued) **S106869098**

Operable Unit:	01
Material ID:	582154
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AD207 **CON EDISON MANHOLE: 4179** **RCRA NonGen / NLR** **1016969613**
North **350 NORTH AVE** **NY MANIFEST** **NYP004432886**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.192 mi.
1012 ft. **Site 1 of 13 in cluster AD**

Relative: **Lower**
Actual: **71 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140304
Handler Name:	CON EDISON MANHOLE: 4179
Handler Address:	350 NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10805
EPA ID:	NYP004432886
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140204
Handler Name:	CON EDISON MANHOLE: 4179
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Electronic Manifest Broker: Not reported

Receive Date: 20140304
Handler Name: CON EDISON MANHOLE: 4179
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 350 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004432886
Facility Status: Not reported
Location Address 1: OPP 350 NORTH AVE
Code: BP
Location Address 2: MH4179
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004432886
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

CON EDISON MANHOLE: 4179 (Continued) **1016969613**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004432886
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692716JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA208 **CON EDISON** **RCRA-VSQG** **1014398214**
SW **35 BARTELS PL** **RCRA NonGen / NLR** **NYP004205654**
1/8-1/4 **NEW ROCHELLE, NY 10805** **NY MANIFEST**
0.192 mi.
1015 ft. **Site 2 of 3 in cluster AA**

Relative: **Lower**
Actual: **67 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20150305
Handler Name:	CON EDISON	
Handler Address:		35 BARTELS PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004205654
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1014398214**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1014398214**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Date Form Received by Agency:		20210428
Handler Name:	CON EDISON	
Handler Address:		35 BARTELS PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP005246981
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON (Continued) **1014398214**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210608
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20210428
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1014398214**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

RCRA-VSQG:

Date Form Received by Agency:		20150305
Handler Name:	CON EDISON	
Handler Address:		35 BARTELS PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004205654
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

CON EDISON (Continued) **1014398214**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1014398214**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Date Form Received by Agency:		20210428
Handler Name:	CON EDISON	
Handler Address:		35 BARTELS PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP005246981
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

CON EDISON (Continued) **1014398214**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210608
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20210428
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

CON EDISON (Continued) **1014398214**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	35 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004205654
Facility Status:	Not reported
Location Address 1:	35 BARTELS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004205654
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2010
Trans1 Recv Date:	04/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004205654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **1014398214**

TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	002012659FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA209 **CON EDISON** **NY MANIFEST** **S117741191**
SW **35 BARTELS PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.192 mi.
1015 ft. **Site 3 of 3 in cluster AA**

Relative: **Lower**

Actual: **67 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	35 BARTELS PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004744074
Facility Status:	Not reported
Location Address 1:	35 BARTELS PL
Code:	BP
Location Address 2:	DRIP WATER
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004744074

CON EDISON (Continued) **S117741191**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	008683680FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117741191**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AE210 **SPILL NUMBER 0109254** **NY LTANKS** **S105230135**
WSW **40 WARREN ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.193 mi.
1018 ft. **Site 1 of 6 in cluster AE**

Relative: **Higher**
Actual: **92 ft.**

LTANKS:

Name:	APT BUILDING
Address:	40 WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0812107 / 2009-03-03
Facility ID:	0812107
Site ID:	409713
Spill Date:	2009-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-06
Spill Record Last Update:	2009-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	UNKNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	359905
DEC Memo:	"Piping failure, need to repair and retest - mm 02/20/2009 Passed retest results that came into PBS to J. O'Dee---BHY 3/3/09: Review of report submitted by WCC Tank Technology. Tank was tested by WCC on 1-9-09 for the property owner. The tank passed the test and documentation was submitted to the owner and the New Rochelle FD. Elite Environmental tested the tank for a prospective buyer on 2-6-09 and failed the tank, resulting in this spill report to the DEC. On 2-12-09 WCC again tested the tank with reps from New Rochelle FD and Royal Environmental. The tank passed this test. All three tests were preformed with the Horner Locator Plus system. Based upon the information received as of this date, DEC is requiring No Further Action at this time. jod"
Remarks:	"550 gal tank failed test/ failure due to bad fitting"

SPILL NUMBER 0109254 (Continued) **S105230135**

All Materials:

Site ID:	409713
Operable Unit ID:	1166213
Operable Unit:	01
Material ID:	2157665
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	SPILL NUMBER 0109254
Address:	40 WARREN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0109254 / 2001-12-19
Facility ID:	0109254
Site ID:	150939
Spill Date:	2001-12-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2001-12-19
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-19
Spill Record Last Update:	2002-01-03
Spiller Name:	Not reported
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MALLARDI RES
Spiller Phone:	(914) 636-7448
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128278
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"DRIVER OVERFILLED TANK - SPILL CONTAINED WITH PADS - CLEAN UP CREW ENROUTE"

All Materials:

Site ID:	150939
Operable Unit ID:	846633

SPILL NUMBER 0109254 (Continued) **S105230135**

Operable Unit:	01
Material ID:	530463
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	BARRAGAN RESIDENCE
Address:	40 WARREN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0908848 / 2010-04-08
Facility ID:	0908848
Facility Type:	ER
DER Facility ID:	128278
Site ID:	421508
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-06
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-06
Spill Record Last Update:	2010-04-08
Spiller Name:	GABREILLE BARRAGAN
Spiller Company:	GABREILLE BARRAGAN
Spiller Address:	40 WARREN ST
Spiller Company:	999
Contact Name:	NIKKI RICKETTS
DEC Memo:	"11/06/09: Property was purchased by a new owner within the past year. New owner passed away, his wife was having the tank replaced for sale of the property. Northeast installed a new AST in the basement and pulled this 1K tank. Contamination evident. New Rochelle FD inspected. Northeast will be completing clean up. jod 02/09/10 Northeast Environmental reported that they excavated and removed one tank along with 35.64 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG"
Remarks:	"REMOVAL OF A 1000 GALLON UST SOIL CONTAMINATION FOUND CLEAN UP PENDING."

SPILL NUMBER 0109254 (Continued) **S105230135**

All Materials:

Site ID:	421508
Operable Unit ID:	1177396
Operable Unit:	01
Material ID:	2170184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AB211 **CON EDISON TRANSFORMER MANHOLE: 5365** **RCRA NonGen / NLR** **1016972665**
SSW **595 MAIN ST** **NY MANIFEST** **NYP004464459**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.195 mi.
1029 ft. **Site 4 of 12 in cluster AB**

Relative: **Higher**

Actual: **93 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140412
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5365
Handler Address:	595 MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10804
EPA ID:	NYP004464459
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140312
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 5365
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140412
Handler Name: CON EDISON TRANSFORMER MANHOLE: 5365
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 595 MAIN ST
City,State,Zip: NEW ROCHELLE, NY 10804
Country: USA
EPA ID: NYP004464459
Facility Status: Not reported
Location Address 1: 595 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10804
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004464459
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON TRANSFORMER MANHOLE: 5365 (Continued) **1016972665**

Mailing Phone: Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/12/2014
Trans1 Recv Date:	03/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004464459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771156JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

212
South
1/8-1/4
0.196 mi.
1034 ft.

CON EDISON TRANSFORMER MANHOLE: 2806
592 MAIN ST
NEW ROCHELLE, NY 10804

RCRA NonGen / NLR **1016962648**
NY MANIFEST **NYP004357059**

Relative:
Higher

Actual:
95 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20131009
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2806
Handler Address:	592 MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10804
EPA ID:	NYP004357059
Contact Name:	CHRISTOPHER BLAICH
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130909
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2806
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131009
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 2806
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	592 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10804
Country:	USA
EPA ID:	NYP004357059
Facility Status:	Not reported
Location Address 1:	592 MAIN ST.
Code:	BP
Location Address 2:	MH # 2806
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004357059
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2013
Trans1 Recv Date:	09/09/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004357059

CON EDISON TRANSFORMER MANHOLE: 2806 (Continued) **1016962648**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707806JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB213 **RUSH MFG CORP** **RCRA NonGen / NLR** **1000238316**
SSW **18 COLUMBUS AVE.** **FINDS** **NYD981185051**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.198 mi. **NY MANIFEST**
1048 ft. **Site 5 of 12 in cluster AB**

Relative: **Lower**
Actual: **79 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	RUSH MFG CORP	
Handler Address:		18 COLUMBUS AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD981185051
Contact Name:		DENNIS MCNAMARA
Contact Address:		HUGUENOT ST
Contact City,State,Zip:		NEW ROCHELLE, NY 10801
Contact Telephone:		914-636-2700
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified

RUSH MFG CORP (Continued) **1000238316**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	HUGUENOT ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	MATTHEW RUSH
Owner Type:	Private
Operator Name:	MATTHEW RUSH
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

RUSH MFG CORP (Continued) **1000238316**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	U080
Waste Description:	METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MATTHEW RUSH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MATTHEW RUSH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MATTHEW RUSH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	RUSH MFG CORP

RUSH MFG CORP (Continued) **1000238316**

Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: RUSH MFG CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860303
Handler Name: RUSH MFG CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002092967

Click Here:

Environmental Interest/Information System:
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are

RUSH MFG CORP (Continued) **1000238316**

transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000238316
Registry ID:	110002092967
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002092967
Name:	RUSH MFG CORP
Address:	18 COLUMBUS AVE.
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	RUSH MANUFACTURING CORPORATION
Address:	18 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD981185051
Facility Status:	Not reported
Location Address 1:	381 HUGUENOT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981185051
Mailing Name:	RUSH MANUFACTURING CORPORATION
Mailing Contact:	RUSH MANUFACTURING CORPORATION
Mailing Address 1:	381 HUGUENOT STREET
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142362700

W214
West
1/8-1/4
0.200 mi.
1058 ft.

NYNEX
UNION AVENUE AND WARREN STREET
NEW ROCHELLE, NY

Site 4 of 4 in cluster W

NY MANIFEST **1009234555**
N/A

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

Name:	NYNEX
Address:	UNION AVENUE AND WARREN STREET
City,State,Zip:	NEW ROCHELLE, NY
Country:	USA
EPA ID:	NYP000932509
Facility Status:	Not reported
Location Address 1:	UNION AVENUE AND WARREN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000932509
Mailing Name:	NYNEX
Mailing Contact:	V ORCHIER
Mailing Address 1:	221 EAST 37TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123387126

215
WSW
1/8-1/4
0.201 mi.
1062 ft.

CITIZEN
33 GROVE ST
NEW ROCHELLE, NY

NY LTANKS **S100165790**
N/A

Relative:
Lower

Actual:
89 ft.

LTANKS:

Name:	CITIZEN
Address:	33 GROVE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8708588 / 1989-11-28
Facility ID:	8708588
Site ID:	135309
Spill Date:	1988-01-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-11-28
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported

CITIZEN (Continued) **S100165790**

Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-27
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	CAPT. FERGESON
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK RUPTURE IN CITIZEN'S BASEMENT. TANK TO BE EMPTIED."

All Materials:

Site ID:	135309
Operable Unit ID:	913258
Operable Unit:	01
Material ID:	463968
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	550.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AF216 **THE MALL** **NY LTANKS** **S100141913**
East **MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.203 mi.
1074 ft. **Site 1 of 3 in cluster AF**

Relative: **Lower**
Actual: **80 ft.**

LTANKS:

Name:	THE MALL
Address:	MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9010648 / 1991-01-04
Facility ID:	9010648
Site ID:	326514
Spill Date:	1991-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-01-04

THE MALL (Continued) **S100141913**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-10
Spill Record Last Update:	1992-07-31
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	263025
DEC Memo:	"Administratively closed due to file review and/or information received. If new information arises to contradict this determination DEC reserves the right to reopen this spill without prejudice. Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WATER FOUND IN TANK TO BE PUMPED OUT HONER EASY -.087"

All TTF:

Facility ID:	9010648
Spill Number:	9010648
Spill Tank Test:	1538129
Site ID:	326514
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	326514
Operable Unit ID:	947782
Operable Unit:	01
Material ID:	430787
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

THE MALL (Continued) **S100141913**

Recovered: .00
Oxygenate: Not reported

AG217 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1017773973**
South **CENTRE AVE & LEROY** **FINDS** **NYP004517694**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.204 mi.
1079 ft. **Site 1 of 5 in cluster AG**

Relative: **Higher**
Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140530
Handler Name:	CON EDISON SERVICE BOX:	3313
Handler Address:		CENTRE AVE & LEROY
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004517694
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140430
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140430
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 3313 (Continued) **1017773973**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140530
Handler Name: CON EDISON SERVICE BOX:	3313
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063800506

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AG218 **CON EDISON** **NY MANIFEST** **S117059593**
South **CENTRE AVE & LEROY** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.204 mi.
1079 ft. **Site 2 of 5 in cluster AG**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	CENTRE AVE & LEROY
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA

CON EDISON (Continued) **S117059593**

EPA ID: NYP004517694
Facility Status: Not reported
Location Address 1: C/O CENTRE AVE & LEROY PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004517694
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/30/2014
Trans1 Recv Date: 04/30/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/01/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004517694
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772797JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117059593**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG219 **CON EDISON SERVICE BOX: 3313** **RCRA NonGen / NLR** **1016973761**
South **LEROY PL & CENTER AVE** **NY MANIFEST** **NYP004475687**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.204 mi.
1079 ft. **Site 3 of 5 in cluster AG**

Relative: **Higher**

Actual: **101 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140422
Handler Name:	CON EDISON SERVICE BOX:	3313
Handler Address:		LEROY PL & CENTER AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10802
EPA ID:		NYP004475687
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140322
Handler Name: CON EDISON SERVICE BOX:	3313
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140422
Handler Name: CON EDISON SERVICE BOX:	3313
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	LEROY PL & CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004475687
Facility Status:	Not reported
Location Address 1:	SEC LEROY & CENTRE AVE
Code:	BP
Location Address 2:	SB3313
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004475687
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON SERVICE BOX: 3313 (Continued) **1016973761**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2014
Trans1 Recv Date:	03/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004475687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772784JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB220 **381-383 HUGUENOT LLC** **NY UST** **U004315578**
SSW **381 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.206 mi.
1086 ft. **Site 6 of 12 in cluster AB**

Relative: **Higher**

Actual: **90 ft.**

WESTCHESTER CO. UST:

Name:	381-383 HUGUENOT LLC
Address:	381 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-802286 / Active
Operator Name:	Not reported
Owner Name:	381-383 Huguenot LLC
Owner Street:	20 Amelia Earhart Lane
Owner Address2:	Not reported
Owner City:	Rye
Owner State:	NY
Owner Zipcode:	10580
GDS Number:	Not reported
Tank Number:	UST-1
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported
Tank Number:	UST-2
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None

381-383 HUGUENOT LLC (Continued) **U004315578**

Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Tank Number:	UST-3
Status:	2. Temporarily out of service
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

AH221 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016970578**
ESE **174 NORTH AVE** **NY MANIFEST** **NYP004442943**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.206 mi.
1089 ft. **Site 1 of 11 in cluster AH**

Relative: **Higher**
Actual: **91 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140316
Handler Name:	CON EDISON SERVICE BOX: 2040
Handler Address:	174 NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10804
EPA ID:	NYP004442943
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Historic Generators:

Receive Date:		20140216
Handler Name:	CON EDISON SERVICE BOX:	2040
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140316
Handler Name:	CON EDISON SERVICE BOX:	2040
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	174 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10804
Country:	USA
EPA ID:	NYP004442943
Facility Status:	Not reported
Location Address 1:	FO 174 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004442943

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/16/2014
Trans1 Recv Date:	02/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004442943
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692698JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016970578**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AD222 **HNJ REALTY** **PA MANIFEST** **S123092729**
North **358-364 N AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1092 ft. **Site 2 of 13 in cluster AD**

Relative: PA MANIFEST:
Lower No Details: No Details

Actual:
74 ft.

AD223 **HNJ REALTY** **PA MANIFEST** **S123092728**
North **358-364 N AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.207 mi.
1092 ft. **Site 3 of 13 in cluster AD**

Relative: Manifest Details:
Lower Year: 2017
Actual: Manifest Number: 006197432FLE
74 ft. Manifest Type: TSD Copy
Generator EPA Id: NYD012950779
Generator Date: 01/31/2017
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Evoqua Water Technologies LLC
TSD Facility Address: 118 Park Rd
TSD Facility City: Darlington
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D040
Container Number: 3
Container Type: Metal drums, barrels, kegs
Waste Quantity: 600
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD987270725
Date TSP Sig: Not reported

Year: 2017
Manifest Number: 006197432FLE
Manifest Type: TSD Copy
Generator EPA Id: NYD012950779
Generator Date: 01/31/2017
Mailing Address: Not reported
Mailing City,St,Zip: Not reported

HNJ REALTY (Continued) **S123092728**

Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Evoqua Water Technologies LLC
TSD Facility Address:	118 Park Rd
TSD Facility City:	Darlington
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	600
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD987270725
Date TSP Sig:	Not reported

AD224 **SCHMUCKLER'S DRY CLEANERS** **NY BROWNFIELDS** **S107787044**
North **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1092 ft. **Site 4 of 13 in cluster AD**

Relative: **Lower**
Actual: **74 ft.**

BROWNFIELDS:

Name:	SCHMUCKLER'S DRY CLEANERS
Address:	358-364 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10804
Program:	BCP
Site Code:	357446
Acres:	0.210
HW Code:	C360088
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/29/2005
Record Updated Date:	06/15/2021
Update By:	KJCARPEN
Site Description:	"Location: The Schmuckler s Dry Cleaners site is located in an urban area located at 258-364 North Avenue in New Rochelle, Westchester County. The site is 0.21 acres, most of which is covered by a two-story row building with a full basement. Site Features: Site Features: In addition to the former dry cleaners, historically located on the first floor, the site also includes an enclosed backyard area to the immediate west of the building. The backyard consists of lawn, elevated planting beds, concrete pad, and a paved walkway. Current Zoning/Use(s): The site is commercially zoned, and currently has five commercial tenants occupying both the first and second floors. Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commercial uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site is provided from a municipal source. Past Uses of the Site: The building on-site was built in 1891, and operated by Schmuckler s Cleaners from 1914 to 2006 on the first floor and basement of the building. Additions were added to the building in 1937, and two in

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

1987. The site was acquired by the Volunteer, HNJ Realty, LLC, in August 2005, and entered into the Brownfield Cleanup Program in June 2006. Site Geology and Hydrogeology: The site is underlain by fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater flows to the southeast. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater. "

Env Problem:

"Based on the investigations conducted to date, the which included the analysis for volatile organic and semi-volatile organic compounds (VOCs and SVOCs), inorganics, polychlorinated bi-phenols (PCBs) and pesticides in soil and groundwater and VOCs in soil vapor, the primary contaminants of concern at the site are chlorinated volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE) and its breakdown compounds, in soils, groundwater, sub-slab vapor, and soil gas; petroleum-related VOCs in soils, groundwater, sub-slab vapor, and soil gas; and semi-volatile organic compounds (SVOCs) in groundwater. In August 2015 an in situ pilot test was performed to assess potential remedial effectiveness of an enhanced biological product. Prior to the pilot injection, the test well contained 27,000 parts per billion (ppb) of PCE, 960 ppb of trichloroethylene (TCE), 2,100 ppb of cis-1,2-dichloroethylene (DCE) and 49 ppb of vinyl chloride (VC). Post injection levels after two months were 8,100 ppb of PCE, 11,000 ppb of TCE, 1,500 ppb of cis-1,2-DCE, and 53 ppb of VC. The decrease in PCE concentrations, coupled with the increase in degradation products, indicate that the breakdown of contaminants (dechlorination) is occurring. SVOC concentrations also decreased in the test well after the pilot. For example phenanthrene levels dropped from 78 ppb to 3.7 ppb two months after the pilot injection. An expansion of the pilot test using the same enhanced biological product was performed in October 2017. This time, the injections occurred in five wells in the basement and outside the building, while monitoring occurred in six wells located around the site. In July 2017, prior to the expansion of the expanded test, the highest concentration of PCE was 17,000 ppb, TCE was 2,100 ppb, cis-1,2-DCE was 1,600 ppb, and VC was 73. Two months after the injections, in December 2017, the concentrations of contaminants in the same well were: 1,300 ppb PCE, 17,000 ppb TCE, 1,900 ppb cis-1,2-DCE, and 61 ppb VC. The highest concentration of SVOCs during the pilot expansion was phenanthrene which dropped from 2,000 ppb to 540 ppb two months after the injection event. In addition, approximately 40-gallons of LNAPL have been collected to date just off-site in the southeast, downgradient direction using both bailers and a sorbent recovery socks left in the well in between monitoring/bailing events. Soils: Tetrachloroethylene (PCE), trichloroethene (TCE), and multiple petroleum related VOCs were detected in onsite soils underneath the building slab. The highest concentration of PCE at 210 parts per million (ppm), exceeding restricted commercial soil cleanup objectives (SCOs), was located underneath the former dry cleaning equipment room. Other contaminants detected in soils only exceeded the Protection of Groundwater SCOs. These exceedences were largely in soils located downgradient of the dry cleaning equipment room and consisted of: TCE at 1.3 ppm, cis-1,2 dichloroethene (cis-1,2-DCE) at 3 ppm, n-propylbenzene at 16 ppm, m+p xylenes at 15 ppm, ethylbenzene

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

at 6.6 ppm, 1,3,5-trimethylbenzene at 63 ppm, and 1,2,4-trimethylbenzene at 99 ppm. There is no indication of off-site soil contamination. Groundwater: Petroleum-based floating product (light non-aqueous phase liquid or LNAPL) was observed in groundwater under much of the on-site building slab, a maximum of 6 inches thick under the former dry cleaning equipment room. Also observed were very high concentrations of select VOCs also under the former drycleaning equipment room. The maximum detected PCE was 830,000 parts per billion (ppb), and TCE at 58,000 ppb. 25 individual VOCs were also detected in site groundwater samples exceeding NYS Class GA groundwater standards. These include the above-mentioned PCE, TCE, as well as other maximum detected concentrations of PCE breakdown products: cis-1,2-DCE at 8,700 ppb, and vinyl chloride at 28 ppb. BTEX was detected, with benzene at 62 ppb, toluene at 130 ppb, ethylbenzene at 150 ppb, m+p xylene at 520 ppb, and o-xylene at 290 ppb. Other significant concentrations of VOCs detected in groundwater include 1,3,5-trimethylbenzene at 890 ppb, and 1,2,4-trimethylbenzene at 840 ppb. Eight SVOCs were detected over groundwater standards in groundwater under the building slab, including napthalene at a concentration of 1300 ppb, phenanthrene at 2400 ppb, acenapthene at 710 ppb, and antracene at 280 ppb. Bedrock wells were installed off-site in the downgradient, sidegradient, and upgradient directions. Petroleum-based VOCs and SVOCs were detected in the bedrock aquifer at concentrations above groundwater standards. For VOCs, total maximum BTEX concentration of 722 ppb was detected in a downgradient bedrock well. 11 individual SVOC contaminants were detected over groundwater standards in the same downgradient off-site bedrock well, including naphthalene at 4100 ppb, phenanthrene at 2800 ppb, acenapthene at 710 ppb, and antracene at 300 ppb. The extent of groundwater contamination is concentrated underneath the on-site building slab, with petroleum-based VOC and SVOC contaminants and LNAPL extending off-site in the bedrock downgradient or southeast direction. Soil Gas/Soil Vapor: The high concentrations of PCE (787,000 ug/m3), TCE (15,200 ug/m3), cis-1,2-DCE (46,000 ug/m3), and Vinyl Chloride (34 ug/m3) in soil vapor under the slab of the on-site building required the installation and continuing operation of a combined soil vapor extraction and sub-slab mitigation system during a 2008-2013 Interim Remedial Measure (IRM) action. PCE (at 91 ug/m3) and TCE (13.4 ug/m3) were also detected in soil gas outside of the building near the location of a former drywell. Benzene (37 ug/m3), toluene (126 ug/m3), ethylbenzene (85 ug/m3), xylene (555 ug/m3), 1,3,5-trimethylbenzene (3 ug/m3), and 1,2,4-trimethylbenzene (14 ug/m3) were also detected in subslab vapor and soil gas. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site. "

Health Problem: "People may contact contaminants in soil or groundwater if they dig below the surface or contact contaminated groundwater. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of the buildings, is referred to as soil vapor intrusion. A combination soil vapor extraction and sub-slab depressurization system was installed in the on-site building to

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

prevent vapors beneath the slab from entering the building. There is a potential for inhalation of site contaminants due to soil vapor intrusion at this building when the sub-slab depressurization system is turned off for a period of time during groundwater bioremediation injection treatments. Soil vapor intrusion sampling at one off-site building did not identify any soil vapor intrusion concerns for that building. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for other off-site buildings."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:54'51 / 73:47'03
Dell:	False
Record Add:	2005-12-29 14:46:00
Record Upd:	2015-11-10 15:54:00
Updated By:	KATHOMPS
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Comfort Homes & Property Management LLC
Owner Address:	358 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Liberty Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	HAL SHAPIRO
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave
Owner Addr2:	#107
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Hal Shapiro
Owner Company:	HNJ REALTY, LLC
Owner Address:	364 North Ave #107
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Stephanie Mossey
Owner Company:	NYSDEC Region 3

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	United Community Center of Westchester, Inc.
Owner Address:	360 - 362 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Neighborhood Taxi
Owner Address:	364 North Ave; Suite 108
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Swan Beauty Spa, Inc
Owner Address:	364 North Ave., Room 101
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	C360088
Waste Type:	fluorine
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	cymene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1-dichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,4-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	acenaphthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2-dichlorobenzene

SCHMUCKLER'S DRY CLEANERS (Continued) **S107787044**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	diethyl phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,1,2,2-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360088
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	571503495
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-09-07 13:27:00
Record Updated:	2017-09-07 13:27:00
Updated By:	KATHOMPS

AD225 **SCHMUCKLER'S DRY CLEANERS - OFF SITE** **NY BROWNFIELDS** **S121933772**
North **358-364 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.207 mi.
1092 ft. **Site 5 of 13 in cluster AD**

Relative: **Lower**

Actual: **74 ft.**

BROWNFIELDS:

Name:	SCHMUCKLER'S DRY CLEANERS - OFF SITE
Address:	358-364 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10804
Program:	BCP
Site Code:	551607
Acres:	Not reported

SCHMUCKLER'S DRY CLEANERS - OFF SITE (Continued) **S121933772**

HW Code:	C360088A
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/13/2017
Record Updated Date:	10/26/2020
Update By:	KJCARPEN
Site Description:	"Location: This is the off-site component to Schmuckler s Dry Cleaners site which is located in an urban area at 258-364 North Avenue in New Rochelle, Westchester County. Site Features: This off-site investigation covers an approximately one city block area encompassing surrounding buildings and downgradient direction of groundwater flow. Current Zoning/Use(s): Properties along North Avenue are predominantly zoned for commercial or mixed use, some maintaining residential apartments above. Commerical uses dominate areas within one block east and west of North Avenue with the exception of a multi-unit residential building immediately to the west of the site. Drinking water on-site is provided from a municipal source. Past Uses of the Site: The area of the off-site includes multiple commercial and residential current and historical uses. Site Geology and Hydrogeology: The site is underlain by fill which is underlain by poorly sorted glacial material (silty-clay with sand and gravel). The highly weathered bedrock surface is between 9 and 13 feet below ground surface at site. Groundwater was encountered between 9 to 12 feet below site. Bedrock groundwater flows to the southeast. Only two overburden wells onsite have produced water, therefore a groundwater flow direction in overburden cannot be determined. It is assumed that it flows in the same basic southeast direction as the bedrock groundwater."
Env Problem:	"Chlorinated volatile organic compounds (CVOCs), Per- and polyfluoroalkyl substances (PFAS) and petroleum-related contaminants are associated with the on-site BCP at levels prompting an on-site significant threat determination. While on-site measures are planned to prevent contamination from leaving the site, contamination in groundwater was known to have migrated off site. Information, including but not limited to the nature and extent of contamination in soils, groundwater, indoor air and sub-slab vapor, will be revised as additional information becomes available. "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported

SCHMUCKLER'S DRY CLEANERS - OFF SITE (Continued) **S121933772**

Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AD226 **SCHMUKLER'S CLEANERS** **NY DRYCLEANERS** **S110247878**
North **360 NORTH AVE.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.210 mi.
1111 ft. **Site 6 of 13 in cluster AD**

Relative: DRYCLEANERS:
Lower

Name:	SCHMUKLER'S CLEANERS
Address:	360 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00327
Phone Number:	914-632-2705
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	2013-11-07 00:00:00
Install Date:	98/06
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
75 ft.

AD227 **SCHMUCKLERS CLEANERS** **RCRA-VSQG** **1000303485**
North **360 NORTH AVE** **NY MANIFEST** **NYD012950770**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.210 mi.
1111 ft. **Site 7 of 13 in cluster AD**

Relative: RCRA-VSQG:
Lower

Date Form Received by Agency:		20080330
Handler Name:	SCHMUCKLERS CLEANERS	
Handler Address:		360 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD012950770
Contact Name:		HAL I SHAPIRO
Contact Address:		BLACK BIRCH LANE
Contact City,State,Zip:		SCARSDALE, NY 10583
Contact Telephone:		917-693-9019
Contact Fax:		Not reported
Contact Email:		HALSHAP@GMAIL.COM
Contact Title:		Not reported

Actual:
75 ft.

SCHMUCKLERS CLEANERS (Continued) **1000303485**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	BLACK BIRCH LANE
Mailing City,State,Zip:	SCARSDALE, NY 10583
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	HNJ REALTY LLC
Legal Status:	Private
Date Became Current:	20070801
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Owner/Operator Name: HNJ REALTY LLC
Legal Status: Private
Date Became Current: 20050801
Date Ended Current: Not reported
Owner/Operator Address: 25 BLACK BIRCH LANE
Owner/Operator City,State,Zip: SCARSDALE, NY 10583
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PREMIUM VALET SERVICES LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 360 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-632-2705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19980309
Handler Name: SCHMUKLERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080331
Handler Name: SCHMUCKLERS CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19931029
Handler Name: SCHMUKLERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SCHMUKLERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080330
Handler Name: SCHMUCKLERS CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19990520
Actual Return to Compliance Date: 20030908
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: 19990806
Enforcement Identifier: 000
Date of Enforcement Action: 19990706
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20030908
Actual Return to Compliance Date: 20030918
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20030918
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19990520
Actual Return to Compliance Date:	20030908
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	19990806
Enforcement Identifier:	000
Date of Enforcement Action:	19990706
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYWME
Enforcement Responsible Sub-Organization:	R3
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	19990520
Actual Return to Compliance Date:	20030908
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	19990806
Enforcement Identifier:	000
Date of Enforcement Action:	19990706
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19990520
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20030908
Scheduled Compliance Date: 19990806
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20030908
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20030918
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19990520
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20030908
Scheduled Compliance Date: 19990806
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Former Citation:	Not reported
Evaluation Date:	19990520
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYWME
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	20030908
Scheduled Compliance Date:	19990806
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	SHMUCKLERS DRY CLEANERS
Address:	360 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD012950770
Facility Status:	Not reported
Location Address 1:	360 NORTH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012950770
Mailing Name:	SHMUCKLERS DRY CLEANERS
Mailing Contact:	SHMUCKLERS DRY CLEANERS
Mailing Address 1:	360 NORTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146322705

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	09/18/2006
Trans1 Recv Date:	09/18/2006
Trans2 Recv Date:	09/25/2006
TSD Site Recv Date:	09/26/2006
Part A Recv Date:	Not reported

SCHMUCKLERS CLEANERS (Continued) **1000303485**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD012950770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	000814271JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI228 **NEW ROCHELLE HOSPITAL** **NY LTANKS** **S100141273**
NW **COVION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.211 mi.
1112 ft. **Site 1 of 6 in cluster AI**

Relative:
Higher

Actual:
102 ft.

LTANKS:

Name:	NEW ROCHELLE HOSPITAL
Address:	COVION PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9003911 / 1991-03-15
Facility ID:	9003911
Site ID:	136814
Spill Date:	1990-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	WXWADSWO

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

Referred To:	Not reported
Reported to Dept:	1990-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-11
Spill Record Last Update:	1991-04-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	117069
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 03/15/91: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WILL EIR PBS TO FOLLOW AINLEY +.094"

All TTF:

Facility ID:	9003911
Spill Number:	9003911
Spill Tank Test:	1537277
Site ID:	136814
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	136814
Operable Unit ID:	941734
Operable Unit:	01
Material ID:	435036
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

NEW ROCHELLE HOSPITAL (Continued) **S100141273**

Recovered: .00
Oxygenate: Not reported

AI229 **SOUND SHORE MED CENTER** **NY LTANKS** **S107523501**
NW **16 GUION PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1138 ft. **Site 2 of 6 in cluster AI**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Name:	SOUND SHORE MED CENTER
Address:	16 GUION PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512440 / 2006-12-19
Facility ID:	0512440
Site ID:	358758
Spill Date:	2006-01-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-01-26
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2021-05-17
Spiller Name:	VERONICA
Spiller Company:	SOUND SHORE MED CENTER
Spiller Address:	16 GUION PLACE
Spiller County:	001
Spiller Contact:	VERONICA
Spiller Phone:	(201) 489-8700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308757
DEC Memo:	"Tank removed, no contamination found. NFA jod 12/22/06 - Letter from Wayne Schneider of WCDOD dated 8/29/06 addressed to Dir. of Engr., Sound Shore Medical Center, has requested NYSDEC to colose this spill #."
Remarks:	"Tank test failure. Ullage leak was detected."

All TTF:

Facility ID:	0512440
Spill Number:	0512440
Spill Tank Test:	1549678
Site ID:	358758
Tank Number:	5
Tank Size:	2000

SOUND SHORE MED CENTER (Continued) **S107523501**

Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	358758
Operable Unit ID:	1115985
Operable Unit:	01
Material ID:	2106096
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI230 **SOUND SHORE MEDICAL CENTER** **PA MANIFEST** **S111771577**
NW **16 GUION PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1138 ft. **Site 3 of 6 in cluster AI**

Relative:
Higher

Actual:
100 ft.

Manifest Details:

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U188
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

SOUND SHORE MEDICAL CENTER (Continued) **S111771577**

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006962317JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD075431502
Generator Date:	10/19/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AI231 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **RCRA-SQG** **1000130172**
NW **16 GUION PL** **FINDS** **NYD075431502**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.216 mi. **NY MANIFEST**
1138 ft. **Site 4 of 6 in cluster AI**

Relative: **Higher**
Actual: **100 ft.**

RCRA-SQG:

Date Form Received by Agency:	20131031
Handler Name:	SOUND SHORE MEDICAL CENTER
Handler Address:	16 GUION PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYD075431502
Contact Name:	GARRETT T DOERING
Contact Address:	E 210TH ST
Contact City,State,Zip:	BRONX, NY 10467
Contact Telephone:	717-920-7600
Contact Fax:	718-920-7609
Contact Email:	GDOREING@MONTEFIORE.ORG
Contact Title:	DIRECTOR OF ENVIRONMENTAL HEALTH & SAFETY
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	GUION PL
Mailing City,State,Zip:	NEW ROCHELLE, NY 10802
Owner Name:	MONTEFIORE NEW ROCHELLE HOSPITAL INC
Owner Type:	Private
Operator Name:	MONTEFIORE NEW ROCHELLE HOSPITAL INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140429
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D009
Waste Description:	MERCURY

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D022
Waste Description:	CHLOROFORM
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	P012
Waste Description:	ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE
Waste Code:	P105
Waste Description:	SODIUM AZIDE
Waste Code:	U010
Waste Description:	AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C
Waste Code:	U035
Waste Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Waste Code:	U044
Waste Description:	CHLOROFORM (OR) METHANE, TRICHLORO-
Waste Code:	U058
Waste Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Waste Code:	U059
Waste Description:	5,12-NAPHTHACENEDIONE,

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U170
Waste Description: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

Waste Code: U188
Waste Description: PHENOL

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: SOUND SHORE MEDICAL CENTER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 16 GUION PL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802-9982
Owner/Operator Telephone: 914-632-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SOUND SHORE MEDICAL CENTER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 16 GUION PL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802-9982
Owner/Operator Telephone: 914-632-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SOUND SHORE MEDICAL CENTER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 16 GUION PL
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10802-9982
Owner/Operator Telephone: 914-632-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Legal Status: Private
Date Became Current: 20131101

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Date Ended Current: Not reported
Owner/Operator Address: 200 CORPORATE BLVD SOUTH SUITE 175
Owner/Operator City,State,Zip: YONKERS, NY 10701
Owner/Operator Telephone: 914-378-6300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MONTEFIORE NEW ROCHELLE HOSPITAL INC
Legal Status: Private
Date Became Current: 20131101
Date Ended Current: Not reported
Owner/Operator Address: 200 CORPORATE BLVD SOUTH SUITE 175
Owner/Operator City,State,Zip: YONKERS, NY 10701
Owner/Operator Telephone: 914-378-6300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SOUNDSHORE MEDICAL CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SOUNDSHORE MEDICAL CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970908
Handler Name: SOUNDSHORE MEDICAL CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131031
Handler Name: SOUND SHORE MEDICAL CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62211
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20120911
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004368620

Click Here:

Environmental Interest/Information System:
COMPLIANCE AND EMISSIONS REPORTING
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ELECTRIC GENERATOR
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000130172
Registry ID: 110004368620
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004368620
Name: MONTEFIORE - NEW ROCHELLE HOSPITAL
Address: 16 GUION PL
City,State,Zip: NEW ROCHELLE, NY 10801

NY MANIFEST:
Name: MONTEFIORE NEW ROCHELLE HOSPITAL
Address: 16 GUION PL
City,State,Zip: NEW ROCHELLE, NY 10802-9982
Country: USA
EPA ID: NYD075431502
Facility Status: Not reported
Location Address 1: 16 GUION PLACE
Code: BP
Location Address 2: Not reported

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD075431502
Mailing Name:	MONTEFIORE NEW ROCHELLE HOSPITAL
Mailing Contact:	JARED SHAPIRO
Mailing Address 1:	111 EAST 210TH STREET
Mailing Address 2:	ENVIRONMENTAL HEALTH & SAFETY
Mailing City:	BRONX
Mailing State:	NY
Mailing Zip:	10467
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189207600

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2013
Trans1 Recv Date:	12/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD075431502
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	006926469FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	51
Units:	P - Pounds

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **1000130172**

Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	U010
Waste Code 1_2:	U035
Waste Code 1_3:	U058
Waste Code 1_4:	U059
Waste Code 1_5:	U150
Waste Code 1_6:	Not reported

AI232 **MONTEFIORE - NEW ROCHELLE HOSPITAL** **NY UST U003857945**
NW **16 GUION PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.216 mi.
1138 ft. **Site 5 of 6 in cluster AI**

Relative: **Higher**
Actual: **100 ft.**

WESTCHESTER CO. UST:

Name:	MONTEFIORE - NEW ROCHELLE HOSPITAL
Address:	16 GUION PLACE
City,State,Zip:	NEW ROCHELLE, NY 10802
Id/Status:	3-123269 / Active
Operator Name:	Montefiore Medical Center
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10467
GDS Number:	Not reported
Tank Number:	2 day
Status:	4. Closed - in place
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1978
Date Perm Closure:	Not reported
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	4
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	0008. Diesel

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1981
Date Perm Closure:	07/19/2006
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5B
Status:	1. In-Service
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	07/01/2006
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	8
Status:	1. In-Service
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	0
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	10/22/2010
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	plastic sleeve
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	MONTEFIORE - NEW ROCHELLE HOSPITAL
Address:	16 GUION PLACE
City,State,Zip:	NEW ROCHELLE, NY 10802
PBS Number:	3-123269
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Montefiore Medical Center
Owner Name:	Montefiore Medical Center
Owner Street:	111 East 210th Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10467

Tank Number:	# 8 Day
Status:	1. In-Service
Date Installation:	10/22/2010
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only),6. Remote impounding area
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	04
Status:	3. Closed - Removed
Date Installation:	01/01/1997
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	12/19/2018
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	other
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	99. Other
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 day
Status:	1. In-Service
Date Installation:	06/01/1976
Capacity:	75
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Date Installation:	12/01/1967
Capacity:	16000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/11/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1971
Capacity:	30000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3 day
Status:	1. In-Service
Date Installation:	07/01/1980
Capacity:	50
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	12/01/1981
Capacity:	500
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/23/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	12/01/2005
Capacity:	700
Product Stored:	0008. Diesel

MONTEFIORE - NEW ROCHELLE HOSPITAL (Continued) **U003857945**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/2016
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

233
West
1/8-1/4
0.216 mi.
1140 ft.

RESIDENCE
79 WARREN ST
NEW ROCHELLE, NY

NY LTANKS **S107489339**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Name:	RESIDENCE
Address:	79 WARREN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0510555 / 2006-03-28
Facility ID:	0510555
Site ID:	356553
Spill Date:	2005-12-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported

RESIDENCE (Continued) **S107489339**

SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-08
Spill Record Last Update:	2006-03-28
Spiller Name:	ISHMAL GALVIN
Spiller Company:	RESIDENCE
Spiller Address:	79 WARREN ST
Spiller County:	001
Spiller Contact:	ISHMAL GALVIN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	306611
DEC Memo:	"March 28, 2006: GRAZI-1 CORP DISPOSED OF LUST AND 67.95 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons"

All Materials:

Site ID:	356553
Operable Unit ID:	1113853
Operable Unit:	01
Material ID:	2103913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI234 **66 MEMORIAL BLVD** **NY LTANKS** **S104621761**
NW **66 MEMORIAL BLVD** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.216 mi.
1140 ft. **Site 6 of 6 in cluster AI**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	66 MEMORIAL BLVD
Address:	66 MEMORIAL BLVD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0002907 / 2000-10-24
Facility ID:	0002907
Site ID:	59397
Spill Date:	2000-06-08
Spill Cause:	Tank Failure

66 MEMORIAL BLVD (Continued) **S104621761**

Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-06-08
CID:	389
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-08
Spill Record Last Update:	2000-11-21
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	58153
DEC Memo:	""
Remarks:	"caller reporting a spill of material from a tank being hit while escavating land for a basement. no callback is necessary caller is anaymous. clena up is being done at this time."

All Materials:

Site ID:	59397
Operable Unit ID:	824416
Operable Unit:	01
Material ID:	551247
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AC235 **LEXINGTON CENTER FOR RECOVERY INC** **NJ MANIFEST** **S117987423**
NNE **3 COTTAGE PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.216 mi.
1141 ft. **Site 2 of 3 in cluster AC**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYR000193854
Mail Address:	COTTAGE PL
Mail City/State/Zip:	NEW ROCHELLE, NY 10801
Facility Phone:	Not reported
Emergency Phone:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Contact:	LISA OBRIEN
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008900746JJK
EPA ID:	NYR000193854
Date Shipped:	5/25/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NY0001031814
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE, NY 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **S117987423**

Quantity:	30.00 Pounds
Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	Not reported
Quantity:	300.00 Pounds

AC236 **LEXINGTON CENTER FOR RECOVERY INC** **RCRA NonGen / NLR** **1014958140**
NNE **3 COTTAGE PL** **NY MANIFEST** **NYR000193854**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.216 mi.
1141 ft. **Site 3 of 3 in cluster AC**

Relative: **Lower**

Actual: **75 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20120927
Handler Name:	LEXINGTON CENTER FOR RECOVERY INC
Handler Address:	3 COTTAGE PL
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000193854
Contact Name:	LISA OBRIEN
Contact Address:	COTTAGE PL
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	914-235-6633 1503
Contact Fax:	Not reported
Contact Email:	LOBRIEN@LEXINGTONCTR.ORG
Contact Title:	OFFICE MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	COTTAGE PL
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	BARRY J JACOBSON
Owner Type:	Private
Operator Name:	LEXINGTON CENTER FOR RECOVERY INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151120
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LEXINGTON CENTER FOR RECOVERY INC
Legal Status:	Private
Date Became Current:	20080701
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	BARRY J JACOBSON
Legal Status:	Private
Date Became Current:	19830202
Date Ended Current:	Not reported
Owner/Operator Address:	9 E 40TH ST 8TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-889-7460
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LEXINGTON CENTER FOR RECOVERY INC
Legal Status:	Private
Date Became Current:	20080701
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	BARRY J JACOBSON
Legal Status:	Private
Date Became Current:	19830202
Date Ended Current:	Not reported
Owner/Operator Address:	9 E 40TH ST 8TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-889-7460
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120927
Handler Name:	LEXINGTON CENTER FOR RECOVERY INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20120518
Handler Name:	LEXINGTON CENTER FOR RECOVERY INC
Federal Waste Generator Description:	Large Quantity Generator

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62142
NAICS Description: OUTPATIENT MENTAL HEALTH AND SUBSTANCE ABUSE CENTERS

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20140219
Evaluation Responsible Agency: State

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYFKY
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	LEXINGTON CENTER FOR RECOVERY INC
Address:	3 COTTAGE PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000193854
Facility Status:	Not reported
Location Address 1:	3 COTTAGE PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000193854
Mailing Name:	LEXINGTON CENTER FOR RECOVERY INC
Mailing Contact:	LEXINGTON CENTER FOR RECOVERY INC
Mailing Address 1:	3 COTTAGE PL
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142356633

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NY0001031814
Trans2 State ID:	NJ0000027193
Generator Ship Date:	05/25/2012
Trans1 Recv Date:	05/25/2012
Trans2 Recv Date:	06/01/2012
TSD Site Recv Date:	06/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000193854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

LEXINGTON CENTER FOR RECOVERY INC (Continued) **1014958140**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008900746JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D009
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH237 **35 CLINTON PLACE LLC** **NY AST** **A100359845**
SE **35 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1150 ft. **Site 2 of 11 in cluster AH**

Relative: **Higher**
Actual: **90 ft.**

WESTCHESTER CO. AST:

Name:	35 CLINTON PLACE LLC
Address:	35 CLINTON PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-078646
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Norman Avelenda
Owner Name:	35 Clinton Place LLC
Owner Street:	35 Clinton Place, #1B
Owner Address2:	Not reported
Owner City/State/Zip:	New Rochelle, NY 10801
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1939
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil

35 CLINTON PLACE LLC (Continued) **A100359845**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	4. Groundwater Well
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	3. Gravity

AJ238 **MAYCO, LLC** **NY AST** **A100252337**
NNW **18-20 MAY ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.218 mi.
1151 ft. **Site 1 of 3 in cluster AJ**

Relative: **Lower**
Actual: **79 ft.**

WESTCHESTER CO. AST:

Name:	MAYCO, LLC
Address:	18-20 MAY ST
City,State,Zip:	NEW ROCHELLE, NY 10801
PBS Number:	3-175447
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Alex Hay
Owner Name:	Mayco, LLC
Owner Street:	P.O. Box 1755
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10156
Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1980
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

239
SE
1/8-1/4
0.218 mi.
1151 ft.

CON EDISON
46 CLINTON PL
NEW ROCHELLE, NY 10801

RCRA NonGen / NLR **1012184999**
NY MANIFEST **NYP004157665**

Relative:
Higher

Actual:
91 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		46 CLINTON PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004157665
Contact Name:		DAVID DUKE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-580-8383
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1012184999**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20080401
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1012184999**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 46 CLINTON PL
City,State,Zip: NEW ROCHELLE, NY 10801
Country: USA
EPA ID: NYP004157665
Facility Status: Not reported
Location Address 1: 46 CLINTON PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10805
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004157665
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRAMKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/01/2008
Trans1 Recv Date: 04/01/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/01/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004157665

CON EDISON (Continued) **1012184999**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	002013408FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	180
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	6
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB240 **THE HUGUENOT** **NY BROWNFIELDS** **S127012987**
SSW **387 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.219 mi.
1154 ft. **Site 7 of 12 in cluster AB**

Relative: **Lower**

Actual: **89 ft.**

BROWNFIELDS:

Name:	THE HUGUENOT
Address:	387 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	544502
Acres:	0.393
HW Code:	C360157
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	03/29/2017
Record Updated Date:	12/29/2021
Update By:	DRLANNER
Site Description:	"Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential

THE HUGUENOT (Continued) **S127012987**

unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem:

"Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual

THE HUGUENOT (Continued) **S127012987**

contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water

THE HUGUENOT (Continued) **S127012987**

quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."

Dump: False

THE HUGUENOT (Continued) **S127012987**

Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-10-22 12:50:00
Record Upd:	2021-12-21 12:03:00
Updated By:	DRLANNER
Own Op:	6
Sub Type:	P02
Owner Name:	Frank Chechile
Owner Company:	381-383 Huguenot LLC
Owner Address:	20 Amelia Earhart Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Rye, NY 10580
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	Frank Chechile
Owner Company:	381-383 Huguenot LLC
Owner Address:	20 Amelia Earhart Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Rye, NY 10580
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Larry Sheldon
Owner Company:	New Rochelle Public Library
Owner Address:	One Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	C360157
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	selenium

THE HUGUENOT (Continued) **S127012987**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN

THE HUGUENOT (Continued) **S127012987**

Waste Code:	Not reported
HW Code:	C360157
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	fluorene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sec-butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360157-08-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-13 16:15:00
Record Updated:	2020-10-13 16:15:00
Updated By:	DRLANNER
Crossref ID:	591483399
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-10-13 15:49:00
Record Updated:	2020-10-13 15:49:00
Updated By:	DRLANNER
Crossref ID:	11/03/2017
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-13 16:19:00

THE HUGUENOT (Continued) **S127012987**

Record Updated:	2020-10-13 16:21:00
Updated By:	DRLANNER
Crossref ID:	9604099
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-10-19 11:54:00
Record Updated:	2018-10-19 11:54:00
Updated By:	JBODEE

AB241 **THE HUGUENOT** **NY ENG CONTROLS** **S127013001**
SSW **387 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.219 mi.
1154 ft. **Site 8 of 12 in cluster AB**

Relative: **Lower**

Actual: **89 ft.**

ENG CONTROLS:

Name:	THE HUGUENOT
Address:	387 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	544502
HW Code:	C360157
Control Code:	36
Control Type:	ENG
Date Record Added:	09/15/2020
Date Rec Updated:	12/29/2021
Updated By:	DRLANNER
Site Description:	"Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential

THE HUGUENOT (Continued) **S127013001**

sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding

THE HUGUENOT (Continued) **S127013001**

the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene

THE HUGUENOT (Continued) **S127013001**

chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository

THE HUGUENOT (Continued) **S127013001**

Sub Type:	NNN
Owner Name:	Larry Sheldon
Owner Company:	New Rochelle Public Library
Owner Address:	One Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	C360157
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	selenium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	iron

THE HUGUENOT (Continued) **S127013001**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	fluorene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN

THE HUGUENOT (Continued) **S127013001**

Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sec-butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360157-08-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-13 16:15:00
Record Updated:	2020-10-13 16:15:00
Updated By:	DRLANNER
Crossref ID:	591483399
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-10-13 15:49:00
Record Updated:	2020-10-13 15:49:00
Updated By:	DRLANNER
Crossref ID:	11/03/2017
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-13 16:19:00
Record Updated:	2020-10-13 16:21:00
Updated By:	DRLANNER
Crossref ID:	9604099
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-10-19 11:54:00
Record Updated:	2018-10-19 11:54:00
Updated By:	JBODEE

Name:	THE HUGUENOT
Address:	387 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	544502
HW Code:	C360157
Control Code:	15
Control Type:	ENG
Date Record Added:	09/15/2020
Date Rec Updated:	12/29/2021
Updated By:	DRLANNER
Site Description:	"Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental

THE HUGUENOT (Continued) **S127013001**

apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs,

THE HUGUENOT (Continued) **S127013001**

SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess

THE HUGUENOT (Continued) **S127013001**

of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported

THE HUGUENOT (Continued) **S127013001**

Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-10-22 12:50:00
Record Upd:	2021-12-21 12:03:00
Updated By:	DRLANNER
Own Op:	6
Sub Type:	P02
Owner Name:	Frank Chechile
Owner Company:	381-383 Huguenot LLC
Owner Address:	20 Amelia Earhart Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Rye, NY 10580
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	Frank Chechile
Owner Company:	381-383 Huguenot LLC
Owner Address:	20 Amelia Earhart Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Rye, NY 10580
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Larry Sheldon
Owner Company:	New Rochelle Public Library
Owner Address:	One Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
HW Code:	C360157
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	selenium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN

THE HUGUENOT (Continued) **S127013001**

Waste Code:	Not reported
HW Code:	C360157
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

THE HUGUENOT (Continued) **S127013001**

HW Code:	C360157
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	fluorene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	sec-butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360157
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360157-08-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-13 16:15:00
Record Updated:	2020-10-13 16:15:00
Updated By:	DRLANNER
Crossref ID:	591483399
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-10-13 15:49:00
Record Updated:	2020-10-13 15:49:00
Updated By:	DRLANNER
Crossref ID:	11/03/2017
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-10-13 16:19:00
Record Updated:	2020-10-13 16:21:00
Updated By:	DRLANNER
Crossref ID:	9604099
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.

THE HUGUENOT (Continued) **S127013001**

Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

AB242 **THE HUGUENOT** **NY INST CONTROL** **S127013008**
SSW **387 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.219 mi.
1154 ft. **Site 9 of 12 in cluster AB**

Relative:
Lower

Actual:
89 ft.

INST CONTROL:
Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: Environmental Easement
HW Code: C360157
Control Code: J
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996

THE HUGUENOT (Continued) **S127013008**

at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water

THE HUGUENOT (Continued) **S127013008**

quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3

THE HUGUENOT (Continued) **S127013008**

(ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library

THE HUGUENOT (Continued) **S127013008**

Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157

THE HUGUENOT (Continued) **S127013008**

Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene

THE HUGUENOT (Continued) **S127013008**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: Landuse Restriction
HW Code: C360157
Control Code: 25
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor,

THE HUGUENOT (Continued) **S127013008**

with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and

THE HUGUENOT (Continued) **S127013008**

metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site

THE HUGUENOT (Continued) **S127013008**

monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

THE HUGUENOT (Continued) **S127013008**

Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported

THE HUGUENOT (Continued) **S127013008**

HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157

THE HUGUENOT (Continued) **S127013008**

Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00

THE HUGUENOT (Continued) **S127013008**

Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: Soil Management Plan
HW Code: C360157
Control Code: 14
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology:

THE HUGUENOT (Continued) **S127013008**

The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these

THE HUGUENOT (Continued) **S127013008**

compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

THE HUGUENOT (Continued) **S127013008**

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN

THE HUGUENOT (Continued) **S127013008**

Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported

THE HUGUENOT (Continued) **S127013008**

HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157

THE HUGUENOT (Continued) **S127013008**

Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: Ground Water Use Restriction
HW Code: C360157
Control Code: 08
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The

THE HUGUENOT (Continued) **S127013008**

nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4

THE HUGUENOT (Continued) **S127013008**

ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene,

THE HUGUENOT (Continued) **S127013008**

collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02

THE HUGUENOT (Continued) **S127013008**

Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN

THE HUGUENOT (Continued) **S127013008**

Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported

THE HUGUENOT (Continued) **S127013008**

HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502

THE HUGUENOT (Continued) **S127013008**

Control Name: Site Management Plan
HW Code: C360157
Control Code: 32
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below

THE HUGUENOT (Continued) **S127013008**

grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for

THE HUGUENOT (Continued) **S127013008**

these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air

THE HUGUENOT (Continued) **S127013008**

quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene

THE HUGUENOT (Continued) **S127013008**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN

THE HUGUENOT (Continued) **S127013008**

Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00

THE HUGUENOT (Continued) **S127013008**

Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: Monitoring Plan
HW Code: C360157
Control Code: 31
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER
Site Code: 544502
Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former

THE HUGUENOT (Continued) **S127013008**

dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in

THE HUGUENOT (Continued) **S127013008**

any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb, 10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six

THE HUGUENOT (Continued) **S127013008**

owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1

THE HUGUENOT (Continued) **S127013008**

Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene

THE HUGUENOT (Continued) **S127013008**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN

THE HUGUENOT (Continued) **S127013008**

Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00
Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

Name: THE HUGUENOT
Address: 387 HUGUENOT STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 544502
Control Name: IC/EC Plan
HW Code: C360157
Control Code: 34
Control Type: INST
Dt record added: 09/15/2020
Dt rec updated: 12/29/2021
Updated By: DRLANNER

THE HUGUENOT (Continued) **S127013008**

Site Code: 544502

Site Description: "Location: The 0.393-acre site is located in an urban area at 387 Huguenot Street, in New Rochelle, Westchester County. The site is bound to the north by a vacant store (first floor) with a residential unit above; to the south by a three-story residential apartment building and a one-story residential building; to the east by Huguenot Street and beyond by a gasoline filling station; and to the west by an office building/warehouse. Site Features: The site is currently being redeveloped as a mixed-use 6-story apartment building with on-site parking. Site development will entail sixty (60) rental apartment units, and two commercial/retail units on the ground floor, with associated parking primarily on the first/ground floor within the footprint of the building and some below ground using a mechanical parking system. Current Zoning and Land Use: The site is located within the City of New Rochelle's recently designated (2015) Downtown Overlay Zone in a mixed-use setting. The intended end use for this site is restricted-residential and commercial. Surrounding parcels are utilized for mixed commercial and residential uses. The nearest residential dwellings include two apartment buildings on the adjacent property south of the site, with mixed-use commercial/residential properties located immediately north of the site and to the east across Huguenot Street. Past Use of the Site: The northern portion of the site was utilized for dry cleaning services since 1931, and for manufacturing since the 1970s to 2010s. Potential sources of contamination in this area included the former dry cleaning operations and former fuel oil underground storage tanks (USTs) located on-site. The central portion of the site maintained a residential dwelling since 1931, and was later used for truck and trailer parking since the 1990s. The potential source of contamination in this area included a former fuel oil UST, which was removed prior to 1997. The southern portion of the site maintained a gasoline filling station and car wash from the 1930s to the 1950s, and then utilized as a warehouse from the 1970s to 2010s. Potential sources of contamination in this area included former gasoline USTs and a car wash operation. In addition, urban fill material was encountered throughout the site. A spill was reported on June 6, 1996 at 381 Huguenot Street due to soil and groundwater contamination encountered during a previous site investigation (NYSDEC Spill #9604099). Phase I and II Environmental Site Assessments (ESAs) were performed in March 2016 at the site to evaluate potential environmental impacts. In February 2017 a Supplemental Subsurface Investigation (SSI) was conducted at the site to further define the environmental impacts present on-site. Site Geology and Hydrogeology: The site is overlain by a layer of urban fill material consisting of a heterogeneous mixture of medium to fine sand and silt, coarse to fine gravel and occasional asphalt, concrete and brick fragments, which varies in thickness between 1 and 6 feet. Below the fill is a native soil layer made up of medium to fine sand with silt, coarse to fine gravel, and occasional cobbles. Weathered bedrock was encountered at depths between approximately 5 and 20 feet below grade, while more competent bedrock was found at depths between approximately 10 and 24 feet below grade. Groundwater was encountered at depths between approximately 6 and 9 feet below grade and flows in a west-northwest direction. "

Env Problem: "Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern found in site soils were semi-volatile organic compounds (SVOCs) and metals. The primary

THE HUGUENOT (Continued) **S127013008**

contaminants of concern found in site groundwater include volatile organic compounds (VOCs), SVOCs, metals, and per- and polyfluoroalkyl substances (PFAS). Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation: Nature and Extent of Contamination: Based upon investigations conducted before remediation, the primary contaminants of concern found in site soils include SVOCs and metals. The primary contaminants of concern found in site groundwater include VOCs, SVOCs, metals, and PFAS. Soil - Investigations identified SVOCs and metals contamination in shallow soils at numerous locations across the site at concentrations exceeding restricted-residential use soil cleanup objectives (RRSCOs). SVOCs detected in the on-site soils exceeding applicable RRSCOs include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3-c,d)pyrene at maximum concentrations of 5.8 parts per million (ppm), 5.8 ppm, 5.6 ppm, 5.4 ppm, 5.8 ppm, 0.72 ppm and 4.0 ppm, respectively. The RRSCOs for these compounds are 1.0 ppm, 1.0 ppm, 1.0 ppm, 3.9 ppm, 3.9 ppm, 0.33 ppm, and 0.5 ppm, respectively. Metals detected in the on-site soil exceeding applicable RRSCOs include cadmium, lead, and mercury at maximum concentrations of 4.79 ppm, 4,330 ppm, and 1.26 ppm, respectively. The RRSCOs for these metals are 4.3 ppm, 400 ppm, and 0.81 ppm, respectively. While no VOCs were detected above RRSCOs in any of the soil samples, VOCs were found in shallow soils at levels exceeding unrestricted use soil cleanup objectives (UUSCOs). VOCs identified in the shallow on-site soils exceeding applicable UUSCOs include trichloroethene (TCE) and xylenes at maximum concentrations of 3.1 ppm and 3.49 ppm, respectively. The UUSCOs for these compounds are 0.47 ppm and 0.26 ppm, respectively. No pesticides were detected above RRSCOs in any of the soil samples. PCBs were identified in deeper soils at one location at a concentration of 3.0 ppm, exceeding the RRSCO of 1.0 ppm. Groundwater - Groundwater investigations included analyses for VOCs, SVOCs, metals, pesticides, PCBs, and PFAS. VOCs identified in site groundwater in excess of ambient water quality standards include ethylbenzene, isopropylbenzene, n-butylbenzene, n-propylbenzene, p-isopropyltoluene, sec-butylbenzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and 1,3-dichlorobenzene at maximum concentrations of 22 parts per billion (ppb), 190 ppb, 240 ppb, 400 ppb, 48 ppb, 220 ppb, 6.3 ppb, 20 ppb, 6 ppb, and 6.8 ppb, respectively. The ambient water quality standard for each of these compounds is 5 ppb, except for 1,3-dichlorobenzene at 3 ppb. SVOCs identified in on-site groundwater in excess of standards include benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, fluorene, indeno(1,2,3-c,d)pyrene, naphthalene, phenanthrene, and phenol at maximum concentrations of 0.55 ppb, 0.35 ppb, 0.29 ppb, 0.57 ppb, 1,700 ppb, 0.05 ppb, 2,900 ppb, 2,900 ppb, and 1.4 ppb, respectively. The ambient water quality standards for these compounds are 0.002 ppb, 0.002 ppb, 0.002 ppb, 0.002 ppb, 50 ppb, 0.002 ppb, 10 ppb, 50 ppb, and 1 ppb, respectively. Metals identified in site groundwater in excess of standards include aluminum, iron, magnesium, manganese, selenium, and sodium at maximum concentrations of 791 ppb, 52,500 ppb, 45,000 ppb, 16,000 ppb, 12 ppb, and 358,000 ppb, respectively. The ambient water quality standards for these metals are 100 ppb, 300 ppb, 35,000 ppb, 300 ppb,

THE HUGUENOT (Continued) **S127013008**

10 ppb, and 20,000 ppb, respectively. No pesticides were detected above standards in any of the groundwater samples collected. PCBs were detected in site groundwater at one upgradient well location at a concentration of 0.094 ppb, slightly exceeding the ambient water quality standard of 0.09 ppb. Several PFAS compounds were detected in groundwater samples collected both on- and off-site. PFOA concentrations were found in excess of the maximum contaminant level of 10 parts per trillion (ppt) in all 4 on-site monitoring wells, ranging from 17 to 64 ppt, and 3 of the 4 off-site monitoring wells, ranging from 8.8 to 35 ppt. PFOS concentrations were found in excess of the maximum contaminant level of 10 ppt in 3 of the 4 on-site monitoring wells, ranging from 8.8 to 120 ppt, and 2 of the 4 off-site monitoring wells, ranging from 6.1 to 17 ppt. Soil Vapor - Soil vapor samples were collected at two locations in the northern portion of the site (former dry cleaner location and beneath existing building) during a Phase II Environmental Site Assessment and analyzed for VOCs. Primary contaminants identified in the on-site soil vapor included benzene, toluene, ethylbenzene, and xylene, collectively known as BTEX, and chlorinated VOCs (tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride) at maximum concentrations of 23.8 micrograms per cubic meter (g/m3), 35.7 g/m3, 133 g/m3, 397 g/m3, 4.37 g/m3, 14.3 g/m3, 18.4 g/m3, and 74.6 g/m3, respectively. Indoor Air and Sub-Slab Vapor Soil vapor intrusion sampling was offered to owners of six buildings surrounding the site during the remedial investigation and only one of the six owners agreed to the sampling. Soil vapor intrusion samples were collected at an adjacent building located north of the site and analyzed for VOCs. Carbon tetrachloride, methylene chloride and tetrachloroethene (PCE) were detected in the sub-slab soil vapor and indoor air (basement and 1st floor), with carbon tetrachloride and PCE also detected in the ambient (outdoor) air locations. Carbon tetrachloride levels ranged from 0.53 g/m3 (sub-slab) to 0.61 g/m3 (indoor air, maximum), to 0.54 g/m3 (ambient air, maximum). Methylene chloride levels ranged from 6.21 g/m3 (sub-slab) to 6.53 g/m3 (indoor air, maximum), to non-detect (ambient air). PCE levels ranged from 0.83 g/m3 (sub-slab) to 0.89 g/m3 (indoor air, maximum), to 0.57 g/m3 (ambient air, maximum). A comparison of the soil vapor intrusion sampling results with the NYSDOH Soil Vapor/Indoor Air Decision Matrices indicates no further actions are recommended to address human exposures. However, since only one of the six off-site buildings was allowed access and sampled, further evaluations are needed to determine if soil vapor intrusion is a potential concern for other off-site buildings. "

Health Problem: "Measures are in place to control the potential for coming in contact with subsurface soil and groundwater contamination remaining at the site. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil) which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential does not exist for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Soil vapor intrusion sampling at one offsite building indicates that soil vapor intrusion is not a concern for that building and no further action is recommended. However, soil

THE HUGUENOT (Continued) **S127013008**

vapor intrusion evaluations with actions taken as needed to address exposures are recommended for other offsite buildings, including those buildings where testing has previously been declined by owners."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-10-22 12:50:00
Record Upd: 2021-12-21 12:03:00
Updated By: DRLANNER
Own Op: 6
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: Frank Chechile
Owner Company: 381-383 Huguenot LLC
Owner Address: 20 Amelia Earhart Lane
Owner Addr2: Not reported
Owner City,St,Zip: Rye, NY 10580
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Larry Sheldon
Owner Company: New Rochelle Public Library
Owner Address: One Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
HW Code: C360157
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157

THE HUGUENOT (Continued) **S127013008**

Waste Type: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: selenium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: phenanthrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: cadmium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: 1,2,4-trimethylbenzene

THE HUGUENOT (Continued) **S127013008**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: fluorene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: sec-butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360157
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C360157-08-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-10-13 16:15:00
Record Updated: 2020-10-13 16:15:00
Updated By: DRLANNER
Crossref ID: 591483399
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-13 15:49:00
Record Updated: 2020-10-13 15:49:00

THE HUGUENOT (Continued) **S127013008**

Updated By: DRLANNER
Crossref ID: 11/03/2017
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-10-13 16:19:00
Record Updated: 2020-10-13 16:21:00
Updated By: DRLANNER
Crossref ID: 9604099
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-10-19 11:54:00
Record Updated: 2018-10-19 11:54:00
Updated By: JBODEE

AF243 **MONROE COLLEGE** **NY UST** **U004340916**
East **420 MAIN STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.222 mi.
1174 ft. **Site 2 of 3 in cluster AF**

Relative: NY UST:
Lower No Details: No Details

Actual:
77 ft.

AB244 **CON EDISON** **NY MANIFEST** **S117535572**
SSW **MAIN ST & MAPLE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.224 mi.
1185 ft. **Site 10 of 12 in cluster AB**

Relative: NY MANIFEST:
Lower
Actual:
88 ft.

Name:	CON EDISON
Address:	MAIN ST & MAPLE AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004674354
Facility Status:	Not reported
Location Address 1:	MAIN ST & MAPLE AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004674354
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117535572**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2014
Trans1 Recv Date:	10/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004674354
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	007747843FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	559
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	D005
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB245 **CON EDISON** **RCRA NonGen / NLR** **1014399091**
SSW **MAPLE AVE & MAIN ST** **NJ MANIFEST** **NYP004214680**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.224 mi.
1185 ft. **Site 11 of 12 in cluster AB**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON	
Handler Address:		MAPLE AVE & MAIN ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10804
EPA ID:		NYP004214680
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1014399091**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20100901
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON (Continued) **1014399091**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004214680
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	004086092GBF
EPA ID:	NYP004214680
Date Shipped:	09/01/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010

CON EDISON (Continued) **1014399091**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	120 P

Manifest Number:	001086092GBF
EPA ID:	NYP004214680
Date Shipped:	09/01/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **1014399091**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	120 P

AB246 **CON EDISON MANHOLE: 734** **RCRA NonGen / NLR** **1016969502**
SSW **MAIN ST & MAPLE ST** **NY MANIFEST** **NYP004431706**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.224 mi.
1185 ft. **Site 12 of 12 in cluster AB**

Relative: **Lower**
Actual: **88 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140301
Handler Name:	CON EDISON MANHOLE: 734	
Handler Address:		MAIN ST & MAPLE ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004431706
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140201
Handler Name: CON EDISON MANHOLE: 734	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON MANHOLE: 734 (Continued) **1016969502**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140301
Handler Name: CON EDISON MANHOLE: 734
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON ED
Address: MAIN ST & MAPLE ST
City,State,Zip: NEW ROCHELLE, NY 10805
Country: USA
EPA ID: NYP004431706
Facility Status: Not reported
Location Address 1: 591 MAIN ST
Code: BP
Location Address 2: MH 734
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004431706
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON MANHOLE: 734 (Continued) **1016969502**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/01/2014
Trans1 Recv Date:	02/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004431706
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011696225JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK247 **CON EDISON MANHOLE 1174** **RCRA NonGen / NLR** **1014918343**
NE **HUGEONOT ST & HARRISON ST** **NJ MANIFEST** **NYP004219570**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.225 mi.
1187 ft. **Site 1 of 6 in cluster AK**

Relative: **Lower**
Actual: **72 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20101204
Handler Name:	CON EDISON MANHOLE 1174
Handler Address:	HUGEONOT ST & HARRISON ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004219570
Contact Name:	DENNIS ROHRER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20101104
Handler Name:	CON EDISON MANHOLE 1174
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20101204
Handler Name:	CON EDISON MANHOLE 1174
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE 1174 (Continued) **1014918343**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004219570
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874917JJK
EPA ID:	NYP004219570
Date Shipped:	11/04/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/04/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/05/2010

CON EDISON MANHOLE 1174 (Continued) **1014918343**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

AK248 **CONSOLIDATED EDISON - MH 1174** **NY MANIFEST** **S110709396**
NE **HUGUENOT ST & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.225 mi.
1187 ft. **Site 2 of 6 in cluster AK**

Relative: **Lower**

Actual: **72 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 1174
Address:	HUGUENOT ST & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYP004219572
Facility Status:	Not reported
Location Address 1:	HUGUENOT ST & HARRISON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004219572
Mailing Name:	CONSOLIDATED EDISON - MH 1174
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CONSOLIDATED EDISON - MH 1174 (Continued) **S110709396**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/2010
Trans1 Recv Date:	11/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004219572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874917JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE249 **PREFERRED CLEANERS** **RCRA NonGen / NLR** **1000353766**
West **95 UNION AVE** **FINDS** **NYD050275254**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.225 mi. **NY MANIFEST**
1188 ft. **Site 2 of 6 in cluster AE**

Relative: **Higher**
Actual: **96 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	PREFERRED CLEANERS	
Handler Address:		95 UNION AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801-6238
EPA ID:		NYD050275254
Contact Name:		Not reported
Contact Address:		UNION AVE
Contact City,State,Zip:		NEW ROCHELLE, NY 10801
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R3
Mailing Address:		UNION AVE
Mailing City,State,Zip:		NEW ROCHELLE, NY 10801
Owner Name:		RICHARD MEYERING
Owner Type:		Private
Operator Name:		RICHARD MEYERING
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

PREFERRED CLEANERS (Continued) **1000353766**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

PREFERRED CLEANERS (Continued) **1000353766**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RICHARD MEYERING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	141 WILMOT RD
Owner/Operator City,State,Zip:	SCARSDALE, NY 10583
Owner/Operator Telephone:	914-472-6038
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RICHARD MEYERING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	141 WILMOT RD
Owner/Operator City,State,Zip:	SCARSDALE, NY 10583
Owner/Operator Telephone:	914-472-6038
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RICHARD MEYERING
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	141 WILMOT RD
Owner/Operator City,State,Zip:	SCARSDALE, NY 10583
Owner/Operator Telephone:	914-472-6038
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: PREFERRED CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: PREFERRED CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

PREFERRED CLEANERS (Continued) **1000353766**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: PREFERRED CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19950619
Handler Name: PREFERRED CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004357918

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PREFERRED CLEANERS (Continued) **1000353766**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000353766
Registry ID:	110004357918
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004357918
Name:	PREFERRED CLEANERS
Address:	95 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	NEBRASKA CLEANERS
Address:	95 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY 10801-6238
Country:	USA
EPA ID:	NYD050275254
Facility Status:	Not reported
Location Address 1:	95 UNION AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD050275254
Mailing Name:	NEBRASKA CLEANERS
Mailing Contact:	NEBRASKA CLEANERS
Mailing Address 1:	95 UNION AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146364937

---

250 SW 1/8-1/4 0.227 mi. 1199 ft.

ALL AMERICAN SPORTS CORP
44 COLUMBUS AVE
NEW ROCHELLE, NY 10802

RCRA NonGen / NLR **1004760316**
FINDS **NYR000040113**
ECHO
NY MANIFEST

Relative: Lower

Actual: 66 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	ALL AMERICAN SPORTS CORP
Handler Address:	44 COLUMBUS AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYR000040113
Contact Name:	LAMELLE WILLIAMS
Contact Address:	COLUMBUS AVE
Contact City,State,Zip:	NEW ROCHELLE, NY 10802
Contact Telephone:	914-636-7070

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	COLUMBUS AVE
Mailing City,State,Zip:	NEW ROCHELLE, NY 10802
Owner Name:	ALL AMERICAN SPORTS CORP
Owner Type:	Private
Operator Name:	ALL AMERICAN SPORTS CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ALL AMERICAN SPORTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	44 COLUMBUS AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10802
Owner/Operator Telephone:	914-636-7070
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ALL AMERICAN SPORTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	44 COLUMBUS AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10802
Owner/Operator Telephone:	914-636-7070
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ALL AMERICAN SPORTS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	44 COLUMBUS AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10802
Owner/Operator Telephone:	914-636-7070
Owner/Operator Telephone Ext:	Not reported

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: ALL AMERICAN SPORTS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ALL AMERICAN SPORTS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970530
Handler Name: ALL AMERICAN SPORTS CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004534709

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004760316
Registry ID:	110004534709
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004534709
Name:	ALL AMERICAN SPORTS CORP
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802

NY MANIFEST:

Name:	RIDDELL ALL AMERICAN
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD002182897
Facility Status:	Not reported
Location Address 1:	44 COLUMBUS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10805
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD002182897
Mailing Name:	RIDDELL ALL AMERICAN
Mailing Contact:	PERSING MEJIA
Mailing Address 1:	44 COLUMBUS AVE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10805
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146367070

Name:	ALL AMERICAN SPORTS CORP
Address:	44 COLUMBUS AVE
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYR000040113
Facility Status:	Not reported

ALL AMERICAN SPORTS CORP (Continued) **1004760316**

Location Address 1: 44 COLUMBUS AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10802
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000040113
Mailing Name: ALL AMERICAN SPORTS CORP
Mailing Contact: LAMELLE WILLIAMS
Mailing Address 1: 44 COLUMBUS AVE
Mailing Address 2: Not reported
Mailing City: NEW ROCHELLE
Mailing State: NY
Mailing Zip: 10802
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146367070

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH251 **30 CLINTON PLACE OWNERS INC.** **NY UST U003855209**
SE **30 CLINTON PLACE** **NY AST N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.228 mi.
1203 ft. **Site 3 of 11 in cluster AH**

Relative:
Lower

Actual:
89 ft.

WESTCHESTER CO. UST:
Name: 30 CLINTON PLACE OWNERS INC.
Address: 30 CLINTON PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
Id/Status: 3-078727 / Active
Operator Name: David Kuilon
Owner Name: 30 Clinton Place Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City: New Rochelle
Owner State: NY
Owner Zipcode: 10801
GDS Number: Not reported

Tank Number: 1old
Status: 3. Closed - Removed
Capacity: 5000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 07/01/1995
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on Ground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 3. Gravity

WESTCHESTER CO. AST:
Name: 30 CLINTON PLACE OWNERS INC.
Address: 30 CLINTON PLACE
City,State,Zip: NEW ROCHELLE, NY 10801
PBS Number: 3-078727
Site Status: Active
GDS Number: Not reported
Operator Name: David Kuilon
Owner Name: 30 Clinton Place Owners Inc.
Owner Street: 30 Clinton Place
Owner Address2: Not reported
Owner City/State/Zip: New Rochelle, NY 10801

Tank Number: 001
Status: 1. In-Service
Date Installation: 10/01/1996
Capacity: 3500
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 0. None
Dispenser: 2. Suction

Tank Number: 1
Status: 4. Closed - in place
Date Installation: 01/01/1996
Capacity: 4200
Product Stored: Not reported
Product Stored Percent: Not reported
Date Perm Closure: 07/01/1995
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None

30 CLINTON PLACE OWNERS INC. (Continued) **U003855209**

Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AH252 **CO-OP** **NY LTANKS** **S101658613**
SE **30 CLINTON PLACE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.228 mi.
1203 ft. **Site 4 of 11 in cluster AH**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	CO-OP
Address:	30 CLINTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9504589 / 1997-04-15
Facility ID:	9504589
Site ID:	189169
Spill Date:	1995-07-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-20
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	MERILITH MNGT.
Spiller Address:	1101 MIDLAND AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157941
DEC Memo:	""
Remarks:	"OIL SEEPING INTO BASEMENT POSSIBLE TANK FAILURE SOME OIL GOT INTO SUMP PIT AND DISCHARGED OUT SUMP PUMP TAKEN OFF LINE"

All TTF:

Facility ID:	9504589
Spill Number:	9504589

CO-OP (Continued) **S101658613**

Spill Tank Test:	1544004
Site ID:	189169
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	189169
Operable Unit ID:	1019355
Operable Unit:	01
Material ID:	366101
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AH253 **CON EDISON** **NY MANIFEST** **S117538379**
ESE **150 NORTH AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.229 mi.
1207 ft. **Site 5 of 11 in cluster AH**

Relative:
Lower

Actual:
89 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	150 NORTH AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004710497
Facility Status:	Not reported
Location Address 1:	150 NORTH AV
Code:	BP
Location Address 2:	SB2044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004710497
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL

CON EDISON (Continued) **S117538379**

Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004710497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774700JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL254 **CON EDISON** **NY MANIFEST** **S118088270**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1218 ft. **Site 1 of 20 in cluster AL**

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	45 HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004758215
Facility Status:	Not reported
Location Address 1:	45 HARRISON ST
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758215
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758215
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091127JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118088270**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL255 **CON EDISON** **NJ MANIFEST** **S120669623**
ENE **45 HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1218 ft. **Site 2 of 20 in cluster AL**

Relative: **Lower**
Actual: **74 ft.**

NJ MANIFEST:

EPA Id:	NYP004758215
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091127JJK
EPA ID:	NYP004758215
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120669623**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL256 **CITY OF NEW ROCHELLE** **NY LTANKS** **S107658678**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.231 mi.
1218 ft. **Site 3 of 20 in cluster AL**

Relative: **Lower**

Actual: **74 ft.**

LTANKS:

Name:	CITY OF NEW ROCHELLE
Address:	45 HARRISON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513733 / 2006-06-21
Facility ID:	0513733
Site ID:	360263
Spill Date:	2006-02-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-02-28

CITY OF NEW ROCHELLE (Continued) **S107658678**

CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-28
Spill Record Last Update:	2006-06-21
Spiller Name:	DEE LESTER
Spiller Company:	CITY OF NEW ROCHELLE
Spiller Address:	45 HARRISON STREET
Spiller County:	001
Spiller Contact:	DEE LESTER
Spiller Phone:	(914) 654-2072
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310380
DEC Memo:	"Tank passed retest after piping was replaced. NFA"
Remarks:	"TANK SIZE IS 5000 GALLON, TEST METHOD WAS EZ3 LOCATOR PLUS,"

All Materials:

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107948
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	360263
Operable Unit ID:	1117439
Operable Unit:	01
Material ID:	2107952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL257 **NEW ROCHELLE FIRE STATION # 1** **NY UST** **U004333984**
ENE **45 HARRISON STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1218 ft. **Site 4 of 20 in cluster AL**

Relative: NY UST:
Lower No Details: No Details

Actual:
74 ft.

AL258 **CON EDISON** **RCRA NonGen / NLR** **1018280911**
ENE **45 HARRISON ST** **FINDS** **NYP004758215**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.231 mi.
1218 ft. **Site 5 of 20 in cluster AL**

Relative: RCRA NonGen / NLR:
Lower

Actual:
74 ft.

Date Form Received by Agency:	20150326
Handler Name: CON EDISON	
Handler Address:	45 HARRISON ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004758215
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

CON EDISON (Continued) **1018280911**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150326
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150326

CON EDISON (Continued) **1018280911**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067684303

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018280911
Registry ID: 110067684303
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067684303
Name: CON EDISON
Address: 45 HARRISON ST
City,State,Zip: NEW ROCHELLE, NY 10801

AH259 **CON EDISON MANHOLE: 2042** **RCRA NonGen / NLR** **1016970603**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004443198**
1/8-1/4 **NEW ROCHELLE, NY 10804**
0.231 mi.
1219 ft. **Site 6 of 11 in cluster AH**

Relative: **Lower**
Actual: **89 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20140316
Handler Name: CON EDISON MANHOLE: 2042
Handler Address: NORTH AVE & CLINTON PL
Handler City,State,Zip: NEW ROCHELLE, NY 10804

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

EPA ID:	NYP004443198
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140216
Handler Name: CON EDISON MANHOLE: 2042	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140316
Handler Name: CON EDISON MANHOLE: 2042	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & CLINTON PL
City,State,Zip:	NEW ROCHELLE, NY 10804
Country:	USA
EPA ID:	NYP004443198
Facility Status:	Not reported
Location Address 1:	NORTH AVE & CLINTON PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004443198
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/16/2014
Trans1 Recv Date:	02/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004443198
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772860JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON MANHOLE: 2042 (Continued) **1016970603**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH260 **CON EDISON SERVICE BOX: 2040** **RCRA NonGen / NLR** **1016971500**
ESE **NORTH AVE & CLINTON PL** **NY MANIFEST** **NYP004452439**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.231 mi.
1219 ft. **Site 7 of 11 in cluster AH**

Relative: **Lower**

Actual: **89 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140326
Handler Name:	CON EDISON SERVICE BOX:	2040
Handler Address:		NORTH AVE & CLINTON PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004452439
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140226
Handler Name: CON EDISON SERVICE BOX:	2040
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140326
Handler Name: CON EDISON SERVICE BOX:	2040
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	NORTH AVE & CLINTON PL
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004452439
Facility Status:	Not reported
Location Address 1:	NORTH AVE & CLINTON PLS
Code:	BP
Location Address 2:	SB2040
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

NY MANIFEST:

EPAID:	NYP004452439
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2014
Trans1 Recv Date:	02/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004452439
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772758JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON SERVICE BOX: 2040 (Continued) **1016971500**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ261 **CON EDISON** **NY MANIFEST** **S117535673**
NNW **OPP 20 LOCKWOOD AV** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.231 mi.
1222 ft. **Site 2 of 3 in cluster AJ**

Relative:
Lower

Actual:
80 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 20 LOCKWOOD AV
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004679965
Facility Status:	Not reported
Location Address 1:	OPP 20 LOCKWOOD AV
Code:	BP
Location Address 2:	MH11199
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004679965
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/18/2014
Trans1 Recv Date:	10/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004679965
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117535673**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774833JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD262 **CON EDISON** **RCRA NonGen / NLR** **1019907792**
North **LOCKWOOD AVE & NORTH AVE** **NYP004838332**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1224 ft. **Site 8 of 13 in cluster AD**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20150914
Actual: Handler Name:	CON EDISON	
78 ft. Handler Address:		LOCKWOOD AVE & NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004838332
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON (Continued) **1019907792**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON (Continued) **1019907792**

Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AD263 **CON EDISON** **NY MANIFEST** **S118259837**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1224 ft. **Site 9 of 13 in cluster AD**

Relative:
Lower

Actual:
78 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	LOCKWOOD AVE & NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004838332
Facility Status:	Not reported
Location Address 1:	LOCKWOOD AVE & NORTH AVE
Code:	BP
Location Address 2:	TM 1552
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004838332
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004838332
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472178JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118259837**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD264 **CON EDISON TRANSFORMER MANHOLE: 1552** **RCRA NonGen / NLR** **1016964344**
North **LOCKWOOD AVE & NORTH ST** **NY MANIFEST** **NYP004372751**
1/8-1/4 **NEW ROCHELLE, NY 10802**
0.232 mi.
1224 ft. **Site 10 of 13 in cluster AD**

Relative: **Lower**
Actual: **78 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20131110
Handler Name:	CON EDISON TRANSFORMER MANHOLE: 1552
Handler Address:	LOCKWOOD AVE & NORTH ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYP004372751
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Historic Generators:
Receive Date: 20131010
Handler Name: CON EDISON TRANSFORMER MANHOLE: 1552
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131110
Handler Name: CON EDISON TRANSFORMER MANHOLE: 1552
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: LOCKWOOD AVE & NORTH ST
City,State,Zip: NEW ROCHELLE, NY 10802
Country: USA
EPA ID: NYP004372751
Facility Status: Not reported
Location Address 1: LOCKWOOD AVE & NORTH ST
Code: BP
Location Address 2: TM 1552
Total Tanks: Not reported
Location City: NEW ROCHELLE
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004372751

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2013
Trans1 Recv Date:	10/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004372751
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693714JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON TRANSFORMER MANHOLE: 1552 (Continued) **1016964344**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AD265 **CON EDISON MANHOLE 1562** **RCRA NonGen / NLR** **1014918646**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004222626**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.232 mi.
1224 ft. **Site 11 of 13 in cluster AD**

Relative: **Lower**
Actual: **78 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20110130
Handler Name:	CON EDISON MANHOLE 1562
Handler Address:	NORTH AVE & LOCKWOOD AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYP004222626
Contact Name:	DONALD SENNO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20111231
Handler Name:	CON EDISON MANHOLE 1562
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110130
Handler Name:	CON EDISON MANHOLE 1562
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004222626
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655578JJK
EPA ID:	NYP004222626
Date Shipped:	12/31/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/31/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON MANHOLE 1562 (Continued) **1014918646**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/04/2011
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	150 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	NORTH AVE & LOCKWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004222626
Facility Status:	Not reported
Location Address 1:	NORTH AVE & LOCKHEED
Code:	BP
Location Address 2:	MH 1962
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004222626
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

CON EDISON MANHOLE 1562 (Continued) **1014918646**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/2010
Trans1 Recv Date:	12/31/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/04/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004222626
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655578JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD266 **CON EDISON** **NJ MANIFEST** **S120676674**
North **LOCKWOOD AVE & NORTH AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1224 ft. **Site 12 of 13 in cluster AD**

Relative:
Lower

Actual:
78 ft.

NJ MANIFEST:

EPA Id:	NYP004838332
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472178JJK
EPA ID:	NYP004838332
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120676674**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AD267 **CON EDISON MANHOLE 1545** **RCRA NonGen / NLR** **1014918224**
North **NORTH AVE & LOCKWOOD AVE** **NJ MANIFEST** **NYP004218356**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.232 mi.
1224 ft. **Site 13 of 13 in cluster AD**

Relative: **Lower**
Actual: **78 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20101118
Handler Name:	CON EDISON MANHOLE 1545	
Handler Address:		NORTH AVE & LOCKWOOD AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004218356
Contact Name:		CHRISTOPHER BLAICH
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		914-925-6219
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SR SPECIALIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20101019
Handler Name:	CON EDISON MANHOLE 1545
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20101118
Handler Name:	CON EDISON MANHOLE 1545

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004218356
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CHRISTOPHER BLAICH
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874846JJK
EPA ID:	NYP004218356
Date Shipped:	10/19/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/19/2010
Date Trans2 Transported Waste:	Not reported

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/20/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2000 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	NORTH AVE & LOCKWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004218356
Facility Status:	Not reported
Location Address 1:	NORTH AV OPP LOCKWOOD
Code:	BP
Location Address 2:	MH 1545
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004218356
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON MANHOLE 1545 (Continued) **1014918224**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2010
Trans1 Recv Date:	10/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004218356
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874846JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE268 **100-102 UNION AVENUE** **NY LTANKS** **S104514442**
West **100-102 UNION AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1225 ft. **Site 3 of 6 in cluster AE**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	100-102 UNION AVENUE
Address:	100-102 UNION AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9608199 / 1996-11-08
Facility ID:	9608199
Site ID:	166425
Spill Date:	1996-10-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-01
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-01
Spill Record Last Update:	1996-12-10
Spiller Name:	LJ NJ ASSOC
Spiller Company:	100-102 UNION AVENUE
Spiller Address:	100-102 UNION AVENUE
Spiller County:	001
Spiller Contact:	LJ NJ ASSOC
Spiller Phone:	(914) 636-7297
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140217
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/96 LETTER SENT BASED ON CLOSURE REPORT NFA"
Remarks:	"caller pulled tank and found contaminated soil."

All Materials:

Site ID:	166425
Operable Unit ID:	1036474
Operable Unit:	01
Material ID:	343940
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AL269 **CON EDISON** **NJ MANIFEST** **S120669767**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1226 ft. **Site 6 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NJ MANIFEST:

EPA Id:	NYP004759924
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091107JJK
EPA ID:	NYP004759924
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669767**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL270 **CON EDISON SERVICE BOX: 8001** **RCRA NonGen / NLR** **1016961840**
ENE **HARRISON AVE & CEDAR AVE** **NY MANIFEST** **NYP004347621**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.232 mi.
1226 ft. **Site 7 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130919
Handler Name:	CON EDISON SERVICE BOX:	8001
Handler Address:		HARRISON AVE & CEDAR AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10805
EPA ID:		NYP004347621
Contact Name:		GINO FRABASILE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		914-925-6219
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SR SPECIALIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 8001 (Continued) **1016961840**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130819
Handler Name: CON EDISON SERVICE BOX:	8001
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130919
Handler Name: CON EDISON SERVICE BOX:	8001

CON EDISON SERVICE BOX: 8001 (Continued) **1016961840**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	HARRISON AVE & CEDAR AVE
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYP004347621
Facility Status:	Not reported
Location Address 1:	HARRISO AVE & CEDAR
Code:	BP
Location Address 2:	SB 8001
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004347621
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON SERVICE BOX: 8001 (Continued) **1016961840**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2013
Trans1 Recv Date:	08/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004347621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694672JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL271 **CON EDISON** **RCRA NonGen / NLR** **1018281062**
ENE **HARRISON ST & CEDER ST** **FINDS** **NYP004759924**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.232 mi.
1226 ft. **Site 8 of 20 in cluster AL**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20150329
Actual: Handler Name:	CON EDISON	
75 ft. Handler Address:		HARRISON ST & CEDER ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004759924
Contact Name:		THOMAS TEELING

CON EDISON (Continued) **1018281062**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON (Continued) **1018281062**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON (Continued) **1018281062**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067686793

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281062
Registry ID:	110067686793
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686793
Name:	CON EDISON
Address:	HARRISON ST & CEDER ST
City,State,Zip:	NEW ROCHELLE, NY 10801

AL272 **CON ED** **NY MANIFEST** **S118088428**
ENE **HARRISON ST & CEDER ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.232 mi.
1226 ft. **Site 9 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Name:	CON ED
Address:	HARRISON ST & CEDER ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004759924
Facility Status:	Not reported
Location Address 1:	HARRISON ST & CEDAR ST
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759924
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON ED (Continued) **S118088428**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091107JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG273 **125** **NY LTANKS** **S104621592**
South **CENTRE AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1227 ft. **Site 4 of 5 in cluster AG**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Name:	125
Address:	CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0001835 / 2000-05-15
Facility ID:	0001835
Site ID:	205498
Spill Date:	2000-05-12
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-12
CID:	196
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-12
Spill Record Last Update:	2000-06-21
Spiller Name:	UNKNOWN
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	OPERATOR 631
Spiller Phone:	(914) 595-5901
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170636
DEC Memo:	""
Remarks:	"TANK OVER FILL AT THIS LOCATION. 10 GALLONS SPILLED AND THE SPILL WAS CLEANED UP BY THE FIRE DEPT. THE SPILL IS AT THE CHURCH BLESSED SACRMENT CHURCH. BABR MCDONALD FROM COUNTY HEATH DEPT. 637-4890 WAS CALLED TO THE SCENE ALSO."

All Materials:

Site ID:	205498
Operable Unit ID:	823753
Operable Unit:	01
Material ID:	290047
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AE274 **KAGEL HOME** **NY LTANKS** **S107658662**
West **99 UNION AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.232 mi.
1227 ft. **Site 4 of 6 in cluster AE**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	KAGEL HOME
Address:	99 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513684 / 2006-03-09
Facility ID:	0513684
Site ID:	360201
Spill Date:	2006-02-27
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	2006-03-06
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-27
Spill Record Last Update:	2006-03-09
Spiller Name:	ANDREW KAGEL
Spiller Company:	KAGEL HOME
Spiller Address:	99 UNION AVE
Spiller County:	001
Spiller Contact:	ANDREW KAGEL
Spiller Phone:	(914) 403-2881
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	310321
DEC Memo:	"Homeowner waiting on proposal from N.E. to finish job. 3/6/06 Northeast Environmental reported that the tank was removed along with eight drums of petroleum impacted soil. NFA. TG"
Remarks:	"55o gallon tank had holes and found contaminated soil;"

All Materials:

Site ID:	360201
Operable Unit ID:	1117385
Operable Unit:	01
Material ID:	2107892
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK275 **GHP 145 HUGUENOT DELAWARE, LLC** **NY UST** **U004315552**
NE **145 HUGUENOT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.235 mi.
1243 ft. **Site 3 of 6 in cluster AK**

Relative: **Lower**
Actual: **70 ft.**

WESTCHESTER CO. UST:

Name:	GHP 145 HUGUENOT DELAWARE, LLC
Address:	145 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Id/Status:	3-497436 / Active
Operator Name:	GHP Office Realty
Owner Name:	GHP 145 Huguenot Delaware, LLC
Owner Street:	4 West Red Oak Lane, Suite 200
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	3-497436
Status:	1. In-Service
Capacity:	6000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	07/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

AK276 **LONGINES WITTNAUER WATCH CO** **RCRA NonGen / NLR** **1000235411**
NE **145 HUGUENOT ST** **FINDS** **NYD001317221**
1/8-1/4 **NEW ROCHELLE, NY 10802** **ECHO**
0.235 mi. **NY MANIFEST**
1243 ft. **Site 4 of 6 in cluster AK**

Relative: **Lower**
Actual: **70 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	LONGINES WITTNAUER WATCH CO
Handler Address:	145 HUGUENOT ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10802
EPA ID:	NYD001317221
Contact Name:	Not reported
Contact Address:	HUGUENOT ST
Contact City,State,Zip:	NEW ROCHELLE, NY 10802
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	HUGUENOT ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10802
Owner Name:	OWNERNAME
Owner Type:	Private
Operator Name:	OWNERNAME
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	P013
Waste Description:	BARIUM CYANIDE
Waste Code:	P029
Waste Description:	COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)
Waste Code:	P097
Waste Description:	FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER
Waste Code:	P098
Waste Description:	POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: LONGINES WITTNAUER WATCH CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: LONGINES WITTNAUER WATCH CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LONGINES WITTNAUER WATCH CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850311

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Handler Name: LONGINES WITTNAUER WATCH CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19940917
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYWME
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850819
Evaluation Responsible Agency:	EPA-Initiated Oversight/Observation/Training Actions
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004333720

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000235411
Registry ID:	110004333720
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004333720
Name:	LONGINES WITTNAUER WATCH CO
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10802

NY MANIFEST:

Name:	LONGINES WITTHAVER WATCH COMPANY
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY 10802
Country:	USA
EPA ID:	NYD001317221
Facility Status:	Not reported
Location Address 1:	145 HUGUENOT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001317221
Mailing Name:	LONGINES WITTHAVER WATCH COMPANY
Mailing Contact:	LONGINES WITTHAVER WATCH COMPANY
Mailing Address 1:	145 HUGUENOT STREET
Mailing Address 2:	Not reported
Mailing City:	NEW RTOCHELLE
Mailing State:	NY
Mailing Zip:	10802
Mailing Zip 4:	Not reported
Mailing Country:	USA

LONGINES WITTNAUER WATCH CO (Continued) **1000235411**

Mailing Phone: 9145761000

AK277 **GALESI ENTERPRICES** **NY LTANKS** **S105236833**
NE **145 HUGUENOT ST** **NY Spills** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.235 mi.
1243 ft. **Site 5 of 6 in cluster AK**

Relative:
Lower

Actual:
70 ft.

LTANKS:

Name:	GALESI ENTERPRICES
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8901038 / 1989-06-01
Facility ID:	8901038
Site ID:	259815
Spill Date:	1989-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1989-06-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212473
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. / / : TANK & CONTAMINATED SOIL HAS BEEN REMOVED N.F.A. "
Remarks:	"8K, -.116"

All TTF:

Facility ID:	8901038
Spill Number:	8901038
Spill Tank Test:	1535410
Site ID:	259815
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported

GALESI ENTERPRICES (Continued) **S105236833**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	259815
Operable Unit ID:	927170
Operable Unit:	01
Material ID:	452349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	HEALTH DEPT OFFICE
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0109500 / 2001-12-28
Facility ID:	0109500
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259813
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2001-12-28
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-12-28
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-28
Spill Record Last Update:	2002-01-03
Spiller Name:	CHRIS LALAK
Spiller Company:	HEALTH DEPT OFFICE

GALESI ENTERPRICES (Continued) **S105236833**

Spiller Address:	145 HUGUENOT ST
Spiller Company:	001
Contact Name:	CHRIS LALAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 12/28/2001 C. LALAK @ WCDOH HANDLED. SPILL CLEANED UP. NO FURTHER ACTION."
Remarks:	"all cleaned up less than 1 oz"

All Materials:

Site ID:	259813
Operable Unit ID:	846776
Operable Unit:	01
Material ID:	527159
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0308837
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308837 / 2003-11-19
Facility ID:	0308837
Facility Type:	ER
DER Facility ID:	212473
Site ID:	259814
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6010
Spill Date:	2003-11-19
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-11-19
CID:	322
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-19
Spill Record Last Update:	2003-12-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 11/19/03: Spill is unrecoverable per C. Lalak, WCDOH.

GALESI ENTERPRICES (Continued) **S105236833**

Recommends NFA at this time."
Remarks: "approx 10 gal unk oil on roadway - highway dept placing sand "

All Materials:
Site ID: 259814
Operable Unit ID: 875003
Operable Unit: 01
Material ID: 571327
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: COMMERICAL PROPERTY
Address: 145 HUGUENOT ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0909155 / 2009-11-16
Facility ID: 0909155
Facility Type: ER
DER Facility ID: 212473
Site ID: 421828
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6010
Spill Date: 2009-11-16
Investigator: MBMASTRO
Referred To: Not reported
Reported to Dept: 2009-11-16
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 2009-11-16
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-11-16
Spill Record Last Update: 2009-11-16
Spiller Name: MILLIE LOPEZ
Spiller Company: CASTLE OIL
Spiller Address: 290 LOCUST AVE
Spiller Company: 999
Contact Name: MILLIE LOPEZ
DEC Memo: "11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks: "DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

All Materials:
Site ID: 421828

GALESI ENTERPRICES (Continued) **S105236833**

Operable Unit ID:	1177706
Operable Unit:	01
Material ID:	2170525
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Name:	COMMERICAL PROPERTY
Address:	145 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0909156 / 2009-11-16
Facility ID:	0909156
Facility Type:	ER
DER Facility ID:	212473
Site ID:	421829
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6010
Spill Date:	2009-11-16
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2009-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2009-11-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-16
Spill Record Last Update:	2009-11-16
Spiller Name:	MILLIE LOPEZ
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	999
Contact Name:	MILLIE LOPEZ
DEC Memo:	"11/16/09 This spill was at the WCDOH bldg, C Lalak confirmed clean up is done, nfa...mm"
Remarks:	"DUE TO AN OVERFILL ABOUT 10 GALLON SPILLED TO CONCRETE AND SOIL. CLEAN UP PENDING."

All Materials:

Site ID:	421829
Operable Unit ID:	1177707
Operable Unit:	01
Material ID:	2170526
Material Code:	0001A
Material Name:	#2 fuel oil

GALESI ENTERPRICES (Continued) **S105236833**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AL278 **CON EDISON** **RCRA NonGen / NLR** **1019902074**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769345**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 10 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150416
Handler Name:	CON EDISON	
Handler Address:		FOUNTAIN PL & HARRISON ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004769345
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019902074**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150416
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150416
Handler Name: CON EDISON	

CON EDISON (Continued) **1019902074**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AL279 **CON EDISON** **NJ MANIFEST** **S120670602**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 11 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYP004769345
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660843GBF
EPA ID:	NYP004769345
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON (Continued) **S120670602**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL280 **CON EDISON** **RCRA NonGen / NLR** **1018280916**
ENE **HARRISON ST & FOUNTAIN PL** **FINDS** **NYP004758272**
1/8-1/4 **NEW ROCHELLE, NY 10801** **ECHO**
0.236 mi.
1245 ft. **Site 12 of 20 in cluster AL**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20150326
Handler Name:	CON EDISON	
Handler Address:		HARRISON ST & FOUNTAIN PL
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004758272
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported

Actual:
75 ft.

CON EDISON (Continued) **1018280916**

State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No

CON EDISON (Continued) **1018280916**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150326
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150326
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067684358

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

CON EDISON (Continued) **1018280916**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280916
Registry ID:	110067684358
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067684358
Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801

AL281 **CON EDISON** **NJ MANIFEST** **S120670610**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 13 of 20 in cluster AL**

Relative: **Lower**

Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYP004769477
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660844GBF
EPA ID:	NYP004769477
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120670610**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL282 **CON EDISON** **NJ MANIFEST** **S120669628**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 14 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NJ MANIFEST:

EPA Id:	NYP004758272
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091128JJK
EPA ID:	NYP004758272
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120669628**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL283 **CON EDISON** **NY MANIFEST** **S118089335**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 15 of 20 in cluster AL**

Relative: **Lower**

Actual: **75 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004769345
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP
Location Address 2:	MH 8008
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769345
Mailing Name:	CON EDISON

CON EDISON (Continued) **S118089335**

Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769345
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660843GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S118089335**

Waste Code 1_6: Not reported

AL284 **CON EDISON** **RCRA NonGen / NLR** **1019902084**
ENE **FOUNTAIN PL & HARRISON ST** **NYP004769477**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 16 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150416
Handler Name:	CON EDISON	
Handler Address:		FOUNTAIN PL & HARRISON ST
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYP004769477
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

CON EDISON (Continued) **1019902084**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150416
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150416
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1019902084**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AL285 **CON EDISON** **NY MANIFEST** **S118089345**
ENE **FOUNTAIN PL & HARRISON ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 17 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FOUNTAIN PL & HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004769477
Facility Status:	Not reported
Location Address 1:	FOUNTAIN PL & HARRISON ST
Code:	BP
Location Address 2:	SB 8007
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004769477
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S118089345**

Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	04/20/2015
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769477
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660844GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL286 **CON ED** **NY MANIFEST** **S118088390**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 18 of 20 in cluster AL**

Relative: **Lower**
Actual: **75 ft.**

NY MANIFEST:

Name:	CON ED
Address:	HARRISON ST & FOUNTAIN PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004759510
Facility Status:	Not reported

CON ED (Continued) **S118088390**

Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	MH 8003
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759510
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2015
Trans1 Recv Date:	03/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091122JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON ED (Continued) **S118088390**

Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL287 **CON EDISON** **NY MANIFEST** **S118088276**
ENE **HARRISON ST & FOUNTAIN PL** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.236 mi.
1245 ft. **Site 19 of 20 in cluster AL**

Relative:
Lower

Actual:
75 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HARRISON ST & FOUNTAIN PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYP004758272
Facility Status:	Not reported
Location Address 1:	HARRISON ST & FOUNTAIN PL
Code:	BP
Location Address 2:	SB 8044
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10802
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758272
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2015

CON EDISON (Continued) **S118088276**

Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091128JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF288 **MONROE COLLEGE** **NY LTANKS** **S106124169**
East **5 FRANKLIN AVE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.236 mi.
1247 ft. **Site 3 of 3 in cluster AF**

Relative: LTANKS:
Lower

Name:	MONROE COLLEGE
Address:	5 FRANKLIN AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0307536 / 2005-03-27
Facility ID:	0307536
Site ID:	165556
Spill Date:	2003-10-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

Actual:
75 ft.

MONROE COLLEGE (Continued) **S106124169**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-10-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-16
Spill Record Last Update:	2005-03-27
Spiller Name:	JIM MOORE
Spiller Company:	MONROE COLLEGE
Spiller Address:	5 FRANKLIN AVE
Spiller County:	001
Spiller Contact:	JIM MOORE
Spiller Phone:	(914) 403-3458
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	278527
DEC Memo:	"03/27/05 CLEAN UP COMPLETED. SPILL FILE CLOSED BY OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod As per email from WCHD: 03-07536 5 Franklin Ave, NEw Rochelle, NY (also known as 420 Main St, New Rochelle) Tank removed from basement, soil disposed of. NFA"
Remarks:	"recomend repair retest"

All TTF:

Facility ID:	0307536
Spill Number:	0307536
Spill Tank Test:	1528740
Site ID:	165556
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	165556
Operable Unit ID:	873930
Operable Unit:	01
Material ID:	501063
Material Code:	0001A

MONROE COLLEGE (Continued) **S106124169**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AE289 **TANK TEST FAILURE** **NY LTANKS** **S111239332**
WSW **50 WALNUT ST** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.239 mi.
1260 ft. **Site 5 of 6 in cluster AE**

Relative: **Higher**

Actual: **94 ft.**

LTANKS:

Name:	TANK TEST FAILURE
Address:	50 WALNUT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1107925 / 2013-02-05
Facility ID:	1107925
Site ID:	455637
Spill Date:	2011-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-21
Spill Record Last Update:	2013-02-06
Spiller Name:	Not reported
Spiller Company:	SAL VIGNA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KEN RONK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	410212
DEC Memo:	"9-21-11 Owner is Pietro Vigna and doesn't speak english. Sal is his son. Sal cell: (914)424-2239. Sal has Eastern Env coming out Wed to investigate further. jc 2/6/13: Northeast Environmental disposed of LUST and a total of 21.05 tons of petroleum contaminated soil. Exit sample results showed residual contamination over CP-51 Guidance values. Additional excavation of contaminted soil is not possible with causing possible structural damage to the building foundations. Based upon the information provided, this Department requires no

TANK TEST FAILURE (Continued) **S111239332**

	further action at this time. Closed - doesn not meet standarsds. jod"
Remarks:	"tank test failure"

All Materials:

Site ID:	455637
Operable Unit ID:	1205789
Operable Unit:	01
Material ID:	2202749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AM290 **DOMENICO PROCOPIO PROPERTY** **NY LTANKS S103558292**
SSW **618 MAIN ST** **NY Spills N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.241 mi.
1273 ft. **Site 1 of 2 in cluster AM**

Relative: **Lower**
Actual: **87 ft.**

LTANKS:

Name:	DOMINIC PROCOPIO
Address:	618 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9809866 / 2004-03-30
Facility ID:	9809866
Site ID:	278454
Spill Date:	1998-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	1998-11-05
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-05
Spill Record Last Update:	2021-05-21
Spiller Name:	DOMINIC PROCOPIO
Spiller Company:	DOMINIC PROCOPIO
Spiller Address:	10 MAPLE AVE
Spiller County:	001
Spiller Contact:	DOMINIC PROCOPIO
Spiller Phone:	(914) 576-0288
Spiller Extention:	Not reported
DEC Region:	3

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

DER Facility ID: 226099
DEC Memo: "3/18/04: As per Fred Beck of WCDOH, this was a TTF, tank was removed, TCR submitted to WCDOH, NFA jod"
Remarks: "CHECK PIPING AND RETEST"

All TTF:
Facility ID: 9809866
Spill Number: 9809866
Spill Tank Test: 1546499
Site ID: 278454
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 278454
Operable Unit ID: 1067125
Operable Unit: 01
Material ID: 313759
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: DOMENICO PROCOPIO PROPERTY
Address: 618 MAIN ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0408557 / 2005-03-17
Facility ID: 0408557
Facility Type: ER
DER Facility ID: 226099
Site ID: 333327
DEC Region: 3
Spill Cause: Other
Spill Class: C3
SWIS: 6010
Spill Date: 2004-11-03
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2004-11-03
CID: 407

DOMENICO PROCOPIO PROPERTY (Continued) **S103558292**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-03
Spill Record Last Update:	2005-04-05
Spiller Name:	DOMINICKO PROCOPIO
Spiller Company:	Not reported
Spiller Address:	618 MAIN ST
Spiller Company:	001
Contact Name:	DOMINICKO PROCOPIO
DEC Memo:	"PBS #3-800233 11/16/2004 Stephan Goreau of WCDOH spill update -- several inches in basement of sewer/oil mix---BHY 4/4/05: Letter to Vincent Rippa, Domenico Procopio Property from Stefan Goreau, WCDOH dated 17Mar2005. WCDOH requires NFA at this time."
Remarks:	"Imporperly Abondoned tank."

All Materials:

Site ID:	333327
Operable Unit ID:	1095482
Operable Unit:	01
Material ID:	575615
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AE291 **ROBERTS HOME** **NY LTANKS** **S108298719**
WSW **58 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.242 mi.
1278 ft. **Site 6 of 6 in cluster AE**

Relative: **Higher**
Actual: **95 ft.**

LTANKS:

Name:	ROBERTS HOME
Address:	58 WALNUT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0608623 / 2012-08-17
Facility ID:	0608623
Site ID:	372634
Spill Date:	2006-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported

ROBERTS HOME (Continued) **S108298719**

Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2012-08-17
Spiller Name:	TOM ROBERTS
Spiller Company:	ROBERTS HOME
Spiller Address:	58 WALNUT STREET
Spiller County:	001
Spiller Contact:	TOM ROBERTS
Spiller Phone:	(914) 755-9816
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	322369
DEC Memo:	"8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M"
Remarks:	""

All TTF:

Facility ID:	0608623
Spill Number:	0608623
Spill Tank Test:	1550391
Site ID:	372634
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	372634
Operable Unit ID:	1130371
Operable Unit:	01
Material ID:	2120048
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AN292 @ **NY LTANKS** **S106971852**
West **60 WALNUT STREET** **N/A**
1/8-1/4 **NEW ROCHELLE, NY**
0.243 mi.
1284 ft. **Site 1 of 3 in cluster AN**

Relative: **Higher**
Actual: **95 ft.**

LTANKS:

Name:	@
Address:	60 WALNUT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0502010 / 2005-07-17
Facility ID:	0502010
Site ID:	346287
Spill Date:	2005-05-19
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-05-19
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-19
Spill Record Last Update:	2005-07-17
Spiller Name:	MR. GALLERO
Spiller Company:	Not reported
Spiller Address:	60 WALNUT STREET
Spiller County:	001
Spiller Contact:	MR. GALLERO
Spiller Phone:	(914) 469-7160
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	292543
DEC Memo:	"July 17, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 33.65 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK HAD HOLES IN IT:"

All Materials:

Site ID:	346287
Operable Unit ID:	1104017
Operable Unit:	01
Material ID:	584224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH293 **OFF-SITE FLAMINGO CLEANERS** **NY BROWNFIELDS** **S110043637**
ESE **149 NORTH AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1295 ft. **Site 8 of 11 in cluster AH**

Relative: **Lower**
Actual: **89 ft.**

BROWNFIELDS:

Name:	OFF-SITE FLAMINGO CLEANERS
Address:	149 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	414661
Acres:	Not reported
HW Code:	C360078A
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/03/2009
Record Updated Date:	11/23/2020
Update By:	KJCARPEN
Site Description:	"Location: This site is the off-site component of the former Flamingo Dry Cleaners site (C360078). The site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site itself is a one-story commercial building which includes four commercial spaces including the former dry cleaner space. This off-site component is comprised of immediately-surrounding areas. Current Zoning/Uses: Surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a college, a medical facility, and a church. Historical Uses: The on-site building was constructed in 1941 and used for retail. Flamingo Cleaners began operations in 1958 and ran until 2005 when all dry-cleaning equipment was removed. On-site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). A referral for off-site work was completed in December 2007 and a SSF RI/FS Work assignment was approved in March 2009. The RI field work was conducted in the summer of 2009 and fall of 2009. An additional round of gw analyses occurred in spring 2010. The on-going off-site investigation thus far indicates that PCE is not present in environmental media above standards in the area surrounding the site. A DEC contractor was called out in August 2020 for emerging contaminant sampling for the off-site wells Site Geology/Hydrogeology: The area surrounding the site is underlain by glacial till which sits atop highly weathered bedrock. Area bedrock ranges from 5-25 feet below ground surface. The water table ranges from 5-11 feet below ground surface. Groundwater flow direction is predominantly to the south-southwest toward Long Island Sound, but site specific groundwater flow direction is radial and seasonally affected. "
Env Problem:	"Nature and Extent of Contamination: Based on investigations to date, the primary contaminant of concern at the site is tetracholoroethylene (PCE), a dry cleaning solvent. On-site, PCE has been detected in soils, soil vapor, indoor air, and groundwater. The off-site investigation to date indicates that there are no off-site impacts. Special Resources Impacted/Threatened: The site is located in an urban area of the City of New Rochelle. There are no special resources identified near the site. The off-site wells are to be sampled for PFOAs and PFCs through a DEC contractor callout which was approved in August 2020. Contractor and Lab were approved."

OFF-SITE FLAMINGO CLEANERS (Continued) **S110043637**

Health Problem:	""
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2010-02-27 13:25:00
Record Upd:	2012-10-18 14:41:00
Updated By:	ldennist
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AH294 **FLAMINGO CLEANERS** **RCRA-LQG** **1000299848**
ESE **149 NORTH AVE** **NY BROWNFIELDS** **NYD012946885**
1/8-1/4 **NEW ROCHELLE, NY 10801** **NY MANIFEST**
0.245 mi.
1295 ft. **Site 9 of 11 in cluster AH**

Relative: **Lower**
Actual: **89 ft.**

RCRA-LQG:

Date Form Received by Agency:		20120710
Handler Name:	FLAMINGO CLEANERS	
Handler Address:		149 NORTH AVE
Handler City,State,Zip:		NEW ROCHELLE, NY 10801
EPA ID:		NYD012946885
Contact Name:		RICHARD H DORAN
Contact Address:		DORSON ENVIRONMENTAL MGMT INC
Contact City,State,Zip:		ELMSFORD, NY 10523
Contact Telephone:		914-592-3117
Contact Fax:		Not reported
Contact Email:		RDORAN@DORSON.COM
Contact Title:		PROJECT MANAGER
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities

FLAMINGO CLEANERS (Continued) **1000299848**

State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	NORTH AVE
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	V & V CAPITAL LLC
Owner Type:	Private
Operator Name:	LUIGI LLESHAJ
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No

FLAMINGO CLEANERS (Continued) **1000299848**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F004
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

FLAMINGO CLEANERS (Continued) **1000299848**

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TAEYOON KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 149 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-235-1591
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: V & V CAPITAL LLC
Legal Status: Private
Date Became Current: 20110714
Date Ended Current: Not reported
Owner/Operator Address: 369 PHILLIPS HILL RD
Owner/Operator City,State,Zip: NEW CITY, NY 10956
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TAEYOON KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 149 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-235-1591
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TAEYOON KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 149 NORTH AVE
Owner/Operator City,State,Zip: NEW ROCHELLE, NY 10801
Owner/Operator Telephone: 914-235-1591
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

FLAMINGO CLEANERS (Continued) **1000299848**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LUIGI LLESHAJ
Legal Status:	Private
Date Became Current:	20110714
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: FLAMINGO CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: FLAMINGO CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19911121
Handler Name: FLAMINGO CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120710
Handler Name: FLAMINGO CLEANERS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

FLAMINGO CLEANERS (Continued) **1000299848**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81231
NAICS Description: COIN-OPERATED LAUNDRIES AND DRYCLEANERS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20060710
Actual Return to Compliance Date: 20060818
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060803
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20060710
Actual Return to Compliance Date: 20060818

FLAMINGO CLEANERS (Continued) **1000299848**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060803
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20060710
Actual Return to Compliance Date: 20060818
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060803
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME

FLAMINGO CLEANERS (Continued) **1000299848**

Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20060710
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20060818
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20060710
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20060818
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20060710
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20060818
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

BROWNFIELDS:

FLAMINGO CLEANERS (Continued) **1000299848**

Name:	FLAMINGO CLEANERS
Address:	149 NORTH AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	BCP
Site Code:	335220
Acres:	0.122
HW Code:	C360078
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	12/16/2004
Record Updated Date:	03/08/2021
Update By:	KJCARPEN
Site Description:	"Location: The Flamingo Cleaners site is located in an urban area of New Rochelle, Westchester County, at the southeastern corner of the intersection of Clinton Place and North Avenue. Site Features: The site is a one-story commercial building with a full basement. The building is divided into four commercial tenant spaces which have been occupied at various times by a bar/lounge, beauty salon, delicatessen, a travel agency and a dry-cleaner. Current Zoning/use(s): The site consists of four retail spaces. The site is zoned for commercial use. The surrounding land uses include parking lots, commercial establishments, a residential apartment complex, a medical center, and a church. Past Uses of the Site: The existing building was constructed in 1941 and used for retail. Flamingo Cleaners began dry cleaning operations in 1958, and ran until 2005 when all dry-cleaning equipment was removed. Site contamination is a result of the former dry cleaner operations from improper management, disposal, and leaks of tetrachloroethylene (PCE). Prior completed investigations include a Phase I Investigation in October of 2003 and a Phase II Investigation completed in March of 2004. The Volunteer entered into a Brownfield Cleanup Agreement in April 2005. A Decision Document was issued in March 2012 for a remedy involving source soil removal and in situ chemical oxidation treatment of groundwater. Based on the extent of the site contamination, a referral to State Superfund for an off-site investigation was completed in December 2007. The groundwater plume was found to be isolated to immediately behind the building and little to no off-site impacts were noted in groundwater, soils, nor in soil vapor. Site Geology/hydrogeology: The site is underlain by glacial till which sits atop highly weathered bedrock. Bedrock ranges from 5 - 22 feet below ground surface. The water table is between 5 - 11 feet below ground surface. Groundwater flow direction is predominantly to the south-southeast toward Long Island Sound, however, site specific groundwater flow direction is radial, and seasonally affected."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), primarily tetrachloroethylene (PCE or perc) which was present in soils, groundwater, and indoor air. PCE breakdown products Trichloroethene (TCE) and 1,2-dichloroethene (1,2-DCE), vinyl chloride, as well as 1,1,1 trichloroethane (1,1,1 TCA), were also present at the site. Remedial actions have removed source soils, treated groundwater, and have prevented contaminants from entering the indoor air. Residual contamination in the soil, groundwater, and indoor air is being managed under a Site Management Plan. "
Health Problem:	"Measures are in place to control the potential for coming in contact with subsurface soil and ground water contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or

FLAMINGO CLEANERS (Continued) **1000299848**

other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater and/or soil may move into the soil vapor (air space within the soil), which in turn may move into overlying building and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system (system that ventilate/remove the air beneath the building) has been installed in the on-site building to prevent the indoor air quality from being affected by the contamination in the soil vapor beneath the building. Sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:90'830 / 73:77'928
Dell:	False
Record Add:	2004-12-16 12:46:00
Record Upd:	2013-10-25 16:35:00
Updated By:	BXANDERS
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	JO-ANNE LATINO
Owner Company:	JAMM North Avenue Realty, LLC.
Owner Address:	31 Green St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Charlestown, MA 02129
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Luigi Tush Lleshaj
Owner Company:	V & V Capital LLC
Owner Address:	369 Phillips Hill Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	4
Sub Type:	09
Owner Name:	Abbas A. Alsaidi
Owner Company:	New Rock Mini Mart & Deli Inc.
Owner Address:	149 North Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America

FLAMINGO CLEANERS (Continued) **1000299848**

Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michael Knipfing
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	149-155 North Corp.
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Luigi Lleshaj
Owner Company:	V&V Capital LLC
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	new City, NY 10956
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Not reported
Owner Company:	Luigi Lleshaj
Owner Address:	369 Phillips Hill Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New City, NY 10956
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Judge Susan I. Kettner
Owner Company:	The Estate of Dorothy Kettner
Owner Address:	87 Taymil Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10804
Owner Country:	United States of America
HW Code:	C360078
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078

FLAMINGO CLEANERS (Continued) **1000299848**

Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360078
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	0905638
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-07-12 12:27:00
Record Updated:	2016-07-12 12:27:00
Updated By:	JBODEE
Crossref ID:	W3-1058-05-03
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-12-05 12:19:00
Record Updated:	2016-12-05 12:19:00
Updated By:	KATHOMPS
Crossref ID:	561793593
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-11-04 10:40:00
Record Updated:	2016-11-04 10:40:00
Updated By:	KATHOMPS
Crossref ID:	1203976
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-07-23 16:23:00
Record Updated:	2012-07-23 16:23:00
Updated By:	JPCUMMIN

NY MANIFEST:

Name:	V & V CAPITAL LLC
Address:	149 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD012946885
Facility Status:	Not reported
Location Address 1:	149 NORTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY

FLAMINGO CLEANERS (Continued) **1000299848**

Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012946885
Mailing Name:	V & V CAPITAL LLC
Mailing Contact:	V&V CAPITAL LLC - FORMER FLAMINGO CLEANERS
Mailing Address 1:	149 NORTH AVENUE
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3615865900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2013
Trans1 Recv Date:	01/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/15/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD012946885
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX168000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	008835161JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	6160
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.

FLAMINGO CLEANERS (Continued) **1000299848**

Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	F002
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH295 **FLAMINGO/TYK CLEANERS** **NY DRYCLEANERS** **S110246604**
ESE **149 NORTH AV.** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1295 ft. **Site 10 of 11 in cluster AH**

Relative: DRYCLEANERS:
Lower

Name:	FLAMINGO/TYK CLEANERS
Address:	149 NORTH AV.
City,State,Zip:	NEW ROCHELLE, NY 10801
Facility ID:	3-5510-00335
Phone Number:	914-235-1591
Region:	Not reported
Registration Effective Date:	9/24/2003 13:22:51:203
Inspection Date:	2019-09-08 00:00:00
Install Date:	94/08
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
89 ft.

AH296 **COLONIAL CLEANERS CORP** **RCRA NonGen / NLR** **1000338874**
ESE **149 NORTH AVE** **NYD982718058**
1/8-1/4 **NEW ROCHELLE, NY 10801**
0.245 mi.
1295 ft. **Site 11 of 11 in cluster AH**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:	20070101
Handler Name:	COLONIAL CLEANERS CORP
Handler Address:	149 NORTH AVE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801-7405
EPA ID:	NYD982718058
Contact Name:	Not reported
Contact Address:	NORTH AVE
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

Actual:
89 ft.

COLONIAL CLEANERS CORP (Continued) **1000338874**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	NORTH AVE
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	COLONIAL CLEANERS CORP
Owner Type:	Private
Operator Name:	COLONIAL CLEANERS CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

COLONIAL CLEANERS CORP (Continued) **1000338874**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COLONIAL CLEANERS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COLONIAL CLEANERS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COLONIAL CLEANERS CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported

COLONIAL CLEANERS CORP (Continued) **1000338874**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: COLONIAL CLEANERS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: COLONIAL CLEANERS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: COLONIAL CLEANERS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19881130
Handler Name: COLONIAL CLEANERS CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

COLONIAL CLEANERS CORP (Continued) **1000338874**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG297 **130 CENTRE AVENUE CO-OP CORP.** **NY AST** **A100204222**
South **130 CENTRE AVENUE** **N/A**
1/8-1/4 **NEW ROCHELLE, NY 10805**
0.250 mi.
1319 ft. **Site 5 of 5 in cluster AG**

Relative:
Higher

Actual:
101 ft.

WESTCHESTER CO. AST:

Name:	130 CENTRE AVENUE CO-OP CORP.
Address:	130 CENTRE AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10805
PBS Number:	3-165735
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Lorraine Quezada
Owner Name:	130 Centre Avenue Co-op Corp.
Owner Street:	1601 Bronxdale Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10462
Tank Number:	1
Status:	1. In-Service
Date Installation:	11/11/1959
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	8. Retrofitted Impressed Current
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	0. None

AL298 **FIREHOUSE** **NY LTANKS** **S103037428**
ENE **HARRISON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.251 mi.
1327 ft. **Site 20 of 20 in cluster AL**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:

Name:	FIREHOUSE
Address:	HARRISON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9713840 / 1998-03-27
Facility ID:	9713840
Site ID:	252028
Spill Date:	1998-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	1998-07-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK GALELLO
Spiller Phone:	(914) 654-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/14/98 TO E.I.R. 3/27/98 PROTEST RETESTED. SYSTEM PASSED. NFA"
Remarks:	""

All TTF:

Facility ID:	9713840
Spill Number:	9713840
Spill Tank Test:	1545673
Site ID:	252028
Tank Number:	2
Tank Size:	5000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

FIREHOUSE (Continued) **S103037428**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	252028
Operable Unit ID:	1059801
Operable Unit:	01
Material ID:	324831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK299 **BERGMAN REALTY SERVICES** **NY LTANKS** **S106972591**
NE **140 HUGUENOT STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.255 mi.
1349 ft. **Site 6 of 6 in cluster AK**

Relative:
Lower

Actual:
66 ft.

LTANKS:

Name:	BERGMAN REALTY SERVICES
Address:	140 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0505137 / 2007-11-07
Facility ID:	0505137
Site ID:	350100
Spill Date:	2005-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	WCDOH
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2007-11-07
Spiller Name:	STEVE RING
Spiller Company:	RING HOME
Spiller Address:	140 HUGINOT STREET
Spiller County:	001
Spiller Contact:	STEVE RING

BERGMAN REALTY SERVICES (Continued) **S106972591**

Spiller Phone:	(732) 855-8600
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	296544
DEC Memo:	"10/13/05 Closure letter sent to the RP from Danielle Jackson of the WCHD based on information submitted in a tank closure report. NFA TG"
Remarks:	""

All TTF:

Facility ID:	0505137
Spill Number:	0505137
Spill Tank Test:	1549133
Site ID:	350100
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	350100
Operable Unit ID:	1107682
Operable Unit:	01
Material ID:	2097572
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO300 **BLESSED SACREMENT CHURCH** **NY LTANKS** **S105996474**
South **15 SHEA PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.263 mi.
1387 ft. **Site 1 of 3 in cluster AO**

Relative:
Higher

Actual:
97 ft.

LTANKS:

Name:	BLESSED SACREMENT CHURCH
Address:	15 SHEA PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0204856 / 2003-10-03
Facility ID:	0204856
Site ID:	167332
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

BLESSED SACREMENT CHURCH (Continued) **S105996474**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	BLESSED SACREMENT CHURCH
Spiller Address:	15 SHEA PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140984
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"DRY LEAK"

All TTF:

Facility ID:	0204856
Spill Number:	0204856
Spill Tank Test:	1527358
Site ID:	167332
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	167332
Operable Unit ID:	856138
Operable Unit:	01
Material ID:	519078
Material Code:	0001A
Material Name:	#2 fuel oil

BLESSED SACREMENT CHURCH (Continued) **S105996474**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AN301 **SPILL NUMBER 0011198** **NY LTANKS** **S104950549**
West **114 UNION AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.263 mi.
1390 ft. **Site 2 of 3 in cluster AN**

Relative: **Higher**
Actual: **92 ft.**

LTANKS:

Name:	SPILL NUMBER 0011198
Address:	114 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0011198 / 2001-04-06
Facility ID:	0011198
Site ID:	151446
Spill Date:	2001-01-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-14
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-14
Spill Record Last Update:	2001-04-24
Spiller Name:	Not reported
Spiller Company:	ALBINO FUELS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128711
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE SEE ONE PAGE UDATE BY V. MCCABE 04/06/2001 NORTHEAST COMPLETED CLEANUP. DISPOSED OF 4 DRUMS OF CONTAMINATION. SPILL INFORMATION FORWARDED TO LAW ENFORCEMENT FOR FURTHER ACTION. SPILLS - NO FURTHER ACTION."
Remarks:	"tank overfilled caused spill - spill is contained in a parking lot spiller is - albano fuel - 667-0900 (914)-clean up crew on site at this time"

SPILL NUMBER 0011198 (Continued) **S104950549**

All Materials:

Site ID:	151446
Operable Unit ID:	832582
Operable Unit:	01
Material ID:	541520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APARTMENT BLDG.
Address:	114 UNION AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9414493 / 1995-02-14
Facility ID:	9414493
Site ID:	238808
Spill Date:	1995-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-02-06
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-07
Spill Record Last Update:	1995-03-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"ESTIMATED WRONG TANK SIZE SPILL CONTAINED NATL.ENVIR.CO. SPILL CREW ON WAY ENV PROD. AND SERVICES HIRED TO CLEAN UP. WILL EXCAVATE DRYWELL."

All Materials:

Site ID:	238808

SPILL NUMBER 0011198 (Continued) **S104950549**

Operable Unit ID: 1012066
Operable Unit: 01
Material ID: 373228
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 175.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: RESIDENCE
Address: 114 UNION AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9414511 / 1995-02-13
Facility ID: 9414511
Facility Type: ER
DER Facility ID: 196552
Site ID: 238809
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6010
Spill Date: 1995-02-02
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1995-02-02
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Fire Department
Cleanup Ceased: 1995-02-13
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-02-07
Spill Record Last Update: 1995-02-13
Spiller Name: Not reported
Spiller Company: REGENT OIL
Spiller Address: 53 CHARLES STREET
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "SPILLER MAKING DELIVERY FILLED WRONG HOLE FD & CLEAN UP CREW ON SCENE TANK OVERFILL EP & S HIRED BY SPILLER AND ON SCENE CONTACTED WCHD WILL RESPOND SEE SPILL #94-14493"

All Materials:
Site ID: 238809
Operable Unit ID: 1008085
Operable Unit: 01

SPILL NUMBER 0011198 (Continued) **S104950549**

Material ID:	373246
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ302 **DIMATTOE TTF** **NY LTANKS** **S113820294**
NNW **55 MAY STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.266 mi.
1403 ft. **Site 3 of 3 in cluster AJ**

Relative: **Lower**
Actual: **79 ft.**

LTANKS:

Name:	DIMATTOE TTF
Address:	55 MAY STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1301890 / 2013-08-08
Facility ID:	1301890
Site ID:	482303
Spill Date:	2013-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2013-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-23
Spill Record Last Update:	2013-08-08
Spiller Name:	Not reported
Spiller Company:	DIMATTOE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	AMELIO DIMATTOE
Spiller Phone:	(914) 403-1942
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	437556
DEC Memo:	"5/23/13 left message on homeowner's phone. Spoke to Kathy, at US Tank Tech Tank is 1000 gal. Real estate transaction, and plans are to retest. dw 07/31/13 Northeast Environmental reported that they cut & cleaned the tank and obtained a soil sample from beneath the tank. The soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"repair/retest pending"

DIMATTOE TTF (Continued) **S113820294**

All TTF:

Facility ID:	1301890
Spill Number:	1301890
Spill Tank Test:	2493480
Site ID:	482303
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.70
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	482303
Operable Unit ID:	1232041
Operable Unit:	01
Material ID:	2230831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

303
East
1/4-1/2
0.267 mi.
1409 ft.

CITY OF NEW ROCHELLE FIRE **NY LTANKS** **S105995871**
1 HARRISON STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
72 ft.

LTANKS:

Name:	CITY OF NEW ROCHELLE FIRE
Address:	1 HARRISON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0201696 / 2002-09-18
Facility ID:	0201696
Site ID:	75380
Spill Date:	2002-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-05-15
CID:	282

CITY OF NEW ROCHELLE FIRE (Continued) **S105995871**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-15
Spill Record Last Update:	2002-09-23
Spiller Name:	SAME
Spiller Company:	NEW ROCHELLE FIRE DEPT
Spiller Address:	1 HARRISON STREET
Spiller County:	001
Spiller Contact:	FRANK GALLELLO-FIRE DEPT
Spiller Phone:	(914) 654-2316
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70557
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST.PBS 3-600407 "

All TTF:

Facility ID:	0201696
Spill Number:	0201696
Spill Tank Test:	1527133
Site ID:	75380
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	75380
Operable Unit ID:	854864
Operable Unit:	01
Material ID:	523106
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM304 **EXXON S/S** **NY LTANKS** **1000553075**
SSW **635 MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.268 mi.
1413 ft. **Site 2 of 2 in cluster AM**

Relative: **Lower**

Actual: **85 ft.**

LTANKS:

Name:	EXXON S/S
Address:	635 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9206930 / 2005-03-11
Facility ID:	9206930
Site ID:	140421
Spill Date:	1992-09-16
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-03-12
Spiller Name:	Not reported
Spiller Company:	EXXON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	119925
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/11/05 per contractors report 7 tanks removes all in good condition (no evidence of holes or cracks; no detect in post excavation samples--close "
Remarks:	"DURING TANK REMOVAL CONTAMINATED SOIL DISCOVERED WILL TEST"

All Materials:

Site ID:	140421
Operable Unit ID:	970699
Operable Unit:	01
Material ID:	407611
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

EXXON S/S (Continued) **1000553075**

SPILLS:

Name:	CUMBERLAND FARM
Address:	635 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0514511 / 2006-03-20
Facility ID:	0514511
Facility Type:	ER
DER Facility ID:	119925
Site ID:	361248
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-20
Investigator:	RXAMATO
Referred To:	WCDOH
Reported to Dept:	2006-03-20
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-31
Spiller Name:	MELISSA GLIDEN
Spiller Company:	CUMBERLAND FARM
Spiller Address:	635 MAIN STREET
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
DEC Memo:	"03/21/06: Closed - NFA R. Amato"
Remarks:	"water in the dispenser pan and tyree enroute to clean up"

Name:	CUMBERLAND FARMS 70288
Address:	635 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1405322 / Not Reported
Facility ID:	1405322
Facility Type:	ER
DER Facility ID:	119925
Site ID:	498745
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2014-08-15
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-08-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other

EXXON S/S (Continued) **1000553075**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2014-08-15
Spill Record Last Update:	2019-12-03
Spiller Name:	Not reported
Spiller Company:	CUMBERLAND FARMS 70288
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOHN
DEC Memo:	"8-15-14 Spoke with Angela Pimento at CF. She will have John return call to dispatch desk. jm Recv'd callback from Chris Lalak - WCDOH. He has spoken with John. Double wall fiberglass piping from dispensers to tanks. Leak is contained in tanktop sump. System has has been shut down at this time until they figure out what they are going to do. They believe they will probably replace lines. Chris says no leak to environment and he will be taking lead. jm 5-15 new spill 15-01325; Phase 2report 10-15-15 email status request sent to WCHD & Cumby RDB 10-22-15, from Cumby In response to the line failure, CFI engaged Island Pump & Tank (IPT) to perform the repairs. In lieu of replacing the product piping, IPT installed a siphon bar on the regular tanks and removed the submersible pump from the regular tank that had the failed product piping. IPT then removed and capped the regular product piping that had failed. The secondary line was tested and the dispenser pans and STP sumps were hydrostatically tested and passed. RDB 2-16 new SPills 15-10746 3-8-16 during meeting with WCHD, Singh, his att, his consultant, Cumby, their consultant and att, taking place in New Rochelle. Closure was denied on spills 14-05322 & 15-01325and RPs agreed to a scope of work by March 16. RDB 5-4-17 Work completed, waiting for closure report. GHP 12-3-19 Call from HighPoint Engineering. Felix and Sons Contractor installed new tanks in September 2016 and tightness tested October 2016. What do we have to do to close the spill . Sunny Singh for 635 Main Street Realty LLC (516-777-4320) is the client. BTR"
Remarks:	"spill to containment/clean up complete"

All Materials:

Site ID:	498745
Operable Unit ID:	1248186
Operable Unit:	01
Material ID:	2249583
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AP305 **NEW ROCHELLE CATH MIDDLE** **NY LTANKS** **S102154123**
South **24 MAPLE AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.269 mi.
1419 ft. **Site 1 of 2 in cluster AP**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	NEW ROCHELLE CATH MIDDLE
Address:	24 MAPLE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0204857 / 2003-10-03
Facility ID:	0204857
Site ID:	80066
Spill Date:	2002-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-08-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-07
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	NEW ROCHELLE CATH MIDDLE
Spiller Address:	24 MAPLE AV
Spiller County:	001
Spiller Contact:	MARV
Spiller Phone:	(914) 637-7505
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74246
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 10/17/03: Letter to Blessed Sacrament Church from Karen Magnuson, WCDOH dated 10/3/2003. Closure report by RND Services has been reviewed. WCDOH recommends NFA at this time."
Remarks:	""

All TTF:

Facility ID:	0204857
Spill Number:	0204857
Spill Tank Test:	1527359
Site ID:	80066
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 80066
Operable Unit ID: 856140
Operable Unit: 01
Material ID: 519079
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: BLESSED SACREMENT SCHOOL
Address: 24 MAPLE AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9008354 / 1990-11-26
Facility ID: 9008354
Facility Type: ER
DER Facility ID: 107755
Site ID: 124420
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6010
Spill Date: 1990-10-30
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1990-10-31
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Fire Department
Cleanup Ceased: 1990-10-31
Cleanup Meets Std: True
Last Inspection: 1990-10-31
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-11-06
Spill Record Last Update: 1990-11-26
Spiller Name: Not reported
Spiller Company: CASTLE FUEL
Spiller Address: 290 LOCUST AVE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

GHIOSAY "
Remarks: "PIPE BURST DURING DELIVERY WC FIRE CONTROL ON SCENE ABSORBANT PADS HAVE BEEN PUT DOWN CHIEF MCCAFFREY CONTACTED BUT HE WASN'T ON SCENE HAS NO INFO."

All Materials:
Site ID: 124420
Operable Unit ID: 945552
Operable Unit: 01
Material ID: 432188
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BLESSED SACRAMENT SCHOOL
Address: 24 MAPLE AVE.
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9111148 / 1992-03-17
Facility ID: 9111148
Facility Type: ER
DER Facility ID: 107755
Site ID: 124421
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6010
Spill Date: 1992-01-29
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1992-01-29
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: 1992-02-05
Cleanup Meets Std: True
Last Inspection: 1992-02-05
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-01-30
Spill Record Last Update: 1992-03-17
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""
Remarks: "OIL DISCOVERED SEEPING OUT OF GROUND/BLACKTOP WALKWAY (BETWEEN SCHOOL AND BEAUTY SALON) SUSPECT BROKEN RETURN LINE APPROX 30' FROM TANK TO BURNER - 2K TANK AL EASTMAN TO EIR CASTLE OIL CREW ENROUTE"

NEW ROCHELLE CATH MIDDLE (Continued) **S102154123**

All Materials:

Site ID:	124421
Operable Unit ID:	964875
Operable Unit:	01
Material ID:	416206
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AQ306 **COMMERCIAL PROPERTY** **NY LTANKS** **S112810152**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.272 mi.
1437 ft. **Site 1 of 6 in cluster AQ**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	COMMERCIAL PROPERTY
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1213228 / 2013-02-04
Facility ID:	1213228
Site ID:	476407
Spill Date:	2012-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-12-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-10
Spill Record Last Update:	2013-02-04
Spiller Name:	Not reported
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	HAL SHAPIRO
Spiller Phone:	(914) 355-5350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"12-10-12 PBS site. Tank failed with popping. US Tank Tech has been

COMMERCIAL PROPERTY (Continued) **S112810152**

testing since '98. Super was at site during test and Shapiro notified by phone. jc 12/19/12: Update from WCDoH PBS: >>> Lalak, Chris >>cjl1@westchestergov.com> 12/11/2012 4:23 PM >>> 1213228 38 Locust, new Rochelle PBS 3-800080 TTF 3K tank from 84 Tyra/Carlos Lead jod 2/4/2013: Tank passed a retest after piping was repaired. Report entered into eDocs. Based upon the information provided, no further action is required at this time. jod"

Remarks: "1211 THE CALLER IS REPORTING A FAILED TANK TEST."

All Materials:

Site ID:	476407
Operable Unit ID:	1226235
Operable Unit:	01
Material ID:	2223616
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ307 **COMMERCIAL SITE** **NY LTANKS** **U003857828**
ESE **38 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.272 mi.
1437 ft. **Site 2 of 6 in cluster AQ**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	COMMERCIAL SITE
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0408593 / 2005-02-13
Facility ID:	0408593
Site ID:	333366
Spill Date:	2004-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-11-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-05
Spill Record Last Update:	2005-02-13
Spiller Name:	BARRY SHAPIRO
Spiller Company:	COMMERCIAL SITE

COMMERCIAL SITE (Continued) **U003857828**

Spiller Address:	38 LOCUS AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	"02/13/05 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-800080 "
Name:	SBJ ASSOCIATES
Address:	38 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0206043 / 2002-09-26
Facility ID:	0206043
Site ID:	239569
Spill Date:	2002-09-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2002-10-29
Spiller Name:	BARRY SHAPIRO
Spiller Company:	SBJ ASSOCIATES
Spiller Address:	38 LOCUST AVE
Spiller County:	001
Spiller Contact:	BARRY SHAPIRO
Spiller Phone:	(914) 393-2581
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197040
DEC Memo:	""
Remarks:	"RECOMMENDATION IS TO UNCOVER - REPAIR - AND RE-TEST."

All TTF:

Facility ID:	0206043
Spill Number:	0206043
Spill Tank Test:	1527440
Site ID:	239569
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported

COMMERCIAL SITE (Continued) **U003857828**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239569
Operable Unit ID:	857630
Operable Unit:	01
Material ID:	571516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR308 **SPILL NUMBER 0208792** **NY LTANKS** **S105997404**
North **386 NORTH AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.274 mi.
1446 ft. **Site 1 of 5 in cluster AR**

Relative: **Lower**

Actual: **75 ft.**

LTANKS:

Name:	SPILL NUMBER 0208792
Address:	386 NORTH AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0208792 / 2002-11-26
Facility ID:	0208792
Site ID:	71430
Spill Date:	2002-11-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-11-26

SPILL NUMBER 0208792 (Continued) **S105997404**

Spiller Name:	ROBERT CRIILLO
Spiller Company:	WILCO
Spiller Address:	95 PLAIN AV
Spiller County:	001
Spiller Contact:	CARTER RESIDENCE
Spiller Phone:	(914) 632-6577
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67588
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 SPILL CLEANUP TO BE COMPLETED TOMORROW."
Remarks:	"take pride environmental enroute to clean up the soil"

All Materials:

Site ID:	71430
Operable Unit ID:	861979
Operable Unit:	01
Material ID:	515786
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AS309 **DEMELIA - TTF** **NY LTANKS** **S117364514**
West **95 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.274 mi.
1448 ft. **Site 1 of 2 in cluster AS**

Relative: **Higher**
Actual: **90 ft.**

LTANKS:

Name:	DEMELIA - TTF
Address:	95 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1406916 / 2015-04-14
Facility ID:	1406916
Site ID:	500408
Spill Date:	2014-10-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

DEMELIA - TTF (Continued) **S117364514**

Date Entered In Computer:	2014-10-01
Spill Record Last Update:	2015-04-14
Spiller Name:	ROSEMARIE DEMELIA
Spiller Company:	Estate of DeMelia
Spiller Address:	95 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455413
DEC Memo:	"This house is the estate of R Demellia's late mother. Tank failed with only hissing, maybe a line leak but cant be sure. House is being prep'ed for sale....mm 12/08/14: From Envirostar: We pulled a 550 UST at 95 Washington Ave New Rochelle that had previously failed a tank test (spill # 1406916). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Chuck LiVecchi 95 Washington Ave New Rochelle NY jod 3/20/15: Update from Envirostar via email: We removed 6 containers of contaminated soil Between march 12th and yesterday we took samples and back filled the hole. We will Submit for closure. jod 4/13/15: Report with request for closure entered into DecDocs. Post-Ex soil samples show contamination in excess of CP-51 Guidance. Additional information being requested from Envirostar. jod 4/14/2015: Envirostar removed and disposed of the leaking UST and a total of 108.96 tons of petroleum contaminated soil. Some residual contamination over CP-51 Guidance could not be excavated from along the foundation and due to safety concerns with buried utility lines. No evidence of ground water impact noted. Based upon information provided, no further action required at this time. jod"
Remarks:	"550 test failure"

All TTF:

Facility ID:	1406916
Spill Number:	1406916
Spill Tank Test:	2496432
Site ID:	500408
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	500408
Operable Unit ID:	1249816
Operable Unit:	01
Material ID:	2251444
Material Code:	0001A

DEMELIA - TTF (Continued) **S117364514**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

---

310 **10 COMMERCE DRIVE RAIL YARD** **NY INST CONTROL** **S125465243**
NE **10 COMMERCE DRIVE** **NY BROWNFIELDS** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 14614** **NY Spills**
0.276 mi.
1459 ft.

Relative:
Lower

Actual:
66 ft.

INST CONTROL:

Name:	10 COMMERCE DRIVE RAIL YARD
Address:	10 COMMERCE DRIVE
City,State,Zip:	NEW ROCHELLE, NY 14614
Site Code:	591030
Control Name:	Environmental Easement
HW Code:	C360192
Control Code:	J
Control Type:	INST
Dt record added:	09/21/2021
Dt rec updated:	12/24/2021
Updated By:	PBAMIN
Site Code:	591030
Site Description:	"Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "

Env Problem: "Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples. Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."

Health Problem: "Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-01-06 16:35:00
Record Upd: 2021-09-21 08:02:00
Updated By: PBAMIN
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Rashid A. Walker

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: C360192
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethanol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: acetone
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: alpha-BHC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

HW Code: C360192
Waste Type: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: 1,1,2-trichlorethylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2006789
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-27 12:40:00
Record Updated: 2020-10-27 12:40:00
Updated By: JAGIORDA
Crossref ID: C360192-01-20
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-21 08:04:00
Record Updated: 2021-09-21 08:04:00
Updated By: PBAMIN
Crossref ID: 612293824
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-24 08:38:00
Record Updated: 2021-11-24 08:38:00

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Updated By: PBAMIN

Name: 10 COMMERCE DRIVE RAIL YARD
Address: 10 COMMERCE DRIVE
City,State,Zip: NEW ROCHELLE, NY 14614
Site Code: 591030
Control Name: Site Management Plan
HW Code: C360192
Control Code: 32
Control Type: INST
Dt record added: 09/21/2021
Dt rec updated: 12/24/2021
Updated By: PBAMIN
Site Code: 591030
Site Description: "Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "
Env Problem: "Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3 micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples.

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."

Health Problem: "Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-01-06 16:35:00
Record Upd: 2021-09-21 08:02:00
Updated By: PBAMIN
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

HW Code: C360192
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethanol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: acetone
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: alpha-BHC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Type: 1,1,2-trichlorethylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2006789
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-27 12:40:00
Record Updated: 2020-10-27 12:40:00
Updated By: JAGIORDA
Crossref ID: C360192-01-20
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-21 08:04:00
Record Updated: 2021-09-21 08:04:00
Updated By: PBAMIN
Crossref ID: 612293824
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-24 08:38:00
Record Updated: 2021-11-24 08:38:00
Updated By: PBAMIN

Name: 10 COMMERCE DRIVE RAIL YARD
Address: 10 COMMERCE DRIVE
City,State,Zip: NEW ROCHELLE, NY 14614
Site Code: 591030
Control Name: Monitoring Plan
HW Code: C360192
Control Code: 31
Control Type: INST
Dt record added: 09/21/2021
Dt rec updated: 12/24/2021
Updated By: PBAMIN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Site Code: 591030

Site Description: "Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "

Env Problem: "Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3 micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples. Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."

Health Problem: "Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-01-06 16:35:00
Record Upd: 2021-09-21 08:02:00
Updated By: PBAMIN
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported
Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: C360192
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethanol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: acetone
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	alpha-BHC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	dichloroethene (cis-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	1,1,2-trichlorethylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	tetrachloroethene (PCE)

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2006789
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-27 12:40:00
Record Updated: 2020-10-27 12:40:00
Updated By: JAGIORDA
Crossref ID: C360192-01-20
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-21 08:04:00
Record Updated: 2021-09-21 08:04:00
Updated By: PBAMIN
Crossref ID: 612293824
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-24 08:38:00
Record Updated: 2021-11-24 08:38:00
Updated By: PBAMIN

Name: 10 COMMERCE DRIVE RAIL YARD
Address: 10 COMMERCE DRIVE
City,State,Zip: NEW ROCHELLE, NY 14614
Site Code: 591030
Control Name: Landuse Restriction
HW Code: C360192
Control Code: 25
Control Type: INST
Dt record added: 09/21/2021
Dt rec updated: 12/24/2021
Updated By: PBAMIN
Site Code: 591030
Site Description: "Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "

Env Problem: "Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3 micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples. Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."

Health Problem: "Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-01-06 16:35:00
Record Upd:	2021-09-21 08:02:00
Updated By:	PBAMIN
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	100 Park Avenue, 36th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	100 Park Avenue, 36th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C360192
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	ethanol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	acetone
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	nickel

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: alpha-BHC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: 1,1,2-trichlorethylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: methylene chloride
Waste Quantity: UNKNOWN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Code: Not reported
Crossref ID: 2006789
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-27 12:40:00
Record Updated: 2020-10-27 12:40:00
Updated By: JAGIORDA
Crossref ID: C360192-01-20
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-21 08:04:00
Record Updated: 2021-09-21 08:04:00
Updated By: PBAMIN
Crossref ID: 612293824
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-24 08:38:00
Record Updated: 2021-11-24 08:38:00
Updated By: PBAMIN

Name: 10 COMMERCE DRIVE RAIL YARD
Address: 10 COMMERCE DRIVE
City,State,Zip: NEW ROCHELLE, NY 14614
Site Code: 591030
Control Name: Ground Water Use Restriction
HW Code: C360192
Control Code: 08
Control Type: INST
Dt record added: 09/21/2021
Dt rec updated: 12/24/2021
Updated By: PBAMIN
Site Code: 591030
Site Description: "Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "

Env Problem: "Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3 micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples. Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."

Health Problem: "Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-01-06 16:35:00
Record Upd: 2021-09-21 08:02:00
Updated By: PBAMIN
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tom Geoffino
Owner Company: New Rochelle Public Library
Owner Address: 1 Library Plaza
Owner Addr2: Not reported

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Owner City,St,Zip: New Rochelle, NY 10801
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Rashid A. Walker
Owner Company: BRP 10 Commerce LLC
Owner Address: 100 Park Avenue, 36th floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: C360192
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethanol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: acetone
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: phenol
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: nickel
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: alpha-BHC
Waste Quantity: UNKNOWN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Code: Not reported
HW Code: C360192
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: 1,1,2-trichlorethylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: carbon tetrachloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360192
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2006789
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-27 12:40:00
Record Updated: 2020-10-27 12:40:00
Updated By: JAGIORDA
Crossref ID: C360192-01-20
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-21 08:04:00
Record Updated: 2021-09-21 08:04:00
Updated By: PBAMIN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Crossref ID: 612293824
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-24 08:38:00
Record Updated: 2021-11-24 08:38:00
Updated By: PBAMIN

BROWNFIELDS:

Name:	10 COMMERCE DRIVE RAIL YARD
Address:	10 COMMERCE DRIVE
City,State,Zip:	NEW ROCHELLE, NY 14614
Program:	BCP
Site Code:	591030
Acres:	0.965
HW Code:	C360192
SWIS:	6010
Town:	New Rochelle (c)
Record Added Date:	06/25/2019
Record Updated Date:	12/27/2021
Update By:	AMSERVIS
Site Description:	"Location: The 10 Commerce Drive Rail Yard site is an approximately one-acre site located at 10 Commerce Drive in a commercial area of New Rochelle in Westchester County. The site is bounded to the north by Renewal Place and to the east, south and west by commercial properties and associated asphalt parking areas. Echo Bay and its associated tributaries are approximately 0.5 miles east of the site. Site Features: The two-story vacant building, including the floor slab, which existed on the site was demolished in late 2019 and early 2020 and the debris was removed from the site. As of 2021, the site is being redeveloped as a multi-story residential building. The new building footprint covers the entire site, and there is no exposed soil on the site. Current Zoning and Land Use: The site is zoned as Downtown Overlay Zone (DOZ) which allows for mixed residential and commercial uses. The surrounding area is predominantly commercial. Past Use of Site: In 1896, the northern and western portions of the site were occupied by the New York, New Haven and Hartford (NYNH&H) Railroad Company. In 1931, Rosa Coal & Oil Company was operating in the central and southern portions of the site until 1951. It appears that sometime in the mid-1960s, the structures associated with NYNH&H Railroad Company and Rosa Coal & Oil Company were demolished. The site remained vacant until a two-story building was constructed on site in or about 1981-1982. Before the two-story building was demolished between 2019 and 2020, an electronic manufacturer occupied a portion of the building between 1992 and 2003. Site Geology and Hydrology: The subsurface underlying the site consists of a layer of fill material overlying dense native fine-grained sandy soil with some clay and trace amounts of fine gravel. The fill extended from ground surface to approximately 4 to 9 feet below ground surface (bgs) and is composed of brown, medium to fine sand with some silt, gravel, brick, concrete, wood and ash. Groundwater was encountered at depths ranging from 2 to 9 feet bgs. Bedrock was encountered at about 18 feet bgs and consisted of granite. Groundwater flows south-southeast. "
Env Problem:	"Nature and Extent of Contamination: The site contamination resulted from the use of waste generated from railroad operation (e.g. railroad ties) to fill the site. There is no indication that the contamination for any media extends off-site. Soil: Remedial

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Investigation of the site soil was performed in April 2020, prior to a soil removal Interim Remedial Measures(IRM). A total of 12 soil borings and 7 test pits were installed to a depth of 6 to 17 feet bgs and 49 samples were collected. Samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), inorganics (metals), polychlorinated biphenyls (PCBs), pesticides and polyfluroalkyl substances (PFAS). Confirmation soil samples collected following the soil removal IRM did not reveal exceedances of unrestricted soil cleanup objectives(SCOs) for VOCs, SVOCs, pesticides, PCBs and inorganics. PFOA and PFOS concentrations were also below the applicable screening values of 0.66 and 0.88 parts per million (ppm), respectively. Approximately 670 cubic yards of soil generated on-site, that met unrestricted use SCOs, was placed beneath the foundation. Additionally, 44,700 tons of virgin coarse aggregate were imported and placed beneath the foundation. Groundwater: A total of ten (10) groundwater samples were collected from depths of 5 to 19 feet bgs and analyzed for VOCs, SVOCs, inorganics, PCBs, pesticides and PFAS. Xylene was detected in one monitoring well at 5.9 parts per billion (ppb) which is slightly above the applicable groundwater standard of 5 ppb. Phenol was detected in the two wells in the range of 1.7 to 10.9 ppb which is above the ground water standard of 1 ppb. Benzo(a)pyrene was detected in three wells in the range of and 0.02 to 0.74 ppb. Benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene and indeno(1,2,3-cd)pyrene were also detected in one sample slightly above their respective ground water standards. Arsenic was detected in two wells, ranging from 66-71.16 ppb compared to a standard of 25 ppb. Total (vs. dissolved) concentrations of chromium, lead, manganese, and nickel were detected in one well at 344, 213, 4,050 and 291 ppb, respectively, which are above the applicable standards of 50, 25, 300 and 100 ppb, respectively. Iron, sodium and copper were also detected in the groundwater samples. Metals in the groundwater are likely related to suspended solids present in the samples. Ethylbenzene, xylene, and naphthalene were detected below their respective ground water standards. Chloroform was detected in the eight out of ten wells in the range of 10 to 55 ppb which is above the ground water standard of 7 ppb. Chloroform is a by-product of drinking water chlorination and is often found in groundwater in urban areas served by (leaking) public water lines. Bromodichloromethane and bromomethane, also byproducts of drinking water chlorination, were also detected below their respective standards. Acetone and 2-butanone (or methyl ethyl ketone [MEK]), common laboratory contaminants, were detected below their respective groundwater standards. No other chlorinated VOCs were detected in any of the groundwater samples. Sub-slab Soil Vapor: The new building is currently under construction. The slab for the new building has been installed, following which a total of eight sub-slab soil vapor samples were collected from beneath the newly-constructed slab and analyzed for VOCs. However, since the building is under construction/incomplete, indoor air samples could not be collected. Benzene was detected in the range of 3.5 to 40.3 micrograms per cubic meter (ug/m3) in seven out of eight samples. Ethylbenzene was detected in the range of 3.0 to 76.0 ug/m3 in all samples. Toluene ranged from non-detect (ND) to 38.1 ug/m3 in seven out of eight samples. Total xylenes were detected in the range of 16 to 292 ug/m3 in all eight samples. Tetrachloroethene (PCE) was detected in the range of 0.61 to 585 ug/m3 in six out of eight samples. Trichloroethylene ranged from ND to 6.4 ug/m3 in two out of

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

	eight samples. Cis 1,2-dichloroethelyene and vinyl chloride were not detected in any samples. Carbon tetrachloride was detected in the range of 0.34 to 7.5 ug/m3 in two out of eight samples. 1,1,1 Trichloroethane was not detected in any samples. Methylene chloride ranged from ND to 1.1 ug/m3 in two out of eight samples. Ethanol was detected in the range of 19 to 18,800 ug/m3 in all the samples. Several other VOCs were also detected in a number of the samples. The source of the VOCs is unclear considering that the soil was excavated to unrestricted use SCOs and very low VOC concentrations were detected in groundwater. Since no VOCs (except a minor xylene exceedance) were detected above their respective ground water standards, it is unlikely that the VOCs detected in soil vapor have migrated off-site. However, based on the above, a post-construction soil vapor intrusion investigation will be required."
Health Problem:	"Soil removal actions have been completed to remove contaminated soil at the site, eliminating this potential exposure pathway. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-01-06 16:35:00
Record Upd:	2021-09-21 08:02:00
Updated By:	PBAMIN
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tom Geoffino
Owner Company:	New Rochelle Public Library
Owner Address:	1 Library Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	100 Park Avenue, 36th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Owner Name:	Rashid A. Walker
Owner Company:	BRP 10 Commerce LLC
Owner Address:	100 Park Avenue, 36th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C360192
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	ethanol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	acetone
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	alpha-BHC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	dichloroethene (cis-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	toluene
Waste Quantity:	UNKNOWN

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Waste Code:	Not reported
HW Code:	C360192
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	1,1,2-trichlorethylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	carbon tetrachloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360192
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2006789
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-10-27 12:40:00
Record Updated:	2020-10-27 12:40:00
Updated By:	JAGIORDA
Crossref ID:	C360192-01-20
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-21 08:04:00
Record Updated:	2021-09-21 08:04:00
Updated By:	PBAMIN
Crossref ID:	612293824
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-24 08:38:00
Record Updated:	2021-11-24 08:38:00
Updated By:	PBAMIN

SPILLS:

Name:	COMMERCIAL
Address:	10 COMMERCE DR
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2006789 / 2021-12-28

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

Facility ID:	2006789
Facility Type:	ER
DER Facility ID:	560711
Site ID:	612651
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6010
Spill Date:	2020-10-27
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2020-10-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-10-27
Spill Record Last Update:	2021-12-28
Spiller Name:	Not reported
Spiller Company:	DRP 10 COMMERCE LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FUAD DAHAN
DEC Memo:	"10/27/20 During excavation activities at this BCP site, a previously unknown single-wall steel UST was discovered. The tank top has been uncovered and the tank measures approximately 11ft long by 4 ft diameter, estimated at 1000-gal capacity. There is some liquid present in the tank (mostly water) and holes are visible. The product and use of the tank are unknown but suspected to be a heating fuel oil. The plan is to pump out, cut, clean and remove the tank, and follow-up with excavation and stockpiling of all impacted soil encountered for eventual disposal. Most of the site is being excavated to a depth between 5 to 13 ft below existing grade for a Track 1 remediation under BCP. The site is not believed to have a PBS registration. DER PM Parag Amin is on-site today. New Rochelle fire inspector has been contacted. JG 11/02/20: Call to dispatch desk from Jesse Maussener from SESI Consultants. He states that during further excavation work they have now located three additional USTs. These tanks appear to be smaller than the 1K UST discovered last week. Tanks will be cleaned and removed and the project will continue. jod 11/9/20- call from Jesse, another 1000 gal UST. Staining and holes in the top of the tank found. The tanks will be registered with Westchester County DOH. Rainwater is believed to be in this tank. - KJ 01-06-21 Update from SESI, the tanks have been removed and clean endpoints achieved. The closure report will be included with the BCP report to be submitted in 6 weeks. The WCHD determined the tanks were not required to be registered. BTR 12-28-21 Sent email requesting an update from Jesse to jam@sesi.org. Received UST closure report from Fuad at SESI. 5 underground storage tanks were removed in November 2020 and this closure report was prepared in March 2021. The liquid in the USTs were removed by Luzon Environmental. Approximately 148

10 COMMERCE DRIVE RAIL YARD (Continued) **S125465243**

cubic yards of petroleum contaminated soil were taken to Former New Jersey Zinc - West Plant in Pennsylvania. Soil analytical results were non-detect for BTEX analytes. Tanks were recycled at Pascap Metal in Bronx NY. WCHD determined that these tanks do not need to be registered. NFA. BTR"

Remarks: "underground tank removal"

All Materials:

Site ID:	612651
Operable Unit ID:	1359778
Operable Unit:	01
Material ID:	2371393
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

311
SE
1/4-1/2
0.280 mi.
1481 ft.

RESIDENCE
64 CHURCH ST
NEW ROCHELLE, NY

NY LTANKS **S106971497**
N/A

Relative:
Lower

Actual:
86 ft.

LTANKS:

Name:	RESIDENCE
Address:	64 CHURCH ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0408510 / 2008-05-01
Facility ID:	0408510
Site ID:	333255
Spill Date:	2004-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-02
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-02-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2008-05-01
Spiller Name:	RAMONE OCEGUERA
Spiller Company:	Not reported
Spiller Address:	64 CHURCH ST
Spiller County:	001

RESIDENCE (Continued) **S106971497**

Spiller Contact:	RAMONE OCEGUERA
Spiller Phone:	(914) 396-7293
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268502
DEC Memo:	"11/22/04 AST ON GROUND UNDER DECK. TANK LOST APPROX 150 GALLONS AFTER TEST. FREE PRODUCT IN SUMP PIT IN BASEMENT. FURTHER INVESTIGATION TO BE DONE BY ADVANCED ENVIRONMENTAL. jod 5/1/2008: Advanced Environmental disposed of LUST and 26.15 tons of contaminated soil. Ground water was impacted and sampled. Spill closure report from ECC submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"tank test failed."

All TTF:

Facility ID:	0408510
Spill Number:	0408510
Spill Tank Test:	1548304
Site ID:	333255
Tank Number:	1
Tank Size:	275
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	333255
Operable Unit ID:	1095424
Operable Unit:	01
Material ID:	575563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT312 **CANDREA/GALLETTA RESIDENCE** **NY LTANKS** **S112148789**
WSW **35 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.286 mi.
1512 ft. **Site 1 of 2 in cluster AT**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Name:	CANDREA/GALLETTA RESIDENCE
Address:	35 CHARLES ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1202322 / 2012-09-13
Facility ID:	1202322
Site ID:	465083
Spill Date:	2012-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-06-07
Spill Record Last Update:	2012-09-13
Spiller Name:	Not reported
Spiller Company:	GALETTA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	GALETTA
Spiller Phone:	914-497-9141
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	419452
DEC Memo:	"6-7-12 Kathy already notified owner. Spoke with Anthony, owners son-in-law. Told him to forward passing retest to office for spill to be closed. He asked for email to that affect. I sent. jc 6/18/12- US Tank reports that retest failed. Unknown further action. DT 09/13/12 Castlton Environmental reported that they excavated and removed the tank along with 21.04 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG "
Remarks:	"550 gal ust"

All Materials:

Site ID:	465083
Operable Unit ID:	1215116
Operable Unit:	01
Material ID:	2213205
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

CANDREA/GALLETTA RESIDENCE (Continued) **S112148789**

Units: G
Recovered: Not reported
Oxygenate: Not reported

AN313 **SPILL NUMBER 0007965** **NY LTANKS** **S104782459**
WSW **45 CHARLES ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.289 mi.
1528 ft. **Site 3 of 3 in cluster AN**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Name:	SPILL NUMBER 0007965
Address:	45 CHARLES ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0007965 / 2000-10-26
Facility ID:	0007965
Site ID:	61314
Spill Date:	2000-10-06
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-06
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-06
Spill Record Last Update:	2000-11-07
Spiller Name:	Not reported
Spiller Company:	ALBANO FUEL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ALBANO FUEL
Spiller Phone:	(914) 667-0900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/26/2000 TRI-STATE COMPLETED CLEANUP AFTER DEC INSPECTION. INITIAL SPILL BY ALBANO FUEL WAS NEVER REPORTED. NFA"
Remarks:	"SPILL OCCURRED DURING FILL. TRI STATE WAS CONTRACTED FOR CLEAN UP."

All Materials:

Site ID:	61314
Operable Unit ID:	830442
Operable Unit:	01
Material ID:	545482
Material Code:	0001A
Material Name:	#2 fuel oil

SPILL NUMBER 0007965 (Continued) **S104782459**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU314 **GKIDS REALTY** **NY LTANKS** **S105995601**
SW **10/12 PINE COURT** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.290 mi.
1530 ft. **Site 1 of 4 in cluster AU**

Relative: **Lower**
Actual: **56 ft.**

LTANKS:

Name:	GKIDS REALTY
Address:	10/12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0200337 / 2003-12-09
Facility ID:	0200337
Site ID:	235436
Spill Date:	2002-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-04-10
CID:	204
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-10
Spill Record Last Update:	2003-12-10
Spiller Name:	GKIDS REALTY
Spiller Company:	GKIDS REALTY
Spiller Address:	10/12 PINE COURT
Spiller County:	001
Spiller Contact:	MICHAEL GOLD
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193919
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER #2 PBS 3-504998 handled by WCHD 12/09/03 TANK CLOSED IN PLACE, SAMPLE RESULTS BELOW TAGM. SPILL CLOSED BY WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE - RECOMMEND TO ISOLATE PIPING AND RETEST "

All TTF:

Facility ID:	0200337
Spill Number:	0200337

GKIDS REALTY (Continued) **S105995601**

Spill Tank Test:	1527023
Site ID:	235436
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235436
Operable Unit ID:	851333
Operable Unit:	01
Material ID:	525339
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU315 **RUSH MANUFACTURING CORP** **CORRACTS** **1000201737**
SW **10-12 PINE CT** **RCRA-VSQG** **NYD075436394**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY Spills**
0.290 mi. **FINDS**
1530 ft. **Site 2 of 4 in cluster AU** **ECHO**
RI MANIFEST
Relative: **NJ MANIFEST**
Lower

Actual: **56 ft.**

CORRACTS:

Name:	RUSH MANUFACTURING CORP
Address:	10-12 PINE CT
Address 2:	Not reported
EPA ID:	NYD075436394
Area Name:	SITEWIDE
Corrective Action:	RFA COMPLETED
Actual Date:	19920922
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

Name:	RUSH MANUFACTURING CORP
Address:	10-12 PINE CT
Address 2:	Not reported
EPA ID:	NYD075436394
Area Name:	SITEWIDE

RUSH MANUFACTURING CORP (Continued) **1000201737**

Corrective Action: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date: 19940503
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

RCRA-VSQG:
Date Form Received by Agency: 20070101
Handler Name: RUSH MANUFACTURING CORP
Handler Address: 10-12 PINE CT
Handler City,State,Zip: NEW ROCHELLE, NY 10801
EPA ID: NYD075436394
Contact Name: DENNIS MCNAMARA
Contact Address: PINE CT
Contact City,State,Zip: NEW ROCHELLE, NY 10801
Contact Telephone: 914-636-2700
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R3
Mailing Address: PINE CT
Mailing City,State,Zip: NEW ROCHELLE, NY 10801
Owner Name: RUSH MANUFACTURING CORP
Owner Type: Private
Operator Name: TELEDYNE HYDRA-POWER
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No
Universal Waste Destination Facility: No
Federal Universal Waste: No
Active Site Fed-Reg Treatment Storage and Disposal Facility: Not reported
Active Site Converter Treatment storage and Disposal Facility: Not reported
Active Site State-Reg Treatment Storage and Disposal Facility: Not reported
Active Site State-Reg Handler: ---
Federal Facility Indicator: Not reported
Hazardous Secondary Material Indicator: NN
Sub-Part K Indicator: Not reported
Commercial TSD Indicator: No
Treatment Storage and Disposal Type: Storage

RUSH MANUFACTURING CORP (Continued) **1000201737**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Storage
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	Yes
Corrective Action Priority Ranking:	Low
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

RUSH MANUFACTURING CORP (Continued) **1000201737**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U238
Waste Description: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: TELEDYNE HYDRA-POWER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10-12 PINE COURT
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 914-632-2200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TELEDYNE HYDRA-POWER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10-12 PINE COURT
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 914-632-2200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: RUSH MANUFACTURING CORP

RUSH MANUFACTURING CORP (Continued) **1000201737**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	10-12 PINE CT
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-636-2700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RUSH MANUFACTURING CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	10-12 PINE CT
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-636-2700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19801119
Handler Name:	RUSH MANUFACTURING CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19801231
Handler Name:	RUSH MANUFACTURING CORP
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	RUSH MANUFACTURING CORP
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

RUSH MANUFACTURING CORP (Continued) **1000201737**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: RUSH MANUFACTURING CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970609
Handler Name: RUSH MANUFACTURING CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920225
Handler Name: TELEDYNE HYDRA-POWER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332999
NAICS Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

NAICS Code: 336413
NAICS Description: OTHER AIRCRAFT PARTS AND AUXILIARY EQUIPMENT MANUFACTURING

NAICS Code: 336999
NAICS Description: ALL OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No

RUSH MANUFACTURING CORP (Continued) **1000201737**

Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19890223
Actual Return to Compliance Date:	19890512
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19890427
Enforcement Identifier:	004
Date of Enforcement Action:	19890327
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19880316
Actual Return to Compliance Date:	19881117
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19880816
Enforcement Identifier:	003
Date of Enforcement Action:	19880509
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes

RUSH MANUFACTURING CORP (Continued) **1000201737**

Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19840223
Actual Return to Compliance Date:	19851007
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19850427
Enforcement Identifier:	001
Date of Enforcement Action:	19850327
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19900126
Actual Return to Compliance Date:	19900502
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19900412
Enforcement Identifier:	005
Date of Enforcement Action:	19900312
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19870827
Actual Return to Compliance Date:	19881117
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes

RUSH MANUFACTURING CORP (Continued) **1000201737**

Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19860319
Actual Return to Compliance Date: 19860527
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19860515
Enforcement Identifier: 002
Date of Enforcement Action: 19860415
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19880311
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19890223
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Actual Return to Compliance Date:	19890512
Scheduled Compliance Date:	19890427
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19880316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19881117
Scheduled Compliance Date:	19880816
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19840223
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19851007
Scheduled Compliance Date:	19850427
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19900126
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19900502
Scheduled Compliance Date:	19900412
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19870827
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CEI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19881117
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Former Citation:	Not reported
Evaluation Date:	19860319
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860527
Scheduled Compliance Date:	19860515
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SPILLS:

Name:	COMMERCIAL MACHINE SHOP
Address:	10-12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0804532 / 2008-09-26
Facility ID:	0804532
Facility Type:	ER
DER Facility ID:	350696
Site ID:	401456
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-07-21
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

RUSH MANUFACTURING CORP (Continued) **1000201737**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-21
Spill Record Last Update:	2008-09-26
Spiller Name:	MICHEAL
Spiller Company:	COMMERCIAL MACHINE SHOP
Spiller Address:	10-12 PINE COURT
Spiller Company:	001
Contact Name:	MICHEAL
DEC Memo:	"08/01/08 Conklin Services & Construction submitted a Limited Subsurface Investigation Report. Four geoprobe borings were placed around an abandoned tank. Slight soil contamination exists in borings 1 and 2, however the levels are below DEC TAGM guidance values. NFA TG"
Remarks:	"SOIL BORINGS SHOWED CONTAMINATED SHOP"

All Materials:

Site ID:	401456
Operable Unit ID:	1158245
Operable Unit:	01
Material ID:	2149301
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ALPHA MEDICAL EQUIPMENT OF NY
Address:	10-12 PINE COURT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0901536 / 2009-06-22
Facility ID:	0901536
Facility Type:	ER
DER Facility ID:	350696
Site ID:	413531
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	2009-05-07
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

RUSH MANUFACTURING CORP (Continued) **1000201737**

Remediation Phase:	0
Date Entered In Computer:	2009-05-07
Spill Record Last Update:	2009-06-22
Spiller Name:	Not reported
Spiller Company:	ALPHA MEDICAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NIKI
DEC Memo:	"5/7/09 At a construction site, contaminated soils were encountered, which was confirmed by soil tests done by Northeast. They will be doing the site remediation and will submit a cleanup report. dw 06/12/09 Northeast Environmental provided oversight activity when petroleum impacted soil was discovered and need to be removed. Remediation consisted of the removal of 425.66 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were all below DEC guidance values. NFA required. TG"
Remarks:	"1231 The caller advised dispatch North East Environmental will conduct the clean up. The caller requested a call back. No water ways affected."

All Materials:

Site ID:	413531
Operable Unit ID:	1169955
Operable Unit:	01
Material ID:	2161660
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

FINDS:
Registry ID: 110009468343

Click Here:

Environmental Interest/Information System:

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RUSH MANUFACTURING CORP (Continued) **1000201737**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000201737
Registry ID:	110009468343
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009468343
Name:	RUSH MFG CORP
Address:	10-12 PINE CT
City,State,Zip:	NEW ROCHELLE, NY 10801

RI MANIFEST:

Name:	TELEDYNE
Address:	10-12 PINE CT
City,State,Zip:	NEW ROCHELLE, NY 10801
EPA Id:	NYD075436394
GEN Cert Date:	10/7/1991
Manifest Document Number:	CTC0168898
Waste Description:	OIL
TSDF Id:	CTD021816889
TSDF Name:	UNITED
Qty:	575
WT/Vol Units:	G
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Item Number:	1
Transporter 2 Name:	Not reported
Transporter Name 2:	SEALAND
Transporter EPAID:	CTD983872748
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Quarter:	Not reported
Waste Description:	OIL
Transporter Contact Name:	Not reported
Quantity:	575
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SEALAND
Billing Name:	Not reported
Transporter EPA ID:	CTD983872748
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/7/1991
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F002
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Year:	Not reported
EPA ID:	NYD075436394
Manifest Docket Number:	CTC0168898
Quarter:	Not reported
Waste Description:	OIL
Transporter Contact Name:	Not reported
Quantity:	575
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SEALAND
Billing Name:	Not reported
Transporter EPA ID:	CTD983872748
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/7/1991
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

NJ MANIFEST:

EPA Id:	NYD075436394
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001619722SKS
EPA ID:	NYD075436394
Date Shipped:	02/23/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/26/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	002115978SKS
EPA ID:	NYD075436394
Date Shipped:	10/01/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/01/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	5 G

Manifest Number:	001803673SKS
EPA ID:	NYD075436394
Date Shipped:	05/08/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

Manifest Number:	001811141SKS
EPA ID:	NYD075436394
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 8 G

Manifest Number: 000266181CEX
EPA ID: NYD075436394
Date Shipped: 10/30/2009
TSDF EPA ID: NJD982270506
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/30/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/05/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: H141
Quantity: 9 G

Manifest Number: 002486638SKS
EPA ID: NYD075436394

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date Shipped:	01/29/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/01/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H020
Quantity:	7 G

Manifest Number:	001819324SKS
EPA ID:	NYD075436394
Date Shipped:	07/16/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	8 G

Manifest Number:	001632477SKS
EPA ID:	NYD075436394
Date Shipped:	01/30/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

RUSH MANUFACTURING CORP (Continued) **1000201737**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H141
Quantity:	7 G

AS316 **BRAM REALTY** **NY LTANKS** **S109583709**
West **105 WASHINGTON AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.293 mi.
1548 ft. **Site 2 of 2 in cluster AS**

Relative: **Lower**
Actual: **85 ft.**

LTANKS:

Name:	BRAM REALTY
Address:	105 WASHINGTON AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0902464 / 2010-02-01
Facility ID:	0902464
Site ID:	414506
Spill Date:	2009-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-06-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

BRAM REALTY (Continued) **S109583709**

Date Entered In Computer:	2009-06-01
Spill Record Last Update:	2010-02-01
Spiller Name:	HAL SHAPIRO
Spiller Company:	BRAM REALTY
Spiller Address:	105 WASHINGTON AVE
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	363644
DEC Memo:	"6-1-09: V.Mc.^ Hal/BRAM REALTY: Left Mess: Req.Callbk. to dispt &/or J.O'Dee. 6-3-09: HAL SHAPIRO CALLED AND STATED IS WAS AWARE OF PROPER PROCEDURES TO FOLLOW. HE WILL CONTACT HIS OIL CO. FOR DIRECTION AND NOTIFY DEC OF OUTCOME. 01/25/10 Enviroshield reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was obseved in the tank excavation. NFA TG "
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST UNK IF ANY PRODUCT WAS SPILLED."

All Materials:

Site ID:	414506
Operable Unit ID:	1170891
Operable Unit:	01
Material ID:	2162674
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AT317 **MERLUCCI RESIDENCE** **NY LTANKS** **S111063886**
WSW **30 CHARLES STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.293 mi.
1548 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
92 ft.

LTANKS:

Name:	MERLUCCI RESIDENCE
Address:	30 CHARLES STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1103221 / 2011-11-14
Facility ID:	1103221
Site ID:	450778
Spill Date:	2011-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-22
CID:	Not reported

MERLUCCI RESIDENCE (Continued) **S111063886**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-22
Spill Record Last Update:	2011-11-14
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MR MERLUCCI
Spiller Phone:	(914) 632-2099
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	405335
DEC Memo:	"6/22/11 UST is 62 years old, according to Ms. Merlucci. House is for sale. US Tank Tech has notified Town & Country Oil not evacuate tank prior to further action (repair, retest, tank pull) of owner. dw 11/14/11: UST removed by JM Associates. Report states tank was inspected and no corrosion holes were found. Soil samples taken from tank grave showed minor amounts of contamination, most below CP-51 with a few slight exceedences of SVOCs. Excavation was backfilled. Report will be entered into eDocs. jod"
Remarks:	"repair retest pending or removal"

All Materials:

Site ID:	450778
Operable Unit ID:	1200979
Operable Unit:	01
Material ID:	2197455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AR318 **KGM PROPERTY ASSOC.** **NY LTANKS** **U003647638**
North **394 N. AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.294 mi.
1551 ft. **Site 2 of 5 in cluster AR**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Name:	KGM PROPERTY ASSOC.
Address:	394 N. AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9202033 / 1993-01-27
Facility ID:	9202033
Site ID:	69270
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure

KGM PROPERTY ASSOC. (Continued) **U003647638**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-20
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65872
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK IS 38 YEARS OLD THIS TANK WAS ORIGINAL REPORTED UNDER #9201744 BUT IS LOCATED AT DIFFERENT ADDRESS PETRO-TITE -.422 GPH"

All TTF:

Facility ID:	9202033
Spill Number:	9202033
Spill Tank Test:	1540014
Site ID:	69270
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	69270
Operable Unit ID:	966124
Operable Unit:	01
Material ID:	557154
Material Code:	0001A

KGM PROPERTY ASSOC. (Continued) **U003647638**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AR319 **GETTY# 677** **NY LTANKS** **S103482965**
North **381 NORTH AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.297 mi.
1570 ft. **Site 3 of 5 in cluster AR**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Name:	GETTY# 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0400912 / 2005-01-18
Facility ID:	0400912
Site ID:	242546
Spill Date:	2004-04-27
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-04-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-27
Spill Record Last Update:	2005-01-18
Spiller Name:	STEVEN PHELTS
Spiller Company:	GETTY# 677
Spiller Address:	381 NORTH AVE
Spiller County:	001
Spiller Contact:	STEVEN PHELTS
Spiller Phone:	(518) 786-3200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 1/18/2005 close and handle under existing spill 9003146 "
Remarks:	"FOUND CONTAMINATED SOIL WHILE REMOVING TANK: "

All Materials:

Site ID:	242546
Operable Unit ID:	882894

GETTY# 677 (Continued) **S103482965**

Operable Unit:	01
Material ID:	555170
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GETTY STATION # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1005811 / 2010-08-25
Facility ID:	1005811
Facility Type:	ER
DER Facility ID:	199318
Site ID:	439142
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	D4
SWIS:	6010
Spill Date:	2010-08-25
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-08-25
Spill Record Last Update:	2010-08-25
Spiller Name:	MIKE CARR
Spiller Company:	GETTY
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"8/25/10 Confirmed clean up with caller, nfa...mm"
Remarks:	"Caller stated they had spilt waste oil on concrete, Are has been cleaned up."

All Materials:

Site ID:	439142
Operable Unit ID:	1189791
Operable Unit:	01
Material ID:	2184749
Material Code:	0022
Material Name:	waste oil/used oil

GETTY# 677 (Continued) **S103482965**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	REAR OF GETTY STATION
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9805150 / 1998-07-27
Facility ID:	9805150
Facility Type:	ER
DER Facility ID:	199318
Site ID:	242548
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1998-07-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-24
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-24
Spill Record Last Update:	1998-08-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ORLANDO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 SITE INSPECTED BY J. O'DEE. TYREE IN PROCESS OF INSTALLING A MONITORING WELL AT 381 NORTH AVE., NEW ROCHELLE. IT APPEARS A RESIDENT PARKED CAR OVER STORM DRAIN WHILE CHANGING OIL. THE S/S EMPLOYEES WILL OBSERVE THE AREA AND CONTACT DEC IF ANY ADDITIONAL DUMPING OCCURS. NFA."
Remarks:	"FOUND OIL SPILLED INTO SEWER IN REAR OF GAS STATION"

All Materials:

Site ID:	242548
Operable Unit ID:	1063026
Operable Unit:	01
Material ID:	319903
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum

GETTY# 677 (Continued) **S103482965**

Quantity:	90.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY STATION#677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0503897 / 2006-12-19
Facility ID:	0503897
Facility Type:	ER
DER Facility ID:	199318
Site ID:	348603
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6010
Spill Date:	2005-07-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-07-01
CID:	409
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-01
Spill Record Last Update:	2006-12-19
Spiller Name:	UNKNOWN
Spiller Company:	CUSTOMER TANK OVERFILL
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	""
Remarks:	"1 cup and has been cleaned up."

All Materials:

Site ID:	348603
Operable Unit ID:	1106254
Operable Unit:	01
Material ID:	1971181
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY 677

GETTY# 677 (Continued) **S103482965**

Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1001015 / 2010-04-27
Facility ID:	1001015
Facility Type:	ER
DER Facility ID:	199318
Site ID:	433723
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-04-27
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2010-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-04-27
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-05-10
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/27/10 - Spill cleaned up. NFA. KAB 5/10/10: Update from Denise Heinzinger of WCDOH who inspected: #1001015 small spill onto concrete at 381 North Ave, New Rochelle, clean up performed jod"
Remarks:	"1 pint onto concrete. Clean up complete"

All Materials:

Site ID:	433723
Operable Unit ID:	1184583
Operable Unit:	01
Material ID:	2178854
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GETTY # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0912229 / 2010-02-23
Facility ID:	0912229
Facility Type:	ER

GETTY# 677 (Continued) **S103482965**

DER Facility ID:	199318
Site ID:	425106
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6010
Spill Date:	2010-02-23
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2010-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-02-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-23
Spill Record Last Update:	2010-03-30
Spiller Name:	MIKE CARR
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"2/23/10 confirmed clean up, nfa...mm"
Remarks:	"HALF GALLON OF WASTE OIL TO CONCRETE CLEAN UP WAS DONE."

All Materials:

Site ID:	425106
Operable Unit ID:	1180837
Operable Unit:	01
Material ID:	2174836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GETTY # 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0900607 / 2009-04-16
Facility ID:	0900607
Facility Type:	ER
DER Facility ID:	199318
Site ID:	412555
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-04-16

GETTY# 677 (Continued) **S103482965**

Investigator:	RXAMATO
Referred To:	Not reported
Reported to Dept:	2009-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-16
Spill Record Last Update:	2009-04-16
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	"4/17/09: Vac truck pumped out dispenser sump...close/nfa..ra"
Remarks:	"DUE TO POOR HOUSEKEEPING A HALF GALLON OF PRODUCT WAS SPILLED TO CONRETE BAY FLOORS. CLEAN UP WAS DONE."

All Materials:

Site ID:	412555
Operable Unit ID:	1169019
Operable Unit:	01
Material ID:	2160665
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	.50
Oxygenate:	Not reported

Name:	GETTY 677
Address:	381 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1012947 / 2011-03-31
Facility ID:	1012947
Facility Type:	ER
DER Facility ID:	401849
Site ID:	447247
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6038
Spill Date:	2011-03-29
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2011-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

GETTY# 677 (Continued) **S103482965**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-29
Spill Record Last Update:	2011-03-31
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 677
Spiller Address:	381 NORTH AVE
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"3-29-11 Called and left message for Mike to return call to dispatch desk. jm 3-31-11 Spoke with Mike. Spill was as stated and cleanup completed. jm"
Remarks:	"contained to bay floor, clean up"

All Materials:

Site ID:	447247
Operable Unit ID:	1197384
Operable Unit:	01
Material ID:	2193703
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AR320 **KGM REALTY CO.** **NY LTANKS** **S100493525**
North **396 NORTH AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.300 mi.
1582 ft. **Site 4 of 5 in cluster AR**

Relative: **Lower**
Actual: **72 ft.**

LTANKS:

Name:	KGM REALTY CO.
Address:	396 NORTH AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9201744 / 1993-01-27
Facility ID:	9201744
Site ID:	89642
Spill Date:	1992-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1993-01-27
SWIS:	6010
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported
Water Affected:	Not reported

KGM REALTY CO. (Continued) **S100493525**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-13
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TANK #1 IS 64 YEARS OLD AND TANK #2 IS 38 YEARS OLD WILL EIR TANK #2 NEXT WEEK"

All TTF:

Facility ID:	9201744
Spill Number:	9201744
Spill Tank Test:	1539987
Site ID:	89642
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	89642
Operable Unit ID:	969160
Operable Unit:	01
Material ID:	413039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AQ321 **APT. BUILDING** **NY LTANKS** **S102660713**
ESE **55-59 LOCUST AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.300 mi.
1582 ft. **Site 3 of 6 in cluster AQ**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	APT. BUILDING
Address:	55-59 LOCUST AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9200639 / 1992-06-26
Facility ID:	9200639
Site ID:	168647
Spill Date:	1992-04-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-05-12
SWIS:	6010
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1992-05-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	1998-01-14
Spiller Name:	Not reported
Spiller Company:	N.Y. PROPERTIES CO.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142042
DEC Memo:	""
Remarks:	"TWO UC TANKS WERE BURIED RAIN FORCES OIL UP THROUGH BLACKTOP MGNT. CO.APPLIES SPEEDI-DRY BUT DOES NOT REPORT OR REPAIR"

All Materials:

Site ID:	168647
Operable Unit ID:	964508
Operable Unit:	01
Material ID:	415419
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AO322 **BLESSED SACRAMENT HS** **NY LTANKS** **S113494296**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.304 mi.
1607 ft. **Site 2 of 3 in cluster AO**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Name:	BLESSED SACRAMENT HS
Address:	24 SHEA PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1300960 / Not Reported
Facility ID:	1300960
Site ID:	481320
Spill Date:	2013-04-29
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-04-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2013-04-29
Spill Record Last Update:	2017-11-16
Spiller Name:	ED SULLIVAN
Spiller Company:	HIGH SCHOOL
Spiller Address:	24 SHEA PLACE
Spiller County:	999
Spiller Contact:	ED SULLIVAN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"This is a 1K ust. Testing done every year. Appears to be a piping problem, will uncover, repair and retest. WCDOH has been notified....mm 8/5/13 Failed retest. Spoke to Kathy Morgan at US Tank Test. dw 11-16-2017 A consultant called-in to say they will submit a closure report today. BTR"
Remarks:	"tank test failure"

All TTF:

Facility ID:	1300960
Spill Number:	1300960
Spill Tank Test:	2493383
Site ID:	481320
Tank Number:	0
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00

BLESSED SACRAMENT HS (Continued) **S113494296**

Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2229789
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	481320
Operable Unit ID:	1231094
Operable Unit:	01
Material ID:	2230143
Material Code:	0001
Material Name:	#2 fuel oil (on-site consumption)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AO323 **BLESSED SACRAMENT HIGH SC** **NY LTANKS** **S106385926**
South **24 SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.305 mi.
1609 ft. **Site 3 of 3 in cluster AO**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Name:	BLESSED SACRAMENT HIGH SC
Address:	24 SHEA PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0400709 / 2004-07-06
Facility ID:	0400709
Site ID:	249284
Spill Date:	2004-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-04-21

BLESSED SACRAMENT HIGH SC (Continued) **S106385926**

CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-21
Spill Record Last Update:	2004-07-06
Spiller Name:	LARRY HANSEN
Spiller Company:	BLESSED SACRAMENT HIGH SC
Spiller Address:	24 SHEA PLACE
Spiller County:	001
Spiller Contact:	LARRY HANSEN
Spiller Phone:	(914) 632-2595
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	204413
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 07/06/04 TANK PASSED RETEST."
Remarks:	"FAILED SUBLINGS RECOMMEND UNCOVER REPAIR & RETEST OR REMOVE: "

All TTF:

Facility ID:	0400709
Spill Number:	0400709
Spill Tank Test:	1529181
Site ID:	249284
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	249284
Operable Unit ID:	884909
Operable Unit:	01
Material ID:	491955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV324 **BLESSED SACRAMENT CHURCH** **NY LTANKS** **S100165619**
SSE **SHEA PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.307 mi.
1623 ft. **Site 1 of 3 in cluster AV**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Name:	BLESSED SACRAMENT CHURCH
Address:	SHEA PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8704259 / 1987-11-20
Facility ID:	8704259
Site ID:	324974
Spill Date:	1987-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-11-20
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-08-02
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-30
Spill Record Last Update:	1987-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261780
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST. / / : 8/2/87-CHURCH TO EXCAVATE,ISOLATE AND RETEST RETEST PASSED.NFA. "
Remarks:	"TTTF-TWO TANKS FAILED"

All TTF:

Facility ID:	8704259
Spill Number:	8704259
Spill Tank Test:	1531452
Site ID:	324974
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

BLESSED SACRAMENT CHURCH (Continued) **S100165619**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	324974
Operable Unit ID:	908133
Operable Unit:	01
Material ID:	466902
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW325 **PROFESSIONAL OFFICE CORP** **NY LTANKS** **S108982494**
SSW **421 HUGUENOT STREET** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.310 mi.
1637 ft. **Site 1 of 2 in cluster AW**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Name:	PROFESSIONAL OFFICE CORP
Address:	421 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606014 / 2007-01-29
Facility ID:	0606014
Site ID:	369299
Spill Date:	2006-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-08-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-24
Spill Record Last Update:	2007-01-29
Spiller Name:	GERRI SEENY
Spiller Company:	PROFESSIONAL OFFICE CORP
Spiller Address:	421 HUGUENOT STREET
Spiller County:	001
Spiller Contact:	GERRI SEENY

PROFESSIONAL OFFICE CORP (Continued) **S108982494**

Spiller Phone:	(914) 632-3400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	319185
DEC Memo:	"RECOMMENDING ISOLATION. 0606014 - 421 Huguenot St, New Rochelle - removed petrometer and remote fill from system and retested, passed. NFA. 10/23/06 test date"
Remarks:	""

All TTF:

Facility ID:	0606014
Spill Number:	0606014
Spill Tank Test:	1550220
Site ID:	369299
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	369299
Operable Unit ID:	1127138
Operable Unit:	01
Material ID:	2116724
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	PROFESSIONAL BUILDING COP
Address:	421 HUGUENOT STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0711337 / 2008-06-24
Facility ID:	0711337
Facility Type:	ER
DER Facility ID:	319185
Site ID:	392804
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-01-28

PROFESSIONAL OFFICE CORP (Continued) **S108982494**

Investigator:	WCHD
Referred To:	SCHNEIDER
Reported to Dept:	2008-01-28
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2008-06-24
Spiller Name:	GERRY
Spiller Company:	PROFESSIONAL BUILDING COP
Spiller Address:	421 HUGUENOT STREET
Spiller Company:	001
Contact Name:	GERRY
DEC Memo:	"Spoke to Gerry. Danielle Jackson of WCHD may be handling. WCHD to inspect today. 06/24/08 Wayne Schneider WCHD reported 421 Huguenot St, New Rochelle - leaking tank. Contaminated soil remediated. See attached NFA TG "
Remarks:	"HOLES AND CONTAMINATED SOIL"

All TTF:

Facility ID:	0711337
Spill Number:	0711337
Spill Tank Test:	2384563
Site ID:	392804
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	392804
Operable Unit ID:	1149789
Operable Unit:	01
Material ID:	2140347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

PROFESSIONAL OFFICE CORP (Continued) **S108982494**

Oxygenate: Not reported

326
West
1/4-1/2
0.310 mi.
1639 ft.

FRANKA INC. **NY LTANKS** **S104276153**
132-143 UNION AVE. **N/A**
NEW ROCHELLE, NY

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	FRANKA INC.
Address:	132-143 UNION AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9312205 / 1995-11-09
Facility ID:	9312205
Site ID:	176106
Spill Date:	1994-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-11-09
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1995-11-08
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-24
Spill Record Last Update:	1995-11-27
Spiller Name:	Not reported
Spiller Company:	REGENT OIL CO.
Spiller Address:	53 CHARLES STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148008
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/08/95 FINAL INSPECTION PERFORMED TRENCH IS OIL FREE SUMP PIT IS OIL FREE BASEMENT IS FREE OF PETROLEUM NO OIL STAIN ON SIDEWALK"
Remarks:	"1K TANK UNDERGROUND POSSIBLE LEAK CLEAN UP CREW ENROUTE"

All Materials:

Site ID:	176106
Operable Unit ID:	994225
Operable Unit:	01
Material ID:	391197
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

FRANKA INC. (Continued) **S104276153**

Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV327 **FAILED TANK TEST** **NY LTANKS** **S114561821**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.312 mi.
1646 ft. **Site 2 of 3 in cluster AV**

Relative: **Lower**
Actual: **89 ft.**

LTANKS:

Name:	FAILED TANK TEST
Address:	156 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1308221 / 2019-08-14
Facility ID:	1308221
Site ID:	488939
Spill Date:	2013-11-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2013-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-11-12
Spill Record Last Update:	2019-08-14
Spiller Name:	WILLIE
Spiller Company:	FAILED TANK TEST
Spiller Address:	156 CENTRE AVE
Spiller County:	999
Spiller Contact:	WILLIE
Spiller Phone:	(914) 774-2508
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	"11/12/13: Residential tank test failure. No indication of a release at this time. Message sent to Elite requesting additional information on the owner, or their realtor. jod 11/12/13: Update received from Chris Lalak. This is not a residential tank. This is a 10K #4 Oil tank, PBS 3-600412. Wayne Schneider will follow up on retest. jod 11-13-18 new management co looking for closure; submitted test from 2013- RDB 11-13-18 I asked WCHD for information. RDB 11-15-18 I requested annual tightness tests, they are not able to provide; RDB 11-19-18 I asked when tank will be removed. RDB 11-19-18 email from WCHD- No work permit application has come in. RDB 1/23/19: I spoke to

FAILED TANK TEST (Continued) **S114561821**

Ray Hilyer at Elite Environmental. Timeline of events: *Nov 2013 tank fails tightness test performed by Elite, Spill 1308221 reported. *2016 Elite is called back to the site to retest. The parking lot or the tank had been patched, another company had excavated and repiped the UST. Tank is retested and passes. Test results sent to WCDOH. *2017 Tank is retested and passes. *Nov 2018 a new owner (management company) Librett Real Estate Group becomes involved with refinancing the property. In order to refinance the open Spill 1308221 needs to be addressed. Elite Environmental is contacted to remove the 10k gallon UST. *Dec2018 the UST is removed, soil contamination is extensive. Spill 180 Elite reports the contamination appears to be older and weathered #4 oil. To date they have excavated approximately 300 tons. jod 8/14/19: The cleanup has been completed by Elite. Closure report for the site was submitted to the Westchester Health Dept. See Spill 1809754 for further information and a scanned copy of the TCR. NFA this spill case number. jod"

Remarks: "Tank test failure"

All TTF:

Facility ID:	1308221
Spill Number:	1308221
Spill Tank Test:	2494704
Site ID:	488939
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	488939
Operable Unit ID:	1238546
Operable Unit:	01
Material ID:	2238468
Material Code:	9999
Material Name:	other - failed tank test
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AV328 **APARTMENT HOUSE** **NY LTANKS** **S106385339**
SSE **156 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.312 mi.
1646 ft. **Site 3 of 3 in cluster AV**

Relative:
Lower

Actual:
89 ft.

LTANKS:

Name:	APARTMENT HOUSE
Address:	156 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0312650 / 2004-04-22
Facility ID:	0312650
Site ID:	267104
Spill Date:	2004-02-13
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	2004-02-13
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-13
Spill Record Last Update:	2019-01-02
Spiller Name:	JIM DONELAN
Spiller Company:	PROTEST
Spiller Address:	PO BOX 1937
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 698-4100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	444002
DEC Memo:	" 04/22/04 TANK PASSED A RETEST ON 3-22-04. NFA jod"
Remarks:	"Failed tank test"

All TTF:

Facility ID:	0312650
Spill Number:	0312650
Spill Tank Test:	1528979
Site ID:	267104
Tank Number:	1
Tank Size:	10000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

APARTMENT HOUSE (Continued) **S106385339**

Modified By: Spills
Last Modified Date: Not reported

AP329 **APT. BUILDING** **NY LTANKS** **S102241692**
South **47 MAPLE AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.312 mi.
1650 ft. **Site 2 of 2 in cluster AP**

Relative:
Lower

Actual:
88 ft.

LTANKS:

Name:	A D VANDROFF
Address:	47 MAPLE AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9603128 / 1996-06-14
Facility ID:	9603128
Site ID:	178537
Spill Date:	1996-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-05
Spill Record Last Update:	1996-09-04
Spiller Name:	A D VANDROFF
Spiller Company:	A D VANDROFF
Spiller Address:	47 MAPLE AVENUE
Spiller County:	001
Spiller Contact:	A D VANDROFF
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/14/96 SEE SPILL # 9603064"
Remarks:	"gross failure of tank."

SPILLS:

Name:	APT. BUILDING
Address:	47 MAPLE AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9603064 / 1996-08-12
Facility ID:	9603064
Facility Type:	ER
DER Facility ID:	248269

APT. BUILDING (Continued) **S102241692**

Site ID:	307417
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1996-06-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-06-04
CID:	349
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1996-06-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-04
Spill Record Last Update:	1996-10-21
Spiller Name:	OWNER - ARTHUR DANDROFF
Spiller Company:	Not reported
Spiller Address:	47 MAPLE AV
Spiller Company:	001
Contact Name:	OWNER - ARTHUR DANDROFF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/04/96 WCHD TO INSPECT 06/14/96 SEE SPILL # 9603128 08/12/96 CONTENTS GONE IN FOUR DAYS AFTER FILL UP TANK REMOVED LINES TESTED NO LEAKS FOUND FROM TESTS SMALL HOLES FOUND IN TANKS VERY MINIMAL CONTAMINATION "
Remarks:	"APARTMENT BLDG - SUPERINTENDENT MRS CHURCHILL 914-636-4142 - RECIEVED 900 GALLONS ON THURSDAY - NOW ITS IS EMPTY - CHECK OF AREA INCLUDING SEWERS NO ODOR - FD ON SCENE - WILL BE TESTING W/WATER - TEMP. TANK TO BE PUT IN"

All Materials:

Site ID:	307417
Operable Unit ID:	1030609
Operable Unit:	01
Material ID:	349302
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR330 **DIPASQUALE PROPERTY** **NY LTANKS** **S111063882**
North **400 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.316 mi.
1671 ft. **Site 5 of 5 in cluster AR**

Relative: LTANKS:
Lower

Actual:
70 ft.

Name:	DIPASQUALE PROPERTY
Address:	400 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1103122 / 2012-04-26
Facility ID:	1103122
Site ID:	450672
Spill Date:	2011-06-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-06-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-20
Spill Record Last Update:	2012-04-26
Spiller Name:	MR CHARLIE DIPASQUALE
Spiller Company:	NDR GROUP
Spiller Address:	400 NORTH AVE
Spiller County:	999
Spiller Contact:	MR DIPASQUALE
Spiller Phone:	(914) 633-7092
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	404310
DEC Memo:	"6/20/11: This spill initially reported as a residential TTF. Property is actually a commercial office building with apartments on the second floor. Previous Spill number for this site is 1102214 which was reported on May 27th. Owner informed US Tank Tech of the prior Phase I site investigation, but apparently did not inform them of the Phase II which found high levels of contamination. US Tank Tech reports they were hired to test the in-service 550 gallon heating oil tank, and perform a site investigation to locate a second, out-of-service tank. The 550 failed the vaccuum test, petroleum odors evident in the well point. US Tank Tech also reports they believe the second out-of-service tank may be located under the office building. Owner states the second tank is a 275 gallon heating oil, but that can not be confirmed at this time. US Tank Tech also reports there are at least two additional sets of fill and vent pipes, for other out-of-service or abandoned USTs. Tester also noted petroleum odors from the basement sump pit. jod 6/21/11: US Tank Tech reported that the owner says he hired Northeast Environmental to address these two spills issues. Message sent to Northeast asking for

DIPASQUALE PROPERTY (Continued) **S111063882**

confirmation. jod 9/29/11: Northeast reports the owner has hired them to begin investigation and remediation. jod 10/21/11: The UST has been removed by Northeast and contaminated soil is evident. Remediation work is being scheduled. jod 4/26/2012: Closure report from Northeast Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"

Remarks: "repair/retest pending"

All Materials:

Site ID:	450672
Operable Unit ID:	1200876
Operable Unit:	01
Material ID:	2197327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AQ331 **SPILL NUMBER 0105779** **NY LTANKS** **S105140483**
ESE **60-70 LOCUST AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1679 ft. **Site 4 of 6 in cluster AQ**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	60-70 OWNERS CORP
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1802312 / 2018-10-17
Facility ID:	1802312
Site ID:	570894
Spill Date:	2018-05-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2018-05-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-05-29
Spill Record Last Update:	2018-11-08
Spiller Name:	NANETTE GIORDANO
Spiller Company:	60-70 OWNERS CORP
Spiller Address:	ARCHER PROPERTY MANAGEMENT

SPILL NUMBER 0105779 (Continued) **S105140483**

Spiller County:	001
Spiller Contact:	NANETTE GIORDANO
Spiller Phone:	914-315-6105
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"5/29/18 Property has 2 8000 gallon UST, not in use. Both tanks had been for #6 fuel oil, were cleaned out, Tank 1 (in building #70) was filled with #2 oil, Tank 2 was left empty (in building #60). Tank 2 now has 28 inches of water in it. Northeast Environmental has been called and will be on site tomorrow. Property has converted to gas. It's an apartment building. ga 6/12/18 received call from Nanette, indicating that she was waiting for board approval to remove one of the tanks. Tank #1 is being repaired and retested, Tank #2 is being removed. BW 7/17/18 - G C Engineering will be submitted tank removal notification to the WCDOH and DEC. A TCR will be submitted to both the WCDOH and DEC. KAB 7-23-18 G C sent email to Carlos and cc'd me. It talks about their plans with remediation. Forwarded to KB. jc 08-09-18 Site visit during soil remediation. Approx. 120 cu. yards removed from the site. There is fuel oil contamination about 12 feet down. G.C. Environmental claimed they excavated to bed rock but the recent heavy rain washed soil back in. They were dewatering at the time to continue excavating. BTR 10/17/18 - G.C. Environmental, Inc. conduct conducted removal liquid and sludge, two 8K USTs, contaminated soils and collected soil samples. A vac truck used to remove 8,772 gal. liquid waste and sludge from the tanks and was disposed at Clean Water Of New York, Inc., NY. 884.7 tons of contaminated soils was removed and disposed at Clean Earth of Carteret, NJ. One excavation was generated to remove the two 8K USTs. 23 sidewalls and bottom soil samples were collected and laboratory analyzed. 13 soil sample results showed VOCs and SVOCs in the low ppb range, well below the NYS soil guidelines. There are no significant impacts from the tank. NFA. KAB"
Remarks:	"tank test failure"

All Materials:

Site ID:	570894
Operable Unit ID:	1318738
Operable Unit:	01
Material ID:	2326671
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 0105779
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0105779 / 2002-11-08
Facility ID:	0105779
Facility Type:	ER

SPILL NUMBER 0105779 (Continued) **S105140483**

DER Facility ID:	142314
Site ID:	168987
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C6
SWIS:	6010
Spill Date:	2001-08-27
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-08-29
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-29
Spill Record Last Update:	2003-02-25
Spiller Name:	FREDERICK BECK
Spiller Company:	Not reported
Spiller Address:	60-70 LOCUST AVE
Spiller Company:	001
Contact Name:	FREDERICK BECK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 08/29/2001 WCDOH ON SITE."
Remarks:	"info to caller that there is a pit at the location filled w/oil and w/heavy rain it overflows onto street"

All Materials:

Site ID:	168987
Operable Unit ID:	844138
Operable Unit:	01
Material ID:	530670
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	60-70 OWNERS CORP
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0900729 / 2009-07-24
Facility ID:	0900729
Facility Type:	ER
DER Facility ID:	142314
Site ID:	412683
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3

SPILL NUMBER 0105779 (Continued) **S105140483**

SWIS:	6010
Spill Date:	2009-04-20
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-20
Spill Record Last Update:	2009-07-24
Spiller Name:	AILEEN DEMARIA
Spiller Company:	ARCHER PROPERTY MANAGEMENT
Spiller Address:	60-70 LOCUST AVE
Spiller Company:	999
Contact Name:	NIKKI RICKETTES
DEC Memo:	"NE ENV. CLEANING UP. REPORT TO BE SUBMITTED. DT 07/22/09 Northeast Environmental reported that they excavated and removed and replaced the removed fill lines. a total of 35.80 tons of petroleum impacted soil was excavated and disposed. NFA TG"
Remarks:	"WHILE REPLACING THE REMOTE FILL LINES, PRODUCT WAS FOUND IN SOIL. CLEAN UP IS IN PROGRESS."

All Materials:

Site ID:	412683
Operable Unit ID:	1169142
Operable Unit:	01
Material ID:	2160789
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	412683
Operable Unit ID:	1169142
Operable Unit:	01
Material ID:	2160788
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AQ332 **APARTMENT BUILDING** **NY LTANKS** **S118707739**
ESE **60-70 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1679 ft. **Site 5 of 6 in cluster AQ**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	APARTMENT BUILDING
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1602555 / 2018-06-26
Facility ID:	1602555
Site ID:	528964
Spill Date:	2016-06-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2016-06-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-06-13
Spill Record Last Update:	2018-06-26
Spiller Name:	ROB HILL
Spiller Company:	Apartment
Spiller Address:	60-70 LOCUST AVE
Spiller County:	999
Spiller Contact:	ROB HILL
Spiller Phone:	(718) 855-7272
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"6/13/16 - To be handle by the Westchester County DOH under PBS. KAB Email from Chris Lalak: Keith, TTF at a PBS SITE. 60-70 Locust 3-413925 8k #6 oil tank UST from 1954 Chris 6/26/18: As per Chris Lalak, of WCDoH: I see notes in our log. It was a Wayne Schneider and Carlos Torres spill case. And it was sent to close in 2016 . This UST currently being removed by Northeast Environmental. See Spill 1803271 for further info. NFA this spill number. jod"
Remarks:	"8,000 gallon tank failed tank test."

All Materials:

Site ID:	528964
Operable Unit ID:	1277806
Operable Unit:	01
Material ID:	2282672
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

APARTMENT BUILDING (Continued) **S118707739**

Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AQ333 **COMMERCIAL USTS** **NY LTANKS** **S122481715**
ESE **60-70 LOCUST AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.318 mi.
1679 ft. **Site 6 of 6 in cluster AQ**

Relative: **Lower**
Actual: **89 ft.**

LTANKS:

Name:	COMMERCIAL USTS
Address:	60-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1803271 / 2018-12-06
Facility ID:	1803271
Site ID:	571898
Spill Date:	2018-06-25
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2018-06-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-06-25
Spill Record Last Update:	2018-12-06
Spiller Name:	Not reported
Spiller Company:	NANETTE DIORDANO
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NANETTE DIORDANO
Spiller Phone:	(914) 315-6105
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	142314
DEC Memo:	"6/25/18 spoke with Cathy Morgan of US Tank. At the end of May they tested Tank #170 and Tank #260, both 8K #2 fuel oil USTs, and both failed. Tank #260 was planned on being removed and Tank #170 was being retested. Tank #170 failed the retest today. Northeast Environmental is completing the repairs and removal of the tanks, BW 6/26/18: Update from Chris Lalak at WCDoH: Isolation test failed. Facility asked to empty the tank immediately. NEE is already on the job. 8000 UST with about 2000 gallon in it. The facility is currently using Natural gas for Heat/hotwater. Second 8k (out of service) on site to be removed by NEE. Property mgmt Nanette Giordano Archer Mgmt 914-315-6105 jod 12/06/18: Closure report for this site was submitted under Spill 1802312. Remediation has been completed, no further

COMMERCIAL USTS (Continued) **S122481715**

action is required at this time. jod"
Remarks: "8000 gallons pbs #3-413925 tank test failure"

All Materials:
Site ID: 571898
Operable Unit ID: 1319717
Operable Unit: 01
Material ID: 2327762
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AU334 **INDUSTRIAL OVERALL SERVICES FORMERLY** **RCRA-LQG** **1004571492**
SW **30 PINE ST** **NY SHWS** **NYD986925808**
1/4-1/2 **NEW ROCHELLE, NY 10805** **NY Spills**
0.319 mi. **FINDS**
1686 ft. **Site 3 of 4 in cluster AU** **ECHO**
NY MANIFEST
Relative: **NJ MANIFEST**
Lower **NY SPDES**

Actual:
49 ft.

RCRA-LQG:
Date Form Received by Agency: 20120627
Handler Name: INDUSTRIAL OVERALL SERVICES FORMERLY
Handler Address: 30 PINE ST
Handler City,State,Zip: NEW ROCHELLE, NY 10805
EPA ID: NYD986925808
Contact Name: BURT DORFMAN
Contact Address: BARTELS AVE
Contact City,State,Zip: NEW ROCHELLE, NY 10801
Contact Telephone: 845-353-3500
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: EQUIRE
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R3
Mailing Address: PINE ST
Mailing City,State,Zip: NEW ROCHELLE, NY 10805
Owner Name: INDUSTRIAL OVERALL SERVICE CORP
Owner Type: Private
Operator Name: NYS DEPT ENVIRONMENTAL CONSERVATION
Operator Type: State
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210929
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BAKERS PRIDE OVEN CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	30 PINE ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10810
Owner/Operator Telephone:	914-576-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BAKERS PRIDE OVEN
Legal Status:	Private
Date Became Current:	19770630
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BAKERS PRIDE OVEN CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	30 PINE ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10810
Owner/Operator Telephone:	914-576-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	INDUSTRIAL OVERALL SERVICE CORP
Legal Status:	Private
Date Became Current:	20100801
Date Ended Current:	Not reported
Owner/Operator Address:	10 BARTELS AVE
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	845-353-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYS DEPT ENVIRONMENTAL CONSERVATION
Legal Status:	State
Date Became Current:	20111213
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BAKERS PRIDE OVEN
Legal Status:	Private
Date Became Current:	19770630
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BAKERS PRIDE OVEN CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	30 PINE ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10810
Owner/Operator Telephone:	914-576-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	BAKERS PRIDE OVEN CO INC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BAKERS PRIDE OVEN CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940512
Handler Name: BAKERS PRIDE OVEN CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081216
Handler Name: BAKERS PRIDE OVEN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120627
Handler Name: INDUSTRIAL OVERALL SERVICES FORMERLY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

List of NAICS Codes and Descriptions:
NAICS Code: 333318
NAICS Description: OTHER COMMERCIAL AND SERVICE INDUSTRY MACHINERY MANUFACTURING

NAICS Code: 333319
NAICS Description: OTHER COMMERCIAL AND SERVICE INDUSTRY MACHINERY MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20120614
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2STP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

SHWS:
Name: BAKER'S PRIDE OVEN
Address: 30 PINE STREET
City,State,Zip: NEW ROCHELLE, NY 10801
Program: HW
Site Code: 355304
Classification: N
Region: 3
Acres: 3.750
HW Code: 360087
Record Add: 11/08/2005
Record Upd: 07/21/2009
Updated By: RXKEATIN
Site Description: "The Baker?s Pride site is located at 30 Pine Street in the City of New Rochelle, Westchester County, NY. The surrounding area is urban with commercial and residential establishments mixed in between the commercial businesses. The Baker?s Pride site is an approximately 3.75 acre flat to severely sloping irregularly shaped parcel. The Baker?s Pride building occupies approximately 111,450 sf of building space and occupies the majority of the property. Baker?s Pride owns the Bakers Pride Oven Company Inc and is engaged in the production of restaurant/commercial grade ovens and broilers. The site is bordered by Metro North railroad tracks to the west and northwest, a mix of commercial and residential properties to the northeast, east, and south. Interstate (I-95) is located to the west of the Metro North railroad tracks. In 2005, a Phase II Environmental Assessment report was completed by Enercon as part of closure proceedings for a 3,000 gallon fuel oil UST that was closed in place and a 10,000 gallon fuel oil UST that was removed. Monitoring wells installed as part of this assessment revealed the presence of PCE in groundwater at levels up to 1,430 ppb. (The State groundwater standard for PCE is 5 ppb.) Also, this report noted chemical storage for cutting oils, lubricants, solvents and paints. No products were indicated that contained PCE. In 2007 a follow up report was conducted which revealed PCE in groundwater at levels up to 1,700 ppb. The site was added as a potential inactive hazardous waste disposal site ("P site") in 2007. A State funded site characterization was initiated in 2008 to determine the source of the PCE groundwater plume. A total of 9 monitoring wells were installed in the fall of 2008. Groundwater contaminated with PCE showed higher levels of PCE in wells upgradient from the Baker?s Pride facility. The PCE concentrations were as high as 3,700 ppb in MW-13 which is located about 300 feet upgradient from the Baker?s Pride facility. This prompted the State to do a second round of groundwater sampling further upgradient of MW-13. Two additional wells (MW-24 and MW-25) were installed about 150 feet upgradient of MW-13 in the winter of 2009. MW-24 revealed PCE at 5,300 ppb. The second round of sampling further defined a groundwater plume with a source area upgradient from the Bakers Pride site. Since the site information for Baker?s Pride indicates that the plume of PCE is coming from an off-site source, the Baker?s Pride site (360087) will not be listed in the Registry of Inactive Hazardous Waste Disposal sites. A separate site

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

	was added to the Registry to address the source of the PCE plume (See site #360109.)"
Env Problem:	"Based upon investigations to date, the primary contaminants of concern at the site include tetrachloroetylene (PCE) and its associated breakdown products. PCE was detected in upgradient groundwater as well as on-site and also in indoor air in residences upgradient of the site. PCE was detected on-site in groundwater from non-detect up to 3,200 parts per billion (ppb) at MW-1) above the respective groundwater standard of 5 ppb. Upgradient off-site levels of PCE were as high as 5,300 ppb. Indoor air was impacted in two residences with the highest level being 530 micrograms per cubic meter (ug/m3) at a property on Bartels Place. Since the highest levels of PCE were identified in the groundwater upgradient of the site this suggests an off-site source that is impacting the Baker?s Pride site. The source of this contamination is the Industrial Overall Service Corp. Class 2 site (#360109)"
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	BAKERS PRIDE OVEN CO
Address:	30 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9404759 / 2003-10-08
Facility ID:	9404759
Facility Type:	ER
DER Facility ID:	122872
Site ID:	144128

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	1994-07-07
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1994-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-11
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 10/17/03: Letter to Mark Fogarty, Baker's Pride from Danielle Jackson, dated 10/8/2003. Closure report by Env. Products & Services and sample results have been reviewed. While there is some contamination remaining, WCDOH does not see the contamination as a risk to human health. WCDOH recommends NFA at this time."
Remarks:	"SOIL STOCKPILED BOB SPERONI WAS ON SITE FAXED TO TARRYTOWN & WCHD"

All Materials:

Site ID:	144128
Operable Unit ID:	1001834
Operable Unit:	01
Material ID:	381361
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110002092949

Click Here:

Environmental Interest/Information System:

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

these facilities release directly to air, water, land, or that are transported off-site.
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004571492
Registry ID:	110002092949
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002092949
Name:	BAKERS PRIDE OVEN CO INC
Address:	30 PINE ST.
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	INDUSTIRAL OVERALL UNIFORM
Address:	30 PINE ST
City,State,Zip:	NEW ROCHELLE, NY 10805
Country:	USA
EPA ID:	NYD986925808
Facility Status:	Not reported
Location Address 1:	30 PINE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986925808
Mailing Name:	INDUSTIRAL OVERALL UNIFORM
Mailing Contact:	IRA NEVIN
Mailing Address 1:	30 PINE ST
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5184029564

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/28/2012
Trans1 Recv Date:	12/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986925808
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	008923493JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1800
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD986925808
Mail Address:	30 PINE ST
Mail City/State/Zip:	NEW ROCHELLE 10801
Facility Phone:	9145760200
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008921150JJK
EPA ID:	NYD986925808
Date Shipped:	7/2/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,815.00 gallons
Manifest Year:	Not reported
Waste Code:	F001 F002

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Hand Code:	Not reported
Quantity:	1,200.00 Pounds

Manifest Number:	008923493JJK
EPA ID:	NYD986925808
Date Shipped:	12/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	1,800.00 Pounds

Manifest Number:	008923039JJK
EPA ID:	NYD986925808
Date Shipped:	7/31/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F001 F002
Hand Code:	Not reported
Quantity:	150.00 Pounds

Manifest Number:	NJA4033255
EPA ID:	NYD986925808
Date Shipped:	04/02/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/02/2004
Date Trans2 Transported Waste:	Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030425
Was Load Rejected:	NEW ROCHELLE 10801
Reason Load Was Rejected:	Not reported

SPDES:

Name:	BAKERS PRIDE OVEN CO INC
Address:	30 PINE ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Permit Number:	NYR00C219
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported

INDUSTRIAL OVERALL SERVICES FORMERLY (Continued) **1004571492**

Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

---

335 **SPILL 0106072 / PBS 3-800919** **NY LTANKS** **S105135128**
ENE **370 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.325 mi.
1717 ft.

Relative: **Lower**

Actual: **57 ft.**

LTANKS:

Name:	SPILL 0106072 / PBS 3-800919
Address:	370 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0106072 / 2001-11-13
Facility ID:	0106072
Site ID:	133647
Spill Date:	2001-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2014-08-15
Spiller Name:	STEVEN WOODS
Spiller Company:	Monroe College
Spiller Address:	370 MAIN ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114844
DEC Memo:	"09/07/2001 PROPERTY FOR SALE. TANK TESTED BY POTENTIAL BUYER. SELLER TO REMOVE OR RETEST. 11/13/2001 TANK PASSED A RETEST AFTER REFIT. NO FURTHER ACTION. 8/15/14: Hard copy file pulled for FOIL. File scanned

SPILL 0106072 / PBS 3-800919 (Continued) **S105135128**

	to PDF, will wiil entered into DecDocs. Paper file discarded. NOTE: WCDoH PBS records indicate this UST was Closed - in place and the site listed as Unregulated 7/30/2002. jod"
Remarks:	"will fill tank with sand and abandoned it"

All TTF:

Facility ID:	0106072
Spill Number:	0106072
Spill Tank Test:	2495803
Site ID:	133647
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	04
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	133647
Operable Unit ID:	844476
Operable Unit:	01
Material ID:	530955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

336
ESE
1/4-1/2
0.326 mi.
1719 ft.

APARTMENT BUILDING **NY LTANKS** **S110611357**
67-70 LOCUST AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
89 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	67-70 LOCUST AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1008207 / 2011-03-10
Facility ID:	1008207
Site ID:	441682
Spill Date:	2010-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010

APARTMENT BUILDING (Continued) **S110611357**

Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-11-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-04
Spill Record Last Update:	2011-03-10
Spiller Name:	ABRAHAM WATHCELL
Spiller Company:	UNKNOWN
Spiller Address:	67- 70 LOCUST AVE
Spiller County:	999
Spiller Contact:	ABRAHAM WATHCELL
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396710
DEC Memo:	"Left message for callback. DT 11/4/10 11/5/10: Call back from Abraham Wathcell of NY Tank Testing to dispatch desk. This was a test failure of an 8K heating oil tank at a co-op. PBS #3-413925 will handled by WCDOH. Mr Wathcell stated he had discussed the results with the management compny and was recommending removal of the tank rather than retest. jod 3/10/11 As per WCDOH eplaced fill pipe, manway gasket and repaired gauge. Passed retest on 2/14/11. NFA JO'M "
Remarks:	Not reported ""

All TTF:

Facility ID:	1008207
Spill Number:	1008207
Spill Tank Test:	2489743
Site ID:	441682
Tank Number:	1
Tank Size:	8000
Material:	0003
EPA UST:	False
UST:	True
Cause:	00
Source:	99
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	441682
Operable Unit ID:	1192229
Operable Unit:	01
Material ID:	2187465
Material Code:	0003A

APARTMENT BUILDING (Continued) **S110611357**

Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AX337 **BUSINESS** **NY LTANKS** **S101341432**
WSW **88 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.331 mi.
1746 ft. **Site 1 of 2 in cluster AX**

Relative: **Lower**

Actual: **89 ft.**

LTANKS:

Name:	BUSINESS
Address:	88 GROVE AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9411669 / 2010-04-28
Facility ID:	9411669
Site ID:	172950
Spill Date:	1994-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	MR. OGMAN
Spiller Address:	88 GROVE AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	145542
DEC Memo:	"4/28/10 16 year old TTF No further info NFA JO'M "
Remarks:	"WILL EXPLORE IT NEXT"

All TTF:

Facility ID:	9411669
Spill Number:	9411669
Spill Tank Test:	1543408
Site ID:	172950

BUSINESS (Continued) **S101341432**

Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	172950
Operable Unit ID:	1005375
Operable Unit:	01
Material ID:	374006
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AX338 **COMMERCIAL BUILDING** **NY LTANKS** **S104276178**
WSW **88-90 GROVE AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.331 mi.
1746 ft. **Site 2 of 2 in cluster AX**

Relative:
Lower

Actual:
89 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	88-90 GROVE AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9411598 / 2010-04-28
Facility ID:	9411598
Site ID:	113133
Spill Date:	1994-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

COMMERCIAL BUILDING (Continued) **S104276178**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2010-04-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	98741
DEC Memo:	"4/28/10 16 year old TTF NFA JO'M"
Remarks:	"TANK TEST FAILURE PETRO-TITE II VISUAL"

All TTF:

Facility ID:	9411598
Spill Number:	9411598
Spill Tank Test:	1543402
Site ID:	113133
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	113133
Operable Unit ID:	1005335
Operable Unit:	01
Material ID:	373942
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AY339 **COMMERICAL BUILDING** **NY LTANKS** **S122878510**
North **405 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.334 mi.
1763 ft. **Site 1 of 4 in cluster AY**

Relative: **Lower**

Actual: **68 ft.**

LTANKS:

Name:	COMMERICAL BUILDING
Address:	405 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1805047 / 2018-11-13
Facility ID:	1805047
Site ID:	574752
Spill Date:	2018-08-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2018-08-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-08-09
Spill Record Last Update:	2018-11-13
Spiller Name:	Not reported
Spiller Company:	HAYCO MANAGEMENT COMPANY
Spiller Address:	405 NORTH AVE
Spiller County:	001
Spiller Contact:	ABE WHSLER
Spiller Phone:	(646) 321-2876
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	527718
DEC Memo:	"8/9/18 tank test failure for 3000 gallon tank at an apartment building. Building is managed by Hayco Mgmt Co. Left message for Hayco to call duty desk. ga 11/13/18 - Westchester County DOH has informed the DEC the tank has passed the tank testing. NFA. KAB"
Remarks:	"caller extremely hard to understand"

All TTF:

Facility ID:	1805047
Spill Number:	1805047
Spill Tank Test:	2506324
Site ID:	574752
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	False
UST:	True
Cause:	00
Source:	04
Test Method:	33

COMMERICAL BUILDING (Continued) **S122878510**

Test Method 2:	EZY 3
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	KABROWNE
Last Modified Date:	Not reported

All Materials:

Site ID:	574752
Operable Unit ID:	1322545
Operable Unit:	01
Material ID:	2330882
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AY340 **RESIDENCE** **NY LTANKS** **S126401838**
North **405 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.334 mi.
1763 ft. **Site 2 of 4 in cluster AY**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Name:	RESIDENCE
Address:	405 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2003161 / Not Reported
Facility ID:	2003161
Site ID:	608877
Spill Date:	2020-07-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2020-07-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2020-07-22
Spill Record Last Update:	2020-10-26
Spiller Name:	Alex Hay
Spiller Company:	Apartment Building
Spiller Address:	Not reported
Spiller County:	001

RESIDENCE (Continued) **S126401838**

Spiller Contact:	ALEX HAY
Spiller Phone:	(212) 545-0050
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	527718
DEC Memo:	"7/22/2020 2000 gallon UST at apartment building failed tank test. Tester said looks like there is residue along the side of the building where the piping goes in. Believed the issue is the piping and not the tank. Left message for property owner to call duty desk. ga 7/22/2020 Spoke to management company representative. Tank is 3000 gallons, PBS# 3-8000033. He will have a plumber in to fix the piping in the next couple of days. ga 10-20-20 No re-test has been submitted. The County health dept has also not rec'd a passing retest. BTR"
Remarks:	"tank test failure"

All Materials:

Site ID:	608877
Operable Unit ID:	1356022
Operable Unit:	01
Material ID:	2367271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

341
WNW
1/4-1/2
0.334 mi.
1764 ft.

KLING
108 VAN GUILDER AVE
NEW ROCHELLE, NY

NY LTANKS **S106124350**
NY Spills **N/A**

Relative:
Lower

Actual:
77 ft.

LTANKS:

Name:	KLING
Address:	108 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0308565 / 2005-02-12
Facility ID:	0308565
Site ID:	214235
Spill Date:	2003-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-11-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

KLING (Continued) **S106124350**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-13
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RICHARD KLING
Spiller Phone:	(914) 636-0076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177496
DEC Memo:	"03/24/04 TANK IS IN A CRAWL SPACE UNDER THE FOUNDATION AND CANNOT BE REMOVED. ROYAL ENVIRONMENTAL INSPECTED TANK AND FOUND NO EVIDENCE OF CONTAMINATION. ROYAL INSTALLED A NEW 275 AST BUT HAS NOT YET PUT THAT TANK IN SERVICE, AWAITING INSPECTION FROM NEW ROCHELLE FIRE DEPT. ONCE AST IS IN SERVICE, ROYAL IS TO CUT AND CLEAN 550 UST AND OBTAIN A SOIL SAMPLE FROM BENEATH TANK. SAMPLE RESULTS TO BE FORWARDED TO DEC. ADDITIONAL SPILL NUMBERS CALLED IN: 03-13745 AND 03-14031. jbo"
Remarks:	"uncover / repair / retest"

All TTF:

Facility ID:	0308565
Spill Number:	0308565
Spill Tank Test:	1528806
Site ID:	214235
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	214235
Operable Unit ID:	874811
Operable Unit:	01
Material ID:	502049
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

KLING (Continued) **S106124350**

SPILLS:

Name:	ANON
Address:	108 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0313745 / 2004-03-24
Facility ID:	0313745
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214236
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	6010
Spill Date:	2004-03-16
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2005-02-12
Spiller Name:	DR RICHARD KLEIN
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	DR RICHARD KLEIN
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo"
Remarks:	"CALLER STATES THAT THERE IS A VERY STRONG ODOR AT THE DOCTOR'S OFFICE AND SHE CAN SMELL IT AT HER HOME. SOMETIMES ODOR IS VERY OVERWELMING: A LARGE CONTAINER IS IN THE BACK YARD OF DOCTOR'S OFFICE: SHE JUST WANTED SOMEONE TO CHECK OUT: *****UPDATE***** SHE CALLED BACK AND SAID THAT SOMEONE TOLD HER THAT A COMPANY CAME IN A CHECKED IT OUT- ROYAL IN PELHAM NY*"

All Materials:

Site ID:	214236
Operable Unit ID:	879034
Operable Unit:	01
Material ID:	495337
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

KLING (Continued) **S106124350**

Name:	SPILL NUMBER 0314031
Address:	108 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0314031 / 2004-03-24
Facility ID:	0314031
Facility Type:	ER
DER Facility ID:	177496
Site ID:	214237
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	6010
Spill Date:	2004-03-24
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-24
CID:	407
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-24
Spill Record Last Update:	2005-02-12
Spiller Name:	RICHARD KLING MD
Spiller Company:	Not reported
Spiller Address:	108 VAN GUILDER AVE
Spiller Company:	001
Contact Name:	RICHARD KLING MD
DEC Memo:	"03/24/04 SEE SPILL 03-08565. jbo 03/30/04 SITE INSPECTED BY STEFAN GOREAU OF WCHD. jbo"
Remarks:	"unknown if spill, caller refused to give name, detected odor of gas/oil from neighbors building, renovation ongoing at building, caller believed odor was related to work."

All Materials:

Site ID:	214237
Operable Unit ID:	880985
Operable Unit:	01
Material ID:	495617
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU342 **BELIVE HOME** **NY LTANKS** **S106869214**
SW **20 PINE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.336 mi.
1774 ft. **Site 4 of 4 in cluster AU**

Relative: **Lower**

Actual: **47 ft.**

LTANKS:

Name:	BELIVE HOME
Address:	20 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0500819 / 2005-05-22
Facility ID:	0500819
Site ID:	343902
Spill Date:	2005-04-20
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2005-05-22
Spiller Name:	JOHN BELIVE
Spiller Company:	BELIVE HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOHN BELIVE
Spiller Phone:	(914) 253-8449
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"05/22/05 PREVIOUSLY REPORTED TTF IS 04-13182. NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 34.56 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 gallon , found holes and contaminated soil:"

All Materials:

Site ID:	343902
Operable Unit ID:	1102568
Operable Unit:	01
Material ID:	582785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BELIVE HOME (Continued) **S106869214**

Name:	PONSERELLA HOME
Address:	20 PINE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413182 / 2005-05-22
Facility ID:	0413182
Site ID:	339043
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-22
Spiller Name:	JOE PONSERELLA
Spiller Company:	PONSERELLA HOME
Spiller Address:	20 PINE STREET
Spiller County:	001
Spiller Contact:	JOE PONSERELLA
Spiller Phone:	(914) 760-6684
Spiller Extention:	CELL
DEC Region:	3
DER Facility ID:	285664
DEC Memo:	"5/22/05 See spill 05-00819. NFA this number. jod"
Remarks:	""

All TTF:

Facility ID:	0413182
Spill Number:	0413182
Spill Tank Test:	1548700
Site ID:	339043
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

BELIVE HOME (Continued) **S106869214**

Site ID:	339043
Operable Unit ID:	1100961
Operable Unit:	01
Material ID:	581111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

343
NE
1/4-1/2
0.339 mi.
1789 ft.

CON EDISON-CEDAR ST WORKS-NEWROCH'LE MGP **EDR MGP** **1008407973**
ONE RAMADA PLAZA **N/A**
NEW ROCHELLE, NY 10801

Relative:
Lower

Actual:
50 ft.

Manufactured Gas Plants:
No additional information available

344
SE
1/4-1/2
0.340 mi.
1794 ft.

CHURCH OF LATTER DAY SAIN **NY LTANKS** **S106471932**
111 NORTH AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
83 ft.

LTANKS:

Name:	CHURCH OF LATTER DAY SAIN
Address:	111 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403126 / 2004-09-21
Facility ID:	0403126
Site ID:	266466
Spill Date:	2004-06-22
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-06-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22

CHURCH OF LATTER DAY SAIN (Continued) **S106471932**

Spill Record Last Update:	2004-09-21
Spiller Name:	MATT SCHIEFERSTEIN
Spiller Company:	CHURCH OF LATTER DAY SAIN
Spiller Address:	111 NORTH AVE
Spiller County:	001
Spiller Contact:	MATT SCHIEFERSTEIN
Spiller Phone:	(631) 351-3555
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	217081
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/23/04 APPROXIMATELY 200 TONS OF CONTAMINATED SOIL REMOVED. CLOSURE REPORT TO FOLLOW. jbo 09/21/04 ANSON ENVIRONMENTAL DISPOSED OF LUST AND 168.02 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"WHILE DIGGING A FOUNDATION FOUND A TANK: CONTAMINATED SOIL ALSO: "

All Materials:

Site ID:	266466
Operable Unit ID:	885085
Operable Unit:	01
Material ID:	490726
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW345 **SPILL NUMBER 9908602** **NY LTANKS** **S104620556**
SSW **HUGUENOT ST & SOUTH PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.347 mi.
1830 ft. **Site 2 of 2 in cluster AW**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	SPILL NUMBER 9908602
Address:	HUGUENOT ST & SOUTH PLAZA
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908602 / 2000-09-14
Facility ID:	9908602
Site ID:	283271
Spill Date:	1999-10-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1999-10-15
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

SPILL NUMBER 9908602 (Continued) **S104620556**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-10-15
Spill Record Last Update:	2000-09-26
Spiller Name:	CITY OF NEW ROCHELLE
Spiller Company:	Not reported
Spiller Address:	HUGUENOT ST
Spiller County:	001
Spiller Contact:	CITY OF NEW ROCHELLE
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229755
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 10/15/99 DELUXE TAXICAB SITE; TANKS HAD BEEN REMOVED BUT CONTAMINATED SOIL; SOIL BEING REMOVED--WILL SUBMIT REPORT. 12/09/99 LETTER SENT TO N. RECCHIA; MUST BETTER DEFINE THE EXTENT OF CONTAMINATION IN THE OVERBURDEN SOIL & GROUNDWATER 05/18/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; ADDITIONAL INVESTIGATION IS REQUIRED AT THIS SITE 09/14/00 LETTER SENT TO CITY OF NEW ROCHELLE BY J. HARDY; BASED ON RESULTS REPORTED BY THE ENERGY & ENVIRONMENTAL ANLAYSISTS, INC. IN AUGUST 2000, THIS SPILL IS CLOSED. "
Remarks:	"VACANT LOT AND DURING EXCAVATION - CONTAMINATED SOIL FOUND"

All Materials:

Site ID:	283271
Operable Unit ID:	1087287
Operable Unit:	01
Material ID:	297711
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY346 **APARTMENT BLDG** **NY LTANKS** **S104515070**
North **1 THE BOULEVARD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.358 mi.
1892 ft. **Site 3 of 4 in cluster AY**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	1 THE BOULEVARD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9809315 / 1999-10-14
Facility ID:	9809315
Site ID:	303319
Spill Date:	1998-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5

APARTMENT BLDG (Continued) **S104515070**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-10-26
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-26
Spill Record Last Update:	1999-11-22
Spiller Name:	ELJAK REALTY
Spiller Company:	APT BLDG
Spiller Address:	1 THE BLVD
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	245085
DEC Memo:	""
Remarks:	"EXCAVATE PIPING AND RETEST"

All TTF:

Facility ID:	9809315
Spill Number:	9809315
Spill Tank Test:	1546451
Site ID:	303319
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	303319
Operable Unit ID:	1070412
Operable Unit:	01
Material ID:	316775
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

APARTMENT BLDG (Continued) **S104515070**

Recovered: .00
Oxygenate: Not reported

AY347 **PRIVATE DWELLING** **NY LTANKS** **S108765819**
NNW **19 ROCHELLE PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.362 mi.
1911 ft. **Site 4 of 4 in cluster AY**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	PRIVATE DWELLING
Address:	19 ROCHELLE PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0706958 / 2008-02-01
Facility ID:	0706958
Site ID:	387568
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2008-02-01
Spiller Name:	ROLAND ANDRALOISKI
Spiller Company:	Not reported
Spiller Address:	19 ROCHELLE PLACE
Spiller County:	001
Spiller Contact:	ROLAND ANDRALOISKI
Spiller Phone:	(914) 774-7362
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	336995
DEC Memo:	"To uncover and retest. 12/05/08 Northeast Environmental reported that the tank was excavated and removed. Noe cotaminated soil was observed in the tank grave. TAGM soil sample results were below DEC guidance values. NFA. TG "
Remarks:	""

All TTF:

Facility ID:	0706958
Spill Number:	0706958
Spill Tank Test:	1764128
Site ID:	387568
Tank Number:	1
Tank Size:	550

PRIVATE DWELLING (Continued) **S108765819**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387568
Operable Unit ID:	1144768
Operable Unit:	01
Material ID:	2135078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

348
SW
1/4-1/2
0.363 mi.
1916 ft.

BUSINESS COMPLEX **NY LTANKS** **S104516367**
55 WEBSTER AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
53 ft.

LTANKS:

Name:	BUSINESS COMPLEX
Address:	55 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9912136 / 2000-05-11
Facility ID:	9912136
Site ID:	86196
Spill Date:	2000-01-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2000-01-20
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

BUSINESS COMPLEX (Continued) **S104516367**

Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2004-11-23
Spiller Name:	MR LIBERETT
Spiller Company:	BUSINESS COMPLEX
Spiller Address:	55 WEBSTER AVE
Spiller County:	001
Spiller Contact:	MR LIBERETT
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79113
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/09/2000 ACCORDING TO MR. BOB ALERES PHASE 11 REPORT COMPLETED. WILL SUBMIT COPY TO T. GHIOSAY. 05/11/00 - Spill closure letter sent by J. O'Mara to: DL Rothberg & Associates PC 1350 Broadway Suite 1711 NY NY 10018 Attention Debra Rothberg, Esq"
Remarks:	"THEY REMOVED A 3,000 GALLON TANK AND PUT IN A NEW 1,000 GALLON TANK THEY SUSPECT THE 3,000 GALLON HAD LEAKED UNKNOWN MATERIAL INTO THE GROUND.THEY GOT THE LAB RESULTS BACK YESTERDAY.THEY SUSPECT IT MAY BE HEATING OIL BUT ARE NOT SURE."

All Materials:

Site ID:	86196
Operable Unit ID:	1086666
Operable Unit:	01
Material ID:	294030
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AZ349 **I-95 EXIT 16** **NY LTANKS** **S102673537**
NNE **OPP. 111 CEDAR ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.366 mi.
1931 ft. **Site 1 of 2 in cluster AZ**

Relative: **Lower**
Actual: **51 ft.**

LTANKS:

Name:	I-95 EXIT 16
Address:	OPP. 111 CEDAR ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9001240 / 1990-08-01
Facility ID:	9001240
Site ID:	244221
Spill Date:	1990-05-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	Not reported
Cleanup Ceased:	1990-08-01
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-05-02

I-95 EXIT 16 (Continued) **S102673537**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	MIGOYA CONST. CO. ?
Spiller Address:	3520 DELAVAL AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	200593
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : N.F.A. 09/27/95: This is additional information about material spilled from the translation of the old spill file: POSS. WASTE OIL."
Remarks:	"DIESEL SPILLED WHILE FILLING HEAVY CONSTRUCTION EQUIPMENT ALSO APPEARSTHAT THEY HAVE CHANGED THEIR CRANKCASE OIL BY DRAINING ONTO GROUND A USED OIL FILTER WAS FOUND THERE ALSO"

All Materials:

Site ID:	244221
Operable Unit ID:	941067
Operable Unit:	01
Material ID:	439592
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AZ350 **CON ED DOWNED O/H TRANSFORMER** **NY LTANKS S103824027**
NNE **115 CEDAR ST** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.366 mi.
1932 ft. **Site 2 of 2 in cluster AZ**

Relative: **Lower**
Actual: **51 ft.**

LTANKS:

Name:	PLASTIC WORKS
Address:	115 CEDAR ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9812998 / 1999-02-22
Facility ID:	9812998
Site ID:	163894
Spill Date:	1999-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial

CON ED DOWNED O/H TRANSFORMER (Continued) **S103824027**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-01-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-22
Spill Record Last Update:	1999-03-01
Spiller Name:	GARY STRUTTEN
Spiller Company:	PLASTIC WORKS
Spiller Address:	115 CEDAR ST
Spiller County:	001
Spiller Contact:	GARY STRUTTEN
Spiller Phone:	(914) 576-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	138224
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER'S COMPANY WAS PULLING A 550GAL UST - TANK WAS FULL OF HOLES"

All Materials:

Site ID:	163894
Operable Unit ID:	1073438
Operable Unit:	01
Material ID:	313271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CON ED DOWNED O/H TRANSFORMER
Address:	115 CEDAR ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2107732 / 2021-11-26
Facility ID:	2107732
Facility Type:	ER
DER Facility ID:	138224
Site ID:	628662
DEC Region:	3
Spill Cause:	Traffic Accident
Spill Class:	B3
SWIS:	6010

CON ED DOWNED O/H TRANSFORMER (Continued) **S103824027**

Spill Date:	2021-11-21
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2021-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-11-21
Spill Record Last Update:	2021-11-26
Spiller Name:	DAVID DUKE
Spiller Company:	CON ED
Spiller Address:	115 CEDAR ST
Spiller Company:	999
Contact Name:	DAVID DUKE
DEC Memo:	"11-21-21 A private vehicle hit the utility pole and took the pole down causing catastrophic failure of the OHT. About 50gal spilled to asphalt with approximately 1 gallon making it s way into a catch basin. Crews investigated and found no running water in the basin and the outfall is filled with leaves. Most of the product was caught on the leaves. Crews will open downstream manholes to confirm where the product went. New Rochelle FD put speedy dry on all free product. Cleanup pending removal of the pole and restoration of power. PCB status unknown. ML 11/22/21 Tim Tegan from Con Ed emailed the following, Crews just reported that the transformer at 115 Cedar Street in New Rochelle states Non PCB mineral oil on the spec plate. They will clean the spill as non haz. TG 11/26/21 Excerpt from EMIS, 11/23/2021 7:22 AM Clean harbors double washed asphalt and concrete with simple green. Removed all debris from catch basins and cleaned and washed with simple green. No environmental tag. Overhead crews replaced pole and installed new transformer. Baxter, Brandon TG"
Remarks:	"one gallon reached storm sewer, one quart to outfall pipe, already full of leaves. cleanup pending. fd on scene placed speedi dri."

All Materials:

Site ID:	628662
Operable Unit ID:	1375780
Operable Unit:	01
Material ID:	2389312
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

351
SSE
1/4-1/2
0.367 mi.
1937 ft.

NICK MAZZA RESIDENCE
20 DAVIS AVE
NEW ROCHELLE, NY

NY LTANKS **S104621408**
N/A

Relative:
Lower

Actual:
77 ft.

LTANKS:

Name:	NICK MAZZA RESIDENCE
Address:	20 DAVIS AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0000532 / 2000-04-20
Facility ID:	0000532
Site ID:	211468
Spill Date:	2000-04-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-13
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-13
Spill Record Last Update:	2000-05-03
Spiller Name:	N/A
Spiller Company:	NICK MAZZA
Spiller Address:	20 DAVIS AVE
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/14/2000 ENVIROSTAR REPAIRED; U.S. TANK TO RETEST ON 4/17/2000. 04/20/2000 U.S. TANK TECH RETESTED TANK AFTER ENVIROSTAR REPLACED PIPING. TANK PASSED RETEST. NFA"
Remarks:	"tank failed the test. he did not have the homeowners name or phone number "

All TTF:

Facility ID:	0000532
Spill Number:	0000532
Spill Tank Test:	1525485
Site ID:	211468
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

NICK MAZZA RESIDENCE (Continued) **S104621408**

Test Method: 18
Test Method 2: Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 211468
Operable Unit ID: 822249
Operable Unit: 01
Material ID: 288777
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BA352 **SHERIDEN PLAZA** **NY LTANKS** **S100138278**
NE **1 SHERIDEN PLAZA** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.370 mi.
1951 ft. **Site 1 of 2 in cluster BA**

Relative: **Lower**
Actual: **36 ft.**

LTANKS:
Name: SHERIDEN PLAZA
Address: 1 SHERIDEN PLAZA
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 8909204 / 1990-03-07
Facility ID: 8909204
Site ID: 80178
Spill Date: 1989-12-19
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
SWIS: 6000
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1989-12-19
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1989-12-21
Spill Record Last Update: 1992-02-10
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported

SHERIDEN PLAZA (Continued) **S100138278**

Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74339
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATION FOUND DURING TANK REMOVAL SOIL TO BE STOCKPILED ON PLASTIC DEC TO INSPECT TANK HOLE TYREE VACING OUT HOLE"

All Materials:

Site ID:	80178
Operable Unit ID:	934143
Operable Unit:	01
Material ID:	442378
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BB353 **JASON PARTNERS LTD** **NY LTANKS** **S105998096**
SSW **675 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.372 mi.
1962 ft. **Site 1 of 3 in cluster BB**

Relative: **Lower**

Actual: **65 ft.**

LTANKS:

Name:	JASON PARTNERS LTD
Address:	675 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0211105 / 2003-03-26
Facility ID:	0211105
Site ID:	86967
Spill Date:	2003-02-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-02-05
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-05
Spill Record Last Update:	2003-04-09

JASON PARTNERS LTD (Continued) **S105998096**

Spiller Name:	JAMIE MIZRAHI
Spiller Company:	JASON PARTNERS LTD
Spiller Address:	675 MAIN ST
Spiller County:	001
Spiller Contact:	JAMIE MIZRAHI
Spiller Phone:	(914) 682-6664
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79721
DEC Memo:	""
Remarks:	"CALLERS COMPANY HIRED TO REMOVE A 3000 GAL INGROUND TANK AT THE ABOVE LOCATION, AFTER TANK WAS REMOVED, HOLE WERE FOUND IN TANK AND CONTAMINATED SOIL WAS DISCOVERED - DIRT IS BEING REMOVED AND STORED ON PLASTIC"

All Materials:

Site ID:	86967
Operable Unit ID:	862143
Operable Unit:	01
Material ID:	514466
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC354 **ABANDONED GAS STATION** **NY LTANKS** **S102660200**
West **197 WEBSTER AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.376 mi.
1984 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
79 ft.

LTANKS:

Name:	ABANDONED GAS STATION
Address:	197 WEBSTER AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9707099 / 2001-07-19
Facility ID:	9707099
Site ID:	231589
Spill Date:	1997-09-15
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-09-15
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

ABANDONED GAS STATION (Continued) **S102660200**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-09-15
Spill Record Last Update:	2001-08-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	EDWARD SELLIAN
Spiller Phone:	(561) 221-1754
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	190875
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/19/2001 LETTER SENT TO IRA CONKLIN & SONS BY T. GHIOSAY; BASED ON SUBSURFACE INVESTIGATION REPORT, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL LISTED AS CLOSED."
Remarks:	"CALLER REMOVING TANKS AND FOUND SOIL CONTAMINATION"

All Materials:

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	231589
Operable Unit ID:	1053327
Operable Unit:	01
Material ID:	332676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA355 **MUTUAL BISCUIT COMPANY** **NY LTANKS** **S104193116**
NE **65 RIVER ST.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.378 mi.
1997 ft. **Site 2 of 2 in cluster BA**

Relative: **Lower**

Actual: **35 ft.**

LTANKS:

Name:	MUTUAL BISCUIT COMPANY
Address:	65 RIVER ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8707334 / 1988-02-18

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Facility ID:	8707334
Site ID:	286036
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-25
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-01
Spill Record Last Update:	1988-03-11
Spiller Name:	HUGH GEORGE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : WILL RETEST. / / : TANKS REMOVED. LR 02-18-88 N F A. "
Remarks:	"TTTF-4K TANK;-0.7584 GPH,4K TANK;-0.3312 GPH"

All TTF:

Facility ID:	8707334
Spill Number:	8707334
Spill Tank Test:	1532438
Site ID:	286036
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286036
Operable Unit ID:	911503
Operable Unit:	01

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Material ID:	466293
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MUTUAL BISCUIT
Address:	65 RIVER ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8708530 / 1988-02-18
Facility ID:	8708530
Site ID:	286037
Spill Date:	1988-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-18
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	HUGH GEORGE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231833
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANKS REMOVED 02-18-88 LR N F A. "
Remarks:	"5K (RETEST) 1.34GPH TO PUMP & PULL TANK"

All TTF:

Facility ID:	8708530
Spill Number:	8708530
Spill Tank Test:	1532919
Site ID:	286037
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286037
Operable Unit ID:	913194
Operable Unit:	01
Material ID:	570954
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	POST MARINE SUPPLY
Address:	65 RIVER ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9904805 / 1999-07-22
Facility ID:	9904805
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139056
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	6010
Spill Date:	1999-07-22
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1999-07-22
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-22
Spill Record Last Update:	1999-09-10
Spiller Name:	NASER JABER
Spiller Company:	POST MARINE SUPPLY

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Spiller Address:	65 RIVER ST
Spiller Company:	001
Contact Name:	NASER JABER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA "
Remarks:	"CALLER STATES THAT HE WITTNESSED SUBJ DUMPING GAS INTO A STORM DRAIN. JOHN O'MARA (REGION 3 SPILLS) NOTIFIED AND ALSO ENCON POLICE"

All Materials:

Site ID:	139056
Operable Unit ID:	1079250
Operable Unit:	01
Material ID:	301132
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	POST MARINE SUPPLY
Address:	65 RIVER ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9908179 / 1999-10-18
Facility ID:	9908179
Facility Type:	ER
DER Facility ID:	118852
Site ID:	139057
DEC Region:	3
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1999-10-05
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-10-05
CID:	388
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-05
Spill Record Last Update:	1999-11-04
Spiller Name:	MICHAEL GRAVANESE
Spiller Company:	POST MARINE SUPLLY
Spiller Address:	65 RIVER SR
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/18/99 DEC INSPECTED SITE. ONE LEAKY BATTERY FOUND NEXT TO

MUTUAL BISCUIT COMPANY (Continued) **S104193116**

Remarks: DIESEL TANKS. BATTERIES TO BE REMOVED LATER TODAY. NFA" "CALLER IS AN EX EMPLOYEE REPORTING BATTERIES BEING STORED NEXT TO GASOLINE TANKS AND BELIEVES THEY MIGHT BE LEAKING BATTERY ACID."

All Materials:

Site ID:	139057
Operable Unit ID:	1082477
Operable Unit:	01
Material ID:	300856
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD356 **GETTY 58114** **NY LTANKS S107657288**
ENE **340 MAIN STREET** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.379 mi.
2002 ft. **Site 1 of 6 in cluster BD**

Relative: **Lower**
Actual: **38 ft.**

LTANKS:

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0913713 / 2010-04-29
Facility ID:	0913713
Site ID:	426673
Spill Date:	2010-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2010-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-26
Spill Record Last Update:	2018-04-09
Spiller Name:	ROBERT O'KEEFE
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TOM ANDERSON
Spiller Phone:	(845) 216-8064
Spiller Extention:	Not reported

GETTY 58114 (Continued) **S107657288**

DEC Region: 3
DER Facility ID: 310476
DEC Memo: "3/26/10 Tyree to go there on Mon. 3/29 to do repairs. dw 4/29/10 Getty 340 Main St New Rochelle line test failed do to faulty check valve. Tyree replaced check valve. Passed retest on 4/12/10 NFA JO'M 10-23-17 SEND OUT 30 day tank letter- RDB 10-25-17 call from Raul Naube @ 5168027171; retuned call; explained the current situation. offered to remove tanks for him. he is waiting for a court case, I advised him that he is in violation of the NYS CRRR pertaining to tanks, he has other sites on Long Island. Never in Westchester, I welcomed him to region; he will move forward with the permits and intends to remove the tanks- RDB 12-12-17 Rahul@lotusmgmt.com 340 Main Street Realty Inc. 25 Newbridge Road, Suite 312, Hicksville, NY 11801 _RDB 12-12-17 called and left another message RDB 12-18-17 email sent, I called your office last week and left a message. The tanks at your facility need to be removed. Please contact me today and discuss the schedule for the tank s removal or this case will be referred to Region 3, Regional Attorney for enforcement. RDB 1-3-18 email from Cider, The owner of the above referenced property has received the permit for removal of the USTs (NR BD/NR FM).We are only waiting on the contractors schedule.In the meantime, we wanted to confirm that there is nothing else required by your department?As soon as the schedule is confirmed, we will let you know. RDB 1-4-18 response, Thanks for the email and call. Who is the contractor for the tank removal? Do you have a guesstimate for the removal date? As I have explained to Rahul, this site is progressing towards enforcement and penalties. RDB 1-4-18, The contractor for the tank removals will be Felik s and Sons. Rahul is pushing them to get out there as soon as possible. My guestimate would be about two/three weeks to begin. As soon as we get the schedule from the contractor/Rahul, I will let you know. RDB Tank removal began. New Spill called in 17-09698 This spill closed- RDB 02-12-18 Spoke with Tim Fisher of Antea Group. Excavation under the northern dispenser island to commence on Thursday. Endpoint samples from both the registered tank removal and ghost tank removal show no exceedances. Sand from inside the ghost tanks is stock piled on site. All soil to be removed upon completion of excavation activities. BTR 4/9/18 pre-work notification from 12/27/17 in D2. BW "
Remarks: "in line problem - Tyree notified - cleanup and repair pending"

All Materials:
Site ID: 426673
Operable Unit ID: 1182349
Operable Unit: 01
Material ID: 2176532
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: GETTY 58114

GETTY 58114 (Continued) **S107657288**

Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513793 / 2006-03-02
Facility ID:	0513793
Facility Type:	ER
DER Facility ID:	310476
Site ID:	360340
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-03-01
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2006-03-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-01
Spill Record Last Update:	2006-03-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"Some staining - Cleaned up NFA"
Remarks:	"LESS THAN A GAL OF BOTH HAS BEEN CLEANED UP."

All Materials:

Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108025
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	360340
Operable Unit ID:	1117511
Operable Unit:	01
Material ID:	2108026
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

GETTY 58114 (Continued) **S107657288**

Units:	G
Recovered:	1.00
Oxygenate:	Not reported
Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600016 / 2006-04-01
Facility ID:	0600016
Facility Type:	ER
DER Facility ID:	310476
Site ID:	361935
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-01
CID:	41
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-01
Spill Record Last Update:	2006-04-04
Spiller Name:	Not reported
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"04/04/06: closed NFA"
Remarks:	"LESS THAN ONE GALLON OF EACH - ON ALPHALT - CLEANED UP"

All Materials:

Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01
Material ID:	2109530
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	361935
Operable Unit ID:	1120047
Operable Unit:	01

GETTY 58114 (Continued) **S107657288**

Material ID:	2109529
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0603586 / 2006-07-03
Facility ID:	0603586
Facility Type:	ER
DER Facility ID:	310476
Site ID:	366335
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-06-30
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2006-06-30
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-30
Spill Record Last Update:	2006-07-11
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"COMBINED TOTAL OF LESS THAN A GAL. HAS BEEN CLEANED UP."

All Materials:

Site ID:	366335
Operable Unit ID:	1124284
Operable Unit:	01
Material ID:	2113775
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G

GETTY 58114 (Continued) **S107657288**

Recovered: 1.00
Oxygenate: Not reported

Site ID: 366335
Operable Unit ID: 1124284
Operable Unit: 01
Material ID: 2113776
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: 1.00
Oxygenate: Not reported

Name: GETTY 58114
Address: 340 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0606253 / 2006-09-03
Facility ID: 0606253
Facility Type: ER
DER Facility ID: 310476
Site ID: 369567
DEC Region: 3
Spill Cause: Housekeeping
Spill Class: C4
SWIS: 6010
Spill Date: 2006-08-30
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-08-30
CID: 77
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-08-31
Spill Record Last Update: 2006-09-03
Spiller Name: MIKE CARR
Spiller Company: GETTY 58114
Spiller Address: 340 MAIN STREET
Spiller Company: 001
Contact Name: MIKE CARR
DEC Memo: ""
Remarks: "1 qt of waste oil spilled onto asphalt, speedy dry applied."

All Materials:
Site ID: 369567
Operable Unit ID: 1127402
Operable Unit: 01
Material ID: 2117000

GETTY 58114 (Continued) **S107657288**

Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0606306 / 2006-09-03
Facility ID:	0606306
Facility Type:	ER
DER Facility ID:	310476
Site ID:	369636
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-09-01
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-01
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-01
Spill Record Last Update:	2006-09-03
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"LESS THAN A GAL OF BOTH ABND THEY HAVE BEEN CLEANED UP."

All Materials:

Site ID:	369636
Operable Unit ID:	1127472
Operable Unit:	01
Material ID:	2117068
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	1.00

GETTY 58114 (Continued) **S107657288**

Oxygenate: Not reported

Site ID: 369636
Operable Unit ID: 1127472
Operable Unit: 01
Material ID: 2117069
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: 1.00
Oxygenate: Not reported

Name: GETTY #58114
Address: 340 MAIN STREET
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0602340 / 2006-06-07
Facility ID: 0602340
Facility Type: ER
DER Facility ID: 310476
Site ID: 364789
DEC Region: 3
Spill Cause: Housekeeping
Spill Class: C4
SWIS: 6010
Spill Date: 2006-06-01
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-06-01
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-06-01
Spill Record Last Update: 2006-06-07
Spiller Name: MIKE CARR
Spiller Company: GETTY #58114
Spiller Address: 340 MAIN STREET
Spiller Company: 001
Contact Name: MIKE CARR
DEC Memo: ""
Remarks: "SPEEDI DRI DOWN STAINING ONLY"

All Materials:
Site ID: 364789
Operable Unit ID: 1122807
Operable Unit: 01
Material ID: 2112286
Material Code: 0022

GETTY 58114 (Continued) **S107657288**

Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	364789
Operable Unit ID:	1122807
Operable Unit:	01
Material ID:	2112285
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	GETTY #58114
Address:	340 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601041 / 2006-04-27
Facility ID:	0601041
Facility Type:	ER
DER Facility ID:	310476
Site ID:	363188
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6010
Spill Date:	2006-04-27
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2006-04-27
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-27
Spill Record Last Update:	2006-05-02
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58114
Spiller Address:	340 MAIN STREET
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"5/2/06: Staining - cleaned up NFA"
Remarks:	"speedi dri applied and cleaned up"

GETTY 58114 (Continued) **S107657288**

All Materials:

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110750
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110748
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	363188
Operable Unit ID:	1121255
Operable Unit:	01
Material ID:	2110749
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

357
ENE
1/4-1/2
0.381 mi.
2012 ft.

SUNOCO
71 HUGUENOT ST
NEW ROCHELLE, NY

NY LTANKS **S102233475**
NY Spills **N/A**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Name:	SUNOCO / A-PLUS
Address:	71 HUGUENOT
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9514850 / 1996-07-26
Facility ID:	9514850
Site ID:	255332
Spill Date:	1996-02-20
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility

SUNOCO (Continued) **S102233475**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-02-20
Spill Record Last Update:	1996-09-05
Spiller Name:	RUSSELL HAMMOND
Spiller Company:	SUNOCO / A-PLUS
Spiller Address:	71 HUGUENOT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209140
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/26/96 EPS SUBMITTED G.W. INVESTIAGATION WHICH INDICATES THAT SUNOCO IS THE SOURCE OF G.W. CONTAM. ON 15 RIVER ST. "
Remarks:	"soil boring for assessment for station upgrade - head space reading indicates potential of petroleum release"

All Materials:

Site ID:	255332
Operable Unit ID:	1025945
Operable Unit:	01
Material ID:	354972
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SUNOCO
Address:	71 HUGUENOT ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9610201 / 2005-01-20
Facility ID:	9610201
Facility Type:	ER
DER Facility ID:	201279
Site ID:	245037
DEC Region:	3
Spill Cause:	Unknown

SUNOCO (Continued) **S102233475**

Spill Class:	B3
SWIS:	6010
Spill Date:	1996-02-28
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-11-15
CID:	366
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-15
Spill Record Last Update:	2005-01-21
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RUSSELL HAMMOND
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 11/15/96 PETROLEUM FOUND DURING WELL SAMPLING; 09/22/97 LETTER SENT; REMEDIATION IS REQUIRED AT THIS SITE; 01/02/98 LETTER SENT; REMEDIATION PROPOSAL IS APPROVED; WORK MUST START WITHIN THIRTY DAYS; 12/30/99 LETTER SENT TO SUN COMPANY; PROPOSAL TO INSTALL HI-VAC SYSTEM AT THIS SITE IS APPROVED & REQUIRED 1/20/05 nfa letter has been sent do to low and declining groundwater contamination--close 05/18/00 LETTER SENT TO MATRIX ENV. BY J. HARDY; REMEDIAL ACTION PLAN OF 1/12/00 IS APPROVED AND REQUIRED 04/19/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; YOU ARE AUTHOR IZED TO OPERATE REMEDIAL SYSTEMS FOR 90 DAYS WHILE DISCHARGE PERMIT APPLICATIONS ARE BEING PROCESSED 06/22/01 LETTER SENT TO MATRIX ENV. BY J. HARDY; AUTHORIZED BY WCDOH TO OPERATE SYSTEM FOR 90 DAYS WHILE PERMITTING IS IN PROGRESS 05/09/03: Letter sent to Matrix Env. Tech. by J. Hardy; Report submitted dated March 20, 2003. Next report due after completion of one year monitoring period. 2/12/04: Letter sent to Matrix Env. Tech. by J. Hardy. No further action is required at this time. Spill cannot be closed due to BTEX levels in monitoring wells 2 & 4."
Remarks:	"while removing old tanks discovered contaminated soil. caller's company is cleaning. "

All Materials:

Site ID:	245037
Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	342418
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUNOCO (Continued) **S102233475**

Site ID:	245037
Operable Unit ID:	1038129
Operable Unit:	01
Material ID:	2096838
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BB358 **6 WEBSTER** **NY LTANKS** **S106472061**
SSW **6 WEBSTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.383 mi.
2020 ft. **Site 2 of 3 in cluster BB**

Relative: **Lower**
Actual: **60 ft.**

LTANKS:

Name:	6 WEBSTER
Address:	6 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0403816 / 2004-10-08
Facility ID:	0403816
Site ID:	81655
Spill Date:	2004-07-09
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-07-09
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-09
Spill Record Last Update:	2004-10-08
Spiller Name:	SANDRA
Spiller Company:	Not reported
Spiller Address:	6 WEBSTER AVE
Spiller County:	001
Spiller Contact:	SANDRA
Spiller Phone:	(914) 738-4106
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75517
DEC Memo:	"10/08/04 TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. SPILL CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NFA REQUIRED AT THIS TIME. jbo "

6 WEBSTER (Continued) **S106472061**

Remarks: "tank test failed.uncover the tank isolate,and retest"

All TTF:

Facility ID:	0403816
Spill Number:	0403816
Spill Tank Test:	1529427
Site ID:	81655
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	81655
Operable Unit ID:	886220
Operable Unit:	01
Material ID:	491374
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BE359 **SPILL NUMBER 0314082** **NY LTANKS** **S106385679**
WNW **136 VANGUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.385 mi.
2035 ft. **Site 1 of 2 in cluster BE**

Relative: **Lower**

Actual: **76 ft.**

LTANKS:

Name:	SPILL NUMBER 0314082
Address:	136 VANGUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0314082 / 2004-06-08
Facility ID:	0314082
Site ID:	80232
Spill Date:	2004-03-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-03-25

SPILL NUMBER 0314082 (Continued) **S106385679**

CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-25
Spill Record Last Update:	2004-06-08
Spiller Name:	SILVANA CARRUSA
Spiller Company:	Not reported
Spiller Address:	136 VANGUILDER AVE
Spiller County:	001
Spiller Contact:	SILVANA CARRUSA
Spiller Phone:	(914) 654-1101
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74387
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/08/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 43.55 TONS OF CONTAMINATED SOIL. NFA REQUIRED. jbo"
Remarks:	"tank test failed. repair and retest and remove"

All TTF:

Facility ID:	0314082
Spill Number:	0314082
Spill Tank Test:	1529072
Site ID:	80232
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	80232
Operable Unit ID:	881015
Operable Unit:	01
Material ID:	495664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF360 **RESIDENCE** **NY LTANKS** **S109414263**
NW **100 SICKLES AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.387 mi.
2042 ft. **Site 1 of 6 in cluster BF**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Name:	STEWART DWELLING
Address:	100 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1200264 / 2012-08-13
Facility ID:	1200264
Site ID:	462885
Spill Date:	2012-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-04-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-10
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	STEWART
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	STEWART
Spiller Phone:	914-235-6390
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	326980
DEC Memo:	"4-10-12 Spoke with Kathy. Failed with a popping sound. They have recommended a retest because this sound usually means piping or fitting leak. Homeowner is elderly so they are dealing with her daughter, Eunice at 914-715-1040. jm 8/13/2012: Envirostar removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"550gal ust"

All Materials:

Site ID:	462885
Operable Unit ID:	1212990
Operable Unit:	01
Material ID:	2210869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

RESIDENCE (Continued) **S109414263**

Units: G
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: STEWART RESIDENCE
Address: 100 SICKLES AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0612561 / 2007-03-12
Facility ID: 0612561
Facility Type: ER
DER Facility ID: 326980
Site ID: 377421
DEC Region: 3
Spill Cause: Other
Spill Class: C4
SWIS: 6010
Spill Date: 2007-02-19
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2007-02-19
CID: 410
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-02-20
Spill Record Last Update: 2007-03-12
Spiller Name: SUZANNE LUGO
Spiller Company: TOWN AND COUNTRY OIL
Spiller Address: 275 EAST 7TH STREET
Spiller Company: 001
Contact Name: NECOLA STEWART
DEC Memo: ""
Remarks: "SPILL WAS LESS THAN ONE GALLON ON ICE OUTSIDE OF RESIDENCE: CLEANUP IN PROGRESS: MATERIAL CAME OUT OF VENT PIPE:"

All Materials:
Site ID: 377421
Operable Unit ID: 1134955
Operable Unit: 01
Material ID: 2124838
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

RESIDENCE (Continued) **S109414263**

Name:	RESIDENCE
Address:	100 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0811178 / 2009-01-09
Facility ID:	0811178
Facility Type:	ER
DER Facility ID:	326980
Site ID:	408736
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2009-01-09
Investigator:	dxweitz
Referred To:	Not reported
Reported to Dept:	2009-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-09
Spill Record Last Update:	2009-01-09
Spiller Name:	SUE LUGO
Spiller Company:	TOWN & COUNTRY OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NECOLA STEWART
DEC Memo:	"1/9/09 Problem with the vent whistle. Town and Country is there fixing the vent, and cleaning up the 1 gal spill. NFA dw"
Remarks:	"Caller states during a fill some oil sprayed out of the vent pipe onto soil. Spill was cleaned."

All Materials:

Site ID:	408736
Operable Unit ID:	1165255
Operable Unit:	01
Material ID:	2156662
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BC361 **MAR-LAP SVC CNTR** **NY LTANKS** **S103568792**
West **210 WEBSTER AVE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.395 mi.
2086 ft. **Site 2 of 2 in cluster BC**

Relative: **Lower**

Actual: **75 ft.**

LTANKS:

Name:	CITGO WEBSTER FOOD MART
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1311416 / 2017-04-06
Facility ID:	1311416
Site ID:	492314
Spill Date:	2014-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-03-06
Spill Record Last Update:	2017-04-06
Spiller Name:	Not reported
Spiller Company:	LINE TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	VISHAL KUMAR
Spiller Phone:	(914) 632-2364
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	216842
DEC Memo:	"Wanye Schneider, WCDOH, is handling...mm 4-5-17 ask American for update"
Remarks:	"regular and super product line test failure - repair/retest pending"

All Materials:

Site ID:	492314
Operable Unit ID:	1241846
Operable Unit:	01
Material ID:	2242337
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

MAR-LAP SVC CNTR (Continued) **S103568792**

SPILLS:

Name:	MAR-LAP SVC CNTR
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8906053 / 1989-09-21
Facility ID:	8906053
Facility Type:	ER
DER Facility ID:	216842
Site ID:	266088
DEC Region:	3
Spill Cause:	Other
Spill Class:	D3
SWIS:	6010
Spill Date:	1989-07-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-09-19
Cleanup Meets Std:	True
Last Inspection:	1989-09-19
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	MAR-LAP SVC CNTR
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL."
Remarks:	"HAVE EXCAVATED AND REMOVED GAS CONTAMINATED SOIL FROM AROUND 3 5ANKS. SOIL BEING REMOVED TODAY BY E.E.S. NFA"

All Materials:

Site ID:	266088
Operable Unit ID:	931218
Operable Unit:	01
Material ID:	446446
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WESTERN AVE CITGO

MAR-LAP SVC CNTR (Continued) **S103568792**

Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413599 / 2005-03-30
Facility ID:	0413599
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342744
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"IT WAS SOME RESIDEU IN A SPILL BUCKET ALL CLEANED UP:"

All Materials:

Site ID:	342744
Operable Unit ID:	1101460
Operable Unit:	01
Material ID:	581627
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WESTERN AVE CITGO
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0413600 / 2005-03-30
Facility ID:	0413600
Facility Type:	ER
DER Facility ID:	289079
Site ID:	342745

MAR-LAP SVC CNTR (Continued) **S103568792**

DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6000
Spill Date:	2005-03-30
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-04-07
Spiller Name:	SEBASTIAN
Spiller Company:	WESTERN AVE CITGO
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN
DEC Memo:	""
Remarks:	"WHILE CHANGING OIL THEY KICKED A BUCKET OVER AND IN PROCESS OF CLEANING UP AT THIS TIME;"

All Materials:

Site ID:	342745
Operable Unit ID:	1101461
Operable Unit:	01
Material ID:	581628
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SSN REALTY
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1200103 / 2013-11-06
Facility ID:	1200103
Facility Type:	ER
DER Facility ID:	216842
Site ID:	462718
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6010
Spill Date:	2012-04-04
Investigator:	RDBENDEL

MAR-LAP SVC CNTR (Continued) **S103568792**

Referred To:	Not reported
Reported to Dept:	2012-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-04
Spill Record Last Update:	2013-11-06
Spiller Name:	MR KUMAR
Spiller Company:	SSN REALTY
Spiller Address:	210 WEBSTER AVE
Spiller Company:	999
Contact Name:	MR KUMAR
DEC Memo:	"4-4-12: V.Mc. call to Mr.Kumar: Phone # no longer is service. 4-4-12: V.Mc. call to SEBASTIAN/WCHD: Left Mess.: Req. callbk. to Dispt. Update from WCDOH: greater than greater than greater than Bimonte, Sebastian greater than spb4@westchestergov.com greater than 4/5/2012 9:46 AM greater than greater than greater than John, SSN Realty 210 Webster Ave New Rochelle NY Super Tank product in interstitial space. Manual check during PBS inspection yesterday. Product clear no water or dirt. Diesel Tank product in interstitial space. Manual check during PBS Inspection yesterday. Product clear no water of dirt. Tanks One was hired to test inner and outer tanks. Super, inner wall passed, outer wall failed. Diesel inner wall failed, outer wall passed. Both tanks should be pumped out by today. Sebastian Bimonte jod 5/23/2012 -- After a meeting in NPO among owner, tank maintenance contractor, Mr. Nesci (attorney), WC DOH, and CK last Friday (5/18), Ispoke to Rachel at Hydro Environmental about a site assessment. Work plan to be submitted shortly. ELM 6/05/12: Update received from Sebastian Bimonte of WCDOH PBS: 1200103: SNN Realty in Mount Vernon. This was product in the interstitial during PBS inspection. No release to environment. Tank repaired NOH issued and can be closed. jod 6/5/2012 -- Site assessment being conducted at my request: field work on 210 Webster Ave in New Rochelle on Tuesday, June 12, 2012 per email from Hydro Enviro. ELM 7/31/2012 -- RI report clearly shows groundwater contamination (BETX/MTBE) around the tank field and dispensers. Need further delineation and RAP. Nothing in unsaturated soils. ELM 8/22/2012 -- Contractor working on a Phase II RI work plan. ELM 9/19/2012 -- Approved an RI work plan. Except that they did include the schedule and failed to mention RAP possibilities. ELM 1/22/2013 -- HydroTech informed me that they have the permit needed from the muny to perform the remediation. ELM 2/21/2013 -- Still no word on mobilizing for remediation. ELM 11-6-13 email from county, There is a whole history here.The 1200103 was for product in the interstitial. Sebastian and Carlos worked with Ed Moore on it.Basically double walled tanks leaked into the interstitial. It appear to be the striker plate were missing and from sticking the tanks they wore out. Eastmond lined the tanks and had trouble removing the product from the IS (completely). We requested spill closure and Ed Moore kept the spill open and continued to work on the PBS issues. They are replacing all tanks now. American

MAR-LAP SVC CNTR (Continued) **S103568792**

Remarks:	Petroleum (Ed- Thank You for making this happen)Wayne Schneider is inspected the site this afternoon and will handle the spill. I suggest we close out spill 1200103 and keep 1307998.(Wayne please provide a brief update to all after your inspection today.) 11-6-13 tanks yanked, new spill 13-07998, close this one RDB " "12 oz per product found during investigation on inter.cont., on the super tank and diesel tank."

All Materials:

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	462718
Operable Unit ID:	1212815
Operable Unit:	01
Material ID:	2210675
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	CITGO STATION
Address:	210 WEBSTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600746 / 2006-08-15
Facility ID:	0600746
Facility Type:	ER
DER Facility ID:	216842
Site ID:	362821
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2006-04-19
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2006-04-19
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

MAR-LAP SVC CNTR (Continued) **S103568792**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-04-19
Spill Record Last Update:	2020-01-21
Spiller Name:	SEBASTIAN BELLAFONTE
Spiller Company:	CITGO STATION.
Spiller Address:	210 WEBSTER AVE
Spiller Company:	001
Contact Name:	SEBASTIAN BELLAFONTE
DEC Memo:	"04/25/06: refer to WC PBS. 12/21/06 - Letter from Barbara McDonald from WCDOH to Sebastian Bulfamonte, SSN Realty 94 1st Street, New Rochelle, NY 10801, states that documentation is acceptable to the Westchester County Department of Health and the work permits issued 5/11/06 and 6/6/06 are closed. NFA."
Remarks:	"FOUND THE MATERIAL BETWEEN THE INTERSTIAL SPACE OF THE TWO TANKS. 4000 GAL TANKS. PBS 3-180092"

All Materials:

Site ID:	362821
Operable Unit ID:	1120900
Operable Unit:	01
Material ID:	2110381
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD362 **JEROME RESIDENCE** **NY LTANKS** **S106702572**
ENE **33 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2092 ft. **Site 2 of 6 in cluster BD**

Relative: **Lower**
Actual: **35 ft.**

LTANKS:

Name:	JEROME RESIDENCE
Address:	33 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0405389 / 2005-02-13
Facility ID:	0405389
Site ID:	235222
Spill Date:	2004-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-08-17
CID:	444
Water Affected:	Not reported

JEROME RESIDENCE (Continued) **S106702572**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-17
Spill Record Last Update:	2005-02-13
Spiller Name:	MARK JEROME
Spiller Company:	JEROME RESIDENCE
Spiller Address:	33 ECHO AVE
Spiller County:	001
Spiller Contact:	MARK JEROME
Spiller Phone:	(914) 632-5400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	193747
DEC Memo:	"02/13/05 MILLER ENVIRONMENTAL REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- ISOLATION & RETEST"

All TTF:

Facility ID:	0405389
Spill Number:	0405389
Spill Tank Test:	1529557
Site ID:	235222
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235222
Operable Unit ID:	888925
Operable Unit:	01
Material ID:	489552
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	235222
Operable Unit ID:	888925

JEROME RESIDENCE (Continued) **S106702572**

Operable Unit:	01
Material ID:	489551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BG363 **MICELI HOME** **NY LTANKS** **S108059468**
SSE **194 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2092 ft. **Site 1 of 4 in cluster BG**

Relative: **Lower**

Actual: **78 ft.**

LTANKS:

Name:	MICELI HOME
Address:	194 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0604103 / 2006-10-22
Facility ID:	0604103
Site ID:	366997
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-10-22
Spiller Name:	MARIO MICELI
Spiller Company:	MICELI HOME
Spiller Address:	194 CENTRE AVE
Spiller County:	001
Spiller Contact:	MARIO MICELI
Spiller Phone:	(914) 235-2198
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317018
DEC Memo:	"CLOSING REPORT TO JOHN O'DEE. October 22, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 23.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 gallon tank had holes"

MICELI HOME (Continued) **S108059468**

All Materials:

Site ID:	366997
Operable Unit ID:	1124924
Operable Unit:	01
Material ID:	2114431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF364 **BRIEN-AMIE RESIDENCE** **NY LTANKS** **S105999591**
NW **105 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.396 mi.
2093 ft. **Site 2 of 6 in cluster BF**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	BRIEN-AMIE RESIDENCE
Address:	105 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0304963 / 2004-02-02
Facility ID:	0304963
Site ID:	219644
Spill Date:	2003-08-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-08-11
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-11
Spill Record Last Update:	2004-02-02
Spiller Name:	BRIEN-AMIE RESIDENCE
Spiller Company:	Not reported
Spiller Address:	105 SICKLES AVE
Spiller County:	001
Spiller Contact:	BRIEN-AMIE RESIDENCE
Spiller Phone:	(914) 576-6823
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181652
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

BRIEN-AMIE RESIDENCE (Continued) **S105999591**

O'DEE 08/11/03: 1000 gal. underground tank. 02/02/04 DUTCHESS DISPOSED OF LUST AND 75.35 TONS OF CONTAMINATED SOIL. SAMPLE RESULTS BELOW TAGM LIMITS. NFA jbo"

Remarks: "they were doing an inplace closure tank abandonment & encountered contaminated soil from the 550 gal underground tank - unk about soil removal at this point"

All Materials:

Site ID:	219644
Operable Unit ID:	873280
Operable Unit:	01
Material ID:	502238
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

365
SE
1/4-1/2
0.396 mi.
2093 ft.

SPILL NUMBER 0302495
85 NORTH AVE
NEW ROCHELLE, NY

NY LTANKS **S105999167**
NY Spills **N/A**

Relative:
Lower

Actual:
69 ft.

LTANKS:

Name:	SPILL NUMBER 0302495
Address:	85 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0302495 / 2003-08-12
Facility ID:	0302495
Site ID:	114935
Spill Date:	2003-06-09
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-06-09
CID:	405
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-08-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	85 NORTH AVE
Spiller County:	001

SPILL NUMBER 0302495 (Continued) **S105999167**

Spiller Contact:	DISPATCHER 629
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	100200
DEC Memo:	""
Remarks:	"caller states that there is an overspill at the above address - some has gone into the sewer - cell # 914-760-1305 is for the fire chief on scene - unknown if the spill is stopped or not"

All Materials:

Site ID:	114935
Operable Unit ID:	869316
Operable Unit:	01
Material ID:	506969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GAS STATION
Address:	85 NORTH AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0507677 / 2009-10-09
Facility ID:	0507677
Site ID:	353132
Spill Date:	2005-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jkomara
Referred To:	WCDOH
Reported to Dept:	2005-09-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2009-10-09
Spiller Name:	FRANK
Spiller Company:	GAS STATION
Spiller Address:	85 NORTH AVE.
Spiller County:	001
Spiller Contact:	FRANK
Spiller Phone:	(914) 632-2109
Spiller Extention:	Not reported
DEC Region:	3

SPILL NUMBER 0302495 (Continued) **S105999167**

DER Facility ID: 100200
DEC Memo: "9/28/05 Also see spills 03-04446, 05-11827 and 05-07653. jod Closure report received and site visit with WCHD performed. NFA if no money State money spent on Spill # 0304446 pin # 03236. 4/5/07 JO'M 10/9/09 Closed this spill refer to 0304446 JO'M"
Remarks: "LINE FAILURE."

All Materials:
Site ID: 353132
Operable Unit ID: 1110599
Operable Unit: 01
Material ID: 2100636
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: FRANKIES AUTO
Address: 85 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0507653 / 2005-10-07
Facility ID: 0507653
Facility Type: ER
DER Facility ID: 100200
Site ID: 353098
DEC Region: 3
Spill Cause: Unknown
Spill Class: B3
SWIS: 6010
Spill Date: 2005-09-26
Investigator: JKOMARA
Referred To: WCDOH
Reported to Dept: 2005-09-26
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-09-26
Spill Record Last Update: 2005-10-07
Spiller Name: FRANK
Spiller Company: FRANKIES AUTO
Spiller Address: 85 NORTH AVE.
Spiller Company: 001
Contact Name: FRANK
DEC Memo: "9/28/05 Also see spills 03-04446, 03-11827 and 05-07677. jod

SPILL NUMBER 0302495 (Continued) **S105999167**

10/07/05 Refer to spill 05-07677 for all updates. This spill number closed. jod"

Remarks: "GASOLINE IN SANITARY SEWER NEXT TO STATION AND ODORS: PLEASE CALL DOH ON THIS ISSUE"

All Materials:

Site ID:	353098
Operable Unit ID:	1110568
Operable Unit:	01
Material ID:	2100602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD366 **POWERTEST,ECHO & MAIN** **NY LTANKS** **S100139866**
ENE **36 ECHO AVE @ MAIN ST.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.399 mi.
2106 ft. **Site 3 of 6 in cluster BD**

Relative: **Lower**

Actual: **33 ft.**

LTANKS:

Name:	POWERTEST,ECHO & MAIN
Address:	36 ECHO AVE @ MAIN ST.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8709260 / 1988-02-11
Facility ID:	8709260
Site ID:	283199
Spill Date:	1988-01-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-02-11
SWIS:	6010
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-02-01
Spill Record Last Update:	1988-06-13
Spiller Name:	Not reported
Spiller Company:	HACKER,JOSHUA;POWERTEST
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

POWERTEST,ECHO & MAIN (Continued) **S100139866**

Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 229700
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 02-01-88 TANK REPLACED 5 YRS.AGO. AS PER DEPUTY CHIEF WILLIAM COMVERY,BASEMENT ODORS GREATLY DISSAPATED, ONCE VENTED. 02/11/88: CHECKED STATION; SEEMS TO BE ODOR PROBLEM DURING DELIVERIES. 11/29/95: This is additional information about material spilled from the translation of the old spill file: FUMES."
Remarks: "DELIVERY THIS MORNING, ONGOING PROBLEM, EXPLOSIVE READING IN BASEMENT. NEW ROCHELLE F.D. HAS VENTED BASEMENT AND WILL MONITOR."

All Materials:
Site ID: 283199
Operable Unit ID: 914517
Operable Unit: 01
Material ID: 464589
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BF367 **POINVIL RESIDENCE** **NY LTANKS** **S111160012**
NW **107 SICKLES AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.399 mi.
2108 ft. **Site 3 of 6 in cluster BF**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:
Name: POINVIL RESIDENCE
Address: 107 SICKLES AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1104844 / 2014-11-05
Facility ID: 1104844
Site ID: 452458
Spill Date: 2011-07-28
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: Unassigned
Referred To: Not reported
Reported to Dept: 2011-07-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2011-07-28

POINVIL RESIDENCE (Continued) **S111160012**

Spill Record Last Update:	2017-08-10
Spiller Name:	HENRY POINVILE
Spiller Company:	POINVILE
Spiller Address:	107 SICKLES AVE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	407046
DEC Memo:	"7-28-11 Spoke with Kathy Morgan, This a is a real estate transaction. The plan at this time is to uncover, isolate and retest. The tank is 1080 gallon UST that is probably the original tank - age unknown. jm 2/17/12: Residential TTF, DEC Lead changed to unassigned. jod 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M 08/10/17 Spoke to the present homeowner who stated that she is attempting to sell the house and that this TTF came up during the transaction. She stated that she not informed by the previous owner that the tank failed a tank test. She is planning to have the tank removed. She was advised to speak to her attorney about the previous owners statement that nothing was wrong with the tank. TG"
Remarks:	"repair/retest pending -"

All Materials:

Site ID:	452458
Operable Unit ID:	1202639
Operable Unit:	01
Material ID:	2199228
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BB368 **AMOCO SERVICE STATION #736** **NY LTANKS** **1001128018**
SSW **690 MAIN ST** **NY Spills** **NYR000036855**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.402 mi. **NY MANIFEST**
2122 ft. **Site 3 of 3 in cluster BB**

Relative: **Lower**
Actual: **64 ft.**

LTANKS:

Name:	RACE TANK INC
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209490 / 2002-12-16
Facility ID:	0209490
Site ID:	274754
Spill Date:	2002-12-16
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-16
CID:	246
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2002-12-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	DAVE BERRY
Spiller Phone:	(914) 231-1905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"Tanker overfilled tank and material spilled at location. Approx 10 gal went into storm drain and sewer. Fire dept on scene now speedy dry applied"

All Materials:

Site ID:	274754
Operable Unit ID:	862563
Operable Unit:	01
Material ID:	512914
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

Name:	RACE TANK INC
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0212950 / 2003-04-01
Facility ID:	0212950
Site ID:	274755
Spill Date:	2003-03-31
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-03-31
CID:	211

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-31
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	WESTCHESTER CO 911
Spiller Phone:	(914) 231-1904
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"PRODUCT DID ENTER CONTAINMENT AREA - NO CLEAN UP"

All Materials:

Site ID:	274755
Operable Unit ID:	863771
Operable Unit:	01
Material ID:	512669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8604411 / 1987-01-14
Facility ID:	8604411
Site ID:	274757
Spill Date:	1986-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1987-01-14
SWIS:	6010
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-01-14
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Remediation Phase:	0
Date Entered In Computer:	1986-10-16
Spill Record Last Update:	1998-03-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	223479
DEC Memo:	""
Remarks:	"TTTF"

All TTF:

Facility ID:	8604411
Spill Number:	8604411
Spill Tank Test:	1530280
Site ID:	274757
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	274757
Operable Unit ID:	901332
Operable Unit:	01
Material ID:	477220
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	AMOCO GAS STATION
Address:	690 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9111342 / 1997-12-10
Facility ID:	9111342
Facility Type:	ER
DER Facility ID:	101511

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Site ID:	116684
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1992-02-03
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1992-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-02-04
Spill Record Last Update:	2004-08-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 09/26/97 LETTER SENT; VES SYSTEM MUST BE OPERATING WITHIN ONE WEEK OR EXPLAIN WHY IT ISN'T GOING TO BE 12/10/97 LETTER & SIGNED STIPULATION SENT; NFA. SEE SPILL 96-13029 FOR UPDATES. jod"
Remarks:	"BALTEC ASSOC. ON SITE PERFORMING SOIL SURVEY TOOK SAMPLE BELOW GRADE AND FOUND FREE PRODUCT NO CALL BACK NEEDED"

All Materials:

Site ID:	116684
Operable Unit ID:	961469
Operable Unit:	01
Material ID:	416381
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	SUNOCO S/S
Address:	690 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9313209 / 1994-02-28
Facility ID:	9313209
Facility Type:	ER
DER Facility ID:	101511
Site ID:	116685
DEC Region:	3
Spill Cause:	Equipment Failure

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spill Class:	D4
SWIS:	6010
Spill Date:	1994-02-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-28
Spill Record Last Update:	1994-06-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/03/94: NO DEC RESPONSE. "
Remarks:	"ICE IN FILL BOX SORBENTS USED TO CLEAN UP"

All Materials:

Site ID:	116685
Operable Unit ID:	995095
Operable Unit:	01
Material ID:	388600
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AM0CO STATION 736
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0002007 / 2000-05-17
Facility ID:	0002007
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274753
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2000-05-17
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-05-17

AMOCO SERVICE STATION #736 (Continued) **1001128018**

CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-05-17
Spill Record Last Update:	2000-07-17
Spiller Name:	ALFRED
Spiller Company:	AM0CO STATION 736
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ALFRED
DEC Memo:	""
Remarks:	"maintance crew on the way for cleanup and repairs"

All Materials:

Site ID:	274753
Operable Unit ID:	823636
Operable Unit:	01
Material ID:	550387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	USA PETRO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0305414 / 2003-10-29
Facility ID:	0305414
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274756
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2003-08-21
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-08-21
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2003-10-29
Spiller Name:	Not reported
Spiller Company:	USA PETRO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	CINDY BADOLATO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BADOLATO 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED AS OF 9/12/03"
Remarks:	"leaking valve on a pump - pbs #3-183660 - pump taken out of service"

All Materials:

Site ID:	274756
Operable Unit ID:	873709
Operable Unit:	01
Material ID:	502669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9613029 / 2013-04-26
Facility ID:	9613029
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274758
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6010
Spill Date:	1997-01-29
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1997-02-04
CID:	312
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-04
Spill Record Last Update:	2013-04-26

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY ALSO SEE SPILL 91-11342. 02/07/97 AS PART OF AN ONGOING REMEDIATION THEY FOUND NEWER PRODUCT INFLUENCING THEIR CLEAN UP. 04/24/97 LETTER & STIPULATION AGREEMENT SENT TO BE SIGNED. 12/10/97 COPY OF SIGNED STIPULATION SENT BACK 08/11/98 LETTER SENT; IMMEDIATE ACTION TOWARD AUTOMATED PRODUCT REMOVAL AND GROUNDWATER CONTROL AT SITE IS REQUIRED. 12/07/00 LETTER SENT TO DELTA ENVIRONMENTAL BY J. HARDY; PROPOSE A REMEDIAL ACTION PLAN WHICH IS SUBSTANTIALLY MORE AGRESSIVE THAN THE ONE EXISTING AT THIS TIME. 01/11/01 LETTER SENT TO DELTA ENV. BY J. HARDY; CONCEPTUAL REMEDIAL ACTION PLAN OF 12/13/00 IS APPROVED & REQUIRED. 4/23/04: Letter to Aaron Lapine, Delta Env. Consultants by J. Hardy. Submit one report per year. Include operating data and GW monitoring data in same report. 8/9/04: Letter to A. Lapine, Delta Env. from J Hardy. Reduce monitor well sampling to semi-annual. Report annually. 6/15/09 annual submitted 6/9/09 shows relatively stable groundwater levels but no info as to system operation--sent email to envirotrac to submit operation info jh 4/20/10 site in remediation as system has been operating for many years. Original impacts to adjoining restaurant have also been resolved for years so it seems spill is contained; spill cannot be closed however as there is still significant contamination jh 07/02/12 Contaminated soils on the station have been excavated down to bedrock. 4 gw wells remain, 1 on-site upgradient, 2 off-site downgradient , 1 in the tank field. After review of the documentation and a phone conversation, consultant will submit a quarterly groundwater monitoring plan for the next year, after which time the monitoring frequency may be adjusted based on results. It appears the source has been removed. mt 4/26/13 Spill Closed, asymptptic conditions approaching gw standards in final well. no further action required. mt "
Remarks:	"THEY HAVE A 1991 SPILL NUMBER, BUT THIS APPEARS TO BE A FRESH SPILL UNK IF SAME"

All Materials:

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	2096843
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	274758
Operable Unit ID:	1040708
Operable Unit:	01
Material ID:	341679
Material Code:	0009
Material Name:	gasoline

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	AMOCO
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9806161 / 2005-02-14
Facility ID:	9806161
Facility Type:	ER
DER Facility ID:	223479
Site ID:	274759
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	1998-08-18
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1998-08-18
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-18
Spill Record Last Update:	2005-02-14
Spiller Name:	ERIC LISMANIS
Spiller Company:	AMOCO
Spiller Address:	690 MAIN ST
Spiller Company:	001
Contact Name:	ERIC LISMANIS
DEC Memo:	"2/14/05 HANDLE AS PART OF 9613029--CLSOE"
Remarks:	"PUMP MALFUNCTION FOR UNDERGROUND STORAGE TANK / NO CLEAN UP"

All Materials:

Site ID:	274759
Operable Unit ID:	1067358
Operable Unit:	01
Material ID:	317336
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	AMOCO SERVICE STATION #736
Handler Address:	690 MAIN ST
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYR000036855
Contact Name:	Not reported
Contact Address:	OLD POST RD
Contact City,State,Zip:	BEDFORD, NY 10506
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	OLD POST RD
Mailing City,State,Zip:	BEDFORD, NY 10506
Owner Name:	AMOCO CORP
Owner Type:	Private
Operator Name:	AMOCO CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AMOCO CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	300 INTERPACE PKWY MORRIS CORP
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054-1177
Owner/Operator Telephone:	201-331-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AMOCO CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	300 INTERPACE PKWY MORRIS CORP
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054-1177
Owner/Operator Telephone:	201-331-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	AMOCO CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	300 INTERPACE PKWY MORRIS CORP
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054-1177
Owner/Operator Telephone:	201-331-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name:	AMOCO SERVICE STATION #736
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	AMOCO SERVICE STATION #736
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	AMOCO SERVICE STATION #736
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19970321
Handler Name:	AMOCO SERVICE STATION #736
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

AMOCO SERVICE STATION #736 (Continued) **1001128018**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	AMOCO SERVICE STATION #736
Address:	690 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYR000036855
Facility Status:	Not reported
Location Address 1:	690 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000036855
Mailing Name:	AMOCO SERVICE STATION #736
Mailing Contact:	JONATHAN LANDAU
Mailing Address 1:	130 BUSINESS PARK DR
Mailing Address 2:	Not reported
Mailing City:	ARMONK
Mailing State:	NY
Mailing Zip:	10504
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142349580

BH369 **RESIDENCE** **NY LTANKS** **S107523528**
East **10 LAFAYETTE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.403 mi.
2126 ft. **Site 1 of 3 in cluster BH**

Relative: **Lower**
Actual: **47 ft.**

LTANKS:

Name:	RESIDENCE
Address:	10 LAFAYETTE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0512638 / 2006-03-15
Facility ID:	0512638
Site ID:	358990
Spill Date:	2006-02-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-01
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-01
Spill Record Last Update:	2006-03-15
Spiller Name:	MARIO KOTLAR
Spiller Company:	RESIDENCE
Spiller Address:	10 LAFFEYTE ST
Spiller County:	001
Spiller Contact:	MARIO KOTLAR
Spiller Phone:	(914) 235-8882
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	308993
DEC Memo:	"Northeast to return 2/3/06 for soil excavation & sampling. March 15, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 42.57 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 1000 gallon."

All Materials:

Site ID:	358990
Operable Unit ID:	1116216
Operable Unit:	01
Material ID:	2106363
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE370 **YOUNG ADULT INSTITUTE** **NY LTANKS** **S107410752**
WNW **150 VAN GUILDER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.403 mi.
2128 ft. **Site 2 of 2 in cluster BE**

Relative: **Lower**

Actual: **77 ft.**

LTANKS:

Name:	YOUNG ADULT INSTITUTE
Address:	150 VAN GUILDER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0507808 / 2005-12-18
Facility ID:	0507808
Site ID:	353295
Spill Date:	2005-09-29
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-29
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-29
Spill Record Last Update:	2005-12-18
Spiller Name:	MARGARET FORC
Spiller Company:	YOUNG ADULT INSTITUTE
Spiller Address:	150 VAN GUILDER AVE
Spiller County:	001
Spiller Contact:	MARGARET FORC
Spiller Phone:	(212) 273-6172
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300615
DEC Memo:	"Left message with contact. Robison returning to clean up fuel in street. New England was removing UST and some product leaked out of tank on ground. Area roped off by Fire Marshal. December 18, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 13.63 TONS OF CONTAMINATED SOIL. CLEAN UP COMPLETED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. DISPOSAL RECEIPT FORWARDED TO BECI. jod"
Remarks:	"550 GALLON TANK AND FOUND HOLES: FIRE MARSHALL ON SCENE"

All Materials:

Site ID:	353295
Operable Unit ID:	1110757
Operable Unit:	01
Material ID:	2100797
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

YOUNG ADULT INSTITUTE (Continued) **S107410752**

Units: G
Recovered: .00
Oxygenate: Not reported

BI371 **COMMERCIAL-TTF** **NY LTANKS** **S117975659**
West **172 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.403 mi.
2129 ft. **Site 1 of 3 in cluster BI**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	COMMERCIAL-TTF
Address:	172 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1502358 / 2020-09-01
Facility ID:	1502358
Site ID:	508618
Spill Date:	2015-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2020-09-01
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	463301
DEC Memo:	"6/3/15 Spoke to Mr. Scorzelli, who did not have contact info for owner at that time, and does not know what owner will be doing. dw 9/01/20: Tank was removed by JM Associates in April of 2018. Tank was not leaking, no contamination was evident. Tank closure report from Gallagher Bassett Technical Services received and will be scanned into DecDocs. jod"
Remarks:	"TEST FAILURE"

All Materials:

Site ID:	508618
Operable Unit ID:	1257927
Operable Unit:	01

COMMERCIAL-TTF (Continued) **S117975659**

Material ID:	2260991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BF372 **GONZALO RESIDENCE** **NY LTANKS S108299038**
NW **112 SICKLES AVE** **NY Spills N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.406 mi.
2142 ft. **Site 4 of 6 in cluster BF**

Relative: **Lower**
Actual: **69 ft.**

LTANKS:

Name:	GONZALO RESIDENCE
Address:	112 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0610140 / 2007-10-24
Facility ID:	0610140
Site ID:	374522
Spill Date:	2006-12-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-12-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-06
Spill Record Last Update:	2007-10-24
Spiller Name:	ISMAIL GALVAN
Spiller Company:	Not reported
Spiller Address:	112 SICKLES AVE
Spiller County:	001
Spiller Contact:	ISMAIL GALVAN
Spiller Phone:	(914) 224-3193
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	324199
DEC Memo:	"09/18/07 Dutchess Environmental reported that the 550 gallon tank was removed and that no sign of oil contamination was observed in the tank grave. NFA TG"
Remarks:	"UNCOVER REPAIR AND TEST OR REMOVE"

All TTF:

GONZALO RESIDENCE (Continued) **S108299038**

Facility ID:	0610140
Spill Number:	0610140
Spill Tank Test:	1550484
Site ID:	374522
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	374522
Operable Unit ID:	1132196
Operable Unit:	01
Material ID:	2121918
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	TAHIR RESIDENCE
Address:	112 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0911724 / 2010-03-22
Facility ID:	0911724
Facility Type:	ER
DER Facility ID:	324199
Site ID:	424559
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	6010
Spill Date:	2010-02-02
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

GONZALO RESIDENCE (Continued) **S108299038**

Last Inspection:	2010-02-12
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2010-03-22
Spiller Name:	CHRIS
Spiller Company:	PARADISE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ISHMAEL TAHIR
DEC Memo:	"2/3/10 homeowner, Mr. Tahir, is satisfied with cleanup done by Paradise Oil Co., both inside and outside the house. NFA dw 2/12/10: Spill re-opened. WCDOH reported this spill, after complaints by home owner that the oil company had taken no action. Marc Grazioli re-inspected the site today and reports the spill has still not been remediated. jod 2/17/10: Update from Marc Grazioli: The outside portion of the spill was handled before the big snow that came last week. I was only able to look into the basement through an open window since no one was home when I was there. There was absorbent on the ground and I would guess it was the second round of cleanup because it appeared dry. jod 3/22/10: DEC requires no further action at this time. jod"
Remarks:	"5gals oil to basement area/10 gals to out side,driveway. Clean up complete"

All Materials:

Site ID:	424559
Operable Unit ID:	1180325
Operable Unit:	01
Material ID:	2174200
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BD373 **GAS STATION** **NY LTANKS** **S116156793**
ENE **44 ECHO AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.406 mi.
2145 ft. **Site 4 of 6 in cluster BD**

Relative: **Lower**
Actual: **32 ft.**

LTANKS:

Name:	GAS STATION
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1309599 / 2014-02-13
Facility ID:	1309599
Site ID:	490405
Spill Date:	2014-01-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3

GAS STATION (Continued) **S116156793**

Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-02
Spill Record Last Update:	2014-02-13
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CARLOS TORREZ
Spiller Phone:	(914) 424-5927
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"1/2/14 - WCDOH is oversight the ongoing tank tests. KAB 1/2/2014 -- APECCO hired by new operator (lease signed within past 6 weeks). Piping and dispensers and electronic leak monitoring equipment to be replaced. Based on lack of leak detection records for past 10 to 12 years, DEC requested TT and IS tests and system check of electronics. Tanks are probably suitable for service, but testing required for confirmation. It appears to be loose fittings. Electronics recently rewired at the computer console within past couple of weeks, but wiring ended near the top of the tanks. No probes in the interstitial space, just loose wiring near top of tank. Owner's representative took electronic system wire ends from the site despite WCDOH's request to take custody. ELM 2-13-14 closed and referred to spill 13-10365 which revealed contaminated soils when the failed lines were removed. RDB"
Remarks:	"repair/retest pending - to Ed Moore (waiting for results)"

All Materials:

Site ID:	490405
Operable Unit ID:	1239966
Operable Unit:	01
Material ID:	2240056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BD374 **MARIO'S S/S** **NY LTANKS** **S110309404**
ENE **44 ECHO AVENUE** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.406 mi.
2145 ft. **Site 5 of 6 in cluster BD**

Relative: **Lower**

Actual: **32 ft.**

LTANKS:

Name:	DAVENPORT AUTO / WEST PLAINS SERVICE
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1001469 / 2010-11-01
Facility ID:	1001469
Site ID:	434525
Spill Date:	2010-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-05-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-07
Spill Record Last Update:	2010-11-01
Spiller Name:	Not reported
Spiller Company:	OWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	INA -
Spiller Phone:	(914) 235-8073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389397
DEC Memo:	"5/7/10 Metro Env. tested UST, and it failed a TT. Davenport Auto thinks it may be fuel lines, and got list of contractors to examine problem more closely, and to determine remedial actions. Site is a WCHD-PBS site# 3-137480 Tank was tank #6- 550 gal. dw 11/1/10 As per WCDOH Two tanks pulled, reviewed TCR, recommend NFA. NFA JOM "
Remarks:	"tank test - cleanup pending"

All Materials:

Site ID:	434525
Operable Unit ID:	1185347
Operable Unit:	01
Material ID:	2179667
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

MARIO'S S/S (Continued) **S110309404**

Oxygenate:	Not reported
Name:	MARIO'S S/S
Address:	44 ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9201557 / 2006-02-17
Facility ID:	9201557
Site ID:	130487
Spill Date:	1992-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	1992-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-05-08
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309856
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/17/06 SEE SPILLS 92-10118 AND 92-10810. jod"
Remarks:	"FOUND LINE LEAKING AT DISPENSER GASOLINE TANK IS OK MAIN & ELMSFORD TO POSS. REPAIR MONDAY WILLIAMS SUGGESTED TO MAIN & ELMSFORD CO. THAT THEUY SHUT THIS PUMP DOWN UNTIL REPAIRS ARE MADE SPOKE W/ WILL"

All TTF:

Facility ID:	9201557
Spill Number:	9201557
Spill Tank Test:	1539973
Site ID:	130487
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

MARIO'S S/S (Continued) **S110309404**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 130487
Operable Unit ID: 968828
Operable Unit: 01
Material ID: 412859
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Name: SCOTT S/S
Address: 44 ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9210810 / 1995-02-09
Facility ID: 9210810
Site ID: 130489
Spill Date: 1992-12-17
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C3
Cleanup Ceased: 1995-02-09
SWIS: 6010
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1992-12-18
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1992-12-18
Spill Record Last Update: 2006-02-17
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 309856
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks: "E.I.R. PETRO-TITE"

MARIO'S S/S (Continued) **S110309404**

All TTF:

Facility ID:	9210810
Spill Number:	9210810
Spill Tank Test:	1540972
Site ID:	130489
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	130489
Operable Unit ID:	975022
Operable Unit:	01
Material ID:	404252
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SCOT S/S
Address:	44 ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9210118 / 1997-11-07
Facility ID:	9210118
Facility Type:	ER
DER Facility ID:	309856
Site ID:	130488
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	1992-12-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported

MARIO'S S/S (Continued) **S110309404**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-15
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"GASOLINE ODOR IN BASEMENT OF APARTMENT BUILDING NEXT DOOR TO GAS STATION GAS STATION RECEIVED A DELIVERY AT 8:00 A.M. T. GHIOSAY RESPONDED"

All Materials:

Site ID:	130488
Operable Unit ID:	976578
Operable Unit:	01
Material ID:	407123
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	ECHO SERVICE STATION
Address:	44 ECHO AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1310365 / 2016-07-26
Facility ID:	1310365
Facility Type:	ER
DER Facility ID:	389397
Site ID:	491212
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2014-01-29
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

MARIO'S S/S (Continued) **S110309404**

Remediation Phase:	0
Date Entered In Computer:	2014-01-29
Spill Record Last Update:	2016-07-26
Spiller Name:	Not reported
Spiller Company:	WEST PLAINS SERVICE INC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MICHAEL BURNSTEIN
DEC Memo:	"Chris Lalak called duty desk. American Petro is pulling tanks today. WCDOH is handling this and will do follow up...mm 1/29/2014 -- Called Pat Dunn @ APECCO to get some details. Dispensers had no sumps; discovered soil contamination under a dispenser. Trench along side dispenser is clean to 2 1/2 feet below grade; they expect limited dig and haul. ELM 2-11-14 lyt was not a tank pull as originally noted by WCHD only line and dispenser replacement. RDB 2-13-14, spill #13-09599 was closed and referred to this one, the line test failure led to thic contamination RDB 03-14 contamination deep in excavation under former dispenser. crews worried about garage and building under neath, met on site with Gary and owner, advised them additional soil needed removal. 03-10-14 Using a Hydro Vac to get the remaining contaminated soils from excavation. 03-18-14 status report in edocs 05-13-14 email from Gary, Work done, report done,plan on forwarding report to you today once we get payment. RDB 07-22-14 gary looking for closure, I am looking for closure report.sent email requesting RDB 7-25-16 TCR submitted- Spill closed RDB"
Remarks:	"cleanup in progress"

All Materials:

Site ID:	491212
Operable Unit ID:	1240767
Operable Unit:	01
Material ID:	2240992
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BH375 **GONCALVES RESIDENCE** **NY LTANKS** **S102674341**
East **1 LAFFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.407 mi.
2150 ft. **Site 2 of 3 in cluster BH**

Relative:
Lower

Actual:
37 ft.

LTANKS:

Name:	GONCALVES RESIDENCE
Address:	1 LAFFAYETTE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9410991 / 1994-11-29
Facility ID:	9410991
Site ID:	156301
Spill Date:	1994-11-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling

GONCALVES RESIDENCE (Continued) **S102674341**

Spill Class:	C3
Cleanup Ceased:	1994-11-29
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132292
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CUSTOMER ORDERED 100 GAL. COULDN'T FIT BEING CLEANED NOW SPEEDI-DRI AND PADS COMPLETED"

All Materials:

Site ID:	156301
Operable Unit ID:	1008868
Operable Unit:	01
Material ID:	376855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG376 **200 CENTRA CORP** **NY LTANKS** **S108059537**
SSE **200 CENTER AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.411 mi.
2169 ft. **Site 2 of 4 in cluster BG**

Relative: **Lower**

Actual: **77 ft.**

LTANKS:

Name:	200 CENTRA CORP
Address:	200 CENTER AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0604650 / 2007-12-12
Facility ID:	0604650
Site ID:	367663

200 CENTRA CORP (Continued) **S108059537**

Spill Date:	2006-07-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2006-07-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-25
Spill Record Last Update:	2007-12-12
Spiller Name:	SHARON ROURKE
Spiller Company:	200 CENTRA CORP
Spiller Address:	200 CENTRE AVE
Spiller County:	001
Spiller Contact:	SHARON ROURKE
Spiller Phone:	(203) 557-3600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	317637
DEC Memo:	"12/04/06 Tank removed and samples ok according to D Jackson - WCHD. TG"
Remarks:	"PBS No: 3-800237 -PBS No. not found in UIS, may be invalid. UNCOVER REPAIR AND TEST"

All TTF:

Facility ID:	0604650
Spill Number:	0604650
Spill Tank Test:	1550151
Site ID:	367663
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	367663
Operable Unit ID:	1125568
Operable Unit:	01
Material ID:	2115091

200 CENTRA CORP (Continued) **S108059537**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD377 **CONSOLIDATED EDISON - ECHO AVE. SITE** **NY SHWS** **S101008407**
ENE **ECHO AVENUE** **NY ENG CONTROLS** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY INST CONTROL**
0.412 mi.
2173 ft. **Site 6 of 6 in cluster BD**

Relative:
Lower

Actual:
30 ft.

SHWS:

Name:	CONSOLIDATED EDISON - ECHO AVE. SITE
Address:	ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Program:	HW
Site Code:	56077
Classification:	C
Region:	3
Acres:	2.613
HW Code:	360016
Record Add:	11/18/1999
Record Upd:	04/07/2021
Updated By:	AMOMOROG
Site Description:	"Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem:	"Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

	yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1981
Lat/Long:	40:54:40:0 / 73:46:24:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	neil o'halloran
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	new rochelle public library
Owner Address:	1 library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	03
Owner Name:	neil o'halloran
Owner Company:	Con Edison
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

ENG CONTROLS:
Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
HW Code: 360016
Control Code: 15
Control Type: ENG
Date Record Added: 12/21/2020
Date Rec Updated: 03/02/2021
Updated By: JTSPELLM
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "

Health Problem:	"Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1981
Lat/Long:	40:54:40:0 / 73:46:24:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	neil o'halloran
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	new rochelle public library
Owner Address:	1 library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	03

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Name:	neil o'halloran
Owner Company:	Con Edison
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America
HW Code:	360016
Waste Type:	PCBS (B007)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD981141252
Cross Ref Type Code:	05
Cross Ref Type:	CERCLA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS
Crossref ID:	W3-0531-91-02
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-03-22 17:09:00
Record Updated:	2021-03-22 17:09:00
Updated By:	JTSPELLM
Crossref ID:	570883402
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-05-24 12:03:00
Record Updated:	2017-05-24 12:03:00
Updated By:	GWHEITZM

INST CONTROL:

Name:	CONSOLIDATED EDISON - ECHO AVE. SITE
Address:	ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	56077
Control Name:	Ground Water Use Restriction
HW Code:	360016
Control Code:	08
Control Type:	INST
Dt record added:	12/21/2020
Dt rec updated:	03/02/2021
Updated By:	JTSPELLM
Site Code:	56077
Site Description:	"Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."

Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran
Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
Control Name: Soil Management Plan
HW Code: 360016
Control Code: 14
Control Type: INST
Dt record added: 12/21/2020
Dt rec updated: 03/02/2021
Updated By: JTSPELLM
Site Code: 56077
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."

Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
Control Name: Landuse Restriction
HW Code: 360016
Control Code: 25
Control Type: INST
Dt record added: 12/21/2020
Dt rec updated: 03/02/2021
Updated By: JTSPELLM
Site Code: 56077
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle,

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."

Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran
Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
Control Name: Monitoring Plan
HW Code: 360016

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Control Code: 31
Control Type: INST
Dt record added: 12/21/2020
Dt rec updated: 03/02/2021
Updated By: JTSPELLM
Site Code: 56077
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "
Health Problem: "Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran
Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Name:	CONSOLIDATED EDISON - ECHO AVE. SITE
Address:	ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Site Code:	56077
Control Name:	Site Management Plan
HW Code:	360016
Control Code:	32
Control Type:	INST
Dt record added:	12/21/2020
Dt rec updated:	03/02/2021
Updated By:	JTSPELLM
Site Code:	56077
Site Description:	"Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem:	"Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump:	False
Structure:	True
Lagoon:	False

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran
Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
Control Name: Deed Restriction
HW Code: 360016
Control Code: A
Control Type: INST
Dt record added: 12/21/2020
Dt rec updated: 03/02/2021
Updated By: JTSPELLM
Site Code: 56077
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

	Plan. "
Health Problem:	"Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1981
Lat/Long:	40:54:40:0 / 73:46:24:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	neil o'halloran
Owner Company:	Consolidated Edison of New York, Inc.
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	new rochelle public library
Owner Address:	1 library plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	new rochelle, NY 10801
Owner Country:	United States of America
Own Op:	1
Sub Type:	03
Owner Name:	neil o'halloran
Owner Company:	Con Edison
Owner Address:	eh&S remediation
Owner Addr2:	31-01 20th ave
Owner City,St,Zip:	astoria, NY 11105
Owner Country:	United States of America
HW Code:	360016
Waste Type:	PCBS (B007)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD981141252
Cross Ref Type Code:	05
Cross Ref Type:	CERCLA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

Name: CONSOLIDATED EDISON - ECHO AVE. SITE
Address: ECHO AVENUE
City,State,Zip: NEW ROCHELLE, NY 10801
Site Code: 56077
Control Name: IC/EC Plan
HW Code: 360016
Control Code: 34
Control Type: INST
Dt record added: 12/21/2020
Dt rec updated: 03/02/2021
Updated By: JTSPELLM
Site Code: 56077
Site Description: "Location The Site is located at 78 Echo Avenue in New Rochelle, Westchester County, New York. The 2.6 acre site is bordered to the north by Echo Bay, an estuary of the Long Island Sound. It is bordered to the east and south by residential properties, to the southwest by Echo Bay Avenue, and to the west by a landscaping company (formerly a fuel oil terminal). Site Features All the former structures and underground utility services have been removed. There are no buildings on the site. The site is flat with a vegetative cover. The site is adjacent to Echo Bay on Long Island Sound. Current Use The site is currently vacant. The surrounding parcels consist of a combination of commercial and residential uses. The nearest residence is adjacent to the site. Past Use of the Site Con Edison used the site as an electrical distribution substation until 1981. Transformers containing PCBs were stored and used at the site. Leaks and spills of PCBs may have occurred in the handling or servicing of these transformers. Site Geology and Hydrogeology The overburden at the site varies from four to 18 feet in thickness and is composed chiefly of well-sorted sand and silt with lesser amounts of clay and gravel. The overburden is underlain by an biotite garnet schist. The groundwater table, at an approximate ten-foot depth, is tidally influenced and generally flows from the southwest to the northeast."
Env Problem: "Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compolounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Off-site sediments in the adjacent Echo bay were analyzed for PCBs. Based upon investigations conducted to date, the primary contaminant of concern was PCBs. PCBs were detected in on-site soil and in substation structures at concentrations up to 47 ppm. PCBs were also found off site in the surface soil of four residential yards at concentrations above 1 ppm. PCBs were not detected in groundwater. However, arsenic, cadmium and chromium were present at

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

concentrations exceeding class GA groundwater standards. PCBs were found in a limited area of Echo Bay shallow sediments, ranging to 232 ppm. Post-Remediation Remediation at the site is complete. Prior to remediation the primary contaminant of concern was PCBs in soil and sediment. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Remedial actions have been completed and measures are place to control the potential for exposures to residual contamination remaining in soil and groundwater. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1981
Lat/Long: 40:54:40:0 / 73:46:24:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 1999-11-18 12:00:00
Updated By: INITIAL
Own Op: 3
Sub Type: NNN
Owner Name: Not reported
Owner Company: CONSOLIDATED EDISON OF NEW YORK, INC
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: neil o'halloran
Owner Company: Consolidated Edison of New York, Inc.
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: new rochelle public library
Owner Address: 1 library plaza
Owner Addr2: Not reported
Owner City,St,Zip: new rochelle, NY 10801
Owner Country: United States of America
Own Op: 1
Sub Type: 03
Owner Name: neil o'halloran
Owner Company: Con Edison
Owner Address: eh&S remediation
Owner Addr2: 31-01 20th ave
Owner City,St,Zip: astoria, NY 11105
Owner Country: United States of America
HW Code: 360016
Waste Type: PCBS (B007)

CONSOLIDATED EDISON - ECHO AVE. SITE (Continued) **S101008407**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD981141252
Cross Ref Type Code: 05
Cross Ref Type: CERCLA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: W3-0531-91-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-03-22 17:09:00
Record Updated: 2021-03-22 17:09:00
Updated By: JTSPELLM
Crossref ID: 570883402
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-24 12:03:00
Record Updated: 2017-05-24 12:03:00
Updated By: GWHEITZM

BI378 **FIRST ASSEMBLY OF GOD** **NY LTANKS** **S110490783**
West **177 UNION AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.413 mi.
2181 ft. **Site 2 of 3 in cluster BI**

Relative: **Lower**
Actual: **75 ft.**

LTANKS:

Name:	FIRST ASSEMBLY OF GOD
Address:	177 UNION AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1002183 / 2010-08-30
Facility ID:	1002183
Site ID:	435290
Spill Date:	2010-05-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-26
Spill Record Last Update:	2010-08-30
Spiller Name:	Not reported
Spiller Company:	BARNABY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BARNABY

FIRST ASSEMBLY OF GOD (Continued) **S110490783**

Spiller Phone:	(914) 632-0031
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	390193
DEC Memo:	"7/1/10: No call backs made by dispatch desk. No indication of contamination at the time of the report. Unknown action at this time. jod 08/19/10 Northeast Environmental reported that they excavated and removed the LUST along with 40.92 tons of petroleum contaminated soil. Post excavation TAGM soil sample results were below DEC guidance values. NFA. TG"
Remarks:	"550gal ust"

All Materials:

Site ID:	435290
Operable Unit ID:	1186074
Operable Unit:	01
Material ID:	2180843
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

379
WSW
1/4-1/2
0.414 mi.
2188 ft.

48 1ST STREET **NY LTANKS** **S104279084**
48 1ST STREET **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
75 ft.

LTANKS:

Name:	48 1ST STREET
Address:	48 1ST STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9911183 / 1999-12-22
Facility ID:	9911183
Site ID:	116893
Spill Date:	1999-12-22
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	PJDECICC
Referred To:	Not reported
Reported to Dept:	1999-12-22
CID:	389
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-22

48 1ST STREET (Continued) **S104279084**

Spill Record Last Update:	1999-12-30
Spiller Name:	CALLER
Spiller Company:	CASTLE OIL CORPORTATION
Spiller Address:	290 LOCUST AVENUE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	101696
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO "
Remarks:	"caller reporting a spill of material from a tank overfill clean up was done no callback is necessary"

All Materials:

Site ID:	116893
Operable Unit ID:	1089889
Operable Unit:	01
Material ID:	296651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BH380 **GONCALVES RESIDENCE** **NY LTANKS** **S108298870**
East **1 LAFAYETTE STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.415 mi.
2191 ft. **Site 3 of 3 in cluster BH**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Name:	GONCALVES RESIDENCE
Address:	1 LAFAYETTE STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0609401 / 2007-01-10
Facility ID:	0609401
Site ID:	373629
Spill Date:	2006-11-15
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-11-15
CID:	410
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

GONCALVES RESIDENCE (Continued) **S108298870**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-15
Spill Record Last Update:	2007-01-10
Spiller Name:	ED ALLEN
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323367
DEC Memo:	""
Remarks:	"CLEANUP IN PROGRESS:"

All Materials:

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

Site ID:	373629
Operable Unit ID:	1131331
Operable Unit:	01
Material ID:	2121025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF381 **RESIDENCE** **NY LTANKS** **S107410404**
NW **7 PRINCE ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.415 mi.
2193 ft. **Site 5 of 6 in cluster BF**

Relative:
Lower

Actual:
67 ft.

LTANKS:

Name:	RESIDENCE
Address:	7 PRINCE ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0506424 / 2005-10-29
Facility ID:	0506424
Site ID:	351640
Spill Date:	2005-08-24

RESIDENCE (Continued) **S107410404**

Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-24
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-24
Spill Record Last Update:	2005-10-29
Spiller Name:	JOHN BROWN
Spiller Company:	RESIDENCE
Spiller Address:	7 PRINCE ST
Spiller County:	001
Spiller Contact:	JOHN BROWN
Spiller Phone:	(914) 879-7900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	298912
DEC Memo:	"Report to John O'Dee -RA October 29, 2005: CASTLTON DISPOSED OF LUST AND 57.27 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

All Materials:

Site ID:	351640
Operable Unit ID:	1109140
Operable Unit:	01
Material ID:	2099127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BJ382 **TROY RESIDENCE** **NY LTANKS** **S105997625**
WNW **150 LOCKWOOD AV** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.417 mi.
2202 ft. **Site 1 of 2 in cluster BJ**

Relative:
Lower

Actual:
83 ft.

LTANKS:

Name:	TROY RESIDENCE
Address:	150 LOCKWOOD AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209497 / 2005-03-18

TROY RESIDENCE (Continued) **S105997625**

Facility ID:	0209497
Site ID:	221207
Spill Date:	2002-12-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2002-12-16
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2005-04-05
Spiller Name:	RICK TROY
Spiller Company:	RICK TROY
Spiller Address:	150 LOCKWOOD AV
Spiller County:	001
Spiller Contact:	RICK TROY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	182943
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - LALAK 12/16/02: WCDOH ON SITE. 140 TONS SOIL REMOVED. CLOSURE REPORT PENDING. 04/08/03: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 3/26/2003. Closure report from GFE has been reviewed. Groundwater samples must be collected. Result submitted to WCHD by May 12, 2003. PBS #3-601067 & 3-601068. 08/13/02: Letter to Lockwood Avenue, LLC, from Christopher Lalak, WCHD, dated 7/21/03. Further remediation and quarterly sampling is required. Results of sampling are to be submitted to WCDOH quarterly. First report due by 9/01/2003. 5/25/04: Letter to Lockwood Realty, LLC, from Christopher Lalak, WCDOH, dated 25May2004. Two rounds of sampling have been received, third is overdue. Third round must be received by 25Jun2004. 11/22/04: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 17Nov2004. Based on groundwater sampling results, closure report and inspections, sampling must continue for the next year on a quarterly basis. After sampling, site will be reviewed. Next results due 28Feb2005. 4/4/05: Letter to Lockwood Realty, LLC from C. Lalak, WCDOH dated 18Mar2005. Spill has been satisfactorily remediated. WCDOH requires NFA."
Remarks:	"CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL"

All Materials:

Site ID:	221207
Operable Unit ID:	860802
Operable Unit:	01
Material ID:	512920
Material Code:	0001A
Material Name:	#2 fuel oil

TROY RESIDENCE (Continued) **S105997625**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	LOCKWOOD MEDICAL CAMPUS
Address:	150 LOCKWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	2009121 / 2021-02-01
Facility ID:	2009121
Facility Type:	ER
DER Facility ID:	563977
Site ID:	616097
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	B2
SWIS:	6010
Spill Date:	2021-01-31
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2021-01-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-01-31
Spill Record Last Update:	2021-02-01
Spiller Name:	DONALD
Spiller Company:	SUPERINTENDENT
Spiller Address:	150 LOCKWOOD AVE
Spiller Company:	999
Contact Name:	DONALD
DEC Memo:	"2/1/21 Spoke to Donald, the superintendent of the medical facility bldg on 1/31. He claimed that the spill was only 1 pint into the sump, and that he cleaned it out. I then contacted Robison Oil, who reported the spill as 8 gal fuel oil. They said that the superintendent thought the day tank pump (20 gal) wasn't working and did something which released fuel oil from the day tank which went into the sump. They report that the sump was disconnected, and that it appeared to be full of fuel oil. They also said there did not appear to be any water in the sump. Spill was contained in the sump. I called Donald back and left a message telling him to keep the sump unplugged, and call an environmental cleanup contractor. I gave him several names of contractors. Robison sent a photo which shows a sump full of fuel oil. They did not do any cleanup as they said they had no responsibility in this incident. dw Update- I called Donald, who said that Robison was there on site fixing the day tank. Tech said

TROY RESIDENCE (Continued) **S105997625**

that the bldg had a service contract with Robison. He also said that the sump was dry and had been cleaned out. He said the sump had been pumped out by the superintendent, and the fuel was pumped back into the day tank. He said that the sump was also cleaned out with sorbents. Sump will remain unplugged. Based on onsite statements, spill seems to be closeable. NFA dw"

Remarks: "super Donald opened a valve on the day tank, oil drained and is now contained to sump pump"

All Materials:

Site ID:	616097
Operable Unit ID:	1363218
Operable Unit:	01
Material ID:	2375417
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	NEW ROCHELLE RADIOLOGY
Address:	150 LOCKWOOD AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0209877 / 2003-03-28
Facility ID:	0209877
Facility Type:	ER
DER Facility ID:	182943
Site ID:	221208
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6010
Spill Date:	2002-12-27
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-30
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-30
Spill Record Last Update:	2003-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""

TROY RESIDENCE (Continued) **S105997625**

Remarks: "CALLER WENT TO HAVE A MAMMOGRAM DONE & SHE STAATED THE ENTIRE BLDG SMELLED LIKE FUEL OIL - UNK IF IT HAD TO DO WITH THE CONSTRUCTION THAT WAS GOING ON IN THE PARKING LOT OR NOT"

All Materials:

Site ID:	221208
Operable Unit ID:	861114
Operable Unit:	01
Material ID:	513296
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF383 **RENTAL HOUSE** **NY LTANKS** **S100153568**
NW **119 SICKLES AVE.** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.420 mi.
2216 ft. **Site 6 of 6 in cluster BF**

Relative: **Lower**
Actual: **68 ft.**

LTANKS:

Name:	RENTAL HOUSE
Address:	119 SICKLES AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9107320 / 1991-11-25
Facility ID:	9107320
Site ID:	119461
Spill Date:	1991-10-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	HOULIHAN & LAWRENCE RLTY.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

RENTAL HOUSE (Continued) **S100153568**

DEC Region: 3
DER Facility ID: 103766
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "DISCOVERED SEEPAGE FROM TANK ON BASEMENT CONCRETE FLOOR APPLIED SPEEDI-DRY SPILLER WILL CONTACT LUZON OIL FOR CLEAN UP"

All Materials:
Site ID: 119461
Operable Unit ID: 961556
Operable Unit: 01
Material ID: 419532
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

BK384 **SPILL NUMBER 0104402** **NY LTANKS** **S105135031**
NE **30 LINCOLN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.425 mi.
2243 ft. **Site 1 of 2 in cluster BK**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:
Name: SPILL NUMBER 0104402
Address: 30 LINCOLN ST
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0104402 / 2001-11-14
Facility ID: 0104402
Site ID: 328750
Spill Date: 2001-07-24
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D3
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-07-25
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-25
Spill Record Last Update: 2002-02-07
Spiller Name: OWNER
Spiller Company: AVALLONE
Spiller Address: 30 LINCOLN ST
Spiller County: 001

SPILL NUMBER 0104402 (Continued) **S105135031**

Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	264577
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/14/2001 G.C. RELIABLE PULLED TANK. NO LEAK OR DISCHARGE EVIDENT. NO FURTHER ACTION."
Remarks:	"failed test"

All TTF:

Facility ID:	0104402
Spill Number:	0104402
Spill Tank Test:	1526481
Site ID:	328750
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	328750
Operable Unit ID:	841036
Operable Unit:	01
Material ID:	532897
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI385 **SPILL NUMBER 0210366** **NY LTANKS** **S105997907**
West **182 UNION AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.426 mi.
2248 ft. **Site 3 of 3 in cluster BI**

Relative: LTANKS:
Lower

Name:	SPILL NUMBER 0210366
Address:	182 UNION AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0210366 / 2003-03-03
Facility ID:	0210366
Site ID:	282696
Spill Date:	2003-01-14

Actual:
71 ft.

SPILL NUMBER 0210366 (Continued) **S105997907**

Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-14
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229505
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Jan 2003 - 1000 gallon tank was removed from the property. 100 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environemtal Assessement. NFA. TG"
Remarks:	"SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL AT ABOVE LOCATION. PROPTERY IS OWNED BY THE CITY OF NEW ROCHELLE AND CALLER IS A CONTRACTOR FOR THE CITY. TANK APPEARS TO HAVE BEEN ABANDONED YEARDS AGO. "

All Materials:

Site ID:	282696
Operable Unit ID:	861605
Operable Unit:	01
Material ID:	513753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG386 **APT. BUILDING** **NY LTANKS** **S102674170**
SSE **208 CENTER AVE.** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.430 mi.
2272 ft. **Site 3 of 4 in cluster BG**

Relative:
Lower

Actual:
73 ft.

LTANKS:

Name:	APT. BUILDING
Address:	208 CENTER AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9314003 / 1994-03-11
Facility ID:	9314003
Site ID:	215702
Spill Date:	1994-02-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1994-03-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-02-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-11
Spill Record Last Update:	1995-01-05
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK WAS OVERFILLED CASTLE CREW TO CLEAN UP"

All Materials:

Site ID:	215702
Operable Unit ID:	996014
Operable Unit:	01
Material ID:	389350
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APT. BUILDING (Continued) **S102674170**

Name:	APT. BUILDING
Address:	208 CENTER AVE.
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9315255 / 1994-04-11
Facility ID:	9315255
Site ID:	215703
Spill Date:	1994-03-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-04-11
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-11
Spill Record Last Update:	1995-01-04
Spiller Name:	Not reported
Spiller Company:	WRG
Spiller Address:	420 WESTCHESTER AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	178636
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY GUAGE RESULTED IN OVERFILL WCHD NOTIFIED CASTLE OIL WILL CLEAN UP"

All Materials:

Site ID:	215703
Operable Unit ID:	997178
Operable Unit:	01
Material ID:	387016
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 0202241
Address:	208 CENTER AVE

APT. BUILDING (Continued) **S102674170**

City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0202241 / 2002-08-12
Facility ID:	0202241
Facility Type:	ER
DER Facility ID:	177797
Site ID:	214599
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6010
Spill Date:	2002-06-01
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-06-01
CID:	257
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-01
Spill Record Last Update:	2002-09-26
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	208 CENTER AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"bad gauge - contained - cleanup to be done by castleton enviromental" Not reported

All Materials:

Site ID:	214599
Operable Unit ID:	855230
Operable Unit:	01
Material ID:	520107
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BK387 **VACCARO RESIDENCE** **NY LTANKS** **S105998684**
NE **52 LINCOLN ST** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.431 mi.
2275 ft. **Site 2 of 2 in cluster BK**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Name:	SPILL NUMBER 0300463
Address:	52 LINCOLN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0300463 / 2003-04-14
Facility ID:	0300463
Site ID:	202585
Spill Date:	2003-04-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-22
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALLAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	168519
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks:	"Above material reported spilled at above location due to tank overfill. Crew is on site and cleanup is in progress at time of call. All material is expected to be recovered."

All Materials:

Site ID:	202585
Operable Unit ID:	868761
Operable Unit:	01
Material ID:	508540
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

VACCARO RESIDENCE (Continued) **S105998684**

SPILLS:

Name:	VACCARO RESIDENCE
Address:	52 LINCOLN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0806544 / 2008-12-26
Facility ID:	0806544
Facility Type:	ER
DER Facility ID:	168519
Site ID:	403827
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6010
Spill Date:	2008-09-10
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-09-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-11
Spill Record Last Update:	2008-12-26
Spiller Name:	LOUIS VACCARO
Spiller Company:	LOIS VACCARO
Spiller Address:	52 LINCOLN ST
Spiller Company:	999
Contact Name:	LOUIS VACCARO
DEC Memo:	"11/16/08 New England Tank Services reported that they removed one 550 gallon tank along with 7.09 tons of petroleum contaminated soil. NFA TG"
Remarks:	"Callers company was removing a 550 gallon tank and found it had holes in it. Unknown how much fuel had been leaking or for how long. Clean up will start within the next few days."

All Materials:

Site ID:	403827
Operable Unit ID:	1160514
Operable Unit:	01
Material ID:	2151689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BL388 **DEFENDER MARINE SUPPLY** **NY LTANKS** **S103479285**
ENE **309 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.437 mi.
2307 ft. **Site 1 of 2 in cluster BL**

Relative:
Lower

Actual:
26 ft.

LTANKS:

Name:	DEFENDER MARINE SUPPLY
Address:	309 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9806235 / 2002-09-19
Facility ID:	9806235
Site ID:	93459
Spill Date:	1998-08-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-08-19
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-19
Spill Record Last Update:	2002-09-19
Spiller Name:	WILLIAM GOING
Spiller Company:	DEFENDER MARINE SUPPLY
Spiller Address:	309 MAIN ST
Spiller County:	001
Spiller Contact:	WILLIAM GOING
Spiller Phone:	(914) 744-3705
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83786
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/19/98 WCHD NOTIFIED. 09/14/02 - 8 TO 10 YARDS OF SOIL STOCKPILED. CLOSURE REPORT TO FOLLOW ONCE SAMPLE RESULTS RECEIVED. 09/19/02 CLOSURE REPORT RECEIVED FROM WILLIAM GOING. DISPOSAL OF TANK AND 10.45 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"during a tank removal caller found contamined soil"

All Materials:

Site ID:	93459
Operable Unit ID:	1067422
Operable Unit:	01
Material ID:	317407
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

DEFENDER MARINE SUPPLY (Continued) **S103479285**

Oxygenate: Not reported

BM389 **SPILL NUMBER 0009195** **NY LTANKS** **S104877181**
SSE **17 POPLAR PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.438 mi.
2311 ft. **Site 1 of 3 in cluster BM**

Relative: **Lower**
Actual: **74 ft.**

LTANKS:

Name:	SPILL NUMBER 0009195
Address:	17 POPLAR PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0009195 / 2001-01-08
Facility ID:	0009195
Site ID:	63217
Spill Date:	2000-11-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-09
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-09
Spill Record Last Update:	2001-02-02
Spiller Name:	DESIGN BUILDERS GROUP
Spiller Company:	Not reported
Spiller Address:	17 POPLAR PL
Spiller County:	001
Spiller Contact:	DESIGN BUILDERS GROUP
Spiller Phone:	(914) 948-9785
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	61128
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/17/2000 TANK TEST FAILURE LETTER SENT. TANK SCHEDULED FOR RETEST ON 11/20/00. 01/08/2001 ENVIROSTAR PULLED TANK. TANK WAS SOUND, NO RELEASE. EVIROSTAR REPORTS TANK FAILED DUE TO FAULTY OIL LINES. NO CONTAMINATION FOUND. NO FURTHER ACTION REQUIRED."
Remarks:	"uncover repair retest"

All Materials:

Site ID:	63217
Operable Unit ID:	831505
Operable Unit:	01
Material ID:	543152
Material Code:	0001A
Material Name:	#2 fuel oil

SPILL NUMBER 0009195 (Continued) **S104877181**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG390 **RESIDENCE** **NY LTANKS** **S106124419**
SSE **6 POPLAR ROAD** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.438 mi.
2315 ft. **Site 4 of 4 in cluster BG**

Relative: **Lower**
Actual: **73 ft.**

LTANKS:

Name:	RESIDENCE
Address:	6 POPLAR ROAD
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0310014 / 2012-08-13
Facility ID:	0310014
Site ID:	82997
Spill Date:	2003-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-11-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2012-08-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	RUDY TAYLOR
Spiller Phone:	(914) 833-0287
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	76439
DEC Memo:	"7/29/10 Homeowner TTF JO'M 7/25/12: There is no such address as 6 Poplar Road in New Rochelle. This should either be 6 Poplar Road in Larchmont, or 6 Poplar Place in New Rochelle. jod 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"
Remarks:	""

All TTF:

Facility ID:	0310014

RESIDENCE (Continued) **S106124419**

Spill Number:	0310014
Spill Tank Test:	1528823
Site ID:	82997
Tank Number:	1
Tank Size:	500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	82997
Operable Unit ID:	875149
Operable Unit:	01
Material ID:	498967
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

391
South
1/4-1/2
0.441 mi.
2328 ft.

LIPMAN RESIDENCE **NY LTANKS** **S106971579**
54 LIBERTY AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
48 ft.

LTANKS:

Name:	LIPMAN RESIDENCE
Address:	54 LIBERTY AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0409061 / 2005-04-02
Facility ID:	0409061
Site ID:	333699
Spill Date:	2004-11-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2004-11-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester

LIPMAN RESIDENCE (Continued) **S106971579**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-16
Spill Record Last Update:	2005-04-02
Spiller Name:	JOSH LITSMAN
Spiller Company:	LISTMAN RESIDENCE
Spiller Address:	54 LIBERTY AVE
Spiller County:	001
Spiller Contact:	JOSH LITSMAN
Spiller Phone:	(914) 813-5024
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	268950
DEC Memo:	"02/18/04 ZURICH CLAIM BEING HANDLED BY LEWIS ENVIRONMENTAL. SMALL AMOUNT OF CONTAMINATION UNDER PUBLIC SIDEWALK/ROADWAY CANNOT BE REMOVED SAFELY. DEC SPOKE WITH LEWIS (BOB KRAUSE) ABOUT SAMPLING REQUIREMENTS. REPORT TO FOLLOW. jod 04/02/05 LEWIS ENVIRONMENTAL DISPOSED OF LUST AND 82.08 TONS OF CONTAMINATED SOIL. BASED UPON THE CLOSURE INFORMATION SUBMITTED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"SOILTEST CAME BACK OVER THE LIMIT:"

392
NW
1/4-1/2
0.441 mi.
2331 ft.

WALTON RESIDENCE **NY LTANKS** **S108639866**
129 SICKLES AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
67 ft.

LTANKS:

Name:	WALTON RESIDENCE
Address:	129 SICKLES AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0703375 / 2007-08-28
Facility ID:	0703375
Site ID:	383296
Spill Date:	2007-06-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-06-22
CID:	408
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2007-06-28
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-22
Spill Record Last Update:	2007-08-28
Spiller Name:	MARGRET WALTON

WALTON RESIDENCE (Continued) **S108639866**

Spiller Company:	PRIVATE HOME
Spiller Address:	129 SICKLES AVE
Spiller County:	001
Spiller Contact:	MARGRET WALTON
Spiller Phone:	(914) 235-5241
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	332760
DEC Memo:	"6/29/07: Envirotrac is consultant for insurance company. Report to follow. jod 08/08/07 Northeast Environmental reported that the tank was excavated and removed along with 19.85 tons of impacted soil. NFA TG"
Remarks:	"soil contamination found during tank removal; NOT YET CONTAINED OR CLEANED;"

All Materials:

Site ID:	383296
Operable Unit ID:	1140659
Operable Unit:	01
Material ID:	2130748
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

393
East
1/4-1/2
0.443 mi.
2339 ft.

FIUMFREDO RESIDENCE **NY LTANKS** **S111012239**
12 BAYVIEW AVE **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
47 ft.

LTANKS:

Name:	FIUMFREDO RESIDENCE
Address:	12 BAYVIEW AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1100096 / 2011-09-22
Facility ID:	1100096
Site ID:	447470
Spill Date:	2011-04-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D2
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2011-08-08
Recommended Penalty:	False
Meets Standard:	False

FIUMFREDO RESIDENCE (Continued) **S111012239**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-04
Spill Record Last Update:	2011-09-22
Spiller Name:	ROSE FIUMFREDO
Spiller Company:	ROSE FIUMFREDO
Spiller Address:	12 DAYVIEW AVE
Spiller County:	999
Spiller Contact:	ROSE FIUMFREDO
Spiller Phone:	(914) 632-0496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	402070
DEC Memo:	"4/4/11 - To retest tank. KAB 4/28/11 Morris called in for follow up. Tank failed again. He said tank top was exposed for most of length and one side and some samples taken. Morris said whoever did repairs, sounds like they only put a new vent riser on. Did not check piping, which is heavily crusted. jc 5-6-11 Failed 2nd retest today. Owner giving Kathy a hard time. Morris will retest again next week. Kathy said road name should be Bayview not Dayview, made change. jc 5/13/11 Tank failed for a 3rd time. Plan to pull, according to Tank Tech. dw 8-4-11 Homeowner called dispatch desk. He wants to remove the tank himself and do ALL of the work. He says he would cut open the tank and clean with speedi dri, dispose of tank at scrap yard, etc. I recommended that he hire an environmental consultant to AT LEAST oversee project because the DEC will need a TCR which would include soil samples, manifests, disposal receipts, etc. I told him that this spill will not be closed out until a proper and acceptable Tank Closure Report has been submitted to this office for review. I told him to contact J O'Dee in White Plains for further info. This guy seems bent on doing everything himself even though it was recommended that he hire a consultant to oversee the project. jm 8/4/11: Recieved call from Sandy Perratta 914-557-0142. He is the same individual who called the dispatch desk earlier today. He is not the property owner but a friend of the owner. States he is in the construction business and he can remove the tank himself. He states he has the OSHA 30-hour training and also states he knows that he doesn't need confined space entry training if the tank is less than 4 feet below ground . I again stated he should have a professional contractor do the work for safety reasons. jod 8/8/11: Received voice-mail message from Mr Perratta stating he had removed the tank and it was on the lawn awaiting a DEC drive-by inspection. I met New Rochelle Fire Captain Henry Senno on site. The tank was cut and cleaned and is on plastic. The excavation is open and is not fenced or secured. There is no evidence of any holes in the tank, and no evidence of any leak or contamination. Captain Senno states he will follow up with the owner, as no permits were filed for the removal as required in New Rochelle. DEC Spills requires no further action at this time. jod 9/8/11: I left this spill open after discussing the situation with Capt Senno on either August 9th or 10th. There was still a 55-gallon drum of heating oil and heating oil sludge that was removed from the tank remaining on the site. On either Aug 11th or 12th I spoke with Mr Perrotta and stated the spill would be left open until he submitted a disposal receipt to DEC for proper disposal of that waste drum. To date, Mr Perrotta has submitted a disposal recipt for the tank (entered in eDocs) but has not submitted a disposal receipt for the drum. jod 9/22/11: Letter from Linda Enes forwarded to DEC. She

FIUMFREDO RESIDENCE (Continued) **S111012239**

states she is in posesseion of the 55-gallon drum, and is using it to fuel a space heater. I called her this morning and she states her husband transported the drum in his pick-up truck from New Rochelle to their home in Dover Plains NY. Letter has been entered into eDocs. DEC requires no further action. jod"

Remarks: "repair/retest pending"

All Materials:

Site ID:	447470
Operable Unit ID:	1197626
Operable Unit:	01
Material ID:	2193927
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BL394 **TELEDYNE HYDRA-POWER** **NY SWF/LF** **1000201735**
ENE **310 MAIN ST** **NY Spills** **NYD001650209**
1/4-1/2 **NEW ROCHELLE, NY 10801** **RCRA NonGen / NLR**
0.443 mi. **FINDS**
2339 ft. **Site 2 of 2 in cluster BL** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
24 ft.

SWF/LF:

Name:	PAR TRADING INC
Address:	310 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY 10801
Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[60J11]
Active:	No
East Coordinate:	603184
North Coordinate:	4529831
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

SPILLS:

Name:	CAR DEALER
Address:	310 MAIN STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0713299 / 2010-11-30
Facility ID:	0713299
Facility Type:	ER
DER Facility ID:	344570
Site ID:	395027
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6010
Spill Date:	2008-03-17
Investigator:	jkomara
Referred To:	WCDOH - PBS
Reported to Dept:	2008-03-17
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-17
Spill Record Last Update:	2010-11-30
Spiller Name:	MIMI
Spiller Company:	CAR DEALER
Spiller Address:	310 MAIN STREET
Spiller Company:	001
Contact Name:	MIMI
DEC Memo:	"11/30/10 No Info 3 years old spills will nbot be following up NFA JO'M "
Remarks:	"DURING SOIL BORINGS FOUND CONTAMINTAED SOIL"

All Materials:

Site ID:	395027
Operable Unit ID:	1151973
Operable Unit:	01
Material ID:	2142744
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Name:	M TECH MOTORS
Address:	310 MAIN ST REAR
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1408123 / 2014-11-06
Facility ID:	1408123
Facility Type:	ER
DER Facility ID:	456652
Site ID:	501675
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6010
Spill Date:	2014-11-06
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2014-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-11-06
Spill Record Last Update:	2014-11-06
Spiller Name:	MIKE TASHENT
Spiller Company:	M TECH MOTORS
Spiller Address:	310 MAIN ST REAR
Spiller Company:	999
Contact Name:	MIKE TASHENT
DEC Memo:	"11/6/14- Spoke to caller. He was on site and noted where auto shop flushed some waste oil to roadside curb. Cleanup completed by spiller with speedidry. Caller states cleanup is complete. NFA DT"
Remarks:	"loss to sewer and roadway. C/u in progress"

All Materials:

Site ID:	501675
Operable Unit ID:	1251062
Operable Unit:	01
Material ID:	2252898
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	TELEDYNE HYDRA-POWER	
Handler Address:		310 MAIN ST

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Handler City,State,Zip:	NEW ROCHELLE, NY 10801-5716
EPA ID:	NYD001650209
Contact Name:	Not reported
Contact Address:	MAIN ST
Contact City,State,Zip:	NEW ROCHELLE, NY 10801
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	MAIN ST
Mailing City,State,Zip:	NEW ROCHELLE, NY 10801
Owner Name:	TELEDYNE HYDRA-POWER
Owner Type:	Private
Operator Name:	TELEDYNE HYDRA-POWER
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

TELEDYNE HYDRA-POWER (Continued) **1000201735**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	U002
Waste Description:	2-PROPANONE (I) (OR) ACETONE (I)
Waste Code:	U140
Waste Description:	1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)
Waste Code:	U238
Waste Description:	CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)
Waste Code:	U239
Waste Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TELEDYNE HYDRA-POWER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	310 MAIN ST

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Owner/Operator City,State,Zip:	OPERCITY, NY 99999
Owner/Operator Telephone:	914-632-2200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	TELEDYNE HYDRA-POWER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	310 MAIN ST
Owner/Operator City,State,Zip:	OPERCITY, NY 99999
Owner/Operator Telephone:	914-632-2200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	TELEDYNE HYDRA-POWER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	310 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-2200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	TELEDYNE HYDRA-POWER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	310 MAIN ST
Owner/Operator City,State,Zip:	NEW ROCHELLE, NY 10801
Owner/Operator Telephone:	914-632-2200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19801119
Handler Name: TELEDYNE HYDRA-POWER	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19990708

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Handler Name: TELEDYNE HYDRA-POWER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: TELEDYNE HYDRA-POWER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: TELEDYNE HYDRA-POWER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: TELEDYNE HYDRA-POWER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332919
NAICS Description: OTHER METAL VALVE AND PIPE FITTING MANUFACTURING

NAICS Code: 332999
NAICS Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

TELEDYNE HYDRA-POWER (Continued) **1000201735**

NAICS Code: 336413
NAICS Description: OTHER AIRCRAFT PARTS AND AUXILIARY EQUIPMENT MANUFACTURING

NAICS Code: 336999
NAICS Description: ALL OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19870827
Evaluation Responsible Agency:	EPA-Initiated Oversight/Observation/Training Actions
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CEI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19860319
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

TELEDYNE HYDRA-POWER (Continued) **1000201735**

FINDS:
Registry ID: 110004335808

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000201735
Registry ID:	110004335808
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004335808
Name:	TELEDYNE HYDRA-POWER
Address:	310 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801

NY MANIFEST:

Name:	TELEDYNE HYDRA POWER INC
Address:	310 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY 10801-5716
Country:	USA
EPA ID:	NYD001650209
Facility Status:	Not reported
Location Address 1:	310 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	5716

NY MANIFEST:

EPAID:	NYD001650209
Mailing Name:	TELEDYNE HYDRA POWER INC
Mailing Contact:	RICHARD C. SNYDER
Mailing Address 1:	10-12 PINE COURT
Mailing Address 2:	Not reported
Mailing City:	NEW ROCHELLE
Mailing State:	NY
Mailing Zip:	10801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146322200

395
WSW
1/4-1/2
0.446 mi.
2355 ft.

WILLIAMS TTF
23 1ST ST
NEW ROCHELLE, NY

NY LTANKS **S104276929**
N/A

Relative:
Lower

Actual:
57 ft.

LTANKS:

Name:	WILLIAMS TTF
Address:	23 1ST ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9702187 / 1999-06-10
Facility ID:	9702187
Site ID:	102476
Spill Date:	1997-05-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-20
CID:	369
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-20
Spill Record Last Update:	2018-01-24
Spiller Name:	Not reported
Spiller Company:	MR WILLIAMS
Spiller Address:	23 FIRST ST
Spiller County:	001
Spiller Contact:	BRIAN SCHUG
Spiller Phone:	(914) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90745
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING SITE EVALUATION-CALLER WILL REMOVE SOIL-CLEANUP IN PROGRESS"

All Materials:

Site ID:	102476
Operable Unit ID:	1048062
Operable Unit:	01
Material ID:	335128
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

396
SW
1/4-1/2
0.447 mi.
2362 ft.

RESIDENCE
38 BEECHWOOD AVE
NEW ROCHELLE, NY

NY LTANKS **S102660166**
N/A

Relative:
Lower

Actual:
37 ft.

LTANKS:

Name:	RESIDENCE
Address:	38 BEECHWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9705244 / 1997-11-10
Facility ID:	9705244
Site ID:	105369
Spill Date:	1997-07-31
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-31
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-31
Spill Record Last Update:	1998-02-05
Spiller Name:	MARVIN KAPUS
Spiller Company:	Not reported
Spiller Address:	38 BEECHWOOD AVE
Spiller County:	001
Spiller Contact:	MARVIN KAPUS
Spiller Phone:	(914) 738-1351
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	92963
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/31/97 CONTAMINATED SOIL BEING REMOVED & STOCKPILED; 08/01/97 TANK FOUND DURING DEMOLITION OF HOUSE; TANK AND CONTAMINATION REMOVED; "
Remarks:	"demolition of building - ust 550 gal tank - tank had holes in it contaminated soil found "

All Materials:

Site ID:	105369
Operable Unit ID:	1048510
Operable Unit:	01
Material ID:	334464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

RESIDENCE (Continued) **S102660166**

Oxygenate: Not reported

BM397 **FUNICELOLO HOME** **NY LTANKS** **S107489124**
SSE **24 POPLAR PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.449 mi.
2369 ft. **Site 2 of 3 in cluster BM**

Relative: **Lower**

Actual: **73 ft.**

LTANKS:

Name:	FUNICELOLO HOME
Address:	24 POPLAR PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0509719 / 2006-11-19
Facility ID:	0509719
Site ID:	355533
Spill Date:	2005-11-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-11-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-14
Spill Record Last Update:	2006-11-19
Spiller Name:	FUNICEOLO HOME
Spiller Company:	FUNICELOLO HOME
Spiller Address:	24 POPULAR PLACE
Spiller County:	001
Spiller Contact:	FUNICEOLO HOME
Spiller Phone:	(914) 636-5043
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305561
DEC Memo:	"PLAN WAS TO ABANDON BUT FOUND HOLES SO NOWTHEY WILL REMOVE NO KNOWN EXPERTS AT THIS TIME November 19, 2006: ONE HOLE FOUND ON TOP OF TANK. TANK CANNOT BE REMOVED DUE TO SAFETY AND STRUCTURAL CONSIDERATIONS. MUNICIPAL WATER AND SEWER. ROYAL ENVIRONMENTAL TOOK A GROUND WATER SAMPLE BENATH TANK, ALL ANALYTES NON-DETECT. TANK ABANDONED IN PLACE WITH SLURRY. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES FOUND IN A 1000 GALLON TANK;"

All Materials:

Site ID:	355533
Operable Unit ID:	1112888
Operable Unit:	01
Material ID:	2102930

FUNICELOLO HOME (Continued) **S107489124**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM398 **LABELLA RESIDENCE** **NY LTANKS** **S107789449**
SSE **219 CENTRE AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.453 mi.
2392 ft. **Site 3 of 3 in cluster BM**

Relative: **Lower**

Actual: **72 ft.**

LTANKS:

Name:	LABELLA RESIDENCE
Address:	219 CENTRE AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0601959 / 2009-09-01
Facility ID:	0601959
Site ID:	364328
Spill Date:	2006-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2009-09-01
Spiller Name:	LARRY LABELLA
Spiller Company:	LABELLA RESIDENCE
Spiller Address:	219 CENTRAL AVE
Spiller County:	001
Spiller Contact:	LARRY LABELLA
Spiller Phone:	(914) 654-0719
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	314554
DEC Memo:	"05/24/06: Soil samples clean. US Tank Tech will be repairing and retesting. 9/1/09: Tank passed a retest in isolation on 6-13-06. At that time, new fuel lines had been run from the tank to the boiler room but were not hooked up at the time of the test. A full system test was performed 7-24-09 with the lines connected. The tank system passed this retest. Based upon the information provided, no further action is required at this time. jod"

LABELLA RESIDENCE (Continued) **S107789449**

Remarks: "UNCOVER REPAIR AND RETEST."

All TTF:

Facility ID:	0601959
Spill Number:	0601959
Spill Tank Test:	1550008
Site ID:	364328
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	364328
Operable Unit ID:	1122357
Operable Unit:	01
Material ID:	2111830
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

399 West 1/4-1/2 0.458 mi. 2418 ft. **SPILL NUMBER 0210080** **NY LTANKS** **S105997807**
196 UNION AV **N/A**
NEW ROCHELLE, NY

Relative: Lower

Actual: 71 ft.

LTANKS:

Name:	SPILL NUMBER 0210080
Address:	196 UNION AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0210080 / 2003-03-03
Facility ID:	0210080
Site ID:	155360
Spill Date:	2003-01-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-06

SPILL NUMBER 0210080 (Continued) **S105997807**

CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-01-06
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	City of New Rochelle
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK TRICARICO
Spiller Phone:	(914) 490-8033
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131601
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY Dec. 2002 - One 1200 gallon tank was removed from the property. 300 tons of petroleum impacted soil was excavated and disposed. Tank removal report submitted by American Environmetnal Assessment. NFA. TG"
Remarks:	"1200 GAL UNDERGROUND STORAGE TANK - 4 OTHER SPILL #'S ON THIS SAME SITE - DELORES FROM DEC SAYS THEY NEED ANOTHER NEW SPILL #"

All Materials:

Site ID:	155360
Operable Unit ID:	861323
Operable Unit:	01
Material ID:	513483
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BN400 **RESIDENCE** **NY LTANKS** **S105230245**
South **98 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.458 mi.
2420 ft. **Site 1 of 4 in cluster BN**

Relative:
Lower

Actual:
46 ft.

LTANKS:

Name:	RESIDENCE
Address:	98 LIBERTY AVE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0107187 / 2002-01-11
Facility ID:	0107187
Site ID:	204562
Spill Date:	2001-10-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

RESIDENCE (Continued) **S105230245**

Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-10-11
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-11
Spill Record Last Update:	2002-03-22
Spiller Name:	REALTOR
Spiller Company:	MR GAMIANO
Spiller Address:	98 LIBERTY AVE
Spiller County:	001
Spiller Contact:	CAROL MASCOLINO-REALTOR
Spiller Phone:	(914) 576-1112
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170048
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/11/2002 ADVANCED PULLED TANK AND 99.6 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"PETROLEUM ODOR AND STAINING IN THE SOIL-RECOMMEND TANK REMOVAL"

All TTF:

Facility ID:	0107187
Spill Number:	0107187
Spill Tank Test:	1526660
Site ID:	204562
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	204562
Operable Unit ID:	844253
Operable Unit:	01
Material ID:	532018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RESIDENCE (Continued) **S105230245**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BJ401 **MANONE PLACE** **NY LTANKS** **S107523607**
WNW **15 COLONIAL PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.462 mi.
2438 ft. **Site 2 of 2 in cluster BJ**

Relative: **Lower**

Actual: **84 ft.**

LTANKS:

Name:	MANONE PLACE
Address:	15 COLONIAL PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0513004 / 2006-05-08
Facility ID:	0513004
Site ID:	359413
Spill Date:	2006-02-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-09
Spill Record Last Update:	2006-05-08
Spiller Name:	FLORENCE MANONE
Spiller Company:	MANONE PLACE
Spiller Address:	15 COLONIAL PLACE
Spiller County:	001
Spiller Contact:	FLORENCE MANONE
Spiller Phone:	(914) 633-7791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	309466
DEC Memo:	"John O'Dee is lead and will/has contacted. May 8, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND FIVE DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"550 GALLON TANK, HOLES AND CONTAMINATION, WOULD LIKE A CALL BACK PERTAINING TO THIS PROPERTY"

All Materials:

Site ID:	359413
Operable Unit ID:	1116622

MANONE PLACE (Continued) **S107523607**

Operable Unit:	01
Material ID:	2107064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

402 **TRINITY ARMS APARTMENTS** **NY LTANKS** **S109416298**
SSE **25 TRINITY PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.466 mi.
2458 ft.

Relative: **Lower**

Actual: **70 ft.**

LTANKS:

Name:	TRINITY ARMS APARTMENTS
Address:	25 TRINITY PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0811859 / 2009-04-22
Facility ID:	0811859
Site ID:	409448
Spill Date:	2009-01-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-30
Spill Record Last Update:	2009-04-22
Spiller Name:	WILLY SILSDORF
Spiller Company:	TRINITY ARMS LTD
Spiller Address:	25 TRINITY PLACE
Spiller County:	999
Spiller Contact:	LARRY BOYD
Spiller Phone:	(914) 682-5676
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Spoke to W. Silsdorf. Think it may be leak in piping or fitting. Will probably Uncover, repair and retest. dvw 04/21/09 Wayne Schnieder reported ttf 1/3/09. passing retest after line replacement. No contamination. NFA TG "
Remarks:	"Caller states he performed a EZ-3 test and had a failure. Caller

TRINITY ARMS APARTMENTS (Continued) **S109416298**

does not believe a spill or resources are affected."

All Materials:

Site ID:	409448
Operable Unit ID:	1165955
Operable Unit:	01
Material ID:	2157389
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	APT BLDG
Address:	25 TRINITY PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	8905211 / 1992-07-30
Facility ID:	8905211
Site ID:	283512
Spill Date:	1989-08-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-31
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ANN JASLOCKI
Spiller Address:	REAL ESTATE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	229952
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"4K PETRO TITE, -.234 GPH"

All TTF:

Facility ID:	8905211
Spill Number:	8905211

TRINITY ARMS APARTMENTS (Continued) **S109416298**

Spill Tank Test:	1535913
Site ID:	283512
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	283512
Operable Unit ID:	932936
Operable Unit:	01
Material ID:	445651
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO403 **SPILL NUMBER 9814027** **NY LTANKS** **S104619985**
NW **48 REMINGTON PL** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.470 mi.
2482 ft. **Site 1 of 2 in cluster BO**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Name:	SPILL NUMBER 9814027
Address:	48 REMINGTON PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9814027 / 1999-02-19
Facility ID:	9814027
Site ID:	80830
Spill Date:	1999-02-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-19
CID:	365
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

SPILL NUMBER 9814027 (Continued) **S104619985**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-19
Spill Record Last Update:	1999-03-01
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AV
Spiller County:	001
Spiller Contact:	MAMMY JONES
Spiller Phone:	(914) 636-5128
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	74863
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"STORAGE TANK OVERFILL - TANK IS OUTSIDE UNDERGROUND - CONTAMINATED SOIL WAS REMOVED & REPLACED WITH FRESH SOIL"

All Materials:

Site ID:	80830
Operable Unit ID:	1071478
Operable Unit:	01
Material ID:	310733
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

---

404 **RITACCO HOME** **NY LTANKS** **S107789088**
ENE **24 JACKSON STREET** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.471 mi.
2485 ft.

Relative: **Lower**

Actual: **24 ft.**

LTANKS:

Name:	RITACCO HOME
Address:	24 JACKSON STREET
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0600187 / 2006-07-28
Facility ID:	0600187
Site ID:	362141
Spill Date:	2006-04-06
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-06
CID:	444

RITACCO HOME (Continued) **S107789088**

Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-06
Spill Record Last Update:	2006-07-28
Spiller Name:	RITACCO HOME
Spiller Company:	RITACCO HOME
Spiller Address:	24 JACKSON STREET
Spiller County:	001
Spiller Contact:	RITACCO HOME
Spiller Phone:	(914) 576-1430
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	312378
DEC Memo:	"04/10/06: Northeast to continue remediation. No GW involved as of now. July 28, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.00 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES IN A 550 GALLON AND CONTAMINATED SOIL;"

All Materials:

Site ID:	362141
Operable Unit ID:	1120244
Operable Unit:	01
Material ID:	2109739
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

405
East
1/4-1/2
0.473 mi.
2500 ft.

CON EDISON - ECHO AVENUE SUBSTATION
ECHO AVENUE
NEW ROCHELLE, NY 10801

SEMS-ARCHIVE **1000111631**
RCRA-VSQG **NYD981141252**
NY Spills
NY MANIFEST

Relative:
Lower

Actual:
17 ft.

SEMS Archive:

Site ID:	0202659
EPA ID:	NYD981141252
Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
Address:	ECHO AVE
Address 2:	Not reported
City,State,Zip:	NEW ROCHELLE, NY 10801
Cong District:	20
FIPS Code:	36119
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

SEMS Archive Detail:

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1992-09-30 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1988-04-19 04:00:00
Finish Date:	1988-04-19 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0202659
EPA ID:	NYD981141252
Site Name:	CONSOLIDATED EDISON-ECHO AVE. SITE
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1992-09-30 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	CON EDISON - ECHO AVENUE SUBSTATION
Handler Address:	ECHO AVENUE
Handler City,State,Zip:	NEW ROCHELLE, NY 10801
EPA ID:	NYD981141252
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Waste Code: X002
Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	19510101
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator: Owner

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19510101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19510101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19510101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: CON EDISON - ECHO AVENUE SUB
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: CON EDISON - ECHO AVENUE SUBSTATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CON EDISON - ECHO AVENUE SUBSTATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19851119
Handler Name: CON EDISON - ECHO AVENUE SUB
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960329
Handler Name: CON EDISON - ECHO AVENUE SUBSTATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: ECHO AVENUE SUBSTATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Receive Date: 20040225
Handler Name: CON EDISON - ECHO AVENUE SUBSTATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SPILLS:
Name: CON EDISON
Address: ECHO AVENUE SUBSTATION
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9711031 / 1998-01-06
Facility ID: 9711031
Facility Type: ER
DER Facility ID: 101608
Site ID: 116789
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6010
Spill Date: 1998-01-01
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-01-01
CID: 204
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-01
Spill Record Last Update:	1998-01-29
Spiller Name:	STEVE ROMERO
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	STEVE ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/01/98 OIL/WATER SEPARATOR OVERFLOWED; SUSPECTS OUTLET PIPE BECAME CLOGGED OR FROZEN CAUSING OVERFLOW; 01/02/98 3,300 GAL CONTAINED IN DIKED AREA; 100 GAL OVERFLOWED DIKE ONTO SOIL AND INTO DRAIN; 01/06/98 SPILL CLEANED UP BY CON ED; H2O HAS LESS THAN 1 PPM PCB "
Remarks:	"OIL / WATER SEPARATOR MALFUNCTIONED 3300 IN CONTAINMENT AREA"

All Materials:

Site ID:	116789
Operable Unit ID:	1053908
Operable Unit:	01
Material ID:	329298
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	3400.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	ECHO AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Country:	USA
EPA ID:	NYD981141252
Facility Status:	Not reported
Location Address 1:	ECHO AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW ROCHELLE
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981141252
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON - ECHO AVENUE SUBSTATION (Continued) **1000111631**

Mailing Country: USA
Mailing Phone: 2124602808

BP406 **COMMERICAL BUILIDING** **NY LTANKS** **S106472134**
SSW **719 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.477 mi.
2518 ft. **Site 1 of 2 in cluster BP**

Relative:
Lower

Actual:
59 ft.

LTANKS:

Name:	COMMERICAL BUILIDING
Address:	719 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0404182 / 2004-10-28
Facility ID:	0404182
Site ID:	301693
Spill Date:	2004-07-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-07-19
CID:	405
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-19
Spill Record Last Update:	2004-10-28
Spiller Name:	JOHN DEURANTE
Spiller Company:	COMMERICAL BUILIDING
Spiller Address:	719 MAIN ST.
Spiller County:	001
Spiller Contact:	JOHN DEURANTE
Spiller Phone:	(914) 632-4222
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	243806
DEC Memo:	"10/28/04 TANK PASSED RETEST AFTER PIPING WAS REPLACED. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"RECOMMEND, UNCOVER, REPAIR, RETEST"

All TTF:

Facility ID:	0404182
Spill Number:	0404182
Spill Tank Test:	1529456
Site ID:	301693
Tank Number:	1
Tank Size:	1080
Material:	Not reported

COMMERICAL BUILIDING (Continued) **S106472134**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BN407 **SPILL NUMBER 9803423** **NY LTANKS** **S104619561**
South **106 LIBERTY AV** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.481 mi.
2541 ft. **Site 2 of 4 in cluster BN**

Relative: **Lower**
Actual: **45 ft.**

LTANKS:

Name:	SPILL NUMBER 9803423
Address:	106 LIBERTY AV
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9803423 / 1998-08-18
Facility ID:	9803423
Site ID:	140786
Spill Date:	1998-06-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-17
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-17
Spill Record Last Update:	1998-10-02
Spiller Name:	MARGURITE FINCH
Spiller Company:	Not reported
Spiller Address:	106 LIBERTY AV
Spiller County:	001
Spiller Contact:	MARGURITE FINCH
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	120231
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PULLED THE TANK TODAY & FOUND IT TO BE LEAKING - CONTAMINATED SOIL IS BEING DUG UP & STOCK PILED"

SPILL NUMBER 9803423 (Continued) **S104619561**

All Materials:

Site ID:	140786
Operable Unit ID:	1064251
Operable Unit:	01
Material ID:	566529
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

408 **TTF AT RESIDENCE** **NY LTANKS** **S108957764**
NE **68 JACKSON ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.484 mi.
2553 ft.

Relative: **Lower**

Actual: **25 ft.**

LTANKS:

Name:	TTF AT RESIDENCE
Address:	68 JACKSON ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0707955 / 2008-03-26
Facility ID:	0707955
Site ID:	388761
Spill Date:	2007-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-10-20
CID:	79
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-22
Spill Record Last Update:	2008-03-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MR JOHNSON
Spiller Phone:	(914) 235-1496
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	338305
DEC Memo:	"March 26, 2008: ENVIROSTAR REMOVED AND DISPOSED OF TANK. NO EVIDENCE

TTF AT RESIDENCE (Continued) **S108957764**

OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "TEST FAILED DUE TO BUBBLING. HORNER EASY 3 TEST,"

All Materials:
Site ID: 388761
Operable Unit ID: 1145917
Operable Unit: 01
Material ID: 2136260
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BN409 **COLLEGE OF NEW ROCHELLE** **NY LTANKS** **S104619776**
South **103 LIBERTY AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.484 mi.
2558 ft. **Site 3 of 4 in cluster BN**

Relative: **Lower**
Actual: **44 ft.**

LTANKS:
Name: COLLEGE OF NEW ROCHELLE
Address: 103 LIBERTY AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 9809357 / 2005-04-17
Facility ID: 9809357
Site ID: 118985
Spill Date: 1998-10-26
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JBODee
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 1998-10-26
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-26
Spill Record Last Update: 2005-04-17
Spiller Name: UNKNOWN
Spiller Company: COLLEGE OF NEW ROCHELLE
Spiller Address: 103 LIBERTY AVE
Spiller County: 001
Spiller Contact: COLLEGE OF NEW ROCHELLE
Spiller Phone: Not reported
Spiller Extention: Not reported

COLLEGE OF NEW ROCHELLE (Continued) **S104619776**

DEC Region: 3
DER Facility ID: 103367
DEC Memo: "02/23/99 Letter sent to tank owner requesting information 04/17/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod"
Remarks: "TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF RESULTS. NO CALL BACK REQUESTED AT TIME OF CALL."

All TTF:
Facility ID: 9809357
Spill Number: 9809357
Spill Tank Test: 1546454
Site ID: 118985
Tank Number: 1
Tank Size: 1080
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 118985
Operable Unit ID: 1066630
Operable Unit: 01
Material ID: 316813
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

410 SE 1/4-1/2 0.485 mi. 2562 ft. **CIUSSETELLI RESIDENCE** **NY LTANKS** **S105996325**
4 FAIRVIEW PLACE **N/A**
NEW ROCHELLE, NY

Relative: Lower
Actual: 40 ft.

LTANKS:
Name: CIUSSETELLI RESIDENCE
Address: 4 FAIRVIEW PLACE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 0204230 / 2010-07-13
Facility ID: 0204230
Site ID: 161898
Spill Date: 2002-07-22
Spill Cause: Tank Test Failure

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-07-23
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2010-07-13
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	RON CIUSSETELLI
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136674
DEC Memo:	"7/13/10: Report of a residential tank test failure. No indication of contamination noted on initial report. Report indicates all exterior piping loose, multiple vents and fills. Probable air leak. No further information received. jod"
Remarks:	"all exterior piping loose...multiple vents and fille..and questions contact caller."

All TTF:

Facility ID:	0204230
Spill Number:	0204230
Spill Tank Test:	1527307
Site ID:	161898
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	161898
Operable Unit ID:	857023
Operable Unit:	01
Material ID:	518487

CIUSSETELLI RESIDENCE (Continued) **S105996325**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BQ411 **FORMER MANCUSO MARINA** **US BROWNFIELDS** **1006975972**
ENE **HUNTINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801**
0.486 mi.
2564 ft. **Site 1 of 2 in cluster BQ**

Relative:
Lower

Actual:
14 ft.

US BROWNFIELDS:

Name:	FORMER MANCUSO MARINA
Address:	HUNTINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY 10801
Recipient Name:	R2 TBA - New York (Pre-law Superfund TBA)
Grant Type:	TBA
Property Number:	-
Parcel size:	1.23
Latitude:	40.912585
Longitude:	-73.773854
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: marina and boat storage facility
Datum:	-
Acres Property ID:	10127
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	11217
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	-
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	3/1/2003
Ownership Entity:	-
Completion Date:	3/1/2003
Current Owner:	City of New Rochelle, NY
Did Owner Change:	N
Cleanup Required:	-
Video Available:	N

FORMER MANCUSO MARINA (Continued) **1006975972**

Photo Available:	N
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	-
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-

FORMER MANCUSO MARINA (Continued) **1006975972**

Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	-
Property Description:	marina and boat storage facility
Below Poverty Number:	1670
Below Poverty Percent:	18.43
Meidan Income:	9092
Meidan Income Number:	3667
Meidan Income Percent:	40.47
Vacant Housing Number:	349
Vacant Housing Percent:	8.63
Unemployed Number:	334
Unemployed Percent:	3.69

BQ412 **NELSTAD MATERIAL CORP** **NY LTANKS** **S102154943**
ENE **40 HUNTINGTON PL** **NY Spills** **N/A**
1/4-1/2 **NEW ROCHELLE, NY 10801** **NY SPDES**
0.486 mi.
2568 ft. **Site 2 of 2 in cluster BQ**

Relative: **Lower**
Actual: **13 ft.**

LTANKS:

Name:	NELSTAD CONCRETE
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	0208898 / 2004-05-03
Facility ID:	0208898
Site ID:	200280
Spill Date:	2002-11-27
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6010

NELSTAD MATERIAL CORP (Continued) **S102154943**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-27
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-11-27
Spill Record Last Update:	2004-05-19
Spiller Name:	JOHN CAPOSELLA
Spiller Company:	NELSTAD CONCRETE
Spiller Address:	40 HUNTINGTON PL
Spiller County:	001
Spiller Contact:	JOHN CAPOSELLA
Spiller Phone:	(914) 636-8090
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	166657
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MANCINI 5/11/04: Letter to Nelstadt Materials Corp from Joe Mancini, WCDOH dated 3May2004. Closure report by Ira D Conklin has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"1000 UST LEAKING - CALLER DOING ABANDONMENT ON TANK AND DISCOVERED WATER IN IT"

All Materials:

Site ID:	200280
Operable Unit ID:	862078
Operable Unit:	01
Material ID:	515890
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CEMENT PLANT
Address:	40 HUNTINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9400648 / 1994-04-20
Facility ID:	9400648
Facility Type:	ER
DER Facility ID:	126495
Site ID:	148664
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6010

NELSTAD MATERIAL CORP (Continued) **S102154943**

Spill Date:	1994-04-14
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-14
CID:	Not reported
Water Affected:	L.I. SOUND
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-20
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PIPE LEAKING OIL INTO SOUND COAST GUARD WILL RESPOND PO NOWACK STORM DRAIN OUTFALL SHEEN PRESENTED BUT NOT RECOVERABLE RECURRING PROBLEM"

All Materials:

Site ID:	148664
Operable Unit ID:	994366
Operable Unit:	01
Material ID:	558757
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
Permit Number:	NYR00D345
State-Region:	03
Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	3273
State Water Body Name:	ECHO BAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.912861 / -73.772611

NELSTAD MATERIAL CORP (Continued) **S102154943**

DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP
Non-Gov Permit Street Address:	NELSTAD MATERIAL CORP
Non-Gov Permit Supplemental Location:	40 HUNTINGTON PL
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Permit Street Address:	40 HUNTINGTON PL
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	NEW ROCHELLE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10801
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported

NELSTAD MATERIAL CORP (Continued) **S102154943**

Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	NELSTAD MATERIAL CORP
Address:	40 HUNTINGTON PL
City,State,Zip:	NEW ROCHELLE, NY 10801
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY119
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NELSTAD MATERIAL CORP.
Non-Gov Facility Street Address:	NELSTAD MATERIAL CORP.
Non-Gov Facility Supplemental Location:	40 HUNTINGTON PL
Non-Gov Facility City:	NEW ROCHELLE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10801
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

BN413 **BLANCO RESIDENCE** **NY LTANKS** **S103238839**
South **30 LINDEN PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.487 mi.
2569 ft. **Site 4 of 4 in cluster BN**

Relative: LTANKS:
Lower

Actual: Name:	BLANCO RESIDENCE
50 ft. Address:	30 LINDEN PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9802704 / 1998-07-30
Facility ID:	9802704
Site ID:	227988
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-06-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other

BLANCO RESIDENCE (Continued) **S103238839**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-01
Spill Record Last Update:	1998-08-04
Spiller Name:	FRANK BLANCO
Spiller Company:	BLANCO RESIDENCE
Spiller Address:	30 LINDEN PLACE
Spiller County:	001
Spiller Contact:	FRANK BLANCO
Spiller Phone:	(914) 633-7605
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188052
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/27/98 LETTER REC'D FROM NES,INC. INDICATING TANK AND APPROX. 21.86 TONS CONTAMINATED SOIL WAS REMOVED. NFA."
Remarks:	"CALLERS AGENCY CALLED FOR NO HOT WATER - SERVICE MAN FOUND TANK EMPTY - POSSIBLY A TANK LEAK OR LINE FAILURE"

All Materials:

Site ID:	227988
Operable Unit ID:	1063369
Operable Unit:	01
Material ID:	321024
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

414
SW
1/4-1/2
0.488 mi.
2578 ft.

BEECHWOOD AVENUE ORGANIC YARD SITE **NY SWF/LF** **S103592520**
85 BEECHWOOD AVENUE **NY SPDES** **N/A**
NEW ROCHELLE, NY 10801

Relative:
Lower

Actual:
57 ft.

SWF/LF:

Name:	NEW ROCHELLE LEAF TS
Address:	85 BEECHWOOD AVE
City,State,Zip:	NEW ROCHELLE, NY 10801
Flag:	ACTIVE
Region Code:	3
Phone Number:	9146542129
Owner Name:	City of New Rochelle
Owner Type:	Municipal
Owner Address:	525 North Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	New Rochelle, NY 10801
Owner Email:	Not reported
Owner Phone:	9142353536
Contact Name:	John O'Keefe

BEECHWOOD AVENUE ORGANIC YARD SITE (Continued) **S103592520**

Contact Address:	224 E. Main St.
Contact Addr2:	Not reported
Contact City,St,Zip:	New Rochelle, NY 10801
Contact Email:	jokeefe@newrochelleny.com
Contact Phone:	9142353536
Activity Desc:	Transfer station - registration
Activity Number:	[60R19]
Active:	Yes
East Coordinate:	601716
North Coordinate:	4529087
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Yard Waste;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #:	60R19
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	City of New Rochelle
Operator Type:	Not reported
Laste Date:	10/30/2019

SPDES:

Name:	BEECHWOOD AVENUE ORGANIC YARD SITE
Address:	85 BEECHWOOD AVENUE
City,State,Zip:	NEW ROCHELLE, NY 10801
Permit Number:	NYR11H566
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.906527 / -73.792320
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported

BEECHWOOD AVENUE ORGANIC YARD SITE (Continued) **S103592520**

Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

415
NE
1/4-1/2
0.489 mi.
2583 ft.

7-UP BOTTLING CO **NY LTANKS** **S100560336**
PALMER AVE & CEDAR ST **N/A**
NEW ROCHELLE, NY

Relative:
Lower

Actual:
28 ft.

LTANKS:

Name:	7-UP BOTTLING CO
Address:	PALMER AVE & CEDAR ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	9302874 / 1999-08-02
Facility ID:	9302874
Site ID:	60684
Spill Date:	1993-06-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-12-08
SWIS:	6010
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1993-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-08
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	59196
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/08/94: CONTRACTOR WAS FENLEY AND NICOL. TANK PULLED AND CONTA. SOIL REMOVEDFROM PIT. TANK REMOVAL REPORT WAS REQUESTED BUT NOT RECIEVED. 08/02/99: FINAL CLOSURE REPORT RECEIVED FROM GIBSON, DUNN & CRUTCHER ON 7/27/99; SENT TO TARRYTOWN OFFICE. "
Remarks:	"TANK PULL DEC (TODD) IS AWARE OF AND HANDLING SPILL"

All Materials:

Site ID:	60684
Operable Unit ID:	981198

7-UP BOTTLING CO (Continued) **S100560336**

Operable Unit:	01
Material ID:	399984
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR416 **NORTH EVARTS** **NY LTANKS** **S104620864**
SE **44 NORTH EVARTS AVE** **N/A**
1/4-1/2 **ELSMFORD, NY**
0.489 mi.
2583 ft. **Site 1 of 2 in cluster BR**

Relative: **Lower**

Actual: **40 ft.**

LTANKS:

Name:	NORTH EVARTS
Address:	44 NORTH EVARTS AVE
City,State,Zip:	ELSMFORD, NY
Spill Number/Closed Date:	9913333 / 2005-02-26
Facility ID:	9913333
Site ID:	74554
Spill Date:	2000-02-24
Spill Cause:	Tank Failure
Spill Source:	Vessel
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	True
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2005-02-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	44 NORTH EVARTS AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	69944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 2/26/05 surface spill from bilge tank on boat--j omara handled-close "
Remarks:	"bilge tank on boat ruptured - spill to soil and some contained in a catch basin - ny boat reg ny4947ju - fire dept and haz mat on scene- "

NORTH EVARTS (Continued) **S104620864**

Not reported

All Materials:

Site ID:	74554
Operable Unit ID:	1087874
Operable Unit:	01
Material ID:	295189
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO417 **HERNANDEZ - TTF** **NY LTANKS** **S117853761**
NW **70 REMINGTON PLACE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.489 mi.
2583 ft. **Site 2 of 2 in cluster BO**

Relative: **Higher**

Actual: **94 ft.**

LTANKS:

Name:	HERNANDEZ - TTF
Address:	70 REMINGTON PLACE
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1411959 / 2015-06-16
Facility ID:	1411959
Site ID:	505764
Spill Date:	2015-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-23
Spill Record Last Update:	2015-06-17
Spiller Name:	DAISE Hernandez
Spiller Company:	Hernandez
Spiller Address:	70 REMINGTON PLACE
Spiller County:	999
Spiller Contact:	DAISE FENANDEZ
Spiller Phone:	(914) 563-3381
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	460572

HERNANDEZ - TTF (Continued) **S117853761**

DEC Memo: "3-23-15: V.Mc call to Ms.Fenandez: Parents house, will speak w/Mom and try to find out age of house/UST and callbk w/update. Noted: gen. life time of UST 20 to 25 years, re-test Vs. remove. 6/16/15: UST removed by Envirostar. No evidence of leak or contamination was found. Tank Closure report entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
Not reported
Remarks: "caller reporting a failed tank test, tank is a 550 gallon tank. repair and retest tank"

All Materials:
Site ID: 505764
Operable Unit ID: 1255071
Operable Unit: 01
Material ID: 2257761
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

BR418 **RESIDENCE APT BLD** **NY LTANKS** **S125358698**
SE **45 NORTH AVE** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.490 mi.
2586 ft. **Site 2 of 2 in cluster BR**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:
Name: RESIDENCE APT BLD
Address: 45 NORTH AVE
City,State,Zip: NEW ROCHELLE, NY
Spill Number/Closed Date: 1905688 / Not Reported
Facility ID: 1905688
Site ID: 593733
Spill Date: 2019-08-30
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6010
Investigator: JPCUMMIN
Referred To: Not reported
Reported to Dept: 2019-08-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Not reported
Meets Standard: False
UST Involvement: False
Remediation Phase: 1
Date Entered In Computer: 2019-08-30
Spill Record Last Update: 2019-08-30
Spiller Name: Not reported

RESIDENCE APT BLD (Continued) **S125358698**

Spiller Company:	RESIDENCE APT BLD
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ABRAHAM
Spiller Phone:	(646) 321-2876
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	543707
DEC Memo:	"8/30/19 Tank tast failure. Caller has not been able to contact the owner as his office closed early today and he isn't sure of the size but believes it is a 3k tank. Caller was not able to provide any additional information. BW"
Remarks:	"tank test"

All Materials:

Site ID:	593733
Operable Unit ID:	1341311
Operable Unit:	01
Material ID:	2351184
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BP419 **10 FAMILY HOUSE + COMMERCIAL BUSINESSES** **NY LTANKS** **S120702902**
SSW **727-729 MAIN ST** **N/A**
1/4-1/2 **NEW ROCHELLE, NY**
0.500 mi.
2640 ft. **Site 2 of 2 in cluster BP**

Relative:
Lower

Actual:
55 ft.

LTANKS:

Name:	10 FAMILY HOUSE + COMMERCIAL BUSINESSES
Address:	727-729 MAIN ST
City,State,Zip:	NEW ROCHELLE, NY
Spill Number/Closed Date:	1610526 / Not Reported
Facility ID:	1610526
Site ID:	541362
Spill Date:	2017-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6010
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2017-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

10 FAMILY HOUSE + COMMERCIAL BUSINESSES (Continued) **S120702902**

Remediation Phase:	4
Date Entered In Computer:	2017-02-22
Spill Record Last Update:	2017-05-04
Spiller Name:	Not reported
Spiller Company:	TTF
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BETTY SHELTON
Spiller Phone:	(914) 409-6824
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	495116
DEC Memo:	"2/22/17 - To be investigated by Westchester County DOH and have the tank registered. KAB 5-4-17 Meeting with WCDOH. Tank was pulled. WC to send closure report to DEC. GHP"
Remarks:	"1500 gallon unregistered tank - unsure of next step"

All Materials:

Site ID:	541362
Operable Unit ID:	1289920
Operable Unit:	01
Material ID:	2295716
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Count: 6 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NEW ROCHELLE	S108467789	SIDEWALK / IN FRONT OF NE	HARRISON STREET		NY LTANKS
NEW ROCHELLE	S100153602	N.SHORE LONG ISLAND SOUND	NEW ROCHELLE TO DANBURY		NY LTANKS
NEW ROCHELLE	S105684699	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY VCP
NEW ROCHELLE	S121933897	CE-CEDAR ST MGP NEW ROCHELLE	ONE RAMADA PLAZA	10801	NY SHWS
NEW ROCHELLE	S113916612	MEARL CORP.	PALMER AVE	10801	NY SHWS
NEW ROCHELLE	S117975694	MM 5.4 LEFT LANE	I-95 SOUTHBOUND		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/01/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/11/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 88

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/19/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 11/19/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/01/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 9

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/22/2022
Number of Days to Update: 85

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 03/29/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 03/15/2022
Date Data Arrived at EDR: 03/15/2022
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/04/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/16/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/22/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 11/23/2021
Date Data Arrived at EDR: 12/15/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 76

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/23/2021
Date Data Arrived at EDR: 12/13/2021
Date Made Active in Reports: 03/02/2022
Number of Days to Update: 79

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/16/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Semi-Annually

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 12/06/2021
Date Data Arrived at EDR: 12/08/2021
Date Made Active in Reports: 01/06/2022
Number of Days to Update: 29

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/09/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/16/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 03/01/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/22/2022
Number of Days to Update: 85

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 03/29/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/14/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 04/28/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 02/22/2022
Date Data Arrived at EDR: 02/23/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/22/2022
Date Data Arrived at EDR: 02/23/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 76

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Quarterly

PFAS 2: New York State Inactive Landfill Initiative

A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. The primary focus is inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants, including per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane.

Date of Government Version: 10/29/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 158

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 05/16/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 05/16/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 01/31/2022
Date Data Arrived at EDR: 02/01/2022
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 84

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/02/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/15/2021
Date Data Arrived at EDR: 12/16/2021
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 84

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/21/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 03/15/2022
Date Data Arrived at EDR: 03/15/2022
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/11/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 02/28/2022
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 04/06/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/01/2021
Date Data Arrived at EDR: 02/15/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 84

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/17/2022
Next Scheduled EDR Contact: 08/29/2022
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/12/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/05/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/06/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/13/2021
Date Data Arrived at EDR: 12/17/2021
Date Made Active in Reports: 03/17/2022
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/21/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 04/28/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/06/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/18/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/18/2022
Next Scheduled EDR Contact: 05/30/2022
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 01/19/2022
Date Data Arrived at EDR: 01/19/2022
Date Made Active in Reports: 04/11/2022
Number of Days to Update: 82

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/20/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/18/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/25/2022
Number of Days to Update: 22

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/08/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 03/31/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/24/2021
Date Made Active in Reports: 11/19/2021
Number of Days to Update: 87

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 04/18/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 02/28/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/28/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/06/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 04/26/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 01/14/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 70

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 04/04/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 07/04/2022
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/05/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 04/28/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/16/2022
Next Scheduled EDR Contact: 08/29/2022
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 05/05/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/22/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 3

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 03/14/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/02/2021
Date Data Arrived at EDR: 11/22/2021
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/23/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/14/2021
Date Data Arrived at EDR: 12/15/2021
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 85

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/04/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/04/2021
Date Data Arrived at EDR: 11/22/2021
Date Made Active in Reports: 02/25/2022
Number of Days to Update: 95

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 05/18/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 01/04/2022
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 04/05/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/22/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 01/11/2022
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 34

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 04/12/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/17/2022
Date Data Arrived at EDR: 02/17/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 82

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/17/2022
Next Scheduled EDR Contact: 08/29/2022
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/31/2022
Date Data Arrived at EDR: 02/01/2022
Date Made Active in Reports: 02/10/2022
Number of Days to Update: 9

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/18/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/27/2021
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 12/10/2021
Date Data Arrived at EDR: 12/10/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/07/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 12/13/2021
Date Data Arrived at EDR: 12/17/2021
Date Made Active in Reports: 12/30/2021
Number of Days to Update: 13

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/15/2022
Next Scheduled EDR Contact: 06/27/2022
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 12/21/2021
Date Data Arrived at EDR: 12/22/2021
Date Made Active in Reports: 03/16/2022
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/28/2022
Next Scheduled EDR Contact: 07/11/2022
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/07/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 04/28/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 03/25/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/18/2022
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/18/2022
Next Scheduled EDR Contact: 08/01/2022
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/13/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 11/29/2021
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/01/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 01/04/2022
Date Data Arrived at EDR: 01/12/2022
Date Made Active in Reports: 04/01/2022
Number of Days to Update: 79

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 04/13/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 02/04/2022
Date Made Active in Reports: 04/28/2022
Number of Days to Update: 83

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 05/04/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 03/31/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 03/31/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Semi-Annually

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/31/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 02/24/2022
Next Scheduled EDR Contact: 06/06/2022
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations
Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 02/01/2022
Date Data Arrived at EDR: 02/02/2022
Date Made Active in Reports: 04/27/2022
Number of Days to Update: 84

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 05/04/2022
Next Scheduled EDR Contact: 08/15/2022
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Quarterly

NASSAU COUNTY:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/21/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/25/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/25/2022
Next Scheduled EDR Contact: 06/13/2022
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/04/2022
Date Data Arrived at EDR: 02/04/2022
Date Made Active in Reports: 04/27/2022
Number of Days to Update: 82

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/04/2022
Date Data Arrived at EDR: 02/04/2022
Date Made Active in Reports: 04/27/2022
Number of Days to Update: 82

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/25/2022
Next Scheduled EDR Contact: 08/08/2022
Data Release Frequency: Semi-Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/03/2021
Date Data Arrived at EDR: 02/11/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 84

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/09/2022
Next Scheduled EDR Contact: 08/22/2022
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/07/2022
Next Scheduled EDR Contact: 07/18/2022
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/08/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/16/2022
Next Scheduled EDR Contact: 08/29/2022
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/12/2022
Next Scheduled EDR Contact: 07/25/2022
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/02/2022
Next Scheduled EDR Contact: 06/20/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

HALSTEAD STATION
255 HUGUENOT STREET
NEW ROCHELLE, NY 10801

TARGET PROPERTY COORDINATES

Latitude (North):	40.91054 - 40ˆ 54’ 37.94’’
Longitude (West):	73.783836 - 73ˆ 47’ 1.81’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	602423.3
UTM Y (Meters):	4529326.5
Elevation:	90 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14105990 MOUNT VERNON, NY
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 90 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36119C0341F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
36119C0342F	FEMA FIRM Flood data
36119C0343F	FEMA FIRM Flood data
36119C0344F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MOUNT VERNON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Ordovician
Series:	Middle Ordovician (Mohawkian)
Code:	O2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 6986656.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Halstead Station	CLIENT:	Blackstone Consulting, LLC
ADDRESS:	255 Huguenot Street New Rochelle NY 10801	CONTACT:	Julie Brunner
		INQUIRY #:	6986656.2s
LAT/LONG:	40.91054 / 73.783836	DATE:	May 19, 2022 9:53 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: gravelly loam

Hydrologic Group: Not reported

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 127 inches

Depth to Watertable Min: > 38 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5
2	3 inches	72 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Clayey Gravel	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
2	USGS40000835790	0 - 1/8 Mile ESE
3	USGS40000835842	1/8 - 1/4 Mile NNE
4	USGS40000835908	1/2 - 1 Mile NNE
5	USGS40000835896	1/2 - 1 Mile NE
6	USGS40000835943	1/2 - 1 Mile NNW
7	USGS40000835557	1/2 - 1 Mile SSW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NY0002662	0 - 1/8 Mile NE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG10000044642	1/4 - 1/2 Mile West
A2	NYOG10000044641	1/4 - 1/2 Mile West
A3	NYOG10000044640	1/4 - 1/2 Mile West
A4	NYOG10000044639	1/4 - 1/2 Mile West
A5	NYOG10000044643	1/4 - 1/2 Mile WSW

PHYSICAL SETTING SOURCE MAP - 6986656.2s


New Rochelle Rd
Eastchester Rd
Pelhamdale Ave
Colonial Ave
Cross County Hwy 84
Lincoln Ave
Highbrook Ave
Washington Ave
Lockwood Ave
Union Ave
Kings Hwy
Weyman Ave
Centre Ave
North Ave
Church St
Cedar St
Rae St
Bonnie Brae Ave
Bonnie Brae Ave
Bonnie Brae Ave

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
NE
0 - 1/8 Mile
Lower

FRDS PWS **NY0002662**

PWS ID:	NY0002662	PWS type:	System Owner/Responsible Party
PWS name:	ROTONDE ANTHONY	PWS address:	C/O ANTHONY ROTONDE
PWS address:	RT 6	PWS city:	BREWSTER
PWS state:	NY	PWS zip:	10509
PWS ID:	NY0002662	PWS type:	System Owner/Responsible Party
PWS name:	ROTONDE ANTHONY	PWS address:	C/O ANTHONY ROTONDE
PWS address:	RT 6	PWS city:	BREWSTER
PWS state:	NY	PWS zip:	10509
PWS ID:	NY0002662	Activity status:	Active
Date system activated:	Not Reported	Date system deactivated:	Not Reported
Retail population:	00000200	System name:	POLO'S
System address:	Not Reported	System address:	RT 6
System city:	BREWSTER	System state:	NY
System zip:	10509		
County FIPS:	039	City served:	SOUTHEAST (T)
Latitude:	405441	Longitude:	0734658

2
ESE
0 - 1/8 Mile
Higher

FED USGS **USGS40000835790**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 105	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	268	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported
Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	8.00	Feet to sea level:	Not Reported
Note:	Not Reported		

3
NNE
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000835842**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 100	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	300	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	8.00	Feet to sea level:	Not Reported
Note:	Not Reported		

4
NNE **FED USGS** **USGS40000835908**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 283	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

5
NE **FED USGS** **USGS40000835896**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 104	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	750	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	15.00	Feet to sea level:	Not Reported
Note:	Not Reported		

6
NNW **FED USGS** **USGS40000835943**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 98	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	401	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	4.00	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
FED USGS	**USGS40000835557**

7
SSW
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 103	Type:	Well
Description:	Not Reported	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	220	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1955
Feet below surface:	12.00	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

A1
West
1/4 - 1/2 Mile

OIL_GAS **NYOG10000044642**

API #:	31119237750000	Well Name:	SCW 4
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	09-OCT-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A2
West
1/4 - 1/2 Mile

OIL_GAS **NYOG10000044641**

API #:	31119237740000	Well Name:	SCW 3
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	09-OCT-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A3
West
1/4 - 1/2 Mile

OIL_GAS **NYOG10000044640**

API #:	31119237730000	Well Name:	SCW 2
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Status:	Plugged and Abandoned	Well Type:	Not Listed
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	Not Reported	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

A4
West
1/4 - 1/2 Mile

OIL_GAS **NYOG10000044639**

API #:	31119237720000	Well Name:	SCW 1
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	09-OCT-08	Plug Date:	Not Reported

Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

A5
WSW
1/4 - 1/2 Mile

OIL_GAS **NYOG10000044643**

API #:	31119237760000	Well Name:	SCW 5
Owner:	180 Union Avenue Owner L.P.	Operator:	2438
Well Status:	Active	Well Type:	Geothermal
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	09-OCT-08	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Not Applicable
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	500
Measured Length:	500		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

BLACKSTONE CONSULTING LLC

PHASE I ENVIRONMENTAL SITE ASSESSMENT
ASTM E 1527-21 USER QUESTIONNAIRE

In order to qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "*Brownfields Amendments*"), the user shall conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that *"all appropriate inquiries"* (AAI) is not complete.

	Yes (Y), No (N), Unknown (U)	Y	N	U
(1.) Environmental liens that are filed or recorded against the *subject property* (40 CFR 312.25). Did a search of *land title records* (or judicial records where appropriate, see *Note 1* below) identify any *environmental liens* filed or recorded against the *subject property* under federal, tribal, state or local law?		☐	☑	☐
(2.) *Activity and use limitations* that are in place on the *subject property* or that have been filed or recorded against the *subject property*. Did a search of *land title records* (or judicial records where appropriate, see Note 1 above) identify any AULs, such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the *subject property* and/or have been filed or recorded against the *subject property* under federal, tribal, state or local law?		☐	☑	☐
(3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the *subject property* or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the *subject property* or an *adjoining property* so that you would have specialized knowledge of the chemicals and processes used by this type of business?		☑	☐	☐
(4.) Relationship of the purchase price to the fair market value of the *subject property* if it were not contaminated (40 CFR 312.29). Does the purchase price being paid for this *subject property* reasonably reflect the fair market value of the *subject property*? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the *subject property*?		☑	☐	☐
(5.) Commonly known or *reasonably ascertainable* information about the *subject property* (40 CFR 312.30). Are you aware of commonly known or *reasonably ascertainable* information about the *subject property* that would help the *environmental professional* to identify conditions indicative of *releases* or threatened *releases*? For example:		☐	☑	☐
(a.) Do you know the past uses of the *subject property*?		☑	☐	☐
(b.) Do you know of specific chemicals that are present or once were present at the *subject property*?		☐	☑	☐
(c.) Do you know of spills or other chemical *releases* that have taken place at the *subject property*?		☐	☑	☐
(d.) Do you know of any environmental cleanups that have taken place at the *subject property*?		☐	☑	☐

Describe (if known): Past Uses - see attached seller provided ESA dated Sept 28, 2020

Yes (Y), No (N), Unknown (U)	Y	N	U
(6.) The degree of obviousness of the presence or likely presence of contamination at the *subject property*, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31). Based on your knowledge and experience related to the *subject property* are there any *obvious* indicators that point to the presence or likely presence of *releases* at the *subject property*?	☐	☑	☐
(7.) Do you know if any of the documents within the attached list of *Helpful Documents* exist? If so, can you provide these documents?	☑	☐	☐

Property Name: Halstead Station

Company/User: Khosla Capital LLC

Name/Title (Printed): Raman Khosla, Managing Member

Date: 6/6/22

BLACKSTONE CONSULTING LLC | A Rimkus Company

LAUREN BEYRENT

Senior Project Manager

PROFESSIONAL SUMMARY:

Ms. Beyrent has over 9 years of experience in the environmental due diligence sector with an emphasis on completing Phase I Environmental Site Assessments (ESAs) and Property Condition Assessments (PCAs) at commercial, industrial, manufacturing/warehouse, and multi-family residential properties. In addition, Ms. Beyrent specializes in Phase I ESAs for Fannie Mae and Freddie Mac loan requirements, radon testing, and asbestos sampling. Other responsibilities include project staffing and management of large portfolio budgets, communicating findings with clients, and ensuring timely completion of her projects.

SELECTED PROJECT EXPERIENCE:

- Project manager for various environmental and property condition assessments throughout the U.S., Canada, and Mexico. Specific job functions include: communication with clients and property contacts, historic and local/state/federal research, government records/environmental regulatory database reviews, and technical report writing. PCA assessments also include the evaluation of typical building systems such as the building site and envelope, interior systems, roofing systems, mechanical equipment, plumbing, electrical/lighting systems, building structure, life safety/fire protection systems, and ADA compliance. Technical writing skills are utilized to prepare PCA reports, which include cost estimations, capital reserve planning, and engineering data analysis.
- Assessments were conducted for real estate owners, investors, and lending institutions in accordance with applicable American Society for Testing and Materials (ASTM) Standards and Guidelines, U.S. EPA All Appropriate Inquiry rules, Fannie Mae and Freddie Mac loan requirements, and additional project-specific guidelines. Routinely conducts radon and asbestos sampling and mold evaluations during the diligence assessments.
- Assisted in several remediation projects for various contaminated properties, which included soil and groundwater sampling, surveying, well-monitoring, and soil removal activities.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

Clemson University – Clemson, South Carolina B.S.- Environmental and Natural Resources, Minor in Biological Sciences
OSHA 10 Hour Occupational Safety & Health Training for Construction
OSHA 40 Hour HAZWOPER
Certified Asbestos Building Inspector (Pennsylvania and Virginia)

BLACKSTONE CONSULTING LLC | A Rimkus Company

ALLAN S. COFFEE

Senior Associate & Environmental Group Leader
714-343-7014 / acoffee@blackstoneconsulting.com / Santa Ana, California

PROFESSIONAL SUMMARY:

Mr. Coffee has over 25 years of experience with commercial real estate due diligence including environmental consulting and other related technical advisory related to real estate transactions, mergers/acquisitions, and property development. Specific experience includes Phase I Environmental Site Assessment (ESA); Asbestos, Lead-based Paint and Mold/IAQ consulting; Subsurface Soil and Groundwater Sampling; and Soil and Groundwater Remediation and Monitoring. Additional experience includes property condition assessment (PCA), vapor intrusion/risk management, environmental compliance/audit and regulatory agency coordination.

As Environmental Group Leader, Mr. Coffee is responsible for managing and directing Blackstone's services associated with environmental due diligence and Phase I ESAs, as well as consulting services and technical compliance associated with the built environment (asbestos, lead and mold, etc.), operational environment (regulatory permitting, compliance testing, etc.) and planned development or redevelopment (regulatory closure, construction worker safety, etc.). Mr. Coffee also provides technical review and concurrence for Phase I ESAs and environmental reviews.

As Senior Associate, Mr. Coffee assists in maintaining the communication and congruence between Blackstone service groups to continue a sustainable growth, which includes efficiency and diversity.

SELECTED PROJECT EXPERIENCE:

Has participated in the execution and delivery of over 2,000 Phase I ESA reports for clients including Private Equity Real Estate (PERE), Fannie Mae/Freddie Mac underwriters, REITs, large national and regional banks, private/public investment groups and numerous fiduciaries throughout the United States.

Managed the due diligence associated with the acquisition of a 75-property, national portfolio of warehouse and industrial properties for a private-equity investor. Environmental issues included past manufacturing operations, underground storage tanks usage, various hazardous materials storage, and adjoining property with known groundwater contamination migrating onto the site. Past on-site use and contamination triggered State reporting and coordination with the multiple regulatory agencies. Phase I ESA and Phase II subsurface investigation work completed within 30-days and evaluation of risk and potential remediation cost defined. Quick response and resolution allowed transaction to occur and assigned liability to the appropriate parties protecting the buyer.

Management and technical lead for the redevelopment of former industrial landfill property into low-income multi-family housing. Contamination identified during due diligence required notification to state regulatory agency with potential to stall acquisition and development approvals. Remediation risk

and cost defined during due diligence allowed transaction to occur before regulatory closure achieved. Remediation, including the removal of over 7,500 tons of lead contaminated soil, was performed in conjunction with construction providing savings and fast-tracking regulatory closure with state agency. Project was completed and remains in publicly traded portfolio.

EDUCATION AND PROFESSIONAL AFFILIATIONS

University of California at Los Angeles, CA, Bachelor of Science

OSHA 40-Hour HAZWOPER (Hazardous Waste Operator and Emergency Response)

NIOSH 582 Analyst Equivalent Certification

Indoor Air Quality Specialist/Inspector

BLACKSTONE CONSULTING LLC | *A Rimkus Company*

REBECCA L. RENICK

Principal, Director of Lending Services
Baltimore, MD
(443) 977-7671
brenick@blackstoneconsulting.com

PROFESSIONAL SUMMARY:

Ms. Renick has over 23 years of management experience in environmental and physical due diligence consulting. She opened Blackstone's Mid-Atlantic Regional Office in Baltimore in 2007, and as Blackstone's Director of Lending Services she is responsible for directing Blackstone's nationwide Fannie and Freddie lending work. Ms. Renick has significant experience in the due diligence industry on a variety of property types but specializes in the multifamily arena.

As Principal and Director of Lending Services, Ms. Renick is responsible for the management, development, and direction of a specialized group of environmental and property condition professionals serving the lending community.

Ms. Renick originates new business and services numerous Fannie Mae Delegated Underwriting and Servicing (DUS), Freddie Mac Seller/Servicers, traditional lenders, and equity clients.

SELECTED PROJECT EXPERIENCE:

- Responsible for cultivating, establishing, and maintaining client relationships.
- Develop and execute solutions for Blackstone Fannie and Freddie projects, having worked on thousands of GSE multifamily reports in recent years. Responsible for a range of client and internal presentations.
- Effectively managed client relationships and portfolios with the country's largest multifamily lenders, including Walker & Dunlop, CBRE Capital Markets, Inc., KeyBank Real Estate Capital, Jones Lang LaSalle, Capital One, and Wells Fargo Multifamily Capital, and numerous private equity organizations.
- Successfully executed numerous multifamily portfolio lending transactions nationwide for both the debt and equity interest.

EDUCATION AND PROFESSIONAL AFFILIATIONS:

B.A., Rutgers University, English.